Available from

Superintendent of Documents U.S. Government Printing Office Post Office Box 37082 Washington, D.C. 20013-7082

A year's subscription consists of 12 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

٨

Title List of Documents Made Publicly Available

April 1-30, 1988

Date Published: June 1988

Division of Freedom of Information and Publications Services Office of Administration and Resources Management U.S. Nuclear Regulatory Commission Washington, DC 20555



CONTENTS

Preface	17
Arrangement of Items by Docket Number	iv
Alphabetic Arrangement of Docket Items by Facility Name	*V
Docketed Items	1
Low Level Radwaste Disposal Sites — Docket 27	1
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	6
Domestic Licensing of Special Nuclear Material — Docket 70	209
Packaging of Radioactive Material for Transport and Transportation of	207
Radioactive Material Under Certain Conditions - Docket 71	213
Licensing of Independent Spent Fuel Storage — Docket 72	216
Nondocketed Items	217
10 CFR — Commission Meeting Records	217
ACRS — Advisory Committee on Reactor Safeguards	217
ADVCM — NRC Advisory Committee	219
COMMISSION — NRC Commissioners	219
CONTRACT — NRC Contracts and Modifications	220
FOIA — Freedom of Information Act Requests and Releases	224
GEN TECH IS — Generic Technical Issues	231
I&E — Inspection and Enforcement	232
MISC — Public Document Room Miscellaneous	233
NUREG — NUREG Reports and Related Correspondence	233
ORG — Correspondence with Other Organizations	239
PR — Proposed Rule	240
PRM — Petition for Rulemaking	243
PROJ — Projects - Predocket Licensing	243
PT21 — Noncompliance Reports and Related Correspondence	244
QA999 — Quality Assurance Inspections	244
REGGD — Regulatory Guides	245
REVIEW GROUP — NRC Research Review Groups	245
SECY — Position Papers Before the Commission	246
STATE PROG — State Programs	247
TOPREP — Vendor Reports and Related Correspondence	248
WASTE MGT — Nuclear Waste Management	249
WASTE RES — Waste Management Research Reports	256
XPORTLIC — Export and Import Licenses	258
Personal Author Index	259
Corporate Source Index	283
Report Number Index	305
Cross Reference of Enclosures to Principal Documents	307
Appendix A — Definitions of Docket 50 Categories	A-1
Appendix B — Definitions of Nondocketed Categories	B-1



PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- V. Decommissioning stage documents and correspondence
- X. Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

1) P. Operating license stage documents & correspondence

② ③

8411270362 Submits renewed, amended & updated petition under 2.206, urging NRC to require that util provide Commission full disclosure of intended sources & environ consequences prior to issuing full power OL.

84/11/21

2pp.

SUGARMAN, R.J. 5 Sugarman, Denworth & Hellegers
Denton, H. Office of Nuclear Reactor Regulation, Director

(7) Denton, H. Office of Nuclear Reactor 27628:356:27628:357 (9) (0) (11) (2) (3)

- 1. NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number (year, month, day, and sequence number of item).
- 3. Description of information contained in the document.
- 4. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source.
- 6. Date of document described.
- 7. Recipient of document and NRC or corporate affiliation.
- 8. Pages in this document.
- 9. This five-digit number is the NRC 48X microfiche designation.
- 10. The three-digit portion of this entry is the number of the frame on which this document starts.
- 11. The five-digit portion of this entry is the number of the frame on which this document ends.
- 12. The three-digit portion of this entry is the number of the frame on which this document ends.
- 13. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

10CFR—Commission Meeting Records
ACRS—Advisory Committee on Reactor Safeguards
COMMISSION—NRC Commissioners
CONTRACT—NRC Contracts and Modifications
DISCLOSURE—Financial Disclosure Information
FOIA—Freedom of Information Act Requests and Releases
GEN TECH IS—Generic Technical Issues

I&E—Inspection and Enforcement MISC—Public Document Room Miscellaneous

NUREG-NUREG Reports and Related Correspondence

ORG-Correspondence with Other Organizations

PR—Proposed Rule

PRM-Petition for Rulemaking

PROJ-Projects-Predocket Licensing

PT21-Noncompliance Reports and Related Correspondence

QA999—Quality Assurance Inspections

REGGD—Regulatory Guides

RES-Research and Technical Assistance Reports

REVIEW GRP—NRC Research Review Groups

RM—Rulemakings

SECY—Position Papers Before the Commission

STATE PROG-State Programs

TOPREP-Vendor Reports and Related Correspondence

WASH-Regulatory Publications-Pre-NUREG Series

WASTE MGT-Nuclear Waste Management


WASTE RES-Waste Management Research Reports

XPORTLIC—Exports and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:

NUREG—NUREG Reports and Related Correspondence



- Nondocket category
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. NRC Report Number
- Title and description of information contained in the document
- Personal author(s). An asterisk in this position indicates that there is no personal author.
- Corporate, agency or other nonindividual source.
- Contract or financial (FIN) number (if any). If the document has a secondary report number, it will appear following this entry.
- 8. Secondary report number assigned by originator.
- Date of document described.
- 10. NRC organizational recipient.
- 11. Pages in document.
- 12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
- 13. Price for which NRC sells the documents.

- 14. This five-digit number is the NRC 48X interoffene designation.
- 15. This three-digit portion of this entry is the number of the frame on which this document starts.
- 16. This five-digit number is the microfiche on which this document ends.
- 17. This three-digit number is the frame on which this document ends.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Publications Services
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 487-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation. Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges and method of payment, based on the current reproduction contract, are obtainable from the PDR.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Le 27	vel Radwaste Disposal Sites - Docket		40-8752	PINAL MINERALS & MINING, LTD., MIAMI, AZ	5
27-047	BARNWELL, SC, CHEM-NUCLEAR SYSTEMS, INC.	1	40-8768	KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK	5
27-048	RICHLAND, WA, U.S. ECOLOGY, INC.	1	40-8783	URANERZ USA, INC., CASPER, WY	٤
Domesi Docket	tic Licensing of Source Material -		40-8800	MCGEAN DISPOSAL DUMP, NEWBURGH HEIGHTS, OH	£
40-0299		1	40-8829	FERRET EXPLORATION CO. OF NEBRASKA, INC., CRAWFORD, NE	£
40-1162		1	40-8902	ANACONDA MINERALS CO., GRANTS, NM	6
40-1341	•	4	40-8903	HOMESTAKE MINING CO., GRANTS, NM	5
40-1341	CHATTANOOGA, TN	1	40-8904	BP AMERICA, INC./L-BAR URANIUM FACILITY, SALT LAKE	5
	CHICAGO, IL	1	40-8905	KERR-MCGEE CORP./QUIVIRA MINING CO., OKLAHOMA CITY, OK	6
40-2259	WY	2	40-8907	UNITED NUCLEAR CORP., SANTA FE, NM	e
40-3392		2	40-8908	CHEVRON, U.S.A., INC., GRANTS, NM	e
40-3453 40-4492	AMERICAN NUCLEAR CORP., CASPER,	2 2	40-8911	MOBIL ALTERNATIVE ENERGY, INC., BOULDER, CO	6
40.0500	WY		40-8913	UNITED NUCLEAR CORP., GALLUP, NM	6
40-6500 40-6622	PATHFINDER MINES CORP., SHIRLEY	3	40-8936	BUTKIN PRECISION MANUFACTURING, INC., MILFORD, CN	6
40 6656	BASIN, WY		40-8938	TEXTRON, INC., LOWELL, MA	6
40-6659	SHIRLEY BASIN, WY	3	40-8943	FERRET EXPLORATION CO. OF NEBRASKA, DENVER, CO	6
40-7102		3	Domestic I	lcensing of Production and	
40-7455	WHITTAKER METALS, LOS ANGELES, CA	3	Utilization	Facilities - Docket 50	
40-7580	FANSTEEL, INC., NORTH CHICAGO, IL	3	50-2	FORD NUCLEAR REACTOR	6
40-7604	SOHIO CHEMICAL CO., LIMA, OH	3	50-3	INDIAN POINT STATION, UNIT 1	E
40-8027	KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK	3	50-5	PENNSYLVANIA STATE UNIV. RESEARCH REACTOR	7
40-8064	EXXON MINERALS CO., USA, HOUSTON,	3	50-6	BATTELLE MEMORIAL INSTITUTE RESEARCH REACTOR	-7
40-8084		4	50-10	DRESDEN NUCLEAR POWER STATION, UNIT 1	7
40-8102		4	50-13	B&W CRITICAL EXPERIMENT FACILITY	9
40-8452	BEAR CREEK URANIUM CO., CASPER, WY	4	50-16	ENRICO FERMI ATOMIC POWER PLANT,	5
40-8502	MALAPAI RESOURCES CO., PHOENIX, AZ	4	50-20	UNIT 1 MASSACHUSETTS INSTITUTE OF TECHNOLOGY RESEARCH REACTOR	е
40-8681	I UMETCO MINERALS CORP., GRAND JUNCTION, CO	4	6 0- 2 2	WESTINGHOUSE TEST REACTOR	ε
40-8684	MALAPAI RESOURCES CO., CASPER, WY	4	60-27	WASHINGTON STATE UNIV. RESEARCH REACTOR (TRIGA)	8
40-8698	PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO	5	50-29	YANKEE-ROWE NUCLEAR POWER STATION	
40-8714	CLEVELAND-CLIFFS IRON CO., CLEVELAND, OH	5	50-30	PLUM BROOK RESEARCH REACTOR FACILITY	8

.

Docket	Name	Page	Docket	Name
50-47	ARMY MATERIALS RESEARCH	10	50-157	CORNELL UNIV. RESEARCH REACTOR
50-54	REACTOR CINTICHEM	10	50-160	GEORGIA INSTITUTE OF TECHNOLOGY RESEARCH REACTOR
50-57	BUFFALO MATERIALS RESEARCH	10	50-163	GA TECHNOLOGIES
50-59	CENTER TEXAS A&M UNIV. RESEARCH	10	50-166	UNIV. OF MARYLAND RESEARCH REACTOR
50-62	REACTOR UNIV. OF VIRGINIA RESEARCH	10	50-170	ARMED FORCES RADIOBIOLOGY RESEARCH INSTITUTE
	REACTOR		50-171	PEACH BOTTOM ATOMIC POWER
50 -70	GENERAL ELECTRIC NUCLEAR TEST REACTOR	10	50-182	STATION, UNIT 1 PURDUE UNIV. RESEARCH REACTOR
50-72	UNIV. OF UTAH RESEARCH REACTOR	10	50-183	VALLECITOS EXPERIMENTAL
50-73	GENERAL ELECTRIC NUCLEAR TEST REACTOR	10	50-184	SUPERHEAT REACTOR NATIONAL BUREAU OF STANDARDS
50-77	CATHOLIC UNIV. OF AMERICA RESEARCH REACTOR	10		REACTOR
50-83	UNIV. OF FLORIDA TRAINING REACTOR	10	50-185	PLUM BROOK REACTOR - MOCK-UP
50-87	WESTINGHOUSE CRITICAL EXPERIMENT	11	50-186	UNIV. OF MISSOURI RESEARCH REACTOR-COLUMBIA
50-89	GENERAL ATOMIC CO.	11	50-188	KANSAS STATE UNIV. RESEARCH REACTOR
50-97	CORNELL UNIV. ZERO POWER REACTOR	11	50-192	UNIV. OF TEXAS RESEARCH REACTOR
50-99	BABCOCK & WILCOX TEST REACTOR	11	50-193	RHODE ISLAND & PROVIDENCE PLANTATIONS AEC
50-112	UNIV. OF OKLAHOMA RESEARCH REACTOR	11	50-199	MANHATTAN COLLEGE RESEARCH REACTOR
50-113	UNIV. OF ARIZONA RESEARCH REACTOR	11	50-206	SAN ONOFRE NUCLEAR STATION, UNIT
50-116	IOWA STATE UNIV. RESEARCH REACTOR	11	50-213	HADDAM NECK PLANT
50-123	UNIV. OF MISSOURI RESEARCH	12	50-214	MALIBU POWER REACTOR
	REACTOR-ROLLA		50-219	OYSTER CREEK NUCLEAR POWER PLANT
50-124	VIRGINIA POLYTECHNIC INSTITUTE TRAINING REACTOR	12	50-220	NINE MILE POINT NUCLEAR STATION, UNIT 1
50-128	TEXAS A&M UNIV. RESEARCH REACTOR	12	50-223	UNIV. OF LOWELL RESEARCH REACTOR
50-131	OMAHA VETERANS ADMINISTRATION HOSPITAL RESEARCH REACTOR	12	50-224	UNIV. OF CALIFORNIA RESEARCH
50-133	HUMBOLDT BAY POWER PLANT, UNIT 3	12	50.005	REACTOR
50-134	WORCESTER POLYTECHNIC INSTITUTE RESEARCH REACTOR	13	50-225 50-228	RPI CRITICAL EXPERIMENT AEROTEST RADIOGRAPHY &
50-139	UNIV. OF WASHINGTON RESEARCH REACTOR	13	50-237	RESEARCH REACTOR DRESDEN NUCLEAR POWER STATION.
50-142	UCLA TRAINING REACTOR	13	30-201	UNIT 2
50-146	SAXTON NUCLEAR EXPERIMENTAL	13	50-238	NUCLEAR SHIP SAVANNAH
E0 + 40	FACILITY		50-243	OREGON STATE UNIV. RESEARCH REACTOR
50-148	UNIV. OF KANSAS RESEARCH REACTOR	13	50-244	ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1
50-150	OHIO STATE UNIV. RESEARCH REACTOR	13	50-245	MILLSTONE NUCLEAR POWER STATION, UNIT 1
50-151	UNIV. OF ILLINOIS RESEARCH REACTOR	13	50-247	INDIAN POINT STATION, UNIT 2
50-155	BIG ROCK POINT NUCLEAR PLANT	13	50-249	DRESDEN NUCLEAR POWER STATION,
50-156	UNIV. OF WISCONSIN RESEARCH REACTOR	14	50-250	UNIT 3 TURKEY POINT PLANT, UNIT 3
				TOTALL CHAT CHAT CHAT C

Docket	Name	Page	Docket	Name	Page
50-251	TURKEY POINT PLANT, UNIT 4	31	50-297	NORTH CAROLINA STATE UNIV.	71
50-252	UNIV. OF NEW MEXICO RESEARCH REACTOR	34		PULSTAR REACTOR	
50-254	QUAD-CITIES STATION, UNIT 1	34	50-298	COOPER NUCLEAR STATION	72
50-255	PALISADES NUCLEAR PLANT	35	50-301	POINT BEACH NUCLEAR PLANT, UNIT 2	73
50-259	BROWNS FERRY NUCLEAR POWER	36	50-302	CRYSTAL RIVER NUCLEAR PLANT, UNIT 3	74
50-260	STATION, UNIT 1 BROWNS FERRY NUCLEAR POWER	39	50-304	ZION NUCLEAR POWER STATION, UNIT 2	76
	STATION, UNIT 2	00	50-305	KEWAUNEE NUCLEAR POWER PLANT	77
50-261	H.B. ROBINSON PLANT, UNIT 2	41	50-306	PRAIRIE ISLAND NUCLEAR STATION,	79
50-262	BRIGHAM YOUNG UNIV. RESEARCH REACTOR	42		UNIT 2	
50-263	MONTICELLO NUCLEAR GENERATING	42	50-309	MAINE YANKEE ATOMIC POWER PLANT	80
=5 =55	PLANT	76	50-311	SALEM NUCLEAR GENERATING STATION, UNIT 2	81
50-264	DOW CHEMICAL CO.	42	50-312	RANCHO SECO NUCLEAR GENERATING	82
50-265	QUAD-CITIES STATION, UNIT 2	42		STATION	
50-266	POINT BEACH NUCLEAR PLANT, UNIT 1	43	50-313	ARKANSAS NUCLEAR ONE, UNIT 1	84
50-267	FORT ST. VRAIN NUCLEAR GENERATING STATION	45	50-314	NUCLEAR SHIP SAVANNAH	85
60-269	OCONEE NUCLEAR STATION, UNIT 1	46	50-315	DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1	85
50-270	OCONEE NUCLEAR STATION, UNIT 2	48	50-316	DONALD C. COOK NUCLEAR POWER	86
50-271	VERMONT YANKEE NUCLEAR POWER	49		PLANT, UNIT 2	
50-272	STATION SALEM NUCLEAR GENERATING	50	50-317	CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1	87
50-274	STATION, UNIT 1 U.S. GEOLOGICAL SURVEY RESEARCH	51	50-318	CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2	89
50-275	REACTOR DIABLO CANYON NUCLEAR POWER		50-320	THREE MILE ISLAND NUCLEAR STATION, UNIT 2	90
30-273	PLANT, UNIT 1	51	50-321	EDWIN I. HATCH NUCLEAR PLANT, UNIT	91
50-277	PEACH BOTTOM ATOMIC POWER STATION, UNIT 2	52	50-322	1 SHOREHAM NUCLEAR POWER STATION	93
50-278	PEACH BOTTOM ATOMIC POWER STATION, UNIT 3	54	50-323	DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2	96
50-280	SURRY POWER STATION, UNIT 1	56	50-324	BRUNSWICK STEAM ELECTRIC PLANT,	97
50-281	SURRY POWER STATION, UNIT 2	58	50-324	UNIT 2	٠.
50-282	PRAIRIE ISLAND NUCLEAR STATION, UNIT 1	60	50-325	BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1	100
50-284	IDAHO STATE UNIV. RESEARCH REACTOR	60	50-326	UNIV. OF CALIFORNIA AT IRVINE RESEARCH REACTOR	101
50-285	FORT CALHOUN STATION, UNIT 1	61	50-327	SEQUOYAH NUCLEAR PLANT, UNIT 1	101
50-286	INDIAN POINT STATION, UNIT 3	62	50-328	SEQUOYAH NUCLEAR PLANT, UNIT 2	105
50-287	OCONEE NUCLEAR STATION, UNIT 3	63	50-329	MIDLAND PLANT, UNIT 1	109
60-288	REED COLLEGE RESEARCH REACTOR	64	50-330	MIDLAND PLANT, UNIT 2	109
50-289	THREE MILE ISLAND NUCLEAR	64	50-331	DUANE ARNOLD ENERGY CENTER	109
50-293	STATION, UNIT 1 PILGRIM NUCLEAR POWER STATION,	66	60-333	JAMES A. FITZPATRICK NUCLEAR POWER PLANT	110
50-294	UNIT 1 MICHIGAN STATE UNIV. RESEARCH REACTOR	68	50-334	BEAVER VALLEY POWER STATION, UNIT 1	111
50-295	ZION NUCLEAR POWER STATION, UNIT	68	50-335	ST. LUCIE PLANT, UNIT 1	112
	1		50-336	MILLSTONE NUCLEAR POWER STATION, UNIT 2	113
50-296	BROWNS FERRY NUCLEAR POWER STATION, UNIT 3	69	50-338	NORTH ANNA POWER STATION, UNIT 1	115

50-339	NORTH ANNA POWER STATION, UNIT 2	117	50-412	BEAVER VALLEY POWER STATION, UNIT 2	158
50-341	ENRICO FERMI ATOMIC POWER PLANT, UNIT 2	119	50-413	CATAWBA NUCLEAR STATION, UNIT 1	159
50-344	TROJAN NUCLEAR PLANT	12 2	50-414	CATAWBA NUCLEAR STATION, UNIT 2	161
50-346	DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1	12 3	50-416	GRAND GULF NUCLEAR STATION, UNIT	164
50-348	JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1	125	50-417	GRAND GULF NUCLEAR STATION, UNIT 2	165
50-352	LIMERICK GENERATING STATION, UNIT	126	50-423	MILLSTONE NUCLEAR POWER STATION, UNIT 3	166
50-353	LIMERICK GENERATING STATION, UNIT 2	128	50-424	ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 1	167
50-354	HOPE CREEK NUCLEAR STATION, UNIT 1	128	50-425	ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 2	169
50-356	UNIV. OF ILLINOIS RESEARCH REACTOR	131	50-433	UNIV. OF CALIFORNIA AT SANTA BARBARA RESEARCH REACTOR	171
50-358	WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1	131	STN-50- 437	FLOATING NUCLEAR PLANT	171
50-361	SAN ONOFRE NUCLEAR STATION, UNIT 2	131	50-438	BELLEFONTE NUCLEAR PLANT, UNIT 1	171
50-362	SAN ONOFRE NUCLEAR STATION, UNIT	133	50-439	BELLEFONTE NUCLEAR PLANT, UNIT 2	172
	3		50-440	PERRY NUCLEAR POWER PLANT, UNIT	173
50-364	JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2	134	50-441	1 PERRY NUCLEAR POWER PLANT, UNIT	174
50-366	EDWIN I. HATCH NUCLEAR PLANT, UNIT 2	135	50.440	2 CEADROOK NIKOLEAR CTATION LINES 4	476
50-368	ARKANSAS NUCLEAR ONE, UNIT 2	137	50-443	SEABROOK NUCLEAR STATION, UNIT 1	175
50-369	WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 1	138	50-444 50-445	SEABROOK NUCLEAR STATION, UNIT 2 COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 1	178 180
50-370	WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 2	140	50-446	COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 2	185
50-373	LASALLE COUNTY STATION, UNIT 1	142	STN-50-	BYRON STATION, UNIT 1	188
50-374	LASALLE COUNTY STATION, UNIT 2	143	454		
50-375	NUCLEAR EXAMINATION REACTOR	144	STN-50- 455	BYRON STATION, UNIT 2	189
50-382	WATERFORD GENERATING STATION, UNIT 3	144	STN-50- 456	BRAIDWOOD STATION, UNIT 1	190
50-387	SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1	146	STN-50- 457	BRAIDWOOD STATION, UNIT 2	192
50-388	SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2	147	50-458	RIVER BEND STATION, UNIT 1	193
50-389	ST. LUCIE PLANT, UNIT 2	148	50-460	WPPSS NUCLEAR PROJECT, UNIT 1	195
50-390	WATTS BAR NUCLEAR PLANT, UNIT 1	149	50-461	CLINTON POWER STATION, UNIT 1	198
50-391	WATTS BAR NUCLEAR PLANT, UNIT 2	151	STN-50-	CESSAR SYSTEM 80	198
50-395	VIRGIL C. SUMMER NUCLEAR STATION, UNIT 1	152	470 STN-50-	WOLF CREEK GENERATING STATION	196
50-396	UNIV. OF VIRGINIA CAVALIER REACTOR	153	482		
50-397	WPPSS NUCLEAR PROJECT, UNIT 2	153	STN-50- 483	CALLAWAY PLANT, UNIT 1	198
50-400	SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1	155	STN-50- 498	SOUTH TEXAS PROJECT, UNIT 1	198
50-407	UNIV. OF UTAH RESEARCH REACTOR	156	STN-50-	SOUTH TEXAS PROJECT, UNIT 2	20
50-409	LA CROSSE BOILING WATER REACTOR	156	499		
50-410	NINE MILE POINT NUCLEAR STATION, UNIT 2	157	50-500	DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2	20:

50-501	DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3	203	70-1257	ADVANCED NUCLEAR FUELS CORP., RICHLAND, WA	212
STN-50- 508	WPPSS NUCLEAR PROJECT, UNIT 3	203	70-1308	GENERAL ELECTRIC CO., SAN JOSE, CA	212
STN-50-	PALO VERDE NUCLEAR STATION, UNIT	203	70-1359	IRT CORP., SAN DIEGO, CA	212
528	1		70-2932	TEXAS UTILITIES GENERATING CO., DALLAS, TX	212
STN-50- 529	PALO VERDE NUCLEAR STATION, UNIT 2	205	70-3051	TRANSNUCLEAR, INC., AIKEN, SC	212
STN-50- 530	PALO VERDE NUCLEAR STATION, UNIT 3	207	Packaging Transport	of Radioactive Material for and Transportation of Radioactive	
50-537	CLINCH RIVER BREEDER REACTOR	208	Material Un	nder Certain Conditions - Docket 71	
50-538	MEMPHIS STATE UNIV. RESEARCH REACTOR	208	71-0202	PACIFIC GAS & ELECTRIC CO.	213
50-601	RESAR SP/90	208	71-0240	POWER AUTHORITY OF STATE OF NEW YORK	213
50-602	UNIV. OF TEXAS RESEARCH REACTOR	209	71-0404	CTI, INC.	213
50-603	ALCHEMIE CENTRIFUGE ENRICHMENT PLANT	209	71-0420	RADIATION TECHNOLOGY, INC.	213
50-604	ALCHEMIE CENTRIFUGE ENRICHMENT	209	71-0423	H&H X-RAY SERVICES, INC.	210
	PLANT		71-0448	MET LAB, INC.	210
STN-50- 605	GE ADVANCED BWR DESIGN	209	71-0460	UNIV. OF VIRGINIA	210
			71-0490	INSPECTION SERVICES CORP.	210
Domestic L Material - D	lcensing of Special Nuclear Docket 70		71-0498	GEARHART-OWEN INDUSTRIES	213
70-0008	BATTELLE MEMORIAL INSTITUTE,	209	71-0500	E.I. DU PONT DE NEMOURS & CO., INC.	213
70-0000	COLUMBUS, OH	200	71-0545	TEXAS NUCLEAR CORP.	213
70-0027	BABCOCK & WILCOX CO., LYNCHBURG, VA	210	71-0598	KANSAS GAS & ELECTRIC CO.	213
70-0036	COMBUSTION ENGINEERING, INC.,	210	71-0641	UNITED STATES TESTING CO., INC.	213
70-0030	WINDSOR, CT	210	71-0651	WESTINGHOUSE ELECTRIC CORP.	213
70-0135	BABCOCK & WILCOX CO., APOLLO, PA	210	71-0652	SAMSON INSPECTION & TECHNICAL SERVICES, INC.	213
70-0143	NUCLEAR FUEL SERVICES, INC., ERWIN, TN	210	71-0653	BRAN-SHON, INC.	21
70-0364	BABCOCK & WILCOX CO., APOLLO, PA	211	71-0654	POWER INSPECTION, INC.	21
70-0371	UNC NAVAL PRODUCTS, INC., UNCASVILLE, CT	211	71-3001	MODEL: S-B/23, STUDSVIK ENERGITEKNIK AB	21
70-0600	SEATTLE UNIV., SEATTLE, WA	211	71-3003	MODEL: TN-1, TRANSNUKLEAR GMBH	21
70-0687	CINTICHEM, INC., TUXEDO, NY	211	71-4986	MODEL: RA-2, RA-3, RA-J, GENERAL	21
70-0734	GA TECHNOLOGIES, INC., SAN DIEGO,	211		ELECTRIC CO.	
70-0754	CA GENERAL ELECTRIC CO., PLEASANTON,	211	71-5450	MODEL: RCC, -1, -2, -3, -4, WESTINGHOUSE ELECTRIC CORP.	21
70-0824	CA BABCOCK & WILCOX CO., LYNCHBURG,	211	71-5926	MODEL: GE-100, GENERAL ELECTRIC CO.	21
	VA		71-5971	MODEL: 200, GENERAL ELECTRIC CO.	21
70-0925	KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK	211	71-6078	MODEL: 927A1 & 927C1, COMBUSTION ENGINEERING, INC.	21
70-1068	FLORIDA, UNIV. OF, GAINESVILLE, FL	212	71-6717	MODEL: 6717-B, GAMMA INDUSTRIES,	21
70-1100	COMBUSTION ENGINEERING, INC., WINDSOR, CT	212	71-9001	INC. MODEL: IF-300, GENERAL ELECTRIC	21
70-1113	GENERAL ELECTRIC CO., WILMINGTON, NC	212		CO.	21
70-1151	WESTINGHOUSE ELECTRIC CORP., COLUMBIA, SC	212	71-9006 71 - 9007	MODEL: AI 500 SU, TECH/OPS, INC. MODEL: 520, TECH/OPS, INC.	21
70-1201	BABCOCK & WILCOX CO., LYNCHBURG,	212	71-9010	MODEL: NLI-1/2, NUCLEAR ASSURANCE	21
70-1201	VA			CORP.	

Docket	Name	Page	Docket	Name
71-9015	MODEL: TN-8, -8L, TRANSNUCLEAR, INC.	214	71-9168	MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC.
71-9032	MODEL: 650, TECH/OPS, INC.	214	71-9176	MODEL: NUPAC 14/210L & 14/210H,
71-9036	MODEL: C-1, SOURCE PRODUCTION & EQUIPMENT CO., INC.	214		NUCLEAR PACKAGING, INC.
71-9056	MODEL: SPEC 2-T, SOURCE PRODUCTION & EQUIPMENT CO.	214	71-9183	MODEL: NAC-1, NUCLEAR ASSURANCE CORP.
71-9057	MODEL: FPD-100, GA TECHNOLOGIES,	214	71-9193	MODEL: NES-5, NUCLEAR ENERGY SERVICES, INC.
	INC.	617	71-9202	MODEL: TN-BRP, TRANSNUCLEAR, INC.
71-9079	MODEL: NUPAC 14D-2.0, WESTINGHOUSE-HITTMAN NUCLEAR	214	71-9208	MODEL: NUPAC 10-142, NUCLEAR PACKAGING, INC.
71-9080	MODEL: HN-600 & NUPAC 100, WESTINGHOUSE-HITTMAN NUCLEAR	214	71-9212	MODEL: 72-B, NUCLEAR PACKAGING, INC.
71-9102	MODEL: NPI-20WC-8, NEUTRON PRODUCTS, INC.	215	71-9213	MODEL: TN-GEMINI, TRANSNUCLEAR
71-9126	MODEL: 20, 20A, 50, 60A, GAMMA INDUSTRIES, INC.	215	71-9216	MODEL: CNS 1-13G, CHEM-NUCLEAR SYSTEMS, INC.
71-9133	MODEL: C-10, GAMMA INDUSTRIES, INC.	215	71-9218	MODEL: TRUPACT-II, ENERGY, DEPT.
71-9135	MODEL: CENTURY S & SA, GAMMA INDUSTRIES, INC.	215	71-9222	MODEL: HN-215H, WESTINGHOUSE
71-9147	MODEL: 850, TECH/OPS, INC.	215	71-9224	HITTMAN NUCLEAR, INC.
71-9161	MODEL: HN-100 SERIES 3, WESTINGHOUSE-HITTMAN NUCLEAR	215	71-9224	MODEL: HN-190-2, WESTINGHOUSE HITTMAN NUCLEAR, INC.
71-9152	MODEL: CNS 1-13C II, CHEM-NUCLEAR SYSTEMS, INC.	215	Licensing of - Docket 72	f Independent Spent Fuel Storage
71-9156	MODEL: IR-50, INDUSTRIAL NUCLEAR CO.	215	72-0001	MORRIS OPERATIONS, GENERAL ELECTRIC CO.
71-9157	MODEL: IR-100, INDUSTRIAL NUCLEAR CO.	215	72-0002	VIRGINIA ELECTRIC & POWER CO.
71-9167	MODEL: 3206B, 3227B & 3218,	215	72-0003	CAROLINA POWER & LIGHT CO.
11-9107	AMERSHAM CORP.	215	72-0004	DUKE POWER CO., 50-269

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites - Docket 27			PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO	40-8698	5
BARNWELL, SC, CHEM-NUCLEAR	27-047	1	RIO ALGOM MINING CORP., MOAB, UT	40-8084	4
SYSTEMS, INC.	07.040	4	SHIELDALLOY CORP., NEWFIELD, NJ	40-7102	3
RICHLAND, WA, U.S. ECOLOGY, INC.	27-048	1	SOHIO CHEMICAL CO., LIMA, OH	40-7604	3
Domestic Licensing of Source Material - Docket 40			TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN	40-1341	1
ALLIED-SIGNAL, INC., METROPOLIS, IL	40-3392	2	TEXTRON, INC., LOWELL, MA	40-8938	6
AMERICAN NUCLEAR CORP., CASPER, WY	40-4492	2	UMETCO MINERALS CORP., GRAND JUNCTION, CO	40-8681	4
ANACONDA MINERALS CO., GRANTS, NM	40-8902	5	UMETCO MINERALS CORP., RIVERTON, WY	40-0299	1
ATLAS MINERALS, INC., DENVER, CO	40-3453	2	UNITED NUCLEAR CORP., GALLUP, NM	40-8913	6
BEAR CREEK URANIUM CO., CASPER, WY	40-8452	4	UNITED NUCLEAR CORP., SANTA FE, NM	40-8907	6
BP AMERICA, INC./L-BAR URANIUM	40-8904	5	URANERZ USA, INC., CASPER, WY	40-8783	5
BUTKIN PRECISION MANUFACTURING, INC.,	40-8936	6	WESTERN NUCLEAR, INC., JEFFREY CITY,	40-1162	1
MILFORD, CN CHEVRON, U.S.A., INC., GRANTS, NM	40-8908	6	WHITTAKER METALS, LOS ANGELES, CA	40-7455	3
CLEVELAND-CLIFFS IRON CO., CLEVELAND, OH	40-8908	5	Domestic Licensing of Production and Utilization Facilities - Docket 50		
ENERGY, DEPT. OF, CANONSBURG, PA	40-6500	3			
EXXON CO., USA, HOUSTON, TX	40-8102	4	AEROTEST RADIOGRAPHY & RESEARCH REACTOR	50-228	23
EXXON MINERALS CO., USA, HOUSTON, TX	40-8064	3	ALCHEMIE CENTRIFUGE ENRICHMENT	50-603	209
FANSTEEL, INC., NORTH CHICAGO, IL	40-7580	3	PLANT		
FERRET EXPLORATION CO. OF NEBRASKA, DENVER, CO	40-8943	6	ALCHEMIE CENTRIFUGE ENRICHMENT PLANT	50-604	209
FERRET EXPLORATION CO. OF NEBRASKA,	40-8829	5	ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 1		167
INC., CRAWFORD, NE			ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 2		169 84
GETTY OIL/PETROTOMICS CO., SHIRLEY BASIN, WY	40-6659	3	ARKANSAS NUCLEAR ONE, UNIT 1	50-313 50-368	137
HOMESTAKE MINING CO., GRANTS, NM	40-8903	5	ARKANSAS NUCLEAR ONE, UNIT 2	50-170	15
KERR-MCGEE CHEMICAL CORP., WEST	40-2061	1	ARMED FORCES RADIOBIOLOGY RESEARCH INSTITUTE	50-170	13
CHICAGO, IL			ARMY MATERIALS RESEARCH REACTOR	50-47	10
KERR-MCGEE CORP./QUIVIRA MINING CO., OKLAHOMA CITY, OK	40-8905	6	B&W CRITICAL EXPERIMENT FACILITY	50-13	8
KERR-MCGEE NUCLEAR CORP.,	40-8027	3	BABCOCK & WILCOX TEST REACTOR	50-99	11
OKLAHOMA CITY, OK KERR-MCGEE NUCLEAR CORP.,	40-8768	5	BATTELLE MEMORIAL INSTITUTE RESEARCH REACTOR	50-6	7
OKLAHOMA CITY, OK			BEAVER VALLEY POWER STATION, UNIT 1	60-334	111
MALAPAI RESOURCES CO., CASPER, WY	40-8684	4	BEAVER VALLEY POWER STATION, UNIT 2	50-412	158
MALAPAI RESOURCES CO., PHOENIX, AZ	40-8502	4	BELLEFONTE NUCLEAR PLANT, UNIT 1	50-438	17 1
MCGEAN DISPOSAL DUMP, NEWBURGH HEIGHTS, OH	40-8800	5	BELLEFONTE NUCLEAR PLANT, UNIT 2	50-439	172
MOBIL ALTERNATIVE ENERGY, INC.,	40-8911	6	BIG ROCK POINT NUCLEAR PLANT	50-155	13
BOULDER, CO			BRAIDWOOD STATION, UNIT 1	STN-50-458	190
PATHFINDER MINES CORP., RIVERTON, WY	40-2259	2	BRAIDWOOD STATION, UNIT 2	STN-50-457	192
PATHFINDER MINES CORP., SHIRLEY BASIN, WY	40-6622	3	BRIGHAM YOUNG UNIV. RESEARCH REACTOR	50-262	42
PINAL MINERALS & MINING, LTD., MIAMI, AZ	40-8752	5	BROWNS FERRY NUCLEAR POWER STATION, UNIT 1	50-259	36

Name	Docket	Page	Name	Docket	Page
BROWNS FERRY NUCLEAR POWER	50-260	39	DUANE ARNOLD ENERGY CENTER	50-331	109
STATION, UNIT 2	50-296	69	EDWIN I. HATCH NUCLEAR PLANT, UNIT 1	50-321	91
BROWNS FERRY NUCLEAR POWER STATION, UNIT 3	50-290	00	EDWIN I. HATCH NUCLEAR PLANT, UNIT 2	50-366	135
BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1	50-325	100	ENRICO FERMI ATOMIC POWER PLANT, UNIT 1	50-16	8
BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2	50-324	97	ENRICO FERMI ATOMIC POWER PLANT, UNIT 2	50-341	119
BUFFALO MATERIALS RESEARCH CENTER	50-57	10	FLOATING NUCLEAR PLANT	STN-50-437	171
BYRON STATION, UNIT 1	STN-50-454	188	FORD NUCLEAR REACTOR	50-2	6
BYRON STATION, UNIT 2	STN-50-455	189	FORT CALHOUN STATION, UNIT 1	50-285	61
CALLAWAY PLANT, UNIT 1	STN-50-483	198	FORT ST. VRAIN NUCLEAR GENERATING	50-267	45
CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1	50-317	87	STATION GA TECHNOLOGIES	50-163	15
CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2	50-318	89	GE ADVANCED BWR DESIGN	STN-50-605	209
CATAWBA NUCLEAR STATION, UNIT 1	50-413	159	GENERAL ATOMIC CO.	50-89	11
CATAWBA NUCLEAR STATION, UNIT 2	50-414	161	GENERAL ELECTRIC NUCLEAR TEST	50-70	10
CATHOLIC UNIV. OF AMERICA RESEARCH REACTOR	50-77	10	REACTOR GENERAL ELECTRIC NUCLEAR TEST	50-73	10
CESSAR SYSTEM 80 S	TN-50-470	196	REACTOR	E0 160	1.4
CINTICHEM	50-54	10	GEORGIA INSTITUTE OF TECHNOLOGY RESEARCH REACTOR	50-160	14
CLINCH RIVER BREEDER REACTOR	50-537	208	GRAND GULF NUCLEAR STATION, UNIT 1	50-416	164
CLINTON POWER STATION, UNIT 1	50-461	195	GRAND GULF NUCLEAR STATION, UNIT 2	50-417	165
COMANCHE PEAK STEAM ELECTRIC	50-445	180	H.B. ROBINSON PLANT, UNIT 2	50-261	41
STATION, UNIT 1	50		HADDAM NECK PLANT	50-213	18
COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 2	50-446	185	HOPE CREEK NUCLEAR STATION, UNIT 1	50-354	128
COOPER NUCLEAR STATION	50-298	72	HUMBOLDT BAY POWER PLANT, UNIT 3	50-133	12
CORNELL UNIV. RESEARCH REACTOR	50-157	14	IDAHO STATE UNIV. RESEARCH REACTOR	50-284	60
CORNELL UNIV. ZERO POWER REACTOR	50-97	11	INDIAN POINT STATION, UNIT 1	50-3	6
CRYSTAL RIVER NUCLEAR PLANT, UNIT 3	50-302	74	INDIAN POINT STATION, UNIT 2	50-247	26
DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1	50-346	123	INDIAN POINT STATION, UNIT 3	60-286	62
DAVIS-BESSE NUCLEAR POWER STATION.	50-500	203	IOWA STATE UNIV. RESEARCH REACTOR	50-116	11
UNIT 2 DAVIS-BESSE NUCLEAR POWER STATION,	50-501	203	JAMES A. FITZPATRICK NUCLEAR POWER PLANT	50-333	110
UNIT 3	50-501	200	JOSEPH M. FARLEY NUCLEAR PLANT, UNIT	50-348	125
DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1	50-275	51	JOSEPH M. FARLEY NUCLEAR PLANT, UNIT	50-364	134
DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2	, 50-323	96	KANSAS STATE UNIV. RESEARCH	50-188	16
DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1	50-315	85	REACTOR KEWAUNEE NUCLEAR POWER PLANT	50-305	77
DONALD C. COOK NUCLEAR POWER	50-316	86	LA CROSSE BOILING WATER REACTOR	50-409	156
L CO.	50-264	42	LASALLE COUNTY STATION, UNIT 1	50-373	142
LEAR POWER STATION,	50-10	7	LASALLE COUNTY STATION, UNIT 2	50-374	143
WALL OF STATION	33-10	•	LIMERICK GENERATING STATION, UNIT 1	50-352	126
EAR POWER STATION,	50-237	23	LIMERICK GENERATING STATION, UNIT 2	50-353	. 128
WOULEAR POWER STATION,	50-249	28	MAINE YANKEE ATOMIC POWER PLANT	50-309	, 80
incomment officer officers	20.240	23	MALIBU POWER REACTOR	50-214	19

Name	Docket	Page	Name	Docket	Page
MANHATTAN COLLEGE RESEARCH	50-199	16	PERRY NUCLEAR POWER PLANT, UNIT 1	50-440	173
REACTOR MASSACHUSETTS INSTITUTE OF	50.00	٥	PERRY NUCLEAR POWER PLANT, UNIT 2	50-441	174
TECHNOLOGY RESEARCH REACTOR	50-20	8	PILGRIM NUCLEAR POWER STATION, UNIT	50-293	66
MEMPHIS STATE UNIV. RESEARCH REACTOR	50-538	208	PLUM BROOK REACTOR - MOCK-UP	50-185	16
MICHIGAN STATE UNIV. RESEARCH REACTOR	50-294	68	PLUM BROOK RESEARCH REACTOR FACILITY	50-30	9
MIDLAND PLANT, UNIT 1	50-329	109	POINT BEACH NUCLEAR PLANT, UNIT 1	50-266	43
MIDLAND PLANT, UNIT 2	50-330	109	POINT BEACH NUCLEAR PLANT, UNIT 2	50-301	73
MILLSTONE NUCLEAR POWER STATION, UNIT 1	50-245	25	PRAIRIE ISLAND NUCLEAR STATION, UNIT	50-282	60
MILLSTONE NUCLEAR POWER STATION, UNIT 2	50-336	113	PRAIRIE ISLAND NUCLEAR STATION, UNIT 2	50-306	79
MILLSTONE NUCLEAR POWER STATION,	50-423	166	PURDUE UNIV. RESEARCH REACTOR	50-182	15
UNIT 3	50 00B	40	QUAD-CITIES STATION, UNIT 1	50-254	34
MONTICELLO NUCLEAR GENERATING PLANT	50-263	42	QUAD-CITIES STATION, UNIT 2	50-265	42
NATIONAL BUREAU OF STANDARDS REACTOR	50-184	15	RANCHO SECO NUCLEAR GENERATING STATION	50-312	82
NINE MILE POINT NUCLEAR STATION, UNIT	50-220	21	REED COLLEGE RESEARCH REACTOR	50-288	64
1	-0.440	4.09	RESAR SP/90	50-601	208
NINE MILE POINT NUCLEAR STATION, UNIT 2	50-410	157	RHODE ISLAND & PROVIDENCE PLANTATIONS AEC	50-193	16
NORTH ANNA POWER STATION, UNIT 1	50-338	115	RIVER BEND STATION, UNIT 1	50-458	193
NORTH ANNA POWER STATION, UNIT 2 NORTH CAROLINA STATE UNIV. PULSTAR	50-339 50 -2 97	117 71	ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1	50-244	24
REACTOR	E0 07E	444	RPI CRITICAL EXPERIMENT	50-225	23
NUCLEAR EXAMINATION REACTOR	50-375	144 24	SALEM NUCLEAR GENERATING STATION,	50-272	50
NUCLEAR SHIP SAVANNAH NUCLEAR SHIP SAVANNAH	50-238 50-314	24 85	UNIT 1		_
OCONEE NUCLEAR STATION, UNIT 1	50-314	46	SALEM NUCLEAR GENERATING STATION, UNIT 2	60-311	81
OCONEE NUCLEAR STATION, UNIT 2	50-270	48	SAN ONOFRE NUCLEAR STATION, UNIT 1	50-206	16
OCONEE NUCLEAR STATION, UNIT 2	50-270	46 63	SAN ONOFRE NUCLEAR STATION, UNIT 2	50-361	131
OHIO STATE UNIV. RESEARCH REACTOR	50-267	13	SAN ONOFRE NUCLEAR STATION, UNIT 3	50-362	133
OMAHA VETERANS ADMINISTRATION HOSPITAL RESEARCH REACTOR	50-131	12	SAXTON NUCLEAR EXPERIMENTAL FACILITY	50-146	13
OREGON STATE UNIV. RESEARCH	50-243	24	SEABROOK NUCLEAR STATION, UNIT 1	50-443	176
REACTOR			SEABROOK NUCLEAR STATION, UNIT 2	50-444	178
OYSTER CREEK NUCLEAR POWER PLANT	50-219	19	SEQUOYAH NUCLEAR PLANT, UNIT 1	50-327	101
PALISADES NUCLEAR PLANT	50-255	35	SEQUOYAH NUCLEAR PLANT, UNIT 2	60-328	105
	TN-50-528	203	SHEARON HARRIS NUCLEAR POWER	50-400	155
PALO VERDE NUCLEAR STATION, UNIT 2 ST		205	PLANT, UNIT 1		
PALO VERDE NUCLEAR STATION, UNIT 3 ST		207	SHOREHAM NUCLEAR POWER STATION	50-322	93
PEACH BOTTOM ATOMIC POWER STATION, UNIT 1	50-171	15	SOUTH TEXAS PROJECT, UNIT 1	STN-60-498	199
PEACH BOTTOM ATOMIC POWER STATION,	50-277	52	SOUTH TEXAS PROJECT, UNIT 2	STN-50-499	201
UNIT 2		•	ST. LUCIE PLANT, UNIT 1	50-335	112
PEACH BOTTOM ATOMIC POWER STATION, UNIT 3	50-278	54	ST. LUCIE PLANT, UNIT 2	50-389	148
PENNSYLVANIA STATE UNIV. RESEARCH REACTOR	50-5	7	SURRY POWER STATION, UNIT 1 SURRY POWER STATION, UNIT 2	50-280 50-281	56 58

STATION, UNIT 2			TRAINING REACTOR	
TEXAS A&M UNIV. RESEARCH REACTOR	50-128	12	WASHINGTON STATE UNIV. RESEARCH	50-27
TEXAS A&M UNIV, RESEARCH REACTOR	50-59	10	REACTOR (TRIGA) WATERFORD GENERATING STATION, UNIT	50-382
THREE MILE ISLAND NUCLEAR STATION, UNIT 1	50-289	64	3	50-362
THREE MILE ISLAND NUCLEAR STATION.	50-320	90	WATTS BAR NUCLEAR PLANT, UNIT 1	50-390
UNIT 2	30.320	ρU	WATTS BAR NUCLEAR PLANT, UNIT 2	50-391
TROJAN NUCLEAR PLANT	50-344	122	WESTINGHOUSE CRITICAL EXPERIMENT	50-87
TURKEY POINT PLANT, UNIT 3	50-250	29	WESTINGHOUSE TEST REACTOR	50-22
TURKEY POINT PLANT, UNIT 4	50-251	31	WILLIAM B. MCGUIRE NUCLEAR STATION,	60-369
U.S. GEOLOGICAL SURVEY RESEARCH REACTOR	50-274	51	UNIT 1 WILLIAM B. MCGUIRE NUCLEAR STATION,	50-370
UCLA TRAINING REACTOR	50-142	13	UNIT 2	50.050
UNIV. OF ARIZONA RESEARCH REACTOR	50-113	11	WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1	50-358
UNIV. OF CALIFORNIA AT IRVINE RESEARCH REACTOR	50-326	101	,	N-50-482
UNIV. OF CALIFORNIA AT SANTA BARBARA RESEARCH REACTOR	50-433	171	WORCESTER POLYTECHNIC INSTITUTE RESEARCH REACTOR	50-134
UNIV. OF CALIFORNIA RESEARCH	50-224	22	WPPSS NUCLEAR PROJECT, UNIT 1	50-460
REACTOR			WPPSS NUCLEAR PROJECT, UNIT 2	50-397
UNIV. OF FLORIDA TRAINING REACTOR	50-83	10	**************************************	N-50-508
UNIV. OF ILLINOIS RESEARCH REACTOR	50-151	13	YANKEE-ROWE NUCLEAR POWER STATION	50-29
UNIV. OF ILLINOIS RESEARCH REACTOR	50-356	131	ZION NUCLEAR POWER STATION, UNIT 1	50-295
UNIV. OF KANSAS RESEARCH REACTOR	50-148	13	ZION NUCLEAR POWER STATION, UNIT 2	50-304
UNIV. OF LOWELL RESEARCH REACTOR	50-223	22	Domestic Licensing of Special Nuclear	
UNIV. OF MARYLAND RESEARCH REACTOR	50-166	15	Material - Docket 70	
UNIV. OF MISSOURI RESEARCH REACTOR- COLUMBIA	50-186	16	ADVANCED NUCLEAR FUELS CORP., RICHLAND, WA	70-1257
UNIV. OF MISSOURI RESEARCH REACTOR- ROLLA	50-123	12	BABCOCK & WILCOX CO., APOLLO, PA	70-0364
UNIV. OF NEW MEXICO RESEARCH	50-252	34	BABCOCK & WILCOX CO., APOLLO, PA	70-0135
REACTOR		•	BABCOCK & WILCOX CO., LYNCHBURG, VA	70-0824
UNIV. OF OKLAHOMA RESEARCH REACTOR	50-112	11	BABCOCK & WILCOX CO., LYNCHBURG, VA	70-0027
UNIV. OF TEXAS RESEARCH REACTOR	60-602	209	BABCOCK & WILCOX CO., LYNCHBURG, VA	70-1201
UNIV. OF TEXAS RESEARCH REACTOR	50-192	16	BATTELLE MEMORIAL INSTITUTE, COLUMBUS, OH	70-0008
UNIV. OF UTAH RESEARCH REACTOR	50-407	156	CINTICHEM, INC., TUXEDO, NY	70-0687
UNIV. OF UTAH RESEARCH REACTOR	50-72	10	COMBUSTION ENGINEERING, INC.,	70-1100
UNIV. OF VIRGINIA CAVALIER REACTOR	50-396	153	WINDSOR, CT	
UNIV. OF VIRGINIA RESEARCH REACTOR	50-62	10	COMBUSTION ENGINEERING, INC., WINDSOR, CT	70-0036
UNIV. OF WASHINGTON RESEARCH REACTOR	50-139	13	FLORIDA, UNIV. OF. GAINESVILLE, FL	70-1068
UNIV. OF WISCONSIN RESEARCH	50-156	14	GA TECHNOLOGIES, INC., SAN DIEGO, CA	70-0734
REACTOR			GENERAL ELECTRIC CO., PLEASANTON, CA	70-0754
VALLECITOS EXPERIMENTAL SUPERHEAT REACTOR	50-183	15	GENERAL ELECTRIC CO., SAN JOSE, CA	70-1308
VERMONT YANKEE NUCLEAR POWER	50-271	49	GENERAL ELECTRIC CO., WILMINGTON, NC	70-1113
STATION			IRT CORP., SAN DIEGO, CA	70-1359

1

xviii

MESTINGHOUSE NUCLEAR CORP. 07-0805 211 MODEL: IN-1902, WESTINGHOUSE 17-922 216 MITCHAN NUCLEAR (INC. 17-922 216 MIT	Name	Docket	Page	Name	Docket	Page
HTTMAN NUCLEAR, INC. TPACE		70-0925	211		71-9224	216
TEXAS UTILITIES GENERATING CO., 70-9932 212 WESTINGHOUSE HITMAN NUCLEAR CO. 71-9030 214 PACKAGING, INC., AIKEN, SC 70-3051 212 WODEL: IR-300, GENERAL ELECTRIC CO. 71-9031 214 MODEL: IR-300, GENERAL ELECTRIC CO. 71-9157 215 MODEL: IR-300, INDUSTRIAL NUCLEAR CO. 71-9157 215 MODEL: IR-300, INDUSTRIAL NUCLEAR CO. 71-9157 215 MODEL: IR-300, INDUSTRIAL NUCLEAR CO. 71-9156 215 WESTINGHOUSE ELECTRIC CORP., COLUMBIA, SC 71-9157 215 MODEL: IR-30, INDUSTRIAL NUCLEAR CO. 71-9156 215 WESTINGHOUSE ELECTRIC CORP., COLUMBIA, SC 71-9059 213 MODEL: IR-30, INDUSTRIAL NUCLEAR CO. 71-9159 215 MODEL: IR-30, INDUSTRIAL NUCLEAR CORP. 71-9102 215 MODEL: IR-30,	NUCLEAR FUEL SERVICES, INC., ERWIN, TN	70-0143	210	MODEL: HN-215H, WESTINGHOUSE	71-9222	216
DALLAS, TWO SEPRIAL RING O. 70-9301 212 MODEL: IR-100, INDUSTRIAL NUCLEAR CO. 71-9101 214	SEATTLE UNIV., SEATTLE, WA	70-0600	211			
DINC NAVAL PROPOLUTS, INC., UNCASVILLE, CT		70-2932	212		71-9080	214
WESTINGHOUSE ELECTRIC CORP., COLUMBIA, SC CORP., COLUMBIA, SC CORP., COLUMBIA, SC COLUMBIA, SC CORP., COLUMBIA, SC COLUM	TRANSNUCLEAR, INC., AIKEN, SC	70-3051	212	MODEL: IF-300, GENERAL ELECTRIC CO.	71-9001	214
WESTINGHOUSE ELECTRIC CORP. 70-1151 212 MODEL: NAC-1, NUCLEAR ASSURANCE 71-9193 215 216 CORP.	UNC NAVAL PRODUCTS, INC., UNCASVILLE,	70-0371	211	MODEL: IR-100, INDUSTRIAL NUCLEAR CO.	71-9157	215
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions - Docket 71 9010 214 900 215 916 917 918				MODEL: IR-50, INDUSTRIAL NUCLEAR CO.	71-9156	215
SERVICES, INC. SERVICES, INC. MODEL: NLI-1/2, NUCLEAR ASSURANCE 71-9010 214	WESTINGHOUSE ELECTRIC CORP., COLUMBIA, SC	70-1151	212		71-9183	215
BRAN-SHON, INC. 71-0653 213 MODEL: NP;20VG-8, NEUTRON 71-9102 215 71-0404 213 MODEL: NP;20VG-8, NEUTRON 71-9102 215 71-0404 213 MODEL: NP;20VG-8, NEUTRON 71-9102 215 71-0404 213 MODEL: NP;20VG-8, NEUTRON 71-9208 215 MODEL: NP;20VG-8, NEUTRON 71-9208 216 MODEL: NP;20VG-8, NEUTRON	Transport and Transportation of				71-9193	215
CTI, INC. E.I. DU PONT DE NEMOURS & CO., INC. FRIEDRUCTS, INC. MODEL: NUPAC 10-142, NUCLEAR PACKAGING, INC. MODEL: NUPAC 10-142, NUCLEAR PACKAGING, INC. MODEL: NUPAC 14/210L & 14/210H, T1-9176 215 MODEL: NUPAC 14/210L & 14/210H, T1-9176 215 MODEL: NUPAC 14/210L & 14/210H, T1-9176 216 MODEL: NUPAC 14/210L & 14/210H, T1-9176 217 MODEL: NUPAC 14/210L & 14/210H, T1-9176 MODEL: NUPAC 14/210L & 14/210H, T1-9176 MODEL: NUPAC 14/210H, MODEL: NUPAC 14/210H, T1-9176 MODEL: NUPAC 14/210H, MODEL: NUPAC 14/21	Conditions - Docket 71				71-9010	214
EI, DU PONT DE NEMOURS & CO., INC. 71-0409 213 MODEL: NUPAC 10-142, NUCLEAR PACKAGING, INC. 71-0498 213 MODEL: NUPAC 14/2/10L & 14/2/10H, 71-9176 215 MODEL: NUPAC 14/2/10L & 14/2/10H, 71-9176 216 MODEL: NUPAC 14/2/10L & 14/2/10H, 71-9176 217 MODEL: ALIAN NUCLEAR MODEL: ALIAN NUCL	•	71-0653	213		71-9102	215
PACKAGING, INC. GEARHART-OWEN INDUSTRIES 71-0498 213 MODEL: NUPAC 14/2101 & 14/2101, NUCLEAR PACKAGING, INC. NODEL: AB, INC. NODEL: AB, INC. NODEL: 20, 20A, 50, 50A, GAMMA NODET: 30CA, 50, 50A, GAMMA NODET: 30CA, 50, 50A, GAMMA NODEL: 20, 00A, 50, 50A, GAMMA NODEL: 200, GENERAL ELECTRIC CO. NODEL: 30CA, 50A, 50A, GAMMA NODEL: 30CA, 50A, 50A, 60A, 60A, 60A NODEL: 30CA, 50A, 50A, 60A, 60A, 60A NODEL: 30CA, 50A, 50A, 60A NODEL: 30CA, 50A, 50A NODEL: 30CA, 50A NODEL: 30CA, 50A NODEL: 30CA, 50A NODEL: 30CA, 50A		71-0404	213	•	74 0200	215
H&H X-RAY SERVICES, INC. 71-0423 213 NUCLEAR PACKAGING, INC. 71-0490 213 NUCLEAR PACKAGING, INC. 71-0490 213 NUCLEAR PACKAGING, INC. 71-0490 213 HODGE: NUPAC 14D-2.0, WESTINGHOUSE 71-0079 214 HAS, INC. 71-0448 213 ELECTRIC CO. 71-0598 214 ELECTRIC CO. 71-0598 215 MODEL: RA-2, RA-3, RA-J, GENERAL 71-4986 214 ELECTRIC CO. 71-0448 213 ELECTRIC CO. 71-0448 213 ELECTRIC CORP. 71-0448 213 ELECTRIC CORP. 71-0448 213 ELECTRIC CORP. 71-0450 214 MODEL: 20, 30A, 50, 50A, GAMMA 71-9167 215 MODEL: 32068, 32278 & 3218, AMERSHAM 71-9167 215 MODEL: S-8/23, STUDSVIK ENERGITEKNIK 71-3001 214 AB EQUIPMENT CO. MODEL: 500, TECH/OPS, INC. 71-9032 214 MODEL: S-8/23, STUDSVIK ENERGITEKNIK 71-3001 214 MODEL: 60, TECH/OPS, INC. 71-9032 214 MODEL: TN-1, TRANSNUKLEAR GMBH 71-3003 214 MODEL: 72-B, NUCLEAR PACKAGING, INC. 71-9147 216 MODEL: 650, TECH/OPS, INC. 71-9147 216 MODEL: 850, TECH/OPS, INC. 71-9147 216 MODEL: 850, TECH/OPS, INC. 71-9147 216 MODEL: 850, TECH/OPS, INC. 71-906 214 MODEL: TN-3, SL, TRANSNUCLEAR, INC. 71-9213 216 MODEL: A1 500 SU, TECH/OPS, INC. 71-906 214 MODEL: A1 500 SU, TECH/OPS, INC. 71-9036 214 MODEL: C-1, SOURCE PRODUCTION & 71-9036 214 MODEL: TN-3EM, INC. 71-903	E.I. DU PONT DE NEMOURS & CO., INC.	71-0500	213		71-9200	210
INSPECTION SERVICES CORP.	GEARHART-OWEN INDUSTRIES	71-0498	213		71-9176	215
KANSAS GAS & ELECTRIC CO. MET LAB, INC. 71-0598 MET LAB, INC. 71-0448 MODEL: 20. 20A, 50, 50A, GAMMA INDUSTRIES, INC. MODEL: 20. 20A, 50, 50A, GAMMA INDUSTRIES, INC. MODEL: 20. GENERAL ELECTRIC CO. 71-6971 MODEL: 3206B, 3227B & 321B, AMERSHAM CORP. MODEL: 520, TECH/OPS, INC. 71-9032 MODEL: 650, TECH/OPS, INC. MODEL: 6717-B, GAMMA INDUSTRIES, INC. MODEL: 6717-B, GAMMA INDUSTRIES, INC. MODEL: 850, TECH/OPS, INC. MODEL: 850, TECH/OPS, INC. MODEL: 927A1 & 927C1, COMBUSTION ENGINEERING, INC. MODEL: -1, SOURCE PRODUCTION & 71-9036 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9135 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9152 215 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9152 216 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9036 217 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9152 218 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9152 219 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9152 215 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9152 216 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9152 217 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9152 218 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9152 219 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9152 210 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9152 211 MODEL: C-10, GAMMA INDUSTRIES, INC. MODEL: G-10, GAMMA INDUS	H&H X-RAY SERVICES, INC.	71-0423	213	·		
MET LAB, INC. 71-0448 213 ELECTRIC CO. 71-0468 214 ELECTRIC CO. 71-0468 215 ELECTRIC CO. 71-0468 215 MODEL: 20, 20A, 50, 50A, GAMMA 71-9126 215 MODEL: 20, 20A, 50, 50A, GAMMA 71-9126 215 MODEL: 20, 20A, 50, 50A, GAMMA 71-9126 215 MODEL: 20, 20B, GENERAL ELECTRIC CO. 71-5971 214 MODEL: 32068, 32278 & 3218, AMERSHAM 71-9167 215 MODEL: 520, TECH/OPS, INC. 71-9067 214 MODEL: 520, TECH/OPS, INC. 71-9032 214 MODEL: 650, TECH/OPS, INC. 71-9032 214 MODEL: 650, TECH/OPS, INC. 71-9032 214 MODEL: 72-B, NUCLEAR PACKAGING, INC. 71-9212 216 MODEL: 78-B, NUCLEAR PACKAGING, INC. 71-9212 216 MODEL: 850, TECH/OPS, INC. 71-9147 215 MODEL: 850, TECH/OPS, INC. 71-9041 216 MODEL: 17-19-19-19-19-19-19-19-19-19-19-19-19-19-		71-0490	213		71-9079	214
MODEL: 20, 20A, 50, 50A, GAMMA 71-9126 215 MODEL: RCC, -1, -2, -3, -4, WESTINGHOUSE 71-5450 214 MODEL: 200, GENERAL ELECTRIC CO. 71-5971 214 MODEL: SP./23, STUDSVIK ENERGITEKNIK 71-3001 214 MODEL: 3206B, 32278 & 3218, AMERSHAM CORP. 71-9167 215 MODEL: SP./23, STUDSVIK ENERGITEKNIK 71-3001 214 MODEL: 3206B, 32278 & 3218, AMERSHAM CORP. 71-9167 215 MODEL: SP./23, STUDSVIK ENERGITEKNIK 71-3001 214 MODEL: 3206B, 32278 & 3218, AMERSHAM CORP. 71-9167 215 MODEL: SP./23, STUDSVIK ENERGITEKNIK 71-3001 214 MODEL: 520, TECH/OPS, INC. 71-9007 214 MODEL: TO1, TANASHUKLEAR GMBH 71-3003 214 MODEL: 650, TECH/OPS, INC. 71-9117 216 MODEL: TN-BRP, TRANSHUCLEAR, INC. 71-9202 215 MODEL: 850, TECH/OPS, INC. 71-9147 215 MODEL: TN-BRP, TRANSHUCLEAR, INC. 71-9202 216 MODEL: 850, TECH/OPS, INC. 71-9018 214 MODEL: TN-BRP, TRANSHUCLEAR, INC. 71-9212 216 MODEL: 850, TECH/OPS, INC. 71-9018 214 MODE		71-0598	213	MODEL: RA-2, RA-3, RA-J, GENERAL	71-4986	214
INDUSTRIES, INC.		71-0448	213			
AB		71-9126	215		71-5450	214
MODEL: 32068, 32278 & 3218, AMERSHAM CORP. 71-9167 CORP. 215 MODEL: 520, TECH/OPS, INC. MODEL: 650, TECH/OPS, INC. 71-9007 214 A EQUIPMENT CO. MODEL: 650, TECH/OPS, INC. 71-9032 214 MODEL: TN-1, TRANSNUKLEAR GMBH 71-3003 214 MODEL: TN-8, -8L, TRANSNUCLEAR, INC. 71-9015 214 MODEL: TN-8, -8L, TRANSNUCLEAR, INC. 71-9015 214 MODEL: TN-8, -8L, TRANSNUCLEAR, INC. 71-9015 214 MODEL: TN-8RP, TRANSNUCLEAR, INC. 71-9015 214 MODEL: TN-8RP, TRANSNUCLEAR, INC. 71-9020 215 MODEL: TN-8RP, TRANSNUCLEAR, INC. 71-9212 216 MODEL: TN-8RP, TRANSNUCLEAR, INC. 71-9213 216 MODEL: TN-8RP, TRANSNUCLEAR, INC. 71-9218 216 MODEL: TN-8RP, TRANSNUCLEAR, INC. 71-9218 216 MODEL: TN-8RP, TRANSNUCLEAR, INC. 71-9218 216 MODEL: TN-8RP, TRANSNUCLEAR, INC	MODEL: 200, GENERAL ELECTRIC CO.	71-5971	214		71-3001	214
MODEL: 520, TECH/OPS, INC. 71-9007 214 MODEL: 650, TECH/OPS, INC. 71-9032 214 MODEL: 650, TECH/OPS, INC. 71-9032 214 MODEL: 650, TECH/OPS, INC. 71-9032 214 MODEL: 6717-8, GAMMA INDUSTRIES, INC. 71-9032 214 MODEL: TN-8, -9L, TRANSNUCLEAR, INC. 71-9015 214 MODEL: 72-8, NUCLEAR PACKAGING, INC. 71-9147 215 MODEL: TN-BRP, TRANSNUCLEAR, INC. 71-9202 215 MODEL: 950, TECH/OPS, INC. 71-9147 215 MODEL: TN-BRP, TRANSNUCLEAR, INC. 71-9212 216 MODEL: 927A1 & 927C1, COMBUSTION ENGINEERING, INC. 71-9068 214 POWER AUTHORITY OF STATE OF NEW YORK 71-9218 216 MODEL: AI 500 SU, TECH/OPS, INC. 71-9036 214 POWER AUTHORITY OF STATE OF NEW YORK 71-0240 213 MODEL: C1, SOURCE PRODUCTION & T1-9036 214 POWER INSPECTION, INC. 71-0654 213 MODEL: C2-10, GAMMA INDUSTRIES, INC. 71-9133 215 RADIATION TECHNOLOGY, INC. 71-0654 213 MODEL: CNS 1-13G II, CHEM-NUCLEAR SYSTEMS, INC. 71-9152 215 TEXAS NUCLEAR CORP. 71-0641 213		71-9167	215	MODEL: SPEC 2-T, SOURCE PRODUCTION	71-9056	214
MODEL: 650, 1ECH/OPS, INC. 71-9032 214 MODEL: TN-8, -8L, TRANSNUCLEAR, INC. 71-9015 214 MODEL: 72-B, NUCLEAR PACKAGING, INC. 71-9212 216 MODEL: TN-BRP, TRANSNUCLEAR, INC. 71-9202 215 MODEL: 850, TECH/OPS, INC. 71-9147 215 MODEL: TN-BRP, TRANSNUCLEAR, INC. 71-9213 216 MODEL: 927A1 & 927C1, COMBUSTION ENGINEERING, INC. 71-9078 214 MODEL: TRUPACT-II, ENERGY, DEPT. OF 71-9218 216 MODEL: AI 500 SU, TECH/OPS, INC. 71-9006 214 POWER AUTHORITY OF STATE OF NEW YORK 71-0202 213 MODEL: C-1, SOURCE PRODUCTION & EQUIPMENT CO., INC. 71-9036 214 POWER INSPECTION, INC. 71-0654 213 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9133 215 RADIATION TECHNOLOGY, INC. 71-0420 213 MODEL: CNS 1-13C, II, CHEM-NUCLEAR SYSTEMS, INC. 71-9152 215 TEXAS NUCLEAR CORP. 71-0545 213 MODEL: CNS 1-13G, CHEM-NUCLEAR SYSTEMS, INC. 71-9168 216 WESTINGHOUSE ELECTRIC CORP. 71-0661 213 MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC. 71-9957 <	• • • • • • • • • • • • • • • • • • • •	71-9007	214		71-3003	214
MODEL: 671-8, GAMMA INDUSTRIES, INC. 71-6717 214 MODEL: TN-BRP, TRANSNUCLEAR, INC. 71-9202 215 MODEL: 850, TECH/OPS, INC. 71-9147 215 MODEL: TN-GEMINI, TRANSNUCLEAR 71-9213 216 MODEL: 927A1 & 927C1, COMBUSTION ENGINEERING, INC. 71-9068 214 MODEL: TRUPACT-II, ENERGY, DEPT. OF 71-9218 216 MODEL: C-1, SOURCE PRODUCTION & EQUIPMENT CO., INC. 71-9036 214 POWER AUTHORITY OF STATE OF NEW YORK 71-0542 213 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9133 215 RADIATION TECHNOLOGY, INC. 71-0654 213 MODEL: CNS 1-13G, II, CHEM-NUCLEAR SYSTEMS, INC. 71-9152 215 TEXAS NUCLEAR CORP. 71-0652 213 MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC. 71-9168 216 WESTINGHOUSE ELECTRIC CORP. 71-0661 213 MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC. 71-9168 216 WESTINGHOUSE ELECTRIC CORP. 71-0661 213 MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC. 71-9168 216 WESTINGHOUSE ELECTRIC CORP. 71-0661 213 MODEL: FPD-100, GA TECHNOLOGIES, INC. 71-9	•	71-9032	214	·		
MODEL: 72-B, NUCLEAR PACKAGING, INC. 71-9212 216 MODEL: 850, TECH/OPS, INC. 71-9147 215 MODEL: TRUPACT-II, ENERGY, DEPT. OF 71-9213 216 MODEL: 927A1 & 927C1, COMBUSTION ENGINEERING, INC. 71-9008 214 MODEL: TRUPACT-II, ENERGY, DEPT. OF 71-9218 216 MODEL: AI 500 SU, TECH/OPS, INC. 71-9006 214 POWER AUTHORITY OF STATE OF NEW YORK 71-0240 213 MODEL: C-1, SOURCE PRODUCTION & EQUIPMENT CO., INC. 71-9036 214 POWER INSPECTION, INC. 71-0654 213 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9133 215 RADIATION TECHNOLOGY, INC. 71-0420 213 MODEL: CENTURY S & SA, GAMMA INDUSTRIES, INC. 71-9135 215 SAMSON INSPECTION & TECHNICAL SERVICES, INC. 71-0652 213 MODEL: CNS 1-13G II, CHEM-NUCLEAR SYSTEMS, INC. 71-9152 215 TEXAS NUCLEAR CORP. 71-0545 213 MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC. 71-9168 216 WESTINGHOUSE ELECTRIC CORP. 71-0661 213 MODEL: FPD-100, GA TECHNOLOGIES, INC. 71-9057 214 Licensing of Independent Spent Fuel Storage - Docket		71-6717	214	•		
MODEL: 950, 1ECH/OPS, INC. 71-9147 215 MODEL: 927A1 & 927C1, COMBUSTION ENGINC. 71-8078 214 MODEL: TRUPACT-II, ENERGY, DEPT. OF PACIFIC GAS & ELECTRIC CO. 71-9218 216 MODEL: AI 500 SU, TECH/OPS, INC. 71-9006 214 POWER AUTHORITY OF STATE OF NEW YORK 71-0240 213 MODEL: C-1, SOURCE PRODUCTION & EQUIPMENT CO., INC. 71-9036 214 POWER INSPECTION, INC. 71-0654 213 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9133 215 RADIATION TECHNOLOGY, INC. 71-0420 213 MODEL: CENTURY S & SA, GAMMA INDUSTRIES, INC. 71-9135 215 SAMSON INSPECTION & TECHNICAL SERVICES, INC. 71-0652 213 MODEL: CNS 1-13C II, CHEM-NUCLEAR SYSTEMS, INC. 71-9152 215 TEXAS NUCLEAR CORP. 71-0545 213 MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC. 71-9216 216 WESTINGHOUSE ELECTRIC CORP. 71-0661 213 MODEL: FPD-100, GA TECHNOLOGIES, INC. 71-9057 214 Licensing of Independent Spent Fuel Storage - Docket 72 Licensing of Independent Spent Fuel Storage - Docket 72 MODEL: HN.100 SERIES 3, 71-9151 215 C	MODEL: 72-B, NUCLEAR PACKAGING, INC.	71-9212	216	•		
MODEL: AI 500 SU, TECH/OPS, INC. 71-9006 214 POWER AUTHORITY OF STATE OF NEW YORK POWER INSPECTION, INC. 71-0240 213 MODEL: C-1, SOURCE PRODUCTION & 71-9036 214 POWER INSPECTION, INC. 71-0654 213 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9133 215 RADIATION TECHNOLOGY, INC. 71-0420 213 MODEL: CENTURY S & SA, GAMMA 71-9135 215 SAMSON INSPECTION & TECHNICAL SERVICES, INC. 71-0652 213 INDUSTRIES, INC. 71-9152 215 TEXAS NUCLEAR CORP. 71-0545 213 SYSTEMS, INC. 71-9216 216 UNITED STATES TESTING CO., INC. 71-0641 213 MODEL: CNS 1-13G, CHEM-NUCLEAR 71-9162 216 UNIV. OF VIRGINIA 71-0460 213 MODEL: CNS 8-120B, CHEM-NUCLEAR 71-9168 216 WESTINGHOUSE ELECTRIC CORP. 71-0651 213 SYSTEMS, INC. 71-9057 214 Licensing of Independent Spent Fuel Storage - Docket 72 MODEL: HN-100 SERIES 3. 71-9151 215 CAROLINA POWER & LIGHT CO. 72-0003 216	· ·			•		
MODEL: AI 500 SU, TECH/OPS, INC. 71-9006 214 POWER AUTHORITY OF STATE OF NEW YORK 71-0240 213 MODEL: C-1, SOURCE PRODUCTION & EQUIPMENT CO., INC. 71-9036 214 POWER INSPECTION, INC. 71-0654 213 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9133 215 RADIATION TECHNOLOGY, INC. 71-0420 213 MODEL: CENTURY S & SA, GAMMA INDUSTRIES, INC. 71-9135 215 SAMSON INSPECTION & TECHNICAL SERVICES, INC. 71-0652 213 MODEL: CNS 1-13G II, CHEM-NUCLEAR SYSTEMS, INC. 71-9152 215 TEXAS NUCLEAR CORP. 71-0545 213 MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC. 71-9216 216 UNITED STATES TESTING CO., INC. 71-0460 213 MODEL: FPD-100, GA TECHNOLOGIES, INC. 71-9168 216 WESTINGHOUSE ELECTRIC CORP. 71-0651 213 MODEL: FPD-100, GENERAL ELECTRIC CO. 71-5926 214 Licensing of Independent Spent Fuel Storage - Docket 72 MODEL: HN-100 SERIES 3, 71-9151 215 CAROLINA POWER & LIGHT CO. 72-0003 216	MODEL: 927A1 & 927C1, COMBUSTION ENGINEERING, INC.	71-6078	214			
MODEL: C-1, SOURCE PRODUCTION & EQUIPMENT CO., INC. 71-9036 214 YORK MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9133 215 RADIATION TECHNOLOGY, INC. 71-0420 213 MODEL: CENTURY S & SA, GAMMA INDUSTRIES, INC. 71-9135 215 SAMSON INSPECTION & TECHNICAL SERVICES, INC. 71-0652 213 MODEL: CNS 1-13C II, CHEM-NUCLEAR SYSTEMS, INC. 71-9152 215 TEXAS NUCLEAR CORP. 71-0545 213 MODEL: CNS 1-13G, CHEM-NUCLEAR SYSTEMS, INC. 71-9216 216 UNITED STATES TESTING CO., INC. 71-0641 213 MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC. 71-9168 215 WESTINGHOUSE ELECTRIC CORP. 71-0651 213 MODEL: FPD-100, GA TECHNOLOGIES, INC. 71-9057 214 Licensing of Independent Spent Fuel Storage - Docket 72 MODEL: HN-100 SERIES 3, 71-9151 215 CAROLINA POWER & LIGHT CO. 72-0003 216		71-9006	214			
## EQUIPMENT CO., INC. POWER INSPECTION, INC. 71-0654 213 MODEL: C-10, GAMMA INDUSTRIES, INC. 71-9133 215 RADIATION TECHNOLOGY, INC. 71-0420 213 MODEL: CENTURY S & SA, GAMMA 71-9135 215 SAMSON INSPECTION & TECHNICAL 71-0652 213 INDUSTRIES, INC. SERVICES, INC. TEXAS NUCLEAR CORP. 71-0545 213 SYSTEMS, INC. UNITED STATES TESTING CO., INC. 71-0641 213 MODEL: CNS 1-13G, CHEM-NUCLEAR 71-9168 216 UNIV. OF VIRGINIA 71-0460 213 MODEL: CNS 8-120B, CHEM-NUCLEAR 71-9168 216 WESTINGHOUSE ELECTRIC CORP. 71-0651 213 SYSTEMS, INC. UNIV. OF VIRGINIA 71-0460 213 MODEL: FPD-100, GA TECHNOLOGIES, INC. 71-9057 214 Licensing of Independent Spent Fuel Storage - Docket 72 MODEL: HN-100 SERIES 3, 71-9151 215 CAROLINA POWER & LIGHT CO. 72-0003 216 **CAROLINA POWER & LIGHT CO. 72-0003 216 **	•					
MODEL: CENTURY S & SA, GAMMA INDUSTRIES, INC. 71-9135 215 SAMSON INSPECTION & TECHNICAL SERVICES, INC. 71-0652 213 MODEL: CNS 1-13C II, CHEM-NUCLEAR SYSTEMS, INC. 71-9152 215 TEXAS NUCLEAR CORP. 71-0545 213 MODEL: CNS 1-13G, CHEM-NUCLEAR SYSTEMS, INC. 71-9216 216 UNIV. OF VIRGINIA 71-0460 213 MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC. 71-9168 216 WESTINGHOUSE ELECTRIC CORP. 71-0851 213 MODEL: FPD-100, GA TECHNOLOGIES, INC. 71-9057 214 Licensing of Independent Spent Fuel Storage - Docket 72 MODEL: HN-100 SERIES 3, 71-9151 215 CAROLINA POWER & LIGHT CO. 72-0003 216	EQUIPMENT CO., INC.			POWER INSPECTION, INC.	71-0654	213
INDUSTRIES, INC. SERVICES, INC. SERVICES, INC.		71-9133	215	RADIATION TECHNOLOGY, INC.	71-0420	213
SYSTEMS, INC. UNITED STATES TESTING CO., INC. 71-0641 213 MODEL: CNS 1-13G, CHEM-NUCLEAR SYSTEMS, INC. 71-9168 216 UNIV. OF VIRGINIA 71-0460 213 MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC. 71-9168 215 WESTINGHOUSE ELECTRIC CORP. 71-0651 213 MODEL: FPD-100, GA TECHNOLOGIES, INC. 71-9057 214 Licensing of Independent Spent Fuel Storage - Docket 72 MODEL: GE-100, GENERAL ELECTRIC CO. 71-5926 214 MODEL: HN-100 SERIES 3, 71-9151 215	INDUSTRIES, INC.	71-9135	215		71-0652	213
MODEL: CNS 1-13G, CHEM-NUCLEAR SYSTEMS, INC. 71-9216 216 UNITED STATES TESTING CO., INC. 71-0641 213 MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC. 71-9168 215 WESTINGHOUSE ELECTRIC CORP. 71-0651 213 MODEL: FPD-100, GA TECHNOLOGIES, INC. 71-9057 214 Licensing of Independent Spent Fuel Storage - Docket 72 MODEL: HN-100 SERIES 3, 71-9151 215 UNITED STATES TESTING CO., INC. 71-0641 213 UNIV. OF VIRGINIA 71-0460 213 WESTINGHOUSE ELECTRIC CORP. 71-0651 213 Licensing of Independent Spent Fuel Storage - Docket 72 CAROLINA POWER & LIGHT CO. 72-0003 216		71-9152	215	TEXAS NUCLEAR CORP.	71-0545	213
SYSTEMS, INC. UNIV. OF VIRGINIA 71-0460 213 MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC. 71-9168 216 WESTINGHOUSE ELECTRIC CORP. 71-0851 213 MODEL: FPD-100, GA TECHNOLOGIES, INC. 71-9057 214 Licensing of Independent Spent Fuel Storage - Docket 72 MODEL: HN-100 SERIES 3, 71-9151 215 CAROLINA POWER & LIGHT CO. 72-0003 216	·	71-9216	216	UNITED STATES TESTING CO., INC.	71-0641	213
SYSTEMS, INC. MODEL: FPD-100, GA TECHNOLOGIES, INC. 71-9057 214 MODEL: GE-100, GENERAL ELECTRIC CO. 71-5926 214 MODEL: HN-100 SERIES 3, 71-9151 215 Licensing of Independent Spent Fuel Storage - Docket 72 CAROLINA POWER & LIGHT CO. 72-0003 216	SYSTEMS, INC.	.,	2.0	UNIV. OF VIRGINIA	71-0460	213
MODEL: GE-100, GENERAL ELECTRIC CO. 71-5926 214 MODEL: HN-100 SERIES 3, 71-9151 215 Storage - Docket 72 CAROLINA POWER & LIGHT CO. 72-0003 216		71-9168	215	WESTINGHOUSE ELECTRIC CORP.	71-0651	213
MODEL: GE-100, GENERAL ELECTRIC CO. 71-5926 214 MODEL: HN-100 SERIES 3, 71-9151 215 CAROLINA POWER & LIGHT CO. 72-0003 216	MODEL: FPD-100, GA TECHNOLOGIES, INC.	71-9057	214	Licensing of Independent Spent Fuel Storage - Docket 72		
MODEL: HN-100 SERIES 3, 71-9151 215	MODEL: GE-100, GENERAL ELECTRIC CO.	71-5926	214		72,0002	218
		71-9151	215			

Name	Docket	Page	Name	Docket	Page
MORRIS OPERATIONS, GENERAL ELECTRIC CO.	72-0001	216	VIRGINIA ELECTRIC & POWER CO.	72-0002	216

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-047 BARNWELL, SC, CHEM-NUCLEAR SYSTEMS, INC.

8804070126 Forwards rept for SNM waste disposal at Barnwell,SC site during 1987. Total of 5,963 SNM packages were disposed. HOUSE,W.B. Chem-huclear Systems, Inc. 88/03/30. KNAPP,M.R. Division of Low Level Waste Management & Decommissioning (Post 870413). 12pp. 45115/036-45115:047

DOCKET 27-048 RICHLAND, WA, U.S. ECOLOGY, INC.

- 8804180133 Forwards copyrighted monthly SNM receipt & burial rept & rept of Isotopic activity for Mar 1988 & revised rept of Isotopic activity for June 1987, Revised rept necessitated by recent inadvortent shipment of source range monitor. RITTENBERGR B. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.). 88/04/08. KNAPP,M.R. NRC No Detailed Affiliation Given. 451pp. 45192:284-45192:286.
- 8804070008 Submits environ monitoring results for Feb 1988, Results Indicate no re-lease of radioactive math & within background levels. COLEMAN, C. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.). 88/03/22. THOMAS, R. Reglon & Olo of the Director. SHAFFNER, J. NRC No Detailed Affilia-ation Given. INGERSOLL, C.E. Washington, State of, Dept. of Social & Health Serv-ices. 4pp. 45022.084-45022:097.
- 8803310063 Forwards SER & environ assessment for renowal of License 16-19204-01,authorizing disposal of SNM. SHAFFNER,J.A. Operations Branch, 88/03/29, LOHAUS,P.H. Operations Branch, 1p. 44953 223-44953:240
- --8803310086 SER supporting licensee application for renewal of License 18-19204-01 for disposal of small quantities of SNM at commercial low level waste disposal facility. Operations Branch. 88/03/29. 9pp. 44953:224-44953:232.
- --8804040151 Environ assessment supporting licensee application for renewal of License 18-19204-01 to allow disposal of small quantities of Pu & enriched U. NRC No Detailed Affiliation Given. 87/02/06, 8pp. 44953:233-44953:240.
- 8804210508 Submits environ monitoring results for wks of 880229-0307 & 880307-14. Results within background levels.

 COLEMAN, C. U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.), 68/04/05.

 THOMAS, B. Region 5, Olc of the Director, INGERSOLL, C.E. Washington, State of. SHAFFNER, J. NRC - No Detailed Alfiliation Given, 3pp. 45280:358-45228.358.

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0299 UMETCO MINERALS CORP., RIVERTON, WY

- 8804080124 Submits rept on Phase 3 of inactive tailings reclamation project, per Condition 54 of License SUA-848.Const of Phase 3 began on 870623 & ended on 871231.Desired thickness of 10 ft achieved.Complete piezometer reading repts encl. Fee paid.
 TRAMMELL, J.W. UMETCO Minerals Corp. (subs. of Union Carbide Corp.). 88/02/17.
 HEYER, R. Uranium Recovery Field Ofo, R4. 8pp. 45078:147-45078:165.
- 8804060177 Requests detetion of MW-21 from Paragraph D of 880229 ltr. Rehabilitation not feasible MW-21 redundant in array of wells & omission will not adversely affect planned monitoring project.
 TRAMMELLJ.W. UMETCO Minerals Corp. (subs. of Union Carbide Corp.). 88/03/03,
 Uranium Recovery Field Ofc, R4. 1p. 45019:294-45019:294.
- 8804050405 Reviews UMETCO Minerals Corp environ monitoring rept for Second Half 1987 for Gas Hills Mill, submitted on 880224. Environ sampling & analysis performed as required by 10CFR40.85.Adequate data evaluation & OC performed. HEYER,R.S., PETENGILL,H.J. Uranium Recovery Field Ofc, R4. 88/03/09, Uranium Recovery Field Ofc, R4. 4pp. 46029:173-45029:178.
- 8804080280 Forwards fee re application for amend to License SUA-648, concerning License Condition 64,revising schedule of reclamation of old latings.

 MODRMAN.B.J. UMETCO Minerals Corp., (subs. of Union Carbide Corp.). 88/03/15, HOOD,M. Uranium Recovery Field Otc, R4. 1p. 45078:200-45078:200.
- 8804280260 Forwards map as promised Revs posted by hand.W/o encl. TRAMMELL,J.W. UMETCO Minerals Corp. (subs. of Union Carbide Corp.), 88/03/29, KONWINSKI,J.W. Uranium Recovery Field Ofg, R4, 1p. 45268:339-45288:339.
- 8804280219 Application for amend to Licensa SUA-648, changing License Condition 53 to authorize reclamation per enci reclamation plan. Fee paid.

 LYONS,P.J. UMETCO Minerals Corp. (subs. of Union Carbide Corp.), 88/03/31.

 HEYER,R.S. Uranium Recovery Field Ofc, R4, 1p. 45275:054-46275;116.
- --8804280254 "QC Procedure for in-Place Density Tests."

 * UMETCO Minerals Corp. (subs. of Union Carbide Corp.). 88/03/31. 13pp. 46276:072-46275:084.
- -8804280257 "OC Procedure for Lab Std Compaction Test."

 * UMETCO Minerals Corp. (subs. of Union Carbide Corp.), 88/03/31, 8pp. 46275:085-
- -8804280262 "QC Procedure Soil Classification for Engineering Purposes." W/two oversize maps.
 * UMETCO Minerals Corp. (subs. of Union Carbide Corp.). 88/03/31. 24pp. 45275:003-45275:118,

DOCKET 40-1162 WESTERN NUCLEAR, INC., JEFFREY CITY, WY

- 8804280290 Forwards "Program for Accelerated Dissipation of Tailings Pond Water" & "Proposed Alternative Concentration Limits," presenting plans for corrective action program to achieve hazardous constituent levels. Fee pard BAKER, S.J. Western Nuclear, Inc. (subs of Phelps Dodge Corp.). 88/04/08. SMITH, R.D. Uranium Recovery Field Otc, R4. 4pp. 45283;168-45263 273.
- -8804280321 "Program for Accelerated Dissipation of Tallings Pend Water." Canonie, Inc. 88/04/30, 27pp. 45263.172-45263;197.
- -6804280331 "Proposed Alternative Concentration Limits."
 Canonia, Inc. 88/04/30, 78pp. 45263:198-45263:273.
- 8804080149 Notifies that proposed corrective action plan will be submitted by 880408 instead of 880308.per 880229 telcon. Confirmation fit requested. BAKER, SJ. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 88/03/01. HAWKINS,E. Uranium Recovery Field Ofc, R4. 1p. 45018:248-45018'248.
- 8804060213 Forwards "Semiannual Environ Mon toring Rept," per License SUA-56 Conditions 24 & 69 Millisite surface & groundwater quality data for Third & Fourth Quarters 1987 will be submitted under separate cover on 880301.

 BAKER,S J. Western Nuclear, Inc. (subs. of Pholps Dodge Corp.). 88/03/01.

 PETTENGILL,H J. Uranium Recovery Field Ofc, R4. 2pp. 45018:267-45018 321.
- -8804060225 "Semianriual Environ Monitoring Rept Jul Dec 1987."
 Western Nuclear, Inc. (subs. of Pholps Dodge Corp.) 87/12/31, 53pp. 45018 269-
- 8804280544 Notifies of two conditions of noncompliance w/License Condition 21 that occurred at Spitt Rock Mill,between 870803 & 880225.Checks of alarm sys to detect repliers of pipeline not documented & personnel fated to monitor alarm meter. KIPPEN,T.A. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) 68/03/01. SMITH,D. Uranium Recovery Field Cfc, R4. 5pp. 45266.348.45288.352
- 8804050412 Advises that company submit detailed update to entire cost estimates for tailings stabilization & evidence of approval of surety by state,per License Condition PETTENGILL,H.J. Uranium Recovery Field Otc, R4, 88/03/04. BAKER,S. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.). 2pp. 45029:180-45029:181.
- 8804070086 Ack receipt of 880301 ltr requesting 1 month extension on submission of corrective action plan to remediate ground water situation at Split Rock M.II Request pranted.
 HAWKINS,E.F. Uranium Recovery Field Oic, R4, 88/03/08 Western Nuclear, Inc. (subs. of Phelps Dodge Corp.), 1p, 45043;238-45043;238.
- 8804060304 Confirms 880315 telcon advising that meeting scheduled for 880321 in Deriver rescheduled for 880328 in Region IV ofc to discuss transfer of license to operate ion exchange plant in Crooks Gap,WY.
 SVILAR,D.P. U.S. Energy Corp. 88/03/17. HEYER,R. Uranium Recovery Field Ofc, R4. 1p. 45018:359-45018.359.

- 8804050290 Reviews Western Nuclear, Inc environ monitoring data for Second Half 1987, submitted by 880301 ftr Data submitted not algorificantly different from previously reviewed 10CFR40.65 rept into.

 SHOPENN,N.M., PETTENGILL,H.J. Uranium Recovery Field Ofc, R4. 88/03/24, Uranium Recovery Field Ofc, R4. 1p. 44997:204-44997:204.
- 8804050393 Advises that Western Nuclear, Inc semiannual ALARA audit conducted on 880105-06 acceptable, based on review of 880216 rept No trends in sample analysis observed since provious audit. HEYER, R.S. Uranium Recovery Field Ofc, R4. PETTENGILL, H.J. Region 4, Ofc of the Director, 88/03/24, Uranium Recovery Field Ofc, R4. 2pp. 44997:229-44997 230.

DOCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

- 8804280226 Application for amend to License SUA-816, revising license Condition 14,to Implement groundwater monitoring program at millsite.
 GRIDLEY,R. Tennessee Valley Authority. 88/03/28. SMITH,R.D. Uranium Recovery Field Oto, R4, 10pp. 45266;306:45266:315.
- 8804280276 Forwards TVA groundwater monitoring program for Edgement decommissioning project.per 10CFR40.Revised program reflects NRC suggestions made during 880126 meeting in Denver,CO.
 GRIDLEY,R. Tennessee Valley Authority. 68/03/28. SMITH,R.D. Uranium Recovery Field Oto, R4. 10pp. 45269:191-45269:200.
- 8804280586 Informs of windblown U tailings on property near Edgemont,SD.Review process of area to be conducted based on author consent. HEPPNER,R.D. Afficiation Not Assigned. 88/03/29. DAVIDSON,R.H. Tennessee Valley Authority. 1p. 45263-077-45263;077.

DOCKET 40-2081 KERR-MCGEE CHEMICAL CORP., WEST CHICAGO, IL

- 8803100016 Requests update on status of site setection process,in order to respond to comments on draft supplito FES re decommissioning of Rare Earths Facility, ROUSE,L.C. Fuel Cycle Safety Branch. 88/03/04. BULLARD,C.W. Springfield, IL. 1p. 44661:052/44861:052.
- 6804040063 Provides addition to dreft supplement of FES reire decommissioning of Rare Earths facility. Rept by Senes Consultants Umited re NRC estimates of dose to general public during util action period enc.

 MESERVE.R.A. Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.).

 MESERVE.R.A. Covington & Burling 88/03/23. SWIFT,J.J. Fuel Cycle Safety Branch.

 8pp. 44972:202-44972:209.

of the General Counsel 1p. 45051:295-45051:295

- 8804190203 Forwards portion of official transcript from 880324 public meeting re-sting of tow fevel redwaste facility.per Suppl 1 to NUREG-0004 Into confirms that subjecter native is not available from either legal or practical perspective.

 MESERVE.R.A. Covington & Burling, 88704708, SWIFT, J.J. Fuel Cycle Safety Branch. 7pp 45164.352-45164.358
- 8804280244 Forwards tabufated summaties of TLD monitoring data noting gross & nor-malized exposure results Region (II concern that exposure rates appear to have in-creased recently not borne out by data. STAUTER.J.C. Kerr-McGee Chemical Corp (subs. of Kerr-McGee Corp.), 88/04/11, HORN.M. Office of Nuclear Material Safety & Safeguards, Director. 13pp. 45266-321-45265-321.
- 8804280503 Forwards excerpts from Westinghouse proposal to design, develop & oper-ale low level waste facility Proposal briefly discusses technique for onsite remedial

GOOPERJ.W. Illinois, State of 88/04/11. ROUSE,L.C. Fuel Cycle Safety Branch. 5pp. 45271:039-45271:044.

8804280167 FOIA request for documents re-stated Kerr-McGee property. YOUNG,P.W. Burdit, Bowles, Radzius & Ruberry, Ltd. 68/04/12, NRC - No Detailed Affiliation Given, 1p. 45322:184-45322:184

8804280179 Responds to FOIA request for documents re stated Kerr-McGee property. Voluminous file of related into available in PDR. GRIMSEEV.DH Drivision of Rules & Records (Post 870413) 88/04/19. YOUNG.P.W. Burd-It, Bowles, Radzius & Ruberry, Ltd. 2pp. 45022:185-45522:186.

DOCKET 40-2259 PATHFINDER MINES CORP., RIVERTON, WY

- 8804050131 Forwards semiannual effluent monitoring tept for Jul-Dec 1987 & annual rept on rate & direction of groundwater flow under tailings impoundment. HAROGROVE T.W. Pathinder Mans Corp. 88/03/01. "HEYER,R. Uranium Recovery Field Ofc, R4. 1p. 45043:309-45043.327.
- -8804060145 Informs that during Juf Dec 1987, one individual exceeded action level of 15 mg On 871102 routine urine sample obtained from mill operator Operator notified & restricted from working in concentrate orders.

 GULLICKE R. Pathlinder Mines Corp. 88/02/16 Uzenium Recovery Field Otc, R4. 1p. 45043:310-45043
- ~8804060159 "Semiannual Effluent Monitoring Rept for Jul Dec 1987." W/one oversize drawing.
 * Pathfinder Mines Corp. 87/12/31, 17pp. 45043;311-45043;327.
- 8604070119 Provides review of environ manularing data for Second Hall 1987 Licensee reported all driviron manufaring data required by License Condition 22,42,47 & 48 w/ exception of samples from dry wells HEYER, B.S., PETTENGILL, H.J. Uranium Recovery Field Ofc, R4. 88/03/24. Uranium Recovery Field Ofc, R4. 4pp. 45043 247-45043:250.

DOCKET 40-3392 ALLIED-SIGNAL, INC., METROPOLIS, IL

- 8804190265 Confirms 880119 telcon w/NRC re Descote UF6 cylinder valve situation Affied has been adequately informed by Descote that valves in question mlg in accordance w/appropriate specs Matter considered resolved BISHOP_J C. Alfied-Signal Corp. 88/01/21. SHAFER, W.D. Region 3, Ofc of the Director. 1p. 45216:330-45216:331.
- 8803300310 Forwards Safety insp Rept 40:3392/68-01 on 880307-11 No violations of NRC requirements noted. SHAFER,W.D. Region 3, Otc of the Director, 88/03/25, BISHOP.J.C. Allied-Signal Corp. 2pp. 44961:284-44961.290.
- --8803300319 Insp Rept 40 3392/88-01 on 880307-11.No violations, deficiencies or de-viations noted.Major areas inspected lacility emergency preparedness progrem.incubing fire protection, ratiological contingency plan & procedures. SMITH,M.J. Region 3, Ofc of the Director, 88/03/24 5pp, 44981-286-44981-290.
- 8804110205 Trip rept of 880314 visit to Altied Signal Metropolis Works Facility re recent incidents reported by licensee to Region III, completion of previously identified items & status of five remaining lessons learned Wienci.
 PENNINGTON.W.S. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/04/04. Division of Industrial & Medical Nuclear Safety (Post 870729) 4pp. 45078:143-45078-145.
- 8804120166 Trip rept of 880314 visit W/Region III to facility re licensee operations,including recent Incidents reported by Iscensee PENNINGTON.W.S. Fuel Cycle Safety Branch. 88/04/04. Fuel Cycle Safety Branch. 45101:054-45101.057.
- 8804120178 Forwards Insp Rept 40-3392/88-02 on B80307-11.No violations noted. SHAFER,W.D. Region 3, Oic of the Official, 88/04/06, BISHOP,J.C. Alfied-Signal Corp. 1p. 45128:272-45128-287.
- --8804120181 Insp Ropt 40-3392/88-02 on 880307-11.No violations or deviations noted Major areas inspected increase action on lessons fearmed recommendations, radiation protection program, radiation engl & unusual incidents. FRANCE G.M. SCHUMACHER,M.C. Region 3, Oic of the Director, 88/04/06, 15pp. 45128-227, 45128-227.
- 8804190136 Forwards one-fourth of each collection plate filter from "Nearest Resident" air sampling station.per License Condition 22d Samples represent mail collected during First Quarter 1988 W/o encis.
 BISHOP,J.C. Alted-Signal Corp. 88704/08. RDUSE L. Office of Nuclear Material Safety & Saleguards, Director. 2pp. 45165-294-45165:295,

- 8804280406 Transmits decommissioning & decontamination plan for facilities p 870731 Order, Item IV.O & 870929 extension granted by RD Martin Fee paid. RLUBAUGH, RE. Attas Corp. 87/11/27. SMITH, R.D. Uranium Recovery Field Ofc, F 20p. 45279:200-45279:291
- -8804280440 "Decommissioning Plan for MOAB Mill,Moab,UT." W/ one oversize mg. Allas Corp. 67/11/30. 91pp. 45279:202-45279:291.
- 8804280434 Forwards probability statistics, detection monitoring methods, per Licen SUA-917 & NRC 870731 order Determination of true background concentration leve for indicator parameters at Moab Mill sire impractical & unfoasible. BLUBAUGH, R.E. Atlas Corp. 88/02/17. PETTENGILL, H. Uranium Recovery Field O R4. 11pp. 45263.053-46263.083.
- 8804060170 Requests proposal to define concentration & extent of Criterion 13 hazar ous constituents in uppermost aquifer within 30 days of itr date.Proposal should a dress Criterion 13 hazardous constituents to be included in program. HAWKINS.EF. Uranium Recovery Field Ofc, R4, 88/03/09. Atlas Corp. 2p. 45019:289-45019.290.
- 8804280359 Remits fee for 871127 & 880217 applications for amends to License SU BLUBAUGH, R.E. Allas Corp. 88/03/09. HOOD, M. Uranium Recovery Field Otc, F 1p. 45269-237-45269-237.
- 8804290197 Provides results of annual survey of land use within 2-mile area of mill of 1997, per License Conchition 47, EDWARDS,OL. Attas Corp. 68/03/28. SMITH,D. Uranium Recovery Field Ofc, R 2pp. 45322:195-45322:196.
- 8804280115 Application for amend to License SUA-917 requesting additime to developed detailed cost estimate for decommissioning of Mill.

 BLUBAUGH,R.E. Atlas Corp. 88/03/29. Uranium Recovery Field Otc, R4. 2p. 45262-329-45262-330.
- 8804280441 Clarifies NRC recent position re groundwater monitoring.per NRC 8803 its 8 telcon.Understands that new detection monitoring program must be submitted proposal to NRC by 880408.

 ROBINSON,G.M. Enecotech, Inc. 88/03/29. KONWINSKI,G. Uranium Recovery Fiel Otc, R4. 1p. 45266.082-45266:082.
- 8804110021 Memorandum & order.* Atlas motion to diamiss proceedings re renewal license granted. Served on 880407. FRYE_JH. Atomic Salety and Licensing Board Panel. #288 6036. 88/04/06. Atl. Corp. 3pp. 45049:022-45049:024.
- 8804110036 NRC Stati response to licensee motion to terminate hearing proceeding Presiding officer should issue order terminating proceeding Certificate of Svc enci. BERRY,G.A. Assistant General Counsel for Hearings. #286 6037, 88/04/06. Atom Safety and Licensing Board Panet. 158pp. 45049.287-45050.084.
- 8804280507 Confirms 880406 telcon re plans to sell approx 340 tons of refined copp concentrate currently stored in bulk form. Understands sale of matt for further refinit BLUBAUGH, R.E. Atlas Corp. 88/04/07, PETTENGILL, H. Uranium Recovery Field Of R4. 1p. 45265:039-45265:039.
- 8804200065 Discusses J Darke call re 880406 memorandum & order found to be list in PDR & not received J Darke also informed about encil 880411 fit from atty Zehl which was returned as not delivered. Temporary address provided Served on 88041 MORAN, D.M. Atomic Safety and Licensing Board Panel. #288 6069. 88/04/13. FRY Atomic Safety and Licensing Board Panel. 1pp. 45162:084-45162:088.
- —8804200080 Informs that on 880325, Alias Corp attempted to serve J Darke copy icensee motion to terminate hearing proceeding. Package returned as not deliverable as addressed Atlas Corp requests that hearing record include this add into. ZAHLER, R.E. Alias Corp. ZAHLER, R.E. Shaw, Pittman, Potts & Trowbridge. 88/0-11. FRYE, J.H. Atomic Safety and Licensing Board Penel. 2pp. 45162.085-45162.08

DOCKET 40-4492 AMERICAN NUCLEAR CORP., CASPER, WY

- 8804080279 Requests review of proposed alternative to pull pumps plug welfs do oth work required for closure of facility & allow buffering action of soils to neutraliz seepage Approval or proposal of new program based on available into requested. ANDRUS,N.J. American Nuclear Corp 88/02/22: HAWKINS,E.F. Uranium Recove Field Otc, R4. 4pp. 45076:196-45076:199.
- 8804060183 Forwards semiannual rept for second half of 1987, representing monitorin data per Jan 1986 Amend 24 to License SUA-887 w/exception of sample size due problem discussed during telcon w/Pettengill or Komwinski.

 ANDRUS.N.J. American Nuclear Corp. 88/02/28. Uranium Recovery Field Oto, R 1p. 45018;139-45018:169.
- ~8804080164 "Semiannual Rept on Radioactive Effluent per 10CFR40.65, Jul-De
 - American Nuclear Corp. 87/12/31, 30pp. 45018:140-45018:169,
- 8804070100 Ack receipt of 880222 ltr in response to NRC 880201 ltr.NRC groundwatt reviews indicate that groundwater mound consistently diminished w/sime,Request conclusive proof that equifer under takings impoundment dewatered. HAWKINS E.F. Uranium Recovery Field Oto, R4. 88/03/08... American Nuclear Constitution of the cons 2pp. 45043;243-45043;244.
- 8804060260 Informs that 880227 exviron monitoring cept not significantly different fro previous reviewed date. Soil samples not submitted as samples were lost & watter samples not taken due to low water levels.

 SHOPENN,N.M. Region 4, Otc of the Director. PETTENGILL, H.J. Uranium Recove Field Ofc, R4. 88/03/24. Region 4, Otc of the Director. 1p. 45017:256:45017:256.

- 8804280391 Informs of error in 880229 transmittal re-semi-annual rept for second half of 1987. Soil samples collected by K Watts but lost or misplaced between field ofc &
- energy labs. ANDRUS,NJ. American Nuclear Corp. 88/03/24. Uranium Recovery Field Ofc. R4. 1p. 45266 071-45266 071
- 8804280311 Forwards documentation supporting licensee position that little can be gained from further pumping of seepage recovery sys on Pond 1. ANDRUS,N J. American Nuclear Corp. 88/03/25. HAWKINS,E.F. Uranium Recovery Field Otc, R4. 18pp. 45263 274-45263:290.
- 8804280177 Confirms conversation wherein author stated that American Nuclear will not pursue Riverton Tallings Relocation project further & thereby withdraws ficense amend to receive Riverton tailings. FERGUSON,J.C. American Nuclear Corp. 88/03/28, PETTENGILL,H. Uranium Recovery Field Ofc, R4. 1p. 45278:229-45278:229.

8804290009 Issues comments & concerns generated during review of draft reclamation spaces submitted w/880331 lit.
MOXLEY,M Wyoming, State of. 88/04/04, ANDRUS,N J. American Nuclear Corp. 2pp. 45322.280-45322:281.

DOCKET 40-6500 ENERGY, DEPT. OF, CANONSBURG, PA

- 8803310116 Discusses results of NRC review of DOE 871120 submittal, "Evaluation of Erosion Protection in Ditches at Canonsburg." Replacement of poor quality rock w/ rock of suitable quality & placement of riprap should be considered LOHAUS.P.H. Operations Branch. 88/03/24. ARTHUR.W.J. Energy, Dept. of. 2pp. 44967:309-44967:320.
- --8803310120 "NRC Staff Review of Cannonsburg Riprap."

 JOHNSON,T.L. NRC No Detailed Affiliation Given, 88/03/17, 10pp. 44967:311-44967:320.

DOCKET 40-8822 PATHFINDER MINES CORP., SHIRLEY BASIN, WY

- 8804060276 "Hydrologic Monitoring for Shirley Basin Tailings Seepage Control Plan." W/lour oversize maps. SMITH,J.C., MURDOCK,S., HOFFMAN,G.L. Pathlinder Mines Corp. 88/02/29. 290pp. 45035:022-45035:317
- 8804060024 Forwards 40.65 rept, "Second Half 1987 Environ Monitoring Data," per License Condillon 22, SMITH, J.C. Pathlinder Mines Corp. 88/02/29. HEYER,R. Uranium Recovery Field Ofc, PA. 1p. 45018,170 45018,196.
- 8604060029 "Second Half 1987 Environ Monitoring Data."
 Pathfinder Mines Corp. 87/12/31, 26pp. 45018;171-45018;196.
- 8804060240 Forwards into required by License Condition 47 re compliance monitoring Second Half 1987, which was mistakenly omitted from 10CFR40.65 repl. SMITH,J.C. Pathilinder Mines Corp. 88/03/03. HEYER,R. Uranium Recovery Field Ofc, R4. 2pp. 45018:325-45018:326.
- 8804060012 Advises that Pathfinder Mines Corp,semiannual ALARA audit aubmitted on 880222 acceptable,per 880216 review.No lurther recommendations made & no further action necessary at present.
 HEYER,R.S., PETTENGILL,H.J. Uranium Recovery Field Ofc, R4. 88/03/24. Uranium Recovery Field Ofc, R4. 38/03/24. Uranium Recovery Field Ofc, R4. 39p. 45018:001-45018:003.
- 8804060166 Discusses review of ticensee 880229 & 0303 submittale of environ monitoring rept for second half of 1987. Lower limits of defection appropriate. All data reported appears accelable & no further action necessary.

 HEYER,R.S., PETTENGILL,H.J. branum Recovery Field Ofc, R4. 88/03/24, Uranium Recovery Field Ofo, R4. 4pp. 45018:257-45018:260.

DOCKET 40-6659 GETTY OIL/PETROTOMICS CO., SHIRLEY BASIN, WY

- 8804060089 Forwards environ into for Third & Fourth Quarters of 1987, per 10CFR40.65 & 190 & License Condition 20.W/o and. PFAFF,S.J. Petrotomics Co. (formerly Getty/Petrolomics Co.), 88/02/29, HAWKINS,E. Uranium Recovery Field Ofc, R4. 1p. 45018:224-46018:224.
- 8804140250 Proposes to drop outlined area from Wyoming Mining Permit 351-C & small undisturbed & unreclaimed areas from Permit 342 & designate subj area as NRC tallings & disposal area.

 PFAFF,S.J. Petrolomics Co. (formerly Getty/Petrolomics Co.), 88/03/10.

 HAWKINS,E.F. Uranium Recovery Field Ofc, R4, 3pp. 45118:185-46118:187.
- 8804060295 Ack receipt of 880310 lit discussing removal of mill failings & mill disposal area from State of WY Dept of Environ Quality permit area.NRC concurs in current bond amount per 880310 submittat.

 HAWKINS,E.F. Uranium Recovery Field Ofc, R4. 88/03/22. MILL,S.B. Petrotomics Co. (formerly Getty/Petrotomics Co.), 1p. 45019:211-45019:211.

DOCKET 40-7102 SHIELDALLOY CORP., NEWFIELD, NJ

6803080283 Requests NRC approval of extension until 880405 to allow submission of 803080283 Requests NHC approval of extension that above a learning more integrated & complete response to questions posed in 860105 lir.
MORGENSTERN,M. Metallurg, Inc. (formerly Shield Alloy Corp.), 88/03
PENNINGTON,S. NRC - No Detailed Affiliation Given. 2pp. 44633:352-44633:353. 88/03/02

DOCKET 40-7455 WHITTAKER METALS, LOS ANGELES, CA

8804180465 Requests listed additinto re 880405 application for amend to License SMA-1018,including length of extension to expiration date quarterly monitoring data for 1987 & justification for reducing quarterly monitoring program to blennial program. HORN,M. Fuel Cycle Safety Branch, 88/04/12. LOUTTIT,G.J. Whittaker Corp. 1p. 69294;268-69294;269.

DOCKET 40-7580 FANSTEEL, INC., NORTH CHICAGO, IL

8804050122 Forwards clarification of licensee responses to Question 11 from 870320 list & Questions 5 & 10 from 870512 list,por 890308 telcon w/G Scenter. CARILETS. Fansteel Metals (subs. of Fansteel, Inc.). 88/03/21. LAROCHE,G Office of Nuclear Material Safety & Safeguards, Director. 8pp. 44997.001-44897:008.

DOCKET 40-7604 SOHIO CHEMICAL CO., LIMA, OH

- 8804040041 Forwards catalyst plant release survey for British Petroleum Chemical Corp In Lime OH. O'CONNELL, P.V. Nuclear Energy Services, Inc. 88/03/30, SWIFT, J. NRC - No De-telled Affiliation Given. 6pp. 44955:193-44960:026
- --8804040043 "Unrestricted Release Survey for Catalyst Plant 8P Chemical Co,Lima,OH."

 * Nuclear Energy Services, Inc. 83A2985. 88/03/31. 1,632pp. 44955:195-44960:026
- 8804160181 Forwards results of Nuclear Energy Svcs,Inc (NES) 8 Lab analysis of seven soil samples from floor cores of Catalyst Bldg,Initial discrepancies for two samples resolved after NES verified sample labels. LANDIS,M R. Oak Ridge Associated Univs. 88/03/30. NRC No Datailed Affiliation Given. 3pp. 45139.061-45139.063.

8604280180 Summary of 880408 meeting w/licensee in Rockville.MD re docontamina-tion effort at plant.Addi info will be required re dose rate total dose assessment & fur-ther surveys of burled pipes soil & outside walls & floor slab juncture. LARCCHE.G. Fuel Cycle Safety Branch. 88/04/15. Fuel Cycle Safety Branch. 1p. 45276:230.45276:230.

DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK

- 8803080015 Forwards listed documents in response to 880115 request for response to State of TX request for Info on use of treated ratifinate as fertilizer. W/o encis. ROUSE L.C. Fuel Cycle Satety Branch. 88/01/16. NUSSBAUMER,D.A. Assistant Director for State Agreements Program. 2pp. 44633:186-44633:188.
- --8803080018 Requests listed into re use of ratifinate as fertilizer in order to respond to State of TX 871218 request. Response requested by 880111. NUSSBAUMER.D.A. Assistant Director for State Agreements Program. 88/01/05. ROUSE,L.C. Fuel Cycle 6afety Branch. 1p. 44633:188-44633:188.
- 8804050429 Forwards U Recovery Field Ofc review of Sequoyah Fuels Gore, OK,fackity 871120 rept in response to 880203 Action Item 88-946 SMITH.R.D. Uranium Recovery Field Ofc, R4, 88/03/16, ROUSE,L.C. Fuel Cycle Safety Branch, 4pp, 44997:343-44997:346
- 8804060243 Forwards DOE 880308 correspondence re overfilled cylinder that was shipped from Paducah gaseous diffusion plant to Sequoyah techty in Aug 1987. STAUTER, J.C. Sequoyah Fuels Corp. (subs. of Kerr-McGee Nuclear Corp.), 88/03/28. ROUSE, L.C. Fuel Cycle Safety Branch. 7pp. 45018.327-45016.333.
- 8604150366 Comments on Paragraph 6.0. "Independent Measurements," from Insp. Rept 40-8027/88-01.NRC gross alpha value inconsistent w/value for U in solution 8 error tound in analytical data for combination stream at Port Bridge Road. STAUTER, J.C. Sequoyah Fuels Corp. (subs. of Kerr-McGee Nuclear Corp.). 88/03/31. FISHER, W. L. Region 4, Otc of the Director. 2pp. 45138.335-45138.336.
- 8604190155 Advises that quarterly lung dose commitment for Third Quarter 1987 calculated at 3.18 miern. Licensee has no account for higher than normal count of 8.25 mrem during Second Quarter 1987. Table of dose estimates encl. STAUTER J.C. Sequoyah Fuels Corp. (subs. of Kerr-McGee Nuclear Corp.). 88/03/31. ROUSE, L. C. Fuel Cycle Safety Branch. 4pp. 45164:343-45164:346.
- 8804190193 Discusses violation of License Condition 30 re failure to achieve required number of U bloassy analyses. Caused by technician receiving erroneous instructions. Lir of reprimand issued to employee responsible for violation. STAUTER. J. C. Sequoyah Fuels Corp. (subs. of Kerr-McGee Nuclear Corp.). 88/03/31. ROUSE, L. C. Fuel Cycle Salaty Branch. 3pp. 45164:349-45164:351.
- 8804110200 Responds to 880226 itr that expressed concerns re existing environ conditions on Keaterson Reservol/Linforms that use of armonium mitrate as ferbizer produces no greater risk to public health or safety than commercial fertilizers. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/04/04, GIBSON,D. Affiliation Not Assigned. 6pp. 45078:093-45078.098.
- 8804280457 Informs that no revs made to radiological contingency plan & that minor changes made to contingency plan implementing procedures (CPIP) to enhance clarity. Listing of CPIPs & summary of revs made during past is it months encoded. STAUTER, JC. Sequoyah Fuels Corp., tsubs. of Kert-McGee Nuclear Corp.). 88/04/15. ROUSE, L.C. Office of Nuclear Material Safety & Safeguards, Director. 9pp. 45264:084-45264:092

DOCKET 40-8064 EXXON MINERALS CO., USA, HOUSTON, TX

- 8804060194 Advises of Issuance of Amend 14 to License SUA-1064,revising License Condition 11 to read as listed re decommissioning of Highland U In-Situ Mire Process Facility 8 expanded R8D wellised per 880203 decommissioning 8 reclamation plan. SMITH.R.D. Uranium Recovery Field Ofc, R4. 88/03/16. Exxon Corp. 2pp. 45019.305-
- --8804060198 Amend 14 to License SUA-1064 for Exxon Corp, revising License Condilion 11 as listed. SMITH.R.D. Uranium Recovery Field Otc, R4. 88/03/16. 6pp. 45019:307-45019:317.
- 8604060339 Summarizes review of 670108 decommissioning & rectamation plan for Highland Pilot U in Situ facility.Concludes that proposed plan acceptable & license should be amended by revising License Condition 11. SHOPENN,N.M.P. PETTENGILL,H.J. Uranium Recovery Field Ofc, R4. 88/03/16. Uranium Recovery Field Ofc, R4. 6pp. 46017:273-45017:277.

DOCKET 40-8084 RIO ALGOM MINING CORP., MOAB, UT

- 8804060039 "Semiannual Environ Monitoring Rept for Jul-Dec, 1987," W/860220 ltr. LAWTON,M.D., FOSSEY,F.G. Rio Algom Mining Corp. 87/12/31, SMITH,R.D. Uranium Recovery Field Otc, R4, 24pp. 45017.305-45017.328.
- 8804140407 Advises that on or about 880531,Rio Algom Mining Corp will indefinitely suspend all U milling operations & activities conducted at Lisbon mill in Moab,UT. LAWTON,M D. Rio Algom Mining Corp. 88/02/17. SMITH,R D. Uranium Recovery Field Otc. R4. 1p. 45118.070-45118.070
- 8804060188 Ack receipt of 680122 application for amend to License SUA-1119 Requests proposal to define concentration 8 extent of Chiterion 13 hazardous constituents in uppermost aquifer. Compliance monitoring program necessary.

 HAWKINS.EF. Utanium Recovery Field Ofc, R4, 88/03/09. Ro Algom Mining Corp. 2cp. 45019:301-45019:302.
- 8804280530 Application for amend to License SUA-1119,amending Condition 45 to reflect isted changes & Conditions 11 & 42 to discontinue every two yr "In Vivo" tung scan. Fee paid.

 PATTISON.R.S. Rio Algom Mining Corp. 88/03/17, SMITH,R.D. Uranium Recovery Field Otc., R4, 4pp. 45271:059-45271.062.
- 8804280023 Forwards addit administrative fee re 680318 license application to reduce feeboard needed at lower teilings pond & climinate blennist in vivo requirement. PATTISONRS. Rico Algom Mining Corp. 88/03/23 SMITH.R.D. Uranium Recovery Field Ofc. R4. 1p. 45286:187-45266:187.
- 8804280342 Confirms that Iconsee will propose surely instrument to NRC on or before 880415, per 880323 discussion.
 COCHRANE, D.B. Rio Algom Mining Corp. 68/03/23 ROSE, H. Uranium Recovery Field Otc, R4. 1p. 45269:219-45269:219.
- 8804260207 Forwards ALARA audit rept for Sept 1987 Feb 1988. FOSSEY,F.G. Rio Algom Mining Corp. 88/03/25. SMITH,R.D. Uranium Recovery Field Old, R4, 37pp, 45276-252-45276-288.

DOCKET 40-8102 EXXON CO., USA, HOUSTON, TX

- 8804070065 Forwards summary of airborne emissions of principal radionuclides & semianiual environ monitioning rept for Jul-Doo 1987 Airborne emissions last rept of perimeter Bit sampling results, per Amend 20 to License SUA-1139. RANGEO M. Exxon Corp. 88/02/16. Uranium Recovery Field Ofc, R4, 1p. 45029.213-
- -8804070104 "Airborne Emissions of Principal Radionuclides From Highland Tailings Bash During Paried Jul-Doc 1987." " Exxon Carp. 67/12/31. 1p 45029.214.45029.214.
- -8804070106 "Environ Monitoring Data Jul Dec 1987." * Exxon Corp. 87/12/31, 20pp. 45029,215-45029 234,
- 8804080215 Forwards into re Highland tailings reclamation project & revised cost estimate reflecting latest changes,per 880223 tr & 880225 meeting Prompt approval urged.
 PATTON, J.D. Exxon Corp. 88/03/04. HAWKINS,E.F. Uranium Recovery Field Otc, R4, 9pp. 45099:001-45089.012.
- 8804060208 Discusses review of licensee 880216 submittel of environ & effluent monitoring rept for second half of 1997 No further action required. KONWINSKI,G R. HAWKINS.E.F. Urantum Recovery Field Ofc, R4. 88/03/08, Urantum Recovery Field Ofc, R4. 3pp. 45018:264. 45018:266.

DOCKET 40-8452 BEAR CREEK URANIUM CO., CASPER, WY

- 8804280514 Notifies of name change from Rocky Mountain Energy Co to Union Pacific Minerals Inc.effective 870603 All correspondence should be sent to issted address, effective immediately.

 MEDLOCK,R.L. Union Pacific Resources (formerly Rocky Mountain Energy), 88/02/08. HAWKINS.E., JACOBY,D. Uran'um Recovery Field Ofc, R4. 1p. 45324:178-4524:17
- 8804080137 Advises that request for amend, detailed update to cost estimate for tailings stabilization & evidence that surery instrument formally accepted by State of WY dept of emritor querity must be submitted PETTENGILL, H.J. Uranium Recovery Field Otc, R4. 88/03/16. SCOTT, E. Bear Creek Uranium Co. 2pp. 45019:253-45019 254.

DOCKET 40-8602 MALAPAI RESOURCES CO., PHOENIX, AZ

- 8804060189 "1997 ALARA Audit Rept,Ingarey Mine Malepal Resources Co, Source Matl Ucense SUA-1341." W/880229 tr. WICHERS.D.L. Watapai Resources Co, 87/12/31, KONW-NSKI,G. Uranium Recovery Field Otc, R4. 26pp. 45019:284-45019 289.
- 8804060313 "Semiannual Effluent & Environ Monitoring Rept for Irigaray Project, Jul-Dec 1987." W/880229 III.
 WICHERS,D.L. Malapal Resources Co. 87/12/31. KONWINSKI,G. Uranium Recovery Field Ofc, R4. 14pp. 45019,212-45019

- 8804060353 Discusses Irigaray Mine annual ALARA audit rept for June-D 1987.ALARA audit indicated that appropriate controls being implemented to redu employee aynosures. Appropriate mpt oversight of ALARA concept also evident. KONWINSKIG.R. HAWKINS,E.F. Uranium Recovery Field Ofc, R4. 88/03/08. Ura um Recovery Field Ofc, R4. 3pp. 45017:283-45017:285.
- 8804050424 Notifies of 880321 meeting to discuss DEQ comments on Malapal appsition to include Wiflow Creek property in Irigaray permit & to discuss responses to our comments included in R Shatter 880307 ltr.

 CLARKINK. Wyoming, State of. 88/03/18 MOONEY,G. Wyoming, State of. 44997:331-44997:331.
- 8804280035 Forwards listed documents re proposed access road between Ingaray ml & Christiansen ranch emend area,per 880208 discussions W/o encis, WICHERS,D.L. Malapai Resources Co. 88/03/18 MOONEY,G. Wyoming, State 2pp. 45276:088-45276.089.
- 8804280477 Ack receipt of 880307 ltr re completeness & preliminary technical review Malapal Resources Co permit to Mine 478. Completeness Issues concerned surface ownership map of road & operation/restoration effort to reduce radium. WICHERS, D.L. Malapal Resources Co. 88703725. SHAFFER, R. Wyoming, State 4pp. 45264 097-45264;100.
- 8804280097 Application for amend to Ucense SUA-1341,reflecting submittal of a "Production Unit 6,Baseline Water Quality Data Package" & modifying Conditions & 25 Shakedown of Unit 6 will begin to test ping & plant circuits. Fee paid. WICHERS.D.L. Matapai Resources Co. 88/04/04. KONWINSKI,G.R. Uranium Reco
- -8804280103 "Production Unit 6,Baseline Water Quality Data Package." One overs map enct.

 **Malapai Resources Co. 88/04/04, 33pp. 45277.007.45277.039.

DOCKET 40-8681 UMETCO MINERALS CORP., GRAND JUNCTION, CO

- 8803080526 Forwards proposed format for litr of credit for White Me surely.Recommended wording for irrevocable fit of credit modified. FROST_JF_UMETCO_Minerals_Corp. (subs. of Union Carbide Corp.), 87/10/2 ROSE_H. Uranium Recovery Field Otc, R4. 3pp. 44638:084-44639:086.
- 8804060140 "Semiannual Effluent Rept,UMETCO Minerals Corp.,Jul-Dec 1987." V 880229 ltr. HAMRICK,J.S. UMETCO Minerals Corp. (subs. of Union Carbide Corp.). 87/12// PETTENGILL,H.J. Uranium Recovery Field Ofc, R4 131pp. 45018:008-45018:138.
- 8804080172 Authorizes NRC to deal directly w/Landmark or representative re miscel negous equipment & remaining soil to be disposed of at White Mesa Mill. SCHIERMAN,S.L. UMETCO Minerals Corp. (subs. of Union Carbide Corp.). 88/02/2 PETTENGILL,H.J. Uranium Recovery Field Ofc, R4. 1p. 45019:291-45019:291.
- 8804070025 Submits Ltr of Credit 00017012 for UMETCO Minerals Corp.to provifunds for decommissioning decontamination, reclamation & long-time surveillance of censes White Mesa, UT, U & vanadium facility, per License SUA-1358.

 1 kving Trust Co. 88/03/03. NRC No Detailed Affiliation Given. 3pp. 45043:174
- 8804050395 Recommends that License SUA-1358 be amended to approve propositively instrument & specify anniversary date for surety updates by revising Condition to read as stated.

 ROSE,HD., PETTENGILL.H.J. Uranium Recovery Field Ofc, R4. 88/03/21, Uranium Recovery Field Ofc, R4. 3pp. 44997:231-44997:233.
- 8804060009 Amend 12 to License SUA-1358 for Umetco Minerals Corp., authorizi possession of natural U generated by licensee milling operations. SMITH,R D. Urenium Recovery Field Ofc, R4, 88/03/21, 12pp. 45017:330-45017:35
- 8804060328 Issues Amend 12 to License SUA-1358.establishing anniversary date 880604 for annual update of surety instrument by revising License Condition 20 read as stated.

 SMITH.R.D. Uranium Recovery Field Ofc, R4, 88/03/21, UMETCO Minerals Co (subs. of Union Carbide Carp.), 3pp. 45017:267-45017:269.

DOCKET 40-8684 MALAPAI RESOURCES CO., CASPER, WY

- 8804050424 Notifies of 880321 meeting to discuss DEO comments on Malapal application to include Willow Creek property in Irigaray permit & to discuss responses to real comments included in R Shatler 880307 ltr.
 CLARKIN.K. Wyoming, State of. 88/03/16. MOONEY.G. Wyoming, State of. 44997:331-44997:331.
- 8804280252 Advises that 680318 & 25 applications to amend License SUA-1337 to clude Willow Creek property considered complete Public notice should be commenc & affidavit of publication should be submitted.
 SHAFFER,R. Wyoming, State of, 88/04/01. WICHERS,D. Malapal Resources Co. 2, 45266:337-45266:338.

DOCKET 40-8698 PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO.

8804080130 Application for amend to Ulcense SUA-1371, revising License Condition 33 to change arsenic & selenium threshold values to 0.022 mg/l Fee paid: SAVIGNAC.N. Plateau Resources, Ltd. 88/02/24. HAWKINS,E. Uranium Recovery Field Ofc, R4, 5pp. 45078;155-45078;165.

DOCKET 40-8714 CLEVELAND-CLIFFS IRON CO., CLEVELAND, OH

- 8804280383 Notifies that reclamation performance bond for Collins Draw Project in Campbell County,WY reduced by stated amount. Signed & sealed rider & related insurance company certificate encl.

 AHO,G.D. Cleveland Citifs Iron Co. 88/02/23. JORDAN,P. Wyoming, State of. 4pp.
 - 45262:352 45262.355.
- 8804060008 Forwards final records & documentation re move of Collins Oraw process equipment to New Mexico W/o encl. AHO.G.O. Cleveland Cliffs from Co. 88/03/07. KONWINSKI,G. Uran'um Recovery
- Field Olg, R4, 1p. 45017:329-45017:329.
- 8804120331 Application for amend to License SUA-1352 to allow onsite surface disposal of plant wash down water from cleanup & decommissioning Fee paid. AHO.G.D. Cleveland-Clittls from Co. 88/03/07, KONWINSKI,G. Uranium Recovery Field Ofc, R4. 2pp. 45091:264-45091:265.
- 8604060161 Responds to licensee 880307 ltr re disposal of water from washing & de-contamination of plant bldg at Collins Draw.No objection raised against disposal of wash water into spill containment sump pump provided no discharge outside pond. WAGNERJ.F. Wyoming, State of. 88/03/17. AHO,G.D. Cleveland-Cliffs Iron Co. 1p. 45019:267-45019:257.
- 8804060176 Summarizes 880315 meeting re Collins Draw groundwater stability monitor-
- ing dala. AHO.G.D. Cleveland-Cliffs fron Co. 88/03/18, KONWINSKI,O. Uranium Recovery Field Ofc, R4, ENGELMAN,R. Wyoming, State of. 2pp. 45019:292-45019:293.
- 8804280552 Forwards Energy Labs analytical repts for March groundwater sampling program at Collins Draw.Five well monitor also reported. AHÖ, G.D. Cleveland-Cliffs Iron Co. 88/03/28, KONMINSKI,G. Uranium Recovery Field Otc, R4. ENGELMAN,R. Wyoming, State of. 29pp. 45285:041-45285:069.

DOCKET 40-8752 PINAL MINERALS & MINING, LTD., MIAMI, AZ

- 8804060038 Recommends that License SUA-1388 be terminated,per licensee 880127 request. Criterion 9 requirement that land must be transferred to US or state can be walved. SHOPENN,N.M., PETTENGILL,H.J. Uranium Recovery Field Ofc, R4. 88/03/18. Uranium Recovery Field Ofc, R4. 2p. 45018:197-45018:196.
- 8904060120 Advises that License SUA-1388 terminated, effective immediately, in response to 870413 & 880128 submittals of final decommissioning rept & disposition of matte rept No addit environ impact resulted from decommissioning activity. SMITH, A.D. Uranium Recovery Field Offo, R4. 88/03/18. CLARY, T. Pinel Minerals & Mining, Ltd. 1p. 45018:227-45018:227.

DOCKET 40-8768 KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK

- 8803080496 Reviews Third Quarter 1987 rept for Sequoyah Fuels Corp O Sand In Situ Leach R&O project.
 JOHNSON,S. Wyoming, State of. 88/01/25, Wyoming, State of. 15pp. 44639:037-
- 8804060148 Discusses conversation w/M Carnevale re selenium concentration in Bill Smith Mine effluent. Advises that div does not have adequate evidence to justify mod in Bill Smith NPDES permit to include moniforing of selenium.

 WAGNER, J.F. Wyoming, State of. 88/03/09. Wyoming, State of. 2pp. 45019:255-45019:258
- 8804280190 Application for amend to License SUA-1387, requesting approval of alternative method (or final disposal of small barlum suttate solids & defetion of sediment sampling requirements for NPDES drainage system.
 FREEMAN,M.D. Sequoyah Fuels Corp. (subs. of Kerr-McGee Nuclear Corp.), 88/03/23, HAWKINS,E, Uranium Recovery Field Ofc, R4, 14pp. 45278:293-45278:306.

DOCKET 40-8783 URANERZ USA, INC., CASPER, WY

8804070111 Ack receipt of 880204 aquifer test submitted & 880226 similarity rept.Proposal to maintain aquifer pumping for 72 to 96 h should induce sufficient stress to assure successful analysis of data.W/o encis. HAWKINS.E.F. Uranium Recovery Field Ofc, R4. 88/03/22. Uranerz USA, Inc. 2pp, 45043;245-45043;246.

DOCKET 40-8800 MCGEAN DISPOSAL DUMP, NEWBURGH HEIGHTS, OH

- 8804180334 Forwards Drawings A & Biclarifying route of storm sewer mentioned in li-
- censee 880122 ltr. ZELLNER,R J. McGean-Rohco, Inc. (formerly McGean Chemical Co., Inc.), 88/03/29, LAROCHE,G. Fuel Cycle Safety Branch. 3pp. 45149:201-45149:204.

DOCKET 40-8829 FERRET EXPLORATION CO. OF NEBRASKA, INC., CRAWFORD,

- 8804280417 Forwards ALARA rept for Crow Butte Project for two quarters ending 871231.W/o enct. COLLINGS.8.P. Ferret Exploration Company of Nebraska, Inc. 88/02/24. GRACE,S. Uranium Recovery Field O(ο, R4, 1ρ. 45266;072.45266:072.
- 8804280042 Application for amend to License SUA-1441, deleting License Condition 13 & revising License Condition 30 to change from quarterly repts to semiannual Restoration rept for Wellfield 2 at Crow Butte Project enc

-8804280048 "Crow Butte R&D Project Welffield 2 Restoration." Ferrel Exploration Company of Nebreske, Inc. 88/03/24. 24pp. 45275-277-45275-300.

DOCKET 40-8902 ANACONDA MINERALS CO., GRANTS, NM

- 8804050432 Advises that Anaconda proposed radiation sefety & environ monitoring programs as mod by NRC, adequate for mill to be decommissioned & recommends that License SUA-1470 be amended to incorporate updated programs GARCIA, P.J., PETTENGILL, H.J. Uranium Recovery Field Ofc, R4. 88/03/10. Uranium Recovery Field Ofc, R4. 7pp. 44997:347-44997:353.
- 8804060411 Advises of issuance of Amend 3 to License SUA-1470,deleting Conditions 28 & 29,revising Condition 16 & adding Conditions 32 & 33 to road as listed. SMITH, R.D. Uranium Recovery Field Ofc, R4, 89/03/10. BERGSTROM,P. Atlantic Richlield Co. (ARCO). 3pp. 45019.338-45019.355.
- --8804080415 Amend 3 to License SUA-1470 for Anaconda Minera's Co., detelling Conditions 28 & 29,revising Condition 16 & adding Conditions 32 & 33 as listed. SMITH, R.D. Uranium Recovery Field Ofc, R4, 88/03/10. 10pp, 45019 341-45019:355.
- 8804280174 Forwards 1987 "ALARA Audit Rept (or Bluewater Mill, Grants,NM," conducted on 880219.
 BERGSTROM,P.D. Anaconda Co. (div. of Allantic Richfield Co.). 88/03/14.
 PETTENGILL,H.J. Uranium Recovery Field Orc, R4. 1p. 45276:219-45276:228.
- ~8804280183 "Annual ALARA Audit Rept for Bluewater Mill, Grants, NM."
 SANCHEZ, C., BERGSTROM, P.D. Anaconda Co. (div. of Atlantic Richheld Co.), 88/02/19, 9pp. 45276:220-45276:228.

DOCKET 40-8903 HOMESTAKE MINING CO., GRANTS, NM

- 8804280218 "Semiennual Effluent Monitoring Rept for Jul-Dec 1987." W/ 880225 ttr. KENNEDY.E.E. Homestake Mining Co. 87/12/31. PETTENGILL,H. Uranium Recovery Field Ofc, R4. 45pp. 45266:262-45268:305.
- 8804060349 Forwards rept on progress of const of tallings Impound for 871126-880225. Certification of structure safety & Kuhn rept also encl. No data for percentage of fines & In-place density, since no dike bldg during parlod. KENNEDY, E.E. Homestake Mining Co. 88/03/10. REYNOLOS, S.E. New Mexico, State of. 5pp. 45017:278-45017:282.

DOCKET 40-8904 BP AMERICA, INC./L-BAR URANIUM FACILITY, SALT LAKE

- 8804140236 Application for amend to License SUA-1472, incorporating features of detection monitoring program, per 10CFR40 amended affective 871214. One oversize well location map encl. Fee paid.
 GRISAK, G.E. INTERA Technologies, Inc. 86/02/05. PETTENGILL, H. Uranium Recovery Field Ofc, R4. 51pp. 45117:018-45117:101.
- 8804280538 Forwards soil gamma survey rept prepared by L. Hersloff of Radiant Energy Mgt for L-Bar site Also a table of background levels not Included in rept encl. South grid sampling not completed due to whether as discussed on 880208 meeting. OSBORN,T.G. INTERA Technologies, Inc. 88/02/11. GRACE,S. NRC · No Detailed Affiliation Given. 13pp. 45269.045-45269.057.
- 8804140539 Advises that proposed alternative to enhanced ovaporation sys at L-Bar tailings area below grade evaporation area constructed in Manco shale on east side & within present tailings impoundment area Graphs of pond vot vs time enci.

 GRISAK, Q.E. INTERA Technologies, Inc. 88/02/29. LEWIS,G. Now Mexico, State of. 3pp. 45130.082-45130.064.
- 804080379 Ack receipt of 880205 detection manitoring program amend request Submittal did not confine proposal for background well & point of compliance wells in alluvium. Requested into should be submitted by 880401.

 HAWKINS,E.F. Uranium Recovery Field Otc, R4, 88/03/08. 8P America, Inc. 2pp. 46019:336-45019:337.
- 8804060388 Forwards Figures 3.5 & 6 Inadvertently om/tted from D'Appolonia rept.per 880208 Meeting Item 20 & outstanding issues from 870730 meeting. OSBORN,T.G. INTERA Technologies, Inc. 88/03/08. GRACE,S. Uranium Recovery Field Oto, R4. 4pp. 45029.059-45029.065.
- 8804050370 Forwards transmittel litrs to J Romero re BP America, L-Bar mill site. Current encis apacify what items transmitted W/o enci. GRACE, S. Uranium Recovery Field Ofc, R4. 88/03/11, Cebolleta, NM. 1p. 44997:228-
- 8604060300 Forwards well const data & map w/new well locations & field measurements after initial well development for pH,Clorine & SO4.Detailed chemistry will be forthcoming from quartedly monitoring sample.

 GRISAK, G.E. INTERA Technologies, Inc. 88/03/16. GRACE,S. Uranium Recovery Field Ofo, R4. 13pp. 45018:348-45018:358.
- 8804080016 Forwards L-8ar semiannual environ monitoring rept dtd 880226 & Jan & Feb 1986 groundwater monitoring second semiannual 1987 analysis.W/o encis. GRACE, S. Uranium Recovery Field Oto, R4, 88/03/22. Cebolleta, NM. 1p. 45018:004-
- 8804280536 Proposes meeting specifically for purpose of exploring applications of 10CFR40, App A re ground water monitoring regulations to L-Bar site. GRISAK,G.E. INTERA Technologies, inc. 88/03/26. HAWKINS,E.F. Uranium Recovery Field Oto, R4. 2pp. 45271.063-45271.064.
- 8804280133 Application for amend to License SUA-1472.incorporating Condition 28 re submitted of gamma survey detailing areas of windblown contamination & proposed schedule & methodology for cleanup. Three oversize drawlings enci. Fee paid OSBORN, T.G. INTERA Technologies, Inc. 88/03/30, HAWKINS, E.F. Uranium Recov-ery Field Ofc, R4. 28pp. 45279:292-45279:320.

- 8803080530 Application for amond to License SUA-1473,authorizing plan for proposed groundwater moritoring locations & chemical parameters both upgradient & downgradient of typproduct mattingt areas Fee paid. One oversize plan end. STAUTER.J.C. Quvirs Mining Co. 88/01/29. HAWKINS,E.F. Uranium Recovery Field Ofc, R4. 10pp. 44638:180-44638.190.
- 8804280367 Forwards effluent monitoring rept for Outvira Mining Co Ambrosia Lake,NM mill for 8/0701-1231 Rept Incturies monitoring results for gaseous,particulate,direct radiation, softs,sediment,vegetation 8 water,per Reg Guide 4.14 CLEVELAND,J.E. Outvira Mining Co. 88/02/24, GARCIAP, Uranium Recovery Field Ofc, R4. 1p. 45269:238-45269.339.
- -8804280389 "Effluent Moritoring Rept,Jul-Dec 1987."
 Ouivirg Mining Co. 87/12/31, 105pp 45269:239 45269:339.
- 8804070048 Discusses gentechnical review for Out/tra reclamation plan. Method used to verify integrity must be established & prior to placement of remaining cover,NRC must concur that interim cover acceptable. JACOBY,DL., HAWKINS,E.F. Uranium Recovery Field Ofc, R4. 88/03/08. Uranium Recovery Field Ofc, R4. 7pp. 45043:173-45043:180

- 8804060206 Discusses several deticiencies identified during review of surface water & erosion protection aspects of Outria reclamation plan Plan acceptable upon satisfactory resolution of fisted deficiencies Evaluation en
- -9804060309 "Surface Water Hydrology & Erosion Protection Aspects of Outvira Mining Co Ambrosia Lake Rectamation Plan* 11876 No Detailed Affication Given. 88/03/14, 9pp. 45019-322-45019.330.

- 8804060419 Advises that review of reclamation plan identified several areas where additionally measures necessary to assure long-term stability of reclaimed takings Additional taking and to the second second with the secon
- 8804280310 Requests inclusion of Siste of NM environ improvement dividentially actions pertaining to licensing changes Need for advice & consent prime in divinterest of activities in low level wastes affecting State of CO.

 JONES, New Mexico, State of, 88/03/24. SMITH, D. Uranium Recovery Field Ofc, R4. 1p. 45262:347-45262:347.

DOCKET 40-8907 UNITED NUCLEAR CORP., SANTA FE, NM

- 8804280543 Forwards revised MOU for remodial action at UNC Churchrock U Mill in Mckinfey County,NM.
 HANNESSCHI AGER Environmental Protection Agency. 88/02/22. PETTENGILL,H.
 Uranium Recovery Field Ofc, R4, 11pp. 45269-083-45269.093.
- 8804280251 Forwards elliuent ropt specifying concentration of each principal radionuclide released in unrestricted areas in air perifculate elliuent period of 870701-1231.Data for First & Second Quarters of 1987 & yearly average also enct. MOPALES,E.M. United Nuclear Corp. (subs. of UNC Resources, Inc.), 88/03/01. GARCJA,P. Region 4, Otc of the Cirector, 10pp. 45269.176.45269:185.
- 8804070090 Ack receipt of 880211 response to NRC 880105 lit & violations noted in lasp Rept 40-8907/87-01 on 871203-04. Second violation clied stands. Third violation will be reclassified as open item.
 PETTENGILL,H J. Urenium Recovery Field Otc., R4. 88/03/04, VELASQUEZ,J.A.
 United Nuclear Corp. (subs. of UNC Resources, Inc.). 4pp, 45043:239-45043:242.
- 8804050414 Forwards response to 880219 ltr re feasibility study (FS) on UNC Church-rock U mil EPA believes that proceeding w/FS in govt best interest. HANNESSCHLAGER Environmental Protection Agency. 88/03/09. LANGE,R.H. United Nuclear Corp (subs. of UNC Resources, Inc.). 1p. 45018:358-45019 359.
- 6804060015 Confirms contact w/addressee re J Velasquez 680211 response to notice of violation & advises that licensee will wait for response before preparing written pro-
- cedures.
 MORALES,E.M. UNC Resources, Inc. 88/03/09. GARCIA,P. Uranium Recovery Field Oic, R4. 1p. 45017.360-45017.360.
- 8804280282 Informs that UNG Mining & Milling should submit written request to Navajo Tribal Minerals Dept re 881202 & 870107 requests for permission to enter Navajo Tribal Trust lands to conduct radiological surveys near U mill.

 * Interior, Dept. of, Bureau of Indian Affairs, 88/03/18, FELINSON,C. United Nuclear Corp. (subs. of UNC Resources, Inc.). 3pp. 46285.105.45285:107.
- 8804060143 Forwards comments & request for addf info based on review of 870601 surface water hydrology & erosion protection aspects of Churchrock Milf reclamation plan.Pran deticlent in that costs not provided per 10CFH40,App A,Criteria 9 & 10. HAWKINS,E.F. Urantum Recovery Field Ofc. R4. 88/03/22. VELASQUEZ,J. United Nuclear Corp. (subs. of UNC Resources, Inc.). 16pp. 45018:232-45018:247.
- 8804280210 Forwards fastest version of draft MOU re remedial action at UNC Churchrock, NM U mill site. EPA in process of signing off on MOU. HANNESSCHLAGER Environmental Protection Agency. 88/03/29. PETTENGILL, H. Uranium Recovery Field Ofc, R4. 11pp. 45268 241-45268:251.
- 8804280582 Requests access to allow const & monitoring of wells & access to property so as to be able to monitor certain wells previously constructed by EPA on Section 1. Expeditious approval requested.

 VELASQUEZ, J. H. United Nuclear Corp. (subs. of UNC Resources, Inc.). 88/04/01.

 ZAMAN, A. Navajo Nation. 2pp. 45264:069-45264.070.
- 8804280600 Proposes that United Nuclear Corp & Environ Improvement Div enter Into settlement agreement providing for establishment of schedule for submittal of approvable dischauge plan to ensure compliance w/state law.

 BURKHART,M. New Mexico, State of 88/04765. VELASOUEZ,J. United Nuclear Corp. (subs. of UNC Resources, Inc.). 2pp. 45284:075-45284:076.

licensee decision not to build proposed mill & failings retention sys in designated gegraphical location.

SMITH,R.D. Uranium Recovery Field Ofc, R4 88/03/10. LEWIS,L.E. Chevron R sources Co. 2pp. 45019:331-45019:332.

8804060314 Informs that since licensee does not intend to build facility of design & totation as Econsed. License will be terminated & exemption from fees recommende ROSE HD. PETTENGILL, HJ. Uranium Recovery Field Ofc, R4. 88/03/1 HOLLOWAY, C.J. License Fee Management Branch. 1p. 45018:360-45018-360.

DOCKET 40-8911 MOBIL ALTERNATIVE ENERGY, INC., BOULDER, CO

8804280567 Informs that mod of Discharge Plan DP-26 for Mobil in situ U pilot proje located in Mckinley,NM approved Mod authorizes Mobil to cease groundwater restortion efforts despite continued presence of Molybdenum above WQCC std of 1 mg/MITZELFELT,R. New Moxico, State of 88/03/29, CULLEN,J.F. Mobil Coal Producin Inc. 2pp. 45266:380-45266:381.

DOCKET 40-8913 UNITED NUCLEAR CORP., GALLUP, NM

- 8604260119 Forwards Insp Rept 40-8913/88-01 on 880330.No violations or deviation PETTENGILL,H J. Uranium Recovery Field Ofc, R4, 88/04/15, VELASQUEZ,J. Unite Nuclear Corp. (subs. of UNC Resources, Inc.). 1p. 45254:214-45254:218.
- ***8804260121 Insp. Rept. 40-8913/88-01 on 880330.No violations & deviation noted Major areas inspected main mill bldg, several storago bldgs & yard area whete barrels were previously stored.
 ROSE, HD Uranium Recovery Field Ofc. R4. 88/04/15 4pp. 45254:215-45254:21

DOCKET 40-8938 BUTKIN PRECISION MANUFACTURING, INC., MILFORD, CN

- 8804190330 Discusses Safety Insp. Rept 40-8936/87-01 on 870602,08 & 12 & forward
- notice of violation.
 WHITE, J.P. Region 1, Ofc of the Diractor, 68/04/11, BUTKA, J. Butkin Pracision Ma ufacturing Corp. 2pp. 45215:174-45215.177.
- -8804190332 Notice of violation from Insp on 870602,08 & 12.Violation noted ticenst falled to store Mg-Th scrap in secure area & place survey instruments at major extrom work areas for personnel monitoring.
 Region 1, Otc of the Director, 88/04/11, pp. 45215;176-45215;177.

DOCKET 40-8938 TEXTRON, INC., LOWELL, MA

8904070318 Discusses Telcon Inquiry 88-001 re activities authorized by Licanse SUI 1500.Understands licansed mail never used & not intended for use in near future. KINNEMAN, J.D. Region 1, Ofc of the Director. 88/03/28. KULESZ, T.A. Textron, In 2pp. 45021:229-45021:230.

DOCKET 40-8943 FERRET EXPLORATION CO. OF NEBRASKA, DENVER, CO

- 8804280469 Forwards corrected replacement pages for application & supporting environger for source mail license. Changes made as result of NDEC completeness revier COLLINGS.9. Ferrel Exploration Company of Nebraska, Inc. 88/03/28. GRACE, NRC No Detailed Affiliation Given. 1p. 45268.085-45266.158.
- --8804290085 Errata to application for source mall license & supporting environ rep.
 Ferret Exploration Company of Nebraska, Inc. 88/03/15 76pp. 45266:08

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION **FACILITIES**

DOCKET 50-2 FORD NUCLEAR REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville MD.Official mailing address s remains same & project managers have new locations & phone numbers TS Michae still lead project manager for facility & A Adams will serve as backup RUBENSTEIN_L.S. Standardization & Non-Power Reactor Project Directorate. 68/03 18. Affiliation Not Assigned. 3pp. 44858:322-44856.324.

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8804120337 Forwards revised page to 871214 proposed amend to security plan.Par withheld (ref 10CFR2.790(d) & 73.21). BRAMS 8. Consolidated Edison Co. of New York, Inc. 88/03/30. Document Conte Branch (Document Control Desk). 2pp. 45135;336-45135;337.

P. Operating license stage documents & correspondence

8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal organization charts from Tech Spec administrative control requirements. Svc list en MIRAGLIA, F.J. Associate Director for Projecte (Post 870411), 88/03/22. Consolidat Edeon Co. of New York, Inc. 47pp. 44972:107-44972:153.

- 8804050042 Forwards supplemental environ into re decommissioning of plant,per NRC 860507 & 1215 No significant environ impacts associated w/either current plant status or SAFSTOR alternative proposed in 1980 decommissioning plan. BRAMS.B. Consolidated Edison Co. of New York, Inc. 88/03/28. RUBENSTEIN,L. Standardization & Non-Power Reactor Project Directorate. 2pp. 45032:083-45032-121.
- --8804350051 "Supplemental Environ Into In Support of Indian Point Unit 1."

 * Consolidated Edison Co. of New York, Inc. 88/03/31, 37pp. 45032:085-45032:121.
- 8804190071 Forwards updated decommissioning table for program implementation rept into on standardization design reviews has been provided to S Black. RUBENSTEIN, L.S. Standardization & Non-Power Reactor Project Directorate. 88/03/ 30. VILLAFRANCO,V. Program Management, Policy Development & Analysis Staff (Post 870411). 3pp. 45158:285-45158:287.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGUIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184:237-45184:285.
- 8904260085 Forwards application for amend to Licenses DPR-5 & DPR-26, incorporating administrative changes to organization charts. Fee paid.
 BRAMS B. Consolidated Edison Co. of New York, Inc. 88/04/16. Document Control Branch (Document Control Desk). 1p. 45282:052-45282:061.
- -8804260090 Application for amende to Licenses DPR-5 & DPR-26,amending Tech Spec Figures 3.1,3.2,6.2.1 & 6.2.2 to reflect administrative changes to organization charts. BRAM,S. Consolidated Edison Co. of New York, Inc. 88/04/15. 2pp. 45282:053-45282:054
- -8804260093 Proposed Tech Specs Figures 3.1,3.2,6.2.1 & 6.2.2 reflecting administrative changes to organization charts.

 * Consolidated Edison Co. of New York, Inc. 88/04/15, 7pp, 45282.055-45282.061.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors." Svo list enct. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 88-010, "Mattle Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list encl. CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 870729). 88/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995;363.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Central Ctr &/or Switchboard Function Due to Faulty Tie Bolts." Svc list encl.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/07.
 Consolidated Edison Co. of New York, Inc. 124pp, 45406:292-45407.051.
- 8804060370 NRC Info Notice 88-012, "Overgressing of Electric Motor Bearings," Svo list encl ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150.

R. Periodic operating reports & related correspondence

- 8904110083 Forwards cover ltre transmitting monthly facility discharge monitoring repts for Jul-Dec 1987.Each cover itr accompanied by excerpts from repts which defail excursions from SPDES permit effluent limits. BRONS.J.C. New York Power Authority (formerly Power Authority of the State of New York). 88/04/05. Document Control Branch (Document Control Desk). 3pp. 45170.201-45170.220.
- -8804110091 Discharge monitoring rept for SPDES Permit NY0004472 for Jul 1987. BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/07/31, 3pp. 46170.004-45170:006
- -8804110093 Discharge monitoring rept for SPDES Permit NY0004472 for Aug 1987. BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/08/31, 2pp. 45170.007-45170 008
- --8804110097 Discharge monitoring rept for SPDES Permit NY0004472 for Aug 1987. BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/09/30. 3pp. 45170.009-45170.011.
- -8804110127 Discharge monitoring rept for SPDES Permit NY0004472 for Oct 1987. BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/10/31, 3pp. 45170.012-
- -8804110141 Discharge monitoring rept for SPDES Permit NY0004472 for Nov 1987.
 BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/11/30, 2pp. 45170-016-45170,016.
- -8804110145 Discharge monitoring rept for Dec 1987.
 BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/12/31. 2pp. 45170:017-

S. Reportable occurrences, LERs & related correspondence

- 8804110063 Forwards cover litra transmitting monthly facility discharge monitoring repts for Jul-Dec 1987. Each cover litr accompanied by excerpts from repts which detail excursions from SPDES permit effluent limits.

 BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York).

 88/04/1005. Document Control Branch (Document Control Desk). 3pp. 45170.001-45170.020.
- --8804110091 Discharge monitoring repl for SPDES Permit NY0004472 for Jul 1987. BASILE.J.A. Consolidated Edison Co. of New York, Inc. 87/07/31, 3pp. 45170.004-45170.008.

- ~8804110093 Discharge monitoring rept for SPDES Permit NY0004472 for Aug 1987. BASILE, J.A. Consolidated Edison Co. of New York, Inc. 87/08/31, 2pp. 45170-007-45170:008
- --8804110097 Discharge monitoring rept for SPDES Permit NY0004472 for Aug 1987. BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/09/30. 3pp. 45170.009-45170.011.
- -8804110127 Discharge monitoring rept for SPDES Permit NY0004472 for Oct 1987. BASILE, J.A. Consolidated Edison Co. of New York, Inc. 87/10/31, 3pp. 45170.012-
- --8804110141 Discharge monitoring rept for SPDES Permit NY0004472 for Nov 1987.
 BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/11/30, 2pp. 45170:015-45170 016
- --8804110145 Discharge monitoring rept for Doc 1987, BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/12/31. 2pp. 45170:017-45170:018.

V. Operator Examinations

- 8804250088 Responds to FOIA request for into re-scores of reactor operators & senior reactor operators. Forwards requalification exam summary source sheets listed in encl app w/personal privacy into deletad. GRIMBLEY,D.H. Division of Rules & Records (Post 870413), 88/04/19, BOLEY,K. Public Citizen's Critical Mass Energy Project, 2pp. 45213.003-45213.095.
- 8804260167 Package of NRC administered requalification exem results summary.
 NRC No Detailed Affiliation Given, 87/07/20, 88pp. 45213:007-45213:095.

DOCKET 50-5 PENNSYLVANIA STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address.Me'ling address unchanged.A Adams project manager & TS Michaels back-up project manager. RUBENSTEIN,LS. Standardization & Non-Power Reactor Project Directorate. 88/03/18. Alfallation Not Assigned. 3pp. 44859.060-44859.062.

V. Operator Examinations

- 8604060443 Forwards revised requalification program for NRC review & approval per 10CFR55.59.Oral facility walk around exam oliminated as separate exam & incorporated into operating test, HOSLER,C.L. Pennsylvania State Univ., Harrisburg, PA. 88/03/23. Document Control Branch (Document Control Desk). 1p. 45093.047-45093.055.
- --8804080499 Revised requalification program for operator & senior operator.
 * Pennsylvania State Univ., Harrisburg, PA, 88/03/23, 8pp. 45093-048-45093.055.

DOCKET 50-6 BATTELLE MEMORIAL INSTITUTE RESEARCH REACTOR

P. Operating license stage documents & correspondence

- 8803250248 Informs of NRC relocation to stated address Malling address unchanged A Adams project manager & TS Michaels back-up project manager.
 RUBENSTEIN L.S. Standardization & Non-Power Reactor Project Directorate. 88/03/ 18. Affiliation Not Assigned, 3pp. 44859.060-44859.062.
- 8804280181 Discusses 21 planned shipments of radwaste between 880420- 1231 Shipments should be similar, except for variation in total curie quantity in each shipment. EMSWILER,T.R. Baltelle Manorial Institute. Columbus Laboratorias. 88/04/07. DAVIS,A.B. Region 3, Otc of the Director. 2pp. 45261:304-45281:305.

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8804250078 Rev 1 to Safe Shutdown Procedure DSSP 010-1, "Safe Shutdown Paths for Extensive Plant Damage" & Rev 4 to Emergency Plan Implementing Procedure EPIP 200-20, "Control Room Evacuation/Safe Shutdown...." Revised tables & indices Commonwealth Edison Co. 88/04/07, 300pp. 45251;122-45252;097.

J. Insurance & Indemnity Information

8804120216 Forwards Endorsement 20 to NELIA Policy NF-294.Endorsement 15 to MAELU Policy MF-128,Endorsement 30 to NELIA Policy NF-277,Endorsement 22 to MAELU Policy MF-114 & Endorsement 194 to NELIA Policy NF-43. OSTERJ, Commonwealth Edicard Co. 897.04706. DINITZ,I. Office of Nuclear Reactor Regulation, Director (Post 870411). 13pp. 45090.030-45090:042.

P. Operating license stage documents & correspondence

8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Syc list enci. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.

- 8804190071 Forwards updated decommissioning table for program implementation rept into an alandardization design reviews has been provided to S Black. RUBENSTEINLLS Standardization & Non-Power Reactor Project Directorate. 88/03/30. VILLAFRANCO,V Program Management, Policy Development & Analysis Staff (Post 870411). 3pp. 45158-285-45158-287.
- 8904080088 Geneno Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 1007FRS0.49, "Environ Qualification of Electrical Equip-ment Important to Satety for Nuclear Power Plants." Sye list enot. MRAGUIA,F.J. Associate Director for Projects (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184.237-45164.285.
- 8804280039 Forwards Rev 50 to CE-1-A, "OA Program for Nuclear Generating Stations." Revs being made to tellect organizational changes. MORGAN.W.E. Commonwealth Edison Co. 88/04/18. Document Control Branch (Document Control Desk), 19 45281:273-45261:299.
- -8804280069 Rev 50 to "QA Program for Nuclear Generating Stations" *Commonwealth Edison Co. CE-1-A R50. 88/04/18, 17pp 45261:274-45261;299.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors," Svc list encl. RQSSI,CE Division of Operational Events Assessment [Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:128-44995;246.
- 8803220296 NRC Info Notice 68-010, "Matts Licensees Lack of Mgt Controls Over Licensed Programs "Svc list engl.

 CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 88/
 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44895.353.
- 8804010256 NRC Info Notice 88-011, "Patential Loss of Mator Control Cit &/or Switch-board Function Due to Faulty Tie Botts "Syc list and, ROSSI.CE. Division of Operational Events Assessment (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 124pp. 45406.292-45407.051,
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc hst end.

 Assertional Events Assertional (Post 870411) 88/04/12.

 Consolidated Edison Co. of New York, Inc. 123pp. 45165028-45165:150.

R. Periodic operating reports & related correspondence

- 8804220163 Forwards correction to "Effluent 8 Waste Disposal Semiannual Rept, Jan-June 1987" Estimated percent of major nuclide composition for irredusted components, control rods, etc inadvertently included in rept. No such waste shipped. EENIGENBURGE. Commonwealth Edison Co. 87712718 DAVIS, A.B. Region 3, Ofc of the Director. 1p. 45254:136-45254-137.
- ~8804220165 Corrected "Effluent & Waste Disposal Semiannual Rept. Jan-June 1987."
 * Commonwealth Edison Co. 87/12/31. 1p. 45254:137-45254:137.
- 8804010238 Forwards Part 3 of plant environ radiological & meteorological monitoring rept.W/o encl EENIGENBURG.E. Commonwealth Edison Co. 88/03/18 DAVIS.A.B. Region 3, Ofc of the Director. 2pp. 45058.061-45058.061.
- 8804270052 Forwards corrected radioactive effluent rept for Jul-Dec 1987. Final data for listed elements included EEN/GENBURG, E Commonwealth Edison Co. 88/04/12. DAVIS.A.B. Region 3, Old of the Director, 1p. 45217:241-45217.257.
- --8804200110 Corrected "Effluent & Waste Disposal Semiannuat Rept,Jul Dec 1987." *Commonwealth Edison Co. 87/12/31, 18pp. 45217:243-45217:257.

V. Operator Examinations

- 8804250088 Responds to FOIA request for into re-scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in encliapp w/personal privacy into defeted.
 GRIMSLEY,D.H. Division of Rules & Records (Post 870413), 88/04/19, BQLEY,K. Public Citizán's Cirtical Mass Energy Project, 2pp. 45213-003-45213-095.
- --8604250157 Package of NRC administered requalification exam results summary.
 NRC No Detailed Affidation Given, 87/07/20, 88pp. 45213:007-45213:095.

DOCKET 50-13 BAW CRITICAL EXPERIMENT FACILITY

J. Insurance & Indemnity Information

- 8804070047 Forwards executed Amend 22 to Indemnity Agreement 6-8, terminating
- agreement
 ÖLSEN,A.F. Babcock & Wilcox Co. 88/03/30, ADAMS.A. Standardization & Non-Power Reactor Project Directorate, 2pp. 45030-345-45030-346.

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Making address unchanged A Adams project manager & 15 Michaels back-up project manager. RUBENSTEIN,LS. Standardization & Non-Power Reactor Project Circotorate. 88/03/18. Alfiliation Not Assigned. 3pp. 44859.060-44859.062.

DOCKET 50-16 ENRICO FERMI ATOMIC POWER PLANT, UNIT 1

P. Operating license stage documents & correspondence

8804190071 Forwards updated decommissioning table for program implementation rept finite on standardization design reviews has been provided to S Black. RUBENSTEINLS. Standardization & Non-Power Reactor Project Directorate 68/03/30. VILLAFRANCO, V. Program Management, Policy Development & Analysis Stall (Post 870411). 3pp. 45158:285-45158:287.

DOCKET 50-20 MASSACHUSETTS INSTITUTE OF TECHNOLOGY RESEARCH

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Mailing address unchanged.A Adams project manager & TS Michaels back-up project manager. RVBEN5TEIN1、S. Standerdization & Non-Power Reactor Project Directorate. 88/03/18 AHiliation Not Assigned. 3pp. 44859.060-44859.062

DOCKET 50-22 WESTINGHOUSE TEST REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville,MD.Official mailing address sull remains same & project managers have new locations & phone numbers 15 Michaels still lead project manager for facility & A Adams will serve as backup. RUBENSTEIN,LS.Standardization & Non-Power Reactor Project Directorate. 88/03/18. Affiliation Not Assigned. 3pp. 44856:322-44856:324.

DOCKET 50-27 WASHINGTON STATE UNIV. RESEARCH REACTOR (TRIGA)

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Mailing address unchanged A Adams project manager & TS Michaels back-up project manager. RUBENSTEINLS. Standardization & Non-Power Reactor Project Directorate. 88/03/18. Affiliation Not Assigned. 3pp. 44859-060-44859-062.

V. Operator Examinations

8804190381 Advises that reactor operator licensing exams scheduled for 880623 & 24 Approved rel matt listed in encl should be provided by 880429.Requirements & guidelines also encl. PATE.R.J. Region 5. Oic of the Director, 88/04/08, WILSON,W.E. Washington State Univ., Pullman, WA. 2pp. 45218:089-45218:070.

DOCKET 50-28 YANKEE-ROWE NUCLEAR POWER STATION

F. Security, medical, emergency & fire protection plans

8804130185 Notification of Licensee Requested Meeting 88.40 on 880318 w/util In Region I to discuss licensee actions to improve security program including plans for region 1 to discuss licensee actions to Improve security program including plans for security reorganization.

HAVERKAMP.D.R. Region 1, Otc of the Orrector. 88/03/11. Region 1, Otc of the Director. 2pp. 45122:211-45122:212.

8804050166 Forwards Saleguards Insp Rept 50-029/88-03 on 880208-11.No violations

noted.
noted.
No. Region 1, Ofc of the Director, 88/03/29, DRAWBRIDGE,B.L. Yankee
Atomic Electric Co. 2pp. 45017:198-45017:203.

- --8804050171 Partially withheld Physical Security Insp Rept 50-029/88-03 on 880208-11 (ref 10CFR73.21) No violations noted Mejor areas inspected plan & implementing procedures, physical barriers-protected vital & access control areas.
 MARTIN.W.G., KEIMIG.R.R. Region 1, Ofc of the Director. 89/03/25. 8pp. 45017:198-
- 8803310003 Revised emergency plan implementing procedures including Rev 8 to OP-3300, "Classification of Emergencies." Rev 8 to OP-3305, "Onsite Medical Emergen-cies" 8 OP-3315, "Control Room During Emergency."

 * Yankes Atomic Electric Co. 88/03/31, 400pp. 44967 347-44969:033.

H. General correspondence

8903310201 Comment supporting proposed rule 10CFR50.App J re alternative method for leakage rate testing. Change would remove util of burden of seeking exemption to App J in order to employ more state-of-the-art statistical analyses. EDWAROS.D.W. Yankee Atomic Electric Co. 88/03/23. Docketing & Services Branch. 1p. 44982-360-44982:360.

i. Financial Information

8804080406 "Yankee Atomic Electric Co,1987 Annual Rept." W/880329 lir. PAPANIC,G. Yankee Atomic Electric Co. 87/12/31, 19pp. 45006:299-45006:316.

J. insurance & indemnity information

8804070146 Forwards Endorsements 1 & 2 to NELIA Certificates NW-98, NW-103 & NW-34 respectively, Endorsements 1 & 2 to MAELU Certificates MW-32, MW-62 & MW-8 respectively & Endorsement 140 to NELIA Policy NW-1 & Endorsement 43 to

Policy MF-95.
O'CONOR,D.J. Marsh & McLennan, Inc. 88/03/26. DINITZ,I. Office of Nuclear Reactor Regulation, Director (Post 870411) 67pp. 45098:028 45098:094

8804040149 Informs of present level of nuclear property insurance coverage for facility as of 880401.in accordance w/requirements of 10CFR50.54(w)(4). PAPANIC,G. Yenkse Alomic Electric Co. 88/00/29. Document Control Branch (Document Control Desk). 1p. 45031:283-45031:283.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88.06 to all power reactor licensees & applicants re-removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972.107-44972.153.
- 8803300217 Application for amend to License DPR-3, rovising Tech Spec 3.1.1.1.2 to change shutdown margin switching temp from 490 to 470 F.Fee paid. DRAWBRIDGE,B.L. Yankee Atomic Electric Co. 88/03/23. Document Control Branch (Document Control Desk). 4pp. 44953:137-44953:144.
- -8803300220 Proposed Tech Spec 3.1.1.1.2 reflecting change in shutdown margin switching temp from 490 to 470 F.

 Yankee Atomic Electric Co. 88/03/23. 4pp. 44953:141-44953:144.
- 8803300168 Application for amend to Liconso DPR-3, consisting of Proposed Change 214, revising Tech Specs re-containment isolation barriers. Fee paid. DRAWBRIDGE.RL. Yankee Atomic Electric Co. 88/03/25. Document Control Branch (Document Control Desk). 8pp. 44975:319-44975:331.
- --8803300169 Proposed Tech Specs moutrying containment isolation barriers

 * Yankee Atomic Electric Co., 88/03/25, 5pp. 44975:327-44975:331.
- 880330228 Application for amend to License DPR-3 doloting Mode 5(1) from "Applicable Modes" of Table 3.3-2 & Mode 5" from "Modes in Which Surveillance Required" of Table 4.3-2 for listed items. Fee paid.

 DRAWBRINGE, B. V. Yankee Afomic Electric Co. 88/03/25. Office of Nuclear Reactor Regulation, Director (Post 870411). 3pp. 44953:155-44953:161.
- -8803300230 Proposed Tech Spec Table 3.3-2, "ESF Instrumentation" & Table 4.3-2, "ESF Instrumentation Surveillance Requirements," rollecting deleted Modes 5(1) & 5*, respectively.

 * Yankee Atomic Electric Co. 88/03/25, 4pp. 44953:158-44953:161.

- 8804050201 Notifies that 870916 application for exemption requesting that 10CFR171 FY88 annual fee for facility be reduced granted. Smallness & age of plant, low generating capacity of 175 MWo, among bases for exemption.

 STELLOV. Ofc of the Executive Director for Operations 88/03/20. SOUCYAR. Yankee Atomic Electric Co. 3pp. 44997:077-44997:080.
- 8804140117 Forwards "Cask Drop Analysis Yenkoe Nuclear Power Station Sport Fuel Pool."
 PAPANIC,G. Yankee Atomic Electric Co. 88/03/31, Document Control Branch (Document Control Deak), 1p. 45098;238-45098;268.
- -8804060483 "Cask Drop Analysis Yankee Nuclear Power Station Spant Fuel Pool." RASHID,Y.R., SULLAWAY,M.F., JAMES,R.J. ANATECH Research Corp. 88/03/31. 31pp. 45086:237-45098:266.
- 8804130376 Application for amend to License DPR-3,changing Tech Spec Page 3/4 8-10 re battery chargers to reflect that charger for new battery upgraded to be identical w/existing Battery Chargers 1 & 2 Fee paid. DRAWBRIDGE,B.L._Yankee Atomic Electric Co. 88/04/04. Document Control Branch (Document Control Desk). 3pp. 45192:222-45192:225
- -8804130378 Proposed Tech Spec Page 3/4 8-10 re battery charge * Yankee Atomic Electric Co. 88/04/04, 1p. 46192:225-45192:225.
- 8804140011 Application for amend to Licanse DPR-3,modifying Tech Specs defining incore detection sys as combination sys of both fixed & movable detectors & associated equipment Fee paid. DRAWBRIDGE,BL. Yankee Atomic Electric Co. 88/04/04. Document Control Branch (Document Control Desk). 3pp. 45162.001-46162:119.
- -8804140029 Proposed Tech Specs defining incore detection sys as combination sys of both fixed & movable detectors & associated equipment.

 * Yankee Atomic Electric Co. 88/04/04, 11pp, 45152,004-45152.014.
- -- 8804140031 "Incore Detection Sys Analysis."

 * Yankee Atomic Electric Co. 88/03/31, 104pp, 45152.015-45152;119.
- 8804080088 Generic Ltr 88.07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." See 18st enct. MIRACLIA.F.J. Associate Director for Projects (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804210010 Forwards YAEC-1363, "CASMO-3G Validation." Rept entitled "Simulate-3 Validation & Verification "Will be submitted by 880701 Schedule for submission of plant-specific repts re subj (apts stated Fee paid. PAPANIC, G. Yanke Atomic Electric Co. 88/04/11. Document Control Branch (Document Control Desk). 2pp. 45216:074.45216:174.
- --8804210012 "CASMO-3G Validation."
 DIGIOVINE,A.S., SPINNEY,K.B., NAPOLITANO,D.G. Yankee Atomic Electric Co. YAEC-1363, 88/04/30, 99pp. 45216;076-45216;174.
- 8604220124 Requests that util remit fee for 880105 application for approval of changes to LOCA reflood heat transfer models. Bill will be issued for addit costs for review of application.

 DIGGS.F.M. License Fee Management Branch. 88/04/15. PAPANIC.G. Yankee DIGGS.R.M. License Fee Management Branch. 88/04/16. PAPANIC,G. Yankee Atomic Electric Co., Fp. 45201;023-45201:023.

8804220039 Notification of 880502,03,04 & 05 meeting w/util,EG&G & Cygna Energy Svcs in Walnut Crook,CA to perform audit review of seismic reanalysis of piping supports inside containment FAIR TILE.M Project Directorate I-3, 88/04/18, WESSMAN,R, Project Directorate I-3, 3pp. 45203.49-45200-351,

Q. Inspection reports, IE Bulletins & correspondence

B803210090 Suppl 1 to NRC into Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors," Svc list encl.
ROSSIGE Division of Operational Events Assessment (Post 870411), 88/03/28.
Consoil dated Edison Co. of New York, Inc. 121pp. 44995-128-44995-246.

8803220296 NRC Into Notice 88-010, "Matts Licensees Lack of Mgt Controls Over Li-

cansod Programs " Svo list encl CUNNINGHAM,R E Division of Industrial & Medical Nuclear Salety (Post 870729), 88/ 03/28. Cansolidated Edison Co. of New York, Inc. 108pp. 44995.247-44995.353.

- 8804050188 Forwards Sateguards Insp Rept 50 029/88-03 on 880208-11.No violations
- noted BELLAMY, R.R. Rogion 1, Ofc of the Director, 88/03/29, DRAWBRIDGE, B.L. Yankee Atomic Electric Co. 2pp. 45017:196-45017:203.
- --8804050171 Partially withheld Physical Secunty Insp Rept 50 029/88-03 on 880208-11 (of 10CFR73 21).No violations noted Major areas inspected plan & implementing procedures, physical bartiers protected vital 8 access control areas.

 MARTIN, 9 G., KEIMIG,R.R. Region 1, Ofc of the Director, 88/03/25, 6pp 45017 198-45017:203
- 8804120032 Forwards Rediological Safety Insp Rept 50-029/88-04 on 680208-11. Violation re failure to provide personnel monitoring topts for 37 terminated individuals noted No citation will be made per 10CFR2.

 BELLAMY.R.R. Region 1, Oic of the Director, 88/04/04, DRAWBRIDGE,B.L. Yankee Atomic Electric Co. 2pp. 45151:001-45151.018.
- -8804120042 Insp Rept 50-029/88-04 on 880208-11.Violation noted Major areas controls and the property of the protection of the protection program during routing operations, including status of previously identified figms & mgl controls. MARKLEY,M., GRESICK,J.A., SHANBAKY,M. Region 1, Old of the Director. 88/03/31. 14pp. 45151 003-4515:018.
- 8804010256 NRC Into Notice 88-011, "Potential Lass of Mator Control Cir &/or Switchboard Function Due to Faulty Tie Bolts." See fist encl.

 ROSSI,CE. Division of Operational Events Assessment (Past 870411). 88/04/07.
 Cansolidated Edison Co. of New York, Inc. 124pp. 45406.292-45407.051.
- 8804060370 NRC Info Notice 68-012, "Overgreasing of Electric Motor Bearings." Svc. list enct. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45185:150.

H. Periodic operating reports & related correspondence

- 8804080101 "Efficient & Waste Disposal Semilannual Rept for Titird & Fourth Quarters, 1987,Including Annual Radiological Impact on Man." W/880329 ltr. PAPANIC,G. Yankoo Alomic Electric Co. 87/12/31, 41pp. 45046 088-45046:108
- 880330D342 Monthly operating rept for Jan 1988,W/980210 ltr.
 WHIPPLES, BEFRY,R.L. Yankeo Atomic Electric Co. 88/01/31. 6pp. 44953:145-44953:160.
- 8804180054 Monthly Statistical Rept 88-03 for Mar 1998 W/880407 Nr. WHIPPLE,S., BERRY,R.L. Yankaa Atomic Electric Co. 88/03/31, 6pp 46208-224-

S. Reportable occurrences, LERs & related correspondence

8804200293 LER 88-001-00 on 880126 procedure Inadequacy discovered that could attow Insufficient load testing of emergancy generators Caused by Inadequate procedure review Procedure change notice prepared & test completed W/880415 ftr.
MAY.E.L. ST.LAURENT,N.N. Yankee Atomic Electric Co. 88/04/15. 4pp. 45221-044-45221:047

V. Operator Examinations

- 8804120360 Forwards Roy 2 to "Guidance for Development of Smulation Facility to Maet Requirements of 10CFR55.45," adressing resolution of issues from 871207 meeting w/NRC. KIRBY,MJ. Southern Cafifornia Edison Co. 88/04/05. Document Control Branch (Document Control Dask). 2pp. 45088:265-45088.345.
- --8804120478 Rev 2 to "Guidance for Development of Simulation Facility to Meet Requirements of 10CFR55,45."
 'Southern Cattorria Edison Co. * Public Service Co. of Coforado. * Consumers Power Co. 88/03/31, 79pp. 45088:267

DOCKET 50-30 PLUM BROOK RESEARCH REACTOR FACILITY

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Mailing address unchanged A Adams project manager & TS Michaels back-up project manager. RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate, 88/03/ 18. Affiliation Not Assigned. 3pp. 44859.060-44859.062.

DOCKET 50-47 ARMY MATERIALS RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Maring address unchanged A Adams project manager & TS Michaels back-up project manager. RUBENSTEIN,LS, Standardization & Non Power Reactor Project Directorate, 88/03/ Altihation Not Assigned, 3pp. 44859,060-44859,082.

DOCKET 50-54 CINTICHEM

F. Security, medical, emergency & fire protection plans

P. Operating license stage documents & correspondence

8893250184 informs of relocation of NRR to Rockville,MD Official mailing address still remains same 8 project managers have new locations 8 phone numbers.TS Michaels still lead project manager for facility 8 A Adams will sorve as backup. RUBENSTEIN.L.S. Standardragtion 8 Non-Power Reactor Project Orectorate. 88/03/18. Affiliation Not Assigned. 3pp. 44856 322-44856.324.

DOCKET 50-57 BUFFALO MATERIALS RESEARCH CENTER

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Flocky, IIe, MD Official mailing address still remains same & project managers have new flocations & phone numbers TS Michaels still tead project manager for facility & A Adams will serve as backup.
RUBENSTEINLS, Standardization & Non-Power Fleactor Project Directorate. 88/03/ Affiliation Not Assigned. 3pp. 44856.322-44856-324.

Q. Inspection reports, IE Builetins & correspondence

8804060096 Forwards Exam Rept 50:057/68-01OL of exam administered during wk of

68420. R.M. Region 1. Ofc of the Director. 88/03/28. RENNIE, D.W. New York, State Univ. of, Albany, NY, 2pp. 45047;286-45047327.

-8804060103 Exam Rept 50 057/88-010L on 880209-10.Exam results two reactor operator candidates passed written & operating exams.
NORRIS,B.S., ESELGROTH,P.W. Region 1, Oic of the Director, 88/03/24, 60pp 45047 268 45047 327

V. Operator Examinations

8904060096 Forwards Exam Rept 50-057/88-01OL of exam administered during wik of 880208. GALLO,R M. Region 1. Ofc of the Director, 68/03/28 RENNIE,D.W. New York, State Univ. of, Arbany, NY, 2pp 45047;286 45047 327.

-8804060103 Exam Rept 50 057/88 01OL on 880209-10 Exam results two reactor operator candidates passed written & operating exams.

NOHRIS, B.S., ESELGROTH, P.W. Region 1, Ofc of the Director, 88/03/24, 60pp.

DOCKET 50-59 TEXAS A&M UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NAR to Rockvilla,MD Official mailing address still remains same & project managers have new locations & phone numbers. TS Michaels still lead project manager for facility & A Adams will serve as backup.

RUBENSTEIN L. S. Standardization & Non-Power Reactor Project Directorate, 88/03/18 Affiliation Not Assigned, 3pp. 44856 322-44856 324.

DOCKET 50-62 UNIV. OF VIRGINIA RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803080467 Clarifies & roddfinos request made in Jan 1998 that NRC view 880205 OA/ OC Plan as info item.Licensee will abide by NRC approved App 1 pending approval of Co-Pierri de Implication (Control Control Con

8803250248 Informs of NRC refocation to stated address.Mailing address unchanged.A Adams project manager & TS Michaels back-up project manager. RUBENSTEIN,L.S. Slandardization & Non-Power Reactor Project Cirectorate, 88/03/18. Affiliation Not Assigned, 3pp. 44858 060-44859:062.

8803310227 Provides low enriched U fuel conversion schedule proposal. Licensee decided to forgo conversion of reactor on 870227 & instead submitted a dismantlement plan at start of 1988. NRC decision re-dismantlement pending MULDER,R U. Virgin'a, Univ. of, Charlottosville, VA. 86/03/25. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 45031:104.45031:110.

--8804070190 "Proposal for Conversion of Univ at VA Nonpower 2 MWt Univ of VA Research Reactor from Highly Enriched U to Low Enriched U Fuel." MULDER, R.U. Virginia. Univ. of, Charlottesville, VA. 88/03/31, MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 6pp. 45031:f05-45031:110.

8804290217 Forwards Amend 16 to License R-66 & safety evaluation Amend clarifes possession, storage & use in Univ of Virginia reactor pool of up to Co-60 in form of doubly encapsulated rod squrces.

ADAMS.A. Standardization & Non-Power Reactor Project Directorate 88/04/25.

MUI.DER.R.U. Virginia, Univ. of, Charlottesville, VA 3pp. 45324:326-45324:337.

-8804290245 Amend 16 to License R-66,claritying possession.storage & use of Univ of Virginia reactor pool of up to 70,000 Ci Co-60 in form of doubly encapsulated tod RUBENSTEIN, L.S. Standardzation & Non-Power Reactor Project Directorate 89/04/

25. 6pp. 45324:328-45324:334.

--8804290247 Safety evaluation supporting Amend 16 to License R-66.
- Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/25 3pp. 45324.335-45324:337.

Q. Inspection reports, IE Bulletins & correspondence

8804080367 Advises that licensee will not request further hearings re imposition of civ. penalty in amount of \$1,250.Remits fee.
MULDER,R.U. Virginia, Univ. of, Charlottesville, VA. 88/03/25 Ofc of Enforcement (Post 870413), 1p. 45006.322.45006.322.

8804080008 Ack receipt of 880325 lit & payment for civil penalties in amount of \$1,250 Corrective actions will be examined during future Insps. LIEBERIMAN_J. Ofc of Enforcement (Post 870413). BB/04706 STARKE,E.A. Virginia, Univ. of, Charlottesville, VA. 1p. 45098:151-45098:151.

DOCKET 50-70 GENERAL ELECTRIC NUCLEAR TEST REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville, MD.Official mailing address still remains same & project managers have new locations & phone numbers. TS Michaels shill lead project manager for facility & A Adams will serve as backup. AUBENSTEIN, L.S. Standardization & Non-Power Reactor Project Directorate. 88/03/16. Alfiliation Not Assigned. 3pp. 44856:322-44856.324

DOCKET 50-72 UNIV. OF UTAH RESEARCH REACTOR

H. General correspondence

8804080459 Informs that fisted personnel make up new reactor operations staff at TRIGA (R-126) & AGN (R-25) reactors. SANDQUIST,G.M. Utah, Univ. of, Saft Lake City, UT. 88/03/03. SEIDLE,W.C. Region 4, Ofc of the Director. 1p. 45076:174-45076:174.

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address. Mailing address unchanged. A Adams project manager & TS Michaels back-up project manager. RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate. 88/03/ 18. Affiliation Not Assigned. 3pp. 44859.060-44859.062.

Q. Inspection reports, IE Bulletins & correspondence

8804060437 Confirmation of Action Ltr CAL 88 08 on 880329 telcon w/ RL Bangari re 880216-19 Insp & 880328 enforcement conference. Understands that reactors will remain shut down until Region IV reviews response to apparent violations MARTIN.R.O. Region 4, Oic of the Director. 88/03/30. BROPHY.J.J. Utah, Univ. of, Salt Lake City, UT. 2pp. 45010:346-45010:347.

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville MD Official mailing address still remains same & project managers have new locations & phone numbers TS Michaels still lead project manager for facility & A Addems will serve as backup. RIJBENSTEIN,L.S. Stendardization & Non-Power Reactor Project Directorate. 88/03/18. Altiflation Not Assigned. 3pp. 44856.322-44856:324.

DOCKET 50-77 CATHOLIC UNIV. OF AMERICA RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Malling address unchanged A Adems project manager & TS Michaels back-up project manager. RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate, 88/03/ 18. Affiliation Not Assigned 3pp. 44859.060-44859.062.

DOCKET 50-83 UNIV, OF FLORIDA TRAINING REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville,MD.Official mailing address still remains same & project managers have new locations & phone numbers.TS Michaels still load project manager for facility & A Adams will serve as backup RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate. 18. Attiliation Not Assigned 3pp. 44856.322-44856:324.

- 8804050177 Forwards updated proposal re requirements of 10CFR50.64(c)(2) Updated proposal includes certification that funding for conversion available through DOE & tentative conversion schedule based on fuel availability. VERNETSON,W.G. Fronda, Univ. ol, Gainesville, FL. 89/03/22. Office of Nuclear Reactor Regulation, Director (Post 870411): 1p. 44996:103-44996:118.
- --8804050189 "Proposal Submitted to NRC to Meet 10CFR50.64 Requirements for Updating Scheduling of Univ of Florida Teaching Reactor Conversion From High Enriched U to Low Enriched U Fuel." VERNETSON, W.G. Florida, Univ. of, Galnesville, Ft. 88/03/22. 15pp. 44998:104-44996:118

Q. Inspection reports, IE Bulletins & correspondence

- 8804150335 Forwards Insp. Rept 50-083/88-01 on 880314-17 & notice of violation. COLLINS,D.M. Region 2, Ofc of the Director. 80/04/07. TULENKO,J.S. Florida, Univ. of, Gainesville, FL. 2pp. 45175:103-45176:118.
- ~8804150344 Notice of violation from insp on 880314-17. Violation noted: licensee falled to conduct adequate surveys to evaluate extent of radiation hazards present in liquid & gaseous effitients released from facility.

 COLLINS,D.M. Region 2, Otc of the Director. 88/03/07. 2pp. 45175:105-45175:106.
- -8804150349 Insp Rept 50-083/88-01 on 880314-17. Violations noted Major areas inspected onsite review of radiation protection, environ surveillance & monitoring transportetion activities, enforcement issues & NRC Into notices. KUZO,G 8., HOSEY,C M. Region 2, Ofc of the Director. 88/04/04. 10pp. 45175:116.

S. Reportable occurrences, LERs & related correspondence

- 8804010034 RO advising that Safety Channel 1 circuit failure, described in 880315 ltr, recurred during power run conducted as final requirement set prior to returning to normal operations. Failed feedback noise-controlling capacitor replaced. VERNETSON,W.G. Florids, Univ. of, Galnewille, FL, 88/03/18, GRACE,J.N. Region 2, Oic of the Director, 1p. 45010:074-45010:074.
- 8804080192 Reportable occurrence:on 880314,safety channel 1 circuit failed to provide proper power indication for several seconds on two occasions. Caused by capacitor failure. Capacitor replaced w/substitute of different mtg. VERNETSON.W.G. Florida, Lufiv. of, Galineswille, FL. 88/03/28. GRACE, J.N. Region 2, Ofc of the Director. 7pp. 45084:200-45084:208.

∀. Operator Examinations

8804010120 Advises that reactor operator & senior operator licensing written exams scheduled for wk of 880520 & oral exams scheduled for 880601-02.List of required ref matts & rules & guidelines enct.Info requested 60 days prior to exams.

JULIAN.C.A. Region 2, Ofic of the Director 88/03/17, WETHINGTON,J.A. Florida, Univ. of, Gainesville, Ft.. 10pp. 45031:124-45031:133.

DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville, MD.Official mailing address abili remains same & project managers have new locations & phone numbers. TS Michaels still lead project manager for facility & A Adams will serve as backup. RUBENSTEIN, L.S. Standardzation & Non-Power Reactor Project Directorate, 68/03/18. Affiliation Not Assigned. 3pp. 44856:322-44856:324.

W. Decommissioning Stage Documents & Correspondence

- 8804190043 Forwards "Westinghouse Nuclear Training Reactor Decommissioning Rept," presenting results of termination radiation survey. Westinghouse has completed dismaniling of reactor per 870708 dismaniling plan.
 NARDI, J. Westinghouse Electric Corp. 88/04/11. Region 3, Ofc of the Director. 2pp. 45199:092-45199:187.
- -9804190051 "Weslinghouse Nuclear Training Reactor Decommissioning Final Rept." Weslinghouse Electric Corp. 88/04/30, 94pp. 45199:094-45199:187.

DOCKET 50-89 GENERAL ATOMIC CO.

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Meiling address unchanged. A Adams project manager & TS Michaels back-up project manager. RUBENSTEIN,L.S. Standardzation & Non-Power Reactor Project Directorate. 88/03/18, Affiliation Not Assigned. 3pp. 44859-080-44859-082.

DOCKET 50-97 CORNELL UNIV. ZERO POWER REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville,MD.Official mailing address still remains same & project manager to have new locations & phone numbers. TS Michaels allil lead project manager for facility & A Adams will serve as backup.

RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate. 88/03/18. Athibation Not Assigned. 3pp. 44856:322-44858:324

O. Inspection reports, IE Bulletins & correspondence

- 8804120242 Ack receipt of 880229 ftr informing NRC of steps taken to correct violations noted in Inap Repts 50-097/87-02 & 50-157/87-02 BELLAMY,R.R. Region 1, Ofc of the Director, 88/04/04, STREETT,W.B. Cornell Univ., thaca, NY, 2pp. 45078-316-45079-318.
- 8804120249 Responds to NRC 880129 ltr re violations noted in Insp on 871117-20.Contective actions quarterly inventory & teak testing of sources by old of environ

CLARK,D.D, Cornell Univ., Ilhace, NY. 88/02/29. MARTIN,T.T. Region 1, Ofc of the Director. 1p. 45079:318-45079:318.

DOCKET 50-99 BABCOCK & WILCOX TEST REACTOR

J. Insurance & Indomnity Information

8804070047 Forwards executed Amend 22 to Indemnity Agreement B-8, terminating agreement.
OLSEN.A.F. Babcock & Wilcox Co. 88/03/30. ADAMS.A. Standardization & Non-Power Reactor Project Directorate. 2pp. 45030;345-45030.346.

DOCKET 50-112 UNIV. OF OKLAHOMA RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville,MD.Official mailing address still remains same & project managers have new locations & phone numbers.TS Michaels still lead project manager for facility & A Adams will serve as backup. RUBENSTEIN,L.S. Standardzeitlon & Non-Power Reactor Project Directorate. 88703718. Affiliation Not Assigned. 3pp. 44856;322-44856;324.

DOCKET 60-113 UNIV. OF ARIZONA RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8804070161 Responds to violations noted during Insp of License R-52 on 880125-26.Corrective actions addendum to 1987 annual exam prepared & all operators suc-Cossifully completed exam.

SMERDON,E.T. Arizona, Univ. of, Tucson, AZ. 88/03/29. Document Control Branch (Document Control Desk). 4pp. 45075.030-45075.033.

P. Operating license stage documents & correspondence

- 8603250184 Informs of relocation of NRR to Rockville,MD.Official mailing address still remains same & project managers have new locations & phone numbers.TS Michaels shill lead project manager for facility & A Adams will serve as backup RUBENSTEIN,L.S. Stendardzation & Non-Power Reactor Project Directorate, 88703718. Affiliation Not Assigned, 3pp. 44856:322-44856:324.
- 8804280405 Reminds that OL R-52 for Univ of Arizona TRIGA reactor facility scheduled to expire on 881120 & provides guidance for preparing application for renewal of license All listed documentation should be included as part of application. MICHAELS,T.S. Standardization & Non-Power Reactor Project Directorate, 88/04/21, NELSON,G.W. Arizona, Univ. of, Tucson, AZ. 8pp. 45270.288-45270:293.

Q. Inspection reports, IE Bulletins & correspondence

- 8804070161 Responds to violations noted during insp of License R-52 on 880125-26.Corrective actions addendum to 1987 annual exam prepared & all operators suc-SMERDON,E.T. Arizona, Univ. of, Tucson, AZ, 88/03/29. Document Control Branch (Document Control Desk). 4pp. 46075:030-45075:033.
- 8804200477 Ack receipt of 880320 ltr informing NRC of steps taken to correct violations noted in Insp. Rept 50-113768-01. Corrective autions will be verified during future insp. WENSLAWSKI,F.A. Region 6, Oic of the Director, 88/04/08. SMERDON,E.T. Arizona, Univ. of, Tucson, A2. 1p. 45174:347-45174:351.

V. Operator Examinations

8804070161 Responds to violations noted during lnsp of License R-52 on 880125-26.Corrective actions:addendum to 1987 annual exam propared & all operators successfully completed exam.

SMERDON,E.T. Arizona, Univ. of, Tucson, AZ. 88/03/29. Document Control Brench (Document Control Desk). 4pp. 45075:030-45075:033.

DOCKET 50-116 IOWA STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of refocation of NRR to Rockville,MD.Official mailing address still remains same & project manager is have new locations & phone numbers.TS Michaels atili lead project manager for facility & A Adams will serve as backup. RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate. 8B/03/18. Aftiliation Not Assigned. 3pp. 44895:322-44858:324.

DOCKET 50-123 UNIV. OF MISSOURI RESEARCH REACTOR-ROLLA

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Meiling address unchanged A Adams project manager & TS Michae's back-up project manager. RUBENSTEIN,L.S Standardstaton & Non-Power Reactor Project Directorate. 88/03/18. Affiliation Not Assigned. 3pp. 44859;060-44659-062.

Q. Inspection reports, IE Bulletins & correspondence

8804190297 Submits ardendum to 871222 ftr re additions & changes to Std Operating Procedure SOP 600, "Lab Rulos," per 880127 felcon. Believes that Lavel 4 citation is too stringent for nature of violation.

SOLON, A.E. Missoun, Univ. of, Rota, MO. 88/02/10. SHAFER, W.D. Region 3, Ofc of the Director. 1p. 45217:258-45217:263

-8804190351 Revised Std Operating Procedure SOP-600, "Lab Rules." BONOR, BOLONIA. Missour. Univ. of, Rol'a, MO 88/02/10. 5pp. 45217:259-45217:259

8804190335 Advises that whench minor mods to SOP-600, treasee 871222 & 880210 responses satisfactorily address NRC concerns. Severity level assigned to violation revised from IV to V based on additinfo SHAFER, W.D. Region 3, Otc. of the Director 88/04/11, BOLON, A.E. Missouri, Univ. of, Rolla, M.O. 2pp. 45225-281-45225-285.

--8804190337 Responds to NRC 871124 litrite violations noted in safety irisp of facility Citation improper & should be dismissed based on inspector using out-of-date Procedure SOP 600 & treating SOP matters as Tech Spec matters.

BOLONA E. Missouri, Univ. of, Rolla, MO: 67/12/22. SHAFER,W.D. Region 3, Old of the Director, 2pp. 45225 263-45225-285.

V. Operator Examinations

8804290109 Forwards request for additinto re-revised operator requalification program for univ submitted on 880310 Univ asked to note that 10CFR55,App A superseded by 10CFR55.59, per Generic Ltr 87-07 Requests response within 30 days.
ADAMS,A. Standardzation & Non-Power Reactor Project Directorate. 88/04/22. STRAKA,M. Missoun, Univ. of, Rolla, MO. 4pp. 45322:218-45322.221.

DOCKET 50-124 VIRGINIA POLYTECHNIC INSTITUTE TRAINING REACTOR

P. Operating license stage documents & correspondence

8803250164 Informs of relocation of NRR to Rockville,MD Official maring address still remains same & project managers have now locations & phone numbers. TS Michaels still lead project manager for facility & A Adams will serve as backup.

All:BENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate. 88/03/18. All:hation Not Assigned. 3pp. 44856:322-44856-324.

DOCKET 50-128 TEXAS A&M UNIV. RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8804060027 Forwards Insp Rept 50-128/68-01 on 880307-09 Enforcement conference scheduled for 830405 to discuss violations & corrective actions.per 860323 telcon. CALLAN.L.J. Region 4, Old of the Director, 88/03/30. RICHARDSON.H H. Texas A&M Univ., College Station, TX. 2pp. 45034:123 45034:138.

-8804060031 Insp Rept 50-128/68-01 on 880307-09 Five violations noted. Major areas inspected licensee radiation protection, emergency planning, nuclear matt safeguards & Physical security programs.

CHANEY HO., MURRAY, HO. Region 4, Old of the Director. 88/03/30, 14pp

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville.MD Official malling address still temains same & project managers have new locations & phone numbers.TS Michaels still lead project manager for facility & A Adams will serve as backup. RUBENSTEIN,L S. Standardzation & Non-Power Reactor Project Directorate 88/03/18. Affiliation Not Assigned. 3pp. 44856:322-44856.324

8804220190 Forwards Amend 11 to License R-83 & safety evaluation. Amend modifies title of one position in organizational structure for station.

MICHAELS I.S. Standardization & Non-Power Reactor Project Directorate 88/03/23.

RICHARDSON,H.H. Texas A&M Univ., College Station, TX. 3pp. 45201:090-45201.090

-8804220102 Amend 11 to License R-83 modifying title of one position in organizational Structure for station.

RUBENSTEIN.LS. Standardization & Non-Power Reactor Project Directorate. 88/03/23. 4pp. 45201:093-45201:098.

--8804220103 Safety evaluation supporting Amend 11 to License R-83,

Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/23, 2pp. 45201.097-45201.098

Q. Inspection reports, IE Builetins & correspondence

8804130238 Provides into re unresolved Item 8701-03 in Insp. Rept 50-128/87-01 on add) pipe tap to auxiliary waste tank, Changes to SOP VII-C-8, "Radioactive Liquid Waste Sys." re addition of pipe tap planned for submittal at next meeting. FELT2, D.E. Texas A&M Univ. Collage Station, TX. 88/03/21, CHANEY,H. Region 4, Otc of the Director, 2pp. 45122:193-45122.194.

8804060027 Forwards Insp. Rept 50-128/88-01 on 880307-09 Enforcement conference scheduled for 880405 to discuss violations & corrective actions.por 880323 telecric CALLANI, J. Regon 4, Olic of the Director 88/03/30, RICHARDSON,H.H. Toxas A&M Univ., College Station, TX. 2pp. 45034:123-45034:138.

-8804060031 Insp Rept 50 128/88 01 on 880307.09 Five violations noted. Major areas inspected icensee radiation protection, emergency planning, nuclear matt sateguards & physical security programs.

CHANEY,HD, MURRAY,HD Region 4, Oic of the Director. 88/03/30. 14pp 45034;125-45034;126

8804110137 Notification of 880405 meeting willicensee at Region IV old for enforce ment conference Agenda enci.

YANDELLI, A. Region 4, Otc of the Director, 88/03/30, Region 4, Otc of the Director, 3pp. 45077:321-45077:323.

R. Periodic operating reports & related correspondence

8804060023 "Twenty-Fourth Progress Rept of Texas A&M Univ Nuclear Science Cir,1987," W7880331 Nr. CRAWFORD,K.C., DAVIS,J.W., KROHN,J.L. Texas A&M Univ., College Station, TX ORO-4207-20, 87712731, RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate, 93pp. 45032:199-45032:291.

DOCKET 50-131 OMAHA VETERANS ADMINISTRATION HOSPITAL RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8804220017 Requests review of 880303 changes to Sections 7.2.2.1.1 & 8.5.4 of Omaha Velerans Administration TRIGA reactor emergency plan affecting radiation protection program. Comments on accopitability requested by 880520.
RUBENSTEIN,L.S. Standardization & Non-Power Pacator Project Directorate. 88/04/14. MURRAY,B. Region 4, Olc of the Director. 2pp. 45200.274-45200:275.

P. Operating license stage documents & correspondence

8903250248 Informs of NRC relocation to stated address.Mailing address unchanged A Adams project manager & TS Michaels back-up project manager. RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate. 88/03/18. Affiliation Not Assigned. 3pp. 44859.060-44859:062.

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

I. Financial information

8804120409 "PG&E 1987 Annual Rept." W/880406 Itr. CLARKE,R.A., LOCKE,R.F. Pacific Gas & Electric Co. 87/12/31, 52pp. 45154:003-45154-056

P. Operating license stage documents & correspondence

8803240426 Generic Ltr 88-08 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIA.F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.

8804190071 Forwards updated decommissioning table for program implementation replants on standardization design reviews has been provided to S Black. RUBENSTEINLLS. Standardization & Non-Power Reactor Project Directorate. 88/03/30. VILLAFRANCO,V. Program Management, Policy Development & Analysis Staff (Post 870411). 3pp. 45158:285-45158:287.

8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svo list encl. MIRAGLIA,F J. Associate Director for Projects (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184,237-45184,285.

8804260216 Forwards Rev 4 to "Humboldt Bay Power Plant Unit 3 SAFSTOR QA Plan." Revs listed.
SHIFFER.J.D. Pacific Gas & Electric Co. 88/04/21. Document Control Branch (Document Control Desk). 1p. 45282:065-45282.075.

-6804260234 "Pacific Gas & Electric Co, Humboldt Bay Power Plant, Unit 3 SAFSTOR Pacific Gas & Electric Co. 88/04/30, 10pp. 45282.086-45282.075.

O. Inspection reports, IE Bulletins & correspondence

8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list encl.
ROSSI,C.E. Division of Operational Events Assessment (Post 670411), 88/03/28.
Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.

8803220296 NRC Info Notice 88-010, "Matts Licensees:Lack of Mgt Controls Over Li-censed Programs" Svc ligt enct. CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 88/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995:353.

8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svc list enct. ROSSICE. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 46406:292-45407.051.

R. Periodic operating reports & related correspondence

8803290362 "Rept of Recorded Personnel Whale Body Exposures for 1987." W/ SHIFFER,J.D. Pacific Gas & Electric Co. 87/12/31. 2pp. 44976.250-44975.251.

8803290368 "1987 Tabulation of Personnel Exposure." W/880324 ltr. SHIFFER,J.D. Pacific Gas & Efectric Co. 87/12/31. 3pp. 44920.024.44920.026.

DOCKET 50-134 WORCESTER POLYTECHNIC INSTITUTE RESEARCH REACTOR

P. Operating ilcense stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockwille, MD Official mailing address still remains same & project managers have now locations & phone numbers. TS Michaels still lead project manager for facility & A Adams will serve as backup. RUBENSTEIN,LS. Standardization & Non-Power Reactor Project Directorate 88/03/18. Affiliation Not Assigned. 3pp. 44856;322-44856;322

DOCKET 50-139 UNIV. OF WASHINGTON RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville,MD.Official mailing address still remains same & project managers have new locations & phone numbors.TS Michaels still feed project manager for facility & A Adams will serve as backup. RUBENSTEIN,L.S. Standardzeitaina & Non-Power Reactor Project Oxectorate, 88/03/18 Alfihiation Not Assigned 3pp. 44856 322-44856 324.

DOCKET 50-142 UCLA TRAINING REACTOR

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated artifrees. Malling address unchanged. A Adams project manager & TS Michaels back-up project manager. RUBENISTEIN,L.S. Standardization & Non-Power Reactor Project Directorate. 88/03/18. Affiliation Not Assigned 3pp. 44859-060-44859-062.

W. Decommissioning Stage Documents & Correspondence

8804190302 Forwards responses to Questions 9-15 & Phase I of summary rept disman-llement of reactor,per NRC 860312 lir. Phase II plan under development. MCLAUGHLIN,J.E. California, Univ. of, Les Angeles, CA. 88/04/12. ADAMS,A. NRC -No Detailed Alfidation Gwen, 28pp. 45225;286-45225,313.

DOCKET 50-146 SAXTON NUCLEAR EXPERIMENTAL FACILITY

J. Insurance & Indomnity Information

8804040167 Forwards Endorsoment 93 to NELIA Policy NF-107.
FARRELL,E. Marsh & McLennan, Inc. 68/03/29, DINIT2,I. Office of Nuclear Reactor Regulation, Director (Post 870411). 3pp. 45058:188-45058;190.

8804200211 Forwards Endorsements 1 & 2 to NELIA Certificate NW-49 & MAELU Cer-

tricate MW-134.

HOFFMANJ, Marsh 8 McLennari, Inc. 88/04/07, DINITZ,I. Office of Nuclear Reactor Regulation, Director (Post 870411). 41pp. 45177:208-45177:248.

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Mailing address unchanged A Adams project manager & TS Michaels back-up project manager. RUBENSTEINL S Slandardzalion & Non-Power Reactor Project Directorate. 88/03/ 18. Affiliation Not Assigned. 3pp. 44859.060-44859:062.

S. Reportable occurrences, LERs & related correspondence

8804130084 RO:on 880303, during first quarterly inspired 1988, water noted to have collected in containment vessel sump. Hadiotectopic analysis of water revealed that containment vessel sump. Hadiotectopic analysis of water revealed that contamination exceeded 10CFR20 limits for unrestricted release.

HEWARD, RW. Saxton Nuclear Experimental Corp. 88/04/05. Document Control Branch (Document Control Desk). 3pp. 45100-022-45100-024. 88/04/05. Document Control

DOCKET 50-148 UNIV. OF KANSAS RESEARCH REACTOR

P. Operating license stage documents & correspondence

6803250248 Informs of NRC relocation to stated address Mailing address unchanged A Adams project manager & TS Michaels back-up project manager. RUBENSTEIN, L.S. Standardization & Non-Power Reactor Project Directorate, 88/03/ Alfillation Not Assigned. 3pp. 44859:060-44859-062.

8804060466 Ack recept of 880314 changes to physical security plan for protection of SNM of moderate strategic significance Changes consisted w/provisions of 10CFR80.54(p) & acceptable except for items identified in and MALLET, B.S. Region 3, Oic of the Director, 88/03/31, REDMOND, R.F. Ohio State Univ., Columbus, OH 2pp 45007.078-45007.079.

P. Operating license slage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville,MD.Official mailing address still romains same & project managers have new locations & phone numbers TS Michaels still lead project manager for facility & A Adams will some as backup. PUBENSTEINLLS. Standardization & Non-Power Reactor Project Directorate. 86/03/18. Athliation Not Assigned. 3pp. 44856 322-44856;324.

6804060421 Forwards questions to change in operating power for research reactor. MICHAELS,T.S. Standardization & Non-Power Reactor Project Directorate, 68703730, REDMOND,R.F. Ohio State Univ., Columbus, OH. 18pp. 44997.313-44997:330.

DOCKET 50-151 UNIV. OF ILLINOIS RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Mailing address unchanged A Adams project manager & TS Michaels back-up project manager. RUBENSTEIN,L S Standardization & Non-Power Rocator Project Directorate. 88/03/18 Afrikation Not Assigned. 3pp. :14859.060 44850.062

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

8804060020 Forwards app to SALP 7 Board Rept 50-155/87-01 for Apr 1986 - Aug DAVIS.A B. Region 3, Oic of the Director, 88/03/30. HEINS.G.L. Consumers Power Co. 2pp. 45028:326-46028:344.

--8804060029 App to SALP 7 Spard Rept 50-155/87-01 for Apr 1986 - Aug 1907.
* Region 3, Old of the Director, 88/03/30, 4pp. 45028.328-45028.337.

8804280412 Final response to FOIA request for documents.Forwards App C documents Documents partially withheld (ref FOIA Exemptions 7.6 & 3). GRIMS1EY,D. Division of Rules & Rocords (Post 870413). 88/04/21. MAXWELL,8, Cosmos Broadcasting Corp. 3pp. 45269.346.45270 006.

--8804280437 Partially willihold Insp. Rept 87010 response.Deficiencies re security dept & valve temporing discussed.Related into encl.

* Consumors Power Co. 87/10/08, 12pp. 45269:351-45270,008.

H. General correspondence

8804280091 Informs of corporate & organizational changes due to resignation of JF Paquette OW Buckman replaces JF Paquette as President & Chief Operating Cilicor.QL Hoins Vice President of Energy Supply.

BERRY,K.W. Consumers Power Co. 88/04/10. Document Control Branch (Document Control Desk). 4pp. 45261:300-45261:303.

P. Operating license stage documents & correspondence

8803100002 Forwards request for add into to util 971109 Tech Spot change request reflecting features & terminology used whow out-of-core power range nuclear instru-nientation described in GE Topical Ropt NEDO-31399. SCOTT,W.E. Project Directorate III-1. 88/03/07. BERRY,K.W. Consumure Power Co. 3pp 44681:022-44681:024.

8803240426 Generic Lir 68 06 to all power reactor licensess & applicants re removat of organization charts from Tech Spee administrative control requirements Svc 1st encl. MRAGLIAF. J. Associate Director for Projects (Post 870411), 88/03/22, Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.

8803300044 Forwards application for amend to License OPR-6,changing Tech Speca ro Itequency of reactor depressurization sys (lepressurizing valve testing by oliminating quarterly partial stroke test. BERRY.K.W. Consumers Power Co. 88/03/22. Document Control Branch (Document Control Deak). 2pp. 44921:281-44921:297.

-- 8803300050 Application for amend to License DPR-6, changing Tech Specs to tro-

quency of reactor depressurization sys depressurizing valve testing *Consumers Power Co. 88/03/22, 13pp. 44921:283-44921;295.

--8803300051 Proposed Tech Specs to reactor depressurization sys.
* Consumers Power Co. 88/03/22, 2pp, 44921;296-44921;297.

8804250298 Forwards notice of consideration of issuance of amond to Liconse DPR-8 & opportunity for hearing re 871109 application for amond.

SCOTT.W.E. Project Directorate III-1. 88/03/25. BERRY,K.W. Consumers Power Co 2pp. 45213.184-45213:170.

--8804250303 Notice of consideration of issuance of amend to License OPR-6 & opportunity for hearing. Amend revises provisions in prent Tech Specs re installation of new out-of-core power range instrumentation.
WAMBACH,T.V. Project Directorate III-1, 88/03/25, 5pp. 45213:186-45213:170.

- 8804050434 Authorizes partial exemption from 10CFR171 FY88 annual fee, per 870911 application Another invoice will be issued when amount of increase for fee due to new STELLOV. Oto of the Executive Director for Operations 88/03/29 BERRY.K W. Consumers Power Co. 4pp. 44997.334-44997.357.
- 8804110288 Forwards additinto on 871109 application for amend to License DPR-6,0hanging Tech Specs to reflect features & terminology used w/new power range monitoring nuclear instrumentation.

 BERRY.K.W. Consumors Power Co. 88/03/31. Document Control Branch (Document Control Desk) 16pp. 45135.046.45135.061.
- 8804130125 Partial response to FOIA request for documents re into Assessment Team notification & alleged velve tempering. App A documents available in PDR Forwards App B documents. App B documents also available in PDR G
- ~8804130141 Handwritten note to into Assessment Team notification of 870413 teleon from Individual fitted from plant on 870220 for sabolago/tampering w/salety related value Individual denied allegation.

 MCPEEK.G. NRC - No Detailed Affiliation Given 87/04/14, PARTLOW, J., GRIMES, B., ERICKSON, B. NRC - No Detailed Affiliation Given 2pp. 45102/034-45102/035.

- -8804130185 Forwards FBI communication to be disseminated only to NRC employees w/need to know.W/o FBI communication Records of 860810,0926.1212,870404 & 0929 leticons & Region III repts of 860610,870318 & 0929 events encl OAVIOSONJ. Office of Nuclear Material Satisty & Saleguards,Director. 87/10/15. HAYES,B. Office of Investigations CREED,J.R. Region 3, Ofc of the Director. 11pp. 45102.038-45102.048.
- 8804140193 Provides listed info requested in 880225 ftr re operating nuclear power units located at twelve sites along Great Lakes.
 STELLOY. Ofto of the Executive Director for Operations 88/04/06 RIDGE,T. House of Rep. 5pp. 45104:138-45104:143.
- -8804140223 Requests assistance in providing into which would identify number & location of nuclear power plants along Great Lakes. RIDGET. House of Rep. 68/02/25. NRC No Detailed Affiliation Given. 1p 45104:143-45104.143.
- 8804080088 Generic Ltr 88.07 to power reactor licensees & applicants re-modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc list end. MiRAGLIA,F J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164.285.
- 8804210473 Notification of 880421 & 22 meetings w/GE,SoMar Inc & util in San Jose,CA to audit plant nuclear measurement analysis & control sys ventication & validation program Agenda enct. SCOTT.W.E. Project Directorate III-1, 68/04/12, VIRGILIO,M.J. Project Directorate III-1, 39p. 45200-240-45200-243.
- 8804260274 Discusses mod of previous commitment to replace feedwater check valve resilient seal Util will replace seal at end of two cycles of svc.approx every 22-28 months Penodic tests will continue to monitor performance of VFW-305. FRISCH.R R. Consumers Power Co. 88/04/18. Document Control Branch (Document Control Desk). 3pp. 45251:102-45251:104.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors," Svc list end ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/09/26, Consolidated Edison Co. of New York, Inc. 121pp. 44995.128-44995:246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees tack of Mgt Controls Over Licensed Programs." Svc list enci.
 CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729) 88/
 03/28, Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.
- 8804060020 Forwards app to SALP 7 Board Rept 50-155/67-01 for Apr 1986 Aug DAVIS,A B. Region 3, Ofc of the Director, 88/03/30, HEINS,G.L. Consumers Power Co. 2pp. 45028-326-45028-344
- -8804060028 App to SALP 7 Board Rept 50-155/87-01 for Apr 1986 Aug 1987.
 * Region 3, Ofc of the Oixector, 88/03/00, 4pp, 45028-328-45028-337.
- -8804070307 Errata to SALP 7 Board Rept 50-155/87-01.
 * Region 3, Old of the Director, 88/03/30, 7pp. 45028 338-45028 344.
- 8804010256 NRC Into Notice 88:011, "Potential Loss of Motor Control Ctr 8/or Switch-board Function Due to Faulty Tie Bolts." Svc list encl.
 ROSSICE. Division of Operational Events Assessment (Post 870411), 88/04/07.
 Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc Busined Rossics Rossis Rossi Ross
- 8804280058 Responds to NRC Bulletin 88-003, "Inadequate Latch Engagement in HFA Type Latching Relays Mfg by GE." Util does not use subjectays.

 BERRY,K.W. Consumers Power Co. 88/04/19, Document Control Branch (Document Control Desk). 1p. 45261-247-45251:247.
- 8804280412 Final response to FOIA request for documents Forwards App C documents Documents partially withheld (ref FOIA Exemptions 7,6 & 3).
 GRIMSLEY, D. Division of Rules & Records (Post 870413), 88/04/21. MAXWELL, 8.
 Cosmos Broadcasting Corp. 3pp. 45269.346.45270.006.
- --8804280437 Partially withheld Insp Rept 87010 response Delictencies (6 security dept & valve tampering discussed Related info enci.

 * Consumers Power Co. 87/10/08 12pp. 45289:351-45270.006.

R. Periodic operating reports & related correspondence

- 8804050348 "1997 Renge Summary Rept" W/880331 III. JOHNSON,B.D. Consumers Power Co. 87/12/31, 7pp. 45045 203-45045 208
- 8804.130024 Monthly operating rept for Mer 1986 W/880405 tir. JOHNSTON.J.R., ELWARD,T.W. Consumers Power Co. 88/03/31. 6pp. 45142.180-45142.185

S. Reportable occurrences, LERs & related correspondence

- 8804130125 Partial response to FOIA request for documents re Info Assessment Team notification & alleged valve tempering App A documents available in PDR Forwards App B documents App B documents also available in PDR. GRIMSLEY_DH. Division of Rules & Records (Post 870413) 88/04/04 MAXWELLB. Cosmos Broadcasting Corp. 3pp. 45102:031-45102:048
- -8804130164 Forwards J Davidson 871015 memo forwarding FBI communication informing NRC that FBI would not investigate altedged valve tempering incident UII 8 alleger have not settled labor grevance WEIL.C.H. Region 3, Olc of the Director, 1p. 45102 037-45102:037.

V. Operator Examinations

- 8804120380 Forwards Rev 2 to "Guidance for Development of Smulation Facility to Meet Requirements of 10CFR55.45," adressing resolution of issues from 871207 meeting w/NRC KIRBY,M.J. Southern California Edison Co. 88/04/05. Document Control Branch (Document Control Resk) 2pp. 45088-265-45088-345.
- --8804120478 Rov 2 to "Guidance for Development of Simulation Facility to Meet Re-quirements of 10CFR55.45."
 Southarn California Edison Co. * Public Service Co. of Colorado. * Consumers Power Co. 88/03/31, 79pp. 45088 267-45088:345.

DOCKET 50-156 UNIV. OF WISCONSIN RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville,MD Official mailing address still remains same & project managers have new locations & phone numbers TS Michae's still lead project manager for facility & A Adams will serve as backup RUBENSTEIN,L.S. Standardization & Non-Power Roactor Project Directorate, 88/03/18 Alfiliation Not Assigned, 3pp. 44856;322-44866;324

V. Operator Examinations

8604040193 Informs that written & oral exams for operator & sonior operators scheduled for wk of 880523.Ref mail needed for exam received on 880317.Administration of reactor/sentor (sector operator) ficensing written exams enci.
WRIGHT.G.C. Region 3, Olc of the Director. 68/03/28. CASHWELL.R.J. Wisconsin, Univ. of, Madison, Wi. 6pp. 45058:182-45058:187.

DOCKET 50-157 CORNELL UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250 184 Informs of relocation of NRR to Rockville,MD Official mailing address still remains same & project managers have new locations & phone numbers TS Michaels still lead project manager for facility & A Adams will serve as backup RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate. 88/03/18. Affiliation Not Assigned. 3pp. 44856:322-44856:324

Q. Inspection reports, IE Builetins & correspondence

- 6804 120242 Ack receipt of 880229 itr informing NRC of steps taken to correct violations noted in insp Repts 50:097/87:02 & 50:157/87:02 BELLAMY.R.R. Hegion 1, Ofc of the Director, 88/04/04 STREETT,W.B. Cornell Univ., Ithaca, NY, 2pp. 45079.316.45079.318.
- -8804120249 Responds to NRC 880129 lit is violations noted in Insp on 87111/-20.Corrective actions quarterly inventory & leak testing of sources by ofc of environ CLARCE. CLARK.D.D. Cornell Univ., Ilhaca, NY, 88/02/29. MARTIN,T.T. Region 1, Ofc of the Director, 1p. 45079.318-45079.318.

DOCKET 50-160 GEORGIA INSTITUTE OF TECHNOLOGY RESEARCH REACTOR

P. Operating license stage documents & correspondence

- 8803280061 Confirms 880315 telcon w/ML Einst re 880321 mgt meeting in Atlanta,GA concerning status of 1988 action plan.
 GRACE,J N. Region 2, Ofc of the Director 88/03/15, CRECINE,J.P. Georgia Institute of Technology, Atlanta, GA, 1p. 44961:350-44961:350.
- 8803250248 Informs of NRC relocation to stated address Mailing address unchanged A Adams project manager & TS Michaels back-up project manager. RUBENSTEIN, L.S. Standardization & Non-Power Reactor Project Onectorate. 88/03/18. Affiliation Not Assigned. 3pp. 44859.060.44859.062.

8804070144 Forwards summary of 880321 mgt meeting at Georgia Inst of Technology re 1988 action plan Moeting beneficial & provided better understanding of problems at facility & licensee ongoing actions to facilitate solution. GHACE, J N. Region 2, Olic of the Director. 88/03/28. CRECINE, J P. Georgia Institute of Technology, Atlanta, GA. 4pp. 45044-185-45044.168

Q. Inspection reports, IE Bulletins & correspondence

8804270256 Forwards "Ropt of Visit to Georgia Tech Research Reactor Facility to Inspect Facilities & to Interview Operational Staff," by W Kerr, Chairman of ACRS. Kerr visited Nooly Nuclear Research Reactor on 80024-25 CRECINEJ.P. Georgia Institute of Technology, Atlanta, GA 88/04/07, GRACE, J.N. Region 2, Ofc of the Director, 1p. 45242-016-45242-020.

--8804270267 "Rept of Visit to Georgia Tech Research Reactor Facility to Inspect Facilities & to Interview Operational Staff."
KERRIW. ACRS - Advisory Committee on Reactor Safeguards 88/03/29 4pp. 45242-017-45242-020.

R. Periodic operating reports & related correspondence

8803280126 Annual ropt for 1987. Related Info including revised Procedure 3800, "Liquid Wasto Disposal Sys." from Chapter 15 of auxiliary sys enct. KARAM,RA Georgia Institute of Technology, Atlanta, GA. 88/02/26. Region 2, Olc of the Director. 20pp. 44945-073-44945-092.

DOCKET 50-163 GA TECHNOLOGIES

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Mailing address unchanged A Adams project manager & TS Michaels back-up project manager. RUBENSTEIN,L S. Standardization & Non-Power Reactor Project Directorate. 88/03/18. Affiliation Not Assigned 3pp. 44850 060-44859 062.

DOCKET 50-166 UNIV. OF MARYLAND RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250248 Informs of NRC rolocation to stated address Mailing address unchanged A Adams project manager & TS Michaels back-up project manager. RUBENSTEINLL S. Slanderdzellon & Non-Power Reactor Project Directorate. 88/03/18 Affiliation Not Assigned. 3pp. 44869.060-44859.062.

DOCKET 50-170 ARMED FORCES RADIOBIOLOGY RESEARCH INSTITUTE

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Mailing address unchanged. A Adams project manager & TS Michaels back-up project manager. RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate. 88/03/18, Affiliation Not Assigned. 3pp. 44859.060-44859.062.

O. Inspection reports, IE Bulletins & correspondence

8804980069 Forwards Exam Ropt 60-170/88-010L of exam edministered on 880224-25. GALLO,R.M. Region 1, Ofc of the Director. 88/04/01. IRVING,G. Armed Forces Radiobiological Research Institute. 2pp. 45216:238-45216 317.

--8804080072 Exam Rept 60-170/68-01QL on 680224-25.Exam results:one senior reactor operator candidate passed operating exam but failed two socilons of written exam. NORRIS, B.S., ESELGROTH,P.W. Region 1, Oic of the Director. 88/03/30, 77pp. 45216:240-45216:317.

R. Periodic operating reports & related correspondence

8804010112 "Reactor Facility Annual Rept Jan-Doc 1987." MOCRE,M.L., HOGDON,K.M., MUNNO,A.M. Armed Forces Radioblological Research Institute, 87/12/31, 127pp. 45020:035-45020:161.

V. Operator Examinations

8804080069 Forwards Exam Rept 50-170/88-010L of exam administered on 880224-25.
GALLO,R.M. Region 1, Oto of the Director. 88/04/01. IRVING,G. Armed Forces Radiobiological Research Institute. 2pp. 45216:238-45216:317.

--8804080072 Exam Rept 50-170/88-010L on 880224-25.Exam results:one sonior reactor operator candidate passed operating exam but falled two sections of written exam. NORIBS.S., ESELGROTH,P.W. Region 1, Old of the Director. 88/03/30. 77pp. 45216:240-45216:317.

DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8804140091 Provides schedule of emergency response activities for remainder of FY88 to regional staff for planning purposes. BELLAMY, R.R. Region 1, Oto of the Director, 88/03/02, RUSSELL, W.T. Region 1, Oto of the Director, 1p. 46122 258-45122:258.

J. Insurance & Indemnity Information

8804130181 Forwards Endorsament 72 to MAELU Policy MF-67 & Endorsament 122 to NELIA Policy NF-140 BRADLEY,E J. Philadelphia Electric Co. 88/04/07. DINITZ,I. NRC - No Detailed Alfiliation Gwen. 5pp. 45099 279-45099 283.

8804190088 Forwards Endorsement 12 to NELIA Policy 1 & Endorsement 3 to MAELU Policy 1. BRADLEY,E J. Philadelphia Electric Co. 88/04/08. DINITZ,I. NRC - No Detailed Affiliation Given. 5pp. 45153 341-45153:345.

P. Operating license stage documents & correspondence

8803240428 Generic Ltr 88.08 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Sycilist encl. MRRACHAE. J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44872:107-44972.163.

8804198071 Forwards updated decommissioning table for program implementation repl.Info on standardization design rev.ews has been provided to \$ Black. RUBENSTEIN,L S Standardization & Non-Power Reactor Project Directorate. 88/03/30. VILLAFRANCO,V. Program Managament, Policy Development & Analysis Statt (Post 870411). 3pp. 45168 285-45158 287.

6804130357 Advises that temporary waiver of compliance not issued in conjunction w/ emergency ilcensing amond granted for plants for first time,por guidance from HR Danton 670227 memo. Twolve waivers have been issued since Sholly rule in effect STELLO,V. Oic of the Executive Director to Operations. 86/04/06. ROBERTS,T.M. Commissioners 2pp. 45117:016-45117:017.

8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA,F. J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 48pp. 45164:237-45164:285.

U. Congressional/Executive Correspondence

8804130356 Responds to 880212 fir raising number of concerns to plant. Decision to permit restart will not be made until Commission convinced that previous problems corrected & that operation of facility in safe manner assured. ZEC11.L.W. Commissioners. 88/04/07. SCHAEFER,W.D. Maryland, State of. 5pp. 45412-351-45412-355.

DOCKET 50-182 PURDUE UNIV. RESEARCH REACTOR

P. Operating license slage documents & correspondence

8803250248 Informs of NRC relocation to stated address Making address unchanged A Adems project manager & 15 Michaels back-up project manager. RUBENSTEIN, L.S. Standardzation & Non-Power Reactor Project Directorate. 8B/03/18 Affiliation Not Assigned. 3pp. 44859.060-44859.062.

DOCKET 50-183 VALLECITOS EXPERIMENTAL SUPERHEAT REACTOR

P. Operating license slage documents & correspondence

8803260184 Informs of refocation of NRR to Rockville,MD.0fficial mailing address still remains same & project managers have new locations & phone numbers TS Michaels still lead project manager for facility & A Adams will serve as backup. RUBENSTEIN,L.S. Standardration & Non-Power Reactor Project Directorate, 88/03/18. Affiliation Not Assigned 3pp. 44856:322-44956:324.

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

F. Security, medical, emergency & fire protection plans

88040800B2 Advises that 871105 changes to NBS reactor safeguards plan consistent w/provisions of 100FR50.54 & acceptable,but resubmission of rev requested within 30 days of lit receipt to ensure proper plan continuity. BELLAMY,R.R. Region 1, Otc of the Director. 88/03/31. CARTER,R.S. Commerce, Dept. of, National Bureau of Standards. 2pp. 45116:250-45116.251.

P. Operating license stage documents & correspondence

88/03250184 Informs of refocation of NRR to Rockville,MD.Official mailing address at II remains same & project managers have new locations & phone numbers.TS Michaels attl feed project manager for facility & A Adams will serve as backup. RUBENSTEIN,LS. Standardization & Non-Power Reactor Project Directorate. 88/03/19 Altiribition Not Assigned. 3pp. 44856.322-44856.324.

B. Periodic operating reports & related correspondence

8804070152 "Operations Rept 40.Jan-Dec 1987." W/880328 ltr. CARTER.R.S. Commerce, Dept. of, National Bureau of Standards. 87/12/31. 11pp. 45044:170.45044:180. 8803250248 Informs of NRC relocation to stated address.Maring address unchanged A Adams project manager & TS Michaels back-up project manager RUBENSTEINL S Standardization & Non-Powor Reactor Project Directorate. 88/03/18 Affic stion Not Assigned. 3pp. 44859.060-44959.062.

DOCKET 50-186 UNIV. OF MISSOURI RESEARCH REACTOR-COLUMBIA

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Maling address unchanged A Adams project manager & TS Michaels back-up project manager. RUBENSTEINL & Slandardzalion & Non-Power Reactor Project Directorate. 88/03/18

DOCKET 50-188 KANSAS STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockvite,MD Official making address still remains same & project managers have new locations & phone numbers.TS Michaels still lead project manager for facility & A Adams will serve as backup RUBENSTEINLS. Standardization & Non-Power Reactor Project Directorate. 88/03/18, Afti-bluon Not Assigned 3pp. 44855 322-44856 324.

DOCKET 50-192 UNIV. OF TEXAS RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8803310127 Forwards Insp Repts 50-192/88-01 & 50-602/88-01 on 880209-10 & notice of violation.

CALLAN,L J. Region 4, Old of the Director 88/03/24 KLEIN,D.E. Texas, Univ. of, Austro, TX. 2pp. 44976,120-44976,129.

--8803310134 Insp. Repts 50-192/88-01 & 50-602/88-01 on 880209-10. Violations noted Major areas inspected review & audit, experiments, health physics, emergency plan organization, logs & records procedures & requalification training PICK, G.A., VICKREY, R.B., GAGLIARDO, J.E. Region 4, Oto of the Director, 88/03/14, 6pp. 44976 124-44976.129.

P. Operating ficense stage documents & correspondence

8893250248 Informs of NRC refocation to stated address Mailing address unchanged A Adams project manager & TS Michaels back-up project manager. RUBENSTEINLS. Standardization & Non-Power Reactor Project Directorate. 887037

Q. Inspection reports, IE Bulletine & correspondence

8803310127 Forwards Insp Repts 50-192/88-01 & 50-602/88-01 on 880209-10 & notice of viciation.
CALLANLU, Region 4, Oic of the Director, 88/03/24, KLEIN,D.E. Texas, Univ. of, Austro, TX, 2pp. 44976;120-44976,129.

ted: failure to erating proce-

.c. J9-10. Violations i physics emergency ing. ne Director, 88/03/14.

ing Lab." W/880329 ltr. KLEIN.D.E., BAUER,T.L. Texas, Univ. of, Austin, TX, 87/12/31, 66pp. 45031:202-45031:267.

V. Operator Examinations

8803310127 Forwards Insp Repts 50-192/88-01 & 50-502/88-01 on 880209-10 & notice of violation CALLAN,LJ. Region 4, Otc of the Director, 88/03/24, KLEIN,D.E. Texas, Univ. of, Austin, TX, 2pp. 44976:120-44976:129.

--8803310134 Insp. Repta 50-192/88-01 & 50-802/88-01 on 880209-10. Violations noted Major areas inspected review & audit, experiments health physics, emergency plan organization, logs & records, procedures & requalitication training.
PICK,G.A. Region 4, Otc of the Director, 88/03/14, 8pp. 44978,124-44978;129.

8804180185 Advises that inclusion of Ctr for Almosphetic Chemistry Studies in emegercy plan for reactor unnecessary due to bldg lying outside of EPZ boundary. Safe ovaluation supporting Leansee 871 (09 responses enct. MICHAELS,T.S. Standardization & Non-Power Reactor Project Directorate, 88/04/1 DIMEGLIO,A.F. Rhode Island, State of, 6pp. 45149,303-45149-310

--8804180213 Safety evaluation supporting licenses 871109 submittel concluding the charge to EP2 to include Cir. for Atmospheric Chemistry Studies bldg unnecesser.
 Office of Nuclear Reactor. Regulation, Director. (Post 870411). 88/04/11, 2p. 45149309-45149:310.

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville,MD,Official mailing address strems a same & project managers have new locations & phone numbers 3.5 M.chae still lead project manager for labelity & A Adams will serve as backup RUBENSTEIN,L S. Standardization & Non-Power Reactor Project Directorate, 88/03/18, Affiration Not Assigned, 3pp. 44856/322-44856/324.

8804210335 Requests concurrence in subj design criteria so as not to interfere w/opa alton of reactor facility exhaust stack.

DIMFELIOA F. Rhode Island, State of: 88/04/12 MICHAELS,T.S. Standardization Non-Power Reactor Project Directorate. 2pp. 45194:259-45194:260.

DOCKET 60-199 MANHATTAN COLLEGE RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of refocation of NRR to Rockville,MD.Official mailing address st remains same & project managers have new locations & phone numbers TS Michae still lead project manager for facility & A Adams wit serve as backup. RUBENSTEIN,L.S Standardzation & Non-Power Reactor Project Directorate #88/0318 Affiliation Not Assigned, 3pp. 44856,322-44856;324.

DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8804190131 Forwards Insp. Repts 50-206/88-07,50-361/88-07 & 50-362/88-07 c 880308-11 & notice of violation WENSLAWSKI, F.A. Region 5, Otc. of the Orioctor, 88/04/01 BASKIN,K.P. Souther Carlornia Edison Co. 2pp. 45196:264

--8804190132 Notice of violation from insp on 880308-11 Violation noted. Independer audit of emergency preparedness program not performed since 861201. WENSLAWSKI,F.A. Region 5, Otc. of the Director. 88/04/01. 1p. 45196-286 45196-266.

--8804190134 Insp Ropis 50-206/88-07,50-361/88-07 & 50-362/88-07 on 880301 1. Wiolations noted Major areas inspected operational status of emergency preparer ness program & Insp Procedure 82701.

GOOD,G.M. Reg.on 5, Orc of the Director. 88/03/29, 11pp 45196-267-45198-277.

I. Financial information

8803300384 Forwards annual rept to Secunbies & Exchange Commission & cash flo statement for yr ordring Dec 1987.

ADAMS, JB. Southern California Edison Co. 88/03/21. Document Control Brend (Occument Control Desk). 44pp. 44979;143-44979;188.

8804250248 Forwards 1987 annual repts for fisted units & cities of Anahelm Riverside,CA.
MEDFORD,M.O. Southern California Edison Co. 88/04/13 Document Control Brand (Document Control Desk) 1p. 45259.001-45259.249.

--8804250248 "San Diego Gas & Electric 1987 Annual Rept." PAGE,T.A. San Diego Gas & Electric Co. 87/12/31, 44pp. 45259:002-45259.045

-8804250251 "City of Anaholm Public Utits Dept 1987 Annual Rept." HOYT,G.W. Anaholm, CA 87/06/30, 55pp 45259.046-45259:100.

--8804250253 "Southern California Edison Co. 1987 Annual Rept." At LEN,H.P. Southern California Edison Co. 87/12/31, 62pp. 45259.101-45259.152.

--8804250264 "City of Riversido, CA Comprehensive Annuel Rept for FY ender 870630." BREWER, H.E. Riversido, CA 87/06/30. 88pp. 45259:153-45259:248.

J. Insurance & Indemnity information

8804130396 Advises of nuclear property & decontamination liability insurance current in force at plant. GOULD.G.J. Southern California Edison Co. 88/04/01. Document Control Brand (Document Control Desk). 1p. 45154:329-45164:329.

P. Operating license stage documents & correspondence

8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants ra removal a organization charts from Tech Spec administrative confrol requirements. Svc list en MIRAGLIA, F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidate Edison Co. of New York, Inc. 47 pp. 44972:107-44972:153.

- 8803310239 Remits lee for inservice testing program for pumps & valves for 10-yr Interval commencing on 880101 per 880307 request.
 MEDFORD M.O. Southern California Edison Co. 88/03/23. Document Control Branch (Document Control Desk). 1p. 45020.002-45020.002.
- 8803310226 Responds to NRC request for addl info re coefficient of friction used in supporting analyses of steam generators. Rept of all tubes in svc which have defects below uppermost inch of sound tube roll expulsion encl. MEDFORD.M.O. Southern California Edison Co. 88/03/29. Document Control Branch (Document Control Desk). 4pp. 45031:100-45031:103.
- 8804010217 Submits Info re environ qualification of electrical equipment Concludes that nsk associated w/any 10CFR50.49(b)(2) equipment that might exists considered low & discrepancies identified will be promptly dispositioned.

 MEDFORD,M.O. Southern California Edison Co. 86/03/30. Document Control Branch (Document Control Desk). 2pp. 45031;121-45031;122.
- 8804080237 Forwards public notice re util 880310 application for amend to License DPR-13.revising steam generator tube plugging criteria to allow tubes w/defects below uppermost 1 Inch of sound roll to remain in svc until next refueling outage. TRAMMELL,C.M. Project Directorate V. 88/03/30. BASKIN,K.P. Southern California Edison Co. 8pp. 45084:349-45084:356.
- 8804970310 Forwards addl into re electrical isolation devices to be used in util SPDS design per RF Dudley 870810 request.
 MEDFORD,M.O. Southern California Edison Co. 88/04/01. Document Control Branch (Document Control Desk), 13pp. 45021;218-45021;228.
- 8804080231 Informs that Allegation Package ATS RV-88-A-011 being forwarded to util for detailed evaluation investigation & response.

 KIRSCH,D,F. Region 5, Ofc of the Director. 88/04/01. 8ASKIN,K.P. Southern California Edison Cg. 1p. 45116:184-45116:184.
- 8804110104 Describes utili compliance w/10CFR60.49.Util believed all safety-related equipment was included on environ qualification master list (EQML) & fully qualified after returning to svc from Cycle 9 retueling outsige.EQML encl. MEDFORD,M.O. Southern Cellifornia Edison Co. 88/04/01. Document Control Branch (Document Control Desk). 54pp. 45073:262-45073:315.
- 8804120033 Forwards proposed Tech Spec changes re overpressure mitigation sys,for review prior to issuance by Commission. Response requested by 880419. TRAMMELL,C.M. Project Directorate V. 88/04/05. BASKIN,K.P. Southern California Edison Co. 22pp. 45101:008-45101:029.
- 8804120341 Forwards Cycle X mods design descriptions for recirculation sys to ESF single failure analysis.
 MEDFORD,M.O. Southern California Edison Co. 88/04/05. Document Control Branch (Document Control Desk). 3pp. 45089:298-45089:300.
- 8804130432 Requests util submit amend to Tech Specs to clear up administrative differences including differences in pagination & overflow form on page to next.Official version encl.Response requested within 60 days of III receipt.

 TRAMMELL,C.M. Project Directorate V 88/04/05. BASKIN,K.P. Southern California Edison Co. 3pp. 45104:133-45104:135.
- 8804190401 Notifies that changes addressed in Change Notice 25 to Amend 10 to SCE-1-A, "QA Program" reviewed & found acceptable per 10CFR50,App B. KIRSCH.D.F. NRC No Detailed Affiliation Given. 88/04/05. BASKIN,K.P. Southern California Edison Co. 1p. 45165:170-46155:170.
- 8804080088 Generic Ltr 88-07 to power reactor incensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Sately for Nuclear Power Plants." Socialist end. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285,
- 8804150019 Forwards approved NPDES permit reflecting changes in rules & regulations made during past five yrs to std NPDES permit.

 MEDFORD,M.O. Southern California Edison Co. 88/04/11. Document Control Brench (Document Control Desk). 8pp. 45153.047-45153:110.
- -8804160102 NPDES Permit CA0001228, "Monitoring & Reporting Program 88-001," Issued to Southern California Edison Co. DELANEY, L.H., California, State of. 88/02/08. 58pp. 45153:055-46153.071.
- 8804210039 Forwards response to NRC 871124 lit re Proposed Change 179 to License DPR-13."Planned shutdown" is shutdown that allows util sufficient lead time to plan for tast.Max lead time to test for normally "planned" gutage is 2 wks. MEDFORD.M.O. Southern California Edison Co. 88/04/13. Document Control Branch (Document Control Desk). 8pp. 45238:313-45238:318.
- 8804220167 Advises that review of 871224 & 880204 ltrs re lasue of whether or not out 2016/ Advises that review of 0.71224 & 36024 for g issue of wrieting or not license amend required for spent fuel transhipment from plant completed. Two criteria of 10CFRS0.59 for unreviewed safety question met.

 MIRAGLIAF. J. Associate Director for Projects (Post 870411), 88/04/14. BASKIN,K.P. Southern California Edison Co. 3pp. 46201:118-46201:118.
- 8804220199 Forwards application for amend to License DPR-13,consisting of Proposed Change 180,revising Tach Spec Sections 2-4 to reflect replacement of nuclear instrumentation sys detectors, dabling & signal processing equipment Fee paid. BASKIN.K.P. Southern California Edison Co. 88/04/15. Document Control Branch (Document Control Deak). 2pp. 45247:151-45247:345.
- --8804220202 Application for amend to License DPR-13,consisting of Proposed Change 180,revising Tech Spec Sections 2,3 & 4 for consistency w/replacement upgraded nuclear instrumentation sys.W/Certificate of Svc. BASKIN,K.P. Southern California Edison Co. 88/04/16, 13pp. 45247:153-45247:165.
- --8804220236 "Satety Review Rept for Nuclear Instrumentation Sys."
 Westinghouse Electric Corp. 88/04/30, 111pp, 45247:231-45247:345.
- 8804280486 Informs that date of listed SIMS generic items for implementation complete earlier than imposition complete due to NUREG.0737 post-implementation review.

 TRAMMELL,C.M. Project 'Directorate V. 88/04/21. Project Oirectorate V. 2pp. 45284:104-45284:105.

- 8804290114 Summary of 880316 meeting w/util re proposed improvements to safety injection sys. Agenda.l-st of attendess & handouts enci. TRAMMELL.CM. Project Ovectorate V. 88/04/22. Project Oxectorate V. 29pp. 45324-260-45324:278
- G. Inspection reports, IE Bulletins & correspondence
- 8804120442 Forwards Insp. Repts 50-206/88-06,50-361/88-06 & 50-362/88-06 on 880229-0304 & notice of violation WENSLAWSKI,F.A. Region 5, Olc of the Director. 88/03/24. BASKIN,K.P. Southern California Edison Co. 2pp. 45132:135-45132:146.
- --8804120446 Notice of violation from Insp on 880229-0304 Violation noted high reduction area behind Steam Generator A w/ Intensity of radiation ranging up to 200 m/h not berricaded & posted as high radiation area.

 WENSLAWSKI,F.A. Region 5, Otc of the Director. 88/03/24. 1p. 45132:137-45132.137.
- ---8804120456 Insp. Repts 50-206/88-06.50-381/88-06 & 50-362/88-06 on 880220-0304-Violations noted Major areas Inspected: maintaining exposures ALARA & Unit 1-occupational exposure during outages & tours of licenses facilities. PUSSELL J.E., YUHAS,G.P. Region 5, Otc of the Director. 88/03/24, 9pp. 45132:138-45132:146.
- 8803300098 Forwards "1988 Steam Generator Insp Results." Rept provides info necessary to facilitate NRC review of insp results & approval of proposed corrective actions. Fee paid.

 MEDFORO,M.O. Southern California Edison Co. 88/03/25. Document Control Branch (Document Control Desk). 2pp. 44916:285-44916:311.
- --9803300102 "1988 Steam Generator Insp Results."
 * Southern California Edison Co. 88/03/31, 25pp. 44916:287-44916:311.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors," Svc list enct. ROSSLCE, Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995.246.
- 8803220296 NRC Info Notice 98-010, "Mails Liconsons.Lack of Mgt Controls Over Li-censed Programs." Svc list enct. CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Salety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp 44995 247-44995:353.
- 8804190091 Forwards Mgt Meeting Rept 50-208/88-11 on 890324 re listed problems w/environ qualification of safety-related oquipment. MARTIN, J.B. Region 5, Olc of the Director 88/03/29. BASKIN,K.P. Southern California Edison Co. 2pp. 45209:138-45209:151.
- MgI Meeting Rept 50-208/88-11 on discussed concerns re environ qualification & transshipment of spent fuel from Unit 1 to Unit 2.Meeting agenda & related into encl.

 HUEY,F.R., JOHNSON,P.H. Region 5, Otc of the Director. 88/03/29, 14pp. 45209:138-45209:151.
- 8804190131 Forwards Insp Repts 50-206/86-07,50-361/88-07 & 50-362/88-07 on 880308-11 & notice of violation.
 WENSLAWSKI,F.A. Region 5, Oic of the Director, 88/04/01. BASKIN,K.P. Southern California Edison Co. 2pp. 45196:264-45186:277.
- --8804190132 Notice of violation from insp on 880308-11. Violation noted independent audit of emergency preparedness program not performed since 861201, WENSLAWSKI,F.A. Region 5, Oto of the Director. 88/04/01. 1p. 46196-266-46196-268
- --8804190134 Inap Repis 50-206/88-07.50-361/88-07 & 50-362/88-07 on 860308-11.Violations noted Major areas inspected operational status of emergency prepared-ness program & Insp Procedure 82701. GOOD, G.M., FISH, R.F., Region 5, Offic of the Director. 88/03/29, 11pp 45196 267-45196 277
- 8804210339 Provides rept on conditions Identified during Inservice Insp of steam generator tubing Of total of 7,425 inspected, 169 tubes were removed from syo by mechanical pluggling Remedial action taken to resolve tube degradation appropriate.

 MORGAN,H.E. Southern California Edison Co. 88/04/01. MARTIN,J.B. Region 5, Oto of the Director, 2pp. 45193:355-45193:358.
- 8804210004 Forwards status of actions in response NRC Bulletin 88-002, "Rapidly Propagating Fatigue Cracks in Steam Generator Tubes." Primary-to-secondary leak rate monitoring program to be implemented due to discovery of evidence of denting MEDFORO,M.O. Southern California Edison Co. 88/04/06 MARTIN,J.B. Region 5, Ofc of the Director, 11pp. 45219:107-45219:117.
- 8804010266 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolls." Svc list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408:292-45407.051
- 8804060370 NRC Info Notice 68-012, "Overgreasing of Electric Motor Bearings." Svc ilst enci. ROSSI,C.E. Division of Operational Events Assessment (Post 870411): 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-46165:160.
- 8804210399 Requests submitted of application for amend to License DPR-13 for NRC approval to leave tubes w/defects unplugged within 60 days & details re nonprogression of intergranular attacks within 30 days.per util Feb-Mar 1988 tube insp. TRAMMELL.C.M. Project Directorate V. 88/04/16, BASKIN,K.P. Southern California Edison Co. 3pp. 45191;132-45191;134.
- 8804210497 Advises that 870918 response to NRC Bulletin 87-001 re program for moni-toring thickness of pipe walls in high energy,single-phase & two-phase carbon steel piping sys being used to determine extent of industry participation. HIGKMAN,D.E. Profect Directorate V. 88/04/15. BASKIN,K.P. Southorn California Edison Co. COTTON,G.D. San Diego Gas & Electric Co. 3pp. 45192:201-45192:203.

S. Reportable occurrences, LERs & related correspondence

- 8803300191 LER 88-004-00 on 880215, during testing of isolation valves w/Tech Spacs method bonnet bloed off solanoid valve SV-3900 for safety injection valve HV-851B laifed to open Causad by crack in steeve of disc. Valve SV-3900 replaced W/880326
- MORGAN,H E. Southern California Ed.son Co. 88/03/25, 8pp. 44962:119-44962:124
- 8804010221 LER 88-001-00:on 880225, several components requiring environ qualifica-bon found omitted from equipment qualification master is Caused by inadequate methodology during list generation installed equipment reviewed W/860330 tr. MEDFORD,MO Southern Catifornia Edison Co. 68/03/30 Spp 45033:162-
- 8804060195 Special reption 880104.0216,0217 & 0228,vanous traignotection instrumen-1ation & fire suppression sys removed from size to prevent spurious actuations during welding activates or performance of schedulad maint work. MORIGAN,H.E. Southern Caltorina Ed.son. Co. 88/03/30. Document Control Branch [Document Control Desk]. 2pp. 45028:301-45028:302
- 8904200247 LER 88-002-00 on 880317. Tech Spec continuous fire watch for containment interrupted when equipment hatch closed Caused by removing contiguous area from combination post when hatch closed Instructions to be more explicit W/880415 MORGAN,H.E. Southern California Edison Co. 89/04/15, 5pp. 45239.076-45239.080.
- 8804260407 LER 88-008-00 on 880021, discovered that backup nitrogen sys (8NS) design criteria had not been (ully implemented in design & installation of sys Caused by surveillance of BNS not being performed Changes instituted W/880420 ltr. MORGAN, H.E. Southern California Edison Co. 88/04/20 2pp. 45224:061-45224-082.

V. Operator Examinations

- 8804120360 Forwards Rev 2 to "Guidance for Development of Simulation Facility to Meet Requirements of 10CFR55.45," addressing resolution of issues from 871207
- meeting w/NRC.

 Meeting w/NRC.

 KIRBY,M.J. Southern Cattornia Edison Co. 88/04/05. Document Control Branch (Document Control Desk). 2pp. 45088.265-45088.345.
- --8804120478 Rev 2 to "Guidance for Development of Simulation Facility to Meet Requirements of 10CFR55.45."

 Southern California Edison Co. 'Public Service Co. of Colorado. 'Consumers Power Co. 88703/31. 79pp. 45088 287-45088 345.

DOCKET 50-213 HADDAM NECK PLANT

F. Security, medical, emergency & fire protection plans

- 8804130162 Forwards Sateguards Insp Rept 50-213/88-07 on 880314-17 No violations
- HOLDAMY, R.R. Region 1, Ofc of the Director, 88/04/04, MROCZKA, E.J. Connecticut Yankee Atumic Power Co. 2pp. 45142:173-45142:179.
- ~8804130169 insp Repl 50:213/68:07 on 680314-17.No violations noted. Major areas inspected plan. § implementing procedures, organization,program. eudit.records. § replis,testing § maint, physical barners,protected § vitel areas § lighting. MARTIN,W.G., KEIMIG,R.R. Region 1, Otc of the Director. 68704/01. 5pp. 45142:175-45142 45142:179.

H. General correspondence

8804070291 Comments supporting proposed rule 10CFR50 re leakage testing of containment to permit use of mass point method as afternative method for calculating containment leakage rates Mass point method more accurate for calculating rates. MROCZKA,E.J. Connecticut Yankee Atomic Power Co. MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA,E.J. Northeast Utilities, 88/03/31. CHILK,S.J. Office of the Secretary of the Commission. 3pp. 45021-184-45021-188.

I. Financial Information

- 8804130265 "Connecticul Yankee Atomic Power Co 1987 Annual Financial Rept." W/ 880407 lu.
 - *Arthur Anderson & Co. GUGLIELMO,F.J. Connecticut Yankga Atomic Power Co. 87/ 12/31, 18pp. 45122:148-45122:164.
- 8804250249 Informs that payment of third quarterly installment of 1988 annual lee per 10CFR171 will be were transferred on 880429. MROCZKA.E.J. Connecticut Yankee Atomic Power Co. MROCZKA.E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA.E.J. Northeast Utilities 887 04/18. Document Control Branch (Document Control Desk). 2pp. 45258:292-45586:292

J. Insurance & Indemnity Information

8804070293 Informs NRC of type & limits of property insurance coverage for facility. MROCZKAEJ, Connecticut Yankee Alomic Power Co. 88/03/30, WOOD,R. Policy Development & Technical Support Branch (Post 870411), 2pp. 45021:187-45021:186.

- 8803080002 Requests remission of fee for util 880108 request for review of plans convert from stainless steel to Zircaloy fuel cladding for plant. DIGGS.RM. License Fee Management Branch. 88/03.03. MROCZKA,E.J. Connecut Yankea Atomic Power Co. 1p. 44633:161-44633:161.
- 8803080503 Requests addl Info to complete review of util 860819 request for pernent exemption from requirements of 10CFR50.62(c), ATWS rufo,including flow plito be maintained for remaining lifetime within conditions assumed for ATWS analysis WANG,A.B. Project Directorate 1-4, 88703/03, MROCZKA,E.J. Connecticul Yank Atomic Power Co. 3pp. 44639:052-44639.054.
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal organization charts from Tech Spoc administrative control requirements Svc Lst er MIRAGLIAF, J. Associate Director for Projects (Post 870411). 88/03/22. Consolidal Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804010149 Provides justification for continued operation w/reduction in EC flowrate Requests that until reanalysis complete/NRC review justification for continuoperation allowing up to 80% power Power prosently limited to 40%.

 MROCZKA,E J. Connecticut Yankee Atomic Power Co. 88/03/25. Document Continuon (Document Continuoperation) pranch (Document Control Dask). 8pp. 45058:106-45058:113.
- 6804050274 Forwards Amend 101 to License DPR-61 3 salety evaluation Amend vises Table 4.2-1, "Min Frequencies for Testing Calibr &/or Checking Instrumi Channels." Offenings.
 WANG.A.B. Project Directorate IV. 88/03/28. MROCZKA,E.J. Northoast Nucl. Energy Co. (subs. of Northeast Utilities). 2pp. 44997:181-44997:190.
- **8804050278 Amend 101 to Licanse OPR-61, revising Tablo 4 2-1, "Min Frequencies Testing Calibr 8/or Checking Instrument Channels." STOLZ, J.F. Project Directorate IV. 88/03/28, Spp. 44937:183-44997:187.
- -8804050279 Safety evaluation supporting Amend 101 to License DPR-61.
 * Office of Nuclear Reactor Regulation, Director (Post 870411). 88/03/28 3(4002/4002/4002) 44997:188-44997:190.
- 8804050278 Daily highlight.Notification of 880330 meeting w/util in Rockville,MD to do coss justification for continued operation for 80 % power operation due to lower care lated ECCS flows
 WANG,A.B. Project Directorate I-4, 88/03/28 MURLEY,T.E., ROSSI,C PARTLOW,J. NRC · No Detailed Affiliation Given 3pp. 44997;191-44997;193
- 8804110207 Forwards safety evaluation supporting util responses to NUREG-0737, Ite ILD.1, "Performance Testing of Relief & Safety Valves." Approval based on util commitment to provide results of Implant tests of block valves. WANGA.B. Project Directorate 1-4, 88/03/30. MROCZKA,E.J. Connecticut Yanki Atomic Power Co. 27pp. 45071;314-45071;340.
- 8804120364 Application for amend to License DPR-61, adding license condition requiri-uit to implement & maintain integrated implementation schedule program plan. MROCZKA, E. J. Connecticut Yankee Alomic Power Co. 88/03/31. Document Control Branch (Document Control Desk). 8pp. 45150.338-45150.353.
- --8804120376 "Haddam Neck Plant Integrated Implementation Schedule Program Plant Connecticut Yankee Atomic Power Co. 88/03/31, 8pp. 45150,346,45150,353
- 8804 110315 Application for amend to License DPR-61, revising Tech Specs Sector 3.17.1, "Axial Offset Limits" 8 Section 3.17.2, "LHGR," Change required due to dicovery of ECCS calculational error. Fee paid.
 MROCZKA,E.J. Connecticut Yankee Atomic Power Co. MROCZKA,E.J. Northeast Utiles, 88/04/05. Document Control Branch (Document Control Desk), 8pp. 45122.00 45122.049.
- --B804110320 Proposed Tech Specs, revising Section 3.17.1, "Axial Offset" & Section 3.17.2, "LHGR."

 Northeast Nuclear Energy Co. (aubs. of Northeast Utilities). 86/04/05. 32pd 45122.018.45122.049.
- 880408088 Generic Ltr 88.07 to power reactor licensess & applicants re-modified e forcement policy concerning 10CFRS0.49, "Environ Qualification of Electrical Equi-ment important to Safety for Nuclear Power Plants." Svc hist encl. MiRAQLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidate Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804120423 Forwards payment on invoice for costs incurred during NRC review of Rev. 8 & 9 to Topical Repl NU-QA-1.
 MROCZKA,E.J. Connecticut Yankee Atomic Power Co. MROCZKA,E.J. Northeast Niclear Energy Co. (subs. of Northeast Utilities), MROCZKA,E.J. Northeast Utilities, 86 04708. Document Control Branch (Document Control Desk) 4pp. 45091:0045091:004.
- 8804190204 Forwards Amend 102 to License DPR-61 & safety evaluation. Amend rouses Figures 3.17-1A & B & Section 3.17.2 of Tech Specs to reduce LHGR by approach twick the project Directorate 1.4 88/04/08 MROCZKA,E.J. Connecticut Yanke Atomic Power Co. 3pp. 46185:001-45185:016.
- -8804190214 Amend 102 to License DPR-61 revising Tech Spec Figures 3.17-1A & B Section 3.17-2 to reduce LHGR by approx 1kW/ft w/corresponding reduction in axi offset limits for four loop operation. STOLZJ.F. Project Directorate 1-4, 98/04/08, 6pp. 45165.004-45165.009.
- -8644190220 Safety evaluation supporting Amend 102 to License DPR-61.
 Office of Nuclear Reactor Regulation, Director (Post 8704+1). 88/04/08. 7p. 45165:010-45165:018.

- 8804200539 Forwards additinto re small break LOCA Model NULAPS5.per 880317 letcon Info from NUREG-0065,into re response of clad swell & rupture model in analysis 8 into requested in 880317 conference call oncl MROCZKA,E.J., SEARS,C.F. Connecticut Yankee Atomic Power Co. MROCZKA,E.J. Northeast Utilines. 88/04/15. Document. Control Branch. (Document Control Desk) 1500, 45230-093, 45230-093, 45230-093. 15pp 45239.095 45239.109.
- 8804270231 Submits comments supporting proposed rule to ensure that presence of NRC inspectors on power reactor sites should not be announced to licensee personnel Licensee leels rule makes sense but not practicable MROCZKAEJ, SEARS,CF. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKAEJ Northeast Utilities. 88/04/18. Docketing & Services Branch. 3pp. 45244.247.45244.249.

Q. Inspection reports, IE Builetins & correspondence

- 8803310117 Responds to NRC Bulletin 88-002, "Rapidly Propagating Fatigue Cracks in Steam Generator Tubos." Steam generator eddy current tushing data for 1987 reviewed for evidence of donling at uppermost tube support.Numbur of tubes donted. MROCZKA,E.J. Connectcut. Yankee. Atomic Power Co. 88/03/24. RUSSELL,W.T. Region 1, Otc of the Director. 37pp. 44867:264-44967:300.
- 8803310043 Responds to NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakers. Two reactor trip breakers & two reactor trip bypass breakers suit) to bulletin used at Mitistona Unit 3 Main pole shall weld insps completed by 880225.

 MROCZKA,E J. Connecticut Yankee Atomic Power Co. MROCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA,E.J. Northeast Utilities). MROCZKA,E.J. Northeast Utilities 88/03/25. RUSSELL,W.T. Region 1, Ofc of the Director. 2pp. 44964:136-44964:137.
- 8803210090 Suppt 1 to NRC Into Notice 87:044, "Thimble Tube Thinning in Westing-house Reactors" Svc list and ROSSI,C E. Division of Operational Events Assessment (Past 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995.246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees Lack of Mgi Controls Over Li-censed Programs." Svc ist end. CUNNINGHAM, R E Division of Industrial & Modical Nuclear Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353
- 8804110207 Forwards safety evaluation supporting util responses to NUREG-0737, item II D 1, "Performance Testing of Relief & Safety Valves." Approval based on util commitment to provide results of in plant tests of block valves WANGA B. Project Directorate 1-4. 88703/30. MROCZKA,E.J. Connecticul Yankee Atomic Power Co. 27pp. 45071:314-45071:340.
- 8804140412 Advises that SEP Topic VIII-2, "Onsite Emergency Power Sys" complete based on mods vontied in 870519 Insp Ropt 87-08. Trip bypass circuitry installed for generator reverse power & generator loss of filed trips during 1984 outage. WANG, A.B. Project Oirectorate 1-4, 88/03/31, MROCZKA,E.J. Connocticut Yankee Atomic Power Co. 2pp. 45118-071-45118-072
- 8804120184 Forwards Insp Rept 50:213/87-28 on 871116-20 & notice of violation. JOHNSTON,W.V. Region 1, Otc of the Director. 88/04/01. MROCZKA,E J. Connecticut Yankee Atomic Power Co. 2pp. 45132.005-45132.037.
- -- 8804120196 Notice of violation from Insp on 871116-20. Violation notod grease added to motor housing instead of goar box by untrained contract personnel w/inedequate direction, written instructions/procodures.
 -- * Region 1, Otc of the Director. 88/04/01. 2pp. 45132.007-45132:008.
- --8804120199 Insp. Rept 50-213/87-28 on 871116-20 Violations noted. Mejor areas inspected licensee implementation of environ qualification program & ventication of implementation por 10CFR50.49 requirements.
 PAOLINO,R.J., ANDERSON,C.J. Region 1, Ofc of the Director. 88/03/29. 28pp. 45132.009-45132.037.
- 8804130162 Forwards Sateguards Insp Rept 50-213/88-07 on 880314-17.No violations actea. BELLAMY,R.R. Region 1, Otc of the Director. 88/04/04. MROCZKA,E.J. Cannecticul Yankae Atomic Power Co. 2pp. 45142:173-45142:179.
- -8804130169 Insp Ropt 50-213/88-07 on 880314-17.No violations noted. Major areas inspected plan & implementing procedures, organization.program audit.records & repts.lessing & maint, physical barriers.protected & vital areas & lighting. MARTIN,W.G., KEIMIG,R.R. Region 1, Otc of the Director. 88/04/01, Spp. 45142:175-45142:179
- 8804010256 NRC Info Notice 88.011, "Potential Loss of Motor Control Ctr &/or Switchboard Function Due to Faulty Tie Bolts." Svc list oncl.
 ROSSI,CE. Division of Operational Events Assessment (Post 870411). 88/04/07, Consolidated Ecison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:160.
- 8904260070 Forwards additinfo in response to IE Bullentin 85.003 re inotor-operated valve common mode tallures. Water hammer due to valvo closure not considered in determination of pressure differentials.

 MROCZKA,E.J., SEARS,C.F. Connecticut Yankee Atomic Power Co. MROCZKA,E.J. Northeast Utilisies. 89/04/18. Document Control Branch (Document Control Desk). 8pp. 45259:274-45259:281.

R. Periodic operating reports & related correspondence

- 8803290219 Forwards revised reactor coolant data rept for Feb 1988.

 MILLER,D.B. Connecticut Yankee Atomic Power Co. 88/03/21, Document Control Branch (Document Control Desk). 1p. 44915:329-44915:330.
- -8803290221 Reactor coolant data for Feb 1986. Connecticut Yankee Atomic Power Co. 88/02/29. 1p. 44915.330-44915:330.
- 8804080058 Forwards bimonthly Progress Rept 9 re major milestones for const of new switchgear bidg.per 860930 commitment & 10CFR50.App R. MROCZKA.E.J. Connecticut Yankee Atomic Power Co. 88/03/31. Document Control Branch (Document Control Desk). 8pp. 45045;145-45045;162.

8604190130 Monthly operating rept for Mar 1998.W/880415 ftr. WALLK C., MILLER,D.B. Connecticut Yankee Atomic Power Co. 88/03/31, 10pp 45198 284-45196-293

S. Reportable occurrences, LERs & related correspondence

- 8803280128 LER 88-004-00:on 880225,dropped rod circuity found improperly wired Caused by friadequate testing following previous maint or mod activities Rod circuity rewired to conform widosign documents W/880318 lit. GALLOWAY.T.J., MILLER,D.8 Connecticut Yankee Atomic Power Co. 88/03/18. 7pp. 44921:108-44921:114.
- 8803310064 Forwards two repts re oil spill at plant on 880314.per WG Counsil 830406 itr re normal ological environ reporting
 MILLER,D.B. Connecticut Yankee Atomic Power Co. 88/03/22. Office of Nuclear Re-actor Regulation, Director (Post 87041). 4pp. 44984-128-44984.131.
- 8804130058 LER 88-007-00 on 880310,RHR sys discovered inoperable for more than 1 h Operations log review revealed similar occurrence on 880305.Caused by failure to observe operating procedures Licensed operators counseled.W/880406 ltr. MAJEWSKI,JL., MILLER,D.B. Connecticut Yankee Atomic Power Co. 88/04/06. 5pp. 45131:121-45131:125.
- 8804220208 LER 88-008-00 on 860318,zero power reactor trip due to spurious high startup rate Suppression d'ode placed across annuciator rollay ceil & nuclear instrumentation sys upgraded during 1989 refuling outlage.W/880515 ltr.
 FLYNN,B.J. MILLER,D.B. Connecticut Yankea Alomic Power Co. 88/04/15. 4pp 45257:235-45257:238
- 8804220209 LER 88-009-00 on 880322,automatic reactor trip occured due to spurious high startup role trip signal caused by electrical noise Source of noise not determined Deteriorated port on of Instrumentation cable replaced W/880415 lir. FLYNN_B.J. MILLER.D.B. Connecticut Yankee Atomic Power Co. 88/04/15 4pp. 45236 281 45236 284
- 8804270265 Forwards oil spill rept submitted to State of CT dept of environ protection per 830408 itr.
 MILLER.D.B. Connecticut Yankee Atomic Power Co. 88/04/15. Office of Nuclear Reactor Regulation, Director (Post 870411), 4pp. 45244 230-45244:233.

DOCKET 50-214 MALIBU POWER REACTOR

O. Advisory Committee on Reactor Safeguards reports & correspondence

- 8804060377 Final response to FOIA request for documents Forwards App A documents App A documents also evailable in PDR Bill for fees associated w/request OBCLINGTOLOGY
 Will be son!
 GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 88/03/30.
 SCHADRACK,M.A. O'Melvony & Myers. 2pp. 45019 015-45019:170.
- --8804060404 Discussos questions raisod by ASLB during Malibu hearing re seismic dosign & quotos statements from draft USC&GS rept. Draft minutes of ACRS 99th meeting on 8807.11-13 in Washington, DC enct. FRALEY, R.F. ACRS Advisory Committee on Roactor Safeguards. 65/09/28. ACRS Advisory Committee on Roactor Safeguards. 65/09/28. ACRS Advisory Committee on Roactor Safeguards. 154pp. 45018.017-45019:170.

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

- 8804070258 Approvos Revs 23 & 24 to security plan transmitted in 670923 ltr.except changes concerning new access authorization program which has potential for policy implications
- BELLAMY, R.R. Region 1, Otc of the Director, 88/03/29, FIEDLER, P.B. General Public Utilities Corp. GPU Service Corp. 3pp. 45098:267-45098:269.
- 8804080242 Revised omergency plan implementing procedures including Rev 2 to 9473-IMP-1300.06, "Addi Assistance & Notification," Rev 2 to 9473-IMP-1300.25, "Emergency Operations Facility (EOF)" & Rev 4 to 9473-IMP-1300.41, "Emergency...." W/ 880330 ftr. 900030 117. SULLIVAN.R.L., BARTON,J.J. General Public Ulrities Corp. - GPU Service Corp. 887 03730. 70pp. 45099.184-46098:253.
- 8804130252 Forwards response to SALP repl.addressing two areas of NPC concern re-plant operations & engineering support & providing addl info & clanifying areas on emergency preparedness & surveillance.per 880303 meeting. CLARK,P.R. General Public Utilities Corp. GPU Service Corp. 88/04/04. Document Control Branch (Document Control Desk). 15pp. 46122:178-45122:192.
- 880.42.10436 Informs that security measures to meet intrusion alarm requirements will be provided Schedule & scope for Implementation of addit work will be developed within context of long range planning program.

 MANGANARO,F.F. General Public Utilities Corp. GPU Service Corp. 88/04/15, OROMERICK,A.W. Division of Reactor Projects I/II (Post 870411), 2pp. 45226.359-45293-360
- 8804250301 D.scusses schedule for project to upgrade projected area intrusion retection sys at facility. Deadline for complotion, lest & turnover of new sys rescheduled from 880331 to 880431 due to unforseon obstacles requiring field changes.

 MANGANARO,F.F. General Public Utilities Corp. GPU Service Corp. 88/04/15. Document Control Branch (Document Control Desk). 2pp. 45239:182-45239:183

H. General correspondence

8904260165 Informs of recent reorganizational changes within GPU Nuclear Effective 880425.PB Fiedler will be reassigned to position of vice president/director of quality & Iraining, newly formed div.

LONG,R.L. General Public Utilities Corp. - GPU Service Corp. 88/04/18. Document Control Branch (Document Control Desk). 2pp. 45280:001-45260:002. 8804140016 Informs that instead property coverage in effect for plant as of 880401 per 10CFR50.54(w)(4).
BARTON.J.J. General Public Utities Cosp. - GPU Service Corp. 88/04/05. Document Control Branch (Document Control Desk). 2pp. 45147-325-45147-326.

8804200568 Forwards Endorsements 126 & 127 to NELIA Policy NF-184 & Endorsements 103 & 104 to MAEU Policy NF-44.
FARRELLE, Marsh & McLennar, Inc. 88/04/11. D.NITZI: Office of Nuclear Reactor Regulation, Director (Post 870411) 90p. 45175:023-45175.031.

P. Operating license stage documents & correspondence

- 8803980495 Forwards hated into re-seismic floor response spectra methodology in re-sponse to AW Ordmanck 871216 ftr request. Into includes variations in soil properties, modeling uncortainties & effect of saturated soil. NAGALY. Ganeral Public Utilities Corp. GPU Service Cosp. 88702/26. DROMERICK.A.W. NRC No Detailed Affiliation Given 41pp 44638/239-44639.005
- ~8803080508 * Predictive Response Computations for Vibration Tests & Earthquake of 880520 Using Assymmetric Finite Element Formulation Based on Complex Response Method & Compansion w/ Measurements-Swiss Contribution."

 BERICERE, FIERZ'H Basin & Hofmann, KLUGE,D. Switzerland, Govt. of 88702726 25pp 44638 280-44638 304.
- -8803080511 "So.I-Structure Interaction Analysis of Quarter Scale Model Using Axera Code: SATO,T, KAKALS, YAMAZAKI,F. Obsaki Research Institute, Inc. 88/02/26, 62pp. 44638-305-44639-005
- 8803240425 Generic Ltr 89-06 to all power reactor fromsees 8 appticants re removal of organization charts from Tech Spec administrative control requirements. Sec list encl. MRAGLAF J. Associate Director for Projects (Post 870411) 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972 107-44972.163.
- 8803300084 Application for amend to License DPR-16, consisting of Tech Spec Change Request 167 re-replacement of organization charts in Toch Specs w/more general organization requirements Foe paid.
 FIEDLER,P.B. General Pubric Utiliues Corp. GPU Service Corp. 88/03/22. Document Control Branch (Document Control Desk), 7pp. 44921-254-44921.280.
- --8803300089 Proposed Tech Specs re replacement of organization charts in Tach Specs w/more general organization requirements.

 General Public Utilities Corp GPU Service Corp. 88/03/22, 20pp. 44921:261-4004:200
- 8604050223 Forwards request for add into re util 860421 & 1106 requests for relicition commitment in integrated plant safety assessement ropt to provide automatic water level gauge for intake canal info requested by 860430.

 DROMERICK,A,W. Project Directorate 14 88703729. FIEDLER,P.B. General Public Utilities Corp. GPU Service Corp. 3pp. 45028;144-45029:146.
- 8804070904 Notices NRC of thil plans to utilize seismic experience data as acceptable afternative to existing enalytical or test methodologies to demonstrate seismic adequacy of future replacement components 8 subcomponents.

 WILSON,R.F. General Public Utilities Corp. GPU Service Corp. 88/03/29. Document Control Branch (Document Control Cest). 2pp. 45048:286-45048:287.
- 8804070198 Informs of util plans to employ seismic experience data to show seismic adequacy of replacement recorders & new instrumentation for control room panels at facility Requestis notification if approach unacceptable within 30 days.

 WILSON.R.F. General Public Utilities Corp. GPU Service Corp. 88703/29. Document Control Branch (Document Control Desk). 2pp. 45075.227-45075-228.
- 8804070003 Forwards application for amend to License DPR-18, revising Tech Spec Section 3.10 to support Cycle 12 reload. Proprietary NEDC-31482P withheld (ref. IOCFR2-790), Fee paid. WitSON R.F., General Public Utilities Corp. GPU Service Corp. 88/03/30, Document Control Branch (Document Control Dask). 2pp. 46030:105-45030.298.
- ~8804070005 Application for amend to License DPR-18,changing Tech Spec Section 3.10 to support Cycle 12 reload. WILSON,R.F. General Public Utilities Corp. GPU Service Corp. 88/03/30. 6pp. 45030 307-45030 112.
- -8804070006 Proposed Tech Spec Section 3.10 supporting Cycle 12 reload. GE athida-
- General Public Utilities Corp. GPU Service Corp. 88/03/30 11pp. 45030:113-45030,123,
- ~8804070011 Rev 0 to "Reload Into & SAR for Oyster Creek Cycle 12 Reload."
 ALAMMAR,M.A., DOUGHER,J.D., FURIA,R.V. General Public Utilities Corp. GPU
 Service Corp. TR 048 R00. 88/03/31. 48pp. 45030:252-45030:298.
- 8804070202 Forwards responses to concerns raised by EGG-NTA-7277, "Conformance to Reg Guide 1.97," technical evaluation rept, per NRC 870904 request. FIEDLER, P.B. General Public Utikles Corp. GPU Service Corp. 88/03/30. Document Control Branch (Document Control Desk). 12pp. 45074.267-45074:278.
- 8804190274 Forwards application for amend to License DPR-16 consisting of Tech Spec Change Request 184 ra deletion of Satety Umit 2.1.E. Limitation more appropriate as limiting condition for operation. Fee paid. FiEDLER.P.B. General Public Utilities Corp. GPU Service Corp. 88/03/31. Document Control Branch (Document Control Desk). 2pp. 45215-250-45215-268.
- --8804190234 Application for amend to License DPR-16,consisting of Tech Spec Change Request 164,detelling Safety Limit 2.1,E. Certificate of Svc enct FIEDLER,P.B. General Public Utilifies Corp. GPU Service Corp. 88/03/31, 11pp. 45215:262-45215:262.

- **Goneal Public Utilities Corp. GPU Service Corp. •8/03/31. 6pp. 45215
 45215-268.
- 8804190317 Forwards application for amond to License OPR-16 consisting of Rev Tech Spec Change Request 148 revising Tech Spece re RCS toding activity Im Survaillance requirements.
 FIEDLER,P.B. General Public Utilities Corp. - GPU Service Corp. 86/04/05 Docu Control Branch (Document Control Desk). 3pp. 45215:201-45215 214.
- ~8804190287 Application for einend to License DPR-16,consisting of Rev I to Spac Change Request 148 Amend changes RCS todine activity limits. FIEDLER P.B. General Public Utilities Corp. GPU Service Corp. 88/04/05 45215:204-45215:205.
- -8804190296 Proposed Tech Specs, revising RCS lodine activity limits & surveilland quirements.
 • General Public Utilities Corp. • GPU Service Corp. 88/04/05. 10pp. 45215
- 8804080088 Generic Ltr 38-07 to power reactor bicensoes & applicants re-module forcement policy concerning 100FR50.49, "Environ Quahrication of Electrical Emant Important to Safety for Nuclear Power Plants." See hist encl. MIRAGLIA, F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolid Edison Co. of New York, Inc. 49pp. 45164:237-45184:285.
- 8804190288 Forwards Amend 121 to License DPR-16 & safety evaluation. Amer vises Tech Specs to allow fuel w/higher enrichments to be stored in fuel storage chiles on site. DROMERICK, A.W. Transportation Branch, 88/04/11, FIEDLER, P.B. General El Co. 2pp. 45165-235-45165-244.
- --8804190314 Amend 121 to License DPR-16,revising Tech Specs to allow fur higher enrichments to be stored in fuel storage facilities on site. STOLZ,J.F. Project Directorate I-4, 88/04/11, 5pp. 45165:237-45165:241.
- 8604190316 Safety evaluation supporting Amend 121 to License DPR-16.
 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/11 45185-242-45185-244.
- 8804190015 Forwards significant hazards determination as supplemental info to Spec Change Request 166 re core reload.per 880404 request. WILSON,R.F. General Public Utilials Corp. GPU Service Corp. 88/04/12. Docu Control Branch (Document Control Oesk). 4pp. 45199:186-45199:191.
- 8804280299 Forwards Rev 2 to 1000-PLN-7200.01, "GPU Nuclear Corp Operation Plan for TMI-1 & Oyster Creek." Plan will be revised to reflect pla reorganization Evaluation of changes associated w/rev also anct. ROCHE,M.B. General Public Ulikiles Corp. GPU Service Corp. 88/04/15. Docu Control Branch (Occument Control Desk). 14pp. 45252:173-45252
- --8804260301 Rev 2 to 1000 PLN-7200.01, "GPU Nuclear Corp Operational QA Pit TMI-1 & Oyster Creek."

 CLARK, P.R. General Public Utilities Corp. GPU Service Corp. 88/04/08. 1: 45252:187-49252:207.
- 8804280201 Advises that util can use selsmic adequacy experience data to demons selsmic adequacy of future replacement components, subj. to requirements apecificinal satety evaluation NRC requests that reporting requirements applies. DROMERICK, A.W. Project Directorate 1-4, 89/04/18, FIEDLER, 3.8, General & Utilities Corp. GPU Service Corp., 2pp. 45276:307-45276:308.
- 8804280465 Forwards exemption from requirements of App J 10CFR50 Para; III.A.3 re "Primary Reactor Containment Leakage Testing for Water-Cooled Powe actors," per 880219 Itr. Safety evaluation also act. DROMERICK,A.W. Project Directorate 1-4. 88/04/18, FtEDLER,P.B. General F Utilities Corp. GPU Service Corp. 3pp. 45270:311-45270:321.
- -8804280480 Exemption granted re-requirements of App J to 10CFR50, ParagilliA.3 to allow use of mass point method as requested in submittal did 880219 VARGA, SA. Division of Fleator Projects VII (Poet 870411), 88/04/18. Ge Public Utilities Corp. GPU Service Corp. 5pp. 45270:314-45270.318.
- -8804280532 Salety evaluation supporting exemption from App J for containment grated leakage rate test methodology. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/18, 45270-319-45270-321.
- 8804289231 Advises that qualification of replacement recorders & new instrument & control room panels by selsmic experience data allowed by IEEE-344-1987 & Reg Gulde 1.100 acceptable, subji to final safety evaluation. DROMERICK,A.W. Project Directorate 1.4. 88/04/20. FIEDLER,P.B. General F Utilities Corp. GPU Service Corp. 2pp. 45286.316-45268.317.

Q. Inspection reports, iE Builetins & correspondence

- 8804130001 Notification of Licensee Meeting 88-025 on 880303 w/util in Parsippar to discuss SALP for plant.
 PELESCHAK, S. Region 1, Ofc of the Director, 88/02/17, Region 1, Ofc of the Director, 2pp. 45099:323-45099:324.
- 8804120449 Notification of Significant Licenses Meeting 88-031 on 880308 w/s King of Prussis PA to discuss NRC Bulletins 79-02 & 79-14. COWGILL,C.J. Region 1, Ofe of the Director, 88/02/25. Region 1, Ote of the Director, 88/02/25.
- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Weshouse Reactors," Sychişt enci.
 ROSSICE. Division of Operational Events Assessment (Post 870411). 88/0. Cansolidated Edison Co. of New York, Inc. 121pp. 44895;126-44995;246.

- 8803220296 NRC Into Notice 88-010, "Mattis Licensees Lack of Mgt Controls Over Li-censed Programs." Svc list encl CUNNINGHAM.A E Division of Industrial & Modical Nuclear Safety (Post 870729), 887 03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44985.247-44995:353
- 8804070158 Responds to NRC fit re-violations noted in Insp. Rept 50-219/88-02 Utili does not concur w/Violation A.Corrective actions plant operating procedures revised as result of mod. Tech Specs changes & errors identified by users. FIEDLER, P.B. General Public Utilities Corp. 4 GPU Sorrice Corp 88/03/30 Document Control Branch (Document Control Desk). 6pp. 45075-257-45075-262.
- 8804130252 Forwards response to SALP ropt.addressing two areas of NRC concern re plant operations & ong neering support & providing addition & clarifying areas on emergency preparedness & surveillance.per 880303 meeting CLARK P R. General Public Utifities Corp GPU Service Corp 88/04/04 Decument Control Branch (Document Control Branch (Document Control Desk). 15pp. 45122-178-45122 192
- 8804130346 Clarifies position on inspiplans for stainless steel piping we'ds during 12R outage currently scheduled to start 881001.
 WILSON,R.F. General Public Utilities Corp. GPU Service Corp. 88/04/05. Document Control Branch (Document Control Desk). 2pp. 45146.339-45146 340.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Cir &/or Switch-board Function Due to Faulty Tia Botts." Svc list encl ROSSI,C E. Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051
- 8804200522 Informs that Wostinghouse DS circuit breakers not utilized in any 1E application at plant but used in non-1E applications & will be included in util preventive marti program FIEDLERIP B. General Public Utilities Corp. - GPU Service Corp. 88/04/07. Document Control Branch (Document Control Desk). 1p. 45175 013-45175 013
- 8804250182 Forwards Vots I & II of "Oyster Creek 870911 Safety Limit Violation" Rept discusses 870911 destruction of portion of sequence of alarm recordor data. CLARK.PR General Public Utilities Corp GPU Service Corp 88/04/11. RUSSELL,W.T Region 1, Oic of the Director. 3pp. 45257 244-45258 222.
- --8804250191 Vol Lot "Oystor Creek 870911 Safety Limit Violetion Rept." Suor, E.H. 88/03/31, 207pp. 45257:247-45258.092.
- -8804250193 Vol III of "Oystor Creek 870911 Safety Limit Violation, Individual Repts." Stier, E.H. 87/03/31, 128pp. 45258:993-45258:222.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings" Svc list enci. ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165:150.
- 8804250309 Responds to NRC 871230 lit re violations noted in Insp Rupt 50:219/87-37.Util does not intend to pursua formal interpretation of 10CFR73.55(d)(8) from Old of General Coursul MANGANARO, Fr. General Public Utilities Corp. GPU Service Corp. 88/04/15. Decument Control Branch (Occument Control Dask). 2pp. 45258:200-45258:201

8804220084 Monthly operating rept for Mar 1988.W/880415 ltr. SEDAR,J.H., FIEDLER,P. Goneral Public Utilities Corp. - GPU Service Corp. 88/03/31. 7pp. 45216 217 45216 223.

S. Reportable occurrences, LERs & related correspondence

- 8803290241 LER 85-005-01 on 850210.six out of eight isolation condensor pipe broak sensors out of spec Caused by Instrument drift on sensors Sensor (B11A1 had defective switch actuating carn. Carn replaced. Five other sensors reset.W/880317 ltr. ROGERS,J., FIEDLER,P.B. General Public Utritios Corp. GPU Service Corp. 987 03/17, Spp. 44916 239-44918 243.
- 8804060237 LER 88:004:00:on 880229.isolation condenser actuation pressure sensors exceeded seleptint limit Caused by Inadoquate Instrument repeatability.Pressure sen-sors adjusted within desired setpoint.W/880328 ftr. 28. 5pp. 45046:153-45048:157.
- 8804260389 LER 88-006-00 on 800325, four isolation condenser pipe break sensors tripped. Caused by past med & switch problems. Switches adjusted within Tech Spec limits & four roactor protection sys digital sensors to be replaced W/880419 ltr. LEITMANL W., FIEDLER, P.B. General Public Utililes Corp. GPU Service Corp. 88/04/19. 6pp. 45281-321-45281:326.

V. Operator Examinations

- 8604250088 Responds to FOIA request for Info re-scores of reactor operators & senior reactor operators Forwards requestification exam summary source sheets itsed in enclupp w/personal privacy into deleted.
 GRIMSLEY,D.H. Division of Rules & Records (Post 870413), 88/04/19, 80/LEY,K. Public Citizen's Critical Mass Energy Project, 2pp. 45213:003-45213.095.
- -6804250167 Package of NRC administered requalification exam results summary
 NRC No Detailed Affiliation Given: 87/07/20, 88pp. 45213.007-45213.095.

DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8804260415 Revised emergency plan implementing procedures including Rev 9 to EPP-17, "Communication Procedures," Rov 6 to EAP-1, "Activation & Direction of Emer-gency Plans" & Rev 9 to EAP-2, "Classification of Emergency....." W/880420 ltr. GORDON,E.C., ROMAN, T.W., ABBOT,R.B. Nagara Mohawk Power Corp. 68/04/20, 70pp. 45224:199-45224:325.

H. General correspondence

- 8804060382 Provides into re proposed reorganization per discussion at 880107 moeting Ultimate organization will relocate vice president nuclear goreitation to site Tech Spec change request to amond affected sections will be submitted Wrunci MANGAN,C.V. Nagara Motiawk Power Corp. 88703/21. Document Control Branch (Document Control Dosk). 3pp. 45007.019-45007.021.
- 8804270198 Informs of organizational changes within facility effective 880401.

 MANGAN,C V. Niegara Mohawk. Power. Corp. 88/04/19. Document Control Branch (Document Control Desk). 1p. 45244;273-45244.273

1. Figancial information

8804200253 "Niagara Mohawk Power Corp Annual Rept 1987." W/880408 ltr. HAEHLJ G., DÖNLON,W J., PERKINS,T.J. Niagara Mohawk Power Corp. 87/12/31 41pp 45176 061-45176:101.

- 8803240426 Genoric Ltr 88:06 to all power reactor Leonsces 8 applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl MIFAGLIA,F.J. Associate Director for Projects (Post 870411) 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972.153
- 8804050289 Forwards Amend 96 to License DPR-63 & safety evaluation. Amend de-lotes main steam warmup valves from Tech Spec Table 3.2.7 Valves removed from plant because they are not required. BENEDICT, PA. Project Directorate 1-1. 88/03/25 MANGAN,C.V. Niagara Mohawk Power Corp. 2pp. 44997.198-44997.203
- -8804050294 Amand 98 to License OPR-63,ravising Tech Spec Table 3.2.7 to dolete me'n steam warmup valves. CAPRA,R.A. Project Directorate I-1, 88/03/25, 4pp. 44997:198-44997:201.
- -8804050296 Safety evaluation supporting Amond 96 to License DPR-63.

 * Office of Nuclear Reactor Regulation, Director (Post 870411) 88/03/25. 2pp 44997 202-44997 203
- 8804060291 Forwards application for amend to License DPR-63,rovising Tech Specs by making Table 6,2-1, "Min Shift Crew Composition" consistent wimin staffing requirements in 10CFR50 54(m)(2)(i). Fee paid MANGAN.C.V. Niagara Mohawk Powor Corp. 88/03/28. Document Control Desk). 1p. 45034:188-45034:174.
- --8804060294 Application for amend to Liconse DPR-63 tevising Toch Specs by making Teble 6.2-1 consistent w/min stalling requirements of 10CFR54(m)(2)(i). MANGAN,C.V. Niagata Mohawk Power Corp. 68/03/28 2pp. 45034-169-45034-170
- --8804060297 Proposed Tech Space revising Table 8.2-1 re min shift crew composition. Niagera Mohawk Power Corp. 88/03/28, 4pp. 45034:171-45034:174
- 8804050181 Forwards safety evaluation granting relief from requirements of Paragraph IWP-3500(b) of ASME Bolfor & Prosauro Vessel Code,Section XI re inservice testing program.per 870708 request. CAPRA,R.A. Project Directorale I-1, 88/03/29, MANGAN,C.V. Niagara Mohawk Power Corp. 5pp. 44997:068-44997.074.
- --8604050207 Saloty avaluation supporting util 870708 requests for relief from requirements of ASME Broiler 8 Pressure Vessel Code, Section XI re inservice testing pro-
- gram. Office of Nuctear Reactor Regulation, Director (Post 870411) 88/03/29. 2pp. 44997.073-44997:074.
- 8804050306 Forwards safety evaluation granting relief from cortain provisions of Saction IX of ASME Boiler & Pressure Vessel Code & applicable addenda.per 10CFR50.65a(g)(G)(i).Rolief granted will not endanger life,property or common defense. CAPRA,R.A. Project Directorale I-1, 88/03/29, MANGAN,C.V. Niegara Mohawk Powor Corp. 4pp. 44997:212-44097:217.
- -8804050309 Safety evaluation granting util request for relief from hydrostatic test pres-
- sure requirements to main steam warmup lines.

 NRC No Detailed Attiliation Given: 68/03/29, 2pp. 44997;216:44997.217.
- 8804120230 Requests withdrawal of 870825 application to use alternative to 10CFR50.55a requirements re-temporary repair of leak in svc water discharge piping Permanent repair will be made during current refueling outage instead MANGAN,CV. Niagara Mohawk Power Corp. 88/04/04 Decument Control Branch (Document Control Desk). 1p. 45980-061-45980-061.
- 8804130418 Withdraws 880205 application & forwards application for amend to License DPR-63.Amend revises Tech Specs adding exception to Definitions 1.1a & 1.1b & adding new Sections 3.7.1 & 4.7.1.Fee paid MANGAN,C.V. Niagara Mohawk Power Corp. 88/04/05. Document Control Branch (Document Control Desk). 1p. 45132.325-45132.348
- --8804130421 Application for amend to License DPR-63,changing Tech Specs table of contents by adding exception to Definitions 1.1a & 1.1b & adding new Sections 3.7.1 & 4.7.1.
- MANGAN,C, Nisgara Mohawk Power Corp. 88/04/05. 3pp. 45132:326-45132:328.
- ~8804130424 Proposed Tech Specs,adding exception to Definitions 1.1a & 1.1b & adding new Sections 3.7.1 & 4.7.1 to table of contents.

 * Niagara Mohawk Power Corp. 88/04/05, 20pp. 45132:329-45132 348.
- 8804080088 Generic Ltr 88 07 to power reactor icensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Pianta." Svc list etcl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.

- DEAL63 MANGAN.C.V. N.agara Mohawk Power Corp. 89/04/08. Document Control Branch (Document Control Desk). 2pp. 45145-257-45145-262.
- ~8804180091 Revised NSHC pages to 880405 application for amend to License DPR-63 * Niagara Mohawk Power Corp. 88/04/08 4pp 45145-259-45145-262.
- 8804200441 Summary of 880329 meeting w/uH re individual road scram testing to be performed during restart following Reload 11. List of meeting attendess & items to be addressed in resubmittal of amend for scram time testing enct. HAUGHYMF, Project. Directorate I-1 88/04/08. Project. Directorate I-1, 4pp. 45178;222-45179;225.
- 8804190027 Advises that enclinduce of consideration of issuance of amend to License DPR-63 proposed NSPC determination & opportunity for hearing torwarded to Otc of FR to/ publication
 BENEDICT.R.A. Project Directorate 1-1 88/04/11. MANGAN.C.V. Niagara Mohawk
- Power Corp. 2pp. 45165 249 45165 259.
- -8804190333 Notice of consideration of issuance of amend to License DPR-63 & pro-posed NSRC determination & opportunity for healing re-adding new Tech Specs 3.7.1 8.4.7.1 to a drow shutdown margin testing to shutdown condution cold. BENEDICT,R A. Project Directorate I-1. 88/04/11. 9pp. 45165-251-45165.259.
- 8804220036 Forwards corrected Rev 0 to 23A5862, "Supplemental Reload Licensing Submitted for Nine Mile Point Nuclear Station Unit 1,Reload 11," submitted w/871218 Icense amend dequest. Pay 1 of supplemental reload licensing submitted glso encl. MANGAN.C.V. Magara Mohawk Power Corp. 88/04/13. Document Control Brench (Document Control Desk) 1p. 45221-222-45221-259.
- -8804220041 Rev 1 to "Supplemental Reload Licensing Submittal for Nine Mile Point Nuclear Power Station Unit 1.Reload 11."
 LAMBERT, P.A., PENTZIEN, D.C., CHARNLEY, J.S., General Electric Co. 23A5862 R01. 88/03/31, 18pp. 45221:243-45221:259,
- 8604220059 Advises that util will perform isotopic analysis of enriched sodium pentaborate in support of 880307 application for amend to Tech Specs 3.1.2 & 4.1.2 re liquid poison sys. Applicables itse procedures will be revised MANGAN,C.V. Nisgara Monawk Power Corp. 88/04/13. Document Control Branch (Document Control Desk). 1p. 45220-027-45220-027

O. Inspection reports, IE Bulletins & correspondence

- 8804130109 Notification of 880328 meeting w/util at Region I ofc to discuss regional evaluation phase of SALP, JOHNSON J. Region 1 ofc to discuss regional JOHNSON J. Region 1, Ofc of the Orector, 88/03/22, Region 1, Ofc of the Orector, 2pp. 45122.221-45122.222.
- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Suc list end.
 ROSSICE: Division of Operational Events Assessment (Post 870411), 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995;246.
- 8803220296 NRC Into Notice 88-010, Matts Licensees Lack of Mgt Controls Over Licensed Programs. Suc list end: CUNNINGHAM, R E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03728. Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804040161 Provides response to NRC Butletin 68 001 re defects in Westinghouse DS sequence in Provides response to NRIC Bulletin 88 up 1 of detects in Westinghouse US series Circuit breakers No Westinghouse series OS circuit breakers are used in any application at Unit 1,therefore, bulletin not applicable. MANGANCV. Ni-apara Mohawk Power Corp 88/03/28. Document Control Branch (Document Control Desk). 2pp. 45058.191-45058:192
- 8804050068 Forwards Insp Hept 50-220/88-01 on 880111-15.No violations noted. DURH, J.P. Region 1, Ofc of the Director, 88/03/30 MANGAN, C.V. Niagara Mohawk Power Corp. 2pp. 45028:254-45028.265.
- ~8804050074 Insp. Rept. 50-220/88-01 on 880111-15.No violations of deviations noted Major areas inspected organization & staffing OA.training & mgt support & com-
- CHAUDHARY,S., KAPLAN,H., WINTERS,R.W. Region 1, Ofc of the Director, 88/03/ 23, 10pp, 45028-258-45028-265.
- 8804120315 Forwards Rad ological Controls Insp Repts 50-220788-04 & 50-410788-05 8 notice of violation.

 BELLAMY,R.R. Region 1, Old of the Director, 68/04/04, MANGAN,C.V. Niagara Mohawk Power Corp. 2pp. 45129:123-45129:142.
- -8804120325 Notice of violation from insp on 890215-19 Violation noted workers using supplied all sand blasting hoods (Bullard 77/46 series) & no approved procedures in place for use & maint.

 Region 1, Ofc of the Director, 88/04/04, 1p. 45129.125-45129.125.
- ~8804120327 Insp. Repts 50-220/88-04 & 50-410/88-05 on 880215-19 No violations noted Major areas inspected Feansee radiological controls during Unit 1 outage & during Journe operations at Unit 2 including organization, staffing & training. NIMITZ, R. L. SHANBAKY, M.M. Region 1, Ofc of the Director. 88/04/01, 17pp.
- 45129 126 45129 142. 8804010256 NRC Into Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svc list encl ROSSICE, Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407.051.
- 8804200221 Forwards request for add into to evaluate valve operability considerations per IE Bulletin 85-003 into requested to suppl 870918 & 0122 responses to bulletin WENICKGER,E.C. Ragion 1, Otc. of the Director, 68704/11. MANGAN,C.V. Niagara Mohawk Power Corp. 4pp. 45226;143-45226:146.
- 8804060370 NRC Info Notice 88 012, "Overgreasing of Electric Motor Bearings." Svc list encl. ROSSI.C.E. Omiston of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150.

- amount of \$100,000.Corrective actions nuclear OA operations assigned respo for performing NDEs required by inservice testing program MANGAN,C.V. Niegara Mohawk Power Corp. 88/04/13. Ofc. of Enfercement 870413): 14pp. 45219.093.45219:106.
- 8804210082 Forwards payment of proposed imposition of civil penalty in am \$100,000,per 880314 notice of violation. MANGAN.CV. Niegara Mohawk Power Corp. 88/04/13. Document Control (Document Control Desk). 1p. 45235:222-45235.222.

R. Periodic operating reports & related correspondence

- 8803300346 Monthly operating rept for Jan 1988.W/880205 ftr. ROMANT, LEMPGES,T.E. Niagara Mohawk Power Corp. 88/01/31 7pp. 449; 44920.055.
- 8804130159 Monthly operating rept for Mar 1988-W/880408 ftr. ROMAN,T., PERKINS,T.J. Niegara Mohawk Power Corp. 88/03/31 10pp. 4513 45132:298.

S. Reportable occurrences, LERs & related correspondence

- 8803310040 LER 88-003-00 on 880222,reactor bidg omergoncy vontilation sys in when power supply housing washer fell into circuitry.Caused by perenro.Damaged power supply repaired & station work request issued W/680321 MAZZAFERRO.P.A., LEMGES,T.E. Niagara Mohawk Power Corp 88/03/244682366 44682366 44953:255-44953:259.
- 8804010002 LER 88-006-00.on 880226.main steam isolation valvos failed local le test Caused by valva packing deterioration. Valves declared inoparatio, settle requests to repair valves generated & failures documented W/880323 ltr. MAZZAFERRO.P.A., LEMPGES,T.E. Niagara Mohawk Power Corp. 88/03/2: 45028:171-45028:175
- 8804060189 LER 88 004-00 on 880225,automatic Initiation of emergency cool occurred Caused by personnel error resulting from procedural deficiency System on on mail standby condition. Temporary change issued WV/880323 fr. MAZZAFERRO,P.A., LEMPGES,T.E. Niegera Mohawik Powor Corp. 68/03/27 45028:345-45028:349
- 8804050383 PNO-I-88-036:on 880222 & 0321, discovered that keensee conduct 8 mentation of licensed operator qualification training did not meet request 10CFR55.58 & approved training procedures. Continuatory action its will be successful. LANGE, D. Region 1, Ofc of the Director. 88/03/28. 1p 45034:046-45034 046
- 8804190257 Special reption 880301,05 & 21,line suppression sys removed from greater than 14 days to support scheduled work in area Firo watch patrols & t suppression will be maintained until sys C-2151 & C-2113 returned to syc. PERKINST.J. Niagara Mohawk Power Corp. 88/04/08 RUSSELL,W.T. Region of the Director. 2pp. 45209.018-45209:019.
- 8804150075 LER 88.007-00.on 880313,automatic initiation of reactor bidg eme ventilation occurred due to procedural deficiency. LPRM assembly lowered into fuel handling procedure will be revised to correct deficiency, W/880412 ltr. MAZZAFERRO_P.A., PERKINS,T.J. Niagara Mohawk Power Corp. 88/04/12 45169.263.45159:268.
- 8804200303 LER 88-001-01:on 880115,0315 & 25,0xams missed during first 10 service losp interval (ISI) Identified Caused by right ineffectiveness in implement program plan flems needed to complete interval Identified W/880414 ltr. MAZZAFERRO P.A., PERKINS,T.J. Niegers Mohawk Power Corp. 88/04/14 45216:001-45216:007.
- 8804200263 LER 88-008-00.on 890317, containment penetration failed local loatest Cause not determined Valves & sys declared inoperable occurrence rept to document failure & work request generated to correct problem W/880415 lir. MAZZAFERRO,PA., PERKINS,T.J. Niegara Mohawk Power Corp. 88/04/15/45235:187-45235:171.

DOCKET 50-223 UNIV. OF LOWELL RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville MD Official mailing addro-remains same & project managers have new locations & phone numbers TS Mi still lead project manager for facility & A Adams will serve as backup. RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate. E 18. Attilitation Not Assigned. 3pp. 44856:322-44856;324.

Q. Inspection reports, IE Bulletine & correspondence

- 8804250153 Forwards Safety Insp Rept 50-223/88-01 on 880314-16 & 22. Three tions noted violations will be discussed at 880429 enforcement conference. KANE_W.F. Region 1, Oft of the Director, 88/04/18, BEGHIAN,L E. Lowell, Ur. Lowell, MA. 2pp. 45224:149-45224:159.
- -8804260154 Insp Rept 50-223/88-01 on 880314-16 & 22.Violations noted Mejor Inspected facility organization sciton on previous NRC findings.log records.procedures, surveillances.mgt oversight & reactor safety subcommittee HAVERIKAMP.D.R. Region 1, Old of the Director, 98/04/15, 9pp. 4522 45224:159.

DOCKET 50-224 UNIV. OF CALIFORNIA RESEARCH REACTOR

23

P. Operating license stage documents & correspondence

- 8803080487 Informs that NRC requested Ofc of FR to publish ench "Notice of Proposed Issuance of Orders Authorizing Disposition of Component Parts & Termination of Facility License," per 880/108 application RUBENSTEIN, IS Standardization & Non-Power Reactor Project Directorate 88/03/04. HEYMAN, IM California, Univ. of, Berkeley, CA 3pp. 44639.025-44639.031.
- --8803080494 Notice of proposed issuance of orders authorizing disposition of component parts & terminating Liconos R-101.
 RUBENSTEIN,L S. Standardzalion & Non-Power Reactor Project Directorate, 88/03/ D4. 4pp 44639 028-44639 031.
- 8803250248 Informs of NRC relocation to stated address Malfing address unchanged A Adams project manager & TS Michael's back-up project manager. RUBENSTEINL S. Standardization & Non-Power Reactor Project Directorate. 86/03/18 Affiliation Not Assigned 3pp. 44859.060-44850.062.

DOCKET 50-225 RPI CRITICAL EXPERIMENT

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of MRR to Rockville,MD.Official making address still remains same & project managers have new locations & phone numbers.TS Michaels stil feat project manager for facility & A Adams will serve as backup. RUBENSTEINLS Standardization & Non-Power Reactor Project Directorate. 88/03/18 Affiliation Not Assigned. 3pp. 44858 322-44856.324.

DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville,MD.Official mailing address still remains same 8 project managers have new locations & phone numbers TS Michaels still lead project manager for facility & A Adams will serve as backup.
RUBENSTEIN,L.S. Standardzation & Non-Power Reactor Project Directorate. 88/03/ 18. Affiliation Not Assignad. 3pp. 44856:322-44856:324.

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8803290341 Forwards Saloty Insp. Repts 50-237/88-04 & 60-249/88-04 on 880228-0302. No wolations of NRC requirements noted. SHAFER.W.D. Region 3, Otc. of the Director. 88/03/18. REED,C. Commonwealth Edison Co. 2pp. 44975
- --8803290343 Insp Repts 50-237/88-04 & 50-249/88-04 on 880229-0302 No violations of NRC requirements noted Major gross inspected: observation by four NRC repre-sentatives of key functions & locations during annual emergency preparedness exer-
- CISO. PLOSKIT, PATTERSON,J., SMITH,M. Region 3, Ofc of the Director, 88/03/18, 16pp.
- 8804250078 Rev 1 to Safe Shutdown Procedure DSSP 010-1, "Safe Shutdown Paths for Extensive Plant Damage" & Rev 4 to Emergency Plan Implementing Procedure EPIP 200-20, "Control Room Evacuation/Safe Shutdown...." Revised tables & indices
 - Commonwealth Edison Co. 88/04/07, 300pp, 45251;122-45252.097.

P. Operating license stage documents & correspondence

- 8803300255 Application for amends to Licenses DPR-19 & DPR-25,revising Tech Specs to clarify applicability of containment oxygen. Fee paid.

 JOHNSON,I.M. Commonwealth Edison Co. 88/03/18. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 3pp. 44975:337-44975:365.
- -- 8803300257 Proposed Tech Space, clarifying applicability of containment oxygen concontration.
- Commonwealth Edison Co. 88/03/18, 16pp. 44975:340-44976:355.
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements. Sec list encl. MIRAGLIAF.J. Associate Director for Projects (Post 870411) 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972.153.
- 880.4010085 Advises that current practice re undervoltage trip adequately meets safety intent of Tech Specs Table 3.2.2 & acceptable.Temporary waiver of 2 months grant-HOLAHAN,G. Assistant Director for Region III & Region V Reactors. 88/03/25. BUTTERFIELD,D. Commonwealth Edison Co. 2pp. 44921;344-44921;355.
- --8804010087 Requests temporary waiver of compliance for Tech Spec 3.2.2 re under-vollage setting for 4 kV relays Basia for first level 4 kV under-voltage relay settings
- SILADY, J.A. Commonwealth Edison Co. 88/D3/23. MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 4pp. 44921.346-44921:355.
- 8804010204 Forwards addi Info requested re SEP Topic VIII-3.B,DC power sys monitors & ennunciators in control room at facility.W/ dc sys monitoring drawings. JOHNSON,I.M. Commonwealth Ed:son Co. 88/03/25. MURLEY,T.E. Öffice of Nuclear Reactor Regulation, Director (Post 870411). 12pp. 44947:288-44947:304.
- --8804010206 Rev 3 to DOA 902(3)-8 E-9, "Undervoltage Alarm for 250 Volt, 125 Volt & 48/24 Volt Batteries."
 * Commonwealth Edison Co. 87/11/30, 1p. 44947:301-44947:301.
- --580 40 10209 Rev 2 to DOA 6900-1, "DC Electrical Sys Failure." Commonwealth Edison Co. 81/08/31, 3pp. 44947:302-44947:304.

- 8804110084 Application for amends to Licenses DPR-19 & DPR-25, correcting discrepancy between Table 3.2 2 value for 4 kV emergency bus undervoltage trip (3.082 volts). Fee paid.
 SILADY.J.A. Commonwealth Edison Co. B8/03/28 MURLEY.T.E. Office of Nuclear
- Reactor Regulation, Director (Post 870411). 6pp. 45142.065-45142.078 --88041†0086 Proposed Tech Speca,correcting discrepancy between Tahle 3.2.2 value for 4 kV emergency bus undervoltage trip (3,092 volts) & current trip value (2,930
- Commonwealth Ed.son Co. 88/03/28, 8pp. 45142,071-45142,078
- 8804060524 Documents 880317 telcon re embedment plate assessment program re analysis method & acceptance criteria for computation of allowable loads for strip embedment plates w/ 24-inch anchor spacing.

 JOHNSON,I.M. Commonwealth Edison Co. 88/03/31. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 45010.287-45010.287.
- 8804070265 Responds to 880129 & 0224 litts re alleged hezardous practices at utili Discusses exidence of licensee compliance to federal regulations & nonviolation of requirements No further action intended.

 GREENMAN,E.G. Region 3, Oic of the Director, 88/03/31, YOUNG,C. Aftiliation Not Assigned 4pp. 45029,261-45029;264.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concorring 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA,F. J. Associato Director for Projects (Post 870411) 89/04/07. Consolidated Edison Co. of New York, Inc. 48pp. 45164:237-45164:285.
- 8804180098 Confirms 860419 mgt meeting w/util at Region III ofc to discuss performance of plant.par 880407 tetcon.
 GREENMAN.E.G. Region 2, Ofc of the Director. 88/04/11. REED.C. Commonwealth Edson Co. 1p. 45145:354-45145:354.
- 8804280039 Forwards Rev 50 to CE-1-A, "QA Program for Nuclear Generating Stations." Revs being made to reflect organizational changes MORGANWE. Commonwealth Edison Co. 88/04/18. Document Control Branch (Document Control Desk) tp. 45261:273-45261:299.
- --8804280069 Ray 50 to "QA Program for Nuclear Generaling Stations."

 **Commonwealth Edison Co. CE-1-A R50. 88/04/18, 17pp, 45261:274-45261.299.

Q. Inspection reports, IE Bulletins & correspondence

- 8803290341 Forwards Salety Insp. Repts 50-237/88-04 & 50-249/88-04 on 880229-0302.No violations of NRC requirements noted. SHAFER.W.D. Region 3, Otc of the Director, 88/03/18. REED.C. Commonwealth Edison Co. 2pp. 44975:232-44975:249.
- --8803290343 Insp Repts 50-237/88-04 & 50-249/88-04 on 880229-0302 No violations of NRC requirements noted Major areas inspected; observation by four NRC representatives of key functions & locations during annual emergency preparedness exer-PLOSKI,T., PATTERSON,J., SMITH,M. Region 3. Ole of the Director. 88/03/18. 16pp. 44975:234-44975.249.
- 8804060315 Responds to NRC 880218 ftr re violations noted in hasp Rept 50:237/87-40. Corrective actions procedure change to App A Issued to specifically require check of intermediato range morellor & APRM bypass configuration.

 SILADY, J.A. Commonwealth Edison Co. 88/03/18. DAVIS, A.B. Region 3, Ofc of the Director. 5pp. 45007:324-45007:328.
- 8803210090 Suppl 1 to NRC Into Notice 87.044, "Thimble Tube Thinning in Westing-house Reactors." Svc list encl.

 HOSSIC.E. Division of Operational Events Assessment (Post 870411). 88/03/28.

 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44095-246.
- 8803220296 NAC Info Notice 88-010, "Mails Licensees Lack of Mgt Controls Over Liconsed Programs." Svc Ist encl.
 CUNNINGHAM,R.E Owision of Industrial & Medical Nuclear Salety (Post 870729), 88/03/28, Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804060486 Ack receipt of 860315 ftr & payment of proposed civil penalty in amount of \$50,000. LIEBERMAN,J. Oic of Enforcement (Post 870413). 88/03/31, O'CONNER,J.O. Com-monwealth Edison Co. 1p. 45010.343-45010:343.
- 88D4080505 Forwards Safety Insp. Repts 50-237/87-30 & 50-249/87-29 on 870903-880316.No violations noted.

 HARRISON, J.J. Region 3, Otc of the Director, 88/04/01. REED,C. Commonwealth Edison Co. 1p. 45092/047-45092:100.
- --8804060511 Insp. Repts 50-237/87-30 & 50-249/87-29 on 870903-880211.No violations noted Major areas inspected previously identified noncompliance & unresolved terms & crisite followup of events at operating facilities.

 GAVULA, J.A., HUBERIM P, DANIELSON, D.H. Region 3, Ofc of the Director. 88/04/01. 39pp. 45092.048-45092:100.
- 8804070169 Ack receipt of 871129 & 880315 responses to 871113 allegations re radi-ation protection & filness for duty issues at plant.Responses adequate & no further questions or requests at this time. NORELUSC.E. Region 3, Oic of the Director. 88/04/01. REED.C. Commonwealth Edison Co. 1p. 45024:354-45024:354.
- 8804120366 Forwards insp Repts 60-237/88-05 & 60-249/88-05 on 880130- 0317 & notice of violation No reply to notice of violation required FORNEY,W.L. Region 3, Oto of the Director. 88/04/05. REED.C. Commonwealth Edison Co. 2pp. 45142.079-45142.085.
- +8804120370 Notice of violation from insp on 880130-0317. Violation noted.CRD E-9 which had been electrically disarmed found to be electrically armed & no out-of-svo card posted in area of hydraulic control unit for E-9. FORNEY, W.L. Region 3, Ofc of the Director 88/04/05. 1p. 45142.081-45142.081.

- -8804120378 fnsp Repts 50-237/68 05 & 50-249/68-05 on 880130-0317. Violations noted Major areas inspected pravious inspectional inspectational safety vertication, following 0 events, LER following into notice following 8 mit meetings HaNG,M A Region 3, Ofc of the Ozcotor, 88/04/05 14pp. 45142-082-45142-085.
- 8804010256 NRC info Notice 88-011, "Potential Loss of Motor Control Cir &/or Switch-board Function Bue to Faulty Tio Boits." Svc fist encl ROSSICE. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407.051.
- 8804060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc iist enci AOSSI,CE Drivision of Operational Events Assossment (Post 870411) 88/04/12. Consolidated Edison Co. of Now York, Inc. 123pp. 45165.028-45165.150
- 8804200498 Confirms plans made between J Stady & DE Jones re 880502 meeting at plant site to present SALP 7 rept.Appropriate corporate & plant mgl requested to be present.
 GREENMANLE G. Region 3, Clc of the Director 88/04/13 REED,C. Commonwealth Edison Co. 2pp. 45174-352-45174-353
- 8804250328 Confirms plans discussed on 880414 between 11 Riss & G VanStokle re upcoming 880508 meeting w/util to discuss response to IE Bulletin 85,003, GREENMAN,E G. Region 3, 01c of the Director, 88/04/18, REED,C Commonwealth Edison Co. 2pp. 45251-120 45251-121.

- 8804220163 Forwards correction to "Effuent & Waste Disposal Somiannual Rept Jan-line 1987." Estimated percent of major nuclide composition for irradiated components control rods, etc inadvertently included in rept No such waste shipped. EENIGENBURGE. Commonwealth Edison Co. 87/12/18 DAVIS, A.B. Region 3, Ofc of the Director, 1p. 45254 136-45254:137.
- --8804220165 Corrected "Effuent & Wasio Disposal Semiannual Rept, Jan-June 1987." Commonwealth Edison Co. 87/12/31, 1p. 45254:137-45254:137.
- 8804150406 Monthly operating repts for Mar 1988 W/580407 ltr.
 MAXWELL.D.C., EFNIGENBERG.E. Commonwealth Edison Co. 88/03/31, 19pp.
 45183184-45183-296
- 8864270052 Forwards corrected radioactive effluent rept for Jul Doc 1987 Final data for Listed elements included.

 EENIGENBURGE. Commonwealth Ed.son Co. 88/04/12. DAVIS.A.B. Region 3, Ofc. of the Director. 1p. 45217 241-45217.257
- --8804200110 Corrected "Eltituent & Waste Disposal Semiannual Rept.Jul/Dec 1987."
 *Commonwealth Edison Co. 87/12/31, 16pp. 45217.243-45217;257.

S. Reportable occurrences, LERs & related correspondence

8803280022 LER 88-004-00-ori 880221 inoperable CRD E-9 found electrically armed due to personnel error CRD disarrised & out-of-sixe card hung on hydrautic control umitizent discussed w/personnel at weakly meeting W/880314 ltr.
FALCONE M.A. EEN:GENBURG,E. Commonwealth Edison Co. 88/03/16. 5pp FALCONE M A. EEN 44920 018 44920 022

V. Operator Examinations

- 8804250088 Responds to FOIA request for info re-scores of reactor operators 8, senior reactor operators Forwards requalification exam summary source sheets listed in end app w/personal privacy info deleted.
 GRIMSLEY,O.H. Division of Rules 8, Records (Post 870413), 88/04/19, BOLEY,K. Public Citizen's Critical Mass Energy Project. 2pp. 45213:003-45213:095
- ~8804250167 Package of NRC administered requalification exam results summary.

 ' NRC No Detailed Affiliation Given, 87/07/20, 88pp, 45213.007-45213.095.

DOCKET 50-238 NUCLEAR SHIP SAVANNAH

P. Operating ficense stage documents & correspondence

- 8803250248 Informs of NRC relocation to stated address.Mailing address unchanged.A Adams project manager, 8.15 Michaels back-up project manager, RUBENSTEIN,L.S. Stendardization & Non-Power Reactor Project Directorate 88/03/18. Affiliation Not Assigned: 3pp. 44859.080-44859.082
- R. Periodic operating reports & related correspondence
- 8804010236 Forwards Part 3 of plant environ radiological & melecrological munitoring rept.W/o enci EENIGENBURG,E. Commonwealth Edison Co. 88/03/18, DAVIS,A.B. Region 3, Old of the Orector, 2pp. 45058-061-15058-061.

DOCKET 50-243 OREGON STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Mailing address unchanged A Adams project manager & TS Michaels back-up project manager. RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Ostectorate. 88/03/18. Affiliation Not Assigned. 3pp. 44859.080-44859.062.

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8804050136 Forwards Amend 26 to License OPR-18 & safety evaluation. Amend modilies Paragreph 2.5 to require compliance w/amended physical security plan.

 STAHLE.C. Project Overcorate 1-3, 88/03/28 KOBER,R. Rochester Gas & Efective

 Additional Application 1-3, 88/03/28 KOBER,R. Rochester Gas & Efective Corp. 4pp. 44997:030-44997.040.
- --8804050152 Amend 26 to License DPR-18, revising Paragraph 2 E to require complanca w/amended physical security plan WESSMAN,R.H. Project Directorate I-3, 88/03/28, 2pp. 44997,035-44997,036
- 8804130018 Informs of upcaming regulatory effectiveness roview to evaluate overall effectiveness of safeguards program & dotermine whether existing safeguards regulations yield level of protection intended by NRC W/enct.

 BELLAMY.R.R. Region 1, Old of the Director 88/04/07. SNOW,B A. Acchester Gas & Electric Corp. 3pp. 45154:152-45154:154.
- 8804200219 Forwards rave to listed pages & drawing to plant security plan Eccls with held (red 10CFR73.21).

 SNOW,8 A. Rochester Gas & Electric Corp. 98/04/15. Document Control Branch (Document Control Desk). 1p. 45225-353-45225-353.

P. Operating license stage documents & correspondence

- 8803100092 Summarizes 880303 discussions re lacility steam generator shibber re-placement program & plans to replace shubbers w/ngid structwed numbers.Completion of technical review requested by 880406 WESSMAN,R.H. Project Directorate I-3, 88/03/04, MARSH,L. Mechanical Engineering Branch, 2pp. 44662:112-44662:413.
- 8803240426 Generic Ltr 88:06 to all power reactor ficensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list end. MiRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972;107-44972;153.
- 8804050138 Forwards Amend 26 to License DPR-18 & safety evaluation. Amend modifies Paragraph 2.5 to require compliance w/amended physical socurity plan.

 STAHLE,C. Project Directorate 1-3, 88/03/28. KOBER,R. Rochester Gas & Electinc Corp. 4pp. 44997-030-44997-040.
- ~8804050152 Amend 26 to License DPR-16, revising Paragraph 2.E to require compilance w/amended physical security plan. WESSMAN,R.H. Project Directorate I-3, 88/03/28, 2pp, 44997:035,44997:036
- -8604050381 Safeguards evaluation rept supporting Amend 26 to License OPR-18, Office of Nuclear Reactor Regulation, Director (Post 870411). 88/03/28. 4pp 44997:037-44997.040.
- 8804120173 Forwards addl into to satisfy requirements & Intent of Parts 3 & 4 of Generic Lit 83:28.per 870928 commitment Util to ensure that engoing performance testing & monitoring program in place by 880531.

 KOBER,R.W. Rochester Gas & Electric Corp. 88/04/04. STAHLE.C. NRC No Delailed Affiliation Given, 3pp. 45079:310-45079:312.
- 8804140193 Provides listed into requested in 880225 ftr re operating nuclear power units located at twelve sites along Great Lakes.
 STELLO,V. Ofc of the Executive Director for Operations. 88/04/06. RIDGE,T. House of Rep. 5pp. 45104:138-45104:143.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment important to Safety for Nuclear Power Plants." Svc list encl MIRAGUA.F.J. Associate Director for Projecta (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 48pp. 45164:237-45184:285.
- 8804200573 Withdraws 880120 application for amend to license & requests that NRC review of amend request be closed out w/o action.

 SNOW,B.A. Rochester Gas & Electric Corp. 88/04/11. STAHLE,C. NRC · No Detailed Alfifilation Given. 1p. 45175:038-45175 038.
- 8604180285 Discusses proposed mod to existing steam generator upper lateral configu-ration & analysis to demonstrate acceptability of resulting loads from postulated seis-mic & other design bases events. STAFLEC Project Directorate 1-3, 88/04/13, KOBER,R.W. Rochester Gas & Electric Corp. 3pp. 45148,357-45148,359.
- 8804280044 Forwards table listing status of current licensing actions on plant. Table will be revised to reflect changes in dates for completion &/or new Issues that need It-
- censing reviews. STAHLE,C. Project Directorate 1-3, 88/04/20, KOBER,R.W. Rochester Gas & Electric Corp. 4pp. 45278:090-45276:093.
- 8604280214 Forwards table lialing facility license action Target dates shown for util & NRR.Tables could be revised to reflect changes in dates for completion &/or Issues that need ficensing review.

 STANLE, C. Project O

Q. inspection reports, IE Bulletins & correspondence

8804120407 Notification of Significant Licensee Meeting 88-032 on 880323 w/util in Rochester,NY to discuss SALP.
COWGILL.C.J. Region 1, Ofc of the Director, 88/03/02, Region 1, Dic of the Director, 2pp. 45090:343-45090:344.

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors" Svc list end. ROSSI,CE Division of Operational Events Assessment (Post 870411) 88/03/28. Consolidated Edson Co. of New York, Inc. 121pp. 44995-128-44995-246.
- 8803220296 NRC Into Notice 88:010, "Mails Licensees Lack of Mgt Contro's Over Licensed Programs " Svc list encl CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28 Consolidated Edison Co of New York, Inc. 108pp. 44995/247-44995:353,
- 8804050355 Forwards Exam Rept 50:244/88-02QL of exam administered on 800212. GALLO,H.M. Region 1, Otc of the Director. 88/03/28. KOBER,R W. Rochester Gas & Electric Corp. 2pp. 45032-059-45032-080
- →8804050358 Exam Rept 50:244/88-02OL on 880212 Exam results reactor operator candidate passed Section 3 of written exam. Warver of Sections 1,2 & 4 granted. SILK.D. ESELGROTH,P. Region 1, Ofc of the Director 88/03/25 20pp 45032 061.
- 6804060141 Ack recept of 880205 lir informing NRC of sleps taken to correct violations noted in Insp Rept 50-244/87-27.
 GALLO,R.M. Region 1, Ofc of the Director, 88/03/28, KOBER,R.W. Rochesier Gas & Electric Corp. 1p. 45074
- --8804080144 Rosponds to NRC 880108 ftr re violations noted in Insp Rept 50:244/87-27 Corrective actions:all P&ID discrepancies identified or to be identified from stated sources will be addressed & tesk force formed SNDW, FM. Rochester Gas & Electric Corp. 88/02/05. RUSSELL,W.T. Region 1, Old of the Director 4pp. 45074.070-45074.073.
- 8804060130 Forwards Insp. Ropt 50-244/88-03 on 880215-18 & notice of violation Weaknesses Identified In areas of posting & labeling.tovel of mg1 oversight & inventory sys for high radiation area keys.

 BELLAMY, R.R. Rogion 1, Otc of the Director, 89/03/29 KOBER,R.W. Rochaster Gas & Electric Corp. 2pp. 45046-250-45046:267.
- --8804060135 Notice of violation from insp on 880215-19.Violations noted on 880215-group of four individuals noted working on prossurizer intermodiate platform-posted high radiation area in containment. Region 1, Olc of the Director. 88/03/29. 2pp. 45046:252-45046:253.
- -- 8804060136 Insp Rept 50-244/88 03 on 880215 19 Violations noted Major areas eoutuou iso misp netri suczenziosus on issuzitis 19.Violations noted Major preas inspected radiation profection program during outago, including posting & labbling.mgt organization & controls, trainting & qualifications & external exposure controls. WEADOCK,A, LOESCH,R, SHANBAKY,M.M. Region 1, Ofc of the Director. 88/03/24 14pp 45046 254.45046:267.
- 8804010256 NRC Into Notice 88:011, "Potential Loss of Motor Control Ctr. &/or Switchboard Function Due to Faulty Tie Bolls." Svc list encl.
 ROSSIC.E. Division of Operational Events Assessment (Post 870411), 88/04/07.
 Consolidated Edison Co. of New York, Inc. 124pp. 45408:292-45407:051.
- 8804140074 Responds to NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakors" Plant does not have Westinghouse circuit breakers subj to buildin SNOW,B A Rochester Gas & Electric Corp. 88/04/07, RUSSELL,W.T. Region 1, Old of the Director 1p 45155.027-45155.027.
- 8804060370 NRC Info Notice 88-012, "Overgroasing of Electric Motor Bearings," Syc list enct. ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150.
- 8804280063 Advises that 671023 response to request for additinfoire US Tool & Die OA/OC of wolds for spont fuel pool rack at plant acceptable,based on util review of acceptable of racks & disposition of deficiencies found in util help STAHLE,C. Project Directorate 1-3, 88/04/15. KOBER,R.W. Rochester Gas & Efectric Corp. 2pp. 45276 094-45276.095.

8604220120 Monthly operating rept for Mar 1988.W/880415 ftr.
MCNAMARA,A.E., SNOW,B.A. Rochester Gas & Electric Corp. 86/03/31, 6pp. 45216:211-45216.216.

S. Reportable occurrences, LERs & related correspondence

- 8804140044 LER 88-002-00:on 880308,level of boric acid slorage tank less than 2,000 gallons in violation of Tech Specs Caused by partial plugging of tevel sensing lines Sensing lines cleaned prior to declaring tank operable.W/880405 ftr. BACKUS W.H. SNOW,B.A. Hochester Gas & Electric Corp 88/04/06. 9pp. 45152:162-45152:170.
- 8804140147 LER 88-003-00 on 880310 reactor trip occurred due to low steam generator. A feval coincident w/steam flow feedwater flow mismatch.Caused by unanlicipeted RCS temp control problems.Plant stabilized.W/880408 ltr.

 8ACKUS,W.H., SNOW,8 A. Rochester Gas & Electric Corp. 88/04/08. 7pp. 45152:120-45152:128.
- 8804180442 LER 88-004-00:on 880314,tube feak detected in steam generator B.Caused by misser cell from recent steam generator eddy current insp program.Eddy current data analysis procedures updated.W/880412 ltr.
 BACKUS,W.H., SNOW.B.A. Rochester Gas & Electric Corp. 88/04/12. 13pp. 45196 248 45196:260

V. Operator Examinations

- 8804050355 Forwards Exam Ropt 50:244/88:02OL of exam administered on 880212. GALLO,R.M. Region 1, Ofc of the Director, 88/03/28, KOBER,R.W. Rochester Gas & Electric Corp. 2pp. 45032:059-45032:080.
- --8804050358 Exam Rept 50-244/88-02QL on 880212.Exam results reactor operator candidate passed Section 3 of written exam Walver of Sections 1,2 & 4 granted. SILK.D., ESELGROTH.P. Region 1, Otc of the Director. 88/03/25, 20pp. 45032.061-45032:080

- 8804250088 Responds to FOIA request for info re-scores of reactor operators & senior reactor operators. Forwards requalification exam summary source sheets listed in encl app w/personal privacy into defered. GRIMSLEY,D H. Dwsfon of Rufes & Records (Post 870413) 88/04/19. BOLEY,K. Public Critical Mass Energy Project. 2pp. 45213.003-45213.035.
- 8804250 167 Package of NRC administered requalification examines uts summary
 NRC No Dotailed Affiliation Given 87/07/20 88pp 45213 007-45213.095

DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8804060003 Forwards addl into clarifying proposed change to NRC 871223 physical se-curity plan per 870516 telecon Encl withhold (rul 10CFR7321 & 2790(a)) MROCZKAE J. Northeast Utilities 88/03/29. Document Control Branch (Document Contro! Desk). 2pp 45947.173-45047.174.
- 8804060142 Forwards SALP Repts 50:245/86-99 & 50:336/86-99 for June 1986 Dec 1987.Util should be prepared to discuss assessments & any plans to improve perform-
 - RUSSELL,W.T. Reg on 1. Old of the Director 88/03/29 MROCZKA,E.J. Northeast Nuclear Energy Co. (subs of Northeast Ulrities) 2pp. 45945-325-45046-063
- --8804060147 SALP Ropts 50-245/86-99 & 50-336/86-99 for June 1988 Dec 1987 * Region 1, Ofc of the Director, 68/02/25 97pp, 45045-327-45046-063
- 8804080269 Rev. 3 to emergency plan implementing procedure (EPIP) Form 4211-1, "Station Emergency Organization Load Oncall Position Managers." Rev. 82 to EPIP form index & 800331 fit enct. MROCZKA,E.J. Northeast Nuclear Energy. Co. (subs. of Northeast Utilities) MROCZKA,E.J. Northeast Utilities, 88/03/31, 8pp. 45123:289-45123:296.
- 8804200028 Forwards Resident Insp. Rept 50 245/88-03 on 880209-0321 No vicinions noted Performance Illaws noted in Itimely Implamentation of Tech Specs amends & continued occurrence of high radiation area doors being loft unlocked. BETTENHAUSENIL Region 1, Off of the Director, 88/04/11 MROCZKA E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 45231:106-45231:118
- --0604200033 Rosident Insp Rept 50-245/88-03 on 880209-0321.No unsate ptent conditions noted Mejor areas inspected.physical security.860312 reactor scram.survetlance.maint.unlocked high radiation area doors, LERs & committee activities. MCCABE,E.C. Region 1, Old of the Director, 88/04/07, 11pp. 45231 108-45231 118.
- 880422027 Advises that revised post-fire sale shutdown methodology conforms w/re-quirements of Sections ING 3, 8 INL of App R, 10CFR50 & acceptable.per 861210 ltr.Technical evaluration Rept SAIC-87/3084 enct BOYLE,M.L. Project, Directorate 1-4, 89/04/14 MROCZKA,6 J Northoast Nuclear Energy Co. (subs. of Northeast Utritios). 2pp. 45201.128-45201:146.
- --8710080577 "Tachinical Evaluation Rept Millstone Nuclear Power Station, Unit 1,Post-Fire Shutdown Evaluation,App R."
 Science Applications International Corp. (formerly Science Applications, Inc.). NRC-03-67-020. SAIC-87/3084. 87/10/02. NRC No Dotard Affiliation Given. 17pp. 45201:130-45201:146.
- 8804250287 Forwards temporary change to physical security plan re-protected area boundary. Roy withhold (ref. 10CFR72-790(a)).
 MROCZKA,E.J., ROMBERG,W.D. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA,E.J. Northeast Utilities). MROCZKA,E.J. Northeast Utilities. 88/04/22 Document Control Branch (Document Control Desk). 2pp. 45281-286-45281-287.

H. General correspondence

8804070291 Comments supporting proposed rule 10CFR50 re teakage testing of containment to permit use of mass point method as alternative method for calculating containment leakage rates Mass point method more accurate for calculating rates MROCZKA,E.J. Connecticut Yankee Atomic Power Co. MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Unities) MROCZKA,E.J. Northeast Unit as 88/03/31. CHILK,S.J. Office of the Secretary of the Commission. 3pp. 45021.184-45021:186

I. Financial Information

- 8804149014 Ferwards Connecticut Light & Power Co & Wostern Massachusetts Electric Co "Annual Rept 1987," per 10CFR50.71(b) Northoest Nuclear Energy Co financial rept will not be available until on or about 88027. GUGLIELMO,F.J. Northeast Ullifies. 88/04/07. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 45122:337-45123.050
- --8804140017 "Annual Ropt 1987."
 FOX.B.M., ELLIS.W.B. Connecticul Light & Power Co. (subs. of Northeast Utillies). 87/12/31. 43pp. 45122.338.45123.019.
- ~8804140022 "Annual Rept 1987."
 FOX.B.M., ELLIS.W.B. Western Massachusetts Electric Co. (subs. of Northeast Utilities), 87/12/31, 31pp. 45123:020-45123:050
- 8804260249 Informs that payment of third quarterly installment of 1998 annual fee per 10CFR171 will be wire transferred on 880429.
 MRIOCZKA,E.J. Connect cut yanke Atomic Power Co. MRIOCZKA,E.J. Northeast Nuclear Energy Co. (subs of Northeast Unitles. MRIOCZKA,E.J. Northeast Unitles. MRIOCZKA,E.J. Northeast Unitles. MRIOCZKA,E.J. Northeast Unitles. MRIOCZKA,E.J. Northeast Unitles. 88/04/18. Document Control Branch (Document Control Desk) 2pp. 45258 292-45268-292-45268-2018 45258:293

J. Insurance & indemnity information

8804070118 Notifies Commission of amount of property insurance coverage currently in force for facilities Types of coverage & markets histed MROCZKA.E.J. Northeast Millies Energy Co. (subs. of Northeast Utifies) MROCZKA.E.J. Northeast Utifies 88/03/30 WOOD.R. Poticy Development & Technical Support Branch (Post 970411), 2pp. 45022 092-45022.093.

K. Utility Final Safety Analysis Report (FSAR) & amends

8804050605 Rev 2 to updated FSAR for Millstone Unit 1 W/890329 Itr MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utivities). MROCZKA,E.J. Northeast Utivities. 88/03/29, 725pp. 45058;921-45060.325

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re-removal of organization charts from Tech Spec administrative control requirements. Suc list and, MITAGLIA.F.J. Associate Director for Projects (Post 870411) 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107.44972:153.
- 8803310207 Application for amend to tucense DPR-21,adding ficense condition re inte-grated implementation schedule. "Milistone Nuclear Power Station,Unit. 1,Integrated Implementation Schedule Program Plan" and Fee paid. MROCZKA.E.J. Northeast. Nuclear. Energy. Co. (subs. of Northeast. Utilities). MROCZKA.E.J. Northeast. Utilities. 88/03/24. Document. Control Branch. (Document Control Desk). 7pp. 44961.327-44961:342
- ~8804040196 "Millstone Nuclear Power Station, Unit 1, Integrated Implementation Schedthe Program Plan "

 Northeast Nuclear Energy Co (subs of Northeast Utilities) 88/03/31. Spp. 44961.334-44961.342.
- 8804010009 Forwards Amend 16 to License DPR-21 & safety evaluation. Amend clarifies facility exclusion area boundary by changing Tech Spec 5.1, "Sile Design Fea-
- lores | Directorate 1-4, 88/03/28, MROCZKA.E.J. Northeast Nuclear BOYLE.ML. Project Directorate 1-4, 88/03/28, MROCZKA.E.J. Northeast Nuclear BOYL Energy Co. (subs. of Northeast Utilities), 2pp. 44920.338-44920.347.
- --8804010011 Amend 16 to License DPR-21, clarifying facility exclusion area boundary by changing Tech Spec 5.1, "Site Design Features." STOLZ,J.F. Project Directorate I-4, 88703728, Spp. 44920:340-44920,344.
- --8804010013 Safety evaluation supporting Amend 16 to License DFR-21. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/28, 2pp 44920 345-44920 347.
- 8804060282 Forwards notice of consideration of issuance of amend to License DPR-21 changing Tech Specs to provide for operational lieutolity by allowing single loop operation at reduced power in event maint of recirculation pump. BOYLE.M.L. Project Directorate 1-4. BB/03/28. MBCGZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utulties). 2pp. 45017.288.45017.291.
- ~3804060287 Notice of consideration of issuance of amend to Ucense DPR:21 & op-portunity for hearing on 870817 request re operational flexibility by allowing single loop operation at reduced power in event maint of recirculation pump STOL2,3 F. Project Directorate I-4, 88/03/28, 4pp. 45017;288-45017;291.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment important to Safety for Nuclear Power Plants" Svc list enct MIRAGLIA.F.J. Associate Director for Projects (Post 870411), 88/04/07 Consolidated Ed.son Co. of New York, Inc. 49pp. 45184:237-45164:285.
- 8804 120423 Forwards payment on invoice for costs incurred during NRC review of Revs 8 8 9 to Topical Rept NU-DA-1.

 MROCZKA,E.J. Connectcut Yankee Atomic Power Co. MROCZKA,E.J. Northeast Nu-clear Energy Co. (subs. of Northeast Utilities). MROCZKA,E.J. Northeast Utilities, 887-04708. Document Control Stanch (Document Control Desk). 4pp. 45091.001-45091.004 45091.004.
- 8804270231 Submits comments supporting proposed rule to ensure that presence of NRC inspectors on power reactor sites should not be announced to licensee personnel Licensee feels rule makes sense but not practicable MROCZKAE J. SEARS,C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA,E.J. Northeast Utilities 88/04/18, Docketing & Services Branch. 3pp. 45244 247-45244;249.
- 8804290282 Advises that Yech Spec revice specific distance for taking radiation measurements in areas where dose rates exceed 1,000 mrem/h will be processed & submitted to NRC to provide improved & consistent program on high radiation areas. MROCZKA,E.J. ROMBERG,W.D. Northeast buctear Energy Co. (subs. of Northeast Utilities). MROCZKA,E.J. Northeast Utilities 88/04/22. Document Control Branch (Document Control Desk). 2pp. 45282 181-45282.182.

O. Inspection reports, IE Bulletins & correspondence

- 8803300412 Provides clarification of commitments re IGSCC & acoustic emission (AE) leak detection sys Revised overlay design calculation using methodology acceptable leax delection sys Hevised overlay design calculation using methodology acceptable to NRC provided.

 MROCZKA.E.J. Northeast Nuclear Energy Co. (subs. of Northoast Utilities).

 MROCZKA.E.J. Northeast Utilities. 88/03/25. Document Control Branch (Document Control Desk). 2pp. 44979;140-44979;141.
- 8803310043 Responds to NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakers." Two reactor trip breakers & two reactor trip bypess breakers subj to bulletin
 used at Milistone Unit 3 Main pole shaft weld insps completed by 880225.
 MROCZKA,E.J. Connecticut Yankee Atomic Power Co. MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utitioas) MROCZKA,E.J. Northeast Utitioa. 887
 03/25 RUSSELL,W.T. Region 1, Old of the Director. 2pp. 44984;136-44984;137.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list end ROSSICE. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:128-44995-246.

- 8803220296 NAC Into Notice 88-010, "Malls Licensees.Lack of Mgt Contro's Over 14-censed Programs " Svc list encl CUNNINGHAM, R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 337-03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995:353
- 8804060142 Forwards SALP Rents 50-245/86-99 & 50-336/86-99 for June 1988 Dec 1967 Util should be prepared to discuss assessments & any plans to improve perform 85.08
- RUSSELL,W.T. Region 1, Ofc. of the Director, 88/03/29, MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Util. Les), 2pp. 45045;325-45046;383
- --8804060147 SALP Repts 50-245/86-99 & 50-336/86-99 for June 1986 Doc 1997 * Region 1, Old of the Director 88/02/25 97pp 45045/327-45046.063.
- 8804070319 Forwards addl into re util 870512 (esponso to Genezic Ltr 87-05 Detailed 1944/1919 Forwards add into re util 87/912 response to Generic Lit 87/99 beared visual-irisp of eight 1-inch drain frees & ultrasonic thickness measurements on drywcl shell plates adjacent to sand cushion conducted during refueling outage MROCZKA,E J. Northeast Nuclear Energy Co. (subs. of North-gast Cti-lest MROCZKA,E J. Northeast Utilities 88/03/31 Document Control Branch (Document Control Desk) 12pp 45048:245-45048-256.
- 8804130306 Advises that NRC reviewed into provided in util 880314 ltr, Teich Spec Section 3/4.6 & associated bases. Current insprinterval of 18 months plus/minus 25% proper interval
 BOYLE,M.L. Project Directorate 1-4, 88/04/06, MROCZKA,E.J. Northeast Nuclear
 Energy Co. (subs. of Northeast Utilities). 3pp. 45103.163-45103:165.
- 8804010256 NRC Info Notice 88.011, "Potential Loss of Motor Control Cir &/or Switch board Function Due to Faulty Tia Bolts." Syc itst and! ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 98/04/97 Consolidated Edison Co. of New York, Inc. 124pp. 45408:292-45407:051.
- 8804200028 Forwards Resident Insp Rept 50-245/88-03 on 880208-0321 No violations noted Performance Illaws noted in timely implementation of Tech Space amands & continued occurrence of high radiation area doors being left unlocked.

 BETTENHAUSENL. Region 1, Ofc of the Director. 88/04/11. MROCZKA,E.J. Northeast Unideed Energy Co. (subs. of Northeast Unidee). 2pp. 45231:106-45231:118
- --8804200033 Resident Insp. Rept 50:245/88:03 on 880209:0321.No unsafe plant conditions noted Mejor areas inspected physical security,880312 respected physical security. tions noted Major areas inspected physical security,880312 lead of scram, surveillance, maint, unlocked high radiation area doors, LEAs & committee activities. MCCABE, E.C. Region 1, Ofc of the Director, 88/04/07, 11pp. 45231:108-45231.118
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings" Sys
- list end. ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165-150
- 8804200506 Responds to NRC 880216 ltr re violations noted in Inso Reat 50-245/87 33 Unit to maintain Increased exercises a sensitivity of need to promptly inform NRC of chant conditions having level of significance of falled leak lest MROCZKA.E.J. Northcast Nuclear Energy Co. (subs. of Northcast Utilizes). MROCZKA.E.J. Northcast Nuclear Energy Co. (subs. of Northcast Utilizes). MROCZKA.E.J. Northcast Utilizes). MROCZKA.E.J. Northcast Utilizes). MROCZKA.E.J. Northcast Utilizes 98/04/14. BETTENHAUSEN,L. Region 1, Oic of the Director. 2pp. 45239.059.45239.080.

R. Periodic operating reports & related correspondence

8804130054 Monthly operating rept for Mar 1988.W/880408 ftr NEWBURGH.G., SCACE.S E. Northeast Nuclear Energy Co. (subs. of Northeast Utifies). SCACE.S E. Northeast Utilities 88/03/31, 8pp. 45131:053-45131 058.

S. Reportable occurrences, LERs & related correspondence

- 8604070049 LER 87-029-01:on 870724.atmospheric control sys valve 1-AC-10 tagged out 8 removed for routine maint isolating standby gas treatment sys for primary containment Caused by operator failure to recognize interlock W/880329 III: YAPCHANYK.O.J., SCACE.S.E. Northeast Nuclear Energy Co. (subs. of Northeast Uslikes) SCACE.S.E. Northeast Utilities. 88/03/29, 4pp. 45030:347-45030:350.
- 804140036 LER 88:003:00:on 880312,reactor scram on low water lovel occurred Caused by feed pump trip Faedwater pump A low suction pressure switch replaced, recaliby & testod satisfactorily.W/880407 ltr. LINDSAY.E.J., SCACE.S.E. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). SCACE,S.E. Northeast Utilities. 88/04/07, 4pp. 45142:261-45142:264.
- 8804140042 LER 88-002-D0.on 880310.discovered that SP 1050, "Inservice Insp Pro gram Pump Vibration & Hydraulic Test" for svc water pump C missed.Caused by per-sonnel error.Methods for surveillance scheduling changed W/880407 Irr. BIGIARELLI,M.J., SCACE,S.E. Northeast Nuclear Energy Co (subs. of Northeast Utili-ties). SCACE,S.E. Northeast Utilities. 88/04/07. 3pp. 45133:001-45133:003
- 9804190019 LER 88.004-00:on 880318, discovered potential for ECCS pump suction strainers to foul withbrous insulation debris Caused by Insufficient area of existing strainers Strainers replaced W/80412 ltr.
 KANE,S.E., SCACE,S.E. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
 SCACE,S.E. Northeast Utilities. 88/04/12, 4pp. 45187.040-45197:043.

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

F. Security, medical, emergency & tire protection plane

- 8804120337 Forwards revised page to 8/1214 proposed amend to security plant Page withheld (ref 10CFR2.790(d) 8 73.21). BRAM,S.B. Consolidated Edison Co. of New York, Inc. 88/03/30 Document Control Branch (Document Control Desk). 2pp. 45135:338.45135:337.
- 8804290071 Forwards notice of withdrawal of 810807 application to amend License DPR-26 & supersedes 850802 application refure protection requirements SLOSSON,M.M. Project Directorate 1-1, 88/04/21, BRAM,S.B. Consolidated Edison Co. of New York, Inc. 2pp. 45322.288-45322.288

--8804290081 Notice of withdrawal of 810807 application for amend to Liconse DPR-26 revising Tech Specs to incorporate requirements for alternate safe shutdown sys SLOSSON,M Project Directorate 1-1 88/04/21, 1p. 45322 288

Q. Advisory Committee on Reactor Safeguards reports & correspondence

880414D215 Submits summary of actions discussed at ACRS 335th meeting on 880310-12 in Washington,DC,including ACRS repts/ recommondations,other actions,agreements,assignments & requests & future agenda KERR,W. ACRS - Advisory Committee on Reactor Safeguards. 88/03/24, 2ECH,L W Commissioners, 4pp. 45118-172-45118-175

P. Operating Ilcense stage documents & correspondence

- 8804190028 "Reactor Containment Bidg Integrated Leakage Rate Test Types A,B & C Pariodic Test." W/880408 ltr BRAM,S.B. Consolidated Edison Co. of New York, Inc. 87/12/31, 146pp. 45198.267-45199.051.
- 8803240426 Generic Ltr 88-06 to all power reactor licensees. 8 applicants re-removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIAF J. Associate Director for Projects (Post 8 70411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804130266 Notification of 880413 meeting w/ut1 in Rockville,MD to discuss util proposed containment heat removal Tech Spec for plant SLOSSON,M.M. Project Directorate I-1. 88/04/06. CAPRA,R.A. Project Directorate I-1. 3pp. 45102:357-45102:359.
- 8804080088 Generic 1.tr 88-07 to power reactor licensees 8, applicants re-modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Salety for Nuclear Power Plants." Svc list encl MIRAGI.IA,F J Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164 237-45164.285.
- 8804220220 Requests tee for 880122 application for approval of proposed steem generator tube exam schedule for facility.
 DIGGS.R.M. License Fee Management Branch. 88/04/15. BRAM,S. Consolidated Ed son Co. of New York, Inc. 1p. 45200 283-45200;283.
- 8804260085 Forwards application for amend to Licenses DPR-5 & DPR-28, incorporating administrative changes to organization charts. Foo paid.
 BRAM, S.B. Consolidated Edison Co. of New York, Inc. 88/04/15. Document Control Branch (Ogcument Control Desk). 1p. 45282-052-45282-061.
- -8604260090 Application for amends to Licenses DPR-5 & DPR-28,amending Tech Spec Figures 3.1,3.2,6.2.1 & 6.2.2 to reflect administrative citarges to organization charts.
 BRAM.S. Consolidated Edison Co. of New York, Inc. 88/04/15. 2pp. 45282.053-45282.054.
- --8804280093 Proposed Toch Spacs Figures 3.1,3.2,6.2.1 & 6.2.2 reflecting administrative changes to organization charts
 'Consolidated Edison Co. of New York, Inc. 88/04/15, 7pp. 45262,055-45282,061.
- 8804260292 Requests schedular extension of time parmitted for completion of implementation of safety assessment sys/SPDS until 880331.Extension needed to complete 2,200 h availability lest 8 associated documentation BRAM,S B. Consolidated Edison Co. of New York, Inc. 88/04/19 Document Control Branch (Document Control Desk). 3pp. 45251:070-45251:072.
- 8804290071 Forwards natice of withdrawal of 610807 application to amond License DPR-26 & supersedes 650802 application re lire protection requirements. SLOSSON,M.M. Project Directorate 1-1. 88/04/21. BHAM,S.B. Consolidated Edison Co. of New York, Inc. 2pp. 45322-286-45322-288.
- -- 8804290081 Notice of withdrawal of 810807 application for amond to License DPR-26, revising Tech Space to incorporate requirements for alternate safe shuldown sys SLOSSON,M. Project Directorate I-1, 88/04/21, 1p. 45322

Q. inspection reports, IE Builelins & correspondence

- 8804130407 Notification of 880317 SALP Board Meeting 88-033 w/uhl In King of Prussla, PA to discuss regional evaluation phase of SALP.
 SWETLAND, PD. Region 1, Oic of the Director, 88/03/03, Region 1, Oic of the Director, 2pp. 45116:357-45116-368.
- 8803280066 Forwards Insp Rept 50:247/88:04 on 870201-29 No violations noted. WENZINGER,E.C. Region 1, Ofc of the Director 88/03/17, BRAM,S. Consolidated Edison Co. of New York, Inc. 2pp. 44961:209-44961:219.
- -8803280068 insp. Rept 50:247/88:04 on 880201:20.No violations noted. Major areas inspected operations,meint,surveillance,review of pariodic & special repts,LER followup, pallegation re security & IE Bulletin B7:001 followup, SWETLANO,P. Region 1, Ofc of the Director. 88/03/15. 9pp. 44961:211-44961:219.
- 8803290123 Forwards Insp Rept 50-247/87-37 on Dec 1987 Jan 1988 & notice of violation. Ack receipt of response to violations noted in Insp Repts 50-247/87-25 & 87-32 & util 880126 it responding to allegations of improper valve maint. WENZINGER,EC. Region 1, Old of the Director. 88/03/22. BRAM,S. Consolidated Edison Co. of New York, Inc. 2pp. 44921:165-44921:189.
- --8803290127 Notice of violation from insp from Oec 1987 Jan 1988. Violation noted OAD-23 Condition I trip ropt for 880125 trip not reviewed at regularly scheduled station nuclear safety committee meeting on 880126.

 * Region 1, Otco the Director: 88/03/22. 1p. 44921:167-44921:167.
- --8803290132 Insp Rept 50:247/87:37 during Dec 1987 Jan 1988.Violations noted Major areas inspected implementation of corrective actions following 88/103 steam generator dryout event & Fronsee actions on previously identified insp findings SWETLAND,P. Region 1, Orc of the Director. 88/03/22, 22pp. 44921:188-44921:189.

- 8804080139 Forwards response to NRC Bulletin 88-002, "Rapidty Propagating Fat gual Cracks in Steam Generator Tubes" Response swimmarizes actions taken by util before issuance of bulletin & Into provided in 871123,1217 & 1223 lins BASILE_JA Consolidate Edison Co. of New York, Inc. 88700/25, RUSSELL,W. Region 1, Oto of the Director, 124pp. 45064 064-45064-187.
- 8803210090 Suppl 1 to NRC Info Notice 97.044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list enct.
 ROSSI/CE Division of Operational Events Assessment 4Past 870411) 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp. 44995.126 44995.246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensoes:Lack of Mgt Controls Over Liconsed Programs" Svc 1st anci. CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44095;247-44995.353.
- 8804120227 Notification of Mgt Meeting 88-050 w/uh! on 880412 in Region I to discuss SALP. SWETLAND,P D. Region 1, Ofc of the Director, 88/04/01 Region 1, Ofc of the Director, 2pp 45080-059-45080-060.
- 8804120216 Forwards Insp. Ropt. 50:247/88.02 on B80111-15 & notice of deviation Apparent deviation from 860814 commitment consists of not revising motor-operated valve maint procedures to include ring specified switch settings JOHNSTON,W.V. Region. 1, Otc. of the Director. 88/04/05. RRAM,S. Consolidated Edison Co. of New York, Inc. 2pp. 45128.297-45128:308.
- --8804120219 Notice of deviation from inspiron 880111-15 Deviation noted, motor-operated valve maint Procedure MP-16 44 not revised to include manufacturer specified switch sultings as of 880112, contrary to 880814 commitment.

 ' Region 1, Old of the Director 88/04/05, 1p 45128,299.45128,299.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switchboard Function Oue to Faulty Tie Bolls." Swc hist encil ROSSI,C E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408.292.45407.051.
- 8804130052 Forwards request for add into relittle 86.0513 & 0814 responses to IE Bulletin 85.003, "Motor-Operated Valve Switch Settings" Response requested within 30 days.

 WENZINGER,E.C. Region 1, Otc of the Director. 88/04/07. BRAM,S. Consolidated Edison Co. of New York, Inc. 3pp. 45137:109-45137:111.
- 8804200548 Forwards adul info re facility second 10-yr Inservice insp program.per 880209 request.
 BRAM.S B. Consolidated Edison Co. of New York, Inc. 88/04/08, Document Control Branch (Document Control Desk). 13pp. 45226:172-45226:184
- 8804200022 Ack receipt of 870911 response to Bulletin 87-001, "Thinning of Pipe Walks at Nuclear Power Plants." Into provided used to determine extent of industry participation 8 implementation of erosion/corrosion inspringram.
 SLOSSON,M.M. Project Directorate 1-1. 89/04/11. 8HAM,S.B. Consolidated Edison Co. of New York, Inc. 2pp. 45179.178.45179.177.
- Co. of New York, Inc. 2pp. 45179.178.45179.177.

 8864060370 NRC Inlo Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc

ROSSI,C.E. Division of Operational Events Assessment (Post 870411): 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150

- 8804200466 Responds to NRC Bulletin 88-001 re defects in Westinghouse circuit breakers Bulletin not applicable to plant. Westinghouse Series DS circuit breakers not used in any safety-related application.

 BRAM,S.B. Consolidated Edison Co. of New York, Inc. 88/04/12. Decument Control Branch (Document Control Desk). 1p. 45226 207-45228 207.
- 8804260138 Forwards results of steam generator inservice inspire followup activity on girth wolds,por 880324 tolton. Wastinghouse WCAP w/detaliad photographs will be available in May 1988 Criticalia for conclusion of program met. 8RAMS-8B. Consolidariad Edson Co. of New York, Inc. 88/04/12. Document Control Branch (Document Control Desk). 7pp. 45239.042-45239.048

R. Periodic operating reports & related correspondence

- 8803300333 Monthly operating rept for Feb 1988.W/880219 ftr. KRIEGER,K., BRAM,S.B. Consolidated Edison Co. of New York, Inc. 88/02/29. 7pp. 44945-27-44945-28
- 8804110063 Forwards cover lire transmitting monthly facility discharge monitoring repts for Arti-Doc 1987. Each cover its accompanied by excerpts from repts which detail excursions from SPDES potents diffusers times. BRONS.J.C. New York Power Authority (formerly Power Authority of the State of New York) 88/04/05. Document Control Branch (Document Control Desk). 3pp. 45170:001-45170.020
- --8804110091 Discharge monitoring rept for SPDES Permit NY0004472 for Jul 1997. BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/07/31, 3pp. 45170 004-45170.006.
- --8804110093 Discharge monitoring ropt for SPDES Permit NY0004472 for Aug 1987. BASILE.J.A. Consolidated Edison Co. of New York, Inc. 87/08/31, 2pp. 45170:007-45170:008.
- --8804110097 Discharge monitoring rapt for SPDES Permit NY0004472 for Aug 1987. BASILE.J.A. Consolidated Edison Co. of New York, Inc. 87/09/30. 3pp 45170.009-45170.011.
- --8804.110.127 D.scharge monitoring rept for SPDES Permit NY0001472 for Oct 1987. BASILE.J.A. Consolidated Edison Co. of New York, Inc. 87/10/31. 3pp. 45170.012-45170.014.

S. Reportable occurrences, LERs & related correspondence

- 8804180374 Summary of Operating Reactors Events Meeting 88-13 on 880329.List of attendess,discussion of events & summary of reactor scrams and LANN'NG.W. Events Assessment Branch 88/03/31, ROSSI,C.E. Ovision of Operational Events Assessment (Post 870411) 18pp. 45149.205-45149.222
- 8804110063 Forwards cover litrs transmitting monthly factility discharge monitoring repts for Jul-Dec 1987 Each cover its accompanied by excerpts from repts which data I ex-BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 88/04/05. Document Control Branch (Document Control Desk). 3pp. 45170.001-45170.020
- --8804110091 Discharge monitoring rept for SPDES Permit NY0004472 for Jul 1987.
 BASILEJA Consolidated Edison Co. of New York, Inc. 87/07/31, 3pp. 45170 004-45120:006
- -8804110093 Discharge monitoring rept for SPDES Parmit NY0004472 for Aug 1987. BASYLEJA: Consolidated Edison Co. of New York, Inc. 87/08/31, 2pp. 45170-007-45170-008.
- -8804110097 Discharge mondoring rept for SPDES Permit NY0004472 for Aug 1987. BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/09/30, 3pp. 45170-009-45170-011.
- --8804110127 Discharge monitoring rept for SPDFS Permit NY0004472 for Oct 1987. BASILE, J.A. Consolidated Edison Co. of New York, Inc. 87/10/31, 3pp. 45170,012-45170 014.
- -8804110141 Discharge monitoring rept for SPDES Permit NY0004472 for Nov 1987. BASKE,J.A. Consolidated Edison Co. of New York, Inc. 87/11/30, 2pp. 45170,015-45170 016
- -8804110 (45 Discharge monitoring rept for Dec 1997.

 BASILEJJA: Consolidated Edison Co. of New York, Inc. 87/12/31, 2pp. 45170:017-45170 OLB

DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

- 8903290341 Forwards Safety Insp Repts 50-237/88-04 8 50-249/88-04 on 880229-0302.Ng violations of NRC requirements noted. SHAFER.W.D. Region 3, Otc of the Director. 88/03/18. REED.C. Commonwealth Ethson Co. 2pp. 44975/23
- ••8603290343 Insp Repts 50-237/88-04 & 50-249/88-04 on 880229-0302 No violations of NRC requirements noted Major areas inspected, observation by four NRC representatives of key functions & locations during annual emergency preparedness exer-PLOSKI,T., SNELL,W, Region 3, Ofc of the Orector, 68/03/18, 16pp. 44975 234-44975 249.
- 8804250078 Rev 1 to Sale Shutdown Procedure DSSP 010-1, "Sale Shutdown Paths for Extensive Plant Damage" & Rev 4 to Emergency Plan Implementing Procedure EPIP 200-20, "Control Room Evacuation/Sale Shutdown..." Revised tables & indices
 - enc!
 * Commonwealth Edison Co. 88/04/07, 300pp. 45251;122-45252.097

P. Operating license stage documents & correspondence

- 8803300255 Application for amends to Licenses DPR-19 & DPR-25, revising Tech Specs to clarify applicability of containment oxygen. Fee paid JOHNSON, M. Commonwealth Edison Co. 88/00/18, MURILEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 3pp. 44975-337-44975,355.
- -8803300257 Proposed Tech Specs, clarifying applicability of containment oxygen concentration, Commonwealth Edison Co. 88/03/18, 16pp, 44975-340-44975-355
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements. Svc list encl. MIRACHAF, J. Associate Director for Projects (Post 870411): 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107.44972.153.
- 8804010085 Advises that current practice re-undervoltage trip adequately meets safety intent of Tech Specs Table 3.2.2 & acceptable Temporary waiver of 2 months grant-HOLAHAN,G. Assistant Director for Region III & Region V Reactors. 88/03/25. BUTTERFIELO,D Commonwealth Edison Co. 2pp. 44921;344-44921;355.
- -8804010087 Requests temporary waiver of compliance for Tech Spec 3.2.2 re under-voltage setting for 4 kV relays. Basia for first level 4 kV under-voltage relay settings encil.
- SILADY, J.A. Commonwealth Edison Co. 88/03/23, MURLEY, T.E. Office of Nuclear Reactor Regulation, Orrector (Post 870411) 4pp. 44921.346-44921.355.
- 8804110084 Application for amends to Licenses DPR-19 & DPR-25, correcting discrepancy between Table 3.2.2 value for 4 kV emergency bus undervoltage trip (3.092 volts) & current trip value (2,930 volts). Fee paid.
 SIKADY, J.A. Commonwealth Edison Co. 88/03/28. MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 6pp. 45142:065

- Reactor Regulation, Director (Post 870411). 1p. 45010 287-45010.287.
- 8804070265 Responds to 880129 & 0224 ltrs re allegad hazardous practices uit Discusses evidence of licensee compliance to federal regulations & nonviolate requirements No further action intended.
 GREENMAN,E.G. Region 3, Ofc of the Director, 88/03/31, YOUNG,C Affiliation Assigned, 4pp. 45029.261-45029.264.
- 8804080088 Generic Ltr 88-07 to power reactor incenseps & applicants to modified forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equator traportant to Safety for Nuclear Power Plants" "Svc list encl. MIRAGELIA,F. J. Associate Director for Projects (Post 870411) 88/04/07. Consolidated on Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804180098 Confirms 880419 mgt meeting w/util at Region III ofc to discuss perfo ance of plantiper 880407 felcon GREENMAN,E.G. Region 2, Old of the Director, 88/04/11, REED,C. Commonwo Edison Co., 1p. 45145-354-45145:354.
- 8804280039 Forwards Rev 50 to CE-1-A, "OA Program for Nuclear Generating tions," Revs being made to relifect organizational changes, MORGAN,W E Commonwealth Edison Co. 88/04/18. Document Control Disk, 1p. 45261-273-45261-299.
- --8804280069 Rev 50 to "OA Program for Nuclear Generating Stations."
 **Commonwealth Edison Co. CE-1-A R50, 88/04/18, 17pp, 45261;274-45261,299.

Q. Inspection reports, IE Builetins & correspondence

- 8803290341 Forwards Satoty Insp. Repts 60:237/88:04 & 50:249/88:04 on 8802 0302 No violations of NRC requirements noted. SHAFER,W.D. Region. 3, Otc. of the Director. 88/03/18. REED,C. Commonwe Edison Co. 2pp. 44875-232-44875:249.
- -8803290343 Insp Ropis 50:237/88-04 & 50:249/88-04 on 880229-0302 No violation NRC requirements noted Major areas inspected: observation by four NRC resentatives of key functions & locations during annual emergency proparedness experiences. DLOSKI,T , PATTERSON,J., SMITH,M. Region 3, Otc of the Director. 88/03/18 11 44975:234-44975:249.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westhouse Reactors," Syc list enct.

 HOSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/03 Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995;246.
- 8803220296 NRC Into Notice 88 010, "Matts Licensees Lack of Mgt Controls Over censed Programs." Svc list encl. CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 870720)-03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995-247-44995-353.
- 8804060423 Forwards Safety Insp Rept 50-249/88-06 on 880216-0316 No violat noted. HARRISON,J.J. Region 3, Ole of the Director. 88/04/01. REED,C. Commonwo Edison Co. 2pp. 45072.082-45072:100.
- -8804060432 Insp Rept 50:249/88:08 on 880216:18,22:26,0301-04,10 & 14:16 Fins stallations deviated from original specs reanalyzed,approved & correct initiated Major areas inspected previous insp findings from safety sys mod repts. GAVULAJA, SCHAPKERJF., SMITH,JF. Region 3, Ofc of the Director. 88/04 17pp. 45072:084:45072:100.
- 8804060505 Forwards Safety Insp Repts 50:237/87-30 & 50:249/87-29 on 8701 880316 No violations noted. HARRISON,J.J. Region 3, Ofc of the Director, 88/04/01, REED,C. Commonwood, Co. 1p. 45092047-45092100
- --8804080511 Insp Repts 50-237/87-30 & 50-249/87-29 on 870903-880211.No vitions noted Major areas inspected previously identified noncompliance & unresolitams & onsite followup of events at operating facilities GAVULAJA, HUBER,M.P., DANIELSON,D.H. Region 3, Ofc of the Director, 88/01, 39pp. 45092.048-45092.100.
- 8804070159 Ack receipt of 871129 & 880315 responses to 871113 allegations re-ation protection & runess for duty issues at plant. Responses adequate & no full questions or requests at this time.

 NORELIUS.C.E. Region 3, Orc of the Director. 88/04/01, REED.C. Commonw6

 Edison Co. 1p. 45024-354-45024-354.
- 8804120368 Forwards Insp. Repts 50-237/88-05 & 50-249/88-05 on 880130-031 notice of violation.No repty to notice of violation required. FORNEY,W.L. Region 3, Ofc of the Director. 88/04/05. REED,C. Commonwellidison Co. 2pp 45142.079-45142.095.
- --8804120378 Insp Repts 50-237/88-05 & 50-249/88-05 on 880130-0317. Violat noted Major areas inspected provious insp findings operational structure from the provided from the
- 8804010256 NRC Into Notice 88-011, "Potential Loss of Molor Control Ctr &/or Sw board Function Due to Faulty Tie Bolts." Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/04 Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407-051.

- 8804060370 NRC Info Notice 88-012, "Overgreasing of Efectric Motor Boarings." Svc list encl ROSSICE Division of Operational Events Assessment (Post 870411) 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150.
- 8804200498 Confirms plans made between J Silady & DE Jones re 880502 meeting at plant site to present SALP 7 rept Appropriate corporate & plant mgt requested to be
 - present GREENMAN.E.G. Region 3. Ofc of the Director 88/04/13. REED,C. Commonwealth Edison Co. 2pp. 45174.352-45174:353
- 8804250328 Confirms plans discussed on 880414 behween H Bl.ss & G VanSickle re upcoming 880506 meeting w/tuti to discuss response to IE Bulletin 85-003. GREENMAN.E G Region 3, Otc of the Director. 88704/18 REED.C Commo

- 8804220163 Forwards correction to "Effluent & Waste Disposal Semiannual Rept, Jan-June 1997." Estimated percent of major nuclide composition for irradiated components control rods also madvertently included in rept. No such waste shipped EENIGENBURG,E. Commonwealth Edison Co. 87/12/18. DAVIS,A.B. Region 3, Ofc of the Director. 1p. 45254.136-45254:137
- --8804220185 Corrected "Elliuent & Waste Disposal Semiannual Rept, Jan-June 1987."
 **Commonwealth Edison Co. 87/12/31. 1p. 45254:137-45254:137.
- 8804010238 Forwards Part 3 of plant environ radiological & meteorological monitoring rept W/o encl EENIGENBURGE Commonwealth Edison Co. 88/03/18 DAVIS,A B Region 3, Old of the Director 2pp. 45058 061, 45058 061.
- 8804150406 Monthly opurating ropts for Mar 1988.W/880407 ffr.
 MAXWELL,D.C., EENIGENBEHG,E. Commonwealth Edison Co. 88/03/31, 19pp
 45183 184-45183 203
- 8804270052 Forwards corrected radioactive effluent rept for Jul-Dec 1987.Final data for Isted elements included EENIGENBURG.E. Commonwealth Edison Co. 88/04/12. DAVIS,A 8. Region 3, Ofc of the Director. 1p. 45217:241-45217:257.
- --8804200110 Corrected "Effluent & Waste Disposal Semiannual Rept. Jul-Dec 1987."
 'Commonwealth Edison Co. 87/12/31, 16pp. 45217:243-45217:257.

V. Operator Examinations

- 8804250088 Responds to FOIA request for into re-acords of reactor operators & senior reactor operators. Forwards requafilication exam summary source sheets Lated in encl app w/personal privacy into doleted.
 GRIMSLEY,D.H. Dwision of Rules & Records (Post 870413). 88/04/19. BOLEY,K Public Citizen's Crifical Mass Energy Project. 2pp. 45213.003-45213:095.
- ~8804250167 Package of NRC administered requalification exam results summary *NRC No Detailed Affiliation Givon, 87/07/20, 88pp 45213 007-45213.095.

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

- 8803250291 Forwards Insp Repts 50:250/87-54 & 50:251/87-54 on 871228: 880118 & notice of violation Evaluation should be performed to ensure that root causes fully Identified & corrected.

 REYES.LA. Region 2, Oto of the Director. 88/03/18. CONWAY,W.F. Florida Power & Light Co. 2pp. 44921:001-44921:028.
- --8803250292 Notice of violation from insp on 871228-880118 Violations noted Plant Change Mode 85-175 & 85-176 not correctly translated into operating procedures 8 sys description & Hallon sys not reestablished within 60 s time interval. REYES,L A. Region 2, Ofc of the Director. 88/03/18. 4pp. 44921-003-44921:006.
- 8804010005 Discusses 880302 meeting w/util on site ro util independent mgt appraisal plan & mgt-on-shift program.Plant status rept, update on plant work order backlog & quality improvement program leam rept also included in meeting agenda. GRACE.J.N. Region 2, Otc of the Director. 88/03/22. WOODY,C.O. Fforida Power & Light Co. 8pp. 45010.068-45010:073.
- 8803290363 Revised emorgency plan Implementing procedures including Emergency Procedure 20109, "Criteria For & Conduct of Local Evacuations," 20110, "Criteria For & Conduct of Owner Area Evacuation" & 20201, "Melintaining..." W/880323 II., CONWAY,W.F. Florida Power & Light Co. 88/03/23, 22pp. 44978.242-44978.263.
- 8804060010 Forwards revised response to notice of violation & proposed imposition of civil penalty noted in Insp. Repits 50-250/87-38 & 50-251/87-47 per Enforcement Action EA-87-179 Encis withheld (rof 10CFR2,790(d) & 73-21).

 CONWAY.W.F. Florida Power & Light Co. 88/03/29. Ofc of Enforcement (Post 870413). 3pp. 45048:075-45048:077.
- 8604200199 Emergency Plan Implementing Procedure EP 20105, "Emergency Response Facilities." W/880411 ltr.
 CONWAY,W.F. Florida Power & Light Co. 88/03/29, 13pp, 45177:195-45177:207.
- 8604070179 Forwards response to NRC 860225 ftr re violations noted in Insp Repts 50-250/88-03 & 50-251/88-03 Interface between engineering & const w/security being improved.Response withheld (ref 10CFR2.790 & 73.21). CONWAY,W.F. Florida Power & Light Co. 88/04/04. Document Control Branch (Docu-ment Control Dask). 2pp. 45115:031-45115:032.
- 8804200276 Confirms 880421 enforcement conference to discuss emergency preparedness issues,per 880325 leticon.
 GRACE, JN. Region 2, Oic of the Director. 88/04/08. CONWAY,W.F. Florida Power & Light Co. 2pp. 45177.294-45177.297.

- -8804200286 Notification of 880421 enforcement conference w/ut1 in Homestead,FL ro emergency preparedinasi issues. CRLENIAK, RV. Region 2, Old of the Director, 88/04/08, Region 2, Old of the Direc-tor, 2pp. 45177 298-45177 297.
- 8804150270 Forwards Rev 13 to physical security plan Rev withheld (ref 10CFR2.790(d) GONWAY,D.F. Florida Power & Light Co. 88/04/11. Document Control Branch (Document Control Dosk). 2pp. 45198 261-45198.262
- 8804250009 Forwards Insp Repts 50:250/88-01 & 50:251/88-01 on 880222-25 Violalons noted in replunder consideration for escalated enforcement act on Enforcement confirence scheduled for 880421. No notice issued currently GRACE.J.N. Region 2, Otc. of the Director. 88/04/12. WOODY, C.O. Florida Power & Light Co. 2pp. 45247 346 45248 012.
- --8804250011 Emergency Response Facilities Appraisal Insp Hepts 50:250/88-01 & 50:251/88-01 on 880222-25 Violations noted. Major areas inspected selected procedures & representative records & emergency response facilities & related equipment TESTALE 0_CUNNINGHAMAL_DECKER.T.R. Rog on 2, Oic of the Director 88/04/ 08. 25pp 45247 348-45248.012
- 8604180242 Forwards corrected page changes to proposed revito physical security plantper 880322 telcion Ray incerporates miscellaneous amend & search requirements rule change Reviewthheld (ref. 10CFR73.21).

 CONWAY, W.F. Florida Powor & Light Co. 88/04/13. Document Control Branch (Document Control Dosk). 1p. 45208.293-45208.293
- 8804200473 Partial response to FOIA request re lire protection Forwards App E documents App D & E documents available in PDR.App F document completely withhold (ref FOIA Exemption 5).
 GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 88/04/14. JONES,C.R. Affiliation Not Assigned 5pp. 45206.037-45208.043
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type inspiror each facility to assess status of comphance w/ 10CFR50 49.Program isted.
 CONLON, T.E. Region 2, Oic of the Director. 84/11/06. HERDT,A.R. Region 2, Oic of the Director. 3pp. 45206.178-45206.178.

G. Adjudicatory correspondence

8804280143 Initial docision (spent fuel pool expansion).* Amends 111 & 105 to Li-censes DPR-31 & DPR-41,respectively,issued by NRC on 841121 shall remain in full force & affect w/o mod. LAZO,R M. COLE,R.F., LUEBKE,E A Atomic Safety and Licensing Board Panel. #288 6111, 89/04/19 53pp. 45209 265-45209 317.

H. General correspondence

8803310206 Comment on proposed rule 10CFR50,App J re primary reactor containment loakage tosting for water-cooled power reactors. Util endorses addition of mass point methodology to acceptable feakage rate cercuralional methods. CONWAY,W.F. Florida Power & Light Co. 88/03/25. Docketing & Services Brench 1p. 44954:074-44984:074.

J. Insurance & Indemnity information

- 8803310268 Forwards Endorsements 1,2 & 3 to MAELU Policy MW-29 & NELIA Policy BUCKLES, J.A. Marsh & McLonnan, Inc. 88/03/21. DINITZ, I Office of Nuclear Reactor Regulation, Director (Post 870411). 25pp. 44984:308-44984:332.
- 8803300400 Discusses nuclear property insurance programs for onsite property damage. CONWAY, W.F. Florida Power & Light Co. 89/03/25. Document Control Branch (Document Control Desk), 2pp. 44987:243-44987:244.

- 8803080286 Notification of 880315 meeting w/util in Flockwilla,MD to discuss operability & Tach Specs for component cooling water & Intake cooling water sys EDISON,G E. Project Directorate II-2. 88/03/02. BERKOW,H N. Project Directorate II-2. 3pp. 44633.364-44633.355.
- 8804040098 Nonficiation of change of meeting date from 880405 to 0408 w/ut1 in Rockvillo,MD to discuss surveillance. Tech Spacs for containment vessul tendons Agenda enct. EDISON,G.E. Project Directorate II-2. 88/03/21. BERKOW,H.N. Project Directorate II-2. 2pp. 44972 213-44972 215.
- 8804110218 Notification of canceled 880408 meeting w/ut1 in Rockvite,MD to discuss surveillance Tech Spacs for containment vassel tendons. EDISON,G.E. Project Directorate II-2. 88/03/21. BERKOW,H N. Project Directorate II-2. 2pp. 45078-330-45078-331.
- 8803240426 Generio Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Toch Spec administrative control requirements Svc fist enct MIRAGLIA,F.J. Associate Orector for Projects (Post 870411) 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 88040 10005 Discusses 980302 meeting w/ulit on site re util independent mgt appraisal plan & mgt-on-shift program Plant status rept, update on plant work order backlog & quality improvement program team rept also included in meeting agenda. GRACE_JN. Region 2, Oic of the Director. 88/03/22. WOODY,C.O. Fforida Power & Light Co. 8pp. 45010,068-45010.073.
- 8804130011 Summary of 880315 meeting w/util in Rockville,MD re Tech Specs & operability of Intake cooling water & component cooling water sys. EDISON,G.E. Project Directorate II-2. 88/03/29. Project Directorate II-2. 24pp

8804070175 Forwards further progress re USI A 46 Generic Uti 67-02, "Varil carron of Seismic Adequacy of Mechanical Equipment in Operating Reactors." Results of site specific valual impact analyses in hand & meet will be scheduled. CONWAY W.F. Frorda Power & Light Co. 88/03/31. Document Control Branch (Document Control Dask). 1p. 45024-355-45024:355.

- 8804110074 Application for amends to Licenses DPR-31 & DPR-41 revising Tech Speci 3.4.4 to require applicability in Modes 1.2.3 & 4 & Blow one CCW HX to be gut of svc for 72 h Action requirements revised for consistency.

 CONWAY,W.F. Florade Power & Light Co. 88/04/04. Document Control Branch (Document Control Desk). 9pp. 45131:089-45131.100
- ~8804110076 Proposed Tech Specs,requiring applicability of Section 3.4.4 in Modes 1.2.3 & 4,810wing one CCW HX to be out of sec for 72 h & revising action requirements to be consistent witmodes specified in Table 1.1.

 Florida Power & Light Co. 88/04/04, 3pp. 45131,098,45131:100.
- 8804120257 Forwards description of 870116 request to amend Licenses DPR-31 & CPR-41 to allow reliveling shurdown margin of 5% & basis for proposed change.per CONWAY,W F, Flonda Pawer 8 Light Co. 88/04/05. Document Control Branch (Document Control Desk). 10pp. 45135.298-45135.311.
- -8804120272 Proposed Tech Specs re-reactor subcritical margin
 * Fibrida Power & Light Co. 88/04/05, 5pp. 45135,308,45135,311
- 8804120422 Forwards summary repl of integrated schedula generated for Feb 1988 Changes to schedules discussed in summary reviewed witnembers of NRC in accordance w/integrated schedule (*an. CONWAY,W F. Florida Power & Light Co. 88/04/05. Document Control Branch (Document Control Bosk). 3pp. 45090.357.45090.359.
- 8804080088 Generic Ltr 88-07 to power reactor Leansees & applicants re-modified en-forcement policy concerning 100FR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Planis," Sec. Instend. MIRACULA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164-237-45164-285.
- 8894180204 Forwards privition assessment & finding of no significant impact re util 871222 Tech Specichanyu request to revised dc power sources to make closer to STS.
- EDISON,G E Project Orectorate II-2, 88/04/07, CONWAY,W F. Fforida Power & Light Co. 2pp 45149 298 45149 302.
- --8804180227 Environ assessment & finding of no significant impact re 871222 Tach Spec change requestes supplemented by 880317, revising surveillance & test requirements for die power sources, per STS.

 BERKOWJEN Project Orectorate II-2, 88/04/07, 3pp. 45149.300-45149.302.
- 8804220281 Forwards notice of consideration of Issuance of amends to Licenses DPR-31.8 EPR-41.8 proposed NSHC determination & opportunity for hearing on 880404 request re-component cooking water HXs. EDISON.G.E. Project Directorate R2 68/04/08 CONWAY,W.F. Florida Power & Light Co. 2pp. 45200.338-45200.348.
- -8804220293 Notico of consideration of issuance of amends to Licenses DPR-31 & DPR-41 & proposed NSHC determination & opportunity for hearing Amends change Tack Specs to component cooling water HXs EDISON G E. Project Directorate II-2 88/04/08, 9pp. 45200:340-45200:348
- 8804210135 Forwards summary rept of integrated schedule generated for month of Mer 1988 Schedules discussed in rept reflect into as of issuance date of 880315. First integrated schedule regulatory rept will be issued in May 1988.

 CONWAY, W.F. Florida Power & Light Co. 88/04/13. Document Control Branch (Document Control Desk). 2pp. 45235:205.45236.206.
- 8804270172 Forwards summary of mgt-on-shift repts including initial repts of shift supervisors.par 871019 order. CONWAY.W F. Florida Power & Light Co. 88/04/13. GRACE,J N. Region 2, Otc of the Director. 49pp. 45244;302-45244;350.
- 6604220245 Forwards Enercon Svcs.inc "Independent Mgl Applaisal," per NRC 871019 order Analysis of rept recommendations undorway. Dolaris of & schedules for implementation will be forthcoming.per order. HUDBIJRG.J.J. Florida Power & Light Co. 88/04/18. GRACE,J.N. Region 2. Ofc of the Director 2pp 45247:028-45247;144
- --8804220247 "Independent Mgt Appraisal." ' Enercon Services, 88/04/18, 115pp, 45247,030-45247;144.
- 8804270258 Forwards ENERCOV Svcs Inc. "Independent Mgt Appreisal." per EA-82-085.did 871019 Recommendations currently being analyzed & details of 8 schedules for implementation will be forthcoming in accordance will order. Wild enci. HIDDBURGJ J Florida Power & Light Co. 88/04/18 GRACEJ.N. Region 2, Ofc of the Director. 2pp. 45244 234-45244 235.
- 8904280239 Forwards schedule for review of revised Tech Specs reviproject for Units 1 & 2.Proposed changes extensive & absorbed considerable resources from util & NRC & expected to involve extensive discussions in luture.

 ED/SON.6.E. Project Directorate In-2. 68/04/18 CONWAY,W.F. Florida Power & Light Co 3pp. 45266 316-45268:320
- 8804280470 Forwards Amends 127 & 121 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of Issuance Amends revise dc power sources. Tech Specs towards STS by triggrading battery & battery charger surveillence & test requirements.
 EDISON,G E. Project Directorate II-2, 88/04/18 CONWAY,W F Florida Power & Light
- Co. 2pp 45270 322 45270 340.
- --8804280484 Amends 127 & 121 to Licenses DPR-31 & DPR-41,respectively, revising do power sources. Tech Spec towards STS by upgrading station batteries & battery chargers surveillance & Lest requirements.

 BERKOW,H.N. Project Directorate II-2, 88/04/18, 12pp. 45270:324-45270:335.
- -8804280491 Safety evaluation supporting Amends 127 & 121 to Licenses DPR-31 & DPR-41,tespectively.
 DR: 01,tespectively.
 Office of Nuclear Reactor Regulation, Director (Post 870411). 88/04/18. 3pp. 45270:336-45270.338

- -8804280498 Notice of issuance & availability of Amends 127 & 121 to Licenses DFR. 8809460490 13,000 03 31 & DPR-41,respect.vely. EDISCN,G.E. Project Directorate II-2 88/04/18 2pp 45270 339-45270 340
- 8804290070 Forwards safety evaluation supporting approval of Leensee Topical RegI NTH-G-6 & accepting proposed methodology described in Incensee topical rept on PWR lattice physics methodology. LAINAS,GC Assistant Director for Region II Reactors 89/04/19 CONWAY,WF Florida Power & Light Co. 5pp. 45324-216-45324-245
- -8804290076 Safety evaluation supporting licensee use of RETRAN computer code to sys transient analyses 8 approving licensee topical rept on PWR lattice physics meth-Assistant Director for Region II Reactors 88/04/19, 7pp, 45324-221-45324:245
- Q. Inspection reports, IE Bulletins & correspondence
- 8803250178 Forwards Exam Rept 50:250/OL-88-01 administered on 880126-28 for Units 3 & 4. Heg cn 2. Old of the Director 88/03/14 WODDY,C O. Florida Power & Light Co. 2pp 44914 267-44915;163.
- --8803250181 Exam Rept 50-250/OL-88-01 on 880126-28 for Units 3-8 4 Exam results eight sentor reactor operators passed exams
 ARILDSEN, J. MUNRO JF. Reg on 2, Old of the Director. 88/03/10 150pp
 44914.289-44915.081
- 8803290323 Forwards Insp Repts 50:250/68-04 & 50:251/68-04 on 880222, 25 No vio-lating or deviations noted. Unrecoived items identified in rept will be pursued during Tulture insps.

 HERDT A.R. Ragion 2, Ofc. of the Circlet. 88/03/14 WOODY, C.O. Florida Power &
 - Light Co. 2pp 44975 258 44975 277
- -8803290325 Insp Repts 50-250/88-04 & 50-251/88-04 on 880222-25 No violations of deviations noted Major areas inspected licensea actions on provious enforcement matters, housekeeping & mattiveliation & control: KLEINSCRGE,W.P., REWISOME,R.W., BLAKE,J.J. Region 2, Ofc of the Director, 88/03/09, 18pp, 44875-260-44975-277.
- 6803280005 Discusses Insp Repts 50-250/87-44 & 50-251/87-44 on 871010-1112 & proposed violation in manipulation of reactivity controls by mon-licensed shift technician on 870913.contrary to 10CFR50.54(i)
 GRACE_J.N. Region 2, Ofc of the Director 88/03/17 WOODY,CO Florida Power & Light Co. 2pp 44912
- 8803250291 Forwards Insp. Repts 50-250/87-54 & 50-251/87-54 on 871228- 880118 & notice of violation Evaluation should be performed to ensure that root causes fully REYES.L A Region 2, Ofc of the Oriector, 88/03/18 CONWAY,W.F. Florida Power & Light Co. 2pp. 44921:001-44921.028
- --8803250292 Notice of violation from inspiring an 871228-880118 Violations noted Plant Change Mode 85-175 & 85-176 not correctly translated into operating procedures & sys descriptions & Hallon sys not reastablished within 60 s true intercipion and Hallon sys not reastablished within 60 s true intercipion 8 Hallon sys not reastablished within 60 s true intercipion 8 GEYES,L A. Region 2, Ofc of the Director 88/03/18 4pp 44921 003-44921 006
- --6803250294 Insp Repts 50-250/87-54 & 50-251/87-54 on 871228-880118. Violations noted Major areas inspected drect has at site of annual 8 monthly surveitance,mant observations & reviews operational safety,facility mods & plant events BHEWER,D.R. MCELHINNEY,T.F., SCHNEBLI,G.A. Region 2, Otc of the Director, 687 03/18. 22pp. 44921.007-44921.028
- 8804010225 Ack receipt of 880309 lir informing NRC of steps taken to correct violations noted in trisp Repts 50-250/87-08 & 50-251/87-08 implementation of corrective actions will be examined during future Insp.
 HERDT.A.R Region 2, Offic of the Director, 88/03/23 CONWAY,W.F. Florida Power & Ught Co. 1p. 45931:123-45931:123.
- 8803210090 Suppl 1 to NRC Into Notice 87:044, "Thimble Tube Thinning in Westing-house Reactors" Svic tist encl ROSSI, CE. Division of Operational Events Assessment (Post 870411). 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp. 44995.126-44995.248
- 8803220296 NRC Into Notice 88-010, "Mails Licensees Lack of Mgl Controls Over Licensed Programs." Svc list enci CUNNINGHAM.R.E. D.vision of Industrial & Medical Nuclear Safety (Post 870729) 88/ 03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353
- 8804010183 Forwards salety evaluation to 880203 request for rebet from visual (VT-2) avam of repaired CRD housing. Hotel granted
 BERKOW, H. N. Project Directorate 11-2. 88/03/28. CONWAY, W.F. Florida Power &
 Light Co. 2pp. 44920:314-44920.321
- -8804010188 Salety evaluation re-request for relief from visual exam of repaired CRO housing Relief granted.
 * Project Directorate II-2, 86/03/26, 5pp. 44920-316, 44920-321
- 8804060010 Forwards revised response to notice at violation & proposed imposition of civil penalty noted in Irisp Repts 50-250/87-38 & 50-251/87-47.per Enforcement Action EA-87-179.Encts withheld (ref 10CFR2,750(d) & 73-21) CONWAY W.F. Florida Powor & Light Cq. 89/03/29. Otc of Enforcement (Post 870413) 3pp. 45048-075-45048-077.
- 8804080238 Forwards Insp Repts 50:250788-06 & 50:251788-06 on 880307-11 No violatrons or deviations noted COLLINS,D M. Region 2, Old of the Diffector, 88/03/31, CONWAY,W.F. Florida Power 8 Light Co. 2pp. 45100 079-45100,091.
- -8804080240 Insp Repts 50-250/88-06 & 50-251/88-06 on 880307-11.No violations or deviations noted Major areas inspected plant chamistry & corrosion ROSS/WJ , ADAMOVITZ.S.S., KAHLE.J.B. Region 2, Otc of the Director 88/03/23 13p. 45100.081.45100.031.

- 8804070179 Forwards response to NRC 880225 fit re-violations noted in Insp Repts 50-259/88-03 & 50-251/88-03 Interface between engineering & corist w/security being improved Response withhelid (ref. 10CFR2 798 & 73.21).

 CONWAY,W F. Florida Power & Light Co. 88/04/04. Document Control Branch (Document Control Dosk). 2pp. 45115-031-45115-032.
- 8804120345 Forwards results of nonradiological confirmatory measurement samples analyzed during Insp Ropis 50.250/88.06 & 50.251/88.06 CONWAY,W F. Florida Power & Light Co. 88/04/05 Document Control Branch (Document Control Desk). 2pp. 45089.301-45089.302.
- 8894010256 NRC Into Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bofts " Svc list end ROSSI,C E. Division of Operational Events Assessment (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 124pp. 45406 202-45407.051.
- 8804150254 Ack receipt of 880314 fir informing NRC of steps taken to correct violations noted in Insp. Repts 50-250/87-51 & 50-251/87-51 WILSON B A. Region 2, Otic of the Director, 98/04/07, CONWAY,W.F. Florida Powor & Light Co. 1p. 45138:214-45138:214.
- 8804200276 Confirms 880421 onforcement conforence to discuss emergency prepared ness issues per 880325 tolcon GRACE, J.N. Region 2, Ofc of the Director, 88/04/08, CONWAY, W.F. Florida Power & Light Co. 2pp. 45177:294-45177:297.
- -- 8804200286 Natification of 860421 enforcement conference w/util In Homestead,FL re emergancy preparedness issues. CRLENJAK,R.V. Region 2, Old of the Director. 2pp. 45177:298-45177.297.
- 8804200552 Confirms 880422 mgt meeting to discuss status of SALP Improvements & other issues,per 880325 fefcon Proposed agenda encl.
 GRACE,J.N. Region 2. Otto of the Director. 88/04/08. CONWAY,W.F. Fforida Power & Light Co. 2pp. 45/75/020-45175.022
- -8804200556 Notification of 880422 mgt meeting w/util onsite to discuss SALP Improvements & mgl on shift program
 CRLENJAK,R V. Region 2, Ofc of the Director, 88/04/08, Region 2, Ofc of the Director, 19, 45175 022-45175 022.
- 8804200359 Responds to IE Bullotin 88.001 re dotects in Washinghouse circuit breakers Subj breakers not used in any Class IE sys at plant. CONWAY, W.F. Florida Power & Light Co. 88/04/11. GRACE, J.N. Region 2, Otc of the Orector. 2pp. 45179.336-45179.337.
- 8804060370 NRC Info Notice 88-012, "Overgroasing of Electric Motor Bearings." Svc list enci. ROSSICE Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165:150.
- 8804250009 Forwards Insp Ropts 50-250/88-01 & 60-251/88-01 on 880222-25. Viola-Tions noted in right under consideration for escalated enforcement action Enforcement conference scheduled for 880421.No notice issued currently.

 GRACE_JN. Region 2, Otc of the Director. 88/04/12. WOODY,C.O. Florida Power & Light Co. 2pp. 45247.346-45248.012.
- --8804259011 Emergency Response Facilities Appraisal Insp Repts 50-250/88-01 & 50-251/88-01 on 680222-25 Violations noted. Major areas inspected selected procedures & representative records & emergency response facilities & related equipment TESTA, E.D., CUNNINGHAM, A.L., DECKER, T.R., Region 2, Old of the Director, 88/04/08, 25pp. 45247:348-45248.012.
- 8804200473 Parlial response to FOIA request re line protection Forwards App E documents App D & E documents available in PDR App F document comptotely withhold (rel FOIA Exemption 5). GRIMSLEY,D H. Division of Rules & Records (Post 870413). 88/04/14, JONES,C R. Affiliation Not Assigned. 5pp. 45208:037-45208:043.
- ~8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFH50.App R-type Insp for each facility to assess status of compliance w/ 10CFR50.48 Program listed.
 CONLON.T.E. Region 2, Oto of the Director, 84/11/06, HERIDT,A.R. Region 2, Oto of the Director, 3pp. 45206.176-45206.178.
- 8804260202 Forwards Insp Ropts 50-250/88-02 & 50-251/88-02 on 880118-0225 & notice of violation.
 WILSON,B.A. Region 2, Oto of the Director, 88/04/15. CONWAY,W.F. Florida Power & Light Co. 2pp. 45268:238-45268:259.
- --8804260218 Insp. Repts 50-250/88-02 & 50-251/88-02 on 880118-0225. Violations noted Majors areas inspected direct insp. at site, including backshill insp,annual & monthly surveillance, maint observations & review.
 SREWER, D.R., MCELHINNEY, T.F., SCHNEBLI,G.A. Region 2, Ofc of the Ovector, 88/04/13, 18pp. 45268:242-45268:250.
- 8804260399 Ack receipt of 880404 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50:250788-03 and 50:251788-03. CLINE,W.E. Hegion 2, Oic of the Director, 88/04/15. CONWAY,W.F. Florida Power & Light Co. 1p. 45223:281-45223-281.
- 8804250094 Responds to violations noted in Insp Repts 50:250/87-54 & 50:251/87-54.Corrective actions Surveillance Procedures 3/4-OSP:075.6 & 3/4-OSP:076.7 revised to correct discrepancies in consumption rates.

 CONWAY,W.F. Florida Power & Light Co. 88/04/18. Document Control Branch (Document Control Desk). 8pp. 45239:218-45239 226.

8804010049 "Annuel Norradiological Environ Monitoring Rept for 1987." CONWAY, W.F. Florida Power & Light Co. 88/03/23, 2pp. 45008:109-45008:110.

- 8894070278 Forwards summary of mgt.on-shift weekly repts per NRC 871019 order. CONWAY,WF. Flonde Power & Light Co. 88/03/23. GRACE,J.N. Region 2, Ofc of the Director, 37pp. 45021-130-45021-166.
- 8804070075 Forwards biweekly status ropt on facility discussing recent operating events 8 performance trends
 GRACE,J.N. Region 2, Olc of the Director 88/03/28. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 4pp. 45024 263-45024.268
- 8804120447 Forwards mgt onstitit weekly rept for wk starting 880321.
 CONWAY,W.F. Florida Power & Light Co. 88/04/08 GRACE,N. Region 2, Old of the Director 30pp. 45091-031-45091-080.
- 8804200005 Forwards mgt-on-shift weekly summary repls,per 871019 NRC order.
 CONWAY,W.F. Florida Power & Light Co. 88/04/06 GRACE,J.N. Region 2, Oic of the Director, 30pp. 45171,084-45171;113.
- 8804220027 Forwards biweokly status ropt on facility Unit 3 shut down due to noise coming from "3D" moisture separator reheater on 880316 Moisture separator reheater ballite plates had cracked webds Repairs made & unit roturned to syc on 880323. GRACE J N. Rogion 2, Otto of the Director, 88/04/08 MURIEKY. E. Office of Nuclear Reactor Regulation, Director (Post 870411), 4pp. 45199.207-45199.210.
- 8804200372 Forwards solect sys assessment progress summary for Mgr 1986 CONWAY,W.F. Florida Pawer & Light Co. 88/04/11. Document Control Branch (Document Control Dock). 3pp. 45170-338-45179-340
- 8804220108 Forwards monthly operating repls for Mar 1988 & conacted Feb 1988 unit shutdowns & power reductions rept for Unit 4. Corrected rept provides into an outage that was omitted from original rept CONWAY W.F. Florid
- --8804220111 Revised rept of unit shutdowns & power reductions for Feb 1988. GRANT,N.W. Florida Power & Light Co. 88/02/29 2pp. 45216.193-45216.194
- --6804220074 Montifly operating repts for Mar 1988.
 GRANT,N,W. Flanda Powor & Light Co. 88/03/31, 18pp. 45218:195-45216 210.

S. Reportable occurrences, LERs & related correspondence

- 8804130144 LER 88-003-00 on 880308,containment vantilation & control room vantilation isolation occurred Caused by minor exertical transient upon failure of one fight intersent. Failed dual hiament buts replaced W/880407 ltr. SALAMON,G., CONWAY,W.F. Florida Power & Light Co. 88/04/07, 4pp. 45142 239-
- 8804130177 Special regt nonfunctional lire battier penetration not returned to functional status within 7 days Caused by mods being performed 8 equipment malfunction Plant continues to implement compensatory measures as applicable. CONWAY,W.F. Florida Power 8. Light Co. 88/04/07. Document Control Branch (Document Control Desk). 5pp. 45132.349-45132.353.
- 8804280303 LER 88-004-00 on 880318,auxiliary leadwater pumps actuated due to drop in steam generator level Caused by reactor control operator fellure to monitor steam generator level. Operator conseled re awareness of actions W/800415 lit. SALAMON,G., CONWAY,W F. Florida Power & Light Co. 88/04/15. 4pp. 45281 291-

V. Operator Examinations

- 8803250178 Forwards Exam Rept 50:250/OL:88:01 administered on 880126:28 for Units 3 & 4. JULIAN,C.A. Region 2, Otc at the Diractor 88/03/14. WOODY,C.O. Florida Power & Light Co. 2pp. 44914/287-44815-183
- -8803250181 Exam Rept 50-250/OL-88-01 on 880126-28 for Units 3 & 4.Exam results eight senior reactor operators passed exams
 ARILDSEN, J. MUNRO.J.F. Region 2, Ote of the Director. 88/03/10. 150pp.
 44914:259-J.4915:081
- --8804010181 Forwards comments on questions in 860126 exam for NAC review & consideration prior to grading exams WODDY,C.D. Florida Power & Light Co. 88/02/01, GRACE,J.N. Region 2, Oic of the Director, 82pp. 44915;082-44915;163.
- 8804260088 Rosponds to FOIA request for info re-scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in enclusp w/personal privacy into doloted GRIMSLEY,D II. Division of Roles & Rocords (Post 870413) 88/04/19 BOLEY,K Public Citizen's Critical Mass Energy Project 2pp. 45213 003-45213:095.
- --8804250167 Package of NRC administered requalification exam results summary.
 NRC No Detailed Affiliation Given. 87/07/20, 88pp. 45213:007-45213:095.

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

F. Security, medical, emergency & fire protection plans

- 8803250291 Forwards Insp Repts 50-250/87-54 & 50-251/87-54 on 871228-980118 & notice of violation. Evaluation should be performed to ensure that root causes livily Identified & corrected corrected REYES,L.A. Region 2, Ofc of the Director 88/03/18 CONWAY,W.F. Florida Power & Light Co. 2pp. 44921:001-44921.028.
- --8803250292 Notice of violation from insp on 871228-880118. Violations noted Plant Change Mods 85-175 & 85-176 not correctly transleted into operating procedures & sys description & Halon sys not reestablished within 60 s lime Interval. REYES,L.A. Reg on 2, Old of the Director 88/03/18 4pp 44921 003-44921 008

- 8804010005 Discusses 880302 meeting w/ult on site relutil independent mgt appraisal plan & mgt-on-shift program.Plant status rept, update on plant work order backtog & quelity improvement program team rapid sis included in medting agenda GRACE_J N. Region 2, Olic of the Director. 88/03/22 WCCDV.CO Florida Power & Light Co. 6pp. 45010 068-45010 073
- 8803290363 Rev.sed emergency plan implementing procedures including Emergency Procedure 20100, "Criteria For & Conduct of Local Evacuations," 20110, "Criteria For & Canduct of Conner Area Evacuation," 8 20201, "Maintaining "WR80323 III" CONWAY,W F. Fforida Power & Light Co. 88/03/23 22pp. 44978 242-44978:263.
- 8804060010 Forwards revised response to notice of violation & proposed imposition of civil penalty noted in Insp. Repts. 50:250/87-38. & 50:251/87-47.per. Enforcement Action EA-87-179 Encis withhold (ref. 10CFR2,780(d) & 73.21). CONWAY, WF. Florida. Power & Light. Co. 88/03/29. Ofc. of Enforcement (Post 870413). 3pp. 45048:075-45048.077.
- 8804200199 Emergency Plan Implementing Procedure EP 20105, "Emergency Response Facilities" W/880411 III.
 CONWAY,W F. Florida Power & Light Co. 88/09/29, 13pp. 45177:195-45177:207.
- 8804070179 Forwards response to NRC 880225 ftr re violations noted in Insp Repts 50-250/88-03 & 50-251/88-03 Interface between engineering & const w/security being improved Response withheld (ref. 10CFR2.790 & 73.21) CONWAY,W.F. Florida Power & Light Co. 88/04/04. Document Control Branch (Document Control Dosk), 2pp. 45115-031-45115-032
- 8804200276 Confirms 880421 enforcement conference to discuss emergency preparedness issues,per 880025 teticon.
 GRACE JN Region 2, Oic of the Director, 88/04/08. CONWAY,W.F. Flonda Power & Light Co. 2pp. 45177:294-45177 297.
- 8804150270 Forwards Ray 13 to physical security plan. Rev withheld (ref 10CFR2.790(d) 8.73.21).

 CONWAY, D.F., Florida Power & Light Co., 88/04/f1 | Document Control Branch (Document Control Desk), 2pp. 45198.261.45198.262.
- 8804250009 Forwards Insp. Repts 50-250/68-01 & 50-251/68-01 on 880222-25 Violations noted in rept under consideration for escalated enforcement action Enforcement conference scheduled for 880421.No notice issued currently. GRACE J.N. Region 2, Otc of the Ovector, 88/04/12 WOODY,C.O. Florida Power & Light Co. 2pp. 45247.346-45248.012
- -8804250011 Emergency Response Facilities Appraisal Insp Repts 50-250/88-01-8-50-251/88-01-0 880222-25 Wicklations noted. Major areas inspected-selected procedures & representative records & emergency response facilities & related equipment. TESTA,E-D. Region 2, Ofc of the Director, 88/04/08-25pp, 45247-248-45248-012.
- 8804180242 Forwards corrected page changes to proposed revito physical security planter 860322 teleon Revincorporates miscellaneous amend & search requirements rule change Ray withhold (ref. 10CFR73.21).

 CONWAY,W.F. Florida Power & Light Co. 88/04/13. Document Control Branch (Document Control Osk), 1p. 45208.293.45208.293.
- 8804200473 Parial response to FOIA request reflire protection.Forwards App E documents App D & E documents available in PDR.App F document completely withhold (ref.FOIA Exemption 5). GRIMSLEY, D.H. Division of Rules & Records (Post 870413) 98/04/14. JONES, C.R. Affiriation Not Assigned. 6pp. 45206 037 45206 043.
- --8804209579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type inspitor each facility to assess status of compliance w/ 10CFR50,48 Program Issted.
 CONLON.T.E. Region 2, Official the Director, 84/41/66, HERDT,A R. Region 2, Official the Director, 3pp. 45206;176,45206;178.

G. Adjudicatory correspondence

8804260143 Initial decision (spent fuel pool expansion),* Amends 111 8 105 to ticenses DPR-31 & DPR-41,respectively,issued by NFC on 841121 shall remain in full force & effect w/o mod. LAZO,R M., COLE,R F., LUEBKE,E A. Ajomic Salety and Licensing Board Panel. #288 6111, 88/04/18, 53pp. 45209;265-45209 317.

H. General correspondence

8803310206 Comment on proposed rule 10CFR50.Acp J re primary reactor containment leakage testing for water-cooled power reactors. Util endorses addition of mass point methodology to acceptable leakage rate calculational methods. CONWAY, W.F. Florida Power & Light Co. 88/03/25. Docketing & Services Branch 1p. 44964:074-44964:074.

J. Insurance & Indemnity Information

- 8803310256 Forwards Endorsements 1.2 & 3 to MAELU Policy MW-29 & NELIA Policy NW-93.
 BUCKLES, J.A. Marsh & McLennan, Inc. 88/03/21. DINITZ.J. Office of Nuclear Reactor Regulation, Director (Post 870411). 25pp. 44984 308-44884.332.
- 8803300400 Discusses nuclear property insurance programs for onsite property damage. CONWAY,W.F. Flonds Power & Light Co. 88/03/25. Document Control Branch (Document Control Desk). 2pp. 44987:243-44987:244.

- 8903080296 Notification of 880315 meeting w/uht in Rockville,MD to discuss operabilly 8 Tech Spacs for component cooling water & Intake cooling water sys. EDISON,G E. Project Directorate II-2. 88/03/02. BERKOW,H.N. Project Directorate I:-2. 3pp. 44633-354-44633-3556.
- 8804040098 Notification of change of meeting date from 880405 to 0408 w/url in Rockville,MD to discuss surveillance Tech Specs for containment vessol tendons Agenda encl.

 EDISON, G.E. Project Directorate II-2, 88/03/21, BERKOW,H.N. Project Directorate II-2, 2pp. 44972 213-44972:215.
- 8804110218 Notification of canceled 880408 meeting w/util in Rockville,MD to discuss surveillance Tech Space for containment vessel tendons. EDISON,G.E. Project Directorate II-2. 88/03/21. BERKOW,H.N. Project Directorate II-2. 2pp. 45078/330-45078/331.
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list enct MIHAGLIA.F.J. Associate Director for Projects (
- 8804010005 Discusses 880302 meeting w/util on site re util independent mgt appraisel plan & mgt-on-shift program.Plant status rept, update on plant work order backlog & quality Improvement program team rept also included in meeting agends. GRACE_3.N. Region 2, Oic of the Director. 88/03/22. WOODY,C.O. Florida Power & Light Co. 6pp. 45010.068-45010.073.
- 8804130011 Summary of 880315 meeting w/utill in Rockville,MD re Tech Specs & operability of Infake cooling water & component cooling water sys EDISON,G.E. Project Directorate II-2. 88/03/29. Project Directorate II-2. 24pp
- 8804070175 Forwards further progress re USI A-46,Generic Ltr 87-02, "Verification of Seismic Adequacy of Mechanical Equipment in Operating Reactors." Results of sitespecific value/impact analyses in hand & meet will be scheduled. CONWAY,W.F. Florida Power & Light Co. 88/03/31. Document Control Branch (Decument Control Desk). 1p. 45024:355-45024:355.
- 8804110074 Application for amends to Licenses DPR-31 & DPR-41, revising Tech Spec 3.4.4 to require applicability in Modes 1,2,3 & 4 & allow one CCW HX to be out of svc for 72 h Action requirements revised for consistency. CONWAY.WF. Florida Power & Light Co. 88/04/04. Document Control Branch (Document Control Desk), 9pp. 45131:089-45131:100.
- ~8804110076 Proposed Tech Specs,requiring applicability of Section 3.4.4 in Modes 1.2.3 & 4,allowing one CCW HX to be out of sec for 72 h & revising action requirements to be consistent w/modes specified in Table 1.1.

 *Florida Power & Light Co. 88/04/04, 3pp. 45131.098-45131:100.
- 8804120257 Forwards description of 870116 request to amend Licenses DPR-31 & DPR-41 to allow refueling shufdown margin of 5% & basis for proposed change,per NRC reguest.

 CONWAY.W.F. Florida Power & Light Co. 88/04/05. Document Control Branch (Document Control Desk), 10pp. 45135.298-45135.311.
- -8804120272 Proposed Tech Specs re reactor subcritical margin.

 Florida Power & Light Co. 88/04/05. 5pp. 45135:308-45135:311.
- 8804120422 Forwards summary rept of integrated schedule generated for Fob-1988.Changes to schedules discussed in summary reviewed w/members of NRC in accordance w/integrated schedule plan. CONWAY,W.F. Florida Power & Light Co. 88/04/05. Document Control Branch (Document Control Desk), 3pp. 45090:357-45090:359
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc list enct. MIRAGLIA.F. J. Associato Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804180204 Forwards environ assessment & finding of no significant impact re util 871222 Tech Spec change request to revised do power sources to make closer to STS.
 EDISON,G.E. Project Directorate II-2, 88/04/07, CONWAY,W.F. Florida Power & Light Co. 2pp. 45148-298-45149-302.
- -8804180227 Environ assessment & finding of no significant impact re 871222 Tech Spec change request, as supplemented by 880317, revising surveillence & test requirements for dispower sources, per STS. BERKOW,H.N. Project Directorate II-2, 88/04/07, 3pp. 45149:300-45149.302.
- 8804220291 Forwards notice of consideration of issuance of amends to Licenses DPR-31 & DPR-41 & proposed NSHC determination & opportunity for hearing on 880404 request to component cooling water HXs. EDISON G.E. Project Directorate It-2: 88/04/08. CONWAY,W.F., Florida Power & Light Co. 2pp. 45200;338-45200;348.
- --8804220293 Notice of consideration of issuance of amends to Licenses DPR-31 & DPR-41 & proposed NSHC determination & opportunity for hearing.Amends change Tech Specs re component cooling water HXS. EDISON,G.E. Project Directorate II-2, 88/04/08. 9pp. 45200.340-45200.348.
- 8804210135 Forwards summary rept of integrated schedule generated for month of Mar 1988.Schedules discussed in rept reflect into as of issuance date of 880315.First integrated schedule regulatory rept will be issued in May 1988. CONWAY,W.F. Florida Power & Light Co. 88/04/13, Occument Control Branch (Occument Control Desk), 2pp. 45235:205-45235:206.
- 8804270172 Forwards summary of mgt-on-shift repts including initial repts of shift supervisors.per 871019 order. CONWAY.W.F. Florids Fower & Light Co. 88/04/13: GRACE,J.N. Region 2, Oto of the Director. 49p. 45244;302;45244;350.

- 8804220245 Forwards Enercon Svcs.Inc "Independent Mgt Appraisal," per NRC 871019 order. Analysis of rept recommendations underway. Details of & schedules for implementation will be forthcoming,per order. HUDBURG.J.J. Flonda Power & Light Co. 88/04/18 GRACE.J.N. Region 2, Oic of the Orrector 2pp. 45247 028-45247-144
- -8804220247 "Independent Mgt Appraisal"
 * Enorcon Services, 88/04/18, 115pp, 45247 030-45247;144.
- 8804270258 Forwards ENERCOV Sycs Inc. "Indopendent MgI Appraisal." por EA-87-085.dtd 871019 Recommendations currently being analyzed & details of & schedules for implamentation will be forthcoming in accordance w/order W/o encl HUDIBURG.J.J. Florida Power & Light Co. 88/04/18. GRACE.J N. Region 2, Oic of the Director. 2pp. 45244:234-45244.235
- 8804280239 Forwards schedule for review of revised Toch Specs rev project for Units 1 & 2.Proposed changes extensive & absorbed considerable resources from util & NRC & expected to Involve extensive discussions in Iuliure. EDISON,G.E. Project Directorate II-2 88/04/18. CONWAY,W.F. Florida Power & Light Co. 3pp. 45268.318-45266.320.
- 8804280470 Forwards Amonds 127 & 121 to Liconses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance Amends rowse de power sources Tech Specs lowards STS by upgrading battery & battery charger surveillance & test requirements EDISON, G.E. Project Directorate II-2. 88/04/18. CONWAY,W.F. Florida Power & Light Co. 2pp. 45270-322-45270-340.
- --8804280484 Amonds 127 & 121 to Licenses DPR-31 & DPR-41, respectively, revising dc power sources Tech Spec towards STS by upgrading station batteries & battery charges surveillance & tost requirements BERKOW,H.N. Project Directorate II-2, 88/04/18, 12pp. 45270 324-45270 335.
- --8804280491 Safety evaluation supporting Amends 127 & 121 to Licensos DPR-31 & DPR-41,respectively.
 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/18, 3pp. 45270.338
- 8804290070 Forwards safely evaluation supporting approval of Leansed Topical Repl NTH-G-8 & accepting proposed methodology described in licensee topical ropt on PWR lattice physics methodology. LAINAS,G.C. Assistant Director for Region II Reactors 88/04/19. CONWAY,W.F. Florida Power & Light Co. Spp. 45324:216-45324:245
- --8804290076 Safety evaluation supporting licensed use of RETRAN computer code for sys transient analyses & approving licensed topical rept on PWR lattice physics methodology.
 * Assistant Director for Region II Reactors, 88/04/19, 7pp. 45324:221-45324:245.

Q. Inspection reports, IE Bulletins & correspondence

- 8803250178 Forwards Exam Rept 50-250/OL-98-01 administered on 080126-28 for Units 3 & 4. JULIAN,C A. Region 2, Ofc of the Director. 88/03/14, WOODY,C.O. Florida Power & Light Co. 2pp 44914.267-44915:163.
- --8803250181 Exam Rept 50-250/OL-88-01 on 880126-28 for Units 3 & 4 Exam results; eight senior reactor operators passed exams. ARILOSEN,J. Region 2, Ofc of the Director, 88/03/10, 150pp. 44914:269-44915.081.
- 8803290323 Forwards thisp Repts 50-250/88-04 & 50-251/88-04 on 880222- 26.No violations or deviations noted. Unresolved items identified in rept will be pursued during future insps.
- future insps. HERDT, A.R. Region 2, Otc of the Director, 88/03/14, WOODY,C.O. Florida Power & Light Co. 2pp. 44975 258-44975:277,
- --8803290325 Insp Repts 50-250/88-04 & 50-251/88-04 on 880222-26.No violations or deviations noted Major areas Inspected Inconsea actions on previous enforcement matters, housekeeping & mall Identification & control. KLEINSORGE,W.P., NEWSOME,R.W., BLAKE,J.J. Region 2, Ofc of the Director. 887 03/09. 18pp. 44975-260-44975-277.
- 8803250291 Forwards Insp Repts 50-250/87-54 & 50-251/87-54 on 871229- 880118 & notice of violation. Evaluation should be performed to onsure that root causes fully identified & corrected. Corrected. REYES,L. A. Hegion 2, Oic of the Director. 88/03/18. CONWAY,W.F. Florida Power & Light Co. 2pp. 44921.001-44921:028.
- --8803250292 Notice of violation from insp on 871228-880118 Violations noted.Plant Change Mods 85-175 & 65-176 not correctly translated into operating procedures & sys description & Halon sys not resistablished within 60 s time interval. REYES, L A. Region 2, Ofc of the Director. 88/03/18. 4pp. 44921:003-44921:006.
- --8803250294 Insp Repts 50:250/87-54 & 50:251/87-54 on 871228-890118. Violations noted Major areas inspected direct insp at site of ennual & monthly surveillance, maint observations & reviews, operational safety, facility mods & plant events. BREWER, DR., MCELHINNEY, T.F., SCHNEBLI,G.A. Region 2, Otc of the Director, 887 03/18, 22pp. 44921:007-44921:028.
- 8804010225 Ack receipt of 880309 fir informing NRC of steps taken to correct violations noted in Insp Repts 50.250/87-08 & 50.251/87-08 Implementation of corrective actions will be examined during future insp. HERDT_A.R. Region 2, Ofc of the Director, 88/03/23. CONWAY,W.F., Florida Power & Light Co. 1p. 45031:123-45031:123.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning In Westinghouse Reactors." Svc list enct.
 ROSSI.C.E Division of Operational Events Assessment (Post 870411). 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:248.
- 8803220296 NRC Into Notice 88:010, "Mattis Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list enct. CUNNINGHAM, RE Division of Industrial & Medical Nuclear Safety (Post 870729), 88/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.

- 8804080010 Ferwards revised response to notice of violation & proposed imposition of civil penalty noted in Insp. Ropts 50-250/87-38 & 50-251/87-47.per Enforcement Action EA-87-179.Encls withheld (ref. 10CFH2,790(d) & 70-21). CONWAY, WF Filerida Power & Light Co. 88/03/29. Ofc of Enforcement (Post 870413). 3pp. 45048-075-45048-077.
- 8804080238 Forwards Insp. Repts 50:250/88-06 & 50-251/88-06 on 880307-11.No violations or deviations noted COLLINS, D.M. Region 2, Cic of the Director 88/03/31. CCNWAY,W.F. Florida Powor & Light Co. 2pp. 45100 079-45100 091
- -8804080240 Insp Repts 50:250/88:06 & 50:251/88:06 on 880307:11 No violations of daylations noted Major areas hispected plant chamistry & corrosion. ROSS,W J., NDAMÓVITZ,S S., KAHLE,J B. Region 2, Ofciol the Director 88/03/23-11pp. 45100 081:45100.091.
- 8804070179 Forwards response to NRC 880225 ltr re violations noted in Insp Repts 50-250/68-03 & 50-251/68-03 Interface between ongineering & const w/security being improved Response withheld (ref 10CFR2.790 & 73-21). CONWAY, W.F. Florida Power & Light Co. 88/04/04. Document Control Branch (Document Control Desk). 2pp. 45115-031-45115-032.
- 8804120345 Forwards rosults of nonradiological confirmatory measurement samples analyzed during Insp Repts 50:250/88-06 & 50:251/88-06 CONWAY, W.F. Florida Power & Light Co. 88/04/05 Document Control Branch (Occument Control Dosk). 2pp. 45089:301-45089.302.
- 8804010256 NRC Into Notice 88-011, "Potental Loss of Motor Control Ctr &/cr Switchboard Function Due to Faulty Tie Belts "Svc Ist and ROSSI, CE. Division of Doperational Events Assessment (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp 45406 292-45407 051
- 8804150254 Ack recept of 880314 ltr informing NRC of stops taken to correct violations noted in Insp Repts 50-250/87-51 & 50-251/87-51. WILSON,B A Region 2, Otc of the Orector, 88704/07 CONWAY,W.F. Ffonda Power & Light Co. 1p 45138,214-45138/214.
- 8804200276 Confirms 880421 enforcement conference to discuss emergency preparednoss Issues, per 880325 forcen GRACE_JN Region 2, Ofic of the Director, 88704708, CONWAY,W.F. Fronda Power & Light Co. 2pp. 45177:294-45177
- -8804200286 Notification of 860421 enforcement conference w/util in Homestead,FL reemergency proparedness issues CRLENJAK,R.V. Region 2, Ofc of the Director 88/04/08 Region 2, Cfc of the Director 2pp 45177.296-45177 297
- 8804200552 Confirms 880422 mgt meeting to discuss status of SALP improvements & other Issues per 880325 felicon Proposed agenda encl. GRACE,J.N. Rog on 2. Ofc of the Director. 88/04/08 CONWAY,W.F. Florida Power & Light Co. 2pp. 45175.020-45175.022
- --8804200556 Notification of 880422 mgt meeting w/u11 ansite to discuss SALP Improvements & mgt on shift program CRLENJAK.RV. Region 2, Oic of the Director, 19, 45175 022-45175 022.
- 8804200359 Responds to IE Bullotin 88-001 re defects in Westinghouse circuit broakers Subj breakers not used in any Class IE sys at plant. CONWAY.W F. Florida Power & Light Co 88/04/11. GRACE, J.N. Region 2, Otc of the Director. 2pp. 46179:394-45179.397.
- 8804060370 NRC Into Notice 88 012, "Overgressing of Electric Motor Bearings." Svolist enci. ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45185 028 45165 150
- 8804250009 Forwards Insp Repts 50-250/68-01 & 50-251/68-01 on 880222-25 Violations noted in rept under consideration for oscalated enforcement action Ecforcement conference scheduled for 890421 No notice Issued currently.

 GRACE_J.N. Region 2, Otc of the Director, 88/04/12, WOODY,C O. Florida Power & Light Co. 2pp. 45247:346-45248:012.
- --8804250011 Emergency Response Facilities Appraisal Insp Repts 50:250/88-01 & 50:251/88-01 on 880222-25 Violations noted. Major areas Inspected selected procedures & representative records & omergency response facilities & related equipment. TESTA, E.D., CUNNINGHAM, A., DECKER, T.R. Region 2, Ofc of the Biroctor. 88/04/08. 25pp. 45247.348-45248.012.
- 8804200473 Partial response to FOIA request re fire protection Forwards App E documents App D & E documents available in PDR App F document completely withheld (ref FOIA Examption 5). GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 88/04/14. JONES,C R. Affiliation Not Assigned. 5pp. 45208.037-45208.043.
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type insp for each facility to assess status of compliance w/ 10CFR50.48 Program listed.
 CONLON,T.E. Region 2, Olic of the Director. 84/11/06. HERDY,A.R. Region 2, Olic of the Director. 3pp. 45206:176.45206:178.
- 8804260202 Forwards Insp. Repts. 60-250/88-02 & 50-251/88-02 on 880118-0225 & notice of violation.
 WILSON B.A. Region 2, Old of the Director, 89/04/15, CONWAY,W.F. Florida Power & Light Co. 2pp. 46288 238-45268.259.
- --8804260211 Notice of violation from insp on 880118-0225. Violation noted valve found closed & intake cooling water strainer not cleaned.
 WILSON,B.A. Region 2, Ofe of the Director. 88/04/15 2pp. 45268:240-45268 241.
- ---8804260218 Insp. Repts 60-250/88-02 & 50-251/88-02 on 880118-0225. Violations noted Majors areas inspected direct insp. at site, including backshift insp,annual & monthly survollance maint maint observations & review BREWER,D.R., MCELHINNEY,T.F., SCHNEBLI.G.A. Region 2, Old of the Director, 88/04/13, 18pp. 45268:242-45268:259.

CLINE,W.E. Region 2, Ofc of the Director 88/04/15 CONWAY,W.F. Florida Power & Light Co. 1p. 45223 281-45223:281.

8804250094 Responds to violations noted in Insp. Repts 50-250/87-54 & 50-251/87-54 Corrective actions Surveillance Procedures 3/4-0SP-0756 & 3/4-0SP-0757 revised to correct discrepancies in consumption rates CONWAY.W.F. Florida Power & Light Co. 88/04/18 Document Control Brench (Document Control Desk) 8pp. 45239 219-45239 226

R. Periodic operating reports & related correspondence

8804010049 "Annual Norrad ological Environ Monitoring Rept for 1987." CONWAY,W.F. Flands Power & Light Co. 88/03/23, 2pp. 45008 109-45008 110.

8804070278 Forwards summary of mgt-on-shift weekly repts,per NAC 871019 order CONWAY,W.F. Florida Power & Light Co. 88/03/23, GRACE,J N. Region 2, Otc of the Director, 37pp. 45021,130-45021;166

8804070075 Forwards timeekly status rept on facility, discussing recent operating events a performance trends GARCE_JN. Region 2, Ofc of the Director, 88/03/28, MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 4pp. 45024 263-45024 266.

8804120447 Forwards mgt onshift weekly rept for wk sterting 880321. CONWAY,W.F. Florida Power & Light Co. 88/04/06, GRACE,N. Region 2, Otc. of the Director, 30pp. 45091,031-45091,080.

8804200005 Forwards mgi-on-shift woukly summary repts.per 871019 NRC order. CONWAY,W.F. Florida Power & Light Co. 88/04/06, GRACE,J N. Region 2, Ofc of the Oxector, 30pp. 45171:084-45171:113

8804220027 Forwards biweekly status rept on facility. Unit 3 shuft down due to noise coming from "3D" moisture separator reheater on 880316. Moisture separator reheater bafflo plates had cracked wedds Repara made 8 unit refurned to svc on 880323. GRACE_J.N. Region 2, Ofc of the Director 88074708. WIRLEY_T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 4pp. 45198-207-45199.210.

8804200372 Forwards select sys assessment progress summary for Mar 1988. CONWAY,W.F., Florida Power & Light Co. 68/04/11. Document Control Branch (Document Control Desk). 3pp. 45178.338-45179.340

8804220108 Forwards monthly operating repts for Mar 1988 & corrected Feb 1988 unit shutdowns & power reductions rept for Unit 4. Corrected rept provides into on outage that was omitted from original rept CONNAY, W.F. Florida Power & Light Co. 88/04/15, Document Control Branch (Document Control Desk), 1p. 45216:192-45216-210.

--8804220111 Revised rept of unit shurdowns & power reductions for Feb 1988 GRANT.N.W. Florida Power & Light Co. 88/02/29, 2pp. 45216;193-45216;194.

-8804220074 Monthly operating repts for Mar 1988. GRANT,N.W. Florida Power & Light Co. 88/03/31, 16pp. 45216;195-45216.210.

S. Reportable occurrences, LERs & related correspondence

8804130177 Special replinonfunctional fire barrier penetration not returned to functional status within 7 days Caused by mods being performed & equipment maltunction Plant continues to implement compensatiory measures as applicable.

CONWAY,W.F. "Tonda Power & Light Co. 88/04/07. Document Control Branch (Occument Control Desk). 5pp. 45132:349-45132:353.

V. Operator Examinations

8803260178 Forwards Exam Rept 50-250/QL-68-01 administered on 880128-28 for Units 3 & 4.

JULIAN,C A. Region 2, Otc of the Director 88/03/14. WOODY,C.O. Florida Power & Light Co. 2pp. 44914 267-44915:163.

-8803250181 Exam Repl 50-250/OL-88-01 on 880126-28 for Units 3 & 4 Exam results eight senior reactor operators passed exams
ARILDSEN_J. MUNRO_JF. Region 2, Orc of the Director. 88/03/10. 150pp 44914-269-44915.081.

-8804010181 Forwards comments on questions in 880126 exam for NRC review & consideration prior to grading exams.
WOODY, CO. Fforida Power & Light Co. 88/02/01. GRACE, J.N. Region 2, Otc of the Director. 82pp. 44915.082-44915;163.

8804250088 Responds to FOIA request for into re-scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in encl app w/personal privacy into deleted GRIMSLEY, D.H. Division of Rules & Records (Post 870413), 88/04/19, BOLEY, K. Public Chizen's Chical Mass Energy Project, 2pp. 45213,003,45213,095.

--8804250167 Package of NRC administered requatrication exam results summary.

NRC - No Data-ted Atfillation Green, 67/07/20, 68pp. 45213 007-45213 095.

DOCKET 50-252 UNIV. OF NEW MEXICO RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Hockville,MD.Official mailing address still remains same & project managers have new locations & phone numbers.TS Michaels still lead project manager for leading & A Adams will serve as backup.

RUBENSTEIN,L S. Standardization & Non-Power Reactor Project Directorate. 88/03/18. Affiliation Not Assigned 3pp 44856;322-44856 324.

8804050165 "Rept on Facility License R-102,Univ of New Mexico AGN-201M Resciol, 860701-870530." W/880328 ltr.
WILLIAMS.F.L. New Mexico, Univ. of, Albuquerque, NM. 87/06/30. 3pp 45021:071-45021:073.

DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8804050061 Forwards Followup Insp Repts 60-254/88-06 & 50-265/88-07 on 880315-17. No violations of NRC requirements noted. SHAFER,W.D. Region 3, Otc of the Director, 88/03/31, REED,C. Commonwea & Edison Co. 2pp. 45028:278-45028:291.

--8804050064 Insp. Repts 50-254/98-06 & 50-265/88-07 on 880315-17-No violations noted Major areas Inspected:ticansee actions on previously Identified items, emergency plan activations, review of licensee initiatives to improve program PLOSKI_TLJ_, SNELL_W.G. Region 3, Otc of the Director, 88/03/31, 11pp. 45028-280-45028-231.

8804280270 Forwards revised safety evaluation re interim compensatory measures 8 request for exemption from t0CFR50.App R,Section III.G.1,re hot shutdown repars ROSS,T. Project Directorate III.2. 88/04/20, BLISS,H. Commonwealth Edison Co 3pp. 45322347-45322:354.

-8804290265 Revised safety evaluation accepting util interim compensatory measures a request for exemption from 10CFR50, App R.Section III.G requirement re hot shuldown repair for lire event in plant.

*Plant Systems Branch. 86/04/20. 5pp 45322:350-45322:354.

J. Insurance & indemnity information

8804120218 Forwards Endorsement 20 to NELIA Policy NF-294,Endorsement 15 to MAELU Policy MF-128 Endorsement 30 to NELIA Policy NF-277,Endorsement 22 to MAELU Policy MF-114 & Endorsement 194 to NELIA Policy NF-43.

OSTER,J. Commonwealth Edison Co. 88704706. DINITZ.I. Office of Nuclear Reactor Regulation, Director (Post 870411). 13pp. 45090:030-45090.042.

8804250042 Forwards Endorsements 107 & 108 to NELIA Policy NF-187 & Endorsements 90 & 91 to MAELU Policy MF-54.

OSTERJ. Commonwealth Edison Co. 88/04/15 DINIT2.1. Office of Nuclear Reactor Regulation, Director (Post 870411). Spp. 45281:277-45281:281.

P. Operating license stage documents & correspondence

8709300402 Responds to request for review & comments on whether or not technically acceptable inerted containment sys could satisfy provisions of 10CFR50.44(g) N9C awailing plant-specific submittals on compliance.ppr 870120 meeting.
DORIAN,T.F. Assistant General Counsel for Rufemaking & Fuet Cycle 87/08/31 JANECEK,R.F. BWH Owners Group. JANECEK,R.F. Commonwealth Edison Co. 2pp 45022 955-45922.395-5.45922.395.

-8804290166 Requests review & comment re scope of Paragraph 50.44(g), whether technically acceptable inerted containment sys could satisfy provision of Paragraph 50.44(g).

JANECEK,R.F. BWR Owners Group, JANECEK,R.F. Commonwealth Edison Co. 87/06/23, DORIAN,T. Office of the General Counsel, 4pp. 45322:357-45322.360.

8803150061 Forwards "Reactor Containment Bidg Integrated Leak Rate Test." Next Type A lest for unit scheduled for Summer 1989. BAX.R.L. Commonwealth Edison Co. 88/02/22. DENTON.H.R. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 44715;327-44716:058.

--8803180044 "Reactor Containment Bldg Integrated Leak Rate Test."
* Commonwealth Edison Co. 87/12/06. 91pp. 44715.328-44716 058.

8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list enct. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc., 47pp. 44972:107-44972:153.

8804050127 Forwards Amend 106 to License DPR-29 & safety evaluation. Amend incorporates changes to limiting conditions for operations, surveillance requirements & bases of 3 4/4.4 Tech Specs for standby liquid control sys

~8804050133 Amend 106 to License DPR-29 incorporating changes to limiting conditions for operations, surveillance requirements & bases of Tech Specs 3.4/4.4 for standby liquid control sys in compliance w/10CFR50.62.

MULLER, D.R. Project Directorate III-2. 88/03/28. 7pp. 44997:020-44997.026.

--8804050138 Salety evaluation supporting Amend 106 to License DPR-29, Project Directorate III-2, 88/03/28, 2pp. 44997;027-44997;029,

8804080524 Documents 880317 telcon re embedment plate assessment program re analysis method & acceptance criteria for computation of allowable loads for strip embedment plates w/ 24-inch anchor spacing.

JOHNSON,I.M. Commonweath Edison Co. 88/03/31, MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 1p. 45010:287-45010:287.

8904070285 Responds to 880128 & 0224 litrs re alleged hazardous practices at util. Discusses evidence of licensee compliance to federal regulations & nonviolation of requirements No further action intended.

GHERMAN.E.G. Region 3, Of of the Director, 88/03/31, YOUNG,C. Affiliation Not Assigned, 4pp. 45029:281-45029:284.

8804210353 Forwards listing of tests, changes & experiments for March 1988 in compli-ance with 10CFR50 59

ROBEY, R.A. Commonwea'th Edison Co. 88/04/01. SNIEZEK, J.H. Office of Nuclear Residentian, Director (Post 870411). 10pp. 45235-320-45235-329.

- 8804080088 Generic Ltr 88-07 to power reactor ficensees & applicants re-modified en-forcement policy concerning 10CFR50-49, "Environ Qualification of Electrical Equip-ment Important to Saldty for Nuclear Power Plants." Svc Ist and MIRAGLIA,F J. Associate Director for Projects (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164;237-45164-285
- 8804280039 Forwards Rev 50 to CE-1-A, "QA Program for Nuclear Generating Stations " Revs being made to reflect organizational changes.
 MORGANIME Commonwealth Edison Co. 88/04/18. Document Control Branch (Document Control Dask) 1p. 45261.273-45261.299
- --8804280069 Rev 50 to "OA Program for Nuclear Generating Stations."

 ' Commonwealth Edison Co. CE-1-A R50. 88/04/18. 17pp. 45261.274-45261.299.

Roacter Regulation, Director (Post 870411), 2pp. 45283 073-45283 074

Q. Inspection reports, IE Bulletins & correspondence

8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors" Svc list onct. HOSSIGE. Division of Operational Events. Assessment (Post 670411), 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp. 44995-126-44995-246.

8803220296 NRC Into Notice 88-010, "Metts Licensees Lack of Mgt Controls Over Liconsed Programs." Svc list encl CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03728 Consolidated Edison Co. of New York, Inc. 108pp. 44985 247-44995,353.

8804140004 Responds to NRC 880225 ftr re-violations noted in Insp Repts 50-254/87-33 & 50.265/87-33 Corrective actions instrument mechanic & toreman made aware of requirements of Station Procedure QIP 5700-2 & procedure discussed at maint mooting TURBAK,M.S. Commonwealth Edison Co. 88/03/29, DAVIS,A.B. Region 3, Otc of the Director, 10pp. 45147,308,45147,315.

8804060441 Forwards request for addit into 10 util responses to IE Bullotin 65.003, "Motor-Operated Valve Common Mode Failures During Plant Transfents Due to Improper Switch Settings." Add into requested within 1 month of itridate. GREENMAN,E.G. Reg on 3, Ofc of the Director, 88/03/30, REED,C. Commonwealth Edison Co. 5pp. 45007 059-45007 083

8804050081 Forwards Followup Insp. Repts 50-254/88-06 & 50-265/88-07 on 880315-17.No violations of NRC requirements noted SHAFER,W.D. Region 3, Otc. of the Director, 88/03/31 REED,C. Commonwealth Edison Co. 2pp. 45028-278

--8804050064 Insp. Repts 50 254/88 06 & 50 265/88 07 on 880315-17 No violations noted Mejor gress inspected Leonseu actions on proviously identified Itoms, omergency plan activations, roview of liconsee intiflativos to Improve program PLOSKI, I.J., SNELL,W.G. Region 3, Otc of the Director, 88/03/31, 11pp. 45028 280-45028 291.

8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faully Tio Bolts." Svc. 1st and ROSSI/CE. Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408:292-45407.051.

8804080370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list end ROSSI,CE. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45185:150

8804190013 Forwards Safety Insp Ropts 50-254/88-04 & 50-265/88-04 on 880207-0.102 Violation noted but notice of violation wit not be resued.
FORNEY.W.L. Region 3, Ofc of the Director, 88/04/12 REED,C. Commonwealth Edison Co. 2pp. 45197 026-45197 038.

--8804190017 Insp Repts 50-254/88-04 & 50-265/88-04 on 880207-0402. Violations noted Major areas inspected operations maint, surveillance LER review, routine repts, temporary Instructions & administrative controls affecting quality. RING,M.A. Region 3, Ofc of the Director, 88/04/12, 12pp. 45197,028-45197;039.

8804210438 Forwards request for addl into re results of expanded inspiplan for piping susceptible to IGSCC at plant thit proposed alternative not acceptable w/o further jus-

Illication

ROSS,T. Project Directorate III-2 88/04/13, BUTTERFIELD,L. Commonwealth Edison
Co. 5pp. 45192:183-45192 187.

8804250328 Confirms plans discussed on 880414 between H Bliss & G VanSickle re upcoming 880506 meeting w/util to discuss response to IE Bulletin 85-003. GREENMAN,E.G. Region 3, Otc of the Director, 88/04/18, REED,C. Commonweelth Edison Co. 2pp. 45251;120-4526;;121.

R. Periodic operating reports & related correspondence

8604220070 Monthly operating repts for Mar 1988.W/880401 ltr.
DEELSNYDER,L., ROBEY,R A Commonwealth Edison Co. 88/03/31. 22pp. 45221:260-45221:281.

S. Reportable occurrences, LERs & related correspondence

8804050283 LER 88-007-00 on 890301 intako beli of standby gas troatment sys covered w/plastic.Caused by personnel error due to lack of communication Plastic removed to prevent blockage 8 painting crew counseled.W/880318 tir. CASTRO 8, BAX.R.L. Commonwealth Edison Co. 88/03/18. 5pp. 45028.298. 45028 300

- 8804200393 LER 86-025-01.on 860827,small bore forus attached piping not meeting FSAR requirements discovered Caused by Inadequate design review.Mod issued to correct remaining Mark 1 issues for small bore piping.W/880323 ltr. KRONCH.C., BAX.R.L. Commonwealth Edison Co. 88/03/23, 7pp. 45239.069-
- 8804270158 Forwards addl into re LER 87-025 concerning control room habilability Agroos to suppl LER 87-02 & provide safety significance assessment by 300422. JDFINSON,I.M. Commonwealth Edison Co. 88/04/15. DAVIS,A.B. Region 3, Otc of the Director. 35pp. 45245:286-45245.320.

V. Operator Examinations

8804250088 Responds to FOIA request for info re scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in encl app w/personal privacy into defeted.

GRIMSLEY,D.H. Divison of Rules & Records (Post 870413), 88/04/19, 80LEY,K.

Public Citizen's Critical Mass Energy Project, 2pp, 45213.003-45213-095.

--8804250167 Package of NRC administered requestication exam results summary. NRC - No Dotalled Affiliation Given, 87/07/20, 88pp. 45213.007-45213.095

DOCKET 50-255 PALISADES NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

- 8804120064 Confirms dates of 880509-13 for insp of plant for compliance w/ 10CFR50,App R.por 880405 telcon Latest ray to 1sted additate requested by 880425. HARRISON,J.J. Region 3, Otc. of the Director. 88/04/06. HEINS,G.L. Consumers Power Co. 3pp. 45135-285-45135-287.
- 8804200171 Withdraws 840423,as revised on 840716,exemption request re charging pumps because,on tev of Off Normal Procedure ONP-25.2 to include P-54B.8. P-66B use,sub) exemption no longer required to meat 10CFR50,App R requirements. SMEDLEY,R.W. Consumers Power Co. 88/04/12. Document Control Branch (Document Control Desk). 2pp. 45174.088-45174.089.

H. General correspondence

8804280091 Informs of corporate & organizational changes due to resignation of JF Paquetto,DW Buckman replaces JF Paquette as President & Chief Operating Officer.GL Heins Vice President of Energy Supply. BERIRY,KW. Consumers Power Co. 88/04/19. Document Control Branch (Document Control Dosk). 4pp. 45261:308.45261:309.

K. Utility Final Safety Analysis Report (FSAR) & amends

8804260397 Rov 4 to updated FSAR for Patrisades Plant.W/860420 tir. HOFFMAN,D P. Consumers Power Co. 88/04/20, 77pp. 45281.056-45281;132.

- 8803080149 Forwards Amend 111 to License DPR-20 & safety evaluation. Amend revises Tock Specs for movement of heavy loads, consolidates all specs in Section (3.21) & expands scope beyond shipping cask.
 WAMBACH,T.V. Project Directorate (6.1). 08/03/01. BERRY,K.W. Consumers Power Co. 2pp. 44634:329.
- -8803080161 Amend 111 to License DPR-20, revising Tech Space for movement of heavy toads, consolidating all space in one Section (3.21) & expanding scope beyond Alloping cask.
 VIRGILIO, M.J. Project Directorate III-1, 88/03/01, 10pp. 44634;331-44634;340
- -- 8803080168 Safety evaluation supporting Amend 111 to License DPR-20, * Project Directorate III-1, 88/03/01, 5pp. 44834:341-44634.345.
- 8803240426 Generic Lit 88-06 to all power reactor ficensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc List enct. MIRAGLIA,F. J. Associate Director for Projects (Post 870411), 88/03/22, Consolidated Edson Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804080120 Forwards corrected Amend 112 to Licenso DPR-20 & safety evaluation, Amend revises Tech Spec to modify inservice finsp program for steam generators to be more consistent w/STS & provide addit has requirements. WAMBACH,T.V. Project Directorate III-1, 88/03/24, BERRY,K.W. Consumers Power Co. 18pp. 45064:281-45064:298.
- 8804060065 Forwards corrected Amend 113 to License DPR-20.Amend defetes foot-notes from Tech Spec Table 4.2.1 Involving sampling frequency of safety injection tank is Cycle 5 operation only 8 now out of dato. WAMBACH, T.V. Project Directorate ill-1, 88/03/25, BERRY,K.W. Consumers Power Co. 4pp. 45029.035.45029.042.
- --8804060104 Corrected Amend 113 to License DFR-20, deteiting footnote Tech Spec Table 4.2.1 Involving sampling frequency of safety injection tank re Cycle 5 operation only & now out of date. VIRGILLIO.M J. Project Directorate III-1, 88/03/25, 4pp. 45029 039-45029 042.
- 8804130031 Application for amend to License DPR-20,revising Tech Specs re-reactor protection sys Changes re Generic Ltr 86-13 & removal of sleam generator trans'ent differential pressure limit discussed.Proprietary repts withheld (ref 10CFR2.790). BERRY, K.W. Consumers Power Co. 88/03/25 Document Control Branch (Document Control Deak). 7pp. 45146:087-45148:182.

- -88C43 30C33 Provides whitein promote to required to reproduce reprising NRC infernal for the movement activities grouping of Garma Metrics proprietary & copyright that in the movement is Florid to 89-34, 37. Document Control Branch (Document of 17) 4, 370-35160, 35160, 35161, 37461, 375.
- -4864 (10049 F) (2004) Typh Stops releastor protection sys Affidavil encl 1007 (2004) (1004) (1004) (1004) (1004) (1004)
- 8804570099 Flows its entotemotive pages for annual page verification of FSAR Winforch SM Companies Flows College Office of Nuclear Reactor Regula-tion for page 12 871411 1345p 45721 225-45021 229
- 880494008) Progress to NAT Environ request for addition in NURES 0737, Item (Control of Structura Control of Relatified Strony Valves in Submittal of response for mora 6 3 response for 66660). VMCLER AW (Control of Strong Strong Control of Strong Control of Control Order Control Or
- 8804113013 Filowards Special 44 in adventoring crutted in 1880325 Tech Specialhange industri Special file is produzement speciwhich provides general requirements, codes & crisitive mornial margin relativations in modify reactor protection sys. N. EM Notici Consumers Power Co. 68103730. Document Control Branch (Document Control Despire of 9.45772, 220, 42072, 555).
- #864310011 Frage scill Tech Spike UIS4 reithermal margin/low pressure mod **On sumers Fower Coll 68 C3 30 35pp i 45072 321-45072 355
- 8804130190 Constitutes that requirements of Tech Spec 3.4.2 met by util interpretation that that size waist pumps restindant to nonontical Size Water Isolation Valve CV-1004 Interpretation withermain in effect until mods complete. Specific with Constitution Power Co. 88704706. Document Control Branch (Document Control Cests), Jpp. 45039-276-45099-278.

- 8804140193 Provided usted of a requested in 880225 for the operating nuclear power units surface as the alegard Great Lakes. STE CODE Of other Resolutive Director for Operations, 88704706, RIDGE,T. House of Page 5504, 434,451,34,143.
- \$8649800\$8 Generic 19 88 07 to power reactor licensees & applicants railmodified en-toxicment power concerning 190ER50.49, "Environ Qualification of Electrical Equip-ment implicant to Safety for Nuclear Power Plants," Soy 1st encil. MRASILARA Sascolara Director for Projects (Post 870411). 88704707. Consolidated Eason Co. of New York, Inc. 43pp. 45164.237.45164.285.
- 8804190047 Forwards application for amend to License DPR-20 updating low temp compressure protection Tech Specificationments. EEFFAIR W. Consumers Power Co. 88/04/12. Document Control Branch (Document Corticl Desk) 2pp 48:299-231-45299-259
- ~8804250194 Application for amend to License DPR-20,changing Tech Specs to update law temp overpressure protection requirements. https://doi.org/10.1009/10.1
- -8804190049 Proposed Tech Specs updating low temp everpressure protection regula-Consumers Power Co. 88/04/12, 21pp, 45209 239-45209 259
- 8604200171 Withdraws 840423 as revised on 840716 exemption requesting charging purps secause on revict Off Normal Procedure ONP-25/2 to include P-548 & P-668 Use Subjected no longer required to meet 100FR50.App R requirements. SMECLEY RIW Consumers Power Co. 88/04/12. Document Control Branch (Document Control Desk) 2pp. 45174 088-45174 089
- 8804220049 Provides cuantication of sixo water pump operability determination re-interpretation of Tech Spec 3.4 submitted on 880406 NJEM NJ. Consumers Power Co. 88/04/13 Document Control Branch (Document Control Desk). 19. 45236.956-45236.956
- 8604210396 Forwards request for addlinfo re-review of response to Generic Ltr 86-06 concerning reactor coolant pump trip. Response requested within 60 days of tit re-WAMBACH, T.V. Project Directorate III-1 88/04/15 BERRY, K.W. Consumers Power Co. 4pp. 45192 159-45192 162

Q. Inspection reports, tE Bulletins & correspondence

- #803100059 Advises that util 870910 response to NRC Bulletin 87-001 re thimning of pipe walts at nuclear power plants reviewed & no further plant-specific action required MAMBACH, T.Y. Project Directorate III-1 88/03/08 BERRY,K.W. Consumers Power Co. 2pp. 44661 349-44661 350
- 8404060120 Forwards corrected Amend 112 to License DPR-20 & safety evaluation. Amend revises Tech Spec to modify inservice insp program for steam generators to be more consistent wi STS & provide addl insp requirements. WAMBACH TV Project Directorate III:1 88/03/24 BERRY,K.W. Consumers Power Consumers about 25/14/2004 2009. Co 18pc 45064 281 45064 298
- 8803210090 Suppl 1 to NRC Info Nobce 87-044, "Thimble Tube Thinning in Westing-rouse Reactors" Svc list end ROSSICE Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995 126-44995 246.
- 8803220296 NRC Into Notice 88-010. Mail's Licensees Lack of Mgt Controls Over Li-censed Programs. Svc list exict CUNHERGHAM R E Division of Industrial & Medical Nuclear Safety (Post 870729): 887 03:28 Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995;353.
- 8904120064 Confirms dates of 880509-13 for insp of plant for compliance w/ 10CFR50.App R.per 880405 tecon Latest rev to listed add info requested by 880425. HARRISON.J.J. Repon 3, Ofc of the Director. 88/04/00 HEINS.G.L. Consumers Power Co. 3pp. 45135 285-45135 287
- 88940 19256 MPC trifo Notice 88-011. Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Fauty Tie Boits. Svc list enct. PO555CE Division of Operational Events Assessment (Post 870411). 88/04/07. Consol

- lstend ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 8870471 Consolidated Edison Co. of New York, Inc. 123pp. 45165 028-46165 150
- 8804280110 Requests additinfo in response to IE Bullotin 80-11 no masonry waits Uncidea's w/specific issues,Enct 2 provides basis for Question 3 & Enct 3 states basis for Question 4. Requests response within 90 days. WAMBACHT V. Project Cirectrate III-1 88/04/15 BERHY,K.W. Consumers Pow. Co. 5pp. 45262,310-45262,328.
- --8804280144 "Tech Rept on Use of Joint Reinforcomont in Block Manuary Walte "HAMIDA A , HARRISH G. Draxet Univ., Philadelphia, PA. HECICA,I J. Franklin. Institle 83/03/31, 14pp. 45262.315.45262.328

A. Periodic operating reports & related correspondence

HRUSUBUSTU IN

- 8804050311 "Palisades Plant Annual Rept to NRC for 16CFH50.59 Ruylows V JOHNSON, B.D. Consumers Power Co. 87/12/31, 26pp. 45032, 127-45032, 151.
- 8804050348 "1987 Range Summary Ropt" W/880331 ftr. JOHNSON,B D. Consumers Power Co. 87/12/31 7pp. 45045:20:1-45045:209
- 8804150398 Monthly operating ropt for Mar 1988 W/880407 ftr.
 PACKARD G C., GORALSKI, G. Consumers. Power. Co. 88703731 5pp. 46175 26
- 8804220026 Forwards corrective work order backing & open control room deficience rept for Feb & Mar 1988 Next rept will be submitted in md-June 1988 1 JOHNSON&O Consumers Power Co 88/04/15 Decument Control Branch (Document Control Desk) 2pp 45226.311-45226.312

S. Reportable occurrences, LERs & related correspondence

- 8803290278 LER 88-003-00 on 880221,23 & 24,sucondary side contents of stront gorestors E-50A & E-50B & scharged to Lake Michigan as continuous release. Striptly disposed of prior to required analyses Caused by procedure d
- 8804070034 LER 88-005-00 on 880304,stroking of svc water containment feofational valves occurred during prohibited conditions. Causard by precedure deficiences Administrative Procedure 9.21 revised & Tech Spec tests reviewed Wagnest in the containing of the contai 880404 tr. KOZUP,C.S., JCHNSON,B.D. Consumers Power Co. 88/04/Q4 Spp. 45072:28:
- 8804070041 LER 88:004-00 on 880303,required dissolved oxygen analysis no completed Caused by personnel error. Data shoots revised to closerly identify analysis required by Tech Specs & required time to be completed W/880404 to KOZUP.C.S. JOHNSON.B.D. Consumers Power Co. 88/04/04 4pp. 45072.20
- 8804130125 Partial response to FOIA request for documents re-info Assessment Tear notification & alleged valve tempering. App A documents available in PDB. Forward App B documents App B documents also available in PDB. G
- -8804130165 Forwards FBI communication to be disseminated only to NRC amployed w/need to know.W/o FBI communication Records of 860610,0026,1212,870404 aggs telcons & Region III repts of 860610,870318 & 0929 events onct. DAVIDSON & Ticle of Nuclear Material Safety & Safeguards, Director. 87/10/15 HAYES.B. Office of Investigations. CREED.J.R. Region 3, Ofc of the Director. 1 1pp 45102,038-45102,048.

V. Operator Examinations

- 8804040233 Requests ref matts fisted in encl be provided for licensing exams, schoduled during wks of 880620 & 27.60 days pirot to exam date. Facility imgl responsible for providing adequate space & accommodations for conducting written exam. WRIGHT.G.C. Region 3, Oils of the Director. 88/03/29 HEINS.G.L. Consumers Power Co. 11pp. 45076.120-45078:130
- 8804250088 Responds to FCtA request for Info re-scores of reactor operators & senior reactor operators Forwards requelification exam summary source sheets "stod in one app w/personal privacy info deletaci.
 GRIMSLEY,D.H. Division of Rufes & Rocords (Post 870413). 88704719. BOLEY,K. Public Citizen's Critical Mass Energy Project. 2pp. 45213:003-45213.085.
- -9804250167 Package of NRC administered requalification exam results summary.
 NRC No Detailed Affiliation Given 87/07/20 88pp. 45213:007-45213:005.

DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 8804010212 Rev 2 to Emergency Plan Implementing Procedure EPIP-8, "Personnal Accountability & Evacuation," WJ880326 Nr GRIDLEY,R. Tennessee Valley Authority, 88/03/25, 20pp. 44916:340-44916:359.
- 8804040124 Temporary Change to Rev 0 to Emergency Plan Implementing Procedure." W/ 880330 ltr. GRIDLEY,R. Tennessee Valley Authority. 88/03/30. 12pp. 44970.244-44970:255

- 8804060285 Forwards "Fire Protection Ropt" as first stop in approach to replace existing Leanse condition Rept includes fire protection plan, IOCFR50 App R safe shutdown analyses & fire hazards analyses for fire areas & zones GRIDIE/FY. Tennessee Valley Authority, 88/04/04. Document Control Branch (Document Control Desk). 9pp. 45067 065-45070.179.
- --8804060290 "Fire Protection Rept " MERRICK, D., WIMBROW,R T., ANDERSON,C E. Tennessee Valley Authority. 88/04/ 04. 1,186pp 45067.074.45070.179.
- 8804210023 Forwards supplemental response to NRC 871119 ltr re-violations noted in Insp. Repls 50:259/87:33.50:260/87:33 8 50:296/87:33.Corrective actions maint request issued to reseal junction boxes & panels line protection sys area.
 GRIDLEY,R Tennesses Valley Authority, 88/04/13. Document Control Branch (Document Control Desk). 7pp. 45219:126-45219 132.
- 8804180257 Forwards Rev. 14 to security personnel training & qualification plan Rev. withheld GRIDLEY,R.L. Tennessee Valley Authority, 88/04/14, Document Control Branch (Document Control Desk), 2pp. 45195.338-45195.339
- 8804200473 Partial response to FOIA request re-fire protection Forwards App E documents App D & E documents available in PDR App F document completely with held (ref FOIA Exemption 5). GRIM-SLEY,D.H. Division of Rules & Records (Post 870413). 88/04/14. JONES,C.R Affiliation Not Assigned 5pp. 45206.037-45208.043
- -- 8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type inspitor each facility to assess status of compliance w/ 10CFR50.48.Program issted. CONLON.T.E. Region 2, Otic of the Director 84/11/66 HERDT.A.R. Region 2, Otic of the Director 3pp 45206.176.45206:178
- 8804220250 Revised amergency plan implementing procedures, including Rev 0 to CECC-EPIP-1, "Emergency Duty Officer Procedure for Notification of Unusual Event, Nert, Site Area Emergency & General Emergency," WV880420 ltr.
 GRIDLEY,R L Tennessee Valley Authority, 88/04/20, 400pp. 45229 308-45230-322

J. Insurance & Indemnity Information

8804050067 Forwards status & dotalls of proporty insurance coverage for lac lities,per 10CFR50.54 for info GRIDLEY.R Tennossee Valley Authority, 88/03/30. Document Control Brench (Document Control Desk), 3pp. 44995-358-44895.358.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8804040111 Forwards util response to ACRS questions from 880212 moeting w/full ACRS committee in Washington,DC.Util will begin screening of LERs of sister plants to Sequeyah & Browns Ferry Nuclear Plants to determine if any actions required. GRIDLEY,R. Tennessee Valley Authority. 88/03/30. Document Control Branch (Document Control Dosk). 4pp. 44970.232-44970:235.

P. Operating license stage documents & correspondence

- 8803240428 Generic Ltr 88-06 to all power reactor licensees & applicants re-removal of organization charts from Tech Spac administrative control requirements Svc list encl MIHAGLIAF J. Associate Director for Projects (Post 870411) 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972-163.
- 8804010052 Forwards safety evaluation re util responses to Generic Ltr 83-28 Items 3.1.1.3.1.2.3.2.1 & 3.2.2. "Post Maint Testing of Reactor Trip Sys & All Other Safety-Related Components." Responses acceptable. ZECH.G.G. 3pp. 44920 348 44920 356
- -8804010057 Safety evaluation supporting util responses to Generic Lir 83-28, items 3.1.1,3.1.2.3.2.1 & 3.2.2, "Post-Maint Testing of Reactor Trip Sys & All Other Safety-Related Components."
 - Otc of Special Projects, 88/03/23, 5pp. 44920,352-44920,356
- 8803310129 Forwards Roy 4 to "Design Baseline & Verification Program." Rev provides detailed explanation of plan essential calculation effort specifically discussed in Rev 2
- GRIDLEY,R. Tennessee Valley Authority, 88/03/25. Document Control Branch (Document Control Desk), 2pp. 44982:325-44982:350.
- ~8803310132 Rev 4 to "Dosign Baseline & Verification Program."
 * Tennessee Valley Authority, 88/02/22, 24pp. 44982 327-44982.350
- 8804070199 Forwards TVA employee concerns task group subcategory repts.
 RUSSELL.J.R. Tonnessee Velfey Authority. 88/03/28. Document Control Branch (Document Control Dock), 5pp. 45022:145-45024:267.
- ~8804070203 Rev 3 to Employee Concerns Special Program Subcategory Engineering Rept 25000, "Civil/Structural Oosign (21500) & Pipe Whip Rostraint Design (22700)." BENKERTJW., RUSSELLJR. Tennessee Valley Authority. 88703/21. 89pp. 45022:150-45022:238.
- --8804070217 Rev 5 to Employee Concerns Special Program Rept 80100, "OA Mgt & Policy." MCCALLUM.N., BROWN.W.R., KARR, J.E. Tennossee Valley Authority, 88/03/18, 96pp. 45022:239-45022:334.
- --8804070224 Rev 6 to Employee Concerns Special Program Subcategory Rept 80200, "Insp." KENZIEL G., WORTHY, J.E., JOYCE, J.W. Tennessee Valley Authority. 88/03/18. 152pp. 45022:333-45023:128.
- -8804070234 Ray 6 to Employee Concerns Special Program Subcategory Rept 80400, "Nonconformance Control & Corrective Action." HALVERSON.R.D., JOYCE,J.W. BROWN,W.R. Tennessee Valley Authority. 88/03/14. 491 pp. 45023:127-45024:257.

- 8804010280 Informs that schedule for response to request for additinto re human fac-tors program & solation devices for SPDS wit be provided by 860922 GRIDLEY,R Tennossee Velley Authority, 86003/29, Document Control Branch (Occu-ment Control Dosk), 7pp. 45050-118-45059,124.
- 8804060067 Requests exemption from timo requirements in 10CFR70.51(d) to perform physical inventory of SNM by 880331 (u/o to util restoring equipment necessary to establish secondary containment.per.10CFR70.14 GRIDLEY,FI. Tennossee Valley Authority, 887/03/30. Document Control Branch (Document Control Ocsk). 3pp. 45073.338-45073.340
- 8804110261 Forwards safety evaluation accepting third vent path of containment atmospheric dilution sys to satisfy requirements of NUREG 0737,fram II E.4.1. ZECH,G.G. Ofc. of Special Projects. 88/03/31 WHITE,S.A. Tennessee Valley Authority. 5pp. 45079.001-45079.005
- 8804070057 Forwards listing of employee concern numbers shown on ufil data base as NRC responsibility for evaluation not included in 861231 submittal. Requests ack of re
 - sponsibility.
 RUSSELLUB Tennessoo Valley Authority, 88/04/01. Document Control Branch (Document Control Dask) 7pp 45075 036-45075 042
- 8804080178 Informs that Multi-Plant Action E-04, "BWR Single Loop Operation" closed TAC numbers for tisted plants should be closed & single toop operation reviews should be tracked as plant-specific actions in future.
 THADANIM C Project Directorate II-2, 88704701, GEARS,G Orc of Special Projects 2pp 45084:311-45084.315
- 8804080088 Generic Ltr 88-07 to power reactor I censens & applicants re-modified enforcement policy concerning 10CFR50-49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants" "Svc list end MIRAGLIA, F. J. Associate Director for Projects (Post 870411) 88/04/07, Consolidated Etison Co. of New York, Inc. 49pp. 45184-237-45184-285.
- 8804130310 Notification of 880413 meeting w/util in Decatur,AL to discuss plant restart test program.
 MORIAN D.H. Old of Special Projects 89/04/07. ZECH,G.G. Old of Special Projects. 3pp 45103:172-45103:174
- 8804200368 Notification of canceled 880413 meeting w/util in Decatur.AL re-briefing on plant restart lest program.

 MORAND H. Otc of Special Projects 88/04/07, ZECH,G.G. Old of Special Projects, 3pp. 45179.275-45179.277.
- 8804130184 Molification of 880414 meeting w/utif in Decatur,AL to discuss ampacity cable derating calculations & cab'e screening,Phase 1,2 & 3 MORAN,D H Olic of Special Projects 88/04/08. ZECH,G G. Olic of Special Projects 3pp. 45101:199-45101:201.
- 8804210026 Supplemental application for amond to Licenses DPR-33, DPR-52 & DPR-68, implementing recommendations in Generic Ltr 84-16, "Proposed Staft Actions to Improve & Maintain Diesel Generator Reliability." Fee paid. GRIDLE-YR. Tennossee Valley Authority, 88704/13, Document Control Branch (Document Control Desk), 5pp. 45219 133-45219:149.
- --8804210027 Proposed revised Tech Spacs implementing recommendations of Generic Ltr 84-15, "Proposed Staff Actions to Improve & Maintain Diesel Generator Reliability."
 * Tonnessoe Valley Authority, 88/04/13, 12pp, 45219:138-45219.149.

- 8804260032 Application for amonds to Liconses DPR-33,DPR-52 & DPR-68, revising Toch Space 3.474 4 re standby liquid control sys. Fee paid.
 GRIDLEY,R. Tonnesseo Valioy Authority, 88704720. Document Control Branch (Document Control Desk). Spp. 45254:222-45254-239.
- --8804260039 Proposed Tech Spec 3 4/4.4 re standby liquid control sys
 * Tennessee Valley Authority, 88/04/20, 13pp. 45254:227-45254:239
- 8804280618 Notification of 880426 meeting w/util onsite to discuss ampacity cable de-rating celculations & cable screening, Phases 1,2 & 3. MORAN,D.H. Oic of Special Projects. 88/04/21. AULUCK.R. Oic of Special Projects. 3pp. 45264.077-45264.079.
- 8804280479 Notification of 880427 meeting w/util in Decatur,At to discuss restart test program. MORAN, D.H., Old of Special Projects 88/04/22 AULUCK, R. Old of Special Projects. 3pp. 45264:101-45264:103

Q. Inspection reports, IE Bulletins & correspondence

- 8803290366 Forwards Insp Repts 50:269/87-38,50:260/87-38,50:296/87-38 50:327/87-68,50:326/87-68,50:390/87-18,50:391/87-18, 50:438/97-08 & 50:439/87-08 on 871005-18 & notice of violation.
 BARIR,K.P. Region 2, Ofc of the Director. 89/03/09. WHITE,S.A. Tennesseg Valley Authority. 3pp. 44975:195-44975-208.
- -8003290390 Notice of violation from Insp on 671005-18. Violations noted: Inadequate div of nuclear engineering training & records, Inelfective followup on audit findings & Improper correction of OA records.

 BARR,K.P. Region 2, Otc of the Director. 88/03/09. 3pp. 44975.198-44975-200.
- --8803290393 Insp. Repis 50-259/67-38,50-260/67-38,50-296/67-38, 50-327/87-68,60-328/67-68,50-390/67-18,50-391/87-18, 50-438/67-08 & 50-439/87-08. Violations noted. Major areas inspected. allegations & licensee action on identified items. WALTON,G.A., POWELL,T.B., ELROD,S.A. Region 2, Oic of the Director. 88/03/08 8pp. 44975:201-44975-208.
- 8804010028 Ack receipt of 880311 fir informing NRC of steps taken to correct violations noted in Inap Repts 50-256/87-20, 50-260/87-20 & 50-296/87-20.

 BARR,K.P. Ofc of Special Projects. 88/03/22. WHITE,S.A. Tennessee Valley Authority. 1p. 45058:094-45058.094.

- 8804010030 Ack receipt of 880301 suppremental response informing NRC of steps taken to correct deviations noted in linsp Repts 50-259/87-30,50-260/87-30 & 50-296/87-30
- BARR.K.P., Ofc of Special Projects 88/03/22, WHITE,S.A. Tønnessee Valley Authority, 1p. 45031.179-45031-179.
- 8803310287 Forwards Insp. Repts 50-259/88-04,50-260/88-04 & 50-298/88-04 on 880201-29 & notice of violation.
 BARRIK P. Region 2, Ofc of the Director, 88/03/24, WhitTELS A. Tennessee Valley Authorly: 2pp 45011:083-45011:109
- -8803310291 Notice of violation from inspirent 880201-29 Violation noted: design basis for Class 1 buried piping not correctly translated into specs & drawings & Std Practice 8.3 not adhered to for Work Plan WP0017-86. BARRIK P. Region 2, Oic of the Director. 88/03/24 3pp. 45011-085-45011-087.
- -8803310292 Insp. Repts. 50-259/88-04,50-260/88-04 & 50-298/88-04. Violations noted Major areas inspected operational salety, maint observation, surveillance testing observation, ROs previous enforcement action & restant test program PAULK,G.L., BROOKS,C.R., CHRISTNOT,E.F. Region 2, Ofc of the Director, 88/03/ 22. 23pp. 45011 088 45011:109.
- 8804010031 Forwards Insp. Repts. 50-259/88-02,50-260/88-02 & 50-296/88-02 on 880101-31 & notice of violation. Concern expressed to implementation of engineering changes & mod programs.

 BARRIK P. Region 2, Ofc of the Director. 68/03/24 WHITE,S A Tennessee Valley Authority. 3pp. 45028.081-45028.128
- --8804010032 Notice of violation from inspiron 890101-31. Violation noted, activities at fecting quality not being accomplished per documented procedures & drawings in that inspirol non DC accepted pipe support revealed devalences from requirements, BARR, K.P. Region 2, Ofciol the Director, 88/03/24, 3pp. 45028.084-45028.08B.
- ~8804010033 Insp. Repts. 50-259/88-02,50-260/88-02 & 50-256/88-02 on 880101-31 Violations noted Major areas inspected open insp. sem. followup, operational salety, maint observation, rostant test program, maint improvement & mgt. meetings. PAULK, G.L., IGNATONIS, A.J. Hegion. 2, O.c. of the Director. 88/03/24, 40pp. 45028-087-45028-126.
- 8803219090 Suppl 1 to NRC Into Notice 87-044, "Trimble Tube Thinning in Westinghouse Reactors." Suc list enct. ROSSIGE. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Erison Co. of New York, Inc. 121pp. 44995.128-44995.248.
- 8803220296 NRC Into Notice 88 010, "Matts Licensees Lack of Mgt Controls Over Licansed Programs "Svc Ist end! CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Salety (Post 870729), 887 03728. Conschidated Edison Co. of New York, Inc. 10Rpp. 44995 247-44995:353.
- 8904060224 Ack receipt of 660316 supplemental response to request for additinto re-previous corrective actions to Violation 3 noted in thisp Rept 50:259/84-12.50-260/84-12.8 50:298/84-12. Extension of corrective action completion date acceptable. BARR K.P. Official Special Projects. 88/03/29. WHITE, S.A. Tennessee Valley Author-ity. 2pp. 45007:314-45007:315.
- 8804060528 Ack receipt of 880314 ftr informing NRC of actions taken to correct violations noted in Insp. Repts 50:259/87-41, 50:260/87-41 & 50:296/87-41.

 BARR,K.P. Ofc of Special Projects 88/03/30, WHITE,S.A. Tennessee Valley Authority, 2pp. 45010:277-45010:278.
- 8804080207 Forwards request for additinto relutil 680513,0930 & 870501 responses to IE Buttetin 85-903, "Motor-Operated Valve Common Mode Faitures During Plant Transients Due to Improper Switch Settings," for response within 30 days. BARRIK P. Oto of Special Projects. 88704/01. WHITE,S A. Tennessee Valley Authority. 4pp. 45099,180-45099,183.
- 8804110131 Supplemental response to violations noted in Insp Repts 50-259/87-14,50-260/87-14-8-50-298/87-14 Corrective actions: work in progress must be completed to demonstrate control bidg pressurization.Completion scheduled for 881115. GRIOLEY,R. Tennessee Valley Authority, 89/04/05. Document Control Branch (Docu-ment Control Desk). 4pp: 45148-016-45146:019
- 8804010256 NRC Into Notice 88.011, "Potential Loss of Motor Control Cir &/or Switch-board Function Oue to Faulty Tie Bolls." Svo Ist enct. ROSSICE, Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406.292-45407.051
- 8804130246 Responds to NRC 880226 ftr re violations noted in Insp Repts 50:259/67-46.50:280/87-46.8 50:298/87-46.Corrective actions: standay gas treatment sys Train B declared inoperable 8 Technical Instruction 17B revised.
 GRIDLEY.R. Tannessee Valley Authority. 88/04/06. Document Control Branch (Document Control Desk). 6pp. 45146.322-45146:327.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc
 - ist encl ROSSIC.E. Division of Operational Events Assessment (Post 870411) 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165.150.
- 8604200555 Forwards Insp Repts 50:259/88-08,50:260/88-08 & 50:298/88-08 on 880322-24 No violations or deviations noted BARR.K.P. Region 2, Olc of the Director. 86/04/13. WHITE,S A Tennessee Valley Authority 2pp. 45235 037-45235 043.
- -8804200558 Insp. Repts. 50:259/88-08:50:260/88-08. 8. 50:296/88-08. on. 880322-24 No. violations noted Major areas inspected, competence of operators in Group 4 accelerated requalification training course to perform ticense duties.

 BROCKMAN,K.E. JOHNSON, 4., HOPPER,G.T. Region. 2, Ofc. of the Director. 88/04/11. 5pp. 45235.038-45235.043.
- 8804210017 Summanzes review of NRC Bulletin 88-001, "Defects in Westinghouse Cir-cuit Breakers" Bulletin not applicable to Browns Ferry nuclear plant Bulletin applica-ble to Watts Bar & Bellefonte nuclear plants. List of commitments enci. GRIDLEY,R. Tannesses Valley Authony, 88/04/13, Document Control Branch (Docu-ment Control Desk). 3pp. 45219:150-45218:152.
- 8804210023 Forwards supplemental response to NRC 871119 ftr re violations noted in Insp Repts 50-259/87-33.50-260/87-33 & 50-298/87-33 Corrective actions maint request issued to reseal junction boxes & panels fire protection sys area. GRIDLEY,R Tennessee Valley Authority, 88/04/13. Document Control Branch (Document Control Desk) 7pp. 45219-126-45219:132.

- 8804200473 Partial response to FOIA request re fire protection.Forwards App E documents.App D & E documents available in PDH App F document completely withhold (ref FOIA Examption 5).
 GRIMSLEY.D.H. Division of Rules & Records (Post 870413). 88/04/14 CONES,C R Alfihalton Not Assigned 5pp. 45206.037-45206.043
- ~8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type inspilor each facility to assess status of compliance w/ 10CFR50.48.Program listed CONLON.T.E. Region 2, Ote of the Director 84/11/06 HERDT,A R Region 2, Ote of the Director, 3pp. 45206:176-45208:178
- 8804220032 Forwards response to NRC Bulletin 87-002, "Fastener Tasting to Catermine Conformance W/Applicable Tech Specs." Encl 4 identifies fasteners transferred from storage & Encl 5 contains hat of commitments being made by TVA in response GRIOLEY,R. Tennessee Valley Authority. 88/04/15. Occurrent Control Branch (Occurrent Control Branch (Occurrent Control Desk). 165pp. 45219:172-45220.026
- 8804280624 Notification of 880427 meeting wiffcensee in Rockville,MO to discuss independent design insp for facilities BEARS.Q.E. Old of Special Projects. 88/04/22. AULUCK,R. Old of Special Projects 3pp. 45271.054-45271.056.
- 8804290635 Responds to NRC 880309 ltr re violations noted in listed insperents,including 50:436/87-08.50-439/87-08 & 50-327/87-68 Corrective actions data base constructed for training.
 GRI/DLEY/R. Tennessee Valley Authority 88/04/22. Document Control Branch (Document Control Desk), 10pp. 45331:341-45331:350.

- 8804060383 "Personnal Whole Body Exposure Repts for 1987." W/880401 ftr. GRIDLEY,R. Tennessee Valley Authority, 87/12/31 7pp 45047 060-45047:066.
- 804070254 "Browns Fetry Nucluar Power Plant Annual Operating Rept to NRC,870101-1231." W/880405 ltr. WALKER,J., GRIDLEY,R. Tennessee Valley Authority, 87/12/31 108pp 45074.279-46725.ne.
- 8804050210 Forwards weekly schedule of TVA activities for wks of 880328 & 0404 KELLYJL. Ofc of Special Projects 88/03/24, ZECH,G.G. Ofc of Special Projects 4pp. 45029.088-45029.091
- 8804140525 Submits weekly schedule of TVA activities for wk of 880404-11.Schedule will be updated & Issued each Friday to reflect activities for forthcoming 2-wk period KELLY,J.L. Ofc of Special Projects 88/03/31. ZECH,G.G. Ofc of Special Projects 4pp. 45130-205-45130:208.
- 8804190140 Monthly operating repts for Mar 1988.W/880414 ftr CRAWFORD,J.D., WALKER,J.G. Tennessee Valley Authority 88/03/31. 84pp 45208.070-45208.153.
- 8804130358 Forwards weekly schedule of TVA activities for wks of 880411 8 18. KELLY.J.L. Oic of Special Projects. 88/04/08. ZECH.G.G. Oic of Special Projects 4pp. 45103:216-45103:219.

S. Reportable occurrences, LERs & related correspondence

- 8804070001 LER 88-012-00 on 880303, discovered that battery failure concurrent w/loss of offsite power/LOCA prevents automatic start of RHR removal pump Caused by design error Design control process revised & criteria issued W/undated Itr.
 JONES,S.B., WALKER,J.G. Tennessee Valley Authority. 88/04/01, 4pp. 45072-288-4532-291.
- 8804070219 Informs that LER will not be prepared under BFRO-50-259/98-04.Info to: LER will be included in Special Rept 98-001. WALKERJ G. Tennessee Valley Authority, 88/04/01. Document Control Branch (Document Control Desk). 1p. 45074;149-45074;149.

U. Congressional/Executive Correspondence

8804280317 Forwards NRR responses to Questions 1 & 3 re Commission stds for permitting restant of power plant after shutdown for safety reasons & Commission requirements for documenting ticensing basis for restant decision,respectively. THOMAS,C.O. Policy Development & Technical Support Branch (Post 870411) 88/04/19. REHM.T.A. Ofc of the Executive Director for Operations. 7pp. 45269:209-45269.215.

V. Operator Examinations

- 8804200555 Forwards Insp. Repts 50-259/88-08.50-260/88-08 & 50-296/68-08 on 880322-24.No violations or deviations noted.
 BARR.K.P. Region 2, Ofc. of the Director. B8/04/13 WHITE.S.A Tennessee Valley Authority. 2pp. 45235-037-45235-043.
- -8804200558 Insp Repts 50-259/88-08,50-260/88-08 & 50-296/88-08 on 880322-24 No violations noted Major area inspected: competence of operators in Group 4 accelerated requalification training course to perform ficense duties BROCKMANK.E., IGNATONIS,A.J. Region 2, Otc of the Director. 88/04/11. 5pp 45235:039-45235:043,

- 8804210471 Confirms 880413 telcon w/NRC re-utilization of Group 4 operators for 1-censed duties Forwards list of Group 4 hoonseas to whom NRC will administer requalification exams prior to Unit 2 restart BARRIK P. Region 2, Ofc. of the Director. 88/04/13 WHITE,S.A. Tonnessee Valley Authority 3pp 45227 214-45227 218
- 8804250988 Responds to FOIA request for into rescribe of reactor operators & sonior reactor operators Forwards requalification exam summary source sheets fisted in encl app w/personal privacy into deleted CRIMSLEY, D.H. Division of Hules & Records (Post 870413) 88/04/19 BOLEY, K. Publ.c Citizen's Critical Mass Energy Project 2pp 45213:003-45213-095
- -8804250167 Package of NRC administered requalification exam results summery
 NRC No Detailed Affiliation Given 87/07/20, 88pp. 45213,007-45213 095

DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8804010212 Rev 2 to Emergency Plan Implementing Procedure EPIP-8, "Personnel Accountability & Evacuation." W/880326 ltr countability & Evacuation * W/880326 ltr GRIDLEY.R Tennessee Valley Authority, 08/03/25, 20pp. 44916:340-44916:359
- 8804040124 Temporary Chango to Rev 0 to Emergancy Pian Implementing Procedure EPIP-14, "Radiological Control Procedure." W/ 880330 ftr GRIDLEY,R. Tennessee Valley Authority 88/03/30 12pp 44970 244-44970 255
- 8804060285 Forwards "Fire Protection Rept" as first step in approach to replace exist-ing license condition Rept includes fire protection plan, IOCFR50 App R safe shuldown analyses & fire hazards analyses for fire areas & zones GRIDLEY,R Tennesseu Valley Authority, 88/04/04 Document Control Branch (Docu-ment Control Dosk), 9pp. 45067-065-45070-179.
- --8804060290 "Fire Protection Rept."

 MEHRICK,D., WIMBROW,R.T., ANDERSON,C E. Tennessee Valley Authority. 88/04/
 04. 1,186pp. 45087.074-45070.179.
- 8804210023 Forwards supplemental response to NRC 871119 lit re violations noted in Insp. Repts 50-259/87-33,50-260/87-33 & 50-256/87-33. Corrective actions maint request issued to reseal junction boxes & panels life protection sys area. GRIDLEY,R Tennesse Valley Authority 88/04/13. Document Control Branch (Document Control Desk). 7pp. 45219-126-45219.132
- 8804180257 Forwards Rev 14 to security personnel training & qualification plan Rev Wilnieso.
 GRIDLEY.R.L. Tennesseo Valley Authority. 88/04/14. Document Control Branch (Document Control Desk). 2pp. 45195:338-45105-339.
- 8804200473 Partial response to FOIA request re fire protection. Forwards App E documents App D & E documents available in PDR App E document completely withhold (self-FOIA Exemption 5).

 GRIMSTEY, DH. Division of Rules & Records (Post 870413) 88/04/14. JCNES, C.R. Affiliation Not Assigned Spp. 45206.037-45206.043.
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type insplict each facility to assess status of compliance w/ 10CFR50.48.Program listed. CONLON,T.E. Region 2, Ote of the Director. 84/11/06 HERDT,A R. Region 2, Ote of the Director. 3pp. 45206:176-45206:178.
- 8804220250 Revised omergency plan implementing procedures.Including Rev 0 to CECC-EPIP-1, "Emergency Duty Officer Procedure for Notification of Unusual Event, Mart, Site Aroa Emergency & Goneral Emergency:" W/880420 Nr. GRIDLEY, R.L. Tennesseo Velloy Authonity. 08/104/20, 400pp. 45228 308-45230 322.

J. Insurance & Indemnity Information

- 8804050067 Forwards status & details of property insurance coverage for facilities,per
 - 10CFR50.54 for info. GRIDLEY,R. Tennessee Valley Authority. 88/03/30. Document Control Branch (Document Control Dask). 3pp. 44995 356-44995 35B.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8804040111 Forwards util response to ACRS questions from 880212 meeting w/full ACRS committee in Washington,DC Util will begin screening of LERs of sister plants to Sequoyah & Browns Forry Nuclear Plants to determine if any actions required. GRIDLEY,R. Tennosseo Valley Authority, 88/03/30 Document Control Branch (Document Control Dask), 4pp. 44970:232-44970.235.

- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spoc administrative control requirements Svc 1st and, MIRAGLIA,F.J. Associate Director for Projects (Post 870411) 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804010052 Forwards safety evaluation to util responses to Generic Lir 83:28, items 3.1.1,3.1.2.3.2.1 & 3.2.2, "Post-Maint Testing of Reactor Trip Sys & All Other Safety-Related Components" Responses acceptable, ZECH, G.G. Ote of Special Projects. 88/03/23. WHITE, S.A. Tønnessee Valley Authority. 3pp. 44920:348-44920:358
- --8804010057 Safety evaluation supporting util responses to Generic Ltr 83-28, Items 3.1.1,3.1.2,3.2.1 & 3.2.2, "Post-Maint Testing of Heactor Trip Sys & All Other Safety-Rejated Components."
 - Old of Special Projects, 88/03/23, 6pp. 44920:352-44920.356
- 8803310129 Forwards Rev 4 to "Dosign Raseline & Verification Program." Rev provides detailed explanation of plan essential calculation effort specifically discussed in Rev 2 Section 4.1.4.
 GRIDLEY,R. Tennossee Valloy Authority, 86/03/25. Document Control Branch (Document Control Dask), 2pp. 44982.325-44982.350.

- -8803310132 Rov 4 to "Design Baselina & Verification Program."
 Tennossoo Voltey Authority, 88/02/22, 24pp. 44982:327-44982:350.
- 8804070199 Forwards TVA employee concerns task group subcategory repts RUSSELLUR, Tennossee Valley Authority 88703728. Document Control Branch (Document Control Dosk). 5pp. 45022 145-45024 257.
- --8804070224 Rev 6 to Employee Concerns Special Program Subcategory Rept 80200, "insp."
 KENZIE,L.G., WORTHY,J.E., JOYCE,J.W Tonnossee Valley Authority, 88/03/18
 152pp. 45022 335-45023:126.
- --8804070234 Rev 6 to Employee Concerns Special Program Subcategory Rept 80400, "Nonconformance Control & Corroctive Action." HALVERSON,R.D., JOYCE, J.W., BROWN,W.B. Tennossee Valley Authority, 88/03/14, 491pp, 45023,127-45024:267.
- 8804010280 Informs that schedule for response to request for adult into re human fac-tors program & isolation devices for SPDS will be provided by 880922 GRIDLEY,R Tennessee Velloy Authority 88/03/29. Document Control Branch (Occu-ment Control Desk). 7pp. 45058 118-45058 124
- 8804010285 Forwards revs to description of utili program for ensuring that any seismic Class II item does not degrade integrity of any seismic Class Filtern Written statement documenting acceptability of program requested.
 GRIDLEY,R. Tennessee Valloy Authority, 88703729. Document Control Branch (Document Control Desk), 8pp. 44946-005-44946-012.
- 8804080067 Requests exemption from time requirements in 10CFR70.51(d) to perform physical inventory of SNM by 800331 due to util restoring equipment necessary to establish secondary containment per 10CFR70.14.
 GRIDLEY,R. Tonnessee Valloy Authority, 88703/30. Document Control Branch (Document Control Desk). 3pp. 45073-338-45073.340.
- 8804110261 Forwards safety evaluation accepting third vent path of containment atmospheric dilution sys to satisfy requirements of NUHEG-0737 Item ILE 4.1. ZECH.G.G. Old of Special Projects 88/03/31. WHITE,S.A. Tennessee Velley Authority 5pp 45079:001-45079:005
- 8804070057 Forwards listing of employee concern numbers shown on util data base as NHC responsibility for evaluation not included in 861231 submittel Requests ack of re-Sponsibility.
 RUSSELL,J.R. Termessee Valley Authority, 86/04/01 Document Control Branch (Document Control Desk), 7pp. 45075 036-45075 042.
- 8804080178 Informs that Multi-Plant Action E-04, "BWR Single Loop Operation" closed TAC numbers for hated plants should be closed 8 single loop operation reviews should be tracked as plant-specific actions in future.

 THADANI,MC Project Directorate II-2, 88/04/01, GEARS,G. Ofc of Special Projects 2pp, 45064,311-45064-315.
- 8804080088 Generic Ltr 88-07 to power reactor ficonseps & applicants re-modified en-forcement policy concerning 10CFR5049, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Piants." Svc 1st encl. MIRAGLIA, F.J. Associato Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184;237-45184;285.
- 8804130310 Notification of 880413 meeting w/util in Decatur,At. to discuss plant restart test program.
 MORAN,D.H. Ofc. of Special Projects, 88/04/07, ZECH,G.G. Ofc. of Special Projects 3pp. 45103:172-45103:174.
- 8804200368 Not-Ecation of canceled 890413 meeting w/util in Decktur.At, re-briefing on plant restart test program.
 MCRAN.D.H. Olic of Special Projects. 88/04/07. ZECH,G.G. Olic of Special Projects. 3pp. 45179:275-45179:277.
- 8804130184 Notification of 680414 meeting w/ut1 in Decalur.At to discuss ampacity cable derating calculations & cable screening Phase 1,2 & 3. MORAN.D.H. Otc. of Special Projects. 88704708, ZECH,G.G. Ofc. of Special Projects. 3pp., 45101:199.45101:201.
- 8804210026 Supplemental application for amond to Licenses OPR-33, DPR-52 & DPR-68, implementing recommendations in Genone Lit 84-15, "Proposed Staff Actions to improve & Maintain Diesel Generator Rol ability." Fee paid.

 GRIOLEY.R. Tennessee Valley Authority, 88704713, Document Control Branch (Document Control Dosk), 5pp. 45219:133-45219:149
- -8804210027 Proposed revised Tech Specs,implementing recommendations of Generic Lit 84-16, "Proposed Staff Actions to Improve & Maintein Diasel Generator Rollabilily.** * Tennessee Vallay Authority. 88/04/13. 12pp. 45219.138-45219.149
- 8804260032 Application for amends to Licenses DPR-33, DPR-62 & DPR-68, revising Tach Specs 3.4/4.4 re standby Equid control sys. Fee paid GRIDLEY, R. Tennessee Valley Authority, 88/04/20. Document Control Branch (Document Control Desk), 5pp. 45254;222-45254;239.
- --8804260039 Proposed Tech Spec 3.4/4.4 to stancey liquid control sys * Tennessee Valley Authority, 88/04/20, 13pp. 45254:227-45254:239.
- 8804280818 Notification of 880426 meeting w/util consider to discuss empacity cable de-rating calculations & cable screening, Phases 1,2 & 3, MORAN,D.H. Ofc of Special Projects, 88704/21, AULUCK,R. Ofc of Special Projects 3pp. 45264 077-45264 079
- 8804280479 Notification of 880427 meeting w/util in Decatur,At. to discuss restart test program.
 MORAN,D.H. Ofc of Special Projects 88/04/22. AULUCK,R. Ofc of Special Projects. 3pp. 45264:101-45264:103.

Q. Inspection reports, IE Bulletins & correspondence

- 8803290366 Forwards Insp Repts 50:259/87.38.50-260/87-38.50-298/87-38.50-327/87-86,50-328/87-68,50-380/87-18,50-391/87-18, 50-438/87-08 & 50:439/87-08 an 87:005-18 & notice of workton.
 - 87(035-16 & notice of violation.

 BARR,K.P. Region 2, Ofc of the Orector, 89/03/09 WHITE,S.A. Tennessee Valley Authority, 3pp. 44975 195 44976 208.
- ~8803290390 Notice of violation from insp on 871005-18 Violations noted inadequate divid nuclear engineering training & records, ineffective followup on audit findings & impreper correction of OA records BARAK.P. Region 2, Ota of the Director, 88703709, 3pp, 44975-198-44975-200.
- ~8803290393 insp. Repts. 50-259/67-38,50-260/87-38,50-286/87-38, 50-327/87-66,50-328/87-68,50-390/87-18,50-391/87-18, 50-438/87-08 & 50-439/87-08 Violations noted Major areas inspected a legations & licensee action on identified items. WALTON,G.A., POWELL,T.B., ELROD,S.A. Region 2, Old of the Director, 88/03/08, 8pp. 44975.201-44975.208
- 8804010028 Ack receipt of 680311 ftr informing NRC of steps taken to correct violations noted in Insp. Repts 50:259/87-20, 50:280/87-20 & 50:295/87-20.

 BARRIK P. Otc of Special Projects, 88/03/22, VMHTE S.A. Tacnessed Valley Authority, 1p. 45958-094-45058-094.
- 8804010030 Ack receipt of 680301 supplemental response Informing NRC of steps taken to correct deviations noted in Insp Repts 50:259/87-30.50-260/87-30 & 50-296/87-30
- 296/87-30 BARR,K.P. Old of Special Projects 88/03/22. WHITE,S.A. Tennessee Valley Authority. 1p. 45031:179 45031:179.
- 8603310287 Forwards (nsp. Rapts 50.259/88-04,50.260/88-04 & 50.296/88-04 on 880201-29 & notice of violation BANR,K.P. Region 2, Old of the Director, 88/03/24 WHITE,S.A. Tennessee Valley Authority, 2pp. 45011:083-45011:109
- ~8803310291 Notice of violation from insp on 880201-29 Violation noted: design basis for Class I buned plying not correctly translated into space & drawings & Std Practice
- --8803310292 Insp. Repls 50-259/88-04.50-260/88-04 & 50-296/88-04. Violations noted Major areas inspected operational safety, maint observation, surveillance testing observation, ROs previous enforcement action & restart test program. PAULK, GL., BROOKS CR., CHRISTNOF, E.F., Region 2, Oic of the Director, 88/03/22 23pp. 45011-088-45011:109.
- 8804010031 Forwards Insp. Repts 50:259/88-02.50-260/88-02 & 50:296/88-02 on 680101-31 & rotice of violation Concern expressed re implementation of engineering changes & mod programs.

 BARAIX P. Region 2, Ofc. of the Director, 88/03/24, WHITE,S.A. Tennassee Valley Authority, 3pp. 45028-081-45028-126.
- -8804010032 Notice of violation from Insp on 880101-31 Violation noted: activities at facting quality not being accomplished per documented procedures & drawings in that into do not QC accopted pipe support revealed deviations from requirements BARRIK.P. Region 2, Old of the Director, 88/03/24, 3pp. 45028.084-45028.086.
- ~8804010033 (nsp. Repts 50:250/68-02:50:260/88-02 & 50:296/88-02 on 880101; 31.Violations noted Major areas inspected:open linsp litem followup.operational safety,maint observation.osta/t test program.maint improvement & mgt meetings PAULK,OL L (BNATONISA J Region 2, Old of the Director, 88/03/24 40pp 45028-037-45028-126
- 8803210090 Supplit to NRC into Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors." Svc list enct ROSSI.CE: Division of Operational Events Assessment (Post 870411), 89/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44095:128 44995:246
- 8803220295 NRC Info Notice 88-010, "Mails Licensees Lack of Mgt Controls Over Licensed Programs," Svc list eact. CUNNINGHAN, R.E. Division of Industrial & Medical Nuclear Safaty (Post 670729), 887 03728, Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804060224 Ack receipt of 680316 supplemental response to request for additinto reprevious corrective actions to Violation 3 noted in Insp Rept 50-259/84-12,50-260/84-12 8 50-296/84-12. Extension of corrective action completion date acceptable. BARR,K-P. Oft of Special Projects. 88/03/29. WHITE,S.A. Tennessed Valley Authority. 2pp. 45607.314-45007:315.
- 8804060528 Ack receipt of 880314 ftr Informing NRC of actions taken to correct violations noted in Insp. Repts 50-259/87-41, 50-250/97-41 & 50-296/87-41.

 BARR,K P. Otc of Special Projects. 88/03/30. WHITE,S.A. Tennessee Valley Authority. 2pp. 45010:277-45010:278.
- 8804080207 Forwards request for additinto re util 860513,0930 & 870501 responses to IE Bulletin 85-003, "Motor-Operated Valve Common Mode Falures During Plant Transfents Due to Improper Switch Settings," for response within 30 days. BARR.K.P. Oft. of Special Projects. 88704/01. WHITE.S.A. Tennassee Valley Authority. 45099:180-45099.183.
- 8804110131 Supplemental response to violations noted in insp Repts 50-259/67-14,50-260/67-14 & 50-296/87-14,Corrective actions: work in progress must be completed to demonstrate control bldg pressurtivation Completion scheduled for 881115. GRIDLEY,R. Tennessee Valley Authority, 88/04/05. Document Control Branch (Document Control Beak), 4pp. 45148-016-45148-019.
- 8804010256 NRC Into Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switchboard Function Due to Faulty Tre Bolts." Svc list encl. ROSSI, CE. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408.292-45407:051.
- 8804130246 Responds to NRC 880226 fit re-violations noted in Insp Repts 50-259/87-46,50-260/87-46 & 50-296/87-46.Corrective actions: standby gas treatment sys Train B declared insperable & Technical Instruction 1719 revised.
 GRIDLEY,R. Tennessee Valley Authority, 88/04/08, Document Control Branch (Document Control Deak), 6pp. 45146:322-45146-327.

- 8804060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list enct.
 - PSI BILL.
 ROSSI.CE Division of Operational Events Assessment (Post 870411) 88/04/12.
 Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165.150.
- 8804200555 Forwards Insp. Repis 50:259/88-08.50:260/88-08.8 50:296/88-08.0 on 880322-24 No volations or dawatrons noted BARR,K.P., Region 2, Oto of the Director, 88/04/13, WHITE,S.A. Tennessee Valley Authority, 2pp. 45235-037-45235-043
- -8804200558 Insp. Ropts. 50-259/88-08-50-260/88-08-8-50-296/88-08-on 880322-24-No violations noted Major areas inspected, competence of operators in Group 4 accelerated requalification training course to parform incense duties. BROCKMAN, K.E., JOHNSON, A.H., HOPPER, G.T. Rogion 2, Otc of the Director. 88/04/11-59p. 45235-039-45235-043.
- 8904210017 Summarizes review of NRC Bulletin 88:001, "Defects in Westinghouse Circu'i Breakers" Bulletin not applicable to Browns Ferry nuclear plant Bulletin applicable to Warts Bar & Belletionto nuclear plants List of commitments encl. GRiDLEY,R. Tennessee Valley Authority. 88/04/13 Document Control Brench (Occument Control Desk). 3pp. 45219:150-45219:152
- 8804210023 Forwards supplemental response to NRC 871119 fir re-violations noted in Insp. Repts 50-259/87-33, 50-260/87-33 & 50-296/87-33. Corrective actions maint request issued to reseal function boxes & panels fire protection sys area. GRIDLEY.R. Tonnessed Valley Authority. 88/04/13. Document Control Branch (Document Control Bask) 7pp. 45219:126-45219-132
- 8804200473 Partial response to FOIA request re fire protection Forwards App E documents App D & E documents available in PDR App F document completely withheld (ref FOIA Exemption 5).

 GRIMSLEY, D.H. Division of Rules & Records (Post 870413), 88/04/14, JONES, C.R. Affination Not Assigned 5pp. 45206.037-45206.043.
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type insp for each facility to assoss status of compliance w/ 10CFR50 48 Propram Insted.
 CONLON,T.E. Region 2, Otro of the Director. 84/11/06. HERDT,A.R. Region 2, Otro of the Director. 3pp. 45208.176.45206.178.
- 8804220032 Forwards response to NRC Bulletin 87-002, "Fastener Testing to Determine Conformance W/Applicable Tech Specs." Encl 4 identifies lasteners transferred from storage & Encl 5 contains list of commitments being made by TVA in response GRIDLEYB, Tennessee Valley Authority. 88/04/15. Document Control Branch (Document Control Dask). 155pp. 45219:172-45220,026.
- 8804280524 Nobification of 880427 meeting w/Ecensee in Rockville,MD to discuss independent design map for factitions. GEARS.G.E. Dic of Special Projects, 88/04/22. AULUCK,R. Ofc of Special Projects 3pp. 45271:054-45271:056.
- 8804280635 Responds to NRC 880303 lift to violations noted in 1:sted inspirepts including 50-438787-08,50-439787-08 & 50-327787-68 Corrective actions data base constructed for training.
 GRIDLEY,R. Tennessee Valley Authority. 88704722 Document Control Branch (Document Control Desk). 10pp. 45331-341-45331-350.

R. Periodic operating reports & related correspondence

- 8804060383 "Personnel Whole Body Exposure Repts for 1987." W/880401 ltr. GRiDLEY,R. Tennessee Valley Authority. 87/12/31. 7pp. 45047.060-45047:066.
- 8804070254 "Browns Ferry Nuclear Power Plant Annual Operating Rept to NRC.870101-1231." W/880405 Nr. WALKER J., GRIDLEY,R. Tennessee Valley Authority. 87/12/31 108pp. 45074:279-45075 026.
- 8804050210 Forwards weekly schedule of TVA activities for wks of 880328 & 0404. KELLY,J.L. Oit of Special Projects. 88703724. ZECH,G.G. Oit of Special Projects. 4pp. 45029.088-45029.081.
- 8804140525 Submits weekly schedule at TVA activities for two of 880404- 11. Schedule will be updated & issued each Finday to reflect activities for forthcoming 2-wk period KELLY.J.C. Ofc of Special Projects. 88/03/31. ZECH.G.G. Ofc of Special Projects. 49p. 45130:205-45130:208.
- 8804190140 Monthly operating repts for Mar 1988.W/880414 ttr.
 CRAWFORD.J.D., WALKER.J.G. Tennessee Valley Authority. 88/03/31. 84pp. 45208/070-45208:153.
- 8804130356 Forwards weekly schedule of TVA activities for wks of 880411 & 18. KELLY,J.L. Old of Special Projects. 88/04/08 ZECH,G.G. Old of Special Projects 4pp. 45103.216.45103.219.

U. Congressional/Executive Correspondence

8804280317 Forwards NRR responses to Questions 1 & 3 re Commission stds for permitting restart of power plant after shutdown for safety reasons & Commission requirements for documenting ficensing basis for restart decision,respectively. THOMAS.C.O. Policy Development & Technical Support Branch (Post 870411), 687 04/18. REHM,T.A. Ofc of the Executive Director for Operations. 7pp. 45269.208-45384-915.

V. Operator Examinations

8804200555 Forwards Insp Repts 50-259/88-08,50-260/88-08 & 50-296/88-08 on 860322-24 No violations or deviations noted. BARR, K.P. Region 2, Otc of the Orrector, 88/04/13, WHITE,S.A. Tennessee Valley Authority, 2pp. 45235-037-45235-043.

- -8804200558 Insp Repts 50-259/88-08,50-260/88-08 & 50-296/88-08 on 880322-24 No violations noted Major areas inspected compotence of operators in Group 4 accelerated requalification training course to perform license duties BROCKMAN.K.E., IGNATONIS.A.J. Region 2, Oic of the Director. 88/04/11. 5pp. 45235 039 45235 043
- 8804210471 Confirms 880413 telcon w/NRC re-utilization of Group 4 operators for si-ceased duties Forwards list of Group 4 Iconsoes to whom NRC will administer requali-fication exams prior to Unit 2 rostart. RARR.KP. Region 2, Ofc of the Director, 88/04/13. WHITE,S.A. Tennessee Valley Authority, 3pp. 45227:214-45227.216.
- 8804250088 Responds to FOIA request for Info re-scoros of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in encluapp w/pursonal privacy into defeted.
 GRIMSLEY.O.H. Division of Rules & Records (Post 870413), 88/04/19. BOLEY,K. Public Critizen's Critical Mass Energy Project, 2pp. 45213 003-45213.095.

--8804250167 Package of NRC administered requantication exam results summary. NRC - No Detailed Athilation Given 87/07/20 88pp. 45213:007-45213:095.

DOCKET 50-261 H.B. ROBINSON PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8804200473 Partial response to FOIA request re line protection.Forwards App E documents.App D & E documents available in PDR.App F document completely withheld (rof FOIA Exemplion 5) GRIMSLEY,O.H. Division of Rules & Records (Post 870413), 88/04/14 JONES,C R. Athilation Not Assigned, 5pp. 45206.037-45206.043

-8804200679 Advisos that Fire Protection Steeling Committee has recommended that each region make one 10CFR50.App R-type insp for each facility to assess status of compliance w/ 10CFR50.48 Program Insted.
CONLONT.E. Region 2, Ofc of the Director. 84/11/06. HERDT, A.R. Region 2, Ofc of the Orector. 3pp. 45206:176.45206:178.

J. Insurance & Indemnity information

- 6804070174 Submits into re-present level & source of arisite property damage insur-LOFLIN,LI Carolina Power & Light Co. 88/03/31. Document Control Branch (Document Control Desk). 1p. 45075-256-45075.256.
- 8804250217 Forwards Endorsoment 76 to MAELU Policy MF-49.
 BARHAM,C D. Carolina Power & Light Co. 88/04/04, NASH,D. NRC No Detailed At-Mation Given 2pp. 45212.226-45212 227.
- 8804260218 Forwards Endorsement 95 to NELIA Policy NF-180. BARHAM,C D. Carolina Power & Light Co. 88/04/04. NASH,D. NRC No Detailed Al-Minition Given. 2pp. 45212 228-45212:229.

P. Operating license stage documents & correspondence

- 8803100023 Summary of 860216 meeting w/util re LOCA analyses for safety injection w/single failure Attendance list vilowgrephs & Wostinghouse evaluation, "Justification for Startup of HB Robison W/Attored High Head Safety Injection..." onci. LOR, Project Directorate II-1. 88/02/23. Project Directorate II-1. 24pp. 44681:266-44661.341.
- --8803100104 "Justification for Startup & Operation of H8 Robinson Unit 2 Nuclear Power Plant W/15 X 15 Advanced Nuclear Fuels Co Fuel In Conformance W/10CFR50.46 Acceptance Criteria."

 "Westinghouse Efectic Corp. 88/02/29, 52pp. 44861.290-44681:341.

- 8803260307 Approves actions re-commitments identified in 880211 confirmatory action. It re-failure of onsite electrical distribution sys to meet single failure criteria under certain circumstances to: availability of injection sys GRACE_J.N. Region 2, Offic of the Director. 88/03/08 UTLEY.E E. Carolina Power & Light Co. 1p. 44845:224-44815:224.
- 8803240428 Generic Ltr 88-08 to all power reactor licensees & applicants re removal of organization charts from Tech Spac administrative control requirements Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Eduson Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8904070089 Responds to 880113 fir re adequacy of station electric distribution sys voltages Analysis demonstrates that plant electrical ac distribution sys capable of supplying auxiliary power to safety-related equipment w/o violating ratings. LOFLIN, I. Carolina Power & Light Co. 88/03/29. Document Control Branch (Document Control Dosk). 5pp. 45024:338-45024:342.
- 8904060392 Confirms 680324 telcon between LJ Loflin & PE Fredrickson ra mgt meet-ing scheduled for 880405 at Region II ofc in Atlanta,GA to discuss status of reconsti-tution of plant design.

 REYESI, A. Region 2, Ofc of the Director. 88/03/30, UTLEY,E.E. Carolina Power & Light Co. 1p. 45008:357-45008:357.
- 8904080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-torcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:286.
- 8604150117 Forwards Amend 116 to License DPR-23 & safety evaluation. Amend to make minor or editorial changes to Tech Specs to delete unnecessary ref to number of flux thimbies available for movable incore instrumentation. LO,R-H, Project Directorate II-1, 88/04/11, UTLEY,E.E. Carolina Power & Light Co. 3pp. 45133:318-45133:329.
- -6804150123 Amend 116 to License DPR-23, revising Tech Specs to delete unnecessary refs to number of flux thimbles available for movable incore instrumentation. ADENSAM,E.G. Project Directorate II-1, 88/04/11, 8pp. 46133:318-45133:325.

- --8804150126 Selety evaluation supporting Amend 116 to License DPR-23.

 Office of Nuclear Reactor Regulation, Director (Post 870411) 88/04/11. 3pp. 46133:2824-45133:299
- 8804210033 Discusses NUREG-0737, Item II E 1.2, "Automatic Bus Transfer Feature of Arixillary Feedwater Sys Testing of Molded Case Circuit Breakers." U1 continues to have reservations re impact of instantaneous trip testing on circuit breaker. RICHEY,R.B. Carolina Power & Light Co. 88/04/11. Document Control Branch (Document Control Desk). 2pp. 45194:165-45194:166.
- 8804200300 Summary of 880322 meeting w/util re introduction of key right personnel & status of facility.including programs for equipment enhancement & right actions to improve performance. Viewgraphs & agenda of four enci. LOR. Project Directorate II-1. 88/04/14. Project Directorate II-1. 22pp 45179:287-45179:308
- 8804260019 Discusses 880405 meeting in Region II ofe re scope & status of plant design basis reconstitution project.List of meeting attendees & viewgraphs encl. REYES,L.A. Region 2, Ofe of the Director. 88/04/14. UTLEY,E.E. Carolina Power & Light Co. 25pp. 45251:073-45251 097.

Q. inspection reports, IE Bulletins & correspondence

- 8804060247 Informs that IE Bulletin 86:002. "Bapidly Propagating Fatigue Cracks in Steam Generator Tubos," not applicable to plant.Confirms that two significant contributors to high fluid elastic stability ratio also not ovident at plant. RIGHEY.R.B. Carolina Power & Light Co. 88/03/24. GRACE.J.N. Region 2, Ofc of the Director. 1p. 45007:317-45007:317.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tuba Thinning in Westinghouse Reactors" Svc list and ROSSI, CF. Division of Oppretional Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of Naw York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 88-010, "Matis Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list encl.
 CUNNINGHAM.R.E. Division of Industrial 8. Medical Nuclear Salety (Post 870729), 887
 03/28, Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353.
- 8804060445 Forwards summary response to IE Bulletins 79-02,Rev 2 & 79-14,Rev 1. Suppl 2 did 791108 & 790907 respectively. Seismic Category I base plates evaluated to include affects of floxibility in determining anchor bott loads LOFLIN,L.I. Carolina Power & Light Co. 88/03/31. Document Control Branch (Document Control Oask). 8pp. 45007:064-45007:071.
- 8804010256 NRC Info Natice 88-011, "Potential Loss of Motor Control Cir 8/or Switch-board Function Due to Faulty Tie Bolts," Svc list enc! ROSSI, C.E. Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408 202-45407-051.
- 8804210009 Responds to NRC Bulletin 88-001, "Detects in Westinghouse Circuit Breakers." Util determined that Westinghouse DS series circuit breakers not used in Class 15 yea at Unit 2 EURY,L.W. Carolina Power & Light Co. 88/04/08. GRACE,J.N. Region 2. Otc of the Director. 1p. 45235-209-45235-209.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list and, ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consol/dated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150.
- 8804200473 Partial response to FQIA request re fire protection Forwards App E documents App D & E documents available in PDR App F document completely withheld (rel FOIA Exemption 5). GRIMSEEV.O.H. Owision of Rules & Records (Post 870413). 88/04/14. JONES,C R Affiliation Not Assigned. 5pp. 45206.037-45207.042.
- ••8804200576 Provides status of Region II safe shutdown Insp program. GRACE J.N. Region 2, Oic of the Director, 85/05/13, TAYLOR, J.M. Oic of Inspection & Enforcement, Director (820201-870413), 2pp. 45206:174-45206:175.
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type Insp for each facility to assess status of compilance w/ 10CFR50.48 Program listed.
 CONLON,T.E. Region 2, Old of the Director, 84/11/08, HERDT,A.R. Region 2, Old of the Director, 3pp. 45208;178, 45206.
- 8804260094 Forwards Insp Rept 50-261/88-01 on 880111-15 & 0125-29 & notice of VOIDENTA.C.A. Region 2, Ofc of the Director. 88/04/14. UTLEY,E.E. Carolina Power & Light Co. 2pp. 45248:058-46248.094.

- -8804280111 Notice of violation from insp on 880111-15 & 0125-29. Violation noted on four occasions licenses reported inoperability of all diesel generators while operating at 100 percent power under incorrect regulation.
 JULIAN,C A. Region 2, Ofc of the Director. 88/04/14. 3pp. 45248.058-45248.060.
- --8804260114 Insp Rept 50-261/88-01 on 880111-15 & 0125-29.Violations noted.Major areas Inspected:maint,design control, operations, commercial grade procurement & QA/QC, MELLEN,L., BELISLE,G. Region 2, Ofc of the Director. 88/03/21. 34pp. 45248.061-45248.094.

H. Periodic operating reports & related correspondence

8804150139 Monthly operating rept for Mar 1988.W/880411 jtr.
HAYNESWORTH,V., MORGAN,R.E., Carolina Power & Light Co. 88/03/31, 4pp. 45153:233-45153:236.

8804040085 Forwards applications for renewal of reactor operator & senior reactor operator licenses for RL Hafey, JA Leone, LL Wiegand, HA Wingert, JH Cox, RL Miller, JM Moon & TC Princhard W/o encis.
BEATTY, G.P. Carolina Power & Light Co. 68/02/26, GRACE, J.N., Region 2, Old of the Director. 1p. 44969 070-44969.070.

Y. Dry Cask Independent Spent Fuel Storage Installations

8804130328 Forwards Amend 3 to "ISFSI SAR." Justification for each change also enci. LOFLIN,L.I. Carolina Power & Light Co. 88/03/15. ROBERTS,J.P. Office of Nuclear Maturial Safety & Safeguards, Owector, 8pp. 45103:190-45103:197.

DOCKET 50-262 BRIGHAM YOUNG UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Malling address unchanged A Adams project manager. A TS Michael's back-up project manager. RUBENSTEINLS. Slandardization & Non-Power Reactor Project Directorate. 88/03/18. Allihahon Not Assigned. 3pp. 44859.060-44859.062.

O. Inspection reports, IE Bulletins & correspondence

8804130038 Forwards into in response to request for insplot HFA type latching relays mfg by GE,per NRC Bulletin 88-003.Licensee has no subjilatchings Reactor fivel removed 8 shipped off site white licensee pursues litt decommissioning JACKSON,E.F. Brigham Young Univ., Provo, UT. 88/04/01. Region 4, Ofc of the Director. 1p. 45099/360-45099/380.

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

F. Security, medical, emergency & fire protection plans

8804180244 Forwards Rev 2 to saleguards contingency plan Changes do not decrease effect venoss of saleguards contingency plan & may be implemented w/o prior NRC review & approval Rev withhold (ref 10CFR73).

LARSON,C.E., Northern States Power Co., 88/04/12. Document Control Branch (Document Cont ment Control Dask). 1p. 45185:340-45195:340.

8804180248 Forwards Rev 24 to security plan,per 10CFR50 54(p).Rev withheld (ref 10CFR73) LARSON,C.E. Northern States Power Co. 88/04/12. Document Control Branch (Document Control Desk). 1p. 45195:341-45195.341.

8804180252 Forwards Rev 8 to security force training & qualification plan per 100FR50 54(p) Rev withheld (ref 100FR73) LAHSONC,E Northern States Power Co. 88/04/12, Document Control Branch (Document Control Desk). 1p. 45198/268-45198-266.

P. Operating license stage documents & correspondence

8803240426 Genoric Lit 68-06 to all power reactor licenseps. 8 applicants re removal of organization, charts from Tools Spec administrative control requirements. Svc list encl. M:HAGLIA.F.J. Associate Director for Projects (Post 8704 t1). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44872:107-44972:163.

8804110334 Forwards commonts on proposed Tech Specs for plant control room venti-tation sysper TMI Action Itam III,D.3.4 Response to fisted findings needed to enable NRC to conclude that subj. sys.continues to meet provisions of Item III.D.3.4 STEFANO,J.J. Project Directorate III.1. 88/04/04 MUSOLF.D.M. Northern States Power Co. 22pp. 45076 275-45078 298.

8804080088 Ganoric Ltr 88:07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50:40, "Environ Qualification of Electrical Equip-ment Important to Saloty for Nuclear Power Plants" Svc list encl. MIRAGUN,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.

8804150170 Notification of 880426 meeting w/unit & BNL in Rocky/le,MD to discuss uht topical rept on reload safety evaluation methodology Meeting agenda enct WHIGHT.R J. Project Directorate III-1, 89/04/11, VIRGILIO,M.J. Project Directorate III-1, 39/-45134-308-45134-308

8804220133 Requests that util remit foe for 860226 application for approval of alternate method of satisfying NUREG-0737, Item II 9.3 to Criterion 4 by removal of dissolved gas monitoring portion of post-accident sampling sys. DIGGS,R.M. License Fee Management Branch, 88/04/15, MUSOLF,D.M. Northern States Power Co. 1p. 45201:022-45201:022.

Q. Inspection reports, IE Bulletins & correspondence

8803100123 Advises that no further plant specific action required based on review of util 870906 response to NRC Bulletin 87-031, "Thinning of Pipe Walts at Nuclear Power Plants"

STEFANOULJ, Project Directorate III-1, 88/03/08, MUSOLF,D.M. Northern States Power Co. 1p 44681/357-44661:357.

8804010219 Responds to NRC 880211 ftr re violations noted in Insp Rept 50-263/87-21 Corrective actions individual involved in example counseled to misinferpretation of procedural stop. LARSON.C.E. Northern States Power Co. 89/03/14, NORELIUS,C.F. Region 3, Ofc of the Director, 4pp. 44847:305-44947:308.

8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors," Suc list end ROSSICE Division of Operational Events Assessment (Post 870411), 68/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995.128-44995-246.

censed Programs." Svc list erici. CUNNINGHAM R E Division of Industrial & Medical Nuclear Safety (Post 870729) 88/ 03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353

8804010266 Informs of plan to cancel Kewaunee and SALP team inspidue to licensee continued excellent performance in all areas Region III Intent is to follow core program at all plants in region.

DAVIS,A.B. Region 3, Old of the Director 88/03/28. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 44945/346-44945/346.

8804060498 Responds to NRC Compliance Bulletin 88-003 All GE fatching: type HFA relays inspected & found to be free of defect & demonstrated to have satisfactory Hallys inspection of House of the Hall of General Both Control of Hall Satisfactory Hallon, Director (Post 870411) 3pp. 45011:001-45011:003.

8804060338 Forwards request for addition or review of responses to Action flem e of IE Bulletin 85-003 to assure valve operability can be approved info requested in 30 GREENMAN,E.G. Region 3, Ofc. of the Director, 88/03/30, LARSON,C.E. Northern States Power Co. 4pp. 45010 265-45010 268

8804110174 Responds to 8B0225 SALP 7 Board Rept 50-263/87-01 for June 1986 Nov 1987 Strongly supports NRC SALP process as noted at 880304 meeting LARSON,C.E. Northern States Power Co. 88/04/04 DAVIS,A.B. Reg.on 3. Oic of the Director. 1p. 45135-277-45135-277

8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Confrol Ctr &/or Switch-board Function Due to Faulty Tio Botts," Svc list and: ROSSI,C E. Division of Operational Events Assessment (Post 870411) 88/04/07 Cons

8804080370 NRC Info Notice 88 012, "Overgreasing of Electric Motor Bearings." Svc Istenct.

ROSSICE: Division of Operational Events Assessment (Post 870411). 88/04/12
Consolidated Edison Co. of New York, Inc. 123pp. 45185:028-45165:150.

R. Periodic operating reports & related correspondence

8804150115 Monthly operating rept for Mar 1988.W/880411 ltr. MYRA80,A L , MUSOLF,D Northern States Power Co. 88/03/31. 5pp 45170.038 45170.042

S. Reportable occurrences, LERs & related correspondence

8804200189 LER 88:002:00:on 880413,fire watch not established,per Tech Spec 3.13.G.2,for fire door found in open position due to inoperable self-closing mechanism.Caused by inadequate procedures & training.Procedure revised.W/890413 IVERSON,O.N., MUSOLF,D. Northern States Power Co. 88/04/13 4pp. 45220.274 45220:277.

V. Operator Examinations

8803300236 Informs of revito commitment made relicensed operator training & requalification programs. Util will conduct future operator training using program accredited by INPO in Dac 1987. Program available for NRC review.
MUSOLF,D. Northern States Power Co. 88/03/21. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 44979:142-44979:142.

8804150328 Informs of revito shift technical advisor (STA) training program onginally provided to NRC in util 810130 ltr.Revidue to completion of STA task list for accredition MUSOLF.D. Northern States Power Co. 88/04/08. Document Control Branch (Document Control Desk), 1p. 45138 204-45138:204.

DOCKET 50-264 DOW CHEMICAL CO.

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address.Malling address unchanged.Adams project manager & TS Michaels back-up project manager. RUBENSTEIN.L.S Standardization & Non-Power Reactor Project Directorate. 88/03/

DOCKET 50-265 QUAD-CITIES STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8804050061 Forwards Followup Insp Repts 50:254/88-06 & 50:265/88-07 on 880315 17. No violations of NRC requirements noted. SHAFER,W.D. Region 3, Otc. of the Director, 86/03/31, REEO,C. Commonwealth Edison Co. 2pp. 45028.278-45028-291.

-8804050064 Insp. Repts. 50-254/88-06. & 50-285/88-07 on 880315-17.No violations noted Major areas inspected licensee actions on previously Identified Items, emergency plan activations, review of licensee Initiatives to Improve program. PLOSKI,T.J. Region 3, Ofc of the Director. 88/03/31, 11pp. 45028:280-45028.291

8804280270 Forwards revised safety evaluation re interim compensatory measures & request for exemption from 10CFR50,App R,Section III.G.1,re hot shuldown regard ROSS,T. Project Directorate III.-2. 88/04/20. BLISS,H. Commonwealth Edison Co 3pp 46322:347-45322:354.

- ~8604290265 Revised safety evaluation accepting util inform compansatory measures 8 request for exemption from 10CFR50, App R.Section III G requirement re hot shut-down repair for fire event in plant.

 * Plant Systems Branch 89/04/20 5pp 45322 350-45322 354

P. Operating license stage documents & correspondence

- 8709300402 Responds to request for review & comments on whether or not technically acceptable inerted containment sys could satisfy provisions of 10CFR50.44(g).NRC awaining plant-specific submittals on compliance.per 870120 meeting. DOHtAN, T.F. Assistant Goneral Counsel for Rulemaking & Fuel Cycle. B7708/31. JANECEK, R.F. BWR Owners Group. JANECEK, R.F. Commonwealth Edison Co. 2pp. 45329.355.45322.360. 45322 355 45322 360
- 8803240426 Generic Lir 88-06 to all power reactor licensees & applicants re-removal of organization charts from Tech Spec administrative control requirements Syc List encl. MIRAGLIAF J Associate Director for Projects (Post 870411). 88/03/22 Consolidated Edison Co. of New York, Inc. 47pp. 44972 107-44972 153.
- 8804060497 Application for amond to License DPR-30,changing Tech Spacs to support operation during Cycle 10 reload.Changes concern MAPLHGR limit for reload fuel.GE proprietary LOCA analysis encil Proprietary analysis withheld Fee paid.

 Stl.ADY.JA. Commonwealth Edson Co. 88/03/28 MURLEY.T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 18pp. 45007 337-45008:108
- -B804070035 Proposed Tech Specs, supporting operation of unit during Cycle 10 by changing MAPLHGR fimits for reload fuel & adjustment of min chilcel ratio.
 * Commonwealth Edison Co. 88/03/28, 26pp. 45007.355-45008.020.
- -8804060506 Rev 0 to, "Supplemental Retoad Licensing Submittal for Quad Cities Nu-cloar Power Station Unit 2.Reload 9.Cyclo 10." LAMBERT,P.A., ELLIOTT,P.E., CHAHNLEY,J.S. General Electric Co. 23A5846 R00. 88701731 20pp. 45008 021-45008 108.
- 8804060524 Documents 880317 telcon re embedment plate assessment program re analysis mothod & acceptance cutoria for computation of allowable loads for strip embeding in plates w/ 24-inch anchor spacing. JOHNSONJ M. Commonwealth Edison Co. 88/03/31, MURLEY, T.E. Office of Nuclear Heactor Regulation, Director (Post 870411). 1p. 45010 287-45010:287.
- 8804070265 Responds to 880129 & 0224 litrs re alleged hazardous practices at unit Discusses evidence of licensee compliance to federal regulations & nonviolation of requirements No lurther action intended.
 GREENMAN,E G Region 3, 0tc of the Director, 88/00/31, YOUNG,C Affiliation Not Assigned, 4pp. 45029/261-45029;264.
- 8804210353 Forwards listing of tests, changes & experiments for March 1988 in compliance with 10CFR50.59.

 ROBEY,R.A. Commonwealth Edison Co. 88/04/01. SNIEZEK,J.H. Office of Nuclear Heactor Regulation, Director (Post 8/0411). 10pp. 45235-320-45235.329.
- 880408088 Generic Ltr 88-07 to power reactor liconsees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants" Svc list onct. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45164 237-45164 285.
- 8804280039 Forwards Rev 50 to CE-1-A, "OA Program for Nuclear Generating Stations" Revs being made to reflect organizational changes.

 MORGAN.W.E. Commonwealth Edison Co. 88/04/18 Document Control Branch (Document Control Dask). 1p. 45261-273-45261-299.
- --8804280069 Rev 50 to "QA Program for Nuclear Generating Stations."

 "Commonwealth Edison Co. CE-1-A R50, 86/04/18, 17pp, 45261;274-45261;299.
- 8804290297 Informs that steam void formation & subsequent water hammer offects during sys startup will not occur in ECCS as result of reactor coolant leakage into sys, por concerns raised by NHC.

 JOHNSONI, M. Commonwealth Edison Co. 88/04/19. MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 2pp. 45283.073-45283.074.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list onct.
 ROSSI,CE. Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995 246
- 8803220296 NRC Info Notice 88-010, "Matts Licensees Lack of Mgt Controls Over Licensed Programs." Svc list encl.
 CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 870729). 88/
 03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804140004 Responds to NRC 880225 ftr re violations noted in Insp Repts 50:254/87-33 & 60:265/87-33.Corrective actions instrument mechanic & foreman made aware of requirements of Station Procedure QIP 5700-2 & procedure discussed at maint meet
 - ing TURBAK,MS. Commonwealth Edison Co. 88/03/29 DAVIS,A.B Region 3, Old of the Director, 10pp, 45147:306-45147:315.
- 8804060441 Forwards request for addl into re util responses to IE Bulletin 85-003, "Motor-Operated Valve Common Mode Failures During Plant Transients Due to Improper Switch Settings." Addl into requested within 1 month of ltr date. GREENMAN.E.G. Region 3, Ot. of the Director. 88/03/30. REED,C. Commonwealth Ed son Co. 5pp. 45007.059-45007.063.
- 6804050061 Forwards Followup Insp Repts 50-254/88-06 & 50-265/88-07 on 880315-SHAFER, V.D. Region 3, Otc of the Director, 88/03/31, REED, C. Commonwealth Ed son Co. 2pp. 45028-278-45028:291.
- ---8804050064 Insp. Repts 50-254/88.06 & 50-265/88-07 on 880315-17.No violations noted, Major areas inspected licensee actions on previously identified items, emergency pflan activations, roview of licensee initiatives to improve program PLOSKIT J., SNELL,W.G. Region 3, Orc of the Director. 88/03/31 11pp. 45028:280-45028:291

- 8804010256 NRC into Notice 88-011, "Potential Loss of Mater Central Cir &/or Switch-board Function Due to Faulty Tie Botts." Svc 1st end ROSSI, GE Division of Operational Events Assessment (Post 870411) 88/04/07 Consolidated Edison Co. of New York, Inc. 124pp 45408 292-45407.051.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc Ist encl.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/04/12.

 Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165.150
- 8804190013 Forwards Safety Insp Repts 50-254/68-04 & 50-265/68-04 on 880207-0402, Violation noted but notice of violation will not be Issued. FORNEY, W.L. Region 3, Old of the Director, 88/04/12 REED,C. Commonwealth Edison Co. 2pp 45197-028-45197-039
- --8804190017 Insp Repts 50:254/88:04 & 50:265/88:04 on 880207-0402. Violations noted Major areas inspected operations, maint, surveillance, LER rev.ew.routine repts, temporary instructions & administrative controls affecting quality. RING,M.A. Reg on 3, Oto of the Director, 88/04/12 12pp. 45197:028-45197.039.
- 8804210438 Forwards request for additinfo re-results of expanded inspipitant for piping susceptible to IGSCC at plant. Util proposed alternative not acceptable w/o further justification. ROSS, T. Project Directorate III-2, 88/04/13, BUTTERFIELD, L. Commonwealth Edison Co. 5pp. 45192 183-45192.187.
- 8804250328 Confirms plans discussed on 880414 between H Bliss & G VanSickle re vpcoming 880508 mooting w/uli0 to discuss response to IE Bulletin 85-003. GREENMAN,E.G. Region 3, Otc of the Director, 88/04/18 REED,C. Commonwealth Edison Co. 2pp 45251:120-45251:121.

R. Periodic operating reports & related correspondence

8804220070 Monthly operating repts for Mar 1988 W/880401 ltr.
DEELSNYDER.L., ROBEY,R.A. Commonwealth Edison Co. 88/03/31. 22pp
45221:260-45221:281.

S. Reportable occurrences, LERs & related correspondence

- 8803300185 LER 87-009-00 on 870801, reactor scram occurred from turbing gonerator load mismatch due to generator top as result of fault in main transformer Cause under investigation. Mein transformer replaced. W/B70824 It.
 WALTERS,S.M., BAX,R.L. Commonwealth Edison Co. 87/08/24 8pp. 44975 299-
- 8803300204 LER 88-002-00 on 880223,HPCI inoperable due to room cooler loss from short circuit of control relay. Caused by short circuit in control relay causing transformer to overheat 8 short. Control relay & transformer replaced. W/880310, III. PACLID.J.D., BAX.R.L. Commonwealth Edison Co. 88/03/10. 5pp. 44961.079-44961.083.
- 8804200387 LER 87-002-01:on 870122,RCIC isolated & declared inoperable due to oil flooding, outboard bearing Caused by mod design deficiency installed during refuel outage Bearing replaced & oil orifice cleaned & reinstalled W/880322 ltr. HILL,K.J., BAX.R.L. Commonwalth Edson Co. 88/03/22. 6pp. 45221:133-45221:138
- 8804130047 LER 88-004-00.on 880308.Insufficient number of operable reactor protection sys channels provided Caused by personnel error Incident discussed w/individuals involved & Tech Spec change drafted to eliminate requirement W7880324 ltr. LECHMAIER_J. DAX_R.L. Commonwealth Edison Co. 88/03/24. 7pp. 45151-028-
- 8804270158 Forwards addl into re LER 87-025 concerning control room habitability Agrees to suppl LER 87-02 & provide safety significance assessment by 880422 JOHNSON,I.M. Commanwealth Edison Co. 8B/04/15. DAVIS,A B Region 3, Ofc of the Director. 35pp. 45245.286-45245.320.

DOCKET 50-286 POINT BEACH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8804050280 Forwards draft technical evaluation rept (TER) to fire protection Tech Specs change for review & response to noted deficiencies
 WAGNEH, D.H. Project Directorate III-3, 88/03/25, FAY, C.W. Wisconsin Electric Power Co. 7pp. 45029 098-45029 105.
- 8804050059 Forwards Safety Insp Repts 50-266/88-07 & 50-301/88-07 on 670307 11.No violations noted.

 11.No violations noted.

 SHAFER,W.D. Regian 3, Ole of the O rector, 88/03/30, FAY.C.W. Wiscons n Electric Power Co. 2pp. 45034:107-45034:118
- --8804060054 Insp Repts 50-266/88-07 & 50-301/88-07 on 880307-11. No violations, deficiencies or devalions noted Major areas inspected emergency preparedness program, including action on previous open items & activations of emergency.
- plan FOSTER, J.E., PATTERSON, J.P., SNELL, W. Region 3, Old of the Oroctor 88/03/29 10pp. 45034:109-45034:118.
- 8604110333 Forwards environ assessment & finding of no significant impactive 860611 application for exemption from requirements of 10CFR50,App. R.Section III.G 3.b. Assessment also forwarded to Ofc of FR for publication. WAGNER,D.H. Project Directorate III-3. 88/04/04, FAY,C.W. Wisconsin Electric Power Co. 2pp. 45078:180-45078.184.
- --BB04110335 Environ assessment & finding of no significant impact re 860611 application as supplemented by 861010 ftr, for exemption from requirements of IOCFR60. App. R. Section III.G.3.b. PERKINS, K.E. Project Directorate III-3. 88/04/04. 3pp. 45078:182-45078:184

- 8804200511 Forwards Safety Insp. Repts 50-266/88-06 & 50-301/88-06 on 880201-0315-No viorations noted. KNOP,RC Region 3, Oic of the Director 88/04/05 FAY,C.W. Wisconsin Electric Power Co. 2pp. 45231-119-46231:128
- -8804200519 Insp Repts 50:266/88-06 & 50:301/88-06 on 880201-0315 No violations or deviations noted Major areas inspected action on previous msp findings,temporary instructions, operational safety, maint, surveillance, physical security & LER followup DEFAYETTE,R. Region 3, Ofc of the Director 88/04/05, 8pp 45231.121-45231.128
- 88D4210245 Forwards Safeguards Insp. Repts 50-266/88-08 & 50-301/88-08 on 80021-31 Apparent violations noted.
 MALLETT,B S. Region 3, Ofc of the Director. 88/04/13. FAY,C.W. Wisconsin Electric Power Co. 2pp. 45226-343-45228
- --8804210248 Partially withheld Insp. Repts 50:266/88 08 & 50:301/88 08 on 890321:31 (ref. 10CFR73.21) Violation & open itom noted. Major areas inspected mgt affectiveness, security organization, records & repts & testing & maint DROUNINB, GALANTID, CREED, J.R. Region 3, Ofci of the Director. 88/04/11, 2pp. 45228.345.45226.346.

H. General correspondence

8803310195 Comment supporting proposed rule 10CFR50.App Jire mass point method of data analysis Recommends test duration cateria in ANSI/ANS-56.8-1987,Section 5.4 be accepted in revised regulations. FAYC.W. Wisconsin Electric Power Co. 88/03/18 CHILK,S. Office of the Secretary of the Commission, 2pp. 44964-061-44964-062.

i. Financial information

8804150278 Forwards 1987 annual rept to stockholders.including certified financial statements Rept included as app to definitive into statement. FLEISSNER,J.W. Wisconsin Electric Power Co. 88/04/11. Office of Nuclear Reactor Regulation, Director (Post 870411) 25pp. 45138:123-45138:147.

A insurance & indemnity information

8804140089 Forwards Endorsament 90 to NELIA Policy NF-178 & Endorsement 74 to MAELU Policy MF-53.

DUNDAS,W.J. Wisconsin Electric Power Co. 88/03/31. DINIT2,I. NRC - No Detailed Affiliation Given 3pp. 45163 315 45163:317.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8804130255 Comments on 871021 final rept NSAC-113, "EPRI/Westinghouse Owners Group Analysis of DHR Risk at Point Beach," per NRC request.Resources did not permit exam of plant,review of training procedures 8 emergancy guidelines. DAVIS, PR. Attiliation Not Assigned 88/01/11, BORHNRT, P. ACRS - Advisory Committee on Reactor Safeguards. 14pp. 45117:326-46117:339.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88 06 to all power reactor l'censees 8 applicants re removal of organization charts from Tech Spec administrative control requiaments svc list encl. MiHAGLIA F. J. Associate Director for Projectis (Post 870411) 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44872;107-44972;153.
- 8804050280 Forwards draft technical evaluation rept (TER) re live protection Tech Specs change for review & response to noted deficiencies WAGNER.D.H. Project Directorate III-3, 88/03/25, FAY,C.W. Wisconsin Electric Power Co. 7pp. 45029.098-45029.105
- 8804080371 Forwards Into package re backround into for Commissioner Carr 880404 & 05 visits to Kewaunee & Point Beach sites, respectively. DAVIS,A B. Region 3, Oto of the Director, 88703/28. JOHNSON,M. Region 3, Oto of the Director, 1p 45078;173-45076;173.
- 8804050088 Forwards response to NRC 870224 request for additing re 871204 audit of DCRDR project & SPDS Set of human engineering discrepancies (HEOs) that have changed since summary rept submitted & set of pending HEDs enci. FAY,C.W. Wisconsin Electic Power Co. 88/03/29. Document Control Branch (Document Control Desk). 209pp. 44996;123-44996;331.
- 8804060236 Ack receipt of uni 980321 ftr re-requested exception to lifetime storage of radiographs contained in ANSI N45.29. Revised program acceptable. WHIGHT.G.C. Region 3, Olic of the Director. 88703729, FAY.C.W. Wisconsin Electric Power Co. 2pp. 45007:299-45007:300.
- 8804140193 Provides fisted info requested in 880225 lir re operating nuclear power units located at twelve sites along Great Lakes.
 STELLO,V. Olic of the Executive Director for Operations. 68/04/06. RIDGE,T. House of Rep. 5pp. 45104:138-45104:143.
- 8604080088 Generic Ltr 88.07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.48, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA,F. J. Associate Duractor for Projects (Post 670411), 88/04/07. Consolidated Edison Co. of New York, Inc., 49pp. 45164:237-45164:285.
- 8804200314 Forwards two page set of graphs pertaining to plant extracted from rept on performance indicators for operating commercial nuclear power reactors, set of definitions for fistert indicators & 7-yr history, WAGNERD, D.H. Project Directors is III-3, 68/04/08, FAY, C.'N., Wisconsin Electric Power Co. 33pp. 45179.178-45179:210.
- 8804200178 Informs that startup for Cycla 16 expected to occur in May 1988 following 8 wks refueling 8 maint outage. FAY,C.W. Wisconsin Electric Power Co. 88/04/11. Document Control Branch (Document Control Dask), 2pp. 45177:185-45177:186.

- 8804220252 Responds to util 880323 fir reaffirming commitment to check auxiliary feed-water piping temp once per shift,per Generic Ltr 88-03.Commitments acceptable Generic Issue 93 considered resolved. WAGNER,D H. Project Directorate III-3. 88/04/12. FAY,C.W. Wisconsin Electric Power Co 2pp. 45200-331-45200-332.

 - 8804210356 Responds to 880125 request for relief from ASME Section XI Code requirement determined to be impractical to perform during second 10-yr insp Interval at plant Util should consider issted comments & revise proposed relief request. WAGNER D.H. Project Directorate III-3, 88/04/14, FAY,C.W. Wisconsin Electric Power Co. 3pp. 45191 291-46191:293.
 - 8804220048 Forwards Amends 113 & 116 to Licenses DPR-24 & DPR-27, respectively & safety evaluation Amends revise asterisked notes to Tech Spec Table 15.4.1-1,tiem 25, "Steam Generator Pressure," which clauties requirements. WAGNERD.H. Project Directorate III-3. 88/04/14. FAY,C.W. Wisconsin Electric Power Co. 2pp. 45201:067-45201:080.
 - -8904220057 Amends 113 & 116 to Licenses DPR-24 & DPR-27, respectively, revising Tech Spec Table 15.4.1-1, Item 25, "Steam Generator Pressure," which clarifles re-quirements for testing of steam generator pressure channels during refueling shut-downs. PERKINS,K.E. Project Directorale III-3, 88/04/14, 7pp. 45201:069-45201:077
 - -8804220060 Safety evaluation supporting Amends 113 & 116 to Licenses DPR-24 & DPR-27,respectively.

 Office of Nuclear Reactor Regulation, Director (Post 870411). 88/04/14. 3pp. 45201:078-45201:080.
 - 8804280540 Forwards Amends 114 & 117 to Licenses DPR-24 & DPR-27, respectively & safety evaluation Amends make administrative changes to & clarities Tech Specs. WAGNER,D.H. Project Directorate III-3, 88/04/18, FAY,C.W. Wisconsin Electric Power Co. 2pp. 45269 058-45269 082.
 - --8804280561 Amends 114 & 117 to Licenses DPR-24 & DPR-27,respectively, clarifying & making administrative changes to Tech Spec. PERKINS,K.E. Project Directorate III-3, 88/04/18, 21pp. 45269:080-45269.080.
 - --8804280558 Safety evaluation supporting Amends 114 & 117 to Licenses DPR-24 & DPR-27,respectively.

 Office of Nuclear Reactor Regulation, Offector (Post 870411), 88/04/18, 2pp. 45269-061-45269.082.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87:044, "Thimble Tube Thinning in Westing: house Reactors." Svo list encl.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/03/28
 Consolidated Edison Co. of New York, Inc. 121pp. 44995:128-44995:248.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list enct.
 CUNNING IAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729). 88/
 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.
- 8804060059 Forwards Safety Insp Repts 60-266/88-07 & 50-301/88-07 on 870307-11. No violations noted SHAFER.W.D. Region 3, Otc of the Director. 88/03/30. FAY.C.W. Wisconsin Electric Power Co. 2pp. 45034:107-45034:118.
- -8804060064 Insp Repts 50-266/88-07 & 50-301/88-07 on 880307-11.No violations,deliciencies or deviations noted. Major areas inspected emergency preparedness program. Including action on previous open items & activations of emergency plan.
 FOSTERJE, PATTERSON, J.P., SNELL, W. Region 3, Ofc of the Director, 88/03/29, 10pp, 45034; 109:45034; 118.
- 8804200511 Forwards Safety Insp. Repts 60-266/88-06 & 50-301/88-06 on 880201-0315.No violations noted. KNOP,R.C. Region 3, OIc of the Director. 88/04/05. FAY,C.W. Wisconsin Electric Power Co. 2pp. 45231:119-45231:128.
- -8804200619 Insp Repts 50-266/88-06 & 50-301/88-06 on 880201-0315 No violations or deviations noted Major areas inspected action on previous insp findings.temporary instructions operational safety meint, surveillance, physical security & LER follows. DEFAYETTE,R. Region 3, Otc of the Director. 88/04/05. 8pp. 45231:121-45231:128.
- 8804010256 NRC into Notice 88-011, "Potential Loss of Motor Control Cit &/or Switch-board Function Due to Faulty Tie Bolls," Syc list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co, of New York, Inc. 124pp. 45406:292-45407:051.
- 8804210032 Responds to NRC Bulletin 88-003, "Inadequate Letch Engagement in HFA Type Latching Relays Mig by GE." Relays not employed at plant. FAY.C.W. Wisconsin Electric Power Co. 88/04/11. DAVIS.A.B. Region 3, Olc of the Director. 1p. 45219:116-45219:118.
- 8804060370 NRC Info Notice 86-012, "Overgreasing of Electric Motor Bearings." Svc list enct.

 ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/04/12.

 Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150.
- 8804210245 Forwards Saleguards Insp Repts 50-266/88-08 & 50-301/88-08 on 880321-31. Apparent violations noted. MALLETT, B.S. Region 3, Oir of the Director. 88/04/13, FAY,C,W. Wisconsin Electric Power Co. 2pp. 46228-343-45226-346.
- --8804210248 Partielly withheld Jnsp Repts 50-266/88-08 & 50-301/88-08 on 880321-31 (ref. 10CPR73.21), Violation & open item noted, Major areas inspected mgt effectiveness, security organization, records & repts & testing & melnt. DROUNI, B., GALANTI, D., CREED, J.R. Region 3, Ofo of the Director, 88/04/11, 2pp 45226:345-45226:346.

8804210366 Responds to 880125 request for refiel from ASME Section XI Code requirement determined to be impractical to perform during second 10-yr insp interval at plant. Unit should consider listed comments & revise proposed relief request WAGNERD.H Project Directorate III-3, 88/04/14, FAY,C.W. Wisconsin Electric Power Co. 3pp. 45191:291-45191:293.

R. Periodic operating reports & related correspondence

8804120415 Monthly operating repts for Mar 1980.W/880408 ltr. KRAUSE.C.W., FAY.C.W. Wisconsin Electric Power Co. 88/03/31. 9pp. 45129:143-45129.151.

S. Reportable occurrences, LERs & related correspondence

- 8803300427 LER 88-003-00 on 880228, discovered that procedures that delineate testing of undervoltage channels of 4,160 volt safeguards power supplies did not ensure adequate testing of channels Caused by personnel error W/880328 ftr. FAY,C.W. Wisconsin Electric Power Co. 89/03/28. 5pp. 44981:074-44981:078
- 8804200584 Requests that Div of Reactor Safety take lead in regional followup re problem at plant 8 potential generic implications. GREENMAN.E G. Region 3, Off. of the Director. 98/04/12. MILLER,H.J. Region 3, Ofc of the Director. 1p. 45175:039-45175-039.

DOCKET 50-287 FORT ST. VRAIN NUCLEAR GENERATING STATION

F. Security, medical, emergency & fire protection plans

- 8804110324 Requests NRC support in obtaining FCC authorization for addit radio frequencies for two major communication improvement projects Projects involve both emergency response & normal plant operations. WILLIAMS.R.O. Public Service Co. of Cotorado. 88/03/09. MARTIN.R.D. Region 4. Otc of the Director. 3pp. 45128.354-45128:357.
- -8804110327 Requests fir supporting request to FCC stating necessity to conduct remedial drill as soon possible after equipment Installation 8 operator training. Special temporary authorization needed until license is received BYFINE_J.P. Colorado, State of. 88703701. MARTIN,R.D. Region 4, Ofc of the Director. 1p. 45129:357-45129:357.
- 8803300359 Provides update on status of emergency response facility upgrades re forward command post & technical support ctr. Upgrados initiated as part of improvement project in area of interface methods during emergency response. 8REV.H. Public Service Co. of Colorado. 88/03/18. Document Control Branch (Document Control Desk), 2pp. 44962.345.44962:346.
- 8804040230 Forwards Insp Rept 50-267/88-03 on 880201-29. Violations noted Actions laken in response to previously identified violations also examined & discussed in Paragraph 2 of rept. CALLAN, J. Region 4, Olc of the Director. 88/03/31, WILLIAMS, R.O. Public Service Co. of Colorado. 2pp. 45075-323-45075:338.
- -8804040236 Insp Rept 50-267/80-03 on 880201-29.Violations noted.Major ereas inspected.licensee action on previously identified findings, operational safety ventication, followup of unusual evonts, ESF walkdown & physical security observation. FARRELL R.E., MICHAUD, P.W., WESTERMAN, T.F. Region 4, Old of the Director, 88/03/25, 12pp. 45075:327-45075:338.
- 8804060281 Informs that util requires representatives to conduct door- to-door survey & slicker replacement Survey rescheduled between third wk of May & June 1988 due to scheduling conflict.Rev to commitment date to 880630 submitted.
 WILLIAMS,R.O. Public Service Co. of Colorado, 88703/3/1. Document Control Branch (Document Control Desk), 2pp. 45006;317-45096;318.
- 8804110102 Forwards supplemental safety evaluation re util compliance w/ IOCFR50,App R concerning fire protection & ability of DHR sys to achieve safe shutdown after fire. DHR capacity of both trains adequate. HEITNER, K.L. Project Directorate IV 88/04/01. WILLIAMS, R.O. Public Service Co. of Colorado. 4pp. 45071:140-45071:155.
- -8804110106 Supplemental safety evaluation supporting util compliance w/ 10CFR50 App R re safe shutdown DHR capacity.
 Office of Nuclear Reactor Regulation, Director (Post 870411). 88/04/01. 3pp. 45071:144-45071:155.
- 8804120128 Forwards Insp Rept 50-267/88-04 on 880222-26.No violetions or deviations noted. CALLAN, J. Region 4, Olc of the Director, 88/04/05, WILLIAMS,R.O. Public Service Co. of Colorado, 2pp. 45128:288-45128:296.
- --8804120134 Insp. Repl. 50:287/88-04 on 880222-26.No violations or deviations noted. Major areas inspected fire protection/ prevention program & implementation. SINGHA., HILDEBRAND, E.P., IRELAND, R.E., Region 4, Ofc of the Director. 68/03/30. 7pp. 46128:290-45128-296.

1. Financial Information

8804200079 "Annual Rept 1987, Stategic Planning." W/880415 ltr.
WALKER,R.F., HOCK,D.O., BREY,H.L. Public Service Co. of Colorado. 87/12/31.
52pp. 45226:038-45226.093.

J. Insurance & Indemnity Information

- 6804120268 Submits Into re property damage insurance for plant.per 10CFR50.54(w)(2). BREY,H.L. Public Service Co. of Colorado. 88/04/01, Document Control Branch (Document Control Desk), 2pp. 45080.017-45080.018.
- 8604120385 Forwards Endorsements 1 & 2 to MAELU Certificate MW-42 & Endorsements 1 & 2 to NELIA Certificate MW-100. BREY,H.L. Public Service Co. of Colorado. 88/04/01. Document Control Branch (Document Control Desk). 21pp. 45089-328-45089-348.

- 8803300063 Forwards safety evaluation re-core support floor casing leak Table depicting effects of variations in primary coolant activity concentrations & release rates on offsite doses & 10CFR20 lm/ts also enci.
 BREY.H.L. Public Service Co. of Colorado, 88/03/18 CALVO,J A. Project Directorate IV. 25pp. 44962.073 44962.097.
- 8803290282 Forwards "CRD Partial Scram Test Results & Max Daily Temp Rept for Feb 1988," per interim Tech Specs requiring rept once every 31 days when one or more CRD motor temp exceeds 215 F. WILLIAMS.R.O. Consumers Power Co. 88/03/21, CALVO,J.A. Project Directorate IV. 2pp. 44852 223-44952 230.
- -8603290283 "CRD Pariel Screm Test Results & Max Daily Temp" for Feb 1988 SPIKER.DL, NOVACHEK.F.J. Public Service Co. of Colorado. 88/03/21. 6pp. 44952.225-44952 230.
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list enci. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/03/22 Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153
- 8804070130 Provides rev to planned const activities discussed in 860829 ltr to Martin Const of new maint & training facility not economically prudent & const post-poned indefinitely Mods to shift supervisor oic postponed.

 WILLIAMS,R.O. Public Service Co. of Colorado 88/03/23. Document Control Branch (Document Control Desk). 2pp. 45044:155-45044:156.
- 8804060400 Forwards application for amend to License DPR-34,deleting requirement to monitor ambient temp in instrument penetrations housing flow sensors for dewpoint moisture monitoring sys Fee paid.
 WILLIAMS.R.O. Public Service Co. of Colorado. 88/03/29, CALVO, J.A. Project Directorate IV. 3pp. 45047:251-45047:264.
- --8804060414 Application for amend to License DPR-34, deleting requirement to monitor ambient temp in instrument penetrations housing flow sensors for dewpoint moisture monitor sys.
 WILLIAMS.R.O. Public Service Co. of Colorado. 88/03/29 4pp. 45047.254-45047.257.
- --8804060416 Proposed Tech Specs delating requirement to monitor ambient temp in instrument penetrations housing flow sensors for dewpoint moisture monitoring sys
 Public Service Co. of Cotorado, 88/03/28, 7pp. 45047:258-45047:264.
- 8804110034 Forwards proposed changes to updated FSAR,App B involving reduction of commitments in QA program description. Equivalent QA controls provided to satisfy 10CFH50,App B criteria Reasons for change included. WILLIAMS,R O. Public Service Co. of Colorado. 88/03/29. Document Control Branch (Document Control Desk). 11pp. 45073;185-45073;195.
- 8804110102 Forwards supplemental safety evaluation is util compliance w/ i0CER50.App R concerning line protection 8 ability of OHR sys to achieve safe shutdown after line.DHR capacity of both trains adequate. HEITNER.K.L. Protect Directorate IV. 88/04/01. WILLIAMS,R.O. Public Service Co. of Colorado. 4pp. 45071;140-45071;155.
- --8804110106 Supplemental safety evaluation supporting util compliance w/ 10CPR50.App R re-safe shutdown DHR capacity.

 'Office of Nuclear Reactor Regulation, Director (Post 870411) 88/04/01. 3pp 4507:1144-4507:155.
- 8604060088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants" Svc list encl MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 48pp. 45164:237-45164:285.
- 8804130327 Provides proposed plan for requalification of CRD mechanisms for elevated temps Items for consideration in temp requalification plan for CRD mechanisms listed. WAREM8QURG,D.W. Public Service Co. of Colorado. 88/04/07. CALVQ,J.A. Project Directorate IV. 9pp. 45163.281-45163.289.
- 8804190086 Forwards Amend 59 to License OPR-34 & safety evaluation. Amend deletes tabular listing of safety-related shubbers from thit Tech Specs. HEITNER,K.L. Project Directorate IV. 88/04/07, WILLIAMS,R.O. Public Service Co. of Colorado. 3pp. 45155:174-45155-229.
- --8804190098 Amend 59 to License DPR-34,dotelling labular listing of safety-related snubbers from Tech Specs. CALVO,J A. Project Directorate IV, 88/04/07. 9pp. 45155;177-45155;185.
- -8804190106 Safety evaluation supporting Amend 59 to License DPR-34.
 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/07 2pp. 45155:186-45155:229.
- 8804220182 Discusses revised helium circulator outage schedule.per NRC 880304 meeting Schedule for 12 wk outage for refurbishment of helium circulators will start on 880705 instead of 880502. WILLIAMS.R.O. Public Service Co. of Colorado, 88/04/14. Document Control Branch (Document Control Desk). 2pp. 45257:215-45257:216.
- 8804250292 Advises that 870721 Rev 5 to updated FSAR & 880321 clarifications meets requirements of 10CFR50,App B & acceptable NRC understands that clarifications will be incorporated into Rev 5 of QA program description. CALLAN,U. J. Region 4, Ofc of the Director. 88/04/15. WILLIAMS,R.O. Public Service Co. of Colorado. 2pp. 45258:223-45258:224.
- 8804250091 Confirms NRC request to move resident inspector ofc within plant protected area boundary Understands that move can be made by end of May 1988. CALLAN, L. J. Region 4, Oic of the Director, 88/04/18. WILLIAMS,R.O. Public Service Co. of Colorado. 1p. 46231:071-45231:071.

- 8804280271 Forwards Rev 1 to EGC-NTA-7356, "Technical Evaluation Rept for Conformance to NRR Generic Lits 83:36 & 83-37 by Fort Saint Vrain Nuclear Generating Station." Meeting wit be arranged within next 60 days to resolve issues. HEITNER, K. L. Project Directorate IV. 88/04/19. WILLIAMS, R.O. Public Service Co. of Colorado. 4pp. 45264 001-45264.048
- --8604280387 Rev 1 to "Technical Evaluation Rept for Conformance to NRR Generic Lis 83:38 8 83:37 by Fort St Vigin Nuclear Generating Station," Informal rept STACHEW.J.C EGS Ideho, Inc. (subs. of EG&G, Inc.). FIN 0-6023. EGG.NTA-7356 RD1. 88/02/29, NRC No Detailed Affiliation Given. 25pp. 45264:008-45264:048.

Q. Inspection reports, IE Bulletins & correspondence

- 8803300350 Forwards into prepared to assist in closing out open items resulting from thisp Rept 50-267/87-12 & info re corrective actions discussed in LER 85-029.Cold checkout tests, functional tests & specific surveitance tests enci. BREY.H.L. Public Service Co of Colorado, 88/03/18 Document Control Branch (Document Control Desk) 2pp. 44979:187-44992-206
- -8803300355 Issue 3 to Procedure TASMAP-7, "Work Review Committee Guidelines." Public Service Co. of Cotorado. 88/01/10, 262pp. 44979:189-44980:115.
- -8803300383 Issue 5 to Procedure SH 5 3 4bt A "Loop I Shuldown Cooling Power Operated Valve Test."
 • Public Service Co. at Colorado, 87/12/31, 114pp. 44980:118-44980:229
- -8803300381 Issue 5 to Procedure SR 5.3.452-A, "Loop II Sale Shuldown Cooling Power Operated Volve Teets." Public Service Co. of Colorado 86/03/05, 108pp. 44980:230-44980:336.
- ~8803300411 Issue 1 to Procedure SR 5.4.1.3.8 abod R2, "Steam Line Rupture Detection/Isotation Sys (StADIS) Calibr & Tosting for Panel 1-93544."

 * Public Service Co. of Colorado 87/03/20, 287pp. 44980;337-44981;273.
- --8803300417 Issue 1 to Procedure SR 5.4.1.3.8 abcd-R1, "Steam Line Rupture Detection/Iscitation Sys (StRDIS) Calibr & Testing for Panel 1-93543."

 * Public Service Co. of Coforado. 88/03/18, 273pp. 44981:274-44982:208.
- 8803210090 Suppl 1 to NAC Into Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactions" Svc 48t enct.
 ROSSIC.E. Division of Operational Events Assessment (Post 870411). 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44895-126-44895-246.
- 8803220296 NRC Into Notice 86-010, "Matts Licensees Lack of Mgt Controls Over Licensed Programs." Svc list encl CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03728. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.
- 8804060482 Ack receipt of 880311 response to NRC 880203 notice of violation noted in finsp Rept 50-267/87-34 implementation of corrective actions will be reviewed during future insp to determine that full compitance acti
- 8804070227 Ack receipt of 880211 response to 880115 violation noted in Insp Rept 50-287/87-25.
 CALLAN,L.J. Region 4, Oic of the Director. 88/03/29, Will. IAMS,R.O. Public Service Co. of Colorado. 2pp. 45029.345-45029.349.
- 8804070320 Responds to IE Bullotin 88-001 re Wastinghouse DS/DSL circuit breakers Ret compansats not utilized at facility.
 WILLIAMS,R.O. Public Service Co. of Colorado, 88/03/30. Document Control Branch (Document Control Desk), 2pp. 45021:231-45021;232.
- 8804040230 Forwards Insp Rept 50-267/88-03 on 860201-29. Violations noted Actions taken in response to previously Identified violations also examined & discussed in Paragraph 2 of rept.
 CALLAN,L.J. Region 4, Ofc of the Director, 88/03/31, WILLIAMS,R.O. Public Service
 Co. of Colorado, 2pp. 45075.323-45075.338
- -8804040234 Notice of violation from insp on 880201-29. Violation noted: on 880202, cables on speed controls of helium circulators interchanged w/o implementa-tion of administrativa controls & on 880210 wrong valves opened, vanting radioactive
- gas. Region 4, Olc of the Director. 89/03/31, 2pp. 45075:325-45075;326.
- --8804040236 Insp Riept 50-267/88-03 on 880201-29. Violations noted Major areas inspected ficensee action on praylously identified findings operational safety varication followup of unusual events ESF walkdown & physical security observation. FARRELL, R.E., Michaudy, P.W. WESTERMAN, T.F. Region 4, Ofc of the Director, 88/03/25, 12pp, 45075-327-45075-338.
- 8804120128 Forwards Insp Rept 50-267/88-04 on 880222-26.No violations or deviatrons noted CALLAN,L.J. Region 4, Ofc of the Director, 88/04/05, WILLIAMS,R.O. Public Service Co. of Colorado, 2pp. 45128 288-45128 296.
- **8804120134 Insp. Repl. 50-267/88-04 on 880222-26.No violations or deviations noted Major areas inspected fire protection/ prevention program & implementation. SINGH,A. Hil DEBRAND,E.P., IRELAND,R.E. Region 4, Ofc of the Director. 88/03/30. 7pp. 46128-290-45128-296.
- 8804010256 NRC Into Notice 88 011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faully Tie Bolls." Svc list end. ROSSICE Division of Operational Events Assessment (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 124pp. 45406;292-45407.051.
- 8804060370 NRC Info Notice 88-012. "Overgreasing of Electric Motor Bearings." Svc ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45166:150.
- 8804250118 Forwards Insp Ropt 50-267/88-06 on 880228-0304.No violations or devi-ations noted. One unresolved tiem identified in Paragraph 2.d of inspirept. CALLAN, J. Region 4, Oic of the Director, 88/04/18, WILLIAMS,R.O. Public Service Co., of Colorado, 3pp. 45231:289-45231:299.

R. Periodic operating reports & related correspondence

8804190273 Monthly operating rept for Mar 1988-W/880415 ftr. NOVACHEK, F. J., FULLER, C.H. Public Service Co. of Colorado. 88/03/31. 17pp 45215-271-45215-28.

S. Reportable occurrences, LERs & related correspondence

- 6804110265 PNO-IV-88-025:on 880404,following manual reactor scram, unplanned ro-lease of noble gas occurred when reflet valve opened to relieve pressure in vent lin-between the core support floor & waste gas sys. WESTERMAN,TF. Region 4, Ofc of the Director. 88/04/05. 1p. 45128:126
- 8804140043 PNO-IV-88-026:on 880407,unplanned release of 157 mCr noble gat occurred Caused by failure of flexible joint in circulating water pump (CWP) pump presulting in flexible of CWP 8 motors Cooldown Initiated.

 WESTERMAN,T.F. Region 4, Old of the Director, 88/04/07, 2pp. 45147/319 45147:320.
- 8604210394 Summary of Operating Reactors Events Meeting 88-15 on 880412.List of attendees & viowgraphs enc.
 LANNING.W. Division of Operational Events Assessment (Post 870411), 88/04/1!
 ROSSI.C.F. Division of Operational Events Assessment (Post 870411), 20p; 45192:139-45192.158.

V. Operator Examinations

8804120360 Forwards Rev 2 to "Guidance for Development of Simulation Facility I Meet Requirements of 10CFR55.45," adressing resolution of issues from 87120 meeting wTNRC.
KIRBY-MJ. Southern California Edison Co. 88/04/05. Document Control Brand (Occument Control Desk). 2pp. 45088:265-45088.345

-8804120478 Rev 2 to "Guidance for Development of Simulation Facility to Meet Ri-quirements of 10CFR55.45."

* Southern Cationnia Edison Co. * Yankee Atomic Electric Co. 88/03/31, 78p. 45088:267.45088:345.

8804250088 Responds to FOIA request for Info re scores of reactor operators & seni-reactor operators.Forwards requalification exam summary source sheets listed in en-app w/personal privacy info deleted. GHMSLEY.O.H. Division of Rules & Records (Post 870413). 88/04/19. BOLEY.I Public Citizen's Critical Mass Energy Project. 2pp. 45213:003-45213:095.

--8804250 167 Package of NRC administered requalification exam results summery.
'NRC - No Detailed Affiliation Given. 87/07/20, 88pp. 45213.007-45213.095.

DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

C. Utility Environmental Report (ER), amends & correspondence

- 8804040024 Application for amends to Licenses DPR-38,DPR-47 & DPR-55 to perm operation of ISFSI for temporary storage of spent fuel until Federal govt provides permanent storage facilities.Fea paid.

 TUCKER,HB. Duke Power Cp. 88/03/31. Document Control Branch (Document Cotrol Desk). 11pp. 45233:050-45233.195.
- -8804040053 "ISFSI Environ Rept." Duke Power Co. 88/03/31, 215pp. 45233:196-45234:050.

F. Security, medical, emergency & fire protection plans

8804110123 Forwards Rev 24 to plant security plan. Rev developed to detete redundate vital equipment lest wording in security plan 8 in comprehensive manner revise hist vital equipment. Rev 24 withheld (ret 10CFR73.21).

TUCKER, H.B. Duke Power Co. 88704704. Document Control Branch (Document Cottol Desk). 2pp. 45129:226-45129:227.

8804200473 Partial response to FOIA request re fire protection.Forwards App documents App D & E documents available in PDR.App F document completely withheld (ref FOIA Examption 5).
GRIMSLEY.D.H. Division of Rules & Records (Post 870413). 88/04/14. JONES,C. Atfiliation Not Assigned. 5pp. 45206.037-45206 043.

-8804200578 Advises that Fire Protection Steering Committee has recommended th each region make one 10CFR50,App R-type Insp for each facility to assess status compliance w/ 10CFR50.48 Program listed. CONLON,T.E. Region 2, Ofc of the Director. 84/11/06. HERDT,A.R. Region 2, Ofc the Director. 3pp. 45206:176-45206:178.

8804290249 Forwards Revs 88:01 & 88:02 to implementing procedures manual (Vots & C) per 10CFR50 54(a) Revs do not decrease effectiveness of emergency implementing procedures or emergency plan. TUCKER.H.B. Duke Power Co. 88/04/21. Document Control Branch (Document Cotrol Desb.) 2pp. 45282:112-45282:170.

--8804290274 Revised emergency plan Implementing procedures Including rev to Proc dure CP/182/A/2002/05, "Post Accident Caustic... Sys," Procedure RP/O/B/100 03, "Natt" & Procedure RP/O/B/1000/04, "Sile Area Emergency." * Duke Power Co. 89/03/31, 49pp. 45282,114,45282;170,



I. Financial information

- 8804040024 Application for amonds to Licenses DPR-38,DPR-47 & DPR-55 to permit operation of ISFSI for temporary storage of spent fuel until Federal govt providos permanent storage facilities Fee pard TUCKER.H B Duke Power Co. 88/03/31 Document Control Branch (Document Control Desk) 11pp 45233 050-45233:195
- --8804040050 "Duke Power Co Annual Rept 1987." LEE W.S., BOOTH,D.W. Duke Power Co. 87/12/31, 101pp. 44999.093-44999.193.

P. Operating license stage documents & correspondence

- 8803 100068 Summary of 880301 meeting w/util in Rockville,MD re ISAP II described in Generic Ltr 88-02 Attendance list & viewgraphs encl. HOOD,D S Project Directorate II-3, 88/03/07, Project Directorate II-3, 29pp. 44662 083-44662 111.
- 88D3240426 Generic Ltr 88-06 to all power reactor Leensees & applicants re-removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIA, F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972.107-44972.153.
- 8804010042 Forwards listing of outstanding Items,per discussion w/NRC re util ongoing program of reducing backlog of outstanding Items,W/o oncl. BHOWNLEE,V.L. Regron 2, Otc of the Director. 88/03/23 TUCKER,H B. Duke Power Co. 1p 45031171.45031171.
- 8804120317 Expresses appreciation for time that members took to present outline of ISAP II program per Generic Lit 88-02 requesting Ecensee to evaluate NRC latest rev & indicate whether interested in participating in program TUCKER/HB. Duke Power Co. 88/03/25, Document Control Branch (Document Control Desk) 2pp. 45091.142-45091:143.
- 8804040024 Application for amonds to Liconsos DPR-38,DPR-47 & DPR-55 to permit operation of ISFSI for temporary storage of spent fuel until Foderal govt provides permanent storage facilities Fee paid.

 TUCKER,H.B. Duke Power Co. 88/03/31, Document Control Branch (Document Control Desk), 11pp. 45233 050-45233;195.
- --8804040025 Proposed Tech Specs re-spent fuel storage facility.
 Duke Power Co. 88/03/31 7pp 45233.060-45233.067
- --8804040059 "ISFSI SAR." * Duko Power Co. 88/03/31, 265pp. 45234.051-45234:315.
- 8804050403 Notifies that ut1 870814 application to revise Tech Specs ro uppor surgo tank level & emergency flow vs time unsuitable for processing. No technical justification or NSHC determination provided HOOD, D.S. Project Directorate II-3 88/03/31, TUCKER, H.B. Duke Power Co. 2pp 45003 334-45009.335
- 8804080172 Forwards SSER NUHEG-1231 re B&W Owners Group plant reassessment program. Overall evaluation remains favorable. Addi improvement in area of integrated control sys/ non-nuclear instrumentation sys review possible W/o enct. CHUTCHFIELD, Division of Reactor Projects III,IV,V & Special Projects (Post 870411), 88/03/31. WILGUS,W.S. Babcock & Wilcox Operating Plants Owners Group. WILGUS,W.S. Florida Power Corp. (subs. of Ficritial Progress Corp.), 7pp. 45076:181-45076:187.
- 8604080086 Generic Ltr 88.07 to power reactor licensees & applicants re-modified enforcement pokey concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Imperiant to Safety for Nuclear Power Plants." Svc list encl. MIRAGUA F. J. Associate Director for Projects (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804210350 Forwards notice of consideration of Issuance of amends to Licenses DPR-38,DPR-47 & DPR-55 & opportunity for hearing on 880106 request to revise Tach Specs re control room habitability. PASTIS,H N Project Directorate II-3. 88/04/15. TUCKER,H.8. Duke Power Co. 2pp 45192-163-45192-175.
- --8804210352 Notice of consideration of Issuance of amend to Licenses DPR-38,DPR-47 & DPR-55 & opportunity for hearing Amend revises Tech Spacs re-control room habitability.
 CROCKER.L.P. Project Directorate II-3, 88/04/13, 11pp. 45192,165-45192;175.

O. Inspection reports, IE Bulletins & correspondence

- 8803160322 Forwards Exam Rept 60-269/OI.-87-03 of exam administered on 871214 for Units 1,2 & 3. JULIAN,C.A. Region 2, Otc of the Director. 88/02/19, TUCKER,H.B. Duke Power Co. 2pp. 44705:027-44705:099.
- -8603160337 Exam Rept 50.269/QL-87-03 on 871214 for Units 1,2 & 3 Exam results:all candidates passed written reexams. DEAN,W.M. Region 2, Otc of the Director, 88/02/18, 139pp, 44705.029-44705.099.
- 8803250321 Forwards addi Info re open Items identified during environ qualification team insp on 880222-26. Design engineering personnel demonstrated methodology to determine similarity of installed vs tested equipment. TUCKER, H.B. Duke Power Co. 88/03/09. GRACE, J.N. Region 2, Ofc of the Director. 4pp. 44945:220.44946:223.
- 8803310278 Forwards Insp Repts 50-289/88-07.50-270/88-07 & 60-287/88-07 on 880307-11.Ng violations or deviations noted. HERDT.A.R. Region 2, Otc of the Director, 88/03/25. TUCKER,H.B. Duke Power Co. 2pp. 4976:159-4976:172.
- ••8603310280 Insp. Ropts 50-269/68-07,50-270/88-07 & 50-287/68-07 on 860307-11.No violations or deviations noted.Major ereas inspected inservice Insp. including NDE procedure review, exam data review & personnel certification records review. NEWSOME.R.W., BLAKE,J.J. Region 2, Ofc of the Director. 88/03/23, 12pp. 44976-161-44976-172.

- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Westinghouso Reactors." Svc list encl.
 ROSSI.CE Division of Operational Events Assessment (Post 870411), 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44095-126-44995-246
- 8803220296 NRC Info Notice 88:010, "Matts Licensees.Lack of Mgt Controls Over Licensed Programs." Svc 1st end: CUNNINGITAM.RE Drusson of Industrial & Medical Nuclear Safety (Post 870729) 887 03/28 Consolidated Edison Co. of New York, Inc. 108pp 44995:247-44995:353.
- 8804110331 Forwards tac his reactor bidg tendon surveillance rept submitted to fulfill requirements of Tech Spac 4.4.2 reitendon inservice insp.
 TUCKER,H.B. Duke Power Co. 88/03/28. Document Control Branch (Document Control Desk). 18pp. 45077:285-45077:312.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switchboard Function Due to Faulty Tie Botts," Svalistienci. ROSSI.CE Division of Operational Events Assessment (Post 870411), 88/04/07, Cons
- 8804060370 NRC Info Notice 88-012. "Overgreasing of Electric Motor Bearings." Svolist end. ROSSI.C.E. Division of Operational Evants Assessment (Post 870411) 88/04/12 Consolkfated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150.
- 8804200473 Parilal response to FOIA request re fire protection.Forwards App E documents App D & E documents available in PDR App F document completely withhold (rol FOIA Exemplion 5).
 GRIMSLEY.D H. Divson of Rules & Records (Post 870413). 88/04/14. JONES,C.R. Afficiation Not Assigned. 5pp 45206.037-45208.043.
- --8804200579 Advises that Fire Protection Stocking Committee has recommended that each region make one 10CFR50.App R-type inspiror each facility to assess status of comphance w/ 10CFR50.49 Program isted CONLON.TE. Region 2, Old of the Director. 84/11/08. HERDT,A.R. Region 2, Old of the Director. 3pp. 45206 176-45206.178.

R. Periodic operating reports & related correspondence

- 8804200152 Monthly operating repts for Mar 1988,W/880415 ltr. REAVIS,J.A., TUCKER,H.B. Ouko Power Co. 88/03/31, 17pp. 45215.343-45215.359.
- S. Reportable occurrences, LERs & related correspondence
- 8804080145 LER 87-001-01:on 870119.feiture to comply with inservice hisp program on PALS sys identified Caused by inadequate turnover of program requirements/ responsibilities Chemistry section provided w/specific training W/880031 ltr. NORTH, P.J., TUCKER, H.B. Duke Power Co. 88/03/31, 5pp. 45100.092-45100.096.
- 8804180256 LEH 88-004-00 on 890222,emergoncy power switching logic retransfer to startup togic defeated Caused by design deficiency due to lack of consideration of human factors. Separate procedure re breakers to be developed W/880408 in. NORTH,P.J., TUCKER,H.B. Duke Power Co. 88/04/06. 9pp. 45183 213-45183:221.
- 8804260231 LER 87-011-01 on 871202,cable Room 3 sprinkler sys Inoperable Caused by design deficiency. Fire watches established until water spray sys operable & sys restored W/880418 It?
 NORTH,P.J., TUCKER,H.B. Duke Power Co. 88/04/19, 17pp. 45252:308-45252:324.

V. Operator Examinations

- 8803160322 Forwards Exam Rept 50-269/OL-87-03 of exam administered on 871214 for Units 1,2 & 3. JULIAN, C.A. Region 2, Otc of the Director, 88/02/19, TUCKER,H.B. Duke Power Co. 2pp 44705-027-44705:099.
- --8803180337 Exam Rept 50-269/OL-87-03 on 871214 for Units 1,2 & 3.Exam results all candidates passed written reoxams.
 DEAN,W.M., BROCKMAN,K.E. Region 2, Ofc of the Director. 88/02/18, 139pp. 44705/029-44705.099.
- --8803310070 Forwards comments concerning writton exam given to plants operators on 871214.Comments divided according to type of test administered wycross ref to redundant questions to assist examinors grading exams. TUCKMAN,M.S. Duke Power Co. 87/12/18. MUNRO,J. Region 2, Ofc of the Director. 20pp. 44968.333-44966.352.
- 8804250088 Responds to FOIA request for into re-scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in encl app w/personal privacy into deleted GRIMSLEY.D.H. Division of Rules & Records (Post 870413). 88/04/19, BOLEY,K. Public Cilizen's Chical Mass Energy Project. 2pp. 45213:003-45213.095
- --8804250167 Package of NRC administered requalification exam results summary.

 * NRC No Detailed Affiliation Given, 87/07/20, 88pp. 46213.007-45213.095.

Y. Dry Cask Independent Spent Fuel Storage Installations

- 8804130203 Notification of 861218 meeting w/utit in Silver Spring.MD to discuss util plans for expansion of spent fuel storage facilities under 10CFR72 & Oconee Nuclear Station.List of attendedos & agende encl.
 ROBERTS.J.P. Advanced Fuel & Spent Fuel Licensing Branch 67/01/07.
 ROUSE L.C. Advanced Fuel & Spent Fuel Licensing Branch 10pp. 45101:202-
- 8804040024 Application for amends to Licenses DPR-38,DPR-47 & DPR-55 to permit operation of ISFSI for temporary storage of spent fuel until Federal govt provides permanent storage facilities, Fee paid.
 TUCKER,H.B. Duke Power Co. 88/03/31. Document Control Branch (Document Control Desk). 11pp. 45233;050-45233:195

- ~8804040029 Forwards application to construct & operate ISFSI for temporary storage of sport fuel per 10CFR12 SAR & environ rept also encifee pard.
 TUCKER.HB Duke Power Co. 88/09/31. Office of Nuclear Material Safety & Safeguards, Director. 5pp. 45233-068-45233-195.
- -8804040049 Application for license to construct & operate dry cask ISFSI at Oconee Nuclear Station.
 * Ouke Power Co. 88/03/31, 23pp. 45233.073-45233.195

- -8804040050 "Duke Power Co Annual Rept 1987." LEE W.S., BOOTH.D.W. Duke Power Co. 87/12/31, 101pp. 44999 093-44999:193.
- -8804040053 "ISFSI Environ Rept." * Duke Power Co. 88/03/31. 215pp. 45233.196 45234 050.
- -8804040059 "ISFSI SAR." Duke Power Co. 88/03/31. 265pp. 45234-051-45234-315

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

C. Utility Environmental Report (ER), amends & correspondence

- 8804040024 Application for amends to Licenses DPR-38,DPR-47-8 DPR-55 to permit operation of ISFSI for temporary storage of spont fuel until Foderal govt provides permanent storage facilities Fee paid.
 TUCKER_H.B. Duke Power Co. 88/03/31. Document Control Branch (Document Control Desk). 11pp. 45233 050-45233 195.
- --8804040053 "ISFS) Environ Rept."
 ' Ouke Power Co. 88/03/31, 215pp 45233, 196-45234:050.

F. Security, medical, emergency & fire protection plans

- 8804110123 Forwards Rev. 24 to plant security plan Rev. developed to detete redundant vital equipment test wording in security plan 8 in comprehensive manner reviso list of vital equipment Rev. 24 withhald (ref. 10CFR73.21).
 TUCKER,H.B. Duke Power Co. 88/04/04. Document Control Branch (Document Control Desk), 2pp. 45129-226-45129-227.
- 880420473 Partial response to FOIA request is fig protection Forwards App E documents App D & E documents available in PDR.App F document completely with-tield (ret FOIA Exemption 5).

 GRIMSLEY.D.H. Division of Rules & Records (Post 870413). 88/04/14. JONES,C R. Affiliation Not Assigned. Spp. 45206.037-45206.043.
- -8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50, App R-type insp for each facility to assess status of compliance w/ 10CFR50 48 Program Issted.
 CONLON,T.E. Region 2, Off of the Director. 84/11/06 HERDT, A.R. Region 2, Ofc of the Director. 3pp. 45206:176. 45206:178.
- 8804290249 Forwards Revs 88-01 & 88-02 to imprementing procedures manual (Vols B & CI per 10CFR50.54(q) Revs do not decroaso affectiveness of emergency implementing procedures or emergency plan. 1UCKER.H.B. Ouks Power Co. 88/04/21, Document Control Branch (Document Control Desk), 2pp. 45282:112-45292:170.
- --8804290274 Revised emergency plan implementing procedures including revito Procedure CP/182/A/2002/05, "Post-Accident Caustic. Sys," Procedure RP/O/B/1000/03, "Alert" & Procedure RP/O/B/1000/04, "Stia Area Emergency," "Duke Power Co. 88/03/31, 48pp. 45282:114.45282:170.

I. Financial Information

- 8804040024 Application for amends to Licenses DPR-38, DPR-47 & DPR-55 to permit operation of ISFS) for temporary storage of spent final until Federal govi provides permanent storage facilities Feb paid. TUCKER-HB Duke Power Co. 887/03/31. Document Control Desk). 11pp. 45233.050-45233:195.
- ~8804040050 "Duke Power Co Annual Rept 1987." LEE W.S., BOOTH,D.W. Duke Power Co. 87/12/31, 101pp. 44999.093.44999.193,

P. Operating ficense stage documents & correspondence

- 8803100068 Summary of 680301 moeting w/util in Rockville,MD re ISAP II described in Goneric Lir 88-92 Attendance list & viowgraphs encl. Project Directorate II-3. 88/03/07. Project Directorate II-3. 88/03/07. Project Directorate II-3. 29pp. 44662 083-44662-111.
- 8803240426 Generic Ltr 68-06 to all power reactor because & applicants re-removal of organization charts from Tech Spec administrative control requirements Svc list encl. MRAGLIA-5 J. Associate Director for Pajects (Post 870411): 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972.107-44972:153.
- 8804010042 Forwards listing of outstanding items,per discussion w/NRC re util ongoing program of reducing backlog of outstanding items.W/o encl. BROWNLES.V.E. Region 2, Orc of the Director. 88/03/23: TUCKER,H.B. Duke Power Co. Lp 45031;171-45031;171.
- 8804120317 Expresses appreciation for time that members took to present outline of ISAP if program per Generic Ltr 88-02 requesting licensee to evaluate NRC latest rev & indicate whether interested in participating in program. TUCKER,H.B. Duke Power Co. 88/03/25, Document Control Branch (Document Control Desk). 2pp. 45091:142-45091:143.
- 8804040024 Application for amends to Licenses DPR-38,DPR-47 & DPR-55 to permit operation of ISFSI for temporary storage of spent fuel until Federal govi provides permanent storage facilities Fee pald. TuCKER,H.B. Duke Power Co. 86/03/31. Document Control Branch (Document Control Dask). 11pp. 45233.050-45233:195.

- --8804040025 Proposed Tech Specs re spent fuel storage facility.
 * Duke Power Co. 88/03/31, 7pp. 45233.060-45233.087.
- --8804040059 "ISFSI SAR." * Duke Power Co. 88/03/31, 265pp. 45234:051-45234:316.
- 8804050403 Notifies that util 870814 application to revise Tech Specs re upper surger tank level & emergency flow vs time unsuitable for processing No technical justication or NSHC determination provided. BOOD DES Project Directorate II-3, 88/03/31, TUCKER,H.B. Duke Power Co. 2pp. 45099-334-45009-335.
- 8804080172 Forwards SSER NUREG-1231 re 8&W Owners Group plant reassessment program. Overall evaluation remains (avorable, Add) improvement in area of integrated control syst non-nuclear instrumentation sys review possible W/o encl. CRUTCHFIELD.D. Division of Reactor Projects III, IV, V. & Special Projects (Post 870411), 88/03731, WILGUS, W.S. Babcock & Wilcox Operating Plants Owners Group 7pp. 45076:181-45076:187.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Syc list enct. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidate Edison Co. of New York, Inc. 48pp. 45164;237-45164;285.
- 8804190102 Confirms that conditions of 870410 & 0819 confirmatory orders have been met & restrictions imposed by order have been lifted. Plant flow pressure injection & reactor bidg cooling unit cleaned & tested.

 GRACE_J.N. Region 2, Oic of the Director. 88/04/08. TUCKER, H.B. Duke Power Co 2pp. 45153.346-45153:347.
- 8904200536 Provides Info re once through steam generators (OTSG) Steam generator plugging for end of Cyclo 9 outage completed on 880320,OTSG A had 13 fubes re moved from svc by plugging & OTSG B had 20 tubes removed.
 TUCKER,H.B. Duke Power Co. 88/04/13, Document Control Branch (Document Control Desk), 1p. 45238:294-45238:294.
- 8804210350 Forwards notice of consideration of issuance of amends to Licanses CPR-38,DPR-47 & DPR-55 & opportunity for hearing on 880108 request to revise Tech Specs re-control room habiliability. PASTIS,H.N Project Directorate II-3. 88/04/15. TUCKER,H.B. Duke Power Co. 200 45192:163-45192:176.
- --8804210352 Notice of consideration of Issuance of amend to Licenses DPH-38,DPR-47 & DPR-55 & opportunity for hearing Amend revises Tech Specs re control room 47 & DFR-93 & Opportunity for Industry 1887 April 2015 April 2015

Q. Inspection reports, IE Bulletins & correspondence

- 8603160322 Forwards Exam Rept 50-269/OL-87-03 of exam administered on 871214 for Units 1,2 & 3.
 JULIAN,C A. Region 2, Olo of the Director. 88/02/19. TUCKER,H.B. Duke Power Co 2pp. 44705:027-44705:099.
- --8803160337 Exam Rept 50-269/OL-87-03 on 871214 for Units 1,2 & 3.Exam results all candidates passed written reexams.
 DEAN,W.M. Region 2, Ofc of the Director. 88/02/18. 139pp. 44705:029-44705:039
- 8803250321 Forwards addi into re open items identified during environ qualification team insp on 880222-26.Design engineering personnel demonstrated methodology to determine similarity of Installed vs tested equipment.

 TUCKER,H.B. Duke Power Co. 88/03/09. GRACE,J.N. Region 2, Otc of the Director. 4pp. 44945;220-44945;223.
- 8803310278 Forwards Insp. Repts 50-269/88-07,50-270/68-07 & 50-287/88-07 ch 880307-11.No violations or deviations noted. HERDT, A.R. Region 2, Otc of the Director. 88/03/25. TUCKER,H.B. Duke Power Co. 2pp. 44978-168-44976
- -8803310280 Insp Repts 50-269/88-07.50-270/88-07 & 50-287/88-07 on 860307-11.No violations or deviations noted Major areas Inspected inservice insp including NDE procedure eview, exam data review & personnel certification records review. NEWSOME,RW., BLAKE,J.J. Region 2, Ofc of the Director, 88/03/23, 12pp 44976:161-44976:172.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svo list enci. ROSSI.CE. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995;246.
- 8803220298 NRC Info Notice 88.010, "Matts Ucensees:Lack of Mgt Controls Over Ucensed Programs." Svo list encl. CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Salety (Post 870729). 897 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44895:247-44995:353.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/cr Switch-board Function Due to Faulty Tie Botts," Syc iist encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407:051.
- 8604060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list enci. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165;150.
- 8804200473 Partial response to FOIA request re fire protection.Forwards App E documents App D & E documents available in PDR.App F document completely withheld (ref FOIA Exemption 5), GRIMSLEY, D.H. Division of Rules & Records (Post 870413), 88/04/14, JONES.C.R. Affiliation Not Assigned, 5pp. 45206:037-45206:043.

49

- -8804200579 Advises that Fire Protection Steering Committee his recommended that each region make one 10CFR50.App R-type insplict each facility to assess status of compliance w/ 10CFR50.48 Program Insted CONLON.T.E. Region 2, Of of the Director. 84/11/06 HERDT, A.R. Region 2, Of of the Director. 3pp. 45206 176-45206 178.
- R. Periodic operating reports & related correspondence
- BB04200152 Monthly operating ropts for Mar 1988 W/880415 ltr.
 REAVIS,J.A., TUCKER,H.B. Duke Power Co. 88/03/31, 17pp. 45215.343-45215.359
- S. Reportable occurrences, LERs & related correspondence
- 8803300087 LER 88-001-00.on 880215,brace used to help secure printed circuit boards in vital power inverter discovered missing during preventive maint procedure Caused by design deficiency New brace febricated & Installed W/680323 ltr. NORTH,PU., TUCKER,H B. Duke Power Co. 66/03/23 8pp. 44916.312-44916.319.
- V. Operator Examinations
- 8603160322 Forwards Exam Rept 50 269/OL-87-03 of exam administered on 871214 Tor Unis 1,2 & 3 JULIAN,C A Region 2, Ofc of the Director, 88/02/19, TUCKER,H B. Ouke Power Co. 2pp. 44705 027-44705:099.
- -8803160337 Exam Rept 50-269/OL-87-03 on 871214 for Units 1,2 & 3 Exam results.all Candidales passed writton reexams
 DEAN,W M , BROCKMAN,K.E. Region 2, Old of the Director, 88/02/18, 139pp. 44705/029-44705.099.
- --8803310070 Forwards comments concerning written exam given to plants operators on 871214. Comments divided according to type of test administered w/cross ref to redundant questions to assist examiners grading exams TUCKMAN S. Duke Power Co. 87712/18. MUNRO, J. Region 2, Old of the Director. 20pp. 44966-333-44966-352.
- 8804250088 Responds to FOIA request for info re-scores of reactor operators & senior reactor operators Forwards requalification exem summary source sheets listed in encl app w/personal privacy info deleted GRIMSLEY.DH. Drwston of Rules & Records (Post 870413). 88/04/19 BOLEY.K. Public Citizen's Critical Mass Energy Project. 2pp. 45213 003-45213 095
- -8804250167 Package of NRC administered requalification exam results summary.
 NRC No Detailed Affiliation Given, 67/07/20, 88pp. 45213:007-45213:095.

Y. Dry Cask Independent Spent Fuel Storage Installations

- 6804130203 Notification of 861218 meeting w/util in Stivot Spring,MD to thiscuse util plans for expansion of spent fuel storage facilities under 10CFR72 & Oconee Nuclear Station List of attendees & agenda encil ROBERTS,J.P. Advanced Fuel & Spont Fuel Licensing Branch 87/01/07, RCUSE,L.C. Advanced Fuel & Spent Fuel Licensing Branch 10pp, 45101:202-45101.211
- 8804040024 Application for amends to Licenses DPR-38,DPR-47 & DPR-55 to permit operation of ISFSI for temporary storage of spent fuel until Federal govt provides permanent storage feditios. Fee paid: TUCKER,H B: Duke Power Co. 88/03/31. Document Control Dask) 11pp 45233.050-45233:195.
- 8804040025 Proposed Tech Specs respont fuel storage facility.
 Duke Power Co. 88/03/31, 7pp. 45233:060-45233:087.
- ~8804040029 Forwards application to construct & operate ISFSI for temporary storage of spent fuel.per 10CFR72.SAR & environ rept also and Fee pald. TUCKER,IHB Duke Power Co 88/03/31. Office of Nuclear Material Safety & Safeguards.Director. 5pp 45233:068-45233:195.
- -8804040049 Application for license to construct & operate dry cask ISFSI at Oconeo Nuclear Station
- Duke Power Co. 88/03/31, 23pp. 45233.073-45233:195.
- -8804040053 "ISFSI Environ Rept." Duke Power Co. 88/03/31, 215pp. 45233;196-45234;050,
- --8804040059 "ISFSI SAR,"
 Duka Power Co. 68/03/31, 265pp, 45234,051-45234;316.

DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

F. Security, medical, emergency & fire protection plans

- 8804070061 Revised emergency plan implementing procedures including Rev 8 to OP 3501, "Alert," Rev 20 to OP 3502, "Site Area Emergency," Rev 22 to OP 3503, "General Emergency" & Rev 9 to OP 3530, "Post-Accident Sampling." Yankee Atomic Electric Co. 88/03/28, 116pp 45021;290-45022.045.
- 8804120182 Forwards Insp. Rept 50:271/88-03 on 880209-0321 & notice of violation. WIGGINS,J.T. Region 1, Ofc of the Director. 88/04/01. MURPHY,W.P. Vermont Yankee Nuclear Power Corp. 2pp 45132:110-45132:134.
- --9804120190 Insp Rept 50-271/68-03 on 880209-0321. Vipilations noted. Major ereas inspected actions on previous findings, routine plant operations, physical security, operational events, maint activities & licensee response to NRC initiatives. HAVERIKAMP.D.R. Region 1. Ofc of the Director. 88/04/05. 22pp. 45132:113-45132:134.
- 8804130132 Forwards Insp Rept 50-271/88-04 on 880208-11 & notice of violation. JOHNSTON,W.V. Region 1, Oic of the Director. 88/04/06. MURPHY,W.P. Vermont Yankee Nuclear Power Corp. 2pp. 45131:006-45131:028.

- --8804130140 Notice of violation from inspired 880208-11.Violation noted emergency lighting units wift-in tattery power not provided in safe shuldown areas 8 access 8 egress routed in control recomportheast section of torus callwalk & Fire Area R8-5 * Region 1, Ofc of the Orector 88/04/06 ip 45131 000-45131.008
- -8804130142 Insp. Rept. 50-271/88-04 on 880208-11.Violations noted Major areas inspected trensee affort to comply w/10CFR50.App R/requirements re-life protection features to ensure obirity to achieve & maintain safe shutdown. KRASOPOULOS,A. Region 1. Oto of the Director. 88/04/01. 18pp. 45131:009-45131 026

G. Adjudicatory correspondence

- 8804180025 NRC Stall motion for further extension of time in which to respond to State of VT & Commonwealth of VA pertitions to intervene. Extension for fling until 880506 requested in order to sollle concerns w/o hearing, W/Cortificate of Svc. HODGDON A P. Assistant Gorerat Counsel for Hearings. #280-6048-88/04/06 Atomic Safety and Licensing Beard Panel. 5pp. 45127-239-45127-243.
- 8804180122 NRC Staff motion for further extension of time in which to respond to State of VT polition to intervene * Extension until 880505 to respond to 880225 petition requested Granted for ASLB on 880407 Wiconflicate of Svc Served on 880411. HIDDGDON.A.P. Assistant Goneral Counsel for Holdings #288 6053. 88/04/06. Atomic Safety and Licensing Board Panel 4pp 45127.157-45127.160.

J. Insurance & Indemnity Information

- 6804040122 Forwards rept re nuclear property insurance coverage per CAPSTICK,R.W Vermont Yankee Nuclear Power Corp. 88/03/29. Decument Control Branch (Document Cont
- P. Operating license stage documents & correspondence
- 880324D426 Generic Ltr 88.06 to all power reactor licenseus & applicants re removal of organization charts from Tech Spoc administrative control requirements. Svc Lst encl MIRAGLIA, F. J. Associate Director for Projects (Post 870411) 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972.107.44972.153.
- 8804120256 Notification of 880413 meeting w/util in Rockwio,MD to discuss concept of astablishing low level waste disposal facility on site ROONEY,VL. Project Discotate 1-3, 88/04/05 WESSMAN,R H. Project Discotate 1-3, 4pp. 45089.288-45089.272.
- 8804090088 Generic Ltr 88 07 to power reactor licensens & applicants re-modified en-tercement policy concenting 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Piants." Svc list encl. MIRAGUA,F. J. Associate Director for Projects (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164.237-45164.285.
- 8804130029 Forwards summary & agenda of 871208 ingt meeting in Region I re util initiatives.plans & prigrities at plant WIGGINS,J.T. Region 1, Old of the Director 88/04/07, MURPHY,W.P. Vermont Yankee Nuclear Power Carp 8pp. 45137;112-45137;117.
- 8804210010 Forwards YAEC-1363, "CASMO-36 Validation." Rept entitled "Simulate-3 Validation & Verification" will be submitted by 680701. Schodule for submission of plant-specific repts to subj repts stated Foe paid.
 PAPANICG Yankee Atomic Electric Co. 88/04/11. Document Control Branch (Document Control Desk). 2pp. 45216 074-45216 174.
- 8804270232 Forwards addlinfo in support of Proposed Chango 142 re logic sys func-tional tost intervals.per NRC 880315 request. Info re equipment relay reliability encl. CAPSTICK,R W. Vermont Yankee Nuclear Power Corp. 88704/13. Document Control Branch (Document Control Dosk). 11pp. 45245 258-45245:268.
- 8804280616 Summary of 880413 meeting w/util in Rockvilfe,MD re tow level waste disposal factity. List of attendees & viewgrapits end.

 HODNEY,VIL. Project Directorate 1-3, 88/04/19, Project Directorate 1-3, 10pp. 46285 080-45265 089.

Q. Inspection reports, IE Bulletins & correspondence

- 8804010159 Provides supplemental response to violations noted in hisp Rept 50-2717 86-25. Corrective actions after completion of testing, results will be assessed within 96 h & maint will develop plan to Identity new rel parameters by next test MURPHY.W.P. Vermont Yankes Nuclear Power Corp. 88/03/25 Document Control Branch (Document Control Desk). 4pp. 45020 031-45020:034.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Roactors." Svc hat onct. ROSSLC.E. Division of Operational Events Assessment (Post 870411), 68/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees Lack of Mgt Controls Over Licensed Programs." Svc list enct.
 CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 887
 03728, Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804010164 Responds to NRC 880222 fit re violations noted in Insp Rept 50-271/87-19.Corrective actions qualification documentation feview package rev in progress,including rev of test rept & upgrade to file as required.

 MURPHY.W.P. Vermont Yankes Nuclear Power Corp. 88/03/28. Document Control Branch (Document Control Desk). 5pp. 45020.017-45020:021.
- 8804120182 Forwards Insp Rept 50-271/88-03 on 880209-0321 & notice of violation. WIGGINS,J.T. Region 1, Old of the Director. 88/04/01 MURPHY,W.P. Vermont Yankee Nuclear Power Corp. 2pp. 45132:110-45132:134

- #884120187 https://disabon.from.insp.on/88020940321 Violation noted Svc. water effect radiation monitor inoperable & required grab sampling not accomplished * Pegicn 1: 01: of the Oseotor 188104701 10 45132 112-45132 112
- #804120190 into Rect 50-211/88-03 on 880209-0321 Violations noted. Major areas inspected actors on previous findings routine plant operations, physical security operational events maint activities & Ticensea response to NRC initiatives. HAPER MAIND PROPRINT OCCUPATION OF the Divertor 88/04/05 22pp 45132 113-4510-249.
- 8604130035 Summarizes 880224 mgl meeting in Region I to discuss various initiatives implemented in response to NRC SALP rept recommendations maint program entrancements & inservice test program initiatives list of attendees & wewpraphs end in 2015.317 Region I, Ora of the Director 88/04705 MURPHY,WP Vermont varkee Nuclear Power Corp. 11pp. 45100.007-45100.017
- 8404130132 Forwards Insp. Rept 50:271/88-04 on 880208-11 & notice of violation JOHNST CN: W.V. Region 1, Ofc of the Director 88/04/06 MURPHY,W.P. Vermont range Nuclear Power Corp. 2pp. 45131-006-45131-026.
- -8804130140 Nobce of violation from inspiron 880208-11 Violation noted lemergency bighting units will in battery power not provided in sale shufdown areas & access & egyess routes in control room northeast section of torus catwalk & Fire Area RB-5 * Region 1, Cfc of the Director 88704706 ↑p. 45131 008-45131 008
- -8804130142 thisp. Rept. 50-271/88-04 on 880208-11 Violations noted Major lareas inspected intensee ethor to comply w/10CFR50.App. R requirements re fire protection features to ensure ability to achieve & maintain safe shutdown. https://doi.org/10.1009/1
- 8804.010256 friRC Info Notice 88-011. Potential Loss of Motor Control Ctr &/or Switch-boad Function Due to Fauth Tile Botts." Sitc hat encl. PIGSEICE Emision of Operational Events Assessment (Post 870411). 88/04/07. Considuated Edison Co. of New York, Inc. 124pp. 45406-292-45407-051.
- 8804 180085 Responds to NRC Bulletin 88-001 re defects in Westinghouse circuit treakers No circuit breakers subjito bulletin used in any application at plant Licensee not considering any future use of crow's breakers SECRPHY, W.P. Vermoort Yarvise Miclear Power Corp. 88/04/08 RUSSELL,W.T. Region 1, Orc of the Overctor 2pp. 45145-352-45145-353.
- 8804060370 NRC Info Notice 88-012. "Overgreasing of Electric Motor Bearings." Svc ist end. POSSICE Dwision of Operational Events Assessment (Post 870411) 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165-150

880446477 Monthly statistical rept for Mar 1988 W/880410 tt.
WALLING A. MURPHY W.P. Vermont Yankee Nuclear Power Corp. 88/03/31, 6pp
45163-248-45163-253.

S. Reportable occurrences, LERs & related correspondence

- 8804060107 LER 68-002 00 on 880301 activation of main steam relief valve above set-port pressure occurred Caused by pilot stage feakage due to steam outs on pilot disc a pilot seat Valve repaired & successitify reflected W/880331 ft. PELLETIERJ P Vermont Yankee Nuclear Power Corp. 88/03/31 4pp 45072.041-
- 8804070068 LIR 88 001-01 on 880211,loss of flow to svc water effluent radiation monitor occurred Caused by design deficiency. Alternate path made available to monitor & pendods surveillance intrated to verify flow W/880401 ftr PELLETIER JP Vermont Yankee httpclast Power Corp. 88/04/01. 6pp 45072.250-
- 8804070748 PNO-188-039 on 880329 uninterruptable power supply (UPS) 8 declared out of the due to blown fuse & falled circuit cards On 880331, valve CS-118 declared incoerable & reactor shutdown initiated Repairs & post-maint of UPS 8 completed GRANT.G. HAYERKAMP.D. Region 1, Dirt. of the Director. 88/04/01. 2pp. 45072.243-45072.241
- \$804200148 LER 88-002-01 on 880301 during tests main steam relief valve 11 activated above setpornt Caused by plot stage leakage due to steam cuts on pilot disc & pilot stage valve reparted and successfully reflected W/880414 till PLETIER JP Vermont Yankee Nuclear Power Corp 88/04/14 4pp 45218.104-

DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8801040036 Forwards Safety Insp. Repts 50-272/88-05.50-311/88-05.50-354/88-02 on 880125-29 No violations or deviations noted.

 BELLAUT: R. R. Repon 1. Otc of the Director. 88/03/24, MCNEILL, C.A. Public Service. Electric & Gas. Co. of New Jersey. 2pp. 45031-305-45031-313.
- 8804040042 insp Repts 50-272/88-05.50-311/88-05 & 50-354/88-02 on 880125-29 No violations deviations or unresolved items noted Major a inspected emergency preparedness program conducted on 880125-29.

 AMATO C.G. Region 1, Oic of the Director, 88/03/11, 7pp. 45031:307-45031:313
- 804050326 Forwards SALP Board Repts 50-272/86-99 & 50-311/86-99 during Oct 1986 Dec 1987 & Rept 50-354/86-99 on 861201-880115 RUSSELL-W T. Region 1, Orc of the Director. 86/03/29 MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 2pp. 45033-282-45034-034.
- -9804090022 SALP Repts 50-272/88-99 & 50-311/88-99 for Oct 1986 Dec 1987, * Region 1, Osc of the Director 88/02/05, 69pp 45033 327-45034 034.

P. Operating license stage documents & correspondence

- 8803240426 Generic Liu 88.06 to all power reactor liconsoos & applicants to removal of programment of removal of an approximation recommends an approximate removal of organization charts from Tech Spec administrative control (organization length of the program of the process (Post 870411), 88/03/22. Conset dated Edison Co. of New York, Inc. 47pp. 44972:107-44972 153.
- 8803310022 Forwards "Reactor Containment Bidg Third/Final Insorvice Integrated Leak Rate Test,First 10.Yr Insp. Intervat & Type B & C Surveillance Tests," per 10.CFR50,App J,Section V.B MILTENBERGER,S. Public Service Electric & Gas Co. of Now Jorsey. 88/03/26. Document Control Branch (Document Control Dosk). 2pp. 44961:108-44961:194
- 8804040100 Requests safety issues mgt sys printout to assist in me'nte'ning curre'l data base of outstanding safety issues in agreement w/NRC into will assist in ident's ing open issues & will facilitate rapid responses to inquirios. MILTENBERGER, S. Public Service Electric & Gas Co. of Now Jorsey, 88/03/25, Decument Control Branch (Document Control Desk), 2pp. 44971 291-44871:292.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFH50.40, "Environ Qualification of Electrical Enuip-ment Important to Safety for Nuclear Power Plants" Svc list oncl MIRAGILA.F.J. Associate Director for Projects (Post 9704.11), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184:237-45184:285.

Q. Inspection reports, IE Builetins & correspondence

- 8802250380 Forwards Safety Insp Repts 50:272/88 04 & 50:311/88:04 on 871221 &
- notice of violation MARTINITT. Region 1, Ofc of the Director, 88/02/22, MCNEILL, C.A. Public Service Electric & Gas Co. of New Jersey, 3pp. 44402:354-44402 350
- 8803390046 Responds to NRC 880222 lit re violations noted in Insp Repts 50-272/88-04 & 50-311/88-04 Corrective actions radwaste shipment procedure revised to more clearly define specific survey locations to be used when surveying truck cab MILTENBERGER, 5-Public Service Electric & Gas Co of Naw Jorsey 88/03/22. Doc-ument Control Branch (Document Control Desk). 3pp. 44945-286-44945:288.
- 8804040036 Forwards Sately Insp Repts 50:272/88-05;60:311/88-05 50:354/88-02 on 880125-29 No violations or deviations noted.

 BELLAMY,R.R. Region 1, OIc of the Director. 88/03/24, MCNEILL,C.A. Public Service Elector & Gas Co. of New Jersey. 2pp. 45031:305-45031.313.
- -8804040042 Insp. Repts 50:272/88-05,60:311/88-05 & 50:354/88-02 on 880125-29 No violations deviations or unresolved items noted Major Breas inspected emergency preparedness program conducted on 860125-29. AMATO.C.G., LAZARUS.W.J. Region 1, Oic of the Director. 86/03/11 7cp. 4501:137-4501:131. 45031.307-45031:313
- 8803310022 Forwards "Reactor Contanment Bldg Third/Final Inservice Integrated Lear Rate Test,First 10-Yr Insp. Interval & Type B & C Surveillance Tests." per 10CFR50.App J.Section V.B. MILTENBERGER.S. Public Service Electric & Gas Co. of New Jorsey. 89/03/25 Doc-ument Control Branch (Document Control Desk). 2pp. 44061;108-44981:194.
- --9803310023 "Reactor Containment Bidg Third/Final Insorvice Integrated Leek Rate TestFirst 10-Yr Insp Interval & Type B & C Surveillance Tests."

 Public Service Electric & Gas Co. of New Jersoy. 87/12/31. 92pp 44981.110 44961:194
- 8804010180 Provides response to concerns raised in trisp Ropts 50-272/87-37 & 50-311/87-37,per 880125 request Corrective action data collection of in-tine monitor vs. Iab results was implemented 880115.

 MILTENBERGER,S. Public Service Electric & Gris Co. of New Jersoy. 88/03/25. Document Control Branch (Document Control Desk). 4pp. 45020:005-45020:008.
- 8804010184 Requests extension of submittel date until 880429 for supplemental response to NRC Compliance Buffetin 87-002 due to delay in receipt of test results. MILTENBERGERS, Public Service Electric & Gas Co. of New Jersey. 88/03/25. RUSSELL.W.T. Regian 1, Old of the Director. 2pp. 45020 008-45020.010.
- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors" Sxc list encl. ROSSIC E. Division of Operational Events Assessment (Poet 870411), 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 88-010, "Mattis Licenseus; Lack of Mgt Controls Over Li-censed Programs," Svc list encl. CUNNINGHAMR & Dwiston of Industrial & Merical Nuclear Safety (Post 870729) 867 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995 353.
- 8804050326 Forwards SALP Board Repts 50:272/86-99 & 50:311/86-99 during Oct 1998 Dec 1987 & Rept 50:354/86-99 on 861201-880115. RUSSELL,W.T. Region 1, Olic of the Director, 88/03/29 MILTENBERGER,S. Public Service Electric & Ges Co. of New Jersey. 2pp. 45033:262-45034.034.
- --8804050334 SALP Rept 50:354/86-98 on 861201-880115. ' Region 1, Otc of the Director, 88/03/04, 63pp. 45033:284-45033:326.
- -8804080022 SALP Repts 50-272/86-99 & 50-311/86-99 for Oct 1986 Dec 1987. * Region 1, Otc of the Oirector, 88/02/05, 69pp, 45033,327-45034,034.
- 8804070315 Responds to NRC Bulletin 88-001 to detects in Westinghouse DS/DSL circuit breakers Plants do not utilize subjicitcuit breakers.

 MILTENBERGER'S, Public Service Efecting & Gas Co. of New Jersey, 88/03/31, Document Control Branch (Document Control Desk), 3pp. 45075:214-45075:216.
- 8804130007 Notification of Licensee Meeting 88-051 on 880414 w/util in Hancocks Bridge,NJ to discuss SALP. SWETLAND,P. Region 1, Ofc of the Director. 88/03/31, Region 1, Ofc of the Director. 2pp. 45098-312-45098-313.

- 8804010256 NRC Info Notice 88-011, "Potential Loss of Malar Central Cir &/or Switchboard Function Due to Faulty Tie Bolts." Svc hist encl. HOSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408:292-45407.051
- 8804130040 Forwards request for addl into re ubl 860527 response to IE Bulletin 85-003, "Motor Operated Valva Switch Settings." Response requested within 30 days WENZINGER.E.C. Region 1, Oic of the Director. 88/04/707, MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersoy. 7pp. 45135.350-45135.35E.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list enct ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/12, Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150.

8804110008 "NPDES Discharge Monitoring Rept for Feb 1988 "
TREJO,J. Public Scruco Electric & Gas Co. of New Jersey, 88/02/29. CAPORALE,G. New Jersey, State of, 26pp. 45072 294-45072.319.

8804190048 Monthly operating rept for Mar 1986 W/880411 ftr.
WHITE,P., RONAFALVY,J., ZUPKO,J.M. Public Service Electric & Gas Co. of New Jersey, 88/03/31, 11pp. 45208:213-45208:223.

S. Reportable occurrences, LERs & related correspondence

- 8804070246 PNO-I-88-038 on 880330 reactor manually tripped following loss of turbine generator hydraulic control oil pumps. Util will remain shutdown for 2 wks to repair steam generator lube loakage State of NJ notified.

 BORCHARDT,W. SWETLAND,P. Region 1, Ofc of the Director. 88/03/31. 1p. 45072 242-45072 242.
- 8804210043 Forwards LER 88-005-00 w/comploted abstract page not included in original 880329 submittal.

 ZUPKO,J.M. Public Service Electric & Gas Co. of New Jersey. 88/04/13. Document Control Branch (Document Control Deak). 1p. 45235:187-45235:192.
- -8804210048 Forwards LER 88-005-00.
 ZUPKO,J.M. Public Service Electric & Gas Co. of New Jorsey. 88/03/29. Document Control Branch (Document Control Desk). 1p. 45235:188-45235:192.
- --8604210047 LER 88-005-00-on B80307, Identified Tech Spec Surveillance 4.7.8.1.2.a, sealed source leak check not performed within 6 months from prior surveillance. Caused by inadequate administrative controls associated w/computer sys POLLACK, M.J. Public Service Electric & Gas Co. of New Jersoy. 88/03/29 4pp. 45235:189-45235:192.
- 8804260054 Special Riopi 87-10:on 871222,svc water bay flooded Caused by equipment malfunction Maint Proceduro M3L revised to verify that actual butterfly position agrees w/Limitorque operator position.

w/Limitorquo operator position.
ZUPKO,J M. Public Service Electric & Gas Co. pl Now Jersey. 88/04/13. Document Control Branch (Document Control Desk). 8pp. 45252:163-45252:170.

8804260061 LER 88-006-00:on 880318,10CFR60 App R cablo design deficiency identified Caused by design error Cable will be re-routed during noxt refueling outage-Roving lire watch will be continued until completion of repair.W/880414 ltr. POLLACK.M.J., ZUPKO.J.M. Public Service Electric & Gas Co. of New Jersey. 88/04/14. 5pp. 45281-295-45281:299.

V. Operator Examinations

- 6804050326 Forwards SALP Board Repts 50:272/86:99 & 50:311/86:99 during Oct 1986 Doc 1997 & Rept 50:354/86:99 on 661201:880115.
 RUSSELL,W.T. Region 1, Otc of the Director. 88/03/29. MILTENBERGER,S. Public Sarvice Electric & Gas Co. of New Jorsoy. 2pp. 45033:262:45034:034.
- --8804080022 SALP Repts 50-272/88-99 & 50-311/88-99 for Oct 1988 Dec 1987.

 * Region 1, Ofc of the Director, 88/02/05, 69pp, 45033-327-45034:034.

DOCKET 50-274 U.S. GEOLOGICAL SURVEY RESEARCH REACTOR

P. Operating license stage documents & correspondence

- 8803250248 Informs of NRC relocation to stated address.Mailing address unchanged A Adams project manager & 15 Michaels back-up project manager. RUBENSTEIN_LS. Standardization & Non-Power Reactor Project Directorate. 88703/18. Affiliation Not Assigned. 3pp. 44859.060-44859.062.
- 8804150365 Informs that alarms on area monitors not verified weekly during periods reactor not in operations Agrees to take steps to assure that alarms will be verified in future.per 880331 telcon. RUSLING.D.H. Interior, Dept. of, Geological Survey. 88/03/31. Region 4, Old of the Director. 1p. 45138:180-45138:180.

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

E. NAC Safety Evaluation Report (SER), suppls & correspondence

8804250224 Responds to appeal re denial of FOIA request for documents re SER (NUREG-0875), Suppl 21 concerning operation of plant. Forwards Documents 1,3,4,5 & 6 of enci app. Document 2 withheld (rel FOIA Exemption 7). STELLO,V. Oic of the Executive Director for Operations, 86/04/19. BAUMAN,L. Government Accountability Project. 2pp. 45232:182-45232:260.

F. Security, medical, emergency & fire protection plans

- 8804070140 Ack receipt of 870630,1013 & 1109 & 880304 firs re Roy 16 of Mar 1988 physical security plan Changes in Rev 18 not fully consistent w/10CFR73.57.Further rays should be submitted per 10CFR50.90. SCARANO.R A Reg on 5, 0tc of the Director, 88/03/30, SHIFFER, J.D. Pacific Gas & Electric Co. 4pp. 45044 160-45044:163.
- 8804200337 Revised emergency plan implementing procedures including Rev 3 to EP RB-15. "Emergency Operating Procedure Post-Accident Sampling Sys." & Rev 5 to EP RB-15.A. "Emergency Operating Procedure Post-Accident Sampling Sys..." W/ 880408 lir.
 TOWNSENDJD., SHIFFERJD. Pactic Gas & Electric Co. 98/04/08. 152pp 45177.014-5177.155.
- 8804220276 Forwards changes to Rev 16 of physical security plan & Rev 2 to training & qualification plan Chargus withhold (ref 10CFR73 21). SHIFFER.J.D. Pacific Gas & Electric Co. 88/04/19. Document Control Branch (Document Control Desk). 1p. 45257 217.45257:217.

G. Adjudicatory correspondence

- 8804050041 Answer of PG&E to patition to intervene in License amend proceedings of San Lus Obispo Mothors for Peace.' San Lus Obispo Mothors for Peace falled to satisfy technical standing requirements of 10CFR2.714.W/Contricate of Svc. NORTON,8 Pacific Gas & Electric Co. #288 5972, 88/03/29. Atomic Safety and Licensing Board Panel. 11pp. 44966:188-44966 190.
- 8804050054 Response to NRC Staff to petition for feave to intervene filed by San Luis Obispo Mothers for Peace.* Notice of appearance & Certificate of Svc encl. VOGLER.B.H. Assistant General Counsol for Hearings. #288 5978 88/03/31. Atomic Safety and Licensing Board Panol. 12pp. 44968 238-44960;249.
- 8804180096 Memorandum & order (providing for amended & supplemental position for leave to Intervene).* San Obispo Mothers for Peace may file amended & supplemental position for leave to Intervene by 880428. Served on 880413 HARBOURJ., LINENBERGER,G., SMITHILW. Atomic Safety and Licensing Board Panol. #288 6040. 88/04/13. San Luis Obispo Mothers for Peace. 4pp. 45127:147-45127:150.
- 8804290019 Amended petition to Intervene. License Condition 2.C (7) of full power License DPR-80 requires that long term setsmic program final rept be submitted on 880731.Ulf license amend request inadequate & must be denied W/Cerlicate of Svc. CULVER.N., CLARK,E.G. Sen Luis Oblego Mothers for Peace. #288 6154, 88/04/25. Atomic Saloty and Licensing Board Panol. 7pp. 45255:230-45255.238.

I. Financial Information

8804120409 "PG8E 1987 Annual Rept." W/880406 fir. CLARKE,R.A., LOCKE,R.F. Pacific Gas & Efectric Co. 87/12/31, 52pp. 45154.003-

O. Advisory Committee on Reactor Safeguards reports & correspondence

- 8804130384 Advises that combination of intensive geologic mapping, reflection & refraclion selsmic surveys,dating of fault movements & analysis of current & past earthquake date reduces chances of underestimating parthquake damage. MAXWELLJC. Maxwell, JC. 08/03/07. SIESS.C.P. ACRS - Advisory Committee on Reactor Saleguards. 3pp. 45130:065-45130.067.
- 8804140215 Submits summary of actions discussed at ACRS 335th meeting on 880310-12 in Washington,DC,including ACRS replay recommendations,other actions,agreements,assignments & requests & tuture agenda. KERR,W. ACRS - Advisory Committee on Reactor Safeguards 89/03/24. ZECH,L.W. Commissioners. 4pp 45118:172-45118 175.
- 8804140163 Summary of ACRS Subcommittee on Diable Caryon meeting on 880223-24 In Burlingame,CA re review of Diable Caryon long term selsmic program * ACRS - Advisory Committee on Reactor Safeguards 88/04/07. ACRS - Advisory Committee on Reactor Safeguards. 11pp. 45118-135-45118:145.

- 8804190231 FOIA request for documents to ACRS subcommittee meetings on 750218-19 to plant. STEWART,M.E. Pacific Gas & Electric Co. 88/02/22. NRC - No Detailed Affiliation
- Given, 2pp. 46185:151-45165:216.
- 8804060427 Forwards JEBCO Selsmit, inc ltr discussing offshore selsmit data collected in 1984 near facility & requests response re issues raised by lit. Confidential maps attached may be released par felcon between G Lightman & R Rollman. ROOD, H. Project Directorate V. 88703/09, SHIFFER, J.D. Pacific Gas & Electric Co 5pp. 44997:332-44997:342.
- --8804050436 Informs that util ignored unique & critical set of seismic data in assessment of major structural trends in area of facility. Slick map of existing data program map for 1988 survey & seismic data enci. LICHTMAN,G.S. JEBCO Seismic, Inc. 68/01/05. REITER,L. NRC No Deta-led Affiliation Given. 6pp. 44097:337-44997:342.
- 8803240428 Generic Ltr 88-06 to all power reactor (icensees & applicants re removal of organization charts from Tech Spoc administrative control requirements Svc list encl. MIRAGLAF.J. Associate Director for Projects (Post 870411), 88/03/22, Consolidated Edison Co. of New York, Inc. 47pp. 44972;107-44972:153
- 8804050091 Forwards description of activities re-util closing of wastewater holding pond & Rev 2 to "Resource Conservation & Recovery Act Hezardous Wastewater Holding Pond at Diablo Carryon Power Plant."
 SHIFFERJ.D. Pacific Gas & Electric Co. 88/04/01. Document Control Branch (Document Control Desk). 17pp. 45082:129-45082.292.

- -8804070289 Rev 2 to "Resources Conservation & Recovery Act Hazardous Waste Closure Plan for Wastewater Holding Pond at Diablo Canyon Power Plant." W/Iwo * Pacific Gas & Electric Co. 87/07/31 153pp. 45062.140-45062.292
- 8804080088 Generic Ltr 88.07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MiRAGLIA.F. J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164 237.45164 285
- 8804140462 Partial response to FOIA request for documents App. A document totally withheld (ref FOIA Exemption 5).
 GRIMSLEY, D.H. Division of Rules & Records (Post 870413). 88/04/08.
 WEISSMAN, S. California, State of 3pp. 45100:150-45130.152.
- 8804190242 Responds to FOIA request for documents re ACRS meeting on plant.Forwards DJ Skovholt 750324 memo to F Schroeder concerning plant pre-ACRS SER supplis Charges for search, review & reproduction provided.
 GRIMSLEY.D H Division of Rules & Records (Post 870413) 89/04/14.
 STEWART.M.E. Pacific Gas & Electric Co. 1p. 45165-217-45165-230.
- -8804200153 Forwards list of plant open items resulting from ACRS subcommittee 58012-0113 Forwards rist or prairi open nears resouring room ACHS subcommittee 750218 & 19 meetings & list of actions requested from raview branches for used in preparing SER suppliprior to next ACRS meeting SKOVHOLTIDU Division of Reactor Licensing (MRR-1976 billy). 75/03/24. SCHROEDER,F. Division of Technical Review (NRR-1975 only). 13pp. 45165-218-45165-218-45165 230
- 8804250017 Forwards application for amends to Licenses DPR-80 & OPR-82, consisting of License Amend Request 88 04,revising Tech Specs 2.2.1 & 3.3.1 lo change reactor tip on furth he ting to thormal power greater than 50%, Fee paid.

 SHIFFER,J.D. Pacific Gas & Electric Co. 88/04/18. Document Control Branch (Document Control Dask). 2pp. 45248 013-45248:032.
- --8804250018 Application for amends to Licenses DPR-60 & DPR-62, consisting of Li-cense Amend Request 88 04/evising Tech Space 2.2 t & 3.3.1 to delete reactor trip on turbine trip below 80% power. SHIFFER.J D Pacific Gas & Electric Co. 88/04/18 13pp. 45248:015-45248:027.
- -8804250022 Proposed Tech Specs 2.2 I & 3.3.1, revising reactor trip on turbine trip from thermal power greater than 10% to thermal power greater than 50%.
 Pacific Gas & Electric Co. 88/04/18. Spp. 45248.028.45248.032.
- 8804260069 Final response to FOIA request for documents App. Y documents enct & available in PDR & LPDR App. Z documents partially withheld (ref. FOIA Exemptions 6 & 7). App. AA documents lotarly withheld (ref. FOIA Exemptions 7).
 GRIMSLEY,D. Div. ston. of Rules & Records (Post 870413), 88/04/19. GARDE,B.P...
 Government Accountability Project. 5pp. 45232;135-45232,172.
- --8804260106 Partially defeted memo re 840120 altegation of drug use at plant Writer received telephone call stating that two individuals bragged about shooting up w/hero-ing in "Blue Room" at plant.

 SHACKLETON,O.C. Region 5, Old of the Director, 84/01/26, Region 5, Old of the Director, 3pp. 45232.142-45232:144.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Roctors." See fist encl.
 ROSSI,C E. Division of Operational Events Assessment (Post 870411), 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995.248.
- 6803220296 NRC Info Notice 88 010, "Mails Licensees Lack of Mgt Controls Over Licensed Programs," Svc list encl CUNNINGHAM,R E Division of Industrial & Medical Nuclear Salety (Post 870729), 887 03/28 Consolidated Ed.son Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804130019 Forwards Insp Repis 50-275/88-03 & 50-323/88-04 on 880131- 0305 & notice of violation this attention directed to Section 4 of end repi dealing w/recent plant events Mgt should carefully reassess problem area. kiRSCH.O.F. Rogion 5. Oic of the Director, 68/03/28. SHiFFER.J.O. Pacific Gas & Electric Co. 2pp. 45151:140-45161:164.
- --8804130020 Notice of violation from insp on 880131-0305 Violations noted employee select 150020 Rolling of violations from his poin cool 31 rolling and rolling employed entered facilities and state of stepping over posted boundary at point not established as normal access control point w/o written autorization.

 KIRSCH,D.F. Region 5, Otc of the Director, 88/03/28, 2pp. 45151:142-45151:143.
- -8804130022 Insp. Repts 50-275/88-04 & 50-323/68-04 on 880131-0305. Violations noted Major areas inspected plant operations, maint & surveillance activities, followup of onsite events, open kems & LERs. PADOVANL M. JOHNSTON, K.E., NARBUT, P.P. Region 5. Ofc of the Director, 88/03/16, 21pp. 45151:144-45151:164.
- 8804080249 Ack receipt of 880310 lit informing NRC of steps taken to correct violations noted in Insp Repts 50-275/87-44 & 50-323/87-45.
 ZIMMERMAN R. Region 5, Otc of the Director, 88/03/29. SHIFFER,J.D. Pacific Gas & Electric Co. 1p. 45054:232-45064:233.
- 8804010258 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switchboard Function Due to Faulty Tie Bolls." Svc list encl.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407;051.
- 8804200531 Responds to NRC 880311 ltr re violations noted in Insp Repts 50-275/88-04 & 50-323/88-03 Corrective actions Surveillance Test Procedure V-3, "Exercising Salety Related Valvas General Procedure" solvised to be consistent w/ASME Code. SHIFFER, J.O. Pacific Gas & Electric Co. 88/04/11. Document Control Branch (Document Control Besk). 8pp. 45175-014-45175-019.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45185:028-45185:150.

- 8804200521 Forwards additinto to suppliabilities poince to IE Bullotin 85-003, "Motor-Operated Valve Common Mode Fallures During Plant Transients Due to Improper Switch Settings," per 880315 request.
 SHIFFER.J.D. Pacific Gas & Electric Co. 88/04/14. Document Control Branch (Occument Control Desk), 10pp. 45226.211-45226.220.
- 8804210449 Informs that completion of survey of safety-related equipment outside containment in response to Insp. Repts. 50-275/87-42 & 50-323/87-43 rescheduled to 880430,due to personnel requirements to support Unit 1 relucing outage. SHIFFER,J.D. Pacific Gas & Electric Co. 88/04/14. Document Control Branch (Occument Control Desk). 1p. 45226:342-45226:342.
- 8804280069 Final response to FOIA request for documents App Y documents encil & evallable in POR & LPDR App Z documents partially withhold (rel FOIA Exemplions 6 & 7) App AA documents (paid) withhold (rel FOIA Exemplions 7). GRIMSLEY,D. Division of Rules & Records (Post 870413). 88/04/19 GARDE,BP. Government Accountability Project, 5pp. 45232:135-45232:172.
- --8804260133 Partially deleted Rept of Inquiry 05-83-018 re allegation of falsification of welding exams by fromworkers from Fresno Union Further (investigation unwarrented, based on failure to confirm that stend-in welder took tests Related info POWER,E.J., SHACKLETON,O.C. Region 5, Ofc of the Director, 83/12/15, 28pp 45232.145-45232:172
- 8804280207 Responds to NRC Bulletin 68-003, "Inadequate Latch Engagement in HFA Type Latching Relays Mig by GE." Subj relays not in use in Class 1E applications at lacility.
 SHIFFER.J.D. Pacific Gas & Electric Co. 88/04/21. Document Control Branch (Document Control Desk). 1p. 45253:048-45253.049.

R. Periodic operating reports & related correspondence

- 8804040009 "Tabulation of Personnel Exposure to Radiation for 1987." W/ 880328 hr, SHIFFER,J.D. Pacific Gas & Electric Co. 87/12/31, 5pp. 44969.071-44969.075.
- 8804220104 Monthly operating repts for Mar 1988.W/880415 lif. BEDESEM.P., TOWNSEND.J.D., MALONE,D.D. Pacific Gas & Electric Co. 88/03/31 12pp. 45216:226-45216:237.

S. Reportable occurrences, LERs & related correspondence

8804070019 LER 87-019-01:on 871020,time interval required by Tach Specs 4.1.3.1.1.8
4.1.3.2 exceeded,Caused by personnel error & equipment/computer program problems Monitor declared inoperable pending completion of investigation.W/880401 tr. HUG.M.T., SHIFFER,J.D. Pacific Gas & Electric Co. 88/04/01. 6pp. 45072:277-45072:282.

V. Operator Examinations

- 8804250088 Responds to FOIA request for info re-scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in enclusive personal privacy info deleted.

 GRIMSLEY,D.H. Division of Rules & Records (Post 870413), 88/04/19, BOLEY,K Public Citizen's Critical Mass Energy Project. 2pp. 45213:003-45213.095.
- --8804250167 Package of NRC administered requalification exam results summary.
 NRC No Detailed Affiliation Given. 87/07/20. 88pp. 45213:007-45213:095.

DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8804140091 Provides schedule of emergency response activities for remainder of FY88 to regional staff for planning purposes.

 BELLAWY, B.R. Region 1, Oic of the Director. 88/03/02. RUSSELL, W.T. Region 1, Ofo of the Director. 1p. 45122.258-45122.258.
- 8804130055 Notification of 880323 Meeting 88 036 w/util In King of Prussia,PA to discuss fire protection open items.
 LINVILLEJ. Region 1, Ofc of the Director. 88/03/22 Region 1, Ofc of the Director.
 2pp. 45099:352-45099:353.
- 8804040091 Responds to NRC 880226 ltr re violations noted in Insp Repts 50:277/88-01 & 50:278/88-01.Corrective actions worker involved suspended from respiratory qualification list untit re-fitted for ultraview respiratory on 880126 GALLAGHERJ.W. Philadelphia Electric Co. 88/03/28. KANE,W.F. Region 1, Oic of the Director. 4pp. 44970:303-44970:306.
- 8804120049 Forwards Radiation Safety Insp. Repts 50-277/88-07 & 50-278/88-07 on 880216-19. Violation relack of procedure for calibr & source checking of portal monitors noted.

 BELLAMY,R.R. Region 1, Ofc of the Director. 88/04/04, KEMPER,J.S. Philadelphia Efectric Co. 3pp. 45142:154-45142:163.
- -8804120053 Safety Insp Repts 50-277/88-07 & 50-278/88-07 on 880216-19. Violation noted Major areas in apected worker allegation re use of respiratory protection & hot spot shielding in Unit 3 drywell & retraining facility staff in radiation protection DRAGOUNT, THOMAS, W., SHANBAKY, M. Region 1, Ofc of the Director, 88/03/31. 7pp. 45142:167-45142;163.
- 8804120200 Forwards Safety Insp Repts 50-277/88-02 & 50-278/88-02 on 680206-0311 & notice of violation.

 KANE,W.F. Region 1, Oto of the Director. 88/04/04. KEMPER,J.S. Philadelphia Electric Co. 2pp. 45130:279-45130:315.

- ■8804120212 Insp Repts 50-277/88-02 8 50-278/88-02 on 880206-0311. Violation noted Major areas inspected accessible portions of operational safety, radiation protection, physical socurity, control room activities 8 licensee events.

 WILLIAMS_J.H. LINVILLE, J.C. Region 1, Ofc of the Director. 88/03/29, 34pp 45130 282-45130 315
- 8804250159 Forwards Insp Repts 50-277/88-09 & 50-278/88-09 on 880229- 0303 & notice of violation BELLAMY,R.R. Region 1, Ofc of the Director, 88/04/16, KEMPER,J.S. Philadelphia Electric Co. 2pp. 45224:161-45224.169.
- -8804250160 Notice of violation from insp on 880229-0303 Violation noted licenses did not maintain documentation of 1983 annual emergency preparedness audit & did not perform annual audit during 1985.

 *Rogion 1, Oic of the Director, 88/04/16, 1p. 45224:163-45224:163.
- -8804250162 insp Repts 50:277/88-09 & 50:278/88-09 on 880229 0303. Violations noted Major areas irrspected emergency preparedness program review of proviously identified insp findings & changes to emergency proparedness program.

 GORDON, C.Z., LAZARUS, W.J. Region 1, Ofc of the Director. 88/04/12. 6pp 45224:164-45224:169.
- 8804270026 Advises that 871209 rev to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable. BELLAMY,R.R. Region 1, Old of the Director. 88/04/18. BAUER,E.G. Philadolphia Electric Co. 5pp. 45241:169-45241:173.

G. Adjudicatory correspondence

- 8804110019 Establishment of ASLB.* Board established to preside over Philladelphia Electric Co.et all proceeding re Tech Spec mod concurring new corporate & plant slaft organizational structure Served on 880407. COTTER,B.
 - 45049.020-45049.021
- 8804180009 Memorandum & order (setting deadline for filling of contentions) * Alters deadlines in Soction 2.714 (a)(3) & (b) of order to provide for filling of commonwealth contentions & amends to 880425 petition. Contentions a animula to booked petition. FRYE, J.H. Atomic Safety and Liconsing Board Panel. #288 6054, 88/04/08, 3pp. 45128:038-45128:041.
- 8804290840 Request for extension of time in which to file contentions & supplement to pelition to intervence & request for hearing.* Thirty-day extension sought for listed reasons. Curlificate of Svc enci.

 SEARCHINGER,T. Pennsylvania, Commonwealth of: #288 6152, 88/04/22.

 FRYE_J.H., BRIGHT,G.O., COLE,R.F. Atomic Safety and Licensing Board Panel, Bpp 45256.033-45268.040.

H. General correspondence

8604070271 Requests that JS Kemper be added to carbon copy 1st for Limerick correspondence.Kemper title incorrectly identified in author 880328 ltr to WT Russell & should be corrected to read "Senior Vice President, Nuclear." MCNETLL C.A. Philadolphia Excitic Co. 88703730. RUSSELL, W.T. Region 1, Otc of the Director. 1p. 45029:266-45029:268.

I. Financial Information

8804270235 Forwards annual repts for Philadelphia Electric Co.PSE&G, Atlantic City Electric Co.& Delmarva Power & Light Co. BRADLEY, E.J. Philadelphia Electric Co. 68/04/18. MURLEY, T.E. Olfice of Nuclear Reactor Regulation, Director (Post 870411). 1p. 45260:221-45261:064.

J. Insurance & Indemnity Information

- 8804130181 Forwards Endorsement 72 to MAELU Policy MF-67 & Endorsement 122 to NELIA Policy NF-140.

 BRADLEY,E.J. Philadelphia Electric Co., 86/04/07, DINITZ,I. NRC No Detailed Aftiration Given, 5pp. 45098.279-45099:283.
- 8804190088 Forwards Endorsement 12 to NELIA Policy I & Endorsement 3 to MAELU Policy 1. BRADLEY,E.J. Philadelphia Electric Co. 88/04/08. DINITZ,I. NRC - No Oetaliad Affiliation Given 5pp 45163:341-45163.345.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8804140215 Submits summary of actions discussed at ACRS 335th meeling on 880310-12 In Washington, DC, Including ACRS repts/ recommendations, other actions, agreements, assignments & requests & tuture agenda. KERR, W. ACRS - Advisory Committee on Reactor Safeguards, 88/03/24, ZECH, L.W. Commissioners, 4pp. 45118:172-45118:176.

P. Operating license stage documents & correspondence

- 8804130046 Notification of 880216 mgt meeting w/util in King of Prussia,PA to discuss announced util mgt change
 LINVILLE, IC. Region 1, Oic of the Director. 88/02/18. Region 1, Oic of the Director.
 2pp. 45099.354-45099-355
- 8804140027 Notification of 880322 Licensee Meeting 88 036 w/util In King of Prussia,PA to discuss plant review process.

 LINVILLE,J. Region 1, Ofc of the Director. 88/03/10. Region 1, Ofc of the Director. 2pp. 45122:283-45122:284.
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re romoval of organization charts from Tech Spec administrative control requirements. Svc list encl. MHAGLIA, F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972;107-44972:153.

- 8804120299 Notification of Licensee Meeting 88.048 on 880331 w/u11 at plant to discuss licensee plans & schedules to make facility ready for restert. LINVILLE, J. Region 1, Old of the Director, 88/03/24 Region 1, Old of the Director, 2pp. 45090.049.45090.050.
- 8604120384 Responds to request for specific confirmatory into to permit NRC to complete raview of application for amond to Tech Specs re-dissel generator fuel of sys in order to bring plant into conformance wifting Guide 1 137
 GALLAGHER J. W. Philadelpha Electric Co. 88/03/30 BUTLER,WR Project Director-BIO 1-2 5pp 45091.155-45091:159.
- 8804110125 Forwards SER supporting util responses to Generic Lir 83-28, Item 2 2 1, "Equipment Classification Program for AT Safety-Related Components." MARTIN,R E. Project Directorate I-2, 88/04/01, BAUER,E G. Philadelphia Electric Co 2pp. 45078 251-45078 272.
- B804110132 SER accepting util responses to Generic Ltr 83-28, Item 2.2.1 re equipment classification program for all safety-related components
 NRC No Detailed Affiliation Given 88/04/01 4pp. 45078 253-45078:272.
- 8804130357 Advises that temporary waiver of compliance not issued in conjunction w/ emergency licensing amend granted for plants for first time,oer guidance from HR Denton 870227 memo. Two-via waivers have been issued since Shotly rule in effect. STELLO,V. Offic of the Executive Overtor for Operations. 68/04/08. ROBERTS,T.M. Commissioners 2pp 45117-016-45117-017
- 8904190093 Forwards Amonds 530 & 133 to Licenses DPR-44 & DPR-56, respectively 8 safuty evaluation Amends add survertance requirements for time delay leature of reactor protection systationnate power supply undervoltage protective device MARTIN, RE. Project Directorate 1-2, 89/04/06. BAUER, E.G. Philadelphia Electric Co. 3pp. 45155.230-45155-245.
- -8804190099 Amends 130 & 133 to Licenses DPR-44 & DPR-56,respectively, adding surveillance requirements for time delay feature of undervoltage protective device for reactor protection systematics power supply. BUTLER,W.R. Project Directorate I-2 88/04/06 10pp 45155 233-45155 242
- --8804190108 Safety evaluation supporting Amends 130 & 133 to Liconses DPR-44 & DPR-56 respectively.
 * Office of Nuclear Reactor Regulation, Director (Post 870411) 88/04/06 3pp 45165:243-45155245
- 8804080088 Genoric Lir 88-07 to power roactor licensees & applicants re-modified en-forcement policy concerning 10CFR50-49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants" Svc list enct. MIRAGLIA,F. J. Associate Director for Projects (Post 970411) 88/04/07, Consordated Edison Co. of New York, Inc. 49pp. 45164-237-45164-285
- 8804120236 Staff requirements memo on 880331 affirmation/discussion 8 voto in Washington,DC to SECY-88-066 concerning Commonwealth of PA 880122 second petition for hearing on facility.

 CHILK,SJ Office of the Secretary of the Commission 88/04/07. PARLER,W C Office of the General Counsel 1p 45100:300-45100:300
- 8804130361 Forwards Sections I & II of Roy I to "Plan for Restart of Peach Bottom Atom'c Power Station," por 880318 commitment. Roy incorporates second & third recommendations from ZT Pate 880111 ftr.Rey summary & activities schedule also onct.
 PAQUETTE, J.F. Philadelphia Electric Co. 88/04/08. RUSSELL, W.T. Region 1, Olc of the Director. 10pp. 45 166.098-45187:104
- --8804130366 Rev 1 to Section I, "Corporate Action," of "Plan for Restart of Peach Bottom Atomic Power Station." Philadelphia Electric Co. 88/04/08 | 113pp. 45186.108-45166.235
- **8804190397 Rev 1 to Section II, "Peach Bottom Atomic Power Station Action," of "Plan for Restart of Peach Bottom Atomic Power Station."
 * Philadolphia Electric Co. 88/04/08. 214pp. 45166.236-45187:104.
- 8804150226 Informs at planned change in util method of performing QC monitoring of shift operations. Present full shift coverage will be modified to include scheduled random monitoring of attornoon 8 night shifts by 880418.

 MCNEILL.C.A. Philadelphia Electric Co. 88/04/08 RUSSELL,W.T. Region 1, Cfc of the Director. 2pp. 45131:360-46131.361.
- 8804250020 Forwards util response to INPO 880111 ftr re Rev 1 to facility restart plan for 800304 request MCNEILL, C.A. Philadelphia Electric Co. 88/04/15. RUSSELL, W.T. Region 1, Ofc of the Director. 6pp 45237:184-45237:189

- 8804010144 Advises that future correspondence re insp & enforcement should be au-dressed to CA McNeill, Executive Vice President-Nuclear. MCNEILL, CA. Philadelphia Electric Co. 88/03/25. RUSSELL, W.T. Region 1, Ofc of the Director. 1p. 45020-016-45020-016.
- 8803210090 Suppl I to NRC Into Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors." See list encl. ROSSI, C.E. Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:128-44995:246.
- 8803220296 NRC Info Notice 88-010, "Matis Licensees Lack of Mgt Controls Over Licensed Programs" Svc list end. CUNNINGFIAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 88/ 03/28, Consolidated Edison Co. of New York, Inc. 108pp. 44995-247-44995 353.
- 8804040091 Responds to NRC 880226 ltr re violations noted in Insp Repts 60-277/88-01 & 50-278/88-01. Corrective actions worker Involved suspended from respiratory qualification list until re-litted for ultraview respiratory on 880128. GALLAGHER.J.W. Philadelphia Electric Co. 88/03/28. KANE,W.F. Region 1, Otc of the Director. 4pp. 44970:303-44970.308.

- cordance w/IE Bulletin 88-003, "Motor: Operated Velve Common Mode Failures During Plant Transients Due to Improper Switch Sattings" WENZINGER, E.C. Region 1, Oto of the Director, 86/03/28 KEMPER, J.S., Philadelphia Electric Co. 4pp. 45021:243-45021.246.
- 8804110310 Forwards Insp Repts 50:277/68:05 & 50:278/88:05 on 880208:12 & notice of violation BELLAMY,R.R. Region 1, Old of the Director, 88/04/04, KEMPER,J.S. Philadolphia Electric Co. 3pp. 45126.178-45128;193.
- --8804110312 Notice of violation from inspiron 880208-12 Violation noted. Agreement State license did not authorize receipt at trium during 871125 transfer & fellure to verify recipient license prior to transfer of and oactive mat/.

 * Region 1, Old of the Director, 88/04/04, 1p. 45128:181-45128-181.
- -8804110319 Insp Repts 50:277/88:05 & 50:278/88:05 on 880208:12. Violations noted Major areas inspected solid ratiwaste & tadioactive mail shipping program including control, radioactionistry & implementation of programs. BICEHOUSEHJ., PASCIANK.W.J. Region 1, Ofc of the Director. 88/03/29. 12pp
- 8804120049 Forwards Radiation Safety Insp Repts 50-277/88-07 & 50-276/88-07 on 880216-19 Violation re-lack of procedure for calibr & source checking of portal months.
- BELLAMY,R.R. Region 1, Oic of the Director, 88/04/04, KEMPER,J.S. Philade/phia Electric Co. 3pp. 45142.154-45142.163
- -8804120053 Safety Insp Repts 50-277/88-07 & 50-278/88-07 on 880218-19 Violation notad: Major areas inspected: worker allegation re use of respiratory protection & hot spot stitleding in Unit 3 drywell & testianing techts staff in radiation protection. DRAGOUNT. THOMAS W, SHANBAKY,M Region 1, Ofc of the Director, 88/03/31. 7pp. 45142.157-45142.163.
- 8804120200 Forwards Safety Insp. Repts 50:277/88-02 & 50:278/88-02 on 880206-0311 & notice of violation KANE,W.F. Regron 1, Oic of the Ovector, 86/04/04 KEMPER,J.S. Privladelphia Elec-tric Co. 2pp. 45130:278-45130:315
- -8604120209 Partially withheld notice of violation from insp on 880208 0311 (ref. 10CFR/3.21). Violation noted unlocked & unattended vehicle parked in util vital area.
- Region 1, Oic of the Director, 88/04/04, 1p. 45130.281-45130,281,
- --8804120212 Insp Repts 50:277/88:02 & 50:278/88:02 on 880206:0311. Violation noted Mejor areas inspected accessible portions of operational safety radiation protection physical security, control room activities & licensee events WILLIAMS_IH_LINVILLE_IC. Region 1, Ofc of the Director. 88/03/29. 34pp 45130:282-45130:315
- 8804130182 Ack receipt of 880311 firs amending util 880225 & 25 firs Informing NRC of steps taken to correct violations noted in firsp Repts 50 277/87-37,50 278/87-37 & 50-352/97-20.
- BELLAMY, R.R. Region 1, Old of the Director, 88/04/04, KEMPER, J.S. Philadelphia Electric Co. 2pp. 45154:099-45154:111.
- 8804010256 NRC Info Notice 08-011, "Potential Loss of Motor Control Ctr 8/or Switch-board Function Due to Faulty Tip Botts," Size hat end, ROSSI, CE. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407.051.
- 8804140501 Notification of 880421 meeting w/util & GE in Rockville,MD to discuss the consee plans & bases for inspecting shroud support access hole covers on facility rectacks found in Unit 3 covers.

 MARTIN,R.E. Project Directorate 1-2, 86/04/08, BUTLER,W.R. Project Directorate 1-2, 3pp. 45130 154-45130:156.
- 8804150230 Hesponds to 880205 NRC Bulletin 88-01 re defects in Westinghouse circuit breakers for facilities. Westinghouse DS series circuit breakers not used at plants. Other provisions of bulletin do not apply to plants. KOWALSKI,S.J. Philadelphia Efectric Co. 88/04/08 RUSSELL,W.T. Region 1, Otc of the Director. 2pp. 45138:028-45138:029.
- 8804220077 Notification of canceled 880421 meeting w/util & GE in Rockvillo,MD to discuss ficensee plans & bases for inspecting shroud support access hole covers on Unil 2 to crecks found in Unil 3 covers on 890122.

 MARTIN,R.E. Project Directorate 1-2. 88/04/08. BUTLER,W.R. Project Directorate 1-2. 3pp. 45201:087-45201:089.
- 8804200036 Summarizes 860322 meeting w/utils re plant restart review process NRC to conduct integrated performance assessment toam linsp to assess effectiveness of Implementation of Incensee plan List of attendeds encit KANE,W.F. Region 1, Offic of the Director, 88/04/11, MCNETLL,C.A. Philadelphia Electric Co. 4pp. 46226:186-45226:189.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svo nateric. ROSSI,C.E. Davision of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150.
- 8804210380 Ack receipt of 880201 fir informing NRC of steps taken to correct violations noted in Insp Repts 50:277/87-23 & 50:278/87-23.
 GALLO,R M. Region 1, Ofc of the Director, 88/04/15, MCNEILL,C.A. Philadelphia Electric Co. 2pp. 45228.350-45228.355.
- 8804250159 Forwards Insp Repts 50-277/88-09 & 50-278/88-09 on 880229- 0303 & notice of violation.

 BELLAMY,R.A. Ragion 1, Oic of the Director, 88/04/16, KEMPER,J.S. Philadelphia Electric Co. 2pp. 45224:161-45224:169,
- --8804250160 Notice of violation from Insp on 880229-0303. Violation noted licensee did not maintain documentation of 1983 annual emergency preparedness audit & did not perform annual audit during 1985.
 * Region 1, Ofc of the Director. 68/04/16, 1p. 45224:163-45224:163.
- -8804250162 Insp Repts 50-277/88-09 & 50-278/88-09 on 880229-0303. Violations noted Mejor areas inspected emergency preparedness program; eview of previously identified insp findings 8 changes to emergency preparedness program.

 GORDONC 2., LAZARUS,W.J. Region 1, Ofc of the Director. 88/04/12. 6pp, 45224:184-45224:189.

n. Periodic querenna reports à relateu curresonnaence

- 8804220040 Monthly operating repts for Mar 1988.W/880415 ltr.
 MIDDLETON, L.L., ALDEN, W.M. Philadelphia Electric Co. 88/03/31 14pp. 45221 33
 45221 348.
- 8804120225 Forwards periodic status rept for 880314-31.Rept intended to provide N8 mgt & public w/loven/lew of plant activities & NRC risp activities. LINVILLEJ C Region 1, Ofc of the Director 88/04/07. KANE,W F. Region 1, Ofc the Director 4pp 45079.305

S. Reportable occurrences, LERs & related correspondence

- 8803300272 LER 88:002:00 on 880301, reactor scrammed during performance of Proc. durid GP-11.E, "Reactor Protection Sys (RPS) Scram Roset." Caused by operation or Operator consisted re-importance of attention to detail WAB0325 ltr BIRELY,W.C., LOGUE,R.H. importance of attention to detail WAB0325 ltr. 88703725. 4pp. 44953.15
- 8804040035 LER 88-003-00.on 880302,ESF actuation occurred due to undervoltage in of breakers while adjusting defective voltage rheostati-Caused by defective voltage rheostati-Caused by defective voltage rheostati-Caused by defective voltage rheostati-Caused by Republic Rep
- 8804060043 LER 88-006-01:on 880303 primary containment isolation sys group the lation signal occurred Caused by loss of power to RHR sys logic bus A due to pulse loss from panel. Fuse replaced & isolation reset W/880330 ftr.

 BIRELYWC LOGUE, R.H. Philadelphia Electric Co. 88/03/30. 5pp. 45072 10
- 8804080034 LER 87-031-01 on 871231 determined that loss of power to extract steam block valves could result in loss of feedwater heating event outside dost basis of feedwater heating event outside dost basis of feedwater heating event outside dost BHCLY.W.C. LOGUE,R.H. Philadelphia Electric Co. 88/03/31, 7pp. 45092:10 45092.110
- 8804080056 LER 88-004-00:on 880302,relay tripped causing breaker trip, resulting containment isotations & inoperability of fire pumps Caused by unexpected trip of edervoltage roley Relay coll shipped to mig for failure analysts W/880331 ftm. BIRELY,W.C., LOGUE,R.H. Philadelphia Electric Co. 88/03/31, 9pp. 45100.06 45100 070
- 8804080162 LER 88-005-00-on 880303,control panels falled to meet original sessa qualifications Caused by Installation error & not following design drawings Passe chainel of each panel wolded to floor embed on outside of panel W/880404 ft. BIRELY,W.C., LOGUE,R.H. Philadelphia Electric Co. 88/04/04, 5pp. 45098-15 45098:162.
- 8804130063 LER 88-004-01:on 880302:relay trip causing breaker trip resulted in co-tainment isolations & inoperable fire pumps. Caused by severe heat damage on rel-coil Coil shipped to mig. Temporary feed installed W/880408 ftr. BIRELY,W.C., LOGUE,R.H. Philadatinia, Electric Co., 88704/09, 9pp. 45131:11 45131:120

U. Congressional/Executive Correspondence

- 8804130356 Responds to 880212 fir raising number of concerns re plant. Decision permit resilant will not be made until Commission convinced that previous problem corrected & that operation of facility in safe manner assured.

 ZECH_L.W. Commissioners. 88/04/07. SCHAEFER,W.D. Maryland, State of. 59 45412.351-45412.358.
- --8802250098 Discusses issues surrounding facility. State of MD has no formal standing review process. NRC should Identify specific restart criteria.
 SCHAEFER, WD. Maryland, State of 88/02/12, ZECH, L.W. Commissioners. 45412:358-45412:358.

V. Operator Examinations

- 8604150225 Informs of planned change in util method of performing QC monitoring shift operations Present full shift coverage will be modified to include schedule random monitoring of alternoon & night shifts by 880418, MCNEILL,C A. Philadelphia Electric Co. 88/04/08. RUSSELL,W T. Region 1, Old the Director. 2pp. 45131:360-45131:361.
- 8804250088 Responds to FOIA request for Info re-scores of reactor operators & sentenctor operators. Forwards requalification exam summary source sheets tisted in orapp w/personal privacy Info deleted.
 GRIMSLEY,O.H. Division of Hurles & Records (Post 870413), 68/04/19. BOLEY, Public Citizon's Critical Mass Energy Project. 2pp. 45213:003-45213:095.
- --8804250167 Package of NRC administered requalification exam results summary. NRC No Detailed Affiliation Given. 87/07/20. 88pp. 45213:007-45213:095.

DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

- F. Security, medical, emergency & fire protection plans
- 8604140091 Provides schedule of emergency response activities for remainder of FY to recional stell for planning purposes.

 BELLAMY,R.R. Region 1, Otc of the Director 88/03/02, RUSSELL,W.T. Region Otc of the Director. 1p. 45122:256-45122.258.
- 8804130055 Notification of 880323 Meeting 88,036 w/util in King of Prussia,PA to d cuss fire protection open items. LINVILLEJ. Region 1, Otc of the Director, 88/03/22. Region 1, Otc of the Direct 2pp. 45099.352-45099.353.

- 8804040091 Responds to NRC 880226 ftrire violations noted in Insp Repts 50-277/88-01 & 50-278/88-01 Corrective actions worker involved suspended from respiratory qualification list until re-litted for ultraview respiratory on 880126.

 GALLAGHER, JW Philadelphia Elocture Co 88/03/28 KANE,WF Region 1, Otc of the Director 4pp 44970 303-44970 306
- 8804120049 Forwards Radiation Safety Insp Repts 50-277/88-07 & 50-278/88-07 on 880216-19 Violation reliack of procedure for calibr & source checking of portal monitors noted

 BELLAMY,R R. Region 1, Old of the Oirector, 88/04/04, KEMPER,J.S. Philadelphia
 Electric Co. 3pp. 45142:154-45142 163.

- -8804120053 Safety Insp Repts 50-277/88-07 & 50-278/88-07 on 880216-19. Violation noted Major greas inspected worker allegation re use of respiratory protection & hot spot shielding in Un13 drywell & retraining facility staff in radiation protection DRAGOUN.1 Region 1, Old of the Director, 88/03/31, 7pp, 45142,157-45142,163
- 8804120200 Forwards Safety Insp Repts 50-277/88-02 & 50-278/88-02 on 880206-0311 8 notice of violation.
 KANE,W F. Rogion 1, Ofc of the Director. 88/04/04 KEMPER,J S. Philadelphia Etoc-tric Co. 2pp. 45130-279-45130-315.
- ~8804120209 Partially withheld notice of violation from linep on 880206.0311 (ref 10CFR73.21) Violation noted un'ocked & unattended vehicle parked in util vital area

Region 1, Ofc of the Director 88/04/04 1p. 45130 281-45130:281.

- ~8804120212 Insp. Repts 50-277/88-02 & 50-278/88-02 on 880205-0311. Violation noted Major areas inspected accessible portions of operational salety, radiation protection, physical security, control room activities & licensoe events WILLIAMS, J.H. Region 1, Otc of the Director, 89/03/20, 34pp. 45130-282-45130-315
- 8804250159 Forwards Insp Repts 50-277/88-09 & 50-278/88-09 on 880229- 0303 & notice of violation BELLAMY,R.R. Region 1, Ofc. of the Director. 86/04/16 KEMPER,J.S. Philadelphia Efactric Co. 2pp. 45224-161-45224-169.
- --8804250160 Notice of violation from inspion 880229-0303. Violation noted licensee dkt not maintain documentation of 1983 annual emergency preparedness audit & d.d. not perform annual audit during 1985.
 * Region 1, Olc of the Director, 88/04/16, 1p, 45224:163-45224:163
- --8804250182 Insp. Repts 50-277/88-09 & 50-278/88-00 on 880229-0303 Violations noted Major areas inspected emorgency preparedness program/review of previously identified insp findings & changes to emorgency preparedness program GORDON,C 2. Region 1, Old of the Director 88/04/12. 8pp. 45224:164-45224:169.
- BB04270026 Advises that 671209 rev to physical security plan consistent w/provisions of 10CFR50.54(p) & acceptable
 BELLAMY.R.R. Region 1, Oto of the Director 88/04/18 BAUER.E.G. Philadelphia Electric Co 5pp. 45241:169-45241:173.

G. Adjudicatory correspondence

- 8804110019 Establishment of ASLB.* Board ostablished to preside over Philadelphia Electric Co.et at proceeding re Tech Spec mod concerning new corporato & plant staff organizational structure Served on 880407. COTTER.B.P. Atomic Safety and Licensing Board Panel #288 6031, 88/04/08, 2pp 45049 020-45049.021.
- 8804180009 Memorandum & order (setting deadline for filing of contentions).* Alters deadlines in Section 2.714 (a)(3) & (b) of order to provide for fiting of commonwealth contentions & amonds to 880425 polition FRYEJH. Atomic Safety and Licensing Board Panel #288 6054, 88/04/08 3pp 45128.039.45128.041.
- 8804290040 Request for extension of time in which to file contentions 8 supplement to petition to intervence 8 request for hearing. Thirty day extension sought for listed reasons. Certificate of Svc enci. SEARCHINGER, T. Pennsylvania, Commonwealth of #288 6152, 86/04/22 FRYE, J.H., BRIGHT, G.O., COLE, R.F. Atomic Safety and Liconsing Board Panel. 8pp. 45256 033-45256:040

H. General correspondence

8804070271 Requests that JS Kemper be added to carbon copy list for Ulmerick correspondence. Kemper little Incorrectly identified in author 880328 fir to WT Russell & should be corrected to road "Senior Vice Prosident. Nucloar." MCNEILL, CA. Philadelphia Electric Co. 88703730. RUSSELL, W.T. Region 1, Ofc of the Director. 1p. 45029:266-45029:266.

i. Financial information

8804270235 Forwards annual repts for Philadelphia Electric Co.PSE&G, Atlantic City Electric Co.& Delmarva Power & Light Co. BRADLEY.E.J. Philadelphia Electric Co. 88/04/18. MURLEY.T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 45260.221-45261:084.

J. Insurance & Indemnity information

- 8804130181 Forwards Endorsement 72 to MAELU Policy MF-67 & Endorsement 122 to NELIA Policy NF-140. BRADLEY.E.J. Philadelphia Electric Co. 88/04/07. DINITZ,I. NRC No Detailed Affiliation Given: 5pp. 45089.278-45099.283.
- 8804190088 Forwards Endorsement 12 to NELIA Policy 1 & Endorsement 3 to MAELU Policy 1. BRADLEY,E.J. Philadelphia Electric Co. 88/04/08: DINITZ,I. NRC - No Detailed Affiliation Given. 5pp. 45153;341-45153;345.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8804140216 Submits summary of actions discussed at ACRS 335th mosting on 880310-12 in Washington,DC,including ACRS repts/ recommendations,other actions,agreements,assignments & requests & future agenda KERR,W ACRS - Advisory Committee on Reactor Safeguards 88703724 ZECH,L.W. Commissioners, 4pp. 45118-172-45118 175.

P. Operating license stage documents & correspondence

- 8804130046 Notification of 880218 mgt meeting w/ulil in King of Prussia PA to discuss announced uttings change in the Director. 88/02/18. Region 1, Ofc of the Director. 20/14. Region 1, Ofc of the Director. 20/14.099 354-45099:355.
- 8804140027 Not1cation of 880322 Licensee Meeting 88-036 w/ull in King of Prussia,PA to discuss plan review process LINVILLE_J. Region 1, Otc of the Director, 88/03/10 Region 1, Otc of the Director, 2pp. 45122:283-45122:284.
- 8803240428 Generic Ltr 88-06 to all power reactor Leensees & applicants re-removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIA, F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804120299 Notification of Licensee Meeting 88-048 on 880331 w/util at plant to discuss l'consen plans & schedules to make facility ready for restart. LINVILLEJ Region 1, Oic of the Director. 88/03/24 Region 1, Oic of the Director. 2pp 45090.04945090.050
- 8804120384 Rosponds to request for specific confirmatory into to permit NRC to complete review of application for amond to Tech Specs re-closed generator fuel oil sys in order to bring plant into conformance w/Rog Guide 1,137.

 GALLAGHER,J.W. Philadelphia Electric Co. 88/03/30. BUTLER,W.R. Project Directorate 1-2, 5pp. 45091.155-45091:159
- 8804110125 Forwards SER supporting util responses to Generic Ltr. 83-28, Item 2.2.1, "Equipment Class-teation Program for All Safety-Rolated Components." MARTIN R.E. Project Directorate I.2. 88/04/01. BAUER,E.G. Philadelphia Electric Co. 2pp 45078 251-45078:272
- --B804110132 SER accepting util responses to Generic Ltr 83-28, tem 2.2.1 re equipment classification program for all satety-related components.
 * NRC No Dotalled Affiliation Given 88/04/01. 4pp 45078:253-45078.272.
- 8804130357 Advises that temporary waiver of compliance not Issued in conjunction w/ emergency licensing amend granted for plants for first time,per guidance from HR Denton 870227 memo. Twelvo waivers have then Issued since Shally rule in effect. STELLO,V. Ofte of the Executive Director for Operations. 88/04/06. ROBERTS,T.M. Commissioners. 2pp. 45117:016-45117.017.
- 8804190093 Forwards Amonds 130 & 133 to Licenses DPR-44 & DPR-56, respectively & safety evaluation Amends and surverlance requirements for time delay feature of reactor protection says alternate power supply undervollage protective device MARTIN,R E. Project Directorate 1-2 88/04/08 BAUER,E.G. Philadelphia Electric Co. 3pp. 45155:230-45155:245.
- --8804190099 Amends 130 & 133 to Licenses DPR-44 & DPR-56, respectively, adding suvolllance requirements for time dotay feature of undervoltage protective device for reactor protection systetionate power supply.

 BUTLER,W.R. Project Directorate 1-2 88/04/06 10pp. 45155-233-45155-242
- --8804190108 Safety evaluation supporting Amends 130 & 133 to Licenses DPR-44 & Book 19 106 Sarry dyaldalion supporting Alliands 130 & 133 to Eleanes DPA-44 & OPR-56, respectively.

 * Office of Nuclear Reactor Regulation, Director (Post 870411): 88/04/06 3pp. 45155-243-45155-245.
- 8804080088 Generic Ltr 88-07 to power roactor licensees 8 applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safuty for Nuclear Power Plants "Svc list enct. MIRAGLIA,F J. Associate Director for Projects (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164-285.
- 8804120236 Staff requirements memo on 880331 affirmation/discussion & vote in Washington,DC re SECY-88-066 concerning Commonwealth of PA 880122 second petition for hearing on facility. CHILK,SJ. Office of the Secretary of the Commission. 88/04/07. PARLER,W.C. Office of the General Counsel 1p. 45100 300-45100:300.
- 8804130361 Forwards Sections I & II of Rev 1 to "Plan for Restart of Peach Bottom Atomic Power Station," per 880318 commitment. Rev Incorporates second & third recommendations from ZT Pato 880111 Itr.Rev summary & activities schedule also
- encl.
- PAQUETTE, J.F. Philadelphia Electric Co. 86/04/08. RUSSELL, W.T. Region 1, Oic of the Director, 10pp. 45166 098-45187:104.
- --8804130366 Rev 1 to Section I, "Corporate Action," of "Plan for Restart of Peach Bollom Atomic Power Station"
 * Philadolphia Electric Co. 88/04/08, 113pp. 45166:108-45166 235.
- --8804190397 Rev 1 to Section II, "Peach Bottom Atomic Power Station Action," of "Plan for Restart of Peach Bottom Atomic Power Station." Philadelphia Electric Co. 89/04/08. 214pp. 45166 238-45167:104.
- 8804150225 Informs of planned change in util method of performing QC monitoring of shift operations Present full shift coverage will be modified to include scheduled random monitoring of afternoon & night shifts by 860418.

 MCNEILL,C.A. Philadelphia Electric Co. 88/04/08. RUSSELL,W.T. Region 1, Otc of the Director, 2pp. 45131:360-45131:361.
- 8804250020 Forwards util response to INPO 880111 ltr re Rev 1 to facility restart plan,per 880304 request.
 MCNEILL,C.A. Philadelphia Electric Co. 88/04/15. RUSSELL,W.T. Region 1, Olc of the Director, 6pp. 45237:164-45237:169.

Q. Inspection reports, IE Bulletins & correspondence

- 8804010144 Advises that future correspondence re-msp & enforcement should be audressed to CA McNed Executive Vice President Nuclear MCNEILL, CA Physiologia Electric Co 88/03/25 RUSSELL, W.T. Rogen 1, Ofc of the Director. Ip. 45020 016-45020 016
- 8803210090 Suppl 1 to IRC Into Notice 87-044, "Thimble Tube Trinning in Westing-house Reactors," Sic List end. ROSS/C.E. Division of Operational Events Assassment (Post 870411) 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995 128 44995 246

- 8803220295 NRC Into Notice 88-010, "Matts Liconsces Lack of Mgt Controls Over Li-censed Programs." Svc list cncl. CUNNINGHAMR E Owiston of Industrial & Medical Nuclear Safety (Post 870729), 887-03728. Consol stated Edison Co. of New York, Inc. 108pp. 44935-247-44995-353.
- 8804040091 Responds to NRC 880228 ftr re-victations noted in linsp Ropis 50:277/88-01 & 50:278/88 01.Corrective actions worker involved suspended from respiratory qualification list until re-litted for ultraview respiratory on 880126 GALLAGITER, W. P. Pladespina Electric Co. 88/03/28 KANE,W.F. Region 1, Ofc. of the Director 4pp. 44970-303-44970-306.
- 8604078332 Requests addit into needed to evaluate valve operability conditions in ac-cordance w/IE Buttetin 88-003, "Motor- Operated Valve Common Mode Farures During Plant Transients Due to Improper Switch Settings" WENZINGER,E.C. Region 1, Otc of the Director 88/03/29 KEMPER,U.S. Philadelphia Electric Co. 4pp. 45021.243-45021:246
- 8804110310 Forwards Insp Repts 50 277/88-05 & 50-278/88-05 on 800208-12 & notice of violation.

 BELLAMY, R.R. Region 1, Ofci of the Director 89/04/04, KEYPER, J.S. Philadelphia Efectric Co. 3pp. 45128-178-45128-193
- --8804110312 Notice of violation from insp on 880208-12 Violation notation Agreement State license did not sulhorize receipt of Intium during 871125 transfer 8 fedure to verity recipent license prior to transfer of radioactive mall.

 ' Region I. Ofc of the Director. 88/04/04 1p 45128:181-45128.181.
- ~8804110319 Insp. Repis 50.277/68-05 & 50-278/88-05 on 880208-12. Violations rolled Major areas inspected solld radwasto & radioactive mail shipping program, including centrol, and octenwistry & implementation of programs. BICEHOUSE.H.J. PASCIAK.W.J. Region 1, Old of the Oraclor, 88/03/20 12pp. 45128:182-45128 193
- 8804120049 Forwards Radiation Safety Insp Ropts 50:277/68-07 & 50:278/fi8-07 on 880216-19 Violation re-fack of procedure for calibr & source checking of portal monitorial source checking of tors noted. BELLAMY.R.R. Region 1. Ofc of the Director, 88/04/04. KEMPER,J.S. Philadelphila Electric Co 3pp 45142 154-45142 163.
- --8804120053 Safety Insp. Repts 50-277/88-07 & 50-278/08-07 on 880216-19. Violation redict Major areas inspected worker allegation to use of respiratory protection. A hot spot shielding in Unit 3 drywell & retraining facility staff in radiation protection. DRAGCUM,T. THOMS.W., SHANBAKY,M. Region 1, Ofc of the Director. 88/03/31, 7pp. 45142,157-45142-163.
- 8804120200 Forwards Safety Insp. Repts 50-277/68-02 & 50-278/68-02 on 880206-0311 & natice of violation KANE,W.F. Rogion 1, Ofc of the Director, 86/04/04, KEMPER,J.S. Philadelphia Elec-tric Co. 2pp. 45130:279-45130:315.
- ~8804120209 Partially withheld notice of violation from insp on 880206-0315 (ref 10CFR73.21) Viciation noted unlocked & unattended vehicle parked in util vital grea on 660220 Fleg'on 1, Old of the Director, 88/04/04, 1p. 45130-281-45130-281.
- ~8804120212 Insp. Repts 50-277/88-02 & 50-278/88-02 on 880206-0311 Violation noted Major larges inspected accessible portions of operational safety radiation protection, physical security, control room activities & licensee events. WILLIAMS_JH. LINVILLE_J.C. Region 1, Ofc of the Director 88/03/29, 34pp. 45130-282-45130-315.
- 8804130162 Ack receipt of 890311 ltrs amending util 880226 & 26 ltrs informing NRC of steps taken to correct violations noted in Insp Repts 50:277/87-37,50:278/87-37 & 50:352/87-20.
- BELLAMY, R.R. Region 1, Ofc of the Director, 88/04/04 KEMPER, J.S. Philadelphia Electric Co. 2pp. 45154:099-45164;111.
- 8804010256 NRC Into Notice 98-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faully Tie Botts." Svc list enct. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Cansolidated Edison Co. of New York, Inc. 124pp. 45406 292 45407.051.
- 8804140501 Notification of 880421 meeting w/util 8 GE in Rockwille,MD to discuss in-consee plans & bases for inspecting shroud support access hole covers on facility re-cracks found in Unil 3 covers. MARTIN,R E. Project Directorale I-2. 88/04/08 BUTLER,W.R. Project Directorate I-2. 3pp. 45130.154-45130:156
- 8804150230 Responds to 880205 NRC Bulletin 88-01 re defects in Westinghouse circuit breakers for facilities Westinghouse DS series circuit breakers not used at plants. Other provisions of bulletin do not apply to plants KOWALSKI, SJ. Philadelphia Electric Co. 88/04/08. RUSSELL, W.T. Region 1, Ofc of the Director. 2pp. 45138.028-45138-029.
- 8804220077 Notification of canceled 880421 meeting w/util 8 GE in Rockville,MD to discuss ticensed plans 8 bases for inspecting shroud support access hole covers on Unit 2 re cracks found in Unit 3 covers on 880122. MARTIN,R.E. Project Directorate I-2, 88/04/08, BUTLER,W.R. Project Directorate I-2, 3pp. 45201:067-45201.089.
- 8804200036 Summarizes 880322 meeting w/u/lis re plant restart review process.NRC to conduct Integrated performance assessment team inspito assess effectiveness of implementation of licensee plan List of attendees end. KANE.W.F. Region 1, Otc of the Orector, 88/04/11, MCNEILL,C A. Philadelphia Efectio Co. 4pp. 45226:186-45228:189.

- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Sza nat gric. #OSSIC E. Dwision of Operational Events Assessment (Post 870411). 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165-150
- 8804210380 Ack receipt of 889201 ftr informing NRC of steps taken to correct violations noted in linsp Ropts 50:277/87-23 & 50:278/97-23 GALLOR M. Region 1, Otc of the Director. 88/04/15. MCNEILL, C.A. Piwadelpha Electric Co. 2pp. 45226.350-45226.355
- 88D425D159 Forwards Insp Repts 50-277/88-09 & 50-278/88-09 on 880228-0303 & natice of violation BELLAMY, R.R. Rogion 1. Ofc of the Director, 88/04/16, KEMPER J.S. Priladelphia Electric Co. 2pp. 45224:161-45224:169
- 8804250180 Notice of violation from insp on 880229-0303 Violation noted licensee did not maintain documentation of 1883 annual amergency preparedness audit & did not partorm annual audit during 1985.
 * Region I, Ofc of the Director, 88/04/16, 1p. 45224;163-45224 163

-8804250162 Insp Flepts 50-277/88-09 & 50-278/88-09 on 880229-0303 Violations roted Mejor areas inspected emergency preparedness program review of previously identified insp findings 8 changes to emergency preparedness program GORDON,C Z. LAZARUS,W J. Region 1, Olc of the Director. 88/04/12. Epp 45224 164-45224-189.

R. Periodic operating reports & related correspondence

- 8804220040 Month'y operating repts for Mar 1988.W/880415 ftr MIDDLETCN,L L., ALDEN,W M. Philadelphia Electric Co. 88/03/31 14pp 45221.335
- 8804120225 Forwards periodic status rept for 880314-31.Rept intended to provide NRC mpt 8 public w/overview of plant activities 8 NRC insplactivities. LINVILLEJ C. Region 1, Ofc of the Director 68/04/07. KANE,W.F. Region 1, Ofc of the Director 4pp. 45079 302-45079.305.

U. Congressional/Executive Correspondence

- 8804130356 Responds to 880212 ftriratsing number of concerns religiant. Decision to permit restart will not be made until Commission convinced that previous problems corrected & that operation of facility in sale manner assured ZECH.L.W. Commissioners. 88/04/07. SCHAEFER.W.D. Maryland, State of 5pp. 45412.351-45412.358.
- --8802260098 Discusses issues surrounding facility State of MD has no formal standing in review process NRC should identify specific restart criteria SCHAEFER,W.D. Maryland, State of, 88/02/12, ZECH,L.W. Commissioners. 3pp. 45412-356. 45412-358.

V. Operator Examinations

- 8804150225 Informs of planned change in util method of performing OC monitoring of shift operations. Present full shift coverage will be modified to include scheduled random monitoring of afternoon 8 night shifts by 880418
 MCNELLC.A. Philadelphia Elactric Co. 88/04/08 RUSSELL.W.T. Region 1, Oto of the Director 2pp. 45131:360-45131:381.
- 8804250088 Responds to FOIA request for Info re-scores of reactor operators & senior reactor operators Forwards requestication exam summary source sheets isled in encl app w/personal privacy into deleted GRIMSLEY.DH. Division of Rules & Records (Post 870413). 88/04/19 BOLEY.K. Public Critzen's Critical Mass Energy Project. 2pp. 45213:003-45213.095.
- --8804250167 Package of NRC administered requalification exam results summary.

 NRC No Detailed Affiliation Given, 87/07/20, 88pp. 45213:007-45213.095.

DOCKET 50-280 SURRY POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8803080803 Forwards exemption granting 840706 request, revised on 860410.0930 8 871016, for exemption from requirements of 10CFR50, App R Exemptions & requests requiring no exemption listed Safety explication also enc.

 VARGA, S.A. Division of Reactor Projects / I/II (Post 870411). 88/02/25. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.), 5pp. 44633-250-44633-250. 44633 297
- --8803080094 Exemption from requirements of 10CFR50,App B.includ.ng containment incore instrument tunnels to extent that redundant excore neutron flux detector cables not separated by horizontal distance of more than 20 ft. VARGA,S.A. Division of Reactor Projects I/II [Post 870411]. 88/02/25. Virgin a Power (Virgin.a Electric & Power Co.). 7pp. 44633:255-44633:261.
- --8803080107 Safety evaluation accepting util 840706 request for exemption from re-quirements of Sections III G.III J. III.L. of 10CFR50.App R & addl into submitted on 841130,860410,9330 & 871016. *Office of Nuclear Reactor Regulation, Director (Post 870411). 88/02/25 35pp
- 8803250156 Forwards draft Rev B to IE Insp Procedure 82412, "Emergency Response Facilities Appraisal." ERF appraisal will be conducted using team approach per recommended insp assignment matrices in procedure.

 COLLINS,D.M. Region 2, Otc. of the Director, 88/03/16, STEWART,W.L. Virginia Power (Virginia Electric & Power Co.), 39pp. 44814:228-44914:286.

- 8804070142 Forwards first 1988 semiannual rev to emergency response plan Changes do not decrease effectiveness of plan & plan continues to meet sids of 10CFH50.47(b).
 STEWART.W.L. Virgin:a Power (Virginia Electric & Power Co.), 88/03/30. Document Control Branch (Document Control Desk) 1p. 45044:164-45044:164
- 8804140047 Advises that 880308 Rov 12 to guard training & qualification plan consistent w/provisions of 10CFR50.54(p) & accopitable.

 CLINE,W.E. Region 2, Ofc of the Director, 88/04/08. STEWART,W.L. Virginia Power (Virginia Efector & Power Co.). 3pp. 45155:056-45155:057.
- 8804200473 Partial response to FOIA request re line protection.Forwards App E documents App D & E documents available in PDR.App F document completely withheld (ref FOIA Exemption 5).
 GRIMSLEY,D H. Dwision of Rules & Records (Post 870413). 88/04/14. JONES,C.R Affiliation Not Assigned 5pp. 45206.037-45206.043
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type losp for each facility to assess status of compliance w/ 10CFR50 48.Program listed.
 CONLONT.E. Region 2. Oto of the Director. 84/11/06 HERDT,A.R. Region 2, Oto of the Director. 3pp. 45208:176-45208:178.
- 8804250200 Responds to NRC 860317 ltr re violations noted in Insp Repts 50:280/88-07 & 50:281/88-07. Corrective actions station hose houses were inspected & restocked to ensure that necessary fire protection equipment was available. CRUDENDS Virginia Power (Virginia Electric & Power Co.). 88/04/15. Document Control Branch (Document Control Desk). 3pp. 45281:283-45281:285.

i. Financial Information

8804120382 Forwards listed into re licensee guarantees of payment of deferred promiums including annual rept to Socurities & Exchange Commission for 1987 & comparative statement of income for 3 months ended Dec 1986 & 1987 STEWART.W.L. Virginia Power (Virginia Electric & Power Co). 88/03/31. Document Control Branch (Document Control Desk). 72pp. 45091:076-45081:141.

J. Insurance & Indemnity information

8804120382 Forwards listed into re liconsed guarantees of payment of deforred premiums including annual rept to Securities & Exchange Commission for 1987 & comparative statement of income for 3 months endout Dec 1986 & 1987. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 88/03/31. Document Control Branch (Document Control Besk). 72pp. 45091:076-45091:141.

P. Operating license stage documents & correspondence

- 8803080520 Forwards revised Tech Spec Page 4.1-9 to 880217 Amends 117 to License DPR-32 & DPR-37,inadvertently left out of amend packago. PATEL,C.P. Project Directorate II-2, 88/03/02, STEWART,W.L. Virgin'a Power (Virgin Electric & Power Co.) 2pp. 44639.058-44639:060
- --8803080522 Revised Tech Spot Page 4.1-9 to Amond 117 to Liconses DPR-32 & DPR-37,respectively.

 * NRC No Detailed Affiliation Given, 88/03/02, 1p. 44639,060-44639,060.
- 8603240426 Generic Lir 88-06 to all power reactor licensees & applicants re removal of organization charts from Toch Spec administrative control requirements Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153
- 8804040070 Requests that NRC exercise enforcement discretion re implementation of organizational changes until amends issued,as result of 880325 folcon w/NRC re 880317 request for Tech Specs changes.
 STEWART,W.L. Virginia Power (Virginia Electric & Power Co.), 88/03/28. Document Control Branch (Document Control Desk), 2pp. 45031:293-45031:294.
- 8804050204 Forwards SER & EGG-NTA-7378 accepting util response to Item 2.2 (Part 1) of Generic Lir 83-28, "Equipment Classification (Program For All Safety-Related Components)."
 PATEL,C. Project Directorate II-2, 88/03/29. STEWART,W.t.. Virginia Power (Virginia Electric & Power Co.). 3pp. 44997:082-44897:108.

- 44997.085-44997:108.
- 8804060268 Application for amends to Licenses DPR-32 & DPR-37, changing Tech Specs to clarify requirement for retaining primary records of inservice inspectormed.per ASME Section XI.Fee paid.

 STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 88/03/30. Document Control Branch (Document Control Desk). 3pp. 45046:122-45046:130.

- --8804060271 Proposed Tech Specs, clarifying requirement for retaining primary records of inservice Insp performed per ASME Section XI.
 * Virginia Power (Virginia Electric & Power Co.). 88/03/30, 6pp. 45046:125-45046:130.
- 8804110243 Ack receipt of 880223 ltr requesting relief from operablisty requirements of Tech Specs 3.13 & 3.14 during planned svc water valve replacement Discretionary enforcement action greated for two 72 h periods.per 880322 telcon. GRACE_JN. Region 2. Ofc of the Director, 88/03/30. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 1p. 45077:343-45077:343.
- 8604080086 Generic Ltr 88-07 to power reactor ficensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Sec list encl. MIRAGI.A.F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 48pp. 45164:237-45164:285.
- 8804210407 Forwards notice of consideration of issuance of amends to Licenses DPR-32 &DPR-37 & opportunity for hearing re 880129 application.Amends revise Tech Specs re heatup & cooldown limits on reactor coolant temp & pressure. PATEL,C. Project Directorate II-2, 88704/07, STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 2pp. 45192:176-45192:182.

- --8804210413 Notice of consideration of Issuance of amends to Licenses DPR-32 & DPR-37 & apportunity for hearing Amends revise Tech Specs by revising heatup & cooldown I mits on reactor coolant temp & pressure. BERKOW,H N. Project Directorate II-2. 86704/07. Spp. 45192.178-45192 182
- 8804260003 Discussos containment integrated foakage rate testing mass point mothod for Type A testing per recent proposed rule change issued for comment that to conducting test for min 24 h., CRUDEN,D.S. Virginia Power (Virginia Electric & Power Co.), 88/04/08 Document Control Branch (Document Control Desk) 1p. 45281:330-45281.330.
- 8804130269 Forwards roy to 850830 proposed Tech Spec changes to inservice Insp & testing in response to concerns relised by NRC Specific responses to NRC reviewer concerns & safety evaluation also encl.

 CRUDEN,D.S. Virgina Power (Virginia Electric & Power Co.). 88/04/11. Document Control Branch (Document Control Dosk). 3pp. 45137.328-45138.014.
- --8804130270 Rev to proposed Tech Specs re inservice Insp & testing requirements

 * Virginia Power (Virginia Electric & Power Co.) 88/04/11. 44pp. 45137-33145138;014.

- 8803250156 Forwards draft Rev B to IE Inep Procedure 82412, "Emergoncy Response Facilities Appraisal." ERF appraisal will be conducted using learn approach per recommended insp assignment maintees in procedure COLLINS,D.M. Region 2, Oic of the Director. 88/03/16. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 39pp. 44914:228-44914:268
- 8804010019 Confirms 880328 enforcement conference w/util in Region II ofc to discuss Inp value operability 8 boric acid pipe heat tracing issues.
 GRACE J.N. Region 2, Olc of the Director. 88/03/21. STEWART,W.L. Virgin a Power (Virginia Electric & Power Co.). 1p. 45031:173-45031:173.
- 8604010046 Forwards Insp Repts 50-280/88-04 & 50-281/88-04 on 880201-27.Escalatod enforcement action for identified violation under consideration. Unresolved items, also identified in rept, wit to pursued during hiture insps. GRACE_JN, Region 2, Ofc of the Director, 88/03/21, STEWART, W.L. Vuginia Power (Virginia Electric & Power Co). 2pp. 45010.002-45010.017.
- --8804010047 Insp. Repts 50-280/88-04 & 50-281/88-04 on 880201-27. Vioration noted fallure to maintain & verily operability of heat trace circuity for boric acid flow path as required by Tech Spacs Util will be notified to escalated enforcement. HOLLAND, W.E., NG-HOLSON, L.E., CANTRELL, F.S. Reg on 2, Ofc of the Director. 98/03/17, 14pp. 45010:034-45010:017.
- 8803310012 Responds to NRC 880225 for re-violations noted in Insp Repts 50-280/88-01 & 50-281/88-01-Corrective actions policy is procedure deviations modified to strengthen steps required prior to procedure changes.

 STEWART,W.L. Vriginia Power (Virginia Electric & Power Co.). 88/03/25. Document Control Branch (Document Control Dask). 5pp. 44965:109-44965:113.
- 8804080344 Ack receipt of 880226 ftr informing NRC of steps taken to correct violations & daviations noted in Insp. Repts 60:280/87-32 & 50:281/87-32.

 JULIAN,C.A. Region 2, Ofc of the Director. 88/03/25. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 1p. 45010:264-45010:264.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning In Westinghouse Reactors," Svc list encl.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 88-010, "Matte Licensons-Lack of Mgt Controls Over Licensed Programs." Svc l'st enct.
 CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729) 88/03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995.247-44995.353.
- 8804060288 Application for amends to Licenses DPR-32 & DPR-37, changing Tech Specs to clarify requirement for retaining primary records of inservice Inspire performed per ASME Section XI.Fee paid.

 STEWART.W.L. Virginia Power (Virginia Electric & Power Co.). 88/03/30. Document Control Branch (Document Control Desk). 3pp. 45046:122-46048:130.
- --8804060271 Proposed Tech Space clarifying requirement for retaining primary records
 of inservice inspiperformed,per ASME Section XI.
 ¹ Virginia Power (Virginia Electric & Power Co.). 88/03/30. 6pp. 45046.125-45046:130.
- 8804120234 Responds to IE Bulletin 88-001, "Defects in Westinghouse Circuit Breakers." No Westinghouse Type DS breakers used at plant. CRUDEN,D.S. Virginia. Power (Virginia. Electric. & Power Co.). 88/04/05. Document Control Branch (Document Control Døsk). 2pp. 46090:045-46090:048.
- 8804110322 Forwards partially withheld Insp Repts 60-280/88-08 & 50-281/88-08 on 880307-111 No violations or deviations noted. CLINE, W.E. Region 2, Oic of the Director. 88/04/06. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 2pp. 45122:008-45122:008.
- ---8804110328 Partially withheld insp. Repts 50:280/68-08 & 50:281/68-08 on 880307-11 (ref. 10CFR2,790(d) & 73:21).No. violation noted, Major areas inspected records & repts tosting & maint.locks, keys & combinedions.

 MASNYK,O.M., STANSBERRY,W.W., MCQUIRE,D.R. Region 2, Ofc of the Director. 88/03/30. 1p. 45122 008 45122 008.
- 8804010258 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Boits," Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidatod Edison Co. of New York, Inc. 124pp. 45406 292-45407:051.
- 8804130269 Forwards ray to 850830 proposed Tech Spec changes re Inservice inap & testing.in response to concerns raised by NRC Specific responses to NRC reviewer concerns & safety evaluation also enci. CRUDEN.D.S. Virginia Power (Virgin & Electric & Power Co.), 88/04/11. Document Control Branch (Document Control Deak), 3pp. 45137:328-45138:014.

8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Syc

list enci. ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165.150.

8804200473 Partial response to FOIA request re fire protection Forwards. App. E. documents App. D. & E. documents available in PDR App. F. document completely withheld (rel. FOIA Exemption 5).
GRIMSLEY.D.H. Division of Rules & Records (Post 870413), 88/04/14, JONES,C.R. Affiliation Not Assigned, 5pp. 45206:037-45206:043.

~8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type linsp for each facility to assess status of compliance w/ 10CFR50 48 Program listed CONLON.T.E. Region 2, Oit of the Director. 84/11/08. HERDT,A.R. Region 2, Oit of the Oirector. 3pp. 45206;176.45206.178

8804250200 Responds to NRC 880317 ftr re violations noted in Insp. Repta 50-280/88-07 & 50-281/88-07 Corrective actions station hose houses were inspected & restocked to ensure that necessary the projection equipment was available. CRUDEN D.S. Virginta. Power (Virginta Electric & Power Co.). 88/04/15. Document Control Branch (Document Control Desk), 3pp. 45281-283-45281-285.

8804260228 Forwards Insp Repts 50-280/88-09 & 50-281/88-09 on 880228-0402.No volations or deviations roted.
WILSON,B A. Region 2, Old of the Director, 88/04/15, CRUDEN,D S. Virginia Power (Virginia Efector, & Power Co.), 2pp. 45254:240-45254:249.

**8804260232 Insp Repts 50-280/88-09 & 50-281/88-09 on 880228-0402 No violations of devations noted Major areas inspected plant operations, plant maint, plant surveil lance & LEF review.

HOLLAND, W.E. NICHOLSON, L.E., CANTRELL, F.S., Region 2, Old of the Director, 88/ 04/14. 8cp. 45254.242-45254.249

8804270051 Ack receipt of 880325 ftr Informing NRC of steps taken to correct violations noted in Irsp Repis 50-280788.01 & 50-281788.01. WILSON B.A. Region 2, Oko of the Director. 88/04/16 CRUDEN.D.S. Virginia Power (Virginia Electric & Power Co.). 1p. 45245:281-45245.281.

8804280072 Forwards Insp Repts 50:280/88:10 & 50:281/88:10 on 880305-11 & 23-25. Violations noted & under consideration for escalated enforcement action. Enforcement conference to discuss violations scheduled for 880421. GRACE.J.N. Region 2, Otc of the Direction 88/04/18. CRUDEN,D.S. Virginia Power (Virginia Electric & Power Co.). 2pp. 45268:177-45268:203.

-8804260075 Insp Repts 50-280/88-10 & 50-281/88-10 on 880305-11 & 23-25. Violations nated faiture to adequately evaluate radiation hazards present during work on incore detector & to conduct operations in accordance w/approved procedures. BASSETT, C.H., HOSEY, C.M. Region 2, Oic of the Director. 88/04/15. 25pp. 45268:179 45268:203

S. Reportable occurrences, LERs & related correspondence

8804130308 LER 88-009-00 on 880311.specific activity sample of reactor coolant showed dose-aguivatent t-131 level of 1.5 uCl which exceed fech Spec limit Caused by fucl element defect in reactor core.W/880405 ltr.

BENSONO.L. Viginia Power (Virginia Electric & Power Co.). 88/04/05. 4pp. 45150.357-45150.360.

8804140048 LER 88 008-00.on 880309 low head salety injection pump inoparable due to tailed motor feads.Cause under evaluation. Motor replaced & returned to svc.W/ 880408 Itr BENSON DI

BENSON.D1. Virgina Power (Virgina Efectric & Power Co.). 88/04/08. 4pp. 45147:321-45147:324.

V. Operator Examinations

8804250088 Responds to FOIA request for into re-scores of reactor operators & sentor reactor operators. Forwards requalification exam summary source sheets listed in encil app w/personal privacy into deleted.

GRIMSLEY,O.H. Dwiston of Rules & Records (Post 870413) 88/04/18. BOLEY,K. Public Citizen's Critical Mass Energy Project. 2pp 45213 003-45213.095.

-8804250167 Package of NRC administered requalification exam results summary. NRC - No Detailed Affiliation Given, 87/07/20, 88pp. 45213:007-45213:095

Y. Dry Cask Independent Spent Fuel Storage Installations

8804120291 Advises that 880308 Rev 12 to Surry (SFS) guard training & qualification plan consistent w/provisions of 10CFR72 84(b) 10CFR72.84(b) & acceptable. CLINE,W.E. Region 2, Ofc of the Ovector, 68704/06, STEWART,W.L. Virginia Power (Virginia Electric & Power Co.) 3pp. 45146-013-45146-015.

DOCKET 50-281 SURRY POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8803080083 Forwards exemption granting 840706 request revised on 860410,0930 & 903080083 Forwards exemption granting 840706 request revised on 850410,0930 & 871016, for exemption from requirements of 10CFR50, App R Exemptions & requests requiring no exemption listed. Safety evaluation also end: VARGAS A. Division of Reactor Projects - IVII (Post 870411). 88/02/25. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 5pp. 44633.250-44633.250

~8803080094 Exemption from requirements of 10CFR50.App R including containment incore Instrument tunnels to extend that redundant accore neutron flux detector cables not separated by horizontal distance of more than 20 ft. VARGA, S. Divistan of Reactor Projects - 1/N (Post 870411). 88/02/25. Virginia Power (Virginia Efectric & Power Co.), 7pp. 44633:255-44833.261. --8803080107 Safety evaluation accepting util 840706 request for exemption from requirements of Sections III.G.III.J III.L of 10CFR50,App R & addl into submitted co 841130,860410,0930 & 871016.

*Office of Nuclear Reactor Regulation, Director (Post 8704111 88/02/25 36pp

44633 262-44633 297

8803250156 Forwards draft Rev B to IE Insp Procedure 82412, "Emergency Rosponse Facilities Appreliast" ERF appreliast will be conducted using team approach per recommended insp assignment matrices in procedure. COLLINS,D.M. Regon 2, Old of the Director, 88703/18, STEWART,W.L. Virgin'a Power (Virginia Electric & Power Co.), 38pp. 44914:228-44914:268.

8804070142 Forwards first 1988 semiannual rev to emergency response plan-Changos do not decrease effectiveness of plan & plan continues to meet side of 10CFR50.47(b).
STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 88/03/30. Document Control Desk). 1p. 45044;164-45044;164.

8804140047 Advises that 880008 Rev 12 to guard training & qualification plan consistent w/provisions of 10CFR50.54(p) & acceptable.

CLINE,W.E. Region 2, Otc of the Director, 88/04/08, STEWART,W.L. Virginia Power (Virginia Efectric & Power Co.), 3pp. 45155-056-45155.057.

8604200473 Partial response to FOIA request re tire protection.Forwards App E documents.App D & E documents available in PDR.App F document completely withheld (ref FOIA Examption 6).
GRIMSLEY,DH. Division of Rules & Records (Post 870413). 86/04/14, JONES,CR Attituation Not Assigned. Spp. 45206:037-45208:043.

--9804200579 Advisss that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type insp for each faculity to assess status of compliance w/ 10CFR50,48Program listed.
CONLON.T.E. Region 2, Ofc of the Director. 84/11/06. HEROT,A.R. Region 2, Ofc of the Director. 3pp. 45206:178.45206:178.

8804250200 Responds to NRC 880317 ltr re violations noted in Insp Repts 50-200703 804290200 Responds to NHC 880317 lit re violations noted in insp Hepis bu-zuuroo-07 & 50-281/88-07. Corrective actions:station hose houses were inspected & re-slocked to ansura that necessary fire protection equipment was available. CRUDEN,D.S. Virginia Power (Virginia Electric & Power Co.). 88/04/15. Document Control Branch (Document Control Desk.). 3pp. 45281:283-45281:285.

J. Financial Information

8804120382 Forwards listed into re licensee guarantees of payment of deferred premiums.including annual rept to Securities & Exchange Commission for 1987 & comparative statement of income for 3 months ended Dec 1986 & 1987. STEWART.W.L. Virginia Power (Virginia Electric & Power Co.) 88/03/31. Document Control Branch (Document Control Desk), 72pp. 45091;076.45091;141.

J. Insurance & Indemnity information

8804120382 Forwards listed into re licensee guarantees of payment of deforted pramiums including annual rept to Securities & Exchange Commission for 1987 & comparative statement of income for 3 months ended Dec 1986 & 1987. STEWART.W.L. Virginia Power (Virginia Electric & Power Co.) 88/03/31. Document Control Branch (Document Control Branch (Document Control Branch (Document Control Desk). 72pp 45091:076-48091:141.

P. Operating license stage documents & correspondence

8803080520 Forwards revised Tech Spec Page 4.1-9 to 880217 Amends 117 to License DPR-32 & DPR-37, inadvertently fett out of amend package. PATEL, C.P. Project Directorate In 2. 88/03/02. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 2pp. 44639.058-44639.060.

-8903080522 Revised Tech Spec Page 4.1-9 to Amend 117 to Licenses DPR-32 & DPA-37.respectively.
* NRC - No Detailed Affiliation Given. 88/03/02. 1p. 44639:060-44639:060.

8803240426 Generic Lit 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list enct. MRAGLIAF J. Associate Director for Projects (Post 670411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44872 107-44972;153.

8804040070 Requests that NRC exercise enforcement discretion re implementation of organizational changes until amends issued, as result of 880325 telcon w/NRC re 880317 toquest for Tach Specs changes.
STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 88/03/28 Document Control Desk). 2pp. 45031:293-45031:294.

8804050204 Forwards SER & EGG-NTA-7378 accepting util response to item 2.2 (Part I) of Generic Ltr 83-28, "Equipment Classification (Program For All Safety-Related Components)."
PATELC. Project Directorate II-2, 88/03/29, STEWART,W.L. Virginia Power (Virginia Electric & Power Co.), 3pp. 44997;082-44997;108.

--8804050211 SER accepting util 831104 & B50208 responses to Item 2.2.1 of Generic Ltt 63:28, "Equipment Classification Programs For All Safety-Related Components." Basis for NRG acceptance documented in EGG-NTA-7378.

Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/29, 7pp 44997.085-44997.108.

8804060288 Application for amends to Licenses DPR-32 & DPR-37, changing Tech Specs to clarify requirement for retaining primary records of inservice insperformed per ASME Section XI,Fee pald.
STEWART,W.L. Virginia Power (Virginia Electric & Power Co.), 88/03/30, Document Control Branch (Occument Control Desk), 3pp. 45046:122-45046;130.

--8804060271 Proposed Tech Space clarifying regultement for retaining primary records of inservice inspiperiormed per ASME Section XI.

* Virginia Power (Virginia Electric & Power Co.), 88/03/30, 8pp. 45048;125-45048;130

- 8894110243 Ack receipt of 880223 ftr requesting reflet from operability requirements of Tech Specs 3.13 & 3.14 during planned svc water valve replacement. Discretionary enforcement action granted for two 72 h poriods, per 880322 talcon GHACE, J.N. Rogon 2, Otc of the Director. 88/03/30. STEWART, W.L. Virginia Power (Virginia Efecting & Power Co.) 1p. 45077.343-45077.343
- 8604080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants" "Scc list onci MIRAGLIA,F. J. Associate Director for Projects (Post 870411) 88/04/07 Consolidated Edison Co. of New York, Inc. 49pp. 45164 237-45164 285.
- 8804210407 Forwards notice of consideration of Issuance of amends to Liconaus DPR-32 8DPR-37 & opportunity for hearing re-880129 application. Amenda revise Tech Spacs re-heating & cookdown limits on reactor cookent temp & pressure. PATELLG Project O rectorate II-2 88/04/07. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 2pp. 45192.176-45192.182.
- --8804210413 Notice of consideration of Issuance of amends to Licenses DPR-32 & DPR-37 & apportunity for hearing Amends rovise Tech Specs by revising heating & cooldown limits on reactor coolant temp & prossure.

 BERKOW.H N Project Directorate II-2: 88/04/07 Spp. 45192 178-45192 182
- 8804260003 Discusses containment integrated leakage rate testing mass point method for Type A lesting,per rocent proposed rule change issued for comment thit commits to conducting test for min 24 h. CRUDEN,D.S. Virginia Power (Virginia Efectic & Power Co.). 88/04/08. Document Control Branch (Document Control Desk). 1p. 45281:330-45281:330.
- 8604130269 Forwards rev to 850830 proposed Tech Specichanges to Inservice Insp. & testing in response to concerns relied by NRC Specific responses to NRC reviewer concerns & safety evaluation also enct.
 CRUDEN.DS Virginia Power (Virginia Electric & Power Co.). 88/04/11. Document Control Branch (Dacument Control Desk). 3pp. 45137-328-45138.014.
- -8804130270 Rev to proposed Tech Specs to inservice insp & testing requirements. Virginia Power (Virginia Electric & Power Co.), 88/04/11, 44pp 45137:331-45138:014.
- 8804250069 Advises that flow tests will be performed to verify acceptable flow rates to steam generators prior to returning unit to power per 880404 telcon. CRUDEN.D.S. Virginia Power (Virginia Electric & Power Co.). 88/04/11. Region 2, Ofc of the Director. 2pp. 45237:141-45237:142.

Q. Inspection reports, IE Builetins & correspondence

- 880/3250/156 Forwards draft Rev B to IE Insp Procedure 82412, "Emergency Response Facilities Appraisal." ERF appraisal will be conducted using toam approach per reccommonded inspessionment malrices in proceeding.

 COLLINS.D.M. Region 2, Ofc of the Director. 88/03/16. STEWART,W L. Virgin:a Power (Virginia Electric & Power Co.). 39pp. 44914:228-44914:266.
- 8804010019 Confirms 880328 enforcement conference w/util in Region II ofc to discuss trip value operability & boric acid pipe heal tracing issues. GRACE, J.N. Region 2, Ofc of the Director. 88/03/21. STEWART, W.L. Virgina Power (Virginia Electric & Power Co.). 1p. 45031:173-45031:173.
- 8804010046 Forwards Insp Repts 50-280/88-04 & 60-281/88-04 on 980201-27 Escalated enforcement action for identified violation under consideration Unresolved items, also identified in rept, will be pursued during future insps. GRACE_JN Region 2. Otic of the Director 88/03/21, STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 2pp. 45010.002-45010.017.
- -8804010047 Insp Repts 50-280/88-04 & 50-281/88-04 on 880201-27. Violation noted failure to maintain & verify operability of hoat trace circuitry for boric acid flow path as required by Tech Specs-Util will be notified to escalated enforcement. HOLLAND,WE, NICHCHOLSON,LE, CANTRELL,F.S. Region 2, Ofe of the Director, 88/03/17, 14pp. 45010.004-45010.017.
- 8803310012 Responds to NRC 880225 fir re violations noted in Insp Repts 50:280/88-01 8 50:281/88-01 Corrective actions policy re procedure deviations modified to strengthen steps required prior to procedure changes. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.), 88/03/26, Document Control Branch (Document Control Desk), 5pp. 44965.109-44965:113.
- 8804060344 Ack receipt of 880226 lit informing NRC of stops taken to correct violations & deviations noted in insp Repts 50-280/97-32 & 50-281/87-32. JULIAN,C.A. Region 2, Ofc of the Director. 88/03/25. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 1p. 45010-284-45010-264.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Washinghouse Reactors." Svc list encl. ROSSI, C.E. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995;128-44995.246
- 8803220296 NRC Into Notice 88-010, "Matte Licensees:Lack of Mgt Controls Over Li-censed Programs." Svc fist enct. CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28, Consolidated Edison Co. of New York, Inc. 108pp. 44995.247-44995.353.
- 8804060268 Application for amends to Licenses DPR-32 & DPR-37, changing Tech Specs to clarify requirement for retaining primary records of inservice inspiporformed per ASME Section XI Fee paid: STEWART, W.L. Virginia Power (Virginia Electric & Power Co.), 88/03/30, Occurrent Control Branch (Document Control Desk), 3pp. 45046:122-45046:130.
- ~8604060271 Proposed Tech Specs.clarifying requirement for retaining primary records of Inservice Insp performed.per ASME Section XI. Virginia Power (Virginia Electric & Power Co.), 88/03/30, 6pp. 45046:125-45046.130.
- 8804120234 Responds to IE Bulletin 88:001, "Defects in Westinghouse Circuit Breekers." No Westinghouse Type DS breakers used at plant CRUDEN,D.S. Virginla Power (Virginla Electric & Power Co.), 98/04/05. Document Control Branch (Occument Control Desk), 2pp. 45090:045-45090:046.

- 8804110322 Forwards partially withheld trisp Ropts 50-280/88-08 & 50-281/88-08 on 880307-f1.No violations or deviations noted CLINE, W.E. Region 2, Old of the Director, 88/04/06 STEWART,W.L. Virgin's Power (Virgin's Electric & Power Co). 2pp. 45122-006-45122-008
- --8804110328 Pertiany withherd this Repts 50:280/88-08 & 50:281/88-08 on 860307-11 (ref. 10CFR2 790(d) & 73.21) No. violation noted. Major areas inspected:records & ropts.tosting & mainflocts, keys & combinations. MASNYKO.M., STANSBERRY.W.W., MCGUIRE.D.R. Region 2, Old of the Director. 88/03/30 1p. 45122.008-45122.008
- 8804010256 NRC Inip Notice 88 011, "Potential Loss of Motor Control Ctr &/or Switchboard Function Due to Faulty Tie Bolts." Svc list encl.
 ROSSIC.E. Division of Operational Events Assessment (Post 870411), 88/04/07.
 Consolidated Edison Co. of New York, Inc. 124pp. 45408-292-45407 051.
- 8804130269 Forwards revito 850830 proposed Tech Spucichanges re Inservice Inspite tosting.in response to concerns raised by NRC Specific responses to NRC reviewer concerns & safety evaluation also encil CRUDEN,D.S. Virginia Power (Virginia Electric & Power Co.), 88/04/11, Document Control Branch (Document Control Branch (Document Control Desk), 3pp. 45137,328-45138-014
- -8004130270 Rev to proposed Tech Specs re inservice insp & testing requirements.
 Vrginia Power (Virginia Efectric & Power Co.) 88/04/11 44pp 45137:331-45138014.
- 8804080370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc 1st enc. ROSSI,C E Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165-150.
- 8804200473 Partial response to FOIA request re like protection.Forwards App E documents.App D & E documents aveilable in PDR.App F document completely withheld (rot FOIA Exemption 5)
 GRIMSLEY,D.H. Dw.s on of Rules & Records (Post 870413), 88/04/14, JONES,C R Affiliation Not Assigned, 5pp. 45206:037-465206.043.
- --8804200579 Adv.ses that Fire Protection Storing Committee has recommended that each region make one 10CFR50,App R-type inspitor each factily to assess status of compriance w/ 10CFR50.48.Program listed CONLON,T E. Region 2, Oic of the Director. 84/11/06. HERDT,A.R. Region 2, Oic of the Director. 3pp. 45206 176-45208:178.
- 980425020D Responds to NRC 880317 ftr ra violations noted in Insp Repts 50:280/88-07 & 50:281/88-07 Corrective actions statlon hose houses were inspected & restocked to ensure that necessary line protection equipment was available CRIUDEN,D.S. Virgina Power (Virginia Electric & Power Co.) 88/04/15 Document Control Branch (Document Control Desk), 3pp. 45281:283-45281:285.
- 8804260228 Forwards Insp Repts 50-280/88-09 & 50-281/88-09 cn 880228-0402 No
 - volations of deviations noted WILSON,B A Regton 2, Ofc of the Director, 88/04/15, CRUDEN,D S. Virginia Power (Virginia Electric & Power Co.), 2pp. 45254-240, 45254-249.
- --8804260232 Insp Repts 50-280/88-08 & 50-281/88-09 on 880228-0402 No violations or deviations noted Major areas inspected plant operations plant maint plant survoil Browship and Alexander and Ale 04/14. 8pp 45254:242-45254 249.
- BB04270051 Ack recorpt of 880325 ftr informing NRC of steps taken to correct violations noted in Insp Repts 50-280/88-01 & 50-281/88-01.
 WILSON B A. Region 2, Ofc of the Director. 88/04/15 CRUDEN,D.S. Virginia Power (Virginia Electric & Power Co.). 1p. 45245-281-45245-281.
- 8804260072 Forwards Insp Repts 50-260/88-10 & 50-281/88-10 on 880305-11 & 23-25 Violations noted & under consideration for escalated engagement action Enforcement conference to discuss violations scheduled for 880421. GRACE, J. Otto of the Director. 88/04/18. CRUDEN,D.S. Virginia Power (Virginia Erectric & Power Co.) 2pp. 45288 177-45288 203
- --8804260075 Insp. Repts 50-280/88-10 & 50-281/88-10 on 880305-11 & 23-25. Violations noted:fallure to adequately evaluate radiation hazards present during work on incore defector & to conduct operations in accordance w/approved procedures BASSETT_CH., HOSEY.C.M. Reg on 2, Oic of the Director. 88/04/15. 25pp. 45208:179-45268:203.

S. Reportable occurrences, LERs & related correspondence

- 804060301 PNO-II-88-020 on 880327,fo5s of power to vital bus III experienced Operator manually Inpped reactor then Inpped reactor coolant pump Unit later experienced automatic safety Injection Unit stabilized in hot shuldown CANTRELL,F.F. Region 2, Otc of the Director 88/03/29, 2pp 45034.183-45034:184. 8804060301
- 8804080038 LER 88-005-00 on 880305,control rod urgent failure alarm received in control roam. Caused by failed phase control card in 18D power cabinal Control room operator placed rod in manual per abnormal procedure for mallunction. W/880330 ftr. BENSON,D.L. Virginia Power (Virginia Electric & Power Co.). 88/03/30. 4pp. 45063:350-45063:353.
- 8804140051 LER 88-008-00 on 880310 line detection circuit for facility containment & emergency switchgear instrument rack room rendered inoperable Caused by failure of remole control module ElIS-IC IMOD Failed module replaced W/880408 ltr. BENSON,D.L. Virginia Power (Virginia Electric & Power Co.). 88/04/08. 4pp. 45158;314-46158;317.

V. Operator Examinations

8804250088 Responds to FOIA request for info re scores of reactor operators & sen or reactor operators Forwards requalification exam summary source sheets listed in encl app w/personal privacy into deleted. GRIMSLEY.D.H. Division of Rules & Records (Post 870413). 88/04/19. 80.LEY,K. Public Citizen's Critical Mess Energy Project. 2pp. 45213.003-45213.095.

-8804250167 Package of NRC administered requal-lication exam results summary.
NRC - No Detailed Attitation Given: 67/07/20, 88pp. 45213,007-45213,095.

Y. Dry Cask Independent Spent Fuel Storage Installations

8804120291 Advises that 880308 Rev 12 to Surry ISFSt guard training & qualification plan consistent w/provisions of 10CFR7284(b) 10CFR7284(b) & acceptable. CLINE WE Region 2, Otto of the Offsctor, 88040406, STEWART,WIL, Virgina Power (Virgina Electric & Power Co.) 3pp. 45146.013-45146.015

DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8804140039 Confirms special inspidales of 880718-22 established during 880405 telcon w/K Beauch to reavaluate compliance w/ applicable 10CFR50,App R sections Current revs to listed add into requested prior to pre-App R meeting HARRISON_J_Region 3, Ofc of the Director 88/04/07 LARSON_C.E. Northern States Power Co. 3pp. 45147:335-45147.337.

8804180252 Forwards Rev 8 to secunty force training & qualification plan per 100FR50 54(p) Rov withhold (ref. 100FR73) LARSON.C E. Northern States Power Co. 88/04/12. Document Control Branch (Document Control Dask), 1p. 45199 266-45198 266.

8804180258 Forwards Rev 18 to security plan.per 10CFR50.54(p).Rev withheld (ref 10CFR73). LARSON,C.E. Northern States Power Co. 88/04/12. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 45198:263-45198:263.

8804180261 Forwards Hev 2 to safeguards contingency plan,per 10CFR50.54(p).Rev withheld (ref. 10CFR73). LARSON,C.E. Northern States Power Co. 88/04/12. Office of Nuclear Reactor Regular on, Director (Post 870411). 1p. 45195-337-45195-337.

8804270274 Ack rece.pt of 880325 ltr re plant emergency plan exercise scheduled for 890622.Exercise scope & objectives acceptable. SHAFEH.WID Region 3, Dic of the Director. 88/04/19 LARSON,C.E. Northern States Power Co. 1p. 45242 360 45242 360

P. Operating license stage documents & correspondence

8803240426 Generic Etr 88.05 to all power reactor licensees & applicants re-removal of organization charts from Tech Spec administrative control requirements Svc 1st encl, MIRAGLIAF J. Associate Director for Projects (Pc st 870411) 88/03/22 Consolidated Edison Co. of New York, Inc. 47pp. 44872 107-44972:153

8804190083 Forwards notice of consideration of issuance of amends to Licenses DPR-42 & CPR 60 & opportunity for hearing concorning 870928 application
Di(4NNI,O.C. Project Directorate III.3, 88/04/05, MUSOLF,D.M. Northern States
Power Co. 3pp. 45158 288-45158 285

-8804180096 Notice of consideration of issuance of amend to License DPR-42 & DPR-60 Amend changes surveillance test frequency of turbine step valves in Tech Specs. VIRGILIO.M J. Project Directorate III 3, 68/04/05, 5pp. 45158291.45158295.

8804080088 Generic Utr 68-07 to power reactor I censees & applicants re-modified en-forcement policy concerning IOCFR50-49, "Environ Quaffication of Electrical Equip-ment Important to Safety for Nuclear Power Plants" "Svc list end MIRAGLIA.F. J. Associate Director for Projects (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 48pp. 45164 237-45164 285.

8804280101 Forwards Amends 62 & 75 to Licenses DPR-42 & DPR-60, respectively & safety evaluation Amends change Tech Specs 6.1-2,6.1.D & 6.5.G re administrative requirements per util 670614,278 & 80104 & 0210 applications. DILANNI,D.C. Project Directorate III-1, 88/04/18 MUSOLF,D.M Northern States Power Co. 3pp 45262-296-45262-309.

--8804280129 Amends 62 & 75 to Licenses DPR-42 & DPR-60,respectively, revising Tech Specs in response to 870814 application suppl by 870827,880104 & 0210 ltrs VIRGILIO,MJ, Project Orectorate III-1, 88/04/18, 8pp 45262 299-45262.306.

--8804280156 Saloty evaluation supporting Amends 82 & 75 to Licenses OPR-42 & DPR-80 respectively.

Ortico of Nuclear Reactor Regulation, Director (Post 870411). 88/04/18. 3pp. 45262 307-45262:300

Q. Inspection reports, IE Bulletins & correspondence

8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimbte Tube Thinning in Westing-house Reactors." Svc Ist encl. POSSIC E Dissort of Operational Events Assessment (Post 670411), 88/03/28. Consotrated Edison Co. of New York, Inc. 121pp. 44995;128-44995;246.

8803220296 NRC Inio Notice 68-010, "Mails Licensces Lack of Mgt Controls Over LIcensed Programs." See 1st enct.

CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 887
03728 Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353.

8804010266 Informs of plan to cancel Kewaunee mid-SALP team inspidue to licensee continued excellent performance in all areas.Region III Intent is to follow core program

DAVIS.A.B. Region 3, Ofc of the Director, 88/03/28, MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 1p. 44945;346-41945.346

8604150374 Responds to NRC Compliance Bulletin 88-003, "Inadequate Latch Engagement in HFA Type Latching Relays Mfg by GE." Subjitatching relays not used in Class IE svc at plant.

LARSONIC E. Northern States Power Co. 88/04/06. Document Control Branch (Document Control Desk), 2pp. 45138:181-45138 182.

8804010256 NRC Into Notice 88-011, "Potential Loss of Mater Central Cit &/or Switch-board Function Due to Faulty Tie Belts." Sec list enc! HOSSI,C.E. Division of Operational Events Assessment (Past 870411) 88/04/07, Consol riated Edison Co. of New York, Inc. 124pp. 45406 292-45407.051

8804140039 Confirms special inspidates of 880718.22 established duting 88040516/cor w/K Beadell to reevaluate compliance w/ applicable 10CFR50,App R sections Cutton revs to Listed add into requested prior to pre-App R meeting HARRISON,J Region 3, Ote of the Director 88704/07 LARSON,C E. Northern States Power Co. 3pp. 45147:335.45147.337.

8804200554 Provides final response to IE Bulletin 85,003, "Motor: Opinated Vene Common Mode Failures During Plant Transients Due to Improper Switch Settings' Program in plemented to ensure valve operator switch operational readinoss LARSON,CE Northern States Power Co. 88/04/08 Office of Nuclear Reactor Regulation, Director (Post 870411), 8pp. 45219-039-45219-047.

8804080370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings," Svc list end. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). BR/04/12 Consolidated Erison Co. of New York, Inc. 123pp. 45185.028-45185 150

8804210327 Forwards proprietary WCAP-11787 & nonproprietary WCAP-11788, "Prano-Island Units 1 & 2 Evaluation for Tube Vibration Induced Fatigue," in response to NRC Compliance Bulletin 88-002 & 880325 application to withhold proprietary info-LARSON,C E Northam States Power Co 88/04/12 Document Control Branch (Docu-ment Control Dosk). 3pp. 45194.001-45194:160

--8804210364 Requests that proprietary WCAP-11767, "Praine Island Units 1 & 2 Evatuation for Tube Vibration Induced Fallgue," be withhold from public disclosure (ref 10CFR2 790(b)(1)).
WIESEMANN,R.A. West righouse Electric Corp. 88/03/25. MURI EY,T. Office of Nuclear Reactor Regulation, Director (Post 870411). 10pp. 45194.004-45194.013

~8804210382 "Prairie Island Units 1 & 2 Evaluation for Tube Vibration Induced Fatigge"
CONNORS,H.J., FRICK,T.M., HALL,J.M. Westinghouse Electric Corp. WCAP 11788
88/03/31 210pp 45194-014-45194:160

R. Periodic operating reports & related correspondence

8804150133 Monthly operating repts for Mar 1988.W/980411 ftr. DUGSTAD.D., MUSOLF.D. Northern States Power Co. 88/03/31, 9pp. 45153:111-45153.119.

S. Reportable occurrences, LERs & related correspondence

8803290359 PNO-III-88-020:on 880310.sample results from Unit 1 sump indicated small amount of reactor coolant leakage showing measurements of loss than 0.1 gpm Visus! inspirevaled misting Inreactor head Reg on III monitoring situation FAREER, M. JACKIW, N. Region 3, Oic of the Director, 88/03/11 1p 44916-250-4006-250

V. Operator Examinations

8803300243 Informs of revito commitment made several yrs ago relitaining of licensed operators in response to Generic Lin 87.07. Facrity to conduct operator training in fulure in accordance w/accredited program
MUSQLF,D. Northern States Power Co. 88/03/21. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 44979 139-44979 139.

8804110054 Informs that operator & senior operator Ircensing exams scheduled for with a 880711 & 18 Requests properly bound & indexed ret matt at least 60 days prior to exam date.W/ stated encis. WRIGHT G.C. Region 3, Ofc of the Director, 86/04/06, LARSON,C.E. Northern States. Power Co., 10pp. 45129.310.45129.319.

8804160362 Informs of revito shift technical advisor (STA) training program originally provided to NRC in this B10130 lin. Revidue to completion of STA task tist for accredited STA program.
MUSOLF,D. Northern States Power Co. 88/04/08. Document Control Branch (Document Control Dask). 1p. 45138.205-45138 205.

8804250088 Responds to FOIA request for into re-scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in enclusive mylersonal privacy into deleted.

GRIMSLEY.D.H. Division of Rules & Records (Post 870413). 88/04/19 BOLEY.K. Public Citizen's Chilical Mass Energy Project. 2pp. 45213:003-45213:095.

--8804250167 Package of NRC administered requalification exam results summary.
NRC - No Detailed Alfiliation Given, 87/07/20, 88pp. 45213:007-45213:095.

POCKET 50-284 IDAHO STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of retocation of NRR to Rockville,MD Official mailing address still remains same & project managers have new locations & phone numbers.TS Michaels still lead project manager for facility & A Adams will serve as backup. RUBENSTEIN,LS. Stendardization & Non-Power Reactor Project Directorate, 88/03/18, Alfiliation Not Assigned, 3pp. 44856;322-44856;324.

R. Periodic operating reports & related correspondence

8804080474 "Annual Operating Rept." W/880328 ltr.
WILSON,A.E. Idaho State Univ., Pocatello, ID. 87/12/31, RUBENSTEIN,L. NRC - No
Detailed Affiliation Given, 77pp. 45011:006-45011:082

F. Security, medical, emergency & fire protection plans

- 8804040003 Revised emorgency plan implementing procedures, including Rev 6 to EPIP-EOF-7, "Protective Action Guidelines" & Rev 3 to EPIP-RR-4, "Reentry & Recovery Onsite NRC Coordination." W/880328 Its. ANDREWS,R L. Omaha Public Power District. 88/02/12. 13pp. 45020:268-45020:280.
- 8803310073 Revised radiological emergency response plan,including revs to table of contents & App C.W/880228 ltr. FHANCO,F.F., ANDREWS,R.L. Omaha Public Power District. 88/02/29. 15pp. 44964 075-44964.089.
- 8804110208 Restates commitments made during 880316 fire protection enforcement conference & transmits set of overheads utilized during conference. Proprietary Info removed from overheads.

 ANDREWS,R.L. Omaha Public Power District. 68/03/18. MARTIN,R.D. Region 4, Ofc of the Director. 27pp. 45135.223-45135:249.

- 8803300099 Documents 880315 Enforcement Conference reitack of fire barrior seals inside of some of electrical conduits. Attendance hist & handouts enct. CALLAN,L.J. Region 4, Ofc of the Director, 88/03/23. ANDREWS,R.L. Omeha Public Power District 22pp. 44945:319-44945:340.
- 8803290112 Rev 4 to Section G of radiological emergency response plan, "Public Info Content & Dissemination." W/880325 ltr. ANDREWS,R L. Omaha Public Power District. 88/03/25. 9pp. 44945:108-44945:114.
- 8803310092 Forwards Insp Rept 50-285/88-07 on 880201-29 & notice of violation. CALLAN,L J. Region 4, Ofc of the Director, 88/03/25, ANDREWS,R.L. Omaha Public Power District. 2pp. 44976:130-44976:150
- --8803310101 Insp Rept 50-285/88-07 on 880201-29.Violations noted.Major areas inspected,followup, on previously identified terms.LER followup.operational safety verification,plant tours,sefety-related sys walkdown & socurity observations. HARRELL.P.II._REIS,T._MULLIKIN,R. Region 4, Okt of the Director. 88/03/25. 17pp. 44976-134-44976:160.
- 8904070060 Responds to violations noted in Insp Rept 50-285/88-05 & 880321 enforcement conference items Corrective actions: health physics technician Italining records reviewed & unqualified lechnicians not performing lasks.
 ANDREWS.R.L. Omata Public Power District. 88/03/31. Document Control Branch (Document Control Desk). 115pp. 45074:152-45074:268.
- 8804130180 Rev 13 to EPIP-OSC-1-1, "Emergoncy Classification," W/880404 ftr. FRANCO,F.F., ANDREWS,R.L. Omaha Public Power District. 88/04/04. 9pp. 45187:300-45167:310.
- 8804120323 Advisos that 880307 rev to amorgancy plan acceptable.
 CALLAN,L J. Region 4, Ofc of the Director. 88/04/07. ANDREWS,R.L. Omaha Public Power District. 2pp. 45090.076-45090.076.
- 8604150292 Informs that NRC completed review of emergency plan changes which util submitted on 880325 & 29.Changes acceptable
 CALLAN,L J. Region 4, Ofc of the Director. 88/04/12 ANDREWS,R.L. Omaha Public
 Power District. 2pp. 45138:169-45138:180.
- 8604200428 Rev 6 to Emergency Plan Implementing Procedure EPIP-EOF-8, "Environ Monitoring," W/880414 ltr. Monitoring." W/880414 ltr. ANDREWS.R.L. Omaha Public Power District. 88/04/14. 18pp. 45218:243-45218:260.

P. Operating license stage documents & correspondence

8804010081 Discusses selsmic qualification into for valves associated w/air asccumula-tors discussed in util 871120 ltr.Util will seismically evaluate any required air operated valves under resolution of USI A-46. ANDREWS.R.L. Omeha Public Power Cistrict. 87/11/25, CALVO.J.A. Project Director-

ate IV. 2pp. 45001:030-45001.031.

- 8803240426 Generic Lir 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements. Svc list encl. MIRAGLIA F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804010084 Forwards safety evaluation re implementation of TMI Action Item II.K.3.5, "Automatic Irip of Reactor Coolant Pumps During LOCA." Submittals acceptable.Requirements for subj TMI action item satisfied.Technical evaluation rept BOURNIA,A. Project Directorate IV. 88/03/25. ANDREWS,R.L. Omaha Public Power District. 16pp. 44921;328-44921;343,
- 8804080086 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Planta." Sec list enci. MRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45184:237-45184:285.
- 8804150021 Forwards safety evaluation granting util 870812 request for relief from re-quirements of ASME Section XI due to inaccessible wolds in feedwater sys. CALVO_JA. Project Directorate IV. 88/04/07. ANDREWS,R.L. Omaha Public Power District, 6pp. 45139:082-45139.092.
- --8804150027 Safety evaluation granting util 870812 request for relief from certain requirements of Section XI of ASME Code.

 **Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/07. 6pp. 45139:088-45139.092.
- 8804120358 Documents 880210 telcon re diverse scram sys designed & Installed by util.per 10CFR50.82,ATWS rule.W/one oversize drawing. ANDREWS,R.L. Omaha Public Power District. 88/044/08. Document Control Branch (Document Control Desk). 8pp. 45091:188-46091:176.

8804250003 Forwards application for amend to License DPR-40,formalizing organizational changes in 880309 application for amend & proposing to remove organizational charts por Generic Ltr 68-06 Fee paid
ANDREWS,R.L. Omaha Public Power District 89/04/15 Document Control Branch (Document Control Dask) 1p. 45231-305-45231-319.

- --8804250004 Application for amend to License DPR-40,amending Tech Spec Section 5 to provide for changes in organizational structure supporting plant ANDREWS,R.L. Omaha Public Power District. 88/04/15 4pp. 45231:306-45231:309.
- -8804250005 Proposed Tech Specs formalizing changes in organizational structure.
 Omaha Public Power District. 88/04/15, 10pp, 45231:310-45231:319.
- 8804250007 Supplemental application for amend to License DPR-40 changing Tech Specs Figure 5-1 re support staff. ANDREWSR L. Omate. Public Power District. 88/04/15. Document Control Branch (Document Control Desk). 1p. 45237:139-45237.140.
- --8804250012 Proposed Tech Spacs, changing Flyure 5-1 re support staff.

 Omaha Public Power District. 88/04/15 1p. 45237:140-45237:140.
- 8804280167 Forwards Amend 112 to License DPR-40 & salety evaluation. Amend revises Tech Specs to permit extension for next due date from 880430 to rofueling outago scheduled for Sept 1988 for performing insplict Generator 1. BOURNIA.A Project Directorate IV. 88/04/19. ANDREWS,R.L. Omaha Public Power District. 4pp. 45262:331-45262:341.
- --8804280163 Amend 112 to License DPR-40 rovises Tech Space to permit extension for next due date from 880430 to refueling outage scheduled for Sept 1986 for performing inspiral Consol Generator 1. CALVO,J.A. Project Directorato IV. 88/04/19, 4pp. 45262:335-45262.338
- --8804280173 Safety evaluation supporting Amend 112 to License DPR-40.

 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/19, 3pp. 45282:339-45282:341.
- 8804280427 Requesis fees for B71214 application re review of revised mechanical design rept for Batchs K & Lifuel for plant.

 DIGGS.R.M. Licenso Fee Menagement Branch. 88/04/25. ANDREWS.R.L. Omaha Public Power District. 1p. 45266-076-45266:075.

Q. Inspection reports, IE Bulletins & correspondence

- 8804110208 Restates commitments made during 880315 fire protection enforcement conference & transmits set of overheads utilized during conference Proprietary Info removed from overheads moved from overneaus. ANDREWS, IL. Omalia Public Power District. 88/03/18. MARTIN,R.D. Region 4, Ofc of the Director. 27pp. 45135:223-45135:249.
- 8803290311 Forwards Exam Rept 50-285/Ot-88-01 of exam administered during wk of 880209. Greater attention needed to assure that mall provided to NRC for preparation.

of exams technically accurate.

CALLAN, L.J. Region 4, Ofc of the Director, 88/03/22, ANDREWS, R.L. Omaha Public Power District, 2pp. 44978;264-44979 343.

- --8803290324 Exam Rept 50-285/OL-88-01 on 880208.Exam results:three candidates passed all portions of exam & have been issued appropriate icense. MCCRORY,S.L., PELLET,J.L. Region 4, Oic of the Director, 88/03/21, 78pp. 44078-286-44978-343.
- 8803300086 Ack receipt of 880204 & 0304 & 18 lirs informing NRC of steps taken to correct violations noted in Insp Rept 50-285/87-24. Response to Violation 285/87-24-05 failed to provide date for Issuance of plant procedure. CALLAN, L.J. Region 4, Otc of the Director, 88/03/23. ANDREWS,R L. Omaha Public Power District. 3pp. 44945:316.44945:318.
- 6803300099 Documents 880315 Enforcement Conference relack of fire barrier soals Inside of some of electrical conduits. Attendance list & handouts enct. CALLAN.L.J. Region 4, Ofc of the Diractor. 88/03/23. ANDREWS.R.L. Omaha Public Power District. 22pp. 44945;318-44945;340.
- 8803300104 Ack receipt of 880226 ftr Informing NRC of steps taken to correct violations noted in Insp Rept 50-285/87-29 CALLAN,L.J. Region 4, Ofc of the Director, 88/03/23. ANDREWS,R.L. Omaha Public Power District, 2pp, 44945:341-44945:342.
- 8803310092 Forwards Insp Rept 50-285/88-07 on 880201-29 & nolice of violation. CALLAN,L.J. Region 4, Ofc of the Director. 88/03/25. ANDREWS,R.L. Omaha Public Power District. 2pp. 44876:130-44876:160.
- --8803310097 Notice of violation from Insp on 880201-29. Violations noted fire brigade consisting of five members independent of demands of other duties not maintained & written procedures not achiered to during performance of surveillance tests.
 * Region 4, Ord of the Director, 88/03/25, 2pp. 44978:132-44978:133.
- -8803310101 Insp Rept 50-285/88-07 on 880201-29. Violations noted. Major areas Inspected followup on previously Identified items_tER followup,operational safety verification.plant tours_safety-related sys walkdown & security observations HARRELL.P.H., REIS.T., MULLIKIN,R. Region 4, Old of the Director. 88/03/25. 17pp. 44976:134-44976:150.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list enci.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/03/28, Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Into Notice 88:010, "Matls Licensees:Lack of Mgt Controls Over Li-censed Programs." Svc list enct. CUNNINGHAM, RE Division of Industrial & Medical Nuclear Safety (Post 870729). 88/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.

- -8804060329 Exam Repl 50-285/QL 88-02 on 880307. Exam results: two senior operators failed walk-through exam 8 all others passed exams, WHITTEMORE, J.E., PELLET, J.L. Region 4, Qic of the Oxioctor, 88/03/28, 6pp. 45007.331-45007.336.
- 8804060472 Ack receipt of 880322 lir & payment of civil penalty in amount of \$176,000 proposed by NRC 880222 lir Response addressing long-term corrective actions expected by 880412. LIEBERHANJ, Ote of Enforcement (Post 870413), 88/03/31, ANDREWS,R.L. Omaha Pubric Power District, 1p. 45010 350-45010 350.

- 8804070060 Responds to violations noted in losp Ropt 50-285/88-05 & 880321 enforcement conference items Corrective actions health physics technician training records reviewed & unque ited technicians not performing tests.

 ANDREWS,R.L. Omaha Public Power District. 88/03/31. Document Control Branch (Document Control Desk). 115pp. 45074:152-45074:266
- 8804070188 Forwards response to NRC 880304 ftr re-violation noted in Insp Rept 50-285/87-35-Response withheld ANDREWS.R.L. Omaha Public Power District. 88/04/04. Document Control Branch [Document Control Desk). 1p. 45115-034-45115-034.
- 8804110209 Forwards Enforcement Conference Hopt 50-265/88-05 on 880321 to discuss apparent violations & NRC enforcement actions.

 CALLANL J. Region 4, Otc of the Director. 88/04/04. ANDREWS,R.L. Omaha Public Power District. 20, 45129:263-45129 309.
- -8804110211 Enforcement Conference Rept 50-285/88-05 on 880321. Major areas discussed:circumstances surrounding six apparent violations & seven significant findings 8 radiological improvement project.
 BAFR, R.E., Region 4, Ofc of the Director, 88/03/30, Region 4, Ofc of the Director, 45pp. 45120 265-45129.309.
- 8804010256 NRC Into Notice 88-0ff, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts" Syc test end ROSSI, CE. Division of Operational Events, Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408.292-45407:051.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc rat birch. 700Stj.C.E. Division of Operational Eventa Assassment (Poet 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165 028-45185:160.
- 8804200295 Contime discussions w/AS Boach that util response addressing long-term corrective actions for violations cited in Enforcement Action EA-87-210 will be provided on or before 880426. LIEBERMANJ. Ote of Enforcement (Post 870413), 88/04/14, ANDREWS,R.L. Ornaha Public Power District, 1p. 45174-136-45174:136.

8804260243 Ack receipt of 880218 payment of \$75,000 for civil penalty proposed by NRC 880119 lic. LIEBERMAN, J. O/o of Enforcement (Post 870413), 88/04/18. ANDREWS,R.L. Omaha Public Power District. 1p. 45281;282-45281;282.

R. Períodic operating reports & related correspondence

8604200142 Monthly operating rept for Mer 1988.W/880413 kr. BLESSiE.W.J., ANDREWS,R.L. Omeha Public Power District. 88/03/31. 9pp. 45221.097 45221:105.

S. Reportable occurrences, LERs & related correspondence

- 8804130079 LER 88 005-00:on 680308,cond-tion discovered by which specific LOCA could incapacitate instrumentation feeding protective function. Further investigation continuing Personnel elerted to problem & consequences W/880408 ltr. HOLLINGSED,MW, ANDREWS,R.L. Ometa Public Power District. 88/04/08. 5pp. 45129.152-45129:156.
- 8804160414 LER 88-004-00 on 880311, determined that instrument elit valve PCV-1849 did not meet containment isolation criteria specified in updated SAR, Cause not stated Procedure changes made to reflect need to close valve W/880411 lfr. SH/DERT, B.W., ANDREWS, R.L. Omaha Public Power District. 88/04/11. 4pp. 45183.180-45183:183.
- 8804200093 Special region 880315,alarms received in control room which indicate problems w/qualified SPDS Channel A (QSPDS A). Personnel noticed smell of hot insufation coming from OSPDS A panel Al-208A Caused by overheated expander card. ANDREWS,R.L. Omaha Public Power District 88/04/14. Document Control Branch (Document Control Desk). 4pp. 45216:008-45218.011.
- 8804200346 LER 88-008-00 on 870503,12 spray heads on containment spray sys not inspected per Surveillance Tast ST-N2-1 within required time interval. Effect of potentially disabled heads on containment spray headers will be evaluated. W/880414 Itr. ROSLONICO,D.J., aNDREWS,R.L. Omeha Public Power District. 88/04/14, 3pp. 45221:062-45221.084.
- 8804200366 LER 88-006-00 on 880315. Surveillance Test ST-DC-1 F.1, "Station Batter-les," not performed during Jan 1988 Caused by way surveillance test schedule pro-gram designed. Test now scheduled for second wk of each month. W/880414 ltr. MOLZLER.D.S., ANDREWS.R.L. Omaha Public Power District. 88/04/14, 4pp. 45236:044-45235.047.

V. Operator Examinations

8803290311 Forwards Exam Rept 50-285/OL-88-01 of exam administered during wk, of 880209. Greater attention needed to assure that mall provided to NRC for preparation of exams technically accurate. CALLAN, J. Fregion 4, Off of the Director, 88/03/22. ANDREWS, R.L. Omaha Public Power District, 2pp. 44978-264-44978-343.

8804060320 Forwards Exam Ropt 50-285/OL-88-02 of written & walkthrough exams ministered during wk of 880307.Requalitation training program will not be rewalted until simulator exams completed Program unsatisfactory. CALLAN, J. Region 4, Otic of the Director, 68/03/28. ANDREWS,R.L. Omeha Ps. Power District. 2pp. 45007:329-45007:336.

- --8804060329 Exam Rept 50-285/OL-88-02 on 880307.Exam results two senior optors falled walk-through exam & all others passed exams
 WHITTEMOREJE. PELLET JL. Region 4, Otc of the Director 88/03/26. 6
 45007.331.45007.336.
- 8804250088 Responds to FOIA request for into re-scores of reactor operators & se-reactor operators. Forwards requalification exam summary source sheets listed in a app w/personal privacy Into deleted. GRIMSLEY, D.H. Division of Rules & Records (Post 870413), 88/04/19 BOLE Public Critizen's Critical Mass Energy Project, 2pp. 45213,003-45213,095.
- -8804250 t67 Package of NRC administered requalification exam results summary.
 NRC No Detailed Afriliation Given. 87/07/20, 88pp. 45213.007-45213.095

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

- 8803310297 Forwards exercise objectives for facility full-scale emergency prepared exercise scheduled for wk of 880320, per W3 Lazarus 861124 kr./Juli Intends to test site response to simulated emergency condition. JOSIGER,W.A. New York Power Authority (formerly Power Authority of the Stat New York). 87/12/11. RUSSELL,W. Region 1, Ofc of the Director. 23pp. 45000.45000.335.
- 8804110149 Discusses support activities for Cycle 6/7 refuefing outage schedule-begin in Feb 1989.Tentative schedule for completion of tasks encl.Enct withheld 10CFR73 21 & 2.790(d)). JOSIGER,W.A. New York Power Authority (tormerly Power Authority of the Stat New York). 88/03/31. RUSSELL.W.T. Region 1, Ofc of the Director. 2pp. 45135.

8804150269 Forwards Rev 3 to safeguards contingency plan indicating organization title changes Rev withheld (ref. 10CFR2.790[d)(i)).
BRONS J.C. New York Power Authority (formerly Power Authority of the State of York).
88/04/08. Document Control Branch (Document Control Desk) YORK). 88704700. U 45192:243-45192:244.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants to romoving anization charts from Tech Spec administrative control requirements. Svc list of MRAGLIA,F. J. Associate Director for Projects (Post 870411), 88/03/22, Consolid Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804110149 Discusses support activities for Cycle 6/7 refuefing outage schedule begin in Feb 1989. Tentative schedule for completion of tasks encl. Encl withheld 10CFR73.21 & 2.790(d)).

 JOSIGER,W.A. New York Power Authority (formerly Power Authority of the Stat New York). 88/03/31. RUSSELL,W.T. Region 1, Oic of the Oliractor. 2pp. 45135-45135:041.
- 8804080088 Generic Lir 88-07 to power reactor licensees & applicants re-modified forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Edition of the Electrical Edition of Electrical Edition of Electrical Edition of Electrical Edition of Electrical Edition Co. of New York, Inc. 48pp. 45164;237-45164;285.
- 8804190165 Forwards request for additintore util 831107 & 850517 responses to neric Ltr 83-28, ltem 2.2 (Part 1). "Equipment Classification Programs (Programs to Other Safety: Related Components)." Response requested within 30 days. NEIGHBORS.J.D. Project Directorate I-1. 88/04/13. BRONS.J.C. New York Powor thority (formerly Power Authority of the State of New York). 12pp. 45165-309.

- 8804040028 Forwards Insp Rept 50-286/88-01 on 880209-0318 No violations noted WENZINGER,E.C. Region 1, Ofc of the Director. 88/03/24. JOSIGER,W. New Power Authority (formerly Power Authority of the State of New York). 2pp. 45017:
- ~8804040033 Insp. Rept. 50-286/88-01 on 880209-0318.No violations noted. In areas inspected/routine onsite regular & backshift linep of plant operations, incl. shift logs & records & licensee actions on previously identified insp findings. JOHNSON,J.R. Region 1, Oic of the Director. 88/03/23. Bpp. 45017;167-45017;
- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Weshouse Reactors," Svc list enci.
 ROSSIC E. Division of Operational Events Assessment (Post 870411), 88/03 Consolidated Edison Co. of New York, Inc. 121pp. 44995126-44995:246.
- 8803220295 NRC Into Notice 88.010, "Matis Licensees:Lack of Mgt Controls Over censed Programs," Svo list enci. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Salety (Post 870729) 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44996:353.
- 8804010256 NRC Info Notice 88+011, "Potential Loss of Motor Control Cir &/or Sv board Function Due to Faulty Tie Boths," Svo list encl. ROSSI,O.E. Division of Operational Events, Assessment (Post 870411), 88/04 Consolidated Edison Co. of New York, Inc. 124pp, 45406:292-45407:051.

- 8804200089 Forwards request for additinfollow the 850513 response to IE Bulletin 85003, "Motor Operated Valve Common Mode Failures During Plant Transients Que to Improper Switch Settings," for response in 1 month, WENZINGER, E.C. Region 1, Ofc of the Director, 88/04/11, JOSIGER, W. New York Power Authority (formerly Power Authority of the State of New York), 4pp. 45218:144-45218.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc.
- ROSSICE Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165.150
- 8804200155 Forwards Safety Insp Rept 50-286/88-03 on 880307-11.No violetions or deviations noted Unresolved Item re audit program Identified. BELLAMY,R.R. Region 1, Ofc of the Director. 88/04/13, JOSIGER,W. New York Power Authority (formarly Power Authority of the State of New York) 2pp. 45220 254-45220 267
- --8804200163 Safety Insp Rept 50-286/88-03 on 880307-11 No violations noted Major areas inspected licensee water chemistry control program to controlling corrosion & out-of-core radiation field buildup Unresolved item re audits also noted BICEHOUSE, H.J., PASCIAK, W. Region 1. Ofc of the Director, 88/04/07, 12pp 45220,256-45220,267.
- 8804270271 Confirms that util continues to implement monitoring 8 procedural actions recommended by Bulletin 65 001, "Steam Binding of Auxi'sary Feedwater Pumps," per Generic Life 86:03 re resolution of Generic Stefaty Issue 93. BRONS JC New York Power Authority (formarly Power Authority of the State of New York). 88/04/18. Document Control Branch (Document Control Desk). 2pp. York). 88/04/18 De 45245-280.

- 8804220081 Monthly operating ropt for Mar 1988.W/680414 ltr.
 KELLY,L., JOSIGER,W.A. New York Power Authority (formerly Power Authority of the State of New York). 88/03/31 8pp. 45216:178-45216:185.
- 8804110063 Forwards cover litrs transmitting monthly facility discharge monitoring repts for Jul-Dec 1987.Each cover litr accompanied by excerpts from repts which detail excursions from SPDES permit ellipent times.

 BRONS,JC. New York Power Authority (formerly Power Authority of the State of New York), 88/04/05. Document Control Branch (Document Control Desk). 3pp. 45170 001-45170.020.
- -8804110091 Discharge monitoring rept for SPDES Permit NY0004472 for Jul 1987. BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/07/31. 3pp. 45170.004-45170 008
- -8804110093 Discharge monitoring ropt for SPDES Permit NY0004472 for Aug 1987. BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/08/31, 2pp. 45170.007-45170.008
- ~8804110097 Discharge monitoring rept for SPDES Permit NY0004472 for Aug 1987. 8ASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/09/30. 3pp. 45170:008-45170.011.
- ~8804110127 Discharge monitoring rept for SPDES Permit NY0004472 for Oct 1987. BASILE, J.A. Consolidated Edison Co. of New York, Inc. 87/10/31. 3pp. 45170.012-45170 014
- ~8804110141 Discharge monitoring ropt for SPDES Permit NY0004472 for Nov 1987. BASILE,JA Consolidated Edison Co. of New York, Inc. 87/11/30. 2pp. 45170:015-
- ~8804110145 Discharge monitoring rept for Dec 1987, BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/12/31, 2pp. 45170.017-45170 018
- --9804110199 Submits rept to correct previous rept of noncompliance for months of Mar.Apr.May & June 1987 Previous rept did not list specific dates per Part II, goneral conditions.
- New York Power Authority (formerly Power Authority of the State of New York). 87/ 06/30. 2pp. 45170.019-45170.020.

S. Reportable occurrences, LERs & related correspondence

8804110063 Forwards cover litrs transmitting monthly facility discharge monitoring repts for Juf-Doc 1987. Each cover litr accompanied by excerpts from repts which detail ex-

tor Juribus 1997. Each cover in accompanies by excepts from repts which detail excursions from SPDES parmit effluent limits.

BRONS.J.C. New York Power Authority (formerly Power Authority of the State of New York). 88/04/05. Document Control Branch (Document Control Desk). 3pp. 45170.001-45170.020.

- --8804110093 Discharge monitoring rept for SPDES Permit NY0004472 for Aug 1967. BASILE,J.A. Consolidated Edison Co. of New York, Inc. 67/08/31, 2pp. 45170.007-45170.008
- --8804110097 Discharge monitoring rept for SPDES Permit NY0004472 for Aug 1987. BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/09/30, 3pp. 45170,009-45170:011.
- --8804110127 Discharge monitoring rept for SPDES Permit NY0004472 for Oct 1987. BASILE,J.A. Consolidated Edison Co. of New York, Inc. 87/10/31. 3pp. 45170:012-45170.014.
- -8604110141 Discharge monitoring rept for SPDES Permit NY0004472 for Nov 1987. BASILE, J.A. Consolidated Edison Co. of New York, Inc. 87/11/30, 2pp. 45170 015-45170:016
- -8804110145 Discharge monitoring rept for Dec 1987.

 BASILE, J.A. Consolidated Edison Co. of New York, Inc. 87/12/31, 2pp. 45170.017-45170:018

- --9804110199 Submits rept to correct previous rept of noncompliance for months of Mar.Apr.May & June 1987 Previous rept of dinot list specific dates,per Part II, general conditions
- Considers

 New York Power Authority (formerly Power Authority of the State of New York): 877
 06/30, 2pp 45170 019-45170.020.

DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

C. Utility Environmental Report (ER), amends & correspondence

- 8804040024 Application for amends to Licenses DPR-38,DPR-47 & DPR-55 to permit operation of ISFSI for temporary storage of spent fuel until Federal govi provides permanent storage facilities. Fee paid: TUCKER,HIB. Duke Power Co. 88/03/31. Document Control Branch (Occument Control Desk). 11pp. 45233 050-45233:195

--6804040053 "ISFSI Environ Rept," Duke Power Co. 88/03/31, 215pp. 45233:196-45234:050

F. Security, medical, emergency & fire protection plans

- 8804110123 Forwards Rev 24 to plant security plan Rev developed to delete redundant vital aguipment test wording in security plan & in comprehensive manner revise list of vital aguipment.Rev 24 withheld (ref 10CFR73.21). TUCKER,H.B. Duke Power Ca. 88/04/04 Document Control Desk). 2pp. 45129:228-45129.227.
- 8804200473 Partial response to FOIA request re (ire protection Forwards App E documents App D & E documents available in PDR.App F document completely withhold (rof FOIA Exemption 5).
 GRIMBLEY,D.H. Division of Rules & Records (Post 870413). 88/04/14. JONES,C.R. Affiliation Not Assigned. 5pp. 45206/037-45208 043.
- --8804200579 Advisos that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type Insp for each facility to assess status of compliance w/ 10CFR50.48 Program listed.
 CONLON,T.E. Region 2, Old of the Director. 84/11/06. HERDT,A.R. Region 2, Old of the Director. 3pp. 45206:176-45206.178.
- 8804290249 Forwards Revs 88-01 & 88-02 to Implementing procedures manual (Vols 8 & C) per 10CFR50.54(q).Revs do not decrease effectiveness of emergency implementing procedures or emergency plan. TUCKER, H.B. Duke Power Co. 88/04/21. Document Central Branch (Document Control Desk). 2pp. 45282;112-45282:170.
- --8804290274 Revised emergency plan implementing procedures including rev to Procedure CP/182/A/2002/05, "Post-Accident Caustic... Sys," Procedure RP/O/8/1000/ 03, "Alort" & Procedure RP/O/8/1000/04, "Sta Area Emergency."

 * Duke Power Co. 88/03/31, 48pp. 45282:114-45282:170.

I. Financial information

- 8804040024 Application for amends to Liconses DPR-38,DPR-47 & DPR-55 to permit operation of ISFSI for temporary storage of spent fuel until Federal govt provides permanent storage facilities. Feo paid.
 TUCKER, H.B. Duke Power Co. 88/03/31. Document Control Branch (Document Control Desk), 11pp. 46233.050-45233:195
- --8804040050 "Duke Power Co Annual Rept 1987." LEE W.S. Duke Power Co. 87/12/31, 101pp, 44999:093-44999.193.

P. Operating license stage documents & correspondence

- 88/03/100068 Summary of 880301 meeting w/util in Rockville,MD re ISAP II described in Generic Ltr 88-02 Attendence list & viewgraphs encl. HOOD,D.S. Project Directorate II-3. 88/03/07. Project Oirectorate II-3. 29pp. 44662: 083-44662: 111.
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spoc administrative control requirements Svotistioned. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804010042 Forwards listing of outstanding items.per discussion w/NRC relutil ongoing program of reducing backlog of outstanding items.W/o encl. BROWNLEE,V.L. Region 2, Olc of the Olicotor, 88/03/23, TUCKER,H.B. Duke Power Co. 1p. 45031;171:45031:171.
- 8804120317 Expressos appreciation for time that members took to present outline of ISAP II program per Generic Ltr 88:02 requesting licensee to evaluate NRC latest rev 8 indicate whether interested in participating in program. TUCKER_HB. Duke Power Co. 88/03/25. Document Control Branch (Document Control Desk). 2pp. 45091:142-45091:143
- 8804040024 Application for amends to Licenses DPR-38,DPR-47 & DPR-55 to permit operation of ISFSI for temporary storage of spent fuel until Federal govi provides permanent storage facilities Fee paid.

 TUCKER,H.B. Duke Power Co. 88/03/31. Document Control Branch (Document Control Desk). 11pp. 45233:050-46233:195.
- --8804040025 Proposed Tech Specs re-spent fuel storage facility.

 * Duke Power Co. 88/03/31, 7pp 45233:060-45233.067.
- --8804040059 "ISFSI SAR." Duke Power Co. 88/03/31, 265pp. 45234:051-45234:315.

- 8804050403 Notifies that util 870814 application to revise Tech Specs re upper surge lank level & emergency flow vs time unsuitable for processing. No technical justification or NSRC determination provided, HOOD,0.5 Project Directorate (I.3. 88/03/31. TUCKER,H.B. Duke Power Co. 2pp 45009 334 45009 335
- 8804080172 Forwards SSER NUREG-1231 re 8&W Owners Group plant reassessment program Overal; evaluation remains (avorable, Add) improvement in area of integrated control sys/ non-nuclear instrumentation sys review possible W/a extended CRUTCHFIELD,D. Div.sion of Reactor Projects II,IV,V & Special Projects (Post 870411) 88/03/31 WILGUS,W.S Babcock & Wilcox Operating Plants Owners Group. 7pp. 45076.181-45076;187
- 8804080088 Gengric Ltr 88.07 to power reactor licensees & applicants re-modified on-lorcement policy concerning 10CFR50.48, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list end MIRAGLIA.F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164 237-45164 285.
- 8804210350 Forwards notice of consideration of issuance of amends to Licenses DPR-38,DPR-47 & DPR-55 & opportunity for hearing on 680106 request to revise Tech Specsive control room inbullability PASTIS,M N Project Directorate II-3, 88/04/15, TUCKER,H.B. Duke Power Co. 2µp. 45192:163-45192 175
- -8804210352 Notice of consideration of issuance of amend to Licenses DPR-38,DPR-47 & DPR-55 & appointments for hearing Amend revises Tech Space re-control room habitability. CROCKER,L.P. Project Directorate N-3, 88/04/13, 11pp. 45192;185-45192;175,

Q. Inspection reports, IE Bulletins & correspondence

- 8803160322 Ferwards Exam Rept 50-269/OL-87-03 of exam administered on 871214 for Units 1,2 & 3.
 JULIAN.C A. Region 2, Old of the Director 88/02/19, TUCKER,H.B. Duke Power Co.
 2pp. 44705.027-44705:099.
- -8803160337 Fxam Rept 50-269/OL-87-03 on 871214 for Units 1,2 & 3 Exam results all candidates passed written resxams. DEAN.W.M. Region 2, Old of the Director, 88/02/18, 139pp, 44705.029-44705.099
- 8803250321 Forwards addl into re open items identified during environ qualification team into on 880222-26. Design engineoring personnel demonstrated methodology to determine similarly of installed vs tested oquipment.

 TUCKER.HB Duke Power Co. 88/03/09. GRACE.J.N. Region 2, Otc of the Oirector. 4ρρ. 44945.220-44945.223.
- 8803310278 Forwards Insp. Repts 50-269/68-07,50-270/68-07 & 50-287/68-07 on 880307-11 No volations or deviations noted HER01,A.R. Region 2, Ofc of the Director, 88/03/25, TUCKER,H.R. Duke Power Co. 2pp 44976-159-449/6:172.
- -8803310280 htsp. Regis 50:269/88-07,50:270/88-07 & 50:287/88-07 on 880307-11 No violations or deviations noted Major areas inspected inservice insp. including NDE procedure review, exam data review & personnet certification records teview. NEWSOMER.W. BLAKE, J.J. Region 2, Old of the Director. 88/03/23, 12pp, 44976 161-44976:172.
- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors" Syc list enct.
 ROSSLCE: Oxiston of Operational Events Assessment (Post 870411), 88/03/28, Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995;246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees.Lack of Mgt Controls Over Li-censed Programs." Svc list enct. CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44895 247-44895.353
- 8804060470 Forwards reactor bidg tendon surveniance reptiper Tech Spec 4.4.2 re lendon inservice insp.

 TUCKER.H.B. Duke Power Co. 88/03/29, Document Control Branch (Document Control Desk), 15pp. 45079:150-45079:174
- 8804010256 NRC Into Notice 88-011, "Potential Loss of Motor Control Cir &/or Switch-board Function Oue to Faulty Tie Boits." Svc 1-s1 enct.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 86/04/07.
 Consolidated Ed.son Co. of New York, Inc. 124pp. 45406:292-46407.051.
- 8804060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svo list enci.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/12.

 Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165.150.
- 8804200473 Partial response to FOIA request to fire protection.Forwards App E documents App D & E documents available in PDR App F document completely witti-held (rel FOIA Exemption 5)
 GRIMSLEY.D H Division of Rules & Records (Post 870413). 88/04/14, JONES.C.R Atfiliation Not Assigned 5pp. 45206 037.45206.043.
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type Insp for each facility to assess status of compliance w/ 10CFR50,48. Program Listed.
 CONLON,T.E. Region 2, Oic of the Director 84/11/08, HERDT,A R Region 2, Oic of the Director. 3pp. 45206:178-45208:178.

R. Periodic operating reports & related correspondence

8804200152 Monthly operating repts for Mar 1988 W/880415 ltr. REAVIS.J.A., TUCKER.H.B. Ouke Power Co. 88/03/31, 17pp. 45215:343-45215:359.

V. Operator Examinations

8803160322 Forwards Exam Rept 50-289/OL-87-03 of exam administered on 871214 for Units 1.2 & 3. Section 2.0 Cold to Director, 88/02/19, TUCKER, H.B. Duke Power Co. 2pp. 44705-029-4705-099.

- ~8803180337 Exam Ropt 50-269/OL-87-03 on 871214 for Units 1,2 & 3.Exam roserts at candidates passed written roserens. DEAN,WM., BROCKMAN,K.E. Region 2, Ofc. of the Director, 88/02/18, 139pp 44705-029-44705-099
- -8803310070 Forwards comments concerning whiten exam given to plants operative on 871214. Comments divided according to type of test administered w/cross ref to redundant questions to assist examiners grading exams. TUCKMAN, M.S. Duke Power Co. 87/12/18. MUNRO, J. Region 2, Ofc of the Oirector. 20pp. 44966.333-44968.352.
- 8804250088 Responds to FOIA request for into re-scores of reactor operators & sonor reactor operators Forwards requalification exam summary source sheets listed in end app w/porsonal privacy into detected.

 GRIMSLEY,D.H. D.vision of Rules & Records (Post 870413). 88/04/19. BOLEY,K Public Chizen's Chizen's Chizen as Energy Project. 2pp. 45213.003-45213.095.

--8804250167 Package of NRC administered requalification exam results summary.
* NRC - No Detailed Attification Given, 87/07/20 88pp. 45213.007-45213.095.

Y. Ory Cask Independent Spent Fuel Storage Installations

- 8804130203 Notification of 861218 meeting w/util in Silver Spring,MD to discuss will plans for expansion of sport fuel storage factifies under 10CFR72 & Oconee Nuclear Station List of attendees & agenda and ROBERTS.J.P. Advanced Fuel & Spent Fuel Licensing Branch 87/01/07 ROUSE,L.C. Advanced Fuel & Spent Fuel Licensing Branch 10pp. 45101262-45101216
- 8804040924 Application for amends to Licenses DPR-38,DPR-47 & DPR-55 to permit operation of ISFSI for temporary storage of spont fuel until Federal govt provides permanent storage facilities. Foe paid.

 TUCKER,H.B. Duke Power Co. 88/03/31. Document Control Branch (Document Control Desk) 11pp. 45233.050-45233:195.
- --8804040025 Proposed Tech Specs re spent fuel storage facility.

 Duke Power Co. 88/03/31, 7pp. 45233.060-45233:067.
- --3804040029 Forwards application to construct & operate ISFSI for temporary alorage of spent fuel.per 10CFR72-SAR & environ rept also encl.Fee paid. TUCKER.HB. Duke Power Co. 88/03/31. Office of Nuclear Material Safety & Safeguards, Director. 5pp. 45233-068-45233-195.
- --8804040049 Application for ficonse to construct & operate dry cask ISFSI at Oconee Nuclear Station.

 * Duke Power Co. 88/03/31, 23pp. 45233-073-45233:195.
- ~8804040053 "ISFSI Environ Rept."
 * Duke Power Co. 88/03/31 215pp. 45233:196-45234.050.
- -8804040059 "ISFSI SARI" Duke Power Co. 88/03/31, 265pp. 45234.051-45234:315.

DOCKET 60-288 REED COLLEGE RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville,MD.Official mailing address still tomains same & project managers have new locations & phone numbers TS Michaels still lead project manager for facility & A Adams will serve as backup, RUBENSTEINLS, Standardization & Non-Power Reactor Project Directorate, 88/03/ Affiliation Not Assigned. 3pp. 44858:322-44856.324.

DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8804120277 Forwards Tech Spec Change Request 181 for amend to License DPR-50, detailing lire protection Tech Specs 3.18 & 4.18 & adding std license condition of Generic Lit 86-10. Certificate of Svc ancil-Fee paid.
 HUKILL,H. General Public Utilities Corp. GPU Service Corp. 88/04/04. Document Control Branch (Document Control Desk). 3pp. 45142 098-45142:113.
- -8804120295 Application for amend to License DPR-50, consisting of Tech Spec Change Request 181, deforing Tech Specs 3.18 & 4.18, per Generic Ltr 86-10. HUKILL.H.D. General Public Utilistics Corp. GPU Service Corp. 88/04/04. 11pp 45142-089-45142-10.
- --9804120302 Proposed Tech Specs deleting Tech Specs 3.18 & 4.18 & adding std li-cense condition of Generic Ltr 86-10.

 * General Public Utilities Corp. GPU Service Corp. 88/04/04. 4pp. 45142-110-45142:113.
- 8804120356 Forwards comments on SALP Rept 50-289/86-98.Guidance in area of procedural compliance will be reinforced to all lovels of supervision & addi action will be taken to strenghlen procedure preparation.

 CLARK.P.R. General Public Unities Corp. - GPU Service Corp. 88/04/05. Document Control Branch (Document Control Deak). 7pp. 45088.352-45088:358.
- 8804140347 Rov 1 to Emergency Plan Implementing Procedure 6415-ADM-1300.01. "Maintaining Emergency Preparedness." BROWN,N.H., MARSHALL,W.J. General Public Utilities Corp. - GPU Service Corp. 88/ 04/12. 38pp. 45187:114-45167:151.

G. Adjudicatory correspondence

8804260096 Advises that time for Commission to roviow ALAB-887 expired. Commission declined review Decision became line! agency action on 880405 Served on 880420. CHILK,S J Office of the Societary of the Commission. #288 6105. 88/04/20. Atomic Safety and Licensing Board Panel 1p. 45210:236-45210:236.

H. General correspondence

8804260185 Informs of record reorganizational changes within GPU Nuclear Effective 880425,PB Fledler will be reassigned to position of vice president/director of quality & training, newly formed div. LONG,R.L. General Public Utilities Corp. - GPU Service Corp. 88/04/18. Document Control Branch (Document Control Dosk), 2pp. 45260.001-45280.002

J. Insurance & indemnity information

8804070065 Forwards Endorsements 1 & 2 to MAELU Certificate MW-48 & NELIA Cer-Lificate NW-125

HOFFMAN J. Marsh & McLennan, Inc. 68/03/30. DINITZ,1. Office of Nuclear Reactor Regulation, Director (Post 870411). 21pp. 46079 232-45079 252.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88:06 to all power reactor licensees & applicants re-removal of organization charts from Toch Spec administrative control requirements. Suc list ench. MiRAGLIA, F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972.107-44972:153.
- 8804130379 Forwards "Radiation Monitoring Sys for Nuclear Power Plants (W/Special Ref to TMI Nuclear Power Station)." BERGER, J. TMI Public Health Fund. 88/03/22. ZECH,L. Commissioners. 1p. 45103-228-45104:033.
- -8804130362 "Radiation Monitoring Sys for Nuclear Power Plants (W/Special Ref to TMI Nuclear Power Station)." BERGER,J. TMI Public Health Fund. 87/12/31. 153pp. 45103 228 45104:033.
- 8804120290 Notification of Significant Licenseo Meeting 88-045 on 880426 w/util in King of Prussia,PA to discuss unit outage.
 COWGILL,C.J. Region 1, Otc of the Director. 88/03/25. Region 1, Otc of the Director. 2pp. 45080
- 8804130171 Notification of Significant Licensed Meeting 88-046 on 880427 w/util in King of Prussia,PA to discuss safety review process problems. COWGILL,C.J. Region 1, Ofc of the Director. 88/03/25 Region 1, Ofc of the Director. 2pp. 45122.217-45122.218.
- 8804130179 Notification of Significant Licensee Mooting 88-47 on 880524 w/ulil in Region I to discuss engineering support assossment. COWGILL, C.J. Region 1, Otc of the Director. B8/03/25. Region 1, Otc of the Director. 2pp. 46122:213-45122:214.
- 8804050059 Clarifies statements made in NRC SER attached to Amond 136 dtd 880114 re chlorine detection sys.Preventive Maint Procedure PM-IC-145 does not specify 5 open level Procedure purpose to perform probe response check only.
 HUKILL,H.D. General Public Utilities Corp. - GPU Service Corp. 88/03/28. Document Control Branch (Document Control Desk). 2pp. 44895:354-44995:355.
- 8804060450 Forwards application for amend to License DPH-50,consisting of Rov 1 to Tech Spec Change Request 178 ravising Sections 6.2.1.3 & 6.2.2.1 to indicate specific mgt positions in place of unspecified rngt positions.
- -8804060451 Application for amend to License DPR-50,consisting of Toch Spoc Change Request 178,changing organization.
 BROUGHTON General Public Utilities Corp. GPU Service Corp. 88/03/28. 2pp. 45078-098-45078-099.
- -8804060452 Proposed Tech Spec Chango Request 178 revising Sections 6.2.1.3 & 6.2.2.1 to indicate specific mgt positions in place of unspecified mgt position.

 ' General Public Utilities Corp. GPU Service Corp. 88/03/28. 1p. 45076:100-
- 8804080172 Forwards SSER NUREG-1231 to B&W Owners Group plant reassessment program Ovorall evaluation remains (avorable, Add Improvement in area of Integrated control sys/ non-nuclear instrumentation sys review possible W/o enci. CRUTCHFIELD. Division of Reactor Projects - IIII.V.V. & Special Projects (Post 870411), 88/03/31, WILGUS,W.S. Babcock & Wilcox Operating Plants Owners Group. 7pp. 45076:181-45076:187.
- 8804120277 Forwards Tech Spec Change Request 181 for amend to License DPR-50, deteiling tire protection Tech Specs 3.18 & 4.18 & adding atd license condition of Generic Lit 86-10. Certificate of Svc oncl.Fee paid.

 HUKIL
- --8804120295 Application for amond to License DPR-50.consisting of Tech Spec Change Request 181.deleting Tech Specs 3.18 & 4.18.per Generic Lir 86-10 HUKILL, H.D. General Public Utilities Corp. GPU Service Corp. 88/04/04. 11pp. 45142-099-45142:109.
- --8804120302 Proposed Tech Specs deleting Tech Specs 3.18 & 4.18 & adding std license condition of Generic Ltr 88-10.

 * General Public Utilities Corp. GPU Service Corp. 88/04/04. 4pp. 46142.110-45142:113.
- 8804120393 Forwards ABC listing of projects on integrated schedule,per commitment made at 871216 meeting based on license Amend Raquest 170. HUKILLH.D. General Public Utilities Corp. GPU Servico Corp. 88/04/04. Document Control Branch (Document Control Desk). 18pp. 45079:286-45079:301.

- 8804120305 Forwards application for amend to License DPR-50 consisting of Tech Spec Change Request 182 re operation during Cycle 7 B&W Cycle 7 retoad rept also enct Fee part d HUKILL+I D. Genoral Public Utilities Corp. GPU Service Corp. 88/04/05. Document Control Brench (Document Control Dosk). 2pp. 45128 309-45129 063
- ---8804120312 Application for amond to License DPR-50,consisting of Tech Specichange Request 182 to appration during Cycle 7.

 HUKILL,H.D. Genoral Public Utilities Corp. GPU Service Corp. 88/04/05 17pp
 45128 311-45128:327.
- --8804120314 Proposed Tech Spacs changes re operation during Cycle 7
 * General Public Utilities Corp. GPU Service Corp. 88/04/05, 39pp. 45128-328-45129-008
- -8804120329 "TMI-1 Cycle 7 Refoad Ropt."
 * Babcock & Wilcox Co. 88/03/31 57pp 45129.007-45129 663
- 8804080088 Generic Ltr 88:07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-mont Important to Safety for Nuclear Power Plants" Svc list encl. MIRAGUA.F. J. Associate Quector for Projects (Post 870411) 88/04/07, Consolidated Edison Co. of New York, Inc. 48pp. 45164-237-45164-285.
- 8804260299 Forwards Rev 2 to 1000 PLN-7200 01, "GPU Nuclear Corp Operational QA Plan for IMI-1 & Oystor Creok." Plan will be revised to reflect planned reorganization Evaluation of changes associated w/rev also encl ROCHE, M.B., General Public Utilities Corp. GPU Service Corp. 88/04/15 Document Control Branch (Document Control Branch (Document Control Dock).
- -8804260301 Rev 2 to 1000 PLN 7200.01, * GPU Nuclear Corp Operational QA Plan for CLARK,P.R. General Public Uillies Corp. GPU Service Corp. 88/04/08. 121pp 45252:187-45252 307
- 8804280351 Forwards not to of consisteration of issuance of amend to License DPR-50 & opportunity of hearing to 880405 application for amend to revise Tech Specs to provide for Cycle 7 of operation. HERNAN,R.W Project Directorate 1-4 88/04/18, HUKILL,H.D. General Public Utilities Corp. GPU Service Corp. 2pp. 45269 228-45269 233
- --8804280361 Notice of consideration of issuance of amend to License DPR-50 & op-portunity for hearing rollid 880405 application to revise Tech Specs to support core rolload for Cycle 7 of operation STOLZ_JF. Project Directorate I-4 88/04/08. 4pp 45269 230-45269 233
- 8804280636 Partial response to FOIA request for documents.Forwards App G documents Documents also available in PDR GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 88/04/22. CONNOR,L Doc-Soerch Associates 2pp. 45279 139-45279 199.
- 6804280639 Forwards communts to be served in facilty restart proceeding Subcommittee on Energy & Environ requests documents be provided to Commission. KAMMERER, C. Office of Congressional Affairs (pre 870413), 84/03/01, PALLADINO, GILINSKY, ROBERTS Commissioners 1p. 45279.141-45279:141.
- --8804280850 Responds to Commission request for comments on hist of TMI integrity issues, including Keaton ropt & Hartman a logations MYERS,H. NRC No Detailed Affiliation Given 84/02/21, KAMMERER,C. NRC No Detailed Affiliation Given, 5pp. 45279, 142, 45279, 148.
- ---8804280857 Forwards into for record of 810825 meeting of TMI-1 subcommittee on Abbott momo concorring facility accident I&E conclusion is open to interpretation that Info Intentionally withhold.

 UDALLMK House of Figs. Interfor & Insular Atlairs, 81/07/06, MOELLER.D.W. ACRS - Advisory Committee on Reactor Saleguards 7pp. 45279:147-45279:168
- --8804290861 Discusses subject into intentionally or wilfully withhold during facility accident Record shows NRC statements logically inconsistent wione another. MYERS,H. NRC No Detailed Affiliation Given. 82/03/08 DIRCKS,B., HALLER,N NRC No Detailed Affiliation Given. 4pp. 45279.189.
- --8804280664 Comments on statements made at 811221 Commission meeting to info flow during faculty accident inconsistencies highlighted. MYERS,H. NRC No Dotalled Affiliation Given, 82/01/11, DIRCKS,B., HALLER,N. NRC No Detailed Affiliation Given, 5pp. 45278:192-45270:196.

Q. Inspection reports, IE Bulletins & correspondence

45089:265-45089-268.

- 8804130066 Notification of 880303 Eliconsee Meeting 88-024 w/util in Persippany,NJ to discuss ptent SALP.
 PELESCHAK,S. Region 1, Otc of the Director 88/02/17, Region 1, Otc of the Oirector 2pp 45098-344-45098-345.
- 8804120070 Forwards safety evaluation accepting util 880920 request for relief from certain Insps at plant required by Section XI of ASME Code Use of proposed alternative exam identified in submittals as Relief Request 7 approved.

 STOLZ,J.F. Project Directorate I-4. 88/03/25. HUKIL,J.I.D. General Public Unitiles Corp. GPU Service Corp. 2pp. 45089.263-45989.268.
- --8804120076 Safety evaluation supporting rated from certain requirements of Section XI of ASME Code Proposed surface exam meets later approved code edition & addenda & acceptable.
 * Office of Nuclear Reactor Regulation, Director (Post 870411). 88/03/25. 4pp.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning In Westing-house Reactors." Svc list end.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995;246.

8803220296 NRC Into Notice 88 010, "Matts Licensees Lack of Mgt Controls Over Licensed Programs." Src 1st encl CUNTi, NGHAM, R.E. Dinsson of Industrial & Medical Nuclear Safety (Post 870729) 887 03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44895:247-44995:353

8804140306 Forwards SSER for second 10 yr interval of inservice testing of pumps & valves commenced in Sept 1984 SSER discusses pair of valves noted in Insp. Rept 50-283/87-10 not to be included in inservice testing program Requests confirmation of STOLZ_JF. Project Ovectorale 1-4, 88/03/31, HUKILL,H.D. General Public Unities Corp. - GPU Service Corp. 3pp. 45118 029-45118 038

-8804140311 SSER of vol 870917 & 1103 justifications for proposals & & relief requests re-pump & valve inservce testing program denied in 870319 SER Exclusion of stated valves excepted. ar Reactor Regulation, Director (Post 870411) 68/03/31. 7pp

45118 032-45118 038

8804120356 Forwards comments on SALP Rept 50 289/86-98 Guidance in area of proout it was comments on SALF nept 30-201/00-90 condition in ered of pro-cedural compliance will be reinforced to all levels of supervision 8 add action will be taken to strenghlen procedure preparation CLARK.P.R. General Public Utilities Corp. - GPU Service Corp. 88/04/05. Document Control Branch (Document Control Desk). 7pp. 45088-352-45088-358.

8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Cir & for Switch-board Function Due to Faulty Tie Boits," Svc list enct. ROSSICE Division of Operational Events Assessment (Post 870411), 88/04/07 Consolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407:051.

8804200060 Forwards Safety Insp Rept 50-289788-06 on 880222-26.No violations DURB J.P. Region 1, O'c of the Director, 88/04/08, HUKILL, H.D. General Public Utilities Corp. - GPU Service Corp. 2pp. 45220 302-45220 311

-880420064 Insp. Rept. 50.289/88-06 on 880222-26 No violations of deviations octed Major preas inspected pump & valve inservice test program implementation & tender of procedures & test results.

GOLDAJA, GREGGH, EAPEMPK, Region 1, Otc of the Director. 88/03/31. 8pp 45220 304-45220 311

8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc ROSSICE, Division of Operational Events Assessment (Past 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165.150

R. Periodic operating reports & related correspondence

8804060469 "TMI-1 Rept of Total Number of Individuals for Whom Personnel Monitoring Provided for 1987." W/880329 ftr
HUKILL-H O General Public Utilibes Corp. - GPU Service Corp. 87/12/31 3pp. 45079:110-45079 112

8803280079 Forwards "TMI Aquatic Study Monthly Progress Rept for Jan 1898."
RESSLER,W.C. General Public Utilities Corp. - GPU Senice Corp. 88/03/01.
MASNIK,M. NRC - No Detailed Affiliation Given. 1p. 44921.061-44921.062.

~8803280080 "TMI Aquatic Study," Monthly Progress Rept for Jan 1988. NARDACCI,G.A. Radiation Management Corp. (RMC). 88/01/31, 1p. 44921.062

8804190158 Monthly operating rept for Mar 1988 W/880414 ltr.
SMYTH,C.W. HUKILL,H.D. General Public Utilities Corp. GPU Service Corp. 68/03/ 31. 6pp. 45:36 278-45196 283.

S. Reportable occurrences, LERs & related correspondence

8804180374 Summary of Operating Reactors Events Meeting 88-13 on 880329.List of attendees, discussion of events & summary of reactor scrams encl LANNING-W. Events Assessment Branch. 88/03/31. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 18pp. 45149-205-45149-222.

V. Operator Examinations

8804250088 Responds to FOIA request for info re scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in encl app w/personal privacy into deleted GRIMSEEY.D.H. Division of Rules & Records (Post 870413), 88/04/19. BOLEY.K. Public Citizen's Chical Mass Energy Project. 2pp. 45213.003-45213.095.

-- 8804250167 Package of NRC administered requalification exam results summs * NRC - No Detailed Affiliation Grven. 67/07/29 88pp 45213:007-45213:065.

DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8803290403 Forwards safety evaluation accepting present penetration seals, per util 871208 submettal of into \$ evaluation to resolve item A of Insp Rept 50-293/87-39. MCCONALD,D. Project Directorate I-3, 88/03/24, BIRD,R.E. Boston Edison Co. 1p.

-8804010086 Safety 4804010088 Safety avaluation supporting exemption from requirements of 10CFRS0.App B relact of 3-hour fire rated penetration seals in cable spreading room cething/control room floor assembly. * Project Oxectorate I-3: 88/03/24, 3pp. 44919:338-44919.341.

8804040130 Rev 18 to Emergency Plan Implementing Procedure 5.7.2.8, "Control Room Emergency Communicator,"

* Boston Edison Co. 88/03/25 27pp. 44971:171-44971:197.

rept Amend modifies Paragraph 3.G of license to require compliance w/amends reprairies a missines i aragrephi a.g. or incurso to require compliance w/ameros; physical security plan MCDONALD.U.G. Project Directorate I-3. 88/03/28. BIRD,R.E. Boston Edison Co. 4pp. 44997:041-44997:050

8804050139 Forwards Ameno 113

LILUITION

מ כניווט

saroguards evaluation

--8804050145 Amend 115 to Liconse DPR-35,revising Paragraph 3 G of license to guire compliance w/amended physical security plan.
WESSMAN,R.H. Project Directorate I-3, 88703728, 2pp. 44997,045-44997,046

**8804050149 Saleguards ovaluation rupt supporting Amend 115 to License DPR-35
** Office of Nuclear Reactor Regulation, Director (Post 670411) 88/03/28 4pp 44997.047-44997-050.

8804200335 Rev 16 to Procedure 5.7.2.8A-1, "Unusual Event Initial Notification Lst." Boston Edison Co. 88703730, 2pp. 45183.355-45183.358.

8804130072 Forwards Mgt Mooting Ropt 50-293/87-30 on 870930 as followin is 870909 enforcement conference. Topics Included licensee responses to apparent volations identified in this Rept 50-293/87-30 & util security program improvements MARTIN.T.T. Region 1, Oic of the Director. 89/04/05. BIRD.H.G. Boston Ed.scn.Co. 2pp. 45131:027-45131.034.

8804130077 Mgt Meeting Rept 50:293/87:30 on 870830 Major area discussed.followup of 870909 enforcement conference,hoonsee responses to appa-ent violations identified in Insp Rept 50:293/87:30 8 programmatic security improve -8804130077 LANCASTER,W.K., SMITH,G.C., KEIMIG,R.R. Region 1, Old of the Director. 88/03/ 31, 2pp. 45131:029-45131:030.

8804130123 Forwards Enforcement Conference Rept 50-293/07-30 on 870909 to Special Insp 50-293/87-30. Topics discussed include status of security program & alegations of delicioncies in program.

BELLAMY, R. Region 1, Ofc of the Director. 88/04/05. BIRD, R.G. Bosion Edser Co. 2pp 45142:186-45142:181.

--9804130129 Partially withheld Enforcement Conference Insp. Rept. 50-293/67-30 or 870909 (ref. 10CFR73.21) Major areas discussed status of security program & allegations re-deficiencies in security program.
LANCASTERW.K. SMITH.G.C., KEIMIG.R.R. Region 1, Otc. of the Director, 85/03/30 4pp. 45142:188-45142.191.

8804130191 Forwards revised procedure generation package, emergency operating pro-cedures training program summary description & response to NRC open items & questions.psr commitment during NRC 880314-18 onsite evaluation. 8/RO,R.G. Boston Edison Co. 68/04/06 Document Control Branch (Document Control Cest), 22pp. 45167;152-45167;299.

--8804130194 Rev 3 to Emergancy Operating Procedure 1.3.4-10, "Writers Golde for Emergency Operating Procedures" * Boston Edison Co. 88/04/08, 37pp. 45167:174-45167:210.

--8804190085 Rev 2 to Emergency Operating Procedure 1.3 4-13, "Emergency Operating Procedures Verification Program."
 Boston Edison Co. 88/04/06, 49pp. 45187:211-45167:259.

-8604190101 Rev 2 to Emergency Operating Procedure 1.2 4-14, "Emergency Operating Procedure Validation Program."

1 Boston Edison Co. 88/04/06, 36pp. 45187:260-45167:295.

-8804130196 "Emergency Operating Procedures Training Program Summary Descrip-MASTRANGELO,P., ZIEMIANSKI,E.J. Boston Edison Co. 88/03/38. 4pp 45167.296 45167:299.

8804200078 Responds to 880311 ltr re 880211 unusual event at plant & forwards Insp Rept 50:293/89.09.Insp concluded that liconago consorvatively class/fied event and provided notification to Commonwealth of MA State Police as required COLLINS.S.J. Region 1, Old of the Director. 88/04/07. VOGLER.D.J. Duxbury, MA 2pp. 45218 265-45218:276.

--8604200067 Responds to 680301 ltr re 880211 fire event at plant & request for adjudcalory hoaring before allowing restant of reactor. Event was not considered as having obtential to escalate to an event which would have threatened public COLLINS, SJ. Region 1, Ofc. of the Director. 88/03/25, OTT.M.C., MUIRHEAO,D.M. Critzens Urging Responsible Energy. 3pp. 45218:274

8804220045 Forwards "Notice of Environmental Assessment & Finding of No Significal Impact" re 871002 request for exemption from provisions of Section III G.1.(a) of App. R to 10CFR50. MCDONALD,D. Project Directorate 1-3, 88/04/08 BIRD,R. Boston Edison Co. 299 45200:352-45200:356,

-8804220062 Environ assessment & finding of no significant Impact re exemption from provisions of Section III G.1.(a) of App R to 10CFR50. NERSES,V. Project Directorate II-3, 88/04/08, 3pp. 45200:354-45200:358.

8804190139 Ack receipt of 870917 lit providing action plan & schedule for assistance in addressing FEMA Issues re offsite emergency response NRC has no specific action & TAC is being closed.

MCDONALD.O.G. Project Oirectorale 1-3, 88/04/13, BIRD,R.G. Boston Edison Co. 2pp. 45164:308-45164:309.

8804210006 Requests extension of deadline for conduct of next blennial full participa-tion emergency exercise until end of 1988. Delay requested to allow Commonwea'th of MA 8 local govts to implement improvements to emergency preparedness pro-

grams BIRD,R.G. Boston Edison Co. 88/04/14, Document Control Branch (Document Control Desk), 3pp. 45226;302-45226;304

8804250170 Forwards exemption from requirements of 10CFR50,App R, Section III.G.1(a) in response to 871002 request Exemption requested for performing repairs for maintaining plant in hot shutdown following fire in certain plant areas. MCDONALD.G. Project Directorate I-3, 88/04/14. BIRD,R. Boston Edison Co. 7pp. 45213:104-45213;117.



--8804250183 Exemption from certain requirements of 10CFR50,App R,Section III.G 1.(a).Exemption concerns taking manual actions which includes hot shutdown repairs. BOGER,B.A. Division of Reactor Projects - I/II (Post 870411), 88/04/19, 7pp 45213 111-45213:117

H. General correspondence

8804270099 Requests change in distribution for NRC correspondence to replace KP Roberts w/KL Highfill at listed address. BIRD,R G Boston Edison Co. 88/04/19. Document Control Desk) 1p. 45241:244-45241:244.

J. Insurance & Indemnity Information

- 8804070146 Forwards Endorsements 1 & 2 to NELIA Certificates NW-96, NW-103 & NW-34 respectively, Endorsements 1 & 2 to MAELU Cortificates MW-32, MW-62 & MW-8 respectively & Endorsement 140 to NELIA Policy NW-1 & Endorsement 43 to Policy MF-95.

 O'CONNOR, D.J., Marsh & McLennan, Inc. 88/03/28. DINITZ, I. Office of Nuclear Reactor Regulation, Oirector (Post 870411), 87pp. 45098:028-45098:094.
- P. Operating license stage documents & correspondence
- 8804120226 Notification of Licensee Meeting 88-028 on 880224 w/util in King of Prussia,PA to discuss restart readiness reviews.

 BLOUGH,A.R. Region 1, Old of the Director. 88/02/22. Region 1, Old of the Director. 2pp. 45080.043-45090.044.
- 8804250340 Requests to rescope FOIA Request 88-84 re matt limited directly to plant. NICKERSON, J. Athilation Not. Assigned. 88/02/20. ROBINSON, L.L. NRC No Detailed Affirlation Given. 1p. 45213:189-45213:189.
- 8803240426 Generio Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIAF. J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc., 47pp. 44972:107-44972:153.
- 8804130097 Notification of Licensee Meeting 88-043 on 880328 w/util in King of Prussia PA to discuss licensee power ascension program. BLOUGH, A.R. Region 1, Oto of the Director. 88/03/22, Region 1, Oto of the Director. 2pp. 45098:358-45099:359.
- 8804050139 Forwards Amend 115 to License DPR-35 & safeguards evaluation rept.Amend modifies Paragraph 3.G of license to require compfiance w/amended physical security plan MCDONALD,D.G. Project Directorate 1-3, 88/03/28, BIRD,R.E. Boston Edison Co. 4pp. 44897.041-44997.050.
- --8804050145 Amend 115 to License DPR-35,revising Paragraph 3.G of license to require compliance w/amended physical security plan.
 WESSMAN,R.H. Project Directorate I/3. 68/03/28. 2pp. 44997:045-44997:046.
- --3804050149 Safeguards evaluation rept supporting Amend 115 to License DPR-35.
 Office of Nuclear Reactor Regulation, Director (Post 870411). 88/03/28. 4pp. 44997:047-44997:050.
- 8804070196 Supergedes 870611 response to Generic Ltr 87-06, "Periodic Verification of Leak Tight Integrity of Pressure Isotation Valves." All valves on encl have been added to inservice teating program 8 satisfactorily tested.

 BIRD,R.G. Boston Edison Co. 88/03/28, Document Control Branch (Document Control Desk), 5pp. 45024:356-45024:360.
- 8804120383 Rev 1 to notification of Licensee Meeting 88-043 on 880408 w/util in King of Prussa, PA to discuss licensee power ascension program. BLOUGH, A.R. Region 1, Ofc of the Director. 88/03/28. Region 1, Ofc of the Director. 2pp. 45069.326-45089:327.
- 6804110329 Forwards corrected Page 159B to Amend 112 to License DPR-35. Greater than or equal to sign inadvertently omitted from phrase instruction sheet Issued w/ Amend 113 should have listed Page 174b for removal. Page should be removed. MCDONALD,D.G. Project Directorate I-3. 86/03/30. BIRD,R.G. Boston Edison Co. 5pp. 45078:099-45078:106.
- --9804120083 Corrected Page 1588 to Amend 112 to License DPR-35.

 ' NRC No Detailed Affiliation Given. 88/03/30, 2pp. 46078:105-45078:106.
- 8804120416 Informs of corrected sentence in final paragraph of 880229 litrire proposed mods to direct torus veni.Corrected sentence stated.Ltr should be encl w/880229 litr. MCDONALD.D.G. Project Directorate I-3. 88/03/30. BIRD,R.G. Boston Edison Co. 4pp. 45081:303-45091:306.
- 8804080178 Informs that Multi-Plant Action E-04, "BWR Single Loop Operation" closed.TAC numbers for listed plants should be closed & single loop operation reviews should be tracked as plant-specific actions in tuture.

 THADANI,M.C. Project Directorate II-2. 88/04/01. GEARS,G. Ofc of Special Projects. 2pp. 45064:311-45064:316.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Salety for Nuclear Power Plants." Svo 181 encl. MIRAGLIA,F.J., Associate Director for Projects (Post 870411), 88/04/07, Consolidated Edison Co, ol New York, Inc. 49pp. 45184;237-45184;285.
- 8804203265 Expresses disappointment w/880409 article Article made inadequate representation of author 880407 conversation w/ reporter. Incorrect conclusions in article attributed to author itr. Herald should no longer contact author.

 BLOUGH.A.R. Region 1, Oho of the Director. 88/04/13. EISNER, A. Boston Herald, Boston, MA. 3pp. 45225:357-45225:359.
- 8604210299 Forwards response to NRC 880318 questions re restart plan. Directive from station director to site personnel has reemphasized importance of individual responsibility & outlined disciplinary policy for future violations. BiRD_R_G. Boston Edison Co. 88/04/14. Document Control Branch (Document Control Desk). 10pp. 45235:237-45235:248.

- 8804250170 Forwards exemption from requirements of 10CFR50,App R, Section III.G.1(a) in response to 871002 request Exemption requested for performing repairs for maintaining plant in hot shutdown following first in certain plant areas.

 MCDONALD.G.G. Project Directorate 13: 88/04/14. BIRD.R. Boston Edison Co. 7pp 45213:104-45213:117
- #804250183 Exemption from cortain requirements of 10CFR50.App R.Section III.G.1.(e).Exemption concerns taking manual actions which includes hot shutdown re-Division of Reactor Projects - I/II (Post 870411) 88/04/19. 7pp 45213:111-45213:117.
- 8804250350 Final response to FOIA request for records to Boston Edison App A documents located in PDR.
 GRIMSLEY,DH. Division of Rules & Records (Post 870413). 68/04/19.
 NICKERSON,J. Affiliation Not Assigned. 2pp 45213:190-45213.191.

- 8804220155 FOIA request for outstanding items first for restart of Pilgrim Nuclear Power Station in Plymouth, MA, GOLDEN,W.B. Massachusetts, Commonwealth of 88/02/11. Region 1, Otc of the Director, 1p. 45201:160-45201:160
- 8803290403 Forwards safety evaluation accepting present penalization seats,per util 871208 submittal of info 8 evaluation to respive Item A of Insp Hept 50:293/87-39. MCDONALDD. Project Directorate I-3. 88/03/24 BIRD,R.F. Boston Edison Co. 1p. 44019;337-44919.341.
- --8804010086 Safety evaluation supporting exemption from requirements of 10CFR50,App R re-lack of 3-hour fire rated penatration seals in cable spreading room celling/control room floor assembly.
 * Project Directorale I-3, 88/03/24, 3pp. 44919;338-44919 341.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list encl.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 88-010, "Matls Licensons:Lack of Mgt Controls Over Li-consod Programs" Svc list and: CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995:353.
- 8804130072 Forwards Mgt Meeting Rept 50-293/87:30 on 870930 as followup to 870909 enforcement conference. Topics included licensee responses to apparent violetions identified in Inap Rept 50-283/87:30 & util security program improvements. MAPTIN, T. Region 1, Otc of the Director 88/04/05 BIRD, R.G. Boston Edison Co. 2pp. 45131:027-45131:034.
- --8804130077 Mgt Meeting Rept 50-293/87-30 on 870930 Major areas discussed followup of 870909 enforcement conference licensee responses to apparent violations identified in Insp Rept 50-293/87-30 & programmatic security Improvements.
 LANCASTER,W.K., SMITH,G.C., KEIMIG,R.R. Region 1, Ofc of the Director. 88/03/31. 2pp. 45131:029-46131:030.
- --8804130089 Forwards response to apparent violations noted in Insp Rept 50-293/87-30 & 670909 enforcement conference Encl withheld. BIRD,R.G. Boston Edison Co. 87/09/26. Document Control Branch (Decument Control Desk) 4pp 45131.031-45131:034.
- 8804130123 Forwards Enforcement Conference Rept 50-293/87-30 on 870909 re Special Insp 50-293/87-30. Topics discussed include status of security program & elliogations of deficiencies in program BELLAMY, R.R. Rogion 1, Ofc of the Director. 88/04/05. BIRD, R.G. Boston Edison Co. 2pp. 45142;186-45142-191.
- --8804130129 Partially withhe'd Enforcement Conference Insp Rept 50:293/87:30 on 870909 (ref 10CFR73.21) Major areas discussed status of security program 8 alfegations re-deficiencies in security program. LANGASTER,W.K., SMITH,G.C., KEIMIG,R.R. Region 1, Old of the Director, 88/03/30, 4pp. 45142:188-45142:191.
- 8804010266 NRC Info Notice 88-011, "Potential Loss of Motor Control Cir &/or Switchboard Function Due to Faulty Tie Bolts." Svc hat enct. ROSSI,CE. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edean Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804200078 Responds to 880311 lit re 680211 unusual event at plant & forwards tosp Rept 50:293/88-09. Insp concluded that licensee conservatively classified event and provided notification to Commonwealth of MA State Police as required. COLLINS,SJ. Region 1, Otc of the Director, 88/04/07, VOGLER,D.J. Duxbury, MA. 2pp. 45218:265-45218:276.
- --8804200087 Responds to 880301 ltr re 880211 fire event at plant & request for adjudicatory hearing before allowing restart of reactor. Event was not considered as having potential to escalate to an event which would have threatened public. COLLINS,S.J. Region 1, Otc of the Director. 88/03/25. OTT,MC, MUIRHEAD,D.M. Citizens Urging Responsible Energy. 3pp. 45218:274-45218:276.
- 8804200049 Ack receipt of 871026 itr informing NRC of steps taken to correct violations noted in Insp Rept 50-293/67-36. Violation re elevated voltages remains Severity Level JOHNSTON,W.V. Region 1, Ofc of the Director, 88/04/11. BIRD,R.G. Boston Edison Co. 2pp. 45226:330-46228:336.
- --9804200069 Ack receipt of 871026 lir informing NRC of steps taken to correction vio-lations noted in Insp Hept 50-293/87-36 As result of review & evaluation of Paragraph 2 of response, Severity Level IV changed to Level V. JOHNSTON,W.V. Region 1, Ofc of the Director, 87/11/13. BIRD,R.G. Boston Edison Co. 1p. 45226-332-46226-338.

house circuit breakers Plant does not use or plant use of circuit breakers, therefore matter closed MCDONALD, Project Directorate 1-3 88/04/13, 8/AD,RIG Boston Edison Co. 2pp. 46165-356-45165:356.

8804190148 Ack receipt of 871002 response to NRC Bulletin 87-001, "Thinning of Pipe Walls at Nuclear Power Plants," Info provided used to determine extent of industry participation & implementation of erosion/corrosion inspiprograms. MACDONALD, Project Directorate 1-3, 88/04/14 BIRD,R E. Boston Edison Co. 2pp. 45164,310-45164,311.

8804210519 Advises that util 871113 request to provide results 120 days after completing testing of valvos.per IE Bulletin 85-003 granted.
MCDONALD.D. Project Orectorate 1:3 88/04/14. BIRD.R E. Boston Edison Co. 2pp. 45191:130-45191:131.

8804210008 Responds to violations noted in Insp Rept 50-293/87-57. Corrective actions investigations conducted which concluded that unauthorized personnol did not access unfocked doors & disciplinary actions taken against individuals involved. BIRD, R.G. Boston Edison Co. 88/04/15. Document Control Branch (Document Control Desk) 4pp 45239.025-45239.028.

8804280072 Provides hat of augmented inspa conducted at facility & discusses conformance w/applicable regulatory guidance. 8:RD.R.G. Boston Edison Co. 88/04/15. Document Control Branch (Document Control Dash). 2pp. 45281:324-45281-325.

8804220169 Final response to FOIA request for outstanding items 1st of open NRC Inspirems for restant of Pilgnm nuclear power Station Forwards App A document.App A document late as even labra in PDR.
CHIMBLEY,D. Division of Rules & Records (Post 870413), 88704719, GOLDEN,W.B. Massachusetts, Commonwealth of. 2pp. 45201:181-45201:169.

-8804250069 "Outstanding Items List"
* NRC - No Data led Attiliation Given 88/03/02 7pp. 45201:163-45201:169

R. Periodic operating reports & related correspondence

8804080155 Etrala to "Number of Personnel & Man-Rem by Work & Job Function, 1987." W/880329 Itr & related into.
BIRD,R G. Boston Edison Co. 87/12/31, 4pp. 45064.191-45084:194.

8804110181 Table re number of personnel & man-rem by work & job function for 1987,W/860329 in.
8/RD.R.G. Boston Edison Co. 87/12/31, 2pp. 45077:341-45077:342

8804110066 Forwards biwoekly status rept for 880312-25 period NRC insp team visited facility & Chitionville training facility to evaluate revised emergency operating proce-

BLOUGH, A.R. Region 1, Ofc of the Orector, 88/03/30, WidGINS, J.T. Region 1, Ofc of the Orector, 6pp. 45077:280-45077, 265.

8804200145 Monthly operating rept for Mar 1988.W/880414 lir. HAMILTON,P., BIRD,R.G. Boston Edison Co. 88/03/31, 7pp. 45221:178-45221:184

8804270155 Forwards plant blweekly status rept for period 880328-0408. NRC will be conducting public meeting in Plymouth MA to respond to public comments & concerns on util restent plant talsed during 880218 meeting.
BLOUGH,A.R. Region 1, Ofc of the Director. 88/04/19. WIGGINS,J.T. Region 1, Ofc of the Director. 6pp. 45245.321-45245.326.

5. Reportable occurrences, LERs & related correspondence

8803300142 LER 88-007-00.on 880223 unexpected automatic actuation of primary contemment isolation control sys & reactor blog isolation control sys occurred Caused by removal of less from power supply of circuit Fuse replaced.W/880324 ftr. ELLIS,D.W., BIRD,R.G. Boston Ed.son Co. 88/03/24. 5pp. 44975-293-44975:297.

8803300146 LER 88-024 00 on 871006 safety-related 4160 VAC toad cir breaker 152-508 tripped causing loss of power to 460 VAC emergency bus 8-1.Cause undeterminded Equipment returned to svc W/880324 tir. 11AMILTON.P.J., BIRD.R.G. Boston Edison Co. 88/03/24, 5pp. 44976:332-44975.336.

8804040208 LER 88-008-00.on 880226,automatic closing of primary containment sys Group 6 Isolation varies occurred Caused by momentary flow fluctuation in RWCU sys ULI evaluating components installed in flow sensing Fines.W/890228 ftr. ELLIS,D.W., BIRO,R.G. Boston Edison Co. 88/03/28. Spp. 45075:301-45075.305.

8904070129 LER 88-009-00 on 880304,documentation for completion of Surveillance Procedure 8.9.13 not focated for diesel generator 8.0auso undetermined Operating supervisor required to log initiation & completion of tests W/880401 ftr. HAMILTON,P.J., BIRD,R.G. Boston Edison Co. 88/04/01, 5pp. 45044:076-45044:080.

8804190065 LER 88-010-00 on 880311,automatic actuation of portion of primary containment Isolation control sys occurred Caused by blown fuse in inboard containment logic circuity during removal of temp switch, Fuse replaced. W/890411 ltr. ELLIS,D.W., BIRD,R.G. Boston Edison Co. 88/04/111, 5pp. 45197.055-45197.059.

U. Congressional/Executive Correspondence

8804050343 Forwards response to 880217 lif expressing concernire both process NRC adopted to reach decision on restant of plant & possible timing of that decision NRC taking necessary stops to assure that plant will not restant unless licensee ready. ZECHL-W. Commissioners. 88/03/28. KENNEDY,E.M. Senate, Labor & Human Resources, 6pp. 45029.126-45029:135.

DOCKET 50-294 MICHIGAN STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

8603250184 Informs of relocation of NRR to Rockville,MD.Official mailing address remains same & project managers have new locations & phone numbers.TS Michasill lead project manager for facility & A Adams will serve as backup. RUDENSTEIN,L.S. Standardzation & Non-Power Reactor Project Directorato. 68/11. Affiilation Not Assigned. 3pp. 44856.322-44856.324.

DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8804120020 Responds to violations noted in Safeguards Insp Repts 50-295/98 0 50-304/98-09 on 680201-19 Response withheld (ref. 10CFR73.21).
BLISS.H.E. Commonwealth Edison Co. 88/03/31, DAVIS,A.B. Region 3, Otc of the control of 4515-344-4555-34. regior. 1p. 45135:348-45135:349.

8804200260 Rov 1 to Emergency Plan Implementing Procedure EPIP 340-1, "C Damage Assessment," table of contents. RIECK,T. Commonwealth Edison Co. 88/04/04. 3pp. 45177:280-45177:282.

8804150016 Forwards Safety Insp Repts 50-295/87-34 & 50-304/87-35 on 871 860314 & notice of violation. MILLER.H.J. Region 3, Oic of the Director. 88/04/08, REED,C. Commonwe Edison Co. 2pp. 45153.014-46163.046.

--8804150018 Notice of violation from insp on 871116-880314. Violations noted shutdown procedures required by Section III.L of App R to 10CFR60 & plant opera Tech Spec not implemented as listed. MILLER, H.J. Region 3, Ofc of the Director, 88/04/08. 2pp. 45153:016-45153:017.

-8804150046 Insp Repts 50-295/B7-34 & 50-304/87-35 on 871116-880314, Violal noted Major areas Inspected: assessment of compliance w/10CFR50,App R & roof fire protection program requirements.
HOLMES, J. Region 3, Ofc of the Director, PARKINSON,K, Sonalysts, Inc. HODO Brookhaven National Laboratory, 68/04/07, 28pp. 45153:018-45153:048.

8804220113 Ack receipt of 880114 revs to proposed amend to physical sec plan.Addl Info & revs required prior to approval. Requests response to enci commit within 30 days of itr receipt. NORRIS.J.A. Project Directorate III-2. 88/04/13. BUTTERFIELD,L. Commonwi-Edison Co. 3pp. 45201 099-45201:101.

J. Insurance & Indemnity Information

8804120218 Forwards Endorsement 20 to NELIA Policy NF-284, Endorsement 1 MAELU Policy MF-128, Endorsement 30 to NELIA Policy NF-277, Endorsement 2 MAELU Policy MF-114 & Endorsement 194 to NELIA Policy NF-43. OSTERA, Commonwealth Edison Co. 88/04/06. DINITZ, 1. Office of Nuclear Regulation, Director (Post 870411). 13pp. 45090:030-45090:042.

P. Operating license stage documents & correspondence

8803240426 Generic Lir 88-06 to all power reactor licensees & applicants re remover agent atton charts from Tech Spac administrative control requirements. Svc list MIRAQLIA, F. J. Associate Director for Projects (Post 870411). 88/03/22. Consolid Edwan Co. of New York, Inc. 47pp. 44872:107-44872:153.

8804040238 Forwards Amends 108 & 98 to Ucenses DPR-39 & DPR-48, respective safety evaluation. Amends change Tech Specs to upgrade plant program for veriexistence of adequate battery capacity. NORRISJA. Project Directorate III-2, 88/03/28. BUTTERFIELD, L. Commonw. Edison Co. 2pp. 44972:216-44972:228.

→8604040248 Amends 109 & 98 to Licenses DPR-39 & DPR-48,respectively, amended Specs to upgrade plant program for verifying existence of adequate batter

pacity. MULLER, D.R. Project Directorate III-2, 88/03/28, 9pp 44972:218-44972:228

--8804040253 Safety evaluation supporting Amends 109 & 98 to Licenses OPR-DPR-48 respectively.
* Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/28, 4997-227-44972-229.

8804110230 Forwards Amends 110 & 99 to Licenses DPR-39 & DPR-48, respective salety evaluation Amends change Tech Specs re low temp overpressure prote NORRIS_J.A. Project Directorate III-2, 88/04/04, BUTTERFIELD,L. Commonwedson Co. 2pp. 45078;126-45078;142,

--8804110235 Amends 110 & 99 to Licenses OPR-39 & DPR-48,respectively, cha Tech Spacs for low temp overpressure protection. MULLER.D.R. Project Directorate III-2. 88/04/04, 11pp. 45078:128-45078;[38.

--8804110237 Safety evaluation supporting Amends 110 & 99 to Licenses DPR --48, respectively;
Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/04. 45078:130-45078:130-45078:142.



8804110220 Forwards request for addlinfo re-re-uvaluation of plants component cooling water sys in light of problems experienced at Byron/Braidwood plants
MULLER,D.R. Project Directorate III-3 88/04/05. BUTTERFIELD,L. Commonwealth
Edison Co. 5pp. 45078:107-45078:111.

- 8804140193 Provides listed into requested in 880225 ltr re operating nuclear power units located at twolve sites along Great Lakes.
 STELLO,V Old of the Executive Director for Operations 88/04/08. RIDGE,T House of Rep. 5pp. 45104:138-45104:143.
- 8804220242 Forwards Amends 111 & 100 to Licenses DPR-39 & DPR-46, respectively, safety evaluation & technical evaluation rept. Amends allow stoam generator tubes to be repelied utilizing Wostinghouse mechanical sleewing methodology. NORRIS,J.A. Project Directorate III-2. 88/04/06. BUTTERFIELD,I. Commonwealth Edison Co. 3pp. 45200-284-45200.324
- --8804220244 Amends 111 & 100 to Licenses DPR-38 & DPR-48, respectively, changing Tech Space to allow steam generator tubes repair utritzing Westinghouse mechanical sleeving methodology.
 MULLER,D.R. Project Directorate III-2 88/04/06, 8pp 45200:287-45200:284
- -8604220248 Safety evaluation supporting Amends 111 & 100 to Licenses DPR-39 & DPR-48,respectively
 Office of Nuclear Reactor Regulation, Director (Post 870411) 88/04/06. 5pp

45200.295-45200.299

- --8803040290 "Zion Nuclear Power Station Units 1 & 2 Proposed Amend to Facility OLs DPR-39 & DPR-49 to Allow Steam Generator Tube Steaving." 'Science Applications International Corp. (formorly Science Applications, Inc.). NRC-03-87-029. SAIC-86/3002. 86/03/02. NRC No Deteiled Afritation Given 25pp. 45200.300-45200.324
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants ro-modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Saloty for Nuclear Power Plants." Sec fist encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804280039 Forwards Roy 50 to CE-1-A, "QA Program for Nuclear Generating Stations." Revs being made to reflect organizational changes. MORGAN,W.E. Commonwealth Edison Co. 88/04/18. Document Control Branch (Document Control Desk). 1p. 45261:273-45261:209.
- --8804280069 Rev 50 to "QA Program for Nuclear Generating Stations."

 * Commonwealth Edison Co. CE-1-A R50, 89/04/18, 17pp, 45261:274-45261:299

Q. Inspection reports, IE Bulletins & correspondence

- 8803300426 Forwards request for additinfo rejutil 860515,0828 & 870424 & 1124 responses to IE Bulfolin 85-003, "Motor-Operated Valve Common Mode Failures During Plant Transients Due to Improper Switch Sottings."
 GREENMAN,E.G. Region 3, Otc of the Director. 88/03/24. REED,C. Commonwealth Edison Co. 5pp. 44967:238-44967:242
- 8804040139 Forwards Safety Insp Repts 50-265/88-05 & 50-304/88-06 on 880115-0224-No violations of NRC requirements noted. FORNEY.W.L. Region 3, Ofc of the Director. 88/03/25. REED,C Commonwealth Edison Co. 2pp. 44971:198-44971:214.
- --8804040142 Insp. Repts 50:295/88-05. & 50:304/88-06 on 880115-0224.No violations or deviations noted.Major areas inspected.action on provious insp findings,summary of operations, operational safety verification, LERs. & IE. builetins.
 HINDS,J.M. Region 3, Oic of the Director. 88/03/25, 15pp. 44971:200-44971;214.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list encl. ROSSI. C.E. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995.126-44995:246.
- 8803220296 NRC Info Notice 68:010, "Matts Liconsoes:Lack of Mgt Controls Over Li-censed Programs." Svc list onci CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/26. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44985.353.
- 8804120020 Responds to violations noted in Safeguards Insp Repts 50-295/88-08 & 60-304/88-09 on 880201-19.Response withheld (rel 10CFR73.21). BLISS.H.E. Commonwealth Edson Co. 88/03/31, DAVIS,A.B. Region 3, Ofc of the Director. 1p. 45135:349-45135:349.
- 8804010256 NRC into Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switchboard Function Due to Faulty Tie Bolts." Svc list encl.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 08/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407:051.
- 8804140023 Corrects types in 880324 response to NRC 8uffetin 88-002 re-potential for steam generator tube rupture event caused by propagating fatigue crack.Enhanced teakeage monitoring program required for Zion Units 1 & 2. MORGAN,W.E. Commonwealth Edeon Co. 88/04/08. DAVIS,A.B. Region 3, Ofc of the Director. 6pp. 45163:341-45163:346.
- 8804140056 Forwards response to NRC Bulletin 88-001 re Westinghouse Series DS circuit breakers & safety concerns w/breaker use. Schedule for short & long-term insps on all installed & spare 1E,DS-416 & DS-206 breakers at Zion listed. MORGAN,W.E. Commonwealth Edison Co. 88/04/08. DAVIS,A 8. Region 3, Olc of the Director. 7pp. 45155.033-46155:039.
- 8804150016 Forwards Safety Insp Repts 50-296/87-34 & 50-304/87-35 on 871116-880314 & notice of violation.

 MILLER,H.J. Region 3, Ofc of the Director, 88/04/08, REED,C. Commonwealth Edison Co. 2pp. 46163.014-45153:046.
- --8804160018 Notice of violation from Insp on 871116-880314.Violations noted:safe shuldown procedures required by Section III.L of App R to 10CFR50 & plant operating Tech Spec not implemented as fisted.

 MILLER,H J. Region 3, Oic of the Director. 88/04/08. 2pp. 46153.016-45153:017.

- ~8804150046 Insp. Repts 50-295/87-34 & 50-304/87-35 on 871116-880314, Violations noted Major areas inspected assessment of compliance w/10CFR50,App R 8 review of fire protection program requirements. HQLMES_J Region 3, Ot of the Director. PARKINSON,K. Sonalysts, Inc. HODDR,R. Brookhaven National Laboratory, 88/04/07, 29pp. 45153.018-45153.046
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc. lst end. ROSSICE Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165 028-45165.150
- 8804250328 Confirms plans discussed on 880414 between H Bliss & G VanSickle re upcoming 880506 meeting w/ulii to discuss response to IE Bulletin 85:003. GREENMAN.E G Region 3. Oic of the Director. 88/04/18 REED.C. Commonwealth Edison Co. 2pp 45251:120-45251:121.

R. Periodic operating reports & related correspondence

- 8804160251 "Annual Operating Rept for 1987." W/880320 ltr. PLIML,G.J. Commonwealth Edison Co. 87/12/31, 10pp. 45138.050-45138.059
- 8804220153 Forwards orrate data for previously submitted radioactive effluent repts for Jul-Dec 1988. PLIML,G.J. Commonwealth Edison Co. 88/02/09. DAVIS,B. Regran 3, Otc of the Director. 1p. 45247.145-45247:150.
- --8804220154 Errala to "Effluent & Waste Disposal Semannual Ropt, 1986." re gaseous 8 Laurd effluents for Jul-Doc 1986. * Commonwealth Edison Co. 87/12/31, 4pp. 45247:146-45247 147
- --8804220159 Forwards Part 3 of operating rept.consisting of results of environted oldgical 8 meteorological monitoring Part 1 submitted under separate cover in Feb & Part 2, "Radioactive Effluents" submitted in Fots & Aug PLIML.G.J. Commonwealth Edison Co. 88/02/09 DAVIS.A 8 Region 3, Orc of the Director. 1p. 45247.150-45247.150
- 8804140359 Monthly operating repts for Mar 1988 W/880407 lir. AUSTIN,G., PLIML,G.J. Commonwealth Edison Co. 88/03/31, 12pp. 45152:150-45152.161.

S. Reportable occurrences, LERs & related correspondence

- 8804040092 LER 87-001-01 on 870108 discovered explosive gas mixture in holdup tank due to missed Tech Spec surveillance. Caused by inadequate procedure which did not include steps necessary to ensure sampling Procedure revised W880322 III CARLSON, J., PLIML, G.J. Commonwealth Edison Co. 87/02/06 4pp 44970.075-44970.078.
- 88040B0292 LER 88-002-00.on 880301 discovered missed tritum sample from svc bldg verifiation radiation monitoring sys dehumidifier. Caused by failure of sample dehumidifier 8 deficiency in sample collection tracking sys W/880331 II. SCHAEVE, L. PLIML, G. J. Commonwealth Edison Co. 88/03/31. 4pp. 45048:138-45048:141.

V. Operator Examinations

- 8804250088 Responds to FOIA request for info re-scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets I sted in encl app w/personal privacy inlo dialeted GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 88/04/19. BDLEY,K. Publio Citizan's Critical Mass Energy Project. 2pp. 45213.003-45213:095.
- --8804250167 Package of NRC administored requalification exam results summary.
 NRC No Detailed Affiliation Given. 67/07/20, 88pp. 45213:007-45213:095

DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

- 8804010212 Rev 2 to Emergency Plan Implementing Procedure EPIP-8, "Personnel Accountability & Evacuation." W/880326 ltr.
 GRIDLEY,R. Tennessee Valley Authority. 88/03/25. 20pp. 44016 340-44916.359.
- 8804040124 Temporary Change to Rev 0 to Emergency Plan Implementing Procedure EPIP-14, "Radiological Control Procedure." W/ 880330 ltr. GRIDLEY,R. Tennessee Valley Authority. 88/03/30. 12pp. 44970.244-44970:255
- 8804060285 Forwards "Fire Protection Rept" as first step in approach to replace oxisting ficense condition. Ropt includes fire protection plan, 10CFR50 App R sate shutdown analyses & fire hazards analyses for fire areas & zones.
 GRIDLEY,R. Tennessee Valley Authority, 88/04/04, Document Control Branch (Document Control Desk), 9pp. 45067.085-45070;179.
- --8804080290 "Fire Protection Rept." MERRICK,D. WIMBROW,R.T., ANDERSON,C.E. Tonnessee Valley Authority. 88/04/ 04. 1,186pp. 45087:074-45070:179.
- 8804210023 Forwards supplemental response to NRC 871119 ltr re violations noted in Insp. Repts. 50-259/87-33,60-260/87-33 & 60-296/87-33. Corrective actions maint request issued to reasel junction boxes & panels fire protection systates. GRIDLEY,R. Tennessee Vallay Authority, 88/04/13. Document Control Branch (Document Control Desk). 7pp. 45219:126-45219:132.
- 8804180257 Forwards Rev 14 to security personnel training & qualification plan. Rev withheld.
 GRIDLEY, R.L. Tennessee Valley Authority. 88/04/14. Document Control Branch (Document Control Desk). 2pp. 45195-338-45195-339.

- 8804200473 Partial response to FOIA request re fine protection Forwards App E documents App D & E documents evailable in PDR App F document completely withheld (ref FOIA Exemption 5).
 GRIMSLEY, D.H. Division of Rules & Records (Post 870413). 88/04/14. JONES, C.R. Affination Not Assigned 5pp. 45206:037-45206.043.
- ~8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type insp for each facility to assess status of compliance w/ 10CFR50 46.Program issted.

 CONLON,T.E. Region 2, Oic of the Director, 84/11/06. HERDT,A.P. Region 2, Ofc of the Director, 3pp. 45206:176-45206:178.
- 8804220250 Revised amergancy plan implementing procedures including Ray 0 to CECC-EPIP-1, "Emergency Duty Officer Procedure for Notification of Unusual Event Alan, Site Area Emergency & Genoral Emergency," W1880420 ft. GRIDLEY,R.L. Tennossee Valley Authority, 88/04/20, 400pp, 4529:308-45230-322.

J. Insurance & Indemnity Information

- 8804050067 Forwards status & details of property insurance coverage for facilities, per 10CFR50.54 for into.
 GRIDLEY,R. Tennessee Valley Authority, 88/03/30. Document Control Branch (Document Control Desk). 3pp. 44995-358. 44995-358.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8804040111 Forwards util response to ACRS questions from 880212 meeting w/full ACRS committee in Washington, DC. Util will begin screening of LERs of sister plants to Sequoyah & Browns Ferry Nuclear Plants to determine it any actions required GRi/DLEY,R. Tennessee Valley Authority. 88/103/30. Document Convol Branch (Document Convol Branch (Document Convol Desk). 4pp. 44970:232-44970.235.

P. Operating ifcense stage documents & correspondence

- 8803240428 Genenc Ltr 88-96 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list enct. MIRAGLIA,F J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972;107-44972;153.
- 8804010052 Forwards safety avaluation is util responses to Generic Ltr 83.28 terms 3.1.1.3.1.2.3.2.1 & 3.2.2, "Post Maint Testing of Reactor Trip Sys & All Other Safety-Roleied Components" Responses acceptable. ZECH,G.G. Oic of Special Projects. 68/03/23, WHITE,S.A. Tennessee Valley Authority, 3pp. 44920:348-44920:356.
- -8804010057 Safety evaluation supporting util responses to Generic Lir 83:28, Items 3.1.1,3.1.2,3.2.1 & 3.2.2, "Post-Maint Testing of Reactor Trip Sys & All Other Safety-Related Components." Ofe of Special Projects, 88/03/23, 5pp. 44920:352-44920:356
- 8803310129 Forwards Rev 4 to "Design Baseline & Ventication Program." Rev provides detailed explanation of plan essential calculation effort specifically discussed in Rev 2 Section 4.1.4. GRIDLEY.R. Tennessee Valley Authority, 8B/03/25, Document Control Branch (Document Control Desk), 2pp. 44982:325-44982 350.
- --8803310132 Rev 4 to "Design Raseline & Verification Program."

 * Tennessee Valley Authority, 88/02/22, 24pp. 44982:327-44982:350.
- 8804070199 Forwards TVA employee concerns task group subcategory repts. RUSSELL J.R. Tennessee Valley Authority, 68/03/28. Document Control Branch (Document Control Desk), 5pp. 45022-145-45024-257.
- --8804070203 Rev 3 to Employee Concerns Special Program Subcategory Engineering Rept 25000, "Covil/Structural Design (21600) 8 Pipe Whip Restraint Design (22700)." BENKERT J.W., RUSSELL, J.R. Tennessee Valley Authority. 88/03/21, 69pp. 45022:150-45022:238.
- -8804070224 Rev 6 to Employee Concerns Special Program Subcategory Rept 80200, Thep.
 Thep.
- --8804070234 Rev 6 to Employee Concerns Special Program Subcategory Rept 80400, "Nonconformance Control & Corrective Action." HALVERSON, P. D., JOYCE, J.W., BROWN, W.R. Tennessee Valley Authority, 88/03/14, 461pp, 45023;127-45024;257.
- 8804010260 Informs that schedule for response to request for additinfo re-human fac-tors program & isolation devices for SPDS will be provided by 880922. GRIDLEY,R. Tennessee Valley Authority, 88/03/29. Document Control Branch (Docu-ment Control Desk), 7pp. 45058;118-45058;124.
- 8804060067 Requests exemption from time requirements in 10CFR70.51(d) to perform physical inventory of SNM by 880331 due to bit restoring equipment necessary to establish secondary containment,per 10CFR70.14.
 GRIDLEY,R. Tennessee Valley Authority. 88/03/30. Document Control Branch (Document Control Desk). 3pp. 45073.338-45073.340.
- 8804110261 Forwards safety evaluation accepting third vent path of containment atmospheric dilution sys to satisfy requirements of NUREG-0737, liern ILE.4.1. ZECH,G G. Ofte of Special Projects 88/03/31. WHITE,S.A. Tennessee Valley Authority. Spp. 45079.001-45079:005.
- 8804070067 Forwards listing of employee concern numbers shown on util data base as NRC responsibility for evaluation not included in 861231 submittal Requests ack of responsibility.
 RUSSELL,J.R. Tennessee Valley Authority, 88/04/01. Document Control Branch (Document Control Desk). 7pp. 45075:036-45075:042.
- 8804080178 Informs that Multi-Plant Action E-04, "BWR Single Loop Operation" closed TAC numbers for listed plants should be closed & single loop operation reviews should be tracked as plant-specific actions in tuture. THADANI,M.C. Project Directorate If 2, 88/04/01, GEARS,G. Ofc of Special Projects. 2pp. 45064:311-45064:315.

- 8804080088 Generic Ltr 88:07 to power reactor licensees & applicants re-modified en-lorcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Engine International to Safety for Nuclear Power Plants" Svc list onci. MRAGLIA,F J. Associate Director for Projects (Post 870411), 88/04/07 Conscioused Edison Co. of New York, Inc. 49pp. 45164 237-45164:285.
- 8804130310 Notification of 880413 meeting w/util in Decatur,AL to discuss plant restart lest program MORAN,D.H. Oic of Special Projects. 88/04/07, ZECH,G.G. Ofc of Special Projects 3pp. 45103:172-45103:174.
- 8804200368 Notification of canceled 880413 meeting w/util in Decatur.AL ra briefing on plant restart lest program.

 MORAN,D.H. Old of Special Projects. 88/04/07. ZECH,G.G. Old of Special Projects. 3pp., 45179.275-46179 277.
- 8804130184 Notification of 880414 meeting w/util in Decatur,AL to discuss ampacry-cable detailing calculations & cable screening Phase 1,2 & 3 MORAN,D.H. Ofc of Special Projects 88/04/08. ZECH,G.G. Ofc of Special Projects 3pc. 45/01:199-45/101:201.
- 8804210026 Supplemental application for amend to Licenses DPR-33, DPR-52 & DPR-68 Implementing recommendations in Generic Ltr 84-15, "Proposed Stats Actions to improve & Maintain Dissel Generator Reliability." Fee paid. GRIDLEY:R. Tennessee Valley Authority, 88/04/13, Document Centrol Branch (Decument Centrol Desk), 5pp. 45219:133-45219:149.
- ~8804210027 Proposed revised Tech Specs.implementing recommendations of Genesc Lit 84-15, "Proposed Staff Actions to Improve & Maintein Diesel Generator Reliability ity." * Tennessee Valley Authority, 88/04/13, 12pp, 45219,138-45219;149
- 8804260032 Application for amends to Licenses DPR-33 DPR-52 & DPR-68, revising Tech Space 3.4/4.4 re standby liquid control sys. Fee paid GRIDLEY.R. Tennessee Valley Authority. 86/04/20. Document Control Branch (Document Control Desk). 8pp 45254:232-45254:239.
- 8804280618 Notification of 880426 meeting w/util onsite to discuss ampacity cable de-rating calculations & cable screening, Phases 1,2 & 3. MORAN,D.H. Otc of Special Projects. 88/04/21. AULUCK,R. Otc of Special Projects 3pp. 45264.077-45284;079.
- 8804280479 Notification of 880427 meeting w/util In Decatur,AL to discuss restart lest program.
 MORAN,D.H. Ofc at Special Projects. 88/04/22. AULUCK,R. Ofc of Special Projects
 3pp. 45264:101-45264:103.

- 8803290368 Forwards Insp. Repts 50:259/87-38.50:260/87-38.50:296/87-38.50:327/87-68.50:328/87-68.50:390/87-18.50:391/87-18, 50:438/87-08 & 50:439/87-08 on 871005-18 & notice of violation.

 BARR.K.P. Region 2. Voic of the Diractor, 88/03/09, WHITE,S.A. Tennessee Valley Authority, 3pp. 44975:195-44975:208.
- -8803290390 Notice of violation from insp on 871005-18 Violations noted inadequate div of nuclear enginearing training & records, ineffective followup on audit flodings & improper correction of QA records.

 BARH.K.P. Region 2, Oic of the Director, 88/03/09, 3pp. 44975:198-44975:200.
- -8803290393 Insp Repts 50-259/87-38,50-260/87-38,50-296/87-38, 50-327/87-88,50-326/87-86,50-326/87-86,50-390/87-18,50-391/87-18, 50-438/87-08 & 50-439/87-08 Violations noted.Major areas Inspected allogations & licensee action on identified items WALTON,CLA, POWELL,T.B., ELROD,S.A. Region 2, Ofc of the Director. 88/03/68. 8pp. 44975:201-44975.208.
- 8804010028 Ack receipt of 880311 lir informing NRC of steps taken to correct violations noted in linsp Repts 50:255/87:20, 50:250/87:20 & 50:296/87:20. BARR,K.P. Ofc of Special Projects, 68/03/22. WHITE,S.A. Tennessee Valley Authority. 1p. 45058:094-45058:094
- 8804010030 Ack receipt of 880301 supplemental response Informing NRC of steps taken to correct deviations noted in Insp Repts 50-269/87-30,50-260/87-30 & 50-296/87-30 BARR.K.P. Ofc of Special Projects. 88/03/22. WHITE,S.A. Tennessee Valley Authority, 1p. 45031:179-45031:179
- 8803310287 Forwards Insp Repts 50:259/88-04;50:260/88-04 & 50:296/88-04 on 880201:29 & notice of violation.

 BARR.K.P. Region 2, Oic of the Director. 88/03/24, WHITE.S.A. Tennessee Valley Authority. 2pp. 45011:083-45011:108.
- -8803310291 Notice of violation from insp on 880201-29. Violation noted: design basis for Class I burled piping not correctly translated into specs & drawings & Std Practice 9.3 not adhered to for Work Plan WP0017-86, BARR.K.P. Region 2, Ofc of the Director. 88/03/24. 3pp. 45011:085-45011:087.
- -8803310292 Inap Repts 50-259/88-04,50-260/68-04 & 60-296/88-04, viorations noted Major areas inspected-operational safety, maint observation, surveillance testing observation, ROs,previous enforcement action & restart test program PAULK,G.L., BROCKS,C.R., CHRISTNOT,E.F. Region 2, Ofc of the Director. 88/03/ 22. 23pp. 45011:088-45011:109.
- 8804010031 Forwards Insp. Repts 50-259/88-02,50-260/88-02 & 50-296/88-02 on 880101-31 & notice of violation.Concern expressed re implementation of engineering changes & mod programs.

 BARRIK.P. Region 2, Oto of the Director, 88/03/24, WHITE.S.A. Tennessee Valley Authority, 3pp. 45026:081-45028126.

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list onct.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995 128-44995 246
- 8803220296 NRC Info Notice 80-010, "Matts Liconsees:Lack of Mgt Controls Over Liconsed Programs" Svc list enci. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353.
- 8804080224 Ack receipt of 880316 supplemental response to request for addl into re previous corrective actions to Violation 3 noted in Insp Rept 50-259/84-12,50-280/84-12 & 50-296/84-12. Extension of corrective action completion date acceptable BARRK P. Ofc of Special Projects 88/03/29. WHITE,S.A. Tennessae Valley Authority. 2pp. 45007.314-45007.315.
- 8804060528 Ack receipt of 880314 ltr informing NRC of actions taken to correct violations noted in Insp Repts 50.259/87-41, 50-280/87-41 & 50-286/87-41.

 BARR,K P. Ofc of Special Projects 88/03/30. WHITE,S A. Tennossea Valley Authority. 2pp. 45010:277-45010:278.
- 8804080207 Forwards request for addition or util 860513,0830 & 870501 responses to IE Bulletin 85-003, "Motor-Operated Valve Common Mode Fallures During Plant Transients Due to Improper Switch Sottings," for response within 30 days BARRIK P. Ofc of Special Projects 88/04/01. WHITE,S.A. Tonnessee Valley Authority, 4pp, 45099:180-45099.183.
- 8804110131 Supplemental response to violations noted in Insp Repts 50:259/87-14,50-260/87-14 & 50:296/87-14 Corrective actions: work in progress must be completed to demonstrate control bidg pressurization.Completion schedulad for 381115.
 GRIDLEY,R. Tennessee Valley Authority, 88/04/05. Document Control Branch (Document Control Dask). 4pp. 45146.016-45146:019.
- 8804010256 NRC Into Notice 88:011, "Patential Loss of Motor Control Cir &/or Switchboard Function Due to Faulty Tip Bolts " Svc list and. ROSSI, CE. Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp 45408:202-45407:051.
- 8804130246 Responds to NRC 880226 ltr re violations noted in Insp Repts 50:259/87-46,50:250/87-46 & 50:296/87-46.Corrective actions: standby gas treatment sys Train B declared inoporable & Technical Instruction 17B revised GRIDLEY,R. Tennessee Valley Authority, 88/04/08. Document Control Branch (Document Control Desk), 6pp. 45146,322-45146;327.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165:150.
- 8804200555 Forwards Insp Repts 50.259/88-08,50.260/88-08 & 50.298/88-08 on 8803/22-24. No violations or doviations noted. BARRIK P. Region 2, Ofc of the Director. 88/04/13. WHITE,S A Tennessee Valley Authority. 2pp. 45235
- --9804200558 Insp. Ropts 50-259/88-08,50-260/88-08 & 50-296/88-08 on 860322-24 No violations noted Major areas Inspected: competence of operators in Group 4 accelerated requalification training course to perform license duties.
 BROCKMAN,K.E., JOHNSON,A.H., HOPPER,G.T. Region 2, Ofe of the Director, 88/04/11, 5pp. 45235-039-45235:043.
- 8804210017 Summarizes review of NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakers." Bulletin not applicable to Browns Ferry nuclear plant Bulletin applicable to Watts Bar & Bettelbente nuclear plants. List of commitments enct.
 GRIDLEY,R. Tennessee Valley Authority, 88/04/13. Document Control Branch (Document Control Desk). 3pp. 45219:150-45219:152.
- 8894210023 Forwards supplemental response to NRC 871119 ltr re violations noted in Insp. Repite 50-259/87-33,50-260/87-33 & 50-296/87-33.Corrective actions maint request issued to reseal junction boxes & panels fire protection sys area. GRIDLEY,R. Tennessee Valley Authority, 88/04/13. Document Control Branch (Document Control Desk), 7pp. 45219:126-45219:132.
- 8804200473 Partial response to FOIA request re fire protection.Forwards App E documents App D & E documents available in PDR.App F document completely withheld (ref FOIA Examption 5).
 GRIMSLEY,D.H. Division of Rufas & Records (Post 870413), 88/04/14. JONES,C.R. Affiliation Not Assigned. 5pp. 45206:037-45207:042.
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type insp for each facility to essess status of compliance w/ 10CFR50.48.Program listed CONLON,T.E. Region 2, Oic of the Director, 84/11/06. HERDT,A.R. Region 2, Oic of the Director, 3pp. 45206:176.45206:178.
- 8804220032 Forwards response to NRC Bulletin 87-002, "Festener Testing to Determine Conformance W/Applicable Tech Specs." Encl 4 Identifies lasteners transferred from storage & Encl 5 contains list of commitments being made by TVA in response. GRIDLEY,R. Tennessee Valley Authority, 88/04/15. Document Control Branch (Document Control Desk), 165pp. 45219:172-45220.026.
- 8804280524 Notification of 880427 meeting w/licensee in Rockville,MD to discuss independent design inspiror facilities. GEARS G.E. Oic of Special Projects. 88/04/22. AULUCK,R. Oic of Special Projects. 3pp. 45271:054-45271:056.

8804280635 Rosponds to NRC 880309 lit re violations noted in fisted inspirepts, including 50.438/87-08.50-439/87-08 & 50-327/87-68.Corrective actions data base constructed for training GRIDLEY,R. Tennessee Valley Authority. 88/04/22. Document Control Branch (Document Control Desk). 10pp. 45331-341-45331-350.

R. Periodic operating reports & related correspondence

- 8804080383 "Personnel Whole Body Exposure Repts for 1987." W/880401 lir. GRIDLEY,R Tennessee Valley Authority, 87/12/31, 7pp. 45047.080.45047.086.
- 8804070254 "Browns Fatry Nuclear Power Plant Annual Operating Rept to NRC,870101+1231 W/880405 ftr, WALKER,J., GRIDLEY,R. Tennessed Valley Authority, 87/12/31, 108pp. 45074:279-45075-028
- 8804050210 Forwards weekly schodule of TVA activities for wks of 880328 & 0404. KELLY.J.L. Oic of Special Projects 68/03/24. ZECH,G.G. Oic of Special Projects 4pp 45029 088 45029 081.
- 8804140525 Submits weakly schedule of TVA activities for wk of 880404- 11.Schedule will be updated & Issued each Friday to reflect activities for forthcoming 2-wk period KELLY, J.L. Ofc of Special Projects 88703/31. ZECH,G.G. Ofc of Special Projects. 4pp. 45130:205-45130:208
- 8804190140 Month'y operating repts for Mar 1988.W/800414 ftr. CRAWFORD, ID. WALKERJ.G. Tennessee Velley Authority. 88/03/31. 84pp. 45208 070-45208150
- 8804130358 Forwards weakly schedule of TVA activities for wks of 880411 & 18, KELLY, J.L. Ofc of Special Projects. BB/04/08 ZECH,G.G. Ofc of Special Projects 4pp. 45103 216-45103 219.

U. Congressional/Executive Correspondence

8804280317 Forwards NRH responses to Questions 1 & 3 re Commission stds for permilling restant of power plant after shutdown for safety reasons & Commission requirements for documenting scensing bas s for restart decision respectively. THOMAS,C.O. Policy Dovetopment & Technical Support Branch (Post 870411), 867 04/19, REHM,T.A. Ofc of the Executive Director for Operations, 7pp. 45269.209 46299-215.

V. Operator Examinations

- 8804200555 Forwards Insp Repts 50-259/88-08,50-260/88-08 & 50-296/88-08 on 880322-24.No violations or deviations noted. BARI,KP. Rogion 9, Otc of the Director. 88/04/13. WHITE,S A Tennessoa Valley Authority. 2pp 45235:037-45235-043.
- 8804210471 Confirms 880413 folcon w/NRC re utilization of Group 4 operators for liconsect duties Forwards list of Group 4 licensees to whom NRC will administer requallication exams prior to Unit 2 rostert. BARR,K.P. Roglon 2, Orto of the Director. 88/04/13. WHITE,S.A. Tennessee Valley Authority. 3pp. 45227;214-45227.216.
- 8804250088 Responds to FOIA request for info reaccres of reactor operators & senior reactor operators. Forwards requalification exam summary source sheets listed in encl app w/porsonal privacy info deleted.
 GRIMSLEY,D.H. Division of Rubes & Records (Post 870413). 88/04/19. BOLEY,K Public Citizen's Critical Mass Energy Project 2pp. 45213:003-45213.095.
- --8804250 167 Package of NRC administered requalification exam results summary.
 NRC No Deterled Affiliation Given. 87/07/20, 88pp. 45213.007-45213.005

DOCKET 50-297 NORTH CAROLINA STATE UNIV. PULSTAR REACTOR

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address.Malling address unchanged A Adams project manager & TS Michaels back-up project manager. RUBENSTEIN,L S. Slandardzat on & Non-Power Record Project Directorate. 88/03/16. Alfili ation Not Assigned 3pp. 44859.060-44859.062.

Q. Inspection reports, IE Sulletins & correspondence

- 8804120301 Forwards Insp Rept 50:297/88-01 on 880301-04.No violations or deviations noted HERDT,A.R. Region 2. Ofc of the Olrector. 88/04/06 TURINSKY,P.J. North Carolina State Univ., Raleigh, NC. 2ρρ. 45135:317-45135.326.
- --8804120303 Insp Rept 50-297/98-01 on 880301-04.No violations or deviations noted Major areas inspected teaks in RCS piping outside reactor bidg & in isolable portion of reactor primary sys within bidg. BURNETT.P.T. BASSETT.C.H., JAPE.F. Region 2, Otc of the Director. 88/04/04. 8pp. 45135.319-45135.326.

S. Reportable accurrences, LERs & related correspondence

8804080325 PNO-II-88-015B:on 880229,Fcensee Informed NRC that 1 MWI pool reactor had been shutdown due to primary coolant leak outsido containment. Two leaks identiced, Util plans to isolate leak & test further to assure that leak is in liner. FREORICKSON,P. Region 2, Otc of the Director. 88/03/24. 2pp. 45071:360-45071:361.

V. Operator Examinations

8803280056 Informs of reactor operator & senior operator Leensing exams scheduled for wk of 860425 Regulæments for administration of written exams.guidelines for exams & regulæments for fact by review of written exam encl JULIAN.CA. Reg on 2, Ofc of the Director 88/03/11. WEHRING,B. North Carolina State Univ., Rateign, NC 6pp. 44945.017-44945.022

DOCKET 50-298 COOPER NUCLEAR STATION

F. Security, medical, emergency & fire protection plans

- 8803290271 Rev 7 to Emergency Plan Implementing Procedure 5.7.12, "Emergency Rediation Exposure Control." W/680323 Itr.
 TREVORS.G.A. Nebraska Public Power District 88/03/23, 7pp. 44945:096-44945:102.
- 8804050364 Forwards Insp Rept 50:298/68-06 on 880201-29 & notice of violation.

 CALLAN,L.J. Region 4, Ofc of the Director, 88/03/29, TREVORS,G.A. Nebraska Public Power District. 2pp. 45007.022-45007.034.
- -8804060387 Notice of violation from Insp on 880201-29 Violations noted: failure to verify jet pump operability, failure to follow fire protection procedure & failure to perform adequate review of five surveillance procedures
 * Region 4, Ofc of the Director, 88703/23, 2pp 45007 024-45007.025
- -8804060397 Insp Rept 50-298/88-06 on 880201-29.Violations noted Major areas inspected ficensee actions on previous insp findings, operational satisfy verification, LER followup, IE Builletin 84-02 followup, monthly surveillance & maint observations. PLETTNER, E.A. BENNETT, W.R., HOLLER, E.J. Reg on 4, Otc of the Director. 88/03/28. 9pp. 45007-024-45007-034.
- 8804080233 Forwards revised pages to Rev 2 of procedures generation package due to upgredes in traitung program as result of INPO accreditation process. TREVORS.G.A. Nobraska Public Power District. 88/03/31. Document Control Branch (Document Control Desk). 4pp. 45099:1484-45090:151.
- 6804120377 Responds to NRC 880224 fir re violations noted in Insp. Rept 50-298/88-02. Corrective actions matrix being developed to correlate emergency response personnel w/appropriate course.

 TREVORS.G.A. Nebraska Public Powar District, 88/04/05 Document Control Branch (Document Control Desk), 6pp. 45079 261-45079 268.
- 8804130026 Revised emergency plan implementing procedures including Rev. 11 to 5.7.7, "Activation of Technical Support Ctr." Rev. 11 to 5.7.16, "Release Rate Determination" & Rev. 11 to 5.7.17, "Dose Assessment" W/860408 itr. TREVORS.G A. Nebraska Public Power District 88/04/08, 70pp. 45137:152-45137.248
- 8804150378 Forwards SALP Board Rept 50-298/88-01 from Aug 1986 Jan 1988. MARTINR D. Region 4, Old of the Director. 88/04/11. TREVORS,G A. Nabraska Public Power District. 2pp. 45183-236-45183-279.
- --8804150399 SALP Rept 50:298/88-01 for 850801-880131. * Region 4, Ofc of the Director: 88/04/11, 42pp. 45183:238-45183:279.
- 8804200297 Forwards "Exercise Evaluation of Implementation of State & Local Radiological Emergency Response Plans" of 871007 joint exercise & 871203 remedial exercise Fivo deliciencies identified & corrected during remedial exercise. CALLANL J. Region 4, Oilc of the Director. 88/04/13. TREVORS,G A. Nebraska Public Power District, 2pp. 45220:343-45221.043.
- -8804200307 "Exercise Evaluation of Implementation of State & Local Red:ological Emergency Response Plans."

 Nebreska Public Power District, 88/04/13, 61pp. 45220-345-45221:043.
- 8804180328 Forwards response to NRC 880314 ftr re-violations noted in finsp Repts 50-298/67-27,50-298/87-31 & 50-298/67-32. Mitigation not being requested & payment of fee for civil penalty end Encl withheld (ref. 10CF873.21). TREVORS.G.A. Nebraska Public Power District. 88/04/14. Document Control Branch (Document Control Desk). 1p. 45195.334. 45195.334.
- 8904280455 Responds to util inquiries re status of procedures generation package/ emergency operating procedures (PGP/EOP) review.NRC intends to complete PGP/ EOP review by conducting PGP/EOP implementation audit per util 600822 fir. LONG,WO, Project Directorate IV. 88/04/18. TREVORS,G.A. Nobraska Public Power District. 4pp. 45/262:348-45262:351.

J. Insurance & Indemnity information

- 8804200129 Forwards Endorsement 61 to MAELU Policy MF-70 8 Endorsement 77 to NELIA Policy NF-200.
 TREVORS A. Nebraska Public Power District. 88/04/08. Office of Nuclear Reactor Regulation, Director (Post 870411). 5pp. 451
- P. Operating license stage documents & correspondence
- 8803240426 Generic Ltr 68-06 to all power reactor licensees & applicants ro removal of organization charts from Tech Spec administrative control requirements Svc list enct. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972;107-44972.153.
- 8804120387 Application for amend to License DPR-48, revising Tech Specs to add operability & surveillance requirements for alternate shutdown panels. Fee paid. KUNCL, L.G. Nebbaska Public Power District. 88/03/25. Document Control Branch (Oocument Control Desk). 9pp. 45130:327-45130
- --8804120404 Proposed Tech Specs adding operability & surveillance requirements for alternate shutdown panels.
 Nabraska Public Power District. 88/03/25. 7pp. 45130.336-45130:342.

- 8804120425 Application for amend to License DPR-46, revising Tech Specs to reflect replacement of 125 volt do station batteries & chargers during upcoming reflecting outage Fee paid.

 KUNCL_L.G. Nebraska Public Power District. 88/03/25. Document Control Branch (Document Control Desk), 7pp. 45135:338-45135:346.
- --8804120429 Proposed Tech Specs changes reflecting replacement of 125 voll oc station batteries & chargers during upcoming refueling outage.
 * Nebraska Public Power District. 88/03/25. 2pp. 45135:345-45135:346.
- 8804050328 Forwards Rev 4 to OA program. Pev reflects current organization & practices & clarifies responsibilities.
 TREVORS,G.A. Nebraska Public Power District. 88/03/29. Document Control Brank (Document Control Desk).
- -8804050330 Rev 4 to QA program for operation.
 * Nebraska Public Power District. 88/03/28, 85pp. 45033:168-45033:252.
- 8804080256 Forwards Amend 118 to Licensa DPR-46 & safety evaluation. Amend revises Tech Specs to permit installation of lead test assembly fuel assemblies & control blades.

 LONG,W.D. Project Directorate IV. 88/04/01. TREVORS,G.A. Nebraska Public Power District. 5pp. 45065:039-45065:049.
- ~8804080259 Amend 118 to License DPR-46 revising Tech Specs to permit installation of lead test assembly fuel assemblies & control blades. CALVO.J.A Project Directorate IV, 88/04/01. 4pp. 45065:044-45065:047.
- --8804090260 Safety evaluation supporting Amend 118 to License DPA-46.

 * Office of Nuclear Reactor Regulation, Director (Post 870411). 88/04/01. 2pp. 45055:048-45065:049.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re modified onforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants," Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45184:237-45184:285.
- 8804200559 Forwards response to anomalies identified in NRC 880113 SER re-facilty laservice testing program Reactor equipment pumps will be tested in accordance w/ Section XI.Util evaluating need for any relief request in performing test. TREVORS.G.A. Nebraska Public Power District. 88/04/13. Document Control Branch (Document Control Desk). 34pp. 45235;076-46235;109.
- 8804200576 Requests that encl repts, "Demonstration of Compliance W/10CFR50App I Suppl" & "Demonstration of Compliance W/10CFR50App I,Rev 1 & Suppl 2," be entered in document control sys for archiving, CUNNINGHAM,L.J. Radiation Protection Branch, 88/04/15, SKOCZLAS,J.A. Document Control Branch (Document Control Branch (Document Control Desk), 2pp. 45178.001-45176:173.
- 8604260013 Application for amend to License DPR-46, revising Tech Specs re containment purge & vent valves as part of final closeout of Multi-Plant Action Item B.24, "Venting & Purging Conteinment While at Full Power & Effect of LOCA." Fee pad PARRIS, H.G. Nebraska Public Power District 86/04/19, Document Control Branch (Document Control Desk), 6ρρ. 45269.361-45259:362.
- --8804269017 Proposed Tech Specs Pages 165a,173,174,175,180 & 184 re containment vent & purge valves.

 * Nebraska Public Power District. 88/04/19, 6pp. 45259,357-45259,362.
- 8804290064 Requests addf into re SPDS to ensure compliance w/ NUREG-0737, Suppl 1 including discussion of SPDS response times, description of SPDS keyboard in accessing displays & into re location of SPDS terminals in control room. LONG, WO. Project Directorate IV, 88/04/22, TREVORS, G.A. Nebraska Public Power District, 10pp. 45268:302-45268-359.
- -8804290075 "Technical Evaluation Rept for SPDS."

 JOHNSON,W., HANSEN,W. Lawrence Livermore National Laboratory. 87/11/09. NRC

 No Delailed Affiliation Given. 48pp. 45268:312-45268:359.

- 8804050212 Ack receipt of 680218 fir informing NRC of steps taken to correct violations noted in Insp. Rept 50-298/87-25, Implementation of corrective actions will be reviewed during future insp.

 CALLANI, J. Region 4, Ofc of the Director, 88/03/22, TREVORS,G.A. Nebraska Public Power District. 3pp. 44996:098-44996:102.
- 8803210090 Suppt 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors," Syc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/03/28 Consolidated Edison Co., of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 88-010, "Malls Licensees:Lack of Mgt Controls Over Licensed Programs," Svc list encl. CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp, 44995;247-44995;353.
- 8804060384 Forwards Insp Rept 50-298/88-06 on 880201-28 & notice of violation.

 CALLAN,L.J. Region 4, Oto of the Director. 88/03/29. TREVORS,G.A. Nebraska Public Power District. 2pp. 45007:022-45007:034.
- --8804080387 Notice of violation from insp on 880201-29. Violations noted; failure to verify fet pump operability, failure to follow lire protection procedure & failure to perform adequate review of fire surveillance procedures.
 * Region 4, Oto of the Director, 88/03/28, 2pp. 45007:024-45007:025.
- -8804060397 Insp. Rept. 50-298/88-09 on 880201-29 Violations nated Major areas inspected licensee actions on previous insp. findings, operational safety verification, LER followup, IE Builetin 84-02 followup, monthly surveillance & maint observations.

 PLETTNER.E.A., BENNETT.W.R., HOLLER.E.J. Region 4, Oto of the Director. 86/03/28.9pp. 45007;024-45007;0344-

4060036 Forwards Exam Rept 50-298/OL-88-01 administered on 880216-19. ALLAN,L.J. Region 4, Old of the Director, 88/03/30, TREVORS,G.A. Nebraska ublic Power District 2pp. 45047:328-45048:068

i04060042 Exam Rept 50-298/OL-88-01 administered during wk of 880215. Exam re-ults:11 of 13 candidates administered tost passed all portions & will be issued approright from se.

Garage Rease.

GRAVES.D.N., PELLET., J.L. Region 4, Oic of the Director. 88/03/28. 89pp.
5047.330-45048.088.

4120377 Responds to NRC 880224 ltr re violations noted in Insp Rept 50-298/88-2.Corrective actions matrix being developed to correlate emergency response peronnel w/appropriata course.

REVORS,G A. Nebraska Public Power District, 88/04/05. Document Control Branch

Document Control Dosk). 6pp. 45079 261-45079:266.

4130025 Confirms 880331 arrangements for 880420 SALP mgt meeting to discuss sessment for Cooper Nuclear Station for portod Aug 1988 - Jan 1988 ALLANL J. Region 4, Ofc of the Director. 88/04/06. TREVORS,G A Nebraska ublic Power District. 2pp. 45009:356-45099.357.

4010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-pard Function Due to Faulty Tile Botts," Svc list oncl. OSSI,CE: Division of Operational Events Assessment (Post 870411). 88/04/07 onsolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407:051.

4120013 Forwards Insp Rept 50-298/88-04 on 880208-12 & 0229-0304 & notice of

olation.
ALLAN,L.J. Region 4, Olc of the Director. 86/04/07. TREVORS,G.A. Nebraska ublic Power District. 2pp. 45142:128-45142:143.

04120015 Notice of violation from insp on 880208-12 & 0229-0304, Violations oried it could not be established from exam of Identification on blades that all blades for mail specified on procurement documents.

Hegion 4, Ofc of the Director. 88/04/07. 2pp. 45142:130-45142:131.

04120017 Insp Rept 50-298/88-04 on 680208-12 & 29-0304 Violations noted Major eas inspected licensee QA program implementation including areas of records gludocument control & receiving & insp of mails & components.

LERSHAWLE, TAYLOR,RG, BARNES,I. Region 4, Otc of the Director. 88/03/

). 12pp. 45142:132-45142:143.

4140026 Notification of 880420 SALP mgt meeting in Brownville,NE to discuss assessment for Aug 1988 - Jan 1988. Director, 88/04/07. Region 4, Ofc of the Director, 88/04/07. Region 4, Ofc of the Director, p. 45155.054-45155.055.

150378 Forwards SALP Board Ropt 50-298/88-01 from Aug 1986 - Jan 1988. ARTIN,R.D. Rogion 4, Ofc of the Director. 88/04/11. TREVORS,G.A. Nebreska Jolic Power District 2pp. 45183:236-45183:279.

04150399 SALP Ropt 50-298/68-01 for 860801-880131, Region 4, Ofc of the Director. 88/04/11, 42pp. 45183:238-45183.279.

4060370 NRC Info Notice 88 012, "Overgreasing of Electric Motor Bearings." Svc

t enci.
DSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/04/12.
DSSI.C.E. Division Co. of New York, Inc. 123pp. 45165:028-45165:150.

1180328 Forwards response to NRC 880314 ftr re violations noted in Insp Repts 50-18/87-27,50-298/87-31 & 50-298/87-32. Mitigation not being requested & payment fee for civil penalty encl Encl withheld (ref. 10CFR73.21). 3EVORS,G A. Nebreska Public Power District 88/04/14. Document Control Branch ocument Control Desk). 1p. 45195-334-46195-334.

eriodic operating reports & related correspondence

1120306 Monthly operating rept for Mar 1988.W/880405 ltr. CHEUERMAN, J.T., HORN, G.R. Nebraska Public Power District. 88/03/31. 5pp. 132:153-45132:157.

eportable occurrences, LERs & related correspondence

1250074 Forwards LERs 88:004 & 88:005. DRN,G R. Nebraska Public Power District. 88:/04/04. Document Control Branch ocument Control Desk) 1p. 45208:326-45208:332.

14190018 LER 88-004-00:on 880305,actuation of ESF group isolations occurred beequent to plannod manual scram.Caused by plant design.Reactor vessel water real Immediately recovered & plant sys restored to normal condition. TEVES,D.L. Nebraska Public Power District. 88/04/04. 3pp. 45208:327-45208:328.

14250080 LER 88-005-00:on 880305,RWCU sys isolation occurred when RWCU mp lost required NPSH.Caused by sys design re margin existing for RWCU pump SH.Engineering evaluation performed to determine feasibility of implementation and to RWCU sys.

EVES,D.L. Nebraska Public Power District, 88/04/04, 3pp. 45208:330-45208:332.

200256 LER 88-006-00.on 880316,unplanned automatic actuation of diesel general starting logic occurred Caused by target rosot lever inadvertenity contacting ercurrent roley seal-in contacts Reley removed & inspected W/880412 lir. EVES.D.L., HORN.G.R. Nebraska Public Powor District. 88/04/12. 4pp. 46221:151-221:154.

perator Examinations

250295 Forwards results aummary sheet for operator licensing exams administered ring wk of 880215 & reactor operator & sentor operator exams & enswer keys used grading W/o encls.

IAVES,D.N. NRC - No Detailed Affifiation Given. 88/03/21, DUTTON,J. Nebraska blic Power District. 1p. 44945:219-44945:219.

060036 Forwards Exam Rept 50-298/OL-88-01 administered on 880216-19. LLAN,L.J. Region 4, Ofc of the Director. 68/03/30. TREVORS,G.A. Nebraska blic Power District. 2pp. 45047:328-45048:068.

--8804060042 Exam Rept 50:298/OL-88-01 administered during wk of 880215 Exam re-suits 11 of 13 candidates administered tost passed all portions & will be issued appropriate license. GRAVES,D.N. PELLET,JL Region 4, Ofc of the Director, 88/03/28 99pp

45047 330 45048 068

8804150378 Forwards SALP Board Rept 50-298/88-01 from Aug 1986 - Jan 1988, MARTIN,R.D. Rogion 4, Ofc. of the Director, 68/04/11, TREVORS,G.A. Nebraska Public Power District, 2pp. 45183:236-45183,278

--8804150399 SALP Rept 50-298/88-01 for 860801-860131.
* Region 4, Ofc of the Director, 88/04/11 | 42pp | 45183-238-45183.279

DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8804050280 Forwards draft technical ovaluation rept (TEA) to lire protection Tech Specs change for review & response to noted deficiencies WAGNER,D.H. Project Directorate III-3 88/03/25. FAY.C.W. Wisconsin Efective Power Co 7pp. 45028 098-45029:105.

8804060059 Forwards Safety Insp Repts 50-266/88-07 & 50-301/88-07 on 870307-804000039 Forwards Salety help freps 30-250-30-31-31 11.No violations noted. SHAFER.W.D. Region 3, Otc of the Director. 88/03/30. FAY,C.W. Wisconsin Electric Power Co. 2pp. 45034:107-45034:118

--8804060064 Insp. Repls 50-266/88-07 & 50-301/88-07 on 880307-11.No violations deficiencies or deviations noted Major areas inspected emergency preparedness program, including action on provious open items & activations of emergency plan - - FOSTER,J.E. Region 3, Olc of the Director. 88/03/29, 10pp. 45034:109-45034:118

8804110333 Forwards environ assessment & finding of no significant impact re 860611 application for exemption from requirements of 10CFR50,App R,Section III.6.3 b Assessment also forwarded to Ofc of FR for publication. WAGNER,D.H. Project Directorate III.3. 88/04/04. FAY,C W. Wisconsin Electric Power Co. 2pp. 45078.186.45078:184.

--8804110335 Environ assossment & finding of no significant impact re 860611 application, as supplemented by 861010 lift, for exemption from requirements of IOCFR50.App R. Section III G 3 b. PERKINS, K.E. Project Directorate III-3, 88/04/04, 3pp. 45078, 182-45078, 184.

8804200511 Forwards Safety Insp Ropts 50 266/88/08 & 50-301/88/06 on 890201-KNOP,R.C. Reglon 3, Olc of the Director. 88/04/05 FAY,C.W. Wisconsin Electric Power Co 2pp 45231:119-45231:128

8804210245 Forwards Saleguards Insp. Repts 50:266/88:08 & 50:301/88:08 on 88021-31 Apparent violations noted.
MALLETT,B.S. Region 3, Olic of the Director. 88/04/13. FAY,C.W. Wisconsin Electric Power Co. 2pp. 45226:348

--8804210248 Partially withheld Insp Repts 50-266/88-08 & 50-301/88-08 on 880321-31 (rd 10CFR73.21). Violation & open than noted Major areas inspected mgt effectiveness. Security organization, records & repts & losting & moint. DROUIN, B. Region 3, Ofc of the Director. 88/04/11. 2pp. 45226:345-45226:346

H. General correspondence

8803310195 Comment supporting proposed rule 10CFR50,App J ro mass point method of data analysis.Recommends test duration criteria in ANSI/ANS-56.8-1987,Section 5.4 be accepted in revised regulations. FAY,C.W. Wisconsin Electric Power Co. 68/03/18 CHILK,S. Office of the Secretary of the Commission. 2pp. 44964:061-44964.062.

I. Financial Information

8804150278 Forwards 1987 annual rept to stockholders including certified financial statements Rept Included as app to definitive into statement. FLEISSNER,JW Wisconsin Electric Power Co. 88/04/11. Office of Nuclear Reactor Regulation, Director (Post 870411). 25pp. 45138:123-45138:147.

J. Insurance & Indemnity Information

8804140089 Forwards Endorsement 90 to NELIA Policy NF-178 & Endorsement 74 to MAELU Policy MF-53. DUNDAS,W.J. Wisconsin Electric Power Co. 88/03/31. DINITZ,I. NRC - No Detailed Affiliation Given. 3pp. 45163:315-45163:317.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8804130256 Comments on 871021 final rept NSAC-113, "EPRI/Westinghouse Owners Group Analysis of DHR Risk at Point Beach," per NRC request Resources did not permit exam of plant,review of training procedures & emergency guidelines. DAVIS,P.A. Affiliation Not Assigned. 88/01/11. BDEHNERT,P. ACRS - Advisory Committee on Reactor Safeguards 14pp. 45117:326-45117:339.

P. Operating license stage documents & correspondence

8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIAF, J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972.107-44972:153.

- 8804050280 Forwards draft technical evaluation rep) (TER) re lire protection Tech Specs change for review & response to noted deficiencies WAGNEH, D.H. Project Directorate III-3, 88/03/25, FAY,C.W. Wisconsin Efectric Power Co. 7pp. 45029.098 45029:105
- 8804060371 Forwards into package re backround into for Commissioner Carr 880404 & 05 vis.ts to Kewaunee & Point Beach sites, respectively.

 DAVIS AB. Region 3, Otc of the 0xactor, 88/03/28, JOHNSON,M. Region 3, Otc of the Director, 1p. 45076:173-45076.173.
- 8804059088 Forwards response to NAC 870224 request for additinto re 871204 audit of DCRDA project & SPDS Set of human engineering discrepancies (HEDs) that have changed since summary rept submitted & set of pending HEDs onci, FAY,C.W. Wisconsin Efectric Power Co. 88703/29. Document Control Branch (Document Control Desk). 209pp. 44996:123-44996.331.
- 8804140193 Provides listed info requested in 880225 ftr re operating nuclear power units located at twelve sites along Great Lakes.

 STELLOV. Oto of the Executive Director for Operations, 88/04/08, RIDGE,T, House of Rep. 5pp 45104:138-45104:143.
- 8804080088 Generic Ltr 88:07 to power reactor licensees & applicants re-modified en-torcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Salety for Nuclear Power Plants." Svo fist encl. MIRAGLIA,F. J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184 237-45164:285.
- 8804200314 Forwards two-page set of graphs pertaining to plant extracted from rept on performance indicators for operaling commercial nuclear power reactors,set of definitions to tisted indicators & 7-yr history.

 WAGNER, D.H., Project Directorate IN-3, 88/04/08. FAY,C.W. Wisconsin Electric Power Co. 33pp. 45179:178-45179 210.
- 8804220252 Responds to util 880323 ltr reaffirming commitment to check auxillary lead-water piping temp once per shift,per Generic Ltr 88-03.Commitments acceptable Generic Issue 93 considered resolved. WAGNER,D.H. Project Directorate Itl-3, 88704/12, FAY,C.W. Wisconsin Electric Power Co. 2pp. 45200.331-45200.332.
- 8804210356 Responds to 880125 request for relief from ASME Section XI Code requirement determined to be impractical to parform during second 10-yr insp interval at plant Util should consider listed comments & revise proposed relief request. WAGNER.D.H. Project Directorate III-3. 88/04/14, FAY,C.W. Wisconsin Electric Power Co. 3pp. 45191:291-45191:293.
- 8804220048 Forwards Amends 113 & 116 to Licenses DPR-24 & DPR-27, respectively & safety evaluation Amends revise asterisked notes to Tech Spec Table 15 4.1-1 [tem 25, "Steam Generator Pressure," which classifies requirements. WAGNER,D H. Project Directorate III-3, 88/04/14, FAY,C.W. Wisconsin Electric Power Co. 2pp. 45201:067-45201:080.
- -8804220057 Amends 113 & 116 to Licenses DPR-24 & DPR-27, respectively, revising Tech Spec Table 15.4.1-1, Item 25, "Steam Generator Pressure," which clarifies re-quirements for testing of steam generator pressure channels during refueling shut-PERKINS,K.E. Project Directorate III-3, 68/04/14, 7pp, 45201:068-45201:077.
- -8804220060 Salety evaluation supporting Amends 113 & 116 to Licenses DPR-24 & DPR-27 respectively.

 Office of Nuclear Reactor Regulation, Director (Post 670411). 88/04/14. 3pp. 45201:078-45201:080.
- 8804280540 Forwards Amends 114 & 117 to Licenses DPR-24 & DPR-27, respectively & safety evaluation Amends make administrative changes to & clarifies Tech Specs WAGNERD, H. Project Directorate iII-3, 88/04/18, FAY,C W. Wisconsin Electric Power Co. 2pp. 45269 058-45269 082,
- ~8804280551 Amends 114 & 117 to Licenses DPR-24 & DPR-27,respectively, clarifying & making administrative changes to Tech Spec PERKINS,K E. Project Directorate III-3, 88/04/18, 21pp. 45269.060-45269.080.
- -9804280556 Safety evaluation supporting Amends 114 & 117 to Licenses DPR-24 & DPR-27,respectively.

 Office of Nuclear Reactor Regulation, Director (Post 870411). 88/04/18. 2pp. 45269 081-45269:082.

O. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list enci. ROSSI.C.F. Orvision of Operational Events Assessment (Post 870411). 88/03/28, Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Into Notice 88 010, "Matts Licensees Lack of Mgt Controls Over Licensed Programs." Svc list encl.
 CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729), 887
 03728. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995:353.
- 8804060059 Forwards Sefety Insp Repts 50-266/88-07 & 50-301/88-07 on 870307-11.No violations noted.

 SHAFER.W.D. Region 3, Ofc of the Director. 88/03/30. FAY,C.W. Wisconsin Electric Power Co. 2pp. 45034;107-45034.118.
- --8804060064 linep Repts 50-268/88-07 8 50-301/88-07 on 860307-11.No violations deficiencies or deviations noted Major areas inspected emergency preparedness program.including action on previous open items & activations of emergency plan. FOSTER, J.E., PATTERSON, J.P., SNELL, W., Region 3, Ofc of the Director. 88/03/28. 10pp. 45034;109-45034;118.
- 8804200511 Forwards Salety Insp Ropts 50-266/88-06 & 50-301/88-08 on 880201-0316 No violations noted: 0316 No violations noted: KNOP,R.C. Region 3, Ofc of the Director, 88/04/05, FAY,C.W. Wisconsin Electric Power Co. 2pp. 45231;119-45231:128.

- --8804200519 Insp Repts 50-266/88-06 & 50-301/88-06 on 880201-0315 No violations of deviations noted Major areas inspected action on previous insp findings.temporary instructions.operational safety.maint.surveillance.physical security & LER following DEFAYETTE,R. Region 3, Oic of the Director, 88/04/05 8pp. 45231 121-45231 128
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Cir 8/or Switch board Function Due to Faulty Tie Bolts "Syc hat onci. ROSSI, CE. Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804210032 Responds to NRC Bulletin 88-003, "Inadequate Latch Engagoment in HFA Type Latching Relays Mig by GE." Relays not employed at plant FAY.C.W. Wisconsin Electric Power Co. 88/04/11. DAVIS,A.B. Region 3, Ofc of the Director. 1p. 45219:118-45219:118.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc ilst elici. ROSSI,GE: Division of Operational Events Assessment (Post 870411), 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45185:028-45165.150.
- 8804210245 Forwards Sateguards Insp. Repts 50-266/88-08 & 50-301/88-08 on 880321-31-Apparent violations noted.
 MALLETT, B.S. Region 3, Old of the Director, 88/04/13, FAY, C.W. Wisconsin Electric Power Co. 2pp. 45226:343-45226.346.
- ~8804210248 Partially withheld Insp Repts 50-266/88-08 & 50-301/88-08 on 880321-31 (ref 10CFR73.21) Violation & open item noted. Major areas inspected regiseffectiveness, security organization, records & repts & testing & maint. DROUNINB., GALANTI.D., CREED, J.R. Region 3, Otc. of the Director. 68/04/11. 2pp 45226.345-45226.346.
- 8804210366 Responds to 880125 request for relief from ASME Section XI Code requirement determined to be Impractical to perform during second 10-yr inspiratoryal at plant. Util should consider listed comments & revise proposed relief request WAGNER, D.H. Project Directorate III-3. 88/04/14, FAY, C.W. Wisconsin Electric Power Co. 3pp. 45191:291-45191:293.

R. Periodic operating reports & related correspondence

- 8804120415 Monthly operating repts for Mar 1988 W/880408 ftr. KRAUSE C.W., FAY,C.W. Wisconsin Electric Power Co. 88/03/31, 9pp. 45129.143
- 5. Reportable occurrences, LERs & related correspondence
- 8804200684 Requests that Div of Reactor Safety take lead in regional followup to prob-tem at plant & potential generic implications. GREENMAN.E.G. Region 3, Ofc of the Director. 88/04/12. MILLER,H.J. Region 3 Ofc of the Director. 1p. 45175:039-45175:039.

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

- 8803290312 Forwards Insp Repl 50:302/88-01 on 871216-880211 & notice of violation. WILSON,B.A. Region 2, Ofc of the Director, 88/03/11, WILGUS,W.S. Florida Power Corp. (subs. of Florida Progress Corp.), 2pp. 44952:293-44952:313.
- -8603290320 Insp Repl 50-302/88-01 on 871216-880211. Violations noted Major areas inspected plant operations security radiological controls, LERs & nonconforming operations repts (acility mode & review of special repts. STETKAT, TEDROWJ, CRLENJAK.R. Region 2, Ofc of the Director. 88/03/10. 17pp. 44952:287-44952:313.
- 8804290289 Revised emergency plan implementing procedures including Rev 29 to EM-202, "Duties of Emergency Coordinator," Rev 7 to AR-702, "SSFQ Annunciator Re-sponse" & Rev 7 to AR-402, "PSA G Annunciator Response." STEPHENSON,JD. Florida Power Corp. (subs. of Florida Progress Corp.), 88/03/14 128pp. 45282:183-45282:310.
- 8804200063 Rev 4 to AR-703, "SSFR Annunciator Response" & Rev 10 to AR-305, "ESE Annunciator Response." MARSHALL,W., WITTMAN.R. Florida Power Corp. (subs. of Florida Progress Corp.) 88/03/17. 20pp. 45219:069-45219:088.
- 8804200440 Rev 14 to Emergency Plan Implementing Procedure EM-307 re sampling & analysis of RCS, reactor sump & misc waste storage & Rev 7 to EM-305 re post-accident sampling & analysis of effluent releases from plant. STEPHENSON,J.D. Florida Power Corp. (subs. of Florida Progress Corp.), 88/03/22, 113pp. 45218.284-45219.036.
- 8804040155 Clarifles ubli commitment in 870507 ltr to install new security computer for vital area access control sys.New computer to be installed during 1988 will replace RUSCO MAC- 540 controller 8 will be compatible w/remaintener of sys. WILGUS.W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 88/03/28, Document Control Branch (Document Control Desk). 2pp. 45031:317-45031:318
- 8804150205 Forwards Insp Rept 50-302/88-06 on 880212-0311 No violations or deviations noted.
 WILSON,B.A. Region 2, Oic of the Director. 88/04/07. WILGUS,W.S. Florida Power
 Corp. (subs. of Florida Progress Corp.). 2pp. 45175:244-45175:255.
- --8804150208 Insp. Rept. 50-302/88-06 on 880229-0311. No violations or deviations noted Major areas inspected; plant operations, security, radiological controls, LERs & nonconforming operations repts & facility mods, STETKA, T., TEDROWJ., HOLMES-RAY, P., Region 2, Ofc of the Director. 88/04/05 10pp. 45175:246-45175:256.

75

- (804150255 Forwards summary of 880300 enforcement conference relinspiRepts 50-302/87-35 & 50:302/88-03 issues discussor to unauthorized entring into high radi-ation area w/o rad attent monitoring device & health physics responsibilities GHACEJ N Region 2. Oto of the Ovector, R8/04/07 WILGUS,W.S. Florida Power Corp. (subs. of Florida Progress Corp.) 5pp. 45138 215-45138 219.
- 804200072 Rev 4 to Emergency Plan Implementing Procedure AR-504, TCS t. Annun ciator Response."
 WITTMAN,R Florida Power Corp. (subs. of Florida Progress Corp.) 88/04/07, 9pp
- 45226 011 45226 019
- 604180236 Forwards Rov 4-20 to modified amonded security ptan.por 100CFR50.54(g) Rov withhold (rof 100CFR73.21) Will SON,K R. Florida Power Corp. (subs. of Florida Progross Corp.). 89/04/13. Docu-mant Control Branch (Document Control Desk). 1p. 45198-265-45198.265.
- 804180241 Forwards Pagos 34a & 45 to security plan inadvertently omitted from 880120 submittel of Licenso Amend Request 150, Roy 1 Encl withheld WILSON KR Florida Power Curp. (subs of Florida Progress Corp.) 88/04/14 Document Control Branch (Document Control Desk). 1p. 45198 264-45198 264
- 804200473 Partial response to FOIA request re-fire protection Forwards App E documents App D & E documents available in PDR App F document completely withheld (rel FOIA Exemption 5).

 GRIMSLEY, DH Division of Rules & Records (Post 870413) 88/04/14. JONES,C.R. Athiration Not Assigned 5pp 45206 037-45206 043.
- 8804200579 Advises that Fire Protection Storring Committee has recommended that each region make one 16CFR50,App R-type Insp for each facility to assess status of compliance w/ 10CFR50 48 Program Instet! CONLON,TE Region 2, Otc of the Director, 84/11/06 HERIOT,A.R. Region 2, Otc of the Director, 3pp 45206 176, 45206 178.
- 304270322 Revised emergency plan implementing procedures including Rov 7 to EM-203 re re entry procedure Rev 13 to EM-208 re duties of radiation emergency team & Rev 7 to EM-204(A) re release & off-site dose assessment during radialogical. ... STEPHENSON, J.D. Florida Power Corp. (subs. of Florida Progress Corp.), 88/04/15 174pp: 45281:075-45281.246
- 304290291 Acks recept of 880315 ftr transmitting Rov 4-21 to util physical socurity plan 8 informs that changes acceptable for inclusion to plan per 10CFR50.54(p) CLINE, WE Region 2, Otc of the Director, 88/04/25 WILGUS,W.S. Florida Power Corp (subs of Florida Progress Corp.) 3pp. 45283.077-45283.079.

Financial Information

- 104010278 Forwards annual financial repts for eight of participating owners of plant SIMPSON,E C. Florida Power Corp. (subs. of Florida Progress Corp.) 88/03/30 Document Centrol Branch (Document Control Desk). 1p. 44946:013-44947.287.
- 1804010279 "Florida Progress Corp. 1987 Annual Rupt."
 * Florida Powur Corp. (subs. of Florida Progress Corp.) 87/12/31, 251pp. 44946.014-44946.264.
- 1804010281 "Comprehensivo Annual Financial Rept for FY Ending Sopt 1987" * Kissimmee Utility Authority, 87/09/30, 211pp 44946 265-44947;115.
- *804010287 "Comprehensive Annual Financial Rept for FY Ending Sept 1987." * Fallahassoe, FL 87/09/30, 172pp, 44947;116-44947;287.

insurance & indemnity information

- 04070146 Forwards Endorsements 1 & 2 to NELIA Cartificates NW-96, NW-103 & NW-34 respectively, Endorsements 1 & 2 to MAELU Cartificates MW-32, MW-82 & MW-8 respectively & Endorsement 140 to NELIA Policy NW-1 & Endorsement 43 to
- Policy MF-95

 CONNOR,D J. Marsh & McLennan, Inc. 88/03/28, DINITZ,1. Office of Nuclear Reactor Regulation, Director (Post 870411) 67pp. 45098.028-45098.094.

Operating license stage documents & correspondence

- 03240426 Generic Lir 88-06 to all power reactor Lonsdes & applicants re romoval of organization charts from Tech Spec administrative control requirements Svc list encl. VIRAGLIA,F J. Associato Director for Projects (Post 870411) 88/03/22 Consolidated Edison Co. of New York, Inc. 47pp 44972-107-44972 153.
- 04010172 Discusses proposed actions & general consensus on Generic Issue 124 reliability provide assurance that adequate reliability is na nitalned & pleased that rigorous treatment of safety is accepted.

 A/ILGUS,W.S. Florida Power Corp (subs of Florida Progress Corp), 88/03/25 Document Control Branch (Document Control Desk), 4pp. 45058:114-45058:117.
- 04050 195 Forwards safety evaluation accopting util 870115 reanalysis of station coot-town following loss of offsite power, conclusion that clarifications of Tech Specs lases & FSAR required & that clarifications most intent of previous SERs. 3ILVERJI. Project Directorate II-2. 88/03/25. WILGUS.W.S. Florida Power Corp. subs. of Florida Progress Corp.). 2pp. 45029 080-45028 084.
- 804050199 Safety evaluation accepting statements of clarification re-natural circulation cooldown Statements will not adversely affect safe shutdown of plant.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/25, 3pp. 15029.082-45029.084.
- 14010163 Forwards request for addl info re util responses to Generic Ltr 86-05 on mplementation of NUREG-0737,ttem ILK.3.5 conerning reactor coolant pump rip. Response requested within 60 days SILVER,H. Project Directorate II:2. 88/03/28. WILGUS,W.S. Florida Power Corp. subs. of Florida Progress Corp.) 5pp. 44949-022.
- 14010169 Forwards request for retel from certain requirements of ASME Code Secon XI re inservice inspiprogram Approval of request will extend recertification ported rom 3 to 5 yrs. NRC action requested before 880501. VILSON,KI.F. Florida Power Corp. (subs. of Florida Progress Corp.) 88/03/28 Document Control Branch (Document Control Desk). 2pp. 45031:153-45031:154.

- 8804950300 Summary of 880311 magring w/util in Rockville,MD to discuss rollability of omergency feedwater sys at Unit 3.List of attendees ericl SILVER.H. Project Directorate II-2 88/03/28 Project Directorate II-2 88/03/28 44997 211
- 8804010277 Forwards request for add into re-control room habitability sys evaluation SILVER.H. Project Directorate II.2. 88/03/29 WILGUS,W.S Flonde Power Corp. (subs. of Florida Progress Corp.), 8pp. 44948-259-44948-267
- 8804110158 Advises that 880201 Rev 9 to FSAR,consisting of operational QA plan,consistent w/provisions of 10CFH50.54(a) & acceptable JULIAN/C A Region 2, Otc of the Director, 88/03/29 WILGUS,W.S. Florida Power Corp. {subs. of Florida Progress Corp.} 1p 45077.340.45077.340
- 8804080172 Forwards SSER NUREG-1201 re B&W Cwners Group plant reassessment program Ovorall evaluation remains favorable. Add improvement in area of integrated control sys/ non-nuclear instrumentation sys review possible W/o enci. CRUTCHFIELD.0 D.vision of Reactor Projects - III.IV.V & Special Projects (Post 8704.11) 88/03/31 WILGUS,W S Babcock & Wilcox Operating Plants Owners Group WILGUS,W S Florida Power Corp. (subs of Florida Progress Corp.) 7pp. 45076-181.
- 8804080088 Generic Ltr 88.07 to power reactor ficensees & applicants to morthlied un-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list and MIRAGLIA,F.J. Associate Director for Projects (Post 870411): 88/04/07 Consolidated Edison Co. of New York, Inc. 48pp. 45164.237-45164.285
- 8804190107 Forwards environ assessment & finding of no significant impact re-util 880120 application for amend concerning surveillance testing of batterics SILVERIAH Project Directorate In2 8870412, WILGUSWS Florida Power Corp (subs. of Florida Progress Corp.) 2pp. 45164-294-45164-299.
- --8804190111 Environ assessment & finding of no significant impact re util 880120 application for amend concerning surveillance testing of batteries. BERKOW,H.N. Project Directorate It-2, 88/04/12, 4pp. 45164;298-45164;299.
- 8804190357 Forwards Amend 105 to Licenso DPR-72 & safety evaluation Amend re-vises containment air lock survol/lance requirements so that Toch Specs conform to 10CFR50.App J & 861209 examption. SILVER,H. Project Directorate II-2 88/04/13. WILGUS,W.S Florida Power Corp (subs of Florida Progress Corp.) 2pp. 45165.261-45165.269.
- --8804190358 Amend 105 to License DPR-72, revising Tech Specs re-containment air lock surveillanco requiroments BERKOW,H.N. Project Directorate II-2, 88/04/13, 5pp. 45165-263-45165-267
- --8804190359 Safety evaluation supporting Amund 105 to Licenso DPR-72.

 * Office of Nucloar Reactor Regulation, Director (Post 870411) 88/04/13. 2pp. 45185 268 45165 269
- 8804280182 Approves util 880328 request to use ASME Code Case N-356 for applica-tion at plant. Use of code case should be documented in inservice insp program plan. SILVER,H. Project Directorate 11-2, 8804419 WILGUSW S. Flor.da. Power Corp. (subs of Florida Progress Corp.), 1p. 45276.231-45276.231.

- 8803290312 Forwards Insp Rept 50:302/88:01 on 871216:880211 & notice of violation WILSON,B A Region 2, Otc of the Director, 88/03/11 WILGUS,W S. Florida Power Corp. (subs. of Florida Progress Corp.) 2pp. 44952:293-44952:313.
- --8803299316 Notice of violation from Insp on 871216-880211 Violation noted Procedure OP-703 not ubilized during operation of vital bus transfer switches & inverter manual bypass switches.

 WILSON,B A Region 2, Oic of the Director. 88/03/11, 2pp 44952:295 44852:296
- --8803290320 Insp Rept 50-302/88-01 on 871216-880211. Violations noted. Major areas inspected plant operations.accurity.radiological controls, LERs & nonconforming operations repts, lackity mode & review of special ropts.

 STETIKA, T., TEDROW, J., CRLENJAK, R. Region 2, Old of the Director 88/03/10 17pp 44852 297-44952 313
- 8803210090 Suppl 1 to MRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors," Svc list encl ROSSI,C E. Division of Operational Events Assessment (Post 870411). 88703/28 Consolidated Edison Co. of New York, Inc. 121pp. 44995.126.44995.246
- 8803220296 NRC Info Notice 88-010, "Metils Licensees Leck of Mat Controls Over Licensed Programs " Svc Ist enc! CUNNINGHAMR E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03728, Consolidated Edison Co. of New York, Inc. 108pp. 44995 247, 44995;353
- 8804010169 Forwards request for relief from certain requirements of ASME Code Seclion XI to inservice inspiritorium Approval of request will extend reconfication period from 3 to 5 yrs. NRC action requested before 880501 WILSON,K.R. Florida Power Corp. (subs. of Florida Progress Corp.). 88/03/28. Document Control Branch (Document Control Branch (Document Control Branch (Document Control Branch).
- 8804120124 Forwards Insp Ropt 50-302/88-07 on 880307-11.No violations or deviations noted.
 COLLINS,D M. Region 2, Ofc of the Director, 88/04/05, WILGUS,W.S. Florida Power
 Corp. (subs. of Florida Progress Corp.), 2pp. 45128 233-45128 242
- --8804120131 Insp Rept 50-302/88-07 on 880307-11-No violations or deviations noted Major areas inspected figure & gaseous radvaste systeffluent monitoring sys & environ monitoring STODDART.P.G., KAHLE.J.B. Region 2, Ofc of the Director. 88/03/31 8pp. 45128 235-45128:242
- 8804010266 NRC Into Notice 88-011, "Potential Loss of Motor Control Cir &/or Sw.tch-board Function Due to Faulty Tie Bolts " Svc list encl ROSSI,C E Division of Operational Events Assessment (Post 870411) 88/04/07 Consol

- 8804130352 Responds to violations noted in thisp Ropt 50-302/88-01. Corrective actions tripped channels reset & plant returned to pre-event status, operators reviewed actions & made aware of improper switching sequence.

 WILSON,K.R. Flonda Power Corp. (subs. of Flonda Progress Corp.). 88/04/07. Document Control Branch (Document Control Desk). 5pp. 45147.288-45147.292.
- 8804150172 Forwards Insp Rept 50:302/88-08 on 880308-11.No violations or deviabons noted Unresolved item kientified in rept will be pursued in future.
 HERDT,A.R., Region 2, Oic of the Director, 88/04/07, WILGUS,W.S. Flonda Power
 Corp. (subs. of Flonda Progress Corp.), 2pp. 45153,222-45153-232.
- -8804150201 insp Rept 50-302/88-08 on 880308-11.No violations or deviations noted Major areas inspected-ficensee actions associated w/LER 88-006 (reactor trip due to failure of feedwater Block Valva FWV-29).
 HALLSTROMG A. BLAKE J.J. Region 2, Ofc of the Director. 68/04/05. 9pp. 45153 224 45153 232
- 8804150205 Forwards Insp Rept 50-302/88-06 on 680212-0311.No violations or deviations noted.

 WILSON,B.A. Region 2, Ofc of the Director, 88/04/07, WILGUS,W.S. Florida Power Corp. (subs. of Florida Progress Corp.), 2pp. 45175/244-45175/255.
- -8804150208 Insp Rept 50-302/88-06 on 880229-0311 No violations or deviations noted Major areas inspected plant operations, security, radiological controls, LERs & nonconforming operations repts & facility mods
 STETIKA,T. TEDROWJ., HOLMES-RAY,P. Region 2, Ofc of the Director. 88/04/05.
 10pp. 45175 246-45175 255.
- 8804150255 Forwards summary of 880309 enforcement conference re Insp Ropts 50-302/87-35 & 50-302/88-03 Issues discussed re unauthorized entries into high radiation area w/o radiation monitoring device & health physics responsibilities. GRACE_JN. Region 2, Ofc of the Director. 88/04/07. WILGUS_W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 5pp. 45138-215-45138-219.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl.

 ROSSI,C E. Division of Operational Events Assessment (Post 870411), 88/04/12.

 Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150.
- 8804200544 Forwards partial revised response to violations noted in Insp Rept 50:302/81-11.Review of changes to Tech Specs & OL first completed by three person sub-committee to assure diversity of review consistent w/Tech Spec 6.5.2.8.d. WILSON,K R. Florida Power Corp. (subs. of Florida Progress Corp.), 88/04/13. Document Control Branch (Document Control Desk), 3pp. 45235-053-45235.055.
- 8804200473 Partial response to FOIA request re fire profection.Forwards App E documents App D & E documents evailable in PDR App F document completely withheld (ref FOIA Exemption 5). GRIMSLEY,D H. Division of Rules & Records (Post 870413). 88/04/14. JONES,C.R. Affiliation Not Assigned. 5pp. 45206.037-45206.043.
- -8804200579 Advises that Fire Protection Stearing Committee has recommended that each region make one 10CFR50,App R-type lasp for each facility to assess status of compliance w/ 10CFR50,48 Program Insted. CONLON.T.E. Region 2, Oic of the Director. 84/11/08 HERDT,A.R. Region 2, Oic of the Director. 3pp. 45206:176-45206:176.
- 8804210001 Requests extension of submittal date for response to violations noted in Insp Repts 50-302/87-05 & 50-302/88-03. Util will continue to implement corrective actions planned. SIMPSON,E.C. Florida Power Corp. (subs. of Florida Progress Corp.). 88/04/14. Doc-ument Control Branch (Document Control Desk). 1p. 45235-338-45235.338.
- 8804270226 Ack receipt of 880316 responses to violations & deviations noted in Insp. Rept. 50-302/87-40 Responses meet requirements of 10CFR2.201.Implemention of corrective actions will be examined during Iulure insps. WILSON,B.A. Region 2, Ofc. of the Director. 88/04/15, WILGUS,W.S. Florida Power Corp. (subs. of Florida Progress Corp.), 1p. 45244:250-45244:250.
- 8804280182 Approves util 880328 request to use ASME Code Case N-356 for applica-tion at plant Use of code case should be documented in inservice Insp program plan. SILVER,H. Project Directorate II-2. 88/04/19, WILGUS,W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 1p. 45278:231-45276:231.

8804150380 Monthly operating rept for Mar 1988 W/880412 ltr. STEWART,S.A., BINKOWSKI,J.A., WILSON,K.R. Florida Power Corp. (subs. of Florida Progress Corp.), 88/03/31, 5pp, 45192:245-45192,249.

S. Reportable occurrences, LERs & related correspondence

- 8804040103 LER 88-006-00:on 880228,unil experienced reactor trip during power decrease Caused by broken stem nut in yoke of feedwater main block valve 8.Stem nut replaced w/nut mig onsite in accordance w/vendor instructions.W/880329 lfr, MOFFATT,L.W., WILSON,K.R. Florida Power Corp. (subs. of Florida Progress Corp.). 88/03/29. 8pp. 44971:293-44971:301.
- 8804120367 LER 87-013-01:on 870716,17 & 18 output breakers of Channels A & B of emergency feedwater initiation & control opened. Caused by degraded light emitting dode in optical transmitter Light emitting dode replaced.W/880331 ftr. MOFFATT, W. WILSON,K.R. Florida Power Corp. (subs. of Florida Progress Corp.). 88/03/31, 4pp. 45091:162-45091;165.
- 8804130100 LER 88-007-00 on 880127, Train A bldg spray pump operating w/ low discharge head Random sampling & surveillance data review revealed no info re occurrence time & cause. Thorough Investigation & mechanical insp planned. W/880406 ltr. MOFFATT, L.W., WILSON, K.R., Florida, Power Corp. (subs. of Fforida Progress Corp.). 88/04/06, 4pp. 45132:243-45132:246.
- 8804200380 LER 88-008-00:on 860104 instrument drift led to loss of required safety function.Cause of instrument error unknown. Nuclear engineering will evaluate instrument error & corrective action will be based on evaluation.W/880414 tr. MOFFATT,L.W., WILSON,K.R., Florida Power Corp. (subs. of Florida Progress Corp.). 88/04/14, 4pp. 45221:147-45221:150.

8804200382 LER 86 009 00 on 880303 plant periodically operated outside design basis 804200382 LEH 88 003-0010 800303, paint period carry operation obtained seguit basis due to insufficient reserve vol in reactor coolant pump labe oil collection sys. Caused by procedural deficiency Procedure will be revised W/880414 ltr.

MOFFATT, L.W., WILSON, K.R., Florida Power Corp. (subs. of Florida Progress Corp.). 68/04/14 5pp 45226 196-45226 200.

V. Operator Examinations

- 8804250088 Responds to FDIA request for Info re-scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in enci app w/personal privacy info deleted.

 GRIMSLEY.D.H. Division of Rules & Records (Post 870413), 88/04/19. BOLEY,K. Public Citizen's Critical Mass Energy Project. 2pp. 45213:003-45213:095.
- →8804250167 Package of NRC administered requalification exam results summery.
 NRC No Detailed Affiliation Given, 87/07/20, 88pp. 45213:007-45213:095.

DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8804120020 Responds to violations noted in Salaguards Insp Repts 50-295/88-08 & 50-304/88-09 on 880201-19. Response withheld (ref 10CFR73.21), BLISS,H.E. Commonwealth Edison Co. 88/03/31. DAVIS,A.B. Region 3, Old of the Director. 1p. 45135.349-45135:349.
- 8804200260 Rev 1 to Emergency Plan Implementing Procedure EPIP 340-1, "Core Damage Assessment," table of contents. RIECK,T. Commonwealth Edison Co. 88/04/04. 3pp. 45177:280-46177:282.
- 8804150016 Forwards Salety Insp Repts 50-295/87-34 & 50-304/87-35 on 871116-860314 & notice of violation.

 MILLER, H.J. Region 3, Ofc of the Director, 88/04/08, REED,C. Commonwealth Edison Co. 2pp. 45163.014.45153.046.
- --8804150018 Notice of violation from Insp on 871118-880314, Violations noted sate shutdown procedures required by Section III.L of App R to 10CFR50 & plant operating Tech Spoc not Implemented as Islad.
 MILLER,H.J. Reg
- -8804150046 Insp Repts 50-295/87-34 & 60-304/87-35 on 871116-880314. Violations noted Major areas inspected assessment of compliance w/10CFR50,App R & review of fire protection program requirements.

 HOLMES J., GARONER,R.N. Region 3, Otc of the Director. 88/04/07, 28pp. 45153:018-45163.048.
- 8804220113 Ack receipt of 880114 revs to proposed amend to physical security plan. Add Info 8 revs required prior to approval. Requests response to enci comments within 30 days of fit receipt. NORRIS JA Project Directorate III-2 88/04/13. BUTTERFIELD,L. Commonwealth Edison Co. 3pp. 45201.099-45201:101.

P. Operating license stage documents & correspondence

- 8804120307 Corrects error on Page 2 of steam generator activities special rept for 1987 refueling outage Total of 2,260 tubes tested through U-bend in Steam Generator D.not 2,360 as listed in table. Total number of tubes tested still 3,379. RECK,T.A. Commonwealth Edison Co. 88/03/19. DAVIS,B. Region 3, Ofc of the Director, 1p. 45080:051-45080:051
- 8803240426 Generic Ltr 88:08 to all power reactor licensees & applicants re removal of organization charts from Tech Spea administrative control requirements. Svc list encl. MiRAGLIAF. J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804040238 Forwards Amends 109 & 98 to Licenses DPR-39 & DPR-48, respectively & safety evaluation. Amends change Tech Specs to upgrade plant program for verifying existence of adequate battery capacity. NORRISJ A. Project Directorate III-2 88/03/28. BUTTERFIELD,L. Commonwealth Edison Co. 2pp. 44972:216-44972:229.
- -8804040248 Amends 109 & 98 to Licenses DPR-39 & DPR-48,respectively, amending Tech Specs to upgrade plant program for verifying existence of adequate battery capacity.
 MULLER,D.R. Project Directorate III-2. 88/03/28, 9pp. 44972:218-44972:226.
- -8804040253 Safety evaluation supporting Amends 109 & 96 to Licenses DPR-39 & DPR-48,respectively.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/28. 2pp. 44972:227-44972:229.
- 8804110230 Forwards Amends 110 & 99 to Licenses DPR-39 & DPR-48, respectively & salety evaluation Amends change Tech Specs re low temp overpressure protection. NORRIS_JA_ Project Directorate III.2. 88/04/04, BUTTERFIELD Edison Co. 2pp. 45078:128-45078:142.
- --8804110235 Amends 110 & 99 to Licenses DPR-39 & DPR-48,respectively, changing Tech Specs for low temp overpressure proteotion, MULLER,D.R. Project Directorate III-2, 88/04/04, 11pp, 45078:128-45078:138.
- --8804110237 Satety evaluation supporting Amends 110 & 99 to Licenses DPR-39 & DPR-46,respectively.
 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/04, 4pp. 450/8:38-45078:142
- 8804110220 Forwards request for addl into re-re-evaluation of plants component cooling water sys in light of problems experienced at Byron/Braidwood plants.

 MULLER, D.R. Project Directorate IN-3. 88/04/05. BUTTERFIELD, Commonwealth Edison Co., 5pp. 45078;107-45078;111.

- 8804140193 Provides listed Info requested in 880225 ltr re operating nuclear power units located at twelve sites along Great Lakes STELLO,V. Oic of the Executive Director for Operations. 88/04/06. RIDGE,T. House of Rep. 5pp. 45104:138-45104:143
- 8804220242 Forwards Amends 111 & 100 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & technical evaluation rept. Amends allow steam generator tubes to be repaired utilizing Wostinghouse mechanical sleaving methodology, NORRIS, JA Project Directorate III-2, 88/04/06. BUTTERFIELD,L. Commonwealth Edison Co. 3pp. 45200 284-45200.324.
- -8804220244 Amends 111 & 100 to Liconses DPR-39 & DPR-48,respectively, changing Tech Spacs to allow steam generator tubes repair utilizing Westinghouse mechanical steeving molthodology.

 MULLER,D.R. Project Directorate III-2. 88/04/06. 8pp. 45200:287-45200:294.
- -8804220248 Salety evaluation supporting Amends 111 & 100 to Licenses DPR-39 &
- DPR-48,respectively.

 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/06, 5pp. 45200.295-45200 299.
- -8803040290 "Zion Nuclear Power Station Units 1 & 2 Proposed Amend to Facility OLs DPR-39 & DPR-48 to Allow Steam Generator Tube Steeving."

 Science Applications International Corp. (formorly Science Applications, Inc.). NRC-03-87-029. SAIC-88/3002. 88/03/02. NRC - No Dotailed Affiliation Given. 25pp. 45280-300-45280-324.
- 8804080088 Genoric Ltr 88:07 to power reactor licensees & applicants re-modified en-forcement policy concorning 10CFR50.49, "Environ Qualification of Electrical Equip-mont Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA, F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184:237-45164:285.
- 8804280039 Forwards Rev 50 to CE-1-A, "OA Program for Nuclear Generating Stations." Revs being made to reflect organizational changes.
 MORGAN,W.E. Commonwealth Edison Co. 88/04/18. Document Control Branch
 (Document Control Desk). 1p. 45261:273-45261:299.
- -8804280069 Rev 50 to "QA Program for Nuclear Generating Stations."
 *Commonwealth Edison Co. CE-1-A R50, 88/04/18, 17pp, 45261:274-45261:299.

Q. Inspection reports, IE Bulletins & correspondence

- 8803300426 Forwards request for addl Info re util 860515,0826 & 870424 & 1124 responses to IE Bullotin 85-003, "Motor-Operated Velve Common Mode Failures During Plant Translents Due to Impropor Switch Settings."
 GREENMAN,
- 8804040139 Forwards Safety Insp. Repts 50-295/88-05 & 60-304/88-06 on 880115-0224.No violations of NRC requirements noted. FORNEY,W.L. Region 3, Ofc of the Director. 88/03/25. REED,C. Commonwealth Edison Co. 2pp. 44971:188-44971:214.
- --8804040142 Insp Repts 50:295/88:05 & 50:304/88:06 on 880115:0224.No violations or deviations noted Major areas inspected action on previous insp findings summary of operations, operational safety verification, LERs & IE bulletins.
 HINDS,J.M. Region 3, Ola of the Director. 88/03/25. 15pp. 44971:200-44971:214.
- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning In Westing-house Reactors." Svc list encl. HOSSI, CE. Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995;128-44995;246.
- 8803220296 NRC Info Notice 88-010, "Mails Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list encl.
 CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 88/
 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804120020 Responds to violations noted in Safeguards insp Repts 50-295/86-08 & 50-304/88-09 on 880201-19.Response withheld (ref 10CFR73.21).
 BUSS.H.E. Commonwealth Edison Co. 88/03/31. DAVIS,A.B. Region 3, Ofe of the Di rector, 1p. 45135:349-45135:349.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Fautty Tie Botts." Svc list and. ROSSI, CE. Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804140023 Corrects typos in 680324 response to NRC Bulletin 68-002 re potential for steam generator tube rupture event caused by propagating fatigue crack.Enhanced leakage monitoring program required for Zion Units 1 & 2.

 MORGAN.W.E. Commonwealth Edison Co. 88/04/08. DAVIS.A.B. Region 3, Ofc of the Director. 6pp. 45163:341-45163:346.
- 8804140056 Forwards response to NRC Bulletin 88:001 re Westinghouse Series DS circuit breakers & safety concerns w/breaker use. Schedule for short & long-term Insps on all installed & spare 15,05:416 & DS:206 breakers at Zion listed. MORGAN,W.E. Commonwealth Edison Co. 88/04/08. DAVIS,A.B. Region 3, Ofc of the Director. 7pp. 45155:033-45155:039.
- 8804150016 Forwards Safety Insp Repts 50:285/87-34 & 50:304/87-35 on 871116-880314 & notice of violation.
 MILLER,HJ. Region 3, Otc of the Director. 88/04/08. REED,C. Commonwealth Edison Co. 2pp. 45153:014-45153:046.
- ---8804150016 Notice of violation from insp on 871116-880314, Violations noted:safe shutdown procedures required by Section III.L of App R to 10CFR50 & plant operating Tech Spec not implemented as listed. MILLER,H.J. Region 3, Ofc of the Director. 88/04/08. 2pp. 45153.016-45153:017.
- --8804150046 Insp Repts 60:295/87-34 & 50:304/87-35 on 871116-880314. Violations noted Major areas inspected:assessment of compliance w/10CFR50,App R & review of lire protection program requirements. HOLMES_J. Region 3, Otc of the Director. PARKINSON,K. Sonalysts, Inc. HODOR,R. Brookhaven National Laboratory. 88/04/07. 28pp. 45153:018-45153:046.

- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc. list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:160.
- 8804260328 Confirms plans discussed on 980414 between H Blass & G VanSickle re upcoming 880506 meeting w/util to discuss response to IE Bulletin 85-003. GREENMAN,E.G. Region 3, Oic of the Oirector. 88/04/18 REED,C. Commonwealth Edison Co. 2pp. 45251:120-45261:121.

R. Periodic operating reports & related correspondence

- 8804150251 "Annual Operating Rept for 1987." W/880320 tr. PLIML,G.J. Commonwealth Edison Co. 87/12/31, 10pp. 45138.050-45138.059.
- 8803300339 Monthly operating rept for Jan 1988.W/880203 ltr. AUSTIN,G., PLIML,G.J. Commonwealth Edison Co. 88/01/31. 8pp. 44975 359-44976:005.
- 8804220153 Forwards exteta data for previously submitted radioactive effluent repts for Jul-Dec 1986.

 PLIML,GJ. Commonwealth Edison Co. 88/02/09. DAVIS,B. Region 3, Otc of the Director. 1p. 45247:145-45247:150.
- -9804220164 Erreta to "Effluent & Waste Disposal Semiannual Rept, 1986." re gaseous 8 Ilquid effluents for Jul-Dec 1986.

 Commonwealth Edison Co. 87/12/31, 4pp. 45247:146-45247:147.
- rector, 1p. 45247:150-45247:160
- 8804140359 Monthly operating repts for Mar 1988.W/880407 ltr. AUSTIN.G., PLIML.G.J. Commonwealth Edison Co. 88/03/31, 12pp. 45152.150-45152.181.

S. Reportable occurrences, LERs & related correspondence

- 8803290248 LER 88-004-00:on 880224 two diesel generators failed while unit in hot shuldown Caused by selzure of turbocharger. Turbocharger replaced w/new one & correct operating parameters verified W/880325 lfr. KRYSIAK,M.W., PLIML,G.J. Commonwealth Edison Co. 88/03/25. 4pp. 44916:244-
- 8804150030 LER 88-002-00:on 880312, discovered that setpoint for three main sleam safety valves exceeded tolerance limit.Caused by difference in main procedure acceptance criteria. Procedure revised & valves retested & reset W/880411 ftr.

 HARWOOD,R., PLIML,G.J. Commonwealth Edison Co. 88/04/11. 5pp. 45164.013-45164:017.

V. Operator Examinations

- 8804260088 Responds to FOIA request for Info re scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets I sted in encl app w/personal privacy Info deleted.
 GRIMSLEY.D.H. Division of Rules & Records (Post 870413), 88/04/19 BOLEY,K. Public Citizen's Critical Mass Energy Project. 2pp. 45213:003-45213.095.
- -- \$804250167 Package of NRC administered requalification exam results summary.

 * NRC No Detailed Affiliation Given, 87/07/20, 88pp. 45213:007-45213:095.

DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

- 8804010027 Forwards Safeguards Insp Rept 50-305/88-05 on 880216-23 & notice of violation Notice withheld (ref 10CFR73.21).
 MALLETT,B.S. Region 3, Olo of the Director. 88/03/25. HINTZ,D.C. Wisconsin Public Service Corp. 2pp. 46016:173.45016:176.
- ~8804010029 Insp Rept 50:305/88:05 on 880216:23.Violation noted Major areas inspected review of security incident involving vital area barrier degradation that was discovered on 880209 & existed since const of plant.
 KNICELEY.J.R., CREED.J.R. Region 3, Oic of the Director. 88/03/23. 1p. 45016:176-
- 8804040156 Rev P to Emergency Plan Implementing Procedures EP-AD-7, "Notification of Unusual Event," Rev J to EP-ENV-3C, "Primary Dose Projection Calculation IBM PC" & Rev B to EP-App B, "Forms" W/880329 ltr & revised Index HINTZ,D.C. Wisconsin Public Service Corp. 88/03/29, 25pp. 44989,255-44960,279.
- 8804110239 Forwards notice of environ assessment & finding of no significant impact re util 870623 request for exemption from 10CFR50,App R,Section III.G requirements. GITTER,J.G. Project Directorate III-3, 88/03/29, HINTZ,O.C. Wisconsin Public Service Corp. 2pp. 45078:335-45078:340.
- --8804110244 Environ assessment & finding of no significant impact re licensee 870623 request for exemption from 10CFR50,App R, Section Itt.G.3 requirements concerning fire protection. PERKINS,K.E. Project Oirectorate III-3. 88/03/29. 4pp. 45078:337-45076:340.
- 8804070907 Responds to 880301 request to reevaluate NRC position that 871019-20 exercise be treated as offhours exercise. Offhour exercise required once every 6 yrs.conducted between 6 pm & 4 am or on weekends. NORELUS,O.E. Region 3, Otc of the Director. 88/04/01. HINTZ,D.C. Wisconsin Public Service Corp. 4pp. 45048:280-45048:283.

I. Financial information

- 8804060151 Forwards 1987 annual financial repts for Wisconsin Public Svc Corp.Wisconsin Power & Light Co & Madison Gas & Efectic Co HINTZ.D.C. Wisconsin Public Service Corp. 88/03/50. Document Control Branch (Document Control Desk). 1p. 45048-133-45048-244.
- -8804060153 "Wisconsin Public Svc Corp 1987 Annual Rept." STOLL,L.M. Wisconsin Public Service Corp 87/12/31, 35pp 45048.134-45048-168.
- -8804060157 "Wisconsin Power & Light Co 1987 Annual Rept."
 UNDERKOFLER J. Wisconsin Power & Light Co. 87/12/31, 44pp. 45048:169
- --8604060162 "Madison Gas & Electric Co 1987 Annual Rept " HELFRECHT,DJ, Madison Gas & Electric Co. 87/12/31. 32pp. 45048.213-45048.244

J. Insurance & Indemnity Information

8804070026 Advises of amount of onsite property damage insurance maintained by utiliper 10CFR50.54(W)(4).
HINTZ.D.C Wisconsin Public Service Corp 88/03/30. Document Control Branch (Document Control Desk), 1p. 45022:110.45022:110.

P. Operating license stage documents & correspondence

- 8803080441 Forwards Amend 76 to License DPR-43 & safety evaluation. Amend adds *Naense condution & ravises Tech Specs to allow steam* generator tube steeving as method to repar defective steam generator tubes. GIITTER, J.G. Project Directorate III.3. 88/03/01, HINTZ,D.C. Wisconsin Public Service Corp. 3pp. 44638 221-44636 238.
- --8803080446 Amend 76 to License DPR-43 revising Tech Specs to allow steam generator tube sleeving as method to repair defective steam generator tubes. PERKINS,K E. Project Directorate III-3. 88/03/01. 9pp. 44638 224-44638 232.
- -8603080451 Safety evaluation supporting Amend 76 to Licensa DPR-43.

 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/01. 6pp. 44636 233-44636 238
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl MIRAGLIAF. J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co of New York, Inc. 47pp. 44972;107-44972:153.
- 8804060371 Forwards into package re backround into for Commissioner Carr 880404 & 05 visits to Kewaunee & Point Beach sites, respectively. DAVIS.A B. Region 3, Otc of the Director. 88/03/28. JOHNSON,M. Region 3, Otc of the Director. 1p. 45076;173-45076;173.
- 8804070170 Informs of sefection of Westinghouse steam generator low feval ATWS mitigation syst design for installation at facility during 1888 refuelting outage.NRC approval by 880603 requested Addl info enci W/seven oversize drawings. HINTZ_OC. Wisconsin Public Service Corp. 88703/31. Document Control Branch (Document Control Desk) 27pp. 45044.081-45044.107.
- 8804070267 Informs that Rev AF to Drawing M-211,Rev X to Drawing M-217, Rev AC to Drawing M-219 & Rev AX to Drawing XK-100-131 being forwarded to Region III Incident Response Ctr ret library per JG Reppter 800320 request.

 HINTZ-0.C Wisconsin Public Service Corp. 88/03/31. Document Control Branch (Document Control Desk). 1p. 45029 265-45029-265.
- 8804 120080 Informs NRC of mod to proposed reactor vessel surveillance capsule with drawal schedule Capsu'e P scheduled for removal loflowing 17 EFPY of operation. HINT2,D.C. Wisconsin Public Service Copp. 88/04/04. Document Control Branch (Document Control Desk). 2pp. 45135:291-45135:292.
- 8804120470 Notities that steam generator sleeving operations performed during current refueling outage required adjustment in one process control variable. Lower hard roll langth shortened, Change presented to NRC at 880331 meeting. HINT2.D.C. Wiscansin Public Service Corp. 88/04/08. Document Control Branch (Document Control Desk). 1p. 45090:173-45090:173.
- 8804130387 Documents 880316 te'con response re LOCA/ECCS analysis. Analysis submitted in support of fac'rity operation w/peaking factors of 2.28 FQ & 1.55 F delts H at steam generation tube plugging level of 5%. HINTZ_DC. Wisconsin Public Service Corp. 88/04/06 Document Control Branch (Document Control Desk). 1p. 45122.135.45122-135.
- 8804140193 Provides listed Info requested in 880225 fit re operating nuclear power units located at twelve sites along Great Lakes.

 STELLO,V. Ofc of the Executive Director for Operations. 88/04/06. RIDGE,T. House of Rep. 5pp. 45104:133-45104.143.
- 8604080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc 1st end. Svc Miller MIRAGLIAF.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45184:285.
- 8804190061 Advises that NRC finds current situation reflects change in process variables. & agrees to operation of plant w/modified steam generator tube sleeving process per 880331 meeting w/ util & Westinghouse.

 GIITTER.J.G. Project Oirectorate III-3. 88/04/07. HINTZ.D.C. Wisconsin Public Service. Corp. 2pp. 45164 287-45164 288.
- 8804200315 Forwards safety evaluation re util 880328 evaluation of Steam Generator A girth weld flaws that exceeded code limits. Plant can safely return to full power w/flaw indications detected during Mar 1988.
 GIITTER, J.G. Project Directorate III-2 88/04/08. HINTZ, D.C. Wisconsin Public Service Corp. 3pp. 45179.278 45179.286.
- -8804206322 Safety evaluation supporting util 860328 evaluation of flaw indications in Steam Generator A girth weld Significant cracking near inner diameter surface not present in facitity Steam Generator A. Office of Nuclear Reactor Regulation, Director (Post 870411). 88/04/08. 6pp. 45179.281-45179:286.

- 8804210325 Summary of 880331 meeting w/util & Westinghouse re Westinghouse test results supporting change in steam generator tube sleeving process described in Topical Rept WCAP-11643 List of attendees & agenda encl. GIITTERJ.G. Project Directorate III-3. 88/04/08. Project Directorate III-3. 9pp. 45192:113-45192 121.
- 8804190266 Forwards safety evaluation re-topical rept on "Reload Safety Evaluation Methods for Application to Plant," per 870327 summittal Rept acceptable for ref in it.
- cansing plant reloads
 GIITTER J.G. Project Directorate III-3. 88/04/11. HINTZ D.C. Washington Public Power Supply System 2pp. 45166 001 45166 012
- **8804190271 Topical rept evaluation re "Reload Safety Evaluation Methods for Application to Plant." Rept acceptable for rel in licensing documents.
 * Office of Nuclear Reactor Regulation, Orrector (Post 870411). 88/04/11. 10pp 45168:003-45165.012.
- 8804290037 Provides pages from Feb 1988 performance indicator rept that contain data periment to util & addl Into to assist in understanding use of Indicators. GIITTER.J.G. Project Directorate III-3. 88/04/19. HINTZ,D.C. Wisconsin Public Service Corp. 31pp. 45324:185-45324:215.

- 8804010027 Forwards Safeguards Insp. Rept 50-305/88-05 on 880216-23 & notice of violation.Notice withhold (ref. 10CFR73-21).
 MALLETT,B.S. Region 3, Otc of the Director, 88/03/25. HINT2,D.C. Wisconsin Public Service Corp. 2pp. 45016.173-45016:175.
- -8604010029 Insp. Rept. 50-305/88-05 on. 880216-23.Violation noted Mejor areas
- inspected review of security incident involving vitel area barrier degradation that was discovered on 880209 & existed since const of plant. KNICELEY,J.R., CREED,J.R. Region 3, Ofc of the Director. 88/03/23 1p. 45016:175 45016:175.
- 8804200467 Forwards Safety Insp Rept 50:305/88-03 on 880101-0229 & notice of vio-KNOP.R.C. Region 3, Otc of the Director, 88/03/25, HINTZ,D.C. Wisconsin Public Service Corp. 2pp. 45224:087-45224:095.
- --8804200488 Notice of violation from Insp on 880101-0229. Violation noted adequate measures not implemented in selection & review process for parts used in Dosign Change Request 1644, re change to selety-related sys. KNOP, R.C. Region 3, Otc of the Director. 88/03/25. 1p. 45224:089-45224:089.
- -8804200502 Insp Rept 50-305/88-03 on 880101-0229 Violations noted. Major areas Inspected previous Insp IIndings operational safety, surveillance, maint, regional requests, design change mode & temporary instruction reinatural circulation. DEFAYETTER. Region 3, Oic of the Director. 88/03/25. 6pp. 45224.090-45224.095.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors" Syc list enct. ROSSIC.E. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44985:246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees-Lack of Mgt Controls Over Licensed Programs." Svc list encl.

 CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729), 88703/28. Consolidated Edison Co. of New York, Inc. 108pp. 44985:247-44995:353.
- 8804010266 Informs of plan to cancel Kewaunee mid-SALP team inspidue to licensee continued excellent performance in all areas Region III Intent is to follow core program
- at all plants in region.

 DAVIS.A.B. Region 3, Oic of the Director. 88/03/28. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 44945:346-44945:346.
- 8804040110 Notifies that util performing NDE of plping & pressure vessels as part of inservice insp program as stated. Indications determined to exceed allowable limits per Table IWB-3511-1 evaluated & found acceptable Results encl. HINTZ, D.C. Wisconsin Public Service Corp. 88/03/28. Document Control Branch (Document Control Desk). 24pp. 44971.322-44971:345.
- 8804060013 Forwards Exam Rept 50-305/OL-88-01 of exam administered during wk of 880222
- 880222. WRIGHT,G.C. Region 3, Ofc of the Director, 88/03/30, HINTZ,D.C. Wisconsin Public Service Corp. 2pp. 45046 268-45047:059.
- -8804060018 Exam Rept 50-305/OL-88-01 of exam administered during wk of 880222.Exam results all six reactor operator & three senior reactor operator candideles passed exams.

 BRIGGS,L.E., HOPKINS,J.A., LENNARTZ,J.A. Region 3, Oic of the Director. 88/03/30 150pp. 45046:270-45047:059.
- 8804060438 Forwards Safety Insp Rept 50-305/88-07 on 880310-11,15-18 & 21-23.No violations noted HARRISON, J. J. Region 3, Ofc of the Director. 88/04/01. HINTZ, D.C. Wisconsin Public Service Corp. 2pp. 45072.074-45072.081.
- --8804060444 Insp Rept 50-305/86-07 on 880310-11,15-18 & 21-23.No violations or deviation noted.Major areas inspected:eddy current exam of steam generator tubing & ufresonic exam of generator transition girth weld.

 SCHAPKERJ.F., DANIELSON,D.H. Region 3, Ofc of the Director. 88/04/01. 8pp. 45072.076-45072.081.
- 8804130307 Responds to NRG Bulletin 88-002, "Rapidly Propagating Fatigue Cracks in Steam Generator Tubes," requiring util to Implement enhanced primary to secondary leak rate monitoring program.

 HINTZ.D.C. Wiscons'n Public Service Corp. 88/04/04. DAVIS,A.B. Region 3, Ofc of the Director. 2pp. 45122:146-45122:147.
- 8804120056 Forwards Safety Insp Repl 50-305/88-09 on 880322-24 No violations HARRISON,J.J. Region 3, Ofc of the Director, 88/04/05, HINTZ,D.C. Wisconsin Public Service Corp. 2pp. 45142.123-45142:127.

- --8804120060 Insp. Rept. 50-305/88-09 on 880322-24.No violations or deviations noted Major areas Inspected licensee activities re-damaged 4160 volt bus & implementation of commitments to Generic Ltr 83-28. NEISLERJJH, GARDNER,R.N. Region 3, Otc of the Director. 88/04/05. 3pp 45142:125-45142-127
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switchboard Function Due to Faulty Tie Bolls," Svc list encl.
 ROSSI, CE. Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804140019 Responds to NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakors "Breakers subj to bulletin not applicable.

 HINTZ,D.C. Wisconsin Public Service Corp. 88/04/08 Document Control Branch (Document Control Desk) 1p. 45163:354-45163:354.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/04/12.

 Consolidated Edison Co. of New York, Inc. 123pp. 45185:028-45165:150.
- 8804250145 Provides addl info re mothod of implementing leakage monitoring program,per NRC Bulletin 88-002 Administrative limits will be incorporated into plant procedures which require increased frequency of leak rate determinations. HINTZ_D.C. Wisconsin Public Service Corp. 88/04/13. DAVIS.A B. Region 3, Ofc of the Director. 7pp. 45237:107-45237:113.
- 8804250275 Forwards response to NRC 880325 litr ra violations noted in insp Rept 50-305/88-05 Response withheld (raf 10CFR73.21). HINTZ,D.C. Wiscansin Public Service Corp 88/04/22. Document Control Branch (Document Control Desk). 1p. 45251:118-45251:118.

8804150143 Monthly operating rept for Mar 1988,W/880411 ltr.
RUITER,G.H., HINTZ,D.C. Wisconsin Public Service Corp. 88/03/31, 5pp. 45183:208-

S. Reportable occurrences, LERs & related correspondence

8804130113 LER 88-001-00 on 880302,reactor trip occurred Caused by Insulation failure on bus bar combined w/accumulation of debris & water.Damagod section of bar will be replaced & bar vendor to recommend corrective actions.W/880404 ltr.
BERGMANN,J.W., HINTZ,D.C. Wisconsin Public Sarvice Corp. 89/04/04. 6pp. 45161:061-45151:066

V. Operator Examinations

- 8804060013 Forwards Exam Rept 50:305/OL-88:01 of exam administered during wk of WRIGHT.G.C. Region 3, Ofc of the Director. 88/03/30. HINTZ,O.C. Wisconsin Public Service Corp. 2pp. 45046:268-45047:059.
- --8804060018 Exam Rept 50:305/OL:88:01 of exam administered during wk of 880222.Exam results;all six reactor operator 8 three senior reactor operator candidates passed exams BRIGGS, L.E., HOPKINS, J.A., LEN 30, 150pp. 45046:270-45047:059. LENNARTZ,J.A. Region 3, Oto of the Director, 88/03/

DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8804140039 Confirms special inspidates of 880718-22 established during 880405 telcon w/K Beadell to reevaluate compliance w/ applicable 10CFR50,App R sections.Current revs to listed add into requested prior to pre-App R meeting. HARRISON.J. Region 3, Otc. of the Director. 88/04/07. LARSON.C.E. Northern States Power Co. 3pp. 45147:335-45147:337.
- 8804180252 Forwards Rev 8 to security force training & quelification plan,per 10CFR50.54(p). Rev withheld (ref 10CFR73). LARSON,C.E. Northern States Power Co. 88/04/12. Document Control Branch (Document Control Desk). 1p. 45198:266-45198:286.
- 8804180258 Forwards Rev 18 to security plan,per 10CFR50.54(p).Rev withheld (ref LARSON,C.E. Northern States Power Co. 88/04/12. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 45198 263-45198:263.
- 8804180261 Forwards Rev 2 to safeguards contingency plan.per 10CFR50.54(p).Rev withheld (ref 10CFR73).

 LARSON.CE. Northern States Power Co. 88/04/12, Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 45195:337-45195:337.
- 8804270274 Ack receipt of 880325 ltr re plant emergency plan exercise scheduled for 880622 Exercise scope & objectives acceptable.
 SHAFER,W.D. Region 3, Old of the Director, 88/04/19, LARSON,C.E. Northern States Power Co. 1p. 45242:360-45242:360.

P. Operating license stage documents & correspondence

- 8903240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements. Svc list encl. MIRAGLIA, F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804190063 Forwards notice of consideration of Issuance of amends to Licenses DPR-42 & DPR-60 & opportunity for hearing concerning 870928 application.
 DIIANNI,D.C. Project Directorate III-3. 88/04/05. MUSOLF,D.M. Northern States Power Co. 3pp. 45158:288-45158:295.

- -8804190096 Notice of consideration of Issuance of amend to License DPR-42 & DPR-60 Amend changes surveillance test frequency of turbine stop valves in Tech Specs VIRGILIO,M J. Project Directorate III-3, 88/04/05, 5pp. 45158.291-45158:295.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Etison Co. of New York, Inc. 49pp. 45164:237-45184:285.
- 8804280101 Forwards Amends 82 & 75 to Licenses DPR-42 & DPR-60, respectively & safety evaluation Amends change Tech Specs 6.1-2.6.1.D & 8.6.G re administrative requirements.per util 870814.27 & 980104 & 0210 applications.

 DILANNI,D.C. Project Directorate III-1, 88/04/18. MUSOLF,D.M. Northern States Power Co. 3pp. 45262:296-45262:309.
- ~8604280129 Amends 82 & 75 to Licenses DPR-42 & DPR-60,respectively, revising Tech Specs in response to 870814 application suppl by 870827,880104 & 0210 firs VIRGILIO,MJ. Project Directorate III-1, 88/04/18, 8pp. 45262:299-45262.306.
- --8804280156 Salety evaluation supporting Amends 82 & 75 to Licenses DPR-42 & DPR-60 respectively.
 Oltroo of Nuclear Reactor Regulation, Director (Post 870411). 88/04/18 3pp. 45262:397-45282:309.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc hist encl ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 88-010, "Matis Licensees:Lack of Mgt Controls Over Li-Censed Programs " Svc Isl enci.
 CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 887
 03/28. Consol dated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.
- 8804010266 Informs of plan to cancel Kewaunee mid-SALP team inspidue to licensee continued excellent performance in all areas. Region III Intent is to follow core program at all plants in region.

DAVIS.A.B. Region 3, Ofc of the Director, 88/03/28, MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 1p. 44945;346-44945;346,

- 8804150374 Responds to NRC Compliance Bulletin 88-003, "Inadequate Latch Engagement in HFA Type Latching Relays Mig by GE." Subj latching relays not used in Class IE svc at plant.

 LARSON,C.E. Northern States Power Co. 88/04/06. Document Control Branch (Docu-
- ment Control Desk). 2pp. 46138:181-45138:182.
- 8804010256 NRC Into Notice 88-011, "Potential Loss of Major Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svc list encl. ROSSI, CE. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804140039 Confirms special inspirates of 880718-22 established during 880405 telcon w/K Beadell to reovaluate compilance w/ applicable 10CFR50,App R sections.Current roys to listed addition requested prior to pre-App R meeting. HARRISON,J.J. Region 3, Oto of the Director, 88/04/07, LARSON,C E. Northern States Power Co. 3pp. 45147:335-45147:337.
- 8804200654 Provides final response to IE Bulletin_85-003, "Motor- Operated Valve Common Mode Fallures During Plant Transients Due to Impropor Switch Settings."

 Program implemented to ensure valve operator switch operational readiness.

 LARSON,CE Northern States Power Co. 88/04/08. Ditce of Nuclear Reactor Regulation, Director (Post 670411). 9pp. 45219.039-45219.047.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc ROSSICE, Division of Operational Events Assessment (Post B70411), 68/04/12, Consolidated Edison Co. of New York, Inc. 123pp. 45165;028-45165;150.
- 8804210327 Forwards proprietary WCAP-11787 & nonproprietary WCAP-11788, "Pre'rie Island Unite 1 & 2 Everuation for Tube Vibration Induced Fatigue," in response to NRC Compliance Bullotin 88-002 & 880325 application to withhold proprietary Info. LARSON.C.E. Nonthern States Power Co. 88/04/12. Document Control Branch (Document Control Branch (Bocument Control Branch (Boc ment Control Deskt. 3pp. 45194:001-45194:160.
- --8804210364 Requests that proprietary WCAP-11787, "Prairie Island Units 1 & 2 Evaluation for Tube Vibration Induced Fatigue," be withheld from public disclosure (ref. 10CFR2.790(b)(1)). WIESEMANN,R.A. Westinghouse Electric Corp. 88/03/25, MURLEY,T. Office of Nuclear Reactor Regulation, Director (Post 870411), 10pp. 45194:004-45194:013.
- -8804210382 "Prairie Island Units 1 & 2 Evaluation for Tube Vibration Induced Fa-
- ligue."
 CONNORS,H.J., FRICK,T.M., HALL,J.M. Westinghouse Electric Corp. WCAP-11788.
 88/03/31, 210pp. 45184.014-45184:160.

R. Periodic operating reports & related correspondence

8804150133 Monthly operating repts for Mar 1988.W/880411 ltr.
DUGSTAD,D., MUSOLF,D. Northern States Power Co. 88/03/31. 8pp. 45153:111-

V. Operator Examinations

8803300243 Informs of rev to commitment made several yrs ago re training of licensed operators in response to Generic Ltr 87-07.Fecility to conduct operator training in future in accordance w/accredited program. MUSOLF.D. Northern States Power Co. 88/03/21. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 44979:139-44979:139.

- 8804110054 Informs that operator & senior operator Loonsing exams scheduled for wks of 880711 & 18 flequests properly bound & indexed ref matt at least 60 days prior to exam date.W/ stated cricls
 WRIGHT,G C. Reg on 3, Old of the Director 88/04/06, LARSON,C E. Northern States Power Co. 10pp. 45129.310.45129.319
- 8804150382 Informs of revito shift technical advisor (STA) training program originally provided to NRC in util 610130 tir. Revidue to completion of STA task list for accreditions of STA task list for accreditions of STA task list for accreditions.
- MUSCLED Northern States Power Co. 88/04/88 Document Control Branch (Document Control Desk) 1p 45138 205 45138 205
- 8804250088 Responds to FOIA request for info re-scores of reactor operators & senior reactor operators. Forwards requestication exam summary source shedts I sted in oncluapp w/personal privacy into defeted.
 GRIMSEEV.D.H. Division of Rules & Records (Post 870413), 88/04/19 BOLEY.K. Public Ciczen's Chical Mass Energy Project. 2pp. 45213 003-45213 095
- --8804250167 Package of NRC administered requalification examinesults summary.
 NRC No Detailed Affiliation Given 87/07/20, 88pp. 45213 007-45213.095.

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

F. Security, medical, emergency & fire protection plans

- 8804010118 Rev 3 to Emergency Plan Implementing Procedure 2 50 23, "Emergency Proparedness Exercises 8 Drils."

 BOULETTE E.T. Maine Yankee Alomic Power Co. 88/03/25, 16pp. 44999.028-
- 8804130150 Forwards Insp Rept 50:309/85-03 on 880204-0316 No violations noted WIGGINS,J.T. Region 1, Old of the Director, 88/04/06 RANDAZZA,J.B. Maine Yankee Atomic Power Co. 3pp. 45151.035-45151.046
- --8804130153 Insp Rept 50-309/88-03 on 880204-0316 No violations noted Major areas inspected followup on previous Insp findings, licenses event followup.cperational safety verification, maint, survoillance, physical security & radiation protection. TRIPP,LE Regian 1, Old of the Director. 88/04/05. 8pp. 45151.039-45151:048
- 8804210232 Forwards changes to emergency plan as a result of State of MN enacted log station which changed boundary of EPZ to co.nc.de w/pot.cal boundaries WHITTIER.G.D. Maine Yankee Atomic Power Co. 88/04/11. RUSSELL,W.T. Region 1, Oto of the Director. 48pp. 45193.031-45193.079.
- 8804250320 Forwards Physical Security Insp Rept 50-309/88-05 on 880314-18.No vio-
- lations noted BELLAMY, R.R., Rogion, 1, Ofc. of the Director, 88/04/13, RANDAZZA, J.B., Maine Yankee Atomic Power Co. 2pp. 45248.033-45248.038
- --8804250329 Partially withheld Physical Security Insp. Rept 50:309/68:05 on 880314-18 (ref. 10CFR?3.2.1) No violations noted Major areas Inspected followup on findings of regulatory effectiveness review conducted on 870508-12 BAILEY, BJ, LANCASTER, W.K., KEIMIG, R.R., Region 1, Ofc of the Oirector, 88/04/11, 4pp. 45248-035-45248-038.

1. Financial information

8804150274 Forwards 1967 annual financial rept for Main Yankee Atomic Power Copper 10CFR50 7 (b) Original rept on 1th w/ Securities 8 Exchange Commission.
WHITTIER,G.D. Maine Yankee Atomic Power Co. 88/04/07. Document Control Branch (Document Control Desk). 62pp. 45138 220-45138-282.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88 06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MiRAGLIA, F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972
- 8803310253 Application for amend to License DPR-36,increasing max nominal fuel en-richment from 3.5% to 3.7% U-235 Fee paid RANDAZA, J.B. Malne Yankee Atomic Power Co. 88/03/24. Office of Nuclear Reac-tor Regulation, Oirector (Post 870411), 7pp. 44998.006-44998.077.
- -8804060176 Proposed Tech Specs,increasing max nominal fuel enrichment from 3.5% to 3.7% U-235 * Maine Yankee Atomic Power Co. 88/03/28, 2pp. 44996.013-44996.014
- --8803310264 "Criticality Analysis of Maine Yankee Sport Fuel Pool & New Fuel Vault." NAPOLITANO.D.G., ADLI.D.G., CACCIAPOUTI,R. Yankee Atomic Efectic Co. 88/02/29. 61pp. 44996.015-44986.072.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety to Nuclear Power Plants." Svc list enct. MIRAGLIA.F. J. Associate Direction for Projects (Post 870411), 88/04/07. Consol dated Edison Co. of New York, Inc. 49pp. 45184:207-45184:285.
- 8804130303 Advises that State of ME has no objection to Proposed Change 137 to
- Tech Spoc 5.2. SCHELL.R.J. Mains, State of. 88/04/07. Document Control Branch (Document Control Desk). Ip. 45154.071.45154:071.
- 8804200192 Informs that State of ME has no objections to util Proposed Change 138 to Tech Spec 1.3 to Increase max nominal fuel enrichment to 3.7% U-235.por 10CFR50.91(b).
 SCHELL,R.J., Maine, State of. 68/04/07. Document Control Desk) 1p. 45177:194-45177:194.
- 8804190336 Discusses Rev 3 to Reg Guide 1.97,which recommends that Category 2 instrumentation be installed Previous commitment amended to propose use of existing alternate instrumentation to provide Info on component cooling water flow. WHITTIER,G.D. Meine Yankoe Atomic Power Co. 88/04/08. WESSMAN,R.H. Project Directorate I-3, 4pp. 45216:342-45216:345.

- 8804210010 Forwards YAEC-1363, "CASMO-3G Validation." Rept entitled "Simulate-3 Validation & Ventication." Will be submitted by 880701 Schodute for submission of plant-specific repts of subjitedts stated Fee paid. PAPANIC, G. Yankee Atomic Electric Co. 88704/11. Document Confrol Branch (Document Confrol Branch (Document Confrol Branch)
- mont Control Desk) 2pp 45218 074 45218 174

Q. Inspection reports, IE Bulletins & correspondence

- 8804010270 Ack receipt of 880212 ltr informing NRC of steps taken to correct vicilations noted in Insp. Rept 50:309/87-12.

 DURR,J.P., Region 1, Otc. of the Director 88/03/24. RANDAZZA,J.B. Maine Yankee Atomic Power Co., 1p. 45058-104-45058:105.
- 8803210090 Suppt 1 to NRC Into Notice 87-044, "Thimble Tubo Thinning in Westing-house Reactors." Svc list encl. ROSSI.C E. Division of Operational Events Assessment (Post 870411) 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995 246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees Lack of Mgt Controls Over Licensed Programs." Svc list enct. CUNNINGHAM R E Division of Industrial & Medical Nuclear Safety (Post 870729), 88/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804060109 Forwards Exam Rept 50-309/68-02(OL) to exam administered on 880211. GALLO,R.M. Region 1, Otc of the Director, 88/03/28, RANDAZZA,J.B. Maine Yankee Atomic Power Co. 2pp. 45045:245-45045:324
- -8804060116 Exam Rept 50:309/88:02(OL) administred on 880211.Exam result one senior reactor oporator passed NORHIS,B.S., ESELGROTH,P.W. Region 1, Ofc of the Director. 88/03/23. 78pp 45/045/24-45/045/24.
- 8804110278 Forwards "Thormal Shield Status Rept " Rept concludes that positioning of thermal shield has not changed signif cently from reppir work performed in 1984 Next reactor vessel inservice hap will be scheduled for 1990 insilead of 1992 WHITTIER,G.D. Maine Yankee Atomic Power Co. 88/04/05 WESSMAN.R.H. Project Directorate 1-3, 2pp. 45128 194-45128 229.
- --8804110280 "Thermal Shield Status Rept."

 ' Maine Yankee Atomic Power Co. 88/03/31, 34pp. 45128:196-45128:229.
- 8804130150 Forwards Insp Rept 50-309/68-03 on 880204-0316 No violations noted. WIGGINS, J.T. Region 1, Otc of the Director. 88/04/06. RANDAZZA, J.B. Maine Yankee Atomic Power Co. 3pp. 45151.035-45151.046.
- --8804130163 Insp. Repl. 50-309/88-03 on 880204-0316 No violations noted Major areas inspected followup on previous insp. findings, licensee event followup, operational satory ventication, maint, surveillance, physical security & radiation protection. TRIPP, L.E., Region 1, Ofc of the Director. 88/04/05 8pp. 45151:038-45151.046
- 8804010256 NRC Info Natice 88:011, "Potential Loss of Motor Control Ctr. &/or Switch-baard Function Due to Faulty Tie Bolts." Svc list enct. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc., 124pp. 45406.292-45407:051.
- 8804060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc ROSSI,C.E. Division of Operational Events Assessment (Post 670411). 68/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150
- 8804250320 Forwards Physical Security Insp Rept 60-309/88-05 on 680314-18.No vio-
- lations noted.
 BELLAMY,R.R. Region 1, Ofc. of the Director, 88/04/13, RANDAZZA,J.B. Maine Yankee Atomic Power Co. 2pp. 45248.033-45248.038.
- --8804260328 Partially withheld Physical Security Insp Ropt 60-309/88-05 on 880314-18 (ref. 10CFR73.21). No violations noted Major areas inspected followup on findings of regulatory effectiveness review conducted on 870608-12.

 BAILEY, B.J., LANCASTER, W.K., KEIMIG, R.R. Region 1, Old of the Director. 88/04/11. 4pp. 45248.035-45248.038.

R. Periodic operating reports & related correspondence

- 8804150111 Monthly operating rept for Mer 1988.W/880408 ltr. RIVARD,D.A., WHITTIER,G.D. Maine Yankeo Atomic Power Co. 88/03/31. 6pp. 45153.243.45153:245
- S. Reportable occurrences, LERs & related correspondence
- 8804270250 LER 88:003:00 on 880321,d.scovered that vol control tank outot isolation motor-operated valve CH-M-87 may not have closed fully during design bases accident Caused by less conservative switch settings Sottings reset.W/880421 it. MCALLISTER,S.A., WHITTIER,G.D. Meine Yankee Atomic Power Co. 88/04/20. 3pp. 45261:065-45261:067.

V. Operator Examinations

- 8804060109 Forwards Exam Rept 50-309/88-02(OL) re exam administered on 880211. GALLO,R.M. Region 1, Ofc of the Director, 88/03/28. RANDAZZA,J.B. Maino Yankea Atamia Power Co. 2pp. 45045:245-45045:324.
- --8804080116 Exam Rept 50-309/88-02(QL) administred on 880211.Exam resultione senior reactor operator passed. NORRIS,B.S., ESELGROTH.P.W. Region 1, Ofc of the Director, 88/03/23, 78pp. 45045:247-45045:324

F. Security, medical, emergency & fire protection plans

- 8803300210 Forwards Design Memo S-C-M200-NDM-0610-0 & results of review by fire area & include affected cables & shutdown equipment as well as alternate shutdown options, in response to Unresolved Item 50-311/07-29 08 re App R compliance. MILTENBERGER, Public Service Electric & Gas Co. of New Jersey 88/03/18 Document Control Branch (Document Control Desk). 3pp. 44945:115-44945.196.
- -8803300215 "Appendix R/Breaker Coordination as-Found Review (Pre-Audil 1987)," ADAMS,M. Public Service Electric & Gas Co. of New Jersey, S-C-M200-NDM-0610-0 88/02/18, 79pp. 44945.118-44945:196.
- 8903310033 EN-85-025 on 880329,notice of violation & proposed imposition of civil penalty in amount of \$50,000 will be issued Action based on several examples of failure to satisfy fire protection requirements.

 WONG,I., LIEBERMAN,J. Ofc of Enforcement (Post 870413). 88/03/24. 1p. 44953-242-44953-243.
- 8804040036 Forwards Safety Insp Ropts 50:272/88-05.50-311/88-05 50:354/88-02 on 880125-29 No violations or deviations noted.
 BELLAMY,R.R. Region 1, Ofc of the Director 88/03/24 MCNEILL,C.A Public Service Electric & Gas Co. of New Jersey 2pp. 45031:305-45031.313.
- -8804040042 Insp Repts 50-272/88-05,50-311/88-05 & 50-354/08-02 on 880125-29 No violations, deviations or unresolved litems noted Mejor areas inspected emergency preparedness program conducted on 880125-29.

 AMATO,C.G. Region 1, Oto of the Director. 88/03/11. 7pp. 45031:307-45031:313.
- 8804050326 Forwards SALP Board Repts 50:272/88-99 & 50:311/86-99 during Oct 1986 Dec 1987 & Rept 50:354/86-99 on 861201-880116.
 RUSSELL,W.T. Region 1, Olo of the Director. 88/03/29. MILTENBERGER,S. Public Service Electric & Gas Co. of New Jorsey. 2pp. 45033:262-45034:034.
- -8604080022 SALP Repts 50-272/86-99 & 50-311/86-99 for Oct 1986 Dec 1987. Region 1, Olc of the Director 88/02/05, 69pp. 45033:327-45034.034.
- 8804120432 Discusses Insp. Rept. 50:311/87-29 on 870914-18 & 1215-18 & forwards notice of violation & proposed imposition of civil penalty in amount of \$50,000.insp included roview of compliance w/fire protection requirements. RUSSELL,W.T. Region 1, Ofc of the Director. 88703/29. MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey, 4pp. 45101:077-45101:084.
- -8804120438 Notice of violation & proposed Imposition of civil penalty in amount of \$50,000 Violations noted unstances existed at unit where cables & equipment located within same fire area outside of primary containment not provided.

 RUSSELL,W.T. Region 1, Ofc of the Director. 88/03/29. 4pp. 45101.081-45101.084.
- 8804080111 Forwards Enforcement Conference Rept 50-311/87-29 on 880212 re findings in Insp Rept 50-311/87-29. JÖHNSTON,W.V. Region 1, Olo of the Director. 88/03/31, MCNEILL,C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 45100:112-45100:162.
- -8804080113 Enforcement Conference Rept 50-311/87-29 on 880212 Violations noted Major areas discussed insp Rept 50-311/87-29 re-safe shutdown in event of KRASOPOULOS,A. Region 1, Ofc of the Director, 88/03/23, 22pp. 45100:114-

P. Operating Ilcense stage documents & correspondence

- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements. Svc list encl. MIRAGLIA, F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153
- 8804040100 Requests safety Issues mgt sys printout to assist in maintaining current data base of outstanding safety issues in agreement w/NRC.info will assist in identifying open issues & will facilitate rapid responses to inquiries.

 MILTENBERGER,S. Public Service Electric & Gas Co. of New Jorsey. 88/03/25, Document Control Branch (Document Control Desk). 2pp. 44971:291-44971:292.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR\$0.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.

Q. Inspection reports, IE Bulletins & correspondence

- 8802250380 Forwards Safety Insp Hepts 50-272/88 04 & 50-311/88-04 on 871221 & MARTIN,T.T. Region 1, Olo of the Director. 88/02/22. MCNEILL,C.A. Public Service Electric & Gas Co. of New Jorsey. 3pp. 44482:354-44482:359.
- 8803300210 Forwards Design Memo S-C-M200-NDM-0610-0 & results of review by fire area & include allected cables & shutdown equipment as well as alternate shutdown options, in response to Unresolved Item 50-311/87-29-08 re App R compliance.

 MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 88/03/18, Document Control Branch (Document Control Desk). 3pp. 44946;115-44945;196.
- --6603300215 "Appendix R/Breaker Coordination as-Found Review (Pre-Audit 1987)," ADAMS,M. Public Service Electric & Gas Co. of New Jersey, S-C-M200-NDM-0810-0, 88/02/18, 79pp, 44945;118-44945;196.
- 8803300046 Responds to NRC 880222 ltr re violations noted in Insp Repts 50-272/88-04 & 50-311/88-04 Corrective actions radwaste shipment procedure revised to more clearly define specific survey locations to be used when surveying truck cab. MILTÉNBERGÉR,S. Publio Service Electric & Gas Co. of New Jersey, 88/03/22. Document Control Branch (Document Control Desk). 3pp. 44945-288-44945-288.

- 8603310033 EN-85-025 on 860329 notice of violation & proposed imposition of civil penalty in amount of \$50,000 will be issued Action based on several examples of failure to satisfy hire protection requirements.

 WONG,H., LIFBERMAN,J. Ofc. of Enforcement (Post 870413): 88/03/24. 1p 44953 242-44953 243.
- 8804040007 Ack receipt of 880226 ftr informing NRC of steps taken to correct violations noted in Insp Rept 50-311/87-29 Actions will be exemined during future insp DURR_JP. Region 1, Okt of the Director 88/03/24 MCNEILL.C.A. Public Service Electric & Gas Co. of New Jersey. 1p. 45010.196-45010.200.
- 8804040036 Forwards Safety Insp Repts 50-272/88-05.50-311/88-05 50-354/88-02 on BB0125-29 No violations or deviations noted:
 BELLAMY,R R Region 1, Ofc of the Director 88/03/24. MCNEILL,C A. Public Service Electric & Gas Co. of New Jersey. 2pp. 45031:305-45031:313.
- --8804040042 Insp. Repts 50-272/88-05,50-311/88-05 & 50-354/88-02 on 880125-29.No violations, deviations or unresolved items noted Mejor areas inspected emergency preparedness program conducted on 880125-29
 AMATO.C.G. LAZARUS.W.J. Region 1, Ofc of the Director. 88/03/11. 7pp. 45031:307-45031:313
- 8804010180 Provides response to concerns raised in Insp Repts 50-272/87-37 & 50-311/87-37.per 880125 request Corrective action data collection of in-Ind monitor vs. lab results was implemented 880115. MILTENBERGER.S. Public Servico Electric & Gas Co. of New Jersey. 88/03/25. Document Control Branch (Document Control Desk). 4pp. 45020:005-45020.008.
- 8804010184 Requests extension of submittel date until 880429 for supplemental re-sponse to NRC Compliance Burletin 87-002 due to delay in receipt of test results. MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 88/03/25. RUSSELL,W.T. Region 1, Otc of the Director. 2pp. 45020 009-45020.010.
- 880321009D Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list encl. ROSSI,C.E. Division of Operational Events Assessment (Past 870411) 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995.126-44995:246
- 8803220296 NRC Inio Notice 88:010, "Matts Licensees:Lack of Mgt Controls Over Li-censed Programs." Svc 1st enct. CUNNINGHAM.R E Division of Industrial & Medical Nuclear Safety (Post 870729). 88/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8604050326 Forwards SALP Board Repts 50-272/86-99 & 50-311/86-99 during Oct 1986 Dec 1987 & Ropt 50-354/86-99 on 861201-880115 RUSSELL,W.T. Region 1, Otc of the Director. 88/03/29 MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey, 2pp. 450332-62-45034-034.
- --8804080022 SALP Repts 50-272/86-99 & 50-311/86-99 for Oct 1986 Dec 1987.
 * Region 1, Old of the Director, 88/02/05, 69pp. 45033-327-45034-034.
- 8804120432 Discussos Insp Rept 50-311/87-29 on 870914-18 & 1215-18 & forwards notice of violation & proposed imposition of civil ponalty in amount of \$50,000 lnsp included review of compliance w/hra protection requirements.

 RUSSELL.W.T. Region 1, Oic of the Director. 89/03/29 MILTENBERGER,S. Public Service Electric & Gas Co. of Now Jersey. 49p. 45101:077-45101:084.
- --8804120438 Notice of violation & proposed imposition of civil panalty in amount of \$50,000 Violations noted firstances existed at unit where cables & equipment located within same fire area outside of primary contentment not provided RUSSELL,W.T. Region 1, Oic of the Director. 88/03/29. 4pp. 45101:081-45101.084.
- 8804070315 Responds to NRC Bulletin 88-001 re detects in Westinghouse DS/DSL circuit breakers Plants do not utilize subj. circuit breakers.
 MILTENBERGER,S. Pub'lo Service Electric & Gas Co. of New Jersey, 88/03/31. Document Control Branch (Document Control Dask), 3pp. 45075;214-45075;218.
- 8804080111 Forwards Enforcement Conference Rept 50-311/87-29 on 880212 re lind-904061111 Forwards Embergham Commence 1001 35-5111 Commence 1001 35-5111 Commence 1001 35-511 Commence 1001 35-51
- --8804080113 Enforcement Conference Rept 50-311/87-29 on 880212, Violations noted Major areas discussed insp Rept 50-311/87-29 re-sale shuldown in event of KRASOPOULOS,A. Region 1, Ofc of the Director, 88/03/23, 22pp. 45100:114-46100:162.
- 8804130007 Notification of Licensee Meeting 88-051 on 880414 w/util in Hancocks Bridge,NJ to discuss SALP.
 SWETLAND,P. Region 1, Otc of the Director, 88/03/31, Region 1, Ofc of the Director, 2pp. 45099:312-45099:313.
- 8804010255 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svc list enct. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804130040 Forwards request for addl Info re util 860527 response to IE. Bulletin 85-003, "Motor-Operated Valve Switch Settings." Response requested within 30 days. WENZINGER.E.C. Region 1, Ofc of the Director. 88/04/07. MILTENRERGER,S. Public Service Electric & Gas Co. of New Jersey. 7pp. 46135:350-45135:358
- 8804060370 NRC Info Notice 88-012, "Overgressing of Electric Motor Bearings," Svc ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45166.028-45165:150.

R. Periodic operating reports & related correspondence

8804110008 "NPDES Discharge Monitoring Rept for Feb 1988."
TREJOJ, Public Service Electric & Gas Co. of New Jersey. 88/02/29. CAPORALE,G. New Jersey, State of. 26pp. 45072:284-45072:319.

8804190844 Month's operating rept for Mar 1988 W/880411 lir.
WHITE.P., RONAFALVY.J., ZUPKO.J.M. Public Service Electric & Gas Co. of New Jersey. 88/03/31, 10pp. 4\$208.247-45206 256.

S. Reportable occurrences, LERs & related correspondence

8804060053 Special Rept 89.3:on 880308, hourly roving lire watch not completed for elevation switchgear room. Caused by personnel error individual involved removed from site & employment terminated by contractor firm ZUPKO, J.M., Public Serv.co Electric & Gas Co. of New Jersey 88/03/29. Document Control Branch (Document Control Dask). 3pp. 45034:185.45034:187

V. Operator Examinations

8804050326 Forwards SALP Board Repts 50:272/86-99 & 50:311/86-99 during Oct 1986 - Doc 1987 & Rept 50:354/86-99 on 861201-880115 RUSSELL WT, Region 1, Oic of the Director, 88/03/29 MILTENBERGER,S Public Service Electric & Gas Co. of New Jersey. 2pp. 45033.262-45034.034

--8804080022 SALP Ropts 50:272/86-99 & 50:311/86-99 for Oct 1986 - Dec 1987. * Region 1, Ofc of the Director. 88/02/05. 69pp. 45033 327-45034:034.

DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

F. Security, medical, emergency & fire protection plans

8804040123 Forwards Insp Rept 50.312/88-09 on 880307-08 No violations noted. WENSLAWSKI,F. Region 5, Oic of the Director. 88/03/17. ANDOGNINI,C. Sacramento Municipal Utility District. 2pp. 44870.239-44970.243

-8804040125 Insp Rept 50:312788:09 on 880307:08 No violations noted. Major areas Inspected emergency preparedness program & followup on open items Insp Procedure 92701 covered PREMDERGAST.K Region 5, Ofc of the Director. 88/03/15. 3pp. 44970.241-

G. Adjudicatory correspondence

8804280044 Informs that time gravided within which Commission may act to review Director's Decision UD-88-05 expired Commission declined review Decision became linal agency action on 880418 Served on 880420.
CHILK, S.J. Office of the Secretary of the Commission, #288 6108 88/04/20.
BRADLEY, T. Louisiana, State of: 1p. 45211.030-45211.030.

8804250066 Advises that time for Commission to review Director's Decision DD-88-04 expired Commission declined review. Decision became lines agency action on 880412. Served on 860420

BBU412. Served on Bbu421 CHILK, 51. Office of the Secretary of the Commission #288 6107. 88/04/20. MOLLER, B. Alfi'lation Not Assigned. 1p. 45211:025-45211:025.

H. General correspondence

8804040073 Requests svc list be updated as stated to reflect appointment of SL Crunk as nuclear licensing dept manager, effective on 880123. CRUNK,SL. Sacramento Municipal Utility District. 88/03/19 MARTIN.J.B. Region 5, Orc. of the Director, MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 1p. 45031.03 (46031005). 45031:295 45031:295

P. Operating license stage documents & correspondence

8803080464 Notification of 880311 meeting w/util in Rockvilla,MD to discuss plant restart status. KALMAN,G. Project Directorate V. 88/03/03 KNIGHTON,G.W. Project Directorate V. 3pp. 44638 218-44638 220

8903100157 Informs of AEOD monitor of select power plants performance as part of expanded performance indicator program J Crews of Region 5,S Stern of AEOD & J Firlit of SMUD mel to imbate program to Rancho Seco.

JORIOAN,E.L. Office for Analys s & Evaluation of Operational Data, Director. 88/03/08. MARTIN,J.B. Ragion 5, Ofc of the Director. 89p. 69241:098-69241:106.

8803180091 Expresses concern that operations factors of utilization ordinance may not be consistent w/reactor safety. Plans to assure that operations staff does not cut corners & that implementation will not adversely impact safety requested MURILEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 98/03/11. ANDOGNINI,G.C. Sacramento Municipal Utility District. 2pp. 44996-342-44996-343.

880-4050205 Forwards updated schedule & summary status for NRC open item closure. Weekly updates wit be provided until restart.

CRUNK, St. Sectemento Municipal Unity District. 88/03/17. MARTIN, J.B. Region 5, Otc of the Director, 10pp. 44996.332-44996.341.

8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list and MERIGLEAF, J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153

8804010234 Forwards list of all util engineering ca'culations associated w/TDI diesel generators developed after 880222. CROLEY,B.G. Sacramento Municipal Utility District. 88/03/24. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 2pp. 45031;150-45031;151.

8804050123 Forwards safety evaluation addressing mods made to TOI diesel engines to reduce vibrations & acceptability of resultant vibration level Considers diesel vibration

Issues resolved.

HOLAHAN,G.M. Division of Reactor Projects III,IV,V & Special Projects (Post 87041), 88/03/28. ANDOGNINI,G.C. Sacramento Municipal Utility District. 3pp. 44997-017.

-8804050128 Safety evaluation supporting resolution of TOI diesel engine vibration

problems at facility. **Drice of Nuclear Reactor Regulation, Director (Post 870411), 68/03/26 6pp. 4497 012-44997 017

8804050318 Forwards biweekly notice of application & amends to keense involving NSHC did 880309 re review of plant for info W/o oncl.

Office of Nuclear Reactor Regulation, Director (Post 870411) 88/03/28 ANDOGNINI,G.C. Secremento Municipal Ullinty District 2pp 45029 124-45029 125

8804080464 Forwards Gale vs Lebog code comparison study. Study represents supplemental radioactive liquid effluent sys evaluation Lebog code used to outrine conditions under which plant can operate within 10CFR50,App (guidelines. ANDOGNINI) G.C. Sacremento Munc pal Ullility District. 88/03/28 MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 13pp. 45010:201-45010:213

8804070053 Discusses util completion of work required for TDI diesel generators in proparation for restart,per restart conditions sel forth at Commissioners 880322 meeting.TDI diesel generators declared operable per Tech Spec 3 7.1. ANDOGNINI,G C. Sacramento Municipal Utility District. 88/03/28. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 3pp. 45022:142-45022:144.

8804050083 Responds to recipient 880317 (fir expressing concerns re implementation of B&W Owners Group recommendations at plant. NRC has not found any new into in lit which could atter NRR recommendation to Commission that plant ready for operation. MURIEY-T.E. Office of Nuctear Reactor Regulation, Director (Post 870411), 88/03/29. POLLARD,R.D. Union of Concerned Scientists. 8pp. 45009 336-45009.347.

--8804050094 Discusses facility restart Plant cannot be permitted to resume operation w/o demonstrable basis for finding that plant can & will be safely operated. POLLARDR D. Union of Concerned Scientists. 88/03/17. ZECH

8804200125 Notifies of completion of prerequisites for reactor criticality & readiness for restert. Util intends to bring reactor critical & commence increase to approx 25% of rated power. Prerequisite libras vorified listed.

ANDGONINI, G.C. Sacramento Municipal Utifity District. 88/03/29. MARTIN, J.B. Region 5, Otc of the Director. 3pp. 45177:159-45177:161.

8804050206 Authorizes facility restart & conduct of power ascension test program Conditions of 851226 confirmatory action litrs mot based on submittals documenting resolution of emergency dieset generator vibration problems & 24 h surveil-

lance run.
MURLEY,T.E. Olfice of Nuclear Reactor Regulation, Director (Post 870411), 88/03/30. ANDOGNINI,G.C. Secramento Municipal Utility District. 3pp. 45029-085-45029-087.

8804080164 Forwards errata to Amends 97 & 98 to Licensu DPR-54, correcting inadvertent errors in Tech Specs.
KALMAN,G. Project Orisectorate V. 88/03/30. ANDOGNINI,G C. Sacramento Municipal Utility District. 3pp. 45084:299-45084:310.

--8804080167 Errata to Amends 97 & 98 to License DPR-54, correcting inadvertent

Project Directorate V. 88/03/30, 9pp. 45064:302-45064:310.

8804080045 Forwards Rev 6 to util position on Reg Guide 1 97 re display of Category i valiables on SPDS in response to Generic Lit 82:33 Changes incorporated in position rev based on NUREG-0737 & NUREG-1286 documentation. ANDOSNINI,G.C. Sacramento Municipal Utility District. 88/03/31. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 22pp. 45099-091-45099-112

8804080172 Forwards SSER NUREG-1231 re B&W Owners Group plant reassessment program Overall evaluation remains fevorable. Add improvement in area of integrated control sys/ non-nuclear instrumentation sys review possible W/o encl. CRUTCHFIELD,D. Division of Reactor Projects «III,IV). 8 Special Projects (Rost 870411), 88/03/31, WILGUS,W.S. Babcock & W/cox Operating Plants Owners Group. 7pp. 45076:181-45076-187.

8804080230 SAFETY EVALUATION REPORT RELATED TO THE RESTART OF RANCHO SECO NUCLEAR GENERATING STATION, UNIT 1, FOLLOWING THE EVENT OF DECEMBER 26,1985 Docket No. 50-312 (Sacramento Municipal Utility

District)

* Distr

8804120044 Notification of 880412 meeting w/util at site to discuss geological conditions in plant vicinity.

KALMAN, G. Project Directorate V. 88/03/31. KNIGHTON, G.W. Project Directorate V. 4pp. 45089:224-45089:227.

8804120149 Notification of canceled 880412 meeting w/util,USGS & California div of

mines & geology to discuss geotogical conditions in vicinity.

KALMAN,G. Project Directorate V. 88/03/31. KNIGHTON,G.W. Project Directorate V. 3pp. 4510].001-48101:003

8804080195 Forwards into re OSR-48 crankshafts,including Johnston 880328 fit to Khan & related mails ref in lit.per tolcon. CHOLEY,8.G Sacramento Municipal Utility District. 88/04/04. MIRAGLIA,F J. Associate Director for Projects (Post 870411). 10pp. 45115-050-45116.101.

8804130288 Discusses long-term corrective action re upgrade of cathodic protection sys Cathodic protection sys upgrado will be prioritized by long range schedule review group & scheduled, per facility administrative procedures.

ANOCGNIN,G.C. Sacramento Municipal Utility O.strict. 88/04/05. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 1p. 45137:017-45137:017.

8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-lorcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Salety for Nuclear Power Plants." Syc list enc! MIHAGLIA,F. J. Associate Director for Projects (Post 870411) 88/04/07 Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.

- 8804270136 Forwards STP.1154, "Remote Shutdown Panel Test," Casually Procedure OP-C 13A, "Remote Shutdown," comparison of subt procedures & evaluation of appropriateness of Casually Procedure OP-C 13A steps to secure reactor coolant
 - pumps
 ANDOGNINI,G C Sacramento Municipal Utility District 88/04/15 MIRAGLIA,F.J. Associate Director for Projects (Post 870411) 1p. 45248 136-45246 252.
- -8804270230 Rev 0 to STP 1154, "Remote Shutdown Panel Tost" 'Sacramente Municipal Utility District 88/04/15 71pp. 45248:137-45246:207.
- --8804270238 Rev 8 to OP-C 13A, "Remote Shutdown." * Sacramento Municipal Utility District. 88/04/15. 45pp. 45246 208-45246 252.
- 8804270303 Responds to 880321 ftr to Zech expressing concerns re SMUD ability to operate facility w/o adversely affecting hoalth & safety of general public in view of referendums scheduled to appoor on 880607 ballot for SMUD ratepayers MUPILEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/18 CONNELLY,L.G. California, State of .8pp. 45266.161-45266:170.
- --8804270308 Request that rostart of facility before 880607 be evaluated solely on public safety considerations by NRC. CONNELLY_LG California, State of 88703721. ZECH,LW. NRC No Detailed Affiliation Given. 2pp 45266 169-45266 170.
- 8804280442 Forwards SER & SSER 1 (NUREG-1231) on B&W Owners Group plant re-assessment program contained in BAW-1919.Rov 5, "B&W Owners Group Safety & Performance Improvement Program (SPIP)" Overall evaluation tavorable W/o enct. KNIGHTON,G W. Project Directorate V. 88/04/19. ANDOGNINI,G.C. Sacramento Mu-nicipal Utility District. 3pp. 45264 081-45264.083.
- 8804280573 Requests SER which summarizes vorbal agreements as outlined in 880125 & 0222 Itrs & ovaluates technical adequacy of GC Andognini 880415 Itr to FJ M regila. KNIGHTON,G.W. Project Directorato V. 88/04/20. WEISS,S.H. Quality Assurance Branch. 2pp. 45271 065-45271:066.
- 8804280369 Discusses NRC briefing by licensee re readiness for restart. Licensee committed to listed action per Commission request CHILK, S.J. Otfice of the Secretary of the Commission, 88/04/22. Office of the Secretary of the Commission, 2pp. 45263,360-45263,361.
- 8804280374 Advises that proposed scope of remote shutdown test appropriate to test auvaeus re Auvises and proposed scope of remote shutdown tiest appropriate to test recent plant mods which may impact capability to control plant shutdown & cooldown from outside control room Remote shutdown test procedure under review. KNIGHTON, G.W. Project Directorate V. 88/04/22. ANDOGNINI,G.C. Sacramento Mu-nicipal Utility District 3pp. 45269 340-45269.342.

Q. Inspection reports, IE Bulletins & correspondence

- 8804040123 Forwards Insp Rept 50-312/88-09 on 880307-08.No violations noted WENSLAWSKI,F. Region 5, Ofc of the Director. 88/03/17. ANDOGNINI,C. Sacramento Municipal Utility District. 2pp. 44970-239-44970 243.
- -8804040125 Insp Ropt 50-312/88-09 on 880307-08.No violations noted. Major areas inspected emergency preparedness program & followup on open items insp Procedure 92701 covered. PRENDERGAST,K. Region 5, Ofc of the Director, 88/03/15. 3pp. 44970:241-44970:243.
- 8804040148 Responds to IE Bulletin 85-003, "Motor-Operated Valve Common Mode Fairures During Plant Translents Due to Improper Switch Settlings." Util expanded refurbishment & test program to Include all Limitorque motor-operated valves on site. ANDOGNINI, G.C. Sacramento Municipal Utility District. 88/03/19. MARTIN, J.B., Reg on 5, Ofc of the Director. 3pp. 45031:296-45031:298.
- 8804120368 Forwards Insp Rept 50:312/87-44 on 871205-880203 & notice of violation, ZIMMERMAN,R. Region 5, Otc of the Director, 88/03/25, ANDOGNINI,G.C. Sacramento Municipal Utility District, 2pp. 45132:176-45132:212.
- --8804120372 Notice of violation from insp on 871205-880203.Violation noted on 870702,NCR \$6053 signed & closed by quality engineer w/o corrective actions in Block II of NCR for Wire 1M1B180B being performed.

 * Region 5, Oto of the Director, 88/03/25, 2pp. 45132:178-45132:179.
- --8804120375 Insp Rept 50-312/87-44 on 871205-880203. Violation noted. Major areas Inspected operational safety verification,maint, surveillance & followup Items. D'ANGELO,A J., MYERS,C.J., QUALLS,P.M. Region 5, Ofc of the Director. 88/03/24. 33pp. 45132-180-45132-212.
- 8803210090 Suppl 1 to NRC into Notice 87-044, "Thimble Tube Thinning In Westinghouse Reactors." Svc list encl. ROSSLCE. Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220298 NRC Into Notice 88-010, "Malls Licensees Lack of Mgt Controls Over Li-censed Programs," Svc list encl. CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.
- 8904200141 Confirms that Westinghouse DS breakers not used at facility, per IE Bulletin 88-001, "Defects in Westinghouse Circuit Breakers." ANDOGNINI,G.C. Sacramento Municipal Utility District. 88/03/28. MARTIN,J.B. Region 5, Oto of the Director. 2pp. 45177:167-45177:188.
- 8804190380 Discusses analysis, refurbishment & test program dealgned to ensure Improvement of IE Bulletin 85-003, "Motor-Operated Valve Common Mode Failures During Plant Translents Due to Improper Switch Seltings." ANDOGNINI,G.C. Sacramento Municipal Utility District. 88/04/01. MARTIN,J.B. Region 5, Ofc of the Director. 2pp. 46164;161-45184;162.
- 8804010256 NRC Into Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svc list encl. ROSSI.CE. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407:051.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150.

- 8804200281 Ack receipt of 880323 itr informing NRC of steps taken to correct violations noted in Insp Rept 50.312788 08. ZIMMERMAN, R.P. Region 5, Ofc of the Director. 88/04/12, ANUOGNINI,G.C. Sacramento Municipal Utility District. 1p. 45225:354-45225-358.
- --8804200272 Responds to NRC 880302 fir re-violations noted in Insp Rept 50-312/88-06.Corrective actions Matts Mgt Desk Instruction MMDI-W036, "Shelf Life," issued to provide instructions on handling stock items w/shelf life.

 ANDOGNINI,G.C. Secremento Municipal Utility District 88/03/23. MARTIN,J.B. Region 5, Ofc of the Director. 2pp. 45225:355-45225:356.
- 8804270208 Ack receipt of 880307 ltr informing NRC of steps taken to correct violations noted in Insp Rept 50-312/87-37 NRC has concluded that notice of violation appopriate as written, per 880415 & 18 telcons. ZIMMERMAN,R.P. Reg on 5, 01c of the Director. 88/04/18. ANDOGNINI,G.C. Sacramento Municipal Utility District. 1p. 45244:266-45244:272.
- --8804270219 Responds to NRC 880216 llr re-violations noted in Insp. Rept 50-312/87-37 Corrective actions personnel involved reinstructed in requirements of Procedures RSAP-0803 & OAP-17. ANDOGNINI,G.C. Sacramento Municipal Utility District. 88/03/07. MARTIN,J B. Region 5, Ofc of the Director. 6pp. 45244-267-45244:272.

R. Periodic operating reports & related correspondence

- 8804060330 "Discharger Self Monitoring Rept for Fob 1986." W/880308 ftr. YOCHHEIM.E., FIRLIT.J.F. Secramento Municipal Utility District. BB/02/29. MURLEY.T. Office of Nuclear Reactor Regulation, Director (Post 870411). 7pp. 45047-100-45047-106.
- 8804200164 Submits monthly update of restart scope list & long-range scope list, including total statistics as of 880325 & restart items downgraded to long-range or voirded since 880222.

 CROLEY,B.G. Sacramento Municipal Utility 0:strict 88/03/25, MARTIN,J.B. Region 5, Otc of the Director. 23pp. 45174 090-45174:112.

S. Reportable occurrences, LERs & related correspondence

- 8803290382 Special Rept 88-06 provides updated list of the nonfunctional lire barriers which have not been restored to functional status within 7 days.per Tech Spec 3.14.6.2. FIRLIT.J.F. Sacramento Municipal Utility District, 88/03/15. MARTIN.J.B. Region 5, Ofc of the Director. 3pp. 44883.027-44983.029.
- 8803290389 Corrected Special Rept 88-05:on 880206 & 08.both electric & diesel driven lire pumps,P-440 & P-996 declared inoperable due to controller replacement Errata corrects date of rept inadvertantly omitted from original submittal. CRUNK,S. Sacramento Municipal Utility Ostrict. 88/03/15. MARTIN.J.B Region 5, Ofc of the Director. 3pp. 44913:001-44913:003.
- 8803290351 PNO-V-88-023.on 880323.undervoltage attachment of CRD breaker failed to operate.Interference of undervoltage attachment trip lever w/exterior label plate,noted. Investigation continuing.
 MILLER, I., D'ANGELO,T. Region 5, Ofc of the Director. 88/03/24. 1p. 44952 235-44952:235.
- 8804010234 Forwards fist of all util engineering calculations associated w/TDI diesel generators developed after 880222. CROLEY,B.G. Sacramento Municipal Utility District. 88/03/24. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 2pp. 45031:150-45031:151.
- 8804190068 Special Rept 88-03:on 880225,Tech Spec 3.14.4 violated. Caused by fire suppression CO2 sys not being restored to operable status within 14 days.Fire watch posted CO2 sys will remain inoperable until redesign of fire damper log. FIRLIT_J.F. Sacramento Municipal Utility District. 88/03/25 MARTIN.J.B. Region 5, Ofc of the Director. 3pp. 45208:197-45208:199.
- 8804050123 Forwards safety evaluation addressing mode made to TDI dissel engines to reduce vibrations & acceptability of resultant vibration level. Considers diesel vibration haylozas zaueel HOLAHAN,G.M. Division of Reactor Projects - III,IV,V & Special Projects (Post 870411), 88/03/28, ANDOGNINI,G.C. Sacramento Municipal Utility District. 3pp 44997:009-44997.017.
- --8604050128 Safety evaluation supporting resolution of TDI diesel engine vibration Problems at facility
 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/28, 6pp 44997:012-44997:017.
- 8804070063 Discusses util completion of work required for TOI diesel generators in preparation for restart,per restart conditions set forth at Commissioners 880322 meeting TOI diesel generators doctared operable per Tech Spec 3.7.1. ANDOGNINI,G.C. Sacramento Municipal Utility District. 89/03/28. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 3pp. 45022:142-45022:144
- nation of release pathway resulting in monitors being declared importable.Caused by inadequate surveillance procedures.Procedure revised.W/880329 Itr. RUTTER,S., ANDOGNINI,G.C. Sacramento Municipal Utility District. 88/03/29. 4pp. 45028:242-45028.245. 8804050023 LER 88 004-00:on 860302 surveillance test did not verify automatic termi-
- 8804050206 Authorizes (scility restart & conduct of power escansion test program.Conditions of 851226 confirmatory action lirs met based on submittals documenting resolution of emergency diesel generator vibration problems & 24 h surveil.
- lance run.
 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 88/03/30, ANDOGNINI,G.C. Sacramento Municipal Utility District. 3pp. 45029.085-45029.087.
- 8804070338 PNO-V-88-024:util received final authorization from NRR to restart facility on 880330.Enhanced operational readiness insp team & resident insp staff observing reactor startup which will require 6-10 h to complete.

 MILLER,L. Region 5, Otc of the Director, 88/03/30. 1p. 45021:254-45021:254.

- 8804180374 Summary of Operating Reactors Events Meeting 88-13 on 880329 List of attendees, discussion of events & summary of reactor scrams enct. LANNINGW. Events Assessment Branch. 88/03/31. ROSSIC. E. Division of Operational Events Assessment (Post 870411). 18pp. 45149 205. 45149 222.
- 8804210136 LER 68-002-00-on 880323,inp breaker failed to open when reactor protection sys Channel D tripped Caused by armature button improperly mounted due to mig defect supplied by GE Maint procedure for trip breaker revised W/880407 ltr.
 RUTTER, ANDGSNINI,G C. Sacramento Municipal Utifity District 88/04/07. 4pp. 45231:178-45231:181.
- 8804210342 Special Rept 88-07 on 880315, water defuge sys for Fire Zone 110 declared inoperable Actuation of defuge sys could adversely affect operability of both auxiliary leedwater pumps Compensatory measures taken & fire watch established FIRUIT_JF Sacramento Municipal Utility District. 88/04/11. MARTIN, J B. Region 5, Otc of the Director. 2pp. 45235 315-45235 316.

V. Operator Examinations

- 880425088 Responds to FOIA request for info re-scores of reactor operators & senior reactor operators Forwards requalification even summary source sheets listed in encl. app w/personal privacy into deteiled. GRIMSLEY.DH. Division of Fluto's & Records (Post 870413) 88/04/19. BOLEY.K. Public Citizen's Critical Mass Energy Project. 2pp. 45213 003-45213 095.
- --8804250167 Package of NRC administered regularication exam results summary.
 NRC No Detailed Affiliation Given 87/07/20 88pp. 45213 007 45213.095

DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8803290313 Rovised emergency plan Implementing procedures (EPiPs), Including Rev 4 to 1903.04, "Administration & Malint of EPiPs," Rev 15 to 1903.23, "Personnel Emergency" & Rev 14 to 1903.50, "Emergency Response Organization."

 Arkansas Power & Light Co. 88/01/12, 25pp. 44962:185-44962:209.
- 8904070151 Fley 6 to "Arkansas Nuclear One Emergency Plan." W/880330 ltr. HOWARD,D.R. Arkansas Power & Light Co. 88/03/01. 48pp. 45044.028-45044:075.
- 8803290318 Rev 4 to Emergency Plan Implementing Procedure 1903 54, "Requests for Addi Personnel " * Arkansas Power & Light Co. 88/03/17, 9pp. 44915 320 44915:328
- 8803290335 Rev 4 to Emergency Plan Implementing Procedure 1905 001, "Emergency Had of ogical Controls."

 * Arkanses Power 8 Light Co. 88/03/17, 3pp. 44978:239-44978:241.
- 8803300360 Rev 7 to Emergency Plan Implementing Procedure 1904.07, "Protective Action Recommendations."
 * Arkansas Power & Light Co. 88/03/23, 14pp. 44979:125-44979:138.
- 8803300352 Rov 3 to Emergency Plan Implementing Procedure 1903 40, "Duties of Dose Assassment Team."
 * Arkansas Power & Light Co. 88/03/24, 19pp. 44962.347-44963-005.
- 8803300353 "Arkansas Nuclear One Emergency Preparedness Exercise REX-88 Exer-
 - Cise Scenario."
 * Arkansas Power & Light Co. 88/03/24, 325pp. 44960.027-44961.029
- 8804210168 Responds to violation noted in Insp. Repts 60.313/88-01 & -60.368/88-01. Corrective action Colh regs removed from room, rubber hoses used for routine mint in room returned to motal storage container & fire watch posted. LEVINE_J.M. Arkansas Power & Light Co. 88/04/07. CALLAN, L.J. Region 4, Ofc of the Oirector. 3pp. 45219:169-45219:171.
- 8804210270 Forwards revised Figure 6.2-2.Sections 6.5.2.2 & 6.5.2.1 & description of amend request to suppl previous submittals, dtd 861212 & 871204.Changes are to note mgt responsibility for omergency preparedness & fire protection function CAMP8ELL,T.G. Arkansas Power & Light Co. 88/04/14. CALVO,J.A. Project Directorate IV. 5pp. 45235:260-45235:266.
- •6804210273 Revised proposed Tech Specs re mgt responsibility for emergency pre-paredness & fire protection function on plant organizational chart * Arkansas Power & Light Co. 88/04/14. 2pp. 45235:265-45235:266.

I. Financial information

8804200085 "Arkansas Power & Light Co 1997 Annual Rept." W/860412 ltr.
MAULDEN, J.L., HOWARD, D.R., Arkansas Power & Light Co. 87/12/31, 49pp
45226.094-45226.194.

J. Insurance & indemnity information

- 8804080372 Forwards ANI certificates of insurance for MAELU Policies 5253,TA6002,X87139 & XTA5246 as evidence of util primary & excess nuclear properly damage insurance coverage. HOWARD,D.R. Arkansas Power & Light Co. 88/03/31, WOOD,R. Document Control Branch (Document Control Desk), 5pp. 45008;323-45008;327.
- 8804190374 Forwards Endorsement 74 to NELIA Policy NF-210 & Endorsement 63 to
- MAELU Policy MF-74.

 SAMUELS,J.L. Marsh & McLennan, Inc. 68/04/08. DINITZ,I. Office of Nuclear Reactor Regulation, Director (Post 870411). 5pp. 45164:163-45164:167.
- 8804200420 Forwards Endorsements 1 & 2 to NELIA Policy NW-118 & MAELU Policy SAMUELS,J.L. Marsh & McLennan, Inc. 88/04/12. DINITZ,I. Office of Nuclear Reacfor Regulation, Director (Post 870411), 21pp. 46226:235-45226:255.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88-96 to all power reactor licensees & applicants re removal of organization charts from Toch Spec administrative control requirements. Svc list encl. MIRAGLIA, F. J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edson Co. of New York, Inc. 47pp. 44972-107-44972-153.
- 8803300117 Documents 880322 meeting w/util List of attendees encl. CALLAN.L J. Region 4, Old of the Director. 88/03/23. CAMPBELL,G. Arkansas Power & Light Co. 2pp. 44962.098-44962.099.
- 8803310114 Ack receipt of 880129 ftr re summary of progress made toward identifica-tion & correction of discrepancies Requests that NRC should be notified of any ex-tremity or skin exposures that exceed any 10CFH20 exposure limits. CALLAN,L J. Rogion 4, Otc of the Director. 88703/25. CAMPBELL,G. Arkansas Power & Light Co. 2pp. 44967.337-44967:338.
- 8804050160 PRA APPLICATIONS PROGRAM FOR INSPECTION AT ARKANSAS NU-CLEAR ONE UNIT 1 Docket No. 50-313.(Arkansas Power And Light Company) VO.T.V., HARRIS, M.S., GORE, B.F. Battello Memorial Institute, Pacific Northwest Lab-oratories, Fin. B-2802. NUREG/CR-5058. 88/03/31. Region 1, Oic of the Director. 74pp. 44972.032-44972:106
- 8804080172 Forwards SSER NUREG-1231 re B&W Owners Group plant reassessmont program Overall evaluation remains favorable. Addit improvement in area of intograted control sys7 non-nuclear instrumentation sys review possible W/o encl. CRUTCHFIELD,D. Division of Reactor Projects III,IV,V & Special Projects (Post 870411) 86/03/31. WILGUS,W S. Bebcock & Wilcox Operating Plants Owners Group. WILGUS,W.S. Florida Power Corp. (subs. of Florida Progress Corp.). 7pp. 45076:181-4578-197. 45076:197
- 8804080088 Generic Ltr 86:07 to power reactor licensees & applicants re-modified en-torcement policy concorning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804210270 Forwards rovised Figure 6.2-2. Sections 6.5.2.2 & 6.5.2.1 & description of amend request to suppl previous submittals, dtd 861212 & 871204. Changes are to note mgt responsibility for emergency preparedness & fire protection function. CAM/BELL, 1.G. Arkenses Power & Light Co. 88/04/14, CALVO, J.A. Project Directorate IV. 6pp. 45235:260-45235:266.
- --8804210273 Revised proposed Tech Spacs re mgt responsibility for emergency proparedness & fire protection function on plant organizational chart.
 ^ Arkansas Power & Light Co. 88/04/14. 2pp. 45235:265-45235:266.

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Roactors," Svc list encl ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:248
- 8803220296 NRC Into Notice 88-010, "Matls Licensons:Lack of Mgt Controls Over Li-censed Programs." Svc ist encl. CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 887-03/28, Consolidated Edison Co. of New York, Inc. 108pp. 44985;247-44995;353.
- 8804120416 Requests that violation noted in Insp Repts 50:313/86:34 & 50:368/86:34 be withdrawn No violation occurred. Util will treat insp team finding as identification of potential weakness Reasons enci. Enci withheld (ref 10CFR73.21). LEVINE_J.M. Arkensas Power & Light Co. 88/03/29. CALLAN, L.J. Region 4, Otc of the Director. 2pp. 45154:057-45154:058.
- 8804080044 Ack receipt of 880321 ltr & payment of \$25,000 for civil penalty imposed by NRC in 680126 order. LIEBERMANJ, Oic of Enforcement (Post 870413), 88/04/01, CAMPBELL,T.G. Arkansas Power & Light Co. 1p. 45044:242
- 8604200343 Responds to violations noted in Insp. Repts 50:313/87-39 & 50:388/87-39.Corrective actions addl personnel assigned to plant licensing section & man-hours increased temporarily to reduce backlog. LEVINE_J.M. Arkansas Power & Light Co. 68/04/04. CALLAN,L.J. Region 4, Ofc of the Director. 4ρρ. 45174;165:45174:168.
- 8804120365 Ack receipt of analytical results transmitted by 880222 ltr re-feedwater, steam generator blowdown & boric acid batch tenk samples collected & noted in Insp. Repts 50-313/87-33 & 50-368/87-33 on 871116-20.BNL results not yet
- CALLANL. J. Region 4, Oic of the Director, 88/04/06, CAMPBELL,G. Arkanses Power & Light Co. 2pp. 45089:322-45089:323.
- 8804210163 Requests extension of submittal date re response to notice of violation & proposed imposition of civil penalty until 880430.Addl time needed to complete preparation of response.
- HOWARD, D.R. Arkensas Power & Light Co. 88/04/06, CALLAN, L.J. Region 4, Ofc of the Director, 1p. 45219:164-45219:164.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tile Bolts." Svc list enct. ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804210168 Responds to violation noted in Insp. Repts 50:313/68:01 & 50:368/68-01.Corrective action.cloth rags removed from room, rubber hoses used for routine maint in room returned to metal storage container & fire watch posted. LEVINE_J.M. Arkaness Power & Light Co. 88/04/07, CALLAN,L.J. Region 4, Ofc of the Director. 3pp. 46219:169-45219:171.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12.
 Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150.

- 8804210317 Forwards Insp Repts 50:313/89:06 & 50:368/88:06 on 880222:0317 &
- notice of violation.

 CALLAN,L.J. Region 4, Ofc of the Director, 8B/04/14, CAMPBELL,G. Arkansas Power & Light Co. 2pp. 45231.150-45231:164.
- -8804210321 Notice of violation from insp on 880222-0327.Violation noted on 880226.replacement of Relay 63X/4926 & Rolay 94-0340.2 Initiated w/o approved job order NRC inspectors observed housekeeping discrepancies on luck handling bridge. * Region 4, Oic of the Director 88/04/14, 2pp. 45231.152-45231:153.
- -8804210326 Insp Hepts 50:313/88-06 & 50:368/88-06 on 880222-0327. Violations noted Major acreas inspected operational safety ventication, maint, surveillance, allegation followup & generic Itr followup.

 JORNSON,W.D., HARBUCK,C.C., HAAG,R.C. Region 4, Old of the Director. 88/04/13. 11pp. 45231:154-45231:164.
- 8804250045 Forwards Insp Repts 50-313/88-07 & 50-368/68-07 on 880307-11 No vio-Dations or deviations noted.

 CALLAN,L.J. Region 4, Oic of the Director, 88/04/15, CAMPBELL,G. Arkansas Power & Light Co. 2pp. 45254:181-45254:189.
- --8804250050 Insp Repts 50-313/88-07 & 50-368/88-07 on 880307-11.No violations or deviations noted-Major areas inspected, inservice testing program for pumps & valves, including tracking methodology for inservice testing stream of the Director SNO4/12. 7pp. STEWART.R.C., SINGH.A., BARNES,I. Region 4, Ofc of the Director 88/04/12. 7pp. 45254:183-45254:189.
- 8804260023 Forwards Insp Repts 50-313/88-02 & 50-368/88-02 on 880221-26 & notice of violation Actions taken in response to previously identified findings also examined & discussed in Paragraph 4 of rept.

 CALLAN,L J. Region 4, Ofc of the Director. 88/04/15. CAMPBELL,G. Arkansas Power & Light Co. 2pp. 45254:313-45254.324.
- --8804260027 Notice of violation from insp on 880221-26. Violation noted: radiation survey instruments inadequate for measuring lower dose rate limits for identifying radiation areas outside controlled access & areas not properly posted. * Region 4, Ofc of the Director. 88/04/15. 2pp. 45254:315-45254:316.
- --8804260031 Insp Repts 50-313/88-02 & 50-368/88-02 on 880221-26. Violation noted Major areas inspected radiation protection activities during Unit 2 refueling outage. CHANEY,H D., MURRAY,B. Region 4, Ofc of the Director. 88/04/08. 8pp. 46254:317-45254:324

880420173 Monthly operating rept for Mar 1988.W/880412 ltr. WHITT.M.S., HOWARD,D.R. Arkansas Power & Light Co. 88/03/31. 6pp. 45220:268-45220:273.

S. Reportable occurrences, LERs & related correspondence

- 8804060228 LER 88:001-00 on 850506 discovered incorrectly configured target rock solendid operated valves.On 880125 discovered that valve still incorrectly configured.Caused by failure to recognize valve directional characteristics.W/880328 TAYLOR,L.A., LEVINE,J.M. Arkansas Power & Light Co. 88/03/28. 9pp. 45048.078-45048.086.
- 8804200027 LER 88-004-00:on 880210,reactor bldg hydrogen concentration instrument observed inoperable during operability verification test Caused by wires not terminated on correct terminal block locations. Wiring corrected.W/880405 III. ROGERS.P.C., LEVINE.J.M. Arksnass Power & Light Co. 88/04/05. 6pp. 45215:288-45215:293.

V. Operator Examinations

- 8804250088 Responds to FOIA request for info re-scores of reactor operators & senior reactor operators. Forwards requalification exam summary source sheets fisted in enclapp w/personal privacy into deleted.
 GRIMSLEY.D.H. Division of Rules & Records (Post 870413), 88/04/18, BOLEY,K. Public Citizen's Critical Mass Energy Project, 2pp. 45213.003-45213.095.
- --8804250167 Package of NRC administered requalification exam results summary.
 NRC No Detailed Affiliation Given. 87/07/20, 88pp. 45213.007-45213.095.

DOCKET 50-314 NUCLEAR SHIP SAVANNAH

O. Advisory Committee on Reactor Safeguards reports & correspondence

8804140215 Submits summary of actions discussed at ACRS 335th meeting on 880310-12 in Washington,DC.Including ACRS repts/ recommendations.other actions,agreements,assignments & requests & future agends. KERR,W. ACRS - Advisory Committee on Reactor Safoguards. 88/03/24, ZECH,L.W. Commissioners. 4pp. 45118:172-45118:175.

DOCKET 50-315 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8804010026 Rev 1 to Emergency Plan Implementing Procedure PMP 2081 EPP.210.
- "Unit Vent Sampling."

 Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 88/03/25.
 9pp. 45031:156-45031:164.
- 8804010035 Change Sheet 1 to Rev 2 to Emergency Plan Implementing Procedure PMP 2080 EPP.107, "Notification of Plant Personnel." BURRIS,L.D. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 88/03/25, 45pp. 45010.023-45010.067.

- 8804060118 Forwards Safety Insp. Repts 50-315/88-08 & 50-316/88-09 on 880127-0314.No violations noted.
- GULDEMOND,W.G. Region 3, Ofc of the Director, 88/03/25, ALEXICH,M.P. American Electric Power Co., Inc. ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 2pp. 45046;235-46046 249.
- --8804060123 Insp Repts 50-315/88 08 & 50-316/88-09 on 880127-0314.No violations or deviations noted Major areas Inspected actions on previously identified items, plant operations, radiological controls, maint, surveillance, fire protection & security. BURGESS,B.L. Region 3, Ofc of the Director, 88/03/25 13pp. 45040 237-45048-249.
- 8804040143 Responds to NRC 880229 ltr re violations noted in Insp Repts 50-315/86-06 & 50.316/88-07 Corrective actions telephones tested for operability on 880128 broper documentation of tests made & filed in emergency planning coordinator files. ALEXICH, MP. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 88/03/20. DAVISA.B. Document Control Branch (Document Control Desk). 4pp. 45020:316 45020:319

I. Financial information

8804200090 "1987 Annual Rept.Indiana Michigan Power Co." W/880413 ltr.
ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.),
87/12/31, MURLEY,T.E. NRC - No Detailed Affiliation Given 32pp. 45218.112-

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re-removal of organization charts from Tech Spec administrative control requirements Svc list end. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/03/22 Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153
- 8804060236 Ack receipt of util 880321 Itr re-requested exception to lifetime storage of radiographs contained in ANSI N45.2.9. Revised program acceptable. WRIGHT,G.C. Region 3, Otc of the Director. 88/03/29. FAY,C.W. Wisconsin Electric Power Co. 2pp. 45007:299-45007:300.
- 8804080095 Responds to NRC 880127 request for addl info on ATWS mitigation sys actuation circuitry.

 ALEXICH,M.P. American Electric Power Co., Inc. 88/03/31. MURLEY,T.E. Document Control Branch (Document Control Dosk). 12pp. 45099:160-45099:171.
- 8804120355 Confirmatory Action Ltr CAL-RIFI-88-07 re A Blind 880405 telcon concern-Ing potential tempering event involving foreign mait found in turbine drive auxiliary feedwater pump bearing housing Preventive actions listed.

 DAVIS.A.B. Region 3, Ofc of the Director. 80/04/05. ALEXICH.M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 2pp. 45146.083-45146:084.
- 8804140193 Provides listed info requested in 880225 lir re operating nuclear power units located at twelve sites along Great Lakes.
 STELLO,V. Old of the Executive Director for Operations. 88/04/06. RIDGE,T. House of Fig. 5pp. 45104:138-45104:145.
- 8804080088 Ganeric Ltr 88-07 to power reactor licensees & applicants re-modified enforcement poticy concerning 10CFR50.48, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc list onct. MIRAGLIA,F.J. Associate Director for Projects (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.

- 8803290085 Forwards Safety Insp Repts 50-315/88-07 & 50-316/88-08 on 880208-26.No violations or deviations noted insp consisted of exam of safety evaluations conducted per requirements of 10CFR50.Section 60.59. WRIGHT,G.C. Region 3, Olc of the Director, 88/03/22, ALEXICH,M.P. Indiana Michigan Power Co. (tormerly Indiana & Michigan Electric Co.), 2pp. 44821:205-44921:215.
- --9803290069 Safety Insp Repts 60-315/88-07 & 60-316/88-08 on 880208-26. No violations or deviations noted.Major areas inspected: adequacy of licensed 10CFR50.59 safety evaluations.
 HASSE, R.A., SUTPHIN,R.N., AZAB,B.A. Region 3, Old of the Director, 88/03/21, 8pp. 44921:207-44921:215.
- 8803300025 Forwards Exam Repts 50-315/OL 88-01 & 50-316/OL-88-01 on 880222-24. WRIGHT,G.C. Region 3, Otc of the Director. 88/03/24. ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 2pp. 44963.013.44963.080.
- --8803300165 Exam Repts 50-315/OL-88-01 & 50-316/OL-88-01 on 880222-24. Exam results:one retake senior reactor operator failed exam, ell other candidates passed DAMON.D.J. Region 3, Ofc of the Director, 88/03/24, 66pp. 44963.015-44963:080,
- 8804060118 Forwards Safety Insp Repts 50-316/88-08 & 50-316/88-09 on 880127-0314.No violations noted.

 0314.No violations noted.

 GULDEMOND,W.G. Region 3, Oic of the Director. 88/03/25. ALEXICH.M.P. American Electric Power Co., Inc. ALEXICH.M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 2pp. 45046:235-45046:249.
- --8804060123 Insp Repts 50-315/88-08 & 50-316/88-09 on 880127-0314.No violations or deviations noted Major areas Inspected actions on previously identified items.plant operations,radiological controls,maint,surveillance,fire protection & security. BURGESS,B.L. Region 3, Ofe of the Director, 88/03/26, 13pp. 46046:237-45046:249.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactiors." Svo list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995 246.
- 8803220296 NRC Info Notice 88-010, "Mattls Licensees:Lack of Mgt Controls Over Licensed Programs." Svo list encl.

 CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 970729), 88/03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995-247-44995:353.

- 8804040143 Responds to NRC 880229 lir re violations noted in Insp Repts 50:315/88-06 & 50:316/86-07 Corrective actions telephones tested for operability on 860129 & proper documentation of tests made & fived in emorgency planning coordinator ides ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.) 88703/30. DAVIS.A.B. Document Control Branch (Document Control Dosk). 4pp 45020.316-45020.319.
- 8804060191 Discusses Salety Insp Repts 50:315/88:03 & 50:316/88:04 & forwards notice of violation Violation categorized as Severity IV for stated reasons Response should include steps to be taken to preclude further inadequate design control MILLER,H J. Region 3, Otro of the Director, 687/03/30 WILLIAMS,D H. Ind ana Michigan Power Co. (formerly Ind ana & Michigan Electric Co.) 2pp. 45028:303-45028:308
- --8804060196 Notice of violation from insp on 880111-14 & 0225-28. Violation noted failure to provide adequate design control measures including reviews relectrical isolation between local shuldown & indication panels. MILLER,H J Region 3, Ofci of the Director, 88703/30, 2pp. 45028-305-45028-306.
- 8804110191 Hesponds to NRC Bulletin 88-002, "Rapidly Propagating Fatigue Cracks in Steam Generator Tubos." Evaluation of steam generator tube denting description of in-place leak defection methods & corrective action program anci.

 ALEXICH.M.P. Indiana Michigan Power Co. (tormerly Indiana & Michigan Electric Co.). 88/03/31, DAVIS.A.B. Document Control Branch (Document Control Desk). 23pp. 45135-250-46135-272.
- 8804010256 NRC Into Notice 88 011, "Potential Loss of Motor Control Cir 8/or Switchboard Function Due to Faulty Tie Bolts." Svc list enc! ROSSI, CE. Division of Operational Events Assessment (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407.051.
- 8804150050 Forwards Safety Insp Repts 50:315/68:13 & 50:316/68:15 on 880315-31 No violations noted HARRISON.J.J. Region 3, Old of the Director, 88/04/11, ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.), 2pp. 45184:037.45184.044.
- -8804150053 fnsp Repts 50:315/88-13 & 50:316/88-15 on 880315-31.No violations or deviations noted Major areas inspected. Implementation of Generic Ltr 93-28 in areas of equipment classification, vondor interface & post-maint testing NEISLER, J. H., GARDNER, H.N., Region 3, Ofc. of the Director. 88/04/08. 6pp. 45184.039-45184.044.
- 8804190403 Forwards request for eddl into supplementing 860516 & 1010 & 870528 & 1110 responses to IE Bulletin 85-003, "Motor: Operated Valve Common Mode Fallures During Plant Translents Due to Improper Switch Setting "GREENMAN,E.G. Region 3, Otc of the Director, 88/04/11, ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.), 3pp. 45155:171-45155:173.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svolist enci. ROSSI.C.E. Dwision of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Ed son Co. of New York, Inc. 123pp. 45165.028-45165.150.
- 8804210015 Responds to NRC Bulletin 88-001, "Deficiencies in Westinghouse Circuit Breakers." Sulfetin addresses deficiencies exclusive to Westinghouse OS/DSL type circuit breakers & outlines specific inspat to be performed ALEXICH,M P. Indiana Michigan Power Co. (formerly Indiana & Michigan Etectric Co.). 88/04/13, MURLEY,T. E. Document Control Branch (Document Control Desk). 2pp. 45235:338-45235-337.

8803300326 Monthly operating rept for Feb 1988.W/880304 ltr.
MICHAELSON, PUPILS,A.S., SMITH,W.G. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.), 68/02/29, 6pp. 44967:250-44967:255.

S. Reportable occurrences, LERs & related correspondence

- 8804110193 Part 21 rept re environ qualification of torque switches designed by Limitorque Corp. Initially reported on 880330. Design not qualification tested for nuclear safety related see Unitested forque switches will be replaced.

 ALEXICH,M.P. Indiana Michigan Power Co. (formorly Indiana & Michigan Electric Co.).

 88704/04. MURLEY,T.E. Document Control Branch (Document Control Desk). 4pp 45135:105-45135:108.
- 8804130125 Partial response to FOtA request for documents re Info Assessment Team notification & alleged veitre tampering. App A documents evailable in PDR.Forwards App B documents App B documents also available in PDR. GRIMSLEY.D.H. Division of Rules & Records (Post 870413), 88/04/04 MAXWELL.B. Cosmos Broadcasting Corp. 3pp. 45102.031-45102.048.
- --8804130165 Forwards FBI communication to be disseminated only to NRC employees w/need to know.W/o FBI communication Records of 860810,0926,1212,870404 & 0929 telcons & Region III repts of 860810,670318 & 0929 events enci. DAVIDSON,J. Office of Nuclear Material Safety & Safeguards,Director. 87/10/15. HAYES,B. Office of Investigations. 11pp. 45102.038-45102.048.
- 8804080211 PNO-III-88-030 on 880404 supervisor discovered two pieces of foam mattinside bearing housing on turbine-driven auxiliary feedwater pump.FBI notified of tampering Region III plans to issue confirmatory action ltr.

 CREED.J. MALLETT.B., BURGESS,B. Region 3, Oic of the Director. 88/04/05. 1p. 45096:182-45098:182.
- 8804220000 RO:on 880411,fire protection water sys not operable per Tech Spec 3.7.9.1 b.Caused by planned isolation of portion of south leg of outside fire protection ring header. Backup fire protection averable from nearby fire dept. SMITH,W.G. Indiana Mich gan Power Co. (formerly Indiana & Michigan Electric Co.) 68/04/11. DAVIS.A.B. Document Control Branch (Document Control Desk). 2pp. 45216/224-45216:225.

V. Operator Examinations

8803300025 Forwards Exam Repts 50-315/OL-88-01 & 50-316/OL-88-01 on 880222-24. WRIGHT,G.C. Region 3, Oic of the Director, 88/03/24. ALEXICH,M.P. Indiana Michi-

- -8803300165 Exam Repts 50:315/OL:08:01 & 50:316/OL:08:01 on 880222:24 Exam results:one relate sentor reactor operator lailed exam, all other candidates passed exams

 DAMON,D.J. Region 3, Olc of the Director: 88/03/24, 66pp. 44963:015-44963.080
- 8804250088 Responds to FOIA request for info re-scores of reactor operators & sonior reactor operators Forwards requalification exem summary source sheets listed in end app w/personal privacy info deleted.
 GRIMSLEY,D.H. Division of Rubs & Records (Post 870413) 88/04/19. BOLEY,K. Public Citizen's Critical Mass Energy Project. 2pp. 45213 003-45213:095
- -8804250167 Package of NRC administered requalification exam results summary. NRC No Detailed Attivistion Given 87/07/29, 88pp 45213.007-45213.095.

DOCKÉT 50-316 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8804010026 Rev 1 to Emergency Plan Implementing Procedure PMP 2081 EPP 210. "Unit Vent Sampling."

 'Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 88/03/25. 9pp. 45031:158-45031:164.
- 8804010035 Change Sheet 1 to Rev 2 to Emergency Plan Implementing Procedure PMP 2080 EPP.107, "Notlication of Plant Personnel." BURRISL. D. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 88/03/25.
- 8804060118 Forwards Safety Insp Repts 50:315/88-08 & 50:316/88-09 on 890127-0314 No violations nated GULDEMOND.W.G. Region 3, Ofc of the Director, 88/03/25. ALEXICH,M.P. American Electric Power Co., Inc. 2pp 45046:235-45046:249.
- --8804060123 Insp Repts 50-315/88-08 & 50-316/88-09 on 880127-0314 No violations or deviations noted Major greas inspected actions on previously identified items, plant operations, radiological controls, maint, surveillance, fire protection & security, BURGESS,B.L. Region 3, Ofc of the Director. 88/03/25 13pp. 45046-237-45046-249.
- 8804040143 Responds to NRC 880229 ftr re violations noted in Insp Repits 50-315/88-06 & 50-316/88-07.Corrective actions telephones tested for operability on 880129 & proper documentation of tests made & filed in emergency planning coordinator lites ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.) 88/03/30. DAVIS.A.B. Document Control Branch (Document Control Desk). 4pp. 45020 316-45020.319.

I. Financial Information

8804200090 "1987 Annual Rept Indiana Michigan Power Co." W/880413 ltr. ALEXICH,M.P. Indiana Michigan Power Co. (Iormerly Indiana & Michigan Electric Co.). 87/12/31. MURLEY,T.E. NRC - No Datailed Affiliation Given. 32pp. 45218:112-45218:143.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spag administrative control requirements Svc list encl. MIRAGLIA, F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972.107-44972:153.
- 8804080095 Responds to NRC 880127 request for addit into on ATWS mitigation sys actuation cricuity.

 ALEXICH,M.P. American Electric Power Co., Inc. 88/03/31, MURLEY,T.E. Document Control Branch (Document Control Desk), 12pp. 45099:160-45098:171.
- 8804120355 Confirmatory Action Ltr CAL-RIII-98-07 re A Blind 880405 telcon concerning potential tempering event involving foreign mett found in turbine drive auxiliary leedwater pump bearing housing Proventive actions listed.

 DAVIS,A.B. Region 3, Otc of the Director. 88704705. ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 2pp. 45146.063-45146:064.
- 8804140193 Provides listed info requested in 880225 ltr re operating nuclear power units located at twelve sites along Great Lakes.
 STELLO,V. Ofc of the Executive Director for Operations, 88/04/06, RIOGE,T. House of Rep. 5pp. 45104:138-45104:143.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified enforcement policy concerning 18CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA,F.J. Associate Orrector for Projects (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.

- 8803290065 Forwards Safety Insp Repts 50:315/88.07 & 50:316/88.08 on 880208.28 No violations or deviations noted insp consisted of exam of safety evaluations conducted per requirements of 10CFR50, Section 50.59.

 WRIGHT,G.C. Region 3, Oic of the Director. 88/03/22. ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.), 2pp. 44921.205-44921:215
- --8803290069 Safety Insp Repts 50:315/88-97 & 50:316/88-98 on 880208-26. No violations or deviations noted Major areas inspected: adequacy of ficenses 10CFR50.59 safety evaluations.

 HASSE,R.A., SUTPHIN,R.N., AZAB,B A Region 3, Ofc of the Director, 88/03/21, 9pp.
- 8803300025 Forwards Exam Repts 50:315/OL-88-01 & 50:316/OL-88-01 on 880222-24.
 WRIGHT G.C. Repting 3, Oto of the Director, 88/03/24, ALSYCHARD Indiana Mark

- -8803300165 Exam Repts 50-315/QL-88-01 & 50-316/QL-88-01 on 880222-24. Exam results:one retake senior reactor operator failed exam, all other candidates passed DAMON, D.J. Region 3, Ofc of the Director, 88/03/24, 66pp. 44963.015-44963:080.
- 8804060118 Forwards Salety Insp Repts 50:315/88-08 & 50:316/88-09 on 880127-0314 No violations noted.

 GulDEMOND,W.G. Hegion 3, Ofc of the Director, 88/03/25 ALEXICH,M.P. American Electric Power Co., Inc. ALEXICH,M.P. Indiana Michigen Power Co. (formerly Indiana & Michigen Electric Co.), 2pp. 45046:235-45046:249.

- --8804060123 insp Repts 60-315/88-08 & 50-316/88-09 on 880127-0314. No violations or deviations noted Major areas inspected actions on previously identified items, plant operations, radiological controls, maint, surveillance, lite protection & security, BURGESS, B.L. Region 3, Ofc of the Director. 88/03/25, 13pp. 45046-237-45046-249.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list encl. ROSSI,CE. Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 88-010, "Matis Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list encl. CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 88/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.
- 8804040143 Responds to NRC 880229 Itr re violations noted in Insp Repts 50-315/88-80440143 Hesponds to NRC 880229 it re violations noted in hisp helps of 315766-66 & 50-318/88-07-Corrective actions:telephones tested for operability on 880129 & proper documentation of tests made & filed in emergency planning coordinator files. ALEXICH, M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 88/03/30. DAVIS,AB. Document Control Branch (Document Control Desk). 4pp. 45020:316-45020:319.
- 8804060191 Discusses Safety Insp. Repts 50-315/88-03 & 50-316/88-04 & forwards notice of violation. Violation categorized as Severity IV for stated reasons. Response should include steps to be taken to preclude further inadequate design control. MILLER, H.J. Region 3, Oic of the Director, 88/03/30, WILLIAMS, D.H. Indians Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 2pp. 45028:303-45028:306.
- --8804060196 Notice of violation from Insp on 880111-14 & 0225-28. Violation noted fallure to provide adequate design control measures, including reviews re electrical isolation between local shuldown & indication penals.

 MILLER,H J. Region 3, Old of the Director, 88/03/30, 2pp. 45028:305-45028.306.
- 8804110191 Responds to NRC Bulletin 88-002, "Rapidly Propagating Fatigue Cracks in Steam Generator Tubes." Evaluation of steam generator tube denting, description of in-place leak detection methods & corrective action program encl. ALEXICH.M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 88/03/31. DAVIS.A.B. Document Control Branch (Document Control Dosk). 23pp. 45135-32. 45135.250-45135:272
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Fautly Tie Botts." Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407:051.
- 8804150050 Forwards Safety Insp. Repts 60-315/88-13 & 50-316/88-15 on 880315-31.No violations noted. HARRISON,J.J. Region 3, Ofc of the Director, 88/04/11, ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.), 2pp. 46184:037-45184:044.
- --8804150053 Insp Repts 50:315/88-13 & 50:316/88-15 on 880315:31 No violations or deviations noted Major areas Inspected, implementation of Generic Ltr 83:28 in areas of equipment classification vendor interface & post-maint testing. NEISLERUH, GARDNER,R.N. Region 3, Ofc of the Director. 88/04/08. 6pp. 45184.039-45184.044.
- 8804190403 Forwards request for additinfo supplementing 860516 & 1010 & 870528 & 1110 responses to IE Bulletin 85-003, "Motor- Operated Valve Common Mode Fallures During Plant Transients Due to Improper Switch Setting."

 GREENMAN,E.G. Region 3, Olc of the Director. 88/04/11, ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 3pp. 45155:171-45155:173.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc
 - ROSSICE. Division of Operational Events Assessment (Post 670411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 46165:028-46185:160.
- 8804210015 Responds to NRC Bulletin 88:001, "Deficiencies in Westinghouse Circuit Breakers." Bulletin addresses deficiencies exclusive to Westinghouse DS/DSL type circuit breakers & outlines specific insps to be performed. ALEXICH.M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 88/04/13. MURLEY.T.E. Document Control Branch (Document Control Desk). 2pp. 45235:336 45235:337.

- 8803300322 Monthly operating rept for Feb 1988.W/880304 ltr.
 MICHAELSON, PUPILS,A.S., SMITH,W.G. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.), 88/02/29, 6pp. 44953;125-44953;130.
- S. Reportable occurrences, LERs & related correspondence
- 8804130125 Partial response to FOIA request for documents re into Assessment Team notification & alleged valve tampering. App A documents available in PDR.Forwards App B documents. App B documents also available in PDR. GRIMSLEY.D.H. Division of Rules & Records (Post 870413): 88/04/04. MAXWELL.B. Cosmos Broadcasting Corp. 3pp. 45102:031-45102:048.
- -8804130165 Forwards FBI communication to be disseminated only to NRC employees w/need to know.W/o FBI communication.Records of 880610,0928,1212,870404 & 0929 leicons & Region III repts of 880610,870318 & 0929 events encl. DAVIDSON,J. Office of Nuclear Material Safety & Safeguards,Director. 87/10/15. HAYES,B. Office of Investigations. 11pp. 45102:038-45102:048.

- 8804210261 LER 88-003-00.on 880311. discovered that setpoints of voltage relays out-side Tech Spec aflowable values. Tech Spec change request will be submitted as soon as engineering review to evaluate acceptable Tech Spec values & tolerance complet
 - od. BEILMAN,T.P., SMITH,W.G. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 88/04/11. 5pp. 45281.259-45281.263.
- 8804220090 RO.on 880411,fire protection water sys not operable per Tech Spec 3.7.9.1.b Caused by planned Isolation of portion of south leg of outside fire protection ring hoader Backup fire protection swallable from nearby fire dept. SMITH.W.G. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 88/04/11. DAVIS.A.B. Document Control Branch (Document Control Desk). 2pp. 45216:224-45216.225.
- 8804190250 RO.lire detection sys inoperable for Fire Zone 34 East main steam encl has been Inoperable in excess of 14 days Caused by Inoperable delector spring Replacement parts received Sys returned to svc on 880412. SMITH.W.G. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 88/04/13. Document Control Branch (Document Control Desk). 2pp. 45215-268-45215:270

V. Operator Examinations

- 8803300025 Forwards Exam Repts 50-315/OL-88-01 & 50-316/OL-88-01 on 880222-
 - 24. WAIGHT,G.C. Region 3, Ofc of the Director. 88/03/24. ALEXICH,M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Electric Co.). 2pp. 44963:013-44963:080.
- --8803300165 Exam Repts 50-316/QL-88-01 & 50-316/QL-88-01 on 880222-24. Exam results:one retake senior reactor operator failed exam, all other candidates passed DAMON,D.J. Region 3, Ofc of the Director. 88/03/24. 66pp. 44963.015-44963.080.
- 8804250088 Responds to FOIA request for info re scoros of reactor operators & senior reactor operators. Forwards requalification exam summary source sheets listed in dirict app w/personal privacy info defeted.
 GRIMSLEY, D.H. Division of Rules & Records (Post 870413), 88/04/19 BOLEY,K. Public Citizen's Critical Mass Energy Project. 2pp. 45213:003-45213:095.
- --8904250167 Package of NRC administered requalification exam results summa NRC No Detailed Affiliation Given. 87/07/20. 88pp. 45213 007-45213.095.

DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 8804070154 Revised emergency response plan implementing procedures, including Change 7 to Rev 11 to Attachment 2 of ERPIP 4.1.6, "Airborne Activity" & Change 13 to Rev 9 to Attachment 4 to ERPIP 4.1.7, "Alrborne Activity."

 * Baltimore Gas & Electric Co. 68/03/16, 12pp. 45029.316.45029.327.
- 8804130209 Forwards Safety Insp Repts 50-317/88-04 & 50-318/88-05 on 880211-12 & notice of violation.

 CONGEL,F.J. Region 1, Olc of the Director. 88/03/24. TIERNAN,J.A. Baltimore Gas & Electric Co. 3pp. 45151:259-45151:268.
- --8804130211 Notice of violation from Insp on 880211-12.Violation noted failure to notify & recall emergency response personnel & activate emergency response facilities after ALERT declared. CONGEL, F.J. Region 1, Oic of the Director, 88/03/24, 1p. 45151:262-45151:262.
- -8804130215 Insp. Repts 50-317/88-04 & 50-318/88-05 on 880211-12. Violations noted Major areas inspected classification, reporting & response to ALERT declared 001 880201. CONKLIN.C., LAZARUS,W.J. Region 1, Oic of the Director, 88/03/14. 4pp.
- 45151:263-45151:266. 8804070259 Advises that 671005 & 880202 & 09 Revs 6.7 & 7-amended to safeguards contingency plan consistent w/provisions of 10CFR60.54(p) & acceptable. BELLAMY.R.R. Region 1, Ofc of the Director. 88/03/29. COSS,H.D. Baltimore Gas & Electric Co. 3pp. 45076:211-45075:213.
- 8804200034 Rev 12, Change 18 to Emergency Plan Implementing Procedure ERPIP 3.0,
 - "Personnel Injury."

 * Baltimore Gas & Electric Co. 88/03/30, 14PP, 45219:055-45219:068.
- 8604150093 Advises that emergency planning zone reduction requests shall remain on plant active docket file,but no further review efforts until notice given to NRC to reactivate review.

 VARGA,S.A. Division of Reactor Projects 1/II (Post 870411). 88/04/11. TIERNAN,J.A. Baltimore Ges & Electric Co. 3pp. 45134.020-46134.022.
- 8804200018 Revised emergency plan implementing procedures including Change 12 to Rev 10 to Attachment 2 of EPRIP 4.1.3, "Technical Support Cir Rostor."

 * Baltimore Gas & Electric Co. 88/04/11, 7pp. 45218 215-45218:221.
- 8804200021 Revised emergency plan implementing procedures.including Rev 9 to Change 3 to ERPIP 4.4.4, "Input Determining Atmospheric Stability Class & Mateorology" & Rev 9 to Change 2 to ERPIP 4.4.9, "Baltimore Cas & Electric Co. 88/04/11, 10pp. 45226:271-45226:279.

I. Financial Information

8804070222 Forwards annual rept for 1987. RINGSDORF, J.E. Baltimore Gas & Electric Co. 88/03/31. Document Control Branch (Document Control Desk). 1p. 45030:048-45030:104.

00

- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8804050271 Rev 7 to updated FSAR for Calvert Cills Nuclear Power Plant Units 1 & 2 W/880331 ht TIERNAN J A. Balt more Gas & Electric Co. 68/03/31. 61pp 45020 331-45021.032.
- P. Operating license stage documents & correspondence
- 8803250284 Requests withdrawal of portion of 880212 application for amond on Cycle 10 reload re Page 3/4 1-1 of Tech Spoc 3 1.1 1.except ref to Figure 3.1-15. MHALCIKJA Battmore Gas & Electric Co 86/03/21. Document Control Branch (Document Control Upsk) 5pp 44945 226 44945 230
- 8803240426 Genenc Lir 88:06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc 1st ench MIRAGLIAF. J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972 107-44972.153
- 8804050001 Provides response to concerns raised in NRC 880311 ltr re Cycle 10 reload design. TIERNANJA Baltimore Gas & Electric Co 88/03/25, Occument Control Branch (Dacument Control Desk) 5pp. 45021 080-45021:064.
- 8803310247 Requests rehel from ASME Code Section XI requirement determined impractical & permission to deter hydrostatic pressure test Relief requested immediately to avoid Unit 2 start-up delay Fee paid.

 TIERNAN,J.A., Battmore Gas & Efectine Co. 88/03/28. Document Control Branch (Document Control Desk). 5pp. 44996.001-44996.005
- 8804120336 Forwards Rev 15 to 1 QA Poticy for Calvert Cliffs Nuclear Power Plant," per 870316 tetcon.
 ANULE A B Baltimora Gas & Electric Ca 88/03/29 EAPEN,P K Region 1, Old of the Director, 10pp. 46132 043-45132 109
- --8804120339 Ray 15 to "OA Policy for Ca'vert Cliffs Nuclear Power Plant" LUNDVALL A.E., TIERNAN,J.A., COSS,H.D. Ballimoro Gas & Electric Co. 68/02/10. 57pp. 45132 053 45132 109.
- 8804060492 Forwards addit requests for relief from ASME Section XI pump & valve test program as supplific 870210 submittal. Justification for removal of various valves & testing requirements from inservice tost program also end.

 ITERNAN,JA Baltimoro Gas & Electric Co. 88/03/30 Document Control Branch (Occument Control Desk). 10pp. 45047;167-45047;166.
- 8804110108 Responds to Generic Ltr 88:03 re resolution of Generic Safety Issue 93, "Steam Binding of Auxiliary Feedwater Pumps" Util impinitains procedures for recognizing steam in oding & restoring feedwater sys to operable status TIERNANUA Rathmure Gas & Electric Co. 86/03/31. Document Control Branch (Document Control Desk). 2cp. 45064:360-45064:381.
- 8804130134 Forwards proprietary & nonpropile/any replacement pages to rept submitted by 871002 ltr re-control element assembly ctr finger cracking. Replacement pages due to changes to proprietary classifications. Proprietary pages with eld LIPPOLD,W.J. Baftimore Gas & Electric Co. 28704706 Document Control Branch (Occument Control Desk). 13pp. 45099.328-45099.341.
- 8804080888 Generic t.tr 88-07 to power reactor liconsees & applicants re-modified enforcement policy concerning 10CFR50.49. "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Suc its encl. MIRAGLIA.F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184;237-45184;285.
- 8904150093 Advises that emergency planning zone reduction requests shall remain on plant active docket file but no further review efforts until notice given to NRC to reactivate review.
 VARGAS A Division of Reactor Projects (VIII (Past 870411) 88/04/11)
- VARIGA,S.A. Division of Reactor Projects 1/11 (Post 870411). 88/04/11. TIEHNAN,J.A. Baltimore Gas & Electric Co. 3pp. 45134.020-45134.022.
- 8804210175 Forwards corrected notice of consideration & Issuance of amend to License *DPR-53* & proposed NSHC determination & hearing on 880212 request re adding upper limits & increasing moderator temp coefficient thermal power levels. MCNEILS A. Project Orrectorate I-1, 88/04/12. TIERNAN,J A. Baltimore Gas & Electric Co. 1p. 45192 097-45192 107.
- --8804210182 Corrected notice of consideration of Issuance of amend to License DPR-53 & proposed NSHC determination & opportunity for hearing on 860212 request to add upper limits & Increase thermal power levels for moderator temp coefficient. MCNEIL,S A. Project Directorate I-1. 88/04/12, 11pp. 45192.088-45192.107.
- 8804210362 Forwards notice of proposed no significant frazards consideration determination & opportunity for hearing re 880212 application to support Unit 1 Cycle 10 operation MCNEIL,S A Project Directorate 1-1, 88/04/12. TIERNAN,J A Baltimore Gas & Electric Co. 2pp. 45181;255-45191;268.
- --8804210396 Notice of consideration of Issuance of amend to License DPR-53 & proposed NSHC determination & opportunity for hearing Amend modifies Tech Spec by adding figure that provides upper limits for moderator temp coefficient. MCNEIC, S.A. Project O rectorato I-1, 88/04/12, 10pp, 45191:257-45191:266.
- 8804220263 Withdraws request for additinfo rejutifies responses to Items 4.2.3 & 4.2.4 Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATWS Events" MCNEIL,S.A. Project Directorate I-1, 88/04/19, TIERNAN,J.A. Ballimore Gas & Electic Co. 2pp. 45201:171-45201:172.
- 8804280934 Requests response to questions provided in 871113 request for additinto re-proposed inservice test program for safety-related pumps & valves within 70 days of fir date, per 880218 & 19 meeting. Trip rept for pump & valve enct. MCNEIL, SA. Project Directorate 1-1, 88/04/19, TIERNAN, J.A. Baltimore Gas & Electino Co. 2pp. 45268-188-45266.216.
- -8804280052 Trip rept of 880218-10 working meeting w/NRC,util & EG&G Idaho re pump & valve inservice teating program.
 ROCKHOLD.H.C., HEMMING,W.C. EG&G Idaho, Inc. (subs. of EG&G, Inc.).
 ROCKHOLD.H.C. Idaho National Engineering Laboratory, 88/03/28. DEMPSEY,K.
 NRC No Detailed Afficiation Green, 27pp. 45286:190-45266 216.

8804290090 Notification of 880502 moeting w/util & Bechtel in Rockville,MD to discuss util 880406 request for ASME Code reflief for up to 151 relief & safety valves which selpoints may be high out-of-spec by up to 70 ps.

MCNEIL,S.A. Project Directorate I-1. 88/04/22. CAPRARIA. Project Directorate I-1. 3pp. 45322;344-45322 346.

Q. Inspection reports, IE Bulletins & correspondence

- 8804120453 Notification of Significant Licensee Meeting 88:023,Rev 1 in King of Prussia,PA on 880218 to discuss licensee SSFI insp.
 TRIPP,LE. Region 1, Ofc of the Director. 88/02/18. Region 1, Ofc of the Director. 2pp. 45091;147-45091:148.
- 8804130209 Forwards Safety Insp. Repts 50:317/88:04 & 50:318/88:05 on 880211-12 & notice of violation.

 CONGEL.F.J. Region 1, Orc of the Director, 88/03/24. TIERNAN, J.A. Beltimore Gas & Electric Co. 3pp. 45151:269:45151:266.
- --8804130211 Notice of violation from Insp on 860211-12.Violation noted: failure to notly & rocall emergency response personne. & activate emergency response facilities after ALERT declared.
 CONGEL,F.J. Region 1, Otc of the Director, 88/03/24, 1p. 45151:262-45151:262
- --8804130215 Insp Repts 50:317/88-04 & 50:318/88-05 on 880211-12. Violations noted Major areas inspected classification, reporting & response to ALERT declared on 880201.

 CONKLIN.C., LAZARUS,W.J. Region 1, Oic of the Director, 88/03/14. 4pp. 45151:263-45151:268.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list encl. ROSSI, C.E. Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:128-44996:246.
- 8803220296 NRC Into Notice 88-010; "Matts Licensees:Lack of Mgt Controls Over Licensed Programs." See ist enct. CUNNINGHAM,R.5 Selvision of Industrial & Medical Nuclear Safety (Post 870729), 887-03728. Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44985;353.
- 8804060481 Responds to NRC Into Notice 88-005 re fire in annunciator control cabinets. Statement re inadequate oxygen in tire area inaccurato. Nausea felt by Individual discharging fire extinguisher but not by other persons in area. If ERNAN, J.A. Balismore das & Electric Co. 88/03/31. Document Control Branch (Document Control Desk). 2pp. 45047:167-45047:168.
- 8804130325 Requests rolled from testing requirements in ASME Boiler & Pressure Vessel Code Section XI for inservice insp Class 2 & 3 valves w/exception of main steam selety valves. Relief requested correct selpoints verified & established Fee paid. LEMONS, R. Bellimore Gas & Electric Co. 88/04/06. Document Control Branch (Document Control Dask). 4pp. 45137:324-45137:327.
- 8804010256 NRC Into Notice 88-011, "Potential Loss of Motor Control Cir &/or Switchbaard Function Due to Faulty Tie Bolts." Svc list encl. ROSSLCE, Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407:051.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svo. list enci.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:160.
- 8804200119 Forwards Safety Insp Repts 50-317/88-03 & 50-318/88-03 on 880229-0304.No violations noted BELLAMY,R.R. Region 1, Otc of the Director, 88/04/13, TIERNAN,J.A. Saltimore Gas & Efectric Co. 2pp. 45220.335-45220.342.
- --8804200127 Insp Repts 50-317/88-03 & 50-317/88-03 on 880229:0304.No violations noted.Major areas inspected-nonradiotogical chemistry program including analytical procedure evaluations & measurement control. ZIBULSKY.H., PASCIAK,W.J. Region 1, Ofc of the Director. 88/04/11. 6pp. 45220:337-45220.342.
- 6804220093 Responds to violations noted in Insp. Repts 50:317/88-01 & 50:318/88-01. Corrective actions:attention being given to loose carls & other matts in switchgear rooms & cable spreading rooms.

 TIERNAN_J.A. Baltimore Gas & Electric Co. 88/04/18. Document Control Branch (Document Control Dask), 3pp. 45220,028-45220,030.
- 8804290113 Discusses util 870909 response to NRC Bulletin 87-001, "Thinning of Pipe Walls at Nuclear Power Plants." (nfo being used to obtain data on observed pipe wall thinning & no further plant-specific action required.

 MCNEIL, S.A. Project Directorate I-1, 88/04/25, TIERNAN, J.A. Baltimore Gas & Electric Co. 3pp. 45322:222-45322;224.

R. Periodic operating reports & related correspondence

- 8804040038 "Radiotogical Environ Monitoring Program Annual Rept for Calvert Clitts Nuclear Power Plant Units 1 & 2, Jan-Dec 1987." W/880324 ltr. BARTALLJ., BAUERIS,E.I., GAVRILAS,M. Baltimore Gas & Electric Co. 87/12/31. 76pp. 45017:089-45017:164.
- 8804010226 Forwards updated Tables 1C,2A & 2B of "Semiannual Effuent Release Rept for Second Half 1987" & revised Table 3A for First Half 1986 Update includes strontium results for fourth quarter for gaseous & liquid effuent releases. TIERNAN_JA. Baltimore Gas & Ejectino Co. 88/03/25. Document Control Branch (Document Control Desk). 2pp. 45033:144-45033:161.
- --8804010229 Revised Tables 1C,2A & 2B of "Semiannual Effluent Release Rept for Second Halt 1987,"
 * Baltimore Gas & Electric Co. 87/12/91, 5pp, 45033;146-45033;150.
- -8804010230 Revised Table 3A of "Semiannual Effluent Release Rept for First Half 1986."

 Ballimore Gas & Electric Co. 88/08/30, 1p. 48033;151-45033;151.

- 8804060520 Provides SPDS progress rept for First Quarter 1988 providing progress in establishing fully operational SPDS status of software development & testing & identification of critical path item Unit 1 SPDS will be operational by 880701. TIERNANJ.A. Balt more Gas & Electric Co. 88/03/31. Document Control Branch (Document Control Desk) 3pp. 45034.073-45034:075.
- 8804180336 Forwards monthly operating repts for Mar 1988 & revised operating status & unit shutdowns & power reductions for Unit 2 for Feb 1988 LEMONS,J.R. Baltimore Gas & Electric Co. 88/04/13. Document Control Branch (Document Control Dask). 1p. 45196;223-45196;235.
- --8804180338 Monthly operating repls for Mar 1988.
 BEHNKE.C. Baltimoro Gas & Electric Co. 88/03/31, 10pp. 45196:224-45196:233.
- --8804180343 Revised monthly operating rept for Feb 1988. BEHNKE,C. Baltimore Gas & Electric Co. 88/02/29. 2pp. 45196:234-45196.235.

S. Reportable occurrences, LERs & related correspondence

8804080168 LER 85:003:01:on 850405,7 of 16 main steam valves found to be out of tolerance.Caused by measurement technique & room equilibrium temp Main steam safety valves resol prior to completion of test.W/880405 ltr.
LUPOLD.T.R., LEMONS,J.R. Baltimore Gas & Electric Co. 88/02/15. 4pp. 45092.200-45092.200 45092:203.

V. Operator Examinations

- 8804250088 Responds to FOIA request for info re scores of reactor operators & senior reactor operators. Forwards requalification exam summary source sheets listed in encl app w/personal privacy info deleted.
 GRIMSLEY.D.H. Division of Rules & Rocords (Post 870413). 68/04/19. BOLEY,K. Public Clibzen's Critical Mass Energy Project. 2pp. 45213:003.45213:095.
- --8804250167 Package of NRC administered requalification exam results summary.
 NRC No Detailed Affiliation Given. 87/07/20, 88pp. 45213:007-45213.095.

DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8804070154 Revised emergency response plan implementing procedures, including Change 7 to Rev 11 to Attachment 2 of ERPIP 4.1.6, "Airborno Activity" & Change 13 to Rev 9 to Attachment 4 to ERPIP 4.1.7, "Alborno Activity".

 * Baltimore Gas & Electric Co. 88/03/18, 12pp. 45029:316-45029:327.
- 8804130209 Forwards Safety Insp Repts 50 317/88-04 & 50 318/88-05 on 880211-12 & notice of violation CONGEL.F.J. Region 1, Otc of the Director. 88/03/24. TIERNAN,J.A. Baltimore Gas & Electric Co. 3pp. 45151:259-45151:268.
- ---8804130211 Notice of violation from insp on 880211-12 Violation noted: failure to notify & recall emergency response personnel & activate emergency response facilities after ALERT declared. CONGEL,F.J. Region 1, Ofc of the Director, 88/03/24, 1p. 45151:262-45151:262
- -8804130216 Insp Repts 50:317/88:04 & 50:318/88:05 on 880211-12. Violations noted Major areas inspected classification, reporting & response to ALERT declared CONKLIN,C. Region 1, Oic of the Director, 88/03/14, 4pp. 45151:263-45151:268.
- 8804070259 Advises that 871005 & 880202 & 09 Revs 6,7 & 7-amended to safeguards contingency plan consistent w/provisions of 10CFR50.54(p) & acceptable. BELLAMY,R.R. Region 1, Ofc of the Director. 88/03/29. COSS,H.D. Baltimore Gas & Electric Co. 3pp. 45075:211-45075:213.
- 8804200034 Rev 12, Change 16 to Emergency Plan Implementing Procedure ERPIP 3.0,
- * Baltimore Gas & Electric Co. 88/03/30, 14PP, 45219:055-45219:068.
- 8804150093 Advises that emergency planning zone reduction requests shall remain on plant active docket the but no further review efforts until notice given to NRC to reactivate review. VARGA,S.A. Division of Reactor Projects 1/II (Post 870411). 88/04/11.
 - VARIGA,S.A. Division of Reactor Projects 1/II (Post 870411). 88/04/11. TIERNAN,J.A. Baltimore Gas & Electric Co. 3pp. 45134:020-45134:022.
- 8804200018 Revised emergency plan implementing procedures.including Change 12 to Rev 10 to Attachment 2 of EPRIP 4.1.3, "Technical Support Ctr Roster."

 * Baltimore Gas & Electric Co. 88/04/11, 7pp. 46218:215-45218:221.
- 8804200021 Revised emergency plan Implementing procedures,including Rev 9 to Change 3 to ERPIP 4.4.4, "Input Determining Atmospheric Stability Class & Meteorology" & Rev 9 to Change 2 to ERPIP 4.4.9, Baltimore Gas & Electric Co. 88/04/11. 10pp. 45226:271-45226:279.

I. Financial Information

8604070222 Forwards annual rept for 1987. RINGSDORF, J.E. Battimore Gas & Electric Co. 88/03/31. Document Control Branch (Occument Control Desk). 1p. 45030.048-45030:104.

K. Utility Final Safety Analysis Report (FSAR) & amends

8804050271 Rev 7 to updated FSAR for Calvert Chilis Nuclear Power Plant Units 1 & TIERNAN,J.A. Baltimore Gas & Electric Co. 68/03/31, 61pp. 45020:331-45021:032.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8804140216 Submits summary of actions discussed at ACRS 335th meeting on 880310-12 in Washington,DC,including ACRS repts/ recommendations,other actions,agreements,assignments & requests & future agenda. KERR,W. ACRS - Advisory Committee on Reactor Safeguards 88/03/24. ZECH,L.W. Commissioners. 4pp. 45118:172-45118:175.

P. Operating license stage documents & correspondence

- 8803250284 Requests withdrawal of portion of 880212 application for amend on Cyclo 10 reload re Page 3/4 1-1 of Tech Spec 3.1.1.1.except ref to Figure 3.1-1b. MIHALCIK.J.A. Baltimore Gas & Electric Co. 88/03/21. Document Control Branch (Document Control Desk). 5pp. 44945:228-44945:230.
- 8803240426 Generic Ltr 88-06 to all power reactor ficonsees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIA.F.J. Associate Director for Projects (Post 87041): 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153
- 6803310247 Requests relief from ASME Code Section XI requirement determined impractical & permission to defer hydrostatic pressure test. Reliaf requested immediately to avoid Unit 2 start-up delay Fae paid.

 TIEHNAN, J.A. Baltimore Gas & Electric Co. 88/03/28. Document Control Branch (Document Control Dosk). 5pp. 44986-001-44996-005.
- 8804120336 Forwards Rev 15 to "QA Policy for Calvert Cliffs Nuclear Power Plant," per 870316 telcon. ANUJE, A.B. Baltimore Gas & Electric Co. 88/03/28. EAPEN,P.K. Region 1, Otc of the Director, 10pp, 45132:043-45132:109.
- --8804120339 Rev 15 to "OA Policy for Calvert Cliffs Nuclear Power Plant." LUNDVALL, A.E., TIERNAN, J.A., COSS, H.D. Baltimore Gas & Electric Co. 88/02/10. 57pp. 45132:053-45132:109.
- 8804060492 Forwards addit requests for relief from ASME Section XI pump & valve test program as suppl to 870210 submittal. Justification for removal of various valves & testing requirements from inservice test program also encl.
 TIERNAN,JA. Batifimore Gas & Electric Co. 88/03/30. Document Control Branch (Document Control Desk). 10pp. 45047:157-45047:166.
- 8804110108 Responds to Generic Lir 88-03 re resolution of Generic Safety Issue 93, "Steam Binding of Auxiliary Feedwater Pumps." Util maintains procedures for recognizing steam binding & restoring feedwater sys to operable status. TIERNANJA. Baltimore Gas & Electric Co. 88/03/31. Document Control Branch (Document Control Dask). 2pp. 45064:360-45084:361.
- 8804130134 Forwards proprietary & nonproprietary replacement pages to rept submitted by 871002 ftr re control element assembly ctr finger cracking Replacement pages due to changes to proprietary classifications. Proprietary pages withheld. LIPPOLD,W.J. Baltimore Gas & Electric Co. 88/04/06. Document Control Branch (Dacument Control Desk). 13pp. 45099:329-45099.341.
- 8804080088 Generic Ltr 88-07 to power reactor icensees & applicants re-modified en-forcement policy concerning 10CFR50,49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184:237-45184:285.
- 8804140534 Confirms Interim approval of relief from requirements of Section XI,Articles IWA-4400 & IWA-4400 of 1983 Edition W/ Addenda through Summer 1983 of ASME Code that portion of mein steam plping be hydrostatically pressure tested. CAPPA, Ph. Project Directorate 1-1, 88/04/11, TIERNAN, J.A. Baltimore Gas & Electric Co. 3pp. 46130:209-45130:211.
- 8804160093 Advises that emergency planning zone reduction requests shall remain on plant active docket file,but no further review efforts until notice given to NRC to reactivate review.

 VARGA.S.A. Division of Reactor Projects - 1/II (Post 870411). 88/04/11.

 TIERNAN,J.A. Baltimore Gas & Electric Co. 3pp. 45134:020-45134:022.
- 8804220283 Withdraws request for additinto re util responses to Items 4.2.3 & 4.2.4 Generic Ltr. 83-28, "Required Actions Based on Generic Implications of Salem ATWS Events."
- EXPINS.
 MCNEIL,S.A. Project Directorate I-1, 88/04/19 TIERNAN,J.A. Baltimore Gas & Electric Co. 2pp. 45201:171-45201:172.
- 8804280034 Requests response to questions provided in 871113 request for addit into re-proposed inservice test program for safety- related pumps & valves within 70 days of fit date,per 880218 & 19 meeting. Trip rept for pump & valve enct. MCNEIL, SA. Project Directorate 1. 88/04/19. TIERNAN, J.A. Baltimore Gas & Electric Co. 2pp. 45266:188-45266:216.
- --8804280052 Trip rept of 880218-19 working meeting w/NRC,util & EG&G Idaho re pump & valve inservice testing program.

 ROCKHOLD.H.C., HEMMING.W.C. EG&G. Idaho, Inc. (subs. of EG&G. Inc.).

 ROCKHOLD.H.C. Idaho, National Engineering Laboratory. 88/03/28. DEMPSEY,K.

 NRC - No Detailed Attiliation Given. 27pp. 45266:190-45266:216.
- 8804290090 Notification of 880502 meeting w/util & Bechtel in Rockville,MD to discuss util 880406 request for ASME Code relief for up to 151 rolled & safety valves which setpoints may be high out-of-spec by up to 70 pst. MCNELL,S.A. Project Directorate I-1, 88/04/22, CAPRA,R.A. Project Directorate I-1, 3pp. 45322:344-45322:346.

Q. Inspection reports, IE Bulletins & correspondence

8804120453 Notification of Significant Licensee Meeting 88-023,Rev 1 In King of Prussia.PA on 880218 to discuss licensee SSFI Insp.
TRIPP.LE. Region 1, Oto of the Director. 88/02/18. Region 1, Oto of the Director. 2pp. 45091:147-45091:148.

- 8804130209 Forwards Safety Insp Repts 50:317/88 04 & 50:318/88 05 on 880211-12
- & notice of violation.
 CONGEL,F.J. Region 1, Ofc of the Director. 88/03/24, TIERNAN,J.A. Baltimore Gas & Electric Co. 3pp. 45151;259-45151;266.
- -8604130211 Notice of violation from insp on 860211-12-Violation noted: failure to notify & recall emergency response personnel & activate emergency response facilities after ALERT declared. CONGEL,F.J. Region 1, Ofc of the Director, 88/03/24, 1p. 45151:262-45151:262
- --8804130215 Insp Repts 50-317/68-94 & 50-318/68-95 on 850211-12. Violations noted Major areas inspected classification, reporting & response to ALERT declared on 880201 AZARUS,W.J. Region 1, Ofc of the Director 68/03/14. 4pp 45151 263 45151 266
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors." Svc I'st encl. ROSSI, C.E. Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44895-126-44995-246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees:Lack of Mgt Controls Over Li-censed Programs." Svc 19t enct. CUNNINGHAM, R.E. Division of Industriel & Medical Nuclear Safety (Post 870729), 88/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353.
- 8804080481 Responds to NRC Info Notice 88-005 re fire in annunciator control cablinets Statement re inadequate oxygen in tire area inaccurate Nausea fell by Individual discharging fixe extinguisher but not by other persons in area TIERNANJA. Beltimore Gas & Electric Co. 88/03/31. Document Control Branch (Document Control Desk). 2pp. 45047;167-45947:168.
- 8804130325 Requests relief from testing requirements in ASME Boller & Pressure Vessel Code Section XI for inservice insp Class 2 & 3 valves w/exception of main steam sately valves Relief requested correct seleptinis venified & established Fee paid LEMONS,J.R. Baltimore Gas & Efectic Co. 88704708. Document Control Branch (Document Control Desk), 4pp. 45137:324-45137:327.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Cir &/or Switchboard Function Due to Faulty Tie Bolts." Svc list encl. ROSSI.C E Division of Operational Events Assessment (Post 870411). 88/04/07. Cansolidated Edison Co. of New York, Inc. 124pp. 45406-292-45407.051.
- 8804060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl. ROSSICE. Division of Operational Events Assessment (Post 870411). 88/04/12. Consordated Edison Co. of New York, Inc. 123pp. 45185.028.45185.165.
- 8804200119 Forwards Safety Insp Repts 50-317/88-03 & 50-318/88-03 on 880229 0304.No violations nated.
 BELLAMY.R.R. Region 1, Ofc of the Director. 88/04/13. TIERNAN,J.A. Baltimore Gas. & Electric Co. 2pp. 45220:335-45220:342.
- --8804200127 Insp Repts 50:317/88-03 & 50:317/88-03 on 880229-0304 No violations noted Major areas inspected nonradiological chemistry program,including analytical procedure evaluations & measurement control. ZfBULSKY,H. PASCIAK,W.J. Region 1, Otc of the Director. 88/04/11. 6pp. 45220:337-45220:342.
- 8804220093 Responds to violations noted in Insp Repts 50:317/88-01 & 50:318/88-01-Couractive actions:attention being given to loose carls & other mails in switchgear rooms & cable spreading rooms.
 TIERNAN,J.A. Baltimore Gas & Efectric Co. 88/04/18. Document Control Branch (Document Control Desk). 3pp. 45220:028-45220:030.
- 8804290113 Discusses util 870909 response to NRC Bulletin 87-001, "Thinning of Pipe Walls at Nuclear Power Plants." Info being used to obtain data on observed pipe wall thinning & no further plant-specific action required.

 MCNEIL, S.A. Project Directorate I-1, 88/04/25. TIERNAN, J.A. Baltimore Gas & Electric Co. 3pp. 45322:222-45322:224.

- 8804040038 "Radiological Environ Monitoring Program Annual Rept for Calvart Cliffs Nuclear Power Plant Units 1 & 2, Jan-Dec 1987," W/880324 ltr. BARTAL.L.J., BAUEREIS.E.I., GAVRILAS,M. Baltimore Gas & Electric Co. 87/12/31, 76pp. 45017:089-45017:184.
- 8804010225 Forwards updated Tables 1C,2A & 28 of "Semiannual Effluent Releasa Ropt for Second Half 1987" & revised Table 3A for First Helf 1986. Update includes strontium results for fourth quarter for gaseous & liquid effluent releases. TIERNANJ.A. Ballimore Gas & Electric Co. 88/03/25. Document Control Branch (Document Cantrol Desk). 2pp. 45033:144-45033:151.
- -8804010229 Revised Tables 1C,2A & 2B of "Semiannual Effluent Release Rept for Second Haif 1987 Ballimore Gas & Electric Co. 87/12/31. 5pp. 45033:146-45033:150.
- -- 8804010230 Revised Table 3A of "Semiannual Effluent Release Rept for First Half 1986.**

 * Baltimore Gas & Electric Co. 86/06/30. 1p. 45033:151-45033:151.
- 8804080520 Provides SPDS progress rept for First Quarter 1988,providing progress in establishing fully operational SPDS, status of software development & testing & Identification of critical path identification of critical path identification of the provided by the state of the provided by the provide
- 8804180336 Forwards monthly operating repts for Mar 1988 & revised operating status & unit shutdowns & power reductions for Unit 2 for Feb 1988. LEMONS,J.P. Battimore Gas & Electric Co 86/04/13. Document Control Branch (Document Control Desk). 1p. 45196:223-45196:235.
- --8804180338 Monthly operating repts for Mar 1988. BEHNKE,C. Baltimore Gas & Electric Co. 88/03/31, 10pp. 45198:224-45196:233.
- -8804180343 Revised monthly operating rept for Feb 1988. BEHNKE,C. Baltimore Gas & Electric Co. 88/02/29, 2pp. 46196:234-45196:235.

- S. Reportable occurrences, LERs & related correspondence
- 8804200389 LER 88-002-02 on 880122,reactor tripped due to reduced feedwater flow due to loss of power to instrument bus 2Y10. Caused by personnel error. Event reviewed w/att electricians. Mig electrical prints clantical W/880415 II. BAUCR.E.R., LEMONS.I.R. Baltimore Gas & Electric Co. 88/04/15. 6pp 45216.049. 45216.054.
- 8804200392 LER 87-009-01:on 871221, reactor tripped due to loss of load signal Caused by failure of main generator permanent magnet generator due to misaligned stator trame. Turbine generator maint procedure upgraded W/880415 ltr. FURIO, P., LEMONS, J.R. Baltimore Gas & Electric Co. 88/04/15 4pp. 45239-119-45239-122.
- 8804220184 LER 88-003-00:on 880317,steam generator isolation check valve felled Caused by normal wear of hinge pins & bushing area in conjunction w/steam eroslon/cutting of disk seating surface Valve replaced W/880415 III 45257:213.

V. Operator Examinations

- 8804250088 Responds to FOIA request for infoire scores of reactor operators & senior reactor operators. Forwards requalification exam summary source shorts listed in encl app w/personal privacy into deleted GRIMSLEV.D.H. Division of Rules & Records (Post 8704.13), 88/04/19 BOLEY, K. Public Citizen's Critical Mass Energy Project. 2pp. 45213.003.45213.095.
- --8804250167 Package of NRC administered regularities at me results summary NRC No Detailed Attribution Given, 87/07/20, 88pp. 45213:007-45213:095.

DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8804140347 Rev 1 to Emergency Pien Implementing Procedure 6415-ADM-1300.01, "Mainteining Emergency Preparedness." BROWN,N.H., MARSHALL,W.J. General Public Utilities Corp. - GPU Servico Corp. 88/ 04/12, 38pp. 45167:114-45167:151.

G. Adjudicatory correspondence

- 8804050111 Forwards 880311 memorandum from Chlef Administrative Judge 8P Cotter Compliance w/Instructions contained in memorandum requested Served on 880331
 - WOLFE, S.L. Atomic Safety and Licensing Board Panel. #288 5983. 88/03/30. Atomic Safety and Licensing Board Panel. 2pp. 44966:142-44966:143.
- 8804060060 Answers to SVA/TMI Alert second set of interrogatories to util.* Submits responses to SVA/TMI Alert 880315 interrogatories.W/Certificate of Svc.Related correspondence.
- * General Public Utilities Corp. GPU Service Corp. #288 6007, 88/03/30. Three Mile Island Alert. 21pp. 44983.054-44983.074.
- 8804110187 Susquehanna Valley Alliance & TMI Alert motion to request that presiding judge order GPU Nuclear to provide addI Info & clarify Intentions to Install test & conduct experiments w/evaporator prior to hearings.*

 SKOLNICK,F. Susquehanna Valley Alliance, Lancaster, PA. SKOLNICK,F. Three Mile Island Alert. #288 6026. 68/03/30. Atomic Safety and Licensing Board Panel. 5PP. 46051:296-45051:308.

- --9804110188 Suppl to Susquehanna Valley Alliance & TMI Alert responses to licensee interrogatories & request for documents.*

 'Susquehanna Valley Alliance, Lancaster, PA. 'Three Mile Island Alert. 88/03/30. General Public Utilities Corp. GPU Service Corp. 3pp. 45051:301-45051:303.
- --8804110190 Susquehanna Valley Alliance/TMI Alert supplemental responses to NRC Interrogatories. *Certificate of Svc encl.
 * Susquehanna Valley Alliance, Lancaster, PA. * Three Mile Island Alert. 88/03/30.
 Office of the General Counsel. 5pp. 46051:304-45051:308.
- 8804080117 Licensee answer to Intervenors motion to compet discovery. Motion should be deried on basis that licensee responded fully to discovery request Certificate of Sec enct.

 BAXTER.T.A. General Public Utilities Corp. GPU Service Corp. BAXTER.T.A. Shaw, Pittman, Potts & Trowbridge. #288 6006. 88/04/01. Atomic Safety and Licensing Board Panel. Spp. 44883:143-44983:147.
- 8804110059 Susquehanna Valley Alliance & Three Mille Island Alert motion to compet GPU Nuclear to present documents for discovery. W/Certificate of Svc. SKOLNICK,F. Three Mile Island Alert. SKOLNICK,F. Susquehanna Valley Alliance, Lancaster, PA. #288 6025, 88/04/01. General Public Utilities Corp. GPU Service Corp. 4pp. 45050:088-45050:091.
- 8804110032 NRC Staff response to supplemental interrogatories from TMI Alortt/Sus-quehanna Valley Atliance.* Related correspondence. WOODHEAD,C.P. Assistant General Counsel for Hearings. #286 6024. 88/04/04. Three Mile Island Alert. 5pp. 45049:277-45049:286.
- -8804110039 Attidavit of LF Munson.* Author prepared answers to Interrogatories 1- Related correspondence.
 MUNSON, L.F. Battelle Memorial Institute, Pacific Northwest Laboratories. 88/03/31 1p. 45049.282-45049.282.
- --8804110042 Affidavit of WD Travers.* Author prepared answer to supplemental Interregatory 8. Related correspondence.
 TRAVERS,W.D. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/04, 1p. 45049:283-45049:283.

- --8804110049 Affidavit of MT Masnik.* Author prepared response to supplemental interrogatory 7.W/Certricate of Svc.Related correspondence.
 MASNIK,M.T. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/ 04. 3pp. 45049 284-45049 286.
- 8804110177 Memorandum & order (granting Joint Intervenors motion to compel). Li-censee production of any pertinent portions of any contract w/sys vendor re Tech Specs for disposal of accident-generated water ordered Served on 880407. WOLFE,S J. Atomic Safety and Licensing Board Panel #288 6027, 88/04/06. Gener-el Public Utilities Corp. GPU Service Corp. 4pp. 45050:092-45050.095.
- 8804180018 Licensee answer to intervenor motion for order on production of into on disposal sys installation & testing.* Intervenor 880330 motion should be denied due to insufficient legal basis.W/Certificate of Svc.
 BAXTER,T.A. General Public Utilities Corp. GPU Service Corp. BAXTER,T.A. Shaw, Pittman, Potts & Trowbridge. #288 6058. 88/04/07. Atomic Safety and Licensing Board Panel. 10pp. 45128.029-45128.038.
- 8804200055 Forwards pertinent contract provisions incorporating procurement Tech Specs & procurement document for disposal of accident-generated water.Into is commercial & does not represent regulatory requirements or license conditions.

 BAXTER,T.A. General Public Utilities Corp. GPU Service Corp. BAXTER,T.A. Shaw, Pittman, Potts & Trowbridge. #288 6077. 88/04/13 SKOLNICK,F. Affiliation Not Assigned. 60pp. 45160:175-45160.234.
- 8804200035 Memorandum & order (denying in part Susquehanna Valley Alliance/TMI Alert molion served on 880330;scheduling summary disposition).* Served on 880415. WOLFE,SJ. Atomic Safety and Licensing Board Panel. #288 6076. 88/04/15. Environmental Coalition on Nuclear Power. Spp. 45162:114-46162:118.
- 8804260062 Requests time on agenda of next prehearing conference re disposal of ac-cident-generated water at TMI-2 so that author can make oral statement. Served on 880420.
 - COOLE, M.A. Allillation Not Assigned #288 6106, 88/04/20. Office of the Secretary of the Commission, 1p. 45210:135-45210:135.
- 88042900 15 Order (directing licensee compliance).* Licensee wasted ASLBP in seeking to elude obvious thrust & sense of 880128 & 0401 orders & 880105 memorandum & order. Design specs must be made available by licensee. Served on 880426. WOLFE, SJ. A tomic Safety and Licensing Board Panel. #288 6153. 88/04/26. 3pp. 45255 225-45255:227.

J. Insurance & Indemnity Information

8804070065 Forwards Endorsements 1 & 2 to MAELU Certificate MW-46 & NELIA Cer-

HOFFMAN, J. Marsh & McLennan, Inc. 88/03/30, DINITZ,I. Office of Nuclear Reactor Regulation, Director (Post 870411), 21pp. 45079:232-45079:252.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88-06 to all power reactor licensees & epplicants re removal of organization charts from Tech Spec administrative control requirements. Svc list encl. MIRAGLIA.F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804130379 Forwards "Radiation Monitoring Sys for Nuclear Power Plants (W/Special Rel to TM) Nuclear Power Statlon)." BERGERJ, TMI Public Health Fund. 88/03/22, ZECH,L. Commissioners. 1p. 45103:228-45104:033.
- --8804130382 "Radiation Monitoring Sys for Nuclear Power Plants (W/Special Ref to TMI Nuclear Power Station)." BERGER,J. TMI Public Health Fund 87/12/31, 153pp. 45103:229-45104:033.
- 8804010220 Staff requirements memo re 870317 briefing of Commission in Washington,DC by GPU & GPUN on cleanup program of TMI 2.No requirements placed on staff. CHILK,S.J. Office of the Secretary of the Commission. 88/03/23. Office of the Secretary of the Commission. 1p. 44919:336-44919.336.
- 8803310197 Forwards Rev 18 to utili organization plan for review & approval Description of revised functional responsibilities listed Proposed reorganization does not change Tech Spec but enhances facility operations. Fee paid.
 STANDERFER,F.R. General Public Utilities Corp. - GPU Service Corp. 88/03/24. Document Control Branch (Document Control Desk). 4pp. 44984:348-44984:351.
- 8803310006 Notifies of plans to use core bore machine for diamentling lower core support assembly.
 STANDERFER, F.R. General Public Utilities Corp. - GPU Service Corp. 88/03/25. Document Control Branch (Document Control Desk). 2pp. 44983:256-44983:266
- 8804060069 Forwards Rev 6 to 4360-3256-85-1, "Canister Handling & Preparation for Shipment," reflecting detetion of restriction requiring use of borated water to spray deteiling canisters during transfer from Fuel Pool A. 3TANDERFER,F.R. General Public Utilities Corp. GPU Service Corp. 88/03/29, Document Control Branch (Document Control Desk). 1p. 45007:280-45007:293.
- -8804060071 Rev 6 to "Canister Handling & Preparation for Shipment."
 * General Public Utilities Corp. GPU Service Corp. 4350-3256-85-1 R08. 88/03/23. 13pp. 45007:281-45007:293.
- 8804150078 Notification of contract execution, Mod 1,to "Test Specimens From Damaged TMI-2 Reactor Bottom Head." Contractor: MTR Assoc, Inc. HAGEY, H. Contract Administration Branch. FIN D-2072. 88/03/31. HOUSTON, R.W. Diviston of Reactor Accident Analysis (Post 870413). VANHOUTEN, R. Office of Nuclear Regulatory Research, Director (Post 860720). 1p. 45134:015-45134:017.
- -8804150083 Mod 1,providing incremental funds,to "Test Specimens From Damaged TMI-2 Reactor Bottom Head."
 MPR Associates, inc. WIGGINS.E.J. Division of Contracts (Post 870413). FIN D-2072. 88/03/31. 2pp. 45134:016-46134:017.
- 8804110170 Forwards safety evaluation approving defueling of lower core support assembly,conlingent upon submittals of related procedures subj to Tech Spec 6.8.2. STOLZ_JF. Project Directorate 1-4. 88/04/01. STANDERFER,F.R. General Public Utili-ties Corp. GPU Service Corp. 2pp. 45078:189-45078:193.

- --8804110175 Safety evaluation supporting lower core support assembly defueling. NRC No Detailed Affiliation Given. 88/04/01, 3pp. 45078:191-45078:193.
- 8804080073 Forwards application for amend to License DPR-73 consisting of Change Request 59 revising Tech Spacs re surveillance terms & definitions STANDERFER,F.R. General Public Utilities Corp. GPU Service Corp. 88/04/04. Document Control Branch (Document Control Desk). 2pp. 45116.252-45116.265.
- --8804080077 Application for amend to License DPR-73,consisting of Tech Spec Change Request 59,revising Tech Specs re surveillance terms & definitions. STANDERFER,F.R. General Public Utilities Corp. GPU Service Corp. 88/04/04. 6pp. 45116:254-45116:259
- -8804080080 Proposed Tech Specs re surveillance terms & definitions to ensure consistent terminology throughout
 * General Public Utilities Corp. - GPU Service Corp. 88/04/04. 6pp. 45116.260-
- 45116 265
- 8804130241 Responds to 880316 submittal of schedule for major submittals to NRC re TMI-2 cleanup & request for monthly mgt meetings to review program status.Commission remains committed to carrying out oversight responsibilities at MIMOURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 887047-04. KINTNER,E.E. General Public Utilities Corp. GPU Service Corp. 4pp. 45102.346-45102.346
- 8904080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants" Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804200551 Responds to NRC 840507 ltr re status of auxiliary & fuel handling bldgs decontamination for First Quarter 1088, addressing areas where Tech Spec surveillances not performed due to ALARA considerations.

 STANDERFER,F. R. General Public Utilities Corp. GPU Service Corp. 88/04/14, Document Control Branch (Document Control Desk), 2pp. 45219 037-45219.038.
- 8804280348 PROGRAMMATIC ENVIRONMENTAL IMPACT STATEMENT RELATED TO DECONTAMINATION AND DISPOSAL OF RADIOACTIVE WASTES RESULTING FROM MARCH 28, 1979 ACCIDENT.THREE MILE ISLAND NUCLEAR STATION,UNIT 2.Dockel No. 50-320.(GPU Nuclear.Incorporated)

 **Office of Nuclear Reactor Regulation, Orector (Post 870411). NUREG-0683 SO3 DRFT. 88/04/30. 100pp. 45270.009-45270.212.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220298 NRC Info Notice 88:010, "Malls Licensees tack of Mgt Controls Over Li-censed Programs." Svc list enct. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 88/ 03/28. Consolidated Ed son Co. of New York, Inc. 108pp. 44995:247-44995:353
- 8804010268 NRC Into Notice 88-011, "Potential Loss of Mater Central Cit &/or Switch-board Function Due to Faulty Tie Bolls." Svc list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406.292-45407.051.
- 8804080370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Rearings" Svc let encl.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12.
 Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165.150.
- 8804210029 Advises that GE latching-type HFA relays discussed in NRC Bulletin 86-003,not used at TMI-2.No further action required STANDERFER,F.R. General Public Utilities Corp GPU Service Corp 88/04/13 Doc-ument Control Branch (Document Control Desk) 2pp 45235:207-45235:208.

R. Periodic operating reports & related correspondence

- 8803280079 Forwards "TMI Aquatic Study Monthly Progress Rept for Jan 1988."
 RESSLER,W.C. General Public Utilities Corp. GPU Service Corp. 88/03/01.
 MASNIK,M. NRC No Detailed Athibation Given. 1p. 44921:061-44921.062.
- --8803280080 "TMI Aquatic Study," Monthly Progress Rept for Jan 1988.
 NARDACCI,G.A. Radiation Management Corp. (RMC). 88/01/31. 1p. 44921:062-

DOCKET 50-321 EDWIN I. HATCH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8803300348 Forwards Insp Repts 50-321/87-32 & 50-368/87-32 on 871207-10 No violations or deviations noted Areas identified that require further review & followup including emergency preparedness program.

 STOHRJ.P. Region 2, Olic of the Director. 88/03/08. HEAD,G.F. Georgia Power Co. 3pp. 44921:216-44921:243
- --8603300354 Insp Repts 50:321/87-32 & 50:366/87-32 on 871207-10.No violations or deviations noted Major areas inspected review of selected procedures & representative records & emergency response facilities & related equipment. GOODENA, DECKEN, I.R. Region 2, Old of the Director. 88/02/19. 25pp 44921:219-44921:243.
- 8803300061 Forwards Insp Repts 60-321/88-05 & 50-366/88-05 on 880123- 0219 & notice of violation.
 BROWNLEE,V.L. Region 2, Ofc of the Director, 88/03/10. HEAD,G.F. Georgia Power
 Co. 2pp. 44961-238-44961:252.

- -8803300068 Insp. Repts 50-321/88-05 & 50-366/88-05 on 880123-0219. Violations noted Major areas inspected ticensee action on previous enforcement matters, maint observation operational safety ventication plant mods & ptysical security. HOLMES-RAY,P., MENNING,J.E., SINKULE,M.V. Rogion 2, Otc of the Director, 887 03/07, 11pp, 49861242-44961.252.
- 8804010214 Advises that most of 880101 ray to physical security plan consistent w/ provisions of 10CFR50.54(p) & acceptable Some changes require further clarification & not consistent w/ provisions of 10CFR50.54(p) Encl withheld (ref. 10CFR73.21). CLINE, WE. Region 2, Okc of the Director 88/03/23. HEAD,G.F. Georgia Power Co. 2pp. 44945.359.44945.350.
- 8804120022 Forwards Insp Rept 50-321/88 09 & 50-366/88-09 on 880229-0304 CLINE.W.E. Region 2, Otc of the Director, 88/03/29, HEAD.G.F. Georgia Power Co. 2pp 45128-230-45128 232.
- -8804120029 Partially withhe'd insp Repts 50:321/88:09 & 50:366/88:09 on 880229-0304 (ref. 10CFR2.790 & 73.21) Major areas inspected plan/procedures.repts/ records.testing/maint_barriors.detection aids & compensatory measures TOBIN,W., MCGUIRE,D.R. Region 2, Old of the Director, 88/03/24, 1p. 45128 232-45128 232
- 8804250019 Forwards Insp. Repts 50:321/89-07 & 50:366/88-07 on 880220-0325 & notice of inclation. The property of the Director B8/04/12 HEAD,G F. Georgia Power Co. 2pp. 45268:153 45268:169
- -8804250024 Insp. Repts 50-321/88-07 & 50-366/88-07 on 880220-0325 Violations noted Major areas Inspected ficensee action on previous enforcement matters, operational safety ventical on rad ological protection & physical security HOLMES RAY,P. MENNING J.E. SINKULE,M.V. Reg on 2, Oic of the Oirector. 887-04/11, 13pp. 45268-157-45268-169.
- 8804200473 Partial response to FOIA request relife protection Forwards App E documents App D & E documents evalable in PDR App F document completely withhold (relificial Examption 5).

 GRIMSLEY,D.H. Division of Ful'as & Records (Post 870413). 88/04/14. JONES,C.R. Afficiation Not Assigned 5pp. 45208 037-45208 043.
- -8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type insp for each facility to essess status of compliance w/ 10CFR50.48 Program Issted. CONLON,T.E. Region 2, Olic of the Director. 34/11/06. HERDT,A R. Region 2, Olic of the Director. 3pp. 45206.176.45206.178.

I. Financial Information

- 8904270175 Forwards 1987 annual financial repts for Georgia Power Co. & Southern Co. GUCWA,L.T. Georgia Power Co. 88/04/19. Decument Control Branch (Document Control Desk) 2pp 45260:109-45260.220.
- --8804270182 "Georgia Power Co. 1987 Annual Rept." SCHERER,R.W. Georgia Power Co. 87/12/31, 45pp, 45260:112-45260:156
- -8804270183 "Southern Co. 1987 Annual Rept." ADDISON,E.L. Southern Co. 87/12/31, 64pp. 45260:157-45260:220

J. Insurance & Indomnity Information

8804010283 Submits present levels & sources of Insurance for plants,per 10CFR50.54(w)(4).
GUCWA.L.T. Georgia Power Co. 88/03/18. Document Control Branch (Document Control Desk). 2pp. 45058.095.

P. Operating Ilcense stage documents & correspondence

- 8803100155 Forwards util 870203 internal memo re inconsistencies noted in NRC 870102 exemption approval ftr.Advisal as to correct staff position requested. RIVENBAFIK, G. NRC No Detailed Affiliation Given 87/02/10. NRC No Detailed Affiliation Given
- 8803240426 Generic Ltr 88:06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements. Svc list encl. MIRAGLIAF, J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44872:107-44872:153.
- 8804010194 Summary of 880318 meeting w/utils in Rockville,MD re Info that would be required in submittal of amends to licenses & CP held by utils Attendees list & viewgraphs enct. ADENSAM,E.G. Project Directorate II-1, 88/03/25, Project Directorate II-1, 25pp. 44920 082-44920 108
- 8804120043 Notification of 880510 meeting w/util in Rockville,MD to discuss application of selsmic mergins work Agenda encl.
 CROCKER,L.P. Project Directorate II-3. 88/04/05. Project Directorate II-3. 4pp.
- 8804140037 Provides results of 880329 audit of 10CFR50.58 reviews performed by li-censee in conjunction w/design change request & test or experiment requests com-pleted during CY87 Licensee reviews getting better & adoquate CROCKER.L.P. Project Directorate II-3. 88/04/08, LAINAS,G.C. Assistant Director for Region II Reactors. 21pp. 45120:333.45120:353.
- 8804080083 Generic Ltr 88-07 to power reactor l'censees & applicants re modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Efectrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list enc. MtRAGLIA,F. J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184:237-45184.285
- 8804150188 Discusses 880318 meeting w/util re proposal to form operating company to handle operation of subjiplants. Summary of meeting issued separately. NDENSAM,E.G. Project Directorate IF-1, 88/04/08, LONG,LB. Southern Company services, Inc. 19pp. 45141:185-45141:203.

- 8804210162 Confirms 880428 mgt meeting in Region If ofc to discuss plant performance Proposed agenda encl.

 GRACE_J N Region 2, Ofc of the Director 88/04/11, HEAD,G.F. Georgia Power Co.
 3pp 45194:172-45194:174.
- 8804290281 Summarizes 880419 mgt meeting in Region II ofc re findings communicated to util by INPO concerning results of evaluation conducted during wks of 880314 & 21.1st of attendees enct GRACE_IN. Region 2, Otc of the Director. 88/04/22 HEAD,G.F. Georgia Power Co 3pp. 45282.178 45282.180

- 8803300348 Forwards Insp Repts 50-321/87-32 & 50-366/87-32 on 871207-10.No violations or deviations noted Areas identified that require further review & followup in-cluding emergency preparedness program STOIR.J.P. Region 2, Otc of the Director. 88/03/08. HEAD,G.F. Georgia Power Co. 3pp. 44921.218
- -8803300354 Insp Repis 50:321/87-32 & 50-366/87-32 on 871207-10.No violations or deviations noted.Major areas inspected review of solected procedures & representative records & emergency response facilities & related equipment. GOODEN,A., DECKER,T R. Region 2, Ofc of the Director. 88/02/19. 25pp 44921:219-44921:243.
- 8803300081 Forwards Insp Repts 50-321/68-05 & 50-366/88-05 on 880123- 0219 & notice of violation. BROWNLEEV.L. Region 2, Ofc of the Director. 88/03/10. HEAD,G.F. Georgia Power Co. 2pp. 44961-238-44961.252.
- -8803300064 Notice of violation from insp on 880123-0219 Violations noted on 880209 plant operated w/only one APRM channel & in Oct of 1987 vacuum Breakers 1748-342C,E & F failed to test properly due to inadequate maint work order instruc-
- BROWNLEE, V.L. Region 2, Old of the Director, 88/03/10, 2pp. 44981:240-44961:241.
- -8803300068 Insp Repts 50-321/88-05 & 50-366/88-05 on 880123-0219. Violations noted Major areas inspected licensee action on previous enforcement malters, maint observation, operational safety verification, plant mods & physical security.

 HOLMES RAY, P., MENNING, E., SINKULE, M.V. Region 2, Ofc of the Director. 88/ 03/07. 11pp. 44961:242-44981 252.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Wostinghouse Reactors." Svc fist encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995.126-44995:246.
- 8803220296 NRC Into Notice 88-010, "Matts Licensees.Lack of Mgt Controls Over Licensod Programs: "Svc list and CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03728. Consolidated Edison Co. of New York, Inc. 108pp. 44905 247-44985 353.
- 8804050373 Forwards Exam Rept 50-321/OL-88-01 of exam administered on 880208-104050173 Forwards Exam Hept 50-321701-06-01 of exam administered on 800206-111 for Units 1 & 2. JULIAN,C A. Region 2, Otc of the Director. 88/03/29. HEAD,G F. Georgia Power Co. 2pp. 45081:154-45062:024.
- 8804070023 Responds to NRC 880310 ltr re violations noted in Insp Repts 50-321/88-05 & 50-366/88-05 Corrective actions:event review team formed,caulion tags placed on intermediate-range monitors & procodures revised.

 GUCWALT. Georgia Power Co. 88/03/29. Document Control Branch (Document Control Desk). 9pp. 45029:352-45029:360.
- 8804120022 Forwards Insp Rept 50-321/88-09 & 50-366/88-09 on 880229-0304. CUNE.W.E. Region 2, Old of the Director. 88/03/29. HEAD.G.F. Goorgia Power Co. 2pp. 45128-230-45128-232.
- -8804120029 Partially withheld Insp. Repts 50-321/88-08 & 50-366/88-09 on 880228-0304 (ref. 10CFR2.790 & 73.21).Major areas inspected plan/procedures,repts/records,testing/maint, barriers,detection alds & compensatory measures. TOBINW, MCGUIRE,D.R. Region 2, Ofc of the Director. 88/03/24, 1p. 45128-232-45128-232.
- 8804050377 Forwards Insp Repts 50-321/88-03 & 50-366/88-03 on 880201-05.No vio-lations of deviations noted HERDT,A.R. Region 2, Ofc of the Director, 88/03/31, HEAD,G.F. Georgia Power Co. 2pp. 46034-053-45034:064.
- -8804050385 Insp Repts 50-321/88-03 & 50-366/88-03 on 880201-05 No violations noted.Major areas inspected.selsmic analysis for as-built safety-related piping sys & Mark I containment long-term program mod. CHOU.R.C., BLAKE,R.P., CARRION,R.P. Region 2, Otc of the Director. 88/03/23. 10pp. 45034:055
- 8804120050 Forwards Insp Repts 50:321/88:08 & 50:366/88:08 on 880307-11.No vio-lations or deviations noted. HERDIT.A.R. Rogion 2, Ofc of the Director, 88/04/04, HEAD,G.F. Georgia Power Co. 2pp. 45132:166-45132:175.
- --8604120054 Insp Repts 60-321/88-08 & 50-366/88-08 on 880307-11.No violations or deviations noted Major areas inspected areas of complex surveillance testing & IE bulletin followup.

 TINGEN,S.G., JAPE,F. Region 2, Ofc of the Director. 86/04/01. 8pp. 45132:168-
- 8804120096 Forwards request for addl into re util responses to IE Bulletin 85-003, "Motor-Operated Valve Common Mode Fallures During Plant Transients Due to Improper Switch Settings." Into requested within 30 days of itr
- 8804010256 NRC Info Notice 88:011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Botts." Svc list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408:292-45407.051.

- 8804130275 Responds to NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakers." No Westinghouse Models DS-206,DSt-206, DS-416,DSt-416 or DS-420 breakers in Class IE circuits at Hatch.
 GUCWALL T. Georgia Power Co. 88/04/07. Document Control Branch (Document Control Desk) 5pp. 45154-065-45154-069
- 8804190021 Discusses SALP Ropts 50-321/86-42 & 50-366/86-42 & forwards view-graphs from 870406 meeting.thi 870506 written comments have been reviewed Proposed Improvements will be monitored during future insp. GRACE_JN. Region 2, Ofc. of the Director. 88/04/11. HEAD,G.F. Georgia Power Co. 23pp. 45199-052-45199.074.
- 8804060370 NRC Info Notice 88-012, "Overgrossing of Electric Motor Bearings." Svc list enc! ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165.150
- 8804250019 Forwards Insp. Repts 50:321/88-07 & 50:366/86-07 on 880220-0325 & notice of violation.

 BROWNLEE,V.L. Region 2, Olc of the Director, 88/04/12, HEAD,G.F. Georgia Power Co. 2pp. 45268:163-45268:169.
- -8604250023 Notice of violation from insp on 880220-0325 Violations noted failure to perform functional test of APRM flow ref thermal power & APRM downsca's trips & failure to follow Surveillance Procedures 578-VSU-070-22
- --8804250024 Insp Repts 50-321/88-07 & 50-386/88-07 on 880220-0325 Violations noted Major areas Inspected ficensee action on previous enforcement maters, operational safety ventication, rad ological protection & physical security. HOLMES-RAY,P., MENNING.J.E., SINKULE,M.V. Region 2, Ofc of the Director. 88/04/11. 13pp. 45268-157-45268-169.
- 8804200473 Partial response to FOIA request re fire protection Forwards App E documents.App D & E documents available in PDR.App F document completely withheld (ref FOIA Exemption 5).
 GRIMSLEY,D H. Division of Rules & Records (Post 870413). 88/04/14 JONES,C R Affiliation Not Assigned, 5pp. 45206.037-45208.043.
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type Insp for each facility to essess status of compliance w/ 10CFR50.49.Program listed.
 CONLON,T.E. Region 2, Ofc of the Director. 84/11/06. HERDT,A.R. Region 2, Ofc of the Director. 3pp. 45206.176.45208.178.
- 8804270244 Responds to NRC 880308 Itr re violations noted in Insp Ropts 50:321/87-32 & 50:366/87-32 Corrective actions primary dose assessment code purchased from vendor in mid 1980s GUCWA,L.T. Goorgia Power Co. 88/04/18. Document Control Branch (Document Control Desk). 8pp 45244:236-45244:243.

- 8804040044 "Annual Environ Surveillance Rept for 1987." W/880329 ltr. GUCWA,L T. Georgia Power Co. 87/12/31, 234pp. 45016 216-45017:088.
- 8804110024 "Augmented Radiological Surve llance Monitoring," for 1997. W/880331 ltr. GUCWA,L.T. Georgia Power Co. 87/12/31. Document Control Branch (Document Control Desk). 18pp. 45128:160-45128:177.
- 8804190116 Monthly operating repts for Mar 1988.W/880411 ltr.
 BEARD,R.M., GUCWA,L.T. Georgia Power Co. 88/03/31, 13pp 45209.160-45209.172

S. Reportable occurrences, LERs & related correspondence

- 8804040072 LER 88:003:00:on 880228,unanticipated actuation of reactor protection sys occurred due to turbine trip.Caused by ground relay spuriously activating.Electrical equipment association wygenerator excitation sys cleaned & tested W/980328 ltr. HEIDT,J.D., GUCWA,L.T. Georgia Power Co. 88/03/28, 14pp. 44971:234-44071:247.
- 8804190097 PNO-II-88-021:on 880404, licensee commenced controlled shutdown Caused by unidentified reactor coolant leakage approaching Tech Spec limit of 5 gallons/minute over 24 h. Licensee plans 7-day outage to correct situation. PATTERSON,C. Region 2, Oto of the Director. 88/04/05. 1p. 45209:159-45209.159.

V. Operator Examinations

- 8804050373 Forwards Exam Rept 50:321/OL-88:01 of exam administered on 880208-11 for Units 1 & 2. JULIAN,CA. Region 2, OIc of the Director. 88/03/29, HEAD,G.F. Georgia Power Co 2pp. 45061:154-45082:024.
- --8804050378 Exam Rept 50-321/QL-88-01 on 880208-11 for Units 1 & 2.Exam results:11 senior reactor operators & three reactor operators passed both written & operating exams.

 BROCKMAN,K.E., MUNRO,J.F. Region 2, Ofc of the Director. 88/03/29, 229pp. 45061:156-45062.024.
- 8804250088 Responds to FOIA request for info re scores of reactor operators & senior reactor operators. Forwards requalification exam summary source sheets listed in encl app w/personal privacy into deleted. GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 88/04/19 BOLEY,K. Public Citizen's Critical Mass Energy Project. 2pp. 45213:003-45213:005.
- --8804250167 Package of NRC administered requalification exam results summary. NRC No Detailed Affiliation Given. 87/07/20. 88pp. 45213.007-45213-095.

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

F. Security, medical, emergency & fire protection plans

- 8804050251 Ack roceipt of 880210 fir expressing concern about apparent lack of progress in licensing of plant due to stated policy of nonpart cipation in offsite omergency exercise by State of NY & local officials VARGA, SA Division of Reactor Projects 1/11 (Post 870411), 88/03/30, LESSARD,E. Affiliation Not Assigned, 5pp. 45029.092-45029.096
- 8804150243 Advises that 880125 Rev 16 to security plan consistent w/ provisions of 10CFR50.54(p) & acceptable. BELLAMY, R.R. Regron 1, Otc of the Director. 88/04/08 LEONARD, J.D. Long Island Lighting Co. 4pp. 45138-045-45138:048
- 6604190368 Forwards response to violations noted in Safety Insp Rept 50:322/87-22 Rosponse withheld (ref 10CFR73 21)
 LEONARD, J D. Long Island Lighting Co. 88/04/15. RUSSELL,W.T. Reg on 1, Ofc of the Director. 2pp. 45208.335-45208 336
- 8804260342 Advises that portions of 871207 Rev 3 to saleguards contingency plan inconsistent w/p:rovisions of 10CFR50.54(p) & unacceptable.Plan should be modified & resubmitted within 30 days of itr receipt W/o stated enct. BELLAMY,R R. Region 1, Otc of the Director. 88/04/15. LEONARD,J D. Long Island Lighting Co. 4pp. 45257:240-45257:243
- 880428081 Requests NRC participation in June 1988 teterally-graded oxercise Exercise will last 3 days 8 include demonstration of protective action doction-making & implementation for 10-mile prime exposure & 50-mile ingostion exposure pathway.

 LEONARD.J.D. Long Island Lighting Co. 89/84/20. Document Control Branch (Document Control Dosk). 2pp. 45261-326-45261:327

G. Adjudicatory correspondence

- 8804050029 Urgos expedicious & proper decision by NRC re licensing of facility Licensing would immediately abate energy crisis. Failure to licensia technique would mean considerable burden, sacrifice & possible necessary additioxpense for customers.

 MCFARLAND,J.T. New York, State of #288 5988, 88/03/23, ZECH,L W. Commissioners, 2pp. 44986,099-44968 100.
- 8804050031 Suffolk County supplemental answers to LILCO first set of interrogatorios & requests for production of documents re LILCO amergency broadcast sys.* Cert.:cate of Svc encl. Related corrospondence.

 MISSAL,M.J. Suffolk County, NY MISSAL,M.J. Kirkpatrick & Lockhart. #288 5980. 88/03/28. Long Island Lighting Co. 7pp. 44966.159.44066.165
- 8804050046 Forwards util completed verification form for responses & objections to Suffolk County third set of inforrogatories & requests for production of documents re emergency broadcast sys-lited 880325 Rolated correspondence LEUGERS.M.J. Long Island Lighting Co. LEUGERS.M.J. Hunton & Williams #286 5079. 88703/28. ZATINLEUTER,R.J. New York, State of. MILLER,M.S. Kirkpatrick & Lockhart. 2pp 44968.074-44966.075
- 8804050016 Advises that author will present oral argument on behalf of Sulfo's County State of NY & town of Sculhampton,per LILCO appeal of ASLB 871207 Partial Initial Decision LBP 87-32 Zahnleufer will also be present to answer quest.ons. LANPHER,L C. Sulfo's County, NY. LANPHER,LC. New York, State of LANPHER,L C. Southampton, NY. #288 5989 89/09/29. SHOEMAKER,C J. Atomic Safety and Licensing Appeal Panel. 1p. 44966:148-44966:148.
- 8804050024 NRC Staff response to govts motion for reconsideration of ruting as to compliance w/10CFR50.47(c)(1)(i) 8 (ii) * Util asked Board to dismiss legal authority contentions in compliance to new rule Confidete of Svc enc.! YOUNG,M.A. Assistant General Counsel for Hearings #288 6977, 88/03/30. Atomic Sefety and Licensing Board Panel 10pp. 44966:149-44966-158.
- 8804050037 Informs that NRC has reviowed county 880303 interrogatorios to & document requests for NRC & FEMA to legal authority/ reafism contentions & not contemplating calling witnesses for remand hearing on realism Related correspondence YOUNG M.A. Assistant General Counsel for Hearings. #288 5978 88/03/30 MILLER,M.S. Kirkpatrick & Lockhart. 1p. 44986:179-44966:179.
- 8804080066 Responses & objections to Sulfolk County first set of interrogatories & requests for production of documents re Contentions 1-2,4-8 & 10 to LILCO.* W/Certificate of Svc. Related correspondence. LEUGERS.M.J. Long Island Lighting Co. LEUGERS.M.J. Hunton & Williams, #288 6008. 86/03/30 Sulfolk County, NY. 10pp. 44983:108-44983.117.
- 8804050038 NRC Staff Frst set of Interrogatories to Sulfolic County,NY State & town of Southampton re Contentions 1-2.4-8 & 10.* Certificate of Svc and Related correspondence.
- spondence.
 YOUNG,M.A. Assistant General Counsel for Hearings. #288 5975. 88/03/31. Atomic Safety and Licensing Board Panel. 5pp. 44966:174-44866:178.
- 8804080081 LILCO brief on substantive relevance of remerting emergency planning contentions to LILCO motion to operate at 25% power.* Afridavit of EJ YoungFing encl.W/Certrilicate of Svc. ZEUGIN.L.B. Long Island Lighting Co. ZEUGIN.L.B. Hunton & Wirliams #288 6015. 88/04/01. Atomic Safety and Licensing Board Panel. 33pp. 44883-075-44983:107
- 8804060102 Govt brief in response to 880226 Board order.' Board must find that responsible assurance findings required by 10CFR50.57 cannot be made w/rospoct to LILCO 25% power request.W/Certificate of Svc.
 LANPHERI, C. Suffolk County, NY. LANHPERI, C. Kirkpatrick & Lockhart ZAINLEUTER, R. Naw York, State of #286.6014. 86/04/01. Atomic Safety and Licensing Board Panel. 49pp. 44983:148-44983:186.

- 880460219 LILCO designation of record & prima facia case on legal authority issues (Contentions 1-22,4-8,8-10).* LILCO laid out essential reassoning on Contentions 1-10,including main parts of supporting record W/Certificate of Svc. CHRISTMANJ.N. Long Island Lighting Co. CHRISTMANJ.N. Hunton & Williams. #288 6012, 88/04/01. Atomic Safety and Licensing Board Panel. 57pp. 44983:187-44983.243
- 8804060238 LILCO supplemental responses & objections to Suffolk County first set of interrogatories & requests for production of documents re Contentions 1-2,4-8,& 10 to LILCO * W/Certif.cate of Svc.Related correspondence. LEUGERS,M.J. Long Island Lighting Co. LEUGERS,M.J. Hunton & Williams. #288 8011. 88/04/01. Atomic Selety and Licensing Board Panel. 10pp. 44983.244-44983.253
- 8804110018 Advises that EJ Reis will present oral argument on 880428 re LILCO emer-
- gency plan exercise.
 REIS,E.J. Assistant General Counsel for Hearings. #288 6019. 88/04/04.
 SHOEMAKER,C.J. Atomic Safety and Licensing Appeal Panel. 1p. 45049.019-45049.019.
- 8804110025 LILCO motion to impose witness designation cut-off.* Moves that Board immediately rule that Suffolk County & State of NY designate witnesses on "best efforts" issue in hime for witnesses to be disposed by 880415 W/Certricate of Svc. CHRISTMAN.J.N. Long Island Lighting Co. CHRISTMAN.J.N. Hunton & Williams. #288 6017. 88/04/05. Atomic Safety and Licensing Board Panel. 5pp. 45049:249-45040.253
- 8804110027 Advises that author will represent LILCO in oral argument re utill appeal from ASLB 871207 Partial Initial Decision LBP-87-32.

 IRWIND.P. 4 tong Island Lighting Co. IRWIND.P. Hunton & Williams. #288 6020. 88/04/05. SHOEMAKER.C.J. Atomic Safety and Licensing Board Panel. 1p. 45049 257-
- 8804180057 Govt motion for extension of time to respond to realism discovery requests & to extend discovery schedule.* Urges prompt issuance of opinion ruling on util motion for summary disposition.W/Cgrifficate of Svc.
 MILLER M.S. Suffalk County, NY, MILLER.M.S. Kirkpatrick & Lockhart.
 PALOMINO.F.G. New York, State of #288 6044, 88/04/06. Atomic Safety and Licensing Board Panef. 16pp. 45127:286-45127:301.
- 8804180020 LILCO response to govt motion for extension of time to respond to realism discovery requests & to extend discovery schedule & request for add rehel.* Licensee opposes motion & requests addl relief.W/Certificate of Svc. CHRISTMAN J.N. Long Island Lighting Co. CHRISTMAN J.N. Hunton & Williams #288 6042, 88/04/07. Atomic Safety and Licensing Board Panel, 16pp. 45127:223-15137.20
- 8604180010 Memorandum (extension of Board ruling & opinion on LILCO summary disposition motions of legal authority realism contentions & guidiance to parties on new rule 10CFR50.347(cgl.1)). Served on 880411.

 GLEASONJ P., KLINEJ R., SHONF J. Atomic Safety and Licensing Board Panel. #288 6047. 88/04/08. 55pp. 45127:169.45127:222.
- 8804180042 Responds to LILCO response to govt motion for extension of time to respond to real sm discovery requests & to extend discovery schedule & request for addit relief Conference call not warranted. LANPHER.L.C. New York, State of LANPHER.L.C. Kirkpatrick & Lockhart. #288 6043. 88/04/08.QLEASON.J.P., KLINE,J.R., SHON,F.J. Atomic Safety and Licensing Board Panel. 3pp. 45127.244.45127.248.
- 8604180048 Notice of oral argument.* Oral argument on LILCO appeal of ASLB 871207 Partial Initial Decision LBP-87-32 will be heard on 680428 in Bethesda,MD.Served on 880411 SHOEMAKER, C.J. Atomic Safety and Licensing Appeal Panel. #288 6050, 88/04/08

1p 45127:249-45127:248.

- 8804200037 NAC Staff response to govt motion for extension of time to respond to re-alism discovery requests & to extend discovery schedule." Intervenors 880406 motion should be denied.W/ Certilicate of Svc. REIS,E.J., Assistant Genoral Counsel for Hearings. #288 8089 88/04/08. Atomic Safety and Licensing Board Panel. 8pp. 45161.063-45161:070.
- 8804180125 Suffolk County second set of interrogatories & requests for production of documents re Contentions 1-2.4-8 & 10 to LILCO.* W/Certricate of Svc Related cor-
- respondence.

 ROSS,R.R. Suffolk County, NY. ROSS,R.R. Kirkpatrick & Lockhart. #288 6041, 88/ 04/09 Atomic Safety and Licensing Board Panel. 7pp. 45127:161-45127:167.
- 8804180004 Confirmatory memorandum & order.* Witnesses must be designated in adequate time for discovery to be completed, per LILCO 880405 motion & extension of time for discovery period on realism issue granted Served on 880413. GLEASONJ.P. Atomic Safety and Licensing Board Panel. #288 6046. 88/04/12. Office of the General Counsel. 2pp. 45128.082-45128.083.
- 8804200047 Suffolk County fifth supplemental response to LILCO first set of Interrogatories & requests for production of documents re-role conflict of school bus drivers.* Certificate of Svc encil Related correspondence.

 TAYLOR,J.L. Suffolk County, NY. TAYLOR,J.L. Kirkpatrick & Lockharl. #288 6093.

 88/04/12. Long Island Lighting Co. 6pp. 45161.078-45161:089.
- 8804180041 Board memorandum & order (ruling on govt motion for reconsideration of Board memorandum & order on Section 50.47(c)(1)(ii)(i) compliance).* Intervenor motion denied. Served on 880414. GLEASON.J.P. Alonic Salaty and Licensing Board Panel. #288 6045, 88/04/13, 3pp.
- 8804200048 Gayts objection to partions of 880229 & 0408 orders in realism remand & offer of proof. Objects to portions of subj orders comparing preclusion of filling response to LILCO realism defense to legal authority contentions. LETSCHE,K.J., ZAHNLEUTER,R.J. New York, State of LETSCHE,K.J. Kirkpatrick & Lockhart. #288 6095. 88/04/13. Atomic Safety and Licensing Board Panel. 61pp. 45160:236:45161:055.

- -8804200994 Direct lest mony of D. Axeirott on behalf of State of NY. Testines that State of NY. In case of accident in facility, would not follow LILCO emergency plan because plan unworkable 8 inadequate W/Gertificate of Svc.

 AXELROD,D. New York, State of 88/04/13, 18pp. 45161-038-45161.055.
 - 880420067 Board memorandum & order (ruing on intervenors motion for reconsideration of Board memorandum & order on contention re LILCO emergency broadcast sys)* Intervenors 880307 motion denied Served on 880415. GLEASON.JP Atomic Safety and Licensing Board Panel. #288 6090. 88/04/14. Suffolk County, NY. 2pp. 45182-157-45162.158
 - 8804200202 Board memorandum & order (ruling on intervenors motion for reconsideration of Board order on symmany disposition of hosp evacuation issue).* Sulfalk County,State of NY & town of Southampton 880307 motion denied.Sorved on 880415. GLEASON, JP. Alomic Safety and Licensing Board Panel. #288 6092. 88/04/14. Sulfalk County, NY. 4pp. 45161:071-45161 074
 - 8804200220 Board memorandum & order (ruling on LILCO motion to compol answers to certain interrogatorics & requests for production of documents).* Util 880311 motion denied based on lack of foundation Served on 880415 GLEASON,J.P. Atomic Safety and Licensing Board Panel. #288 6091, 88/04/14. Long Island Lighting Co. 3pp. 45161:075.45161:077.
 - 8804260047 Responds to Langher 880415 ftr & treats malters raised by Intervenors 880413 ftings & 880414 fits re govis objection to portions of 880229 & 0408 orders in realism remaind & offer of proof. Depositions should be made available.

 [RWIN.D.P. Long Island Lighting Co. IRWIN.D.P. Hunton & Williams #288 6132 887 04115. GLEASON.J.P. KLINEJJR. SHON.F.J. Atomic Safety and Licensing Board Resolutions of Association and Control of Control of Association and Control of Control Panel. 4pp. 45210.326-45210.329.
 - 8804260035 Confirmatory memorandum & order.* Board denies util request to suspend scheduled depositions on grounds that Board denial of forthcoming util motion would cause delay in hearing schedule Served on 880419.

 GLEASON,J.P. Atomic Satory and Licensing Board Panel. #288 6136 88/04/18.

 Long Island
 - 8804260102 Request for temporary suspension of "realism" depositions." Motion does not extend to Intervenors obligation to answer interrogalories by 880422.Expodiled treatment of motion requested Certificate of Svc enci. IRWIN.D.P. Long Island Lighting Co. IRWIN.D.P. Harmon & Weiss #288 6131, 887.04718. Atomic Salety and Licensing Board Panel. 4pp. 45210:237-45210.240.
 - 8804260103 Govis brief in opposition to LILCO appeal from LBP-88.2.* Decision of Li-censing Board on Contentions EX 38,39,40,41 & 50 should be attirmed Corrificate of Six encl. CASEY,S.M. Suffolk County, NY. CASEY,S.M. Kirkpatrick & Lockhart CASEY,S.M. Sulfolk County, NY. CASEY,S.M. Kirkpatrick & Lockhart ZAHNLEUTER,R.J. New York, State of. #288 613B. 88/04/18 Atomic Safety and Li-censing Appeal Panel 275pp. 45211:121-45212.106
 - 8804260081 Discusses Board 880413 memorandum & ordor (ruling on govts motion for reconsideration of Board memorandum & order on Section 50.47(c)(1)(0)(u) compliance) Govts neither seek further reconsideration nor agree w/views expressed LANPHER, LC. Kirkpatrick & Lockharl. #288 6133 88/04/20 GLEASON,J.P., KLINE,J.R., SHON,F.J. Atomic Salety and Licensing Board Panel 1p. 45210.157-45210.157 45210:157.
 - 8804260089 Govts motion to strike portion of LiLCO testimony ra Contention 25 C.* Ouestion & Answer 67 appearing on Page 58 of LiLCO testimony should be striken Certricate of Svc end.

 TAYLOR,J.L. Sulfolk County, NY. ZAHULEUTER,R.J. New York, State of, LATHAM,S.B. Twompy, Latham & Shea #288 5134, 88/04/20 Atomic Safety and Licensing Board Panel. 9pp. 45210:227-45210.235
 - 8804260136 Advises that ASLB unfounded assumption in 880413 order re-fact that govts did not seek reconsideration of ruling does not mean & should not mean that govis do not seek reconsideration of ruling does not mean a should not mean that govis do not find fault in ruling.

 LANPHER, L.C. New York, State of LANPHER, L.C. Suffork County, NY.

 LANPHER, L.C. Kirkpatirck & Lockhart. #288 6130. 88/04/20. GLEASON, J.P., KUNE, J.R., SHON, F.C. Atomic Safety and Licensing Board Panel. 1p. 45210-304-45210-304.
 - 8804290025 NRC Staff response to LILCO & intervenors briefs of 880401 on motion to authorize operation at 25% of full power.* NRC believes proceedings should continue to determine whether LILCO antifled to License request Certificate of Svc encl. REIS.E.J. Assistant General Counset for Hearings. #288 6142. 88/04/20 Atomic Safety and Licensing Board Panet. 8pp. 45255:307-45255:314.
 - 8804290087 LILCO motion to strike testimony of Brodsky,et al.* Requirement for Suffolk County to resubmit lestimony leaving out objectionable & impermissible portions of 880413 testimony requested Supporting into encl. CHRISTMAN, J.N. Long Island Ughtung Co. CHRISTMAN, J.N. Particles & Williams #288 8168, 88/04/20 Atomic Safety and Licensing Board Panel 73pp. 45255:030-
 - ••8804290096 LILCO motion to strike testimony of S Cole at al. Striking of portions of 880413 testimony as inadmissable requested because testimony dredges up & asks for reconsideration of old issues Certificate of Svc encl. CHRISTMAN,JN. Long Island Lighting Co. CHRISTMAN,JN. Hunton & Williams. 887 04720. Atomic Safety and Licensing Roard Panel. 34pp. 45255:109-45255:142.
 - 8804290091 LILCO motion to strike direct testimony of State of NY witness DT Harlgen re hosp evacuation time estimates. Listed passages should be striken since already litigated & outside scope of remand proceeding W/Certillicate of Svc.
 SHEFFEY,RA Long Island Lighting Co. SHEFFEY,RA Hunton & Williams. #288 6161. 88/04/20 Atomic Safety and Licensing Board Panel 11pp 45257.152-

 - 8804290147 LILCO motion to strike direct testimony of CG Perry & GC Minor on behalf of Sulfolk County re LILCO emergency broadcast sys. * Arguments for stricking portions of 8804.31 testimony stated W/Certificate of Svc SHEFFEY,RA Long Island Lighting Co. SHEFFEY,RA Hunton & Williams #288 6162. 88/04/20. Atomic Satety and Licensing Board Panel 21pp. 45255.182-45355.182

- 8804290161 Govts objections to LILCO second set of interrogatories re Consumptions 1-2,4-8, & 10.* Certificate of Svc enci Related correspondence LANPHERILC Sulfolk County, NY LANPHERILC. Kirkpatrick & Lockhert ZAHNLEUTER,R J. New York, State of . #288 6164 68/04/20. Long Island Lighting Co. 33pp. 45255 183-45255-215
- 8804290188 NRC staff motion to strike portion of testimony of GC Minor re Emergency Broadcast Sys issue * Pages 13 & 14 of testimony should be stricken due to direct contradiction w/ ASLB 880224 order W/Certificate of Svc.

 8ACHMANN,R.G. Assistant General Counsel for Hearings #288 6163 88/04/20 Atomic Safety and Licensing Board Panel. 4pp. 45255.216-45255.219.
- 8804290030 Govts response to LILCO brief on relevance of pending contentions to LILCO 25% power motion. *LILCO request must be denied CASE DT Suffolk County, NY, CASE DT, Kirkpatrick & Lockhart, PALOMINO.F.G. New York, State of, #289,6143, 88/04/21. Atomic Safety and Licensing Board Panel. 19pp 45255 341-45256-009
- -9804290038 Alfidavit of GC Minor & SC Sholly re-validity of analyses & conclusions ref-in Younging affidavit W/Certificate of Svc. MINOR G G , SHOLLY S C. MHB Technical Associates. 88/04/21, 10pp. 45255.360-
- 6804290052 LILCO reply to intervenors brief on 25% power.* Board should proceed to consider ments of motion to increase power to 25% & to determine that intervenors contentions not substantively relevant to motion W/Cortificate of Svc. INGEBRETSON,C. Long Island Lighting Co. INGEBRETSON,C. Hunton & Williams #288 6144 88/04/21. Atomic Safety and Licensing Board Panel. 14pp. 45256:177-45256:100
- 8804290021 Govt enswer & addi objections to LILCO sucond set of interrogatories ro Contentions 1-2,4-8 & 10.* Answers & objections listed Notification to county executive & Certificate of Svc encl Related Correspondence.

 MCMURRAY,C M. Suffolk County, NY. ZAHNLEUTER,R.J. New York, State of, MCMURRAY,C M. Kirkpatrick & Lockhart. #288 6158 88/04/22. Atomic Safety and Licensing Board Panel 43pp. 45255:237-45255.279.
- 8804290031 Order.* Grants unopposed request of Intervening govts to advance time of scheduled oral argument re facility emergency planning exercise to 880428 Other terms of argument remains Served on 880425. SHOEMAKER,C.J. Atomic Safety and Licensing Appeal Penel. #288 6151, 88/04/22. 1p. 45256-010-45256.010.
- 8804290066 Forwards LILCO response to Intervenors 880413 objection presenting proposed direct evidence on Contontions 1-2,4-8 & 10 Response Incomplete because arguments will be affected by events on 880422. CHRISTMAN,J.N. Long Island Lighting Co. CHRISTMAN,J.N. Hunton & Williams. #288 6165. 88/04/22 GLEASON,J.P. Atomic Satoly and Licensing Board Panel. 1p. 45255-001-45255-029.
- --8804290077 LILCO response to govts objection to portions of 880229 & 0408 orders in realism remand & offer of proof.* Contentions 1-2,4-8 & 10 should be dismissed or ruling re adequacy of stated procedures should be made W/Cortificate of Svc. CHRISTMAN,J.N. Honton & Williams 88/04/22. Alomic Safety and Licensing Board Panel. 28pp. 45255.002-45255.029.
- 8804290068 Govi answers to NRC staff interrogatories ro Contentions 1:2,4:8 & 10.* W/Certificate of Svc Related Correspondence MCMURRAY.C.M. Sulfolk County, NY. MCMURRAY.C.M. Kirkpatrick & Lockhart. ZAHNLEUTER.R.J. New York, State of. #228 6159. 88/04/22. 8pp. 45266:211-4525R-21R
- 8804290086 LILCO responses & objections to Sulfolk County second set of interregatones & requests for production of documents re Contentions 1-2,4-8 & 10 to liconsee.* W/Cerdificate of Svc. Related Correspondence.

 HARLOW,D.S. Long Island Lighting Co. HARLOW,D.S. Hunton & Williams #288 6160, 88/04/22. Atomic Safety and Licensing Board Panel 11pp 45257:141-45257:151.

i. Financial information

8803110365 "LILCO 1987 Annual Rept." W/880328 ftr. CATACOSINOS,W., LEONAHD,J.D. Long Island Lighting Co. 87/12/31. 38pp 44964-090-44964-127.

J. Insurance & indemnity information

8803300439 Forwards listing of nuclear property insurance in force for facility,in accordance w/requirements of 10CFR50.54(m)(4). LEONAND.J.D. Long Island Lighting Co. 88/03/28. Document Control Branch (Document Control Desk). 2pp. 44967:248-44967:249.

P. Operating license stage documents & correspondence

- 8804140354 FOIA request for all records including preparatory mattle & contemporane-ous notes & info submitted by util re 880114 meeting involving NRC & util concerning Gecility.

 BELAIR,R.R. Kirkpatrick & Lockhart, BELAIR,R.R. Suffolk County, NY, 88/01/27, NRC

 - No Detailed Affiliation Given. 2pp. 45104:155-45104;156.
- 8803240426 Generic Ltr 88-06 to all power reactor liconsees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIA,F. J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Erilson Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804040136 Requests permission to reinstall thermal overload heaters for 1E11*MOV052 during normal plant operation Valve will provide greater operational flexibility & control over suppression pool levol. Fee paid. LEONARD, J. D. Long Island Lighting Co. 88/03/24. Document Control Branch (Document Control Desk) 2pp. 44972.030-44972.031.

- 8803300434 Requests NRC concurrence w/util position that all induction healing stress improvement treated wolds at plant can be placed in Category B classification of NUREG-0313,Rev 2 & Generic Ltr 88-01. LEONARD,J D Long Island Lighting Co. 88/03/28 Document Control Branch (Document Control Desk) 2pp 44967.246-44987 247.
- 8804130082 Requests addI Info re supplemental containment sys (SCS) project dosign and const schedule, including those milestones which will require NRC input Util updated SAR acceptable for design of SCS VARGA, SA Division of Reactor Projects I/II (Post 870411) 88/04/06 LEONARD, J.D. Long Island Lighting Co. 4pp. 45102.011-45102.014.
- 8804080088 Generic Ltr 88:07 to power reactor licensees & apphicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants" "Sve list end. MIRAGLIAF, J. Associate Director for Projects (Post 870411), 88/04/07 Consolidated Edison Co. of New York, Inc. 49pp. 45164 237-45164-285
- 8804130261 Responds to 880205 lit to L Zech expressing concern for adequacy of electric energy supply for Long Island NY & questions to whether NRC could accelerate Leansing of plant. Stated into on Loensing schedule sont to Congress MURLEY,T.E. Office of Nuclear Reactor Requiation, Director (Post 870411). 88/04/07. MCFARLAND, J.T. New York, State of 4pp 45102.353-45102.356.
- 8804220031 Forwards request for add: into re-ubil 870312 submittal of procedures generation package Response requested within 90 days of ltr receipt. BROWN,S.W. Project Directorate 1-2, 86/04/15, LEONARD,J.D. Long Island Lighting Co. 15pp 45201:051-45201:068.
- 8804280188 Notification of 880429 meeting in Rockville-MD to discuss status of SER. BROWN,S. Project Directorate I-2, 88/04/20 BUTLER,W.R. Project Directorate II-1, 2pp. 45276,232-45276,233

Q. Inspection reports, IE Bulletins & correspondence

- 8804210209 Forwards response to Items 1-6 of NRC Compliance Bulletin 67-002 re lastener testing to determine conformance w/ applicable mall specs.including data sheets & results of mechanical & chemical testing. LEONARD. JD. Long Island Lighting Co. 88/02/16. RUSSELL,W. Regron 1, Olc of the Director, 59pp. 45194:177-45194:235.
- 8803210090 Suppl 1 to NRC toto Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors" Svc list enci.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/03/28

 Consolidated Edison Co. of New York, Inc. 121pp. 44995.126-44995.246
- 8803220296 NRC Info Notice 88-010, "Malls Licensees.Lack of Mgt Controls Over Liconsed Programs." Syc list encl. CUNNINGHAM, R.E. Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28. Consolidated Ed-syon Co. of New York, Inc. 108pp. 44995:247-44985:353.
- 8603300434 Requests NRC concurrence w/ulil position that all induction healing stress improvement treated welds at plant can be placed in Category B class/fication of NUREG-0313,Rev 2 & Generic Ltr 88-01. LEONARD,J.D. Long Island Lighting Co. 88/03/28 Document Control Branch (Document Control Desk). 2pp. 44967:246-44967-247.
- 8804110311 Discussos Insp Rept 50:322/86:03 & two Ofc of Investigation Investigations in response to altegation re delicencies in radiochemistry dept at plant & forwards notice of violation Synopsis for investigation repts also enci. RUSSELL,W.T. Region 1, Ofc of the Director. 88/03/28. LEONARD,J.D. Long Island Lighting Co. 4pp. 45079.094-45079.104
- --8804110317 Notice of violation from insp on 860127-0214-Violations noted practical abilities of chomistry technicians demonstrated by open book exams rather than by use of procedure checkout guidelines.
 RUSSELL,W.T. Region 1, Ofc of the Director 88/03/28, 7pp 45079-098-45079:104
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-hoard Function Due to Faulty The Bolts" Svc 1st encl ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407.051.
- 8804200209 Forwards requests for addi Info re review of responses to IE Bulletin 85-003 concerning motor-operated valve switch settings Response requested within 30 days.

 days.

 WIGGINS,J.T. Region 1, OIc of the Director. 88/04/07. LEONARD,J.D. Long Island Lighting Co. 7pp. 45174:117-45174:122.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc. list encl.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12.
 Consolidated Edison Co. of New York, Inc. 123pp. 45165 028-45165:150
- 8804190368 Forwards response to violations noted in Safety Insp Rept 50:322/87-22.Response withheld (ref 10CFR73.21). LEONARD.J.D. Long Island Ughting Co. 88/04/15 RUSSELL,W.T. Region 1, Ofc of the Director. 2pp. 45208.335-45208:338.

R. Periodic operating reports & related correspondence

- 8803300380 Forwards "10CFR50.59 Rept for 870608-1231" & "10CFR50.59 Rept,Revised Item SM 86.055," from previous rept submitted did 871204. LEDNARD.J.D. Long Island Lighting Co. 88/03/28. Decument Control Branch (Document Control Desh.) 2pp. 44979.101-44979.124 & "10CFR50.59
- --8803300381 "10CFR50 59 Rept for 870608-1231."
 * Long Island Lighting Co. 87/12/31, 20pp. 44979.103-44979:122
- -8803300386 "Revised Item SM 86-055 for 10CFR50.59 Rept for 860101-870607." Long Island Lighting Co. 87/06/07. 2pp. 44979.123-44979:124.

S. Reportable occurrences, LERs & related correspondence

8804260248 LER 88 003 00 on 880322,unplanned automatic initiation of reactor bldg standby ventilation sys Train A occurred Caused by technician inadvertently deener-gizing relay Engineering evaluation request initiated W/880421 ttr. GRUNSEICHAW, STEIGER,W.E. Long Island Lighting Co. 88/04/21. Spp. 45258 334-45258:338

T. Hearing transcripts on non-antitrust matters

- 8804130135 Transcript of ASLB 880411 prehearing conference in Bethosda, MD re-remand/emergency planning Pp 19,295-19,322.

 ' Atomic Safety and Licensing Board Panel. 88/04/11, 30pp. 45116:276-45116:305.
- 8804206042 Forwards lestimony of T Urbanik re hosp evacuation time estimates,per Board 880310 order.Related correspondence. BACHMAN,R.G. Assistant General Counsel for Hearings. #288 6088. 88/04/10. GLEASON,J.P., KILINE,J.R., SHON,F.J. Atomic Safety and Licensing Board Panel. 1p. 45162:139-45162:145.
- --8804200051 Testimony of T Urbanik re bases & accuracy of hosp evacuation time estimates contamed in Rev 9 of util emergency plan Related correspondence URBANIK, T. Texas A&M Univ., College Station, TX. 68/04/13. 6pp 45162:140-
- 8804200046 Govia objection to portions of 880229 & 0408 orders in realism remand & offer of proof.* Objects to portions of subj orders comprising preclusion of filling response to LILCO realism detense to legal authority contentions. LETSCHE,K.J., ZAHNIEUTER,R.J. New York, State of LETSCHE,K.J. Kirkpatrick & Lockhart. #288 6095. 88/04/13. Atomic Safety and Licensing Board Panel. 61pp. 45160:236-45161.055
- --8804200070 Direct testimony of PG Halpin on behalf of Suffolk County re Contentions 1-2.4.6 & 10.1 Testifies that county govt made no plans & will not develop one for responding to accident at util & that LILCO plan cannot protect citizens: HALPIN.P.G. Suffolk County, NY. 88/04/13: 89pp. 45160:299-45161:037.
- --8804200094 Direct testimony of D Axelrod on behalf of State of NY.1 Testifies that State of NY.1 case of accident in facility, would not follow Lift.CO emergency plan because plan unwoukable & inadequate W/Certificate of Svc.

 AXELROD,D. New York, State of. 88/04/13. 18pp. 45181:038-45161:055.
- 8804200058 Forwards Suffolk County prefiled testimony re remand Issues on util schools evacuation & emergency broadcast sys proposals, including direct leatmony of CG Perry, III & GC Minor, Certificate of Svc encl. Related correspondence.

 MILLER,M S Suffolk County, NY, MILLER,M.S. Kirkpatrick & Lockhart. #288 6094, 88/04/13, GLEASON,J.P., SHON,F.J., KLINE,J.R. Atomic Safety and Licensing Board Panel. 4pp. 45161.084-45162 083.
- --8804200084 Direct testimony of CG Perry & GC Minor on behalf of Sulfolk County re LILCO emergency broadcast sys.* PERRY,CG, MINOR,GC, Sulfolk County, NY, PERRY,CG, Moffet, Larson & Johnson, Ind 88/04/13, 62pp. 45161:088
- --8604200101 Testimony of S Cole,RH Turner & AH Barton on remand of Contention 25.C -- rote conflict of school bus drivers * Research completely irrelevant for under-standing how school bus drivers will behave in radiological emergency. COLE,S., TURNER,R H. Suffolk County, NY. COLE,S. New York, State Univ. of, Stony Brook, NY. 88/04/13, 100pp. 45161:149-45161;282.
- --8804200113 Direct testimony of BG Brodsky,EJ Doherty,HM Koenig,NF Muto, RW Potriak,AR RossI,JT Smith & RN Suprina on behalf of Suffolk County re Contention 25.C.* Unit plans for school evacuation & other alternative actions inadequate. BRODSKY,8.G., DOHERTY,E.J., KOENIG,H.M. Suffolk County, NY. 88/04/13, 100pp. 45161:283-45162-083.
- 8804200082 Testimony of DP Dreikorn & E8 Lieberman on the remanded Issue of bases & accuracy of UILCO hosp evacuation time estimates.' Certificate of Svc end Related correspondence. DREIKORN, DP., LIEBERMAN, E.B. Long Island Lighting Co. LIEBERMAN, E.B. KLD Associates, Inc. #288 6097. 88/04/13. 63pp. 45159.324-45160.017.
- 8904200114 Testimony of D Crocker, RE Dippell & WG Johnson on remanded Issue of coverage of LILCO emergency broadcast sys.* Certificate of Svc encil. Related correspondence. CROCKER.D., DIPPELL,R.E. Long Island Lighting Co. DIPPELL,R.E. Cohen & Dippell, P.C. #288 8098, 88/04/13, 154pp. 45180.018-45180:172.
- 8804200147 Testimony of DM Crocker,RB Kelly,MK Lindell & DS Mileti on remanded issue of rofe conflict of school bus drivers. Add into re bus driver issue during emergency evacuations encl.W/Certificate of Svc.Related correspondence. CRICKER,D.M., KELLY,R.B. Long Island Lighting Co. KELLY,R.B. Weston (Roy F. Weston, Inc.). #288 6096. 88/04/13. 172pp. 45182:159-45162:331.
- 8804280043 Oirect testimony of DT Hartgen,on behalf of State of NY re hosp evacuation time estimates." Util hosp evacuation time estimates not reliable for stated reasons Cartificate of Syo encl. Related correspondence.

 HARTGEN,D.T. New York, State of. #288 6137, 88/04/13. 87pp. 45211:031-
- 8804260118 Requests that ASLB rule re add) nine depositions requested by LILCO need not be held based on LILCO not submitting prima factor case & govts entitlement to be present at all depositions. Supporting documentation encl.

 LANPHER.L.C. Surfolk County, NY. LANPHER.L.C. New York, State of. LANPHER.L.C. Southampton, NY. #288 8129 88/04/16, GLEASON.J.P., KILNEJ.R., SHON,F.C. Atomic Safety and Licensing Board Panel. 9pp. 45210.305-45210.313.

U. Congressional/Executive Correspondence

8804180322 Responds to 880216 referral re inquiry from B Lohmiller concerning prob-lems associated w/licensing of plant. Lohmiller statement that on 880203 NRC denied util license to operate incorrect NRC licensing review continuing. STELLO,V. Old of the Executive Director for Operations, 88/04/11, DECONCINI,D. Senate, 15pp. 45150:282-45180:277.

--8804180333 Submits comments on NRC denial of OL to plant on 880203 & therefore, surrendering authority to State of NY. Problem of histeria would not exist if nuclear energy industry prepared to deal w/TMI incident quickly. LOHMILLER B. Affiliation Assigned. 88/02/05. NRC - No Detailed Affiliation Given. 1p. 45150:277-45150.277.

DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

E. NRC Safety Evaluation Report (SER), supple & correspondence

8804260224 Responds to appeal re denial of FOIA request for documents re SER (NUREG-0675),Suppl 21 concerning operation of plant. Forwards Documents 1,3,4,5 & 6 of end app. Document 2 withheld (ref FOIA Exemption 7).
STELLO,V. Oic of the Executive Director for Operations. 88/04/19. BAUMAN.L. Government Accountability Project 2pp. 45232:182-45232:260.

F. Security, medical, emergency & fire protection plans

8804070140 Ack receipt of 870630,1013 & 1109 & 880304 itrs re Rev 16 of Mar 1988 physical security plan. Changes in Rev 16 not fully consistent w/10CFR73.57. Further reve should be submitted per 10CFR50.90. SCARANO.R.A. Region 5, Olc of the Director. 88/03/30. SHIFFER, J.D. Pacific Gas & Electric Co. 4pp. 45044:160.45044:163.

8804200337 Revised emergency plan Implementing procedures including Rev 3 to EP RB-15, "Emergency Operating Procedure Post-Accident Sampling Sys" & Rev 5 to EP RB-15-A, "Emergency Operating Procedure Post-Accident Sampling Sys...." W/880458 Iter. TOWNSEND, J.D., SHIFFER, J.D. Pacific Gas & Electric Co. 88/04/08. 152pp. 45177:01-45177:155.

8804220276 Forwards changes to Rev 16 of physical security plan & Rev 2 to training & qualification plan.Changes withheld (ref. 10CFR73 21).
SHIFFER_J.D. Pacific Gas & Electric Co. 88/04/19. Document Control Branch (Document Control Desk). 1p. 45257:217-45257:217.

G. Adjudicatory correspondence

8804050054 Response to NRC Staff to polition for leave to intervene filed by San Luis Obispo Mothers for Peace. Notice of appearance & Certificate of Svc enct. VOGLER,B.H. Assistant General Counsol for Hearings. #288 5976.

I. Financial information

8804120409 "PG&E 1987 Annual Rept." W/880406 ltr. CLARKE,R.A., LOCKE,R.F. Pacific Gas & Electric Co. 87/12/31, 52pp. 45154:003-

O. Advisory Committee on Reactor Safeguards reports & correspondence

8804130384 Advises that combination of intensive geologic mapping, reflection & refrac-tion selsmic surveys, dating of fault movements & analysis of current & past earth-quake data reduces chances of underestimating earth-quake damage. MAXWELL,J.C. Maxwell, J.C. 88/03/07. SIESS,C.P. ACRS - Advisory Committee on Reactor Safeguards. 3pp. 45130.085-45130.067.

8804140216 Submits summary of actions discussed at ACRS 335th meeting on 880310-12 in Washington, DC, Including ACRS repts/ recommendations, other actions, agreements, assignments & requests & future agenda. KERR,W. ACR3 - Advisory Committee on Reactor Safeguards. 88/03/24, ZECH,L.W. Commissioners 4pp. 45118:172-45118:175.

8804140163 Summary of ACRS Subcommittee on Diablo Canyon meeting on 880223-24 in Burlingame.CA re review of Diablo Canyon long term selsmic program. *ACRS - Advisory Committee on Reactor Saleguards. 88/04/07. ACRS - Advisory Committee on Reactor Saleguards. 11pp. 45118:135-45118:145.

P. Operating license stage documents & correspondence

6804190231 FOIA request for documents re ACRS subcommittee meetings on 750218-19 re plant. STEWART,M.E. Pacific Gas & Electric Co. 88/02/22. NRC - No Detailed Affiliation

Given. 2pp. 45165:151-45165:216.

- 8804050427 Forwards JEBCO Selsmic, Inc. Itr discussing offshore selsmic data collected in 1984 near facility & requests response re issues raised by Itr. Confidential maps attached may be released per telcon between G Lichtman & R Rohman, ROOD.H. Project Directorate V. 88/03/09. SHIFFER, J.D. Pacific Gas & Electric Co. 5pp. 44997:332-44997:342.
- -8804050438 Informs that util ignored unique & critical set of selsmic data in assessment of major structural trends in area of facility. Stick map of existing data.program map for 1988 survey & selsmic data encl. LICHTMAN, G.S. JEBCO Selsmic, finc. 88/01/05, REITER, L., NRC No Detailed Affilliation Given. 6pp. 44997:337-44997:342.
- 8803240426 Generic Lir 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements. Svo list encl. MIRAGLIA,F.J., Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972159.
- 8804050091 Forwards description of activities re util closing of wastewater holding pond & Rev 2 to "Resource Conservation & Recovery Act Hazardous Wastewater Holding Pond at Diablo Canyon Power Plant."

 SHIFFER, J.D., Pactife Gas & Electric Co., 88/04/01., Document Control Branch (Document Control Desk), 11pp. 45062;129-45062;292.

- -8804070289 Rev 2 to "Resources Conservation & Recovery Act Hazardous Waste Closure Plan for Wastewater Holding Pond at Diablo Canyon Power Plant." W/two oversize drawings.
 * Pacific Gas & Electric Co. 87/07/31, 153pp. 45062:140-45062:292
- 8804080088 Genenc Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA,F. J. Associate Director for Projects (Post 870411). 88/04/07. Consolidated Edison Co. of Now York, Inc. 49pp. 45164:237-45164:285.
- 8804140462 Partial response to FOIA request for documents App A document totally withheld (ref FOIA Exemption 5).
 GRIMSLEY, D.H. Division of Rules & Records (Post 870413). 88/04/08. WEISSMAN,S. California, State of 3pp. 45130:150-45130:152.
- 8804190242 Responds to FOIA request for documents re ACRS meeting on plant. Forwards DJ Skovholt 750324 memo to F Schroeder concerning plant pre-ACRS SER supplie Charges for search, review & reproduction provided. GRIMSLEY, D.H. Division of Rules & Records (Post 970413). 88/04/14. STEWART, M.E. Pacific Gas & Electric Co. 1p. 45165.217-45165:230.
- 45165:230
- 8804250017 Forwards application for amends to Licenses DPR-80 & DPR-82, consisting of License Amend Request 88-04,revising Tech Spacs 2.2.1 & 3.3.1 to change reactor trip on turbino trip to thermal power greater than 50%. Fee paid: SHIFFER_JD, Pacific Gas & Electric Co. 88/04/18. Document Control Branch (Document Control Desk). 2pp. 45248:013-45248.032.
- -8804250018 Application for amonds to Liconses DPR-80 & DPR-82, consisting of Liconse Amend Request 88-04,revising Tech Specs 2.2.1 & 3.3.1 to delete reactor trip on turbine trip below 60% power.
 SHIFFER,J.D. Pacific Gas & Electric Co. 88/04/18. 13pp. 45248.015-45248.027.
- --8804250022 Proposed Tech Spacs 2.2.1.8.3.3.1,revising reactor trip on turbine trip from thermal power greater than 10% to thermal power greater than 50%.
 Pacific Gas & Electric Co. 88/04/18. 5pp. 45248:028-45248:032.
- 8804260069 Final response to FOIA request for documents.App Y documents enci & available in PDR & LPDR.App Z documents partially withheld (rot FOIA Exemptions 6 & 7).App AA documents lotally withheld (rot FOIA Exemptions 7).
 GRIMSLEY,D. Division of Rules & Records (Post 870413). 88/04/19. GARDE,B.P. Government Accountability Project. 5pp. 45232:135-45232:172.
- -8804260106 Parilally deleted memo re 840120 allegation of drug use at plant.Writer received telephone call stating that two individuals bragged about shooting up w/heroine in "Blue Room" at plant. SHACKLETON,O.C. Region 5, Ofc of the Director. 84/01/26. Region 5, Ofc of the Director. 3pp. 45232:142-45232:144.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svo list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 98:010, "Matts Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list encl. CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Satety (Post 970729), 86/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.
- 8804130019 Forwards Insp Ropts 50:275/88-03 & 50-323/88-04 on 880131- 0305 & notice of violation.Uni attention directed to Section 4 of encl rept dealing w/recent plant events Mgt should carefully reassess problem area. KIRSCH,D.F. Region 5, Oto of the Director, 88/03/28. SHIFFER,J.D. Pacific Gas & Electric Co. 2pp. 45151:140-45151:164.
- -8804130020 Notice of violation from Insp on 880131-0305 Violations noted:employee entered radiological controls area by stepping over posted boundary at point not established as normal access control point w/o written autorization. KIRSCH,0.F. Region 5, Oto of the Director. 88/03/28. 2pp. 45181:142-45161:143.
- --8804130022 Insp Repts 50-276/88-04 & 50-323/88-04 on 880131-0305. Violations noted Major areas inspected plant operations, maint & surveillance activities, followup of onsite events, open items & LERs. PADOVAN,L.M., JOHNSTON,K.E., NARBUT,P.P. Region 5, Ofo of the Director, 88/03/16, 21pp. 45151;144-45151;184.
- 8804080249 Ack receipt of 880310 ltr Informing NRC of steps taken to correct violations noted in Insp Repts 50-275/87-44 & 50-323/87-45. ZIMMERMAN,R. Region 5, Ofc of the Director. 88/03/29. SHIFFER,J.D. Pacific Gas & Electric Co. 1p. 4564:232-45064:233.
- 8804010256 NRC Into Notice 88-011, "Patential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolls." Svc list and. ROSSI.CE. Division of Operational Events Assessment (Post 870411). 88/04/07, Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407:051.
- 8804200531 Responds to NRC 980311 ltr re violations noted in Insp Repts 50-276/88-04 & 50-323/88-03.Corrective actions Surveillance Test Procedure V-3, "Exercising Safety-Related Valves General Procedure" revised to be consistent w/ASME Code. SHIFFERJ.D. Pacific Gas & Electric Co. 88/04/11. Document Control Brench (Document Control Desk). 6pp. 45176:014-45175:019.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl.

 ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/04/12.

 Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150.

- 8804200521 Forwards addl into to suppl util responso to IE Bulletin 85:003, "Motor-Operated Valve Common Mode Failures During Plant Transients Due to Improper Switch Sottings," per 880315 request SHIFFER,J.D. Pacific Gas & Electric Co. 88704/14. Document Control Branch (Document Control Desk). 10pp. 45228:211-45226.220
- 8604210449 Informs that completion of survey of safety-related equipment outside containment in response to Insp. Repts 50:275/87-42 & 50:323/87-43 rescheduled to 880430,due to personnel requirements to support Unit 1 refueling outage. SHIFFER, J. D. Pectic Gas & Electric Co. 88/04/14. Document Control Branch (Document Control Desk). 1p. 45226 342-45226 342.
- 8604260069 Final response to FOIA request for documents App Y documents encl & available in PDR & LPDR.App Z documents partially withheld (ref FOIA Exemptions 6 & 7) App AA documents totally withheld (ref FOIA Exemptions 7). GRIMSLEY.D. Division of Rules & Records (Post 870413). 88/04/19. GARDE,B P. Government Accountability Project. Spp. 45232:135-45232:172.
- -8804260133 Partially deleted Rept of Inquiry O5-83-018 re allegation of falsilication of welding exams by ironworkers from Fresno Union Further investigation unwarranted based on failure to confirm that stand in welder took tests Related into encl. POWER,E.J., SHACKLETON,O.C. Region 5, Old of the Director. 83/12/15, 26pp. 45232:146-45232:172.
- 8804260207 Responds to NRC Bulletin 88-003, "Inadequate Latch Engagement in HFA Type Latching Relays Mfg by GE." Subj relays not in use in Class 1E applications at facility.

 SHIFFER,J.D. Pacific Gas & Electric Co. 88/04/21. Document Control Branch (Document Control Desk). 1p. 45253.049-45253.049.

R. Periodic operating reports & related correspondence

- 8804040009 "Tabulation of Personnel Exposure to Radiation for 1987." W/ 880328 ltr. SHIFFER,J.D. Pacific Gas & Electric Co. 87/12/31. 5pp. 44969.071-44969.075.
- 8804220104 Monthly operating repts for Mar 1988.W/680415 ltr.
 BEDESEM.P., TOWNSEND.J.D., MALONE,D.D. Pacific Gas & Electric Co 88/03/31.
 12pp. 45216:226-45216:237.

S. Reportable occurrences, LERs & related correspondence

- 8803290400 LER 88:001:00:on 880226, spurious actuation of fuel handling btdg ventilelion sys lodine removal mode occurred following alarm on radiation monitor 2-RM-59 Caused by apparant electrical noise Procedures revised W/880324 ltr. SISK.D.P., SHIFFER,J.D. Pacilic Gas & Electric Co 88/03/24. 5pp. 44961:220-44961:224.
- 8804010284 LER 88-002-00 on 880303,reactor trip & subsequent turbine trip occurred during Surveillance Teat Procedure 1-728. Caused by failure of K4 relay together w/ lack of annunciation Faited roley replaced W/880328 ltr.
 HAMPSHIRE,D., SHIFFER,J.D. Pacific Ges & Electric Co. 88/03/28. 5pp. 44845.354-
- 804070014 LER 88-003-00.on 880304.containment ventilation isolation occurred.Caused by electrical short due to water intrusion into pressure switch PS-526.Switch.conduit connector cover screw & gasket replaced.W/880401 ltr. 8804070014
- 8804070024 LER 88-004-00:on 880305,containment ventilation isolation actuation signal received from radiation monitor RM-148. Caused by procedural deticionicies Design change to modify NE-52 & NE-51 power supply will be issued.W/880401 ftr. MALONE.D.D., SHIFFER,J.D. Pacific Gas & Electric Co. 68/04/01. 6pp. 45072:271-45072:276.

V. Operator Examinations

- 8804260088 Responds to FOIA request for info re scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in encl app w/personal privacy info deleted.
 GRIMSLEY,D.H. Division of Rules & Records (Post 870413), 88/04/19, BOLEY,K Public Clizen's Critical Mass Energy Project. 2pp. 45213:003-45213:095
- --8804250167 Package of NRC administered requalification exam results summary.

 NRC No Detailed Affiliation Given. 87/07/20, 98pp. 45213.007-45213.095.

DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8804060317 Forwards Insp Repts 50-325/88-12 & 50-324/88-12 on 880222-25.No vio-lations or deviations noted. HERDT,A.R. Region 2, Ofc of the Director. 88/03/29. UTLEY,E.E. Cerolina Power & Light Co. 2pp. 45072-052-45072
- -8804060319 Insp Repts 60-324/88-12 & 50-325/88-12 on 880222-25.No violations or deviations noted Major areas inspected fire protection/prevention, review of status of App R lire protection mode & previously Identified insp Items.
 WISEMANG.R., CONLON,T.E. Region 2, Ofc of the Director. 88/03/22, 7pp. 45072.054-45072.060.
- 8804150385 "Rev Plant Emergency Procedures." W/880330 ltr.
 DIETZ,C.R. Carolina Power & Light Co. 86/03/30. GRACE,J.N. Region 2, Ofc of the Director. 2pp. 45138:308-45138:310.

- 8804180454 Forwards Rev 25 to emergency response plan & revised emergency plan implementing procedures including Rev 8 to PEP-02 6 12, "Operational Support Ctr. Leader" & Rev 8 to PEP-04 3, "Performance of Training Exercise & Drifs". DIETZ, CR Carolina Power & Light Co. 88/03/30 GRACE, J.N. Region 2, Otc of the Director, 2pp. 45170 119-45170.164
- --8804130048 Revised emergency plan implementing procedures,including Rev 8 to PEP-04.3, "Performance of Training,Exercises & Onlis" Rev 8 to PEP-02.5.12, "Operational Support CIL Leader," SMITH.J.D. Garolina Power & Light Co. 88/03/23, 22pp. 45170.121-45170.142.
- -8804180461 Rev 25 to Vol 13,80ok 1 to "Emergency Response Pian." SMITH,JS Carolina Power & Light Co. 88/03/30, 22pp. 45170 143-45170.164.
- 8804270069 Forwards revs to emergency procedures including Rev 4 to PEP-2 6.1 re plant operations director & Rev 1 to PEP-02 6.22 re technical assessment director.List of revs to procedures enc.W/o procedures.
 DIETZ,CFD. Carolina Power & Light Co. 88/04/11. GRACE,J.N. Region 2, O/c of the Director 2pp. 45245:282-45245 283
- 8804200473 Pamal response to FOIA request re fire protection Forwards App E documents.App D & E documents available in PDR App F document completely withheld (ref FOIA Exemption 5).
 GRIMSLEY,O.H. Division of Rules & Records (Post 870413) 88/04/14 JONES,C R. Alfi'lation Not Assigned. Spp. 45206 037-45206 043.
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type insp for each facility to assess status of comphance w/ 10CFR50.48 Program listed.
 CONLON,T.E. Region 2, Ofc of the Director. 84/11/06 HERDT,A.R. Region 2, Ofc of the D-rector. 3pp. 45206.178. 45206.179.

J. Insurance & Indemnity Information

- 8804070174 Submits into re present level & source of onsite property damage Insur-LOPLIN,L.I. Carolina Power & Light Co. 88/03/31. Document Control Branch (Document Control Desk). 1p. 45075.256-45075.258.
- 8804250219 Forwards Endorsement 59 to MAELU Policy MF-80. BARIHAM,C.D. Carolina Power & Light Co. 58/04/04 NASH,D. NRC No Detailed Af-filiation Given. 2pp. 45212.230-45212.231
- 8804250221 Forwards Endorsement 69 to NELIA Policy NF-218.
 BARHAM,C.D. Carolina Power & Light Co. 88/04/04, NASH,D. NRC No Detailed Af-Litation Given. 2pp. 45212 232-45212 233.

P. Operating license stage documents & correspondence

- 8803080108 Forwards SER supporting proposed functional testing plan for snubbers Proposed plan meets ASME Code, Section XI requirements & compiles w/ Tech Spec 4.7.5 requirements so relial request deemed unnecessary.

 ADENSAM.E. Project Directorate II-1, 88/03/02, UTLEY,E.E. Carolina Power & Light Co. 2pp. 44633.305-44633.308.
- -8803080118 Safety evaluation supporting proposed functional testing plan for snub-
- bers.
 * Project Directorate II-1, 88/03/02, 2pp. 44633:307-44633:308
- 8803240426 Generic Ltr 88-08 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIAF_J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Ce of New York, Inc. 47pp. 44972:107-44972:153
- 8804040040 Advises that util has now staffed shift technical advisor program w/appropriately trained personnel so that contract engineers no longer needed. LOFLIN,L.1. Carolina Power & Light Co. 88/03/24, Document Control Branch (Document Control Desk), 1p. 44969.034-44989-034.
- 8803310223 Forwards revised Relief Requests PR-05,VR-15,VR-16 & VR-17 to Inservice testing program for svc water tubricating sys, per 870721-22 moeting commitment Svc pumps will be modified to provide internal sall-lubrication. RICHEY,R.B. Carolina Power & Light Co. 88/03/28. Document Control Branch (Document Control Desk) 7pp, 45000:336-45000.342.
- 8804050009 Forwards addl into in support of util 880203 application to amend License DPR-82,re upgraded min critical power ratio safety limit for Cycle 8,per NRC 880315 LOFLIN,L.I Carolina Power & Light Co. 88/03/30. Document Control Branch (Document Control Desk) 4pp. 45062-025-45062-029.
- -8804050021 Proposed Tech Spec Bases 2.1.2, "Thermal Power (High Pressure & High
- Carolina Power & Light Co. 88/03/30, 1p. 45082.029.45062.029
- 8804060284 Suppl to 880203 application for amend to License DPR-62, revising critical power ratio fuel cladding integrity safety limit value specified in Tech Specs Section 3/4 3 4, Action Statement b 3.

 MCDUFFIE,M A. Carolina Power & Light Co. 88/03/30. Document Control Branch (Document Control Desk). 3pp. 45047:169-45047:172.
- -8804060286 Proposed Tech Specs 3/4,3.4, "Control Rod Withdrawal Block Instrumen-
- Carolina Power & Light Co. 68/03/30. 1p. 45047:172-45047:172.
- 8604080201 Forwards Amend 146 to License DPR-62 & safety evaluation. Amend changes Tech Spec to lower reactor water level solpoints for isolation of Group 1 primary containment isolation valves from Low Level 2 to 3 & correct error. SYLVESTERE D. Project Directorate 1-1, 88/04/01, UTLEY,E.E. Carolina Power & Light Co. 3pp. 45064.316-45064:338
- --8804080222 Amend 146 to License DPA-82, revising Tech Spec to lower reactor water level setpoints for isolation of Group 1 primary containment isolation valves from Low Level 2 to 3 & correct error.
 ADENSAM,E.G. Project Directorate II-1. 88/04/01. 15pp, 45064:319-45064:333.

- Project Directorate II-1, 88/04/01, 3pp. 45064,334-45064;336
- 8804110227 Forwards Amonds 117 & 147 to Licenses DPR-71 & DPR-62, respectively & salety evaluation Amends change Tech Specs to revise Table 4.4.6.1.3-1 re reactor vessel mail surveillance test.

 SYLVESTER,E.D. Project Directorate II-1, 88/04/04 UTLEY,E.E. Carolina Power & Light Co. 3pp. 45071;341-45071,358.
- -8804110236 Amends 147 & 117 to Licenses OPR-62 & OPR-71 trespectively, changing Tech Spacs to revise Table 4.4.6.1.3-1 to require removal of second & third surveil-lance capsules after results of first capsule ovaluated & added to Tech Spec ADENSAM.E.G. Project Directorate II-1. 88/04/04 10pp. 45071.344-45071.353
- -8804110240 Safety evaluation supporting Amends 147 & 117 to Licenses DPR-62 & DPR-71, respectively.

 * NRC No Deleted Affiliation Given 88/04/04. Spp. 45071:354-45071.358.
- 8804120348 Supplemental application for amends to Licenses DPR-71 & DPR-62,removing specific safety limit min critical power ratio value from Tech Spec Bases Section 2.2.1.1 & Tech Spec Sections 3.1.4.3 & 3.3.4.

 EURYL.W. Carolina Power & Light Co. 08/04/05 Document Control Branch (Document Control Desk). 9pp. 45146.045-45146.061.
- --8804120350 Proposed Tech Space to dimination of cycle specific variables * Carolina Power & Light Co. 88704/05. 8pp. 45146.054-45146.061
- 8804120287 Forwards response to NRC 880308 request for addit into re-optical disk storage system microterming plant records LOFLINLLI. Carolina Power & Light Co. 88/04/406. Document Control Desk) 4pp. 45089.071-45080-074
- 8804120434 Forwards corrected Bases Pages 8 3/4 4-1,8 3/4 4-2 & B 3/4 4-3,restor-ing into inadvertently removed from Sections 3/4.4 2 & 3/4.4 3.1. LOFLIN,L.I. Carolina Power & Light Co. 88/04/06 Document Control Branch (Docu-ment Control Desk), 1p. 45091.010-45091.017.
- ~8804120460 Corrocted Tech Specs Bases Pages B 3/4 4-1,B 3/4 4-2 & B 3/4 4-3,restoring Info inadvertently removed from Sections 3/4.4.2 & 3/4.4.3.1.
 * Carolina Power & Light Co. 88/04/08. 7pp. 45091.011-45091.017.
- 8804080088 Generic Ltr 88-07 to power roactor licensees & applicants re-monified en-forcement policy concerning 10CFR50.48. "Environ Qualification of Electrical Equip-ment important to Safety for Nuclear Power Plants." Svc list oncl. MIRAGLIA.F. J. Associate Director for Projects (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184:237-45164:285
- 8804140285 Forwards Amond 148 to License OPR-62 & safety evaluation. Amond revises Instrument Tag Numbers B21-LI-R604AX & B21-LT-N026A to B21-LI-R604BX & B21-LT-N026B, respectively, in Tech Space 3.3.5.2-1 & 4.3.5.2-1. SYLVESTER,E.D. Project Directorate II-1. 88/04/07. UTLEY,E.E. Carolina Power & Light Co. 2pp. 45130.051-45130.061.
- -8804140290 Amend 148 to Liconso DPR-82 revising Instrument Tag Numburs 821-L1-R604AX & 821-L1-N026A to B21-L1-R604BX & 621-L1-N026B respectively in Tech Specs 3.3.5.2-1 & 4.3.5.2-1. ADENSAM,E.G. Project Directorate II-1, 88/04/07, 5pp. 46130 053-45130 057
- --8804140292 Satety evaluation supporting Amond 148 to License DPR-62.

 * Office of Nuclear Floactor Regulation, Director (Post 670411), 88/04/07, 4pp 45130.056-45130:061.
- 8804140120 Forwards Amond 150 to License DPR-62 & safety evaluation. Amond changes Tech Specs to be consistent w/new instruments installed for alternate red injection 8 recirculation pump trip sys.Extension of time to comply w/10CFR50.82 granted. SYLVESTER.E.D. Project Oirectorate II-1. 88/04/08. UTLEY.E.E. Carolina Power & Light Co. App. 45120.227-45120:243.
- --8804140132 Amend 150 to License DPR-82,changing Tech Spec Tables 3:3.6.1-1,3.3.6.1-2 & 4.3.6.1-1 & Section 3/4.3.6 to be consistent w/new instruments that have been installed for alternate roof injection & recticulation pump trip sys. ADENSAM,E.G. Project Directorate II-1, 88/04/08, 8pp. 45120:231-45120:238.
- --8804140135 Safety evaluation supporting Amend 150 to Liconse OPR-62.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/08, 5pp. 45120 239-45120.243
- 8804140299 Forwards Amend 149 to License DPR-62 & safety evaluation. Amend changes Tech Specs to incorporate operating limits for all fuel types for Cycle 8 operating the control of the SYLVESTER.E.D. Project Directorate II-1, 88/04/08, UTLEY,E.E. Carolina Power & Light Co. 2pp 45118:002-45118:028.
- ~8804140302 Amend 149 to License DPR-62,changing Tech Specs to incorporate operating limits for all fuel types for Cycle B operation of Unit 2.

 ADENSAM,E.G. Project Directorate II-1, 88/04/08, 19pp, 45118:004-45118.023.
- -8804140304 Safety evaluation supporting Amend 148 to License DPR-62.
 * Office of Nuclear Reactor Regulation, Director (Post 870411). 88/04/08. Spp. 45118.024-45118.028
- 8804150421 Forwards Amend 151 to License DPR-62 & safety evaluation. Amend changes Tech Specs to Incorporate upgraded min critical power ratio fuel cladding integrity safety limit & associated operating limit values. SYLVESTER,E.D. Project Directorate H-1, 88/04/12, UTLEY,E.E. Carolina Power & Light Co. 3pp. 45133:121-45133:185.
- --9804160434 Amend 151 to License DPR-62, changing Tech Specs to incorporate upgraded min critical power ratto fuel cladding integrity safety limit & associated operating limit values applicable to operation of facility Cycle 8.
 ADENSAM,E.G. Project Directorate II-1, 88704/12, 17pp, 45133:124-45133:140
- -9804150436 Safety evaluation supporting Amend 161 to License DPR-62.
 * Office of Nuclear Reactor Regulation, Director (Post 870411). 88/04/12. 3pp. 45133:141-45133:185.

- 8804270088 Discusses util reconsideration of commitment to reduce low Level 2 water level selpcint provided in 871013 updated status of facility strategy for avoiding partial tow Level 2 initiations/isolation on scrams DIET7.C R Carcina Power & Light Co. 88/04/12 GRACE.J N Region 2, Ofc of the Director 1p 45244-360-45244-360
- 8804210411 Notification of 880419 meeting w/util in Rockytle,MD to discuss util design of nitrogen pnoumatic sys for operation of pneumatic valves inside drywell SYLVESTER,E.D. Project Directorate II-1 88/04/15 MURLEY,T., SNIEZEK,J., MIRAGLIA,F. NRC No Datailed Alfretion Given 3pp 45191.135-45191.137
- 8804210336 Forwards correct Tech Spec page for Amend 146 to License DPR-62 Incorrect page inadvertently issued

 SYLVESTER,E D. Project. Directorate II-1, 88/04/18. UTLEY,E E. Carolina Power &
 Light Co. 2pp. 45191.252-45191:254
- -8804220065 Corrected Tech Spec page to Amend 146 to License DPR-62. Incorrect page inadvertently issued Project Directorate III 1 88/04/18 1p. 45191-254-45191-254
- 8804220047 Forwards two corrected Tech Spec pages for Amend 151,issued on 880412,for License DPR-62 incorrect page Inadvertionly issued for Page B 2-2 & Page 3/4 3.39 inadvertently omitted from amend SYLVESTER, E.D. Project Directorato II-1, 88/04/18, UTLEY, E.E. Carolina Power & Light Co. 2pp. 45201:012-45201.015.
- --8804220052 Errate to Amend 151 to Licenso DPR-62,consisting of Tech Spec Pages 3/4 3-39 & B 2-2 rd control rod withdrawel block instrumentation & thermal power (high pressure & high flow), respectively.

 * Project Directorate II-1, 88/04/18, 2pp. 45201,014-45201,015.
- 8804280160 Forwards corrected pages to Amends 116 & 144 to Licenses DPR-71 & DPR-62 respectively Amend inadvertently Issued w/ Incorrect amend numbers on bottom of two pages.

 SYLVESTERIED Project Directorate N-1 88/04/19. UTLEY,E.E. Carolina Power & Light Co 2pp 45276.215-45276.218.
- -8804280162 Corrected pages to Amends 116 & 144 to Licenses DPR-71 & DPR-62,respectively.
 • NRC - No Detailed Affiliation Given, 88/04/18, 2pp. 45276/217-45276/218.

- 8803080293 Forwards comments re inspiplan & proposed miligation & ropair of Incondi-butter welds Comments should be addressed in outage insp/reper rept to be submit-ted at least 2 wks prior to rostert of Umi 2 from Reload 7 outage. SYLVESTER,E D Project Directorate II-1, 88/03/02, UTLEY,E.E. Carolina Power & Light Co. 3pp. 44633:357-44633-359.
- 8803300079 Forwards Insp Repts 50-324/88-06 & 50-325/88-06 on 880125-29 & notice of wollation HERDT.A.R. Region 2, Ofc of the Director, 88/03/10, UTLEY,E.E. Carolina Power & Light Co. 2pp. 44920.058-44920.075.
- --8803300080 Notice of violation from insp on 880125-29. Violation noted: applicable ASME test requirements not mot & procedures did not contain stops or criteria which would assure conformance of festing to ASME requirements. HERDT, A.R. Region 2, Otc. of the Director: 88/03/10, 3pp. 44920.058-44920.060
- --8803300083 Insp Ropts 50:324/88:06 & 50:325/88:06 on 880125-29. Violations noted Major areas inspected area of inservice testing of pumps & vs/ves. GIRAND.E.H., BLAKE,J.J. Region 2, Ofc of the Director, 88/03/02, 15pp 44920:061-4620025.
- 8803280135 Forwards Insp Repts 50-324/88-02 & 50-325/88-02 on 880111-15,19-22 & 0131-0205 No violations or deviations noted HERDT,A.R. Region 2, Ofc of the Director, 88/03/11, UTLEY,E.E. Carolina Power & Light Co. 2pp. 44921:046-44921:060.
- --8803280137 Insp Repts 50-324/88-02 & 50-325/88-02 on 880111-15,19-22 & 0131-0205 No violations or deviations noted Major areas inspected inservice insp. of welds, piping & components for IGSCC & weld overlay repair welding.

 COLEY, J.L., BLAKE, J.J. Region 2, Olc of the Director. 88/03/04. 13pp. 44921.048-
- 8803310035 Discusses miligative actions weld overlay upgrades & IGSCC insps per-formed during Reload 7 outage. Updated classification of svc sensitive weldments into 7 categories per NUAEG-0313, Rev 2 also included. LOFLIN, L.I. Carolina Power & Light Co. 88/03/25. Document Control Branch (Docu-ment Control Dask). 20pp. 44982.207-44982.324.
- --8803310044 "Weld Overlay Repair for Safe End-to-Nozzle Weld 12-AR-E5 Brunswick Stoam Electric Plant Unit 2." GIANNUZZIA J. TANG.S S., GUSTIN.H.L. Structural Integrity Associates, SIR-88-003 R00, 89/03/17, 82pp. 44982:227-44982:289.
- ~8803310039 "Design Rept for Recirculation Sys Ropairs Performed During 1988 Refu-eling Outage at Brunswick Steam Electric Plant Unit 2." GUSTIN,H.L., RICCARDELLAP, PITCAIRND.D.R. Structural Integrity Associates, SIR-88-010 R00 88/03/21, 34pp. 44982:290-44982:324.
- 8803210090 Suppl 1 to NRC Info Notice B7-044, "Thimble Tuba Thinning in Westing-house Reactions" Svc list encl. ROSSIGE. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:128-44995:246.
- 8803220296 NAC Into Notice 88-010, "Matts Liconsees:Lack of Mgt Controls Over Licensed Programs." Svc list encl.

 CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 88/03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.
- 8804060231 Ack receipt of 880309 ltr Informing NRC of steps laken to correct violations noted in Insp Repts 50-324/87-43 & 50-325/87-42 Based on util position on definition of deactivate, response being forwarded to NRR for review. VERRELLI, D.M. Region 2, Otc of the Director. 88/03/29. UTLEY, E.E. Carolina Power & Light Co. 1p. 45007:316-45007:316.

- 8804080317 Forwards Insp. Repts 50-325/88-12 & 50-324/88-12 on 880222-25.No vio-lations or devaluons noted HERDT, A. R. Region 2, Ofc of the Director 88/03/28, UTLEY,E.E. Carolina Power & Light Co. 2pp. 45072-052-45072
- --8804050319 Insp Repts 50-324/88-12 8 50-325/88-12 on 880222-25 No violations or deviations noted Major areas inspected fire protection/prevention,review of status of App R fire protection mods 8 previously identified inspirers WISEMANG R. CONLON.T E. Region 2. Ofc of the Director. 88/03/22 7pp. 45072.054-45072.060
- 8804050353 Forwards Insp. Repts 50:325/68:05 & 50:324/68 05 on 880201-29.No vio-lations or doviations noted Unresolved Items Identified. VERRELLID.M. Region 2, Otc of the Director. 88/03/30. UTLEY,E.E. Carolina Power & Light Co. 2pp. 45045 229-45045-244.
- --8604050354 Insp Repts 50 324/88 05 & 50 325/88 05 on 880201-29 No violations or deviations noted Major areas inspected, previous enforcement matters, maint observation, surveillance observation & hydrogen leak/unusual event. RULAND, W.H., FREDRICKSON, P. Region 2, Ofc of the Director 88/03/30, 14pp. 45045 231 45045 244
- 8804110050 Responds to IE Bullotin 80-13 re exam of core spray sys spargers, Crack Indication identified on north core spray line outside shroud Crack result of IGSCC Unit 2 can safety operate w/crack dui-rig nort fue! cycle.No changus required. MCDUFFIE,M A Carolina Power & Light Co. 88/03/31, GRACE,J N. Region 2, Ofc of the Director, 3pp. 45121:088-45121:130
- -8804110052 "Core Spray Line Crack Analysis for Brunswick Steam Electric Plant, Unit 2." CORNWELL,K.F., STEVENS,G.L., TRAN,P.T. General Electric Co. EAS-14-0388-887 03/31 40pp 45121:091-45121.130.
- 8804010258 NRC Info Notice 89-011, "Potential Loss of Motor Control Ctr. &/or Switch-board Function Due to Faulty Tie Bolts: "Svc list encl. ROSSI,C E. Division of Oporational Events Assessment (Post. 870411) 89/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406.292-45407.051.
- 8804130350 Responds to violations noted in Insp. Repts 50-324/88-06 & 50-325/88-80410350 Hespinds to via this indice it hisp replits 303276600 a 30328766 (G. Corrective actions periodic test procedures revised to specify method for stroke time testing air-operated valves DIETZ, C.R. Carolina Power & Light Co. 88/04/08 Document Control Branch (Document Control Dask), 8pp. 45154/330-45154.335.
- 8804210218 Responds to NRC Bulletin 88-001, "Defects in Westinghouse Circuit Break-era." Util determinud that Westinghouse DS series circuit breakers not used in Class
- 1E sys. EURY,L.W. Carolina Power & Light Co. 88/04/08. GRACE,J.N. Region 2, Olc of the Director. 1p. 45235-267-45235.267.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl. ROSSI,CE, Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150.
- 8804200516 Forwards response to violations noted in Insp Repts 50-324/88-01 & 50-325/88-01 Shift operations personnel trained on importance of meeting surveillance times Timers also provided to personnel.

 DIETZ,C.R. Carolina Power & Light Co. 88/04/13. Document Control Branch (Document Control Desk). 3pp. 45218:277-45218 279
- 8804200473 Partial response to FOIA request re live protection. Forwards App E documents. App D & E documents available in PDR App F document completely withheld (rel FOIA Examplion 5) GRIMSLEY, D.H. Division of Rules & Records (Post 870413). 88/04/14. JONES, C.R. Affiliation Not Assigned 6pp. 45206.037.45206.043.
- --8804200579 Advises that Fire Protection Stooring Committee has recommended that each region make one 10CFR50,App R-type Insp for each facility to assess status of compliance w/ 10CFR50 48 Program listed.
 CONLON,T.E. Region 2, Oic of the Director. 84/11/06. HERDT,A R. Region 2, Oic of the Director. 3pp. 45206;178-45206;178
- 8804210067 Requests exemption from requirements of ASME Boiler & Pressure Vessel Code, Saction XI re Inservice Insp. Insp. at 1,005 pag pressure could cause stated personnel hazards. Exam at lower pressure proposed Fee paid EURYLLW. Carolina Power & Light Co. 88/04/14. Dacument Control Branch (Document Control Desk). 6pp. 45226:290-45226 295.
- 8804260242 Forwards revised Page 2 & Encl 2 re Insp Repls 50-324/88-05 & 50-325/ 88-05-880330 transmittel fir Encl 2 inadvortently omitted during submittel of repl. VERRELLI,O.M. Region 2, Otc of the Director, 88/04/14, UTLEY,E.E. Carolina Power & Light Co. Spp. 45282-076-45282-083.
- 8804200098 Responds to violations noted in Insp Repts 50 324/88 09 & 50 325/88-09.Corrective actions red-ation control supprivisor conducted training sessions w/operations personnel & E&RC Procedure 0230 revised to clearly state requirements. DIETZ.C.R. Carolina Power & Light Co. 88/04/15. Document Control Branch (Document Control Desk), 7pp. 45218 227-45218.233.
- 8804270106 Forwards request for addl into ro util 860513,0829,1002 & 880304 re-sponses to Bulletin 85.003, "Motor-Operated Valve Common Mode Fairures During Plant Transients Duo to Improper Switch Settings" Info requested within 30 days of itr HERDT, A.R. Region 2, Otc of the Director, 88/04/18, UTLEY, E.E. Cerolina Power & Light Co. 3pp 45241:245-45241.247.
- 8804290277 Ack recelpt of 880408 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-324/88-06 & 50-325/88-08. Engineering evaluation rept clarifying numeric limits for abnormat or erratic data requested by 880503.

 HERDT,AR. Region 2, Oic of the Director. 88/04/25. UTLEY,E.E. Carolina Power & Light Co. 2pp. 45283 075-45283-076.

100 DOCKETED ITEMS

R. Periodic operating reports & related correspondence

8803300324 Monthly operating repts for Feb 1988 W/880303 itr HARRISON,F, DIETZ,C.R. Carolina Power & Light Co. 88/02/29. SCROGGINS,R.M. Quice of Administration & Resources Managemont, Director (Post 870413). 9pp 44981.058

S. Reportable occurrences, LERs & related correspondence

- 8804130331 LER 88-006 00 on 880309 control rod 10-39 unknowingly withdrawn w/reactor protection sys shorting links installed. Caused by personnal error individuals involved counseled & process of software mod to be reviewed W/880406 ftr. PASTVA.M.J., DIETZ,C.R. Carolina Power & Light Co. 88/04/06. 6pp. 45154:082-45164-087.
- 8804280001 LER 88-007-00:on 880319,visual & inquid penetrant insps of unit CRD insert/withdraw times revealed existence of pinhote & linear indications in lines Caused by chlaride contamination Affected Lines replaced W/880418 itr.
 PASTYAM. J. DIETZ, G.R. Carolina Power & Light Co. 88/04/18. 6pp 45281:300-45281:305.

DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8804060317 Forwards Insp Repts 50:325/88-12 & 50:324/88-12 on 880222-25 No viofations or dewistions noted HERDTJAR. Reg on 2, Old of the Director. 88/03/29 UTLEY,E.E. Carolina Power & Light Co. 2pp. 45072.052-45072.060.
- --8804060319 Insp Repts 50:324/88-12 & 50:325/88-12 on 880222-25.No violations or deviations noted Mejor areas inspected tire protection/prevention,review of status of App R fire protection mods & previously identified insp Itams. WISEMAN,G.R. Reg on 2, Ofc of the Oirector. 88/03/22. 7pp 45072 054-45072.080.
- 8804150385 "Rev Plant Emergency Procedures." W/880330 IIr DIETZ,C R. Carofina Power & Light Co. 88/03/30 GRACE,J.N. Region 2, Old of the Director. 2pp. 45138 309-45138.310.
- 8804180454 Forwards Rev 25 to emergency response plan & revised emergency plan Implementing procedures, including Rev 8 to PEP-02.6.12, "Operational Support Ctr Leader" & Riev 8 to PEP-04.3, "Performance of Training, Exercise & Drills." DIETZ,C.R. Carolina Power & Light Co. 88/03/30, GRACE,J.N. Region 2, Ofc of the Director, 2pp. 45170,119-45170:164.
- --8804180461 Riev 25 to Vol 13,80ok 1 to "Emergency Response Plan." SMITH,J.S. Carolina Power & Light Co. 88/03/30, 22pp. 45170:143.45170:164.
- 8804270069 Forwards revs to emergency procedures including Rev 4 to PEP-2.6.1 re plant operations director & Rev 1 to PEP-02.6.22 re technical assessment director.List of revs to procedures encl W/o procedures.

 DIETZ,CR. Carolina Power & Light Co. 88/04/11, GRACE,J N. Region 2, Orc of the Director. 2pp. 45245-282-45245-283.
- 8804200473 Parkal response to FOIA request re fire protection.Forwards App E documents App D & E documents available in PDR.App F document completely withheld (ref FOIA Exemption 5).

 GRIMSLEY,D.H. Division of Rules & Records (Post 870413), 88/04/14, JONES,C R. Affaliation Not Assigned. 5pp. 45206.037-45208.043.
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type insp for each facility to assess status of compilance w/ 10CFR50 48.Program issed. CONLON.T.E. Region 2, Oft of the Director. 34/11/06. HERDT, A.R. Region 2, Otc of the Director. 3pp. 45208:176-45208:178.

J. Insurance & Indemnity information

- 8804070174 Submits Info re present level & source of onside property damage insurance. LOFLINI.L. Carolina Power & Light Co. 88/03/31. Document Control Branch (Document Control Desk). 1p. 45075/258-45076:256.
- 8804250219 Forwards Endorsement 59 to MAELU Policy MF-80, BARHAM,C.D. Carolina Power & Light Co. 88/04/04, NASH,D. NRC - No Data led Aflifiation Given. 2pp. 45212.230-45212:231.
- 8804250221 Forwards Endorsement 69 to NELIA Policy NF-218.

 BARHAM,C.D. Carolina Power & Light Co. 88/04/04. NASH,D. NRC No Dotalled At-filiation Given. 2pp. 45212:232-45212:233.

P. Operating license stage documents & correspondence

- 8803080108 Forwards SER supporting proposed functional testing plan for shubbers Proposed plan meets ASME Code,Section XI requirements & complies w/ Tech Spec 4.7.5 requirements so relief request deemed unnecessary.

 ADENSAME. Project Directorate II-1. 88/03/02. UTLEY.E.E. Carolina Power & Light Co. 2pp. 44633:305-44633:306.
- -8803080118 Safety evaluation supporting proposed functional testing plan for snubbers.

 * Project Directorate II-1, 88/03/02, 2pp. 44633,307-44633,308.
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svo list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York Inc. 430, 48073-182.

- 6804040040 Advises that util has now staffed shift technical advisor program w/appropriately trained personnal so that contract engineers no longer needed. LOFLINL1 Carolina Power & Light Co. 88/03/24. Document Control Branch (Document Control Desk) 1p. 44969.034-44969.034.
- 8803310223 Forwards revised Rel of Requests PR-05,VR-15,VR-16 & VR-17 re inservice testing program for svc water lubricating sys. per 870721-22 meeting commitment Svc pumps will be modified to provide internal self-lubrication RICHEY R B. Carolina Power & Light Co. 88/03/28. Occument Control Branch (Document Control Dask) 7pp. 45000.336-45000.342.
- 8804110227 Forwards Amends 117 & 147 to Licenses DPR-71 & DPR-62, respectively & safety evaluation. Amends change Tech Specs to revise Table 4.4.6.1.3-1 re reactor vessel mail surveillance test. SYLVESTER,ED Project Directorate II-1. 88/04/04. UTLEY,E.E. Carolina Power & Light Co. 3pp. 45071.341.45071.358.
- --8804110236 Amends 147 & 117 to Licenses DPR-62 & DPR-71 respectively, changing Tech Specs to revise Table 4.4.6.1.3-1 to require removal of second & third surveillance capsules after results of first capsule evaluated & added to Tech Spec. ADENSAM,E G. Project Directorate II-1. 88/04/04 10pp. 45071.344-45071.353
- --8804110240 Safety evaluation supporting Amends 147 & 117 to Licenses DPR-62 & DPR-71, respectively.

 'NRC No Detailed Athilation Given, 88/04/04, 5pp. 45071;354-45071;358.
- 8804120348 Supplemental application for amends to Licenses DPR-71 & DPR-62,re-moving specific safety I mit min critical power ratio value from Tech Spec Bases Section 2.2.1.1 & Toch Spec Sections 3.1.4.3 & 3.3.4.
 EURY,L.W. Caronna Power & Light Co. 88/04/05. Document Control Branch (Document Control Desk). 9pp. 45146.046-45146.061.
- --8804120350 Proposed Tech Specs (e elimination of cycle specific variables.

 * Carolina Power & Light Co. 88/04/05, Bpp. 45146.054-45146.061.
- 8804120287 Forwards response to NRC 880308 request for addl info re optical disk storage sys for microforming plant records. LOFLIN.L.I. Carolina Power & Light Co. 88/04/08. Document Control Branch (Document Control Desk). 4pp. 45080.071-45080.074.
- 8804120434 Forwards corrected Bases Pages B 3/4 4-1,8 3/4 4-2 & B 3/4 4-3,restoring into inadvertently removed from Sections 3/4,4.2 & 3/4,4.3 1. LOFLIN_L.I. Carolina Power & Light Co. 88/04/06. Document Control Branch (Document Control Dask), 1p. 45091 010-45091:017.
- 8804120450 Corrected Tech Specs Bases Pages B 3/4 4-1,B 3/4 4-2 & B 3/4 4-3,restoring info inadvertently removed from Sections 3/4.4.2 & 3/4.4.3.1.
 Carolina Power & Light Co. 88/04/08. 7pp. 45091:011-45091:017.
- 8804080088 Generic Ltr 88:07 to power reactor licensees & applicants re-modified enlorcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc list and: M/RAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804270088 Discusses util reconsideration of commitment to reduce low Lovel 2 water level salpoint provided in 871013 updated status of facility strategy for avoiding partial low Level 2 initiations/isolation on scrams. DIETZ.C.R. Carolina Power & Light Co. 88/04/12. GRACE.J.N. Region 2, Ofc of the Director. 1p. 45244:360-45244:360.
- 8804210411 Notification of 880419 meeting w/util in Rockville,MD to discuss util design of nitrogen pneumatic sys for operation of pneumatic valves inside drywell. SYLVESTER.E.D. Project Directorate 11-1. 88/04/15. MURLEY.T., SNIEZEK,J., MIRAGLIA,F. NRC No Detailed Affiliation Given. 3pp. 45191:135-45191:137.
- 8804280160 Forwards corrected pages to Amends 116 & 144 to Licenses DPR-71 & DPR-82,respectively. Amend inadvertently issued w/ incorrect amend numbers on bottom of two pages.

 SYLVESTER,E.O. Project Directorate II-1, 88/04/19, UTLEY,E.E. Carolina Power & Light Co. 2pp. 45276:215-45279:218.
- --8804280162 Corrected pages to Amends 116 & 144 to Licenses DPR-71 & DPR-62, respectively.
 NRC No Detailed Affirlation Given, 88/04/18, 2pp. 45276;217-45276;218.

- 8803300079 Forwards Insp Repts 50-324/88-06 & 50-325/88-06 on 880125-29 & notice of violation.
 HERDT,A.R. Region 2, Otc of the Director, 88/03/10, UTLEY,E.E. Carolina Power & Light Co. 2pp. 44920.056-44920:075.
- --8803300080 Notice of violation from insp on 880125-29 Violation noted: applicable ASME test requirements not met & procedures did not contain steps or criteria which would assure conformance of testing to ASME requirements. HERDT, A.R. Region 2, Ofc of the Director. 88/03/10. 3pp. 44920.058-44920:060.
- --8803300083 Insp Repts 50:324/88:06 & 50:325/88:06 on 880125-29. Violations noted Major areas inspected:area of Inservice testing of pumps & valves. GIRARD,E.H., BLAKE,J.J. Region 2, Oic of the Director, 88/03/02, 15pp. 44920:061-44920:075.
- 8803280135 Forwards Insp Repts 50-324/88-02 & 50-325/88-02 on 880111-15,19-22 & 0131-0205 No violations or deviations noted.
 HERDT,A R. Region 2, Oto of the Director. 88/03/11. UTLEY,E.E. Carolina Power & Light Co 2pp. 44921.046-44921:080.

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors." Svc list enci.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/03/28.

 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995.246.
- 8803220296 NRC Info Notice 88-010, "Malls Licensees.Lack of Mgt Controls Over Licensed Programs." Svc let encl. CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995;353.
- 8804060231 Ack receipt of 680309 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-324/87-43 & 50-325/87-42.Based on util position on definition of deactivate, response being forwarded to NRR for review. VERRELLI,D.M. Region 2, Otro of the Director. 88/03/29. UTLEY,E.E. Carolina Power & Light Co. 1p. 45007:316-45007:316.
- 8804060317 Forwards Insp Repts 50-325/88-12 & 50-324/88-12 on 880222-25 No vio-lations or deviations noted. HERDTA.R. Region 2, Oic of the Director, 88/03/29, UTLEY,E.E. Carolina Power & Light Co. 2pp. 45072.052-45072.060.
- --8804060319 Insp Repts 50-324/88-12 & 50-325/88-12 on 880222-25.No violations or deviations noted Major areas inspected. It protection/prevention, review of status of App R fire protection mode & previously identified insp Items. WISEMAN,G.R., CONLON,T.E. Region 2, Ofc of the Director. 88/03/22, 7pp. 45072.054-45072.060.
- 8804050353 Forwards Insp. Repts 50-325/88-05 & 50-324/88-05 on 880201-29 No vio-lations or deviations noted Unresolved Items (dentified. VEARELLI,D.M. Region 2, Oto of the Director. 88/03/30 UTLEY,E.E. Carolina Power & Light Co. 2pp. 45045:229-45045:244.
- -- 8804050354 Insp Repts 50-324/86-05 & 50-325/86-05 on 880201-29.No violations or devations noted Major areas inspected: previous enforcement matters,maint observation.survettlence observation & hydrogen leak/unusual event.

 RULAND.W.H. FREDRICKSON,P. Region 2, Otc of the Director. 88/03/30. 14pp. 45045:231-45045:244
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr 8/or Switch-board Function Due to Faulty Tie Bolts." Svc list encl. ROSSLC.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804130350 Responds to violations noted in Insp Repts 60-324/88-06 & 50-325/88-O6 Corrective actions periodic test procedures revised to specify method for stroke time testing air-operated valves DIETZ,CR. Carolina Power & Light Co. 88/04/08. Document Control Branch (Document Control Desk). 8pp 45154:330-45154:335.
- 8804210218 Responds to NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakers." Unit determined that Westinghouse DS series circuit breakers not used in Class 1E sys. EE sys. EURY.L.W. Carolina Power & Light Co. 88/04/08, GRACE,J.N. Region 2, Olc of the Director. 1p. 45235:287-48235:287.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list enct ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165;028-45165;160.
- 8804200516 Forwards response to violations noted in Insp Repts 50-324/88-01 & 50-326/86-01. Shift operations personnel trained on importance of meeting surveillance times. Timers also provided to personnel. DIETZ.CR. Carolina Power & Light Co. 86/04/13. Document Control Branch (Document Control Desk). 3pp. 45218:277-45218:279.
- 8804200473 Partial response to FOIA request re lire protection.Forwards App E documents App D & E documents available in PDR.App F document completely withheld (ref FOIA Exemption 5).
 GRIMSLEY.D.H. Division of Rules & Records (Post 870413), 88/04/14. JONES,C.R. Affiliation Not Assigned. 5pp. 45206:037-45206.043.

- ~8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type Insp for each facility to assess status of compliance w/ 10CFR50.48,Program listed.
 CONLON,T.E. Region 2, Ofc of the Director, 84/11/06, HERDT,A.R. Region 2, Ofc of the Director, 3pp. 45206:178.45208:178.
- 8804260242 Forwards revised Page 2 & Encl 2 re Insp Repts 50:324/88-05 & 50:325/88-05 880330 transmittal fit.Encl 2 inadvertently omitted during submittal of rept. VERRELLI,D.M. Reglon 2, Ofo of the Director. 88/04/14, UTLEY,E.E. Carolina Power & Light Co. 8pp. 45282:078-46282:083.
- 8804200098 Responds to violations noted in Insp Repts 60:324/88-09 & 50:325/88-09. Corrective actions:radiation control supervisor conducted training sessions w/operations personnel & E&RC Procedure 0230 revised to clearly state requirements. DIETZ.C.R. Carolina Power & Light Co. 88/04/15. Document Control Branch (Document Control Desk). 7pp. 45218:227-45218:233.
- 8804270106 Forwards request for addl Info re util 860513,0829,1002 & 880304 responses to Bulletin 86-003, "Motor-Operated Valve Common Mode Fallures During Plant Transients Due to Improper Switch Settings." Info requested within 30 days of the
- date. HERDT,A.R. Region 2, Ofo of the Director, 88/04/18, UTLEY,E.E. Carolina Power & Light Co. 3pp. 45241:245-45241:247,
- 8804290277 Ack receipt of 880408 lir informing NRC of steps taken to correct violations noted in Insp. Repts 60-324/88-06 & 50-325/88-08. Engineering evaluation rept clarifying numeric limits for abnormal or erratio data requested by 880503.
 HERDT, AR. Region 2, Ofic of the Director. 88/04/25. UTLEY,E.E. Carolina Power & Light Co. 2pp. 45283:075-45283:076.

8803300324 Monthly operating repts for Feb 1988,W/880303 kr. HARRISON,F., DIETZ,C.R. Carolina Power & Light Co. 88/02/29. SCROGGINS,R.M. Office of Administration & Resources Management, Director (Post 870413). 9pp. 44961:058-44961:058.

S. Reportable occurrences, LERs & related correspondence

- 8803290251 LER 88-006-00 on 880218,existence of common mode failure mechanism involving carriage botts refermined Caused by overforquing of botts due to error in drawing 8/or procedures Failed botts replaced w/880321 ftr. PASTVA,M.J., DIETZ,C.R. Carolina Power & Light Co. 88/03/21, 16pp. 44921.149-44921:164
- 8804080277 LER 88:008:01 on 880302 determined that generic failure mechanism existed for supply fans of common diesel generator bldg ventilation sys.Caused by cracks due to frequent stop & start A & B rotors repfaced.W/880331 lfr. PASTVA.M.J., DIETZ,C.R. Carolina Power & Light Co. 88/03/31, 11pp. 45046.142-45046:152.
- 8804070163 LER 87-020-01:on 870703 reactor safety relief valve failed to open when given manual open signal despite attempt made to control pressure following 870701 reactor scram Caused by excess Locate on interior of valves.W/880331 lir. PASTYAM J. DIETZ,C R. Carolina Power & Light Co. 88/03/31. 5pp 45076.105-16724.00
- 8804110041 LER 88-009-00 on 880309 primary containment Group 6 isolation of reactor bidg ventilation sys & auto start of standby gas treatment sys Trains A & B occurred Caused by accidental opening of circuit breaker.W/880405.

 PASTVA,M.J., DIETZ,C.R. Carolina Power & Light Co. 88/04/05. 4pp. 45121:131-

DOCKET 50-326 UNIV. OF CALIFORNIA AT IRVINE RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250184 Informs of relocation of NRR to Rockville,MD.Official mailing address still remains same & project managers have new locations & phone numbers.TS Michaels still lead project manager for facility & A Adams will serve as backup. RUBENSTEIN,LS Standardization & Non-Power Reactor Project Directorate. 88/03/18. Alfiliation Not Assigned. 3pp. 44856:322-44856:324.

O. Inspection reports, IE Bulletins & correspondence

- 8804190377 Ack receipt of 880404 ltr Informing NRC of steps taken to correct violations noted in Insp Rept 50-326/88-01.Position re calibr of emergency air sampling air flow or vol matering devices stated in Paragraph C of Reg Guide 8.25. WENSLAWSKI,F.A. Region 5, Oct of Ine Director. 88/04/11. LILLYMAN,W.J. Cahlornia, Univ. of, Irvine, CA. 1p. 45225:275-45225:280.
- --8804190379 Responds to NRC 880303 ltr re-violations noted in Insp. Rept. 50-326/88-01. Corrective actions teview sheet being created to assure review of all checklists during insps & roactor supervisor & radiation safety officer reviewed issues. LILLYMAN,W.J. Celtidorina, Univ. of, Irvine, CA. 68/04/04. SCARANO,R A. Region 5, Old of the Director. 3pp. 45225:276-45226:280.

DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8804130374 Rev 31 to radiological emergency plan.W/880408 ltr. GRIDLEY,R. Tennessee Valley Authority, 88/03/11, 9pp. 45154:090-45154:098.
- 8904010258 Confirms notification to NRC of conditions of entry into Limiting Condition for Operation 3.7.11.1,Action b.of plant Tech Specs for facility re 880320 event involving inoperable lire pumps.

 SMITH.5.J. Tannesse Valley Authority, 88/03/21, Region 2, Otc of the Director. 1p. 45058:101-45058:101
- 8804010073 Summary of 880309 meeting w/TVA in Rockville,MD re technical issues related to 10CFR60,App R.Attendance list, transcription,agenda & meeting handout
- ROTELLA,T.S. Oto of Special Projects. 88/03/22. Ofc of Special Projects. 2pp. 44950,339-44951;163.
- --8804010078 Transcript of 880309 meeting in Rockville,MD re 10CFR50,App R Issues.Supporting documentation encl.
 * Commissioners. 88/03/09. 173pp. 44950 341-44951:153.
- 8804250068 Forwards Insp Repts 50-327/88-21 & 50-328/88-21 on 880303. No violations or deviations noted. BARR,K.P. Ofc of Special Projects. 88/03/28, WHITE,S.A. Tennessee Valley Authority. 2pp. 45231:302-45231:304.
- -8804250070 Partially Withheld Insp Repts 50-327/88-21 8 50-328/88-21 on 880303.No Violations noted Major areas inspected previously identified vital area barrier leaves & followup to licensee Inspector general ofc Investigation of alleged drug USB. MASNYK,O.M., MCGUIRE,D.R. Region 2, Ofc of the Director, 88/03/18. tp. 46231:304-46231:304.
- 8804180250 Forwards Rev 18 to physical security & contingency plan Rev withheld (ref 10CFR73.21).
 GRIDLEY,RL. Tennessee Valley Authority, 88/04/07. Document Control Branch (Document Control Desk). 2pp. 45195:335-45195:336.
- 8804130296 Forwards Fire Protection Insp Repts 60-327/88-24 & 50-328/68-24 on B80314-18. Violation noted under consideration for escalated enforcement action. No notice of violation being issued. EBNETER, S.D. Otc of Special Projects. 88/04/08. WHITE, S.A. Tennossed Valley Authority. 2pp. 45151:067-45181:136.

8804150279 Temporary Instruction Change Form ICF-88-0595 to Rev 13 to Radiological Emergency Plan Implementing Procedure IP-17, "Emergency Equipment & Supplies " W/880411 ltr.

GRIDLEY R Tennessee Valley Authority, 89/04/11, 11pp, 45138,148-45138,158

8804200484 Forwards addit into requested by NRC App R inspiteam during 880314-18 inspin/o includes revised response to Question 4,4mended response to Question 12 & addition on Question 18. GHIDLE VR. Fennessee Valley Authority. 88/04/13. Document Control Branch (Document Control Desk). 800pp. 45171:203-45174.073.

8804260021 Forwards Insp Repts 50-327/88 18 & 50-328/88-18 on 680307-11 & 18 &

- notice of violation.

 BARRIX.P. Otc of Special Projects 88/04/13: WHITE,S.A. Tempessee Valloy Authority 2pp. 45248 114-45248.123
- -8804260025 Notice of violation from insp on 880307-11 & 18.Violation noted technical support of communicator last received required training in Aug 1986 BARR,K.P. Oto of Special Projects. 88/04/13, 2pp. 45248.116-45248.117.
- -8804260028 Insp Repts 50.327/88-18 & 50.328/88-18 on 880307-11 & 18 Violation noted Major areas inspected review & evaluation of emergency preparedness program KREH.J.L., DECKEH,T.R. Ofc of Special Projects 88/03/31, 2pp 45248.118-45248.123.
- 8804260040 Forwards Insp Repls 50:327/88:22 & 50:328/88:22 on 880319: 0402 One unresolved item noted to closed auxiliary feedwater block valve Response addressing tool cause & corective actions requested within 30 days of til date. MCCOV,F R. Otco 1 Special Projects 88/04/13. WHITE,S A Tennessee Valley Authority. 2pp 45268 217:45268:237.
- -8804260042 Insp. Repts 50-327/88-22 & 50-328/88-22 on 880319-0402 No violations noted Major areas inspected extended control room observation & operational safety venfication, including operations performance, systimoups & saleguards.
 LONG, A.A., JENISON, K., BRANCH, M., Region 2, Ofc of the Director, 88/04/13, 19pp 45268:219-45268-237
- 8804180257 Forwards Rev. 14 to security personnel training & qualification planifles GRIDLEY, R.L. Tonnessee Valley Authority, 88/04/14. Document Control Branch (Document Control Desk). 2pp. 45195:338-45195.339.
- 8804200473 Partial response to FOIA request re fire protection Forwards App E documents App D & E documents available in PDR App F document completely withheld (rol FOIA Examption 5).
 GRINASEEY,D.H. Division of Rules & Records (Post 870413), 89/04/14. JONES,C R Affiliation Not Assigned. Spp. 45206.037-45206.043.
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type hap for each facility to essess status of compriance w/ 10CFR50.48.Program issted CONLON, E. Region 2, Oic of the Director, 3pp. 45206.176.45208.178.
- 8804220250 Revised emergency plan implementing procedures.including Rev 0 to CECC-EPIP-1, "Emergency Duty Officer Procedure for Notification of Unusual Event, Alert, Site Area Emergency & General Emergency," W/880420 tr. GRIDLEY, R.L. Tonnessee Valley Authority, 88/04/20 400pp. 45229.308-45230:322.
- 8804280095 Forwards radiological emergency plan implementing procedures document audit of controlled riccuments GRIDLEY,R. Tennessee Valley Authority, 88/04/21, Document Control Branch (Document Control Deek) 19pp 45281:254-45281272.

H. General correspondence

- 8804220050 Responds to 880302 ltr.torwarding P Pierce III expressing concern re cost of util operator uniforms Malter of util uniform cost outside purview of NRC. STELLO,V. Oic of the Executive Oirector for Operations 88/04/14 DUNCAN,J.J. House of Rep. 4pp. 45201.005-45201.011
- -8804220054 Forwards P Pierce ltr re cost of util operators uniforms for consideration & responso DUNCAN,J.J. House of Rep. 88/03/02. Congressional Affairs. 3pp. 45201.009-

J. Insurance & indemnity information

- 8804050067 Forwards status & details of property insurance coverage for facilities per 10CFR50.54 for Info.
 GRIDLEY,R. Tennessee Valley Authority, 88/03/30, Document Control Branch (Document Control Branch (Document Control Desk), 3pp. 44995.356-44995.358.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8804260371 Amend 5 to updated FSAR for Sequoyah Nuclear Plant.W/880420 ltr. GRIDLEY,R. Tennessee Valley Authority, 88/04/20, 1,200pp 45315:001-45318;147.
- O. Advisory Committee on Reactor Safeguards reports & correspondence
- 8804 140215 Submits summary of actions discussed at ACRS 335th meeting on 880310-12 in Washington,DC,Including ACRS repts/ recommendations,other actions, agreements, assignments & requests & future agends. KERR,W. ACRS Advisory Committee on Reactor Safeguards 88/03/24, ZECH,L.W. Commissioners. 4pp. 45118:172-45118.175.

8804040111 Forwards ut1 response to ACRS questions from 880212 meeting w/full ACRS committee in Washington,DC Util will begin screening of LERs of sister plants to Sequoyah & Browns Farry Nuclear Plants to determine if any actions required GRIDLEYR. Tannessee Valley Authority. 88:703/30. Document Control Branch (Document Control Desk). 4pp. 44970 232-44970 235.

P. Operating license stage documents & correspondence

- 8803080517 Notification of 880308 meeting w/util in Rockvillo,MD to discuss technical issues re electrical cable tray/conduit separation. ROTELLA,T.S. Ofc of Special Projects. 88/03/04. ZECH,G G. Ofc of Special Projects 3pp. 44039 055-44639.057.
- 8803240426 Generio Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list end. MIRAGLIA.F.J. Associate Director for Projects (Post 870411) 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804120213 Requests that immediate emergency action be taken in form of order suspending full power operation of plant until remediat action can be taken. Basis for request is failure of util to meet requirements of Rog Guides 1.9 & 1.108.

 BATES,A.K. Natural Rights Center. BATES,A.K. Bates, A.K. B8/03/24. ZECH,L.W. Commissioners. STELLO.V. Ofc of the Executive Director for Operations. MURLEY,T. Office of Nuclear Reactor Regulation, Director (Post 870411). 2pp. 45091:262-45091:263.
- 8804050313 Forwards second revised preliminary SER re plant performance planedding new or modified sections concerning design control civil & electrical calculations & App R.per 880121 & 0217 Itrs.Final evaluation will be issued as NUREG-

EBNETER,S.O. Otc of Special Projects. 88/03/25. WHITE,S.A. Tennessas Valley Authority. 361pp. 44998.001-44998:361.

- 8803310263 Denies 880324 request for emergency relief Remainder of request will be treated as polition for enforcement action under 10CFR2 206 & will issue director's decision shortly. Lit relised no new issues not already considered by NRC. EBNCTERS.O. Otc. of Special Projects. 88/03/28. BATES,A.K., Natural Rights Conter. 3pp. 44949.175-44949.178.
- 8804070199 Forwards TVA employee concerns lask group subcategory repts RUSSELL,J.R. Tennessee Valley Authority. 88/03/28. Document Control Branch (Document Control Desk). 5pp. 45022:145-45024:257.
- --8804070203 Rev 3 to Employee Concerns Special Program Subcategory Engineering Rept 25000, "Civil/Structural Design (21500) & Pipe Whip Restraint Design (22700)." BENKERT,J.W. Tennessee Valley Authority. 88/03/21. 89pp. 45022:150-45022-238.
- --8804070224 Rev 6 to Employee Concerns Special Program Subcategory Repl 80200, KENZIE, L.G. Tennessee Valley Authority, 88/03/18, 152pp. 45022 335-45023.126.

--8804070234 Rev 6 to Employee Concerns Special Program Subcategory Rept 80400. "Nonconformance Control & Corrective Action." HALVERSON.R.D Tennessee Valley Authority. 86/03/14, 491pp. 45023;127-45024.257

- 8804040016 Forwards 14th update of activities list.in accordance w/ 860717 submitted of plant performance planttems that have been reopened listed in Encl 2 Items that have final disposition listed in Encl 3. GRIDLEY.R. Tennessee Velley Authority, 88/03/29. Document Control Branch (Document Control Desk), 40pp. 44969.076-44969.115.
- 8804040076 Notifies of proposed use of sodium bromide in addition to sodium hypo-
- Chipmen RERCW sys to control blofouling Use of bromities in abortion to somium hypo-chipmen RERCW sys to control blofouling Use of bromitide reduces total residual chip-rine 8 aids in compliance w/NPDES permit Info on products being considered encl. BRODKS.R.H. Tennessee Valley Authority. 88/03/30. SINCLAIR.R.M. Tennessee, State of, 88pp. 45031:321-45032.058.
- 8804060440 Documents differences between util programs planned for restart of Unit 1 & programs used for restart of Unit 2. Nuclear performance plan will be revised to include detailed info on four Unit 1 programs by 880429. New commitments encl. GRIDLEY,R. Tennessee Valley Authority. 88/03/31. Document Control Branch (Document Control Beach & Spp. 45007.051-45007.058).
- 8804110226 Forwards safety evaluation & technical evaluation rept re program for mi-crobiologically induced corrosion (MIC) control in ERCW sys.TVA insp.evaluation & repair program for MIC capable of safety function. ZECH.6.G. Otc of Special Projects. 88/03/31, WHITE,S.A. Tennessee Valley Author-ity. 3pp. 45078:112-45078:125
- -8804110229 Safety evaluation supporting microbiologically induced corrosion (MIC) program in ERCW sys.
 * Olic of Special Projects, 86/03/31, 11pp, 45078:115-45078:125.
- 8804070057 Forwards listing of employee concern numbers shown on util data base as NRC responsibility for evaluation not included in 861231 submittal Requests ack of re-Sponsibility.
 RUSSELL,J.R. Tennessee Valley Authority. 88/04/01. Document Control Branch (Document Control Desk). 7pp. 45075:038-45075:042.
- 8804050417 Provides supplemental response re microbiologically induced corrosion program Correct Preventive Maint Instructions 2241 & 2242,reptace 2240 & 2241, respectively,per util 880120 ltr. GRIDLEY,R. Tennessee Valley Authority, 88/04/04. Document Control Branch (Document Control Desk), 2pp. 45078:160-45078:181.
- 8804060427 Forwards addition form of relief request from ASME Code Section XI re microbiologically induced corrosion (MIC) program.per NRC 880318 request.MIC program will ensure that structural integrity of ERCW piping maintained.
 GRIDLEYR. Tennessee Valley Authority. 88/04/04: Document Control Branch (Document Control Desk). 5pp. 45073:356-45073:360.

IIY JPP 43110 270 43110.799

- -8804140097 Amends 69 & 61 to Licenses DPR-77 & DPR-79, respectively, revising Tech Specs to separately define operability & surveillance requirements for RHR spray trains ZECH.G.G. Old of Special Projects 88/04/04 18pp. 45118 279 45118 296.
- -8804140101 Safety evaluation supporting Amends 69 & 61 to Licenses DPR-77 & DPR-79-respectively-* Olc of Special Projects: 68/04/04. 3pp. 45118 297-45118 299.
- 8804120090 Forwards suppl to consultants 880325 ltr re review of diesel generators at plant.
 STELLQV. Old of the Executive Director for Operations, 88/04/09, ZECH, ROBERTS, BERNTHAL Commissioners, 1p. 45101,004,45101,006.
- --8804120105 Forwards suppl to 880325 ltr re plant diesel generators. Suppl replaces Item 4. "Tests on Diesel Generators" & clarifies ltr concerning tests required by Reg Guido 1.108 KUSKO, A. PEERAN, S.M. Failure Analysis Associates 88/03/28 MARINOS, A. NRC No Detailed Affiliation Given 2pp. 45101.005-45101.006.
- 8804080088 Generic Lir 88:07 to power reactor I censees & applicants re-modified en-forcement policy concoming 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants:" Svc list oncl MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consol dated Edison Co. of New York, Inc. 49pp. 45164:237-45164.285.
- 8804130392 Notification of 880425-26 meeting w/util in Soddy Dalsy,TN to discuss status of licensing actions on facility DONOHEW,J N. Ofc. of Special Projects. 88/04/07. ZECH,G.G. Ofc. of Special Projects 3pp. 45104-046-45104-048
- 8804140176 Notification of 880414-15 meetings w/util in Rockvilla,MD to discuss tech-nical details of differences in civil design calculation program & closure of Bulletin 79-

DONOHEW.J.N. Ofc of Special Projects 88/04/07, ZECH,G.G. Ofc of Special Projects 3pp 45118:146-45118:148.

- 8804150048 Notification of 880421 meeting w/TVA in Rockville,MO to discuss technical details of loss of downstream dam & on Unit 1 differences in design baseline & verification program from that described in Jul 1987 per
- 8804140006 Forwards followup rept to 880309 fishkill.Initial notification made by tele-phone on 880309.Water analysis could not uncover causative agent for fishkill Fish probably stressed by aligne bloom State of TN concurs. GRIOLEV,R. Tennessee Valley Authority, 88/04/08. Document Control Branch (Docu-ment Control Dask). 3pp. 45147:340-45147:342.
- 8804280286 Corrected notification of 880504 meeting w/util in Rockville,MD to discuss technical datals of loss of downstream dam DONOHEW,J.N. Ofc. of Special Projects 3pp. 45264:057-45264:059.
- 8804290151 Forwards FR notice ack receipt of 880324 potition & stating that petition being treated per 10CFR2.206. ERNETER,S.D. Ofc of Special Projects. 88/04/22. BATES,A.K. Bates, A.K. 1p. 45322.197-45322.200.
- -8804290164 Notice of receipt of getition for Director's Decision under 10CFR2 206 for Commission order suspending full-power plant operation until remedial action taken Request for emergency relief denied Further action per 10CFR2 206 pending EBNETER,S D. Otc of Special Projects 88/04/22 3pp. 45322:198 45322 200.

Q. Inspection reports, iE Builetins & correspondence

- 8803290349 Forwards Insp Repts 50-327/87-73 & 50-328/87-73 on 871026-30 & notice of violation.

 BARR,K.P. Old of Special Projects, 88/03/09, WHITE,S.A. Tennessee Valley Authority, 2pp. 44952-236-44952:292.
- -8803290352 Notice of violation from insp on 871026-30 & 880104-14. Violation noted:icensee falled to perform or fared to adequately perform written safety evaluations for 15 mods. BARR.K.P. Old of Special Projects. 88/03/09. 2pp. 44952-238-44952.239.
- -- 8803290355 Insp Repts 50:327/87-73 & 50:328/87-73 on 871026:30 & 880104-14. Violations noted Major areas inspected testing activities, liant heatup procedure & TVA operational reachness essessment & compensatory measures. BRANCH,M., MCCOY,F. Region 2, Ofc of the Director, 88/03/04, 51pp. 44952:240-44952-292
- 8803290366 Forwards Insp. Repts 50-259/67-38,50-260/87-36,50-296/87-38-50-327/ 87-68,50-328/87-68,50-390/87-18,50-391/87-18, 50-438/87-08-8-50-439/87-08 on 87-1005-18-8 notice of violation. BARR,K.P. Region 2, Ofc of the Director, 88/03/09, WHITE,S.A. Tennessee Valley Authority, 3pp. 44975:195-44975:208.
- -- 9803290390 Notice of violation from Insp on 871005-18. Violations noted: inadequate div of nuclear engineering training & records, inelfective followup on euclid findings & improper correction of QA records.
 BARR, K.P. Region 2, Ofc of the Director. 88/03/09. 3pp. 44975:198-44975:200.
- -- 8803290393 Insp Repts 50-259/87-36,50-260/87-38,50-296/87-38, 50-327/87-68,50-328/87-68,50-390/87-18, 50-338/87-08 & 50-439/87-08 Violations noted. Major areas inspected: allegations & Ilcensee action on identified items. WALTON,G.A. Region 2, Otc of the Director, 88/03/08, 8pp. 44975:201-44975:208.

- Valley Authority 3pp 45028 035-45028 040.
 - --8804010060 Notice of violation from insps on 870406 0505 & 0508 0612. Violations noted on 870201,sys real-grament improvised w/o written or formally approved instructions & on 870201,live valves shut down w/o entry into configuration log. RICHARDSON,S D. Regon 2, Ofc of the Director. 88703714 3pp. 45026.038 45028-040

DIECLUL DOLUGITA, WHILE S.A. TENRESSEE

- 8804010037 Ack receipt of 880216 fit informing NRC of steps taken to correct violations noted in Insp Repts 50-327/87-52 & 50-328/87-52 RICHARDSON,S D. Old of Special Projects 88/03/21 WHITE,S A Tennessee Valley Authority
- 8804010023 Forwards Special Team Insp Repls 50:327/88:08 & 50:328/88:08 on 880111+15 & 25:29 No violations or daviations noted. BARR.K.P. Old of Special Projects. 88/03/22 WHITE,S A Tennessed Valley Authority 2pp 45028:127-45028:145
- --8804010025 Insp Ropts 50-327/69-08 & 50-328/88-08 on 880111-15 & 0125-29 No violations or deviations noted Major areas inspected layup & preservation of equip-YORK, J., WALTON, G., ELROD, S. Hegion 2, Ofc of the Director. 88/03/18 17pp 45028:129-45028:145.
- 8804080249 Forwards Insp Ropis 50.327/88-17 & 50.328/88-17 on 880212-25 & notice of violation this Indings identified what appears to be add example of previous violation to staff overlime limits Unresolved item noted.

 MCCOY,F.R. Old of Special Projects. 88/03/24. WHITE,S.A. Tennossee Valley Authority, 3pp. 45046 204-45046:234.
- --8804080252 Notice of violation from insp on 880212-26 Violations noted, maint activities on Valve 2-LCV-62-118 not adequately described or implemented, resulting in inadvertent diversion of approx 465 gallons of RCS water to holdup lank MCCOY,F.R. Old of Special Projects. 88/03/24, 2pp. 45046/207-45046.208.
- --8804060255 Insp Ropts 50-327/88-17 & 50-328/88-17 on 880212-26 Violations noted Major areas inspected:confrol room observation & operational safety vent-cation,including operations performance & systimoups JENISON,K. BRANCH,M. HUNEGS,G. Region 2, Ofc of the Director. 88/03/22. 24pp. 45046.209-45046:234.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors." Svc list encl.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995:128-44995:246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees Lack of Mgt Contro's Over Liconsed Programs " Svc list onc! CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353.
- 8804080185 Forwards Insp. Repis 50-327/85-15 & 50-328/88-15 on 880208-12.No vio-lations or devisitions noted MCCOY,F.R. Region 2, Olc of the Director, 88/03/28, WHITE,S.A. Tennessee Valley Authority, 2pp. 45/100/235-45100.267.
- ---8804080188 Insp Ropts 50-327/88-15 & 50-328/88-15 on 880208-12 No violations or deviations noted Major areas inspected LER followup, action on previous 1nd ngs, info notices, potential RO & problom indontification repts.

 JENISON, K., HUNEGS, G., MCCOY, F. Reg on 2, Ofc of the Director. 88/03/30. 31pp. 45100:237-45100:267.
- 8804250066 Forwards Insp Repts 50-327/68-21 & 50-326/68-21 on 880303. No violations or deviations noted BARR,K.P. Otc of Special Projects 88/03/28, WHITE,S.A. Tennessee Valley Authority, 2pp. 45231:302-45231.304.
- use. MASNYK,O.M., MCGUIRE, D.R. Region 2, Old of the Director, 88/03/18, 1p.
- 8804040272 Responds to NRC 880225 lir re violations noted in Insp Repts 50:327/88-02 & 50:328/88-02.Corrective actions:Procedure SOI-1.1, "Main Steam," upgraded to Category A to ensure that procedure present & ref directly during performance. GRIDLEYR. Tennessee Valley Authority. 88/03/29. Document Control Branch (Docu-ment Control Dask). 6pp. 44969.352-44969.357.

45231:304-45231:304.

- 8804040129 Responds to NRC 880301 ftr re violations noted in Insp Repts 50-327/88-06 & 50-328/88-06 Corrective actions AI-58 revised to include min qualification re-quirements for independent venification personnal. GRIDLEY,R. Tennessee Valley Authority, 88/03/30. Document Control Branch (Docu-ment Control Desk), 8pp 44972:022-44972.029.
- 8804060241 Forwards response to NRC Bulletin 88-002, "Rapid Propagating Fatigue Cracks in Steam Generator Tubes." Recommendations of Paragraphs A & C of bulletin not applicable to Watte Bar Units 1 & 2. GRIDLEY,R. Tennessee Valley Authority, 68/03/31. Document Control Branch (Document Control Desk) 8pp. 45007:301-45007:308.
- 8804150159 Forwards Insp Repts 50:327/88:14 & 50:328/88-14 on 880208-12 No vio-lations or deviations noted Requests to be informed if understanding of documentation of oral commitment by util representative differs from rept BARR,K.P. Region 2, Olc of the Director, 88/04/06 WHITE,S.A. Tennessee Valley Authority, 2pp. 45175:122-45176:145.

- 8804010256 NRC Info Notice 88 011, "Potential Loss of Motor Control Cir &/or Switch-board Function Due to Faulty Tie Botts." Svc Ist encl. ROSSI,C.E. Dwision of Operational Events Assessment (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804140176 Notification of 880414-15 meetings w/wtl in Rockville,MD to discuss technical details of differences in civil design calculation program & closure of Bulletin 79-
- OONOHEW.J.N. Ofc of Special Projects 88/04/07 ZECH.G.G. Ofc of Special Projects, 3pp. 45118:146-45118.148.
- 8804130296 Forwards Fire Protection Insp Repts 50-327/88-24 & 50-328/88-24 on 880314-18-Violation noted under consideration for escalated enforcement action No notice of violation being issued

 EBNETER,S.D. Ofc of Special Projects 88/04/08 WHITE,S.A. Tennesses Valley Authority. 2pp. 45151:087-45151:136.
- -8804130302 Insp. Repts. 50.327/88-24 & 50.328/88-24 on 680314-23. Violation noted Major areas inspected fire protection & Licensee action to implementation of requirements of 10CFR50 App. H.Sections III G.III. J.III. L. III. D. PIERSON, R.C., WESCOTT, R.G., GARG, H.C. Olic of Special Projects. 88/04/06. 88pp. 45151:069 45151:138.
- 8804150107 Forwards Insp. Repts 50:327/87-76 & 50:328/87-76 on 871206 880205 & notice of violation One unresolved item identified re deficiencies w/fifth vital battery.Matter will be pursued during future insps. BARR R.P. Otc. of Special Projects. 88/04/08. WHITE,S.A. Tennessee Valley Authority. 2pp. 45152:171-45152 247.
- -8804150119 Notice of violation from insp on 871206-880205 Violation noted licensee failed to adequately implement SI-153 on Hydrogen Recombiner 2A-A.in that visual vertication of recombiner orfice clear of obstruction inadequately done. BARR.K.P. Oic of Special Projects. 88/04/08. 2pp. 45152:173-45152:174.
- -8804150132 Insp Repts 50-327/87-76 & 50-328/87-76 on 671206-880205 Two violations incled Major areas inspected operational safety ventication maint tions noted Major areas inspected operational safety verification, maint observations, review of previous insplicings, followup of events & review of IE Info nolices
 JEMISON,K.M. Region 2, Ofc of the Director. MCCOY,F.R. Ofc of Special Projects
 88/04/08, 71pp 45152.175-45152.247.
- 8804190122 Requests addl. Info re main steam line breaks in ice condenser containments, in support of ANL Independent confirmatory analysis of WCAP-10366P Info requested 45 days after receipt. ZECH.Q.G. Otc of Spocial Projects 88/04/08. WHITE,S.A. Tennossee Valley Authority. 7pp. 45165 287-45165:293
- 8804060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165 028-45165 150.
- 8804200464 Forwards addit hito requested by NRC App R inspiteam during 880314-18 inspinito includes revised response to Question 4,amended response to Question 12
- GRIDLEY,R. Tennessee Velley Authority. 88/04/13. Document Control Branch (Document Control Desk). 800pp. 45171:203-45174.073.
- 8804210017 Summanzes review of NRC Bulletin 88-001, "Defects in Westinghouse Cir-cuit Breakors." Bul'etin not applicable to Browns Ferry nuclear plant Bulletin applica-ble to Watts Bar & Bettefonte nuclear plants List of commitments enci. GRIDLEY,R, Tennassea Valley Authority, 88/04/13, Document Control Branch (Docu-ment Control Desk), 3pp. 45219.150-45219.152.
- 8804210022 Confirms extension of due date for response to thisp Repts 50:327/87-73 & 50:328/87-73 until 880422 based on conversation between F McCoy & G Kirk. GRIDLEY,R. Tennessee Valley Authority. 80/04/13 Document Control Branch (Document Control Dask). 1p. 45219:089-45219:089.
- 8804210024 Responds to NRC 880314 ltr re violations noted in Insp Repts 50-327/87-78 & 50-328/87-79 Corrective actions: Administrative Instruction Al. 30 revised to require verbal approval from plant manager or deputy plant manager.

 CRIDLEY, H. Tennessee Valley Authority, 88/04/13, Document Control Branch (Document Control Desk). 8pp. 45219:120-45219:125.
- 8804260021 Forwards Insp Repts 50-327/88-18 & 50-328/88-18 on 880307-11 & 18 & notice of violation.

 BARRINEP. Olic of Special Projects. 88/04/13. WHITE,S.A. Tennessee Valley Authority, 2pp. 45248-114-45248-123.
- --8804260025 Notice of violation from Insp on 880307-11 & 18 Violation noted technical support ctr communicator last received required training in Aug 1986 BARRIKIP, Ofc of Special Projects 88/04/13, 2pp. 45248:116-45248:117.
- -9804260028 Insp Repts 50-327/88-18 & 50-328/88-18 on 880307-11 & 18. Violation noted Major areas inspected review & evaluation of emergency preparedness program. KREH_JL. DECKER,T.R. Ofc of Special Projects. 88/03/31, 2pp. 45248:118-45248-123.
- 8804260040 Forwards Insp Repts 50:327/88-22 8 50:328/88-22 on 880319- 0402.One unresolved item noted re closed auxiliary feedwaler block valve.Response addressing root cause & corrective actions requested within 30 days of fir date. MCCOY.F.R. Otc of Special Projects 88/04/13. WHITE,S.A. Tannessee Valley Authority. 2pp. 45268.217-45268:237.
- -8804250042 Insp Repts 50-327/88-22 & 50-328/88-22 on 880319-0402 No violations noted Major areas inspected extended control room observation & operational safety verification including operations performance, sys lineups & safeguards. LONG, A R., JENISON, K., BRANCH, M. Region 2, Ofc of the Director, 88/04/13, 19pp. 45269-219-45268-237.

- ---8804280057 Insp. Repts 50-327/88-07 & 50-328/88-07 on 880125-28. Violation noted Major areas inspected followup to review ficonsee corrective actions relative to findings identified in 1sted NRC Insp Repts. HUBBARD.G.T. BAKER,E.T., PIERSON,R.C. Old of Special Projects. 88/04/08. 15pp. 45266 220 45266 234.
- 8804200473 Partial response to FOIA request re line protection Forwards App E documents App D & E documents available in PDR App F document completely withheld (rel FOIA Exemption 5) GRIMSLEY, DH. Division of Rules & Records (Post 870413). 88/04/14. JONES, C.R. Affidation Not Assigned 5pp. 45206.037-45206.043.
- --8804200575 Provides status of Region II safe shutdown insp program.
 GRACE, J.N. Region 2, Ofc of the Director. 85/05/13. TAYLOR, J.M. Ofc of Inspection & Enforcement, Director (620201-870413). 2pp. 45208:174-45206:175.
- ~8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R type insp for each facility to assess stitus of compriance w/ 10CFR50 48.Program listed.

 CONLON,T.E. Region 2, Oic of the Director. 84/11/08 HERDT,A.R. Region 2, Oic of the Director. 3pp. 45206.178.
- 8804220022 Forwards supplemental response to violations noted in Insp Repta 50:327/ 86:27 & 50:328/86:27.Encl will provide original Sequeyah deficiency followed by Waits Bar Nuclear Plant supplemental response. GRIDLEY R Tennassee Valley Authority 88/04/15. Document Control Branch (Docu-ment Control Desk) 11pp. 45226:313 45226:323.
- 8804210312 Advises that due date for response to Insp Ropts 50:327/87-30 & 50:328/ 87-30 extended to 880422,per telcon GRIDLEY R. Tennessee Valley Authority, 88/04/18. Document Control Brench (Document Control Dask). 1p. 45235:268-45235.268.
- 8804260385 Responds to NRC 880314 ltr re violations noted in Insp Repts 50-327/87-30 & 50-328/87-30 Corrective actions: SI-166 revised to provide correct alignment for strking valve & importance of configuration control & tailure emphasized. GRIDLEY,R. Tennessee Valley Authority, 88/04/20. Document Control Brench (Document Control Desk). 9pp. 45281:331-45281:339.
- 8804270164 Responds to NRC 880318 fit re violations noted in Insp Repts 50-327/87-18 & 50-328/87-18 Corrective actions missing fastener replaced & Insps performed on other three boric acid transfer pumps to onsure no fasteners missing GRIDLEY,R. Tennessee Valley Authority, 68/04/20. Document Control Branch (Document Control Dask) 5pp. 45244:351-45244:356.
- 8804270223 Forwards response to NRC Insp Repts 50-327/88-23 & 60-328/88-23 recommendations Future audits of LER program will include evaluation of effectiveness of event analysis & reporting GRIDLEY, fl. Tennessee Valley Authority 88/04/20. Document Control Branch (Document Control Desk). 4pp. 45242-355-45242-359.
- 8804270299 Responds to NRC 880309 ftr re violations noted in Insp Repts 50:327/87-73 & 50:328/87-73.Corrective actions task force developed to review potential com-
- 73 a 50-320-10-73-contected accessed to the pensatory measures.
 GRIDLEY R. Tennessee Valley Authority. 88/04/20. Document Control Branch (Document Control Desk), 11pp. 45244:217-45244:227.
- 8804260095 Forwards supplemental response to Integrated Design Insp Repts 50:327/ 87-48 & 50:328/87-48.Corrective action.FSAR will be revised in areas of automatic isolation of ERCW sys & monitor scale for liquid rediation monitors. RAY,M.J. Tennessee Valley Authority. 88/04/21. Document Control Branch (Docu-ment Control Desk). 4pp. 45281.314-45281:320.
- 8804260166 Responds to NRC 880222 für re confirmation of integrated Design Insp. Items D4.3.9,D5.2-3 & D5.2-10.Insp. rept. documents NRC IDI followup insp. on 871102-19 RAY,M.J. Tennessee Valley Authority. 88/04/21. Document Control Branch (Document Control Dosk). 5pp. 45281:309-45281:313.
- 8804280635 Responds to NRC 880309 ltr re violations noted in listed inspreps.includ.ng 50:439/87-08,50:439/87-08 & 50:327/87-68.Corrective actions.delabase constructed for training. GRIDLEFyR. Tannessee Valley Authority. 88/04/22. Document Control Branch (Document Control Desk). 10pp. 45331:341-45331:350.
- R. Periodic operating reports & related correspondence
- 8804060383 "Personnel Whole Body Exposure Repts for 1987." W/880401 ltr. GRIDLEY,R, Tennessee Valley Authority. 87/12/31. 7pp. 45047:060-45047:066.
- 8804060390 "Radiological Impact Assessment Rept Sequoyah Nuclear Plant 1987." W/ 880401 ltr. LEE,B.E., GRIDLEY,R. Tennessee Valley Authority, 87/12/31, 43pp, 45079:113-45079:155.
- 8804050210 Forwards weekly schedule of TVA activities for wks of 880328 & 0404. KELLY,JL. Old of Special Projects. 88/03/24. ZECH,G.G. Old of Special Projects. 4pp. 45028-088-45029.091.
- 8804140525 Submits weekly schedule of TVA activities for wk of 880404: 11.Schedule will be updated & Issued each Friday to reflect activities for forthcoming 2-wk period. KELLY_JL. Ofc of Special Projects. 88/03/31. ZECH
- 8804220020 Monthly operating repis for Mar 1988.W/880411 [tr. DUPAEE,D.C., SMITH,S.J. Tennessee Valley Authority, 88/03/31, 63pp, 45221:282-45221:334.

8804130358 Forwards weekly schedule of TVA activities for wks of 880411 & 18. KELLY,J.L. Ofc of Special Projects. 88/04/08. ZECH,G G. Ofc of Special Projects 4pp. 45103:216-45103.219.

S. Reportable occurrences, LERs & related correspondence

- 8803290224 LER 87-070-03 on 871021 discovered voltage regulator problem on emergency dissel generator (D/G) 2A-A Caused by relays in D/G output breaker closing permissive circuit Defective regulator repaired Also reportable per Part 21.W/880322
- LONG, J.L., SMITH, S.J. Tennessee Valley Authority. 88/03/22 5pp 44921:144-44921:148.
- 8804050004 LER 88-010-01 on 880205, procedure governing stroke time testing for motor-operated valves determined inconsistent w/ design criteria for ESF accusted valves Max allowable stroke time corrected as speciallod by SI-166 W/880401 it. SISKA.D. MEADE.K.E., SMITH,S.J. Tennessee Valley Authority. 88/04/01. 5pp. 45021.055-45021.069.
- 8804050007 LER 88-013-00.on 880314,four steam generator b'owdown sys radiation monitors discovered inadequately tested. Caused by oversight during implementation of surveillance instruction review program Tests satisfactorily completed W7800401 ltr. ROGERS, T., FENN,K.W., SMITH,S.J. Tennessee Valloy Authority. 88704/01. Spp. 45045:219-45045.223.
- 8804050014 Special Rept 88-07 on 880320 & 23 four fire pumps technically inoperable per Tech Specs Caused by design deficiency. Deficiency corrected for automatic operation upon completion of testing.

 SMITILS J. Tennesse

- 8804110309 Special Bent 88-08:on 880301 line breach nermit issued for fire door C-14 which exceeded 7-day limit allowed by Tech Spec Caused by unavailability of correct door knob. Continuous fire watch established.

 SMITH, 37 Tennessee Valley Authority. 88/04/01. Document Control Branch (Document Control Desk). 2pp. 45123 320-45123.321.
- 8804150022 LER 88-015-00:on 880317,Tech Spec surveillance requirement not completely incorporated into implementing procedure. Caused by incomplete procedure review Surveillance Instruction 410.2 rovised W/880411 ltr. ROGERS, NAIK,J.A., SMITH,S.J. Tennessee Valley Authority. 88/04/08. 5pp. 45152:356-45152:360.
- 8804200278 LER 88-014-00:on 880314, Train A containment ventilation isolation (CVI) occurred Caused by personnel noncompliance w/configuration control requirements following post-mod test. CVI reset 8 memo sent to personnel W/880412 ltr SISKA, DP., KILGORE, B.E., SMITH, S.J. Tonnessee Valley Authority. 88/04/12 6pp. 45221:121-45221:126.
- 8804130343 RO:on 880412,fish kill of approx 200 fish in yard drainage pond observed Cause not stated. Effects of pond effluent concentrations on fish will be detailed in 30-day rept.

 SMITH,S.J. Tennessee Valley Authority. 88/04/13. Document Control Branch (Document Control Desk). 1p. 45146.360-45146.360.
- 8804200123 LER 88-016-00:on B80324,Inadvertent main steam Isolation signal occurred.Caused by high steam flow signal from unknown source.Investigation into root cause of event continuing.W/880415 ltr. FENN.KW, SMITH,S J. Tennessee Valley Authority. 88/04/15. 5pp. 45215:309-
- 8804270074 LER 87-078-02:on 871221 inadequate procedure for RCS chemical addition resulted in noncompliance w/Tech Spec action statement Procedures revised to provide instructions for RCS chemical addition W/880421 lic.
 SMITISJ., NAIK.JA. Tunnossee Valley Authority 88/04/21. 5pp. 45245:034-
- 8804270157 LER 87-027-02:on 870609,surveillance requirement not fulfilled because four essential raw cooling water valves not verified in correct position.Caused by procedural error. Valves returned to correct position.W/880421 ltr. SISKAD, KILGOHE,B.E., SMITH,S.J. Tennessee Valley Authority. 88/04/21. 7pp. 45241:158-45241:164.

T. Hearing transcripts on non-antitrust matters

- 8803100145 Forwards transcript of 880224 meeting w/licensee in Chattanooga,TN re Unit 2 operational readiness,including technical support & plant readiness.Presentation stides also enci. ROTELLA,T.S. Otc of Special Projects. 88/03/02. Otc of Special Projects. 3pp. 44862:132-44662:307.
- -8803100147 Transcript of 880224 public meeting in Chattanooga,TN re util operational readiness Presentation stides also encl.
 * Commissioners. 88/02/24, 173pp. 44662:135-44662:307.
- 8804010073 Summary of 880309 meeting w/TVA in Rockville,MD re technical issues related to 10CFR50,App R.Attendance list, transcription,agenda & meeting handout ROTELLA,T.S. Ofc of Special Projects, 88/03/22, Ofc of Special Projects, 2pp. 44950.339-44951:163.
- →8804010078 Transcript of 880309 meeting in Rockville,MD re 10CFR50,App R Issues Supporting documentation encl. * Commissioners. 88703709. 173pp. 44950:341-44951:153.

U. Congressional/Executive Correspondence

8804280317 Forwards NRR responses to Questions 1 & 3 re Commission sids for permitting restant of power plant after shutdown for safety reasons & Commission requirements for documenting licensing basis for restant decision, respectively.

THOMAS,C.O. Policy Development & Technical Support Branch (Post 870411). 887 04/19, REHM,T.A. Ofc of the Executive Director for Operations, 7pp. 45269:209-45269:215.

V. Operator Examinations

8804260088 Responds to FOIA request for info re scores of reactor operators & senior reactor operators Forwards requalification exam summary source streets listed in encl app w/personal privacy into deleted GRIMSLEY.D H Dwiston of Rules & Records (Post 870413) 88/04/19. BOLEY,K Public Citizen's Critical Mass Energy Project. 2pp. 45213.003.45213.095

--8804250167 Package of NRC administered regual fication exam results summary.
NRC - No Detailed Affiliation Given. 87/07/20 88pp. 45213.007-45213.095.

DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8804130374 Rev 31 to rediological emergency plan.W/860408 lir. GRIDLEY,R Tennessee Valley Authority, 86/03/11, 9pp. 45154:090-45154.098.
- 8804010258 Confirms notification to NRC of conditions of entry into Limiting Condition for Operation 3.7.11.1,Action b.of plant Tech Spacs for facility re 880320 event involving inoperable fire pumps. SMITH,S.J. Tennessee Velley Authority. 88/03/21. Region 2, Olc of the Director. 1p. 45058:101-45058 101.
- 8804010073 Summary of 880309 meeting w/TVA in Rockville,MD re technical issues related to 10CFR50,App R Attendance list, transcription agenda & meeting handout

encl. ROTELLA,T.S. Ofc of Special Projects. 88/03/22. Ofc of Special Projects 2pp. 44950:339-44951:153.

- --8804010078 Transcript of 880309 meeting in Rockville,MD to 10CFR50,App R Issues.Supporting documentation encl.

 * Commissioners. 88/03/09, 173pp. 44950 341-44951:153.
- 8804250068 Forwards Insp. Repts 50:327/88:21 & 50:328/88:21 on 880303. No violations or deviations noted BARR,K.P. Old of Special Projects. 88/03/28. WHITE,S.A. Tennessee Valley Authority. 2pp. 45231:302-45231:304.
- --8804250070 Partially Withheld Insp. Repts 50-327/88-21 & 50-328/88-21 on 880303.No Violations noted Major areas inspected previously identified vital area barrier issues & followup to Leensee Inspector general ofc investigation of a leged drug
- MASNYK,O.M. Region 2, Ofc of the Director, 88/03/18, 1p. 45231:304-45231.304 8804180250 Forwards Rev 18 to physical security & contingency plan. Rev withheld (ref.
- 10CFR7:21). GRIDLEY,R.L. Tennessee Valley Authority 88/04/07. Document Control Branch (Document Control Desk). 2pp. 45195:335-45195:336
- 8804130298 Forwards Fire Protection Insp Repts 50:327/88:24 & 50:328/88:24 on 880314-18 Violation noted under consideration for escalated enforcement action No notice of violation being issued. EBNETER,S.D. Old of Special Projects. 88/04/08 WHITE,S.A. Tennessee Valley Authonity. 2pp. 45151:067-45161:136.
- --8804130302 Insp. Repts 50-327/88-24 & 50-328/88-24 on 880314-23. Violation noted Major areas inspected fire protect on & liconsee action re implementation of requirements of 10CFR50 App R.Sections III.G.III.J.III.L. & III.D. PiERSON,R.C., HUBBARD,G.T. Old of Special Projects. SULLIVAN,K. Brookhaven National Laboratory. 88/04/08. 68pp. 45151:089-45151:138

- 8804150279 Temporary instruction Change Form ICF-88-0595 to Rev 13 to Radiological Emergency Plan Implementing Procedure IP-17, "Emergency Equipment & Supplies" W/880411 ltr.
- GRIDLEY, H. Tennessee Valley Authority, 88/04/11, 11pp. 45138-148-45138-168.
- 8804200464 Forwards addl info requested by NRC App R insp team during 880314-18 insp.Info Includes revised response to Question 4,amended response to Question 12 & addi Into on Question 18.
 GRIDLEY,R. Tennessee Valtey Authority. 88/04/13. Document Control Branch (Document Control Desk). 800pp. 46171:203-45174:073.
- 8804260021 Forwards Insp Repla 50-327/88-18 & 50-328/88-18 on 880307-11 & 18 &
- nolice of violation BARR,K.P. Ofe of Special Projects, 88/04/13. WHITE,S.A. Tonnessoe Valley Author-ity, 2pp. 45248:114-45248:123.
- --9804260025 Notice of violation from Insp on 880307-11 & 18 Violation noted technical support of communicator last received required training in Aug 1988.
 BARR,K.P. Old of Special Projects. 88/04/13. 2pp. 45248:116-45248:117.
- --8804260028 Insp Repts 50-327/88-18 & 50-328/88-18 on 880307-11 & 18 Violation noted Major areas inspected review & evaluation of emergency preparedness program. KREH, J.L. Ofc of Special Projects. 88/03/31, 2pp. 45248:118-45248.123
- 8804260040 Forwards Insp Repte 50-327/88-22 & 50-328/88-22 on 680319 0402. One unresolved item noted re closed auxiliary feedwater block valve Response addressing root cause & corrective actions requested within 30 days of ltr date. MCCOY,F.R. Ofc of Spacial Projects. 88/04/13. WHITE,S.A. Tennessee Valley Authority. 2pp. 45288:217-45268:237.
- -8804260042 Insp Repts 50-327/88-22 & 50-328/88-22 on 880319-0402.No violations noted.Major areas inspected extended control room observation & operational safety verification,including operations performance, sys lineups & safeguards. LONG,A.R. Region 2, Otc of the Director, 88/04/13, 19pp. 45268:218-45268:237.
- 8804180257 Forwards Rev 14 to security personnel fraining & qualification plan. Rev withnest. GRIDLEY,R.L. Tennessee Valley Authority, 88/04/14. Document Control Branch (Document Control Desk). 2pp. 45195-338-45195-339.

- 8804200473 Partial response to FOIA request re line protect on Forwards App E documents.App D & E documents available in PDR App F document completely withheld (ref FOIA Exemption 5).
 GRIMSELF(D.H. Division of Rules & Records (Post 870413). 88/04/14. JONES,C R. Alfiliation Not Assigned 5pp 45206 037-45206 043
- -8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type inspifor each factify to assess status of complaince w/ 10CFR50 48 Program Islad CONLON,T.E. Region 2, Oto of the Director. 3pp. 45206:176.45208:178.
- 8804220250 Revised emergency plan Implementing procedures,including Rev 0 to CECC-EPIP-1, "Emergency Buty Officer Procedure for Notification of Unusual Event Alert Site Area Emergency & General Emergency," W/880420 ltr. GRIDLEY,R.L. Tennessee Valley Authority. 88/04/20, 400pp. 45229 308-45230 322.
- 8804280095 Forwards radiological emergency plan implementing procedures document audit of controlled documents GRIDLE Y.R. Tennessee Valley Authority. 88/04/21. Document Control Branch (Document Control Desk). 19pp. 45261:254-45261:272

H. General correspondence

- 8804220050 Responds to 880302 ltr.forwarding P Pierce ltr expressing concern re cost of util operator unforms Matter of util uniform cost outside purview of NRC STELLO.V. Ofc of the Executive Director for Operations, 88/04/14, DUNCAN, J.J. House of Rep. 4pp. 45201:005-45201.011.
- -8804220054 Forwards P Pierce fit re cost of util operators uniforms for consideration & response
 DUNCAN,J.J. House of Rep. 88/03/02. Congressional Affairs. 3pp. 45201 009-45201.011.

J. Insurance & Indemnity Information

- 8804050067 Forwards status & details of property insurance coverage for facilities,per 10CFR50.54 for Info GRIDLEY,R Tennessee Valley Authority 88/03/30. Document Control Branch (Document Control Desk). 3pp. 44995:356-44995

K. Utility Final Safety Analysis Report (FSAR) & amends

- 8804260371 Amend 5 to updated FSAR for Sequoyah Nuclear Plant W/880420 ltr, GRIDLEY,R. Tennessee Valley Authority 88/04/20. 1,200pp. 45315:001-45318.147.
- O. Advisory Committee on Reactor Saleguards reports & correspondence
- 8804140090 Summary of ACRS Subcommittee on TVA Organizational Issues meeting on 880202-03 in Chattenoogs,TN re-review of TVA mgt reorganization & issues re-re-
- start of Unit 2.

 * ACRS Advisory Committee on Reactor Safeguards. 88/03/12. ACRS Advisory Committee on Reactor Safeguards. 10pp 45118:321-45118:330.
- 8804140215 Submits summary of actions discussed at ACHS 335th meeting on 880310-12 In Washington, DC, including ACRS repts/ recommendations, other actions, agreements assignments & requests & future agenda. KERR,W. ACRS Advisory Committee on Reactor Safeguards. 88/03/24, ZECH,L,W. Commissioners. 4pp. 45118.172-45118:175.
- 8804040111 Forwards util response to ACRS questions from 880212 meeting w/full ACRS committee in Washington,DC.Util will begin screening of LERs of sister plants to Sequoyah & Browns Ferry Nuclear Plants to determine if any actions required. GRIDLEYA, Fennessee Valley Authority. 88/03/30, Document Control Branch (Document Control Desk). 4pp. 44970 232-44870-235.

P. Operating license stage documents & correspondence

- 8803080517 Notification of 880308 meeting w/util in Rockville,MD to discuss technical Issues re electrical cable tray/condut separation.

 ROTELLA,T.S. Ofc of Special Projects. 88/03/04. ZECH,G.G. Ofc of Special Projects. 3pp. 44639.055-44639.057.
- 8803240426 Generic Ltr 88-06 to all power reactor hoensees & applicants re removal of organization charts from Tech Spec administrative control requirements. Svc list and MIRAGLIAF. J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972;153.
- 8804 120213 Hequests that immediate emergency action be taken in form of order suspending full power operation of plant until remedial action can be taken. Basis for request is failure of util to meet requirements of Reg Guides 1 9 & 1.108.
 BATES.A.K. Natural Rights Conter. BATES.A.K. Bates, A.K. 88/03/24. ZECH,L.W. Commissioners. STELLO,V. Ofc of the Executive Director for Operations. MURLEY.T. Office of Nuclear Reactor Regulation, Director (Post 870411) 2pp. 45091:262-45091:263.
- 8804050313 Forwards second revised prehminary SER re plant performance plan, adding new or modified sections concerning design control civil & electrical calculations & App Riper 880121 & 0217 ltrs. Final evaluation will be issued as NUREG.
 - EBNETER, S.D. Ofc of Special Projects 88/03/25, WHITE, S.A. Tennessee Valley Authority, 361pp. 44998.001-44998.361.
- 8803310263 Denies 880324 request for emergency retail.Remander of request will be treated as petition for enforcement action under 10CFR2 206 & will issue director's decision shortly. Lit related no new issues not already considered by NRC EBNETERS.D. Ofc of Special Projects. 88/03/28 BATES,A.K. Natural Rights Center. 3pp. 44949:175-44949:178.
- 8804070199 Forwards TVA employee concerns task group subcalegory repts. RUSSELL,J.R. Tennessee Valley Authority. 88703728. Document Control Branch (Occument Control Desk). 5pp. 45022.145-45024.257.

- --8804070203 Rev 3 to Employee Concerns Special Program Subcategory Engineering Rept 25000, "Civil/Structural Design (21500) & Pipe Whip Restraint Design (22700)" BENKERT,J.W. Tennessee Valley Authority, 88/03/21, 89pp. 45022:150-45022 238
- ←8804070224 Rev 6 to Employee Concerns Special Program Subcategory Rept 80200, KENZIE, L.G. Tennessee Valley Authority. 88/03/18. 152pp. 45022:335-45023:126
- ~8804070234 Rev 6 to Employee Concerns Special Program Subcategory Rept 80400, "Nonconformance Control & Corrective Action." HALVERSON,R.D. Tennessee Valley Authority. 88/03/14. 491pp. 45023:127-
- 8804040016 Forwards 14th update of activities list,in accordance w/ 860717 submittel of plant performance plan Items that have been reopened listed in Encl 2.Items that have linglid-sposition listed in Encl 3. GRIOLEY,R. Tennessee Valley Authority. 88/03/29. Document Control Branch (Document Control Desk). 40pp. 44969.076-44989:115.
- 8804040076 Notifies of proposed use of sodium bromide in addition to sodium hypochlorite in ERCW systic control biolouling. Use of bromide radiuces total residual chlorine & aids in compliance w/NPDES permit. Info on products being considered encl. BROOKS,R.H. Tennessee Valley Authority. 88/03/30. SINCLAIR,R.M. Tennessee, State of, 98pp. 45031:321-45032.058.
- 8804040282 Staff requirements memo on 880322 affirmation/discussion & vote in Washington,DC reflectly restart Commission authorized NRC to permit util to restart upon resolution of RTD Issue & other prerequisites.

 CHILK,S.J. Office of the Secretary of the Commission. 88/03/30. STELLO,V. Ofc of the Executive Director for Operations. 1p. 44974;256:44974;256.
- 8804050440 Documents differences between util programs planned for restart of Unit 1 & programs used for restart of Unit 2. Nuclear performance plan will be revised to include detailed info on four Unit 1 programs by 880429.New commitments encl. GRIDLEY.R. Tennessee Valley Authority. 88/03/31. Document Control Branch (Document Control Desk). 8pp. 45007.051.45007.058.
- 8804110226 Forwards safety evaluation & technical evaluation rept re program for mi-crobiologically induced corrosion (MIC) control in ERCW sys.TVA insp.evaluation & repair program for MIC capable of safety function. ZECH.G.G. Ofc of Special Projects. 88/03/31. WHITE,S.A. Tennessee Valley Author-ity. 3pp. 45078:112-45078:125.
- --8804110229 Safety evaluation supporting microbiologically induced corrosion (MiC) program in ERCW sys.
 O'c of Special Projects. 88/03/31, 11pp. 45078:116-45078:125.
- 8804070057 Forwards I sting of employee concern numbers shown on util data base as NHC responsibility for evaluation not included in 861231 submittal Requests ack of responsibility.

 RUSSEL 1, J.R. Tennessee Vailey Authority. 88/04/01, Document Control Branch (Occument Control Dask). 7pp. 45075:038-45075:042
- 8804060417 Provides supplemental response re microbiologically induced corrosion program. Correct Preventive Maint Instructions 2241 & 2242.replace 2240 & 2241.respectively.per util 880120 ltr. GRIDLEY,R. Tennessee Valley Authority. 88/04/04. Document Control Branch (Document Control Desk). 2pp. 45076;160-45076;161.
- 8804080427 Forwards addl info in form of relief request from ASME Code Section XI re microbiologically induced corrosion (MIC) program.per NRC 880318 request MIC program will ensure that structural integrity of ERCW piping maintained. GRIDLEFYR. Tennessee Valley Authority. 88/04/04. Document Control Branch (Document Control Desk). 5pp. 45073:356-45073:360.
- 8804140081 Forwards Amends 69 & 61 to Licenses DPR-77 & DPR-79, respectively & safety evaluation Amends revise Tech Specs to separately define operability & surveillance requirements for RHR spray trains. ZECH.G. Ofc of Special Projects. 88/04/04. WHITE,S.A. Tennessee Valley Authority. 3pp. 45118:278-45118:299.
- --8804140097 Amends 89 & 61 to Licenses DPR-77 & DPR-79 respectively, revising Tach Speca to separately define operability & surveillance requirements for RHR spray trains. ZECH,G.G. Ofc of Special Projects. 88/04/04, 18pp. 45118:279-45118:296.
- --8804140101 Safety evaluation supporting Amends 69 & 61 to Licenses DPR-77 & DPR-79,respectively.
 * Old of Special Projects: 88/04/04, 3pp. 45118:297-45118:299-
- 8804120090 Forwards suppl to consultants 880325 ftr re review of diesel generators at plant. STELLO,V. Oic of the Executive Oirector for Operations, 88/04/06, ZECH, ROBERTS, BERNTHAL Commissioners, 1p. 45101:004-45101:006.
- -8804120105 Forwards suppl to 880325 ltr re plant diesel generators. Suppl replaces tiem 4. "Tests on Diesel Generators" & clarifies ttr concerning tests required by Reg Guide 1.108. KUSKO,A, PEERAN,S M. Fallure Analysis Associates, 88/03/28, MARINOS,A. NRC - No Detailed Affiliation Given. 2pp. 45101:005-45101:006.
- 8804080088 Generic Ltr 88:07 to power reactor licensees & applicants re-modified en-lorcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svo tist encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804140006 Forwards followup rept to 880309 (ishkill.Initial notification made by telephone on 880309. Water analysis could not uncover causative agent for fishkill.Fish probably stressed by atgae bloom State of TN concurs.

 GRIDLEY, I. Tennessee Valley Authority. 88704708, Document Control Branch (Document Control Desk). 3pp. 45147:340-45147;342.
- 8804290151 Forwards FR notice ack receipt of 880324 polition & stating that petition being treated per 10CFR2.206. EBNETER,S.D. Ofc of Special Projects, 88/04/22, BATES.A.K. Bates, A.K. 1p 45322 197-45322 200.

- --8804290164 Notice of receipt of petition for Director's Decision under 10CFR2:206 for Commission order suspending full-power plant operation until remedial action taken Request for energency retrol denied Further action per I0CFR2:206 pending. EBNETER,S D. Otc of Special Projects. 88/04/22: 3pp. 45322:198-45322:200.
- 8804290167 Notification of 880429 meeting w/util in Rockville,MD to discuss technical datails of tube leaks in steam generators & action taken by util.

 ROTELLA,T.S. Oto of Special Projects 88/04/25. HERMANN,R A. Oto of Special Projects, 3pp. 45322,226-45322,228.
- Q. Inspection reports, IE Bulletins & correspondence
- 8803290349 Forwards Insp Repts 50:327/87-73 & 50:328/87-73 on 871026:30 & notice of violation.

 BARR,K P. Otc of Special Projects, 88/03/08, WHITE,S.A. Tennessee Valley Authority 2pp 44952:236-44952:292.
- --8803290352 Notice of violation from insp on 871026:30 & 980104:14. Violation noted licenses failed to perform or failed to adequately perform written safety evaluations for 15 mods
 BARR,K.P. Ofc of Special Projects 88/03/09. 2pp. 44952:238-44952:239.
- --8803290355 Insp. Repts 50-327/87-73 & 50-328/87-73 on 871026-30 & 880104-14. Violations noted Major areas inspected flosting activities plant heatup procedure & TVA operational readiness assessment & compensatory measures. BRANCH.M., MCCOY,F. Regton 2, Otc of the Director. 88/03/04. 51pp. 44952 240-44952:292.
- 8803290366 Forwards Insp. Ropts 50:259/87:38,50:260/87:38,50:298/87:38 50:327/ 87-68,50:328/87-68,50:398/87-18,50:391/87-18, 50:438/87:08 & 50:439/87:08 on 87:1005-18 & notice of violation. BARR,K.P. Region 2, Olc of the Director. 88/03/09. WHITE,S.A. Tennessee Valley Authority. 3pp. 44975:195-44975:208.
- -8803290390 Notice of violation from insp on 871005-18. Violations noted: inadequate div of nuclear engineering trainling & records, Ineffective followup on audit findings & Improper correction of QA records.
 BARH,K P. Region 2, Otc of the Director. 88/03/09. 3pp. 44975:198-44975:200.
- --8803290393 Insp Repts 50-259/87-38,50-260/87-38,50-296/87-38, 50-327/87-68,50-328/87-68,50-390/87-18,50-391/87-18, 50-436/87-08 & 50-439/87-08 Violations noted Major areas inspected ellegations & licensee action on Identified Items, WALTON,G A. Region 2. Otc of the Director. 88/03/08, 8pp 44875:201-44975:208.
- 8804010058 Discusses Insp. Repts 50-327/87-24,50-328/87-24.60-327/87-30 & 50-328/87-30 on 870408-0505 & 0506-0612,respectively & forwards notice of violation Involves inadequate procedure Implementation & lack of control over testing.
 - RICHARDSON,S.D. Region 2, Old of the Director, 88/03/14. WHITE,S.A. Tennessee Valley Authority. 3pp. 45028:035-45028:040.
- --8804010060 Notice of violation from insps on 870406-0505 & 0506-0612. Violations noted on 870201, sys realignment improvised w/o written or formally approved instructions & on 870201, two valves shut down w/o entry into configuration log. RICHAROSON,S.D. Region 2, Ofc of the Director. 88/03/14. 3pp. 45028:038-45028:040.
- 8804010037 Ack receipt of 880216 ftr informing NRC of steps taken to correct violations noted in Insp.Repts 50:327/87.52 & 60:328/87.52.

 RICHARDSON,S.D. Ofc of Special Projects. 88/03/21, WHITE,S.A. Tennessee Valley Authority. 1p. 45031:155-45031:155.
- 8804010023 Forwards Special Team Insp. Repts 50-327/88-08 & 50-328/88-08 on 88011+15 & 25-29.No violations or deviations noted. BARR,K.P. Ofc of Special Projects. 88/03/22. WHITE,S.A. Tennessee Valley Authority. 2pp. 45028:127-45028:145.
- -8804010025 Insp Repts 50:327/88:08 & 50:328/88:08 on 880111-15 & 0125-29 No violations or deviations noted Major areas Inspected layup & preservation of equipment. YORK, J. WALTON, G., ELROD, S. Region 2, Ofc of the Director, 88/03/18, 17pp. 45028:129-45028:145.
- 8804060249 Forwards Insp Repts 50:327/88-17 & 50:328/88-17 on 880212-26 & notice of violation Insp findings Identified what appears to be addl example of previous violation re staff overtime limits. Unresolved item noted. MCCOY.F.R. Ofc of Special Projects. 88/03/24. WHITE,S.A. Tennessee Valley Authority. 3pp. 45046:204-45046:234.
- --8804060252 Notice of violation from insp on 880212-28. Violations noted: maint activities on Valve 2-LCV-62-118 not adequately described or implemented, resulting in Inadvertent diversion of approx 465 gallons of RCS water to holdup tank, MCCOY,F.P. Ofc of Special Projects. 88/03/24, 2pp. 45046-207-45046:208.
- --8804060255 Insp. Repts 50:327/98-17 & 50:328/88-17 on 880212-26. Violations noted Major areas inspected control room observation & operational safety verification, including operations performance & sys lineups. JENISON,K., BRANCH,M., HUNEGS,G. Region 2, Ofc of the Director. 88/03/22. 24pp. 45046-209-45046-234.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors," Svc list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:128-44996:248.
- 8803220296 NRC Info Notice 88:010, "Matts Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list encl. CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Salety (Post 870729), 867 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44985;247-44986;353.
- 8804080185 Forwards Insp Repts 50-327/88-15 & 50-328/88-15 on 880208-12.No violations or deviations noted. MCCOY,F.R. Region 2, Oic of the Director. 88/03/28. WHITE,S.A. Tennessee Valley Authority. 2pp. 45100.235-45100

- --8804080186 Insp Repts 50-327/88-15 & 50-328/88-15 on 880208-12.No violations or deviations noted Major areas inspected LER followup.act.on on previous findings.info. notices.potential RO & problem identification repts. JENISON.K., HUNEGS.G., MCCOY,F. Region 2, Old of the Director. 88/03/30. 31pp. 45100-237-45100:287.
- 8804250068 Forwards Insp Repts 50-327/88-21 & 50-328/88-21 on 880303 No violations or deviations noted.

 BARR.K.P. OIC of Special Projects. 88/03/28. WHITE,S A. Tennessee Velley Authority. 2pp. 45231:302-45231:304.
- --8804250070 Partially Withheld Insp Repts 50-327/88-21 & 50-328/88-21 on 880303.No Violations noted. Major areas inspected previously identified vital area barrier issues & followup to licensee inspector general ofc investigation of alleged drug use.

 MASNYK,O.M., MCGUIRE,D.R., Region 2, Otc of the Director, 88/03/18, 1p.

45231:304-45231:304

- 8804040272 Responds to NRC 880225 ltr re violations noted in Insp Repts 50-327/86-02 & 50-328/88-02 Corrective actions Procedure SOI-1.1, "Main Steam," upgraded to Category A to ensure that procedure present & rel directly during performance. GRIDLEY,R. Tennessee Valley Authority. 88/03/29. Document Control Branch (Document Control Desk). 6pp. 44969:352-44869.357.
- 8804040129 Responds to NRC 880301 ltr re violations noted in Insp Repts 50:327/88-06 & 50:328/88-06 Corrective actions: Al-58 revised to include min qualification requirements for independent verification personnal. GRIDLEY,R. Tennessee Valley Authority. 88/03/30. Document Control Branch (Document Control Desk). 8pp. 44972.022-44972.029.
- 8804060241 Forwards response to NRC Bulletin 88-002, "Repid Propagating Fatigue Cracks in Steam Generator Tubes." Recommendations of Paragraphs A & C of bulletin not applicable to Watts Bar Units 1 & 2. GRIDLEY,R. Tennessee Valley Authority. 88/03/31. Document Control Branch (Document Control Oesk). 8pp. 45007:301-45007:308.
- 8804150159 Forwards Insp. Repts 50:327/88:14 & 50:328/88-14 on 880208:12.No viofallons or deviations noted Requests to be informed if understanding of documentation of oral commitment by util representative differs from rept. BARR,K.P. Region 2, Ofto of the Director, 88/04/08. WHITE,S.A. Tennessee Valley Authority. 2pp. 45176:122-45175:145.
- ~8804150183 Insp Repts 50-327/88-14 & 50-328/88-14 on 880208-12 No violations or deviations noted Major areas inspected: evaluation of licensee resolution of inspector followup items re-emergency operating procedures. LEWIS,M., SHYMLOCK,M. Region 2, Ofc of the Director. 88/03/23, 22pp. 45175:124-45175:145.
- 8804010256 NRC Into Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switchboard Function Due to Faulty Tie Botts," Svc list enct. ROSSI.CE. Division of Opporational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408:292-45407.051.
- 8604130296 Forwards Fire Protection Insp Repts 50:327/68:24 & 50:328/68:24 on B80314-18. Violation noted under consideration for escalated enforcement action. No notice of violation being issued. EBNETERS.D. Ofc of Special Projects. 88/04/08. WHITE,S.A. Tennessee Valley Authority. 2pp. 45151:067-45151:136.
- --8604130302 Insp Repts 50:327/88:24 & 50:328/88:24 on 880314:23. Violation noted Major areas Inspected fire protection & licensee action re implementation of requirements of 10CFR50 App R.Sections III.G,III.J,III. L & III.O. PIERSON,R.C., WESCOTT,R.G., GARG,H.C. Ofc of Special Projects. 88/04/06. 68pp. 45161:089-45151:136
- 8804150107 Forwards Insp Repts 50:327/87-76 & 50:328/87-76 on 871206-880205 & notice of violation.One unresolved item identified re deliciences w/fifth vital battery.Matter will be pursued during future insps.
 BARR,K.P. Otc of Special Projects. 88/04/08. WHITE,S.A. Tennessee Valley Authority. 2pp. 45152:171-45152:247.
- --8804150119 Notice of violation from insp on 871206-880205. Violation noted licensee failed to adequately implement SI-153 on Hydrogen Recombiner 2A-A, in that visual verification of recombiner critico clear of obstruction inadequately done. BARR,K.P. Ofc of Special Projects. 88/04/08. 2pp. 45152:173-45152:174.
- --8804150132 Insp Repts 50-327/87-76 & 50-328/87-76 on 871206-880205 Two violations noted Major areas inspected operational safety verification maint observations, review of previous insp findings, followup of events & review of IE info notices.
- notices.
 JENISON.K.M. Region 2, Ofc of the Director. MCCOY,F.R. Ofc of Special Projects.
 BB/04/08, 71pp. 45162:176-45152:247.
- 8804190122 Requests addl into re main steam line breaks in ice condenser contenments,in support of ANL independent confirmatory analysis of WCAP-10988P.into requested 45 days after receipt. ZECH,G.G. Ofc of Special Projects. 88/04/08 WHITE,S A Tennessee Valley Authority. 7pp. 45165:287-46165:293.
- 8904060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-46165:150.
- 8804200464 Forwards addi Into requested by NRC App R insp team during 880314-18 Insp.Into Includes revised response to Question 4,amended response to Question 12 & addi Into on Question 18.

 GRIDLEY,R. Tennessee Valley Authority. 88/04/13. Document Control Branch (Document Control Desk). 800pp. 45171:203-45174.073.
- 8804210017 Summarizes review of NRC Bulletin 86-001, "Defects in Westinghouse Crcuil Breakers." Bultetin not applicable to Browns Ferry nuclear plant Bulletin applicable to Walts Bar & Belletonte nuclear plants List of commitments encl. GRIDLEY.R. Tennessee Valley Authority, 88/04/19. Document Control Branch (Document Control Desk), 3pp. 45219:150-45219:152.

- 88D4210022 Confirms extension of due data for response to Insp Repts 50-327/87-73 & 50-328/87-73 until 880422,based on conversation between F McCoy & G Kirk. GRIDLEY,R. Tennessee Verley Authority, 88/04/13. Document Control Branch (Document Control Desk) 1p. 45219 089-45219 089.
- 8804210024 Responds to NRC 880314 ftr re-violations noted in linsp Repts 50:327/87-78 & 50:328/87-78. Corrective actions: Administrative Instruction Al-30 revised to regure verbal approval from plant manager or deputy plant manager. GR:DLEYR, Tennessee Velley Authority, 88/04/13. Document Control Branch (Document Control Desk), 6pp. 45219-120-45219.125.
- 8804260021 Forwards Insp Flepts 50-327/88-18 & 50-328/88-18 on 880307-11 & 18 & notice of violation.
 BARRIKP Oic of Special Projects, 88/04/13, WHITE,S.A. Tennessee Valley Authorty 2pp. 45248 114-45248:123
- -8804260025 Notice of violation from insp on 880307-11 & 18.Violation noted technical support cir communicator last received required training in Aug 1986. BARR,K P. Ofc of Special Projects 88/04/13, 2pp. 45248.116-45248:117.
- --8804280028 Insp. Repts 50:327/88-18 & 50-328/88-18 on 880307-11 & 18. Violation noted Major areas inspected review & evaluation of emergency preparedness pro-KREHJL, DECKER,TR Otc of Special Projects, 88/03/31, 2pp. 45248:118-45248:123.
- 8804260040 Forwards Insp Repis 50:327/88-22 & 50:328/88-22 on 880319- 0402.One unresolved from noted re-closed auxiliary feedwater block valve Response addressing root cause & corrective actions requested within 30 days of fit date. MCCOY,F R Otic of Special Projects. 88/04/13. WHITE,S A. Tennessee Valley Authority. 2pp 45268:217-45268:237.
- -8804260042 Insp Repts 50:327/88-22 & 50:328/68-22 on 880319-0402 No violations noted Major areas inspected extended control from observation & operational safety verification, including operations performance, sys lineups & saleguards.

 LONG A.R. JENSON,K., BRANCH,M. Region 2, Ofc of the Director. 88/04/13. 19pp. 45268:219-45268.237
- 8804280040 Forwards Followup Insp Repts 50-327/88-07 & 50-328/88-07 on 880125-29. Violation noted insp determined that facility implemented program rept to correct procurement delic encles identified in repl. RICHARDSON,S D. Ofc of Special Projects. 68/04/13. WHITE,S A. Tennesses Valley Authority. 3pp. 45266:217-45266:234.
- --8604280057 Insp Repts 50-327/86-07 & 50-328/88-07 on 880125-29. Violation noted Major areas inspected followup to review licensee corrective actions relative to lindings identified in fisted NRC Insp Repts.
 HUBBARD.G. ... BAKER,E.T. PIERSON,R.C. Otc of Special Projects 88/04/08. 15pp. 45266 220 45266 234
- 8804200473 Partial response to FOIA request re fire protection.Forwards App E documents App D & E documents available in POR.App F document completely withheld (ref FO/A Exemplion 6).
 GRIMSLEY,D H. Division of Rules & Records (Post 870413). 88/04/14. JONES,C.R. Auntation Not Assigned. 5pp. 45206.037.45206.043.
- --8804200575 Provides status of Region II sate shutdown insp program. GRACE,J.N. Region 2, Ofc of the Director. 85/05/13, TAYLOR,J.M. Ofc of Inspection, & Enforcement, Director (820201-870413), 2pp. 45206:174-45206:175.
- --8804200579 Advises that Five Protection Steering Committee has recommended that each region make one 10CFR50,App R-type inspiror each facility to assess status of compliance w/ 10CFR50,48 Program listed.
 CONLON.T.E. Region 2, Oto of the Director. 84/11/06. HERDT,A.R. Region 2, Oto of the Director. 3pp. 45206.176-45206:178.
- 8804220022 Forwards supplemental response to violations noted in insp Repts 50-327/ 86-27 & 50-328/86-27 Enct will provide original Sequeyah deficiency followed by Watts Bar Nuclear Plant supplemental response. GRIDLEY,R. Tennessee Valley Authority, 88/04/15, Document Control Branch (Occument Control Desk) 11pp 45226:313-45226:323.
- 8804210312 Advises that due date for response to Insp Repts 50:327/87-30 & 50:328/ 87:30 extended to 880422,per telcon. GRIDLEY,R. Tennossee Velley Authority, 88/04/18. Document Control Branch (Document Control Desk). 1p, 45235.268-45235:268.
- 8804260385 Responds to NRC 880314 ftr re violations noted in Insp Repts 50-327/87-30 & 50-328/87-30.Corrective actions:SI-166 revised to provide correct alignment for strking valve & importance of configuration control & failure emphasized. GRIDLEY,R. Tennessee Valley Authority, 88/04/20, Document Control Branch (Document Control Desk), 9pp. 45281:331-45281:339.
- 8804270164 Responds to NRC 880318 itrire violations noted in Insp Repts 50-327/87-18 & 50-328/87-18 Corrective actions:missing fastener replaced & hisps performed on other three boric acid fransfer pumps to ensure no fasteners missing. GRIDLETYR. Tennassee Valley Authority, 88/04/20, Document Control Branch (Document Control Desk), 6pp, 45244:351-45244:356.
- 8804270223 Forwards response to NRC Insp. Repts 50-327/88-23 & 50-328/88-23 recommendations. Future audits of LER program, will include evaluation of effectiveness of event analysis & reporting. GRIDLEY,R Tenassee Valley Authority, 88/04/20, Document Control Branch (Document Control Desk). 4pp. 45242 358-45242:359.
- 8804270299 Responds to NRC 880309 ltr re violations noted in Inap Repts 60:327/87-73 & 50:328/87-73.Corrective actions task force developed to review potential compensetory measures.
 GRIDLEY,R. Tennessee Valley Authority, 88/04/20, Document Control Branch (Document Control Desk). 11pp. 45244:217-45244:227.
- 8804260095 Forwards supplemental response to Integrated Design Insp Repts 60-327/ 87-48 & 50-328/87-48. Corrective action:FSAR will be revised in areas of automatic isolation of ERCW sys & monitor scale for liquid radiation monitors. RAY,M.J. Tennessee Valley Authority, 88/04/21. Document Control Branch (Docu-ment Control Desk). 4pp. 45281:314-45281:320.

- 8804280188 Responds to NRC 880222 ltr re confirmation of Integrated Design Insp Items D4.3.9,D5.2.3 & D5.2.10.Insp rept documents NRC IDI followup insp on
- 871102-19
 RAY.M.J. Tennessee Valley Authority. 88/04/21. Document Control Branch (Document Control Desk), 5pp. 45281;309-45281:313.
- 8804280635 Responds to NRC 880309 Itr re violations noted in listed insprepts including 50-438/87-08.50-439/87-08 & 50-327/87-68 Corrective actions data base constructed for training.
 GRIDLEY/R. Tentassee Valtey Authority. 88/04/22 Document Control Branch (Document Control Desk). 10pp. 45331-341-45331:350.

- 8804060383 "Personnel Whole Body Exposure Repts for 1987." W/880401 lir. GRIDLEY,R. Tennessee Valley Authority. 87/12/31. 7pp. 45047.080-45047.066.
- 8804060390 "Rad ological Impact Assessment Rept Sequoyah Nuclear Plant 1987." W/ BB0401 ft.
 LEE,B E., GRIDLEY,R. Tennessee Valley Authority 87/12/31 43pp. 45079 113-
- 8804050210 Forwards weekly schedule of TVA activities for wks of 880328 & 0404. KELLY,J.L. Old of Special Projects. 88/03/24. ZECH,G.G. Old of Special Projects. 4pp. 45029:088-45029:091.
- 8804110525 Submits weekly schedule of TVA activities for wk of 880404- 11. Schedu'e will be updated & Issued each Friday to reflect activities for forthcoming 2-wk period KELLY.J.L. Ofc of Special Projects. 88/03/31. ZECH.G.G. Ofc of Special Projects 4pp. 45130:205-45130:208.
- 8804220020 Monthly operating repts for Mar 1988.W/880411 ltr.
 DUPREE,D.C., SMITH,S.J. Tennessee Valley Authority, 88/03/31, 53pp. 45221:282-
- 8804130358 Forwards weekly schedule of TVA activities for wks of 880411 & 18. KELLYJL. Ofc of Special Projects. 88/04/08. ZECH,G.G. Ofc of Special Projects 4pp. 45103:219.

S. Reportable occurrences, LERs & related correspondence

- 8604050006 LER 88-012-00.on 880305, level control valve 2-LCV-3-175 could not be opened from main control room. Caused by crew not immediately entering Limiting Condition for Operation 3.0.5. Late entry of condition made W/880401 ftr. SISKA,D., LONG,J.L., SMITH,S.J. Tennesses Valley Authority. 88/04/01. 9pp. 46045:210-45045:218.
- 8804050010 LER 88-011-00.on 880306,cold leg accumulator 3 declared inoperable due to 1s lure to perform surveillance requirement 4.5.1.1.1.b.Caused by shift crews not considering RCS leak as filling operation.W/880401 lir.

 MEADE.K.E., SMITH.S.J. Tennessee Valley Authority. 88/04/01. 4pp. 45034:065-
- 8804110309 Special Rept 88-08:on 880301, fire breach permit issued for fire door C-14 which exceeded 7-day limit allowed by Tech Spec Caused by unavailability of correct door knob. Continuous fire watch established.

 SMITH,S.J. Tennessee Valley Authority. 88/04/01. Document Control Branch (Document Control Desk). 2pp. 45123:320-45123:321.
- 8904150029 LER 88-013-00.on 880316 & 17, rod control sys deficiencies caused inaccuracies in rod group demand position indication resulting in manual reactor trips. Caused by demand step counter circuitry failure & internal binding W/880408 ltr. SISKA, D. MEADE, K.E., SMITH, S.J. Tennessee Valley Authority. 88/04/08. 8pp. 46170:030-45170:037.
- 8804160033 LER 88-003-01:on 880119, discovered ice buildup in flow passage of ice condenser. Caused by failure to convert original design requirements into verifiable, repeatable surveillance requirements. Condenser defrosted W/880411 ltr. MEADE, K.E., SMITH, S.J. Tennessee Valley Authority. 88/04/08. 11pp. 45152.248-
- 8804150042 LER 88-005-01:on 880212 smoke discovered coming from speed increaser unit for centrifugal charging pump 2A-A Caused by bolts backing out due to lack of periodic adjustments. Speed increaser lube oil pump 2A-A CCP replaced.W/880411 ltr. ROGERS, T., KILGOPE, BE., SMITH, S.J. Tennessee Valley Authority. 88/04/08. 9pp. 45159:254-45159.262.
- 8804210211 PNO:OSP-88-004A on 880406 calculated unidentified leak rate of 1.09 gpm obtained, exceeding Tech Spec limit of 1 gpm. Differential pressure transmitter reactor coolant seal return limit stollated Plant currently in Mode 5 for repairs. RICHARDSON,S. Ofc of Special Projects. 88/04/12, 4pp. 45231:165-45231:168.
- 8804130343 RO:on 860412 fish kill of approx 200 lish in yard drainage pond observed. Cause not stated. Effects of pond effluent concentrations on tish will be detailed in 30-day rept.
 SMITH, 5J. Tennessee Valley Authority. 88/04/13. Document Control Branch (Document Control Desk). 1p. 45146.360. 45146.360.
- 8804200131 LER 88-014-00:on 880320 pressure changes in balance-of-plant condensate sys caused main feedwater pumps to trip.Procedure revised to de-energize main feedwater pump trip bus while filling & deaerating condensate sys.W/880415 ltr. NAIX.J.A., SMITH,S.J. Tennessee Valley Authority, 88/04/15, 4pp. 45216:070-45216:073.

T. Hearing transcripts on non-antitrust matters

8803100146 Forwards transcript of 880224 meeting w/licensee in Chattanooga,TN re-Unit 2 operational readiness including technical support & plant readiness.Presemation slides also end. ROBELLAT.S. Ofc. of Special Projects. 88/03/02. Ofc. of Special Projects. 3pp. 44652:132-44662:307.

109

- --8803100147 Transcript of 880224 public meeting in Chattanooga,TN re util operational readiness Presentation slides also encl.
 * Commissioners. 88/02/24. 173pp. 44662:135-44682:307.
- 8804010073 Summary of 880309 meeting w/TVA in Rockville,MD re technical Issues related to 10CFR50,App R.Attendance list, transcription,agenda & meeting handout ROTELLA.T.S. Ofc of Special Projects, 88/03/22, Ofc of Special Projects, 200
- --8804010078 Transcript of 880309 meeting in Rockville, MD re 10CFR50, App R issues Supporting documentation encl. ** Commissioners. 88/03/09. 173pp. 44950:34f-44951;153.

U. Congressional/Executive Correspondence

sular Affairs, 8pp. 45101:220-45101:230.

- 8804130222 Responds to questions in 880315 ltr re NRC investigation of S WHITE manager of Oic of Nuclear Power at TVA & discusses role of Oic of Investigations in subj case Assures that NRC made no attempts to dismiss Oic of Investigation 7001. ZECH,L.W. Commissioners 88/03/22. GEJDENSON,S. House of Rep., Interior & In-
- --8804130233 Requests answers to questions made by Subcommittee on general oversight & investigations re alleged NRC attempt to dismiss Ofc of investigation rept about credibility of 5 White, director of TVA nuclear program.
 GEJDENSON,S. House of Rep., Interior & Insular Affairs. 88/03/15, ZECH,L.W. Commissioners, 3pp. 45101:228-45101:230.
- 8804280317 Forwards NRR responses to Questions 1 & 3 re Commission stds for permitting restant of power plant after shutdown for safety reasons & Commission requirements for documenting licensing basis for restant decision, respectively.

 THOMAS.C.O. Policy Development & Technical Support Branch (Post 870411). 86/.
 04/19. REHM.T.A. Ofc of the Executive Director for Operations, 7pp. 45269:209-

V. Operator Examinations

44950:338-44851:153

- 8804250088 Responds to FOIA request for info re scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in encl app w/personal privacy info deleted.
 GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 88/04/19, BOLEY,K. Public Citizen's Critical Mass Energy Project. 2pp. 45213.003-45213:095.
- --8804250167 Package of NRC administered requalification exam results summary. NRC No Detailed Alfiliation Given. 87/07/20, 88pp. 45213:007-45213:095.

DOCKET 50-329 MIDLAND PLANT, UNIT 1

A. Application/construction stage documents & correspondence

- 8803240426 Generic Ltr 68-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements.Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972-107-44972-153.
- 8804080088 Generic LIr 88-07 to power reactor licensees & applicants re modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Satety for Nuclear Power Plants." Sve list encl. MIRAGLIA,F. J. Associate Director for Projects (Post 8704.11). 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors." Svc list encl. ROSSI.Cs. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 88-010, "Matte Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list encl.
 CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870729). 88/
 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Cit &/or Switchboard Function Due to Faulty Tie Bolts." Svc list encl. ROSSI.CE. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407:051.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/12.
 Consolidated Edison Co. of New York, Inc. 123pp. 45185:028-45185:150.

DOCKET 50-330 MIDLAND PLANT, UNIT 2

A. Application/construction stage documents & correspondence

- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svo list encl. MIRAGLIA, F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svo list and: MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors" Svc list enci.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/03/28
 Consol dated Edison Co. of New York, Inc. 121pp. 44995;128-44995.246
- 8803220296 NRC Info Notice 88-010, "Matts Licensees:Lack of Mgt Controls Over Liconsed Programs." Svc list enct. CUNNINGHAMR E Division of Industrial & Medical Nuclear Safety (Post 870729). 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353
- 8804010258 NRC Info Notice 88-011, "Potential Loss of Motor Control Cir &/or Switch-board Function Due to Faulty Tie Bolts." Svc list encl. ROSSI, CE. Division of Operational Eventis Assessment (Post 870411). 88/04/07 Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list and ROSSICE. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165.150.

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

F. Security, medical, emergency & fire protection plans

- 8804070027 Updates slatus of offsite radiological emergency planning & preparedness for plant & summarizes 880308 meeting re discussion of all unresolved planning inadequactes noted to date JD Overstreat 980307 lift to G Peterson encl PETERSON.G.C. Federal Emergency Management Agency. 88/03/30. STELLO.V. Ofc of the Executive Director for Operations. 22pp. 45234.355-45235.016.
- --8804110028 "Interim Evaluation of Linn County Radiological Emergency Plans for Duane Arno'd Energy Ctr."

 1 Federal Emergency Management Agency. 88/03/07, 98pp. 45072:132-45072:229.
- 8804200461 Forwards Mgt Meeting Rept 50:331/88-08 on 680407 re inadequacies in offsite emergency planning Understands I censee pursuing resolution of FEMA identified concerns & Issues to be addressed within time limit agreed to by FEMA NORELIUS, CE. Region 3, Offs of the Director, 88/04/12, LIU,L. Iowa Efectric Light & Power Co. 2pp. 45234:348-45234:354.
- --8804200509 Mgt Meeting Rept 50-331/88-08 on 880407.Major areas discussed licensee efforts in response to FEMA concern re adequacy of offsite emergency planning for Linn & Benion Counties & State of IA. PATTERSON.JP., SNELL.W.G. Region 3, Ofc of the Director. 88/04/12. 4pp 45234:351-45234:354.

J. Insurance & Indemnity Information

- 8804200026 Forwards Endorsements 1 & 2 to NEUA & MAELU Certificates NW-119 & 30420028 Forwards Endotsements 1 a 2 to Netth & MAELO Certificates Neverth 6 MW-45, respectively.
 SAMUELS,J.L. Marsh & McLennan, Inc. 88/04/13. DINITZ,I. Olfice of Nuclear Reactor Regulation, Director (Post 870411). 21pp. 45218:083-45218:103.

P. Operating license stage documents & correspondence

- 8803240426 Generio Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements. Svc list encl. MIRAGLIA, F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:163.
- 8804070237 Ack receipt of 880307 ftr Informing NRC of steps taken to investigate items of concerns re 880210 allegation of Improper use of non-1E electrical cable No further questions at this time.

 MILLER, HJ. Region 3, Ofc of the Director. 88/03/31, LIU,L. Iowa Electric Light & Power Co. 1p. 46031:009-45031:012.
- 8804120016 Application for amend to License DPR-49, revising Tech Specs re lodine reporting requirements to be consistent w/Generic Ltr 85-19 Fee paid. ROTHERT, W.C. lows Electric Light & Power Co. 88/03/31. MURLEY, T. Office of Nuclear Reactor Regulation, Director (Post 870411). 8pp. 45128:243-45128:268.
- --8804120026 Proposed Tech Specs, revising lodine reporting requirements.
 * lowa Electric Light & Power Co. 88/03/31, 18pp. 45128 251-45128.268.
- 8804140624 Forwards SER & contractor technical evaluation rept re util 841130 & 881215 submittals of DCRDR program plan & DCRDR summary rept,respectively, Submittals acceptable.

 HALL_JR, Project Directorate III-3, 88/04/08. LIU,L. lowa Electric Light & Power Co 2pp. 45130:188-45130.204.
- --8804140526 SER accepting util 861216 submittel of DCRDR summary rept.
 * Human Factors Assessment Branch. 88/04/06. 2pp. 45130:188-45130.189.
- -- 8802230018 "Technical Evaluation Rept of DCRDR for lowe Electric Light & Power Co.
- Duane Annold Energy Cit."

 Science Applications International Corp. (formerly Science Applications, Inc.). NAC-03-02-096. SAIC-88/3121. 88/02/18. NRC No Detailed Affiliation Given 15pp. 45130:190-45130:204.
- 8804080088 Generio Ltr 88-07 to power reactor licensees & applicants re-modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc ist encl MIRAGUIA,F.J. Associate Director for Projects (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184:237-45164.285.

Q. Inspection reports, IE Bulletins & correspondence

- 8804010119 Forwards response to IE Bulletin 87-002, "Fastner Testing to Determine Conformance W/Applicable Mall Specs."
 ROTHERT,W.C. lowe Electric Light & Power Co. 88/01/15, DAVIS,A 8, Region 3, Ofc of the Director, 93pp. 44983:303-44984.035.
- 8804060493 Forwards final rept on program carried out in response to IE Bulletin 85-003, "Motor-Operated Valva Common Mode Faitures During Plant Transients," per 860528, 1001 & 1222 tiris Proprietary MOVATS, Inc. rept encl. Rept withheld. ROTHERT,W.C. lowa Efectine Light & Power Co. 88/01/15, DAVIS,A.B. Region 3, Oic of the Director, 43pp. 45010 300-45010 342.
- 8803080514 Requests submittal of fee for 870115 application for relief from ASME Section XI requirements for second 10-yr inservice Inspiplen DIGGS.R.M. License Fee Management Branch. 88/03/04. LIU.L. Iowa Efectific Light & Power Co. 1p. 44634-360-44634-360.
- 8803210090 Suppl 1 to NAC Info Notice 87-044, "Thimble Tube Thinning In Westing-house Reactors," Svc list end.
 ROSSICE Division of Operational Events Assessment (Post 870411), 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp. 44995-126-44995-248
- 8803220296 NRC into Notice 88-010, "Matts Licensees Lack of Mgt Controls Over Licensed Programs." Svc list encl CUNNINGHAM R.E Dwiston of Industrial & Medical Nuclear Safety (Post 870729), 887 03728 Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353.
- 8804110098 Responds to NRC Bultorn 88-001, "Detects in Westinghouse Circuit Breakers." Review of facility equipment concludes that circuit breaker models not used Insprequired by Butletin 68-001 not explicable to plant.
 ROTHERT.W.C Towe Electric Light & Power Co. 88/03/30. MURLEY,T. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 45077.268-45077:268.
- 8804110057 Forwards Safety Insp. Rept 50:331/88-05 on 860229-0304 No violations noted.

 SHAFER,W.D. Region 3, Ofc of the Director. 88/04/05. LIU,t. Iowa Electric Light & Power Co. 2pp. 45128-129-45128-143.
- ~8804110090 insp Ropt 50:331/88:05 on 880229:0304 & 22 No violations noted Major areas inspected OA & confirmatory measurements for in-plant radiochemical analyses,vertication of TLD collocation, action on open items & mgt controls. JANUSKA,A., BOCANEGRARI, SCHUMACHER,M.C. Region 3, Old of the Director. 68/04/04, 13pp. 45128:131-45128:143.
- 8804150092 Advises that no further plant specific action required re-increse 970911 response to NRC 80feth 87-001, "Thinning of Pipa Walls at Noclear Power Plants." HALL, J.R. Project Directorate III-3, 88/04/06, LIU, L. Iowa Electric Light & Power Co. 2pp 45133:224-45133:225.
- 8804010256 NAC Info Notice 88-011, "Potential Loss of Motor Control Ctr. &/or Switchboard Function Due to Faulty Tie Bolts." Svc itst encl.

 ROSSI, CE. Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407.051.
- 8804060370 NRC Info Notice 88:012, "Overgreasing of Electric Motor Bearings." Svc hat enct ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150.
- 8804200481 Forwards Mgt Meeting Rept 50-331/88-98 on 880407 ie inadequacies in offsile emergency planning Understands licenses pursuing resolution of FEMA Identified concerns & issues to be addressed within time finitiagreed to by FEMA. NORELUS, CE. Region 3, Off of the Director. 88/04/12, UU, L. lowa Electric Ught & Power Co. 2pt. 45234:349-45234.354.
- -8804200509 Mgt Meeting Rept 50-331/88-08 on 880407.Major areas discussed licensee efforts in response to FEMA concern /e adequacy of offsite emergency planning for Linn & Benton Counties & State of IA. PATTERSON.J.P., SNELL,W.G. Region 3, Ofc of the Director. 88/04/12. 4pp. 45234.351.45234.351.

S. Reportable occurrences, LERs & related correspondence

8804060242 PNO-III-88-027:on 880330.FEMA informed NRC that offsite radiological emergency plan inadequate.FEMA review revealed that areas of Cedar Rapids & Marion,IA beyond identified 10- mile EPZ not included in offsite emergency planning effort SNELL.W., SHAFER,W. Region 3, Qfc of the Oirector, 88/04/01, 1p. 45034:101-45034:101.

V. Operator Examinations

- 8804250088 Responds to FOIA request for info re-scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in enciapp w/personal privacy info deloted.

 GRIMSLEY,D.H. Owision of Rules & Records (Post 870413), 88/04/19. BOLEY,K Public Critizen's Critical Mass Energy Project, 2pp. 45213:003-45213.095.
- --8804250167 Package of NRC administered requalification exam results summary. NRC - No Detailed Affiliation Given, 87/07/20, 68pp. 45213.007-45213.005

DOCKET 50-333 JAMES A. FITZPATRICK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

8804050153 Forwards Saleguards Insp Rept 50-303/88-03 on 880222-25.No violations noted MARTIN,T.T. Region 1, Ofc of the Director. 88/03/29, CONVERSE,R.J. New York Power Authority (formerly Power Authority of the State of New York). 2pp. 45017:175-45017.182.

- --8604050157 Partially withhold Physical Security Insp Rept 50-333/88-03 on 880225/25 (rel 10CFR73:21). No violations noted Major areas inspected plan 8 implementing procedures protected 8 vital areas 8 security sys power supply. MARTIN, W.G., KEIMIG,R.R. Region 1, Ofc of the Director. 88/03/24. Spp. 45017 177-45017:192.
- 8604080109 Revised emergency plan implementing procedures,including covershed to Rev 5 to IAP-2, "Classification of Emergency Conditions" & Rev 8 to EAP-4, "Dose Assessment Calculations." W/880329 It & revised index. MCMILER,M.A. New York Power Authority (formerly Power Authority of the State of New York). 88/03/29. 7pp. 45084 009-45064.016.
- 8804130384 Rev 9 to App C, "Lirs of Agreement" to emergency plan.
 * New York Power Authority (formerly Power Authority of the State of New York). 887
 03/31, 37pp. 45154;115-45154;151.

P. Operating license stage documents & correspondence

- 8604060114 Requests relief from performing hydrostatic test on RCIC & HPCI steam supply & exhaust piping in favor of inservice testing to demonstrate adequacy of pressure boundary & reduce exposure to test personnel.W/lour oversize drawings BRONS_JC. New York Power Authority (formerly Power Authority of the State of New York). 86/03/09. Document Control Branch (Document Control Desk) 6pp. 45098:152-45098.15
- 8603240426 Generic Ltr 88-05 to all power reactor licensees & applicants re removal of organization charts from Tech Spoc administrative control requirements Svc list encl MIRAGLIA.F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8803300015 Forwards proprietary NEDC-30799-P, "Feedwater Nozzle Fracture Mechanics Analysis to Show Compliance w/ NUREG-0619," & description of proposed inspiprogram for feedwater nozzles & discussion of program justification.

 BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York). 88/03/25. Document Control Branch (Document Control Desk). 9pp 44962-065-44962-072.
- 8804140193 Provides listed Info requested in 880225 ltr re operating nuclear power units located at twelve sites along Great Lakes. STELLO,V. Ofc of the Executive Director for Operations. 88/04/06. RIDGE,T. House of Rep. 5pp. 45104:138-45104:143.
- 880408088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified enlorcement policy concerning 10/CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIAF_J. Associate Director for Projects (Post 870411) 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804190161 Application for amend to License DPR-59, requesting exemption from containment integrated leak rate test retest schedule Exemption request, corrective action plan & plant drawings litentifying valve location enci. Fee patd.

 BRONS.J.C. New York Power Authority (formerly Power Authority of the State of New York), 88/04/08 Occument Control Brench (Document Control Desk), 46pp 45209.081-45209.106.
- 8804220108 Application for amend to License DPR-59,revising Tech Spec Section 4.6.G.1 re jet pumps to correct typo.Fee paid. BRONS.J.C. New York Power Authority (formerly Power Authority of the State of New York). 88/04/14. Document Control Branch (Document Control Desk). 3pp. 45221:243-45221:221.
- ~8804220107 Proposed Tech Spec Section 4.6.G.1, reducing max permissible recirculation loop flow imbalance from 15 to 10%.

 New York Power Authority (formerly Power Authority of the State of New York). 88/ 04/14, 6pp. 45221:216-45221:221.
- 8804270261 Notifies that BWR Owners Group "Guidelines for Permanent 8WR Hydrogen Water Chemistry (HWC) Installations-1987 Rev," resolves Generic Issue 136, "Storage & Use of Large Quentities..." & acceptable for ref in HWC installation. ABEL SON,H. Project Directorate 1-2 88/04/18, BRONS,J.C. New York Power Authority (formerly Power Authority of the State of New York). 3pp. 45243.001-45243.003

- 8804080114 Requests relief from performing hydrostatic test on RCIC & HPCI steam supply & exhaust piping in favor of inservice testing to demonstrate adequacy of pressure boundary & reduce exposure to test personnel W/four oversize drawings. BRONS.J.C. New York Power Authority (formetly Power Authority of the State of New York). 88/03/09. Document. Control. Branch. (Document. Control. Desk). 6pp. 45098;152-45098;157.
- 8803300015 Forwards proprietary NEDC-30799-P, "Feedwater Nozzle Fracture Mechanics Analysis to Show Compliance w/ NUREG-0619;" & description of proposed insp program for feedwater nozzles & discussion of program justification.
 BRONS.J.C. New York Power Authority (formetly Power Authority of the State of New York), 88/03/25. Document Control Branch (Document Control Desk). 9pp 44992-085-4498-2-072
- 8803210090 Suppl 1 to NPC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors" Svc list encl. ROSSI, C.E. Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995;246.
- 8803220296 NRC Into Notice 88-010, "Matts Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list encl. CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 870729). 887 03/28, Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804050153 Forwards Safeguards Insp Rept 50-333/88-03 on 880222-25 No violations noted.

 MARTIN,T.T. Region 1, Otc of the Director. 88/03/29. CONVERSE,R.J. New York Power Authority (formerly Power Authority of the State of New York) 2pp. 45017:175-45017-192

- --8804050157 Partially withhold Physical Security Insp Rupt 50-333/88-03 on 880225-25 (ref. 10CFR73.21).No. violations noted Major areas inspected plan. 8 implementing procedures, profected 8 vital areas 8 security sys power supply. MARTIN, W.G., KEIMIG, R.R. Region. 1, Olic of the Director. 88/03/24, 5pp. 45017.177-45013.18.
- 8804080174 Forwards Insp Rept 50:333/88-01 on 880112-0307 & notice of violation Additingt attention needed to assure that valves locked when required since similar event identified in lasp rept 50:333/87-22 WENZINGER.E.C. Region 1, Ofc of the Director, 88/03/29 CONVERSE.R.J. New York Power Authority (formerly Power Authority of the State of New York) 2pp. 45028 307-45028.325
- -8804080181 Notice of violation from inspirence 880112-0307. Violation noted LPCI Manual Isolation Valve 10-RHR-81A open but not locked on 880123.

 'Hogion 1, Ofc of the Director, 88/03/29. Ip: 45028:309-45028.309
- -8804060185 Insp Rept 50-333/88-01 on 870112-880312 Violation noted. Major areas inspected LER review.operational safety ventication, surveillance & maint observations, ESF sys walkdown, incensee reorganization & litness for duty poticy. JOHNSON, J. Region 1, Old of the Director, 88/03/25, 16pp. 45028 310-45028 325
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolls," Svc list onct. ROSSLC E Division of Operational Events Assessment (Post 870411), 88/04/07. Cansolidated Edison Co. of New York, Inc. 124pp. 45408 282-45407 051.
- 8804200206 Forwards request for addl info to ovaluate valve operability considerations in accordance w/IE Bulletin 85-003 Requests suppl to 860514,0904,1001 & 880115 responses to IE Bulletin 85-003 w/Info Idontified in encl. WENZINGER,E.C. Region 1, Olc of the Director, 88/04/11, CONVERSE,R.J. New York, Power Authority (formorly Power Authority of the State of New York), 4pp 45226.168-45226.171.
- 8604060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list and:
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12
 Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150.

8804150054 Monthly operating rept for Mar 1988 W/880409 ttr. COOK, J., CONVERSE, R. J., New York Power Authority (formerly Power Authority of the State of New York), 88/03/31, 12pp. 45159.286-45159.286

S. Reportable occurrences, LFRs & related correspondence

- 8804130405 LER 68-001-00:on 880310,HPCI lurbine steam supply valve 23-MOV-14 lailed to open during survoillance tosting Caused by destruction of commutator in motor due to excessive current Failed motor replaced W/680406 ftr. CHILDS.W.Y., CONVERSE, B.J., Now York Power Authority (formerly Power Authority of the State of New York). 88/04/06. Spp. 45151:272-45151:278.
- 8804130412 LER 88-002-00 on 880310,RCIC made inoperable for approx 1 minute due to automatic closure of steam supply valve while HPCI inoperable.Caused by failure to follow procedures RCIC restored to svc.W/880400 ltr. CHILDS,W.Y., CONVERSE,R.J. New York Power Authority (formerly Power Authority of the State of New York). 88/04/08. 5pp. 45138:015-45138.019.

DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8804220087 Revised emergency plan implementing procedures including Rev 2 to Issue 8 to EPP/IP 1.1, "Notifications" & Rev 1 to Issue 8 to EPP/IP 1.4, "Technical Support Cit Activation Operation & Operativation "W880414 Itr. NOONAN,T.P., SIEBER,J.D. Duquesne Light Co. 88/04/14, 218pp. 45236.057-45236 280

P. Operating license stage documents & correspondence

- 8803080023 Requests fed for application dtid 871112 re submitted Cycle 7 reload SER DIGGS,R.M. License Fee Management Branch, 88/03/03, CAREY,J.J. Duquesno Light Co. 1p. 44633:232-44633.232.
- 8804130188 Notification of Enforcement Conference 88-41 on 880324 w/ util in Region I to discuss inoperable containment pressure channels TRIPPLE. Region 1, Otc of the Director, 88/03/14, Region 1, Otc of the Director, 2pp 45122:206-45122:210.
- 8804050369 Forwards Rev 3 to Issue 2 to "Inservice Testing Program for Pumps & Valves" & results of safety injection accumulator discharge check valve testing SIEBER, J.D. Duquesne Light Co. 88/03/21. Document Control Branch (Document Control Desk). 2pp. 45060-328-45061:145.
- --8804050364 Rev 3 to Issue 2 to, "Inservice Testing Program for Pumps & Valves." Ouquesne Light Co. 88/03/21, 178pp. 45060:328-45061.145.
- 8804140511 Forwards Amend 122 to License DPR-66 & safety evaluation. Amend changes Tech Specs re station battery voltage Portion of 870701 application, supplemented on 870126 re battery specific gravity not granted Notice of

definal also enci TAM.P.S. Project Directorate I-4, 86/03/21, SIEBER,J.D. Duquesne Light Co. 2pp. 45130.172-45130 182.

- --8804140515 Amend 122 to License DPR-66, changing Tech Specs re station battery voltage requirements. STOLZ,J.F. Project Directorate I-4, 88/03/21, 4pp. 45130:174-45130:177.
- --8804140520 Safety evaluation supporting Amend 122 to License DPR-66.
 Office of Nuclear Reactor Regulation, Director (Post 870411). 88/03/21. 2pp. 45130:178-45130:179.

- --8804140528 Notice of partial denial of application for amend to License DPR-66, revising Tech Space requirements for operability & surve l'ance for station batteries. TAM, P.S. Project Oirectorate I-4, 88/03/21, 3pp. 45130.180-45130:182.
- 8803240426 Generic Lir 88:06 to a'l power reactor licensess & applicants re removal of organization charts from Tech Spec administrative control requirements. Svc fist encl. MIRACLIA, F.J. Associate Director for Projecto (Post 870411) 88/03/22 Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804010211 Forwards 801224 correspondence re allegations of inadequate stress analyses performed by contractor Review of circumstances surrounding document & rept of findings & conclusions requested within 30 days of ltr
- 8804010129 Informs that I sted commitments made in 880303 (osponse to Generic Ltr. 88-03, "Resolution of Generic Safety Issue 93, Steam Binding of Auxiliary Feedwater Pumps" responsive to guidance of generic fit.

 TAM_P.S. Project Orrectorate I-4. 88/03/28. SIEBER, J.D. Duquesne Light Co. 2pp. 44921:356.44921:357.
- 8804140340 FOIA request for correspondence between NRC & Duquesne Light Co re NRC Inquiry Into 801224 memo by B Gupta to C McCullough concerning work done by Schneider, Inc. at plant BRELISM, Pittsburgh Press Pittsburgh, PA. 88/03/28. Office of Administration & Resources Management, Director (Post 870413). 1p. 45118 047-45118 047.
- 8804120025 Forwards corrected copy of page 3/4 11-8 of Amend 121 to License DPR-66 Issued 880314 Amend erronegusly ref Figure 5.1-2 Instead of Figure 5.1-1. TAM.P.S. Project Directorate 1-4, 68/03/30. SEIBER,J.D. Duquesne Light Co. 3pp. 45089-195-45089-197.
- --8804120297 Corrected page 3/4 11-6 of Amend 121 to License DPR-66, correcting typo to Figure 5.1-2 to Figure 5.1-1.
 TAM.P.S. Project Directorate I-4, 68/03/30, 1p. 45089:197-45089:197.

- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nucloar Power Planta;" Svc list encl. MIRAGUA,F. J. Associate Director for Projects (Post 870411), 88/04/07, Conscindated Edison Co. of New York, Inc. 48pp. 45164:237-45184-285.
- 8804190268 Forwards Amend 123 to License DPR-66 & safety evaluation. Amend revises certain Tech Specs re waste gas decay tank to remove requirements associated w/radiation monitor.
 TAM.P.S. Project Directorate 1-4, 88/04/07, SIEBER,J.D. Duquesne Light Co. 2pp.
- 45155 268 45155 300
- -- 8804190278 Amend 123 to License DPR-66, revising Tech Specs re waste gas decay tenk to remove requirements associated w/radiation monitor. STOLZ,J.F. Project Directorate I-4, 89/04/07, 7pp. 45155:290-45155:296.
- --8804190282 Safety evaluation supporting Amend 123 to License DPR-66.

 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/07, 3pp. 45155-297-45155-300.
- 8804210044 Forwards application (eg. for NAC review of Cycle 7 reload SER submitted by 871112 fir.per 880303 request.Fae paid. VASSELLO,J.V. Duquesne Light Co. 88/04/12. License Fee Management Branch. 19 45219;119:45219;119
- 8804210359 Notification of 880421 meeting w/util in Rockville,MD to discuss status of current active licensing actions.

 TAM,P S. Project Directorate I-4, 88/04/18, MURLEY,T, SNIEZEK,J, MIRAGLIA,F, NRC No Detailed Affiliation Given, 3pp. 45192,094-45192,096.
- 8804280464 Approves request for exception to location requirement for technical support center (TSC) & retraction of commitment to provide alternate TSC near control room Stated emergency preparedness inspring rept also reviewed.

 TAM.P.S. Project Directorate 1-4. 88/04/20. SIEBER,J.D. Duquesne Light Co. 2pp. 45263:032-45263 033.

- 8804010138 Forwards requests for reflet from listed ASME Section XI inservice insp re-quirements for pressurizer surge line & steam generator nozzle rad1 & conregenera-live HX CH-E-2. SIEBER_JD. Duquesna Light Co 87/11/10. Document Control Branch (Document Control Desk): 18pp. 44983:285-44983:302.
- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Wastinghouse Reactors." Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:128-44995:246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees:Lack of Mgt Controls Over Licensed Programs " Svc list enci.
 CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 88/03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995.353.
- 8804130257 Forwards response to NRC Bulletin 88-002, "Rapidly Propagating Fatigue Cracks in Steam Generator Tubes," Evaluation addressing Itams C.2 a & C.2.b will be submitted by 880531.
 SIEBERJD. Duquesne Light Co. 88/03/28. Document Control Branch (Document Control Desk). 8pp. 45154:161-45154:188.
- 8804120352 Responds to NRC 880304 ltr re violations noted in Insp Rept 50-334/88-03 Corrective actions memo noting violation circulated for radiological control personnel reviews, noting that personnel will be accountable for actions. SIEBERIJD, Ducussne Light Co. 88/04/04. Document Control Branch (Document Control Desk). 2pp. 46089:320-45089:321.

- 8804110274 Final response to FOIA request Forwards App A document. Document parhalfy whineld (rol FDIA Exemption 6) Bockman was resident inspection at facility from late 1970 unit. 1982 GRIMSLEY, D.H. Division of Rules & Records (Post (870413) 88/04/05. ZLATOS,B. Pullsburgh Press Pillsburgh,PA. 3pp. 45078-172-45078-175.
- 8804010256 NRC Into Natice 88-011. Polential Loss of Motor Control Cir. 8/or Switch-Boson Country of Pauly Tie Bots: Svc Lst end:

 HOSSI, C.E. Division Oue of Operational Events Assessment (Post 670411) 89/04/07

 Consolidated Edison Co. of New York, Inc. 124cp. 45406 292-45407 051
- 8804200040 Forwards Salety Insp Repts 50-334/88-09 & 50-412/68-05 on 890222-26 8 notice of wickling BELLAMY, R.A. Region 1. Ofc of the Director 88/04/08. CAREY, J.J. Disquesne Light Co. 3pp. 45235-056-45235-068
- -8804200044 Notice of violation from inspirence 802222.26 Violation nated ich 870908 Shipment Number 0951 of redwaste sent to supercompacting facility & accompanied by manifest which did not identify existence & quantilities of redwaste in stripment 1 Region 1, Occidition Director 88/04/08 tip 45235 059-45235 059
- -8804200046 Insp. Repts. 50:334/88:00 & 50:412/88:05 on 880222:26. Violations noted Major arcas inspecified transee soil radwaste & transportation program including rigid control, shipments of radioactive matts training & procedures DAVIDSON,BIS. PASCIAK,W.J. Region 1. O'c of the Director. 88/04/04. 9pp. 45/235.060. 45/235.060.
- 8804200074 Forwards Insp Rept 50 334/88-05 on 880208-12 No viciations noted JOHNSTON,W V Region 1, Otc of the Director, 89/04/08, SFBER,JiD. Duquesno Light Co. 2pp. 45216/039-45216/048
- -8804200075 Insp Rept 50:304/89:06 on 880208-12 No violations or deviations noted Miltor areas inspected steam generator oddly current inspirator chemistry controls & steam generator maint radiological controls.

 WINTERS,R.W., STROSNIDER,J. Region 1, Old of the Director 88/03/24 8pp. 45216.041-45218 048
- 8804 (10257 FQIA request for D Beckman employment dates as NRC resident inspector at plant ZLATOS B. Prisburgh Press Pittsburgh PA 88/04/11 NRC - No Dotailed Afficiation Given: Ep. 45078:171-45078-171
- 8804080370 NRC into Notice 88-012. Overgreasing of Electric Motor Bearings." Svc ROSSI,C E. Div. sion of Operational Evants Assessment (Post 870411). 88/04/12. Conscitated Edison Co. of New York, Inc. 123pp. 45165 028-45165 150.
- 8804250310 Forwards Insp. Rept. 50-334/88 02 cn. 860201-05 & notice of deviation Specific response to numerous inconsistencies w/ procedures generation package identified in procedural stops of omergency operating procedures requested GALLO.R.W. Region 1, Ofc of the Director 88/04/14 SIEBER.J.D. Duqueene Light Co. 2pp. 45268:125-45268-152
- +8804250312 Notice of doviation from insp on 880201-05 Deviation noted, failure to follow NRC approved procedures generation package
 * Region 1, Otc of the Director 88/04/14, 2pp. 45268 127-45268.128.
- --8804250315 Insp. Ropt 50:334/88-02 on 880201-05 Deviation noted Major areas inspected houses conformance to NRC approved procedure generation package redevelopment & implementation of emergency operating procedures. BISSETT, DUDLEY.N., ESELGROTH,P. Region 1, Ofc of the Director. 88/04/13. 24pp. 45268 129-45288:152

- 8804060095 NPDES Monthly Dischargo Monitoring Rept for Feb 1988." W/ 880328 Br. DRUGAR.J Duquesne Light Co 88/02/28 VARGA,S. Office of Nuclear Reactor Regulation, Director (Post 870411) 21pp. 45046.176.45046 196
- 8804040058 Forwards monthly operating rapts for Fab 1988 & revised monthly operating rept for Jan 1988,consisting of revised unit shuldown & power reduction sheet SIEBER,J.D. Duquesne Light Co. 88/03/10. NRC - No Detailed Affiliation Given. 1p 44921 318 44921 327
- --8803300320 Monthly operating repts for Feb. 1988. WINGER,M.A. Duquesne Light Co. 88/02/29, 8pp. 44921:319-44921:326.
- --8804040064 Revised monthly operating rept for Jan 1988 WINGER,M.A. Duquesno Light Co. 88/01/31, 1p. 44921:327-44921:327.
- 8804190038 Monthly operating repts for Mar 1988 W/860413 ftr WINGER,M.A., SIEBER,J.O. Duquesne Light Co 88/03/31, 10pp. 45208:237-45208 246

S. Reportable occurrences, LERs & related correspondence

- 8803280034 LER 88:002:00 on 880219 reactor trip on to to steam generator level oc-curred due to personnel cirror. Simulated level signals inserted into steam generator level circultry to confune ditalning 8 refiting evolutions W1980318 iff. NOONAN,T.P. Duquesne Light Co. 88/03/18. 4pp. 44921:042-44921.045
- 8804040221 LEA 88-003-00.on 880225,inadvertent start of auxiliary feedwater pump occurred Caused: by procedural deficiency in surverlance test Procedure revised to transfer steam in/et valve control w/valves open.W/880328 ltr. NOONAN,T P. Duquesne Light Co. 88/03/28, 5pp. 45075 314-45075 318.
- 8804080060 LER 88-004-00 on 880303,two containment hi-hi pressure bistables bypassed Caused by procedure deficiency. Bistables returned to evo; surveillance procedures fev sed & review initiated W/880404 Itr. NOONAN,T.P. Duquesne Light Co. 88704/04. 8pp. 45098-183. 45098-188.
- 8804130086 LER 88-001-01:on 880208,steam generator tubes plugged due to excessive degradation Caused by cold leg support plate thinning.Uibend cracking & hot leg support plate dimage. Degraded tubes preventively plugged W/880404 itr NOONAN,T,P Duquesne Light Co. 88/04/04. 6pp. 45131-035-45131-040

8804140166 Special reption 880309, line protection sysitest did not verify manual & automatic operation of three CO2 fire nampers as required by Tech Spec 4.7.14.3.b.l. Continuous fire watch posted immediately for all effected areas NOONAN, T.P. Disquession Light Co. 88704768. Occument Control Branch (Document Control Desk). 29p. 45158-296-45158-297.

V. Operator Examinations

- 8804250088 Responds to FOtA request for infoire scores of reactor appretors & sonior reactor operators for one request to find the sched of perator updates updated updates forwards requested on each summary source sheets listed in encl. app w/personal privacy into defeted. GRIMSLEY.DH. Division of Rules & Records (Post 870413). 88/04/19. BCLEY.K. Public Citizen's Critical Mass Energy Project. 2pp. 45213.003-45213.095.
- --8804250167 Package of NAC administered requalification exam results summary NAC No Detailed Affiliation Given 87/07/20 88pp 45213 007 45213 095.

DOCKET 50-336 ST. LUCIE PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8804010061 Forwards Irisp Repts 50 335/88 05 & 50-389/88 05 on 880307 11 No vio fations or deviations noted.

 HERDT,A.R. Region 2, Old of the Director, 88/03/24. CONWAY,W.F. Florida Power & Light Co. 2pp. 45008:111-45008 123.
- --8804010062 Insp Repts 50:335/88:05 & 50:389/88:05 on 880307-11 No violations or deviations noted Major areas inspected fire protect on/prevention WISEMAN, G.R., CONLON, T.E., Region 2, Ofc of the Director, 88/03/21, 11pp 45008 113 45008 123
- 8804120174 Forwards Insp Hepts 50:335/88:02 & 50:389/88:02 on 880208:12 & notice of wc/ation.Notice of violation & rept details withherd (ref) 10CFR2.790(d) & 73.21) GRACE, J.N. Region 2, Olic of the Director. 88/04/04. WOODY, C.O. Florida Power & Light Co. 2pp. 45132, 150:45132 152.
- **8804120176 Parhally withheld Insp. Repts 50:335/88-02 & 50-389/88-02 on 880208-12 Violations noted Major areas inspected security plan, security organization, records & repts, testing & maint, physical barriers protected area & vital areas THOMPSON, D.H., STANSBERRY, W.W., MCGUIRE, D.R. Regton 2, Otc of the Orector. 88/04/04. 1p 45132 152-45132 152
- 8804140297 Forwards periodic rept updating population estimate for area within 10 miles of plant per Tech 6.9.1.9.Into will be included in 1989 revs of updated FSAR Rept also forwarded to State of FL for possible incorporation in emergency plan CONWAY,W.F. Florida Power & Light Co. 88/04/06. Document Control Branch (Document Control Desk). 44pp. 45131:128-45131:169
- 8804150190 Forwards proposed changes to Rov 12 to physical security plan ro miscollaneous amends & search requirements. Changes withhold (ref 10CFR73 21). CONWAY, W.F. Florida Power & Light Co. 88/04/11. Document Control Branch (Decument Control Desk). 1p. 45238 291-45238 291
- 8804150194 Forwards Rev 14 to physical security plan Rev does not decrease safe quards effectiveness of plan.End withheld (ref 10CFR73.21 & 2.790). CONWAY,W.F. Florida Power & Light Co. 98/04/11. Document Control Branch (Docu-ment Control Desk). 2pp. 45183 359-45183 369.
- B804200473 Partial response to FOIA request re line protection Forwards App E documents App D & E documents available in PDR App F document completely withheld (ref FOIA Examption of Ru'es & Records (Post 870413). 88/04/14, JONES,C.R. Afficiation Not Assigned. 5pp 45206.037-45206.043
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App Ritype inspiror each facility to assess status of comphanics w/ 10CFR50.48 Program Insted. CONLON,T.E. Region 2, Ofc of the Director. 84/11/08. HEHDT,A.R. Region 2, Ofc of the Director. 3pp. 45206:176-45206:178.

G. Adjudicatory correspondence

- 8804110044 Advises that Martin County Conservation Alliance voted to support recipient activity of monitoring plant Alliance expected to be represented at 880329 meeting in Jensen Beach FL Served on 880407. FILONOWICZ.J.C. Martin County Conservation Alliance. #288 6022. 88/04/04. RICH.C. Affiliation Not Assigned 1p. 45050:086-45050 086.
- 8804200054 Forwards NRC analysis of radiological consequences of spent fuel pool boiling at Unit 1,per 880329 prehearing conference w/util & NRC commitment to provide subjimati. Related correspondence.

 VGGLER,B.H. Assistant General Counsel for Hearings. #288 6074. 88/04/15 RICH,C Attitation Not Assigned. 1p 45162.087-45162.087

8804260049 Memorandum & order * C Rich admitted as party to proceeding. Petitioner Contentions 3,4,6,8,0,11 & 15 admitted,as amended Parties desiring to invoke hybrid hearing procedures should file request by 880506 Served on 893422 COTTER,B.P., BRIGHT,G.O., COLE,R.F. Atomic Safety and Licensing Roard Panel. #288 8119. 88704720, 34pp. 45210.101-45210.134.

J. Insurance & Indemnity Information

8803300400 Discusses nuclear property insurance programs for onsite property damage.
CONWAY,W.F. Florida Power & Light Co. 88/03/25 Document Control Branch (Document Control Desk). 2pp. 44967-243-44967.244

113

- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants to removal of organization charts from Tech Spec administrative control requirements Svc list encl MiRAGLIA,F. J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972.107-44972.153.
- 8804070175 Forwards further progress re USI A-48,Generic Ltr 87-02, "Vor" cation of Seismic Adequacy of Machanical Equipment in Operating Reactors." Results of site-specific value/impact analyses in hand & meet wit be scheduled CONWAY,W.F. Florida Power & Light Co. 88/03/31. Document Control Branch (Document Control Desk). 1p. 45024:355-45024:355.
- 8604110256 Forwards SER & contractor rept accepting util responses to Generic Lir 83-28, "ATWS Item 2.1 (Part 2), Vendor Interface Program Reactor Trip Sys Compo-nents."
- TOURIGNY,E G. Project Directorate II-2. 88/04/01 CONWAY,W.F. Florida Power & Light Co. 2pp. 45079.069-45079.085.
- -8804110275 SER accepting util response to Generic Ltr 83-28, Item 2 1 (Parl 2)
 * Project Directorate II-2, 88/04/01, 3pp. 45079.071-45079.085 8804130333 Forwards Amend 92 to License DPR-67 & safety evaluation. Amend increases max U-235 enrichment contained in unirradiated fuel stored in new fuel stor
 - age racks to 4.5 weight percent.
 TOURIGNY,E.G. Project Directorate 11-2. 88/04/05. CONWAY,W.F. Flunda Power & Light Co. 2pp. 45103:198-45103:207
- --8804130337 Amend 92 to License DPR-87,Increasing max U-235 enrichment contained in unirradiated fixel stored in new fuel storage racks to 4.5 weight percent. BERKOW,H.N. Project Directorate II-2, 88/04/05, 5pp. 45103:200-45103.204.
- --8804130340 Satety evaluation supporting Amend 92 to License DPR-67.
 Office of Nuclear Reactor Regulation, Director (Post 870411) 88/04/05 3pp 45103 205-45103:207.
- 8804120332 Forwards add! into an proposed license amend re boric acid concentration reduction.per NRC 880310 telcon request. CONWAY.W F. Florida Power & Ught Co. 88/04/06. Document Control Branch (Document Control Desk). Bpp. 45090 084-45090.091.
- 8804080088 Generic Ltr 88-07 to power reactor licenseos & applicants ro modified on-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list enct. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285
- 8804190135 Forwards response to 880223 request for additinto re Generic Ltr 86-08, "Reactor Coolant Pump Trip Criteria." CEN-268 revised to delinte any rolls to use of containment radiation alarms as possible criteria for tripping second two pumps. CONWAY,W.F. Florida Power & Light Co. 88/04/11. Document Control Branch (Docu-ment Control Desk). 8pp. 45163:348-45153:355.
- 8804290070 Forwards safety evaluation supporting approval of licensee Topical Rept NTH.G-6 & accepting proposed methodology described in licensee topical rept on PWR taitice physics methodology. LAINAS,GC. Assistant Director for Region II Reactors. 89/04/19. CONWAY,W F Florida Power & Light Co. 5pp. 45324:216-45324:245.
- --8804290076 Safety evaluation supporting licensed use of RETRAN computer code for sys translent analyses & approving licensed topical rept on PWR lattice physics methodology.
 - Assistant Director for Region II Reactors, 88/04/19, 7pp. 45324:221-45324:245
- 8804290058 Forwards request for addlinto re ATWS Item 2.2 (Part 1) of Generic Ltr 83-28 Info requested within 45 days of date of fir in order to maintain roview schodule TOURIGNY,E.G. Project Directorate II-2. 88/04/22. CONWAY,W.F. Florida Power & Light Co. 4pp. 45322 209-45322.212.

Q. inspection reports, IE Builetins & correspondence

- 8804010061 Forwards Insp Repts 50:335/88-05 & 50:389/88-05 on 880307-11.No vio-
- lations of deviations noted.
 HERDT,A.R. Region 2, Ofc of the Director. 88/03/24, CONWAY,W.F. Florida Power & Light Co. 2pp. 45008.111-45008.123.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors." Svc list encl.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NHC Info Notice 88-010, "Matts Liconsees:Lack of Mgt Controls Over Li-censed Programs." Svc list enct. CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870729). 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995-247-44995:353.
- 8804060381 Ack receipt of 880307 ftr Informing NRC of steps taken to correct violations noted in Insp. Repts 50-335/87-31 & 50-389/87-30.Implementation of corrective actions will be examined during future Insp. WILSON,B.A. Region 2, Ofc of the Director. 88/03/28. CONWAY,W.F. Flonda Power & Light Co. 1p. 45010:351-45010:351.
- 8804120003 Ack receipt of 880321 Itr informing NRC of steps taken to correct violations noted in Insp Repts 50:335/86-08 & 50:389/88-07.

 HERDT.A.R. Region 2, Ofc of the Director. 88/04/04. CONWAY,W.F. Florida Power & Light Co. 1p. 45135:294-45135:294.
- 8804120174 Forwards Insp Repts 50-335/88-02 & 50-389/68-02 on 880208-12 & notice of violation.Notice of violation & rept details withheld (ref 10CFR2.790(d) & 73.21). GRACE, J.N. Region 2, Ofc of the Director. 88/04/04. WOODY, C.O. Florida Power & Light Co. 2pp. 46132:150-45132:152.

- --8804120176 Parihally withhold Insp Repts 50:335/88.02 & 50:339/88-02 on 890208-12 Violations nated Major areas inspected security plan security organization, records & repts testing & maint, plays call bair are protected area & vital areas. THOMPSON,D H. STANSSERRY.W W., MCGUIRE,D R. Region 2, Old of the Director 88/04/04 1p 45132 152-45132.152
- 8804010256 NRC Info Notice 88.011, "Potential Loss of Motor Control Cir &/or Switch-board Function Due to Faulty Tie Bolts." Svc list encl. ROSSI,C E. Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Foison Co. of New York, Inc. 124pp. 45406/292/45407.051.
- 6804060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc. list encil ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp 45165.028-45165.150
- 8804200473 Partial response to FOIA request reltire protection Forwards App E documents App D & E documents available in PDR App F document completely with held (ref FOIA Exemption 5) GHIMSLEY, 0.H. Division of Rules & Records (Post 870413), 88/04/14, JONES,C R. Alfidiation Not Assigned 5pp 45206 037-45208 043.
- --8804200579 Advisos that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type insp for each facility to assess status of compliance will 10CFR50 48 Program I sted CONLOY,T.E. Region 2, Oic of the Director, 3pp. 45266,176-45206,178.

R. Periodic operating reports & related correspondence

- 8804190272 "Annual Radiological Environ Operating Rept St Lucie Plant Units 1 & 2." CONWAY,W F. Florida Power & Light Co. 67/12/31 65pp. 45207:317-45208:021.
- 8804220108 Forwards monthly operating ropis for Mar. 1988 & corrected Feb. 1988 unit shutdowns & power reductions rept for Unit 4. Corrected rept provides info on outage that was omitted from oughal rept. CONWAY, W.F. Florida Pawer & Light Co. 88/04/15. Document Control Branch (Document Control Desk). 1p. 45216 192-45218 210.
- --8804220074 Monthly operating repts for Mar 1988 GRANT,N W. Florida Power & Light Co. 88/03/31, 16pp. 45216:195-45216.210.

S. Reportable occurrences, LERs & related correspondence

- 8803290210 Special reption ti80314,steam generator blowdown bldg exhaust nobio gas radiation monitor talled Caused by failed central processing unit processor board Portable particulato,odino & nobio gas monitor installed until new monitor in place
 - CONWAY,W F. Florida Power & Light Co. 88/03/25, Document Control Branch (Decument Control Desk), 2pp. 44903:294-44903-295.

T. Hearing transcripts on non-antitrust matters

8804010197 Transcript of 880329 hearing in Jensen Beach,FL.Pp 1-128.

* Atomic Safety and Licensing Board Panet 98/03/29, 134pp. 44917:168-44917:301.

DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

- F. Security, medical, emergency & fire protection plans
- 8804080003 Forwards addl into clarifying proposed change to NRC 871223 physical security plan, per 870816 leicon Enct withhold (ref. 10CFR73.21 & 2.700(a)).

 MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).

 MROCZKA,E.J. Northeast Utilities 88/03/29 Dacument Control Branch (Document Control Desk). 2pp. 45047.173-45047:174
- 8804060142 Forwards SALP Repts 50-245/86-99 & 50-336/86-99 for June 1986 Dec 1987.Util should be prepared to discuss assessments & any plans to improve perform-
 - RUSSELL, W.T. Region 1, Ofc of the Director, 88/03/29, MROCZKA, E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 45045-325-45048.063.
- --8804060147 SALP Ropts 50:245/66:99 & 50:336/66:99 for June 1986 Dec 1987 * Region I, Ofc of the Director. 88/02/25. 87pp. 45045:327-45046.063.
- 8804080269 Rev 3 to emergency plan implementing procedure (EPIP) Form 4211-1, "Station Emergency Organization Lead Oncall Position Managers." Rev 82 to EPIP form Index & 880331 lift each. MROCZKA,E.J. Northeast Nuclear Energy Co. (subs of Northeast Utilaties) MROCZKA,E.J. Northeast Utilaties, 88/03/31, 8pp. 45123 289-45123:296.
- 8804280189 Forwards environ assessment & finding of no significant impact re 880229 application for exemption from requirements of 10CFR50,App R. JAFFE,D.H. Project Directorate 1-4. 88/04/89. MRCOZKA,EJ. Northeast Nuclear Energy Co. (subs of Northeast Utilities). 2pp. 45276.234-45276.238.
- --8804280194 Environ assessment & finding of no significant impact re exemption from requirements of 10CFR50,App R concerning separation of auxiliary feedwater isolation valves,por 880229 request.

 STOLZ_J.F. Project Directorate I-4 88/04/08. 3pp. 45276:236:45276.238.
- 8804200172 Forwards Insp Rept 50:338/88-06 on 880208-0321.No violations noted. Attention ca'ted to control of overtime Maint hot work performed w/o fire watch Licensee 880210 response to violation from Insp 50:336/87-25 adequate. BETTENHAUSENL. Region 1, Otc of the Director. 88/04/13, MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Ub'ties). 2pp. 45221.065-45221.085.

-8804200194 Insp Rept 50-336/88-06 on 880208-0321 No violations noted Major areas inspected previously identified items.plant operations, surveillance, radiation protection physical security fire protection & review of periodic repts MCCABE, E.C. Region 1, Drc of the Director 88/04/13 19pp, 45221.067-45221-085.

8804250267 Forwards temporary change to physical security plan re-protected area boundary Rev withheld (rel 10CFR72 790(a)) MROCZKA.E.J. ROMBERG.W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA.E.J. Northeast Utilities 88/04/22. Document Control Branch (Document Control Desk). 2pp. 45281 288-45281 287.

H. Beneral correspondence

8804070291 Comments supporting proposed rule 10CFR50 re leakage testing of containment to permit use of mass point method as alternative method for calculating containment leakage rates Mass point method more accurate for calculating rates. MROCZKAE J. Connecteut Yankee Atomic Power Ca 88/03/21. CHILK,S.J. Office of the Secretary of the Commission. 3pp. 45021:184.45021:186.

8804140014 Forwards Connectcut Light & Power Co & Western Massachusetts Electric Co "Annual Rept 1987," per 10CFR50 71(b) Northeast Nuclear Energy Co financial rept will not be available until on or about 880427 GUGLEEUM

-8804140017 "Annual Rept 1987."
FOX.B.M., ELLIS.W.B. Connecticut Light & Power Co. (subs. of Northeast Utilities).
87/12/31 43pp 45122.338-45123.019

-8804140022 "Annual Rept 1987"
FOX.B.M., EELIS,W.B. Western Massachusetts Electric Co. (subs. of Northeast Utili-bes) 87/12/31, 31pp. 45123 020-45123 050

8804250249 Informs that payment of third quarterly installment of 1988 annual fee per 10CFR171 will be wire transferred on 880429. MROCZKA,E J. Connectical Yankee Atomic Power Co. MROCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA,E J. Northeast Utilities, 887-04/18. Document Control Branch (Document Control Desk). 2pp. 45258-292-45258-292. 45258.293

J. Insurance & indemnity information

8804070118 Notifies Commission of amount of property insurance coverage currently in force for facilities Types of coverage 8 markets listed.

MROCZKA,E J Northeast Nuclear Energy Co. (subs. of Northeast Utilities).

MROCZKA,E J Northeast Utilities 88/09/30 WOOD,R. Policy Development & Technical Support Branch (Post 870411) 2pp. 45022 092-45022 093.

P. Operating license stage documents & correspondence

8803080019 Forwards safety evaluation approving capability of primary sys safety & relief valves & associated block valves per TMI Action Item II D.I Conclusions predicated upon successful completion of valve test program.

JAFFE, D.H. Project Directorate 1-4, 88/03/01 MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 30pp. 44633-183-44633-222.

8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIA.F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972.107-44972.153

8804050317 Forwards Amend 127 to License DPR 65 & safety evaluation. Amend revises Tech Specs to dolete chlorine defection sys from Tech Spec 3/4.3.3.6 & Table 39-1 to reflect installation of new access door to spent fuel pool area. JAFFE,DH Project Directorate 1-4, 88/03/28 MROCZYAE,J. Northeast Nuclear Energy Co (subs. of Northeast Utilities) 2pp. 44997 299-44997:312.

-8804050320 Amend 127 to License OPR-65 revising Tech Specs to delete chlorine detection sys from Tech Spec 3/4/3/3/6 & Table 3/9-1 to reflect installation of new access door to spent five pool area. STOLZ,JF Project Directorate I-4. 88/03/28 9pp 44997:301-44997:309

-8804050322 Safety evaluation supporting Amend 127 to License DPR-65.
Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/28, 3pp.
44997 310-44997.312

8804110150 Forwards Amend 128 to License DPR-65 & safety evaluation. Amend modifies Tech Spec. 3 9 20, "Spent Fuel Pool," detering tootnote limiting storage of consolidated spent fuel storage canisters.

JAFFE,D.H. Project Directorate 1-4, 88/03/31 MROCZYAKE, J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities), 2pp. 45077-349-45077-359.

-9804110172 Amend 128 to License DPR-65,modifing Tech Spec 3.9.20, "Spent Fuel Poot," by deleting tootnote limiting storage of consolidated spent fuel to five consolidated spent fuel storage canisters. STOL2_JF. Project Directorate I-4. 88/03/31, 4pp. 45077.351-45077.354.

-8644110178 Safety evaluation supporting Amend 128 to License DPR-65.

**Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/31, 3pp.

**45077352-45077357.

-8804120047 Notice of issuance of amend to License DPR-85 Amend changes Tech Spec 3.9.20, "Spent Fuel Pool," by defeting footnote firmling storage of consolidated spent fuel to five consolidated spent fuel storage canisters. JAFFE,D.H. Project Directorate II-2, 88/03/31, 2pp. 45077.358-45077:359.

8404120012 Forwards corrected copy of page 6-19 of Amend 120 to License DPR-65 assed 870928 Amend failed to incorporate change made by Amend 119.

JAFFE,D.H. Project Directorate I-4 88/03/31. MROCZKA,E.J. Nortneast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 45089:191-45089.194.

-8804120255 Corrected page 8-19 of Amend 120 to License Divines. Incorporation omitted change made by Amend 119.
 Project Directorate 1-4: 68/03/31. 2pp. 45069:193-45089:194.

8804120153 Submits correction to inadvertently assigned Amend 125 to License DPR 65.Correct amend should be Amend 126.

JAFFE,O.H. Project Directorate I-4, 88/03/31, MROCZKA,E.J. Northeast Nuclea Energy Co. (subs. of Northeast Utilities), 2pp. 45100:360-45100:361.

8804080088 Generic Ltr 88-07 to power reactor beensoes & applicants re-modified en forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc list and. MIRAGLIA,F.J. Associate Director for Projects (Post 8704.11), '88/04/07, Consol date: Ed son Co. of New York, Inc. 49pp. 45164:237-45164:285.

8804120423 Forwards payment on Invoice for costs incurred during NRC review of Rev B & 9 to Topical Rept NU-QA-1.
MROCZKA,E.J. Connecticut Yankee Atomic Power Co. MROCZKA,E.J. Northeast Nuclear Energy Co (subs. of Northeast Utilities). MROCZKA,E.J. Northeast Utilities). MROCZKA,E.J. Northeast Utilities 68 04/08. Document Control Branch (Document Control Dosk). 4pp. 45091.001 45091:004.

8804200533 Advises that util plans to assess operational roadinoss of solocled safet sys to function under operational & analyzed accident conditions. Assessment program will use format of 871204 NRC Insp Manual Chapter 2515,App C as guide. MROCZKA,E.J., SEARS,C.F. Northeast Nuclear Energy Co. (subs. of Northoast Utiles). MROCZKA,E.J. Northeast Utilities. 88/04/15 Document Control Branch (Occument Control Desk). 2pp. 45238:292-45238:293.

8804270231 Submits comments supporting proposed rule to ensure that presence of NRC inspectors on power reactor sites should not be announced to license personnel Licensee feets rule makes sense but not practicable.

MROCZKA,E.J., SEARS,C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities), MROCZKA,E.J. Northeast Utilities 88/04/18 Docketing & Services Branch 3pc 45944/24,66244-286. 45244 247-45244 249

8804290282 Advises that Tech Spec rev re specific distance for taking radiation meas utements in great where dose rates exceed 1,000 mrom/h will be processed & submitted to NRC to provide improved & consistent program on high radiation greats. MROCZKA,E.J. ROMBERG,W.D. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA,E.J. Northeast Utilities. 88/04/22. Document Control Brand (Document Control Dask). 2pp. 45282:181-45282:182.

Q. Inspection reports, IE Bulletins & correspondence

8804050376 Forwards response to NRC 870728 request for addl into re util response I IE Bulletin 85-003, "Motor-Operated Valvo Common Mode Faitures." MROCKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities, MROCKA,E.J. Northeast Utilities, 87/09/04. Region 1, Ofc of the Director. Spr 45061:149-45081:153.

8803310043 Responds to NRC Bulletin 88-001, "Datects in Westinghouse Circuit Breakers." Two reactor trip breakers & two reactor trip bypass breakers subj to building used at Milistone Unit 3 Main pole shaft weld inspe completed by 880225 MROCZKA,E.J. Connecticut Yankee Atomic Power Co. MROCZKA,E.J. Northoast Nt. clear Energy Co. (subs. of Northeast Utilities). MROCZKA,E.J. Northeast Utilities. 88 03/25. RUSSELL,W.T. Region 1, Ofc of the Director. 2pp. 44964:136-44964:137.

8803310109 Advises that based on reevaluation of Insp requirements for steam generator steaded tubes tubes can be reclassified as nonsusceptible to pitting & will be in spected to 3% random sample.

MROCZKA,E.J. Northeast Utilities. 88/03/26. Document Control Branch (Document Control Desk). 2pp. 44996:082-44996:083.

8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Wosting house Reactors." Svc list encl. ROSSI.CE. Division of Operational Events Assessment (Post 870411). 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.

8803220296 NRC Info Notice 88-010, "Matis Licensees:Lack of Mg1 Controls Over L cansed Programs." Svc hist enct. CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 670729), 88 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44996:247-44995:353.

8804130225 Forwards Exam Rept 50:336/87:31OL administered during wk. of 880111 GALLO.R.M. Region 1, Olo of the Director, 88/03/28 MROCZKA,E.J. Northeast Nuclear Energy Co. (aubs. of Northeast Utilities). 2pp. 45147:159-45147:278.

-8804130229 Exam Rept 60-336/87-31OL on 880111-14.Exam results:slx reactor operators & two instant senior reactor operators passed exam.
SILK,D.M. ESELGROTH.P.W. Region 1, Olo of the Director. 88/03/25 114pp.
45147:161-45147:276.

8804080142 Forwards SALP Repts 50:245/86-99 & 50:336/86-99 for June 1086 - De 1987 Uhi should be prepared to discuss assessments & any plans to Improve perform BUSSELL,W.T. Region 1, Ofc of the Director, 88/03/29, MROCZKA,E.J. Northees Nuclear Energy Co. (subs. of Northeast Utiliflee), 2pp. 45045;326-45046.063.

-8804060147 SALP Repts 50-245/86-99 & 50-336/86-99 for June 1986 - Dec 1987 * Region 1, Ofc of the Director. 88/02/26, 97pp. 46045:327-45046:083.

8804050236 Forwards Safety Insp Rept 50-336/88-04 on 880202-08.No violation noted.
DURR,J.P. Region 1, Ofc of the Director. 88/03/81. MROCZKA,E.J. Northeast Nucle
ar Energy Co. (subs. of Northeast Utilities). 2pp. 45017:211-45017:218.

--8804060240 Insp. Rept. 50.338/88-04 on 880202-08.No violations or daviation noted Major areas inspected containment integrated leak rate testing & preliminar test results evaluation. KUCHARSKI,S.D., EAPEN,P.K. Region 1, Oic of the Director, 88/03/29, 6pq 45017.213-45017.218.

- 8804010256 NRC Info Notice 88:011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svc list encl. ROSSI/GE. Division of Operational Events. Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406/292-45407:051.
- 8804060370 NRC Info Notice 86-012, "Overgreasing of Electric Motor Bearings." Svc list enct ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165;150.
- 8804200172 Forwards Insp. Rept. 50:338/88-06 on 880208-0321 No violations noted Attention called to control of overtime Maint hot work performed w/o fire watch Licensee 860210 response to violation from Insp. 50:338/87-25 adequate. BETITENHAUSEN, Region 1, Oic of the Director. 88/04/13. MROCZKA, E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 45221-085-45221-085.
- -8804200194 Insp. Rept. 50-336/88-06 on 880208-0321 No violations noted. Major areas inspected previously identified items,plant operations,surveillance,radiation protection,physical security,fire protection & review of periodic repts. MCCABE,E.C. Region 1, Ofc of the Director, 88/04/13, 19pp. 45221:067-45221.085

8804130060 Monthly operating rept for Mar 1988.W/880408 ltr.
NERON.G., SCACE,S.E. Northoast Nuclear Energy Co. (subs. of Northeast Util.lies).
SCACE,S.E. Northeast Util.lies. 88/03/31. 5pp. 45129.157-45129:161.

S. Reportable occurrences, LERs & related correspondence

8804140370 PNO-I-88-04D on 880408.during planned maneuver to correct unidentified primary sys feakago.control rods CEA-44 & CEA-4 dropped into core.Contelliment opened on 880409 to Identify teakage Facility shut down in excess of 48 h RAYMONDW, MCCABE,E, BETTENHAUSEN,L Rogion 1, Ofc of the Director. 88/04/11 2pp. 45158:325-45158:326

V. Operator Examinations

- 8804010276 Informs of senior reactor operator licensing exams scheduled for 880718. Facility needs to send enclined real requirements for reactor/senior reactor operator licensing exams, by 880513 in order to meet schedule.

 ESELGROTH,P.W. Region 1, Ofc of the Director, 88703724. MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 10pp. 45058.125-45058:134.
- 8804130225 Forwards Exam Rept 50:336/87:310L administered during wk of 880111. GALLO,R.M. Region 1, Otc of the Director. 88/03/28. MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 45147:159
- -8804130229 Exam Rept 50-336/87-31QL, on 880111-14.Exam results six reactor operators & two instant sonior reactor operators passed exam. SiLK,D.M., ESELGROTH.P.W. Region 1, Oic of the Director. 88/03/25. 114pp. 45147:181-45147:278.
- 8804130332 Advises that listed operators & senior operators no longer maintain licenses, effective on 880401.

 SCACE, S.E. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). SCACE, S.E. Northeast Utilities. 88/04/08. Document Control Branch (Document Control Desk). 1p. 45184-019.

DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8803250156 Forwards draft Rev B to IE Insp Procedure 82412, "Emergency Response Facilities Appraisal" ERF appraisal will be conducted using learn approach per recommended insp assignment matrices in procedure. COLLINS.D.M. Region 2, Ofc of the Director. 88/03/16, STEWART, W.L. Virginla Power (Virginla Electric & Power Co.), 39pp. 44914:226-44914:266.
- 8804050218 Forwards Exemption to 10CFR50,App E,Section IV.F.2 re conduct of emergency preparetness exercise for facility in response to 871009 lin. Exemption forwarded to Old of FR for publication.

 VAHGA.S Division of Roactor Projects - I/II (Post 870411), 88/03/28

 STEWART.W.L. Virginia Power (Virginia Electric & Power Co.). 2pp. 44997:109-
- --8804050226 Exemption from requirements of 10CFR50.12(a) re conduct of exercise of plant emergency plan in 1987. Underlying purpose of regulation achieved through util response to 870715 steam generator fube rupture ovent.

 VARGA,S.A. Dwision of Reactor Projects I/II (Post 870411). 88/03/28. 9pp. 44997:111-44997:119.
- 8804070142 Forwards first 1988 semiannual rev to omergency response plan. Changes to not decrease effectiveness of plan & plan continues to meet stds of 10CFRS0.47(b) STEWART.W.L. Virginia Power (Virginia Electric & Power Co.). 88/03/30. Document Control Branch (Document Control Desk). 1p. 45044:164-45044:164.
- 8804140133 Advises that 880308 Ray 12 to guard fraining & qualification plan consistent w/provisions of 10CFR50.54(p) & acceptable.

 CLINE.W.E. Region 2, Olc of the Director, 68/04/07, STEWART,W.L. Virginia Power (Virginia Electric & Power Co.), 3pp. 45163:347-45163.349.
- 8804200473 Partial response to FOIA request re fire protection.Forwards App E documents App D & E documents available in PDR.App F document completely with-tield (ref FOIA Exemption 5). GRIMSLEY,D.H. Division of Rules & Records (Post 870413), 88/04/14, JONES.C R. Alfiliation Not Assigned. 5pp. 45206 037-45206:043.
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type Insp for each facility to assess status of compliance w/ 10CFR50.48.Program listed.
 CONLONT.E. Region 2, Oto of the Director. 84/11/06. HERIDT,A.R. Region 2, Oto of the Director. 3pp. 45206:176.45206:178.

- 8804260004 Forwards Insp Repts 50-338/88-07 & 50-339/88-07 on 880321-25 & notice of violation.W/o notice of violation CLINE,W.E. Region 2, Ord of the Director, 88/04/18, STEWART,W.L. Virginia Powor (Virginia Electric & Power Co.) 2pp. 45254:219-45254:221.
- lowup item noted Major areas inspected security program audit 8 records 8 repts. MASNYK,OM, MCGUIRE,D.R. Region 2. Ole of the Director 88/04/13. 1p 45254 221-45254 221.

I. Financial information

8804120382 Forwards listed info re I censee gua:antees of payment of deferred premiums, including annual rept to Securities & Exchange Commission for 1987 & comparative statement of Income for 3 months ended Dec 1988 & 1987. STEWART, W.L. Virginia Power (Virginia Efectine & Power Co). 88703/31 Document Control Branch (Document Control Dask) 72pp 45091:076-45091:141.

J. Insurance & Indemnity Information

8804120382 Forwards Tisted into re licensee guarantees of payment of deferred premums/including annual rept to Securities & Exchange Commission for 1987 & comparative statement of income for 3 months ended Dat 1986 & 1987. STEWART.W.L. Virgin's Power (Virgin's Fection & Power Co), 88703/31. Document Control Brench (Document Control Brench (Document Control Desk), 72pp. 45091;076-45091;141,

O. Advisory Committee on Reactor Safeguards reports & correspondence

- 8804130393 Comments on Wastinghouse arguments to plant stoam generator tube rupture. Wastinghouse unconvictingly explained incident but arguments to not expecting simultaneous rupture of many tubes seems reasonable CATTONI. ACRS Advisory Committee on Reactor Saleguards. 88/03/07. WARD,D ACRS Advisory Committee on Reactor Saleguards. 6pp. 45117 292-45117 297.
- 8804140215 Submits summary of actions discussed at ACRS 335th meeting on 680310-12 in Weshington,DC,including ACRS repts/ recommendations,other actions,agreements,assignments & requests & future agenda. KERR,W. ACRS Advisory Committee on Reactor Safeguards 8B/03/24, ZECH,L.W. Commissioners, 4pp. 45118-172-45118.175.

P. Operating license stage documents & correspondence

- 8804120048 Requests that final tickel response re 671109 staff briefing on will steam generator tube rupture event be sent to Div of Engineering & Sys Technology by 880111.Requests to include "LShao" in concurrence page distribution & tickel NORBERG,J. Division of Engineering & Systems Technology (Post 870411). 87/12/ 01. AICHARDSON,J., CHENG,C.Y. Division of Engineering & Systems Technology (Post 870411). 3pp. 45100:339-45100:342
- 8803100022 Forwards SER & technical evaluation rept accepting util responses to Generic Ltr 83-26, ltem 2.2 (Peart 1). "Equipment Classification (Program for All Safety-Helated Components)." Schedule for completion of new listing requested ENGLEL. Project Directorate II-2 88/03/04. STEWART,W.L. Virgina Power (Virginia Electric & Power Co.), 4pp. 44661:243-44681:265.
- --8603100024 SER relut I 831104 & 850208 responses to Genor-c Lit 83-28, Item 2.2.1, "Equipment Classification (Program for All Safety-Related Components." Responses NRC - No Detailed Alfillation Given. 88/03/04. 7pp. 44661:247-44661:265.
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants to removal of organization charts from Tech Spec administrative control requirements Svc list end. MIRAGLIA,F.J. Associate Director for Projects (Post 870411) BB/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:163
- 8804050244 Forwards Amends 97 & 84 to Licenses NPF-4 & NPF-7, respectively & safety evaluation Amends modify Tech Specs 4.8 1.1.3 & 4 & 2.3 2 re survollance requirements for emergency dressl generators & station batteries. ENGLE,L.B. Project Directorate II-2, 88/03/25, STEWART,W.L. Virgina Power (Virginia Electric & Power Co.), 2pp. 44997:134-44997:159
- --8804060254 Amends 97 & 84 to Licenses NFP-4 & NPF-7, respectively, modifying Tech Specs 4.8.1.1.3 & 4.8.2.3.2 re surveillance requirements for emergency disselgence to a station batteries. BERKOW,H.N. Project Directorate II-2. 88/03/25. 21pp. 44997:136-44997:156.
- -8804050259 Safety evaluation supporting Amenda 97 & 84 to Licenses NPF-4 & NPF-7.respectively.

 Oilice of Nuclear Reactor Regulation, Director (Post 870411): 89/03/25. 3pp. 44997:157-44997:159.
- 8804040070 Requests that NRC exercise enforcement discretion re implementation of organizational changes until amends issued,as result of 860315 felcon w/NRC to 880317 request for fech Space changes.
 STEWART.W.L. Virginia Power (Virginia Electric & Power Co.), 88/03/28. Document Control Branch (Document Control Desk), 2pp. 45031:293-45031:284.
- 8804050299 Forwards Amends 98 & 85 to Licenses NPF-4 & NPF-7, respectively & safety evaluation Amends revise Tech Spec by placing hydrogen recombiner containment isolation valvas under administrative control.

 ENGLE, L.B. Project Directorate II-2, 88/03/29 STEWART,W.L. Virginia Power (Virginia Electric & Power Co.), 2pp. 45029:106-45029.121.
- ~8804050301 Amends 98 & 85 to Licenses NPF-4 & NPF-7, respectively, revising Tech Spec by placing hydrogen recombiner containment isolation valves under administrative control to permit functional testing. BERKOW,H.N. Project Directorate II-2, 88/03/29, 10pp. 45029.108-45029:117.

- -8804050302 Salety evaluation supporting Amends 98 & 85 to Licenses NPF-4 & NPF-
- 7, respectively.
 * Office of Nuclear Reactor Regulation, Director (Post 870411) 88/03/29, 4pp. 45029.118-45029.121
- 8804060248 Application for amends to Licenses NPF-4 & NPF-7, changing Tech Spec Tables 3.3-10 & 4.3-7 to include incore thermocouples in accident monitoring instrumentation per NUFEG-0737, flem ILF 2.8 Generic Ltr 83-37,Fee paid. STEWART,W.L. Virgina Power (Virginia Efectin: & Power Co.), 88/03/30. Document Control Branch (Occument Control Desk), 3pp. 45034 080-45034 090.
- -8804060250 Proposed Tech Specs Tables 3.3-10, "Accident Monitoring Instrumenta-tion" & 4.3-7, "Accident Monitoring Instrumentation Surveillance Requirements."
 * Virginia Power (Virginia Electric & Power Co.). 88/03/30. 8pp. 45034-083-45034.090.
- 8804070268 Forwards safety evaluation accepting util 840131,850510,0705 & 0802 submittal re-conformance to post-accident monitoring instrumentation guidelines of Reg.
 - ENGLE, LB. Project Directorate II-2 88/03/31, STEWART, W.L. Virginia Power (Virginia Electric & Power Co.), 1p. 45043-260-45043-263.
- -8804070269 Safety evaluation supporting util submittals re-conformance to post-accident monitoring instrumentation guidelines of Reg Guide 1.97.
 Project Oractorate II-2, 88/03/31, 3pp. 45043.261-45043.263
- ~8605300376 "Conformance to Reg Guide 1.97, North Anna Power Station, Units 1 & UDY.A.C. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6483. EGG-EA-6800. 86/02/ 28. NRC - No Detailed Affiliation Given: 18pp. 45043:264-45043:281.
- 8804080097 Clanfies 871109 application for amends to Licenses NPF-4 & NPF-7 (e intermed ale range neutron flux trip.Proposed rev claffles modes in which monthly channel check required to verify that Permissives P-6 & P-10 in required state. STEWART.W.L. Virgina Power (Virginia Electric & Power Co.). 88/03/31. Document Control Branch (Document Control
- -8804140428 Rev to proposed Tech Spec Table 4.3-1, "Reactor Trip Sys Instrumentation Surveillance Requirements."
 * Virginia Power (Virginia Electric & Power Co.), 88/03/31, 2pp. 45116.268-45118.269.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc list encl., MIRAGUÁ,F.J. Associate Director for Projects (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804130295 Notification of 880406 meeting w/util in Flockville,MD to discuss very low level radioactive concentrations on reverse osmosis sys used to generate makeup water at plant ENGLE,LB. Project Directorate 11-2. 88/04/07. MURLEY,T, SNI MIRAGUA,F NRC - No Detailed Affiliation Given 2pp. 45102.360-45102.361. SNIEZEK,J.
- 8804150422 Forwards corrected Tech Spec Page 6:12 for Amends 87 & 73 to Licenses NPF-4 & NPF-7,respectively & corresponding overleaf page. ENGLE.L.B. Project Directorate II-2. 88/04/11. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.) 1p. 45133.166-45133.169.
- -8804180298 Corrected Tech Spec Page 6-12 to Amends 87 & 73 to Licenses NPF-4 & NPF-7, respectively, revising audit of process & control program & implementing procedures for processing a packaging radwastes.

 ' Project Directorate II-2, 88/04/11, 2pp. 45133:167-45133:169.
- 8804199080 Forwards corrected Page 3/4 8-14 to Amends 97 & 84 to Licenses NPF-4 & NPF-7, respectively, Amends modify surveillance requirements for emergency diesel generator & station batteries. ENGLE L.B. Project Oirectories II-2, 88/04/13, STEWART, W.L. Virginia Power (Virginia Electric & Power Co.), 1p. 45164:290-45184:293
- -8804190087 Corrected Page 3/4 8-14 to Amends 97 & 84 to Licenses NPF-4 & NPF-7, respectively. Amends modify surveillance requirements to emergency diesel generator & station batteries.

 * Project Directorate II-2: 88/04/13, 3pp. 45164;291-45164;293.
- 8804280492 Forwards notice of environ assessment & finding of no significant Impact re 880303 request for exemption from 10CFR50 553(g)(4) to extend current facility 120-month Insp Interval from 880606 to 901214.
 ENGLEL.B. Project Directivate II-2. 88/04/19. CRUDEN.D.S. Virginia Power (Virginia Electric & Power Co.), 2pp. 45264:063-45264:068.
- -8804280496 Notice of anviron assessment & finding of no significant impact re 880303 application for exemption from 10CFR50.554(g)(4) to allow common start date of 901214 for inservice insp & feeting programs for Units 1 & 2, SILVER,H. Project Directorate II-2, 88/04/19, 4pp. 45284,065-45264,068.
- O. inspection reports, IE Bulletins & correspondence
- 8804110298 Discusses insp on 871120-1218 & torwards notice of violation & proposed imposition of civil penalty, insp included review of failure to place inoperable steam flow channels in trip and perform adequate post-maint testing.

 GRACE, J.N. Region 2, Oits of the Director, 88/03/08. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 4pp. 45128:120-45128:127.
- -8804110301 Notice of violation & proposed imposition of civil penalty in amount of \$100,000 Noncompliance noted:Unit 2 operated in Modes 1-3 with Inoperable steam flow channel in steam lines A & B & failure to perform post-maint test (GRACE,J N. Region 2, Ofc of the Director, 88/03/08, 4pp. 45128:124-45128:127.
- 8803250156 Forwards draft Rev B to IE Insp Procedure 82412, "Emergency Response Facilities Appraisa!." ERF appraisal will be conducted using team approach per recommended insp assignment matrices in procedure.

 COLLINS,D.M. Region 2, Olo of the Director. 68/03/16 STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 39pp. 44914;228-44914;266.
- 8604010019 Confirms 880328 enforcement conference w/util in Region II ofe to discuss trip value operability & boric acid pipe heat tracing issues.
 GRACE J.N. Region 2, Ofe of the Director, 88/03/21, STEWART,W.L. Virginia Power of the Conference o

- 8803300328 Forwards "North Anna 2 Steam Generator Tube Fatigue Evaluation & Remedial Actions Rept." & Rev 2 to "North Anna Unit 1 870715 Steam Generator Tube Rugture Event Rept." In response to NRC Compliance Bullotin 88-002. STEWART.W.L. Vignis Power (Virginia Fleetric & Power Co.), 86/03/24. Document Control Branch (Document Control Desk). 4pp. 44963:081-44964.058.
- -- 8803300330 "North Anna 2 Steam Generator Tube Fatigue Evaluation & Remedial Actions Rept."
 " Westinghouse Electric Corp. STD-7.2.2.1-8079. 88/03/16. 23pp. 44963.085-44963:107.
- -8803300334 Rev 2 to "North Anna Unit 1 870715 Steam Generator Tube Rupture Event Rept."

 Virginia Power (Virginia Electric & Power Co.): 88/02/12: 160pp. 44963:108-44964058
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list oncl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 88-010, "Matis Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list enct.
 CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 88/
 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995.353.
- 8804060433 Forwards corrected Page 2 to Attachment 1 to util 870206 & 0522 requests for relief from various requirements of ASME Code Section XI for first inservice Insp Interval for unit.

 STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 88/03/30. Document Control Branch (Document Control Desk), 2pp. 45010.221-45010.222.
- 8804080253 Forwards Insp Repls 50-338/88-01 & 50-339/88-01 on 880116- 0223 & notice of violation.
 WILSON,B.A. Region 2, Ofc of the Director. 88/03/31, STEWART,W.L. Virginla Power (Virginla Electric & Power Co.), 2pp. 45088:214-45098:231.
- --8904030257 Notice of violation from insp on 880116-0223 Violations noted RCS level sandpipe scale Installed w/o procedural guidance & verification to ensure proper in-stallation & failure to follow maint procedure resulted in RCS leak. WILSON,B.A. Region 2, Ofc of the Director, 88/03/31, 2pp. 45098:216-45098:217.
- -8804080259 Insp. Repts 50:338/88-01. 8 50:339/88-01 on 880116-0223. Violations noted Major areas inspected plant status, unresolved Items, licensee action on previous enforcement matters, LER followup & review of Inspector followup Items. CALDWELL, Jt., KING, L.P., CANTRELL, F. Region 2, Ofc of the Director. 88/03/30. 14pp. 45098.218-45096:231.
- 8804130169 Responds to IE Bulletin 88-001, "Defects in Westinghouse Circuit Breakers." Station does not utilize Westinghouse Series DS circuit breakers. CRUDEN,O.S. Virginia Power (Virginal Electria & Power Ca.): 88/04/05. Document Control Branch (Document Control Desk). 3pp. 45122:203-46122:205.
- 8804140013 Responds to NRC 880314 ltr re-violations noted in Insp. Repts 50-338/88 02 & 50-339/86-02-site engineering ofc personnel reinstructed in requirements for completing formal supporting documentation re design calculations. CRUDEN, DS. Virginia Power (Virginia Electric & Power Co.), 88/04/05. Occument Control Branch (Document Control Desk), 3pp. 45147:316-45147:318.
- 6804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr 8/or Switchboard Function Due to Faulty Tie Bolts." Svo list encl.
 ROSSI,C.E. Division of Operational Events Assessment (Post 370411), 88/04/07.
 Consolidated Edison Co. of New York, Inc. 124pp. 45408-292-45407:051.
- 8804130264 Responds to NRC 880308 litr re violations noted in Insp Repts 50-338/87-38 & 50-338/67-38. Corrective actions: steam flow channel instrument calibr procedures will be revised by 880430. Remits fee for civil penalty. CRUDEN,D.S. Virginia Power (Virginia Electric & Power Co.), 88/04/07. Ofc of Enforcement (Post 870413), 8pp. 45138:020-45138:027.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list enci. ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165;150.
- 8804200473 Partial response to FOIA request re fire protection.Forwards App E documents.App D & E documents available in PDR.App F document completely withheld (ref FOIA Exemption 5).

 QRIMSLEY,D.H. Division of Rules & Records (Post 870413), 88/04/14, JONES,C.R. Affiliation Not Assigned. 5pp. 45206:037-45206:043.
- -8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type insp for each facility to assess status of compliance w/ 10CFR50.48.Program listed.
 CONLON,T.E. Region 2, Off of the Director, 84/11/08. HERDT,A.R. Region 2, Ofc of the Director. 3pp. 45206:178-45206:178.
- 8804260004 Forwards Insp Repts 50-338/88-07 & 50-339/88-07 on 880321-25 & notice of violation.W/o notice of violation. CLINE.W.E. Region 2, Ofo of the Director, 88/04/18, STEWART,W.L. Virginia Power (Virginia Electric & Power Co.), 2pp. 45254:219-45254:221.
- -8804260006 Partially withheld Physical Security Insp Repts 50:336/88-07 & 50:339/88-07 on 860321-25 (ref 10CFR2.790(d) & 73.21). One violation & one inspector follows if the noted Major areas inspected; security program audit & records & repts. MASNYK.O.M., MCGUIRE, D.R. Region 2, Oto of the Director. 88/04/13. 1p. 45254:221-45264:221.
- 8804280492 Forwards notice of environ assessment & finding of no significant impact re 880303 request for exemption from 10CFR50.55a(g)(4) to extend current lacility 120-month insp interval from 880808 to 901214, ENGLE,

117

- --8804280496 Notice of environ assessment & finding of no significant impact re 880303 application for exemption from 10CFR50.55a(g)(4) to allow common start date of 901214 for inservice insp.& leasing programs for Units 1 & 2. SILVER,H. Project Directorate fi-2, 88/04/19, 4pp. 45264:065-45264:068.
- 8804260180 Responds to NRC 880308 itrie violations noted in linsp Repts 50-338/87-38 & 50-339/87-38 Corrective actions station mgt brioted on requirements of 10CFR50.73 re-scope & contont of LERs & mgt interviews will be conducted as required CRUDEN, D.S. Virginia Power (Virginia Electric & Power Co.) 88/04/21. Ofc of En-lorcement (Post 870413). 9pp. 45253.040-45253.048.

R. Periodic operating reports & related correspondence

- 8804070252 Summary of procedure changes, facility changes & special test for 1987.W/ STEWART,W.L. Virginia Power (Virginia Electric & Power Co.), 87/12/31, 160pp. 45075:051-45075 210.
- 8804190253 Monthly operating repts for Mer 1988,W/880414 ltr.
 GARNER,B., CRUDEN,D.S. Virginia Power (Virginia Electric & Power Co.), 88/03/31, 15pp. 4\$208;182-45208;198
- 8804260325 Comments on comparison review of 1986 somiannual effluent release repts per 880311 request Percent of Tech Spec limit for total body dose rate for fourth quarter on Page 7 changed from 7.63E3% to 7.63E-3%. CRUDON.D.S. Virginia Power (Virginia Electric & Power Co.). 86/04/20. TICHLER,J. Brookhaven National Laboratory, 2pp. 45282 032-45282 051
- * Virginia Power (Virginia Electric & Power Co.). 86/12/31, 18pp. 45282 034-45282 051. -- AR04260302 "Etiluent & Waste Disposal Annual Rept for 1966"

S. Reportable occurrences, LERs & related correspondence

- 8803310163 LER 87-007-02-on 870422,RHR suction line isolated when MOV-1701 closed due to loss of power to 120-voll ac vital bus 1-III.Caused by blown fuse Fuse replaced 8 vital bus 1-III transforred back to normal power supply.W/880324 ftr. HARRELLE.W. Virginia Power (Virginia Electric & Power Co.). 88/03/24, 3pp. 44961:343-44981:345.
- 803310237 LER 85:003-02 on 850319,ticoding potential not previously evaluated. Concrete wall will be constructed adjacent to west wall of turbine bldg Wall height sufficient to provent flooding above still-water max flood level W/880324 ltr. HARRELLE.W. Virginia Power (Virginia Electric & Power Co.). 88/03/24. 3pp. 45028-032-45028.034. 8803310237
- 8804190094 PNO-II-88-022:on 880405 low lovels of radioactive mall detected in demin-eralizer beds for plant makeup water. Caused by concentrating offect of radionuclides. Licensee currently storing spent demineralizer beds onsite until NRC approval. KAHLE,J. Region 2, Ofc of the Director. 88/04/06 1p. 45209.173:45209:173.
- 8604130080 LER 88-011-00:on 880311,post-mod testing not performed as required by two Tech Spocs.Caused by Inadequacy of original engineering work request investigation performed to determine if valves been stroke time tested.W/ 860407 ltr. KANE,G.E. Virginia Power (Virginia Electric & Power Co.), 88/04/07. 6pp. 45132 356-
- 8804150004 LER 88-012-00:on 880315.RHR capability lost due to failed selenoid operated valve.Caused by failure of containment valve 1-CC-TV-1038 to stroke close within the required time limit valve returbished and stroked.W/880408 ltr. KANE.G.E. Virginia Power (Virginia Electric & Power Co.): 98/04/08. 5pp. 45165:109-45155:113
- 8804200195 LER 88-013-00.on 880319.turbina trip/reactor trip occurred. Caused by electrohydraulic fluid control sys malfunction. Serve control valves for four governor valves replaced & tested settsfactor/lyW/880414 ltr.

 KANE G E. Virginia Power (Virginia Ciectric & Power Co.). 88/04/14. 5pp. 45215:319-45215:323.
- 8804200432 LER 68-015-00 on 680322, discovered that RHA pumps not tested during steam generator tube rupture outage Caused by administrative error Station deviation rept submitted to responsible dept to reschedule missed test.W/880414 ltr. KANEGE. Virginia Power (Virginia Electric & Power Co.). 88/04/14, 4pp. 45238;115-
- 8804220214 Forwards LER 88-017-00 correcting rept number.LER re personnel air lock submitted on 880315 should have rept number changed to LER-N1-88-017-00, KANE G E. Vrginia Power (Virginia Electric & Power Co.), 88/04/14. Decument Control Branch (Document Control Branch (Document Control Desk), 2pp. 45236:048-45236.065.
- KANE,G E. Virginia Power (Virginia Electric & Power Co.), 88/04/14, 5pp. 45236.051-45236 055.
- 8804250030 LER 87-017-01:on 870716;reactor manually tripped due to indication of steam generator tube rupture in steam generator C Cause of tube rupture under investigation. Cookdown & depressurization of RCS conducted W/880414 ltr. KANE,G.E. Virginia Power (Virginia Electric & Power Co.), 88/04/14, 4pp. 45281:287-45281:270.
- 8804250035 LER 87-021-01:on 870911, discovered that environ seals on sensor necks of safety injection accumulator tank pressure transmitters broken during installation in May 1987. Transmitters removed & sensor necks resealed.W/8804141 kg. KANE,G.E. Virginia Power (Virginia Electric & Power Co.). 88/04/14. 4pp. 45237:170-45237:472
- 8804200438 LER 88-014-00:on 880318.reactor trip occurred due to steam generator C narrow range level decreasing to 25% while Channel IV steam bistable in trip.Caused by failure to maintain level above 25% Level restored,W/880415 tr. KANE G.E. Virginia Power (Virginia Electric & Power Co.). 88/04/16. 5pp. 45235:162-45235:166.

V. Operator Examinations

- 8804280088 Responds to FOIA request for info re-scores of reactor operators & senior reactor operators Forwards requestfication exam summary source sheets listed in encl app w/personal privacy info deleted GRIMSLEY,D.H. Division of Rules & Records (Post 870413) 88/04/19 BOLEY,K Public Critizen's Critical Mass Energy Project 2pp 45213:003-45213.095.
- --8804250167 Package of NRC administered requalification exam results summary. * NRC No Detailed Affiliation Given. 87/07/20. 88pp. 45213.007-45213:095.

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8803250156 Forwards d'eft Rey B to IE Inso Procedure 82412, "Emergency Response Facilities Appraisal." ERF appraisal will be conducted using team approach per recommended insp assignment matrices in procedure. COLLINS.D.M. Region 2, Ofe of the Director. 88/03/16. STEWART.W.L. Virginia Power (Virginia Electric & Power Co.). 39pp. 44914-228-44914-266
- 8804050216 Forwards Exemption to 10CFR50.App E.Section IV F.2 re conduct of emergency preparedness exercise for facility in response to 871009 fit Exemption forwarded to Ofc of FR for publication.

 VARGA,S.A. Division of Reactor Projects I/II (Post 870411), 88/03/28. STEWART,WL. Virgin'a Power (Virginia Electric & Power Co.). 2pp. 44997:109-44997:119 44997:119.
- -- 8804050226 Exemption from requirements of 10CFR50.12(a) re-conduct of exercise of plant emergency plan in 1987. Underlying purpose of regulation achieved through ut-lifetypone to 870715 steam generator tube rupture event. VARGA, SA. Division of Reactor Projects I/II (Post 870411). 88/03/28, 9pp. 44997:111-44997:119.
- 8804070142 Forwards first 1988 semiannual revito emergency response plan Changes do not decrease effectiveness of plan & plan continues to meet stds of 10CFR50.47(b). STEWART.W.L. Virginia Power (Virginia Electric & Power Co.). 88/03/30. Document Control Branch (Document Control Desk). 1p. 45044-164-45044:164.
- 8804140133 Advises that 880308 Rev 12 to guard training & qualification plan consistent w/provisions of 100CR50.54(p) & accceptable.

 CLINE.W.E. Region 2, Otc of the Director, 88/04/07, STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 3pp. 45163 347-45163 349.
- 8804200473 Partial response to FOIA request re fire protection.Forwards App E documents.App D & E documents available in PDR.App F document completely withheld (ref FOIA Exemption 5).
 GRIMSLEY,D.H. Dwision of Rules & Records (Post 870413), 88/04/14, JONES,C R. Affiliation Not Assigned, 5pp. 45206.037-45206.043.
- ~8804200579 Advises that Five Protection Steering Committee has recommended that each region make one 10CFR50,App R-type Insp for each facility to assess status of compliance w/ 10CFR50 48.Program listed. CONLONITE. Region 2, Oic of the Director. 84/11/06, HERDT,A.R. Region 2, Oic of the Director. 3pp. 45206:176-45208:178.
- 8804260004 Forwards Insp Repts 50-338/88-07 & 50-339/88-07 on 880321-25 & notice of violation.W/o notice of violation. CLINE,W.E. Region 2, Oit of the Director, 88/04/18, STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 2pp. 45254-219-45254-221.
- --8804260006 Pertielly withheld Physical Security Insp Repts 50-338/88-07 & 50-339/88-07 on 880321-25 (ref 10CFR2.790(d) & 73-21) One violation & one inspector following item noted Major ereas inspected security program aud 1 & records & project MASNYK,O.M. Region 2, Otc of the Director. 88/04/13. 1p. 45254/221-45254/221.

i. Financial information

8804120382 Forwards listed info re licensee guarantees of payment of deferred premiums.Including annual rept to Securities & Exchange Commission for 1997 & comparative statement of income for 3 months ended Oec 1986 & 1987. STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 88/03/31. Document Control Branch (Document Control Desk). 72pp. 45091:076-45091:141.

J. Insurance & Indemnity Information

8804120382 Forwards listed Info re licensee guarantees of payment of deterred premiums, including annual rept to Securities & Exchange Commission for 1987 & comparative statement of Income for 3 months ended Dec 1986 & 1987. STEWART, W.L. Vignial Power (Virginia Electric & Power Co.). 88/03/31. Document Control Branch (Document Control Desk). 72pp. 45091,076-45091:141.

O. Advisory Committee on Reactor Safeguards reports & correspondence

- 8804130393 Comments on Westinghouse arguments re plant steam generator tube rupture. Westinghouse unconvincingly explained incident but arguments re not expecting simultaneous rupture of many tubes seems reasonable. CATTONI. ACRS Advisory Committee on Reactor Safeguards. 88/03/07. WARD,D. ACRS Advisory Committee on Reactor Safeguards. 8pp. 45117:292-45117:297.
- 8804140215 Submits summary of actions discussed at ACRS 335th meeting on 880310-12 in Washington,OC,including ACRS repts/ recommendations,other actions.agreements.assignments & requests & future agends. KERR,W. ACRS Advisory Committee on Reactor Safeguards. 88/03/24, ZECH,L.W. Commissioners. 4pp. 45118:172-45118:176.

P. Operating Ilcense stage documents & correspondence

- 8804120048 Requests that final ticket response re 871109 staff briefing on util steam generator tube rupture event be sent to Drv of Engineering & Sys Technology by 880111 Requests to include "LShao" in concurrence page distribution & ticket
- NORBERG J. Division of Engineering & Systems Technology (Post 670411), 87/12/ 01. A(CHARDSON J., CHENG, C.Y. Division of Engineering & Systems Technology (Post 870411), 3pp. 45100-339-45100 342.
- 8803100022 Forwards SER & technical evaluation rept accepting bill responses to Ganeric Ltr 83-28, Item 2.2 (Part 1), "Equipment Classification (Program for All Safety-Related Components)" Schedule for completion of new listing requested. ENGLEL, Project Directorate III-2 88/03/04. STEWART, W.L. Virginia Power (Virginia Electric & Power Co.). 4pp. 44661.243-44661.265.
- -8803100024 SER re util 831104 & 850208 responses to Generic Ltr 83-28, Item 2.2.1, Equipment Classification (Program for All Safety-Related Components." Responses acceptable.
 - NRC No Detailed Affiliation Given, 88/03/04, 7pp, 44661:247-44661:265
- 8803240426 Generic Ltr 88:06 to all power reactor licensees & applicants to removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIHAGLIAF J. Associate Director for Projects (Post B70411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153
- 8804050244 Forwards Amends 97 & 84 to Licenses NPF-4 & NPF-7, respectively & safety evaluation Amends modify Tech Specs 4 8 1.1.3 & 4.8.2.3.2 re surverl'ance requirements for emergency deset generators & sation batteries ENGLE, B. Project Directorate It.2. 88/00/2/25 STEWART,W.L. Virginia Power (Virginia Electric & Power Co.) 2pp. 44997.134-44997.159
- -8804050259 Safety evaluation supporting Amends 97 & 84 to Licenses NPF-4 & NPF-
- 7.respectively.
 Office of Nuclear Reactor Regulation, Director (Post 870411) 88/03/25. 3pp. 44997.157-44997.159.
- 8804040070 Requests that NRC exercise enforcement discretion re implementation of organizational changes until amends issued as result of 880325 telcon w/NRC re 880317 request for Tech Specs changes STEWART,W L. Virginia Power (Virginia Electric & Power Co.). 88/03/28. Document Control Branch (Occument Control Desk). 2pp. 45031:293-45031:294.
- 8804050299 Forwards Amends 98 & 85 to Licenses NPF-4 & NPF-7, respectively & salety evaluation Amends revise Tech Spec by placing hydrogen recombiner contament isolation values under administrative control ENGLE_LB Project Divectorate it.2: 88/03/29. STEWART,W L. Virginia Power (Virginia Electric & Power Co.). 2pp. 45029.106-45029.121
- -8804050301 Amends 98 & 85 to Licenses NPF-4 & NPF-7, respectively, revising Tech Spec by placing hydrogen recombiner containment isolation valves under administrative control to permit functional testing BERKOW,H.N. Project Directorate II-2, 88/03/29, 10pp. 45029;108-45029;117.
- --8804050302 Safety evaluation supporting Amends 98 & 85 to Licenses NPF 4 & NPF-
- 7.respectively.
 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/29, 4pp. 45029:118-45029:121
- 8804060248 Application for amends to Licenses NPF-4 & NPF-7, changing Tech Spec Tables 3 3-10 & 4-3-7 to include incore thermocouples in accident monitoring instrumentation.per NUREG-0737.Item II.F 2 & Generic Lir 83-37 Fee paid: STEWART.W.L. Virginia Power (Virginia Electric & Power Co.) 880/03/30. Document Control Branch (Document Cantrol Cesk). 3pp. 45034-080-45034-090.
- -8804060250 Proposed Tech Specs Tables 3.3-10, "Accident Monitoring Instrumenta-tion" & 4.3-7, "Accident Monitoring Instrumentation Surveillance Requirements."

 ' Virginia Power (Virginia Electric & Power Co.) 88/03/30 8pp. 45034.083.45034.090.
- 8804070268 Forwards safety evaluation accepting util 840131,650510,0705 & 0802 submitted re-conformance to post-accident monitoring instrumentation guidelines of Reg Guide 1.97.
- ENGLE,L.B. Project Directorate It-2, 88/03/31, STEWART,W.L. Virginia Power (Virginia Electric & Power Co.), 1p. 45043:260-45043:263,
- --8804070269 Salety evaluation supporting util submittals re conformance to post-accident monitoring instrumentation guidelines of Reg Guide 1.97.
 ' Project Directorate II-2, 68/03/31, 3pp. 45043 261-45043 263.
- -8605300376 "Conformance to Reg Guide 1.97, North Anna Power Station, Units 1 & UDY,A.C. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6483, EGG EA-6800, 86/02/ 28. NRC - No Detailed Affiliation Given. 18pp. 45043.264-45043:281.
- 8804080097 Clarifies 871109 application for amends to Licenses NPF-4 & NPF-7 re intermediate range neutron flux trip Proposed rev clarifies modes in which monthly channel check required to verify that Permissives P-6 & P-10 In required state. STEWART.W L. Virginia Power (Virginia Electric & Power Co.). 88/03/31. Document Control Branch (Document Control Dask). 2pp. 45116:268-45116:289.
- ~8804140428 Rev to proposed Tech Spec Table 4.3-1, "Reactor Trip Sys Instrumentaton Surveillance Requirements."

 Virginia Power (Virginia Electric & Power Co.), 88/03/31, 2pp. 45116:268-45116:269.
- 8804080088 Generic Lir 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR\$0.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants: "Sec isla end, MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, inc. 49pp. 45164:237-45184:285
- 8804130295 Notification of 880408 meeting w/util in Rockville,MD to discuss very low level radioactive concentrations on reverse osmosis sys used to generate makeup water at plant.

 ENGLE,L.B. Project Directorate II-2, 88/04/07, MURLEYT SNIEZEV I Wald at Picture 18 Project Oirectorate II-2. 68/04/07. MURLEY.T. SN. MIRAGLIA,F. NRC - No Detailed Affiliation Given. 2pp. 45102:360-45102:361. SNIEZEK,J.,

- 8804150422 Forwards corrected Tech Spec Page 6-12 for Amends 87 & 73 to Licenses NPF-4 & NPF-7,respectively & corresponding overloaf page.
 ENGLE L. B. Project Directorate II-2 f8/04/11. STEWART,W.L. Virginia Power (Virginia Electine & Power Co.) 1p. 45133:166-45133:169.
- --8804180298 Corrected Tech Spec Page 6-12 to Amends 87 & 73 to Licenses NPF-4 & NPF-7, respectively, revising audit of process & control program & Implementing procedures for processing & packaging radivastes.

 **Project Directorate II-2, 88/04/11, 2pp. 45133:167-45133:169.
- 8804190080 Forwards corrected Page 374 8-14 to Amends 97 & 64 to Liconses NPF-4 & NPF-7, respectively Amonds modify surveillance requirements for emergency diesel generator & station betteries ENGLE, B. Project Directorate it. 2: 88/04/13 STEWART.W.L. Virgin a Power (Virgin
 - ia Electric & Power Co) 1p 45164.290-45164.293.
- --8804190087 Corrected Page 3/4 8-14 to Amends 97 & 84 to Licenses NPF-4 & NPF-7,respectively Amends modify surveillance requirements to emergency deset genera-tor & station batteries. Project Directorate II-2, 88/04/13, 3pp. 45164:291-45164.293.

- 8803250156 Forwards draft Rev B to IE Insp Procedure 82412, "Emergency Response Facilities Appraisal." ERF appraisal will be conducted using team approach per recommended insp assignment matrices in procedure. COLLINS.D.M. Region 2, Otc of the Director. 88/03/16. STEWART.W.L. Virgin a Power (Virginia Electric & Power CO.). 39pp. 44914-228-44914:286.
- 8804010019 Confirms 880328 enforcement conference w/util in Rugion II ofc to discuss trip varue operabitly & boric acrd pipe heat tracing issues. GRACE_JN. Region 2, Ofc of the Director. 68/03/21_STEWART,W.L. Virginia Power (Virginia Electric & Power Co.): 1p. 45031:173-46031:173.
- 8803300328 Forwards "North Anna 2 Stoam Generator Tuba Fatigue Evaluation & Remedial Actions Rept" & Roy 2 to "North Anna Unit 1 870715 Steam Generator Tube Rupture Event Rept." in response to NRC Complance Bullatin 68-002. STEWART.WL. Virginia Power (Virginia Efectire & Power Co.). 88/03/24 Document Control Branch (Document Control Desk). 4pp. 44963:081-44964:058.
- →8803300330 "North Anna 2 Steam Generator Tube Fatigue Evaluation & Remedial Ac-* Westinghouse Electric Corp. STD-7.2 2.1-8079. 88/03/16. 23pp. 44963.085-44963.107.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thrining in Westinghouse Reactors." Svc I'st encl. ROSSI,CE Division of Operational Events Assessment (Post (170411): 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995-126-44995:246.
- 8803220296 NRC Into Notice 88-010, "Mails Licensees.Lack of Mgt Controls Over Li-censed Programs" Svc list end. CUNNINGHAM, B. D. Vision of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28, Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353
- 8804080252 Forwards "Supplemental Inservice Insp Rept." Supplemental rept includes repair & replacement into & related addi NDEs.
 STEWART,W.L. Virginia Power (Virginia Electric & Power Co.), 88/03/31. Document Control Branch (Document Control Desk), 1p. 45092;133-45092;192.
- --8804080255 "Supplemental Inservice Insp Rept." STEWART,W.L. Virginia Power (Virginia Electric & Power Co.). 88/03/31, 46pp. 45092:134-45092:192.
- 8804080263 Forwards Insp Repts 50-338/88-01 & 50-339/88-01 on 880116- 0223 & not ce of violation
 WILSON,B.A. Region 2, OIc of the Director. 88/03/31. STEWART,W.L. Virgina Power
 (Virginia Efectric & Power Co.) 2pp. 45098:214-45098:231.
- -8804080257 Notice of violation from Insp on 880116-0223 Violations noted RCS level sandp.pe scale installed w/o procedural guidance & verification to ensure proper in-stallation 8 lailure to follow maint procedure resulted in RCS leak. WILSON,B A. Region 2, Oic of the Director, 88/03/31, 2pp. 45098:216-45098:217.
- --8804080259 Insp Repts 50-338/88-01 & 50-339/88-01 on 880116-0223 Violations noted Major areas inspected plant status, unresolved items, licensee action on previous enforcement matters, LER followup & review of inspector followup items. CALDWELLJL. KINGL P., CANTRELL,F. Region 2, Ofc of the Director 88/03/30. 14pp. 45098:218-45098:231.
- 8804130189 Responds to IE Bulletin 88-001, "Defects in Westinghouse Circuit Breakers." Statuon does not utilize Westinghouse Series DS circuit breakers
 CRUDEN,D.S. Virginia Power (Virginia Ejectric & Power Co.), 88/04/05. Occument
 Control Branch (Document Control Desk), 3pp. 45122:203-45122:205.
- 8804140013 Responds to NRC 880314 lit re violations noted in Insp. Repts 50:338/88-02 & 50:339/88-02. Site engineering of personnel reinstructed in requirements for completing formal supporting documentation re design calculations. CRUDEN,D.S. Virginia Power (Virginia Electric & Power Co.). 88/04/05. Document Control Branch (Document Control Desk), 3pp. 45147:316.45147:318.
- 8804010256 NRC Into Notice 88-011, "Potential Loss of Motor Control Cit &/or Switchboard Function Due to Faulty Tie Bolts," Svc list encl.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/04/07 Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407:051.
- 8804130264 Responds to NRC 880308 ltr re violations noted in Insp. Repts 50:338/87-38 & 50:339/87-38. Corrective actions:steam flow channel instrument calibr procedures will be revised by 880430. Remits fee for civil penalty. CRUDEN,D.S. Viginia Power (Virginia Electric & Power Co.), 88r/04/07. Ofc of Enforcement (Post 870413), 8pp. 45138:020-45138.027.

- 8804050370 NRC Info Notice 88 012, "Overgreasing of Electric Motor Bearings" Svc isterici HOSSI.C E Division of Operational Events Assessment (Post 870411). 88/84/12 Consolidated Edison Co. of New York, Inc. 123pp. 45185-028-45185-150
- 8804200473 Partial response to FOIA request re like protection Forwards App E documents App D & E documents available in PDR App F document completely withheld (ref FOIA Exemption 5). GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 88/04/14. JONES,C R Affiliation Not Assigned. 5pp. 45206 037-45206 043.
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type insp for each facility to assess status of compliance w/ 10CFR50,48. Program listed. CONLON,T.E. Region 2, Ote of the Director. 84/11/06. HERDT,A.R. Region 2, Ote of the Director. 3pp. 45206:176.45206:178.
- 8804260004 Forwards Insp Repts 50:338/88-07 & 50:339/88-07 on 880321-25 & notice of violation. W/o notice of violation. CLINE,W.E. Region 2, Otc of the Director. 88/04/18, STEWART,W.L. Virginia Power (Virginia Electric & Power Co.), 2pp. 45254:219-45254:221.
- -8804260006 Partially withheld Physical Security Insp. Repts 50-338/88-07 & 50-339/88-07 on 880321-25 (ref. 10CFR2 790(d) & 73.21) One violation & one Inspector followup Item noted Major areas Inspected security program eaulit & records & repts, MASNYK O.M., MCGUIRE, D.R. Region 2, Ofc of the Director. 88/04/13. 1p. 45254 221 45254:221.
- 8804260180 Responds to NRC 880308 lit re violations noted in linsp Repts 50-338/87-38 & 50-339/87-38.Corrective actions:station mgt briefed on requirements of 10CFR50.73 re scope & content of LERs & mgt interviews will be conducted as required CRUDEN,D.S. Virginia Power (Virginia Electric & Power Co.). 88/04/21. Oic of En-lorcement (Post 870413), 9pp, 45253.040-45253:048,

- 8804070252 Summary of procedure changes, lecility changes & special tost for 1987.W/ 880331 III. STEWART.W.L. Virginia Power (Virginia Electric & Power Co.). 87/12/31, 160pp. 45076.051-45075;210.
- 8804190253 Monthly operating repts for Mar 1988.W/860414 ltr. GARNER,B., CRUDEN,D.S. Virginia Power (Virginia Electric & Power Co.), 88/03/31, 15pp. 45208.182-45208:196.
- 8804260325 Comments on comparison review of 1986 semiannual effluent release repls,per 880311 request Percent of Tech Spec Limit for total body dose rate for fourth quarter on Page 7 changed from 7.63E3% to 7.63E.3%. CAUCON,D.S. Vigolial Power (Virginia Electric & Power Co.). 88/04/20. TICHLER,J. Brookhaven National Laboratory. 2pp. 45282.032.45282.051.
- --8804280302 "Effluent & Wasto Disposal Annual Rept for 1986."

 Virginia Power (Virginia Electric & Power Co.). 86712/31. 18pp. 45282 034-45282051.

S. Reportable occurrences, LERs & related correspondence

- 8804080029 LER 87-012-01:on 870831,three valvos failed Type C local leak rate testing.Caused by Incorrect testing methods & seating surface degradation Air-operated valve releated correctly & check valve cleaned & relapped.W/880331 ltr. HARRELLE.W. Virginia Power (Virginia Electric & Power Co.). 88/03/31, 4pp 45100:269-45100.272.
- 8804190094 PNO-II-88-022:on 880405 low levels of rad pactive mall detected in demin-eralizer beds for plant makeup water. Caused by concentrating effect of radionuclides. Licensee currently storing spent demineralizer beds onsite until NRC approval. KAHLE,J. Region 2, Ofc of the Director. 68/04/08. 1p. 45209:173-45209.173.

V. Operator Examinations

- 8804250088 Responds to FOIA request for Info re-scores of reactor operators & senior reactor operators. Forwards requalification exam summary source sheets i.sted in encl app w/personal privacy into deleted. GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 88/04/19. BOLEY,K. Public Citizen's Critical Mass Energy Project. 2pp. 45213:003-45213.095.
- -8804250167 Package of NRC administered requalification exam results summary.
 * NRC No Detailed Afailation Given, 87/07/20, 88pp. 45213.007-45213:095.

DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8804010126 Rev 3 to Emergency Plan Implementing Procedure EP-304-01-SO, "Atternate Emergency Operations Facility." FRASIER,L. Detroil Edison Co. 88/03/25, 8pp, 45020,022-45020,029.
- 8804050072 Forwards Allegation & Saleguards Insp Rept 50-341/88-02 on 880201-05.No violations noted.

 MALLETT,B. Region 3, Oto of the Oirector. 88/03/31, SYLVIA,B.R. Detroit Edison Co. 2pp. 45028:269-45028:277.
- -8804050078 Partially withheld Allegation Review & Physical Security Insp Rept 50-341/88-02 (ref 10CFR73.21(c)(2)). No violations noted Major areas inspected security plan & implementing procedures,mot effectiveness & records & repts. KNICELEV_J.R., DROUIN.B.S., CREED,J.R. Region 3, Ofc of the Director. 86/03/30.7pp. 45028:271-45028:277.

- 8904060516 Forwards updated response to SALP 8 Board rept.oor NRC 880202 request Most actions described in util 880924 fir for improving performance complete Compfetion of Tech Spec improvement program extended to 681231. SYLVIA,B R. Detroi Edson Co. 88/03/31. Document Centrol Branch (Document Control Desk), 16pp. 45008.330-45008.345.
- 8804120388 Confirms 880413 enforcement conference in Gren Ellyn, it to discuss findings identified during safeguards insp conducted on 880310-24, per R Cooper 880401 telcon. Meeting notice encl GREENMAN, E.G., Region 3, Ofc of the Oirector. 88704705. SYLVIA, B.R. Detroit Etison Co. 2pp. 45135-280-45135:281.
- 8804150338 Rev 5 to Radiological Emergency Response Preparedness Plan Administrative Procedure EPA-08-SQ, "Radiological Emergency Response Prepardness Training Program."
 FRASIERIL. Dotrot Edison Co. 88/04/07. 11pp. 45138.164-45138 174.
- 8804190211 Forwards selety evaluation accepting util 670923 request to change fire bri-gade training schedules to allow flexibility in scheduling use of To'ede Fire Dept facility Scheduled intervals should not exceed 3.25 times specified intervals. CUAY_TR. Project Directorate III-1. 88/04/13. SYLVIA,B R. Detroit Edison Co. 3pp 45156:268-45155:273.
- --8804190218 Safety evaluation accepting util 870923 request to change fire brigade training to provide flexibility in scheduling use of Toledo Fire Academy training facility. Training Intervals should not exceed 3.25 times specified interval. *Office of Nuclear Reactor Regulation, Director (Post 870411). 68/04/13. 3pp. 45155:271-45155:273.
- 8804200410 Forwards Safeguards Insp Rept 50:341/88-10 on 880310-24, Potentiat vio-lations noted especially waspon-rolated incident on 880308 NORELIUS,C.E. Region 3, Ote of the Director. 88/04/13, SYLVIA,B.R. Dotic.t Ed son Co. 2pp. 45231:082-45231:085.
- --8804200413 Partially withhe'd Insp. Rept. 50:341/86-10 on 880310:24 (rof 10CFR73.21) Violation noted Mejor areas inspected: security program audits,records & ropts,testing & maint, locks,keys & combinations & vital area barriers.
 PIRTLE_G., FUNK,D., CREED,J.R. Region 3, Ofc of the Director. 88/04/12. 2pp. 45231.084-45231.085.

G. Adjudicatory correspondence

8804050049 Informs of 880329 docketing & tiling in in Camora file of preliminary investi-gation of plant prepared by GAP. JULIAN,EL. Docketing & Services Branch. #288 6000. 88/03/31. Docketing & Serv-ices Branch. 1p. 44966 232-44966:232.

J. Insurance & indemnity information

- 8804070133 Forwards Endorsements 1,2 & 3 to MAELU Master Worker Policy MW-90 & certificate of insurance & NELIA Master Worker Policy NW-42 & certificate of Insurance, aspectively.

 SYLVIA,B.R. Detroit Edison Co., 88/03/31. Document Control Branch (Document Control Desk), 45pp. 46029;267-45029 311.
- 8804210319 Provides total amount of property damage & deconfamination insurance coverage. SYLVIA.B.R. Detroit Edison Co. 88/03/31. Document Control Branch (Document Contro! Dask). 1p. 45235:252-45235:252.

K. Utility Final Safety Analysis Report (FSAR) & amends

- 8804060085 Rev 1 to updated FSAR for Fermi 2.
 * Detroit Edison Co. 88/03/31, 771pp. 45112:339-45115.029.
- 8804140025 Forwards errete to Rev 1 to 880317 updated FSAR Errete corrects error made in assembling Rev 1 for printing SYLVIA B. Delicit Edison Co. 88704706. Document Control Brench (Document Control Oosk). 1p. 45155:047-45155.053.
- --8804140087 Errata to Rev 1 to updated FSAR for Fermi 2.
 * Detroit Edison Co. 88/04/06. 8pp. 45185 048-45155.053.

P. Operating license stage documents & correspondence

- 8803 100061 Forwards notice of issuance of amend to License NPF-43 & opportunity for hearing re 871 1130 application for amend to License. QUAY,T.R. Project Directorate III-1. 88/03/04. SYLVIA,B.R. Detroit Edison Co. 2pp. 44661:351-44661:355.
- --8803100070 Notice of consideration of issuance of amend to License NPF-43 & op-portunity for hearing. Amend would revise Tech Spec Table 3.3.7.5-1 to require that min of two channels be operable for stanchy gas treatment systradiation monitors. QUAY.T.R. Project Directorate III-1, 88703/04, 4pp. 44661-353-44661:356.
- 8803240428 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAQLIA,F.J. Associate Director for Projects (Post 870411), 88/03/22. Consol dated Edison Co. of New York, Inc. 47pp. 44972;107-44972.153.
- 8804190196 Forwards notice of consideration of issuance of amend to License NPF-43 QUAY.T.R. Project Directorate IB-1, 88/03/22, SYLVIA,B R. Detroit Edison Co. 2pp. 46165:333-45165:339.
- --8804190207 Notice of consideration of issuance of amend to License NPF-43 & op-porturity for hearing on 880127 request re rays to Tech Spocs to clarify bases of op-eration w/moisture separator reheator out-of-syc. WAMBACH,T.V. Project Directorate III-1, 88/03/29, 5pp. 45185:335-45165-339.

- 8804200394 Recommends M Parker for cash award due to assessment of startup test corrective action programs During review of licensee actions listed problems identified
- & resolved KNOP R C Region 3, Otc of the Director, 88/03/25, GREENMAN,E G. Region 3, Otc of the Director, 1p, 45234,348-45234,348
- 8804010090 Application to amend License NPF-43 changing Tech Specs to modify foot-note number to include provisions to place mode switch in refuel position to facilitate source dange monifor & intermediate range monitor operativity testing Fee paid SYLVIA,B R. Detroit Edison Co. 88/03/28. Document Control Branch (Document Con-trol Desk). 7pp. 45008:148-45008.155.
- —8804010093 Proposed Tech Specs modifying footnote number to include provisions to place mode switch in refuel position to facilitate source range monitor & intermediate range monitor operability testing ** Detroit Edison Co. 88/03/28 1p. 45008:155-45008:155
- 8804010103 Application for amend to License NPF-43,changing Tech Spacs 3/ 4.37.11,3/4.37.12.8.6.9.1.8.to allow continued use of release pathways for which ef-fluent monitoring instruments may not be operable Fee paid. SYLVIA.B.R. Detroit Edison Co. 88/03/28. Document Control Branch (Document Con-trol Desk). 8pp. 45031:181-45031:194.
- --8804010108 Proposed Tach Specs, allowing continued use of release palhways for which eithern monitoring instruments may not be operable provided grab samples & analyses & for flow rate calculation made at specified frequencies.
 * Detroit Edison Co. 88/03/28. 6pp. 45031:189-45031:194
- 8804080148 Forwards Amend 17 to License NPF-43 & safety evaluation. Amend modifies Tech Specs to add isolation valves for primary containment radiation monitor. OUAY,T.R. Project Directorate III-1, 88/03/28 SYLVIA,B.R. Detroit Edison Co. 4pp. 45064 257-45064 270.
- -8804080160 Amend 17 to License NPF-43,modifying Tech Specs to add valves for primary containment radiation monitor.
 VIRGILIO.M.J. Project Directorate III-1. 88/03/29. 8pp. 45064:261-45064.267.
- -8804080169 Salety evaluation supporting Amend 17 to License NPF-43.

 Office of Nuclear Reactor Regulation, Director (Past 870411), 88/03/29, 3pp. 45064 268-45064 270.
- 8804120058 Forwards request for additinfoire util 870227 submittal of infoion implementation of ATWS rule Additinfoion recirculation pump trip & atternate rod injection sys GUAY,T.A. Project Directorate III-1 88/03/31. SYLVIA.B.R. Detroit Edison Co. 5pp. 45069 258-45089 262
- 8804080032 Discusses allegation re tool issuance,per 880323 memo. Action recommended will be held in abeyance pending results of ref appeal by util & status of AMS Number Rill 87.4-0172 should be revised accordingly.

 GREENMAN,E.G. Region 3, Otc of the Director, 88704/04 WEIL.C.H. Region 3, Otc of the Director, 1p. 45098 150-45098.150.
- 8804110251 Informs that potential mail false statement in enci to 871221 memo from J Stefano to E Greenwood re Tech Spec certification will not be pursued further.Matter may be included along w/other issues being investigated at plant OUAY,TR. Project Directorate III-1. 2pp. 45078 355-45078 356.
- 8804140193 Provides histed into requested in 880225 lit re operating nuclear power units located at twelve sites along Great Lakes. STELLO,V. Otc of the Executive Director for Operations 88/04/06. RIDGE,T. House of Rep. 5pp. 45104:138-45104.143.
- 8804210266 Forwards plant preventive maint program stalus rept for Feb 1988 per NRC 871009 request 871019 request SYLVIA, B.R. Detroit Edison Co. 88/04/06. DAVIS, A.B. Region 3, Olic of the Director. 4pp. 45235 253-45235 258.
- 8804080088 Generic Lv 88.07 to power reactor licensees & applicants re-modified en-lorcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Salety for Nuclear Power Plants." Svc list encl. MIRAGLIA.F.J. Associate Director for Projects (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804190175 Forwards environ assessment & finding of no significant Impact re 880222 application for exemption from requirements of App J to 10CFR50. GUAY,T.R. Project Directorate III-1, 88/04/07. SYLVIA,B R. Detroit Edison Co. 3pp. 45155 260-45155 287.
- -8804190181 Environ assessment & finding of no significant impact on util 880222 application for examption from requirements of App J to 10CFR50. OUAY,T.R. Project Ovectorate III-1, 88/04/07, 5pp. 45155:263-45155:267.
- 8804140488 Discusses util 851227 notification of intent to remove moisture-sensitive tape leak detection sys using 10CFR50.59 review based on NRC Branch Technical Positions ASB3-1 & MEB 3-1 Intent consistent w/Jul 1981 SER & acceptable, OUAYT, Project Directorate III-1, 88/04/11, KNOP,D. Region 3, Ofc of the Director. 2pp. 45120-360-45120.361.
- 8804140490 Application for amend to License NPF-43 providing one-time extension of 24 month surveillance interval for Type C local leak rate testing of RHR shutdown cooling inboard isolation valves Fee paid. SYLVIA,B.R. Oetroil Edison Co. 88704/11. Document Control Branch (Document Control Desk). 7pp. 45164 005-45164 012.
- -8804140506 Proposed Tech Specs.providing one-time extension of 24 month surveil-take interval for Type C local leak rate testing of three RHR shutdown cooling inboard isolation valves. * Detroit Edison Co. 88/04/11, 1p. 45164.012-45164:012.
- 8904200403 Advises that Region III in basic agreement w/need to followup on previously proposed design change to plant MSIV circuitry. Onsite insp scheduled to be conducted in middle of May 1988 to determine adequacy of design.

 GREENMAN.E.G. Region 3, Oto of the Director, 88/04/12. HAUGHNEY, C.J.; Special inspection Branch. 1p. 45174:169-45174:189.

Region III requesting responses to number of questions. Response to Oudstions 1 to 5 requested by 880801. W/o encl.
GREENMAN, E. G. Region 3, Ofc of the Director. 88/04/12. CRUTCHFIELD,D. Division of Reactor Projects - III, IV.V. & Special Projects (Post 870411). 1p. 45175.037-45175.037.

RRG12005/2 FORWARDS BBOJ 17 III JIOTTI MICHIGO CITY CO

- 8894250014 Informs of approval of request to retain & dispose contaminated soil onsite under 10CFR20,302(a) on condition that licensee comply w/procedures outlined in 870526 submittal. VIRGILIO M.J. Project Directorate III-1, 88/04/14. SYLVIA B.R. Detroit Edison Co 4pp. 45201:176-45201:179.
- 8804210453 Forwards Amend 18 to License NPF-43 & salety evaluation. Amend tevises Tech Spec 4.6.1.2 b to provide one-time extension of 24-month surveillance interval for Type C local leak rate test of three RHR sys. QUAY.TR Project Directorate III-1. 88/04/15. SYLVIA,B.R. Detroit Edison Co. 3pp 45192:188-45192:198.
- --8804210457 Amend 18 to License NPF-43 revising Tech Spec 4.6.1.2 b to provide one-time extension of 24-month surveillance interest for Type C tocal light rate lesses three RHR shufdown cooling isolation values. VIRGILIO,M.J. Project Directorate III-1. 88/04/15. Spp. 45192:191-45192:105.
- -8804210459 Safety evaluation supporting Amend 18 to License NPF-43.

 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/15, 3pp 45192.196-45192;198.
- 8804280500 Fowards exemption from requirements of Section III.D.3 of App J to 10CFR50 re Type C Local Leak Rate Tast for 3 RHR shutdown cooling isolation valves (£11-F009,E11-F408 & E11-F-609). DUAY,TA, Project Directorate III-1, 88/04/15, SYLVIA,B.R. Detroit Edison Co. 4pp 45271:029-45271.038.
- --8804250210 Exemption from 10CFR50,App J requirements to extend 24-month testing interval for three RHR shutdown cooling inboard tsoletton valves. CRUTCHFIELD.D. Division of Reactor Projects III,IV,V & Special Projects (Pos 870411), 88/04/15, 7pp. 45271:033-45271:036.
- 8804270185 Requests response to listed items re employee allegation of removal to raising safety concerns. Response requested within 30 days NRC will determine upor receipt of response if enforcement action necessary. DAVIS.AB. Region 3, Ofic of the Director. 88/04/18. SYLVIA,B.R. Detroit Edison Co. 2pp. 45245:344-45245:345.
- 8804280303 Notification of 880421 meeting w/util in Rockville,MD to discuss rocen events at facility,status of plant for restart from current outage & util soft-assessmen QUAY,T.R. Project Directorate III-1, 88/04/19, MURLEY,T., SNIEZEK,J., MIRAGLIA,F, NRC No betailed Affiliation Given. 3pp. 45269:206-45289:208.
- 8804260026 Application for amend to License NPF-43, revising Tech Spec Table 4.3.1.1 1, reactor protection sys instrumentation surveillance requirements. Fee paid. SYLVIA, B.R. Detroit Edison Co. 88/04/20, Document Control Branch (Document Control Dash). 11pp. 45268:204-45268:216.
- -8804260030 Proposed Tech Specs Table 4.3.1.1-1, reactor protection systems instruments tion surveillance requirements deleting dally check requirements of Note g for APRI flow blased neutron flux-high scram functional unit.

 * Detroit Edison Co. 68/04/20. 2pp. 45268:215-45268:216.
- 8804270191 Revises response to Generic Lir 87-05 re identification of potential degre-dation of Mark I drywells.Response to Item 2 revised to correctly reflect util commi-ments concerning minimizing possibility of leakage from refueling cavity. SYLVIA.B.R. Detroit Edison Co. 88/04/20. Document Control Branch (Document Cor-trol Desk). 5pp. 45244:275-45244:279.
- 8804270203 Forwards response to questions in NRC 880931 ftr requesting addition util recirculation pump trip & alternate rod injection sys. SYLVIA,B.R. Detroit Edison Co. 88/04/20. Document Control Branch (Document Cottrol Desk). 9pt. 45280:100-45280:108.
- 8804260045 Supplemental application for amend to License NPF-43, revising Tec Spec 3/4.3.2 re isolation actualion instrumentation. SYLVIA.B.R. Detroit Edison Co. 88/04/21. Document Control Branch (Document Control Desk). 3pp. 45259:282-45259:288.
- -8804260048 Tech Spec 3/4.3.2 re isolation actuation instrumentation.

 * Detroit Edison Co. 88/04/21. 4pp. 45259:285-45259:288.
- Q. Inspection reports, IE Bullstins & correspondence
- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Westinhouse Reactors." Svq list enci.

 ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/03/2 Consolidated Edison Co. of New York, Inc. 121pp. 44995:128-44995:246.
- 8803220296 NRC Info Notice 88-010, "Malls Licensees:Lack of Mgt Controls Over I censed Programs." Svo list encl. CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 870729). 8 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:359.
- 8804070115 Forwards request for additinfoire util 880515,1001,1219 & 871117 & 122 response to IE Bulletin 85-003, "Motor-Operated Valve Common Mode Fallum During Plant Translants Due to Improper Switch Settings," for response in 1 mont GREENMAN,E.G. Region 3, 016 of the Director, 88/03/30, SYLVIA,B.R. Defection Co. 4pp. 45031:001-45031:004.
- 8804050072 Forwards Allegation & Safeguards Insp. Rept 50-341/88-02 on 88020 05. No violations noted. MALLETT.8 Region 9, Oto of the Okedtor. 88/09/61, SYLVIA,B.R. Detroit Edison C 2pp. 45028:269-45028:277.

- -8804050076 Parially withhold Allegation Roview & Physical Security Insp Rept 50-341/88-02 (red 10CFR73 21(c)(2)). No violations noted Major areas inspected security plan & implementing procedures, migt effectiveness & records & rept KNICELEY, J.R., DROUIN,B.S., CREED,J.R., Region 3, Ofc of the Director, 88703/30, 7pp 45028 271-45028 277.
- 8804060516 Forwards updated response to SALP 8 Board rept,per NRC 880202 request Most actions described in util 880924 fit for improving performance complete Completion of Tech Spec improvement program extended to 881231. SYLVIA B.R. Detroit Edison Co. 88/03/31. Document Control Desk) 16pp. 45008:330-45008:345.
- 8804080367 Responds to violations noted in Insp Rept 50-341/88-05. Corrective actions urgent required reading issued to operations thits to make aware of event & consequences & requirements for HPCI & RCIC sys above 150 ps/g claided SYLVIA,B.R. Dotro: Echson Co. 88/04/02. Document Control Branch (Document Control Branch (Document Control Branch) trol Desk). 2pp 45010 249-45010 250
- 8804110154 Responds to NRC 871209 ftr re violations noted in Insp. Rept 50:341/87-44 Corrective actions:Procedure 24:202.01, "HPCI Pump Operability & Flow Test at 1,000 psi & Valve Operability" revised Change to Tech Spec will be pursued SYLVIA.BR. Dottott Edison Co. 88/04/04. Document Control Branch (Document Control Desk). 2pp. 45135.078-45135:079.
- 8804120078 Confirms 880413 meeting in Glon Ellyn, IL to discuse results of safety systemicional inspiral HPCI sysper 880401 to'con. Notification of meeting enclication of meeting enclication Co. 3 (Apr. 1998) 1 (1998) 1
- 8804120388 Confirms 860413 enforcement conference in Gfen Ellyn, IL to discuss find-ings identified during safeguards insp conducted on 860310-24, per R Cooper 880401 telcon, Meeting notice enct. GREENMAN.E.G. Region 3, Ofc of the Director, 68/04/05, SYLVIA, B.R. Detroit Edison Co. 2pp. 45135-280-45135-281.
- 8804120398 Confirms plans for 880406 meeting at Region III ofc to discuss licensee corrective actions re internal damage to moisture separator reheaters.per 880331 tetoon.Notice of significant licensee meeting encl.

 GREENMAN.E.G. Region 3, Ofc of the Director. 88/04/05 SYLVIA.8 R. Detroit Edison Co. 3pp. 45129-358-45129-360.
- 8804110160 Commonts on CJ Pepariello 880323 memo re insplof allegations at plants Significance of allegations low & do not warrant immediate review & closure. KNOP,R.C. Region 3, Otc of the Director. 88/04/06 GREENMAN,E.G. NRC No Detailed Afrillation Given 2pp. 45135-074-45135-076.
- 8804140060 Forwards Safety Insp Rept 50-341/88-09 on 880307-11.No violations Noted Transport Transport
- -8804140070 Insp Rept 50-341/88-09 on 880307-11. No violations noted. Major areas inspected radiation protection program during maint outage organization & mgt controls & changes in organization personnel facilities equipment & procedures. PAULIRA, SLAWINSKI, W.J., GREGER, L.R. Region 3, Oic of the Director. 88/04/05. 1304-651-124-651-2446. 13pp. 45152:132-45152 144.
- 8804010256 NRC Into Notice 88:011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tile Bolts." Svc list encl ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consol dated Edison Co. of New York, Inc. 124pp. 45408 292-45407.051.
- 8804130110 Deletes commitment made in 871117 lir to change actuator on RCIC Velver F012, in response to IE Bulletin 85-003. Design change to RCIC sys will be implemented during local leak rate test outage to remove power to RCIC Valve F012. SYLVIA,BR. Detroit Edison Co. 88704/08. Document Control Branch (Document Control Desk). 3pp. 45137:106-45137:108.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Boarings." Svc
- list eact.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12.

 Consolidated Edison Co. of New York, Inc. 123pp. 45166 028-45165:150.
- 8804210252 Requests followup on certain areas at plant, including shift activities, operation evolution evaluation program & operation communications, per 880404 lefcon between recipient & D Cooper. KNOP,R.C. Region 3, Otc of the Director. 88/04/12. HAUGHNEY,C.J. Special Inspection Branch. 2pp. 45194:236-45194:237.
- 8804200410 Forwards Sateguards Insp Rept 50:341/88-10 on 880310-24. Potential vio-lations noted aspecially weapon-related incident on 880308. NORELIUS,CE. Region 3, Otc of the Director. 88/04/13. SYLVIA,B.R, Detroit Edison Co. 2pp. 45231:082-45231:085.
- --8804200413 Partially withhold Insp Ropt 50-341/88-10 on 880310-24 (ref 10CFR73.21) Violation noted Major areas inspected, security program audits,records & repts,testing & maint, locks,keys & combinations & vital area barriors. PIRTLE,G., FUNKD. CREED,J.R. Region 3, Ofc of the Director. 88/04/12 2pp. 45231.084-45231.085.
- 8804260175 Forwards Insp Rept 60-341/88-11 on 880328-30 No violations or deviations noted. HARRISON, J.J. Region 3, Ofc of the Director. 88/04/15. SYLVIA,B.R. Detroit Edison Co. 2pp. 45248.039-45248.048.
- -8804260183 Insp Rept 50-341/88-11 on 880328-30 No violations or deviations noted Major areas inspected activities to main steam Isolation valve spring failures & E-Builetin 85-003 concerning motor-operated valve switch settings. SMITH_J.F._DANIELSON,D.H. Region 3, Ofc of the Director. 88/04/15. 8pp. 45248.041-45248.048.

8804190129 Monthly operating rept for Mar 1988.W/880415 ltr.
ANTHONY,P.M., ORSER,W.S. Detroit Edison Co 88/03/31. 7pp. 45199.076-

- 8804270211 Forwards plant monthly status rept for period 880220-0318. Ropt Intended to provide NRC mgt 8 public w/pverview of plant activities & NRC map activities. KNOP,RIC Region 3, Otc of the O.rectic. 88/04/15. GREENMAN,E.G. Region 3, Otc of the Director. 5pp 45244:261-45244:285
- S. Reportable occurrences, LERs & related correspondence
- 8803310147 LER 88-048-02:on 871008,discovered Tech Spac requirement to perform channel check for reactor protection sys drywell high pressure instruments not boing met On 880226.log c functional testing for ECCS found inadequate W/880328 ftr. ANTHONY,P., DRSER,WIS Obtro.1 Edison Co. 88/03/28. 7pp 44953-202-44953-208
- 8804050172 LER 89-006 00 on 880229.unexpected less of RHR shutdown cooling experienced after transfer of reactor protection sys B power supply.Appears that operation felled to reset valve closure logic after transfer Procedure revised W7880330 R ANTHONY.P., ORSER.W S Detroit Edison Co. 88/03/30. 8pp 45017-190-45017 195
- 8804050185 LER 88-008-00:on BB0229,MSIVs & Div I MSIV leakago control sys Isola-tion valve discovered leaking in excess of Toch Special exable limits Caused by valve degredation or conteminants in valve seats Tests continuing W/cindated III. ANTHOMY.P., ORSER,W.S. Detroit Edison Co. 88/03/30. 4pp 45076.025-45076-028
- 8804130125 Panial response to FOIA request for documents re Info Assessment Team notification & alleged valve tampering. App A documents available in PDR.Forwards App B documents App B documents also available in PDR.Forwards GRIMSLEY,D.H. Division of Rules & Records (Post 870413) 88/04/04 MAXWELL,B Cosmos Broadcasting Corp. 3pp. 45102/031-46102/048.
- -8804130151 PNO-III-87-101 on 870726. I censed received bomb threat from caffer angry because place of residence lost power during storm. Security personnel notified & search procedures implemented No bomb discovered. CREED. AXELSON, W. Region 3, Old of the Director, 87/07/27, 1p. 45102-036-45102-036
- --8804130185 Forwards FBI communication to be disseminated only to NRC employees w/noed to know.W/o FBI communication Rocords of 860810,0928,1212,870404 & 0929 totcons & Region III repts of 860810,0928 1312,870404 & DAVIDSONJ. Office of Nuclear Material Safety & Safeguards,Director 87/10/15 HAYES,B. Office of Investigations. 11pp. 45102,038-45102,048.
- 8804150405 LER 88-010-00.on 880310.turbine bldg stationary particulate, lodine & noble gas radiation monitor test power Caused by fallers of operations personnel to comply w/requirement of abnormal line-up sheet W/860411 ltr. ANTHONY, P., ORSER, W.S. Detroit Ed son Co. 88/04/11, 5pp. 45183:130-45183:134
- 8804150417 LER 88 009 00 on 880311, safety rollet valves failed set pressure surveilfance tolerance test. Cause of failure under review. All valvos removed from plant for testing returb shed, closhed, rotested & recertified. W/800411 ftr. ANTHONY, P., ORSER, W.S. Detroit Edison Co. 88/04/11. 6pp. 45183:124-45183.129.
- 8804190008 Special rept on 880110,ECCS actuation occurred Operator manually tripped sys. Detai's of event discussed in LER 88-004. SYLVIABR Detroit Edison Co. 88/04/11. DAVIS,A.B. Region 3, Ofci of the Director.
- 8804190238 LER 88-011-00:on 880313,faiture to perform shiftly surveillance within required time occurred Caused by faiture to designate person to perform survo.llance when personnol reessigned Requirement added.W/880412 ir.
 ANTHONY,P., ORSER,W.S. Detroit Edison Co. 88/04/12 Spp. 45196:315-45196.319.
- 8804200139 LER 88.012-00.on 880316,rack Isolation valva for reactor protection sys Channel C drywe'l pressure instrument found closed Caused by failure to fully open valve alter 86.1016 survo llance. Procedure 23, 327 revised W/880415, fir. ANTHONY, P., ORSER, W.S. Detroit Edison Co. 88/04/15, 6pp. 45226;221-45226;226
- 8804200375 LER 87-048-03 on 871008, several inadequacies in Tech Spec survaillances were found during survailance review. Caused by incomplete or inadequate survailance procedures Appropriate procedures revised &/or reviewod.W480415 itr. ANTHORY.P., ORSER.W.S. Detroit Edison Co. 88/04/15. 10pp 45226.001-45226:010
- 8804210394 Summary of Operating Reactors Events Meeting 88-16 on 880412 List of Altendess & viewgraphs enci.

 LANNING,W. Division of Operational Events Assessment (Post 870411), 88/04/15

 RDSSI,CE, Division of Operational Events Assessment (Post 870411), 20pp. 45192:139-45192:158
- 8804200159 LER 88-013-00 on 880318, shutdown cooling was lost due to closure of suction Isolation valve & subsequent tripping of RHR pump. Caused by procedurating adequacies & personnel error. Sys operating procedures will be revised W-804-18 it. ANTHONY, P., ORSER, W.S. Detroit Edison Co. 88/04/18. 4pp. 45218:261-45218-264.
- 8804270004 LER 88-014-00 on 880320.Div I emergency diesel generators inadvertently started.Caused by procedural error. Revs Issued which corrected sequence of steps.W/800419 ltc.
 - ANTHONY,P., ORSER,W.S. Detroit Edison Co. 88/04/19. 4pp 45282 097-45282:100
- 8804270221 Confirms 880419 telcon re recent problems that have occurred a plant Licensee should make available results of actions taken to correct problems & startup of plant will only occur w/concurrence of regional administrator.

 DAVIS A B. Region 3, Ofc of the Director, 8B/04/19, SYLVIA,B.R. Detroit Edison Co 3pp. 45244/252-45244/254.

V. Operator Examinations

2pg. 45197:060-45197:061

app w/personal privacy into deleted
GRIMSLEY,D.H. Dwiston of Rutes & Records (Post 870413). 88/04/19. BOLEY,K.
Public Citizen's Critical Mass Energy Project. 2pp. 45213 003-45213 095

~8804250167 Package of NRC administered requalification exam results summary.

* NRC - No Detailed Affiliation Given, 87/07/20, 88pp. 45213.007-45213.095.

DOCKET 50-344 TROJAN NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

- 8804070294 Revised emergency plan implementing procedures including Rev 1 to EP-005,Table 005.01, "Dedicated Telephone Sys Stations," Rev 1 to EP-100, "Control Room," Rev 1 to EP-103, Figure 103-18 & Rev 1 to EP-104, "Company Support Ctr." Portland General Electric Co. 88/03/11, 11pp. 45021;190-45021.200.
- 8804050389 Rev 1 to Emergency Plan Implementing Procedure EP-500, "Inventories."
 * Portland General Electric Co. 88/03/16. 128pp. 45058:193-45058 320.
- 8804060475 Forwards Saleguards Insp Rept 50:344/88-05 on 880218-0311 & notice of violaton.Rept & notice withheld (ref 10CFR2.790(d) & 73-21).

 MONTGOMERY,JL. Region 5, Oic of the Director. 88/03/30. COCKFIELD,D.W. Portland General Electric Co. 2pp. 45010-344-45010.345.
- 8804190145 Forwards SALP Rept 50-344/87-41 for Nov 1986 Nov 1987. Meeting to discuss rept planned for 880422.Expresses concern that problems experienced during SALP period may be reflective of tack of understanding of tall initiatives. MARTINJ.B. Region 5, Otc of the Director 88/03/30. COCKFIELD,D.W. Portland General Electric Co. 3pp. 45197.062-45197:108.
- --8804190149 SALP Rept 50:344/87-41 for 661101-871130.

 ' Region 5, Ofc of the Director. 87/11/30, 44pp. 45197:085-45197:108.
- 8804200569 Provides conective actions taken re-nonfunctional fire barriers.per NRC 871113 Itr. Proper application of NEPA 80 cnteria established & lire protection supervisor will now be responsible for all onsite lire prevention 8 protection. COCKFIELD.D.W. Portland General Efectic Co. 88/04/12. Document Control Branch (Document Control Desk). 2pp. 45235.022-45235.023.
- 8804270186 Amend 13 to Vol 1,8pok 1 of "Radiological Emergency Plan & Procedures Manuel." W/880415 ltr. WALT, T.O. Portland General Electric Co. 88/84/15 315pp. 45243.258-45244:212.
- 8804220277 Forwards Rev 20 to security plan Rev withheld (ret 10CFR73 21). COCKFIELD, D.W. Portland General Electric Co., 88/04/20. Document Control Branch (Document Control Desk). 1p. 45257:184-45257:184.
- 8804280533 Notification of 880428 meeting w/util & T Walt in Rockville,MD to discuss util security plan.
 CHAN,T.L. Project Orrectorate V. 88/04/21. KNIGHTON,G.W. Project Orrectorate V
 4pp. 15289:088-45283:089.

J. Insurance & Indemnity Information

8804070323 Forwards list of util property insurance coverage for 1988 per 10CFR50.54(w)[2].
COCKFIELD,D.W. Portland General Electric Co. 88/03/31. Document Control Branch (Document Control Desk), 2pp. 45021;233-45021;234

P. Operating (Icense stage documents & correspondence

- 8804040134 Advises that based on review of util 870501 response to NRC request for Into reflood relied capability of turbine bldg in event of expansion joint break in circu-lation along the supposition of turbine bldg in event of expansion joint break in circu-lating weller sys. updated FSAR changes acceptable. CHAN,T. Project Directorate V. 68/02/22. COCKFIELD,D.W. Pontand General Electric Co. 3pp. 44972:210-44972.212.
- 8803240428 Generic Lir 88:06 to all power reactor licensees & applicants re-removal of organization charts from Tech Spec administrative control requirements. Suc list enci. MIRAGLIA, F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804040088 Forwards Cycle 1) radial peaking limit rept per Tech Spec 6.9.1.7.Results applicable for current Tech Spec FO limit of 2.32 & proposed limit of 2.50 currently under review as part of License Change Application 161. COCKFIELD.D.W. Portland General Electric Co. 88/03/24. Document Control Branch (Document Control Desk), 3pp. 44970:300-44970;302.
- 8804040048 Advises that specific actions taken to modify component cooling water sysper 871204 commitment. Mods necessary to meet pips break criteria in 870402 SER. Mods will be complated prior to startup from 1989 relie
- 8804040160 Discusses design mods which tall committed to perform for control room habitability by and of 1988 refueling outage. Proposed design mod will eliminate need to restart control bidg ventilation sys in specific sequence. COCKFIELD,D.W. Portland General Electric Co. 88/03/25. Document Control Branch (Document Control Desk). 2pp. 45031;281-45031;282.
- 8804060272 Requests NRC approval to delay mod of dampers in control room emergency ventilation sys outside air supply lines by 1 yr until 1989 refueling outage. Delay due to possible unreviewed safety question re relocation of damper. Widnel. COCKFIELD. O.W. Portland General Electric Co. 88/03/31, Occument Control Branch (Document Control Desk), 2pp. 45007;130-45007;270.

- 8804080188 Forwards Amend 139 to License NPF+1 8 safety availation. Amend revises Tach Spac Section 374.10, "Spacial Test Exceptions" by extending surveillance time gened for variying control rod insertability. CHANTLL Project Directorate V. 88703/31, COCKFIELD,D.W. Portland General Efecting Co. 3pp. 45084-271-45084-280.
- --8804080197 Amend 139 to License NPF-1,revising Tech Spoc Section 3/4.10, "Special Test Exceptions" by extending serveillance time period for verifying control rad insertability during rod worth & shutdown margin tests from 24 h to 7 days KNB/HTON,G W. Project Directorate V. 88/03/31. 4pp 45064.274.45064.277
- --8804080199 Satety evaluation supporting Amend 139 to License NPF-1.

 Office of Nuclear Reactor Regulation, Director (Post 970411). 88/03/31. 3pp 45064:278-45064:280.
- 8804110065 Forwards application for amend consisting of License Change Application 166,deleting offsite & organization charts from Yech Specs.Certificate of Svc encl Fee paid.
 COCKFIELD,D.W. Portland General Electric Co. 88/03/31. Document Control Branch (Document Control Desk). 2pp. 45146-035-45146-044.
- 45146:040
- --8804110068 Proposed Tech Specs.deleting offsite & facility organization charts
 * Pertland General Electric Co. 88/03/31, 4pp. 45146.041-45146.044.
- 8804080088 Generic Ltr 88-07 to power reactor Icensees & applicants re-modified en-forcement policy concerning 10CFR50-49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants" "Svc list and: MIRAGLIA,F.J. Associato Director for Projects (Post 870411), 88/04/07, Consolidated Ed.son Co. of New York, Inc. 49pp. 45164 237-45184:285
- 8804190137 Forwards Amend 140 to License NPF-1 & safety evaluation. Amend revises offeite & facility organization charts for Tach Spacs CHAN, T.L. Project Directorate V. 88/04/11. COCKFIELD, D.W. Portland General Elec-tric Co. 2pp. 45155.246-45155.259.
- --8804190142 Amend 140 to License NPF-1, revising offsite & facility organization charts for Tech Specs. KNIGHTON,G.W. Project Directorate V. 88/04/11, 6pp. 45155:248-45155.263.
- ~8604190143 Safety evaluation supporting Amand 140 to License NPF-1.
 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/11, 6pp. 45155-254-45155-259.
- 8804210291 Forwards application for amend to License NPF-1, consisting of License Change Application 167, revising Tech Space to detete rate to turbine bidg 45-ft elevation for location of remote shutdown monitoring instrumentation Foe paid COCKFELD,DW. Porlland General Electric Co. 88/04/12. Document Control Branch (Document Control Desk). 3pp. 45231:138-45231:146.
- 45231:144
- --8804210296 Proposed Tech Specs, deteiling refs to turbine bidg as location for remote shuldown monitoring Instrumentation Panel C-160.
 Portland General Electric Co. 88/04/12. 2pp. 45231:145-45231:146.
- 8804250203 Advises that no further plant specific action required presently,based on util 870918 response to NRC Bulletin 87-01, "Thinning of Prining Walls at Nuclear Power Planta ' CHAN,T.L. Project Directorate V. 88/04/12, COCKFIELD,D.W. Portland General Elec-tric Co. 2pp. 45213:118-45213:119.
- 8804220177 Forwards supplemental response to NRC safety evaluation of WCAP-10858, "ATWS Millgating Sys Actuation Circuitry Generic Design Package," por re-quest during 871214 felcon. Addl Info will be provided por commitment in 871030 ftr. BARR,R.C. Portland General Electric Co. 88/04/13. Document Control Branch (Docu-ment Control Desk). 10pp. 45257:185-45257:195.
- 8804220173 Forwards addl info ie six open litems/recommendations noted in NRC 871111 safety evaluation of fallure of Main Feedwator Sys Restraint SR-8.por commitment during audit of long-term pipa support design verification program in Jan 1988 COCKFIELD.D.W. Portland General Electric Co. 88/04/15. Document Control Branch (Document Control Desk). 8pp. 45257:218-45267:225.

- 8804050040 Ack receipt of 880304 ltr informing NRC of actions taken to correct violations noted in Insp Rept 50-344/88-01.

 PATE,R.J. Region 5, Oto of the Director. 88/03/25, COCKFIELD,D.W. Portland General Electric Co. 1p. 44996;119-44996;122.
- 8603210090 Suppl 1 to NRC info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors." See its enci. ROSSI, C.E. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995;248.
- 8803220296 NRC Info Notice 88-010, "Matts Licenseos Lack of Mgt Controls Over Li-censed Programs," Syo list encl. CUNNINGHAM, E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28, Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.
- 8804130013 Forwards (nsp Rept 50-344/88-04 on 880208-12 & 0229-0304 & notice of violation.
 WENSLAWSKI,F.A. Region 5, Old of the Director, 88/03/28, COCKFIELD.D.W. Portland General Electric Co. 2pp. 45131:069-45131:086.

- 014 Notice of violation from insp on 880208-12 & 0229-0304, Violation work area.w/general background radiation level of 15 mrem/hr, four hot spots g contact radiation levels of 800 mrem/hr to 1,200 mrem/hr not posted AWSKI,F A Flegion 5, Ofc of the Director. 88/03/28, 1p. 45131.071-
- 015 Insp Hept 50:344/88-04 on 880208-12 & 0229-0304.No violation agor areas inspected ficensee action on previous findings,organization & ming & qualifications,solid wastes,transportation & facility fours. 72 45131.086.
- 75 Forwards Safeguards Insp Rept 50-344/88-05 on 880219-0311 & notice of Rept & notice withheld (ref 10CFR2.780(d) & 73-21). OMERY.J.L. Region 6, Ofc of the Director. 88/03/30. COCKFIELD,D.W. Port-neral Electric Co. 2pp.
- 15 Forwards SALP Rept 50-344/87-41 for Nov 1986 Nov 1987. Meeting to rept planned for 880422 Expresses concern that problems experienced during mod may be rollective of lack of understanding of util initiatives J.J.B. Region 5, Olic of the Director. 88/03/30. COCKFIELD,D.W. Portland Electric Co. 3pp. 45197.082-45197:108.
- 149 SALP Rept 50 344/87-41 for 861101-871130. 5, Oto of the Director. 87/11/30. 44pp -45197.065-45197:108.
- 13 Suppls 880311 response to NRC Bulletin 88-002 re rapidly propagating ta-icks in steam generator tubes Commits to plant power level reduction to 50% re predicted tube rupture & clarifies replacement power cost. ELD,D.W. Portland General Electric Co. 88/04/01. MARTIN,J.B. Reg.on 5, to O.rector. 2pp. 45171:114-45171:115.
- of Ack receipt of 871228 ftr informing NRC of steps taken to correct violations. Insp. Rept. 50:344/87:34.Note that exception to Violation 87:34:02 re unupervisors issuing working 8 culting permits. J. Region 5, Ofc of the Director. 88/04/05. COCKFIELD,D.W. Portland Gentic Co. 1p. 45090.342:45090.342.
- 6 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-inction Due to Faulty Tie Bolls," Svc list and: E. Division of Operational Eventia Assessment (Post 870411). 88/04/07. ated Edison Co. of New York, Inc. 124pp. 45408 292-45407:051.
- 19 Forwards Insp Rept 50-344/88-08 on 880214-0326.No violations noted. MAN.R.P. Region 5, Old of the Director. 88/04/07. COCKFIELD, D.W. Porteral Electric Co. 2pp. 45237.077-45237:092. 043 Insp. Rept. 50:344/88:08 on 880214:0326.No violations noted. Major spected operational safety ventication,maint, survaillance & open Item follow-
- C., SUH,G.Y., MENDONCA,M.M. Roglon 5, Old of the Director, 88/04/07 237:079-45237.092.
- 18 Forwards Insp Rept 50-344/68-10 on 880314-18.No violations noted. MAN,R P. Region 5, Old of the Director. 88/04/07. CQCKFIELD Portland Electric Co. 2pp. 45231:320-45231.331.
- 048 Insp. Rept. 50:344/88-10 on 880314-18.No violations or deviations object areas inspected annual review of licensee program to handle into aview of procedures 8 onsite followup of written repts of non-routine events. A.D.B., MENDCCA,M.M. Region 5, Ofc of the Director. 88/04/07. 10pp. 22-45231:331.
- 4 Responds to request for additinfo re IE Bulletin 85:003. "Motor-Operated mmon Mode Falures During Plant Transients Due to Improper Switch Set-
- ELD,D.W. Portland General Electric Co. 88/04/08. MARTIN,J.B. Region 5, e Director. 4pp. 45218:280-45218:283.
- 0 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc
- E. Division of Operational Events Assessment (Post 870411). 88/04/12. ated Edison Co. of New York, Inc. 123pp. 45165-028-45165:150.
- i1 Confirms 880422 mgt meeting w/util in Portland, OR to discuss SALP reptial enforcement items, por 880415 telcon Agenda & meeting notification encl. OF. Region 6, Offic of the Director. 88/04/16. COCKFIELD, D.W. Portland Electric Co. 5pp. 45237:125-45237:129.

c operating reports & related correspondence

- 1 Monthly operating data rept for Mar 1988;W/880406 ltr. FJ, 0LMSTEAD,C.A. Portland General Electric Co. 88/03/31. 6pp. 7-45142.125
- 0 Forwards NPDES rept for Mar 1988 & supporting Info. D. Portland General Electric Co. 88/04/11. Oragon, Stale of. 2pp. 45231:275-
- "Monthly NPDES Data for Mar 1986,"
 Portland General Electric Co. 88/03/31, 12pp. 45231;277-45231;288.

ble occurrences, LERs & related correspondence

- 9 LER 87-026-01 on 870830 containment ventilation isolation occurred during ent pressure reduction.Caused by faulty noble gas monitor PRM-1C detector glithermittent noise Circuit card replaced.W/880407 ltr. J., OLMSTEAD,CA Portland General Electric Co. 88/04/07. 3pp. 27-45152:129.
- 9 LER 87-015-01:on 870413, discovered that 10 steam generator transmitters by califor. Caused by procedure deficiency. Transmitters properly recalibr within tolerance & califor data sheets revised W/880407 ltr.

 1. OLMSTEAD, C.A. Portland General Electric Co. BB/04/07. 4pp. 01-45184.004.

- 8804140169 LER 87-020-01 on 870803,monthly channel check of seismic monitoring in-strument not performed in Jul 1997.Caused by inadvertent deterior of surveillance from computerized surveillance schedule Surveillance performed.W/880407 ftr HINSON, OLMSTEAD,C.A Portland General Efectric Co. 88/04/07, 3pp. 45152;147-45152,149.
- 8804200257 LER 86-011-01.on 861114.reactor trip from spurious high vitration signal on main turbine Caused by loose wires in vibration probe junction box.Trip signal disabled Loose wiring lightened.W/880414 ltr. HINSONL., DLMSTEAD.C.A., Portland General Electric Co. 88/84/14. 5pp. 45221:052-45221:056

V. Operator Examinations

- 8804190145 Forwards SALP Rept 50-344/87-41 for Nov 1986 Nov 1987. Meeting to discuss rept planned for 880422.Expresses concern that problems expenenced during SALP period may be reflective of tack of understanding of util initiatives MARTIN.1B Reglon 5, Otc. of the Director 88/03/30. COCKFIELD.D.W. Portland General Electric Co. 3pp. 45197:662-45197:108.
- -8804190149 SALP Rept 50-344/87-41 for 861101-871130.
 * Region 5, Ofc of the Director, 87/11/30, 44pp, 45197,065-45197;108.
- 8804250088 Responds to FOIA request for info re-scores of reactor operators & sentor reactor operators Forwards requal fication exam summary source sheets fisted in onci app w/personal privacy into deleted GRIMSLEY,C.H. Division of Rules & Records (Post 870413), 88/04/19 BOLEY,K. Public Citizen's Citical Mass Energy Project. 2pp. 45213:003-45213:095
- --8804250167 Package of NRC administered requestrication exam results summary. NRC No Detailed Affiliation Given. 87/07/20 88pp. 45213:007-45213.095

DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8804150393 Revised emergency plan implementing procedures including Rev 1 to HS-EP-1500(EP-1500), "Emergency Classification," Rev 1 to HS-EP-1600(EP-1600), "Unique Event," Rev 1 to HS-EP-1600 (EP-1700), "Alert" & Rev 1 to HS-EP-1600(EP-1600), "Unique Event," Rev 1 to HS-EP-1600(EP-1600), "Unique Event," Rev 2 to HS-EP-1600(EP-1600), "Unique Event," Rev 2 to HS-EP-1600(EP-1600), "Unique Event," Rev 3 to HS-EP-1600(EP-1600), "Unique Event," Rev 4 to HS-EP-1600(EP-1600), "Unique Event," Rev 4 to HS-EP-1600(EP-1600), "Unique Event," Rev 5 to HS-EP-1600(EP-1600), "Unique E 1800) STORZ,L.F. Toledo Ed son Co. 87/02/04 700pp. 45124:117-45126:104.
- 8804220030 Rev I to "Development of Evacuation Time Estimates for Davis Besse Nuclear Power Station."
 * KLD Associates, Inc. KLD TR 190 R01. 87/11/10. 400pp. 45237:274-45238:252.
- 8804130262 Hevised emergency plan off normal occurrence procedures, including Rev 0 to HS-EP-02807, "Helipad Use & Control," Rev 0 to EP-4100, "Tornado," Rev 1 to HS-EP-02820, "Earthquake" & Rev 0 to EP-4300, "Flooding," WASILKJ.S. To'ado Edison Co. 88/04/08. 100pp. 45154:188-45154:328,
- 8804200538 Forwards Safety Insp Rept 50-346/88-02 on 880101-0215 & notice of violation.
 GUILDEMOND,W.G. Region 3, Old of the Director. 89/04/08, SHELTON,D. Toledo Edison Co. 2pp. 45238-259-45238:275.
- --8804200650 Insp Rept 50-346/88-02 on 800101-0215.Violations noted Major areas Inspected action on previous Insp Indings maint, operational safety serveillance performance annancement program, LER followup, security & onsite sarety, sorvertenice porteriors.

 followup of events.

 DEFAYETTE, H. Region 3, Ofc of the Director. 88/04/05. 14pp. 45238:262-45238:275.
- 8804270252 Forwards Rev 8 to Implementing Procedure AD 1808.16 (IS-AC-00516), "Unescorted Access Requirements" Note that screening program will change significantly in that facility will essentially parallel requirements of Rev 8A. SCHUMAKER.A F. Toledo Edison Co. 88/04/12. Region 3, Ofc of the Director. 2pp. 45242 323-45242:355.
- -8804270263 Rev 8 to Emergency Plan Implamenting Procedure AD 1808.16, "Unescrited Access Requirements."
 GRIN,G.M., STORZ Totedo Edison Co. 88/06/01. 31pp. 45242 325-45242 355.

H. General correspondence

8804270166 Requests removal of DH Hauser & addition of DE Burke to mailing list. BURKE, D.E. Cleveland Electric Illuminating Co. 88/04/21, NRC - No Detailed Affiliation Given. 1p. 45241:165-45241:165.

J. Insurance & Indomnity Information

8803300054 Submits list of util insurers policy numbers 8 coverage limits,per 10CF-R50.54(w)[4] reporting requirements. SHELTON,D.C. Toledo Edison Co. 88/03/23. Document Control Branch (Document Control Desk). 1p. 44945-214-44945.214.

P. Operating license stage documents & correspondence

- 8804070117 FOIA request for rept did 870901 re allegations about incident at plant on 861231 concerning ordering of plant manager back into plant after drinking at new yrs ave perly.

 MAXWELL,B. Cosmos Broadcasting Corp. 88/03/07. NRC - No Detailed Athilation Given 2pp. 45043-286-45043-287.
- 8803300365 Responds to NRC 880303 request for addl info re 870807 application to amend fech Specs 3/4.3 2 & 3/4.6 3. Amend to proposed removing closure time requirements for ten valves connected to secondary side of steam generators. SHELTON,D.C. Toledo Edison Co. 88/03/21. Document Control Branch (Document Control Dask), 3pp. 44982.125-44962:127.

- 8803240426 Generic Ltr 88 06 to all power reactor Leansees & applicants re removal of crean ration charts from Tech Spec administrative control requirements Svc list encl MIRAGLIAF J. Associate Director for Projects (Post 87041) 88/03/22 Consolidated Edison Co. of New York, Inc. 47pp. 44972 107-44972 IS3
- 8804080442 Forwards application to amend Licenso NPF-3,rev.s.ng License Condition 2 C.(3)(d), rc.Lusing Tech Spac 374.4.2, Figures 3.4.2.3.4.3.8, 3.4.4.1at/s 4.4.5.8 Tech Spac Bases Section 374.4.9.1.F gures 3.4.2.3.4.3.8, 3.4.4.1at/s 4.4.5.8 Tech Spac Bases Section 374.4.9. SHELTON,D.C. Toledo Edison Co. 88/03/30. Obcument Central Branch (Occument Control Desk), 2pp. 45076 046-45076.032
- -8804060449 Application for amend to License NPF-3,revising License Condition 2 C (3)(d),rickwising Toch Spec 374.4.2 Figures 3.4.2.8.20,Tech Spec 374.4.9.1,Figures 3.4.2.3.4.3.8.3.4.4.8.Table 4.4.5.8.Toch Spec Bases Section 374.4.9. SHELTON,D C Totedo Edison Co. 88703/33, 24pp. 45076.048-45076.071
- --8804060463 Proposed Tech Specs revising Tech Spec 3/4.42,Figures 3.4.2a & 25,Tech Spec 3/4.4.9 1.Figures 3.4.2.3.4.3.4.4. Table 4.4.5 & Tech Spec Bases Section 3/4.4.9 Bases Table 4.1.4.8 Bases 4.1.8.4.2
 * Toledo Edison Co. 88/03/30 21pp 450/6.072.450/76.002
- 8804080172 Forwards SSER NUREG-1231 re B&W Owners Group plant reassossment program Overall ovaluation remains tavorable. Additimprovement in area of integrated control syst pro-nuclear instrumentation syst roview poss by Wro end: CRUFCHFIELD. Division of Reactor Projects III.IV,V & Special Projects (Post 870411) 88/03/31 VILIGUS,VI.S Babcock & Wilcox Operating Plants Owners Group 7pp. 45076 181-45076;187
- 8804110144 Provides eddl info re MSIV stroke time requirements.gor NRC 880303 telcon request to assist in review of 870727 application for amend to License NPF-3 Amend would revise Tech Specs 374 2:374 6:3 8:374 7.1. SHELTCH,DC Teledio Edson Co. 88703/31. Document Control Desky 9pp. 45131:101-45131:109.
- 8804140193 Provides fisted into requested in 880225 ltr re operating nuclear power units located at two/ve sites along Great Lakes STELLO,V Oic of the Executive Orector for Operations, 88/04/06, RIDGE,T, House of Rep. 5pp.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 18CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Sergly for Nuclear Power Plants" Svc. Lst encl MIRAGLIAF J. Associate Director for Projects (Post 870411), 89/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164 237-45164:285.
- 8804210172 Forwards graphs & statistical plots of trends of performance indicators for plant from AECO rept. "Performance Indicators for Operating Commercial Nuclear Powor Reactors," per SECY:87-207.

 DE AGAZIO,A.W. Project Directorate IIII-3. 88/04/08. SHELTON,D.C. Toledo Edison Co. 22pp. 45191:287-45191:288.
- 8804200069 Notifies of plans to use instrumented insplicational steed including implementation over next 10 yrs for inservice inspiressure test program 8 taking credit for inservice valve testing SHELYON, 0.C. Totelde Edison Co. 88/04/11 Document Control Branch (Document Control Dest) 8pp. 45176 037-45176.060
- --8804200091 Submits recap of topics discussed during 870930 meeting w/ NRC in Betthesds,MO1 is instrumented risp techniques W/nind oversize figures. ASKWITH,HH, H, AF, A. Intl. Inc. 87/10/07 JOHNSCN,G NRC No Detailed Affiliation Given 14pp 45176.055-45176.060.
- 8804220131 Forwards application for amend to License NPF-9,adding Tech Spec 3/4.0.1.13 & bases stiction re-reflueling operations, & spentituel assembly storage & revising Tech Spoc 5.3.1 to fuel assembles & Tech Spec 5.6.1.2 re-critically-Fee pald SHELTON,D.C. Toleda Edison Co. 88/04/11. Document Control Branch (Cocument Control Desk). 1p. 45231.219.45231.274
- --8804220134 Application for amend to License NPF-3,adding Toch Spec & Bases 3/ 4.9.1.13 fer refueling operations, spent fuel pool assembly storage & revising Tech Spec 5.3.1 refuel assemblies & Tech Spec 5.6.1.2 to crucestry. SHELTON, D.C. To eto Edison Co. 08/04/11, 45pp. 45231:20-45231:264.
- --8804220136 Proposed Tech Specs, adding Tech Spec & Bases 3/4.9.1.13 re refueling operations, spent fuel pool assembly storage & revising Tech Spec 6.3.1 re fuel assembles & Tech Spec 5.6.1.2 re culcality.
 * Totalo Ecison Co. 86/04/11. 10pp. 45/211:265-45/231 274.
- 8804250148 Submits addl into re 880111 application for amend to Ucense NPF-3,revising Tech Spec 44.5.2. "Steam Generator Tube Sample Selection & Insp to Include Third Special Interest Group," per 880318 teleon request Supporting into enci. SHELTON, DC Tolledo Edison Co. 88704/14 Document Control Branch (Document Control Desk). 25pp. 45258:278.
- 8804250314 Confirms mgt meeting on 880418 in Glen Eilyn, IL to discuss various facility aspects, including status of reflueling outage GREENMAN, E.G. Region 3, Oto of the Director. 88/04/15. SHELTON, D. Toledo Edison Co. 2pp. 45239:180-45239:181.
- 8804260018 Notification of 880428 meeting w/whi in Oak Herbor,OH re technical dis-cussions concerning prant control cir. DE AGAZIO,A.W Project Directorate III-3, 89/04/18 PERKINS,K.E. Project Director-ate III-3, 3pp. 45232 252-45232 264.
- 8804280005 Forwards Rev 6 to USAR reflecting organization changes implemented between 880122-0422 re removal of 0-8 organization from Toch Specs in accordance w/Generic Lir 88-06 Annual update to be submitted in Jul 1988. SHELTON, DC Toledo Edison Co. 88/04/22. Document Control Branch (Document Control Desk). 21pp. 45251 049-45251:089.

O. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Trimble Tube Thinning In Westing-house Reactions" Svc 1st oncl. ROSSIC E. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995.128-44995.248.

- 8803220296 NRC Into Notice 88-010, "Malls Licensees.Lack of Mgt Controls Over Li-
- cansed Programs " Svc llst encl CUNKINGHAM, R. E. Orwson of Industrial & Medical Nuclear Satety (Post 870729). 897 03728 Consol dated Edison Co. of New York, Inc. 108pp. 44895:247-44895:333.
- 8804110160 Comments on CJ Papariello 880323 memo re insp of allegations at plants Significance of allegations low & do not warrant immediate review & closure KNOP,RIC Region 3, Ofc of the Director. 88/04/08. GREENMAN,R.G. NRC No Detailed Afficiation Green 2pp 45135:074-45135:075.
- 8804010256 NPC Into Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch board Function Due to Faulty Tie Botts," Svo list encl. ROSSICE. Division of Operational Events Assessment (Post 870411). 88/04/07 Consol
- 8804120395 Forwards Radiological Controls Team Insp Rept 50-346/88-08 on 880223-26 & 0307-11 No victations noted. SHAFER,W D. Rogion 3, Otc of the Director. 88/04/07, SHELTON,D. Tollodo Edison Co. 2pp 45129 064-45129 093.
- ~8804120400 Insp Rept 50-346/88-08 on 880223-26 & 0307-11.No violations or devialions noted Major areas inspected operational rediation protection, soful radwasto mgl 8 nonrediological chemistry programs including mgl controls 8 training MILLER, D.E., GRANT, W.B., HOLTZMAN, R.B. Region 3, Ofc of the Director 88/04/ 05 28pp. 45120,066-45129.093.
- 8804150429 Forwards util response to NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakers," Subjectival breakers not used at plant SHELTON,D.C. Toledo Edison Co. 88/04/08. Document Control Branch (Document Control Dosk) 2pp. 45138-199-45138-200.
- 8804200538 Forwards Safety Insp Rept 50-346/88-02 on 880101-0215 & notice of violation.
 GULDEMOND,W.G. Region 3, Ofc of the Director, 88/04/08. SHELTON,D. Toledo Edison Co. 2pp. 45238-259-45238-275.
- -8804200541 Notice of violation from insp on 880101-0215 Violation noted licenses did not restore selamic trigger to operability or submit special rept after discovering that selamic trigger did not have required range.

 GUIDEMOND,W.G. Region 3, Ofc of the Director. 88/04/05. 1p. 45238.261-45238:261
- -8804200550 Insp Rept 50:346/88:02 on 880101-0215 Violations noted Major areas inspected action on previousy insp findings,maint, operational safety, surveillance, performance enhancement program, LER followup, security & onsite followup of events. DEFAYETTE,R. Region 3, Old of the Director, 88/04/05, 14pp. 45238-262-45238-275.
- 8804200069 Notifies of plans to use instrumented insp techniques for applications Isladunci Juling implementation ovar next 10 yrs for inservice insp prossure test program & taking credit for inservice valve testing SHELTGN,D.C. Toledo Edison Co. 88/04/11. Document Control Branch (Document Control Dask), 8pp. 45178 037-45178 060.
- --8804200091 Submits recap of topics discussed during 970930 maeting w/ NRC in Bethosda,MD re instrumented inspitachniques.W/nine oversize figures. ASKWTH-H1: H1-R-A. Intl. Inc. 87/10/07. JOHNSON,G. NRC No Detailed Affination Given 14pp. 45176.055-45176:060.
- 8804060370 NRC into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45185,028-45185;150.
- 8804250148 Submits addl Info re 880111 application for amend to License NPF-3, revising Tech Spec 4.4.5.2, "Steam Generator Tube Sample Selection & Insp to Include Third Special Interest Group," por 880318 telcon request Supporting Into enci SHELTON.D.C. Toledo Edison Co. 88/04/14. Document Control Branch (Document Control Desk). 25pp. 45258:225-45258 279.

R. Periodic operating reports & related correspondence

- 8803290376 "Whole Body Exposures for CY87." W/880220 ltr. STORZ.L.F. Tolodo Edison Co. 87/12/31, 4pp. 44952 231-44952:234
- 8804250201 "Annual Environ Operating Rept 1987." W/880412 ltr. SHELTON,D.C. Toledo Edison Co. 87/12/31, 250pp. 45239.301-45241:078.
- 8804220044 Monthly operating rept for Mar 1988.W/880414 ltr. CIPRIANI,J., STORZ,L.F. Toledo Edison Co. 88/03/31. 6pp. 45216:186-45216:191.

S. Reportable occurrences, LERs & related correspondence

- 8804070205 LER 88-007-00:on 880304, discovered that air operated temp control valves for DHR HXs inoperable caused by air leakage from valve accumulator sys Valve CC1469 opened & operator manually engaged to hold valve open, WA80331 Hz. GORDON,C.S., STORZ,L.F. Toledo Edison Cu. 88/03/31. 4pp. 45072.258-45072:259.
- 8804180460 LER 68:008:00:00 a80312, discovered that nuclear safety- related (NSR) equipment located within fating arc distance of nonsolamic electrical panel Potential for panels to fall 8 impact NSR equipment everlooked.
- 8804250086 LER 88-004-01:on 880120 hourly lire watch intentionally missed due to pre-carillonary evacuation of radiological control area (RCA)-Hourly fire watch patrols re-sumed upon galining access to RCA,W/880414 lfr. STOTZ,J., STORZ,L.F. Toledo Edison Co. 88/04/14, 3pp. 45239:207-45239:209.
- 8804200311 LER 88-005-01:on 880121, Inoperable fire barrier w/Inoperable fire detection discovered. Caused by procedural inadequacles. Procedures revised to require more thorough review of design package prior to implementation W/880415 ltr. STOT2, J.C. Toledo Edison Co. 88/04/15. Spp. 45235:172-45235:178.

125

V. Operator Examinations

8804060308 Certifies that plant operator training programs accredited by INPO & use sys approach to training SHELTON,D.C. Toledo Edison Co. 88/03/29 Document Control Branch (Document

Control Desk). 1p. 45073.342-45073.342

8804110326 Advises that operator & sonlor operator exams scheduled for week of 880828.Encl listed ref malt requested 60 days prior to exam date.

WRIGHT.G.C. Region 3, Ofc of the Director. 88/04/08. SHELTON,D. Toledo Edison Co. 10pp. 45123 310-45123 310.

DOCKET 50-348 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8803250263 Forwards Insp Repte 50-348/88-06 & 50-384/88-06 on 880229- 0304 & notice of violation.

 COLLINS,D.M. Region 2, Ofc of the Director 88/03/18 MCDCNALD,H.P. Afabama
 Power Co. 2pp. 44920,001-44920,013.
- -8803250265 Notice of violation from insp on 880228-0304-Violation noted personnel designated as operations shift side, appointed by interim emergency director, did not receive required enual rotalning for communications personnel.

 COLUNS,D.M. Region 2, Old of the Director. 88/03/18. 2pp. 44920.003-44920.004.
- --8803250266 Insp Repts 50-348/86.00 & 50-364/88.00 on 680220-0304 Violutions noted Major areas inspected operational readiness of site omergency preparedness program & to determine if changes to emurgency preparedness maet NRC requiremonts GOODEN,A , DECKER,T.R. Region 2, Ofc of the Director 88/03/16. 9pp 44920 005-44920.013
- 8803300029 Rovised emergency plan implementing procedures.including Rev 18 to FNP-0-EIP-10, "Evacuation & Personnul Accountability," Rev 19 to FNP-0-EIP-16, "Emergency Equipment & Supplies" & Rev 54 to FNP-0-EIP-8, "Emergency." W/860322 tr. HUDSPETH, J.B. Alabama Power Co. 88/03/22, 200pp. 44966 354-44967,237
- 8804070039 Advisos that GO-EIP-121 being volded All Items in procedure incorporated into Rev 6 of GO-EIP-118, "CCD Corporato Activation & Notification Procedures." HARRIS,R. Alabama Power Co. 88/03/24. Region 2, Otc of the Director. Ip. 45022:128-45022:128
- 8804070285 General Otc Emergency Implementing Procedure GO-EIP-112, "Emergency Mobile Communications." W/880324 lfr.
 MCGOWAN J.W., HARRIS,R. Alabama Power Co. 88/03/24. 11pp. 45021:173-
- 8804060262 Forwards Insp Ropts 50-348/88-07 & 50-384/88-07 on 880211-0310 No violations or deviations noted.

 VERELLI,D.M. Region 2, Old of the Director. 88/03/28. MCDONALD,R.P. Alabama
 Power Co. 2pp. 45048:126-45048:132.
- ~8804060267 Insp Ropts 50-348/88-07 & 50-364/98-07 on 980211-0310 No violations or devetions noted Major gross inspected review of monthly surveillance & maint observations, redological protection program & physical security program. BRADFORD,W.H., MILLER,W.H., DANCE,H.C. Region 2, Ofc of the Director. 88/03/28. 6pp. 45048;127-45048:132.
- 8804200057 Roy 12 to Emergency Plan Implementing Procedure FNP-O-EIP-15, "Emergency Dulls " WOODARD,J.D. Alabama Power Co. 88/03/29, 9pp. 45228:262-45228:270
- 8804080085 Responds to DM Collins 880219 ltr re FEMA analysis of prompt aloit & notification sys for facility.Defalls of util roviow of FEMA ltr & questions re FEMA survoy encl.
 MCDONALD.R.P. Alabama Power Co. 88/03/31. Document Control Branch (Document Control Dask), 28pp. 45088:270-45008-304.
- 8804140093 Forwards Rev 8 to GO-EIP-122, "Emergency Mobile Communications," per EQ Reevos 870921 ftr.
 MCCRACKEN,K.W. Alabama Power Co. 88/03/31. Document Control Branch (Document Control Desk). 1p. 45169.331-45160:340.
- 8804110121 Responds to violations noted in Insp Repts 50-348/88-08 & 50-304/88-06 Corrective actions:assessment will be made to ensure that training defined for all personnel w/responsibilities under emergency plan.
 MCDONALD,R.P. Alabama Power Co. 88/04/04 Document Control Branch (Document Control Desk), 2pp. 45135:080-45135.091.
- 8804110134 Forwards Rov 15 to securily plan Rev withhold MCDONALD,R.P. Alabama Power Co. 88/04/05. Document Control Branch (Document Control Desk). 1p. 45129:226-45129.228.
- 8804130255 Rev 20 to Emergency Plan Implementing Procedure FNP-0-EIP-16, "Emergency Equipment & Supplies." Alabama Power Co. 68/04/07, 85pp. 45137.018-45137:103
- 8804270061 Revised emergency plan implementing procedures including Rev 6 to GO-EIP-101, "Corporate Emergency Organization" & Rev 3 to GO-EIP-137, "Siren Sys Testing & Maint." W/880411 ltr.
- Testing & Maint." W/880411 ltr. HARRIS,R. Alabama Power Co. 88/04/11. 29pp 45241:174-45241:202
- 8604200043 Forwards reprinted Rev 8 to Emergency Plan Implementing Procedure GO-EIP-112, "Emergency Mobile Communications." Procedure transmitted as uncon-trolled per EA Reeves 870821 ltr. MCCRACKEN,K.W. Alabama Power Co. 88/04/12. Document Control Branch (Docu-ment Control Desk), 1p. 45231:072-45231-081.
- --8804200046 Reprinted uncontrolled Rev 8 to Emergency Plan Implementing Procedure, GO-EIP-112, "Emergency Mobile Communications." MCGOWEN, J.W. Alabama Power Co. 88/03/23, 9pp. 45231:073-45231:081.

- 8804200473 Partial response to FOIA request re line protection Forwards App E documents App D & E documents available in PDR App F document completely withheld (ref FOIA Exemption 5)
 GRIMSLEY, D11. Division of Rules & Records (Post 870413). 88/04/14. JONES.C R
 Allikation Not Assigned 5pp 45206 037-45206 043
- -8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type inspired sech facility to assess status of compliance w/ 10CFR50 48 Program Isted CONLCN,T E Region 2, Otc of the Director 3pp 45206:178-45208:178.
- 8904270296 Rov 5 to Genoral Otc Emorgency Implementing Procedure GOP-EIP-116, "Emorgency Operations Facility Shift Turnover," W/880414 ltr. MCGOWAN,J.K., HARRIS,R. Alabama Power Co. 89/04/14, 32pp. 45242 291-45242 322
- 8804250128 Revised emergency plan implementing procedures including Rev 5 to GO-EIP-116, "Emergency Operations Facility Shift Tunover" & Rev 6 to GO-EIP-101, "Corporate Emergency Organization." W/880415 ffr. MCCRACKEN.K W Alabama Power Co 88/04/15 57pp 45239:123-45239 179.
- 8804260024 Forwards Insp Repts 50-348/88-09 & 50-364/88-09 & notice of violation CLINE,W.E. Region 2, Ofc of the Director 88/04/19 MCDONALD.R.P. Alabama Power Co 2pp. 45318.148 45318:152
- -8804260029 Notice of violation from Inspiron 880321-24. Violation noted cabinet containing safeguards into insecure 8 unattended CLINE, W.E. Region 2, Old of the Oirector, 88/04/19, 2pp. 45318-150-45318-151.
- --8804260034 Partially withheld Insp Rupts 50-348/88-09 & 50-384/88-09 on 880321-24 (rof 10CFR2.790 & 73.21). Violation includ Major areas Inspected security organization, records, ropts, tosting, imaint, locks, keys, combinations & physical barriors THOMPSON, D.H., MCGUIRE, D.R., Rogion 2, Ofci of the Director, 88/04/13, 1p 45318:152-45318 152.

J. Insurance & Indemnity Information

8804110147 Submits verification of property insurance coverage per 10CFR50.54 w(2) nuclear property insurance reporting requirement MCDONALD,R P. Alabama Power Co. 88/04/01 WOOD,R. NRC - No Detailed Affiliation Given. 1p. 46077.339-45077.339.

M. Antitrust correspondence

- 8804110284 Not-lication of 680406 meeting w/util in Rocky l'e,MD to discuss 2 206 patrillon antitrust sottoment lissuss.

 REEVES,E A Project Directorate II-1. 88/04/05. MURLEY,T., SNIEZEK,J., MIRAGLIA,F. NRC No Data led Alfillat on Given. 2pp. 45079.092-45079 093.
- 8804130301 Summary of 880408 meeting w/ufl & Alabama Electric Powor Cooperative in Rockwille,MD to status of settlement proposal presented to NRC in Jan 1989,per 2 208 antitiust proceeding. List of attendees encl.

 LAMBE,W M. Policy Development & Technical Support Branch (Post 870411), 887047
 88. THOMASCO. Policy Development & Technical Support Branch (Post 870411), 2pp. 45101:238-45101:239.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88-05 to all power reactor licensees & applicants re removal of organization charts from Tech Spac administrative control requirements Svc list encl. MIDAGLIA,F.J. Associate Director for Projects (Post 870411) B8/03/22. Consolidated Ed son Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804010194 Summary of 880318 moeling w/utifa in Rockvillo,MD re into that would be required in submittal of amends to Icenses & CP hold by utils Attendees list & viewgraphs and. ADENSAMEG Project Directorate II-1 88/03/25 Project Directorate II-1, 25pp. 44020.082-44920.108
- 8804040178 Requests relief from requirements of second 10-yr interval Inservice testing program for ASME Class 1.2 & 3 pumps & valves to enable use of valve disassembly & Installetian of instrumental on as acceptable lost alternatives. MCDONALD.R.P. Alabame Power Co. 88/03/29. Document Control Branch (Document Control Desk), 21pp. 44969-280-44909-300.
- 8804110277 Forwards list of valves inside containment w/equironmentally qualified NAMCO EA-180 km,t switches which utlike Raychem/ CHICO seals,per 860401 teleon.Connectors will be replaced before startup for Unit 1 & during next outage for MCDONALD,R P. Alabama Power Co. 88/04/04. GRACE,J.N. Region 2, Ofc of the

- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-lorcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list ericl. MIRAGLTA,F.J. Associate Director for Projects (Pagt 870411) 88/04/07, Consnictated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804 150 168 Discusses 680318 meeting w/util re proposal to form operating company to hand's operation of subl prants. Summary of meeting issued soperatoly. ADENSAM.E.G. Project Directorate 11-1, 88/04/08, LONG,L.B. Southern Company Services, Inc., 18pp., 45141:185-45141:203.

Q. Inspection reports, IE Bulletins & correspondence

8803250263 Forwards Insp Repts 50-348/88-08 & 50-364/88-08 on 880229- 0304 & notice of violation COLLINS.D.M. Region 2, Ofc of the Director, 88/03/18, MCDONALD.R.P. Alabama Power Co. 2pp. 44920.001-44920.013.

- -8803250265 Notice of violation from inspirent 880229 0304 Violation incled personnel designated as operations shift aide, appointed by interim emergency director, did not receive required annual retraining for communications personnel COLLINS, D.M. Region 2, Otc of the Director, 88703/18 2pp. 44920 003-44920,004.
- -8803250266 Insp. Repts 50-348/88-06 & 50-364/88-06 on 880229-0304. Violations noted Major areas inspected operational readness of site emergency preparedness program & to determine if changes to emergency preparedness meet NRC require-GOODEN_A DECKER, T.R. Region 2, Ofc of the Director, 88/03/16, 9pp. 44920.005-
- 8804060094 Ack receipt of 880316 ftr informing NRC of steps taken to correct violations noted in Insp Repts 50-348/87:35 & 50-364/87:35.

 JULIAN.C.A. Region 2, Otc of the Oirector. 88/03/25. MCDONALD,R.P. Alabama Power Co. 1p. 45007:296-45007.296

44920.013

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Wosling-house Reactors" Svc list encl. ADSSLCE. Division of Operational Events Assessment (Post 870411): 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995.246.
- 8803220296 NRC Info Notice 88-010, "Mails Licensees Lack of MgI Controls Over Li-censed Programs," Svc list enc! CUNNINGHAM,R E Dritsion of Industrial 8 Medical Nuclear Safety (Post 870729) 88/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995/247-44995/353.
- 8804060262 Forwards Insp Repts 50:348/88-07 & 50:364/88-07 on 880211-0310 No violations or deviations noted: VERELLI,D.M. Region 2, Ofc of the Director, 86/03/28 MCDONALD,R.P. Alahama Power Co. 2pp. 45048:125-45048 132.
- -8804060267 Insp Ropts 50-348/88-07 & 50-364/88-07 on 880211-0310 No violations or deviations noted Major areas inspected:review of monthly surveillance & maint observations;radiological protection program & physical security program. BRADFORDW.H., MILLERW.H., DANCE,H.C. Region 2, Ofc of the Director, 88/03/28, 6pp. 45048:127-45048.132.
- 8804040093 Revised response to violations noted in Insp Repts 50-348/87-29 & 50-364/87-29-Corrective actions:procedure implemented to provide documentation of compliance w/Tech Spec action requirements involving radiation monitors MCDONALD.R.P. Alabama Power Co. 88/03/29. Document Control Branch (Occument Control Desk). 2pp. 44971;289-44971;290.
- 8804050154 Grants revised interim approval for reliefs for inservice testing program for second 10 yr interval until NRC final action & safety evaluation issued Agrees that remaining two valves do not need to be included in subj program. ADENSAME G. Project Directorate II-1, 88/03/30, MCDONALD,R.P. Alabama Power Co. 3pp. 44997:051-44997:050.
- 8804080094 Responds to NRC Bulletin 88:001 re defects in Westinghouse circuit breakers Ingo of all Westinghouse DS-415 reactor trip 8 bypass breakers completed on 680308 & results encl.

 MCDONALD,R.P. Alabama Power Co 88/04/04. Document Control Branch (Document Control Desk), 3pp. 45116:273-45116:275.
- 8804110121 Responds to violations noted in Insp. Repts 50:348/88-06 & 50:364/88-06 Corrective actions assessment will be made to ensure that training defined for all personnel wiresponsibilities under emergency plan MCDONALO,R.P. Alabama Power Co. 88/04/04. Document Control Branch (Occument Control Desk). 2pp. 45135.080-45135:081.
- 8804140001 Responds to viotations noted in Insp. Repts 50:348/88-02 & 50:364/88-02.Corrective actions two workers & foreman restricted from further radiation work pending counseling & retraining.

 MCOONALD,R.P. Alabama Power Co. 88/04/06. Document Control Branch (Document Control Desk) 5pp. 45147:327-45147:331.
- 8804140005 Forwards list of exceptions & positions taken by util during 880217 enforcement conference re Insp. Repts. 50-348/68-02. & 50-364/68-02. Submittal not in response to 880310 notice of violation. MCDONALD,R.P., Alabama. Power. Co. 88/04/06. Document Control Branch (Document Control Oesk). 3pp. 46155-028-45155.030.
- 8804010256 NRC Into Notice 88:011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Botts " Svc list encl. ROSSI, C F. Division of Operational Events Assessment (Post 970411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp 45406:292-45407.051.
- 8804150154 Ack receipt of 880321 ftr Informing NRC of steps taken to correct violations noted in Insp Repts 50:348/88-03 & 50:364/88-03.
 VERRELLI,D.M. Region 2, Ofc. of the Director, 88/04/07, MCDONALD,R P. Alabama Power Co. 1p. 45131:322-45131:322.
- 8804150289 Forwards Insp. Repts 50-348/88-01 & 50-364/88-01 on 860104-07 No vio-lations or deviations noted. Rept also details findings of Repts 50-348/88-05 & 60-364/86-05 which initially reviewed many allogations. STOHR.J.P. Region 2, Otc of the Director, 68/04/07, MCDONALD, R.P. Alabama Power Co. 2pp. 45183:135-45183:179
- ~8804150299 Insp Repts 50-348/88-01 & 50-364/88-01 on 880104-07.No violations or deviations noted Major areas inspected, allegations re facility. STOODART,P.G., GŁOERSEN,W.B., KAHLEJ,B. Region 2, Ofc of the Director, 88/03/31, 43pp. 45183,137-45183,179.
- 8804150411 Forwards corrected cover lit for Insp Repts 50-348/88-07 & 50-364/88-07 on 880211-0310 Lit dtd 880328 incorrectly listed notice of violation due to administra-
- the oversight.
 VERRELLI,D.M. Region 2, Ofc of the Director, 88/04/07, MCDONALD,R P. Alabama
 Power Co 2pp, 45138 330-45138 333.
- -8804150425 Corrected Its forwarding Insp. Repts 50:348/88:07 & 50:364/88:07 on 880211-0310 No violations of deviations identified.

 VERRELLI,D.M. Region 2, Oto of the Director, 88/04/07, MCDONALD,R.P. Alabama Power Co., 2pp. 45138 332-45138 333.
- 8804150303 Ack receipt of 880329 ftr informing NRC of steps taken to correct violations noted in Insp Repts 50-388/87-29 & 50-364/87-29. VERRELLI,D.M. Region 2, Ofc of the Director. 88/04/06, MCDONALD,R.P. Alabama Power Co. 1p. 45138 284-45136:284

- 8804060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Rearings." Svc HOSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150
- 8804210474 Forwards summary of 880315 enforcement conference re environ qualifica-tion of electrical equipment at facility. List of attendees & handouts also enci GRACE, N. Region 2, Otc of the Director. 88/04/13. MCDONALD,R.P. Alabama Power Co. 54pp. 45227:137-45227.183.
- 8804200473 Partial response to FOIA request re fire protection Forwards Acp E documents. App D & E documents available in PDR App F document completely with held (rof FOIA Exemption 6).
 GRIMSEEY, D.H. Division of Rules & Records (Post 870413). 88/04/14. JONES, C R Affiliation Not Assigned. 5pp. 45208.037.45208:043.
- -8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type Insp for each facility to assess status of compliance w/ 10CFR50,40Program listed.
 CONLON,T.E. Region 2, Oic of the Director, 84/11/06. HERDT,A R. Region 2, Oic of the Director, 3pp. 45206.178-45208.178.
- 8804280024 Forwards Insp Repts 50:348/88-09 & 50:364/88-09 & notice of violation CLINE,W.E. Region 2, Oic of the Director. 66/04/19. MCDONALD,R.P. Alabama Power Co. 2pp. 45318:148-45318:152
- --8804260029 Notice of violation from Insp on 880321-24. Violation noted: cabinet containing saleguards into insocure & unattended.

 GLINE, W.E. Region 2, Oic of the Director. 88/04/19. 2pp. 45318:150-45318:151.
- -8804260034 Partially withheld lnsp Repts 50-346/88-09 & 50-364/88-09 on 880321-24 (ref 10CFR2.790 & 73.21) Violation noted Major areas inspected security organization records repts tosting, maint locks, keys, combinations & physical barriers THOMPSON,D.H., MCGUIRE,D.R. Region 2, Ofc of the Director, 88/04/13, 1p. 45318:152-45318:152.
- 8804280200 Forwards "Testing of 11 Bolts" & requests addition or chemical analysis & mechanical testing of bolts samples obtained during insp Repts 50-348/87-11 & 50-364/87-11 on 870511-22 including results of raview of test data.

 REEVES.A. Project Directorate 11-1. 88/04/21. MCDONALD,R.P. Alabama Power Co. 3pp. 45276:309-45276:340.
- --8804280217 "Testing of 11 Boits." CZAJKOWSKI,C. Brookhayen National Laboratory, 87/10/30, 29pp. 45276.312-45276:340
- 8804290278 Ack receipt of 880406 fir informing NRC of steps taken to correct violations noted in Insp Repts 50:348788-02 & 60:364788-02 GRACE,J.N. Region 2, Oic of the Director. 88/04/22. MCDONALD,R.P. Alabama Power Co. 1p. 45282:171-45282:171,
- R. Periodic operating reports & related correspondence
- 8804110337 "JM Farley Nuclear Plant, Unit 1 Annual Rept," for 1987.W/ 880331 ltr. MCDONALD,R.P. Alabama Power Co. 87/12/31, 25pp. 45077:289-45077:299.
- 8804190144 Monthly operating rept for Mar 1968.W/860411 ltr. WOODARD,J.D., MCDONALD,R.P. Alabama Power Co. 88/03/31. 9pp. 45209.208-45209:216.
- S. Reportable occurrences, LERs & related correspondence
- 8804060324 LER 88-008-00:on 880301,potential inoperability of Train A charging pump noted due to gas accumulation supply line. Caused by plping configuration. Hydrogen vented from plping & periodio venting program initiated. W/880331 ltr. WOODARD, J.D., MCDONALD, R.P. Alabama Power Co. 88/03/31. 10pp. 45048 087-45048.086.
- 8804080198 LER 88-007-00:on 680306,both 1A & 1B battery were inoperable for 19 minutes & Tech Spec 3.0.3 entered Caused by ladure of 1B battery charger white swing charger 1C aligned to 1A battery, Failed parts replaced, W/880404 ltr. WOODARO, J.D., MCDONALD,R.P., Alabama Power Co. 88/04/04. 4pp. 45098:178-
- 8804290298 LER 88-006-01:on 880301, determined that hydrogen accumulating in supply line from RHR pump. Caused by piping configuration in layout of train supply tine A. Hydrogen vented from piping. Perfodic program initiated. W/860426 ltr. WOODARD, J.D., MCDONALD, R.P. Alabama Power Co. 88/04/25. 11pp. 45283 080-45283 090

V. Operator Examinations

- 8804250088 Responds to FOIA request for into re-scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in enclusive w/personal privacy into deleted.

 GRIMSLEY,O.H. Division of Rules & Records (Post 870413), 88/04/19. BOLEY,K Public Citizen's Critical Mass Energy Project. 2pp. 45213:003-45213.095.
- --8804250167 Package of NRC administered requalification exam results summary. NRC No Detalled Affiliation Given. 87/07/20, 68pp. 45213:007-45213:095.

DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

- F. Security, medical, emergency & tire protection plans
- 8804040068 Forwards public version of revised emergency plan implementing procedures including Rev 4 to Procedure EP-254, "Vehicle & Evacuee Control Group & Rev 3 to Procedure EP-255, "Vehicle Decontamination." W/880329 release memo. GALLAGHER,J.W. Philagelphila Eleotric Co. 88/03/17, Document Control Branch (Document Control Desk). 5pp. 45009:001-45009.049.

- —8804040075 Public version of revised emergency plan implementing procedures,including flev 4 to Procedure EP-254, "Vahicle & Evacuee Control Group," Rev 3 to EP-255, "Vehicle Decontamination" & Roy 14 to EP-291, "Staffing." ing 177 * Philadelphia Electric Co. 88/03/17, 44pp, 45009.006-45009.049
- 8 604060204 Forwards Amend 89 to license application, revising fire protection evaluation rept by making various changes to accurately reflect facility sys,including mods & providing partial description of plant fire protection. BRADLEY,E.J. Philadelph a Electric Co. 86704705. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 1p. 45062.293-45063.099.

—8804060210 Amend 89 to Leense application,rovising fire protection evaluation rept by making various changes to accurately reflect facility sys,including mods & providing partial description of protection features MCREILL,CA Philadelphia Electric Co. 88704704, 4pp. 45082:294-45062:297.

- -- 8804060239 Rev 10 to "Limonick Generating Station Units 1 & 2 Fire Protection Evaluation Rept."
 * Philadelphia Electric Co. 88/04/05, 162pp. 45062.298-45063.099.

G. Adjudicatory correspondence

- 8-804050116 Forwards 880311 memorandum from Chief Administrative Judge BP Cotter.Compliance w/instructions contained in memorandum requested.Served on
 - WOLFE,S.J. Atomic Safety and Licensing Board Panel, #289 5984, 68/03/30. Atomic Safety and Licensing Board Panel. 2pp. 44968:144-44966.145.
- 8 804060044 Licensee response to order of 880317 requesting clarifying into,* Clarifying into needed to decide parties submissions on licensee motion for summary disposition
 - CONNER,T.B., WETTERHAHN,M.J. Philadelphia Electric Co. CONNER,T.B. Connor & Wetterhahn. #288 6009 88/03/31. Atomic Salety and Licensing Board Panel. 1p. 44983.030 44983.039.
- -- 8804060079 Affidavit of JS Wiley." Responds to six questions raised by ASLB dtd 880317 ra "iodino spike." Certificate of Svc enct. WiLEY,J.S. Philadelphia Electric Co. 88703729, 9pp. 44993-031-44993:039.
- 8 804110030 Response of NRC Staff to Board 880317 order requesting clarifying Info.*
 RJ Clark affidavitanswering tive questions in ASLB 880317 order encl.
 WEISMANR M. Assistant General Courset for Enforcement. #288 6018. 1p 45049 258 45049 276
- --8804110035 Aftidavit of RJ Clark in response to ASLB 880317 questions.* Provides NRR answers to first tive questions in ASLB 880317 order.Question 8 left for I consequence answer W/Certificate of Svc. CLARK,RJ, Qffice of Nuclear Reactor Regulation, Director (Post 970411), 88/04/04.
 - 18pp. 45049:259-45049:276.
- 8.804180024 Submits updated info re licensee 880331 response to ASLB 860317 order re peak value for lodine concentration in primary reactor coolant for second fuel cycle.lodine values for 880401 & 08 stated.

 WETTERHAHINAJ Philadelphia Electric Co. WETTERHAHN,M.J. Conner & Wetterhahn. #286 6059. 88704708. WQLFE,S.J., FERGUSON,G.A., COLE,R.F. Atomic Sefety and Licensing Board Panol. 1p. 45128 028.4\$128 028.
- 8804290110 Response of Intervenor RL Anthony to PECO 880331 response & NRC Stall 880404. Donial of applicant motion for summary disposition & application for
 - ANTHONY,R L. Anthony, R.L. #288 6155. 88/04/25. Atom'c Safety and Licensing Board Panel. 2pp. 45255:143-45255:144

\$4. General correspondence

8804070271 Requests that JS Kemper be added to carbon copy list for Limerick correspondence Kemper title incorrectly identified in author 880328 fir to WT Russell & should be corrected to read "Senior Vice President Nuclear." MCNEILL, C.A. Philadelphia Electric Co. 88/03/30. RUSSELL, W.T. Region 1, Old of the Director. 1p. 45029 266: 45029:266.

1. Financial information

- 8603310075 Forwards "Philadelphia Electric Co. Annual Rept for 1987."
 BRADLEY,E.J. Philadelphia Electric Co. 88/03/28. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 1p. 44984.041-44984:041.
- J. Insurance & Indemnity Information
- 8804130145 Forwards Endorsement 24 to NELIA Policy NF-284 & Endorsement 18 to MAELU Policy MF-113, BRADLEY,E J. Philadelphia Electric Co. 88/04/07, DINITZ,I, NRC - No Detailed Affilia ation Given 5pp. 45099:284-45099:288.
- 8894190387 Forwards Endorsement 12 to NELIA Policy 1 & Endorsement 3 to MAELU Policy 1. BRADLEY.E J. Phriadolphia Efectric Co. 88/04/08. DINITZ,I. NRC - No Detailed Affiration Given 5pp 45164:188-45164:172.
- P. Operating license stage documents & correspondence
- 8803240426 Generic Ltr 88-06 to all power reactor I censees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc 1st encl MIRAGLIA.F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972;107-44972.153.
- 8804040104 Forwards Rev 5 to offsite dose calculation manual.per 871123 request Rev addresses all but three discrepancies noted in technical evaluation rept. Discrepancies not addressed, restated followed by util response.
 GALLAGHER, J.W. Philadelphia Electric Co. 88/03/30. CLARK, R.J. Project Directorate
 1-2. 3pp. 44970.096-44970:229.

- --8804040108 Rev 5 to 1 Offsite Dose Calculation Manual " ** Philadelphia Electric Co. 88703730, 131pp. 44970.009.44970 229
- 8804060204 Forwards Amend 89 to I cense application revising the protection evaluation ropt by making various changes to inccurately reflect facility systectiong mode & providing partial description of plant fire protection BRADLEY.E.J. Philadelphia Efection Co. 68704705 MURLEY.F.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 1p. 45062:293 45063 099

- --8804060210 Amend 89 to 'icense app! cation,revising fire protection evaluation rept by making various changes to accurately reflect facility systincturing mods 8 providing partial description of plant fire protection features MCNEILL,C.A Philadelphia Electric Co. 88/04/04. 4pp. 45062:294-45082:297
- -8804060239 Roy 10 to "Limerick Generating Station Units 1 & 2 Fire Protection Evaluallon Rept."
 * Phradalphia Electric Co. 88/04/05, 162pp. 45062 238-45063 099
- 8804130357 Advises that temporary waiver of compliance not issued in conjunction w/ emergency licensing amend granted for plants for first time,per guidance from HR Denton 070227 memo. Twelvo waivers have been issued since Shoty rule in effect STELLO,V. Ofc of the Executive Director for Operations. 88704706. HOBERTS,T M. Commissioners. 2pp. 45117-016-45117;017.
- 8804080088 Generic Ltr 88-07 to power reactor ficonsees & applicants re-modified en-forcement policy concerning 10CFR50-49, "Environ Qualitication of Electrical Equip-ment Important to Safety for Nuclear Power Plants" Svc 1st enct MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 15164:237-45164:285.

Q. Inspection reports, IE Bulletins & correspondence

- 8804010144 Advises that luture correspondence to linsp & enforcement should be ad-dressed to CA McNeil,Executive Vice President-Nuclear. MCNEILL, CA Philadelphia Electric Co. 88/03/25, RUSSELL,W.T. Region 1, Otc of the Director, 1p. 45020 016-45020 016
- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Trimble Tube Thinning in Westing-house Reactors," Swc 1st enci. ROSSI,C E Division of Operational Events Assessment (Post 870411) 88/03/28 Consol dated Edison Co. of New York, Inc. 121pp. 44995:126-44995.246.
- 8803220298 NRC Into Notice 68 010, "Mails Licensees Lack of Mgt Controls Over Liconsed Programs." Svc list end: CUNNINGHAM,R E Division of Industriat & Medical Nuclea: Safety (Post 870729) 88/ 03/28. Consol dated Edison Co. of New York, Inc. 108pp 44995 247-44995 353.
- 8804070337 Requests addition needed to ovaluate valve operability considerations in accordance with 8u leth 85.003, "Motor Operated Valve Common Mode Faltures During Plant Transloats Due To Impropor Switch Sollings" WENZINGER.E.C. Region 1, Oic of the Director. 88/03/29, KEMPER, J.S. Philadelphia Electric Co. 5pp. 45021:249-45021.253.
- 8804110098 Responds to NRC 880304 ltr re violations noted in Insp Rept 50:352/88-01. Corrective actions:nuclear OA organization assigned responsibility for performance of future 1007FR50.64(f) reviews & distribution GALLAGHER,JW. Philadelphina Efectric Co. 88/04/04. BELLAMY,R R. Region 1, Ofe of the Director, 4pp. 45135:273-45135.276.
- 8804130182 Ack receipt of 880311 ftrs amending util 880225 & 26 ltrs Informing NRC of steps taken to correct violations noted in Insp. Repts 50:277/87:37,50:278/87:37 & 50:352/87:20.

BELLAMY, R.R. Region 1, Old of the Director, 88/04/04, KEMPER, J.S. Philadelphia, Electric Co. 2pp. 45154,099-45154;111.

- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Cir &/or Switch-board Function Due to Faulty Tie Beits." Svollist enct. RGSSI, C.E. Division of Opportational Events Assessment (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051,
- 8804150230 Responds to 880205 NRC Bulletin 88 01 re delocts in Westinghouse circuit broakers for facilities. Westinghouse DS series circuit breakers not used at plants Other provisions of bulletin do not apply to plants.

 KOWALSKI,SJ. Philadelph & Electric Co. 88/04/08, RUSSELL,W T. Region 1, Otc of the Director. 2pp. 45138 028-45138 029.
- 8804060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl. ROSSI, C.E., Division of Operational Events Assessment (Post 870411), 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165028-45165.160.

R. Periodic operating reports & related correspondence

- 8804190153 Monthly operating rept for Mar 1988.W/880415 ftr. GROPP,R.W., ALDEN,W.M. Philadelphia Electric Co. 88/03/31, 6pp. 45209 040-45209.045.
- S. Reportable occurrences, LERs & related correspondence
- 8803280104 LER 88:005:00 on 880218 determined one of four reactor coolant leakage monitoring sys inoperable in violation of Tech Spec 34.3.1 Investigation continuing Wring restored to as built continuin 8 sys declared operable W/860318 lin. MENGERS,C.A., LOGUE,R.H. Philadelptra Electric Co. 88/03/18. Spp. 44915:164-44915:168
- 8804060035 LER 88:006-00:on 880229, fire protection sys required by Tech Specs de-clared administratively inoperable. Caused by design deficiency. Frewarch posted 8 addl. fire hoses made available in area of inoperable water curtains W/880330 ltr. MENGERS, CA, LOGUE, RH. Philadelphia Electric Co. 88/03/30. Spp. 45048 069-45048.073

- 8804080031 LER 87:057:01.on 87:1017.false control room high radiation signal imitiated during troubleshooting of faired check source alarm Caused by inadequate technician instruction Issue discussed at technician training course W/8803031 ftr. MENGERS.C.A. LOGUER H. Philadelphia Etectine Co. 88/03/31. 5pp. 45092.111-45092.115
- 804080147 LER 85-027-01:on 850225, spurious isolation of RWCU sys occurred Caused by trip signal generated by important voltage spike RWCU isolation reset 8 returned to svc W/860406 ftr.

 MENGERS.C.A. LOGUE,R.H. Philadelphia Electric Co. 88/04/06. 5pp. 45092 184-8804080147
- 8804080151 LER 85-035-01 on 850323,isolation of reactor water cleanup sys occurred Caused by tip signal generated by momentary voltage spike. Resistor added to suppress momentary voltage transient W/880406 ltr MENGERS.C.A., LOGUE.R.H. Philadelphia Electric Co. 88/04/06 4pp. 45100:108-
- 8804060220 LER 85-056-01 on 850529 isolation of RWCU sys occurred. Caused by deficient differential temp switch RWCU sys Togic reset.panel 10C609 inspected & TDTS-44-1N802A tested four times.No defects found W/880406 ltr.
 MENGERS.C.A. LOGUE,R H. Philadelphia Efectric Co. 88/04/06. Spp. 45098-189-45098 193
- 8804130187 PNSI-86 001 on 880406,handgun detected during routine x-ray machine search at protected area entrance point Worker access badge temporarily withdrawn pending investigation. Licensee believes incident unintentional. BAILETY, R. KEIMIG.R. Region 1, Old of the Director. 88/04/05. 1p. 45154:070-45154:070.
- 8804130070 LER 88:007:00 on 880309,HPCI sys declared inoperable Caused by pressure transmitter lailure Transmitter replaced & tested & cause for false signal due to failed amplifier board W/880408 fit.

 VENGERS.C.A., LOGUE,R.H. Philadelphia Electric Co. 88/04/08. 5pp. 45131:059-45131:063

V. Operator Examinations

8804010265 Forwards summary of 680129 meeting w/util in Region I ofcire proposal to license currently Icensed operators at Unit 1 to operate Unit 2 GALLO, BM. Region 1, Otc. of the Director. 88/03/24, KEMPER, J.S. Philadelphia Electric Co. 47pp. 45058 135-45058.181.

DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

A. Application/construction stage documents & correspondence

- B803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re-removal of organization charts from Tech Spec administrative control requirements Svc Lst encl, MFAGLIAF, J. Associato Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972.153
- 8804040104 Forwards Rev 5 to offsite dose calculation manual,per 871123 request Rev addresses all but three discrepancies noted in technical evaluation rept Discrepancies not addressed, restated,followed by usi response.

 GALLAGHERJW Philadelphia Electric Co. 88/03/30 CLARK,R J. Project Directorate 1-2 3pp. 44970.096-44970.229.
- --8804040108 Rev 5 to "Offsite Dose Calculation Manual."
 * Philadelphia Electric Co. 88/03/30. 131pp. 44970 099-44970:229.
- 8804060204 Forwards Amend 89 to license application, revising fire protection evaluation rept by making various changes to accurately reflect facility sys, including mode & providing partial description of plant fire protection. BRADLEY, E.J. Philadelphia Electric Co. 88/04/05. MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 1p. 45082 293-45083 099.
- --8804060210 Amend 89 to license application,ravising fire protection availuation rept by making valuous changes to accurately reflect facility sys,including mode & providing partial description of plant fire protection features. MCNEILL,C.A. Philade'phia Electric Co. 88/04/04. 4pp. 45062-294-45062-297.
- 8804060088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10/CFR50 49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Suc list encl. MIRACUA.F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804150055 Forwards ' Reediness Program Assessment for Limerick 2." Plans for self-assessment activities consist of readiness program assessment & readiness verifica-tion program. KEMPERJS Philadelphia Electric Co. 88/04/11. RUSSELL,W.T. Rogion 1, Ofc of the Director. 2pp. 45158 327-45159:250.
- -8804150059 "Readiness Program Assessment for Limetick 2." MATTSON,R.J. ERC International, Inc. 88/03/08, 300pp, 45158-329-45159.250.

F. Security, medical, emergency & fire protection plans

- 8804040068 Forwards public version of revised emergency plan implementing procedures including Rev. 4 to Procedure EP-254, "Vehicle & Evacuee Control Group" & Rev. 3 to Procedure EP-255, "Vehicle Decontamination." W/880328 refease memo. GALLAGHER, JW. Philadelphia Electric Co. 88/03/17. Document Control Branch (Document Control Desk). Spp. 45009.001-45009.049.
- 8804040075 Public version of revised emergency plan implementing procedures.including Rev 4 to Procedure EP-254, "Vehicle & Evacueo Control Group," Rev 3 to EP-255, "Vehicle Decontamination" & Rev 14 to EP-291, "Statiing. "
 * Philadelphia Electric Co. 88/03/17, 44pp. 45009:006-45009.049.

- 8804060204 Forwards Amond 89 to license application, rovising lire protection evaluation rept by making various changes to accurately reflect facility sys.including mods & providing partial description of prant fire protection BHADLEY, E.J. Philadelphia Electric Co. 88/04/05. MURLEY, T.E. Othes of Nuclear
- Reactor Regulation, Director (Post 870411) 1p. 45062:293-45062:297.
- ~8804060210 Amend 89 to Ilconse application, rovising fire protection evaluation rept by making various changes to accurately reflect facility sys. including mids & providing partial description of plant fire protection teatures.

 MCNETLL,C.A. Philadelphia Electric Co. 88/04/04. 4pp. 45062:294-45062.297.
- -8804060239 Rev 10 to "Limerick Generating Station Units 1 & 2 Fire Protection Evaluation Rept."
 * Philadelphia Efectric Co. 88/04/05. 162pp. 45062:298-45063:099.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8804140215 Submits summary of actions discussed at ACRS 335th meeting on 880310, 12 in Washington.DC.including ACRS replat recommendations, other actions, agreements, assignments & requests & future agenda. KERR,W. ACRS - Advisory Committee on Reactor Safeguards. 88/03/24 ZECH,L,W. Commissioners. 4pp. 45118:172-45118:175.

Q. inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimb'e Tubo Thinning in Westinghouse Reactors," Svo list onci.
 ROSSIGE Division of Operational Events Assessment (Post 870411). 88/03/28
 Consolidated Edison Co. of New York, Inc. 121pp. 44995:128-44995.246
- 8803220296 NRC Info Notice 88-010, "Matts Liconsees:Leck of Mgt Contro's Over L-censed Programs." Sve list enct. CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safaty (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.
- 8804010273 Forwards Safety Insp Ropt 50-353/88-04 on 880208-12.No violations noted. DURR.J.P. Region 1, Ofc of the Director. 88/03/28, KEMPER,J.S. Philadelphia Elec-tric Co. 2pp. 45045:155-46045:163.
- -8804010274 Insp Rept 50:353/88-04 on 880208-12 No violations noted. Major areas Inspected preoperational test program including test procedures & overall preopera-tional test program raview requirements two unresolved Items noted. VAN KESSEL,HF. EAPEN,P.K. Region 1, Otc of the Director. 88/03/28. 7pp 45045:157-45045:163.
- 8804070249 Forwards Safety Insp. Ropt 50-353/88-02 on 880125-29.No violations noted OURR.J.P. Region 1, Oic of the Director, 88/03/31, KEMPER,J.S. Philadelphia Elec-tric Co. 2pp. 45072 230-45072:239.
- --6804070251 Insp Flept 50-353/68-02 on 880125-29.No violations noted. Major areas inspected prespectational test program including review of test procedures, overall program review requirements & QA/QC interface.

 VANKESSEL.H.F., EAPEN,P.K., Region 1, Old of the Director, 88/03/30, 8pp. 45072:232-45072:239.
- 8804010256 NRC Into Notice 88:011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svc list enct. ROSSI, CE. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804150230 Responds to 880205 NRC Bulletin 68-01 re detects in Westinghouse cucul breakers for facitiles. Wastinghouse DS sories circuit breakers not used at plants. Other provisions of bulletin do not apply to plants. KOWALSKI, S.J. Philadolphia, Electric Co., 88/04/08. RUSSELL, W.T. Region 1, Ofc of the Director. 2pp. 45138:028-45138:029.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc BOSSICE. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150.

S. Reportable occurrences, LEAs & related correspondence

8804070225 Final significant Deficiency Rept 215 re App R safe shutdown capability for Fire Area 76 Diesel generator control circuits redesigned & re-reviewed electrical schematics & application of Class 15 isolation relay.

KOWALSKI,S.J. Philadelphila Electric Co. 88/04/04. RUSSELL,W.T. Region 1, Oic of the Director. 7pp. 45072:243-45072.249.

V. Operator Examinations

8804010265 Forwards summary of 880129 meeting w/util in Region I ofc re proposal to license currently licensed operators at Unit 1 to operate Unit 2. GALLO.RM. Region 1, Olc of the Director. 88/03/24. KEMPER,J.S. Philadelphia Electrio Co. 47pp. 45058:135-45068:181.

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8804040036 Forwards Safety Insp Repts 60-272/88-05-60-311/88-05-50-354/88-02 on 880125-29.No violations or deviations noted. 880125-29.No violations or deviations noted. 8ELLAMY R.R. Region 1, Olc of the Director. 8B/03/24. MCNEILL.C.A. Public Service Electric & Gas Co. of New Jersoy. 2pp. 45031:305-45031:313.

- -8804040042 Insp. Repts 50-272/88-05.50-311/88-05 & 50-354/88-02 on 680125-29. No violations,deviations or unresolved items noted Major areas inspected emergency preparedness program conducted on 880125-29. AMATO,C G. Region 1, Oic of the Director. 88/03/11. 7pp. 46031:307-45031:313
- 8804050326 Forwards SALP Board Repts 50:272/86:99 & 50:311/86:99 during Oct 1986 Dac 1987 & Rept 50:354/86:99 on 861201:480115. RUSSELL,W.T. Region 1, Ofc of the Director. 88/03/29. MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 2pp. 45033:282-45034:034.
- -8804050334 SALP Rept 50-354/86-99 on 861201-880115.
 * Region 1, Oto of the Director. 88/03/04. 63pp. 45033:264-45033:326.

K. Utility Final Safety Analysis Report (FSAR) & amends

- 8804210372 Forwards updated FSAR,Rev 0,for Hope Creek Generating Station Brief explanation for each change processed during transition from FSAR to updated FSAR provided as Attachment 1 to util 880411 ltr.
 MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 88/04/20. Document Control Branch (Document Control Desk). 3pp. 45285:001-45314:023.
- -8804210378 Updated FSAR for Hope Creek Generating Station.

 * Public Service Electric & Ges Co. of New Jersey. 88/04/11, 14,787pp. 45285.005-45301:152.
- -8804210392 Chapter 1, "Intro & General Description of Plant," to Hope Creek Generating Station updated FSAR.
 Public Service Electric & Gas Co. of New Jersey. 88/04/11, 900pp. 45285:092-
- -8804210395 Chapter 2, "Site Characteristics," to Hope Creek Generating Station updated FSAR. Public Service Electric & Gas Co. of New Jersey, 88/04/11, 1,875pp, 45287:152-45290:124
- -8804210401 Chapter 8, "Electric Power," to Hope Creek Generating Station updated Public Service Electric & Gas Co. of New Jersey, 88/04/11, 760pp, 45301:153-
- 45302:170. -8804210406 Chapter 9, "Auxiliary Sys," to Hope Creek Generating Station updated
- Public Service Electric & Gas Co. of New Jersey. 88/04/11, 1,600pp. 45302:171-45305 332
- -8804210415 App 9A, "App R Comparison," to Hope Creek Generating Station updated FSAR.
 * Public Service Electric & Gas Co. of New Jersey, 88/04/11, 1600pp, 45305:333-
- -9804210416 Chapter 3, "Design of Structures, Components, Equipment & Sys," to Hope Creek Generating Station updated FSAR,
 Public Service Electric & Gas Co. of New Jersey, 88/04/11, 1,850pp, 45290:125-45294:161.
- -8804210422 App 9B, "Design Analysis & Const," to Hope Creek Generating Station updated FSAR.
- Public Service Electric & Gas Co. of New Jersey, 88/04/11, 16pp. 45307:206-
- --8804210424 App 3A, "Computer Programs Used in Structural Analysis & Design," to Hope Creek Generating Station updated FSAR.

 * Public Service Electric & Gas Co. of New Jersey. 88/04/11, 25pp. 45294:182-4504-19.
- -8804210427 App 3B, "Mark I Long-Term Program,Plant Unique Analysis,FSAR Summary Rept," to Hope Creek Generating Station updated FSAR,

 * Public Service Electric & Gas Co. of New Jersey, 88/04/11, 43pp. 46294:188-45294-230
- -8804210429 App 3C, "Reactor Asymmetria Loads Analysis," to Hope Creek Generating Station updated FSAR.

 * Public Service Electric & Gas Co. of New Jersey, 88/04/11. 4pp, 45294:231-4504-66. 45294:234
- ~8804210431 Chapter 10, "Steam & Power Conversion Sys," to Hope Creek Generating Station updated FSAR.

 * Public Service Electric & Gas Co. of New Jersey. 88/04/11, 425pp. 45307:220-45307.
- -8804210432 App 3D, "Foundation Mat Design," to Hope Creek Generating Station updated FSAR.
 * Public Service Electric & Gas Co. of New Jersey. 88/04/11. 9pp. 45294:235-
- -8804210435 App 3E, "Buckling Analysis of Drywell Vessel," to Hope Creek Generating Station updated FSAR,

 * Public Service Electric & Gas Co. of New Jersey, 88/04/11, 8pp. 45294:244-45294-250
- ~8804210439 App 3F, "Analysis & Design of Fuel Pool Liner & Slab," to Hope Creek Generating Station updated FSAR. Public Service Electric & Gas Co. of New Jersey, 88/04/11, 4pp. 45294:251-45294:254.
- --8804210440 App 3G, "Intake Structure Stability Analyses," to Hope Creek Generating Station updated FSAR,
 Public Service Electric & Gas Co. of New Jersey, 88/04/11, 4pp, 45294:255-46304:650
- -8804210441 App 3H, "Power Block Stability Analysis," to Hope Creek Generating Sta-tion updated FSAR,
 Public Service Electric & Gas Co. of New Jersey, 88/04/11, 8pp. 46294:269-

- -8804210442 Chapter 11, "Radwaste Mgt," to Hope Creek Generating Station updated Public Service Electric & Gas Co. of New Jersey, 88/04/11, 600pp 45308:003-
- **8804210443 App 3t, "Ultimate Capacity of Containment," to Hope Greek Generating Station updated FSAR.

 ** Public Service Electric & Gas Co. of New Jersey 88/04/11, 4pp 45294:267-45294:270
- --8804210444 Chapter 4, "Reactor," to Hope Creek Generating Station updated FSAR * Public Service Electric & Gas Co. of New Jersey. 88/04/11, 200pp. 45294:271-
- -8804210445 Chapter 5, "RCS & Connected Sys," to Hope Creek Generating Station updated FSAR Public Service Electric & Gas Co. of New Jersey, 88/04/11, 400pp. 45295.075-
- -8804210446 App \$A, "Compliance w/10CFR50,App G & App H," to Hope Creek Generaling Station updated FSAR.

 * Public Service Electric & Gas Co. of New Jersey, 88/04/11, 49pp. 45296.031-45298 078
- -8804210447 Chapter 12, "Radiation Protection," to Hope Creek Generating Station updated FSAR. Public Service Electric & Gas Co. of New Jersey. 88/04/11, 1,000pp. 45308-269-
- --8804210450 Chapter 6, "ESFs," to Hope Creek Generating Station updated FSAR.

 Public Service Electric & Gas Co. of New Jersey, 88/04/11, 900pp, 45296-079-45298-094.
- -8804210456 Chapter 13, "Conduct of Operation," to Hope Creek Generaling Station updated FSAR.
 * Public Service Electric & Gas Co. of New Jersey. 88/04/11. 200pp. 45310:201-45310 333
- -8804210456 App 13A, "Nuclear Reactor Fundamentals," to Hope Creek Generating Station updated FSAR.

 * Public Service Electric & Gas Co. of New Jersey. 88/04/11, 20pp. 45310 334-45310:352
- --8804210462 App 8A, "Negative Pressure Design Evaluation," to Hope Creek Generaling Station updated FSAR.

 * Public Service Electric & Gas Co. of New Jersey. 88/04/11. 28pp. 45298.095-45298:122
- --8804210466 App 6B, "Subcompartment Differential Pressure Considerations, " to Hope Creek Generating Station updated FSAR.

 Public Service Electric & Gas Co. of New Jersey. 88/04/11, 71pp. 45298:123-

45298 194

- --9804210468 App 6C, "Structural Design Criteria for Seismic Category I HVAC Ducts 8 Duct Supports," to Hope Creek Generating Station updated FSAH.

 * Public Service Electric & Gas Co. of New Jersey. 88/04/11, 15pp. 45298:195-
- -8804210469 Chapter 7, "Instrumentation & Centrols," to Hope Creek Generating Station updated FSAR.

 *Public Service Electric & Gas Co. of New Jersey. 88/04/11. 1,100pp. 45298:207-45301:152.
- -8804210475 App 13B, "Reactor Startup Experience," to Hope Creek Generating Station updated FSAR.
 Public Service Electric & Gas Co. of New Jersey. 88/04/11. 3pp. 45310:353-45340.65
- -8804210477 App 13C, "Advanced Technical Training," to Hope Creek Generating Station updated FSAR.

 * Public Service Electric & Gas Co. of New Jersey. 88/04/11. 21pp. 45310:355-
- --8804210478 App 130, "Precertification 8WR Sys Training," to Hope Creek Generating Station updated FSAR.

 * Public Service Electric & Gas Co. of New Jersey. 88/04/11. Spp. 45311:015-
- --8804210483 App 13E, "Cold License Cerillication Training," to Hope Creek, Generating Station updated FSAR.

 Public Service Electric & Gas Co. of New Jersey. 88/04/11, 14pp. 45311:018-
- --8804210464 App 13G, "Hope Creek Specific Sys Training," to Hope Creek Generating Station updated FSAR. Public Service Electric & Gas Co. of New Jersey, 88/04/11, 10pp, 45311:065-
- --9804210486 App 13H, "Equipment Operator Training Program," to Hope Creek Generating Station updated FSAR.

 * Public Service Electric & Gas Co. of New Jersey. 88/04/11. 15pp, 45311:074-450406.
- 45311:087
- --8804210487 App 13F, "SS-N Training Program," to Hope Creek Generating Station updated FSAH. Public Service Electric & Gas Co. of New Jersey, 88/04/11, 35pp. 45311-032.
- -- 8804210488 App 13I, "Cold License Operator Inplant Training," to Hope Creek Generating Statlon updated FSAR.

 * Public Service Electric & Gas Co. of New Jersey. 88/04/11, 2pp. 45311 088. 45311:089.
- -- 8804210489 App 13J, "Prelicensing Exam Testing & Training," to Hope Creek Gener-BB04210469 App 133, Frenchishing CASH 1990-1991 (1990) Alling Station updated FSAR.
 * Public Service Electric & Gas Co. of New Jersey. 88/04/11, 4pp, 45311:090-45311:092.

- -8804210490 App 13K, "Plant Observation/Experience Training." to Hope Creek Gonerating Station updated FSAR.
 "Public Service Electric & Gas Co. of New Jorsey 88/04/11. Spp. 45311:093-
 - 45311:097
- -8804210491 App 15A to Hope Greek Generating Station updated FSAR. Untilled.

 * Public Service Electric & Gas Co. of New Jersey, 88/04/11, 28pp 45313 230-45313 256.
- -8804210492 App 13L, "Procedures Generation Package for Hope Creek Generating Station," to Hope Creek Generating Station updated FSAR.

 * Public Service Electric & Gas Co. of New Jersoy. 88/04/11 118pp. 45311.098-
- -8804210493 App 15B, "Special Analysis," to Hope Creek Generating Station updated
- Public Service Electric & Gas Co. of New Jersey, 88/04/11, 13pp. 45313 257-
- -8804210494 Chapter 14, "Inval Test Program," Hope Crock Generating Station update ed FSAR.

 * Public Service Electric & Gas Co. of New Jersey, 88/04/11, 250pp. 45311:213-
- -8804210495 Chapter 15, "Accident Analyses," to Hope Creek Generating Station up-
- dated FSAR.

 * Public Service Electric & Gas Co. of New Jersey, 88/04/11, 700pp. 45312:102-45313-229
- -8804210496 App. 15C, "Hope Creek Single Loop Operation Analysis," to Hope Creek Generating Station updated FSAH. * General Electric Co. 88/04/11, 46pp. 45313:259-45313.313.
- -8804210499 Chapter 16, "Tech Specs," to Hope Creek Generating Station updated
- FSAR * Public Service Electric & Gas Co. of New Jersey, 88/04/11, 7pp. 45313:314-
- --8804210501 Chapter 17, "OA," to Hope Creek Generating Station updated FSAR.
 Public Service Electric & Gas Co. of New Jersey, 68/04/11, 59pp. 45313-318-45314:013.
- -8804210502 Chapter 18, "Human Factors Engineering," to Hope Creek Generating Station updated FSAR.

 * Pubric Service Electric & Gas Co. of New Jersey. 88/04/11, 15pp. 45314/014-45314/023.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ur 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Syc list end MIRAGLIA.F.J. Associate Director for Projects [Post 974411], 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972/107-44972:153.
- 8804060446 Provides final info necessary to support Issuance of license amend to permit extended operation of drywelf. 8 suppression chamber purge sys All station mode required for amend will be completed by restart following first rollucing outage. MILTENBERGERS, Public Service Effectic & Gas Co. of New Jersey. 88/03/29. Document Control Branch (Document Control Desk). 2pp. 45010.348.45010.349.
- 8804150150 Forwards Amend 16 to License NPF-57 & safety evaluation. Amend revises Section 374.6.1.8 to permit operation of valves in one conforment purge supply line & one conforment purge exhaust line for up to 120 h annually. RIVENBARK IS. Project Oriectorate 1-2. 88/03/30. MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 3pp. 45133-337-45133-361.
- ~8804150156 Amend 16 to License NPF-57,revising Section 3/4.6.1.8 to permit operation of valves in one containment purge supply line 8 one containment exhaust fine 8.6 linch nitrogen supply valves for up to 120 hin 365-day period BUTLER,W.R. Project Directorate 1-2.88/03/30, 14pp. 45133:340-45133:353.
- --8804150160 Salety evaluation supporting Amend 16 to License NPF-57.

 * Office of Nuclear Reactor Regulation, Director (Post 970411), 88/03/30. Bpp. 45133 354 45133 361.
- 8804120031 Requests meeting w/util to resolve encl questions. & comments to inservice testing program.Formal responses to questions prior to meeting not required, however draft responses should be prepared for discussion in meeting. RIVENBARK, G. Project Directorate 1-2. 88/04/01. MILTENBERGER, S. Public Service Electric & Gas Co. of New Jersey. 15pp. 45089:203-45089:217.
- 8804150394 Corrects date for itr requesting meeting to resolve encil questions & comments re-proposed inservice testing program. Draft responses should be prepared for discussion at meeting.

 RIVENBARK.G. Project Directorate 1-2: 88/04/01. MiLTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 1p. 45133.120-45133:120.
- 8804070088 Forwards overall executive summary of reliability program & rolated repts detailing bases for summary.Proprietary ropts, "Functional Veurlication Rept..." & "...Feasibility Study for In-Situ Testing..." also encl.Repts withheld. MILTENBERGERS. Public Service Electric & Gas Co. of New Jarsey, 88/04/04. Document Control Branch (Document Control Dask), 24pp. 45093.056-45097;172.
- --8804070091 "Reliability Summary Repl for Bailey 862 Solid State Logic Module."
 MASSARO,M J Public Service Electric & Gas Co. of New Jersey, 88/03/31, 17pp 45093.080-45093.096.
- -8804070169 "Component Failure Analysis Rept 862 Logic Module."
 * Bailey Controls Co. (subs. of Babcock & Wilcox Co.); QR-5106-E93-75-ADD1, 887-01/12, 85pp. 45093-097-46093-161.
- -8804070182 Vols I-IV to "Reliability Test Program for Barley Model 862 Logic Modulos for Use in Hope Creek Generating Station," last rept. WALTER,R.T. Wyle Laboratories 48815-02. 88/03/25. 1,451pp. 45093;162-

- 8804140058 Confirms telcon re relaxation of Tech Spec 4.6.5.3 c testing requirements on litration recirculation & ventilation systater maint 8 painting Statement restrictural maint on HEPA litter or charcoal absorber housings unclear. SINGHIS, New Jersey, State of 88704705, RIVENBARK,G. Project Oirectorate 12 2pp. 45155:031-45155:032
- 8804080088 Generic Ltf 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MRAGLIAF, J. Associate Director for Projects (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804150169 Forwards SER accepting util responses to Part 1, Item 2.1 of Gonoric Ltr 83:28, "Required Actions Based on Gonoric Implications of Salem ATWS Events." BUTLER, W.A. Project Directorate 1:2, 88/04/11, MILTENBERGER, S. Public Service Electric & Gas Co. of New Jersey, 3pp. 45134:003-45134:007.
- -8804150173 SER supporting util responses to Part I, Item 2.1 of Generic I,Ir 83-26, "Required Actions Based on Generic Implications of Salem ATWS Events." "Project Directorate II-2, 88/04/11, 2pp. 45134;006-45134;007.
- 8804180109 Forwards summary of changes to Rev 0 to updated FSAR Rev 0 will be provided under separate cover.
 MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey, 88/04/11. Document Control Branch (Document Control Desk). 27pp. 45145-267-45145-293.
- 8804260194 Forwards Rev 3 to NOV-1000-87-003, "Hope Creek SPDS Verification & Validation Program Plan." Document revised to reflect redesigned Hope Creek SPDS es presented in 870521 staff meeting. MILTENBERGER, S. Public Sorvico Electric & Gas Co. of New Jersey. 88/04/21. Document Control Branch (Document Control Dask), 2pp. 45258:294-45258:333.
- 8804260200 "Hope Creek SFDS Verilication & Validation Program Plan"
 Eigen Engineering, Inc. 87/12/02. 38pp. 45258 286-45258.333.

O. Inspection reports, IE Bulletins & correspondence

- 8804040036 Forwards Safety Insp Repts 50-272/88-05,50-311/88-05 50-354/88-02 on 880125-20 No violations or deviations noted.

 BELLAMY,R R. Region 1, Oic of the Director, 88/03/24, MCNEILL,C.A. Public Service Electric & Gas Co. of New Jersey. 2pp. 45031:305-45031:313
- --8804040042 Insp Repts 50-272/88-05,50-311/88-05 & 50-354/88-02 on 883126-29 No violations, deviations or unresolved items noted Major areas inspected: emergency preparedness program conducted on 880125-29.

 AMATOC G. LAZARUS, W.J. Region 1, Oic of the Director. 88/03/11. 7pn. 45031.307-45031.313
- 8804010184 Requests extension of submittel date until 880429 for supplemental re-sponse to NRC Compliance Bulletin 87:002 due to delay in receipt of lest results. MILTENBERGER,S. Public Servico Electric & Gas Co. of New Jersey. 68/03/25 RUSSELL,W.T. Region 1, Otc of the Director. 2pp. 45020.008-45020.010.
- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list enct.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/03/28
 Consolidated Ed.son Co. of New York, Inc. 121pp. 44995.126-44895:246.
- 8803220296 NRC Into Notice 88-010, "Mails Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list encl. CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870720) 88/ 03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804050326 Forwards SALP Board Repts 50-272/86-99 & 50-311/88-99 during Oct 1986 Dec 1987 & Rept 50-354/88-99 on 861201-880115.
 RUSSELL,W.T. Region 1, Otc of the Director. 88/03/29. MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 2pp. 45033:282-46034-034.
- --8804050334 SALP Rept 50-354/86-99 on 861201-880116. * Region 1, Ofe of the Director, 88/03/04. 63pp. 45033:264-45033.326.
- 8804070315 Responds to NRC Bulletin 88-001 re defects in Westinghouse DS/DSL crecuit treakers Plants do not utilize subj circuit breakers
 MILTENBERGER,S. Public Service Electric 8 Gas Co. of New Jersey. 88/03/31. Document Control Branch (Document Control Uesk). 3pp. 45075:214-45075:216.
- 8804130007 Notification of Licensee Meeting 88:051 on 880414 w/util in Hancocks Bridge NJ to discuss SALP. SWETLAND,P. Region 1, Old of the Director, 88:03/31, Region 1, Old of the Director, 2pp. 45099;312-45099;313.
- 8804130006 Forwards Safety Insp Rept 50-354/88-05 on 880209-0321 & notice of violation Responses & corrective actions re-violations cited in Insp Repts 50-354/87-23 & 50-354/87-29 will be examined during furture Insps. WENZINGER,EC. Region 1, Old of the Director. 88/04/04. MILTENBERGER,S Public Service Electric & Gas Co. of New Jersey, 2pp. 45132:255-45132-266.
- --8804130010 Notice of violation from this on 880209-0321. Violation noted on 880226, recirculation & ventilation sys fan flow pressure switch-not correctly restored to svc during implementation of Procedure IC-DC ZZ-057.

 * Region 1, Oic of the Director. 88/04/04. 1p. 45132:257-45132:257.
- -9804130012 Onsite Resident Insp Rept 50-354/88-05 on 880209-0321. Violation noted Major areas inspected operational safety verification surveillance testing meint activities reactor coolant spill in torus basement & assurance of quality. SWETLAND,P. Region 1, Ofc of the Director. 88/04/04. 9pp. 45132:258-45132:258.
- 8804120326 Responds to NRC 880307 ltr re violations noted in Insp Rept 60:354/88-01.Corrective actions:design change implemented on 880113 which modified Equid radwaste d.scherge monitor logic.

 MILTENBERGER, S. Public Service Electric & Gas Co. of New Jersey. 88/04/06. Document Control Branch (Document Control Desk). 3pp. 45090.081-45090:083.

- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Cir &/or Switch-board Function Duo to Faulty Tie Bolts." Syc list encl ROSSI.C E. Division of Operational Events Assessment (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406.292-45407.051
- 8804130040 Forwards request for addl info re util R60527 response to IE Bul'etin 85-803, "Motor-Operated Valve Switch Settings." Response requested within 30 days. WENZINGER,E.C. Region 1, Otc of the Director. 88/04/07. MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 7pp. 45135:350-45135:356
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc
- Lst encl ROSSI,C.E. Division of Operational Events Assosament (Post 870411) 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45166-150.
- 8804220018 Requests date for presentation of plan to restructure equipment qualifica-tion files be changed to 880630 Change of date will allow time for alternative ap-proaches to be evaluated & for estimated expenditures to be approved MILITERBERGER,S Public Service Electric & Gas Co. of Now Jersey. 88/04/15. Doc-ement Control Branch (Document Control Dask). 2pp. 45226-328-45226-329.

R. Periodic operating reports & related correspondence

- 8804190389 Forwards monthly operating repts for Mar 1988. Operating data repts for Jan.Feb.June & Jul 1987 also encl. LABRUNAS. Public Servico Electric & Gas Co. of New Jersey. 88/04/15 Document Control Branch (Document Control Desk). 1p. 45220 227-45220 249.
- --8804190301 Monthly operating rept for Mar 1988.

 ZAPOLSKI,M., JENSEN, H Public Service Electric & Gas Co. of New Jersey. 88/03/31 19pp. 45220:228-45220:245.
- -8804190391 Updated monthly operating rept for Jan 1987,consisting of operating data repl JENSEN.H Public Service Electric & Gas Co. of New Jersey. 87/01/31. 1p. 45220.246-45220.246.
- -8804190393 Updated monthly operating rept for Feb 1987, consisting of operating data JENSEN,H. Public Service Electric & Gas Co. of New Jersey. 87/02/28. 1p. 45220 247-45220 247
- -8804190394 Updated monthly operating rept for June 1987,consisting of operating data rept.

 JENSEN,H. Public Service Electric & Gas Co. of New Jorsey. 87/06/30. 1p 45220 248-45220 248.
- -8804190396 Updated monthly operating rept for Jul 1987,consisting of operating date rept.

 JENSEN,H. Public Service Electric & Gas Co. of New Jorsoy. 87/07/31. 1p. 45220.249-45220 249

S. Reportable occurrences, LERs & related correspondence

- 8804060251 LER 88-004-00.on 880301, discovered that required surveillance of refueling floor exhaust process radiation monitoring Channel B not performed Caused by personnel error Sonlor supervisor counseled W/880330 ft. ERVINA M. LABRUNA S. Public Service Electric & Gas Co. of New Jersey. 88/03/ 31. 5pp. 45046:199-45046:203.
- 8804140155 LER 88-002-01:on 880213,primary containment isolation valves inoperable. Caused by feture of inservice inspire notify control room personnel that surveillance overdue Both inboard & outboard valves reworked. W/880405 lir. ERVIN,A.M., LABRUNA.S. Public Service Electric & Gas Co. of New Jersey. 88/04/08. 5pp. 45158:298-45158:302.
- 8804190025 LER 88-005-00 on 880220, Inoperable inputs to primary containment isofa-lion sys discovered & required Tech Spec action not taken Caused by Inadequate design change package (DCP) description. New DCP process phased in W/880408 ltr. COWLES, R.B., LABRUNA, S. Public Service Electric & Gas Co. of New Jersey. 88/04/ 11. 7pp. 45208:164-45208:160.
- 8804200088 FIO on 880320 shift supervisor made 4 in nonemergency rept to NRC reintermediate range monitior upscale trip due to momentary nosis spike on channel. LABRUNAS. Public Service Electric & Gas Co. of New Jersey. 88/04/12. Document Control Branch (Document Control Desk). 2pp. 45218:234-45218:235.
- 8804200269 LER 88-005-01:on 880310.primary containment isolation sys inputs inoperable & required Tech. Spacs actions not taken. Caused by inadequate design change package (OCP) description. Secondary containment established.W/880413 ltr. COWLES.R.B. LABRUNA.S. Public Service Electric & Gas Co. of New Jorsey. 88/04/ 13. 7pp. 45216.059-45216:065.
- 8804260263 LER 88-006-00:on 880321, momentary upscale spike on intermediate range monitor resulted in full reactor protection sys actuation. Caused by electronic noise generated by welders. Methods evaluated W/880420 ftr. COWLES, RB, LABRUNAS. Public Service Electric & Gas Co. of New Jersey. 88/04/20. 5pp. 45281.033-45281.037.

V. Operator Examinations

- 8804050326 Forwards SALP Board Repts 50:272/86:99 & 50:311/86:99 during Oct 1986: Doc 1987 & Rept 50:354/86:99 on 861201-880115. RUSSELLW.T. Region 1, Oic of the Director. 88/02/29. MILTENBERGER,S. Public Service Electric & Gas Co. of New Jersey. 2pp. 45033:282-45034:034.
- --8804050334 SALP Rept 50-354/86-99 on 861201-880115.
 Region 1, Ofc of the Director, 88/03/04, 63pp. 45033:264-45033.328.

DOCKET 50-356 UNIV. OF ILLINOIS RESEARCH REACTOR

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Mailing address unchanged A Adams project manager 8 TS Michaels back-up project manager RUBENSTEIN,LS Standardization 8 Non-Power Reactor Project Directorate 88/03/18. Affiliation Not Assigned. 3pp. 44859.080 44859.082

DOCKET 50-358 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

- 8803240426 Generic Ltr 88:06 to all power roactor licensees & applicants re-removal of organization charts from Tech Spec administrative control requirements Syc list and MRAGLIAF J. Associate Director for Projects (Post 870411): 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972.153.
- 8804080088 Genoric Ltr 88 07 to power reactor Icensess 8 applicants re-modified en-lorcement policy concerning 10CFR50 49, "Environ Qualification of Electrical Equip-ment Important to Salety for Nuclear Power Planis." Sec isst enct. MIRAGLIA,F.J. Associate Director for Projects (Post 870411) 88/04/07. Consol detection Co. of New York, Inc. 49pp. 45184-237-45184-285

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list encl. ROSSI, CE. Division of Operational Events Assessment (Post 870411) 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995.126-44995.246
- 8803220296 NRC Info Notice 88-010, "Matts Licensess.Lack of Mgt Controls Over Liconsed Programs." Svc list onci. CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 807 03728. Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Cir &/or Switch-board Function Due to Faulty Tie Bolls." Svc list encl ROSSI,CE Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407 051.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list enct ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165-150

DOCKET 60-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8804060001 Forwards Addendum 10-1D to physical security plan. Addendum withheld (rel 1005F973.21).
 MORGAN,H.E. Southern Centron's Edison Co. 88/03/28. Document Control Branch (Document Control Desk). 1p. 45032.294-45032.284.
- 8804190131 Forwards Insp. Repts 50-206/88-07,50-361/88-07 & 50-362/88-07 on 880308-11 & notice of violation. WENSLAWSKI,F.A. Region 5, Old of the Director, 88/04/01, BASKIN,K.P. Southern California Edison Co. 2pp. 45198.264-45196-277.
- -8804190132 Notice of violation from insp. on 880308-11. Violation noted: independent audit of emergency preparedness program not performed since 861201.
 WENSLAWSKI,F.A. Region 5, Old of the Director. 88/04/01. 1p. 45196 266-
- --8804190134 Insp. Repts 50:206/88:07,50:361/88:07 & 50:362/88:07 on 880008-11.Violations noted Major areas inspected:operational status of emergency prepared-ness program & Insp. Procedure 82701. GOOD, G.M. Regton 5, Otc of the Director. 88/03/29, 11pp. 45106 267-45196:277,

G. Adjudicatory correspondence

- 8804260150 Stipulation & proposed order re remand of medical svcs issue.* Stipulates Inal pariles involved reviewed relevant documentation re licensee compliance w/ 10CFR50.47(b)(12) including licensee 870529 submittal.W/Declaration of Svc. VOGLER,8.H. Assistant General Counsel for Hearings PIGOTT, D.R. Southern Carlornia Etilson, Co. PIGOTT, D.R. San Diego Gas & Electric Co. #288 6112, 88/03/22. 34pp. 45210.020-46210.053
- 8804050130 Forwards 880311 memorandum from Chief Administrative Judge BP Cotter.Compliance w/instructions contained in memorandum requested Served on 880331.
- WOLFE,S.J. Atomic Safety and Licensing Board Penel. #288 5985 88/03/30. Atomic Safety and Licensing Board Panel. 2pp. 44966:146-44966;147.
- 8804110048 Forwards stipulation & proposed order re-remand of medical sycs issue re-ceived from C McClung. All documents have been executed per request & returned for lining W/o encl. Related correspondence. VOGLER, B.H. Assistant General Counsel for Hearings. #288 6034, 88/04/05. PIGOTT, D.R. Orrick, Herrington & Suichite. 1p. 45050:087-45050:087.

I. Financial Information

8803300384 Forwards annual rept to Securities & Exchange Commission & cash flow statement for yr ending Dec 1987.

ADAMS,J.B. Southern California Edison Co. 88/03/21. Document Control Branch (Document Control Ossk). 44pp. 44979:143-44979:186.

Allers do CA.

MEDPORD,M O. Southorn Cattorna Edison Co. 68/04/13 Document Control Branch
(Document Control Desk) 1p. 45259 001-45259.249

J. Insurance & Indemnity Information

8804130396 Advises of nuclear property & decontamination hability insurance currently

in force at plant. GOULD.G.J. Southern Cahlornia Edison Co. 88/04/01. Document Control Branch (Document Control Dask). 1p. 45154:329-45154-329.

P. Operating license stage documents & correspondence

8803240426 Generic Ltr 68-06 to all power reactor I censees 8 applicants re-removal of organization charts from Tech Spec administrative control requirements Svc IIst end MRAGUAF J. Associate Director for Projects (Post 870411), 88/03/22 Consolidated Edison Color New York, Inc. 47pp. 44972 107-44972.153.

8804010117 Forwards notice of consideration of issuance of amends to Licensos NPF-10 & NPF-15 & opportunity for hearing to 871214 & 880126 requests for proposed changes to Tach Specs. HICKMAN.D.E. Project Directorate V. 88/03/23 BASKIN,K.P. Southern Californ a Edison Co. COTTON,G.D. San Diego Gas & Efective Co. 5pp. 44946 287-44948 301.

--8804010127 Notice of consideration of issuance of amends to Licenses NPF-10 & NPF-15 & opportunity for hearing re-871214 & 880126 regulates for proposed changes to Tech Specs,including retraing Fig. at 3.1-2. "Regulating Control Element..." ROOD,H: Project Directorate V. 88/03/23 10pp 44948 292-44948 301

8804080231 Informs triat Allegation Package ATS RV 58-A-011 being forwarded to util for detailed evaluation. Investigation & response K/RSCH, D.F. Region 5, Otc of the Ozed'or, 88/04/01, BASKIN,K.P. Southern California Ed son Co. 1p. 45116:184-45116 184.

8804130075 Confirmatory action fit on resolution of technical (saues reliatelying of steam generator tube glugs NRC understands that util will not take facility above 20% of rated power until after technical issues resolved w/NRR.
MARTIN, J.B. Region 5, Otc. of the Director 89/04/04 MCCARTHY, C.B. Southern California Edison Co. 1p. 45099-298-45099-298.

8804110202 Forwards revised just fication for continued operation w/C-E steam genera-tor tube plugs Discussion of mgt philosophy re continued operation of either Unit 2 or 3 in event of steam generator tube leak also addressed. MEDFORD,M.O. Southern Californ a Edison Co. 88/04/05. Document Control Branch (Document Control Disk), 23pp. 45135.082-45135-104.

8804120464 Discusses 880404 confirmatory action litriconfirming understanding reached re-actions to be taken to resolve technical issues associated w/facility steam generator tube plug latures NRC rescinded 880404 confirmatory action litring. Begins 5, Otc. of the Director. 88704705 MCCARTHY, C.B. Southern California Edison Co., 1p. 45090, 169–45090, 169.

8804190401 Notifies that changes addressed in Change Notice 25 to Amend 10 to SCE-1-A, "OA Program" reviewed 8 found acceptable per 10CFR50 App B KIRSCHUF. NRC - No Dotatied Affiliation Given 88/04/05 BASKIN,K.P. Sputhern California Edison Co. 1p. 45155:170-45155 170.

8804080088 Generic Ltr 68-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50-48, "Environ Qualification of Efectrical Equip-ment Important to Safety for Nuclear Power Plants." Svc 1st enct. MIRACUA.F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164.237-45184.285.

8804190128 Forwards request for addl info re implementation of reactor content pump up cutoria.per TMI Action from It.K 3.5. HIGKMAN.D.E. Project Directorate V. 88/04/12. BASKIN.K.P. Southern California Edison Co. COTTON,G.D. San Diego Gas & Electric Co. 4pp. 45164/304/45164/307.

8804220152 Requests addf info re shutdown action requirements orn.ted from Tech Specs 3.0.1 & 3.0.3. HICKMAN,O.E. Project Directorate V. 88/04/13. BASKIN,K.P. Southern California Edison Co. COTTON,G.D. San Diego Gas & Electric Co. 2pp. 45201.112-45201:113.

8804210187 Provides addi into re Proposed Change Notice PCN-234 to change Tech Specs to increase max safety injection tank nitrogen gas cover pressure,per NRC 880223 request. Southern California Edison Co. 88/04/14. Document Control Branch (Document Control Desk). 2pp. 45194-175-45194;176.

8804290447 Informs that util 880227 proposed change to Tech Spec Table 3.7-1 to remove steam line safety valve number designations & pulice sizes from table not ac-

ceptable.

Ceptable.

HICKMAN, D.E. Project Directorate V. 88/04/18 BASKIN, K.P. Southern California

Edison Co. 2pp. 45263 064-45263 065

8804280377 Responds to util 871120 request for approval of changes to decay times associated w/control element assembly calculator penaity factors. Reported net reduction in core melt frequency does not warrant further NRC evaluation KNGHTON,G.W. Project Directorate V. 88/04/21. BASKIN,K.P. Southern Californ's Edison Co. 5pp. 45245-357-45245;361.

Q. Inspection reports, If: Bulletins & correspondence

8804120442 Forwards Insp. Ropts 50-206/88-06,50-361/88-06 & 50-362/88-06 on 880229-0304 & notice of violation.
WENSLAWSKLF.A. Region 5, Otc. of the Director. 88/03/24. BASKIN,K.P. Southern Cellifornia Edison Co. 2pp. 45132:135-45132:146

8804120456 Insp Repla 50-208/88-06.50-361/88-08 & 50-362/88-06 on 880229-0304 Violations noted Major areas inspected: maintaining exposures ALARA & Unit 1-occupational exposure during outages & tours of licensee tac-lities. RUSSELL, J.E., YUHAS,G.P. Region 5, Old of the Director, 88/03/24, 9pp. 45132:138-45132:146.

House Reactors "Svolist and Rosce 97-044, Intimate Training in Westing house Reactors "Svolist and ROSSICE Division of Operational Events Assessment (Post 870411), 88/03/26 Consolidated Eurison Co. of New York, Inc. 121pp. 44995-126-44995-246

8803220298 NRC Info Notice 88-010, "Matts Licenseos Lack of Mgt Controls Over Licenseo Programs" Svc Lst enct.
CUNNINGHAM,R 5 Division of Industrial & Medical Nuclear Salety (Post 870729), 88
03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44095/247-44995:353

8804190131 Forwards Insp. Repts. 50.208/68-07.50-361/89.07 & 50-362/88-07 of 800309-11 & notice of wolation. WENSLAWSKI, F. A. Region. 5, O.c. of the Director. 88/04/01. BASKIN,K.P. Souther California Edison Co., 2pp. 45196:264-45196.277.

--8804190132 Notice of violation from insp on 880308-11.Violation noted; independent audit of emergency preparedness program not performed since 861201.
WENSLAWSKI,F.A. Region 5, Otc. of the Director. 88/04/01. 1p. 45185-266

--8804190134 Insp. Ropis 50-206/88-07.50-361/98-07 & 50-362/88-07 on 880338 11.Victations noted Major areas inspected operational status of emergency preparedness program & Insp. Procedure 82701. GOOD, S. M., FISH,R. F. Region 5, Otc of the Director 88/03/29 11pp. 45196-267 45196-277.

8804010256 NRC Into Notice 88:011, "Potential Loss of Motor Control Ctr &/cr Switch board Function Duo to Faully Tie Botts" Svc list end ROSSIC E. Dw.5 cn. of Opporational Events Assessment (Post 870411), 88/04/07 Consolidated Edison Co. of New York, Inc. 124pp. 45408:292-45407:051.

8804210412 Responds to NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakers." Roview conducted & confirmed that Westinghouse DS-206,DSL-206,DS-410 DSL-1416 or DS-420 circuit breakers not utilized as reactor trip breakers. PILMER,D F. Sculhern Catifornia Edison Co. 88/04/08 MARTIN,J B. Region 5, Orcicitie Director. 2pp. 45227 212-45227.213

8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings," Sv hist enct ROSSICE Division of Operational Events Assessment (Post 870411) 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165-150.

8804190230 Forwards safety evaluations accepting util final low pressure turbine dis-insp. repts,our utl. 860620 & 870323 the License Conditions 2 C(15) & 2.C(13) complete Util commitment to implement mig reps accommendations acceptable. HICKMAN, D.E. Project Directorate V. 88704/12 BASKIN, K.P. Southorn Californied on Co. COTTON, G.D. San Diego Gas & Electric Co. 3pp. 45155 274-45155:287

--9804190246 Safety evaluation accepting uttinap of tow pressure furbine rotors Base on into provided in uttl 860820 ltr,NRC concludes that License Condition 2.C(15) com

plate. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/12, 5pt 45155 277-45155 281.

--8804190249 Safety evaluation accepting util insplot flow pressure turbino rotors. Result of examishow no evidence of stress corrosion cracking in disclore region and dowe holes NRC concludes that License Condition 2 C(13) complete.

Office of Nuclear Reactor Regulation, Director (Post 870411) 88/04/12. 6pg 45155 282-45155 287.

8804210497 Advises that 87091B response to NRC Bulletin 87-001 re program for mon loring thickness of pipe walls in high onergy, single-phase & two-phase carbon size printing sys being used to determine extent of industry participation HICKMAN, D.E. Project Directorate V. 88/04/15 BASKIN,K.P. Southern California Edison Co. COTTON,G.D. San Diego Gas & Electric Co. 3pp. 45192.201-45192.203

R. Periodic operating reports & related correspondence

8804200137 Monthly operating repts for Mar 1988.W/880414 ltr.
SIACOR,E R., MORGAN,H.E. Southern California Edison Co. 88/03/31. 11pp
45221.086-45221:096.

S. Reportable occurrences, LERs & related correspondence

8803290354 PNO-V-88-022:on 880316,reactor shutdown Caused by increased stear generator tube leak to 200 gallons per day. Outage shou'd take 3.4 wks. Unit should beack on line approx mid-Apr 1988
JOHNSON,P.H., TATUM,J. Region 5, Ofc of the Director 88/03/16, 1p. 44920:023 44920.023

8804040105 LER 88-007-00.on 880223.iodine channels of containment purge Isolations systatistics monitors did not meet linearity spec in upper portion of range.Caused to design deficiency W/880323 fff.
MORGAN,H E Southern Carlornia Edison Co. 88/03/23, 2pp. 44970:230-44970:231

8804200267 LER 88-004-00:an 880310.control room isolation sys Train B actuation oc curred due to spike on radiation monitor. Cause unknown Time-domain reflectionated measurements taken & radiation monitor response observed for 4 wks.W/880411 kt MORGAN,H.E. Southern California Edison Co. 88/04/11. Spp. 46254:325-45254:336

8804200216 LER 88-027-01:on 871130,QA audit determined that Tech Spec 4.7.9.1 surveillance requirements not met for 11 lire doors. Caused by procedural deficiencies, inadequate training. Fire door: Tech Specs surveillances performed W/880414 tir MORGAN,H E Southern California Edison Co. 88/04/14, 6pp. 45225.256-45226.281

8804200224 LER 87-031-01:on 871217, reactor manually Impped due to main foedwate isolation value (MFIV) talting closed. Caused by power tead failure to Train 8 solenois for MFIV 2HV-048. Leads replaced. Reassembly procedure revised W/880414 ftr. MORGAN, H.E. Southern California Edison Co. 88/04/14. 7pp. 45215:324-45215.336

DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

- 8804190131 Forwards Insp. Repts 50:206/88-07,50:361/88-07 & 50:362/88-07 on 880308-11 & notice of violation. WENSLAWSKI,F.A. Region 5, Old of the Director, 88/04/01, BASKIN,K.P. Southern California Edison Co. 2pp. 45196:284-45196 277.
- #804190134 Insp. Ropis 50:206/88:07,50:361/68:07 & 50:362/88:07 on 880308-11 Violations noted Major areas inspected operational status of emergancy preparedness program & Insp. Procedum 82701. GOOD,G.M. Reg on 5, Oic of the Director. 89/03/29 11pp. 45196:267-45196:277.

G. Adjudicatory correspondence

- 8804280160 Stiputation & proposed order re-remend of medical svcs Issue.* Stiputates that parties involved reviewed refevent documentation re-licensee compliance w/100CH50-47(b)(12) including licensee 8/0629 submitted W/Dectaration of Svc. VOGLER.B.H. Assistant General Counsel for Hearings. PrGOTT,D.R. Southern California Edison Co. PrGOTT,D.R. San Diogo Gas & Electric Co. #288 6112, 88/03/22, 34pp. 45210.020-45240.053.
- 8804050130 Forwards 880311 memorandum from Chief Administrative Judge BP Cotter Compliance w/instructions contained in memorandum requested Served on 880331.

 WOLFE,S J. Atomic Safety and Liconsing Board Panel. #288 5885.
- 8804119046 Forwards simulation & proposed order retromand of medical sixes issue received from C McClung All documents have been executed per request & returned for filing.W/o enct Related correspondence VOGLER.B.H Assistant General Coursel for Hearings, #288 6034, 88/04/05. PIGOTT.D.R Orrick, Herrington & Sulcliffe, 1p. 45050.087, 45050.087.

1. Financial Information

- 8803300384 Forwards annual rept to Securities & Exchange Commission & cash flow statement for yr and ng Doc 1987.

 ADAMS,JB. Southern Cg-(fornia Edison Co. 88/03/21, Document Control Branch (Document Control Desk), 44pp. 44978:143-44979.186.
- 8804250246 Forwards 1987 annual repts for listed utilis & cities of Anahelm & Riverside,CA.

 MEDFORD,M.O. Southern California Edison Co. 88/04/13. Document Control Branch (Document Control Desk), 1p. 45259.001-45259.249.

J. Insurance & Indemnity Information

8804130395 Advises of nuclear property & decontamination Lability insurance currently in force at plant.
GOULD,G.J. Southern California Edison Co. 88/04/01. Document Control Branch (Occument Control Desk). 1p. 45154:329-45154:329.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88-08 to all power reactor liconspos & applicants re removal of organization charts from Toch Spec administrative control requirements Svc list end. MIRAGLIAF J. Associate Director for Projects (Post 870411), 88/03/22, Consolidated Edison Co. of New York, Inc. 47pp. 44972.107.44972:153.
- 8804010117 Forwards notice of consideration of issuance of amends to Licenses NPF-10 & NPF-16 & opportunity for hoaring re 871214 & 880126 requests for proposed changes to Tech Specs.
 HICKMAN,D.E. Project Directorato V. 88/03/23. BASKIN,K.P. Southern California Edison Co. COTTON,G.D. San Diago Ges & Electric Co. 6pp. 44948:287-44948:301.
- --8804010127 Notice of consideration of issuance of amends to Licenses NPF-10 & NPF-15 & opportunity for healing to 871214 & 880126 requests for proposed changes to Tech Specs, including revising Figure 3.1-2, "Regulating Control Elament ..." ROOD,H. Project Directorate V. 88/03/23. https://doi.org/10.1007/23.1009.44848:292-44948:301.
- 8804080231 Informs that Allegation Packago ATS RV-88-A-011 being forwarded to utilifor detailed evaluation, investigation & response. KIRSCH,D.F. Region 5, Otc. of the Director. 88/04/01. BASKIN,K.P. Southern California Edison Co. 1p. 45116 184-45116;184.
- 8804110202 Forwards revised justification for continued operation w/C-E steam generator tube plugs Discussion of ringt philosophy re-continued operation of either Unit 2 or 3 in event of steam generator tube leak also addressed. MEDFORD,M.O. Southern Carifornia Edison Co. 88/04/05 Document Control Branch (Occument Control Desk). 23pp. 45135:082-45135.104
- 8804190401 Notifies that changes addressed in Change Notice 25 to Amend 10 to SCE-1-A, "OA Program" (evidwod & found acceptable per 10CFR50,App B. KIRSCH,D.F. NRC No Deteiled Affiliation Given. 88/04/05. 8ASKIN,K.P. Southern Carlfornia Edison Co. 1p. 45155:170-45155:170.
- 8804080088 Generic Lir 88.07 to power reactor ficensees & applicants re-modified enforcement policy concerning 10CFR50.48, "Environ Qualification of Efectrical Equipment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804190126 Forwards request for additinto re implementation of reactor coolant pump trip criteria.per TMI Action Item II.K 3.5. HICKMAN.D.E. Project Directorate V. 68/04/12 BASKIN,K.P. Southern California Edison Co. COTTON.G.D. San Diego Gas & Electric Co. 4pp. 45164:304-45164:307.

- 880422D152 Requests addition to shuldown action requirements omitted from Tech Specs 3.0.1 & 3.0.3. HICKMANDE. Project Directorate V 88/04/13 BASKIN,k P. Southern California Edison Co. COTTCN,G.D. San Diego Gas & Electric Co. 2pp. 45201:112-45201.113
- Edison Co. COTTCN.G.D. San Diego Gas & Electric Co. 2pp. 45201:112-45201.113
- 8804210187 Provides addlinfo to Proposed Change Notice PCN-234 to change Tech Specs to increase max safety injection tank natiogen gas cover pressure, per NRC 880223 request MEDFORD.MO Southern California Edison Co 88/04/14 Document Control Branch (Document Control Besk). 2pp. 45194 175-45194:176
- 8804280447 Informs that util 880227 proposed change to Tech Spec Table 3.7-1 to remove steam line safety valve number designations & onlice sizes from table not acceptable. HICKMAN,D.E. Project Directorate V. 88/04/18. BASKIN,K.P. Southern California Edison Co. 2pp. 45263.064-45263:065.
- 8804280377 Responds to util 871120 request for approval of changes to decay times associated w/control element assembly calculator penalty factors Reported net reduction in core met frequency does not warrant further NRC evaluation KNIGHTON,G W. Project Directorate V. 88/04/21. BASKIN,K P. Sculhorn California Edison Co. Spp. 45245-357-45245:361.

Q. Inspection reports, IE Bulletins & correspondence

- 8884120442 Forwards Insp. Repts. 50-205/88-06.50-351/88-06. 8. 50-352/88-06. on. 860229-0304 & notice of violation. WENSLAWSKIF A. Region 5, Oic of the Director. 88/03/24. BASKINK P. Southern Californ a Edison Co. 2pp. 45132-135-45132-146.
- ••8804120458 Insp. Repts. 50:206/88-06.50-361/88-06. & 50:392/88-06 on 680229-0304 Violations noted Major areas inspected meritaining exposures ALARA & Unit 1-occupational exposure during outages & tours of licensee facilities. RUSSELL_J.E., YUHAS,G.P., Region 5, Old of the Director, 88/03/24, 9pp. 45132-138-45132-148.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors" Svc list and ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp. 44995;128-44905;246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees:Lack of Mgt Controls Over Liconsed Programs" Svc I at enct. CUNNINGHAM, R E. Division of Industrial & Vedical Nuclear Salety (Post 870729) 887 03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353
- 8804190131 Forwards Insp. Repts 50:208/68:07,50:361/86:07 & 50:362/88:07 on 680308:11 & notice of violation.

 WENSLAWSKI,F.A. Region 5, Ofc of the Director 88/04/01. BASKIN,K.P. Southern California Edison Co. 2pp. 45196
- ---8804190132 Notice of violation from inspirence 860308-11.Violation noted: Independent audit of emergency preparedness program cot performed since 861201. WENSLAWSKI,F.A. Region 5, Old of the Director. 88704701 tp. 45198-266-45186-266
- -8804190134 Insp Repts 50:206/88 07:50:361/88-07 8 50:362/88-07 on 880308-11. Violations noted Major areas inspected operational status of emergency preparedness program & Insp Procedure 88701.
 GOOD G.M., FISH,R.F. Region 5, Ofc of the Director. 88/03/29 11pp. 45196 267-45196 277.
- 8804120318 Ack receipt of 880331 ftr informing NRC of steps taken to correct wolations noted in Insp Rept 50:362788-04 WENSLAWSKI,F.A. Region 5, Otc. of the Director, 88/04/06 BASKIN,K.P. Southern California Edison Co. 1p. 46099:263-45099:267
- -8804130064 Responds to NRC 880303 ltr re violations noted in Insp Rept 50:362/88-04. Carrective achievs indepth sudit of 10CFR71, Subpart II requirements added to master audit schedu's for 1988 & to be conducted during Fourth Quarter 1988. BASKIN,K.P. Southern California Ecison Co. 88703731. MARTIN,J B. Region 5, Otc of the Director. 4pp. 45090:284-45099.287.
- 8804010256 NRC Info Notice 88:011, "Potential Loss of Motor Control Ctr & for Switchboard Function Due to Faulty Tie Bolls." Svc 1st enct. ROSSI, C.E. Division of Operational Events Assessment (Post 870411). 89/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408:292-45407:051.
- 8804210412 Responds to NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakers". Review conducted & confirmed that Westinghouse DS-208.DS1-206.DS 416 DS1-1416 or DS-420 circuit breakers not utilized as reactor trip breakers. PILMER,D.F. Southern California Edison Co. 88/04/09 MARTIN,J.B. Reg on 5, Circ of the Director. 2pp. 45227:212-45227:213.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svo. list encl. ROSSI.C.E. Oxision of Operational Events Assessment (Post 670411), 89/04/12, Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150.
- 8804190230 Forwards safety evaluations accepting util final flow pressure turbine disc inspire repts,per util 860620 & 870323 litis.License Conditions 2.C(15) & 2.C(13) complete.Util commitment to implement milg inspire
- --8804 190249 Safety evaluation accepting util inspiral flow pressure turbine rotors Results of exam show no evidence of stress corrosion cracking in disc bore region and dowel holes NRC concludes that License Condition 2 C(13) complete.
 Office of Nuclear Reactor Regulation, Director (Post 870411), 69/04/12 8pp 45155 282-45155 287.

8804210497 Advises that 870918 response to NRC Bulletin 87 001 re-program for mor toring Inchness of ppe waits in high encrysing a phase & two phase carbon steel piping sys being used to determine extent of industry participation. HICKMAN.DE Project Directorate V 88704/15 BASKIN.K.P. Southern Californ a Edison Co COTTON.G.D. San Diego Gas & Electric Co 3pp. 45192/201-45192/203

R. Periodic operating reports & related correspondence

8804200137 Monthly operating repts for Mar 1988 W/880414 ltr.
SIACORER, MORGAN, HE Southern California Edison Co. 8B/03/31 11pp.
45221 086-45221 096.

S. Reportable occurrences, LERs & related correspondence

8804060246 LER 88:003:00:on 880301, discovered that containment emergency cooling subsystem watve exceeded time period for completing quarterly stroke test required by Tech Spec, Caused by personnel error Procedure rovised Wy880331 ltr. MORGAN, HE Southern California Edison Co. 88/03/31, 7pp. 45046:131-45046:137.

OOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

8803250263 Forwards Insp. Repts 50:348/88-06 & 50:364/88-06 on 890229- 0304 & notice of violation COLLNS.D.M. Region 2, Old of the Director, 88/03/18, MCDONALD.R.P. Alabama Power Co. 2pp. 44920 001-44920 013

-8803250265 Notice of violation from insp. on 880229-0304.Violation noted personnel designated as operations shift aide, appointed by Interim emergency director, did not receive required annual retraining for communications personnel. COLLINS.D.M. Region 2, Otc of the Director, 88/03/18 2pp. 44920.003-44920.004.

--8803250266 Insp Repts 50:348/88-06 & 50:364/88-06 on 880229-0304. Violations noted Major areas inspected operational readiness of site emergency preparedness program 8 to determine if changes to emergency preparedness meet NRC require-

GOODEN,A Region 2, Ofc of the Director, 88/03/16 9pp. 44920.005-44920.013.

8803300029 Revised emergency plan implementing procedures including Rev. 18 to FNP-0-EIP-10, "Evacuation & Personnel Accountability," Rev. 19 to FNP-0-EIP-16, "Emergency Equipment & Supplies" & Rev. 54 to FNP-0-EIP-8, "Emergency...." W/880322 tr HUDSPETH J.B. Alabama Power Co. 88/03/22, 200pp. 44968:354-44967;237.

8804070039 Advises that GO-EIP-121 being voided All items in procedure incorporated into Rev 5 of GO-EIP-118, "CCD Corporate Activation & Notification Procedures." HARRISR: Alabama Power Co. 88/03/24. Region 2, Ofc of the Director. 1p. 45022 128-45022:128.

8804070285 General Old Emergency Implementing Procedure GO-EIP-112, "Emergency Mobile Communications" W/880324 ltr. Mobile Communications "W/880324 ltr.
MCGOWAN,J.W., HARRIS,R. Alabama Power Co. 88/03/24. 11pp 45021:173-

8804060262 Forwards Insp. Repis 50:348/88-07 & 50:364/88-07 on 880211:0310 No violations or deviations noted VERELLIJ.D.M. Region 2, Olc of the Director. 88/03/28. MCDONALD.R.P. Alabama Power Co. 2pp. 45048:125-45048.132

-8804050267 Insp Repts 50:348/88 07 & 50:364/88 07 on 880211-0310 No violations 880460267 Insp repts 50-349780 or a 50-304780 or of 11 documents of 120-304780 or devalopes noted Major areas Inspected:review of monthly surveillance & maint observations, radiological protection program & physical security program.

88ADFORD.W.H. Region 2, Olc of the Director. 88/03/28 6pp. 45048.127-

8804200057 Rev. 12 to Emergency Plan Implementing Procedure FNP-O-EIP-15, "Emergency Dnils." WOODARD, J.D. Alabama Power Co. 88/03/29, 9pp. 45226 262-46226 270

8804080086 Responds to DM Collins 880219 Iti re FEMA analysis of prompt alert & notication sys for facility.Details of util review of FEMA Iti & questions re FEMA

MCDONALD,R.P. Alabama Power Co. 88/03/31. Document Control Branch (Document Control Desk). 26pp. 45098 278-45098:304.

8804140093 Forwards Rev 8 to GO-EIP-122, "Emergency Mobile Communications," per

BO Reves 8 70821 It.

MCCRACKEN,K.W. Alabama Power Co. 88/03/31, Document Control Branch (Document Control Desk). 1p. 45169 331-45169:340.

8804110121 Responds to violations noted in Insp. Repts 50-348/88-06 & 50-384/88-06 Corrective actions assessment will be made to ensure that training defined for all personnel w/responsibilities under emergency ptan.

MCDCNALD,R P. Alabama Power Co. 88/04/04. Document Control Branch (Document Control Desk). 2pp. 45135.080-45135.081.

8804110134 Forwards Rev 15 to security plan Rev withheld.

MCDONALD,R P. Alabama Power Co. 88/04/05, Document Control Branch (Document Control Desk), 1p, 45129.228-45129:228.

8804130255 Rev 20 to Emergency Plan Implementing Procedure FNP-0-EIP-16, "Emergency Equipment & Supplies."

* Alabama Power Co. 88704/07, 85pp. 45137.018-45137:103.

8804270061 Revised emergency plan implementing procedures including Rev 6 to GO-EIP-101, "Corporate Emergency Organization" 8 Rev 3 to GO-EIP-137, "Siren Sys Testing & Maint," W/880411 ltr.

HARRIS,R. Alabama Power Co. 88/04/11, 29pp. 45241:174-45241:202.

8804200043 Forwards reprinted Rev 8 to Emergency Plan Implementing Procedure GO-EIP-112, "Emergency Mobile Communications." Procedure transmitted as uncon-trolled per EA Reeves 870821 ltr. MCCRACKEN,K.W. Alabama Power Co. 88/04/12. Document Control Branch (Docu-ment Control Desk). 1p. 45231:072-45231:081.

-880420045 Repr.nted uncontrolled Ray 8 to Emergency Plan Implementing Procedure GO EIP-112, "Emergency Mobile Communications" MCGOVEN,J W. Alabama Power Co. 88/03/23, 9pp. 45231.073.45231.081.

8804200473 Partial response to FOIA request re fire protection Forwards App E documents App 0 & E documents available in PDR App F document completely withheld (ref FOIA Exemption 5).

GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 88/04/14, JONES.C.R.

--8804200679 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50 App R-type inspiror each facility to assess status of compliance w/ 10CFR50 48 Program listed.
CONLON,T.E. Region 2, Otc of the Director, 84/11/06, HERDT,A.R. Region 2, Otc of the Director, 3pp. 46206,176-45206;178.

Affiliation Not Assigned 5pp. 45206.037-45206.043.

8804270296 Rev 5 to General Cfc Emergency implementing Procedure GOP-EIP-116, "Emergency Operations Facility Shift Turnover," W/880414 ltr. MCGOWAN,J.K., HARRIS,R. Alabama Power Co. 88/04/14. 32pp 45242:291-45242 322

8804250126 Revised emergency plan Implementing procedures, Including Rev 5 to GO-EIP-116, "Emergency Operations Facility Shift Turnover" & Rev 6 to GO-EIP-101, "Corporate Emergency Organization." W7880415 ltr. MCCRACKEN

8804260024 Forwards Insp Repts 50:348/88:09 & 50:364/88:09 & notice of yielation. CLINE,W.E. Region 2, Ofc of the Director. 88/04/19, MCDONALD,R.P. Alabama Power Co. 2pp. 45318-148-45318-152.

-- 8804260029 Notice of violation from Insp. on 880321-24. Violation noted cabinet containing safeguards into insecure & unattended CLINE, W.E. Region 2, Oic of the Director, 88/04/19, 2pp. 45313:150-45318:151

~8804280034 Partially withhold Insp Repts 50:346/88:09 & 50:364/88:09 on g80321:24 (ref 10CFR2.790 & 73:21). Violation noted Major areas inspected security organization records repts testing, maint locks keys, combinations & physical barriers THOMPSON,D.H. Region 2, Ofc of the Director, 88/04/13, 1p. 45316:152-45318:152.

J. Insurance & Indemnity Information

8804110147 Submits verification of property insurance coverage par 10CFR50.54 w(2) nuclear property insurance reporting requirement. MCDONALD.R.P. Alabama Power Co. 88/04/01. WOOD.R. NRC - No Detailed Afficiation Given. 1p. 45077:339-45077:339.

M. Antitrust correspondence

8804110264 Natrication of 880406 meeting w/util in Rockville,MD to discuss 2.206 petition antitrust sett'ement issues. REEVES,E.A. Project Directorate II-1, 88/04/05, MURLEY,T., SNI MIRAGLIA,F. NRC - No Detailed Affiliation Given, 2pp. 45079:092-45079:093. SNIEZEK.J.

8804130301 Summary of 880406 meeting w/util & Alabama Electric Power Coopprative in Rockville,MD re-status of settlement proposal presented to NRC in Jan 1968,per 2 206 antitrust proceeding List of attendees encl. LAMBE,WM. Policy Development & Technical Support Branch (Post 870411), 89/04/08 THOMAS,C O. Policy Development & Technical Support Branch (Post 870411), 2pp. 45101:238-45101:239.

P. Operating license stage documents & correspondence

8803240428 Generio Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIAF, J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972;107-44972;163.

8804010194 Summary of 880318 meeting w/ulils in Rockville,MD re info that would be required in submittal of amonds to licenses & CP held by utilis.Attendees list & view-graphs encl.

ADENSAM,E.G. Project Directorate II-1, 88/03/25, Project Directorate II-1, 25pp. 44920.082-44920.106.

8804110277 Forwards list of valves inside containment w/environmentally qualified NAMCO EA-180 limit switches which utilize Raychem/ CHICO seals.per 880401 totron Connectors will be replaced before startup for Unit 1 & during next outage for OMECONALD.R.P. Alabama Power Co. 88/04/04, GRACE,J.N. Region 2, Ofc of the Director. 4pp. 45135:042-45135-045.

8804080088 Generic Ltr 88:07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR60.49, "Environ Qualification of Electrical Equip-ment Important to Salety for Nuclear Power Plants." You faile arcd. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.

8804150188 Discusses 880318 meeting w/utili re proposal to form operating company to handle operation of subj plants. Summary of meeting issued separately. ADENSAM,E.G. Project Orrectorate II-1 88/04/08. LONG,L.B. Southern Company Services, Inc. 18pp. 45141:185-45141:203.

Q. Inspection reports, IE Builetins & correspondence

8803250263 Forwards Insp Repts 50-348/68-06 & 50-364/68-06 on 880229- 0304 & notice of violation.
COLLINS,D.M. Region 2, Oto of the Director, 88/03/18, MGDONALD,R.P. Afabama Power Co. 2pp. 44920.001-44920:013.

- -8803250265 Notice of violation from insp on 880229 0304 Violation noted personnel designated as operations shift aide, appointed by interim emergency director, did not receive required annual retraining for communications personnel. COLLINS,D.M. Region 2, Otc of the Director, 88/03/18, 2pp. 44920 003-44920.004
- -8803250266 Insp. Repts 50:348/88-06 & 50:364/88-08 on 880229-0304. Violations noted Major areas inspected operational readiness of site emergency proparedness program & to determine it changes to emergency preparedness meet NRC require-
- GOODEN,A, DECKER,T.H. Region 2, Ofc of the Director. 88/03/16, 9pp. 44920,005-44920 013
- 8804060094 Ack receipt of 880316 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-316/487-35 & 50-364/87-35.

 JULIAN,C A. Region 2, Otc of the Director 88/03/25 MCDONALD,R P. Alabama Power Co. 1p. 45007 298-45007:298
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tubo Thinning In Westing-house Reactors." Svc list encl ROSSI.CE. Division of Opprational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44095 126-44995 246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensons:Lack of Mgt Controls Over Liconsed Programs." Svc list uncl CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28. Consultdated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804060282 Forwards Insp. Repts 50:348/88:07 8:50:364/88:07 on 880211:0310:No violations or deviations noted VERELLI,D.M. Region 2, Otc. of the Director 88/03/28. MCDONALD,R.P. Alabama Power Co. 2pp. 45048 125-45048:132.
- -8804060267 Insp Repts 50-348/88-07 & 50-364/88-07 on 880211-0310.No violations
- or deviations noted Major areas inspected review of monthly survoillance & maint observations, ratiological protection program & physical security program. BRADFORD W H., MILLER W.H., DANCE, H.C. Region 2, Otc of the Director. 88/03/28.6pp. 45048:127-45048:132.
- 8804040093 Rovisod response to violations noted in Insp. Repts 50-348/87-29 & 50-364/87-29 Corroctive actions procedure implemented to provide documentation of complence w7-deh Spac action requirements involving radiation monitors. MCDONALD,R P. Alabama Power Co. 88/03/29. Document Control Branch (Document Control Dosk). 2pp. 44971:289-44971:290.
- 8804080094 Responds to NRC Bulletin 88-001 ro defects in Westinghouse circuit breakers linsp of all Westinghouse DS-415 reactor trip & bypass breakers completed on 8803008 & results onct. MCDDNALD,R P. Alabama Power Co. 88/04/04. Document Control Branch (Document Control Dask). 3pp. 45116:273-45116-275.
- 8804110121 Responds to violations noted in Insp. Rapts 50:348/88-96 & 50:364/88-96 Corrective actions assessment will be made to ensure that training defined for all parsonnel w/responsibilities under emergency plan MCDONALD,R.P. Alabama Power Co. 86/04/04. Document Control Branch (Document Control Dask). 2pp. 46135.080-45135:081.
- 8804140001 Responds to violations noted in Insp. Ropts 50-348/88-02 & 50-364/88-02.Corrective actions:two workers & foreman restricted from further radiation work
- pending counseling & retraining.
 MCDDNALD,R.P. Alabama Power Co. 88/04/08. Document Control Branch (Document Control Desk). 5pp. 45147:327-45147:331.
- 8804140005 Forwards list of exceptions & positions taken by util during 880217 enforce-ment conference re Insp Repts 50-348/88-02 & 50-364/88-02 Submittat not in re-sponse to 880310 notice of violation. MCDONALD,R.P. Alabama Power Co. 88/04/06. Document Control Branch (Docu-ment Control Desk). 3pp. 45155:028-45155.030.
- 8804010266 NRC Info Natice 88-011, "Potential Loss of Motor Control Cir &/or Switch-board Function Due to Faulty Tia Bolls." Svc list and. ROSSI,CE Division of Operational Evants Assessment (Past 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 46406:292-45407.051.
- 8804150154 Ack receipt of 880321 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-348/88-03 & 50-364/86-03. VERRELLI,D.M. Region 2, Ofc of the Director. 88/04/07. MCDONALD,R P. Alabama Power Co. 1p. 45131:322-45131:322.
- 8804150288 Forwards Insp. Repts 50.348/88-01 & 50.384/88-01 on 880104-07. No vio-lations or deviations noted Ropt also details findings of Repts 50.348/86-05 & 50. 364/86-05,which initially reviewed many allegations. STOHRJP. Region 2, Otc of the Director. 88/04/07. MCDONALD,R.P. Alabama Power Co. 2pp. 45183:135-45183.179.
- ***-8804150299 Insp Repts 50:348/88:01 & 50:364/88:01 on 880104:07.No violations or deviations noted Major greas inspected: allogations to facility. STODDART.P.G., GLOERSEN,W.B., KAHLE,J.B. Region 2, Ofc of the Director. 88/03/31, 43pp. 45183:137-45183:178.
- 8804150411 Forwards corrected cover itr for Insp Repts 50-348/88-07 & 50-384/88-07 on 880211-0310.Ltr dtd 880328 incorrectly listed notice of violation due to administra-
- live oversight.
 VERRELLI,D.M. Rogion 2, Ofc of the Director. 88/04/07. MCDONALD,R.P. Alabama
 Power Co. 2pp. 45138:330-45138.333.
- --8804150425 Corrected lir forwarding Insp. Repts 50-348/88-07 & 50-364/86-07 on 880211-0310 No violations or deviations identified.
 VERRELLI,D.M. Region 2, Olc of the Director. 88/04/07, MCDONALD,R.P. Alabama Power Co 2pp. 45138-332-45138-333.
- 8804150303 Ack receipt of 880329 its informing NRC of steps taken to correct violations noted in Insp Ropts 50-348/87-29 & 50-364/87-29 VERRELLI, D.M. Region 2, Otc of the Director, 68/04/08. MCDONALD,R.P. Alabama Power Co. 1p. 45138-284-45138-284.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc insteric). ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150.

- 8804210474 Forwards summary of 880315 enforcement conference re-environ qualifica-tion of efectrical equipment at facility. List of attendees & handouts also encl. GRACE.J.N. Region 2, Olic of the Director. 88/04/13. MCD
- 8804200473 Partial response to FOIA request re fire protection Forwards App E documents App D & E documents available in PDR App F flocument completely with hold (ref FOIA Exemption 5) GRIMSLEY,D.H. Division of Rules & Records (Post 870413), 88/04/14 JONES,C.R. Affiliation Not Assigned 5pp. 45206:037-45206:043.
- --8804200579 Adwsos that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type insp for each facility to assess statue of compliance w/ 10CFR50 48.Program Issted. CONLON,T.E. Region 2, Oic of the Director. 3pp. 45206:176.45206:178.
- 8804260024 Forwards Insp. Repts 50:348/66:09 & 50:364/66:09 & notice of violation. CLINE,W.E. Region 2, Ofc of the Director. 88/04/19 MCDONALD,R.P. Alabama Power Co. 2pp. 45318:148-45318:152.
- --8804260029 Nolice of violation from Insp on 880321-24. Violation noted cabinet containing sateguards into insecure & unattended.

 CLINE, W.E. Region 2, Ofc of the Director. 88/04/19, 2pp. 45318:150-45318:151.
- --8804260034 Partially withhold Insp Repts 50-348/88-09 & 50-364/88-09 on 880321-24 (rel 10CFR2.790 & 73.21).Violation noted Major areas inspected security organization, records, ropts, lesting, mernt, locks, keys, combinations & physical barriers. THOMPSON, D.H., MCGUIRE, D.R., Reg on 2, Ofc of the Director. 88/04/13. 1p. 45318:152-45318.152.
- 8804280200 Forwards "Tosting of 11 Bolts" & requests addl into re chemical analysis & mechanical tosting of bolts samples obtained during Insp Repts 50-348/87-11 & 50-364/87-11 on 870511-22,including results of review of test data REEVES,E A. Project Directorate II-1, 88/04/21, MCDONALD,R.P. Alabama Power Co 3pp. 45276 309-45276.340
- -8804280217 "Testing of 11 Boils." CZAJKOWSKI,C. Brookhaven National Laboratory, 87/10/30, 29pp. 45276:312-
- 8804290278 Ack receipt at 880406 ltr Informing NRC at steps taken to correct violations noted in Insp Repts 50-348/88-02 & 50-364/88-02.
 GRACE_J.N. Region 2, Oic of the Director 88/04/22. MCDONALD,R.P. Alabama Power Co. 1p. 45282-171-45282-171.
- R. Periodio operating reports & related correspondence
- 8804060626 "JM Ferley Nuclear Plant Unit 2, Annual Rept," for 1987.W/ 880331 ftr. MCDONALD,R P. Alabama Power Co. 87/12/31, 29pp. 45008;301-45008;329.
- 8804190141 Monthly operating rept for Mar 1988 W/880411 ltr. WOODARD.J.D., MCDONALD.R.P. Alabama Power Co. 88/03/31. 9pp 45209.117-45209.25
- S. Reportable occurrences, LERs & related correspondence
- 8803280145 LER 88-002-00:on 890218,Toch Spec 3.0.3 entered when fire damper in filtration sys common suction line closed Caused by personnel error. Design change infillated to ensure proper operation of fire damper Personnel counseled W/880321 lir. WOODARD,J.D. MCDONALD,R.P. Alebama Power Co. 88/03/21, 4pp. 44921:115-
- 8804160032 LER 87:010:01:on 871209.ligak discovered in section of safety injection plaing on RCS Loop B cold leg Causert by detect in weldod joint between long rad us elbow & straight section of pipe.Cooldown commenced W/880411 iff.
 WOODARD.JO., MCDONALD.R.P. Alahama Power Co. 88/04/11. 6pp. 45153:216-
- 804200371 LER 88-004-00 on 880315,fire watch patrol not established as required Shift foroman failed to recognize ponotration reloased to be breached as fire barrier penetralion. Caused by personnol error. Skill foroman counseled Wx880414, WOODWARD, J.D., MCDONALD, R.P. Alabama Power Co. 88/04/14. 4pp. 45220.250-
- 8804220212 LER 87:004:01:on 87:1113,stoam generator tubo degradation discovered.Coased by aniivibration bar wear, primary water stress corrosion cracking in tubeshed teres. OD stress corrosion cracking at support priess. ...W/800418 lir. WCODARD, J D., MCDONALD, R P. Alabama Power Co. 88/04/18. 7pp. 45257:226-
- V. Operator Examinations
- 8804250088 Responds to FOIA request for into re-scores of reactor operators & senior reactor operators. Forwards requalification exam summary source sheets listed in enciapp w/personal privacy into deleted GRIMSLEY,D.H D.vision of Rules & Records (Post 870413), 88/04/19. BOLEY,K. Publio Gillzen's Critical Mass Energy Project. 2pp. 45213.003.45213.005.
- --8804250167 Package of NRC administered requalification exam results summary.
 NRC No Detailed Affiliation Given: 87/07/20, 88pp. 45213.007-45213.095
- DOCKET 50-368 EDWIN I. HATCH NUCLEAR PLANT, UNIT 2
- F. Security, medical, emergency & fire protection plans

- 8803300348 Forwards Insp. Repts 50-321/87-32 & 50-366/87-32 on 871207-10 No violations or deviations noted Areas identified that require further review & followup including emergency preparedness program. STOHR.J.P. Region 2, Otc of the Director. 88/03/08. HEAD,G.F. Georgia Power Co 3pp. 44921 216-44921 243.
- -8803300354 Insp Repts 50-321/87-32 & 50-358/87-32 on 871207-10.No violations of deviations nated Major areas inspected review of selected procedures & representative records & emergency response facilities & related equipment GOCDEN & Region 2, Ofc of the Director, 88/02/19, 25pp, 44921:219-44921:243
- 8803300061 Forwards Insp. Repts 50-321/88-05 & 50-366/88-05 on 880123- 0219 & notice of violation. BROWNLEE,V.L. Region 2, Ofc of the Director, 88/03/10, HEAD,G.F. Georgia Power Co. 2op. 44961-238-44961.252.
- -8803300068 Insp. Repts 50-321/88-05 & 50-366/88-05 on 880123-0219. Violations noted Major areas inspected icensee action on previous enforcement matters,maint observation operational safety verification,plant mods & physical security. HOLMES-RAY-P. Region 2, Ofic of the Director 88/03/07. 11pp 44981-242-44961-252
- 8804010214 Admiss that most of 880101 rev to physical security plan consistent w/ provisions of 10CFR50 54(p) & acceptable Some changes require further chartication & not consistent w/ provisions of 10CFR50 54(p) Encl withheld (ref 10CFR73 21). CLINE.W E Region 2. Oto of the Director. 88703/23. HEAD.G.F. Georgia Power Co. 2pp. 44945 359-44945 360
- 8804120022 Forwards Insp Rept 50-321/88-09 & 50-366/88-09 on 880229-0304. CUNE WE Respon 2. Otc of the Director. 88/03/29 HEAD,G.F. Georgia Power Co 2pp 45128-230-45128-232.
- ~8804120029 Parbally withheld insp. Repts 50:321/88:09 & 50:368/88 09 on 880229-0304 (ref. 10CFR2:790 & 73:21) Major areas inspected plan/procedures.repts/ records.testing/maint, barners.detection aids & compensatory measures. TOB:1t,W. Region 2, Ofc of the Director. 88/03/24, 1p. 45128:232-45128:232.
- 8804250019 Forwards Insp Repts 50-321/88-07 & 50-368/88-07 on 880220-0325 & nette of wolston.

 BROWNLEE, V.L. Region 2, Ofc of the Director, 88/04/12, HEAD,G.F. Georgia Power Co. 2pp. 45268 153-45268-169.
- -8804250024 insp Repts 50-321/88-07 & 50-366/88-07 on 880220-0325. Violations noted Major areas inspected bicensee action on previous enforcement matters coorational safety verification, radiological protection & physical security. HQLMES-RAY,P. Region 2, Ofc of the Director. 88/04/11. 13pp. 45288:157-45288 169.
- 8804200473 Partial response to FOIA request re-fire protection Forwards App E documents App D & E documents available in POR.App F document completely withheld (ref FDIA Exemption 5) GR MSLEY, DH. Division of Rules & Records (Post 870413), 88/04/14. JONES,C.R. Affiliation Not Assigned. 5pp 45206 037-45206 043.
- -8854200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R. type insp for each facility to assess status of compliance w/ 10CFR50.48 Program listed CONLON.T.E, Region 2, Otc of the Director, 84/11/06, HERDT, A.R. Region 2, Otc of the Director, 3pp. 45206,176-45206,178.

I. Financial information

- 8804270175 Forwards 1987 annual financial repts for Georgia Power Co & Southern Co. GUCWALLT Georgia Power Co. 88/04/19. Document Control Branch (Document Control Desk). 2pp. 45260:109-45260:220.
- -6804270182 "Georgia Power Co. 1987 Annual Rept." SCHERER,R.W. Georgia Power Co. 87/12/31, 45pp, 45260,112-45260,158.
- -8804270183 "Southern Co. 1987 Annual Rept." ADDISON,E. L. Southern Co. 87/12/31, 64pp. 45260:157-45260:220.

J. Insurance & Indemnity Information

8804010263 Submits present levels & sources of insurance (or plants,per 10CFR50.54(m)(4) GUCWALT. Georgia Power Co. 88/03/18. Document Control Branch (Document Control Desk) 2pp 45058.096.

P. Operating Reense stage documents & correspondence

- 8803100155 Forwards util 870203 internal memo re inconsistencies noted in NRC 870102 exemption approval its Advisal as to correct staff position requested. RIVENBARK G. NRC No Detailed Affiliation Given. 87/02/10, NRC No Detailed Affiliation Given. 87/02/10, NRC No Detailed Affiliation Given. 3pp
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIA.F.J. Associate Oractor for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp, 44972:107-44972:153.
- graphs enct.
 ADENSAM.E.G. Project Directorate II-1. 88/03/25. Project Directorate II-1. 25pp.
 44920-082-44920-108.
- 8804120043 Notification of 880510 meeting w/util in Rockville,MO to discuss application of seismic margins work. Agenda encl. CROCKERL.P. Project. Directorate II-3. 88/04/05. Project. Directorate II-3. 49ρ. 45089 220-45089 223.

- 8804140037 Provides results of sources a tournest & tost of experiment requests concenses in conjunction w/design change request & tost of experiment requests conpleted during CY97.Licanses reviews grilling botter & edicquate. CROCKER.L.P. Projecto Directorate II-3. 86/04/06. LAINAS.G.C. Assistant D. octor fo Region II Reactors. 21pp. 45120 333-45120 353
- 8804080088 Generic Ltr 89:07 to power reactor licensees 8 applicants re-modified enforcement policy concorning 10CFR50 49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc list encl MIRAGCLAF, J. Associate Director for Projects (Post 870411) 89/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164-285.
- 8804130298 Forwards corrected Page 3/4 3-15 to Amend 91 to License NPF-5. CROCKER.L.P. Project Directorate II-3 88/04/07. HEAD, G.F. Georgia Power Co. 2pp 45103 160-45103:162.
- 8804130304 Corrected Page 3/4 3-15 to Amond 91 to Liconso NPF-5 ro isolation actuation instrumentation
 Project Directorate 11-3, 89/04/07, 1p. 45103.162-45103:162.
- 8804150188 Discusses 880318 meeting w/utilire proposal to form operating company thandle operation of subjiplants. Summary of moeting issued separately.

 ADENSAM,E.G. Project Directorate II-1. 88/04/08. LONG,L.B. Southern Compar. Services, Inc. 19pp. 45141:185-45141:203
- 8804210162 Confirms 880428 mgt mouting in Region II old to discuss plant gerformance Proposed agenda enct. GRACE.J.N. Region 2, Old of the Director, 88/04/11, HEAD,G.F. Georgia Power Co. 3pp. 45194:172-45184.174.
- 8804250041 Provides followup of 880415 request for ratiof from Toch Spe requirements, allowing for one-time extension of 30-tiny limiting condition for operatio for primary contaktment recombiner sys. GUCWALT. Georgia Power Co. 88/04/18. GRACE, J.N. Region 2, Ofc of the Director, 2pp. 45239-213-45239-214.
- 8804290281 Summarizes 880419 mgt mooting in Rogion II ofc ro findings communicated to util by tNPO concerning results of evaluation conducted during was of 800314 if 21.List of attendees and:
 GRACE_J.N. Rogion 2, Ofc of the Director. 88/04/22. HEAD,G.F. Goorgin Power Co. 3pp. 45282.178-45282:180.

Q. Inspection reports, IE Bulletins & correspondence

- 8803300348 Forwards Insp. Repts 50-321/87-32 & 50-366/87-32 on 971207-10.No victations or deviations noted Areas identified that require further review & followup in cluding emergency preparedness program. STOHRJ.P. Region 2, Ofc of the Director. 88/03/08. HEAD,G.F. Georgia Power Cd. 3pp. 44921:216-44921:243.
- **8903300354 Insp Repts 50:321/87:32 & 50:366/87:32 on 871207-10 No violations deviations noted Major areas inspected review of solected procedures & representative records & emergency response facilities & related agrupment. GOODEN,A, DECKER,T.R. Region 2, Ofc of the Director, 88/02/19, 25pt 44921:219:44921:243.
- 8803300061 Forwards Insp. Repts 50-321/88-05 & 50-366/88-05 on 860123- 0219 notice of violation. BROWNLEE,VL. Region 2, Ofc of the Director, 88/03/10, HEAD,G.F. Georgia Power Co. 2pp. 44961:236-44961:252.
- --8803300068 Insp. Repts 50-321/88-05 & 50-366/88-05 on 880123-0219. Violotron noted Major areas inspected licenses ection on provious enforcement matters, mail observation, operational safety verification, plant mode & physical security, HOLMES-RAY, P., MENNING, J.E., SINKULE, M.V. Region 2, Ofc of the Director. 86 03/07. 11pp. 44961.242-44981:252.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westin house Reactors," Syc List encl.
 ROSSIC E. Dulsion of Operational Events Assessment (Post 970411). 86/03/2 Consolidated Edison Co. of New York, Inc. 121pp. 44995 126 44995 246,
- 8803220298 NRC Info Notice 88-010, "Matis Licensees.Lack of Mgt Controls Over I censed Programs." Svc ist enct. CUNNINGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870729). 61 03/28 Consol'dated Edison Co. of New York, Inc. 108pp 44905:247-44995.363.
- 8804050373 Forwards Exam Rept 50-321/OL-88-01 of exam administered on 88020 11 for Units 1 & 2. JULIAN,C.A. Region 2, Ofc of the Director. 88/03/29, HEAD,G.F. Georgia Power C 2pp. 45061:154-45082.024.
- --8804050378 Exam Rept 50:321/OL-88-01 on 880208-11 for Units 1 & 2.Exam r sults:11 senior reactor operators & three reactor operators passed both written & o erating exams.
 BROCKMAN,K.E., MUNRO,J.F. Region 2, Ofc of the Director, 88/03/29, 229p 45061:155-45062:024.
- 8804070023 Responds to NRC 880310 ltr re violations noted in Insp Repts 50-32178 05 & 50-366/98-05.Corrective actions:event review toam formed,caution tags place on intermediate;range monitors & procedures revised. GUCWAL.T. Georgia Power Co. 88/03/29. Document Control Branch (Docume Control Desk). 9pp. 45029.352-45029.380.
- 8804120022 Forwards Insp Rept 50-321/88-09 & 50-366/88-09 an 880229-0304. CLINE,W.E. Region 2, Oic of the Director. 88/03/29. HEAD,G.F. Georgia Power C 2pp. 45128:230-45128:232.
- --9804120029 Partially withheld Insp Repts 50-321/88-09 & 50-366/88-09 on 88022 0304 (ref. 10CFR2.790 & 73.21).Major areas inspected;plan/procedures,rept records,testing/maint, bacriers,detection aids & compensatory measures. TOBIN,W., MCGUIRE,D.R. Region 2, Old of the Director, 88/03/24, 1p. 45126:23

- Jaions or deviations noted. HERDT, A.F. Rogion 2, Olic of the Director, 88/03/31, HEAD,G.F. Georgia Power Co 2pp 45034.053 45034.064. 8804050377 Forwards Insp Repts 50-321/88-03 & 50-366/88-03 on 880201-05 No vio-
- -8804050385 insp Repts 50-321/88-03 & 50-366/88-03 on 880201-05 No violations noted Major areas inspected salsmic analysis for as built safety-related plping sys & Mark I containment long-term program mod. Cri/OURC, BLAKE,R.P., CARRION,R.P. Region 2, Oic of the Director. 88/03/23 10pp. 45034.055-45034.064.
- lations or deviations noted. HERDT.A. Region 2, Ofc of the Director, 88/04/04, HEAD,G.F. Georgia Power Co 2pp. 45132:166-45132:175. 8804120050 Forwards Insp Hopis 50-321/68-08 & 50-366/68-08 on 880307-11 No vio-
- -8804120054 Insp Repts 50 321/88 08 & 50 366/88 08 on 880307-11 No violations or deviations noted Major areas inspected areas of complex surveillance testing & IE bulletin followup TINGEN,S.G., JAPE,F. Region 2, Ofc of the Director 88/04/01. 8pp. 45132.168-
- 8804120096 Forwards request for addl into re util responses to IE Bullotin 85:003, "Motor Operated Valve Common Mode Failures During Plant Translents Due to Improper Switch Settings." Into requested within 30 days of tir date. HERDT.A.R. Region 2, Ofc of the Director, 88/04/04, HEAD,G.F. Georgia Power Co 3pp. 45135:314-45135:316.
- 8804010256 NRC Info Notice 88:011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts," Syc list encl. HOSSLCE. Division of Operational Events Assessment (Post 870411). 88/04/07 Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804130275 Responds to NRC Bullotin 88:001, "Defects in Westinghouse Circuit Broakers." No Westinghouse Models DS-206,DSL-206, DS-416,DSL-416 or DS-420 breakers in Class 1E circuits at Halch. GUCWALT. Georgia Power Co. 88/04/07. Document Control Branch (Document Control Desk). 5pp. 45154.085-45154:069.
- 8804190021 Discusses SALP Repts 50-321/86-42 & 50-366/86-42 & forwards view-graphs from 870406 mosting.Util 870508 written comments have been roviewed.Proposed improvements will be monitored during future insp. GRACE_3.N Region 2, Otc of the Director, 88/04/11, HEAD,G.F. Goorgia Power Co. 23pp. 45199.052-45199.074.
- 8894960370 NRC Info Natice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl.

 ROSSICE: Division of Operational Events Assessment (Post 870411). 88/04/12
 Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150.
- 8804250019 Forwards Insp Repts 50-321/88-07 & 50-366/88-07 on 880220-0325 & natice of violation. BROWNI EE V. L. Region 2, Ofc of the Director, 88/04/12, HEAD.G.F. Georgia Power Co. 2pp. 45268:153-45268:169.
- -8804250023 Notice of violation from insp on 880220-0326-Violations noted failure to perform functional test of APPIM flow ref thermal power & APPIM downscale trips & lature to follow Surveillanco Procedures 578V-SUV-007-2S & 578V-D11-016-15. BROWNLEE,V.L. Heglon 2, Oto of the Director. 88/04/12. 2pp, 45268:155-45268-156.
- -8804260024 Insp Repts 50-321/66-07 & 50-366/68-07 on 880220-0325. Violations objectives in spiriting in the property and the property of th
- 8804200473 Partial response to FOIA request re tire protection.Forwards App E documents App D & E documents available in PDR.App F document completely withheld (rel FOIA Exemption 5).
 GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 88/04/14, JONES,C.R. Affiliation Not Assigned, 5pp. 45206.037-45208.043.
- -8604200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type insp for each facility to essess status of compliance w/ 10CFR50.48 Program listed. CONLON,I.E. Region 2, Ofc of the Director. 84/11/06. HERDT,A.R. Region 2, Ofc of the Director. 3pp. 45206:176-45206:178.
- 8804270244 Responds to NRC 880308 itr re violations noted in Insp Repts 50:321/87-32 & 50:366/87-32 Corrective actions primary dose assessment code purchased from See a 2000007-22-Corrective actions primary dose assessment code purchased from vendor in mid 1980s.

 GUCWA,L.T. Georgia Powor Co. 88/04/18. Document Control Branch (Document Control Desk). 8pp. 45244:238-45244:243.
- R. Periodic operating reports & related correspondence
- 8804040044 "Annual Environ Surveillance Rept for 1987." W/880329 IIr. GUCWA,L.T. Georgia Power Co. 87/12/31, 234pp. 45016-215-45017.088.
- 8804110024 "Augmented Radiological Surveillance Mon-tering," for 1987. W/880331 ltr. GUCWA,L.T. Georgia Power Co, 87/12/31. Document Control Branch (Document Control Dask), 18pp. 45128:160-45128:177.
- 8804190118 Monthly operating repts for Mar 1988.W/880411 ltr. BEARD,R.M., GUCWA,L.T., Georgia Power Co. 68/03/31, 13pp. 45209.160-45209:172,
- S. Reportable occurrences, LERS & related correspondence
- 8804040242 LER 87-004-01:on 870616,HPCI determined incapable of performing intended safety function.Caused by defective procedure & personnel errors.Equipment replaced,checked & calibr & as built notice issued W/880235 ltr.
 BAKEH,R.D., GUCWA,L.T. Georgia Power Co. 88/03/26. 14pp. 44971:215-44971:228.

- 8804080051 LER 88-005-00 on 880305 instruments remained inoperable for longer than permitted by Tech Specs.Caused by personnal error in failing to comply w/procedure Procedure rovised & plant personnal counselled W/680331 ltr. HEIDT.J.D., GUCWA,L.T. Georgia Power Co. 88/03/31, 11pp. 45100.097-45100.107.
- 8804270003 LER 88 009:00 on 880321,local feak rate test missed resulting in condition prohibited by Tech Specs Caused by personnel error. Test performed & penetrations declared operable W/680418 ltr.
 HEIDT.J.D., GUCWA.L.T. Goorgia Power Co. 89/04/18 13pp. 45282.084.45282.096.
- 8804270057 LER 88 006:00:cn 880318 unplanned screm occurred & main steam line iso'ation valve tailed to close Scram caused by deficiency in procedure Cause of valve to ture unknown. Procedure revissued.W/880418 ltr. HEIDT,J D., GUCWA,L.T. Georgia Power Co. 88704/18, 12pp. 45253:289-45253:300.

V. Operator Examinations

- 8804050373 Forwards Exam Rept 50-321/QL-88 01 of exam administered on 880208-11 for Units 1-8-2. JULIAN.C.A. Region 2, Ofc of the Director. 88/03/29 HEAD,G.F. Georgia Power Co 2pp. 45081:154-45082 024.
- 8804250088 Responds to FOIA request for info re scores of reactor operators & senior reactor operators Forwards regulal fication exam summary source sheets listed in enci. app w/personal privacy info deleted
 GRIMSLEY,D.H. Division of Rules & Records (Post 870413) 89/04/19. BOLEY,K.
 Public Citizen's Critical Mass Energy Project. 2pp. 45213-003-45213 095
- --8804250167 Package of NRC edministered requalification examinesults summary.

 NRC No Detailed Affiliation Given. 87/07/20: 88pp. 45213:007-45213:095.

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8803290313 Rovised emergency plan implamenting procedures (EPIPs), including Rev 4 to 1903.04, "Administration & Maint of EPIPs," Rev 15 to 1903.23, "Personnel Emergency" & Rev 14 to 1903.50, "Emergency Response Organization" Arkansas Power & Light Co. 88/01/12 25pp. 44982:185-44962
- 8804070151 Rev 6 to "Arkensas Nuclear One Emergency Plan." W/880330 ltr. HOWARD₆D.R. Arkensas Power & Light Co. 88/03/01, 46pp. 45044-028-45044:075.
- 8803290318 Rev 4 to Emergency Plan implementing Procedure 1903.54, "Requests for Arkansas Power & Light Co. 88/03/17, 9pp. 44915 320-44915 328.
- 8804210168 Responds to violation noted in Insp Repts 50:313/88:01 & 50:368/88-01.Corrective action c'oth rags removed from room, rubber hoses used for routine maint in room returned to metal storage container & fire watch posted. LEVINEJ JM. Arkansas Power & Light Co. 88/04/07. CALLAN,L.J. Region 4, Ofc of the Director. 3pp. 45219:169-45218 171.
- 8804210054 Supplemental application to 861212 & 871204 applications for amend to Ucense NPF-8 re administrative control. Changes denote ingli responsibility for emergency preparedness & fire protection function on plant organizational chart CAMPBELLTG. Arkansas Power & Light Co. 88/04/14. Document Control Branch (Occument Control Desk). CALVO JA. Division of Reactor Projects III,IV,V & Special Projects (Post 870411), 5pp. 45238:305-45238:312.
- --8804210057 Proposed Tech Specs noting mgt responsibility for emergency preparedness & fire protection function on plant organizational chart & specifying allowable range for SRC membership.

 *Arkansas Power & Light Co. 66/04/14. 3pp. 45238.310-45238.312.

J. Financial Information

880420085 "Arkansas Power & Light Co. 1987 Annual Rept." W/880412 ltr.
MAULDEN.J.L., HOWARD.D.R. Arkansas Power & Light Co. 87/12/31, 49pp.
45226:094-45226:194-

J. Insurance & Indemnity information

- 804060372 Forwards ANI certificates of insurance for MAELU Policies 5253,TA6002,X87139 & XTA5246 as evidence of util primary & excess nuclear property damage insurance coverage. HOWARD,D.R. Arkansas Power & Light Co. 88/03/31, WOOD,R. Document Control Branch (Document Control Dock). 5pp. 45006.323-45006.327. 8804060372
- 8804190374 Forwards Endorsement 74 to NELIA Policy NF-210 & Endorsement 63 to MAELU Policy MF-74.
 SAMUELS, J.L. Marsh & McLennan, Inc. 88/04/08. DINITZ, I. Office of Nuclear Reactor Regulation, Director (Post 870411). 6pp. 45164:163-45164:167.
- 8804200420 Forwards Endorsements 1 & 2 to NELIA Policy NW-116 & MAELU Policy
- MW-47.
 SAMUELS, J.L. Marsh & McLennan, Inc. 88/04/12. DINITZ,I. Office of Nuclear Reactor Regulation, Director (Post 870411). 21pp. 45226 235-45226 255.

P. Operating license stage documents & correspondence

8803080483 Forwards request for addl info re 861124 response to Generic Ltr 86.06/im-plementation of TMI Action Item II.K 3.5, "Automatic Trip of Reactor Coolant Pumps." Response requested within 50 days of ltr date. DICK,G.F. Project Directorate IV. 88/03/02. CAMPBELL,T.G. Arkansas Power & Light Co. 4pp. 44639.021-44639.024.

- 8803240426 Generic Etr 88 06 to all power reactor licensoes & applicants re removal of organization charts from Eech Spec administrative control requirements Svc list encl M.RAGLIA, F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972 107-44972-153
- 8803300117 Documents 680322 meeting w/u/i*List of attendees enci. CALLAN,L J. Region 4, Old of the Director, 88703723 CAMPBELL,G, Arkansas Power 8 Light Co. 2pp. 44982:099-44962:099.
- 8803310114 Ack receipt of 880129 fit re-summary of progress made toward identifica-tion & correction of discrepancies Requests that NRC should be notified of any ex-tremity or skin exposures that exceed any 10CFR20 exposure imits CALLAN,L.J. Region 4, Ols of the Director, 68/03/25. CAMPBELL,G. Arkansas Power & Light Co. 2pp. 44967:337-44967:338
- 8804140034 Forwards Amend 83 to License NPF-6 & safety evaluation Amend mortifies Tech Specs to permit util to render 8 of 10 main sleam safety valves inoperable & reset 2 remaining valves in Mode 3 for 10 yr hydrostatc test on sys DICK,G.F. Project Directorate IV. 88/04/06 CAMPBELL,T.G. Arkansas Power & Light Cq. 4pp. 45104:144-45104:154
- --8804140050 Amend 83 to License NPF-6,modifying Tech Specs to permit util to render 8 of 10 main steam safety valves inoperable & reset 2 valves in Mode 3 for 10-yr hydrostetic test on mein steam sys. CALVOJ, A, Project Directorate IV. 68/04/06 4pp. 45104.148-45104.151.
- 8804140054 Safety evaluation supporting Amend 83 to License NPF 6.
 Project Directorate IV. 88/04/06, 3pp. 45104:152-45104:154.
- 8864190046 Corrected ltr forwarding Amend 83 to License NPF-6 & safety evaluation Amend pormits utilities render 8 of 10 main steam safety valves inoperative 8 reset remaining two valves in Mode 3 to perform 10-yr hydrostelic test on main steam sys.
 DICK,G.F. Project Directorate IV. 88/04/06, CAMPBELL,T.G. Arkansas Power & Light Co. 3pp. 45158 266-45168.274.
- 880408088 Generic Ltr 88-07 to power reactor licensies & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc 1st encl. MIRAGE IA.F.J. Associate Director for Projects (Post 870411) 88/04/07. Consolidated Edison Co. of Now York, Inc. 48pp. 45164.237-45164:285
- 8804210054 Supplemental application to 881212 & 871204 applications for amend to License NPF-5 re administrative control Changes denote mgt responsibility for emergency preparedness & fire protection function on plant organizational chart. CAMPBELL,T.G. Arkenses Power & Light Co. 88/04/14. Document Control Branch (Document Control Besk), CALVO, J.A. Division of Reactor Projects (Post 870411). 5pp. 45238:305-45238:312
- -8804210057 Proposed Tech Specs noting mgt responsibility for emergency preparedness & fire protection function on plant organizational chart & specifying allowable range for SRC membership. Arkansas Power & Light Co. 88/04/14, 3pp. 45238.310-45238.312.

O. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 97-044, "Thimble Tube Thinning in Wosting-house Reactors," Sve list end.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/03/28, Consolidated Edison Co. of New York, Inc. 121pp. 44995 126-44995 248.
- 8803220296 NRC Info Notice 88-010, "Mattis Licensees Lack of Mgt Controls Over Li-censed Programs," Suc list encl. censed Programs "Suc list encl CUNNINGHAN,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 88/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353
- 8804120418 Requests that violation noted in Insp Ropts 50-313/86-34 & 50-368/88-34 be willidiawn No volation occurred Util will treat insp team Inding as identification of potential weakness Reasons end Encl withheld (ref 10CFR73.21). IEVINE JN. Arkanses Power & Light Co. 88/03/28. CALLAN, L.J. Region 4, Ofc of the Director. 2pp. 45154 057.45154 058.
- 8804200343 Responds to violations noted in Insp. Repts 50:313/87:39 & 50:368/87-39 Corrective actions additional personnel assigned to plant I-censing section & man-hours increased temporarily to roduce backlog. LEVINE.J.M. Arkansas Power & Light Co. 88/04/04. CALLAN,L.J. Region 4, Ofc of the Director. 4pp. 45174:165-45174;168.

- 8804120365 Ack receipt of analytical results transmitted by 880222 ltr re-feedwater, steam generator blowdown & bonc acid batch tank samples collected & noted in Insp Repts 50-313/87-33 & 50-369/87-33 on 871116-20.8Nt results not yet tecewed.
- CALLAN, L. J. Rogion 4, Orc of the Orector, 88/04/08, CAMPBELL, G. Arkansas Power & Light Co. 2pp. 45089 322-45089.323.
- 8804010256 NRC Into Notice 88-011, "Potential Loss of Motor Control Cir &/or Switch-board Function Due to Faulty Tie Bofts." Svc fist end. ROSSI,C E. Division of Operational Events Assessment (Post 870411), 88/04/07 Consolidated Edison Co. of New York, Inc. 124pp. 45408-292-45407.051.
- 8804210168 Responds to violation noted in finsp Repts 50-313/88-01 & 50-388/88-01 Corrective action cloth rags removed from room, rubber hoses used for routine maint in room returned to metal storage container & tire watch poster.

 LEVINEJ.M. Arkansas Power & Light Co. 88/04/07. CALLAN, L.J. Region 4, Ofc of the Director, 3pp. 45219:169-46219-171.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc Lst enci.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/12.
 Consolidated Edison Co. of New York, Inc. 123pp. 45165 028-45165:150.
- 8804210317 Forwards Insp Repts 50:313/88:08 & 50:368/88:06 on 880222:0317 &
- notice of violation.

 CALLAN,L J. Region 4, Ofc of the Director, 88/04/14, CAMPBELL,G. Arkansas Power & Light Co. 2pp. 45231:150-45231:164.

- --8804210321 Notice of v.o'aton from insp on 880222-0327 Violation noted on 880226-replacement of Relay 63X/4926 & Relay 94-0340-2 Initiated w/o approved job order NRC inspectors observed housekeeping discrepancies on fuel handing bridgo 'Region 4, Ofc of the Director 88/04/14, 2pp. 45231:152-45231:153
- --9804210326 Insp Repts 50-313/88-06 & 50-369/88-06 on 880222-0327 Velations noted Major areas inspected operational safety verification maint surveillance, allegation followup & generic ftr followup JCHNSCN, W.D., HARBUCK, C.C., HAAG, R.C., Region 4, Ofci of the Director, 88/04/ 13 11pp 45231 154-45231 164
- 8804250045 Forwards Insp Repts 50:313/88-07 & 50:368/88-07 on 880307-11 No violations or deviations noted.

 CALLAN,L.J. Region 4, Ofc of the Director 88/04/15 CAMPBELL,G Arkansas Power & Light Co. 2pp. 45254 181-45254:189
- -8804250050 Insp Hepts 50-313/88-07 & 50-368/88-07 on 880307-11 No violations of 45254 183 45254 189.
- 8804260023 Forwards thisp Repts 50:313/88:02 & 50:368/88:02 on 880221-26 & notice of violation. Actions taken in response to previously identified findings also examined & discussed in Peragraph 4 of rept. CALLAN, L. J. Region 4, Oto of the Director. 88/04/15. CAMPBELL, G. Arkansas Power & Light Co. 2pp. 45254 313-45254.324
- --8804260027 Notice of violation from Insp on 880221-26 Violation halled recitation
 - Survey instruments inadequate for measuring lower dose rate limits for identifying radi-ation areas outside controlled access & areas not properly posted.
 * Region 4, Ofc of the Director, 88/04/15, 2pp. 45254,315,45254,316.
- -8804260031 Insp Repts 50-313/88-02 & 50-368/88-02 on 880221-26. Violation noted.Major areas inspected.radiation protection activities during Unit 2 refuelling outage: CHANEY,H.D., MURRAY,B. Region 4, Old of the Director 8B/04/08, 8pp. 45254:3 1 7-

R. Periodic operating reports & related correspondence

- 8804250341 Monthly operating rept for Mar 1988 W/880412 ltr HARRISON,D.F., HOWARD,D.R. Arkensas Power & Light Co. 88/03/31 7pp. 45254:190-45254:197.
- S. Reportable occurrences, LERs & related correspondence
- B804060211 LER 88-001-00.on 850429 leakage discovered in two selecoid operated valves while performing containment test Caused by inadequate post-installation voorst-cation testing Valves removed & reinstalled in reverse condition W/880328 in WICHALK P.L., LEVINE,J.M. Arkenses Power & Light Co. 88/03/28, 7pp. 45048,158-45046:164.
- 8804130399 LEH 88:005:00:on 880319:continuous fire watch personnel found asleep Cause not stated Personnel immediately releved and omploymont terminated. Fire watch personnel now rotated at 30-moute intervals w//800407 tr. M. CHALK.P.I... LEVINE.J.M. Arkansas Power & Light Co. 88/04/07 2pp 45146:358-45146:359
- 8804200014 LER 88:003:00.on 880310.unplanned automatic actuation of ESFAS occurred due to deenergizing of electrical distribution sys vital power panel for maint Caused by drift of time delay relay Rolay recaliby My880411 lir.
 TAYLORILA, LEVINEJ, M. Arkanses Power & Light Co. 88/04/11. 8pp. 45221:194-45221:201
- 8804210461 LER 88-004-00.on 880211,observed degraded sys flow lind to discovery that vol damper in sys ductwork to control room closed Caused by fature to provide locking device to prevent wingout from loosening by vibration W/880411 ltr. MICHALK, P.L., LEVINE, J.M. Arkensas Power & Light Co. 88/04/11. 6pp. 45238:356-45238:45 45230 361

V. Operator Examinations

- 8804250088 Responds to FOIA request for infoire scores of reactor operators & socilor reactor operators Forwards requalification exam summary source sheets listed in enci. app w/personal privacy into deleted.

 GAIMSLEY,D.H Division of Ru'es & Records (Post 870413). 88/04/19 BOLEY,K.

 Public Citizen's Critical Mass Energy Project. 2pp. 45213.003-45213.095.
- 8804250167 Package of NRC administered regual fication exam results summary
 NRC No Detailed Affiliation Given 87/07/20, 88pp. 45213 007-45213:095.

DOCKET 50-369 WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 8604010036 Advises that encil rev mailed on 860317 to update emergency plan impte. menting procedures LEONARD,R Duke Power Co 88/03/22. Region 2, Ofc of the Director. 1p. 45020 242-45020 242
- 8804010232 Forwards Amends 79 & 60 to Licenses NPF-9 & NPF-17, respectively & safeguerd evaluation Amends modify Paragraphs 2.E of licenses to require compliance w/amended physical security plan Plan amended to conform w/10CFR73 55. HOOD,H Project Directorate II-3, 88/03/28 TUCKER,H.B Duke Power Co. App. 44948-268-44948-278.
- --8804010237 Amends 79 & 60 to Licenses NPF-9 & NPF-17, respectively, amending Paragraphs 2.E of licenses to require compliance w/ emonded physical socurity plan. HOOD,D S. Project Directorate II-3, 86/03/28, 4pp. 44948 272-44948,275.

- -aan4010241 Salequards evaluation rept supporting Amends 79 & 60 to Liceuses NPF. 9 & NPF-17 (espectively. • Project Directorate II-3 88/03/28 3pp. 44948.276-44948.278
- 8804120154 Forwards Insp Repts 50-369/88-08 & 50-370/88-08 on 680314-18 No vig
 - lations or deviations noted.

 HERDT.A.R. Region 2, Ofc of the Director, 88/04/06, TUCKER,H.B. Duke Power Co. 2pp. 45122.084-45122.098.
- -8804120160 Insp Rept 50-369/98-08 on 8880314-18 No violations or deviations nated Major areas inspected seismic mornitoring, tire protection/prevention & followup of incensee identified LERs 50-369/87-34 & 50-379/87-18-01. HARRIS, J.R. Region 2, Ofc of the Director, 88/04/05, 13pp, 45122,086-45122,098
- 8804120328 Forwards Rev 34 to security plan, deleting redundant vital equipment test wording & making comprehensive rev of vital equipment list Rev withheld (ref 10CFR73.21).
- TUCKER, H.B. Duke Power Co. 88/04/06. Document Control Branch (Document Control Desk). 2pp. 45135:334-45135:335
- 8804270194 Forwards revs to emergency plan implementing procedures. W/o encl LEONARD,R. Duke Power Co. 88/04/14. Region 2, Oic of the Director. 1p. 45244:274-45244:274.

P. Operating license stage documents & correspondence

- 8710270289 Forwards proprietary DPC-NE-2000, "DCHF-1 Correlation for Predicting Chitical Heat Flux in Mixing Vane Grid Fuel Assemblius." Rept submitted to obtain approval to use DCHF-1 correlation Fee paid Rept withhold (ref 10CFR2-790). TUCKER_NB. Duke Power Co. 8710/21. Document Control Branch (Document Control Desk), 6pp. 43177:210-43177:215.
- 8803100025 Forwards request for addition or 870908 request for exception to one of four criteria for radiologina & particulate sampling requirements of NUREG-0737, item IF 1 concerning design basis shielding envelope. HODD,D.S. Project Directorato II-3. 88/03/07. TUCKER,H.B. Duke Power Co. 3pp. 44661:358-44661:360.
- 8803240426 Generic Ltr 88:06 to all power reactor licensees & applicants re romoval of organization charts from Tech Spec administrative control requirements. Sec list encl MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/03/22 Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804010042 Forwards listing of outstanding Items,per discussion w/NRC re util ongoing program of reducing backlog of outstanding Items.W/o encl. BROWNLEE,V.L. Region 2, Ofc of the Director. 88/03/23. FUCKER,H.B. Duke Power Co. 1p. 45031:171-45031:171.
- 8804120317 Expresses appreciation for time that members took to present outline of ISAP II program per Generic Ltr 88-02 requesting licensee to evaluate NRC latest rev & indicate whether interested in participating in program. TUCKER,H.B. Duke Power Co. 88/03/25. Document Control Branch (Document Control Desk), 2pp. 45091:142-45091:143.
- 8804150241 Forwards addl Info re util 870209 request for reliof from ASME Code Section XI hydrostatic testing requirements from portions of mads on Units 1 & 2 nuclear svc water sys.per NRC request.
 TUCKER,H.B. Duke Power Co. 88/03/25. Document Control Branch (Document Control Desk), 4pp. 45138:041-45138:044.
- 8804010232 Forwards Amends 79 & 60 to Licenses NPF-9 & NPF-17, respectively & saleguard evaluation Amends modify Paragraphs 2.E of licenses to require compliance w/amended physical security plan.Plan amended to conform w/10CFR73.55. HOOD.H. Project Directorate II-3, 88/03/28, TUCKER,H.B. Duke Power Co. 4pp 44948-268-44948:278.
- --8804010237 Amends 79 & 60 to Licenses NPF-9 & NPF-17,respectively, amending Paragraphs 2.E of licenses to require compliance w/ amended physical security plan. HOOD,D.S. Project Directorate II-3, 88/03/28, 4pp. 44948 272-44949:275.
- -8804010241 Safeguards evaluation rept supporting Amends 79 & 60 to Licenses NPF-9 & NPF-17,respectively.

 Project Directorate II-3, 88/03/28, 3pp. 44948:276-44918:278.
- 8804180447 Forwards updated pages to proprietary BAW-10171P, "REFLOD3B- Model for Multinode Core Reflooding Analysis," per ECCS methodology for facilities reloads.Mod removes Henry quench temp chteria & potential conflict in logic.Pages
- withheld.
 TAYLOR,J.H. Babcock & Wilcox Co. 88/03/28. NORBERG,J.A. D.vision of Engineering & Systems Technology (Post 670411). 2pp. 45207:232-45207:233.
- 8804060124 Forwards notice of consideration of issuance of amends to Licenses NPF-9 & NPF-17 & opportunity for hearing Amonds change Tech Spec 3/4.7.7 to reflect veri-tation exhaust sys consists of two shared safety-grade sys for suritary bidg. HOOD,D.S. Project Directorate II-3. 88/03/31, TUCKER,HB. Duke Power Co. 1p. 45019:236-45019:242.
- -8804080127 Notice of consideration of issuance of amend to Licenses NPF-9 & NPF-17 proposed NSHC determination & opportunity for hearing. Amends change Tech Spec 3/4.7.7, "Auxiliary Bidg Filtered Veniliation Exhaust Sys" HOOD,D.S. Project Directorate II-3, 88/03/31, 6pp. 45019:237-45019:242.
- 8804130406 Application for amends to Elcenses NPF-9,NPF-17,NPF-35 & NPF-52,changing Tech Specs to allow credit to be taken for Radiation Monitor EMF-36 if EMF-39 inoperable below Mode 4 (Inol shutdown), Fee paid.

 TUCKER,H.B. Duke Power Co. 88/04/01. Document Control Branch (Document Control Desk), 4pp. 45132:299-45132:324.
- --8804130410 Proposed Tech Specs allowing credit to be taken for Radiation Monitor EMF-36 (unit vent monitor) if EMF-39 (on containment purge sys) inoperable below Mode 4 (hot shuldown).

 **Duke Power Co. 88/04/01. 22pp. 45132:303-45132:324.
- 8804210262 Revised application for amends to Licenses NPF-9,NPF-17, NPF-35 & NPF-52 re fuel assemblies.Proposed amends broaden scope of mods allowed to fuel assemblies involving fuel rod locations & delete max fuel rod U limit. TUCKER,H.B. Duke Power Co. 88/04/01. Document Control Branch (Document Control Desk), 4pp. 45239:029-45239:041.

- ~9804210287 Proposed Tech Specs broadening scope of mods allowed to tuol assembles involving fuel rod locations & delete specified max total fuel rod U weight firm.t
 Duke Power Co. 86/04/01 9pp. 45239.033-45239.041
- 8804130081 Advises that HED M-1-0018 should be canceled due to listed reasons Rearrangament of annunciator & status light sys windows constitutes greater potential for operator error. Util will implement only items 1 & 3 of annunciator mods TUCKER,HB, Duke Power Co. 8B/04/05. Decument Control Branch (Document Control Dosk), 4pp. 45100-029-45100,032.
- 8804080088 Generic Ltr 88-07 to power reactor licensess 8 applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list onci MIRAGULAF J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164.237-45164:285.
- 8804130308 Forwards request for add, info re Topical Rept WCAP-10388, "COBRANC, Analysis for Main Steam Line Break in Ico Condonser Contaminent." Response requested within 45 days from Itr date.

 JABBOURK N. Project Directorate III-3, 88/04/07, TUCKER,HB, Duke Power Co 6pp. 45103:166-45103.171.
- 8804190056 Application for amends to Licenses NPF-35,NPF-52,NPF-9 8 NPF-17, changing required survel lance interval for ico condenser lower intel doors from cur-rent frequencies to 100% hisp every 18 months TUCKER,H.B. Duke Power Co. 88/04/07 Document Centrol Branch (Document Con-trol Desk) 2pp 45197 044-45197.049.
- --8804190058 Proposed Tech Specs, changing required surveillance interval for ice con-denser lower inlet doors from current frequencies to 100% insplayory 18 monitis 1 Duke Power Co. 88/04/07, 4pp, 45197:048-45197:049.
- 8804150097 Forwards Amends 80 & 61 to Licensos NPF-09 & NPF-17, respectively. Amends correct Tach Specs 3 1.2.5 & 3 1.2.6 by increasing min vol of borated water to be maintained in boric acid storage sys. HOOD,D. Project Directorate II-3. 88704/11. TUCKER, H.B. Duke Power Co. 2pp 45146.001-45146.012.
- ~8804150095 Amonds 80 & 61 to Licenses NPF-9 & NPF-17, respectively, correcting Tech Specs 3.1.2.5 & 3.1.2.6 by increasing min vol of borated water to be maintained In bond acid storage sys.

 CROCKER,L Project Directorate II-3 88/04/11, 7pp, 45146:003-45146:009
- ~8804150400 Safety evaluation supporting Amends 80 & 61 to Licenses NPF-9 & NPFrespectively.
- 17,respectively.
 * Project Directorate II-3, 88/04/11, 2pp. 45146 010-45146 011.
- --8804150104 Requests FR publication of notice of Issuance of Amends 80 & 61 to Liconses NPF-9 & NPF-17, respectively. Amends correct Tech Spacs 3 1.2 5 & 3.1.2 6 by increasing min vol of boreled water maintained in boric acid storage sys. HOOD, D. Project Directorate II-3, 88/04/11 NRC No Detailed Affiliation Given. 1p 45146 012-45146.012.
- 8804260078 Requests approval of enci revised "Startup Physics Test Program" Changes made to rod swap isothermal temp cooliticant & flux symmetry check. TUCKER, H.B. Duke Power Co. 88/04/14. Document Control Branch [Document Control Branch | Document Co trol Deak), 4pp. 45282 018-45282:031,
- --8804260082 "Startup Physics Test Program Apr 1888."
 * Duke Power Co. 88/04/30, 12pp, 45282.020-45282.031,
- 8804220181 Forwards notice of consideration of Issuance of amends to Licenses NPF-9 & NPF-17 & opportunity for hearing to groundwater level. HOOD,D.S. Project Directorate II-3, 88/04/15, TUCKER,H B. Duke Power Co. 2pp. 45201;139-45201;127.
- --8804220183 Notice of consideration of Issuance of amends to Licenses NPF-9 & NPF-17 & opportunity for hearing Amends revise Tech Specs to delate groundwater monitors for reactor bridgs & diesel generator bldgs CROCKER,L.P. Project Directorate II-3, 88/04/15, 6pp. 45201:121-45201;127.
- 8804220261 Not/Ication of 880428 trip/meating w/util in Huntersville, NC to observe & discuss inadequate core cooling instrumentation.
 HODD,D.S. Project Directorate II-3, 88/04/15 CROCKER,t.P. Project Directorate III-3, 88/04/15 CROCKER,t 3pp. 45200.333 45200:335.

Q. Inspection reports, IE Bulletins & correspondence

- 8804060369 FOIA request for Statio 870908 memo to Commission,w/encl.re assessment of NRC Const Insp Program at River Bend & all periodic regional trisp program. assessment repts written since 1980
 CONNORLL Doc-Search Associates 66/01/18, Division of Rules & Records (Post
- 870413), 1p. 45029.001-45029:001. 8803290331 Forwards Insp Repts 50:369/88-04 & 50:370/88-04 on 880121- 0226 &
- notice of violation BROWNLEE.V.L. Region 2, Ofc of the Director BB/03/10. TUCKER.H.B. Duke Power Co. 2pp. 44912:349-44912:381.
- --8803290333 Notice of violation from Insp on 880121-0226 Violation noted Procedure IP/O/A/3061/08 not properly implemented & procedure for removing cation bad demineralize from svc not properly maintened. BROWNLEE,VI. Region 2, Ofc of the Director. 88/03/10 2pp. 44912:351-44912:352
- ~9803290336 Insp. Repts 50-369/88-04 & 50-370/88-04 on 860121-0226 Violation noted Major areas inspected operations, safety verification, surveillance testing, maint activities & tollowup on previous insplindings, ORDERS,W., PEEBLES,T.A. Region 2, Ofc of the Director, 88/03/08, 9pp ORDERS W. PEEBLE 44912:353-44912:361.
- 8803310283 Forwards Insp Riepts 50-369/88-07 & 50-370/88-07 on 880227-0318 No violations or deviations noted. BROWNLEEV.L. Region 2, Ofci of the Director, 88/03/24, TUCKER,H.B. Duke Power Co. 2pp. 44976-151-44976;15B

- --8803310285 Insp Repts 50:369/88:07 & 50:370/68:07 on 880227:0318 No violations or deviations noted Major areas inspected: operations safety ventication, surveillance testing maint activities & followup on previous insp Endings.

 ORDERS,W., PEEBLES,T.A. Region 2, Ofc of the Director. 88/03/24. 6pp 44976:153-44976.158.
- 8804010235 Informs that util unable to establish firm dates for completion of work described in NRC Bulletin 88-002 Rept will now be provided by 880425.

 TUCKER.H.B. Duke Power Co. 88/03/24. Document Control Branch (Document Control Desk) 2pp. 45031.119-45031:120.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning In Westinghouse Reactors," Svc list end. ROSSIC E. Drisson of Operational Events Assessment (Post 870411). 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995.246.

- 8803220296 NRC Info Motice 88-010, "Mattis Licensees Lack of Mgt Controls Over Li-censed Programs." Svc list encl. CUNNINGHAM.R.E. Division of Industrial & Medical Nucleer Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995;353.
- 8804070066 Forwards request for additinfo re util 860516,1120 & 870218 responses to IE Bulletin 85-003, "Motor-Operated Valve Common Mode Fartures During Plant Transients Due to Improper Switch Settings," for response within 30 days HERDTA R. Region 2, Ofc of the Director, 88/03/31, TUCKER, H.B. Duke Power Co. 3pp. 45030-351-45030:353.
- 8804120023 Ack receipt of 860321 ftr informing NRC of steps taken to correct violations noted in Imsp. Repis 50-369/87-43 & 50-376/87-43.

 BROWNLEE,V.L. Region 2, Old of the Director. 88/03/31. TUCKER,H.B. Duke Power Co. 1p 45135-297-45135-297.
- 8804060409 Remits fee for payment of civil penalty in amount of \$100,000.Util beliaves, as set forth in B71125 response that decision was incorrect application of enforcement policy. Disagrees w/NRC assessment of matter, TUCKERI-LB. Duke Power Co. 88/04/01. Ofc of Enforcement (Post 870413), 2pp.
 - 45007.041-45007.042
- 8804110299 Forwards response to NRC Bulletin 88-001, "Defects in Westinghouse Circut Breakers."
 TUCKER,H.B. Duke Power Co. 88/04/05. Document Control Branch (Document Control Desk). 2pp. 45154-001-45154:002.
- 8804120139 Forwards Insp Repts 50:369/88-06 & 50:370/88-06 on 880307-11 & notice
- of violation COLLINS.D.M. Region 2. Ofc of the Director. 88/04/05. TUCKER.H.B. Duke Power Co. 2pp. 45122.122-45122.134.
- -8804120142 Notice of violation from insp on 880307-11.Violation noted: on 880308,li-censed failed to barricade & post high radiation area at Unit 2 pipe chase entrance in Room 647 on 716-ft elevation. COLLINS,D M. Region 2, Orc of the Director. 88/04/05, 2pp. 45122:124-45122:125.
- -8804120146 Insp. Rept. 50:369/88-06 on 880:307-11 Violation noted Major areas inspected organization & mgl controls, training & qualifications, external exposure control & dosametry, infernal exposure control & assessment, COI.; INS,T.R. Region 2, Oic of the Director. 88/04/01, 9pp. 45122:126-45122:134.
- 8804120154 Forwards Insp Repts 50-369/88-08 & 50-370/88-08 on 880314-18 No violations or deviations noted.

 HERDT.A.R. Regard. 2, Ofc of the Director, 88/04/06, TUCKER,H.B. Duke Power Co. 2pp. 45122-084-45122-098
- -8604120160 Insp Rept 50-369/68-06 on 6880314-18.No violations or deviations noted Major areas inspected seismic monitoring, fire protection/prevention & followup of licensee identified LERs 50-369/87-34 & 50-370/87-18-01.
- of licensee identified LERs 50-369/87-34 & 50-370/87-18-01.
 HARRIS,J.R. Region 2, Old of the Director, 88/04/05, 13pp. 45122-086-45122-098.
- 8804010256 NRC Info Notice 88:011, "Potential Loss of Motor Control Ctr \$/or Switch-board Function Due to Faulty Tie Bolts." Svc list encl. ROSSICE. Division of Operational Events Assessment (Post 870411). 68/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804190056 Application for amends to Licenses NPF-35,NPF-52,NPF-9 & NPF-17,changing required surveillance interval for ice condenser lower inlet doors from current frequencies to 100% inspleyer 18 months, TUCKER,H.B. Duke Power Co. 88/04/07, Document Control Desk). 2pp. 45197.044-45197.049.
- -8804190068 Proposed Tech Specs changing required surveillance interval for ice condenser lower inlet doors from current frequencies to 100% inspleyery 18 months.

 Duke Power Co. 88/04/07. 4pp. 45197.048-45197:049.
- 8804130260 Forwards Diagnostic Evaluation Rept 2 of evaluation conducted onsite on 871130-1211. Overall performance of plant was solid SALP Category 2 w/Improving trans Evaluation of rept requested.

 STELLOV. Oto of the Executive Director for Operations. 88/04/08. OWEN,W.H. Duke Power Co. 2pp. 45103.018-45103:143.
- -8804130299 Diagnostic Evaluation Rept 2 on 871130-880108. SPESSARD,R.L. Diagnostic Evaluation & Incident Investigation Branch. JORDAN,E.L. Office for Analysis & Evaluation of Operational Data, Director. 88/03/08. 126pp.
- 8804150163 Responds to violations noted in Insp. Repts 50-369/88-04 & 50-370/88-04 Corrective actions:procedure adherence being discussed in instrument & electrical crew meetings & Procedure OP/1/A/8200/01 revised to place steps in order, TUCKER_HS, Duke Power Co. 88/04/08, Document Control Branch (Document Control Desk), 4pp. 45131:337-45131:340.
- 8804060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list anci.
 ROSSI.C.E. Division of Operational Events Assessment (Post 87041)) 88/04/12.
 Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-15165:150.
- 8804200473 Partial response to FCIA request re fire protection Forwards App E documents App D & E documents available in PDR.App F document completely with-field (rel FOIA Exemption 5).
 GRIMSLEY,D.H. Division of Rules & Records (Post 670413). 88/04/14, JONES,C.R. Affiliation Not Assigned. 5pp. 45206:037-45206:043.

the state of the s

- -8804206575 Provides status of Region II safe shufdown Insp program. GRACE_JN Region 2, Ofc of the Director, 65/05/13, TAYLORJ, JM. Ofc of Inspection 8 Enforcement, Director (620201-870413), 2pp. 45208:174-45208:175.
- R. Periodic operating reports & related correspondence
- 8804050339 "Annual Environ Operating Rept for 1987." W/880329 ltr. TUCKER,H.B. Duke Power Co. 87/12/31, 3pp. 46061:146-45061:148.
- 8804260381 "Annual Environ Operating Rept 1987." W/680420 Nr. TUCKER,H.B. Duke Power Co. 67/12/31, 1,000pp. 45248:148-45251.048.
- 8804200156 Monthly operating repts for Mar 1988.W/880415 ltr. REAVIS,J.A., TUCKER,H.B. Duke Power Co. 88/03/31. 12pp. 45215:331-45215:342.
- S. Reportable occurrences, LERs & related correspondence
- 8804 130 168 RO. change of commitment submitted re diesel generator turbocharger rotor assembly replacement. Turbocharger inlet casings replaced on all four engines w/new design. Dye penetrant testing will continue to be performed. TUCKER.H.B. Duke Power Co. 88/04/04. Document Control Branch (Document Control Desk), 2pp. 45132.354-45132.355.
- 8804180243 LER 88-003-00 on 880309,discovered that component cooling HX 18 con-trol inoperable due to nuclear svc water sys valve being in nonconservative position & w/Liavel stops toese Hax nuts for travel stops set in correct position W/880409 in; LE ROY,SE, TUCKER,H.B. Duke Power Co. 88/04/08, 7pp. 45183:280-45183-286
- 8604200328 LER 88-004-00:on 880309,Tech Spec 3.0.3 entered when EVCB vital bal-lery charger de energized.Caused by problem of unknown origin w/power supply broakers for vital battery charger.Investigation completed W/880408 ltr. LEROY,S.E., TUCKER,H.B. Duke Power Co. 88/04/08. 8pp. 45221:139-45221:146.
- 8804250037 LER 87-033-01:on 871206,four main steam to auxiliary equipment valves omitted from inservice testing program. Caused by personnel error Valves successfully stroked from fully opened to fully closed position.W/880418 ltr. LE ROY,S.E., TUCKER,H.B. Duke Power Co. 88704/18. 9pp. 45239.050-45239.058

DOCKET 50-370 WILLIAM B. MCGUIRE NUCLEAR STATION, UNIT 2

- F. Security, medical, emergency & fire protection plans
- 8604010036 Advises that encl rev mailed on 880317 to update emergency plan impleneenting procedures.
 LEONARD,R. Duke Power Co. 88/03/22. Region 2, Otc of the Director. 1p.
- 8804010232 Forwards Amends 79 & 60 to Licenses NPF-9 & NPF-17, respectively 8 safeguard evaluation Amends modify Paragraphs 2.E of licenses to require comptioned with the comption of the conformation of the comption of the conformation of the con
- --8804010237 Amends 79 & 60 to Licenses NPF-9 & NPF-17,respectively, amending Paragraphs 2.E of licenses to require compliance w/ amended physical security plan HOOD, D.S. Project Directorate II-3, 88/03/28, 4pp. 44948:272-44948:275.
- --9804010241 Safeguards evaluation rept supporting Amende 78 & 60 to Licenses NPF-9 & NPF-17,respectively. * Project Directorate II-3, 88/03/28, 3pp. 44948:276-44948:278.
- 8804120154 Forwards Insp Repts 50-369/88-08 & 50-370/88-08 on 880314-18.No vio-Talkins or deviations noted.
 HERDT, A.R. Region 2, Oic of the Director, 88/04/08, TUCKER, H.B. Duke Power Co. 2pp. 45122.084.
- --8804120160 Insp. Repl. 50-369/88-08 on 8880314-18.No violations or deviations noted Major areas inspected:seismic monitoring, life protection/prevention & followup of licenses identified LERs 50-369/87-34 & 50-370/87-18-01.

 HARRIS,J.R. Region 2, Oto of the Director, 88/04/08, 13pp. 45122:088-45122:098
- 8804120328 Forwards Rev 34 to security plan, detetting redundant vital equipment test wording 8 making comprehensive rev of vital equipment list.Rev withheld (ref 10CFR73,21).

 TUCKER,H.B. Duke Power Cq. 88/04/06, Document Control Branch (Document Control Desk). 2pp. 45135:334-46135:335.
- 8604270194 Forwards revs to emergency plan implementing procedures. W/o encl. LEONARD.R. Duke Power Co. 88/04/14. Region 2, Ofc of the Director. 1p. 45244:274.45244:274.
- P. Operating license stage documents & correspondence
- 8710270269 Forwards proprietary DPC-NE-2000, "DCHF-1 Correlation for Predicting Critical Heat Flux in Mixing Vane Grid Fuel Assemblies." Rept submitted to obtain approval to use DCHF-1 correlation. Fee paid. Rept withheld (ref 10CFR2.790). TUCKER, H.B. Duke Power Co. 87/10/21, Document Control Branch (Document Control Desk). 8pp. 43177:210-43177:216.
- 8803100026 Forwards request for additinfoire 870908 request for exception to one of four criteria for radiolodine & particulate sampling requirements of NUREG-0737, tem II.F.1 concerning design basis shielding envelope.

 HOOD,D.S. Project Directorate II-3. 88/03/07, TUCKER,H.B. Duke Power Co. 3pp. 44661:358-44661:360.
- 8803240426 Generio Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svo list encl MIRAGULAFJ. Associate Director (or Projectis (Ross 870411), 86/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.

141

- 8804010042 Forwards listing of outstanding items,per discussion w/NRC roluit ongoing program of reducing backlog of outstanding items W/o encl. BROWNLEE.V.L. Region 2, Ofc of the Director. 88/03/23 TUCKER,H.B. Duke Power Co. 1p. 45031.171-45031.171
- 8804120317 Expresses appreciation for time that members took to present outline of ISAP II program per Generic Ltr 88-02 requesting licensee to evaluate NRC latest rev & indicate whether interested in participating in program TUCKER,H.B. Duke Power Co. 88703725 Document Control Branch (Document Control Desk). 2pp. 45091:142-45091.143.
- 8804150241 Forwards addl into ro util 870209 request for relief from ASME Code Section XI hydrostatic testing requirements from partions of mods on Units 1 & 2 nuclear see water sysper NRC raquest TUCKER.H.B. Duke Power Co. 88/03/25 Document Control Branch (Document Control Desk) 4pp 45138-041-45138-044
- 8804010232 Forwards Amends 78 & 60 to Licenses NPF-9 & NPF-17, respectively & saleguard evaluation Amends modify Paragraphs 2 E of licenses to require compliance w/amended physical security plan Plan amended to conform w/10CFR/3.55 HOOD.H. Project Directorate II-3. 88/03/28. TUCKER,H B. Duke Power Co. 4pp 44948-268-44948-278
- -8804010237 Amends 79 & 60 to Licenses NPF-9 & NPF-17,respectively, amending Paragraphs 2.E of licenses to require compliance w/ amended physical security plan HOOD, D.S. Project Directorate II-3, 88/03/28 4pp, 44948 272-44948 275
- -8804010241 Saleguards evaluation rept supporting Amends 79 & 60 to Licenses NPF-9 & NPF-17,respectively.
 • Project Directorate II-3 88/03/28, 3pp. 44948:276-44948:278
- 8804180447 Forwards updated pages to proprietery BAW-10171P, "REFLOD3B-Model for Mullinode Core Reflooding Analysis," per ECCS methodology for tacilities reloads.Mod removes Henry quench temp criteria & potential conflict in logic Pages
 - winnieru. TAYLOR,J.H. Babcock & Wilcox Co. 88/03/29. NORBERG,J.A. Division of Engineering & Systems Technology (Post 870411). 2pp. 45207.232-45207.233
- 8804060124 Forwards notice of consideration of Issuance of amonds to Licenses NPF-9 & NPF-17 & opportunity for hearing Amends change Tech Spec 3/4.7.7 to rollect ventiation exhaust syst consists of two shared safety-grade syst for auxiliary bridg HCCD.O.S. Project Directorate II-3. 88/03/31. TUCKER.H.8 Duke Power Co. 1p. 45019:236-45019:242.
- -8804060127 Notice of consideration of issuance of amend to Licenses NPF-9 & NPF-17 proposed NSHC determination & opportunity for hoaring Amenda change Tech Spec 3/4.7, "Auxi'ary Bidg Fritored Venhalton Exhaust Sys," HOOD,D S. Project Directorate II-3. 88/03/31. 6pp. 45019.237-45019 242.
- 8804130406 Application for amonds to Licenses NPF-9,NPF-17,NPF-35 & NPF-52,changing Tech Specs to allow credit to be taken for Radiation Monitor EMF-36 If EMF-39 Inoperable below Mode 4 (tiot shuldown) Fee pe d TUCKER,I18 Duke Power Co. 88/04/01. Document Control Desk). 4pp. 45132 299-45132.324.
- -8804130410 Proposed Toch Spocs allowing credit to be taken for Radiation Monitor EMF-36 (unit vent monitor) if EMF-39 (on containment purge sys) (noperable below Mode 4 (hot shutdown).

 **Duke Power Co. 88/04/01 22pp. 45132:303-45132:324.
- 8804210282 Rovised application for amonds to Liconsos NPF-9,NPF-17, NPF-35 & NPF-52 re fuel assemblies.Proposed amends broaden scope of mode allowed to fuel assemblies involving fuel rod locations & delate max fuel rod U limit. TUCKER,H.B. Duke Power Co. 68/04/01. Document Control Branch (Document Control Desk). 4pp. 45239:029-45239.041.
- --8804210287 Proposed Toch Specs,broadening scope of mods allowed to fuel assemblies involving fuel rod locations & dolete specified max total fuel rod U weight I mit.
 * Duke Power Co. 88/04/01. 9pp. 45239.033-45239-041.
- 8804130081 Advises that HED M-1-0018 should be canceled due to listed reasons Rearrangement of annunciator & status light sys windows constitutes greater potential for operator error. Unit will implement only items 1 & 3 of annunciator mods. TUCKER,H.B. Duke Power Co. 88/04/05. Document Control Branch (Document Control Desk). 4pp. 45100.020-45100.032.
- 8804080089 Generic Ltr 88-07 to power reactor ticensees & applicants re-modified en-torcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 40pp. 45164:237-45164:285
- 8804130309 Forwards request for additinto re Topical Rept WCAP-10988, "COBRA-NC, Analysis for Main Steam Line Break In Ice Condenser Containment." Response requested within 45 days from Itr date.

 JABBOUR,K.N. Project Directorate II-3. 88/04/07. TUCKER,H.B. Duke Power Co. 6pp. 45103:166-45103:171.
- 8804190056 Application for amonds to Licensos NPF-35,NPF-52,NPF-9 & NPF-17,changing required surveillance interval for ice condenser lower inlet doors from current frequencies to 100% inspleasely 18 months.

 TUCKER,H.B. Duke Power Co. 88/04/07. Document Control Brench (Document Control Desk). 2pp. 45197:044-45197.049.
- --8804190058 Proposed Tech Specs, changing required surveillance interval for ice condenser lower inlet doors from current frequencies to 100% insplayery 18 months.
 * Duke Power Co. 88/04/07. 4pp. 45107:048-45197-049.
- 8804150087 Forwards Amonds 80 & 61 to Liconses NPF-09 & NPF-17, respectively. Amends correct Tech Spocs 3.1.2.5 & 3.1.2.6 by increasing min vol of boraled water to be maintained in boric acid elorage sys. HOOD.D. Project Directorate Ir-3. 88/04/11. TUCKER, H.B. Duke Power Co. 2pp. 45146.001-45146.012.
- ~8804160095 Amends 80 & 61 to Licenses NPF-9 & NPF-17 respectively, correcting Tech Specs 3.1.2.5 & 3.1.2.6 by increasing min vol of borated water to be maintained In boric acid storage sys. CROCKER,L. Project Directorate II-3, 86/04/11, 7pp. 45146:003-45146:009.

- --8804150400 Safety evaluation supporting Amends 80 & 61 to Licenses NPF-9 & NPF-17, respectively.
 * Project Directorate II-3 88/04/11 2pp. 45146 010-45146 011
- --8804150104 Requesis FR publication of notice of issuance of Amends 80 & 61 to Licenses NPF-8 & NPF-17, respectively Amends correct Tech Specs 3.1.2.5 & 3.1.2.6 by increasing min vol of borated water meintained in boric acid storage systemOOD Project Deteorate II-3 88/04/11 NRC No Detailed Affiliation Given. 1p. 45146.012-45146.012.
- 8804260078 Requests approval of encl revised "Startup Physics Test Program," Changes made to rod swap isothermal temp coefficient & flux symmetry check TUCKER, H.B. Duke Power Co. 88/04/14 Document Control Branch (Document Control Desk) 4pp. 45282 016.45282 031.
- --8804260082 "Startup Physics Test Program Apr 1988"
 DuNe Power Co. 88/04/30, 12pp. 45282.020-45282.031.
- 8804220181 Forwards notice of consideration of issuance of amends to Licenses NPF-9 & NPF-17 & apportunity for hearing re-groundwater level HOOD, 0.S. Project Directorate It-3 88/04/15 TUCKER,H.B. Duke Power Co. 2pp 45201:119-45201:127
- --8804220183 Notice of consideration of issuance of amends to Licenses NPF-9 & NPF-17 & opportunity for hearing Amends revise Tech Specs to defate groundwater moni-tors for reactor bidgs & diesal generator bidgs CHOCKERLP. Project Oractorate II-3. 88/04/15 6pp 45201:121-45201:127
- 8804220261 Nolification of 880428 trip/mooting w/util in Huntersville, NC to observe & discuss inadequate core cooling instrumentation HOOD,DIS, Project Directorate II-3 68/04/15, CROCKER,L.P. Project Directorate II-3 3pp
- Q. Inspection reports, IE Bulletins & correspondence
- 8803290331 Forwards Insp Repts 50-369/88-04 & 50-370/88-04 on 880121- 0226 & notice of violation. BROWNI.EE.V.L. Region 2, Ofc. of the Director. 88/03/10. TUCKER,H.B. Duke Power Co. 2pp. 44912 349-44912:361.
- --8803290333 Notice of violation from Insp. on 880121-0226 Violation noted Procedure IP/O/A/3061/08 not properly implemented & procedure for removing cation bed demineralizer from sec not properly maintained.

 BROWNI EE,V L. Region 2, Ofc of the Director: 88/03/10 2pp. 44912:351-44912:352.
- --8803290336 Insp. Repts 60-368/88-04 & 50-370/88-04 on 880121-0226. Violation noted Major largest inspected operations, safety verification, surveillance testing maint activities & followup on previous insp findings. ORDERS.W. PEEBLES.T.A. Region 2. Otc of the Director. 98/03/08 9pp 44912.353-44912.361.
- 8803310283 Forwards Insp Repls 50-369/88-07 & 50-370/68-07 on 880227-0318 No violations or deviations noted.

 BROWNLEE,V L. Region 2, Otc of the Director. 88/03/24. TUCKER,H 8 Duke Power Co. 2pp. 44976:151-44976:158.
- -8803310285 Insp Repts 60-369/68-07 & 50-370/88-07 on 880227-0318 No violations or dowations noted. Mejor areas inspected, operations safety verification, surveillence testing, maint activities & followup on provious Insp findings. ORDERS.W., PEEBLES.T.A. Region 2, Otc of the Director. 88/03/24. 6pp. 44976.153-44076-158.
- 8804010235 Informs that util unable to establish firm dates for completion of work de-scribed in NRC Bullotin 88-002.Ropt will now be provided by 880425 TUCKER, H.B. Duke Power Co. 88/03/24. Document Control Branch (Document Con-trol Desk) 2pp. 45031:119-45031:120
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors," Svc list enci.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995-126-44995-246
- 8803220298 NRC Info Notice 88:010, "Metls Licensees:Lack of Mgt Controls Over Li-censed Programs." Svc list enct. CUNNINGHAM, R.E. Division of Industrial & Med-cal Nuclear Safety (Post 870720), 88/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353
- 8804070086 Forwards request for add into re util 860518,1120 & 870218 responses to IE Bultetin 85-003, "Motor-Operated Valve Common Mode Failures During Plant Transtents Due to Improper Switch Settings," for response within 30 days. HERDTA.R. Region 2, Ofc. of the Director. 88/03/31, TUCKER,H.B. Duke Power Co 3pp. 45030:351-45030:353.
- 8604120023 Ack receipt of 880321 ftr informing NRC of steps taken to correct volations noted in Insp Repts 50-369/87-43 & 50-370/87-43.

 BROWNLEE.V.L. Region 2, Ofc of the Director. 88/03/31, TUCKER,H 8. Duke Power Co. 1p. 45135-297-45136-297.
- 8834110299 Forwards response to NRC Bulletin 88-001, "Defects in Westinghouse Circult Broakers"

 Duke Power Co. 68/04/05. Document Control Brench (Document Control Desh. 2pp. 45154.001-45154.002.
- 8804120139 Forwards Insp Repts 60-369/88-08 & 50-370/88-06 on 880307-11 & notice of violation. COLLINS,D.M. Region 2, Ofc. of the Director, 88/04/05, TUCKER,H.B. Duke Power Co. 2pp. 45122:122-45122:134.
- -8804120142 Notice of violation from Insp on 880307-11.Violation noted: on 880308,li-censee felfed to barricade & post high radiation area at Unit 2 pipe chase entrance in Room 647 on 716-ft elevation. COLLINS,O.M. Region 2. Of

- inspected organization & mgt controls the ring & qualifications, external exposure control & dosimetry, internal exposure control & assessment COLLINSTR. Region 2, Old of the Director 88/04/01 9pp. 45122.126.45122.134
- 8804120154 Forwards Insp. Repts 50:369/88:08 & 50:370/88:08 on 680314:18 No v.o. lations or deviations noted. HERDT.A.R. Region 2, Ofc of the Director 68/04/06. TUCKER.H.B. Duke Power Co 2pp. 45122 084: 45122 098
- ~8804120160 Insp. Rept. 50-369/88.08 on. 8860314-18.No. violations of deviations noted Major areas inspected seismic monitoring, line protection/prevention 8 followup of licenses identified LERs 50-369/87-34.8 50-370/87-18-01 HARRIS,J.R. Region 2, Ofc. of the Director. 88/04/05 13pp. 45122 086-45122 098
- 8804010256 NRC Into Notice 88-011, "Potential Loss of Motor Control Cir &for Switchboard Function Due to Faulty Tie Botis" Svc Inst end ROSSIGE, Division of Operational Events Assessment (Post 970411) 88/04/07 Consolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407 051
- 8804190056 Application for amends to Licenses NPF-35.NPF-52.NPF-9 & NPF-17.changing required surveillance interval for rice condenser lower infet doors from current frequencies to 100% inspleyer 18 months TUCKER.H.B. Duta Power Co. 88/04/07 Document Control Branch (Document Control Desk). 2pp. 45197.044-45197.049
- -8804190058 Proposed Tech Specs,changing required surveillance interval for ice condenser lower intel doors from current frequencies to 100% linsp every 18 months.
 * Duke Power Co. 88/04/07, 4pp. 45197.046.45197.049.
- 8804130260 Forwards Diagnostic Evaluation Hept 2 of evaluation conducted distilled on 871130-1211 Overall performance of plant was solid SALP Category 2 w/improving trend Evaluation of rept requested STELLOV, Oils of the Executive Director for Operations 88/04/08 OWEN,W.H. Duke Power Co. 2pp. 45103.016-45103.143.
- -8804130299 Diagnostic Evaluation Rept 2 on 871130-880108. SPESSARD,R.L. Diagnostic Evaluation & Incident Investigation Branch, JORDAN,E.L. Office for Analysis & Evaluation of Operational Data, Director. 88/03/08. 128pp. 45103.018-45103.143.
- 8804150183 Responds to violations noted in Insp. Repts 50:369/68-04 & 50:370/88-04 Corrective actions procedure adherence being discussed in instrument & electrical crew meetings & Procedure OP/1/A/6200/01 revised to place steps in order. TUCKER_HB. Duke Power Co. 88/04/08. Document Control Branch (Document Control Desk). 4pp. 45131:337-45131:340.
- 8804080370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings" Svc list enci. ROSSI.C.E. Drivision of Operational Events Assessment (Post 870411), 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165-150.
- 8804200473 Parual response to FOIA request re fre protection Forwards App E documents App D & E documents available in PDR App F document completely withheld (ref FOIA Exemption 5).
 GRIMSLEY,D.H. Division of Rules & Records (Post 870413), 88/04/14 JONES,C.R. Affiliation Not Assigned 5pp 45206 037-45206 043.
- --8804200575 Provides status of Region II safe shutdown insp program.
 GRACE J N Region 2, Ofc of the Director 85/05/13 TAYLOR, J.M. Ofc of Inspection & Enforcement, Director (820201-870413). 2pp. 45206.174-45208.175.
- R. Periodic operating reports & related correspondence
- 8804050339 "Annual Environ Operating Rept for 1987." W/880329 ltr. TUCKER,H.B. Duke Power Co. 87/12/31. 3pp. 45061:146-45061:148.
- 8804260381 "Annual Environ Operating Rept 1987." W/860420 IIIr TUCKER,H.B. Duke Power Co. 87/12/31, 1,000pp, 45248.148-45251;048.
- 8804200156 Monthly operating repts for Mar 1988.W/880415 ltr. REAVIS,J.A., TUCKER,H.B., Duke Power Co., 68/03/31, 12pp, 45215:331-45216-342
- S. Reportable occurrences, LERs & related correspondence
- 8804010151 LER 87-011-01 on 870814,hold down bolt discovered missing from missile shield blocks over reactor cavity Caused by Inadequate instructions Hole redicted & bolts installed & verified in accordance w/approved drawings.W/880328 ft; LERDY,S.E., TUCKER,H.B. Duke Power Co. 88/03/23, 8pp. 45016:176-45016.183.
- 8804010154 LER 87-009-01.on 970702.reactor trip breaker (ailed to automatically open.Caused by mechanical failure Breaker B-4 locally tripped 8 removed from 2RT8 cubicle Breaker declared inoperable 8 secured from rod drop timing test W/880325 ltr LEROY.S.E. TUCKER,H B. Duke Power Co. 88/03/25 15pp. 45018:193-45016:214.
- 8804130166 RO change of commitment submitted re diesel generator turbocharger rotor assembly replacement. Turbocharger inlet casings replaced on all four engines w/new design Oye pentrant testing will continue to be performed. TUCKER, H.B. Duke Power Co. 88704/04. Document Control Branch (Document Control Desk). 2pp. 45132.354-45132.355.
- 8804270045 LER 86 001-01 on 860115,reactor trip on lo-lo steam generator level occurred Caused by reducted main feedwater flow after pump turbine tripped on low condenser vacuum. Plant stebitized & vacuum inspectad/repaired.W/860418 ltr. LERDY,S.E., TUCKER,H.B. Duke Power Co. 88/04/19. 8pp. 45321:071-45321078.

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

- F. Security, medical, emergency & fire protection plans
- 8804130162 Revised emergency plan implementing procedures including Rev 6 to L2P-1200-1, "Classification For Generating Station Emergency Plan Conditions," Rev 0 to L2P-1230-1, "A. Model Operation." & Rev 6 to L2P-1330, "Sampling." "Commonwealth Edison Co. 88/04/06. 52pp. 45146.267-45148.318.

- exercise acceptable.

 SHAFER W D. Region 3, Ofc. of the Director 88/04/06 REED.C Commonwealin Edison Co. 1p. 45163-353-45163-353
- 8804250006 Revised emergency plan implementing procedures including Revi 4 to L2P-1330-28. "Sampling of Process Waters Containing Radioactivity at High Radiation Sampling Sys" & Rev 1 to L2P-1330-30, "Transfer of Wastes from High Radiation." Commonwealth Edison Co. 88/04/08. 47pp. 45239-254-45239-300.
- J. Insurance & Indemnity Information
- 8804120216 Forwards Endorsement 20 to NELIA Policy NF-294,Endorsement 15 to MAELU Policy MF-128,Endorsement 30 to NELIA Policy NF-277,Endorsement 22 to MAELU Policy MF-114 & Endorsement 194 to NELIA Policy NF-43 OSTERJ, Commonwealth Edison Co 88/04/06, DINITZ.I. Offico of Nuclear Reactor Regulation, Director (Post 870411), 13pp. 45090 030-45000 042.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8804220012 Forwards Rev 4 to updated FSAR (or LaSalle County Station Units 1 & 2 ALLEN.C.M Commonwealth Edison Co. 88/04/08 Document Control Branch (Occument Control Desk). 2pp. 45227:217-45229.307.
- -8804220013 Rev 4 to updated FSAR for LaSalie County Station Units 1 & 2 ** Commonwealth Edison Co 88/04/30 900pp 45227:219 45229.307.
- P. Operating license stage documents & correspondence
- 8803080125 Forwards safety evaluation conditionally supporting proposed dosign of standby liquid control sys consistent w/ requirements of 10CFR50 82 Values of concentration & selpoint should be included in Tach Spec rev MULLER,D R. Project Directorale III-2, 88/03/01. BUTTERFIELD,L D Commonwealth Edison Co. 4pp. 44633.309-44633.316
- -8803080131 Safety evaluation supporting standby liquid control sys consistent w/ 10CFR50.82 ** Project Directorate III-2, 88703/01, 4pp. 44633:313-44633-316.
- 170ject Directoratu III-2. 66703701. 4pp. 44033.313-44033.310
- 8803080447 Forwards Amends 55 & 36 to Licenses NPF-11 & NPF-18, respectively & safety evaluation Amends revise Tech Specs re jet pump operability surveillance & corrects typos.

 SHEMANSKI,P Project Directorate III-2, 88/03/04, 8UTTERFIELD,L Commonwealth Edison Co. 2pp. 44639 008-44639.020
- --8803080455 Amends 55 & 36 to Licenses NPF-11 & NPF-18, respectively, revising Tech Specs re jet pump operability surveillance & correcting typos. MULLER, D. R. Project birectorale III-2 88/03/04. 10pp. 44639:008-44639.017.
- --8803080460 Salety evaluation supporting Amends 55 & 36 to Licenses NPF-11 & NPF-18,respectively.

 *Project Orectorate III-2, 88/03/04, 3pp. 44639:018-44639.020.
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc 1st encl. MIRAGLIAF, J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972.107-44972.153.
- 8804060476 Informs that plant A-Model scheduled for operation on 890331 now projected to be operational by 880830 due to complexity of program JOHNSON,I.M. Commonwealth Edison Co. 88/03/30. DAVIS,A B. Rug on 3, Ofc of the Director. 1p 45093.046-45093 046.
- 8804130377 Forwards request for addl into on alternate rod injection & recirculation pump frip sysper util 870406 & 1023 lirs or implementation of ATWS rule HOCFR50 62 Response requested by 880420 in order to meet schoduled safety evaluation date

 SHEMANSKI,P. Project Directorate III-2. 88/04/06, BUTTERFIELD,L. Commonwea/th Edison Co 8pp. 45103.220-45103.227.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA,F J. Associate Director for Projects (Post 870411), 88704/07 Consolidated Edison Co. of New York, Inc. 49pp. 45164:237.45164:285.
- 8804280039 Forwards Rev 50 to CE-1+A, "OA Program for Nuclear Generating Stations," Revs being made to reflect organizational changes.
 MORGAN.W.E. Commonwealth Ed.son Co. 88/04/18. Document Control Branch (Document Control Desk). 1p. 45261:273-45261:299.
- --8804280069 Rev 50 to "QA Program for Nuclear Generating Stations." **Commonwealth Edison Co. CE-1-A R50 88/04/18, 17pp, 45261.274.45261.299
- Q. Inspection reports, IE Bulletins & correspondence
- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors," Syc list and, ROSSIC.E. Division of Operational Events Assessment (Post 870411), 88/03/28, Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995;246.
- 8803220298 NRC Info Notice 88-010, "Matts Licensees:Lack of Mgt Contro's Over Licensed Programs." Svc list encl. CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 687 03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44985;247-44995;353.
- 8804060460 Forwards request for addl Into re util response to IE Bullotin 85:003, "Motor-Operated Valve Common Mode Failures During Plant Transients Due to Improper Switch Settings." Response requested within 1 month of Itr date. GREENMAN, E.G. Region 3, Ofc of the Director. 88/03/31, REED,C. Commonwea'th Edison Co. 5pp. 45007:073-45007:077.

2PP 45092 116 45092:128.

PRepts 50:373/88-04 & 50:374/88-04 on 880210:0325 No violations noted Major lareas inspected provious insplicatings operational manage. LERs outagos unit trips & mg1 meeting. https://doi.org/10.1007

C In'o Nolice 88-011, "Potential Loss of Molor Contro! Cir 8/or Switch-Dus to Faully Tis Botts "Swc 1st enc! Discontrol Operational Events Assossmont (Post 870411), 88/04/07, Edison Co of New York, Inc. 124pp. 45406.292-45407.051

Avaids Safety Insp Hepts 50.373/88-06 & 50.374/88 06 on 880314-18 (Clation Most significant observations made by inspectors Islad Region 3, Oz of the Director, 88/04/08, REED.C Commonwealth pp. 45153 001-45153.013

office of victation from Insp. on 880314-18 Victations noted 64 discrepare open greater than 90 days & included problems winstruments out allation of nonseterly-related parts in safety rotated sys. Region 3, Olc of the Director, 88/04/08, 1p. 45153-003-45153:003

Insp Repls 50-373/88 06 & 50-374/88-06 on 880314-18. Violations areas inspected maint activities & liconsee actions on previous insp l'indiction concla wiplanned outage.

IOULES,NC., JABLONSKI,F.J. Region 3, Old of the Director 88/04/08.

O04-45153 013

FRG Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc

Cojvision of Operational Events Assossment (Post 870411). 88/04/12 Edison Co of New York, Inc. 123pp. 45165.028-45165.150

onlitms plans discussed on 880414 botween H Biss & G VanSckle to 0.505 meeting w/ut to discuss response to IE Buttern 85,003. E G Region 3, Oto of the Director 88/04/18. REED,C Commonwealth pp. 45251:120-45251:121.

Orwards Salety Insp Repts 50 373/88 05 & 50 374/88 05 on 680332.

pms noted.

3. Region 3, Ofc of the Director 88/04/19. REED,C. Commonwealth pp 45254:301-45254:312.

rnsp Repts 50:373/88 05 & 50:374/88-05 on 880302-10 No violations or noted Major areas inspected chemistry program.including riganization.training & reactor sys water OC control programs. ER.M.C. HOUSEJE Region 3, Ofc of the Director 88/04/19, 10pp 5254/312.

erating reports & related correspondence

to ron protection plan annual operating rept for 1987. ⊒ J. Commonwealth Edison Co. 88/03/25, DAVIS,A.B. Reg.on 3, Olc of Bpp. 45021:235-45021:240.

Onthly operating ropts for Mar 1988.W/880410 ltr. .SJ., DIEDERICH,G.J. Commonwealth Edison Co. 88/03/31, 36pp. .8J DI

Occurrences, LERs & related correspondence

≟FR 88-002-00 on 880316,Type B & C total loakage exceeded 0.6 La 11e testing Cause undetermined Valves repaired as necessary W/880415

PIEDERICH,G.J. Commonwealth Edison Co. 88/04/15, 4pp. 45218 086-

aninations.

Sponds to FOIA request for Info ro scores of reactor operators & senior fors Forwards requalification exam summary source sheets listed in encilled privacy info deloted.

H. Division of Rules & Records (Post 870413), 88/04/19, BOLEY,K. Significat Mass Energy Project, 2pp. 45213,003-45213,095.

eckage of NRC administered requalification exam resu'ts suminary. ●1ailed Alfitation Given 87/07/20, 88pp. 45213:007-45213 085.

4 LASALLE COUNTY STATION, UNIT 2

dical, emergency & fire protection plans

Vised emergency plan implementing procedures, including Rev 6 to LZP-sitication For Generating Station Emergency Plan Conditions," Rev 0 to Amodel Operation" & Rov 6 to LZP-1330, "Samp"ing..." Alth Edison Co. 88/04/06. 52pp. 45146 267-45146 318.

oims that util 880330 submittel re scope & objectives for 860615 Planie: Region 3, Old of the Olirector, 68/04/06, REED.C. Commonwealth 45163.353-45163.353.

Vised emergency plan implementing procedures including Rev 4 to LZP-Diling of Process Waters Containing Radioactivity at High Radiation & Rev 1 to LZP-1330-30, "Transfer of Wastes from High Radiation...." at Edison Co. 88/04/06: 47pp. 45239:254-45239.300.

- 8804220012 Forwards Rev 4 to updated FSAR for LaSalle County Station Units 1 & 2 ALLEN, C M. Commonwealth Edison Co. 897-04708. Document Control Branch (Document Control Oask). 2pp. 45227-217-45229-337.
- --8804220013 Roy 4 to updated FSAR for LeSa le County Station Units 1 & 2. Commor:wealth Edison Co. 88/04/30, 900pp. 45227 219 45229 307

P. Operating license stage documents & correspondence

- 8803080125 Forwards safety evaluation conditionally supporting proposed design of standby I quid control sys consistent w/ requirements of 10CFR50 82 Values of concentration & selpoint should be included in Tech Specific.

 MULLER,DIR Project Directorate III-2, 88703/01 BUTTERF,ELD,LID Commonwealth Edison Co. 4pp. 44633-309-44633-316.
- --8803080131 Safety evaluation supporting standby liquid control sys consistent w/ 10CFR50.62 Project Directorate III-2 86703701, 4pp. 44633.313-44633.316
- 8803080447 Forwards Arnends 55 & 36 to Licenses NPF-11 & NPF-18, respectively & safety evaluation Amends revise Tech Specs to jet pump operability surveillance & corrocts types.

 SHEMANSKI,P. Project Directorale III-2 88/03/04 BUTTERFIELD.L Commonwealth Edison Co. 2pp. 44639.036.44639.020.
- --8803080455 Amends 55 & 36 to Licenses NPF-11 & NPF-10 respectively, levising Tech Spacs religit pump operability surveillance & correcting types MULLER, D.R. Project Directorate III-2, 88703764, 10pp, 44630 008-44639:017.
- -8803080460 Safety evaluation supporting Amends 55 8 36 to Licenses NPF-11 & NPF-18, respectively, 1 Project Directorate III-2, 88/03/04, 3pp. 44639 018-44639 020.
- 8803240426 Generic Ltr R8-66 to all power reactor I consoos 8 applicants re removal of organization charts from Tech Spec administrative control requirements. Sec list encl. MIRAGUIA,F.J. Associate Director for Projects (Post 870411) 88/03/22 Consolidated Edison Co. of New York, Inc. 47pp. 44972 107-44972 153.
- 8804060476 Informs that plant A.Model schodured for operation on 680331 now projected to be appearonal by 800630 due to complexity of program JOHNSON.LM, Commonwealth Edison Co 88/03/30 DAVIS.A.B. Region 3, Oto of the Director. 1p 45093:046-45093.046.
- 8804130377 Forwards request for additinto on alternate rod injection & recirculation pump. Irip. sysipor. util. 870406. 8. 1023. Itis ire. Impromentation of ATWS rule 10CFR50.82 Response requested by 880420 in order to meet scheduled safety evaluation. SHEMANSKI.P. Project Directorate III-2 88/04/06 BUTTERFIELD,L. Commenwealth Edison Co. 8pp 45103 220-45103 227.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants" Syc list enci. MIRAG1IA,F.J. Associate Director for Projects (Post 8704111), 68/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45184.237-45164.285
- 8804280039 Forwards Rev 50 to CE-1-A, "OA Program for Nuclear Generaling Stations." Rovs boing made to reflect organizational changes. MORGAN,W.E. Commonwealth Edison Co. 88/04/18. Document Control Branch (Document Control Desk), 1p. 45281:273-45261:299.
- **8804280089 Rov 50 to "OA Program for Nuclear Generating Stations."
 **Commonwealth Edison Co. CE-1-A R50, 88704/18, 17pp, 45261-274-45261-299.

Q. inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87 044, "Thimble Tube Tinning in Westing-house Reactions." Sec list and ROSSICE Owision of Operational Events Assessment (Post 870411) 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995.126.44995:246
- 8803220296 NRC Info Notice 88-010, "Matis Licensees:Lack of Mgt Controls Over Li-censed Programs" Svc list encl. CUNNINGHAM, R E Ovision of Industrial & Medical Nuclear Safety (Post 870729) 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353
- 8804050480 Forwards request for add1 info re util response to IE Builotin 85-003. "Motor-Operated Valve Common Mode Fairres During Plant Transionts Due to Improper Switch Settings." Response requested within 1 month of Itr data GREENMAN.E.G. Region 3, Ofc of the Director 88/03/31. REED,C. Commonwea'th Edison Co. Spp. 45007 073-45007 077.
- 8804080027 Forwards Safety Insp Repts 50:373/88-04 8 50:374/88-04 on 880210-0325 No violations noted FORNEY,W.E. Region 3, Ofc of the Director, 68/04/04, REED.C. Commonwealth Ecison Co. 2pp. 45092,116-45092,128.
- --8804080030 Insp. Repts 50-373/88-04 & 50-374/88-04 on 880210-0325.No violations of doviations includingly areas inspected previous insp. findings.operational safety, surveillance, trefining. ERS, outages, sunt lips & mgt meeting. BING,MIA. Region 3, Ofciot the Director. 68/04/04. https://doi.org/10.1009/2118-45092.128.
- 8804010256 NRC Into Notice 88-011, "Potential Loss of Motor Control Cir &/cr Switch-board Function Due to Faully Tio Boits." Svc list anci. ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 89/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408:292-45407:051.
- 8804150005 Forwards Safety Insp Repts 50:373/88-06 & 50:374/88-06 on 69/314-18 & notice of violation Most significant observations made by inspectors insted HARRISON.J.J. Region 3, Ofc. of the Director. 88/04/08, REED,C. Commonwealth Edison Co. 2pp. 45153:001-45153.013

- --8804150008 Notice of violation from insp on 880314-18 Violations noted: 64 discrepancy records were open greater than 90 days & included problems w/nstruments out of calibit & installation of nonsafety related parts in safety-related sys HARR-SON,J.J. Region 3, Oze of the Director 88/04/08. Ip. 45153:003.45153.003.
- -8804150009 Insp. Repts 50:373/88/06 8 50:374/88/06 on 880314-18. Violations 8894150009 Insp. Repts. 50:373/88:06. 8:50:374/88:06 on 880314-18. Violations noted Major areas inspected/maint activities & licensee actions on previous insp. lindings schedured to coincide w/planned outage. EICK.S.D., CHOULES.N.C., JABLONSKI,F. J. Region 3, Old of the Director. 88/04/08, 10pp. 45153:004:45153:013.
- 8804060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encil ROSSI.C E. Division of Operational Events Assessment (Post 870411): 88/04/12, Consolidated Edison Co. of New York, Inc. 123pp 45165:028-45165:150.
- 8804250328 Confirms plans discussed on 880414 between H Bliss & G VanSickle re upcoming 880506 meeting w/util to discuss response to IE Bulletin 85-003. GREENMAN.E.G. Region 3, Oto of the Director. 86/04/18. REED,C. Commonwealth Edison Co. 2pp 45251:120-45251.121.
- 8804260068 Forwards Salety Insp Repts 50-373/88-05 & 50-374/88-05 on 680302-10 No violations noted SHAFER.W.D. Region 3, Ofc. of the Director 88/04/19. REED,C. Commonwealth Edison Co. 2pp. 45254:301-45254.312.
- --8804260071 Insp Repts 50-373/88-05 & 50-374/88-05 on 680302-10 No violations or deviations noted Major areas inspected: Chemistry program.including procedures organization,trauning & reactor sys water OC control programs. SCHUMACHER.M.C., HOUSE,J.E. Region 3, Ofc of the Director. 88/04/19. 10pp. 45254:303.45254-312.

R. Periodic operating reports & related correspondence

- 8804070326 Environ protection plan annual operating rept for 1987
 DIEDERICH,G.J. Commonwealth Edison Co. 88703725, DAVIS,A.B. Region 3, Ofc of the Director, 6pp. 45021;235-45021;240.
- 8804140330 Monthly operating repts for Mar 1988.W/880410 ltr.
 SAMOLINSKI,S.J., DIEDERICH,G.J. Commonwealth Edison Co. 88/03/31, 36pp. 45151:277-45151:313.

S. Reportable occurrences, LERs & related correspondence

- 8804040201 PNO III-88-0183 on 880316 augmented insp. team dispatched to site to roview events re 860309 dual recirculation pump trip followed by loss of feedwater heating resulting in reactor scram Unit restarted on 880318 w/o further problems. RING.M., FORNEY,W. Region 3, Ofc. of the Director, 88/03/25, 2pp. 45078:105-
- 8804050267 Summary of Operating Reactor Events Meeting 88.012 on 880322 List of attendeps discussion of events & rept-to-date of long-term followup assignments & aummary reactor screms enci.

 LANNING,W. Events Assessment Branch. 86/03/29. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 13pp. 45017;292-45017;304.
- 8804050374 LER 86 001-00 on 880302,28 diesel generator cooling water pump failed to aulo start Caused by contact (5-6) of relay 2E22-K18 being pitted & out of alignment Pitted & misaligned contacts cleaned,burnished & realigned,W/660331 ftr, SAMPSON,P., DIEDERICH,G.J. Commonwealth Edison Co. 88/03/31, 5pp. 45045 224-45045-228.
- 8804080047 LER 88-002-00:on 880303.Group 10 isolation occurred white performing instrument surveillance test Caused by failed contact on test switch Test switch replaced tested & returned to operation.W/880401 ltr.

 JACKEN,N.W., DIEDERICH,G.J. Commonwealth Edison Co. 88/04/01. 6pp. 45098.163-45098-167.
- 8804140127 LER 88-003-00 on 880309 reactor scram on neutron flux high from APRMs occurred due to neutron flux oscillation Caused by personnel error for initial transient & procedural inadequacy for scram.Personnel counseled,W/880407 ltr. RICHTER.M.H., DIEDERICH,G.J. Commonwealth Edison Co. 88/04/07. 6pp. 45183:335-45183:340.

V. Operator Examinations

- 8804250088 Responds to FOIA request for info re-scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in encluapp w/personal privacy info deleted.
 GRIMSLEY.0 H. Division of Rules & Records (Post 870413), 88/04/19. BOLEY.K. Public Critizen's Critical Mass Energy Project. 2pp. 45213:003-45213:095.
- --8804250167 Package of NRC administered requalification exam results summary.

 NRC No Detailed Affiliation Given, 67/07/20, 88pp, 45213:007-45213:095.

DOCKET 50-375 NUCLEAR EXAMINATION REACTOR

P. Operating license stage documents & correspondence

8603250184 Informs of relocation of NRR to Rockville,MD-Official mailing address still remains same & project managers have new locations & phone numbers.TS Michaels still lead project manager for facility & A Adams will serve as backup. RUBENSTEIN,LS. Standardization & Non-Power Reactor Project Directorate. 88/03/18. Affiliation Not Assigned. 3pp. 44856 322-44856:324.

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

- 8804040 107 Revised emergency plan Implementing procedures including Rev 13 to EP-2-010, "Notification & Communications" & Rev 10 to EP-2-130, "Emergency Team Assignments." W/980328 ltr, BURSKIRIF, Louis'ana Power & Light Co 88/03/28, 83pp. 44969:173-44969-254,
- 8804070127 Forwards marked-up Pages 1-2 & 7-7 of Rev 11 to emergency plan, changing location of corporate command cir as listed. Change does not decrease effectiveness of plan based on review of 10CFR50.54(g).
 BURSKIR.F. Louisiana Power & Light Co. 88/04/04. Document Control Branch (Document Control Desk). †p. 45092:101-45092:103.
- -8804070186 Markert-up Pages 1-2 & 7-7 of Rev 11 to Waterford 3 Steam Electric Sta-Ilon emergency plan.
 * Louisiana Power & Light Co. 88/04/04. 2pp. 45092:102-45092:103.
- 8804070207 Advises that exercise objectives meeting scheduled for 880523 to discuss 881012 emergency exercise objective prior to submittal to NRC & FEMA. BURSKI,R.F. Louislana Power & Light Co. 88/04/04. Document Control Branch (Document Control Desk). 1p. 45075 035-45075.035.
- 8804200333 Forwards "Finat Radiological Emergency Proparedness Exercise Rept," did 880122 re uill 871014 exercise No deficiencles identified Approval granted under 44CFR350 on 850715 remains in effect.
 CALLAN,L.J. Region 4, Otc of the Director, 88/04/14. DEWEASE,JG Louisena Power & Light Co. 2pp. 45218:155-45218:203.
- 8804 190291 Forwards "Waterlord 3 Nuclear Unit Satety Info,Pians to Help During Emergencies." for Info & use Booklet recently distributed to general public in area of gencies," for Info & use Booklet recently distributed to general public in area of plant Widne oversize encl.

 BURSKI, R.F. Louislana Power & Light Co. 88/04/15. Document Control Branch (Document Control Desk). 9pp. 45225.260-45225:287.

I. Financial Information

- 8904250103 Forwards annual repts for 1987 for Louisiana Power & Light, Inc,New Orleans Public Svc Co & Middle South Utils,Inc. BURSKI, RF. Louisiana Power & Light Co. 66/04/19, Office of Nuclear Reactor Regulation, Director (Post 870411), 1p. 45236:285-45237.076.
- --8804250111 "New Orleans Public Svc Inc Annual Rept, 1987."
 CAIN,J.M. New Orleans Public Service Co. 87/12/31, 44pp, 45236 341-45237:024.
- --8804250115 "Middle South Utils, Inc. Annual Rept. 1987." LUPBERGER,E. Middle South Utilities, Inc. 87/12/31, 62pp. 45237:025-45237.076

J. Insurance & Indomnity information

8803310104 Forwards documentation from ANI & Electric Insurance,Ltd, evidencing present coverage in effect for onsite property damage insurance.

BURSKI,R.F. Louisiana Power & Light Co. 88/03/28. Document Control Branch (Document Control Desk). 5pp. 44996:084-44996.088.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8803300241 Application for Tech Spec Change Request NPF 38-75 to Licenso NPF-38 re fire detection instrumentation Fee paid.

 DEWEASE,J.G. Louislana Power & Light Co. 88/03/22. Document Control Branch (Occument Control Desk). 6pp. 44975:278-44975-283.
- --8803300242 Proposed Tech Specs re fire detection instrumentation.

 * Louislana Power & Light Co. 88/03/22. 9pp. 44975:284-44975:292.
- 8803300176 Application for amend to License NPF-38, changing bases section of Tech Spec 3.5.2. "ECCS Subsystems." BURSKIR, F. Louislans Power & Light Co. 88/03/24, Document Control Branch (Document Control Desk). 3pp. 44961.087-44961.073.
- --8803300180 Proposed Tech Specs re ECCS.

 * Louislana Power & Light Co. 88/03/24, 4pp. 44981:070-44961:073.
- 8803310009 Forwards control wiring diagrams for 4.16 kV 3B3·S bus undervoltage relays.Diesel Generator B engine control interface & Sequencer B. MEISNER, M.J. Louiselane Power & Light Co. 68/03/25. WIGGINTON,D.L. NRC · No Detailed Alfillation Given. 9pp. 44965;114-44985;118.
- 8803310265 Application for amend to License NPF-38, revising Tech Spec 3.1.2.9 to regular plant operators to isolate unborated primary makeup to RCS when in Modes 4 & 5 in order to minimize potential for boron dilution event. DEWEASE,J.G. Louisiana Power & Light Co. 68/03/25. Document Control Branch (Document Control Desk). 7pp. 46008:229-45008;251.
- -88033 10266 Proposed Tech Spec 3.1.2.9,incorporating controls to require plant opera-tors to isotate unborated primary makeup to RCS when in Modes 4 & 6 to minimize potential for boron diution even).

 **Louislana Power & Light Co. 88/03/26, 16pp, 45008:236-45008:251.

- 8803310171 Application for amend to License NPF-38, requesting change to Tach Spec bases socion to better reflect control room air conditioning sys design Fae paid. BURSKI, B. F. Louisiana Power & Light Co. 88/03/28. Document Control Branch (Document Control Desk). 8pp. 44964:083-44984.073.
- -8803310173 Proposed Tech Spec change to bases section to better reflect control room air conditioning sys design.

 * Louislana Power & Light Co. 88/03/28, 4pp. 44984:071-44984:073.
- 8804040057 Application for amend to License NPF-38, consisting of Tech Spec Change Request NPF-38-77, revising Tech Spec 6.5.1.6, "Plant Operations Review Committee" & adding Spec 6.5., "Fechnical Roview." Fee paid DEWEASE_J.G. Louislana Power & Light Co. 88/03/29. Document Control Branch (Document Control Desk). 6pp. 44970.059-44970.074.
- --8804040061 Proposed Tech Specs,revising Tech Spec 6.5.1.6, "Plant Operations Review Committee & adding Spec 6.5.3, "Technical Review."

 * Louisiana Power & Light Co. 88/03/29, 10pp. 44970.065-44970.074.
- 8804080247 Forwards Amend 34 to License NPF-38 & safety evaluation. Amend revises Tech Specs by adding requirement to have two emergency core cooling sys subsystems operable when average temp of RCS exceeds or equals to 500 F. WIGGINGTON,DL. Project Directorate IV. 88/03/30. DEWEASE,J.G. Louisiana Power & Light Co. 4pp. 45065:001-45065:038.
- --8804080250 Amend 34 to License NPF-38, revising Tech Specs by adding requirement for having two emergency core cooling subsystems operable when average RCS tempexceeds or equals to 500 F. CALVO, J.A. Project Directorate IV. 88/03/30. 11pp. 45085:005-45065.016.
- -8904080251 Safety evaluation supporting Amend 34 to License NPF-36.

 * Office of Nuclear Reactor Regulation, Director (Post 870411). 88/03/30. 3pp. 4508-016-45065-038.
- 8804110002 Forwards SER accepting util 831104 & 15 responses to Generic Lir 83:28 Concerning programs for equipment for classification of all safety-related components. Technical evaluation rept also encl. WIGGINTON,D.L. Project Directorate IV, 88/03/30. DEWEASE, J.G. Louislana Power & Light Co. 4pp. 45071:044-45071:073.
- 8804110004 SER accepting util proposal re Item 2.2.1 of Generic Ltr 83-26 concerning equipment classification programs for all safety-related components.
 Project Directorate IV. 88/03/30. 6pp. 45071:048-45071:073.
- 8804060302 Application for amend to Licenso NPF-38,consisting of Tech Spec Change Request NPF-38-78 Amend revises surveillance requirements for hydrogen analyzers. During Apr 1988, refueling outage hydrogen analyzors will be replaced. DEWEASE,J.G. Louislana Power & Light Co. 88/03/31. Document Control Branch (Document Control Desk). 5pp. 45034:175-46034:182.
- ~8604060305 Proposed Tech Specs consisting of Tech Change Request NPF-38-78 re hydrogen analyzers. Louislana Power & Light Co. 88/03/31, 3pp. 45034:180-45034:182.
- 8804080209 Forwards Amend 35 to License NPF-38 & safety evaluation. Amend changes Tech Specs by revising shutdown cooling flow to 2,000 gpm at 375 h after reactor shutdown.

 WIGGINTON,D.L. Project Directorate IV. 88/04/01. DEWEASE,J.G. Louisiana Power & Light Co. 4pp. 45064:337-45084:348.
- --8804080221 Amend 35 to License NPF-38, changing Tech Specs by revising shutdown cooling flow to 2,000 gpm at 376 h after reactor shutdown. CALVO,J.A. Project Directorate IV. 88/04/01, 6pp. 45064:341-45064:345.
- -8804080229 Safety evaluation supporting Amend 35 to License NPF-36, Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/01, 3pp. 45064.348-45064.348.
- 8804110166 Forwards Revs 4 & 5 to "Pump & Valve Inservice Test Plan." Rev 5 contains typo which will be corrected in next rev.
 BURSKI,R.F. Louislana Power & Light Co. 88/04/04. Document Control Branch (Document Control Desk). 11pp. 45148:024-45146:034.
- 8804110165 Responds to Generic Ltr 88-03 re implementation & maint of procedures to reduce probability of suxillary feedwater pump feiture due to steam binding. Surface mounted thermometers on pump discharge lines installed & procedures implemented. BURSKI,R.F. Louislans Power & Light Co. 88/04/05. Document Control Branch (Document Control Desk). 2pp. 45135.076-45135:077.
- 8804210376 Forwards Technical Evaluation Rept EGG-NTA-7883, "TMI-Action NUREG-0737 (II.D.1) Relief & Safety Valve Testing, Waterlord Steam Electric Station Unit 3." Util response acceptable based on results of review. WIGGINTON,O.L. Project Directorate IV. 88/04/05. DEWEASE,J.G. Louisiana Power & Light Co. 4pp. 45191:294-45191:317.
- --8710140348 "TMI Action-NUREG-0737 (II.D.1) Relief & Safety Valve Testing Water-ford Steam Electric Station.Unil 3." technical evaluation rept.
 PACE,N.E., FINEMAN,C.P. EG&B Idaho, Inc. (subs. of EG&G, Inc.). PACE,N.E. Idaho National Engineering Laboratory. FIN A-8492. EGG-NTA-7863. 87/09/30, NRC No Detailed Affiliation Given. 20pp. 45191:298-45191:317.
- 8804140275 Requests addi into to complete review of licensee response to Generio Ltr 83-28 litem 1.2.Response found to be incomplete in three areas evaluated.Appears that needed into on facility could be obtained by leicon. WIGGINTON,D.L. Project Directorate IV, 88/04/08. DEWEASE,J.G. Louisiana Power & Light Co. 4pp. 45118:267-45118:275.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re modified enforcement policy concerning 10CFR60.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svo list and: MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 804130342 Forwards revised Attachments 2 & 3 to updated QA program description, FSAR Chapter 17.2 to aid in review. BURSKI, RF. Louisiana, Power & Light Co. 88/04/07. Document Control Branch (Document Control Desk), 81pp. 45148:183-45146;283.

- 8804180155 Forwards safety evaluation supporting util 840229 & 870707 Itrs re natural circulation cooldown tests performed at plant Util demonstrates conformance w/Technical Position RSB 5-1, "Design Requirements of RHR Sys." WIGGINTON, D.L. Project Orectorate IV. 88704708 DEWEASE, J.G. Louisiara Power & Light Co. 4pp. 45149 097-45149-116
- --9804180171 Saloty evaluation suporting natural circulation cocidown tests performed at plant.per will 840229 & 870707 trs.per Suppl 1 to NUREG-0787

 Office of Nuclear Reactor Regulation, Director (Post 870411): 88/04/08 3pp 45149:101-45149:103.
- -- 8804050231 "Technical Evaluation Rept for Natural Circulation, Boron Mixing & Cool-
- beutqubux31 "Technical Evaluation Rept for Natural Circulation,Boron Mixing & Cooldown at Waterford Unit 3."

 JOJ.H., PERKINS.K.R. Brookhaven National Laboratory, FIN A-3843, 88/03/31 Office of Nuclear Reactor Regulation, Director (Post 870411), 21pp. 45149.104-45149.116.
- 8804220128 Requests that util remit fee for 880303 application for exemption from requirement to terminate Type A containment leakage test for conditions listed in Section III A.1(a) of 10CFR50,App J.

 DIGGS.R.M. License Fee Management Branch. 88/04/15. COOK,K.W. Louisiana Power & Light Co. 1p. 45200:360-45200:360.

Q. Inspection reports, IE Bulletins & correspondence

- 8804180224 Forwards "1997 SALP Progress Rept," for current SALP rating period for Feb 1987 Jul 1988.Rept will be supplemented w/ review of outage activities following completion of outage.

 DEWEASE.J.G. Louisiana Power & Light Co. 88/03/24. MARTIN.R.D. Reg on 4, Ofc of the Director. 2pp. 45129:162-45129 219.
- --8804110270 "1987 SALP Progress Rept."

 * Louisiana Power & Light Co. 88/03/31, 58pp. 45129;184-45129 219.
- B804050117 Advises that contractor review of inservice insp program through Rev 2 & NRC review of differences between Revs 2 & 3 submitted by 871120 itr complete. Safety evaluation should be issued before end of refueling outage in Apr
- CALVO.J.A. Project Directorate IV. 88/03/25. DEWEASE.J.G. Louisiana Power & Light Co. 5pp. 45029.068-45029.073.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimb'e Tube Thinning in Westing-house Reactors," Svc list encl.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995-246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees.Lack of Mgt Controls Over Liconsed Programs." Svc list enct.

 CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 88/03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995-247-44995.353
- 8804110269 Responds to NRC Bulletin 88-001 re defects in Westinghouse circuit breakers. Util does not use Westinghouse Series DS circuit breakers & not subj to inspa requested in bulletin.

 BURSKI,R.F. Louislana Power & Light Co. 88/03/29. MARTIN,R.D. Region 4, Otc of the Director. 2ρρ. 45129:324-45129.349.
- -- 8801040586 NSID-TB-87-11, "Westinghouse Circuit Breakers Type DS/DSL: Welds on Breaker Pole Shaft."
 DEB.A., SMITH.W.J. Westinghouse Electric Corp. 87/12/01. 17pp. 45129:331-45129:331-
- 8804040208 Responds to violations noted in Insp. Rept. 50-382/87-31. Corrective actions:CC verified that forque values used in work package correct for application & Procedure MM-6-004 revised to include instructions for assembly of couplings. BURSKI,R.F. Louislang Power & Light Co. 88/03/30. Document Control Branch (Document Control Desk), 5pp. 45076:115-45076:119.
- 8804040246 Forwards Insp Rept 50-382/88-04 on 880201-0315 & notice of violation. Directs attention to repeat fallure to store combustible lluids in liammable
- Violation Colors automotic in Experimental Colors (Region 4, Old of the Director, 88/03/30, DEWEASE, J.G. Louis'and Power & Light Co. 2pp. 45072:001-45072:011.
- --8804040249 Notice of violation from Insp on 880201-0315. Violation noted: two cans of lubrication oil found unattended & not slored in flammable laguds locker on -4 level of reactor auxiliary blod wing area which has no liquids lockers.

 * Region 4, Ofc of the Director, 88/03/30. 1p. 45072:003-45072.003.
- --8804040252 Insp Rept 50-382/68-04 on 880201-0315.Violations noted Major ereas inspected operational safety verification, onsite followup of events, monthly maint observation, ESF sys walkdown, monthly surveillance observation & plant status SMITH, W.F., STAKER, T.R., CHAMBERLAIN, D. Region 4, Ofc of the Director 88/03/28, 8pp. 45072:004-45072:011.
- 8904110155 Responds to Generio Ltr 88-03 re Implementation & maint of procedures to reduce probability of auxiliary feedwater pump failure due to steam binding Surface mounted thermometers on pump discharge lines Installed & procedures Implemented. BURSKI,R.F. Louislana Power & Light Co. 88/04/05. Document Control Branch (Document Control Deak). 2pp. 46135:076-46135.077.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Cit &/or Switch-board Function Due to Faulty Tie Bolla." Svc list encl. ROSSLC.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407:051.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc. list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165 150.
- 8804250082 Forwards Insp Rept 60-382/88-06 on 880229-0304.No violations or devi-Actions noted.

 OALLAN,L.J. Region 4, Otc of the Director. 88/04/15, DEWEASE,J.G. Louistena Power & Light Co. 2pp. 45268:114-45268:124.

- -8804250067 Insp. Rept. 50:382/88.06 on 880229-0304 No violations or deviations noted Concern re-operation of Diesel Generator A outsido of design basis noted Major areas inspected diesel generator reliability/operability & Tech Spec reportability. KELLEY, D.L., P.CK.G.A., SEIDLE, W.C. Region 4, Ofc of the Director. 88/04/12. 9pp. 45258, 116-45268, 124.
- 8804250334 Forwards thisp Rept 50:382/68-05 on 860307-11 No violations or devi-ations noted.Post-accident sampling sysid scussod. CALLANIL J. Region 4, Ofci of the Director. 88/04/15. DEWEASE.J.G. Louisiana Power & Light Co. 3pp. 45254-138-45254-161.
- -8804250336 Insp Rept 50-382/88-05 on 880307-11 No violations or deviations noted Major areas (inspected chemistry radiochemistry program & water chemistry & radiochemistry confurmatory measurements MICHOLAS, J B., WISE, R., MURRAY, B. Region 4, Ofci of the Director, 88/04/07, 21pp. 45254:141-45254:161.

R. Periodic operating reports & related correspondence

8804190289 Monthly operating rept for Mar 1988 W/880415 ltr.
MILLER,G., BURSKI,R.F., Louisiana Power & Light Co. 88/03/31, 7pp. 45215.232-45215.238.

S. Reportable occurrences, LERs & related correspondence

- 8803280085 Special Rept SR-85 002-01 on 851230 discovered emergency diesel generator A faited to complete surveillance run as defined in Procedure OP-903-068 & Tech Spec 4,8 1.1 2 s. Cause not determined Minor adjustments made to governor. CARNS,N S. Lou-stand Power & Light Co. 88/03/21. Document Control Branch (Document Control Dask). 4pp. 44961:205-44961 208.
- 8804070213 LER 88-004-00 on 880303, Identified that environ qualification of containment isolation valve position indication was suspect Caused by personnel error due to improper review W4860404 ftr
 BAKERDE., CARNS,N.S. Louisiana Power 8 Light Co. 88/04/04 7pp. 45072:260-45072 266.
- 8804210259 Retracts Special Riept SR-68-002-00, "Radioactively Contaminated Tools Discovered in Unrestricted Areas." Review of event determined that too's never inside CARNS,N.S. Louisiana Power & Light Co. 88/04/12 Document Control Branch (Document Control Dask). 1p. 45235;204-45235;204
- 8604200373 LER 88:004-01:on 880303, required environ soal (ES) found missing from valve position indication (VPI) conduit VPI may not have complied w/Reg Guide 1.9.7 Caused by porsonnel error due to improper review ES instelled W/880418 III BAKEHDE. CARNS,N.S. Louisiana Power & Light Co. 88/04/18. 7pp. 45221:171-45221:177
- 8804200377 LER 87-029-00 on 870402, failure to meet safety to nonsafety electrical dis-tribution separation criticinal discovered Caused by cognitive personnal error in devel-oping design changes Sys suport to review design changes W/880418 itr. BAKER, D.E., CARNS, N.S., Louistana Power & Light Co. 88/04/18, 7pp. 45239-081-45239.097
- 8804200379 LER 87-030-00 on 870819.gas decay tank hydrogen & oxygen samples not analyzed at required interval Caused by plugged sample injection syringe for gas chromatograph Syringe repaired Station modification implemented. W/880418 ttr. ALLEN,R.E., CARNS,N.S. Louisiana Power & Light Co. 88/04/18 7pp 45220.328-
- 8804200363 LER B7-031-00:on 871021, personnel discovered containment isolation valvos exceeded required stroke-time surveillance periodicity Caused by inadequate administrative controls. Procedures revised to account for components.W/880418 ltr. SCHULTZ,D A., CARNS,N.S., Louisiana Power & Light Co., 68/04/18, 8pp. 45220 285-45220 292.
- 8804270055 LER 88-005-00 on 880321,blown undervoltage circuit fuse replacement results in Tech Spec 3.0.3 entry. Caused by inadvarient shortening of two wind connections Change to Tech Spec being pussued to correct delicency. W/880420 ltr. GAINES, C. R., CARNS, N. S. Lou s'ana Power & Light Co. 88/04/20. 11pp. 45282:101-
- 8803280037 LER 97.022-01 on 870814,ESF venilation actuations occurred due to shorted relay Caused by failure of Nuclear Analog Comparator (NAC) card which caused cycling 8 subsequent overheating NAC card replaced W/680321 lir BAKER,DE., CARNS,N.S. Louisiana Power & Light Co. 88705/21. 4pp. 44920.014-44920 017

DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8604140095 Notification of 880331 Licensee Meeting 88 049 w/util at Region I ofc to discuss I censee schedule for App R upgrafes & compensatory measures. BLOUGH.A.R. Region 1, Ofc of the Director. 88/03/25 Region 1, Ofc of the Director. 2pp. 45122.259.45122.260.
- 8804260015 Informs of completion of review of physical security plan Change AA trans-milled by util 871228 Nr.Changes consistent w/10CFR50.54(p) & considered accepta-BELLAMY, R.R. Region 1, Ofc of the Director, 88/04/15, KEISER, H.W. Pennsylvania Power & Light Co. 3pp. 45251;113-45251;115.
- 8804290288 Revised emergency plan implementing procedures including Rev 4 to EP-IP-029, "Activation of Technical Support Ctr" & Rev 6 to EP-IP-042, "in-Plant & Emergency Operations Facility Chemistry Lab Emergency Preparation " W7880419 III. KEISER,H.W. Pennsylvania Power & Light Co. 88704719, 121pp. 45282:311-45283.071.

H. General correspondence

8804070149 Confirms conversations w/NRC re-personnel changes at util which are to take place on 880404. Author promoted to senior vice president-nuclear.FSAR w. barevised to reflect change KEISER,H.W. Pennsylvania Power & Light Co. 88703729. BUTLER,W.R. Project Directions torate I-2 1p 45044:169-45044-169.

I. Financial information

- 8804060175 "Pennsylvania Power & Light Co Annual Rept 1987." W/880330 ltr CAMPBELL.R.K., KEISER.H.W. Pennsylvania Power & Light Co. 87/12/31 49:pt 45047:107-45047:156.
- 88D4040116 Forwards 1988 Internal cash flow projection to demonstrate adequate cash flow for payment of deferred promiums.per 10CFR140 21(e). KEISER,H.W. Pennsylvenia Power & Light Co. 88/03/25 RODRIGUEZ,J. Drv.s.cn cl. Accounting & Finance (Post 870413). 2pp. 44970:236-44970-238.

P. Operating license stage documents & correspondence

- 8804130121 Natification of 880302 Licensee Meeting 88:029 in King of Prussia PA to discuss I.censes rept on inattentiveness of shift supervisor.

 BLOUGH,A.R. Region 1, Ofc of the Director, 88/02/24. Region 1, Ofc of the Director 2pp. 45099 288-45099;290.
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re-removal of organization charts from Tech Spec administrative control requirements Svc list end MIRAGLIA F.J. Associate Director for Projects (Post 870411) 88/03/22 Consolidated Edison Co. of New York, Inc. 47pp. 44972 107-44972:153.
- 8804110148 Forwards Amends 76 & 41 to Licenses NPF-14 & NPF-22, respectively & salety evaluelion Amends revise action statement for standby gas treatment sys BUTLER,W.R. Project Orectorate I-2, 88/03/28, KEISER,H.W. Ponnsylvan a Power & Light Co. 3pp. 45071:292-45071:309.
- -8804110161 Amends 76 & 41 to Licenses NPF-14 & NPF-22, respectively, rowsing action statement for standby gas treatment sys. BUTLER,W.R. Project Directorate I-2, 88/03/28, 12pp, 45071;295-45071 336
- --8804110167 Safety evaluation supporting Amends 76 & 41 to Licenses NPF-14 & NPF-22,respectively.

 **Office of Nuclear Reactor Regulation, Director (Post 870411). 88/03/28 3pp. 45071:307-45071:309.
- 8804120157 Forwards Amends 77 & 42 to Licenses NPF-14 & NPF-22, respectively & safety evaluation Amends incorporate changes to Tech Specs re-diesel generalize loading timer.
 BUTLER,W.R. Project Directorate 1.2, 88/03/30, KEISER,H.W. Ponnsylvania Power &

Light Co. 3pp. 45101:058-45101:076,

- --8804120164 Amends 77 & 42 to Licenses NPF-14 & NPF-22, respectively, incorporat-Ing changes to Tech Specs re clesel generator loading timer.
 BUTLER, W.R. Project Directorate I-2, 88/03/30, 12pp, 45101.061-45101.072
- -8804120170 Safety evaluation supporting Amends 77 & 42 to Licenses NPF-14 & NPF-22 respectively.
 * Project Directorate I-2: 88/03/30 2pp. 45101:073-45101:074.
- --8804110279 Notice of issuance of Amends 77 & 42 to Licenses NPF-14 & NPF-22,respectively. Amends modify Tech Specs to incorporate changes re-diesel generafor loading timer. BUTLER W.R. Project Directorate I-2, 88/03/30, 2pp. 45101:075-45101:076
- 8804150126 Forwards Amends 78 & 43 to Licenses NPF-14 & NPF-22, respectively & safety evaluation. Amends revise Tech Specs Sections 3.0.4,4.0.3 & 4.0.4 re-operational conditions in response to Generic Lir 87-09.

 BUTLER,W.R. Project Directorate 1-2, 88/04/04. KEISER,H.W. Pennsylvania Power & Light Co. 3pp. 45134:138-45134-346.

- -8804150136 Amerids 78 & 43 to Licenses NPF-14 & NPF-22, respectively, revising Tech Specs Sections 3.0.4,4.0.3 & 4.0.4 re operational conditions in response to Goneric Lit 87-09. BUTLER,W.R. Project Directorate II-2, 88/04/04, 203pp. 45134:141-45134:341.
- --B804150141 Safety evaluation supporting Amends 78 & 43 to Licenses NPF-14 & NPF-22,respectively.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/04 592 45134-342-45134-346
- 8804140003 Forwards application for proposed Amends 110 & 61 to Licenses NPF-14 & NPF-22, respectively, revising Tach Space re-radiation monitoring instrumentation Fee

paid. KEISER,H.W. Pennsylvania Power & Light Co. 88/04/06. BUTLER,W.A. Project Directorate I-2. 4pp. 45142-252-45142-260.

- --8804140007 Application for Amends 61 & 110 to Licenses NPF-22 & NPF-14, respectively revising Tech Specs re-radiation monitoring instrumentation KEISER,H.W. Pennsylvania Power & Light Co. 88/04/06. 2pp. 45142.256-45142.257
- --8804140008 Proposed Tech Specs re radiation monitoring instrumentation Pennsylvania Power & Light Co. 88/04/06. 3pp. 45142:258-45142:260.
- 8804080088 Genenc Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR60.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Sec isls enct. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164;237-45[64:285.
- 8604250021 Notification of 880421 meeting w/licensee in Rockville,MD to review Econs-THADANI,M. Project Directorate I-2, 86/04/18, MURLLY,T, SN MIRAGLIA,T, NRC - No Detailed Affiliation Given 3pp, 45201:173-45201.175 SNIEZEK.J.,

8804280202 Forwards environ assossment & linding of no significant impact for pro-posed amond to Tech Spec re load profiles for 125 V dc batteries BUTLEH,W R Project Directorate 1-2 88/04/18 KEISER,H W. Philadolphia Electric Co 3pp 45276 239 45276 244

Q. Inspection reports, IE Bulletins & correspondence

8803210090 Suppl 1 to NRC Info Natice 87-044, "Thimble Tubo Thinning in Westinghouse Reactors" Svc list onci ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/03/28

Consolidated Edison Co of New York, Inc. 121pp. 44995 126-44995:246

8803220296 NRC Info Notice 88-010, "Mails Licensees Lack of Mgt Controls Over Licansed Programs "Svc Lst encl.
CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 887
03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353.

8804040020 Forwards into which provides util results for Action Items 5 & 6 of IE Bullis-In 87-002

KEISERH W. Ponnsylvania Power & Light Co. 88/03/29. RUSSELL.W.T. Region 1, Ofc of the Director. 51pp. 44969 301-44969 351.

8804010256 NRC into Notice 88-011, "Patential Loss of Motor Central Ctr. 8/or Switch-board Function Due to Faulty Tie Bolts." Svc list encl. ROSSICE. Division of Operational Events Assessment (Past 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407 051.

8904140484 Discusses util 870911 response to NRC Bullotin 87-001, "Thinning of Pipe Walls at Nuclear Power Plants," Info being used to determine extent of industry par-ticipation & implementation of orosion/corposition inspiritograms, THADANI,M.C. Project Directorate 1.2 88/04/08, KEISER.H.W. Pennsylvania Power & Light Co. 3pp. 45130.143-45130.145.

8804060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc ist enci ROSSI,C.E., Division of Operational Events Assessment (Post 870411) 88/04/12. Consolidated Edison Co. of New York, Inc. 123pg. 45165/028-45165:150.

8804210051 Rosponds to NRC 880314 ltr re violations noted in Insp Repts 50:387/88-04 & 50:388/88-03 Corrective actions on 880113, metal blocking plates on Unit 1 & Unit 2 tactions locked & high radiation proparagins posted in area of each tactor. KEISER, H.W. Ponnsylvania Power & Light Co. 88/04/13. WIGGINS, J.T. Region 1, Oic of the Director. 2pp. 45254:332-45254.333.

3. Periodic operating reports & related correspondence

8804 190110 Monthly operating repts for Mer 1988.W/880414 ltr.
HIRT.J.A., KEISER, H.W. Ponnsylvania Power & Light Co. 88/03/31.
MCDONALD, W.G. Office of Administration & Ruscurcus Management, Director (Post 870413), 10pp. 45209.107-45209.116.

8804270047 "Discharge Maniforing Ropt for Mar 1988" W/880419 ftr. KAUFFMAN, J.T., SAXTON, C.H. Pannsylvania, Power & Light Co. 8 BREZINSKI, R. Pannsylvania, Commonwealth of. 13pp. 45245 039-45245 051. 88/03/31.

S. Reportable occurrences, LERs & related correspondence

8804040096 LER 88:006:00 on 880304,roactor scram occurred Caused by technician in-advertently bumping sensitive protoctive relay in 230 kV switchyard Relay replaced w/ flushmounted relay & protoctive barriers installed W/860328 ltr WEHRYRR BRAMARG Pennsylvania Power & Light Co. 88/03/29. 3pp. 44970 083-44970 086

8804040217 LER 88 005 00 on 880308.unexpected closure of vort & purge containment solation valves during surveillance testing occurred.Caused by jumper failing to make proper contact Yent & purge valves responsed W/880330 ltr.
RYDER,T.S. BYRAM,R.G. Pennsylvania Power & Light Co. 88/03/30, 4pp. 45075 319-45075 322.

8804060257 LER 86 014 01 on 860410 two scram discharge vol level transmitters found isolated during hydrostatic pressure testing of reactor vessel Causad by lack of com-munication. Adm astrative Procedure AD-QA-410 revised W/880331 lir. WEHRY,R.R., BYHAM,B.G. Pennsylvania Power & Light Co. 88/03/31, 4pp. 45034 076-45034.079.

DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8804140095 Notification of 880331 Licensee Meeting 88-049 w/utif at Region I ofc to discuss licensee schedule for App R upgrades & compensatory measures. BLOUGH.A R Region 1, Ofc of the Director. 88/03/25. Region 1, Ofc of the Director. 2pp. 45122 256-45122 260.

8804250015 Informs of completion of review of physical security plan Change AA transmitted by util 871228 ltr.Changes consistent w/10CFR50 54(p) & considered accepta-BELLAMY, R. Region 1, Ofc of the Director, 88/04/15, KEISER, H.W. Pennsylvania Power & Light Co. 3pp. 45251:113-45251:115.

8804290286 Revised emergency plan implementing procedures including Rev 4 to EP-IP-029, "Activation of Technical Support Cit" & Rev 6 to EP-IP-042, "In-Plant & Emer-gency Operations Facility Chem'stry Lab Emergency Preparation." W880419 III: KEISERJHW, Pennsylvania Power & Light Co. 88/04/19, 121pp. 45282311-45283 071.

H. General correspondence

8804070149 Confirms conversations w/NRC re-personnol changes at util which are to take place on 880404 Author promoted to senior vice president nuclear.FSAR will be revised to refect change.
KEISER,H.W. Pennsylvania Power & Light Co. 88/03/29 BUTLER,W.R. Project Directorate F2. 1p. 45044-169-45044-169

i. Financial information

8804060175 "Pennsylvania Power & Light Co. Annual Rept 1987 " W/880330 ltr CAMPBELL, R.K., KEISER, H.W., Pennsylvania Power & Light Co. 87/12/31 49pp. 45047:107-45047:156.

8804040116 Forwards 1988 internal cash flow projection to demonstrate adequate cash flow for payment of deferred pramiums.per 10CFR140.21(a). KEISER,H.W. Pennsylvans Power & Light Co. 88/03/25 ROORIGUEZ.J. Division of Accounting & Finance (Post 870413). 2pp. 44870 238-449/0 238

P. Operating license stage documents & correspondence

8804130121 Notification of 880302 Licensee Meeting 88-029 in King of Prussia PA to discuss licensee topt on inattentiveness of shift supervisor.

BLOUGH,A.R. Regon 1, Otc of the Director. 88/02/24. Regon 1, Otc of the Director. 2pp. 45099.289-45099.290.

8803240428 Generic Ltr 88-06 to all power reactor l'consees & applicants re removal of organization charts from Tech Spec administrative control requirements. Suc list encl. MIRAGLIA, F.J. Associate Director for Projects (Post 870411) 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972.107-44972.153

8803310232 Forwards Tech Specs re RHR waterhammer mod missing from util 880311 request to revise implementation of proposed Amend 57 to License NPF-22 KEISER,H.W. Ponnsylvania Power & Light Co. 88/03/24 Office of Nuclear Reactor Regulation, Director (Post 870411). BUTLER,W.R. Project Directorate 1-2 tp. 45031:094-45031:099.

--8803310235 Proposed Tech Specs re RHR waterhammer mods
* Pennsylvania Power & Light Co. 88/03/24, 5pp. 45031:095-45031:099.

8804010147 Withdraws proposed Amend 52 to Liconse NPF-22,allowing extended operation whome recirculation loop out of svc during Cycle 2 Safety evaluation of Amend 52 requested to support ongoing review of Cycle 3 refeat submitted KEISER,H.W. Pennsylvania Power & Light Co. 88/03/24, BUTLER,W.R. Project Directorate 1-2, 2pp. 45020:014-45020.015.

8804110148 Forwards Amends 76 & 41 to Licenses NPF-14 & NPF-22, respectively & safety evaluation Amends rovise action statement for standby gas treatment sys. BUTLER.W.R. Project Directorise 1-2 88/03/28. KEISER.H.W. Pennsylvaria Power & Light Co. 3pp 45071:292-45071:309.

-8804110161 Amends 76 & 41 to Licenses NPF-14 & NPF-22,respectively, revising action statement for standby gas treatment sys. BUTLER,W.R. Project Directorate 1-2, 88/03/28, 12pp 45071,295-45071,306

--8804110187 Safety evaluation supporting Amends 78 & 41 to Liconses NPF-14 & NPF-22,respectively.

Office of Nuclear Reactor Regulation, Director (Post 670411), 68/03/28, 3pp. 45071;307-45071;309.

8804120157 Forwards Amends 77 & 42 to Licenses NPF-14 & NPF-22, respectively & safety evaluation Amonds incorporate changes to Tech Specs re diesel generator Toading timer. BUTLER,W.R. Project Directorate I-2: 88/03/30. KEISER,H.W. Pennsylvania Power & Light Co. 3pp. 45101.058-45101.076

-8804120164 Amends 77 & 42 to Licenses NPF-14 & NPF-22, respectively, incorporating changes to Tach Specsife diesel generator loading limer. BUTLER,W.R. Project Directorate 1-2, 88/03/30, 12pp. 45101 061-45101:072

--8804120170 Salety evaluation supporting Amends 77 & 42 to Licenses NPF-14 & NPF-22;respectively.

* Project Cirectorate I-2. 88/03/30, 2pp. 45101 073-45101:074.

--8804110279 Notice of Issuance of Amends 77 & 42 to Licenses NPF-14 & NPF-22, respectively Amends modify Tech Specs to incorporate changes reld eset genera-tor loading timer. BUTLER, W.R. Project Directorate I-2 88/03/30. 2pp. 45101.075-45101.076

8804150126 Forwards Amends 78 & 43 to Liceases NPF-14 & NPF-22, respectively & safety evaruation Amends revise Tech Specs Sections 3.0.4.4.0.3 & 4.0.4 re operational conditions in response to Generic Lift 87-09.
BUTLERW.F. Project Directorate 1-2. 88/04/04. KEISER,H.W. Pennsylvania Power & Light Co. 3pp. 45134.138-45134.346

-8804150136 Amends 78 & 43 to Licenses NPF-14 & NPF-22, respectively, revising Tech Spacs Sections 30 4,4 0 3 & 4,0 4 re operational conditions in response to Generic Lir 87-09.

BUTLER,W.R. Project Directorate 11-2, 88/04/04, 203pp. 45134:141-45134:341.

--8804150141 Safety evaluation supporting Amends 78 & 43 to Licenses NPF-14 & NPF-22 respectively.

* Office of Nuclear Reactor Regulation, Oractor (Post 870411), 88/04/04, 5pp. 46134:342-45134:346.

8804140003 Forwards application for proposed Amends 110 & 61 to Licenses NPF-14 & NPF-22, respectively, revising Tech Specs re-radiation monitoring instrumentation Fee pald KEISER,H.W. Pennsylvania Power 8 Light Co. 86/04/06. BUTLER,W.R. Project Direc-torate I-2. 4pp. 45142:252.45142:260.

--8804140007 Application for Amends 81 & 110 to Licenses NPF-22 & NPF-14, respectively, revising Tech Specs to radiation monitoring instrumentation. KEISER,H.W. Pennsylvania Power & Light Co. 88704/08 2pp. 45142-256-45142-257.

- ~8804140008 Proposed Tech Specsire radiation monitoring instrumentation * Pennsylvania Power & Light Co. 88/04/06, 3pp. 45142 258-45142 260
- 8804080088 Generic Ltr 88-07 to power reactor I censees & applicants re-modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Flants." Svc 1st end. MRAGLIA,F. J. Associate Director for Projects (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164-237-45164-285
- 8804150431 Forwards application for amend to License NPF-22, changing Tech Specs re-drywell cooling sys Fee paid KEISER H.W. Pennsylvania Power & Light Co. 88/04/08. BUTLER, W.R. Project Directorate I-2, 3pp. 45183,116-45183,122.
- --8804150438 Application for proposed Amend 62 to License NPF-22,revising 3.6.6.2 & Table 3.8.4.1-1 re drywe!! cooling sys Fee pa'd KEISER.H.W. Pennsylvania Power & Light Co. 88/04/08. 1p. 45163:119-45183:119.
- -8804150439 Proposed Tech Specs re drywell air flow sys * Pennsylvania Power & Light Co. 86/04/08 3pp 45183.120-45183 122.
- 8804280211 Forwards notice of consideration of Issuance of amend to facility OL & proposed NSHC determination & opportunity for hearing Natice re 880408 application for amend reflecting fact that previously proposed mods involving installation THADANI,M.C. Project Directorate 1-2, 88/04/12, KEISER,H.W. Pennsylvania Power & Light Co. 3pp. 45266:252-45266:261
- -8804280223 Notice of consideration of issuance of amend to Licenso NPF-22 & proposed NSFIC determination & opportunity for hearing Amend would delate ref to recirculation lans & flan associated breakers & add fans 2V415 A88 & breakers BUTLER,W.R. Project Orectorate I-2 86/04/12, 7pp. 45266 255-45266 261.
- 8804250021 Not-fication of 880421 meeting w/ficensee in Rockville,MD to review Leansing action schedules
 THADANIM. Project Directorate I-2 88/04/18 MURLEY,T, SNIEZEKJL,
 MIRAGEIA,T, NRC No Detailed Affiliation Given 3pp 45201:173-45201:175
- 8804280202 Forwards environ assessment 8 finding of no significant Impact for proposed amend to Tech Spocine load profiles for 125 V dc batteries. BUTLER,W.R. Project Orectorate I-2 88/04/18. KEISER,H.W. Philadelphia Electric Co. 3pp. 45276239.45276.244

O. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors" Svc list encl.
 ROSSI/C E. Orivision of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995.126-44995.246.
- 8803220296 NAC Info Notice 88:010, "Mails Licenseos:Lack of Mgt Controls Over Licensed Programs." Svc list encl. CUNNINGHAM, E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44895.247-44995:353.
- 880404020 Forwards Into which provides util results for Action items 5 & 6 of IE Bulletin 67-002. KEISERHIW. Pounsylvania Power & Light Co. 88/03/29, RUSSELL,W.T. Region 1, Ofc of the Director. 51pp. 44989:301-44989:351.
- 8804010255 NRC Info Notice 88-011, "Potential Loss of Motor Centrol Ctr &/or Switchboard Function Due to Faulty Tie Bolts" Svc IIst encl.
 ROSSI-C E. Division of Operational Events Assessment (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407:051.
- 8804140484 Discusses util 870911 response to NRC Bullotin 87:001, "Thinning of Pipe Walis at Nuclear Power Plants." Info being used to determine extent of industry participation & implementation of eroslon/corrosion insp programs. THADANI,M.C. Project Directorate 1-2-88/04/08. KEISER,H.W. Pennsylvania Power & Light Co. 3pp. 45130:143-45130:145.
- 8804060376 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165:150.
- 8804210051 Responds to NRC 880314 ltr re violations noted in Insp Repts 50:387/88-04 & 50:388/88-03 Corrective actions on 880113, metal blocking plates on Unit 1 & Unit 2 ladders locked & high radiation area signs posted in area of each ladder. KEISER.H.W. Pennsylvan's Power & Light Co 88/04/13 WIGGINS,J.T. Region 1, Ofc of the Director. 2pp. 45254:332-45254:333.

R. Periodic operating reports & related correspondence

- 8804190110 Monthly operating repts for Mar 1988 W/880414 ltr. HIRT.J.A., KEISER.H.W. Pennsylvania Power & Light Co. 88/03/31. MCDONALD.W.G. Office of Administration & Resources Management, Director (Post 670413), 10pp. 45209:107-45209:116.
- 8804270047 "Discharge Monitoring Rept for Mar 1988," W/880419 IIr.
 KAUFFMAN,J.T., SAXTON,C.H. Pennsylvania Power & Light Co. 88/03/31
 BREZINSKI,R Pennsylvania, Commonwealth of, 13pp. 45245.039-45245.051.

S. Reportable occurrences, LERs & related correspondence

- 8804060269 LER 88-003-00:pn 880306.unanlicipated ESF actuation occurred.Caused by spurious pressure signal.Reactor pressure switch suction flow switch checked & suction flow switch not functioning properly.Switch calibr.W/880331 ltr. SHERANCA.G. BYRAM.R.G. Pennsylvania Power & Uight Co. 88/03/31. 4pp. 45046:064-45046:067.
- 8804120073 LER 88-002-00:on 880309,ESF actuation occurred when inboard & outboard containment isolation valves for Loop A of containment almosphere control sys unexpectedly closed Cause undetermined. Voftages will be determined. W/880406 ltr. RYDER,T.S., BYRAM,R.G. Pennsylvania Power & Light Co. 88/04/06. 5pp 45132:238-45132:242

- 8804200222 LER 88-005-00.on 880319.during refucting multiple ESF actuations occurred when primary power lost to reactor protection sys panel 2Y201A due to unplanned imp Caused by failed log cleard Failed logic card replaced W/880415 in SHEHANKO,R., BYRAM,R.G. Pennsylvania Power & Light Co. 88/04/15. 4pp 45218:108-45218.111.
- 8804250032 LER R8-006-00 on 880323,full MSIV isolation signal received. Caused by conflicting into in work instructions of const work order resulting in removal of wrong reflay. Relay roinstated & MSIV isolation signal resot W/880419 tir.

 RYDER,T.S., BYRAM,R.G., Pernsylvania, Power & Light Co. 88/04/19, 4pp. 45258-286-45258-289.

DOCKET 50-389 ST. LUCIE PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8804010081 Forwards Insp Repts 50-335/88-05 & 50-309/88-05 on 880307-11.No violations or deviations noted HERDT, A.R. Region 2, OIc of the Director 88/03/24, CONWAY,W.F. Florida Power & Light Co. 2pp. 45008.111-45008
- --8804010062 Insp Repts 50-335/88-05 & 50-389/88-05 on 880307-11 No violations or deviations noted Major areas inspected fire protection/prevention. WISEMAN,G R Region 2, Old of the Director, 88/03/21 | 11pp | 45008-113-45008-123.
- 8804120174 Forwards Insp Repts 50-335/88-02 & 50-389/88-02 on 880208-12 & notice of violation Notice of violation & rept data is withheld (ref 10CFR2.790(d) & 73.21). GRACE,J.N. Region 2, Oic of the Oirector. 88/04/04. WOODY,C.O. Florida Power & Light Co. 2pp. 45132-150-45132-152
- --8804120176 Partially withheld Insp Repts 50:335/88:02 & 50:389/88:02 on 880208-12 Violations noted Major areas Inspected/security plan, security organization, records & repts, testing & maint, physical beariers protected area & vital areas THOMPSON, D.H. Reg on 2, Ofc of the Director, 88/04/04 1p. 45132.152-45132.152
- 8804140297 Forwards periodic rept updating population estimate for area within 10 miles of plant,per Tech 6.9.1.9.Into will be included in 1889 rows of updation FSAR Rept atso forwarded to State of FL for possible incorporation in emergency plan.

 CONWAY,W.F. Florida Power & Light Co. 88/04/06. Document Control Branch (Document Control Dosk). 44pp. 45131:126-45131:169.
- 8804160190 Forwards proposed changes to Rev 12 to physical security plan ro miscollaneous amends & search requirements Changes withheld (ref 10CFR73.21). CONWAY,W.F. Florida Power & Light Co. 88/04/11. Document Control Branch (Document Control Desk). 1p. 45238:201-45238.291.
- 8804150194 Forwards Rev 14 to physical security plan.Rev does not decroase salequards effectiveness of plan Encl withheld (ref 10CFR73 21 & 2.780). CONWAY,W.F. Florida Power & Light Co. 88/04/11. Document Control Branch (Occument Control Dosk). 2pp. 45183:359-45183:360.
- 8804200473 Partial response to FOIA request re line protection.Forwards App E documents App D & E documents available in PDR.App F document completely withheld (ref FOIA Exemption 5) GRIMSLEY.D.H. Division of Rules & Records (Post 870413). 88/04/14. JONES.C.R. Affilation Not Assigned. 5pp. 45206-037-45206.043.
- --8804200578 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type inspiror each facility to assess status of compliance w/ 10CFR50.48 Program listed.
 CONLON.T.E. Region 2, Oic of the Director, 84/11/06, HERDT,A R. Region 2, Oic of the Director, 3pp. 45206.176-45208:178.

J. Insurance & Indemnity Information

8803300400 Discusses nuclear property Insurance programs for onsite property damage CONWAY,W.F. Florida Power & Light Co. 88/03/25. Document Control Branch (Document Control Desk), 2pp. 44967;243-44967,244.

K. Utility Final Safety Analysis Report (FSAR) & amends

- 8804080059 Forwards Rev 3 to updated FSAR for St Lucie Unit 2.List of plant changes/ mods completed under provisions of 10CFR50.59 also encl.Description of changes 8 safety evaluation of each submitted under separate cover. CONWAY,W.F. Florida Power & Light Co. 88/04/04. Document Control Branch (Document Control Desk). 4pp. 45051:309-45053:289.
- --8804050150 Amend 3 to updated FSAR for St Lucie Unit 2.W/880404 ltr.
 * Florida Power & Ught Co. 88/04/30, 698pp. 45051:314-45063:289.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88.06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list enct, MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Ed.son Co. of New York, Inc. 47pp. 44972;107-44972;153.
- 8803300224 Forwards addl into re util 680128 submittal of into re ASME Code relief requests for vanous safety-related pumps. Corrections to Page 5 of 19 of util 880128 submittal also enct. CONWAY,W.F. Florida Power & Light Co. 88/03/23. Document Control Branch (Occument Control Desk). 13pp. 44945:187-44945:209.
- 8804110266 Forwards SER & contractor rept accepting util responses to Generic Ltr 83-28, "ATWS Item 2.1 (Part 2), Vendor Interface Program Reactor Trip Sys Components."

 TOURIGNY,E G. Project Directorate It-2, 88/04/01, CONWAY,W.F. Florida Power & Light Co. 2pp. 45079.069-45079.085.

- -8804110275 SER accepting util response to Generic Ltr 83:28,Item 2 1 (Part 2)
 Project O rectorate II-2, 88/04/01, 3pp. 45079.071-45079.085.
- 8804080112 Forwards Rev 0 to "Pump & Valve Inservice Tost Program." List of plan changes encificevised plan includes three revised relief requests & one new relief request re safety injection & containment spray.

 CONWAY,W.F. Florida Power & Light Co. 88704/04 Document Control Branch (Document Control Desk). 8pp. 45098 305-45099 090.
- -8804080163 Rov 0 to "Pump & Valve Inservice Test Program." * Florida Power & Light Co. 88/04/04, 138pp. 45098 313-45099:090
- 8804130429 Forwards request for add into re ASME code relief requests for various safety related pumps info requested within 45 days from receipt of tir TOURIGNY,E G Project Directorate II-2 88/04/05 CONWAY,W.F. Florida Power & Light Co 3pp. 45104:109-45104:111.
- 8804120459 Discussos requirements of NUREG-0737, liem II.K.3.17 re rept of ECCS outages Reporting of ECCS equipment faitures provide NRC w/better reporting sys & obviates FSAR ECCS outage 5-yr reporting commitment. CONWAY,WF. Florida Power & Light Co. 88704706 Document Control Branch (Document Control Dosk). 2pp. 45090:161-45090:162.
- 8804130315 Forwards rept to plant changes/mods from 861006-871006 Rept correlates winto included in Rev 3 to updated FSAR.Summary of safety evaluation of rept also CONWAY,W.F. Florida Power & Light Co. 88/04/06. Document Control Branch (Document Control Desk). 1p. 45151:185-45151:225.
- -8804130318 Annual rept re plant Changes/mods made between 861006 & 871006. *Florida Power & Light Co. 87/10/06. 60pp. 45151:166-45151:225.
- 8804080088 Generic Ltr 88-07 to power reactor ficensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list and. MIRAGUA,F. J. Associatio Director for Projects (Post 870411), 80/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804190135 Forwards response to 880223 request for additinfo re Generic Ltr 88-06, "Reactor Coolant Pump Trip Criteria." CEN-268 revised to delete any refs to use of contannent rad abon starms as possible criteria for tripping second two pumps. CONWAY,W.F. Florida Power & Light Co. 88704711. (Jocument Control Branch (Docu-ment Control Dosk). 8pp. 45153:348-45153.355.
- 8804210345 Grants util 880210 request for delay in ATWS rule implementation schedule until filth outage currently scheduled for Feb 1889. BERKOW,H.N. Project Directorate II-2, 88/04/12, CONWAY,W.F. Florida Power & Ught Co Spp. 45192:136-45192-138.
- 8804280122 Forwards safety evaluation & technical evaluation ro plant natural circulation cooldown & boron mixing.Compliance demonstrated w/stated requirements.Supplementary method of cooldown suggested.
 TOURIGNY,E.G. Project Directorate II-1. 88/04/12. CONWAY,W.F. Florida Power & Light Co. 2pp. 45276:180-45276:209.
- -8804280137 Safety ovaluation re plant natural circulation cooldown & boron mixing suggests need to include use of pressurizer power operated relief valves as * Olice of Niclear Reactor Regulation, Director (Post 870411). 88/04/12. 2pp. 45276 182-45276:184.
- -8804050128 "Technical Evaluation Rept for Natural Circulation, Boron Mixing & Cooldown at St Lucle Unit 2."

 JOJH, PERKINS,K.R. Brookhaven National Laboratory. FIN A-3843. 88/03/31.

 Office of Nuclear Reactor Regulation, Director (Post 870411). 28pp. 45276 185-
- 8804290070 Forwards safety evaluation supporting approval of licensee Topical Rept NTH-G-6 & accepting proposed methodology described in licensee topical rept on PWR lattice physics methodology.

 LNINAS, C. Assistant Director for Region II Reactors. 88/04/19. CONWAY,W.F. Florida Power & Light Co. 5pp. 45324:216-45324:245.
- -8804290076 Salety evaluation supporting licensee use of RETRAN computer code for sys transient analyses & approving licensee topical rept on PWR lettice physics methodology.
 * Assistant Director for Region II Reactors, 88/04/19, 7pp, 45324:221-45324:245.
- 8804290058 Forwards request for additinfo re ATWS Item 2.2 (Part 1) of Generic Lir 83-28 Info requested within 45 days of date of itr in order to maintain review schodule. TOURIGNY,E.G. Project Directorate II-2. 88/04/22. CONWAY,W.F. Florida Power & Ught Co. 4pp. 46322:208-45322.212.

Q. Inspection reports, IE Bulletina & correspondence

46276 200.

- 8804010061 Forwards Insp Repts 50-335/88-05 & 50-389/88-05 on 880307-11.No violations or deviations noted.

 HEROT,A.R. Region 2, Ofc of the Director, 88/03/24, CONWAY,W.F. Florida Power & Ught Co. 2pp. 45008:111-45008:123
- ~8604010062 Insp Repts 50:335/88-05 & 50:389/88-05 on 880307-11.No violations or deviations noted Major areas inspected fire protection/prevention.
 WISEMAN,G.R., CONLON,T.E. Region 2, Ofc. of the Director, 88/03/21, 11pp. 45008:113-45008:123
- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors." Syc list encl.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44985:126-44995:248.
- 8803220296 NRC Info Notice 88-010, "Matis Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list encl. CUNNINGHAM, R.E. Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44985:247-44985:353.

- 8804080381 Ack receipt of 880307 ftr informing NRC of steps taken to correct violations noted in Insp. Repts 50:335/87:31 & 50:399/87:30.Implementation of corrective actions will be examined during future insp.
 WILSON,B.A. Region 2, Old of the Director. 88/03/28. CONWAY,W.F. Flor da Power & Light Co. 1p. 45016-351-45016-351.
- 8804120003 Ack receipt of 880321 ftr informing NRC of steps taken to correct violations noted in Insp Repts 50-335/86.08 & 50-389/86.07. HERDT.A.R. Region 2. Oile of the Director. 88/04/04 CONWAY,W.F. Florida Power & Light Co. 1p. 45135/294-45135.294
- 8804120174 Forwards Insp. Repts 50:335788-02 & 50:389788-02 on 880208-12 & notice of violation Notice of violation & rept details withheld (ref. 10CFR2.790(d) & 73.21) GRACEJN Region 2, Otc of the Director 88704704 WOODY,C O. Florida Power & Light Co. 2pp. 45132-150-45132-152
- --8804120176 Partially withheld Insp. Repts 50:335/88-02 & 50:388/68-02 on 880208-12 Violations noted Major areas inspected security ptansecurity organization records & rupts testing & maint, physical barriers protected area & wial areas. THOMPSON, D.H., STANSBERRY, W.W., MCGUIRE, D.R. Reg on 2, Ofc of the Director, 88/04/04, 1p. 45132-152-45132:152.
- 8804010258 NRC Info Notice 88 011, "Potential Loss of Molor Centrol Cir &/or Switch-board Function Due to Faulty Tie Bolts." Svc list and. ROSSI,CE. Division of Operational Events Assessment (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407.051.
- 8804080370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165-150.
- 8804200473 Partial response to FCIA request ro fire protection.Forwards App E documents App D & E documents available in POR.App F document completely withheld (rol FOIA Exemption 5) GRIMSLEY,D.H. Division of Hules & Records (Post 870413), 88/04/14, JONES,C.R. Allifiation Not Assigned 5pp. 45206:037-45206.043,
- --8804200576 Provides status of Region II safe shuldown inspiprogram.
 GRACE,J.N. Region 2, Old of the Director. 85/05/13. TAYLOR,J.M. Old of Inspection & Enforcement, Director (820201-870413). 2pp. 45206.174-45208.175.
- --8804200579 Adv.ses that Fire Protection Steering Committee has recommended that each region make one 100FR50,App R-type insplice each facility to assess status of compliance w/ 100FR50-48.Program listed CONLON,T.E. Region 2, Oic of the Director. 84/11/08 HERDT,A.R. Region 2, Oic of the Director. 3pp. 45206:176-45206:178.

R. Periodic operating reports & related correspondence

- 8804190272 "Annual Radiological Environ Operating Rept,St Lucie Plant Units 1 & 2." CONWAY,W.F. Florida Power & Light Co. 87/12/31, 65pp. 45207.317-45208:021.
- 8803290280 Forwards discharge monitoring repts re-driving protection plan CONWAY,W.F. Florida Power & Light Co. 88/03/23. Document Control Branch (Document Control Dask). 1p. 44921.200-44921.204.
- --8803290254 "Discharge Monitoring Rept," for Fab 1987. WOODY,C.O. Florida Power & Light Co. 87/02/28, 2pp. 44921;201-44921.202.
- --8803290284 "Discharge Monitoring Flept," for Sopt 1987. WOODY,C O. Florida Power & Light Co. 67/09/30. 2pp. 44921:203-44921:204
- 8804220108 Forwards monthly operating repts for Mar 1988 & corrected Feb 1988 unit shutdowns & power reductions rept for Unit 4. Corrected rept provides into on outage that was omitted from original rept. CONWAY,W.F. Florida Power & Light Co. 88/04/15. Document Control Branch (Document Control Desk). 1p. 45216:192-45216:210.
- --8804220074 Monthly operating repts for Mar 1988. GRANT,N.W. Florida Power & Light Co. 88/03/31, 16pp 45216.195-45216:210.

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

- 8803240426 Generio Ltr 88 08 to all powor reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list end MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972;107-44972.153.
- 8804070199 Forwards TVA employee concerns task group subcategory repts, RUSSELL,J.R. Tennessee Valley Authority. 88/03/28. Document Control Branch (Document Control Desk). 5pp. 45022:145-45024:257.
- --8804070203 Rev 3 to Employee Concerns Special Program Subcategory Engineering Rept 26000, "Civil/Structural Design (21500) & Pipe Why Restraint Design (22700)." BENKERT,J.W. Tennessee Valley Authority. 88/03/21. 89pp. 45022:150-45022:238.
- --8804070217 Rev 5 to Employee Concerns Special Program Rept 60100, "QA Mgt & Policy." MCCALLUM,N, BROWN,W.R., KARR,J.E. Tennassee Valley Authority. 88/03/18. 86pp. 45022:239-45022:334.
- --8804070224 Rev 6 to Employee Concerns Special Program Subcategory Rept 80200, KENZIE,L.G. Tennessee Velley Authority, 88/03/16, 152pp. 45022:335-45023:126
- --8804070234 Rev 6 to Employee Concorns Special Program Subcatogory Rept 80400, "Nonconformance Control & Corrective Action." HALVERSON,R.D. Tennessee Valley Authority, 86/03/14, 491pp, 45023:127-45024:257.

- 8804060378 Forwards revised description of plant completion program plan in response to 880217 its Further definition & specific delated program milestones being developed to reflect early NRC review & involvement in completion process WhitE, S.A. Tennessee Valley Authority 68/03/31. EBNETER, S.D. Ofc. of Special Projects 19pp 45010 226-45010 244
- 8804060500 Advises that submittal of Chapter 15 revs along w/other FSAR changes to reflect upper head injection removal 8 up*ow conversion will be delayed until 880715. GRIDLEY,R Tennessee Valley Authority 88/03/31. Document Control Branch (Document Control Desk). 2pp. 45007.085-45007.086
- 8804070057 Forwards listing of employee concern numbers shown on util data base as ARC responsibility for evaluation not included in 861231 submittal Requests ack of rosponsibility RUSSELLUR Tennessee Valley Authority 88/04/01 Document Control Branch (Document Control Dos4) 7pp 45075 036 45075 042
- 8804080088 Generic Ltr 88-07 to power reactor licensees 8 applicants re-modified en-forcement policy concerning 10CFR5049, "Environ Qualification of Electrical Equip ment Important to Safety for Nuclear Power Plants," Svc. Lst end; Svc. Lst end. M:RAGLIA.F.J. Associate Director for Projects (Post 870411), 88/04/07. Consortdated Edison Co. of New York, Inc. 49pp. 45164.237-45164.285.

F. Security, medical, emergency & fire protection plans

- 8803290314 Forwards Insp Repts 50:390/87-20 & 50:391/87-20 on 871128-880103 & notice of devation Uroscived items re mail storage, handing & shipping requirements & FSAR commitments associated w/fire professor by some storage and sharity P. Otc. of Special Projects 88/03/09 VirilTE.S.A. Tennessee Valley Authorry. 200 44963 008-44983 026
- --8803290321 insp Repts 50 390/87-20 & 50-391/87-20 on 871123-880103. Deviations noted Major areas inspected licensee action on inspector identified items, followup of licensee identified items, fire prevention & protection & pipe sys WALTON, G.A., HUMMEY, P.G., POWELL, T.B. Reg on 2, Ofc of the Director, 88/02/12, 15pp. 44983-012-44983-026
- 8804180257 Forwards Rev 14 to security personnel training & qualification plan Rev GRIDLEY R.L. Tennessee Vallay Authority 68/04/14 Document Control Branch (Document Control Desk) 2pp 45195/338-45195/339.
- 8804200473 Partial response to FOIA request re-fire protection Folwards App E documents App D & E documents available in PDR App F document completely withheld (ref FOIA Exemption 5).
 GRI MSLEY D H. Division of Rules & Records (Post 870413), 88/04/14. JONES, C R Affiliation Not Assigned, 5pp. 45206 037-45206 043
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type insplict for each facility to assess status of comphance w/ 10CFR50 48 Program Isled CONLON,T. E. Region 2, Ofc of the Director 3pp 45206 176-45206,178
- 8804220250 Revised omergency plan implementing procedures,including Rev 0 to CECC EPIP-1. "Emergency Duty Officer Procedure for Notification of Unusual Event, Refr. Stid Area Emergency Bengrale Emergency "Wi8804201" GRIDLEY,R L. Tennessee Valley Authority 88/04/20 400pp 45229 308-45230 322.

K. Utility Final Salety Analysis Report (FSAR) & amends

- 8803290339 Forwards Amend 62 to FSAR for Watts Bar Nuclear Plant GRIDLEY.H. Tennessee Valley Authority. 88/03/25 Document Control Brench (Document Control Desk). 3pp. 44915.173.44915.285.
- -8803290345 Amend 62 to FSAR for Watts Bar Nuclear Plant * Tennessee Valley Authorty 68/03/25 110pp. 44915.176-44915.285.
- 8804070312 Forwards alfidavit certifying that on 880401 Amend 62 to FSAR served upon individuals identified in alfidavit. GRIDLE-VF.R.L. Tennessee Valley Authority. 88/04/05 Document Control Branch (Document Control Desk) 2pp. 45075.217-45075.218

Q. Inspection reports, IE Bulletins & correspondence

- 8803290314 Forwards Ensp Repts 50-390/87-20 & 50-391/87-20 on 871128- 880103 & notice of deviation Urasolved items re-matt storage handling & shipping requirements & FSAR commitments associated w/fire protection sys noted BARR KP. Oft of Special Projects 88/03/09 WHITE,S.A. Tennessee Valley Authority. 2pp 44983-008-44983-026.
- ~8803290317 Notice of deviation from insp on 871128-880103 Deviation noted documentation inadequately substantiates qualification as Class 1E for listed BARR KP Oic of Special Projects, 89703709, 2pp. 44983-010-44983-011.
- --8803290321 Insp Repts 50:390/87-20 & 50:391/87-20 on 871123 880103. Deviations noted Major areas inspected licensee action on inspector identified items.followup of licensee dentified items.followup of licensee dentified items.followup of MALTONIG A., HUMH-REY.P.G., POWELL,T.B. Region 2, Ofc of the Director. 88/02/12. 15pp 44983 012-44983 026.
- 8803290366 Forwards Insp. Repts. 50.258/87.38.50.260/87.38.50.296/87.38.50.327/ 87-88.50.328/87-68.50.390/87.18.50.391/87-18, 50.438/87-08 & 50.439/87-08 on 871005-18 & notice of violation. BARR, K.P. Region 2, Ofc of the Director. 88/03/09 WHITE, S.A. Tennessee Valley Authority. 3pp. 44975 195-44975 208.
- --8803290390 Notice of violation from insp on 871005-18.Violations noted: inadequate div of nuclear engineering training & records, ineffective followup on audit findings & improper correction of QA records BARRIK P. Region 2, Ofc of the Director 88/03/09, 3pp. 44975-198-44975:200

- -8803290393 Insp. Hepts 50:299/87:48, 30:203/h7:30.30:293/h7:40, 30:2278/90,32 228/87-68,50:390/87:48,50:391/87:18, 50:439/87:08 & 50:430/87:08 Violations noted May or areas inspected allegations & licenson action on Iduntifue Items WALTON,G.A. Region 2, Oic of the Director, 88/03/08 8pp. 44975:201-44975:23
 - 8803210090 Suppl 1 to NRC Info Notico 87-044, "Thrmble Tube Thinning in Weslighouse Reactors," Svc hist encl ROSSICE Division of Operational Events Assessment (Post 870411) 88/03/25 Consolidated Edison Collot New York, Inc. 121pp. 44995.126-44995.246.
 - 8803220296 NRC Info Notice 88-010, "Mar's Licensees Lack of Mgt Controls Over to censed Programs." Svc Ist encl. CUNNINGHAM.R E Division of Industrial 8 Metrical Nuclear Salety (Post 870720) 667 03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44095 247-44095 353
 - 8804060241 Forwards response to NRC Bulletin 88:002, "Right Propagating Faligue Cracks in Steam Generator Tubes." Recommendations of Paragraphs A & C of bulletin not applicable to Watts Bar Units 1 & 2 GRIDLEYR, Tecnesses valley Authority, 88/03/31, Document Control Branch (Occoment Control Dosk), 8pp. 45007;301-45507.308.
 - 8804970112 Responds to NRC 880224 ltr re violations nated in Insp Repts 50-300/87 13 & 50-391/87-13.Corrective actions mgt now involved in approval of each 10CFR50 55(e) rept submitted to NRC GRIDLEY, Tiennessee Velley Authority, 88/03/31, Decument Control Branch (Document Control Desk) 8pp. 45044-143-45044:150
 - 8804110206 Provides supplemental response to violations noted in hisp Riopts 50.397. 87-07 & 50.397/87-07 Sample reinsp program of HVAC supports to determine scope of violation initiated. Final rept on violation will be provided by 880531. GRIDLEY,R Tennessee Valley Authority 88/04/05. Decument Control Branch (Document Control Desk). 2pp. 45129.352-45129.353.
 - 8804120111 Forwards updated info & final action plan for programmatic corporate centers to violations noted in Insp. Repts 50-390/86-20 & 50-301/86-20 Action plan for corporate guidance for implementation of QA program enci.

 GRIDLEY, R. Tonnessee Valley Authority, 88/04/05. Decument Control Branch (Occument Control Desk), 7pp. 45123-333-45123-339
 - 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch board Function Due to Faulty Tie Bots " Svc list and ROSSI,CE. Division of Operational Events Assessment (Post 870411) 88/04/07 Consolidated Edison Co. of New York, Inc. 124pp. 45406 202-45407.051.
 - 8804140009 Advises that commitment to complete layup implementation rescheduled to 880701 from 880331.pcr 871016 submittel responding to Violation 50-390/87-12-0 noted in Insp Repts 50-390/87-12-8 50-391/87-12
 GRIDLEY.R. Tennessee Valley Authority 88/04/08 Document Control Branch (Document Control Dock), 2pp. 45147:338-45147.339.
- 8804190122 Requests addl into re-main steam tino breaks in ico condense containments,in support of ANL Independent confirmatory analysis of WCAP 10986P into requested 45 days after receipt ZECH, GG Otc of Special Projects 88/04/08. WHITE, S.A. Tonninssee Valley Authority, 7pp. 45165-287-45165-293.
- 8804080370 NRC Info Notice 88-012, "Overgreasing of Efectric Motor Dearings." Sv list encl. ROSSICE: Division of Operational Events Assessment (Post 870411) 68/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165-150
- 8804210017 Summarizes review of NRC Bullohn 88-001, "Dofects in Washinghouse Cucut Breakers" Bullehin not applicable to Browns Ferry nuclear plant Builolin applicable to Watts Par & Bellefonio nuclear plants List of commitments and GRIDLEY.R. Tennossee Valley Authority 88/04/13. Occument Control Branch (Document Control Desk). 3pp. 45219.150-45219:152
- 8604200473 Partial response to FOIA request re-fire protection Forwards Applicuments Appl D & E documents available in PDR Appl F document completely with held (ref FOIA Examption 5).

 GRIMSLEY, D H Division of Rules & Records (Post 870413), 88/04/14. JONES, C FAIffilation Not Assigned. 5pp. 45206.037-45206.043.
- --8804200575 Provides status of Flegion II safe shutdown inspiprogram. GRACE,J.N. Region 2, Ofc of the Director 85/05/13. TAYLOR,J.M. Ofc of Inspectio & Enforcement, Director (820201-870413). 2pp. 45208-174-45208:175.
- -8804200579 Advises that Fire Protection Steering Committee has recommended the each region make one 10CFR50,App Bitype inspitor each facility to assess status of compliance w/ 10CFR50.48 Program listed.

 CONLON,TE Region 2, Oto of the Oirector, 84/11/06, HERDT,A.R. Region 2, Oto of the Director, 3pp. 45208.176-45208.178
- 8804220022 Forwards supplemental response to violations noted in insp Ropis 50:327 86:27 & 50:328/86:27.Encl will provide original Sequeyah deficiency followed to Walts Ber Nuclear Plant supplemental response.
 GRIDLEY,R Tennossee Vallay Authority. 88/04/15. Document Control Branch (Document Control Desk). 11pp. 45226:313:45226:323.
- 8904220032 Forwards response to NRC Bulletin 87-002. "Festener Testing to Determine Conformance WiApplicable Tech Specs." Encl 4 identifies festunds transferrer from storage & Encl 5 contains list of commitments being made by TVA in response GRIDLEY.A Tennossee Vellay Authority. 88/04/15. Document Control Branch (Document Control Desk). 155pp. 45219.172-45220.026.
- 8804280835 Responds to NRC 880309 ftr re violations noted in listed insteptis, including 50-438787-08.50-439787-08.8 50-327787-68.Corroctive actions dailbase constructed for training GRIDLEY,R. Tennessee Velley Authority. 88704722. Document Control Branch (Document Control Desk). 10pp. 45331:341-45331:350

R. Periodic operating reports & related correspondence

8804060383 "Personnel Whole Body Exposure Repts for 1987." W.880401 ltr. GRiDLEY.R. Tennessee Valley Authority, 87/12/31, 7pp., 45047:060-45047:086.

S. Reportable occurrences, LERs & related correspondence

- 8804040102 Second inform deficiency rept re failure to adequately control & document instrument accuracy requirements. Initially reported on 870626 TVA contracting w/ Wostinghouse to review selpoint methodology document.
- 8804060439 Revised final deficiency ropt re whother effects of zoro period acceleration should be considered in priping analysis calculations, Initially reported on 860327 Calculations not appropriate for type analysis Support designs to be rovised GRIDLEY,R Tennessee Valley Authority, 88/04/04. Document Control Branch (Document Control Desk), 4pp. 45076 101-45076.104.
- 8804270007 Second interim deliciency rept re-safety-related HVAC duct welding Initially reported on 870312 Program developed to establish structural adequacy of wolded safety-related ductwork. Nox rept expected by 890929.

 GRIDLEY,R. Tennessee Valley Authority, 88704712. Document Control Branch (Document Control Desk), 6pp. 45280-260. 45280.265.

U. Congressional/Executive Correspondence

- 8804130222 Responds to questions in 880315 ftr re NRC investigation of S WHITE,manager of Ofc of Nuclear Power at TVA & discusses role of Ofc of Investigations in subj case Assures that NRC made no attempts to dismiss Ofc of Investigation
- rept ZECH,L.W Commissioners 88/03/22, GEJDENSON,S. House of Rep., Interior & Insular Alfairs, 8pp. 45101:220-45101:230
- --3804130233 Requests enswers to questions made by Subcommittee on general oversight & investigations re alleged NRC attempt to dismiss Ofc of Investigation rept about credibility of S WHite, director of TVA nuclear program. GEJDENSON,S. House of Rep., Interior & Insular Attars. 88/03/15. ZECH,L.W. Commissioners. 3pp. 45101:228-45101:230.
- 8804280317 Forwards NRR responses to Questions 1 & 3 re Commission stds for per-mitting restart of power plant after shutdown for safety reasons & Commission require-ments for documenting licensing basis for restart de 45269 215.

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

- 8803240426 Generic Lir 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIA,F.J. Associate Director for Projecte (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc., 47pp. 44972:107-44972:153.
- 8904070199 Forwards TVA employee concerns task group subcategory repts.
 RUSSELL,J.R. Tennessee Valley Authority. 88/03/28. Document Control Branch (Document Control Dosk). 5pp. 45022:145-45024-257.
- -9804070203 Rev 3 to Employee Concerns Special Program Subcategory Engineering Rept 25000, "Civil/Structural Design (21500) & Pipe Whip Restraint Design (22700)." BENKERT, J.W. Tennessee Valley Authority. 68/03/21. 89pp. 45022:150-45022.238.
- --8804070217 Rev 5 to Employee Concerns Special Program Rept 80100, "OA Mgt & Policy." MCCALLUM.N., BROWN,W.R., KARR.J.E. Tennessee Velley Authority. 88/03/18. 98pp. 45022:239-45022:334.
- -8804070224 Rev 6 to Employee Concerns Special Program Subcategory Rept B0200, KENZIE, L.G. Tennessee Valley Authority, 88/03/18, 152pp. 45022:335-45023:126.
- --8604070234 Rev 6 to Employee Concerns Special Program Subcategory Rept 80400, "Nonconformance Control & Corrective Action." HALVERSON,R.D. Tennessee Valley Authority, 88/03/14, 481pp. 45023:127-45024 257.
- 8804060378 Forwards revised description of plant completion program pfan in response to 880217 its Further definition & specific detailed program milestones being developed to reflect early NRC review & involvement in completion process. WHITE,SA. Tennessee Valley Authority. 88/03/31. EBNETER,S.O. Ofc of Special Projects. 19pp. 45010.226-45010:244.
- 8804060500 Advises that submittal of Chapter 15 revs along w/other FSAR changes to reflect upper head injection removal & upliow conversion will be delayed until 880715. GRIDLE/JR. Tennessee Valley Authority. 88/03/31. Document Control Branch (Document Control Dask). 2pp. 45007:085-45007:086.
- 8804070057 Forwards listing of employee concern numbers shown on util data base as NRC responsibility for evaluation not included in 861231 submittal Requests ack of responsibility.

 RUSSELL, J.R. Tennessee Valley Authority, 88/04/01. Document Control Branch (Document Control Desk), 7pp. 45075:036-45075.042.
- 8804090088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc 1814 serci. MIRAGLIAF.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45184:285.

F. Security, medical, emergency & fire protection plans

8803290314 Forwards Insp Repts 50-390/87-20 & 50-391/87-20 on 871128-880103 & notice of deviation. Uresolved items re matt storage, handling & shipping requirements & FSAR commitments associated w/fire protection sys noted. 8ARR,K-, Ofc of Special Projects, 88/03/09, WHITE,S.A. Tennessee Valley Authority, 2pp 44963:008-44963:026.

- --8803290321 Insp Repts 50:390/87-20 & 50:391/87-20 on 971123-880103 Deviations noted Major stess inspected licensee action on inspector identified items, followup of licensee identified tems, fire prevention & protection & pipe sys.

 WALTONG A. ELROD,S A. Region 2, Old of the Director. 88/02/12, 15pp. WALTON G.A. ELRO 14983 012 44983 026
- 8804180257 Forwards Rev 14 to Security personnel training & qualification plan Rev GRIDLEY,R.L. Tannessee Valley Authority. 86/04/14. Document Confrot Branch (Document Control Desk). 2pp. 45195/338-45195/339.
- 8804200473 Partial response to FOIA request re tire protection.Forwards App E documents App D & E documents available in PDR.App F document completely withheld (ref FOIA Examption 5). GRIMSLEY,D.H. Division of Rules & Records (Post 970413) 88/04/14. JONES,C R Affiliation Not Assigned. Spp. 45206:037-45206.043
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type insp for each facility to assess status of compliance w/ 10CFR50.48 Program listed CONLON,TE. Region 2, Ote of the Director. 84/11/06 HERDT,A.R. Region 2, Ote of the Director 3pp. 45206:176-45206:178
- 8804220260 Revised emergency plan implementing procedures,including Rev 0 to CECC-EPIP-1, "Emergency Duty Officer Procedure for Notfication of Unusual Event, Nett, Site Area Emergency & General Emergency "W/880420 lit." GRIDLEY,R.L. Tennessee Varley Authority 88/04/20, 400pp, 45229-308-45230-322

K. Utility Final Safety Analysis Report (FSAR) & amends

- 8803290339 Forwards Amend 62 to FSAR for Watts Bar Nuclear Plant, GRIDLEY,R. Tennessee Valley Authority 88/03/25. Document Control Branch (Document Control Desk), 3pp. 44815-173-44915-285
- --\$803290345 Amend 62 to FSAR for Watts Bar Nuclear Plant.
 Tennessee Valley Authority, 88/03/25, 110pp, 44915:176-44915:285
- 8804070312 Forwards attidavit contriguing that on 880401 Amend 62 to FSAH served upon individuals identified in aftidavit. GRIDLEY,R.L. Tennesses Vell'ey Authority 88/04/05. Document Control Branch (Document Control Desk). 2pp. 45075;217-45075;218.

Q. Inspection reports, IE Bulletins & correspondence

- 8803290314 Forwards Insp Repts 50-390/87-20 & 50-391/87-20 on 871128-880103 & notice of deviation. Uresolved items re-mail storage, handling & shipping requirements & FSAR commitments associated w/fre-protection sys-noted. BARIK, P. Ofc of Special Protects. 88/03/09. WHITE, S.A. Tennessee Varley Authority. 2pp. 44883 008-44983 028
- --8803290317 Notice of deviation from Insp on 671128-880103 Deviation noted documentation inadequately substantiates qualification as Class 1E for Isted BARR,K.P. Ofc of Special Projects, 88/03/09, 2pp. 44983 010-44983 011.
- -8803290321 Insp Repis 60-390/67-20 & 50-391/67-20 on 671123-880103. Deviations noted Mejor areas inspected licensee action on inspector identified items, followup of licensee lidentified items, fire prevention & protection & piesys WALTON,G A., HUMHREY,P.G., POWELL,T.B. Region 2, Ofciol the Director.
- 8803290366 Forwards Insp Repls 50:259/87-36,50:260/87-38,50:298/87-38 50:327/ 87-68,50:328/87-68,50:390/87-18,50:391/87-18, 50:438/87-08 & 50:439/87-08 on 871005-18 & notice of violation BARR,K.P. Region 2, Ofc of the Director, 88/03/09, WHITE,S.A. Tennessee Valley Authority, 3pp. 44875:195-44975 208.
- --8803290390 Notice of violation from insp on 871005-18 Violations noted inadequate dv of nuclear engineering training & records, inoffective followup on audit findings & improper correction of QA records BARRIK.P. Region 2, Oto of the Director, 88703700, 3pp. 44975-198-44975 200
- --8803290393 Insp Hepts 50:259/87:38,50:260/87:38,50:296/87:38, 50:327/87:68,50-328/87:68,50-390/87:18,50:391/87-18, 50:438/87:08 & 50:439/87:08.Violations noted Major areas inspected allegations & licensee action on identified items. WALTON.G.A Region 2, Oic of the Director, 88/03/08, 8pp 44975:201-44975:208.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors," Sec list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995 246
- 8803220296 NRC Infp Notice 68-010, "Matts Licenseps Lack of Mgt Controls Over Licensed Programs." Svc list encl. CUNNINGHAM,R.E Division of Industrial & Modical Nuclear Safety (Post 870729). 8B/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995.353.
- 8804060241 Forwards response to NRC Bulletin 88-002, "Rapid Propagating Fatigue Cracks in Steam Generator Tubos," Recommendations of Paragraphs A & C of building applicable to Watts Bar Units 1 & 2. GRIDLEY,R. Tennessee Valley Authority, 88/03/31, Document Control Branch (Document Control Desk), 8pp. 45007.301-45007.308
- 8804070112 Responds to NRC 880224 lit re violations noted in linsp. Repts 50:390/87-13 & 6D:391/87-13.Corrective actions mgt now involved in approval of each 10CFR50.65(e) rept submitted to NRC. GRIDLEY,R. Tennessee Valley Authority. 88/03/31. Document Control Branch (Document Control Desk). 8pp. 45044:143-45044:150.
- 8804110206 Provides supplemental response to violations nated in Insp Repts 50-3907 87-07 & 50-391/87-07. Sample reinsp program of HVAC supports to determine scope of violation Initiated. Final rept on violation will be provided by 880531. GRIDLEY,R. Tennessee Valley Authority. 88/04/05. Document Control Branch (Docu-ment Control Desk). 2pp. 45129:352-45129:353.

- 8804120111 Forwards updated into & final action plan for programmatic corporate concerns re-violations noted in Insp. Repts 50:390/86-20 & 50:391/86-20 Action plan for corporate guidance for implementation of OA program enct GRIDLEY,R Tennasses Valley Authority 88/04/05. Document Control Branch (Document Control Desk). 7pp. 45123:393-45123:339
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Cir &/or Switchboard Function Due to Faulty Tio Botts." Svc 1st end ROSSI.C E. Division of Operational Events Assessment (Post 870411), 88/04/07 Conso
- 8804140009 Advises that commitment to complete layup implementation rescheduled to 880701 from 880331,per 871016 submittal responding to Violation 50:390/87-12-01 noted in Insp. Ropis 50:390/87-12 & 50:391/87-12. GRIDLEY,R. Tennossee Veltey Authority, 88/04/06, Document Control Branch (Document Control Disk), 2pp. 45147-338-45147-339.
- 8804190122 Requests addl info re main steam line breaks in ice condensor contamments in support of ANL independent confirmatory enalysis of WCAP-10986P info requested 45 days after receipt ZECH,G G Otc of Special Projects 88/04/08. WHITE,S A. Tennessee Valley Authority, 7pp. 45165 287-45165 293.
- 8804060370 NRC Into Notice 88:012, "Overgreasing of Electric Motor Bearings." Svc list end! ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/12, Consolidated Edison Collections, Inc. 123pp. 45165
- B804210017 Summarizes review of NRC Bultetin 88-001, "Defects in Westinghouse Circuit Breakers." Bultetin not applicable to Browns Forry nuclear plant Bulletin applicable to Watts Bar & Belletonte nuclear plants List of commitments encl. GRIDLEY,R Tennessee Valley Authority, 88/04/13. Occument Control Branch (Document Control Desk) 3pp. 45219:150-45219:152.
- 8804200473 Partial response to FOIA request re fire protection.Forwards App E documents App O & E documents available in PDR App F document completely withheld (ref FOIA Examplion 5). GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 89/04/14. JONES,C.R. Affikation Not Assigned 5pp. 45206.037-45206.043
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type insp for each facility to assess status of compliance w/ 10CFR50 48 Program I sted. CONLON.T.E. Region 2, Oto of the Director. θ4/11/06. HERDT,A R. Region 2, Oto of the Director. 3pp. 45206 176-45206 178.
- 8804220022 Forwards supplemental response to violations noted in Insp Repts 50-327/ 88-27 & 50-328/86-27. End will provide original Sequeyah deficiency followed by Watts Bar Nuccar Plant supplemental rosponse. GRIDLEY, R. Tonnessee Valley Authority. 88/04/15. Document Control Branch (Document Control Desk), 11pp. 45226-313-45226-323.
- 8804220032 Forwards response to NRC Bulletin 67-002, "Fasioner Testing to Determine Conformance W/App"icable Tech Specs." Encl 4 Identifies fasteners transferred from storage & Encl 5 contains list of commitments being made by TVA in response. GRIDLEYR, Tennessee Velley Authority, 88/04/15. Document Control Branch (Document Control Desk), 165pp. 45218:172-45220:028.
- 8804280635 Responds to NRC 880308 ltr re violations noted in listed insprepts including 50-438/87-08,50-439/97-08 8 50-327/87-68 Corrective actions data base constructed for training GRIDLEY,H. Tennessec Valley Authority. 88/04/22. Document Control Branch (Document Control Desk). 10pp. 45331:341-45331:350
- R. Periodic operating reports & related correspondence
- 8804060383 "Personnel Whole Body Exposure Repts for 1987," W/880401 Nr. GRIDLEY,R. Tennessee Valley Authority, 87/12/31, 7pp. 45047,060-45047,068.
- S. Reportable occurrences, LERs & related correspondence
- 8804040102 Second Interim deficiency rept re-tailure to adequately control & document instrument accuracy requirements. Initially reported on 870626.TVA contracting w/ Westinghouse to review setpoint methodology document Next rept by 890321, GRIDLEY,R. Tennessee Valley Authority, 88/03/30, Document Control Branch (Document Control Desk). 4pp. 44970.079-44970:082.
- 8804060439 Revised final deticiency rept re whether effects of zero period acceleration should be considered in piping analysis calculations initially reported on 860327. Calculations not appropriate for type analysis. Support designs to be revised. GRIDLEY,R. Tennassee Valley Authority, 88/04/04. Document Control Branch (Document Control Desk). 4pp. 45076:101-45076:104.
- 8804270007 Second Interim deficiency rept re safety-related HVAC duct welding initially reported on 870312 Program developed to establish structural adequacy of welded safety-related ductwork Next rept expected by 890929.
 GRIDLEY,R. Tennessee Valley Authority, 88/04/12. Document Control Branch (Document Control Desk), 8pp. 45280.260-45280.265.

U. Congressional/Executive Correspondence

- 8804130222 Responds to questions in 880315 lit re NRC investigation of S WHITE,manager of Ofc of Nuclear Power at TVA & discusses role of Ofc of Investigations in subjects Assures that NRC made no attempts to dismiss Ofc of Investigation rept.
- ZECH.L.W. Commissioners 88/03/22, GEJDENSON,S. House of Rep., interior & Insular Affairs, 8pp. 45101:220-45101:230.
- -8804130233 Requests answers to questions made by Subcommittee on general oversight & investigations re alleged NRC attempt to dismiss Oic of Investigation rept about cred-bility of SWHite, director of TVA nuclear program. GEJDENSON,S. House of Rep., Interior & Insular Affairs. 88/03/15. ZECH,L.W. Commissions. 3pp. 45101:228-45101:230.

8804280317 Forwards NRR responses to Questions 1 & 3 re Commission stds for parmitting restent of power plant later shutdown for safety reasons & Commission requirements for documenting licensing basis for restart decision, respectively THOMAS.C.O. Policy Development & Technical Support Branch (Post 870411), 89/04/19 REHM,T.A. Ofc of the Executive Director for Operations 7pp. 45269 200-45269 215.

DOCKET 50-395 VIRGIL C. SUMMER NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8803300122 Forwards Insp. Repts 50:395/88-04 on 880201-05 No violations of deviations noted.
 HERDTA.R. Region 2, Ofc of the Director, 88/03/04, NAUMAN.D.A. South Carolina Electric & Gas Co. 2pp. 44961:269-44981:283.
- --8803300129 Insp Rept 50:395/68:04 on 880201-05 No violations noted. Major areas inspected selsmic monitoring program & fire protection/prevention program HARRISJ.R., CONLON,T.E. Region 3, Ofc of the Director 88/02/29, 13pp 44861:221-44961:283.
- 8804010242 Change A to Rev 9 of Emergency Plan Procedura EPP-016, "Operations Support Ctr Activation Checklist." W/880325 ftr.

 NAUMAN,D.A. South Carolina Electric 8 Gas Co. 88/03/25. 5pp. 45031:195-45031:199.
- 8804040239 Advises that 880216 Amends 6,7 & 21 to physical security plan consistent w/provisions of 10CFR54(p) & acceptable, CLINE,W.E. Region 2, Ofc of the Director, 88/03/28, NAUMAN,D.A. Scuth Caro'na Electric & Cas Co. 3pp. 450/f8:131-450/f8:133.
- 8804150361 Forwards Insp. Rept. 50-395/88-08 on 880301-31.No violetions or devations noted. VERRELLI,D.M. Region 2, Oic of the Director, 88/04/08, NAUMAN,D.A. South Cardina Electric & Gas Co. 2pp. 45192:213-45192:221.
- -6804150366 Insp. Rept. 60-395/88-08 on. 880301-31. No violations or deviations noted Major areas inspected: illicensee action on previous insp. findings, monthly survoillance observations, radiological protection, physicial security & written repts. PREVATTE, R.L., HOPKINS, P.G., DANCE, H.C. Region 1, Ofc of the Director, 68/04/06, 7pp. 45182-216-45192:221.
- 8804200473 Partial response to FOIA request re fire protection.Forwards App E documents.App D & E documents available in PDR.App F document complately withhold (ref FOIA Exemption 5).
 GRIMSLEY.D.H. Division of Rules & Records (Post 870413). 88/04/14. JONES,C R Affiliation Not Assigned. 5pp. 45206:037-45206:043.
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type Insp for each facility to assess status of compliance w/ 10CFR50.48. Program listed.
 CONLON,T.E. Region 2, Ofc of the Director. 84/11/06. HERDT,A.R. Region 2, Olc of the Director. 3pp. 45206:178-45206:178.
- 880426008 Forwards Insp. Rept. 50-395/88-09 on 880314-18 No violations or doviations noted. CLINEW.E. Region 2, Otc of the Director, 88/04/16, NAUMAN.D.A. South Carolina Electric & Ges Co. 2pp. 45268:174-45268:178.
- --8804280010 Partially withheld Physical Security Insp Rept 50:395/88-09 on 880314-16 (ref 10CFR2.790(d) & 73.21).No violations noted Major areas inspected security program audit, records & repts, testing & maint & security sys power supply. TILLMAN.A., MCGUIRE, D.R. Region 2, Ofc of the Director, 88/04/13, 1p. 45268:176-45268:176.

I. Financial information

8803290274 Forwards South Carolina Electric & Gas Co & South Carolina Public Svc Authority 1987 annual linancial repts. NAUMAN.D.A. South Carolina Electric & Gas Co. 88/03/16. Document Control Branch (Document Control Desk). 1p. 44904;155-44904;261.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl MIRAGLIA, F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8803290300 Forwards proprietary & nonproprietary Rev 0 to WCAP-8587, "Equipment Qualification Data Package,ATWS Mittigating Sys Actuation Circuitry (AMSAC) in Std Seismic Cabinet." Affidavi encl. Proprietary rept withheld (ref 10CFR2.790). NAUMAN,D.A. South Carolina Electric & Gas Co. 88/03/24. Document Control Branch (Document Control Dask), 20pp. 44916:193-44916:238.
- --8803290305 Requests that Proprietary Rev 0 to WCAP-8687, "Qualification of ATWS Miligating Sys Actuation Circuitry in STD Seismic Cabinet" be withheld from public disclosure (ref 10CFR2.790).
 WIESEMANN.R.A. Westinghouse Electric Corp. 88/03/21 MURLEY.T. Office of Nuclear Reactor Regulation, Director (Poet 870411). 9pp. 44916.213-44916:221.
- -8803290306 Nonproprietary Rev 0 to WOAP-8587, "Equipment Qualification Data Package,ATWS Mitigating Sys Actuation Circuitry (AMSAC) in Std Seismic Cabinet." RYGG,DE. Westinghouse Electric Corp. WCAP-8587 R00. 88/02/29. 17pp. 44916-222-44918-238.
- 8804060391 Requests relief from ASME Code,Section XI hydrostatic test requirements for steam generator blowdown sys. Relief needed to support steam generator blowdown sys mod scheduled to commence on 880916. Fee paid NAUMAN.D.A. South Carolina Elegific & Gas Go. 88/03/30. HAYES,J.J. NRC No Detailed Affiliation Given. 4pp. 45078:189-45076:172.

153

- 8804060394 Submits addlinto in support of util 850802 request to extend expiration date of ticense NPF-12 NAUMAN,D.A. South Cardina Efectric & Gas Co. 88/03/30 HAYES,JJ. NRC No. Detailed Affiliation Given HAYES,JJ. Document Control Branch (Document Control Desk) 4pp. 45010.245-45010.248
- 8804080088 Generic Ltr 88.07 to power reactor licensees & applicants re-moul ed en-lorcement policy concerning 10CFR50.49. "Environ Qualitication of Electrical Equip-ment important to Safety for Nuclear Power Plants." Svc list end MIRAGLIAF. J. Associate Director for Projects (Post 8704.11) 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164.237.45164.285.
- 8804130250 Notification of 880412 moeting w/util in Alfanta,GA to discuss status of Licensing actions on plant HAYES, J.J. Project Directorate III-1, 88/04/07 MURLEY, T., SNIEZEK, J., MIRAGLIA, F. NRC - No Detailed Affiliation Given. 20p. 45102.351-45102.352
- 8804180137 Documents util response to NRC concern raised in 880328 tetron ra Generic Lir 82:33, "DCRDR." Opurator is not operating components blindly & arrangement of instruments not considered to be problem requiring further resolution. NAUMANDA South Carolina Electric & Gas Co. 88/04/11 Document Control Branch (Document Control Desk). 2pp. 45145:355-45145.356
- here autono Forwards Amend by to Liconse NPF-12 & safety evaluation. Amend modifies existing reactor hidg cooling unit six water cullet valves to automatic valves Amend to be implemented prior to startup eller roox refueling outage. HAYES_J_Project Directorate II-1, 88/04/13, NAUMAN,D.A. South Carolina Electric & Gas Co. 2pp. 45191 102-45191 111. 8804200363 Forwards Amend 69 to License NPF-12 & safety evaluation. Amend modi-
- --8804200365 Amend 69 to License NPF-12, modifying existing reactor bidg cooling unit svc water outlet valves to be automatic valves.

 ADENSAM,E.G. Project Directorate II-1, 88/04/13 Spp. 45191:104-45191:108.
- -8804200367 Safety evaluation supporting Amend 69 to Licenso NPF-12.

 1 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/13 3pp. 45191:109-45191:111.
- 8904210242 Requests approval to perform short duration integrated leakage rate test (Type A periodic) & to utilize mass point analysis technique of ANSI 56.9-1981.Plant presently scheduled for fourth refueling outage in Sept 1989 NAUMAN,D.A. South Carolina Electric & Gas Co. 88/04/15. Document Control Branch (Document Control Dask). 1p. 45235-236-45235-236.
- 8804280105 Forwards safety evaluation providing results of NRC review of summer in-service testing program for pumps & valves. Technical evaluation rept encl. ADENSAME G. Project Directorate III-1. 88704/19. NAUMANID A. South Carolina Electric & Gas Co. 4pp. 45276.099-45276.176.
- -8804280112 Safety evaluation supporting related inservice testing program & request for reliat of utilis.
 * Office of Nuclear Reactor Regulation, Director (Post 870411) 88/04/19, 15pp 45276 102 45276 116
- -8801260033 Rev 1 to "Pump & Valve Inservice Testing Program, VC Summer Nuclear Station," technical evaluation rept.

 MONNIE,D.I., RANSON,C B. EG&G. Idaho, Inc. (subs. of EG&G, Inc.), MONNIE,D.I. Idaho National Engineering Laboratory, FIN. A-6812, EGG-NTA-7424, R01, 87712/31, NRC No Detailed Altifation Given. 59pp. 45276:117-45276.175.
- 8804280426 Summary of 880412 meeting w/util in Atlanta,GA,to discuss status of li-censing issues List of attonders,agenda,status of TACs & proposed Tech Specs encl. HAYES,JJ Project Directorate II-1. 86/04/22. Project Directorate II-1. 15pp. 45270 296-45270.310

Q. Inspection reports, IE Bulletins & correspondence

- 8803300122 Forwards Insp. Repts 50-385/88-04 on 860201-05.No violations or devi-
- ations noted HERDT.A.R. Rogion 2, Otc of the Director, 88/03/04, NAUMAN,D.A. South Carolina Electric & Gas Co. 2pp. 44961:269-44961:283.
- -8803300129 Insp Rept 50-395/88-04 on 880201-05.No violations noted Major areas inspected seismic monitoring program & firo protection/prevention program HARRIS.J.R., CONLON,T.E. Region 3, Ofc of the Director, 88/02/29, 13pp 44961 271 44961 283
- 8803250131 Responds to NRC 880219 lit re violations noted in Insp Rept 60-385/88-03 Corrective actions Station Administrativo Procedure 139 revised to require that red 2-yr hold stemp be used on procedures exceeding 2-yr review period NAUMAN.D.A. South Carolina Electric & Gas Co. 88/03/18, GRACE,J.N. Region 2, Old of the Director. 4pp. 44945.005-44945:016.
- 8804010012 Forwards Insp. Rept 50:395/88-07 on 880220-0304 & notice of violation. HERDT,A.R. Region 2, Ofc of the Director, 88/03/24 NAUMAN,D.A. South Carolina Electric & Ges. Co., 2pp. 45008,124-45008-133.
- ~8804010014 Notice of violation from insp on 880229-0304-Violation noted failure to properly implement Admistrative Procedure SAP-134, "Control of Station Surveillance Test Activities," re-erroneous isothermal temp coefficient reading on 870607. HERDT,A.R. Region 2, Oic of the Director, 88/03/24, 2pp. 45008:126-45008:127.
- ***B804010016 Insp. Rept. 50:385/88:07 on 880228:0304.Violations noted Major ereas inspected post-relucing startup tests & local leak rate testing SPARKS.SE , JAPE,F. Region 2, Ofc of the Director. 88/03/21. 6pp. 45008:128-4508-132 45008:133
- 8804110286 Discusses util response to NRC Bulletin 88-002, "Raprilly Propagating Fa-tique Cracks in Steam Generator Tubes." Liconsee roview of Mar & Apr 1987 steem generator data found no ovidence of deating at uppormost support plate at prant. NAUMAN.D.A. South Carolina Electric & Gas Co. 88/03/24. GRACE.J.N. Region 2, Oic of the Director 2pp 45129:350-46129:351.
- 8803210090 Suppl 1 to NHC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Syc fist encl. ROSSI.CE Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44895:128-44995:246.

- 8803220296 NRC 'nto Notice 88-010, "Matts Licenseds Lack of Mgt Controls Over LIceased Programs. Svc 1st and Country and Successor Services Safety (Post 870729) 887 03728 Consoldated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353
- 8804110292 Responds to NRC Buildin 68:001, "Defects in Westinghouse Circuit Breakers" to confum that shot-term inspicompleted on 880309,per request Replacement pole shalts ordered Cost of compliance w/Eurlain stated NAUNAN,D.A. South Carolina Electric & Gas Co. 88/09/30. GRACE,J.N. Reg on 2, Cit. of the Circuit 2pp. 45123.331-45123.332.
- 8804010256 NRC Info Notice 88:011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Botts," Svc tist and. ROSSICE Division of Operational Events Assessment (Post 870411), 88/04/07 Consol
- 8804150348 Ack recept of 880316 to informing NRC of stops taken to correct indiations coted in this Rept 50.395/88-03 VERRELLUD M. Region 2. Ofciol the Director, 88/04/07 NAUMAN,D.A. South Carolina Electric 8 Gas Co. 1p. 45138 293-45138 293.
- 8804150381 Forwards Insp. Rept 50-395/88-08 on 880301-31 No violations or deviat one noted
 VERRELLI,D.M. Reg on 2, Oic of the Director 88/04/08 NAUMAN,D.A. South Caro'ina Electric 8 Gas Co. 2pp. 45192:213-45192:221
- -8804150386 Insp. Rept. 50:395/88:08 on 860301:31 No violations or deviations noted Major areas inspected licensee action on previous Insp. findings monthly surveillance observations, radiotogical protection, physical security & written repts. PREVATE, R.L., PDRINS, P. G., DANCE, H.C. Region 1, Ofc. of the Director, 887047-08, 7pp. 45192:215-45192:221.
- 8804060370 NRC Into Notice 69-012, "Overgreasing of Electric Motor Bearings." Svc. RIOSSICE. Division of Operational Events Assessment (Post 870411), 98/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165-150
- 8804200473 Partial response to FOIA request re tire protection Forwards App E documents App D 8 E documents symbolic in PDR App F document completely withheld (rel FOIA Exemption 5) GRIMSLEY, D.H. Division of Rules & Records (Post 870413) 88/04/14 JONES, CR Att:liation Not Assigned 5pp. 45206 037-45206 043
- --88D4200579 Advises that Fire Protection Stoering Committee has recommended that each region make one 10CFR50,App R-type insplict for each facility to assess status of compliance w/ 10CFR50.48. Program Insted CONLON,T.E. Region 2, Ofc of the Director 84/11/06. HERDT,A.R. Region 2, Ofc of the Director. 3pp. 45206.176-45208:178.
- 8804260008 Forwards Insp Rept 50 395/88-09 on 880314-18.No violations or deviations noted CLINE.W.E. Region 2, Oto of the Director, 88/04/16 NAUMAN,D.A. Scuth Carolina Electric 8 Gas Co. 2pp. 45268:174-46288:176.
- --8804260010 Partially withhold Physical Security Insp. Rept 50-395/88-09 on 880314-18 (rdf 10CFR2.780(d) & 73.21).No wordstons noted Major areas inspected security program audit records a repts testing & mental & security sys power supply.

 TILLMAN.A., MCGUIRE.D.R. Region 2, Ofc of the Director 88/04/13. 1p. 45268-176-45268 176.

R. Periodic operating reports & related correspondence

- 8804010239 Forwards Technical Rept 87-4, "Seismic Activity Near VC Summor Nuclear Station for Period Oct-Dec 1987."

 NAUMAN,D.A. South Carolina Electric & Gas Co. 88/03/25. Document Control Branch (Document Control Branch (Document Control Dosk), 1p. 45059.063-45058-083.
- --8804010240 "Saismic Activity Near VC Summer Nuclear Station for Period Oct-Dec 1987." TALWANI,P. South Carolina, Univ. of, Columbia, SC, 67-4 87/12/31, 20pp. 45058.064-45058.063.
- 8804190133 Monthly operating rept for Mar 1988 W/880413 ftr. HALTIWANGERJ., NAUMAN,D.A. South Carolina Electric & Gas Co. 88/03/31, BARRY,L.W. NRC No Detailed Affrication Given, 5pp. 45209.191-45209:195.

S. Reportable occurrences, LERs & related correspondence

8904010059 Adv.ses that 890601 is new target date for return to svc of integrated fra computer sys due to implementation of mode discussed in Special Rept SPR 88-001. New date includes relocation of unaccounted for equipment. NAUMANIOA South Carolina Electric & Gas Co. 88/03/22. GRACE, J.N. Region 2, Otc of the Director. 1p. 45031:112-45031:113.

DOCKET 50-396 UNIV. OF VIRGINIA CAVALIER REACTOR

- P. Operating license stage documents & correspondence
- 8803250248 Informs of NRC refocation to stated address Malting address unchanged. A Adams project manager & TS Michaels back-up project manager. RUBENSTEINLS. Stendardization & Non-Power Reactor Project Directorate 88/03/18. Affiliation Not Assigned. 3pp. 44859 080-44859.062.

DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

- 8804070038 Forwards response to NPC 650303 ltr re-violations noted in Insp Riopt 50-537-98 Gt Response withfeld (ref-10CFR73-21) 5CRES-SERGC Washington Public Power Supply System 88/03/30 Document Control Branch (Document Control Desk) 1p. 45115-033-45115.033.
- 8804920001 Forwards Rev 6 to facility guard training & qual-fication plan Rev describes of angles made as result of undepth supernsory job/lask analysis & other administrative & procedural changes Rev withheld (10CFR73.21). SURENSENGC: Washington Public Power Supply System. 88/04/04. Document Cox trip Branch (Document Control Desk). 2pp. 45135.295-45135.296.
- 8804150152 Revised emergency plan implementing procedures, including Rev. 5 to 13.5.5 to personnel accountability Rev. 5 to 13.10.1 to control room operations & shift manager dutes & Rev. 4 to 13.10.3 to technical support ctr operations.

 haltington Public Power Supply System. 88704706, 132pp. 45131:189-45131:321.
- 8804150313 Forwards corrected pages to Rev 6 to guard training & qualification plan, for 804130111 FORMAIS GOVERNMENT OF THE SUPPLY SYSTEM 88/04/11. Document SUPPLYSE'S C. Washington Public Power Supply System 88/04/11. Document Control Branch (Document Control Desk). 1p. 45184-061-45184-061.
- 8504260080 Provides additurio roquested by NRC at 880119 meating relifie protection & sate shudown capability into provided re-separation & protection of redundant shut-down sys in gap between primary contamment vessel & biological shield wall. SCRENSEN GC Washington Fubic Power Supply System 89/04/15. Document Control Branch (Document Control Desk). 8pp. 45253 064-45253 071.
- 8404290101 Adnises that C. Ramsey of Region V will lead insp. on fire protection at paint List of pioposed insp. learn members & tentative schedule encl.W/o draft plan SAMWORTH R.B. Project Directorate V. 88/04/18. KNIGHTON,G.W. Project Directorate V. 4pp. 45024.245-45024.249
- P. Operating Scense stage documents & correspondence
- 8803080029 Notification of significant licensies meeting on 880301 at Region V.

 * Region 5 Dric of the Director 88/02/29 Region 5, Orc of the Director, 1p.
 44622-021-44622-021
- 8403300288 Application for amend to Lucense NPF-21 changing Tech Specs to afflow operation of plant up to power level of 75% w/one recirculation loop operating Repts on analyses of single loop operation also encil Fee paid SORENSENIG C Washington Public Power Supply System. 88/03/07. Document Control Branch (Document Control Desk) 4pp. 44962 211-44962:344.
- ~860300291 Washington Nuclear Plant 2 Single-Loop Operation Analysis." ARAJ/CEK JE Advanced Nuclear Fuels Corp. (formerly Exxon Nuclear Co., Inc.). ANF-87-113 87/09/30 28pp 44962 215-44962 242
- -8803300294 Washington Nuclear Plant 2 LOCA Analysis for Single-Loop Operation." KRAJ/CEK JE Advanced Nuclear Fuels Corp. (formerly Exxon Nuclear Co., Inc.). ANF-87-118 68/09/30 48pp 44962 243 44962 290
- -8803300296 Washington Nuclear Plant 2 Single-Loop Operation Summary Rept." WOLKENHAUER W., TALBERT.J., HUMPHREYS.M.C. Washington Public Power Supply System WPPSS-EANF-115 88/02/29 17pp, 44962.291-44962.308.
- -8603300298 Proposed Tech Specs re single-loop operation.
 * Washington Public Power Supply System. 88/03/07, 36pp. 44962:308-44962:344.
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MRAGLIAF J. Associate Director for Projects (Post 870411): 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972 107-44972:153.
- \$804110122 Provides status of activities in addressing aspects of NRC 871013 fit re DCRDR Supplementary rept will be submitted upon completion of items identified in status rept.

 SCHENSEN G.C. Washington. Public. Power. Supply. System. 88/03/29. Document. Control Branch (Document Control Desk). 46pp. 45078.038-45078.083.
- 8604130322 Forwards for into notice of consideration of issuance of amend to License NPF-21 & opportunity for hearing re 871223 to allow continued operation until fourth refluence outage w/o meeting requirements of Rev 2 to Reg Guide 1.97. SAMWORTH R.B. Project Directorate V. 88/03/29. SORENSEN.G.C. Washington Pubec Power Supply System. 4pp. 45103.1884.
- --8804050184 Notice of consideration of issuance of amend to License NPF-21 & proposed NSHC determination & opportunity for hearing Amend continues operation of Unit 2 unit fourth refusing outage w/o meeting Reg Guide 1.97 requirements. ROOD.H Project Directorate V 88703729 5pp 45103:186-45103:189.
- 8804120052 Documents 880030 felcon w/NRC re dieset generator LOCA response mod Design includes indicating light in control room that will indicate position of engine speed selector switch. SCRENSEN.G.C. Washington Public Power Supply System. 88/04/01. Document Control Branch (Document Control Desk). 2pp. 45145.062-45148.062.
- 8804120130 Forwards Amend S2 to License NPF-21 & safety evaluation Amend revises Section 3.7.1.3 of Tech Spects to permit two spray ponds that comprise ultimate heat sink to be used undividually for dissipation of heat during refueling mode. SAMMORTH.R.B. Project Directoral V. 88/04/104. SORENSEN.G.C. Washington Public Power Supply System. 3pp. 45100:343-45100:359
- -9804120136 Amend 52 to License NPF-21 rensing Tech Specs Section 3.7.1.3 to permit the spray pends that comprise utimate heat sink to be used individually for dissipation of heat during refueling operational mode. KNRGHTON,G.W Project Orectorate V 88/04/04 10pp. 45100:346-45100:355.
- -8804120136 Safety evaluation supporting Amend 52 to License NPF-21.

 **Office of Nuclear Reactor Regulation, Orector (Post 870411): 88/04/04. 4pp. 45100-356-45100-359

- RAMWORTH,R B. Project Directorate V. 88/04/04. SORENSEN,G,C. Washings Public Power Supply System. 3pp. 45100.273-45100.283.
- -8804120197 Amend 53 to License NPF-21,rovising Tech Spoc Section 4.1 3.5 to say veillance requirements for control rod scram accumulators. KNIGHTON,G.W. Project Directorate V. 88/04/04, Spp. 45100,278-45103;280
- --8804120239 Safety evaluation supporting Amend 53 to License NPF-21.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/04 35; 45100 281 45100 283
- 8804120266 Forwards Amend 51 to License NPF-21 & safety evaluation. Amend revise Tech Spec 3.3.7.1, "Rediation Monitoring Instrumentation," changing fluc value of 5 R/h. SAMWORTH.R.B. Project Directorate V. 88/04/94, SORENSEN,G C. Washingto Public Power Supply System. 4pp. 45089:176-45089.188.
- -8804120276 Amend 51 to License NPF-21, revising Tech Spec 3.3.71, "Radate Monitoring Instrumentation," to change fuel vault criticality monitor plants scipping to 5.8/h.
- KNIGHTON, G.W. Project Directorate V. 88/04/04, 7pp. 45089:180-46089:186
- -8804120280 Safety evaluation supporting Amend 51 to Liconso NPF-21
 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/04, 2p. 45089:187-45089:188.
- 8804130230 Forwards notice of consideration of issuance of amend to Eleanso NPF-3 opportunity for hearing re 871119 request to change indicated number of change per tip by a sesociated wirmain steam times SAMMORTH.R.B. Project Directorate V. 88/04/05. SORENSEN.G.C. Washing's Public Power Supply System. 4pp. 45102 338-45102:345.
- --8804130234 Notice of consideration of Issuance of amend to License NPF-21 & proposed NSHC datermination & opportunity for hearing Amend changes statement number of channels pet trip system at seam line flow & tunnel tompt. KNIGHTON,G.W. Project Directorate V. 88/04/05. 4pp. 46102 342-45102 345
- 8904130314 Forwards notice of consideration of issuance of amend to tilcense NPF: & opportunity for hearing re 880307 request to permit operation up to power level 75% w/one recirculation loop operating. SAMWORTH,R B. Project Directorate V. 88/04/05. SORENSEN,G.C. Washing? Public Power Supply System. 3pp. 45103:175-45103;181.
- -8804130321 Notice of consideration of issuance of amend to Liconso NPI⁻-21 & property NPIC determination & opportunity for hearing on 880307 request to allow o ratioo up to power level of 75% w/one recirculation loop operating.

 KNIGHTON,G,W. Project Directorate V. 88/04/06, 4pp. 45103:178-45103:181.
- 8804140010 Requests that revidate of 861112 noted in Table 1 of draft gonoric fir inservice testing program be changed to 871012 to reflect revidate of current submitted new implemented at taclity, par 860314 telcon.
 SORENSEN.G.C Washington Public Power Supply System. 88/04/08 Documer Control Branch (Document Control Desk). 2pp. 46184:135-45184:136.
- 8804080088 Ganeric Ltr 88-07 to power reactor icensees & applicants to modified of forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment important to Safety for Nuclear Power Plants." Syc hat enci. MIRAGELAF.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidat Edison Co. of New York, Inc. 49pp. 45164:237-45184:285. 8804210418 Forwards Amend 64 to License NPF-21 & safety evaluation. Amond revision
- Tech Spec 4.7.4.e re snubber functional testing sampling plans.
 SAMWORTH,R.B. Project Directorate V. 88/04/11, SORENSEN,G.C. Washingt
 Public Power Supply System. 2pp. 45191:138.45191:159.
- -8804210425 Amend 54 to License NPF-21, revising Tech Specs re snubber function testing sampling plans. KNIGHTON,G.W. Project Oirectorate V. 88/04/11, 10pp. 46191:140-46191:149.
- -9804210433 Safety evaluation supporting Amend 54 to License NPF-21. Office of Nuclear Reactor Regulation, Director (Post 870411), 66/04/11. 4(45191:150-4519):150-45191:150-4519:150-45191:150-45191:150-4
- -8804210451 Notice of Issuance of Amend 54 to License NPF-21.Amend revisos Te Spec 4.7.7.e re functional testing sampling plans. SAMWORTH.R.B. Project Orectorate V. 88/04/11. 2pp. 45191:154-45191:155.
- --8804050418 Notice of environ assessment & lindings of no significant impact to some functional testing sample plans.
 KNIGHTON,G.W. Project Directorate V, 88/04/01, 4pp, 46191;156-46191;169.
- 8804210034 Forwards addi Tech Specs pages not included in 880307 application amend to Ucense NPF-21 te Cycle 4 reload. Administrative changes to Figures 3.2. 1.3.2.1.3.2.3.1.8.3.2.6.1 also enci.
 SORENSEN.G.C. Washington Public Power Supply System. 88/04/12. Docume Control Branch (Document Control Desk). 2pp. 45231:195-45231:199.
- -9804210079 Proposed Tech Spacs.consisting of administrative corrections to Cycle reload * Washington Public Power Supply System, 88/04/12, 3pp. 45231:197-45231:199
- 8804210341 Forwards Amend 55 to License NPF-21 & safety evaluation. Amend revision Spec Table 4.3.2.1-1, "Isolation Actuation Instrumentation Surveillance Requirents" to delete channel check requirements for reactor water Level 2. SAMWORTH R B. Project Disectorate, V. 88/04/13. SORENSEN,G.C. Washingt Public Power Supply System. 3pp. 45192:124-45192:135.
- --8804210347 Amend 55 to License NPF-21, revising Tech Spec Table 4.3.2.1-1, "Isc ion Actuation Instrumentation Surveillance Requirements" to delete channel che requirements for reactor water Level 2 instruments. KNIGHTON.G.W. Project Directorate V. 88/04/13, 7pp, 45192:127-45192:133.

- --8804210348 Salety evaluation supporting Amend 55 to License NPF-21.

 * Office of Nuclear Reactor Regulation, Director (Post 870411) 88/04/13. 2pp. 45192134-45192135.
- 8804280357 Advises that administrative removal of notes added to Tech Specs Pages 374 3-71 8 3-74 requires filing of application for amond to license Americans Agency (July 1974) 3-71 8 3-74 requires filing of application for amond to license Americansersery (July 6 operating of acoustic morner.

 KNIGHTON, G.W. Project Directorate V 88/04/18 SORENSEN, G.C. Washington Public Pawer Supply System 3pp. 45269.234-45269.236

8804280539 Forwards request for additinfo re recirculation pump trip sys & afternate rod

injection sys to compfele rowew
SAMWORTH.R.B. Project Directorate V 88/04/18, SORENSEN,G.C. Washington
Public Power Supply System 4pp 45263 073-45263.076

Q. Inspection reports, IE Bulletins & correspondence

- 8804040225 Forwards Mgt Moeting Rept 50:397/88-07 on 880301 Topics discussed
 - MARTIN, J.B. Region 5, Ofc. of the Director, 88/03/16, MAZUR, D.W. Washington Public Power Supply System 3pp. 44970.347-44970.358.
- --8804040235 Mgt Mueling Insp Rept 50-397/88-07 on 880301 Major areas discussed root cause assessment & corrective actions in response to secondary con-lainment roof overpressurization on 880214, recent design control issues & oversight groups CALDWELL,C.W., JOHNSON,P.H. Region 5, Ofc of the Director. 88/03/15. 7pp. 449/0 350 44970 358
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors." Syc tist and ROSSIC E Division of Operational Events Assessment (Post 870411) 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp. 44995-126-44995-248.
- 8803220296 NRC Info Notico 88:010, "Matts Liconsees:Lack of Mgt Controls Over Li-censed Programs" Svc 1st enct. CUNNINGHAM,R E Dwison of Industrial & Modical Nuclear Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353
- 8804130008 Forwards Insp Rept 50:397/88:04 on 880222-26 No violations noted. WENSLAWSKI,F.A. Region 5, Old of the Director 88/03/28, SORENSEN,G.C. Washington Public Power Supply System. 2pp. 45132:277-45132 288
- ~8804130009 Insp Rept 50.397/68.04 on 880222-26 No violations or deviations noted Major aricas inspected fliquid & liquid wastes, gaseous waste sys, solid wastes, including followup of previous insp findings & facility tour. CILLISM, YUHAS, G.P. Region 5, Ofc. of the Director, 88/03/25, 10pp. 45132.279-45132.288
- 8804040245 Requests addl into re util 860528,1001 & 871218 responses to IE Bulletin 85,003, "Motor-Operator Valve Common Mode Failures During Plant Transionis due to Improper Switch Sattings." Into sant within 30 days of Itr dato requested. KIRSCH.D F Region 5, Olic of the Director. 88/03/20. SORENSEN.G C. Washington Public Power Supply System 4pp. 45074:065-45074.068.
- 8804070038 Forwards response to NRC 880303 filt re-violations noted in Insp Rept 50-307/88 01 Response withhold (ref 10CFR73 21).

 SORENSEN,G.C. Washington Public Power Supply System, 88/03/30. Document Control Branch (Document Control Desk). 1p. 45115.033-45115.033.
- 8804190119 Forwards Insp Rept 50-397/88-09 on 880307-11.No violations noted. ZIMMERMAN,R.P. Region 5, Ofc of the Director. 88/03/30, SORENSEN,G C Washington Public Power Supply System. 2pp. 45209:174-45209.183.
- -8804190120 Insp. Rept. 50:397/88:09 on 880307-11.No violations or deviations noted Major areas Inspected response to NRC Buffelin 85:003, "Motor-Operated Valve Common Mode Failure," followup of Inspector Identified Items & review of events CALDWELL.C.W., JOHNSON,P.H. Reg on 5, Ofc of the Director, 88/03/30, 8pp. 45090 124, 45300 129 45209 176 45209 183.
- 8804110249 Submits evaluation of marking deficiency of two nuts (Samptos N18 & N10),per 880111 commitment in response to IE Bullatin 87-001 re fastener testing Subjinuts not used during const & no critical strength reduction likely. SORENSEN,G C. Washington Public Power Supply System. 88/03/31. Document Control Branch (Document Control Dosk). 3pp. 45077:344-45077:346.
- 8804180416 Forwards Insp Rept 60-397/88-11 on 880314-18.No violations noted PATE.R.J. Region 5, Oic of the Director. 88/03/31, SORENSON,G.C. Washington Public Power Supply System. 2pp. 45183:222-45183:230.
- -8804180417 Insp. Rept. 50-397/88-11 on. 880314-18.No violations or deviations noted.Major areas Inspected licensee actions taken to implement Generic Ltr 84-11 & util response to NRC Bullotin 87-001.

 WAGNER,W.J., RICHARDS,S.A. Region 5, Ofc. of the Director. 88/03/31. 6pp. 45182-224 45183 224-45183 230
- 8804010256 NRC Into Notice 88-011, "Patential Loss of Mater Control Cir 8/or Switchboard Function Due to Faulty Tie Bolts." Svc list enct. POSSI.CE. Division of Operational Events Assessment (Post 870411). 88/04/07. Consol dated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804200103 Submits into as requested by NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakers." SORENSEN.G.C. Washington Public Power Supply System. 88/04/11. MARTIN.J.B. Region 5, Ofc of the Director. 3pp. 45177:156-45177:158.
- 8804200228 Submits listed addl Info to provide clarification of selected items in re-sponse to violations noted in Insp Rept 50-397/87-19,per R Zimmerman 880302 re-
- quest SORENSEN,G.C. Washington Public Power Supply System, 88/04/11, Document Control Brench (Document Control Desk), 5pp. 45177:287-45177:271.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl. ist drich. ROSSI.CE. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.026-45165:150.

- 8804220282 Ack receipt of 880330 ftr informing NRC of steps taken to correct violations noted in first Ropt 50:397/88-01 MONTGOMERTY_LI Rogion 5, Otc of the Director, 88/04/14 SORENSEN.G C Washington Public Power Supply System 1p 45257 234, 45257:234.
- 8804290101 Advises that C Ramsey of Region V will feed inspirent inspirent on at plant List of proposed inspirent members & tentative schedule end W/o draft plant SAMWORTH.R B Project Directionato V, 88/04/18, KNIGHTCN.G W Project Directorate V 4pp. 45324;284-45324 249.

R. Periodic operating reports & related correspondence

- 8803300329 Monthly operating rept for Feb 1988 W/880309 fir HUTCHISONL B., POWERS,C.M. Washington Public Power Supply System 88/02/ 29 Spp. 44953.162-44953 165.
- 8804150401 Monthly operating rept for Mar 1988 W/660408 fr. HUTCHISON,L.B., POWERS,C.M. Westington Public Power Supply System 66/03/31, 4pp. 45183-204-45183-207.

DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

- F. Security, medical, emergancy & fire protection plans
- 8804250059 Forwards Insp. Rept. 50.400/88-05 on 880220-0304 & notice of violation.Notice of violation.withhold (ref. 10CFR2.790 & 73.21).

 CLINE,W.E. Region 2, Otc. of the Director, 88703/24, UTLEY,E.E. Carolina Power & Light Co. 2pp. 45239:210-45239:212.
- --8804250061 Partially Withhold Physical Socurity Insp. Rept 50-400/86-05 on 880229-0304. Violation noted Major areas inspected, security plan 8 implementing procedures 8 mgt effactiveness. Osta's withheld (rof 10CFR2.790 & 73.21) ENNIS, J.D., MCGUIRE, D.R. Region 2, Ofc of the Director, 88/03/21, 1p. 45239:212-45239:212.
- 8804070101 Forwards "Plan for Shearon Harris Nuclear Power Plant Emergency Exercise 880517," in response to JP Stohr 920129,RC Lewis 841011 & DM Verrelli csa - 880517," in response to JP Stohr 820129,RC Lowis 841011 & DM Verrelli 870102 lirs:W/o enci. LOFLIN,L.I. Carolina Power & Light Co. 88/03/30. Document Control Branch (Document Control Desk). 1p. 45022:063-45022:063.

J. Insurance & Indemnity Information

- 8604070174 Submits into re present fevel & source of onsite property damage insur-LOFLIN.L.I. Carckna Power & Light Co. 88/03/31, Document Control Branch (Occument Control Desk), 1p. 45076:256-45075;258,
- 8804250222 Forwards Endorsement 13 to MAELU Policy MF-126 BARHAM,C.D. Carolina Power & Light Co. 88/04/04. NASH,D. NRC No Detailed Af-Mation Given. 2pp. 45212 222-45212 223.
- 8804250223 Forwards Enforsement 21 to NELIA Policy NF-288.
 BARHAM,C D. Carolina Power & Light Co., 88/04/04, NASH,D NRC No Detailed Af-fliation Given. 2pp. 45212 224-45212 225.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88-98 to all power reactor I censees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc 1st encl. MIRAGLIAF J. Associate Director for Projects (Past 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972.153.
- 8904080088 Generic Ltr 88-07 to power reactor I censees & applicants re-modified en-forcement policy concerning 10CFR50 49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants" Svc list enct. MIRAGUIA,F.J. Associate Director for Projects (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804130388 Forwards Amend 5 to License NPF-63 & safety evaluation. Amend modifies Tech Spec 5:3 to allow only storage & handling of fuel elements having max fuel enrichment of 4.2 weight % U-235. BUCKLEY, B.C. Project Directorate II-1. 88/04/07, UTLEY, E.E. Carolina Power & Light Co. 3pp. 45104.034-45104.043.
- --8804130395 Amend 5 to License NPF-63,mod fing Tech Spec 5.3 to allow only storage 8 handling of fuel elements having max fuel enrichment of 4.2 weight % U-235. ADENSAM,E.G. Project Directorate II-1, 88/04/07, 4pp. 45104:037-45104.040.
- -8804130398 Safety evaluation supporting Amond 5 to License NPF.03.
 Office of Nuclear Resolutation, Director (Post 870411) 88/04/07. 3pp. 45104.041-45104.043.
- 8804210144 Submits addl into to suppl 880111 lir re plant-specific ATWS intigating sys actuation circuitry per 10CFR50.82, including sys test frequencies, simplified logic diagram & SER, App A Into.
 LOFLIN, I. Catrofina Power & Light Co. 38/04/12. Document Control Branch (Document Control Oesk), 16pp. 45238:319-45238.334.
- 8804210035 Supplemental application for amend to License NPF-63, revising proposed wording for Tech Spec 53.1, "Fuel Assemblies" & 10CFR50.92 evaluations of Tech Specs re boron dilution/sliding shutdown marg in 880201 application. EURYL W. Carolina Power & Light Co. 68/04/13. Document Control Branch (Document Control Desk), 4pp. 45254;334-45254.359.
- --8804210036 Proposed revised Tech Specs re wording of Tech Spec 6.3.1 & 10CFR50.92 evaluations re boron dilutton/sliding shutdown margin. ** **Carolina Power & Light Co. 88/04/13 22pp. 45254;338-45254;359.

0004210330 1/10113 04 ment approved per util 870902 request BUCKLEY,B C. Project Directorate II-1, 88/04/14. UTLEY,E E. Carolina Power & Light Co. 2pp. 45192 122-45192 123

8804210452 Forwards safety evaluation on 870605,0725 & 1012 changes to Initial test program. Changes will not affect health & safety of public & acceptable BUCKLEY.B.C. Project Directorate III-1 88/04/15 UTLEY.E.E. Carolina Power & Light Co. 2pp. 45191 170-45191:174

~8804250460 Safety evaluation supporting changes to util initial test program per B70605,0727 & 1012 ltrs **Office of Nuclear Reactor Regulation, Director (Post 870411) 88/04/15 3pp. 45191.172.45191.174

Q. Inspection reports, IE Bulletins & correspondence

8803250256 Ack 880226 supplemental response to violations noted in Insp. Repte 50-400/87-31 & 50-400/87-40
VERRELLIO M. Region 2, Ofc of the Director, 88/03/14, UTLEY,E.E. Carolina Power & Light Co. 1p. 44945 225-44945 225

890.4060054 Responds to NRC Bulletin 88-002. "Rapidly Propagating Patigue Cracks in Steam Generator Tubes." Rept will be submitted within 45 days of completing steam generator inservice insps scheduled for upcoming refucing outage. EURYLW Carolina Power & Light Co. 88/03/24. GRACE.J.N. Region 2, Otc of the Director. 1p. 45007 112-45007 112

8804060477 Forwards response to NRC Butletin 87-002, "Fastener Testing to Determine Conformance W/Applicable Metl Specs," to provide addl Info on internal controls for use of fasteners procured during util const. EURY_LW Carolina Power & Light Co. 88/03/24 GRACE, J.N. Region 2, Otc of the Director. 49pp. 45008 252-45008 300.

8804250059 Forwards Insp. Rept. 50.400/88.05 on 880220-0304 & notice of violation Notice of violation withheld (ref. 100FR2.790 & 73.21).

CLINE,W.E. Region 2, Ofc of the Director, 68/03/24, UTLEY,E.E. Carolina Power & Light Co. 2pp. 45239.210-45239.212.

--8804250061 Partially Withheld Physical Security Insp Rept 50-400/88.05 on 880229-0304 Violation noted Major areas inspected, security plan & implementing procedures & mgt effectiveness. Details withheld (ref 1007FR 796 & 73 21) ENNIS. D. MCGUIRE,D R. Region 2, Ofc of the Director. 88/03/21, 1p. 45239.212-

8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning In Westing-house Reactors" Svc list end! ROSSI, C.E. Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995.246.

6603220296 NRC Into Notice 88-010, "Mails Licensees:Lack of Mgt Controls Over Li-censed Programs." Svc hist enct CUNNINGHAMR 5 Obision of Industrial & Medical Nuclear Safety (Post 870729), 867 03/26 Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.

8804060454 Responds to Violation "A" noted in Insp Rept 50-400/86-77. Review to confirm adequacy of in-house design of Seismic Class I steel completed & final rept on file for NRC msp WATSON R.A. Carolina Power & Light Co. 88/03/30. Document Control Branch (Document Control Desk). 1p. 45007-072-45007.072

8804120071 Forwards Insp. Rept 50-400/88-06 on 880220-0320 & notice of violation. VERRELLI, D.M. Region 2, Oic of the Director. 88/04/01. UTLEY, E.E. Carolina Power & Light Co. 2pp. 45131.041-45131:052.

--8804120076 Notice of violation from insp on 880220-0320-Violation noted failure to revise Emergency Operating Procedure EQP-EPP-010, "Transfer to Cold Leg Recirculation" to include valve configuration described in FSAR Table 6.3.2-6, VERRELLID M. Region 2, Oic of the Director. 88/04/01, 1p. 45131.043-45131:043.

-8804120087 Insp. Rept 50-400/88-06 on 880220-0320.Violation noted.Major areas inspected iscensee action on previous enforcement matters, operational safety verification, monthly surveillance observation & monthly maint observation. MAXWELL, G.F., FREDRICKSON,P. Region 2, Ofc of the Director, 88/04/01, 9pp. 45131:044-45131.052.

8804120191 Responds to NRC Bulletin 88-001 re defects in Westinghouse circuit breakers. Util intends to perform long-term insps required by bulletin during upcoming refueling outage EURY,L.W. Carolina Power & Light Co. 88/04/05. Document Control Branch (Document Control Desk) 2pp. 45080 047-45080 048

8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Cit &/or Switch-board Function Due to Faulty Tie Bolts." Svc list encl. ROSSLG E. Dwisson of Operational Events Assessment (Post 870411). 98/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406;282-45407.051.

8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list eric.

ROSSI,C E. Division of Operational Events Assessment (Post 870411), 88/04/12

Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150.

8804270154 Ack receipt of 880324 response to violations noted in Insp Rept 50-400/ 87-41 Response meets requirements of 10CFR2 201 Implementation of corrective ac-tions will be examined during future insps. HERDT_A R. Region 2, Ofc of the Director. 88/04/14. UTLEY.E.E. Carolina Power & Light Co. 1p. 45244.357-45244.357.

R. Periodic operating reports & related correspondence

8804 190 123 Monthly operating rept for Mar 1988.W/880414 ltr. HALE.M., WATSON.R.A. Carolina Power & Light Co. 88/03/31, 7pp. 45209:184-45209:19

8804010055 Advises that Attachment 3 to util 871029 ltr should be removed & Page ret be deleted due to questions re copyright privileges in 10CFR21 not fication to ow up rept WATSON,R A. Carolina Power & Light Co. 88/03/24 GRACE,J N. Hegion 2, Olc clifte D.rector. 1p. 45031:201-45031.201.

8804080126 LER 88-001-01 on 880115 procedural deficiency which could have rescite in failure of ECCS during recirculation phase of accident identified Caused by failure in note new requirement in procedure Procedures revised W/880320 III of the NOVE AL WATSON, R.A. Carolina Power & Light Co. 88/03/29, 10pp 4507203 45072.039.

8804130293 LER 88:007:00.on 880309.sevoral alarms received by operators at ma-control board indicating low water level in steam generator B.Caused by failed renew abits fuse Fuse replaced. W/880408 ftv. SCHWABENBAUER, WATSON,R A. Carolina Power & Light Co. 86/04/08 5p. 45137 012-45137 016.

8804250240 LER 88-006-01:on 880208 both emergency svc water sys declared inope able due to isolation valve failures Caused by debris accumulation Fated valves in peried & retested W/880415 ltr. HOWE.A. WATSON,R A. Carolina Power & Light Co. 88/04/16. 6pp. 45258 28, 45258-285

DOCKET 50-407 UNIV. OF UTAH RESEARCH REACTOR

H. General correspondence

8804060459 Informs that listed personnel make up now reactor operations staff TRIGA (R-126) & AGN (R-25) reactors SANOQUIST G.M. Utah, Univ. of, Sall Lake City, UT. 88/03/03. SEIDLE,W.C. Rego. 4, Oic of the Director. 1p. 45076:174-45076.174.

P. Operating license stage documents & correspondence

8803250248 Informs of NRC relocation to stated address Mailing address unchanged Adams project manager & TS Michaels back-up project manager. RUBENSTEIN.L.S. Standardization & Non-Power Reactor Project Directorate. 88/0

Q. Inspection reports, IE Bulletins & correspondence

8804060437 Confirmation of Action Ltr CAL-88-06 on 880329 telcon w/ RL Bangart 880216-19 insp & 880328 enforcement conterance.Understands that reactors warmain strut down until Region IV reviews response to apparent violations. MARTIN,R.D. Region 4, Circ of the Director, 88703730. BROPHY,J J. Utah, Urix, Salt Lake City, UT. 2pp. 45010:346-45010:347.

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F. Security, medical, emergency & fire protection plans

8804150068 Forwards notice of consideration of issuance of amend to License DPR-8 opportunity for hearing re 870924 application. ERICKSON P. B. Standardization. 8 Non-Power Reactor Project Directorate. 88/04/ TAYLOR,J.W. Deiryland Power Cooperative. 4pp. 45133:197-45133:205.

--9804150095 Notice of consideration of issuance of amond to License DPR-45 & portunity for hearing Amend revises physical security plan guard force training & quification plan & safeguards contingency plan for LACBWR. ERICKSON.P.B. Stenderdization & Non-Power Reactor Project Directorate. 88/03/5pp. 45133:201-45133:205.

8804250135 Responds to 880128 & 0219 requests for additinfo re plant emerger plan & forwards Rev 10 to plan Map of LACBWR site delining emergency plant zone will be added to emergency plane as Figure A-2 on Page A-15.

TAYLORJ.W. Dairyland Power Cooperative. 88/04/15. Document Control Brad (Document Control Desk). 6pp. 45230:326-45231:070.

I. Financial information

8804250128 Forwards annual financial rept & celtified financial statements for 1986 1987 Annual rept for 1987 will be forwarded as soon as possible. MUELLER,R.C. Delryland Power Cooperative. 88704/18. Document Control Brai (Document Control Desk). 17pp. 45237.093-45237;106.

P. Operating license stage documents & correspondence

8803240426 Generic Ltr 68-06 to all power reactor licensees & applicants re remova organization charts from Tech Spec administrative control requirements Svc list 6 MRAGLIAF.J. Associate Director for Projects (Post 8704.11). 88/03/22. Conso^{rdal} Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.

8804080104 Forwards revised Rev 5 to QA program description for possession of condition Revised pages reflect recent organizational change. TAYLOR,JW. Oalryland Power Cooperative, 88/03/28, Document Control Bra (Document Control Desk), 4pp. 45118:192-45118,221.

--8804080108 Revised Rev 5 to "OA Program Description." TAYLOR,J.W. Dailyland Power Cooperative, 87/10/20, 42pp, 45116:196-45116.22

- 8804040265 Requests FR publication of notice of consideration of issuance of amond to License DPR-45 & proposed NSHC determination & opportunity for hearing on 870930 request re-removal of requirements for operational conditions. RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate 88/03/29, NRC No Detailed Affiliation Given, 5pp. 44972 234-44972 238.
- 8804190071 Forwards updated decomm.ss:oning table for program implementation replinto on stendardization design reviews has been provided to S Black RUBENSTEINLLS Stendardization & Non-Power Reactor Project Directorate 88/03/30 VILLAFRANCO,V. Program Managament, Policy Development & Analysis Staff (Post 870411) 3pp 45158:285 45158:287
- 8804180452 Forwards notice of consideration of issuance of amends & opportunity for hearing (decommissioning plan & safstor Tech Spec).
 ERICKSON,P.B. Standardzation & Non-Power Reactor Project Directorate. 88/04/01.
 TAYLOR,J.W. Daryland Power Cooperative, 3pp 45149:314-45140.329.
- -8604180458 Notice of consideration of issuance of amend to License DPR-45 & proposed NSHC determination & opportunity for hearing. Amend involves approval of LACEWR decommissioning plan & Tech Specs & extension of License DPR-45 ERICKSON, P.B. Standardization & Non-Power Reactor Project Directorate, 88/04/01, 8pp. 45149.317-45149.329.
- 8804080098 Generic Ltr 88-07 to power reactor Leensees & applicants re-modified en-forcement policy concorning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Syc list end MIRACLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164.237-45164:285.
- 8804180296 Requests FR publication of notice of issuance of Amend 60 to License DFR-45.Amend revises Tech Specs to reduce required shift crew size since reactor permanently shufdown & fuel removed to fuel element storage well. RUBENSTEINLS. Standardization & Non-Power Reactor Project Directorate. 88/04/ 11. NRC - No Detailed Affiliation Given, 3pp. 45179:219-45179 221.
- 8804190184 Forwards Amend 60 to provisional License DPR-45 & safety evaluation Amend revises Toch Specs in response to 871112 application as revised on 880129 Environ assessment also encl. ERICKSON,P.B. Standardization & Non-Power Reactor Project Directorate 88/04/11. TAYLOR,J.W. Dairyland Power Cooperative. 3pp. 45165:311-45165-323.
- --8804190187 Amend 60 to provisional License DPR-45,revising Toch Specs in response to 871112 & 880129 application HUBENSTEIN, L.S. Standardzation & Non-Power Reactor Project Directorate, 88/04/11, 5pp. 45165/314-46165/318.
- 8804190190 Safety evaluation supporting Amend 60 to provisional License DPR-45.
 Office of Nuclear Reactor Regulation, Director (Post 670411). 86/04/11. 3pp. 45165:319-45165:321.
- --8804190208 Environ assessment & finding of no significant impact re revite Tech Specs to reduce required crew size EIS unwarrented. EHICKSON,P.B. Standardization & Non-Power Reactor Project Directorate. 88/03/31. 2pp. 45165:322-45165-323.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87:044, "Thimble Tube Timning In Westinghouse Reactors" Svc list encl.
 HOSSI,GE Division of Operational Events Assessment (Post 870411), 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44985:126:44995:246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees:Lack of Mgt Controls Over Licensed Programs " Svc list encl.
 CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 88/
 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995.247-44995;353.
- 8804130370 Discussos NRC Bulletin 88-003 re inadequate latch engagement in HFA type latching relays mig by GE Six types of relays installed at LACBWR are Type 12HFA151A9H. TAYLOR,J.W. Dairyland Power Cooperative, 88/03/30, DAVIS,AB Region 3, Old of the Director, 2pp. 45122-136-45122;137.
- 8804140436 Forwards Safety Insp Hept 50-409/88.03 on 880207-0320. Violation involving failure to maintain min shift crew composition noted Rosponse addressing tack of attention to responsibilities & controls to prevent recurrence requested. GREENMAN,E.G. Region 3, Otc of the Ofrector. 88/04/05. TAYLOR,J.W. Dairyland Power Cooperative. 2pp. 45170.021-45170:029.
- --8804140449 Insp Rept 50:409/88:03 on 880207-0320. Violation noted Major areas Inspected operatronal safety, maint, surveillance & surveillance procedures & secords, LERs, bulletins, special repts & organization & administration JACKIW, I.N. Region 3, Ofc of the Director. 88/04/01. 7pp. 45170:023-45170.029.
- 8804010256 NRC Into Notice 88:011, "Potential Loss of Motor Control Ctr &/or Sw.tch-board Function Due to Faulty Tie Bolts." Svc list and. ROSSI, CE. Division of Operational Events. Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407:051.
- 8804060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings," Svc list enc.1 ROSSI, C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150.

V. Operator Examinations

- 8804250088 Responds to FOIA request for info re accres of reactor operators & senior reactor operators. Forwards requalification exam summary source sheets listed in encl. app w/personal privacy into deleted. GHIMSLEV.D.H. Division of Rules & Records (Post 870413). 88/04/19. BOLEY,K. Public Critzen's Critical Mass Energy Project. 2pp. 45213.003-45213.095.
- ~8804250167 Package of NRC administered requalification exam results summary. *NRC No Detailed Affiliation Given, 87/07/20, 88pp. 45213:007-45213:095.

DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8804260415 Revised emergency plan implementing procedures including Rev 9 to EPP-17, "Communication Procedures," Rev 8 to EAP-1, "Activation 8 Direction of Emergency Plans" 8 Rev 9 to EAP-2, "Classification of Emergency..." W/880420 tr. GORDON,E.C., ROMAN, T.W., ABBOT,R.B. Niagara Mohawk Power Corp. 88/04/20 70pp. 45224:199-45224:325.
- 8804270118 Rev 9 to EPP-17. "Communication Procedure," Rev 8 to EAP-1, "Activation & Direction of Emergency Plans" & Rev 9 to EAP-2, "Classification of Emergency Conditions." W/880420 lfr.
 MANGAN,C.V. Niagara Mohawk Power Corp 88/04/20 127p 45241:248-45242.014.

H. General correspondence

- 8804060382 Provides Info re proposed reorganization.per discussion at 880107 meeting. Ultimate organization will refocate vice prosident nuclear generation to site. Tech Spec change request to amend affected sections will be schmilled. Whenci MANGAN, C.V. N agars Mohawik Power Corp. 88/03/21. Decument Control Branch (Document Control Desk). 3pp. 45007-018-45007-021.
- 8804270198 Informs of organizational changes within facility effective 880401 MANGAN,C,V. Niagara Mohawk Power Corp. 88/04/19. Document Control Branch (Document Control Desk). 1p. 45244.273-45244.273

I. Financial information

8804200253 "Niagara Mohawk Power Corp Annuel Rept 1987" W/880406 lir. HAEHL,J.G., DONLON,W.J., PERKINS,T.J. Niagara Mohawk Power Corp. 87/12/31. 41pp. 45176.061-45178:101.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8804140215 Submits summary of actions discussed at ACRS 335th meeting on 880310-12 In Washington,DC,Including ACRS repts/ recommendations,other actions,agreements,assignments & requests & luture agenda KERR,W. ACRS - Advisory Committee on Reactor Safoguards 88/03/24. ZECH,L.W. Commissioners. 4pp. 45118:172-45118:175

P. Operating license stage documents & correspondence

- 8803080248 Forwards Amend 2 to License NPF-69.Amend revises allowable value & isolation trip setpoint for RCIC high steam line flow in Table 3.3 2-2 of Tech Specs. HAUGHEY,M.F. Project Directorate +1 88/02/26. MANGAN,C.V. Niegara Mohawk Power Corp. 3pp. 44633:331-44633:337
- --8803080255 Amend 2 to License NPF-69, revising allowable value & isolation trip set-point for RCIC high steam line flow in Table 3.3.2-2 of Tach Specs CAPRA,R.A. Project Directorate I-1. 88/02/28, 4pp. 44633.334-44633.337
- 6803240426 Generic Ltr 88-06 to all power reactor fromsees & applicants re-removal of organization charts from Tech Spec administrative control requirements Svc list end. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972-107-44972:153.
- 6604110194 Forwards Rev 1 to Inservice testing program Incorporating 880223 interim & editorial changes

 MANGAN,C.V. Niagara Mohawk Power Corp. 88/03/31. Document Control Branch
 (Document Control Desk). 1p. 45121.135.45122:005.
- -9804110198 Rev 1 to Inservice testing program.
 Niagara Mohawk Power Corp. 88/03/31 227pp. 45122 001-45122 005
- 8804140193 Provides listed into requested in 880225 ltr re operating nuclear power units located at twelve altes along Great Lakes STELLO,V. Official the Executive Director for Operations, 88/04/08 RIDGE,T. House of Rep. 5pp. 46104;138-45104;143.
- 8604080088 Generic Ltr 88-07 to powor reactor licensoes & applicants re-modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc list oncl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184 237-45164:285.
- 8804190063 Forwards Amend 4 to License NPF-69 & safety evaluation Amend revises allowable value & Isolation trip setpoint for RHR/RCIC steam Inc high flow in Tech Specs Table 3.3.2-2. HAUGHEY,M.F. Project Oirectorate 1-1, 88/04/11, MANGAN,C.V. Niagara Mohawk Power Corp. 2pp. 45158:277-45168.284.
- --8804190076 Amend 4 to License NPF-69 changing Tech Specs to revise allowable value 8 isolation trip setpoint for RHR/RCIC steam tine flow-high in Table 3 3 2-2. CAPRA,R.A. Project Directorate I-1. 88/04/11, 4pp. 45158:279-45158:282.
- --8804190084 Safety evaluation supporting Amend 4 to License NPF-69 * Project Directorate I-1, 86/04/11, 2pp. 46158:283-45158:284.
- 8804190235 Forwards Amend 3 to License NPF-69, changing Tech Specs to revise svc water supply header discharge temp limit to 81 F. HAUGHEY, M.F. Project Directorals 1-1, 88/04/11. MANGAN, C.V. Niegara Mohawk Power Corp. 2pp. 45165:349-45165:354.
- **8804190241 Amend 3 to License NPF-59, revising evolvater supply header discharge temp limit in Tech Spec 3/4.7.1 to 81 F. CAPRA,R.A. Project Directorate I-1. 88/04/11. 7pp. 45165.342-45165.348.

Office of Nuclear Reactor Regulation, Director (Post 870411) 88704711. 6pp 45165 349-45165 354

8804210003 Forwards revised page to FSAR Chapter 14 re change in Initial startup test program & GE 880304 ftr that provides basis & justification for change Change made to page from existing FSAR updated through Amerid 28. MANGAN, CV. Niagara Mohask Power Corp. 88/04/14 Document Control Branch (Occument Control Desk). 3pp. 45226-282-45226-284.

8804220014 Grants relief for use of ASME Code Case N.415 for inservice testing program per util 880108 request Code Case will be used for testing relief valves,safety values 8 rupture discs in pump 8 valve testing program CAPRAR A Project Directorate 1-1. 88/04/14 MANGAN,C.V. Niagara Mohawk Power Corp. 4pp 45200 270-45200:273

8804280036 Forwards Amend 5 to License NPF-69 & safety evaluation. Amend revises Tech Spec 3/4 4 8 2.1 b 2, "DC Sources: Operating," to allow alternate method of determining battery operability when visible corrosion appears. HAUGHEY,M.F. Project Directorate 1-1, 88/04/19, MANGAN,C.V. Niegera Mohawk Power Corp. 2pp. 45263.088-45263.096.

--8804280046 Amend 5 to License NFF-69, revising Tech Spec 3/4.4.8.2.1.b.2, "DC Sources-Operating," to allow alternate method of determining battery operability when visible concision appears at terminals or connectors.

CAPRA, F.A. Project Directorate 1-1, 88/04/19, 4pp. 45263:090-45263:093.

--8804280049 Safety evaluation supporting Amend 5 to License NPF-69.

' Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/19 3pp. 45263 094-45263.096.

8804270167 Informs that 100-h warranty run for plant completed & Rev 3 to QA topical rept governing QA program for facility.

MANGAN,C.V. Nagara Mohawk Power Corp. 88/04/20. Document Control Branch (Document Control Desk). 1p. 45245-284-45245-284

Q. Inspection reports, IE Bulletins & correspondence

8804120362 Notification of Licensee Meeting 98-027 on 880318 in King of Prussis,PA re NRC Otc of Investigations Rept I 85-020 findings involving validity of info concerning neutron monitoring systeable installations Agenda encl JOHNSON,J Region 1, Otc of the Director. 88/02/23 Region 1, Otc of the Director. 2pp 45079 281-45079 283.

8804130109 Notification of 880328 meeting w/util at Region I ofc to discuss regional evaluation phase of SALP.

JOHNSON,J. Region 1, Otc of the Director 88/03/22. Region 1, Otc of the Director. 2pp 45122:221-45122 222.

8804040019 Confirms dates of 880418-22 for NRC Environ Qualification hasp 50-4107 88-08 per 880309 telcon Listed documents required 2 wks prior to insp. JOHNSTON,W.V. Region 1, Olic of the Director, 88/03/23, MANGAN,C.V. Niegara Mohawk Power Corp 3pp. 45020 284-45020 286.

8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors." Svc I st end. ROSSICE Division of Operational Events Assassment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44895;126-44995;246.

8803220295 NRC Info Notice 88-010, "Mattls Licensees Lack of MgI Controls Over Li-censed Programs" Svc list enci CUNNINGHAMR E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44985:353.

8804040158 Provides response to NRC Bulletin 88-001 re dofects in Westinghouse DS sones circuit breakers No Westinghouse sories DS circuit breakers used in any applications at Unit 2,therefore bulletin not applicable MANGAN.C.V. Niagara Mohawk Power Corp. 88/03/28 Document Control Branch (Document Control Desk), 2pp. 45031:318-45031:320

8804110273 Discusses util 870914 response to IE Buttetin 87-001, "Thinning of Pipe Walls at Nuclear Power Plants," Info being used to determine extent of industry participation 8 implementation of erosion/corrosion insp programs. HAUGHEY,M.F. Project Directorate 1-1, 88/04/04, MANGAN,C.V. Niagara Mohawk Power Corp. 3pp. 45078:358-45078.360.

8804120315 Forwards Radiological Controls Insp Repts 50-220/88-04 & 50-410/88-05 & notice of violation.

8 Notice of violation.

8 ELLAMY,R.R. Region 1, Ofc of the Director. 88/04/04. MANGAN,C.V. Niagara Mohawk Power Corp. 2pp 45128:123-45129,142.

-8804120327 Insp Repts 50-220/88-04 & 50-410/88-05 on 880215-19.No violations noted Major areas inspected licensee radiological controls during Unit 1 ounage & during routine operations at Unit 2,ncfuding organization, staffling & training NIMITZ.R.L. SHANBAKY.M.M. Region 1, Ofc of the Director. 88/04/01. 17pp. 45129 126 45 129 142

8804010256 NHC Info Notice 68-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svc list encl. ROSSICE: Division of Operational Events. Assessment (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407 051.

880420095 Forwards request for additinione but 880512 & 870218 & 1112 submittals in response to IE Butletin 85-003, "Motor Operated Valve Common Mode Failures During Plant Transients Due to Improper Switch....." for response within 1 month WENZINGER,E.C. Region 1, Ofc. of the Director. 88/04/11, MANGAN.C.V. Nagara Mohawk Power Corp. 4pp. 45218 223-45218 226.

8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc ist eacl. ROSSICE: Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150.

8604250144 Forwards Enforcement Conference Rept Of 85-022 on 860318
WENZINGER, E.C. Region 1, Ofc of the Director, 88/04/18, DONLON, W.J. Niagara
Mohawk Power Corp. 2pp. 45234:317-45234:347.

Bleaz Maggidateo autoniano capaez or due ità mer biofissi, a comme cercu ce c encies. JOHNSON,J R. Region 1, Ofc of the Director 88/04/12, 19pp, 45234:319-45234:343

R. Periodic operating reports & related correspondence

8804130166 Monthly operating rept for Mar 1988 W/880408 ltr.

TOMLINSON,E., PERKINS,T.J. Niagara Mohawk Power Corp. 88/03/31 27pc 45142:212-45142:238.

S. Reportable occurrences, LERs & related correspondence

8803290379 LER 87-024-01:on 870517 & 27, sensed low air flow condition in refueing floor main exhaust duct & below refueling floor main exhaust caused actuation of ESF. Caused by excessively conservative trip set points for flow switches W/880324 LEMPGES, T.E. Niagara Mohawk Power Corp. 88/03/24 6pp 44975 252-44975 257.

8803290401 LER 88:010:00:on 880212,missed surveillance dud to personnel error resulting in Tech Spec violation. Required surveillance performed & total core exposural effective 120 days or less verified W/880324 ltr.

JENKINS.R.E., LEMPGES.T.E. Niagara Mohawk Power Corp 88/03/24 Spp 44975.190-44975.194.

8804040199 LER 88-011-00 on 880301.ESF actuation occurred Caused by detective trip/calibr unit (equipment failure) generating spurious trip signals Isolation cooling systematic inoperable & Inp/calibr unit pulled.W/860328 inp/calibr. JENKINS.R.E. LEMPGES.T.E. Niagara Mohawk Power Corp. 88/03/28 5pp 45077.255-45077:259.

8804070282 LER 88-012-00.on 880305.actuation of several ESF's occurred during per-formance of generator load rejection test Causod by design deficiency Mod PN2Y88MX014 implemented to separate primary & backup protective relaying packages W/880331 ltr. JENKINS.FI.E., LEMPGES,T.E. Niagara Mohawk Powur Corp. 88/03/31 6pp. 45021:167-45021:172

8804070309 LER 88-013-00 on 880306,Tech Spoc surverlance requirement for pres-sure/temp limits for RCS missed Caused by cognitive personnel error & contributing procedural deficiency. Operator counseled & procedure revised.W/880331 ltr. JENKINS,R.E., LEMPGES,T.E. Niagara Mohawk Power Corp. 88/03/31, 5pp 45021.211-45021.215.

8804190038 LER 88-014-00 on 880313 reactor scram & ESF actuations occurred Caused by equipment failure due to design deficiency. Transmitter replaced w/upgraded model & temporary mod performed to bypass logic for valves W/980412 JENKINS.R.E., PERKINS.T.J. Niagara Mohawk Powor Corp. 88/04/12 939. 45215-220-45215-228.

8804190067 Forwards special reptire reactor scram & ECCS actuation included as part of LER 89-14.
PERKINS,T J. Niagara Mohawk Power Corp. 88/04/12. RUSSELL,W.T. Region 1. O'c of the Director. 1p. 45199-083-45199-081

8804200294 LER 88-016-00:on 880318.primary containment incrted by nitrogen purge w/o obtaining sample analysis & purge rate. Caused by procedural disciency. Procedural revised to require sample analysis & purge rate before purging. W/880415 lir.

JENKINS.H.E. PERKINS.P.J. Nlagara Mohawk Power Corp. 88/04/15 5pp 45221:057-45221 081

V. Operator Examinations

8804250088 Responds to FOIA request for info re-scores of reactor operators & senior reactor operators Forwards requalification exam summary sources should listed in end app w/personal privacy into deleted.

GHIMSLEY.DH. Division of Rules & Records (Post 870413). 88/04/19 BOLEY.K.

Public Cilizen's Critical Mass Energy Project. 2pp. 45213.003-45213.095.

-9804250187 Package of NRC administered requalification exam results summary
 NRC - No Detailed Affiliation Given: 87/07/20, 88pp. 45213-007-45213-095.

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8804280464 Approves request for exception to location requirement for technical support center (TSC) & refraction of commitment to provide alternate TSC near control room. Stated emergency preparedness inspirept also reviewed TAM.P.S. Project Directorate 1-4. 88/04/20, SIEBER, J.D. Duquesne Light Co. 2pp. 45263 032-45263 033.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8804 140215 Submits summary of actions discussed at ACRS 335th meeting on 880310-12 in Washington, DC, including ACRS repts/ recommendations other actions, agreements, assignments & inquests & future agenda. KERR,W. ACRS - Advisory Committee on Reactor Safeguards 88703/24, ZECH, L.W. Commissioners, 4pp. 45118-172-45118:175.

erating license stage documents & correspondence

240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of anization charts from Tech Spec administrative control requirements Svc list encl (AGLIA,F. J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated son Co. of Now York, Inc. 47pp. 44972-107-44972.153.

070110 Forwards response to draft technical evaluation rept on Generic Ltr 83-liem 1.2 per NRC 860722 request BERJ D. Duquesna Light Co. 88703722. Document Control Branch (Document lifol Desk), 6pp. 45044:137-45044:142.

010211 Forwards 801224 correspondence re altogations of inadequate stress anal-s performed by contractor.Review of circumstances surrounding document & rept indings & conclusions requested within 30 days of lit receipt SGINS, J. T. Region 1, Ofc of the Director 88/03/23 SIEBER, J.D. Dirquesno Light 3pp. 45058-091-45058-093.

010129 Informs that listed commitments made in 880303 response to Generic Ltr 03, "Hosolution of Genoric Safety Issue 93, Steam Binding of Auxillary Feedwater nps" responsive to guidance of generic tir MP.S. Project Directorate 1-4, 88/03/28. SIEBER, J.D. Duquesne Light Co. 2pp. 121-356-44921-357.

(30130 Advises that Crano-Demony Co no longer accepting new orders for Model 9 chemical injection pumps but product line will be available from another dor, Gorman Rupp, Inc.w/o "N" stamp certification. BERJ, JD. Duquesne Light Co. 80/03/28. Document Control Branch (Document Intol Desk). 2pp. 45099-342-45099.343

140340 FOIA request for correspondence between NRC & Duquesno Light Co re Ciriquiry into 801224 memo by B Gupla to C McCullough concerning work done Schnoider, Inc at plant. ELIS,M. Pittsburgh Press Pittsburgh, PA 88/03/28. Office of Administration & Reuces Management, Director (Post 870413). 1p. 45118-047-45118-047.

380088 Genoric Ltr 88-07 to power reactor licensees & applicants re-modified en-tement policy concerning 10CFRS0.49, "Environ Qualification of Electrical Equip-torial Environment to Safety for Nuclear Power Plants" "Svc list encl. Associate Director for Projects (Post 870411), 88/04/07, Consolidated son Co. of New York, Inc. 48pp. 45164:237-45164:285.

210359 Notification of 880421 meeting w/util in Rockville,MD to discuss status of

rent active licensing actions. M.P.S. Project Directorate 1-4. 88/04/18, MURLEY,T., SNIEZEK,J., MIRAGLIA,F. C - No Detailed Affillation Given 3pp 45192:094-45192.096.

280464 Approves request for exception to location requirement for technical sup-ticenter (TSC) & retraction of commitment to provide alternate TSC near control m Stated emergency proparedness insp roph also reviewed MPS_Project_Directorate 1-4, 88/04/20. SIEBER, J.D. Duquesne Light Co. 2pp.

63,032-45263:033

spection reports, IE Bulletins & correspondence

210090 Suppl 1 to NRC Into Notice 87:044, "Thimble Tube Thinning in Westing-ise Reactors." Svc hat enct. SSI,C E. Division of Operational Events Assossment (Post 870411), 88/03/28. isolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995;246.

220298 NRC Info Natice 88-010, "Malls Liconsons:Lack of Mgt Controls Over Li-sed Programs." Svc list anct. NNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729). 887 '28 Consolidated Edison Co. of New York, Inc. 108pp. 44095:247-44995.353

130257 Forwards response to NRC Bulletin 88:002, "Rapidly Propagating Fatigueicks in Steam Generator Tubes." Evaluation addressing Items C.2.a & C.2.b will be imitted by 880531.
BERAJD. Duquesne Light Co. 88/03/28, Document Control Branch (Document Intol Desk), 8pp. 45154:161-45154:168.

010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-ard Function Oue to Faulty Tio Bolts." Svc list anct. SSI,C.E. Division of Operational Events. Assessment (Post. 870411), 88/04/07. nsolidated Edison Co. of New York, Inc. 124pp. 45408:292-45407:051.

200040 Forwards Salety Insp Repts 50:334/88-00 & 50:412/88-05 on 880222-26

oblice of violation.
LLAMY,R.R. Region 1, Ofc of the Director, 88/04/08 CAREY,J.J. Duquesne Light
3pp. 45235.056-45235-068.

4200046 Insp. Ropts 50-334/88-09 & 50-412/88-05 on 880222-26. Violations ed.Major areas inspected liconsee solid radwaste & transportation program including control, shipmonts of rad oactive metis, training & procedures. VIDSONESS, PASCIAK,W.J. Region 1, Olc of the Director. 88/04/04. 9pp. 235 060 45235 068

110257 FOIA request for D Beckman employment dates as NRC resident inspector

plant. ATOS,B. Pittsburgh Press Pittsburgh PA, 88/04/11, NRC - No Detailed Affiliation en. 1p. 45078:171-45078:171.

060370 NRC Info Notice 88:012, "Overgreasing of Electric Motor Bearings" Svc

enci. PSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. asolidated Edison Co. of New York, Inc. 123pp. 45165 028-45165:150.

250374 Forwards "Preservice Insp Summary Rept,1985-1988." Preservice exams appleted on 880201.Listing of preservice Insp rolled requests for code required sms included in rept. BER.J.D. Duquesne Light Co. B8/04/18. Document Control Branch (Document ntrol Desk). 1p. 45253.072-45253:287.

4260377 "Preservice Insp Summary Rept, Beaver Valley Power Station Unit 2,1985-

/ING,C.E. Duquesne Light Co. 88/03/31, 275pp. 45253:073-45253:287.

8804280116 Requests listed into in order to resolve remaining concerns re 880128 event involving annunclator cabinet fire per 880303 meeting & Safety Insp Rept 50-412/86-03 Response requested within 45 days of ltr receipt TAM_PS. Project Directorate I-4. 88/04/18 SIEBEH.J.D. Duquesno Light Co. 2pp. 45263.030-45263-031.

8804280484 Approves request for exception to location requirement for technical support center (TSC) & retraction of commitment to provide afternate TSC near control room Stated emergency preparedness inspiring talso reviewed TAMP, P. Project Directorate I-4 88/04/20. SIEBER, J.O. Duquesne Light Co. 2pp. 45263 032-45263 033

R. Periodic operating reports & related correspondence

8804260349 "1987 Rept of Facility Changes, Tests & Experiments " W/880408 ltr SIEBER, J D Duquesne Light Co. 87/12/31, 69pp 45252.325-45253.033.

8804060095 "NPDES Monthly Discharge Monitoring Rept for Feb 1988." W/ 860328 ltr. DRUGA,R J. Duquesne Light Co. 88/02/28. VARGA,S. Office of Nuclear Reactor Regulation, Director (Post 870411) 21pp. 45046.176-45046.196.

8804040058 Forwards monthly operating repts for Feb 1988 & revised monthly operating rept for Jan 1988, consisting of revised unit shutdown & power reduction sheet SIEBER, J.D. Duguesne Light Co. 88/03/10. NRC - No Detailed Affitiation Given. 1p 44921:318-44921:327.

--8803300320 Monthly operating ropts for Feb 1988. WINGER,M A. Duquesne Light Co. 88/02/29 8pp 44921:319-44921 326.

--8804040064 Revised monthly operating ropt for Jan 1988. WINGER,M A. Duquesne Light Co. 88/01/31. 1p. 44921:327-44921.327.

8804190036 Monthly operating repts for Mar 1988.W/880413 ftr. WINGER,M.A., SIEBER,J.D. Duquinsne Light Co. 88/03/31. 10pp 45208.237-45208.246.

S. Reportable occurrences, LERs & related correspondence

8804130091 LER 87-032-01 on 871024 reactor trip occurred on to to steam generator level Caused by elevated pressure in high pressure turbine. Plant stabilized by using reactor trip response procedure W/880404 trip response procedure W/880404 trip response procedure W/880404 trip response trip NOONAN, T.P. Duquesne Light Co. 87/11/23, 8pp. 45151:047-45151:052

8803290304 LER 87-033-01 on 871028, operator noticed performance frequency changed from quarterly to monthly Caused by personnel error. Procedure writers instructed to notify scheduler of test changes W/880303 ltr. NOONAN, T.P. Duquesne Light Co. 88/03/03. 4pp 44975-218-44975-221.

DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8803290266 Forwards Insp Repts 50-413/88-11 & 50-414/88-11 on 880216-18.No vio-lations or deviations noted CLINE,W.E. Region 2, Otc of the Director. 88/03/03. TUCKER,H.B. Duke Power Co. 2pp. 44921:141-44921:143.

--8803290269 Partially withheld insp Repts 50-413/88-11 & 50-414/88-11 on 880216-18 (rol 10CFR2.790(d) & 73.21) No violations or deviations noted Mejor areas inspected procedures, records & operations for control & accountability of SNM. TODD,G.A., SEYMOUR.D.A., MCALPINE.E.J. Region 2, Ofc of the Director. 88/03/01. 1p. 44921:143-44921:143.

8803280123 Forwards Insp Repts 50-413/88-03 & 50-414/88-03 on 880217-21.No vio-lations or deviations noted Corrective actions discussed & agreed to via oral commitment from licensee representatives. STOHR,J.P. Region 2, Oic of the Director 88/03/14. TUCKER,H.B. Duke Power Co. 2pp. 44921:063-44921:078.

--8803280132 Insp Repts 50-413/88-03 & 50-414/88-03 on 880217-21. No violations noted Major areas inspected observation of annual emergency exercise. Weaknesses noted failure to meet exercise objectives in area of emergency mgt & accident assess-THERT. SARTOR,W.M., DECKER,T.R. Region 2, Old of the Director, 88/03/10, 14pp. 44921,065-44921-078.

8804110117 Forwards Rev 19 to plant security plan Rev delotes soveral redundant sections from security plan & revises list of vital equipment.Rev withhold (ref 10CFR73.2.1).
TUCKER,H.B. Duke Power Co. 88/04/01. Document Control Branch (Document Control Desk). 2pp. 45135.278.45135.279.

8804150423 Notilies that changes contained in Rev 10 of emergency plan consistent w/planning stds of 10CFR50.47(b) & requirements of 10CFR50.App E. COLLINS,D.M. Region 2, Ofc of the Director. 88/04/07. TUCKER,H.B. Duke Power Co. 1p. 45138-334-45138.334.

8804150038 Forwards Amends 43 & 38 to Licenses NPF-35 & NPF-52, respectively & safety ovaluation. Amends modify Paragraphs 2.E of Icenses to require compliance w/ amended physical security plan.
JARBOURK. Project Directorate II:3 88/04/11. TUCKER, H.B. Duke Power Co. 3pp. 45139.083-45139:104.

--8804150066 Amends 43 & 36 to Licenses NPF-35 & NPF-52,respectively, modifying Paragraphs 2.E of licenses to require compliance w/amended physical security plan. CROCKER,L. Project Directorate il-3, 88/04/11, 4pp. 45139.036-45139.099.

-- 8804150070 Safeguards evaluation rept supporting Amends 43 & 36 to Licenses NPF -35 & NPF-52 respectively.
* NRC - No Detailed Affiliation Given, 88/04/11, 3pp. 45139:100-45139:102.

- -8804150.199 Hequesis FH publication of notice of issuance of amends 4.3 & 50 to Universe NPF-358 NPF-52, respectively. Amends modified Paragraphs 2.8 of ficenses to require compliance whamended physical security plan.

 JABBOURK, Project Directorate II-3 88/04/11, NRC No Detailed Affiliation Given 2pp. 45130.103-45139.104
- 8804200473 Partial response to FOIA request re fire protection Forwards App E documents App D & E documents available in PDR App F document completely with tield (ref FOIA Exemption 5).
 GRIMSLEY,D H Division of Rules & Records (Post 870413). 88/04/14. JONES,C R. Affiliation Not Assigned. 5pp. 45206:037-45206:043.
- --8804200679 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50,App R-type rinsplit of each facility to assess status of compliance w/ 10CFR50,48.Program listed CONLON,T.E. Region 2, Old of the Director, 847±1/05, HERDT,A.R. Region 2, Old of the Director 3pp. 45208-176-45208,178.

P. Operating license stage documents & correspondence

- 8710270289 Forwards proprietary DPC-NE-2000, "DCHF-1 Coue*etion for Predicting Chical Heat Flux in Mixing Vane Grid Fuel Assembles." Rept submitted to obtain approval to use DCHF-1 correlation Fee paid Rept withheld (ref 10CFR2.790). TUCKER,H.B. Duke Power Co. 87/10/21. Document Control Branch (Document Control Desk) 6pp. 43177:210-43177.215
- 8803290097 Forwards Rev 7 to util 830414 response to Suppl 1 to NUREG-0737 including solutions to human engineering discrepancies
 TUCKER,H.B. Duke Power Co. 88/03/15. Document Control Branch (Document Control Desk), 13pp. 44945/237-44945/249
- 8803240426 Generic Ltr 68-06 to a'l power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIAF J. Associate Director for Projects (Post 970411), 88/03/22. Consolidated Edison Co. cf New York, Inc. 47pp. 44972:107-44972:153.
- 8803300263 Application for amends to Licenses NPF-35 & NPF-52,adding Tech Specific requirements for monitor tank bridg sys & components Fee gald.

 TUCKER,H B, Duke Power Co. 68/03/23. Document Control Branch (Document Control Desk). 4pp. 44961:084-44961:107.
- 8803300267 Proposed Tech Specs, adding requirements for operation of monitor tank bldg sys & components.
 * Duke Power Co. 88/03/23, 20pp, 44961.088-44961:107
- 8804010042 Forwards listing of outstanding Items.per discussion w/NRC re util ongoing program of radicing backlog of outstanding Items.W/o encl. BROWNLEE.V.L. Region 2, 0.0c. of the Director, 86/03/23, TUCKER,H.B. Duke Power Co. 1p. 45031;171-45031;171.
- 8804010045 Confirms concurrence w/intention to restart facility following completion of corrective action re-880309 tnp & subsequent swap-over of auxiliary feedwaler sys flow
- GRACEJ N. Region 2, Ofc of the Director, 68/09/23, TUCKER,H.B. Duke Power Co. 1p. 45010 001-45010;001.
- 8804120317 Expresses appreciation for time that members took to present outline of ISAP II program per Generic Ltr 88-02 requesting ticensee to ovaluate NRC latest row & indicate whether interested in participating in program. TUGKER,H.8. Duke Power Co. 88/03/25. Document Control Desk). 2pp. 45091;142-45091;143.
- 8804120069 Advises that revised analysis justifying less restrictive action statement for steam generator PORV & Tech Spec change will be submitted by 880516,per util 871204 application for amends to Licenses NPF-35 & NPF-52. TUCKER,H.B. Duke Power Co. 88703/29. Document Control Branch (Document Control Desk), 1p. 45135/313.45135:313.
- 8604180447 Forwards updated pages to proprietary BAW-10171P, "REFLOD3B- Model for Multinode Core Reflooding Analysis," per ECCS methodology for facilities reloads Mod removes Henry quench temp criteria & potential conflict in logic.Pages
- TAYLOR, J.H. Babcock & Wilcox Co. 88/03/29, NORBERG, J.A. Division of Engineering & Systems Technology (Post 870411), 2pp. 45207:232-45207:233.
- 8804120036 Provides addI info to util 870629 & 1204 requests to delete requirement to verify reactor temp detector bypass loop flow on 18-month basis from Tech Spec Table 4.3-1,1tem 7, TUCKER,H B, Duke Power Co. 88/04/01. Document Control Branch (Document Control Desk). 2pp. 45154 059-45154;080.
- 8804130406 Application for amends to Licenses NPF-9,NPF-17,NPF-35 & NPF-52;changing Tech Specs to allow credit to be taken for Radiation Monitor EMF-36 if EMF-39 inoperable below Mode 4 (hot shutdown), Fee paid.
 TUCKER, HB. Duke Power Co. 88/04/01, Document Control Brench (Document Control Desk), 4pp. 45132:299-45132:324.
- ••8804130410 Proposed Tech Specs allowing credit to be taken for Radiation Monitor EMF-38 (unit vent monitor) if EMF-39 (on containment purge sys) Inoperable below Mode 4 (hot shutdown).
 * Duke Power Co. 88/04/01, 22pp. 45132.303-45132.324.
- 8804210282 Revised application for amends to Licenses NPF-9,NPF-17, NPF-35 & NPF-52 re luel assemblies.Proposed amends broaden scope of mods allowed to fuel assemblies involving fuel rod locations & delete max fuel rod U limit. TUCKER,H.B. Duke Power Co. 88/04/01. Document Control Branch (Document Control Desk). 4pp. 45239:029-45239.041.
- -8804210287 Proposed Tech Specs,broadening scope of mods allowed to fuel assembles involving fuel rod locations & delete specified max total fuel rod U weight limit.

 * Duke Power Co. 88/04/01. 9pp. 45238.033-45239.041.
- 8804110297 Forwards Rev 8 to response to Suppl 1 to NUREG-0737, Including revised writers guide for emergency & abnormal procedures for facility App 2, "Abnormal Procedure Outline," not included & will be updated & provided in subsequent rev. TUCKER,H.B., Duke Power Ca. 88/04/05. Document Control Branch (Occument Control Oesk), 2pp. 45135:109-45135:222.

- i i ir juu nev o LI II II I IUIMai Fiocedures * Duke Power Co. 88/03/09, 112pp. 45135:111-45135:222.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment important to Safety for Nuclear Power Plants." Svc list and. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164.285.
- 8804130309 Forwards request for addl info ro Topical Rept WCAP-10988, "COBRA-NC,Analysis for Main Steam Line Break in Ice Condenser Containment." Response requested within 45 days from Itr date.

 JABBOUR, K.N. Project Directorate II-3. 88/04/07. TUCKER,H.B. Duke Power Co. 6ρρ. 45103:166-45103:171.
- 8804190056 Application for amonds to Licenses NPF-35,NPF-52,NPF-9 & NPF-17, changing required surveillance interval for ice condenser lower inlat doors from current frequencies to 100% insp. every 18 months.

 TUCKER,H.B. Duke Power Co. 88/04/07. Document Control Branch (Document Control Desk). 2pp. 45197:044-45197.049.
- --8804190058 Proposed Tech Specs, changing required surveillance interval for ico condenser lower inlet doors from current frequencies to 100% insplaying 16 months. Duke Power Co. 88/04/07, 4pp. 45197,046-46197,049.
- 8804 150036 Forwards Amends 43 & 36 to Licenses NPF-35 & NPF-52, respectively & safety gvaluation Amends modify Paragraphs 2.E. of licenses to require compliance w/ amonded physical security plan.

 JABBOURIK Project Dractorate II-3. 88/04/11. TUCKER,H.B. Duke Power Co. 3pp. 45139 093-45139 104.
- --8804150066 Amends 43 & 36 to Licenses NPF.35 & NPF.52 respectively, modifying Paragraphs 2 E of licenses to require compliance w/amended physical security plan. CROCKER,L. Project Directorate II-3 88/04/11, 4pp. 45139.096-45139.099.
- --8804150070 Saleguards evaluation rept supporting Amends 43 & 36 to Licenses NFF-35 & NPF-52 respectively.

 * NRC No Detailed Affiliation Given: 88/04/11, 3pp. 45139:100-45139:102.
- -8804160199 Requests FR publication of notice of issuance of Amends 43 & 36 to Li-conses NPF-358 NPF-52, respectively. Amends modified Paragraphs 2.E of licenses to require compliance w/amended physical security plan. JABBOUR, K. Project Directorate II-3. 88/04/11, NRC No Detailed Affiliation Given. 2pp. 45139:103-45139:104.
- 8804260078 Requests approval of encl revised "Startup Physics Test Program" Changes made to rod swap isothermal temp coefficient & flux symmetry check. TUCKER,HB. Duke Power Co. 88/04/14. Document Control Branch (Document Control Desk). 4pp. 45282.016-45282.031.
- 8804260082 "Startup Physics Test Program Apr 1988."
 Duke Power Co. 88/04/30. 12pp. 45282.020-45282.031.
- 8804260001 Application for amends to Licenses NPF-35 & NPF-52,adding breakers to list of of containment ponetration conductor overcurrent protective devices for Tech Specs Tables 3.8-1A & 3.8-18.Fee paid.
 TUCKER_H.B. Duke Power Co. 88/04/15. Document Control Branch (Document Control Desk), 4pp. 45238:282-45238:290.
- --8804250002 Proposed Tech Specs re listing of containment penetration conductor overcurrent protection devices.

 Duke Power Co. 88/04/15. 5pp. 45238:286-45238:290.
- 8804260099 Supplemental application for amends to Licenses NPF-35 & NPF-52,rovaling Tech Spec 3/4,7.8 re shubbers.
 TUCKER,H.B. Duke Power Co. 88/04/15. Document Control Branch (Document Control Desk), 3pp. 45254:276-45254:300.
- --8804260104 Proposed Tech Specs re snubbers, Duke Power Co. 88704715, 22pp. 45254:279-45254:300.
- 8804260310 Informs that util conducting review of vendor supplied info re 870731 request for add info on NUREG-0737, item II.D.1, "Performance Testing of Refiel & Safety Valves."

 TUCKER,H.B. Duke Power Co. 88/04/15. Document Control Branch (Document Control Desk), 1p. 45253:063-45253:063.

Q. Inspection reports, IE Bulletins & correspondence

- 8803290268 Forwards Insp Repts 60-413/88-11 & 50-414/88-11 on 880216 18 No vio lations or deviations noted.

 CLINE,W.E. Region 2, Otc of the Director, 88/03/03, TUCKER,H.B. Duke Power Co. 2pp. 44921;141-44921;143.
- --8803290269 Partially withheld Insp Repts 50-413/88-11 & 50-414/88-11 on 880/216-18 (ref. 10CFR2/790(d)) & 73.21).No violations or deviations noted Major areas inspected procedures, records & operations for control & accountability of SNM TODD, G.A., SEYMOUR, D.A., MCALPINE, E.J. Region 2, Ofc of the Director. 88/03/01. 1p. 44921:143-44921:143.
- 8803300072 Forwards Insp Repts 50-413/88-08 & 50-414/88-08 on 880126- 0225 &
- notice of violation. 9ROWNLEE,V.L. Region 2. Ofc of the Director, 88/03/10, TUCKER,H.B. Duke Powel Co. 2pp. 44920:034-44920.047.
- --9803300073 Notice of violation from insp on 880126-0225. Violations noted or 680123,RGS pressure allowed to exceed 1,955 psig & on 880109, equipment operator designated to remove Safety Tag 410 removed tag & repositioned switch w/o approvements. BROWNLEE,V L. Region 2, Ofc of the Director, 88/03/10, 2pp. 44920.036-44920.037

- -8803300075 Insp Repts 50.413/88.08 & 50.414/88.08 on 980126-0225. Violations noted Major areas inspected survoillance observation,maint,roview of licensee nonroutne event repts & followup of previously identified items VAN DOORN,P.K., LESSER,M.S., PEEBLES,T.A. Region 2, Ofc of the Director. 88/03/08. 10pp. 44920.039.44920.047
- 8803280123 Forwards Insp Repts 50-413/88-03 & 50-414/88-03 on 880217-21.No vio-lations or deviations noted.Corrective actions discussed & agreed to via oral commitinducts of deviations noted. Connective actions discussed & agreed to via oral commit-ment from licensed representatives. STOHR, JP. Region 2, Otc of the Director. 88/03/14. TUCKER, H B. Duke Power Co 2pp. 44921:063-44921 078.

-8803280132 Insp Repts 50-413/88-03 & 50-414/88-03 on 880217-21.No violations noted Major areas inspected observation of annual emergency exercise. Weaknesses noted failure to meet exercise objectives in area of emergency mgt & accident assess-DECKER, T.R. Region 2, Old of the Director, 88/03/10, 14pp. SARTOR, W.M.

44921:065 44921 078

- 8804010050 Ack receipt of 880303 ltr informing NRC of steps taken to correct violations noted in Insp Repts 50-413/87-44 & 50-414/87-44.

 BROWNLEE,V.L. Region 2, Ofc of the Director. 88/03/23, TUCKER,H.B. Duke Power Co. 1p. 45010.022-45010.022.
- 8804010245 Requests addl into re response to IE Bullotin 85-003. "Motor-Operated Valve Common Mode Failures During Plant Translents Due to Improper Switch Settings." Response needed within 30 days of Itr date. HERDT AR. Region 2, Olic of the Director. 88/03/23. TUCKER,H B. Duke Power Co. 2pp. 45058:102-45058.103.
- 8804010235 Informs that util unable to establish firm dates for completion of work de-scribed in NRC Bullotin 88 002.Rept will now be provided by 880425. TUCKER,H.B. Drike Power Co. 88/03/24. Document Control Branch (Document Con-
- trol Oesk) 2pp. 45031:119-45031:120
- 8804040101 Responds to NHC fit re violations noted in Insp Ropts 50-413/88-05 & 50-414/88-05. Violation contending that sufficient records maintained to turnish evidence of activities affecting quality.per 10CF450,App 8 deried.

 TUCKER,H 8. Duke Power Co. 88/03/25. Document Control Branch (Document Control Dask) 9pp. 44970 097-44970 095.
- 8803210090 Suppl 1 to NHC Info Notice 87-044, "Thimble Tube Thinning in Westinghousn Reactors" Svc list and HOSSI,CE Division of Operational Events Assessment (Post 870411), 88/03/28, Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995;246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensoos:Lack of Mgt Controls Over Licensed Programs." Svc list oncl.

 CUNNINGHAM,R.E Division of Industrial & Modical Nuclear Safety (Post 870729), 88/
 03/28 Consolidated Edison Co. of Now York, Inc. 108pp. 44905:247-44995:353.
- 8804120061 Advisos that plannod corrective actions for violations noted in Insp Repts 50-413/87-30 & 50-414/87-30 postponed from 880401 to 880501.
 TUCKER,H B. Duke Power Co. 88/03/30. Document Control Branch (Document Control Desk). 1p. 45135-284-45135-284.
- 8804080175 Forwards Insp Repts 50-413/88-13 & 50-414/88-13 on 880226- 0325 & natics of violation. BROWNLEE, V.L. Region 2, Olc of the Director. 88/03/31, TUCKER, H.B. Duke Power Co. 2pp. 45100 048-45100.061.
- --8804080176 Notice of violation from insp on 680225-0325. Violation noted failure to follow Tech Spec administrative requirements for approval of mods. BROWNLEE,V.L. Region 2, Oto of the Director. 88/03/31. 2pp. 45100.051-45100.052.
- ~8804080181 Insp. Repts 60-413/88-13 & 60-414/88-13 on 880226-0325. Violation noted Major areas inspected review of plant operations, surveillance & maint observaions & review of licenson nonroutine event ropts.

 VAN DOORN,P.K., LESSER,M.S., PEEBLES,T A. Region 2, Olc of the Director, 88/03/31, 9pp. 45100.053-45100.061.
- 8804110299 Forwards response to NRC Bullotin 88-001, "Defects in Westinghouse Circuit Breakers."
 TUCKER,H.B. Duke Power Co. 88/04/05. Document Control Branch (Document Control Desk). 2pp. 45154:001-45154:002.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svo list encl. ROSSI.CE. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407:051.
- 8804150392 Forwards Insp. Repts 50-413/68-12 & 60-414/68-12 on 980222-26.Viotation not cited because all criteria for categorization of licensee-identified violation were
- COLLINS.D.M. Region 2, Ofc of the Director, 88/04/07, TUCKER.H.B. Duke Power Co. 2pp. 45192:266-45192:269.
- -8804150396 Insp Repts 50-413/88-12 & 50-414/88-12 on 880222-26. Violation noted Major areas inspected radiation protection area of Unit 2 outage including audits surveillances, planning preparation training qualification & IE notices.

 BASSETT.C.H., HOSEY,C.M. Region 2, Ofc of the Director, 88/04/04, 12pp. 45192 258 45192 269.
- 8804190056 Application for amonds to Licenses NPF-35,NPF-52,NPF-9 & NPF-17,changing required survisillance interval for ice condenser lower inlet doors from current frequencies to 100% insp. every 18 months.
 TUCKER.H.B. Duke Power Co. 88/04/07. Document Control Branch (Document Control Desk). 2pp. 45197-044-45197-049.
- -8804190058 Proposed Tech Specs, changing required surveillance interval for ice condenser lower inlet doors from current frequencies to 100% inspleyery 18 months. * Duke Power Co. 88/04/07, 4pp. 45197.046-45197.049.
- 8804200571 Responds to violations noted in Insp Repts 50-413/88-08 & 50-414/88-08.Corrective actions.Individuals involved counseled in performance & greater supervisory involvement in non-routine activities stressed.

 TUCKER, H.B. Duke Powor Co. 88/04/08. Document Control Branch (Document Control Desk). 5pp. 45175/032-45175/038.

- 8804060370 NRC Info Notice 68-012, "Overgreasing of Electric Motor Bearings." Svc
- ROSSI,C E. Division of Operational Events Assessment (Post 870411) 88/04/12. Consolidated Edison Co of New York, Inc. 123pp. 45165.028-45165.150
- 8804200524 Responds to NRC 880314 fir re-violations noted in this Repts 50-413/88-06 & 50-414/88-06 re-mishterpretation of operating procedure affecting independent nuclear syclewater floors Procedure corrected & sys design reviewed in detail TUCKER,H.B. Duke Power Co. 88/04/12 | Document Control Branch (Document Control Branch (Document Control Branch (Document Control Desk) 3pp 45228-208-45226-210
- 8804200473 Partial response to FC/A request re-fre-protection.Fcrwards App E documents App D & E documents available in PDR App F document completely withhald (ref FCIA Exemption 5) GRIMSLEY.DH Division of Ru'es & Records (Post 870413), 88/04/14 JONES,C R Affiliation Not Assigned, 5pp. 45206-037-45206.043
- -8804200575 Provides status of Region II safe shutdown insp program.
 GRACE,J.N. Region 2, Old of the Director 85/05/13, TAYLCR,J.M. Old of Inspection & Enforcement, Director (820201-870413). 2pp. 45206-174-45208-175
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFH50.App R-type insplict each facility to assess status of compliance w/ 10CFH5048 Program listed CONLONITE. Region 2, Ofc of the Oirector. 84/11/06. HERDT.A.R. Region 2, Ofc of the Director 3pp. 45206 176-45206-178.
- 8804260002 Responds to violations noted in Insp Repts 50-413/68-09 & 50-414/88-On-Corrective action violation result of personnel errors made in interpretation of eddy current test data Measures to centrol & accomptish NDT edequate TUCKER, HB. Duke Power Co. 88/04/14. Document Control Branch (Document Control Dask) 3pp. 45281 306-45281 338
- R. Periodic operating reports & related correspondence
- 8804200168 Monthly operating repts for Mar 1988.W/880415 ltr.

 REAVIS,J.A., TUCKER,H.B., Duke Power Co., 88/03/31, 16pp. 45220 312-45220 327.
- S. Reportable occurrences, LEAs & related correspondence
- 8804050267 Summary of Operating Reactor Events Meeting 88-012 on 680322 List of attendeds, discussion of events & rept-to date of lang-term followup assignments & summary reactor screme encl. LANNING, W. Events Assessment Branch. 88/03/29. ROSSI, C.E. D.w.ston of Operational Events Assessment (Post 870411). 13pp. 45017:292-45017:304.

- 8804060420 Part 21 rept re broken/cracked springs in plant pressure valves. Magnetic particle exam of springs from 18 valves on Unit 2 performed in Jan 1988 & spring from valve BS-02893 rejected for I near indication. Insp. completed BRUNSON, B.G. Drosser Industries, Inc. 88/03/30 CILIMBERG, R.L. NRC No Detailed Alfriation Given, 1p. 45077.254.
- 8804060030 LER 88-013-00.on 880229,containment spray sys taken out of svo for maint purposes & declared inoperable On 880301 both trains out of svo in violation of Tech Specs Caused by mgt deliciency Event reviewed w/linvolved personnel W/
- TORRE, J.G., TUCKER, H.B. Duke Power Co. 88/03/31, 5pp. 45046 165-45046, 169.
- 8804080213 LER 68-012-00 on 880208,waste gas decay tank contents inadvertently re-leased to environ due to leak following maint.Caused by personnel error.Leak identified,sollated 8 repaired.Personnel counseled.Wh880331 ltr. TORRE,J.G., TUCKER,H.B. Duko Power Co. 88/03/31, 10pp. 45098:168-45098:177.
- 8804180441 LER 88-014-00 on 880113,electricians Improperly Installed telaphone in auxiliary feedwater pump turbine control panel room rendering firewall inoperable Caused by mgt deficiency. Penelication properly sealed_dW/880401 ltr. TUCKER.H.B. Duke Power Co. 88/04/01. 6pp. 45196-218-45196-222.
- 8804120338 Confirms 880429 enforcement meeting to discuss concerns to degraded auxiliary feedwater sys flow & long-term corrective actions resulting from Unit 2 trip on 880309.

 GRACE, J N. Region 2, Ofc of the Director. 88/04/08. TUCKER,H.S. Duke Power Co. 1p. 45089:297-45089 297

8804180424 Special reption 880307 & 08 diesel generator 1A experienced one valid & three invalid fallures, respectively. Causad by loss of generator excitation due to shorted rectifier diodo CR6 Crout replaced. TUCKER_H8. Duke Power Co. 88704706. Document Control Branch (Document Control Desk). 2pp. 46184-062-45184:063.

- 8804190264 LER 88-015-00 on 880309, degraded performance of auxiliary feedwater sys required hot shutdown of both units Caused by Asiatic clam larvae infestation the nuclear service water sys. Nuclear svc water sys blockages removed W-880408 ltr. TORRE,J.G., TUCKER,H.B. Duke Power Co. 88/04/08. 12pp 45218.071-45218:082.
- 8804200323 LER 87-042-01:on 871117,breaker tripped & locked out due to out-of-ad-justment wiper being stathed during cooling fan control testing. Caused by equipment malfunctions Technicians Instructed to dissible ground fault relays W/860412 ltr. TORREJ.G., TUCKER,H.B. Ouke Power Co. 88/04/12. 6pp. 45226:201-45226:206.

DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

- F. Security, medical, emergency & fire protection plans
- 8803290266 Forwards Insp Repts 50-413/88-11 & 50-414/88-11 on 880216-18.No violations or deviations noted. CLINE,W.E. Region 2, Ofc of the Director. 88/03/03. TUCKER,H.B. Duke Pawer Co. 2pp. 44921:141-44921:143.

- -8803290269 Partially withheld Insp Repts 50:413/88-11 & 50:414/88-11 on 660216-16 (rof 10CFR2 790(d) & 73:21) No violations or deviations noted Major areas inspected procedures records & operations for control & accountability of SNM TODD,G A. Region 2, Old of the Director, 88/03/01 1p 44921:143-44921:143
- 8803280123 Forwards Insp Repts 50.413/88 03 & 50.414/88.03 on 880217:21.No vio-lations or deviations noted Corrective actions discussed & agreed to wall commit-ment from treansee representatives STOHRJP, Region 2, Ofc of the Director, 88/03/14 TUCKER,H B. Duke Power Co. 2pp. 44921:063-44921:078.
- --8803280132 Insp. Ropts 50 413/88-03 & 50-414/68-03 on 880217-21 No violations noted Major areas inspected observation of annual emergency exercise Weaknesses noted failure to meet exercise objectives in area of emergency mgt & accident assessment
 - SARTOR,W.M. Region 2, Ofc of the Director 88/03/10, 14pp. 44921 065-44921.078.
- 8804110117 Forwards Rev 19 to plant security plan Rev deletes several redundant sections from security plan & revises flist of vital equipment. Rev withheld (ref 10CFR73.21).
 TUCKER.H.B. Duke Power Co. 68/04/01. Document Control Branch (Document Control Desk). 2pp. 45135.278.45135.279

- 8804150423 Notities that changes contained in Rev 10 of emergency plan consistent w/planning stds of 10CFR50.47(b) & requirements of 10CFR50.4pp E COLLINS,D.M. Region 2, Ofc of the Director, 88/04/07, TUCKER,H.B. Duke Power Co. 1p. 45139 334-45138-334
- 8804150038 Forwards Amends 43 8 36 to Licenses NPF-35 & NPF-52, respectively & safety evaluation. Amends modify Paragraphs 2 E of Licenses to require compliance w/ amended physical security plan JABBOUR,K. Project Directorate Ik-3 88/04/11 TUCKER,H B. Duke Power Co. 3pp 45139.0924.45139 103
- 45139 093-45139.102. --8804150066 Amends 43 & 36 to Ucenses NPF-35 & NPF-52 respectively, modifying Paregraphs 2 E of ficenses to require compliance w/amended physical security plan CROCKER,L. Project Directorate II-3, 68/04/11, 4pp. 45139 096-45139 099
- -8804150070 Sateguards evaluation rept supporting Amerids 43 & 36 to Licenses NPF-35 & NPF-52, respectively.

 * NRC No Detailed Affiliation Given, 88/04/11, 3pp. 45139:100-45139.102.

- -8804150199 Requests FR publication of notice of issuance of Amends 43 & 36 to Licenses NPF-35& NPF-52-respectively Amends modified Paragraphs 2 E of Lenses to require compliance w/amended physical security plan.

 JABBOUR, K. Project Directorate II-3. 88/04/11, NRC No Detailed Affiliation Given.

 2pp. 45139-103-45139-104.
- P. Operating license stage documents & correspondence
- 8803290097 Forwards Rev 7 to ulit 830414 response to Suppl 1 to NUREG-0737,including solutions to truman engineering discrepancies. TUCKER,H.B. Duke Power Co. 88/03/16. Document Control Branch (Document Control Desk). 13pp. 44945:237-44945:249.
- 8804010088 Documents that on 880226 util verbally granted one-time 12-h relief from compliance w/Tech Spec Limiting Condition for Operation Action Statement 3.7.1.2(a), "Auxiliary Feedwater Sys." GRACEJN. Region 2, Otc of the Director. 88/03/16 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). TAYLORJ.M. Deputy Executive Director for Regional Operations. EDO (Post 870413). LIEBERMAN,J. Otc of Enforcement (Post 870413). 2pp. 45031:155-45031:170.
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removat of organization charts from Tech Spec administrative control requirements Svc list end. MIHAGLIA, F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of Naw York, Inc. 47pp. 44972:107-44972.153
- 8803300263 Application for amends to Licenses NPF-35 & NPF-52,adding Tech Spec requirements for monitor tank bldg sys & components. Fee paid.

 TUCKER,H.B. Duke Power Co. 88/03/23. Document Control Branch (Document Control Desk). 4pp. 44961;084-44961;107.
- -8803300267 Proposed Tech Specs, adding requirements for operation of monitor tank bldg sys & components.
 * Duke Power Co. 88/03/23, 20pp. 44961.088-44981;107
- 8804010042 Forwards listing of outstanding items,per discussion w/NRC re util ongoing program of reducing backlog of outstanding items. W/o encl. BROWNLEE,V.L. Region 2, Otc of the Director. 88/03/23. TUCKER,H.B. Duke Power Co. 1p. 45031:171-45031:171.
- 8804010045 Confirms concurrence w/intention to restart facility following completion of corrective action to 880309 trip & subsequent swap-over of auxiliary feedwater sys
- GRACE, J.N. Region 2, OJc of the Director, 88/03/23, TUCKER, H.B. Duke Power Co. 1p. 45010.001-45010.001.
- 8804120317 Expresses appreciation for time that members look to present outling of ISAP it program per Generic Ltr 88-02 requesting licenses to evaluate NRC latest rev & Indicate whether rulerested in participating in program. TUCKER.H.B. Duke Power Ca. 88/03/25. Document Control Branch (Document Control Desk). 2pp. 45091:142-45081:143.
- 8804120069 Advises that revised analysis justifying less restrictive action statement for steam generator PORV & Tech Spec change will be submitted by 880516,per util 871204 application for amends to Uceases NPF-35 & NPF-52 TUCKER.H.B. Duke Power Co. 88/03/29. Occument Control Desk), 1p. 45135-313-45135:313.
- 8804180447 Forwards updated pages to proprietary BAW-10171P, "REFLOD3B-Model for Multimode Core Reflooding Analysis." per ECCS methodology for facilities reloads.Mod removes Henry quench temp criteria & potential conflict in logic Pages

wittinetd.
TAYLOR J.H. Babcock & Wilcox Co. 88/03/29. NORBERG J.A. Division of Engineer-ing & Systems Technology (Post 870411). 2pp. 45207:232-45207:233.

8804120036 Provides addl info to util 870629 & 1204 requests to delete requirement to verify reactor temp detector bypass loop flow on 18-month basis from Tech Spec Table 4.3-1,flom 7.

TUCKER,H,B. Duke Power Co. 88/04/01, Document Control Branch (Occument Control Desk), 2pp. 45154-059.45154-060.

- 8804130406 Application for amends to Licenses NPF-9,NPF-17,NPF-35 & NPF-52, changing Tech Specs to allow credit to be taken for Hadiation Monitor EMF-36 I EMF-39 Inoperable below Mode 4 (hot shutdown) Fee pald.

 TUCKER,H.B. Duke Power Co. 88/04/01. Document Control Branch (Document Control Desk). 4pp. 45132:298-45132:324.
- -8804130410 Proposed Tech Specs allowing credit to be taken for Radiation Mor.to: EMF-36 (unit vent monitor) if EMF-39 (on containment purge sys) inoperable below Mode 4 (hot shutdown).

 * Duke Power Co. 88/04/01. 22pp. 45132:303-45132:324.

- 8804210282 Revised application for amends to Licanses NPF-9,NPF-17, NPF-35 & NPF-52 re-fuel assemblies Proposed amends broaden scope of mode allowed to fuel assemblies involving fuel rod locations & delete max fuel rod U flimit. TUCKER,H.B. Duke Power Co. 88/04/01. Document Control Branch (Document Control Deak). 4pp. 45239-029-45239-041.
- --8804210287 Proposed Tech Specs,broadening scope of mods allowed to fuol assemblios involving fuel rod locations & delete specified max total fuel rod U weight I mil.

 **Duke Power Co. 88/04/01. 9pp. 45239.033-45239.041.
- 8804110297 Forwards Rev 8 to response to Suppl 1 to NUREG-0737, including revised writers guide for emergency 8 abnormal procedures for facility-App 2, "Abnormal Procedure Outhine," not included 8 will be updated 8 provided in subsequent rev. TUCKER_H.B. Duke Power Co. 88/04/05. Document Control Branch (Occurrent Control Desk). 2pp. 45135-109-45135-222.
- --8804110300 Rev 8 to "Writers Guide for Emergency & Abnormal Procedures" * Duke Power Co. 88/03/09, 112pp. 46135:111-45135 222.
- 880408088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA, F.J. Associate Director for Projecte (Post 870411), 88704/07. Consolidade Edison Co. of New York, Inc. 49pp. 45154:237-45164:285.
- 8804130309 Forwards request for addl Info re Topical Rept WCAP-10988, "COBRANC, Analysis for Main Steam Line Break in Ice Condenser Contemment." Rosponse requested within 45 days from lit date.

 JABBOUR, K.N. Project Directorate II-3, 88/04/07, TUCKER, H.B. Duke Power Co 6pp. 45103:166-45103:171.
- 8804190056 Application for amends to Licenses NPF-35.NPF-52.NPF-9 8 NPF-17.changing required surveillance interval for Ice condenser lower inlet doors from cur-rent frequencies to 100% insp. every 18 months. TUCKER,H.B. Duke Power Co. 88/04/07. Document Control Brench (Document Con-trol Desk). 2pp. 45197-044-45197:049.
- -8804190058 Proposed Tech Specs, changing required surveillance interval for ica condensor lower intel doors from current frequencies to 100% insplayery 18 months. Duke Power Co. 88/04/07. 4pp. 45197:046-45197.049.
- 8804150038 Forwards Amends 43 & 36 to Licenses NPF-35 & NPF-52, respectively 8 safety evaluation Amends modify Paragraphs 2.E of licenses to require compliance w/ amended physical security plan.

 JABBOURK, Project Directorate II-3, 88/04/11, TUCKER,H.B. Cuke Power Co. 3pp 45139.093-45139:104.
- --8804150066 Amends 43 & 36 to Licenses NPF-35 & NPF-52 respectively, modifying Paragraphs 2.E of licenses to require compilance w/amended physical security glan. CROCKER,L. Project Directorate II-3, 88/04/11, 4pp. 45139.098-45139.099.
- --8804150070 Saleguards evaluation rept supporting Amends 43 & 36 to Licenses NFF-35 & NPF-52 respectively.
 * NRC - No Detailed Attiliation Given. 88/04/11. 3pp. 45139;100-45138:102.
- 200. 45139:103-45139:104.
- 8804260078 Requests approval of encl revised "Startup Physics Test Program" Changes made to rod swap isothermal temp coefficient & flux symmetry check. TUCKER,H.B. Duke Power Co. 88/04/14. Document Control Branch (Document Control Desk). 4pp. 45282.016.45282:031.
- --8804260082 "Startup Physics Test Program Apr 1988." " Duke Power Co. 88/04/30, 12pp, 45282:020-45282:031.
- 8804250001 Application for amends to Licenses NPF-35 & NPF-52,adding breakers to list of containment penetration conductor overcurrent protective devices for Tech Specs Tables 3 8-1A & 3.8-1B. Fee paid, TUCKE R.H.B. Duke Power Co. 88/04/15. Document Control Branch (Document Control Desk), 4pp. 45238:282-45238:290.
- --3804250002 Proposed Tech Specs re listing of containment penetration conductor overcurrent protection devices.

 * Duke Power Co. 88/04/15, 5pp. 45238:286-45238:290.
- 8804280099 Supplemental application for amends to Licenses NPF-35 & NPF-52,1evising Tech Spec 3/4,7.8 re snubbers.
 TUCKER,H.B. Duke Power Co. 88/04/15. Document Control Branch (Document Control Desk). 3pp. 45254:276-45254:300.

163

8604260310 Informs that util conducting review of vendor supplied info ro 870731 re-quest for add info on NUREG-0737, Item III.D.1, "Performance Testing of Relief & Safety Valves" TUCKEH, H.B. Duke Power Co. 88/04/15. Document Control Branch (Document Con-trol Desk). 1p. 45253 063-45253.063.

Q. Inspection reports, IE Bulletins & correspondence

- 8803290266 Forwards Insp Repts 50-413/88-11 & 50-414/88-11 on 880216-18 No vio-
 - Talions or deviations noted.

 CLINE,W.E. Region 2, Old of the Director. 88/03/03. TUCKER,H.B. Duke Power Co 2pp. 44921:141-44921:143.
- --8803290269 Partially withheld insp. Repts 50-413/88-11 & 50-414/88-11 on 680216-18 (ref. 10CFR2.790(d) & 73.21).No violations or deviations noted Major areas inspected procedures, jecords & operations for control & accountability of SNM TODD,G A , SEYMOUR,D A., MCALPINE,E J. Region 2, Ofc of the Director, 88/03/01. p. 44921:143-44921:143.
- 8803300072 Forwards Insp Repts 50-413/88-08 & 50-414/88-08 on 880126- 0225 &
 - notice of violation.

 BROWNLEE,V.L. Region 2, Old of the Director, 88/03/10, TUCKER,H.B. Duke Power Co. 2pp. 44920 034-44920 047.
- -8803300073 Notice of violation from Insp. on 880126-0225.Violations noted:on 880123.RCS pressure allowed to exceed 1,955 psig & on 880109,equipment operator designated to remove Safety Tag 410 removed tag & repositioned switch w/o approv-BROWNLEE, V.L. Region 2, Ofc of the Oirector, 88/03/10, 2pp. 44920/038-44920/037.
- --8803300076 Insp Repts 50:413/88:08 & 50:414/88:08 on 880126:0225. Victations noted.Major areas inspected surveillance observation,maint,review of licensee nonroutine event repts & followup of previously identified items.

 VAN DOORN,P.K., LESSER,M.S., PEEBLES,T.A. Region 2, Ofc of the Director, 88/
- 03/08. 10pp. 44920.038-44920.047.
- 8803280123 Forwards Insp Repts 50-413/88-03 & 50-414/88-03 on 880217-21.No violations or deviations noted Corrective actions discussed & agreed to via oral commit-hations or deviations noted Corrective actions discussed & agreed to via oral commit-ment from licensee representatives, STOHR,J.P. Region 2, Oto of the Director. 88/03/14, TUCKER,H.B. Duke Power Co. 2pp. 44921:063-44921:078
- -8803280132 Insp. Repts 60:413/88:03 & 50:414/68:03 on 880217-21.No violations noted Major areas inspected observation of annual emergency exercise. Weaknosses noted:failure to meet exercise objectives in area of emergency mgt & accident assess-
- SARTOR, W.M., DECKER, T.R. Region 2, Ofc of the Director, 88/03/10, 14pp. 44921.065 44921.078.
- 8804010050 Ack receipt of 880303 kr Informing NRC of steps taken to correct violations noted in Insp Repts 50-413/87-44 & 50-414/87-44. BROWNLEE,V.L. Region 2, Ofc of the Director. 68/03/23. TUCKER,H.B. Duke Power Co. 1p. 45010.022-45010.022.
- 8804010245 Requests additinfo to response to IE Bulletin 85-003. "Motor Operated Valve Common Mode Failures During Plant Transients Due to Improper Switch Setlings." Response needed within 30 days of lit date. HERDT.A.R. Region 2, Oic of the Director. 88/03/23. TUCKER,H.B. Duke Power Co 2pp. 45058.102-45058:103.
- 8804010235 Informs that util unable to establish firm dates for completion of work descabed in NRC Bulletin 88-002 Rept will now be provided by 880425. TUCKER,H.B. Duke Power Co. 88/03/24, Document Control Branch (Document Control Desk), 2pp. 45031:119-45031:120
- 8804040101 Responds to NRC lir re violations noted in Insp. Repts 50-413/88-05 & 50-414/88-05. Violation contending that sufficient records mainteined to furnish evidence of activities affecting quality.ger 10CFR50,App B denied. TUCKER,H B. Duke Power Co. 88/03/26. Document Control Branch (Document Control Desk). 9pp. 44970.087-44970.095.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors," Svc list encl. HOSSI, C.E. Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees:tack of Mgt Controls Over Li-censed Programs." Svc list encl. CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Salety (Post 870729), 26/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995 353
- 8804120061 Advises that planned corrective actions for violations noted in Insp Ropis 50.413/87-30 8 50-414/87-30 postponed from 880401 to 880501. TUCKER,H.B. Duke Power Co. 88/03/30. Document Control Branch (Document Control Desk). 1p. 45135:284-45135:284.
- 8804080175 Forwards Insp. Repts. 50-413/88-13 & 50-414/88-13 on 880226- 0325 & notice of violation.
 BROWNLEE,V.L. Region 2, Oto of the Director, 88/03/31, TUCKER,H.B. Duke Power Co. 2pp. 45100.049-45100.081.
- --8804080176 Notice of violation from Insp. on 880225-0325.Violation noted la lure to follow Tech Spec administrative requirements for approval of mods. BROWNLEE,V.L. Region 2, Oic of the Director. 88/03/31, 2pp. 45100.051-45100.052.
- --8804080181 Insp. Repts 50-413/88-13 & 50-414/88-13 on 880226-0325. Violation noted Major areas inspected review of plant operations surveillance & maint observations & review of licenses nonroutine event repts. VAN DOORN.P.K. LESSER,M.S., PEEBLES,T.A. Region 2, Ofc of the Director. 88/03/31, 9pp. 45100.053-45100.061,
- 8804110299 Forwards response to NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakers."
 TUCKER,H.B. Duke Power Co. 88/04/05. Document Control Branch (Document Control Desk). 2pp. 45154;001-46154;002.

- 8804010256 NRC Info Notice 88:011, "Potential Loss of Molor Control Crr &/or Switch-board Function Due to Faulty Tie Bolts," Svc list end! ROSSI,C E Division of Operational Events Assessment (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 324pp. 45406 292-45407:051.
- 8804150392 Forwards Insp. Repts. 50-413/86-12 & 50-414/88-12 on 880222-26.Violation not cited because all criteria for categorization of Leansee dentified Violation were COLLINS.D.M. Region 2, Old of the Director 88/04/07 TUCKER,HB Cuke Power Co 2pp 45192 256-45192 269
- ~8804150396 Insp. Ropts 50-413/88-12 & 50-414/88-12 on 880222-26 Violation noted Major areas inspected radiation protection area of Unit 2 cutago, including audits surveillances, planning, preparation, training qualification & IE notices BASSETT.C.H. HOSEY.C.M. Region 2, Cit. of the Director, 68/04/04, 12pp. BASSETT, C.H. HOS 45192:258-45192:269
- 8804180056 Application for amends to Licenses NPF-35,NPF-52,NPF-9 & NPF-17, changing required surveillance interval for ico condonser tower interded doors from current frequencies to 100% Inspleyery 16 months.
 TUCKER,H 8. Duko Power Co. 68/04/07 Document Control Branch (Document Control Dask). 2pp. 45197-044-45197,049.
- --8804190058 Proposed Tech Spacs,changing required surveillance interval for ico con-densor lower falet doors from current frequencies to 100% map every 18 months. * Duke Power Co. 88/04/07, 4pp. 45197,046-45197,049.
- 8804200571 Responds to violations noted in Insp. Repts 50-413768-08-8-50-414788 08 Corrective actions individuals involved counsiled to performance 8 greater supervisory involvement in non-routine activities stressed. TUCKER, H.B. Duke Power Co. 88/04/08, Decument Control Branch (Document Control Desk). Spp. 45175:032-45175.036.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc Agrenct
 ROSSICE Division of Operational Events Assessment (Post 870411) 88/04/12
 Consolidated Edison Colod New York, Inc. 123pp. 45185/028-45185 150
- 8804200524 Responds to NRC 880314 fir to violations noted in Insp Repts 50-413/88-No. 8:00-14/08-68 in mishingrotation of operating procedure affecting independent nuclear sec water loops Procedure corrected & sys design reviewed in detail. TUCKER, H.B. Duke Power Co. 88/04/12. Document Control Branch (Document Control Desk). 3pp. 45226:208-45226:210
- 8804260002 Responds to violations noted in Insp. Repts 50-413/88-09 & 50-414/88-OD-COPOLON RESIDENCE OF VIOLENCES OF THE RESIDENCE OF THE PROPERTY OF A STATE OF THE PROPERTY OF THE PROPERTY

R. Periodic operating reports & related correspondence

- 8804200168 Monthly operating repts for Mar 1908.W/880416 ftr REAVIS,JA., TUCKER,H.B. Duko Power Co. 88/03/31, 16pp 45220.312-45220.327.
- S. Reportable occurrences, LERs & related correspondence
- 8804050246 LER 88-007-00.on 880222 main feedwater pump turbine tripped due to low vacuum in condenser Probably caused by condenser cooling water interior pipe coating matt Auxiliary feedwater pumps secured & affected valves repositioned.W/880323 TORREJ G., TUCKER,HB. Duke Power Co. 88/03/23, 6pp. 45017:219-45017:224.
- 8804050388 LER 88-009-00:on 880226,discovered that RCS gross radioactivity calculation had not been performed on 880222 as required by Tech Speca.Caused by personnel error incident reviewed withrooked chemistry technician W/880325 in TORRE_J.G., TUCKER_H.B. Duke Power Co. 88/03/25, 5pp. 48034.041-45034.045
- 8804060032 LER 88 008 00 on 880224,Tech Spec violation due to implementation of inadequate compensatory measures Caused by mgt deliciency Mentioning Instrumentation returned to six before roduction in reactor tomp in tit
- 8804050267 Summery of Operating Reactor Events Meeting 88-012 on 880022 List of attendees,discussion of events & repi-to-date of long-form followup assignments & summary reactor scrams enci.

 LANNINGW. Events Assessment Branch 88/03/29. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 13pp. 45017:202-45017:304
- 8804080420 Part 21 rept re brokon/cracked springs in plant pressure valves Mingrotic particle exam of springs from 18 valves on Unit 2 performed in Jon 1988 & spring from valve 95-02893 rejected for linear indication linsp completed.

 BRUNSON,B.G. Drosser Industries, Inc. 66/03/30. CILIMBERG,R.L. NRC No Detailed Alfillation Given. 1p. 45077:254-45077-254.
- 8804050390 LER 88-010-00:cn 880203,during NRC equipment qualification inspidamaged RHR sys Rotork electric motor operated valve actuator discovered. Caused by improper installation of motor to actuator on valve 2ND2A. Valve repaired W/880331 ftr.
 TORRE, J.G., TUCKER, H.B. Duke Power Co. 88/03/31 5pp. 45034:036-45034:040.
- 8804180426 LER 88-011-00:on 871229,incoming breaker to 4,160 volt essential Switch-gear 2ETB failed to trip during ESF actuation periodia testing Caused by open stiding Ink in breaker control crouit Skiding Link closed W/880401 ltr. TORRE,J.G., TUCKER,H.B. Duke Power Co. 88/04/01. Spp. 45183:231-45183:235.
- 8804120338 Confirms 880429 enforcement meeting to discuss concorns re-diagraded auxiliary feedwater sys flow & tong-term corrective actions resulting from Unit 2 trip on 880309.

 GRACE J.N., Region 2, Ofc of the Director, 88/04/06, TUCKER,H.B. Duke Power Co. 1p. 45089 297-45089 297.

water swap of suction from Train A to nuclear svc water sys Caused by opening of control valve due to defective circuit card & card driver W1880408 ftr. TORREJG_TUCKERHB_Duke Power Co_88/04/08.9pp 45220.293.45220.301.

DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8803310288 Forwards proposed agenda for Southeastern Utilities Emergency Planning Group Meeting on 880421-22 in Vicksburg, MS Transportation from Jackson to Vicksburg & to & from motet/meeting and airport will be provided. MORGANC System Energy Resources, Inc. 88/03/25. Affiliation Not Assigned. 7pp. 44984 333-44984 339.
- 8804110156 Summary of 850210 & 11 meetings w/util relicensing actions, including status of completion of license conditions,Rev 2 to updated FSAR & implementation dates for Safety Issues Mgl Sys Attendance list, agenda handout & date end KINTER,LL. Project Directorate II-1. 88/03/30. Project Directorate II-1. 57pp 45078 194-45078 250
- 8804200473 Partial response to FOIA request re fire protection.Forwards App E documents App D & E documents available in POR App F document completely withheld (ref FOIA Exemption 5) GRI:MSLEY,D H Division of Rules & Records (Post 870413) 88/04/14. JONES,C R. Affiliation Not Assigned, 5pp. 45206 037-45206.043
- -8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFH50.App R-type insp for each facility to assess status of compliance w/ 10CFH50 48 Program Isted. CONLON.T.E. Region 2, Ofc of the Director. 3pp 45206 176-45206 178.

H. General correspondence

- 8804150249 Informs of changes to listed telephone prefixes at corporate headquarters due to improvements in telecommunications sys to become effective 880411. CAVANAUGH,W. System Energy Resources, Inc. 68/04/05. MARTIN,R.D. Region 4, O?c of the Director. 1p. 45138 201-45138 201.
- 8804150262 Notifies of change in last four digits of telephone number. Changes will be effective on 880411
 CAVANAUGH, W. System Energy Resources, Inc. 88/04/05 GRACE, J.N. Region 2, Ofc of the Director, 1p. 45145 253-45145 253.

J. Insurance & Indemnity Information

- 8804070076 Forwards certificates of coverage by Nuclear Electric Insurance Ltd & Americar. Nuclear Insurers/MAELU Nuclear Mutual Ltd will not Issue certificate until coverage commences on 880401 Coverage in effect on 880401 summarized XINGSLEY.O D. System Energy Resources, Inc. 88/03/31 Document Control Branch (Document Control Desk). 7pp. 45024 267-45024-273
- 8804200116 Forwards Endorsements 8.47 & 48 to NELIA Policies Ni-79, NF-257 & NF-257,respectively & Endorsements 8.26 & 27 to MAELU Policies Mi-79,MF-108 & MF-106,respectively. KINGSLEY,O.D. System Energy Resources, Inc. 88/04/14. Document Control Branch (Document Control Desk). 13pp. 45226 025-45226 037.

P. Operating license stage documents & correspondence

- 8803100153 Discusses NRC reviews re 880217 ftr providing results of analysis NRC review concludes that plant instruments lines meet nine criteria in ANSI/ANS Std 56.2 . 1984 for closed sys outside containment & acceptable. XINTNER_LL_Project_Directorate II-1. 88/03/07. KINGSLEY,O.D. System Energy Resources, Inc. 2pp. 44662.114.44662.115
- 8803240426 Generic Ltr 88-08 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc List encl. MIRAGLIAF J. Associate Director for Projects (Post 870411) 88/03/22, Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804070135 Forwards plant specific final response to Item 4.5.3 of Generic Ltr 83.28 re actions based on generic implications Safern ATWS events. Proprietary MDE-80-0485 & rept addendum withheld (ref 10CFR2.790). KINGSLEY.O.D. System Energy Resources, Inc. 88/03/30. Document Control Branch (Oocument Control Desk). 4pp. 45029.312.45029.315.
- 8804110156 Summary of 880210 & 11 meetings w/util re licensing actions, Including status of completion of license conditions Rev 2 to updated FSAR & implementation dates for Salety Issues Mgt Sys Attendence list.agenda.handout & data enct. KINTER.L.L. Project Directorate II-1. 88/03/30. Project Directorate II-1. 57pp. 45078.194-45078.250

reflects SPDS design valuring SPDS audit

I Control Branch

Lir 83-28 frems

no itis received Control Branch

- forcement policy concerning 10CFR5049, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc list enct. WIRAGLIAF J. Associate Director for Profects (Past 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184 237-45184:285.
- 8804190082 Application for amend to License NPF-28,revising Tech Spec Table 4 8 1.1 2-1, "Dissel Generator Tost Schedule," per Generic Ltr 84-15 Fee paid. KINGSLEY,O.D. System Energy Hesources, Inc 88/04/08. Document Control Desk). 3pp. 45209-126-45209-135
- -8804190090 Proposed Tech Spec Table 4.8.1.1 2-1, "Diesel Generator Test Sched ule." " System Energy Resources, Inc. 88/04/08. 1p. 45209:135-45209:135.
- 8804200584 Forwards implementation data on addl satety issues mgl sys items re-ceived on 871001.Final data for remaining items will be submitted by 880429. CESAREJ.G. System Energy Pessucces, Inc. 88/04/11, KINTNETS.L. Office of Nu-clear Reactor Regulation, Director (Post 870411), 13pp. 45235:024-45235.038.
- 8804210013 Forwards description & diagram of design of containment air lock seal at sys at plant,per 880404 telcon Into provided in support of review of plant air lock configuration as followup to 880404 discussion KINGSLEY.O D. System Energy Resources, Inc. 88/04/15, Document Control Branch (Document Control Desk), Spp. 45219:153-45219:157.

Q. Inspection reports, IE Bulletins & correspondence

- 8804010054 Ack receipt of 880219 itr Informing NRC of steps taken to correct violations haled in Insp Rept 50-46/87-35.
 VERNELLIO, M. Rept 50-46/87-35.
 VERNELLIO, M. Rept 50-46/87-35.
 Energy Resources, Inc. 1p. 45010 021-45010:021.
- 8804040056 Forwards response to NRC Bulletin 88:001, "Defects in Westinghouse Or-cuit Breakers." Investigation determined that Westinghouse DS series breakers not used at plant.
 KINGSLEY,O.D. System Energy Resources, Inc. 88/03/22. Document Control Branch (Document Control Desk). 2pp. 44969 358-44969.359.
- 8803300376 Responds to NRC 880222 lir re violations noted in Insp Rept 50 418/87-40 Corrective actions:new setpoints based on determined normal indicated dp estab-ished & trip unit instrumentation for HPCS & LPCI recation per Toch Specs. CESAREJ.G. System Energy Resources, Inc. 88/03/23. Document Control Branch (Document Control Desk). 3pp. 44979.049-44979.051.
- 8804010063 Forwards Insp Rept 50-416/87-32 on 871214-18 & notice of violation. HERDT.A.R. Region 2, Ofc of the Director, 88/03/25. KINGSLEY,O.D. System Energy Resources, Inc. 2pp. 45028:146-45028:170.
- --8804010064 Notice of violation from insp on 881214-18. Violation noted: licensee in-statled commercial grade parts on equipment requiring environ qualification w/o ade-quate evaluation of subtibility for use in safety-related applications. HEROT, A.R. Region 2, Ofc of the Director. 88/03/25. 3pp. 45028:148-45028:150.
- -8804010067 Insp. Rept. 50-416/87-32 on 871214-18.Violations noted.Major areas inspected environ qualification of electrical equipment.Implementation of 10CFR50.49 requirements a electrical equipment within scope of 10CFR50.49.

 RUFF.A., CONLON,T.E. Region 2, Old of the Director. 88/03/24, 20pp. 45028:151-45028:151
- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning In Westinghouse Reactors." Syc list encl. ROSSI.CE. Division of Operational Events Assessment (Post 870411). 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:248.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees:Lack of Mgt Controls Over Li-censed Programs." Svc fist enct. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/ 03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44995-247-44995.353.
- 8804070275 Forwards Rev 1 to "SPDS Safety Analysis" which reflects SPDS design considerations as of Sept 1986.Rev 1 reviewed by NRC insp team during SPDS audit conducted in Mar 1987. KINGSLEY,O.D. System Energy Resources, Inc. 88/04/01. Document Control Branch (Document Control Desk). 1p. 45024:276-45024:335
- 8804080118 Responds to NRC ltr re violations noted in Insp Rept 50-416/88-01.Corrective actions Quality Deficiency Rept (QDR 070-88) Initiated to document & resolve improper storage of nitrogen boillos.

 KINGSLEY,Ö.D. System Energy Resources, Inc. 88/04/01. Document Control Branch (Document Control Desk). 3pp. 45064:061-45064.063.
- 8804120039 Forwards corrected Pages 2,9,14 & 17 to Insp Rept 50-416/87-32. HERDT.A.R. Region 2, Oic of the Director, 88/04/01, KINGSLEY,O.D. System Energy Resources, Inc. 2pp. 45150:332-46150.337.
- -8804120072 Revised Pages 2,9,14 & 17 to Insp Rept 50-416/67-32.
 * Region 2, Ofc of the Director: 86/04/01, 4pp. 45150:334-45150:337.
- 8804120163 Forwards Insp Rept 50-416/88-03 on 880220-0318 & notice of violation. VERRELLI,D.M. Region 2, Ofc of the Director. 88/04/05. KINGSLEY,O.D. System Energy Resources, Inc. 2pp. 45132:213-45132:225.
- -8804120167 Notice of violation from insp on 880220-0318.Violation noted jumpered Terminals 9 to 10 on ground overcurrent relay on Breaker 152-1609 instead of 152-1608 & failure to document installation of equipment in condenser offgas sys. VERRELLI,D.M. Region 2, Ofc. of the Director. 88/04/05. 2pp. 45132:215-45132:216.
- --8604120171 Insp Rept 50-416/68-03 on 880220-0318.Violations noted. Major areas inspected action on previous enforcement metters, operational safety verification, maint observation, surveillance observation, ROs & operating reactor sevents. BUTCHER, R.C., MATHIS, J.L., DANCE, H.C. Region 2, Oto of the Director. 86/04/01. 9pp. 45132:217-45132:225.

- 8804150100 Forwards NIS-1-00006, "Inservice Insp Summary Rept for Grand Gulf Nuclear Station Unit 1," for period ending second refueling outage. KINGSLEY,O.D. System Energy Resources, Inc. 88/04/05. Document Control Branch (Document Control Desk). 2pp. 45143-352-45145:210
- -8804150103 "Inservice Insp Summary Rept for Grend Gulf Nuclear Station Unit 1."
 * System Energy Resources, Inc. NIS-1-00008. 8B/03/22. 600pp. 45143:354-
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svc list encl. ROSSI.C E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consoldated Edison Co. of New York, Inc. 124pp. 45408:292-45407:051.
- 8804 1503 15 Ack receipt of 880323 ltr Informing NRC of steps taken to correct violations noted in Insp Rept 50-416/87-40.
 VERRELLIOM. Region 2. Ofc of the Director. 88/04/07. KINGSLEY,O.O. System Energy Resources, Inc. 1p. 45138:163-45138:163.
- 8804150325 Forwards Insp Rept 50-416/68-05 on 880307-11.No violations or devietions noted.

 COLLINS,D.M. Region 2, Ofc of the Director. 88/04/07. KINGSLEY,O.D. System Energy Resources, Inc. 2pp. 45184:046-45184.060.
- -8804150357 Insp Rept 60-416/88-05 on 880307-11.No violations noted. Major areas Inspected offgas sys hydrogen control & offsite dose assessments during charcoal
- bed bypass. MARSTON,R.R. KAHLE, J.B. Region 2, Ofc of the Director, 88/04/07. 14pp. 45184:047-45184:060.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc
 - INSTRUCT.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/12.

 Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150.
- 8804210324 Ack receipt of util 870911 response to NRC Bulletin 87-001, "Thinning of Pipe Walls at Nuclear Power Plants." Util Info being used to determine extent of industry participation & implementation of erosion/corrosion insp programs. KINTNER, L.k. Project Directorate In-1. 88/04/13. KINGSLEY,O.D. System Energy Resources, Inc. 2pp. 45192:111-45192:112.
- 8604220053 Ack receipt or 860322 response to NRC Bulletin 88:001, "Defects in Wes-linghouse Circuit Breakers." Util determined that circuit breaker models Identified not used at facility. No further action required.
 KINTNER,L.L. Project Directorate II-1, 88/04/13. KINGSLEY,O.L. System Energy Resources, Inc. 2pp. 45201:081-45201:082.
- 8804200473 Partial response to FOIA request re fire protection.Forwards App E documents App D & E documents available in PDR.App F document completely withheld (ref FOIA Exemption 5). GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 88/04/14. JONES,C.R. Affiliation Not Assigned. 5pp. 46206:037-45206:043.
- -8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type insp for each facility to assess status of compliance w/ 10CFR50 48.Program listed.
 CONLON.T.E. Region 2, Ofc of the Director. 84/11/08. HERDT.A.R. Region 2, Ofc of the Director, 3pp. 45206:176-45206:178.

- 8804220200 "Grand Gulf Nuclear Station 1987 Annual Radiological Environ Operating Rept." W/880411 ltr. KINGSLEY.O.D. System Energy Resources, Inc. 87/12/31. 200pp. 45253.301-
- 8804190089 Monthly operating rept for Mar 1988.W/880414 ltr. HOBBS,S.H., KINGSLEY,O.D. System Energy Resources, Inc. 88/03/31. 5pp. 45197:050-45197:054.

S. Reportable occurrences, LERs & related correspondence

- 8804070187 Special Rept 88-001/0:on 880302, diesel generator 12 automatically tripped on low lube oil pressure. Caused by automatic start due to lube oil pressure fluctuations that may occur during engine startup. Diesel generator tested. KINGSLEY,O.D. System Energy Resources, Inc. 88/03/29. Document Control Branch (Document Control Desk). 2pp. 46072:282-46072:293.
- 8804080277 LER 88-009-01:on 880227, hydrogen ignition occurred in offgas sys causing ignition of lower portion of first charcoal absorber beds. Caused by wetting of catelyst in olfgas hydrogen combiner, Instruction revised W/880329 ftr. DIFFERENT, P.M., KINGSLEY, O.D. System Energy Resources, Inc. 88/03/29. 6pp. 45084-22 45084-20.
- 8804080063 LER 88-003-01:on 880109,line break Instrumentation for RHR A high differential pressure alarmed & sealed in Caused by use of calculated do value instead of indicated do per Tech Specs. Tealing & troubleshooting performed.W/88031 II.

 DIFFERENT.P.M., KINGSLEY,O.D. System Energy Resources, Inc. 88/03/31. 5pp. 45063:354-45063:358.
- 8804130175 Special Rept 88-001/1:on 880302 & 30, diesel generator 12 automatically inpped during performance of monthly functional surveillance. Caused by low turbo-charger oil pressure. Addit controls implemented on regulators. KINGSLEY.O.D. System Energy Resources, Inc. 88/04/05. Document Control Branch (Document Control Desk), 5pp. 46151:267-45161:271.
- 8804200007 LER 88-010-00:on 880315,reactor scram on low water level occurred Caused by loose connection in reactor protection sys terminal box de-enger-gizing scram pilot A sciencids of control rods.Connection cleaned & tightened.W/880413 ltr. DIFFERENT, P.M., KINGSLEY, O.D. System Energy Resources, Inc. 88/04/13. 4pp. 45221;112-45221;115

8804250265 LER 88-011-00 on 880317,inadvertion RHR pump start occurred during monthly functional test of RHR pump 8 start time delay.Caused by electrican error Appropriate personnel will be retrained & procedures will be enhanced.W/ 880415 ltr BYRD,R , KINGSLEY,O D. System Energy Resources, Inc. 88/04/15. 6pp. 45281.271-45281:278

V. Operator Examinations

- 8804250088 Responds to FOIA request for info re accres of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in enci app w/personal privacy info deleted.

 GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 88/04/19. BOLEY,K. Public Citizen's Critical Mass Energy Project. 2pp. 45213:003-45213.095.
- --8804250187 Package of NRC administered requalification exam results summary.
 NRC No Detailed Affiliation Given 87/07/20, 88pp. 45213:007-45213:095.

DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

- 8803240426 Goneric Ltr 88-98 to all power reactor licensees & applicants re removal of organization charts from Tach Spac administrative control requirements Svc list enci. MIRAGLIA.F. J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972.153
- 8804080046 Provides supplemental into to 841119 response to Generic Lir 83:28, Items 2.1.2 & 2.2 per NRC 880311 request. Explanation of how all GE svc into itrs received provided. KINGSLEY,O.D. System Energy Resources, Inc. 88/04/01. Document Control Branch (Document Control Desk). 2pp. 45044:243-45044:244.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Sve list encl. MIRAGLIA.F.J. Associato Director for Projects (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164-237-45164-285.

F. Security, medical, emergency & fire protection plans

8803310286 Forwards proposed agenda for Southeastern Utilities Emergency Planning Group Meeting on 880421-22 in Vicksburg, MS Transportation from Jackson to Vicksburg & to & from motel/meeting and airport will be provided. MORGANC. System Energy Resources, Inc. 88/03/25. Affiliation Not Assigned. 7pp. 44984:333-44984:339.

H. General correspondence

- 8804150249 Informs of changes to listed telephone prefixes at corporate headquarters due to improvements in telecommunications sys to become effective 880411. CAVANAUGH,W. System Energy Resources, Inc. 88/04/05. MARTIN,R.D. Region 4, Old of the Director. 1p. 45138 201-45138:201.
- 8804150262 Notifies of change in last four digits of telephone number. Changes will be offective on 880411.
 CAVANAUGH,W. System Energy Resources, Inc. 88/04/05. GRACE,J.N. Region 2, Ofc of the Director, 1p. 45145:253-45145:253.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC into Notice 87-044, "Thimb's Tube Thinning in Westinghouse Reactors." Svc 1st end.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/03/28.
 Consolidated Edison Co. of New York, Inc. 12 [pp. 44995:126-44995-246.
- 8803220296 NRC Info Notice 88-010, "Mails Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list enci.
 CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 88/03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804010258 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408:292-45407:051.
- 8804060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12.
 Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150.

V. Operator Examinations

- 8804250088 Responds to FOIA request for info re scores of reactor operators & sentor reactor operators. Forwards requellification exam summary source sheets listed in encl app w/personal privacy info deleted.
 GRIMSLEY, D.H. Division of Rules & Records (Post 870413). 88/04/19. BOLEY.K. Public Citizen's Critical Mass Energy Project. 2pp. 45213:003-45213.095.
- --8604250167 Package of NRC administered requalification exam results summary.
 NRC No Detailed Affiliation Given. 87/07/20, 88pp. 45213:007-45213:095.

F. Security, medical, emergency & fire protection plans

8804060003 Forwards add) into clarifying proposed change to NRC 871223 physical security plan per 870616 telcon End withheld (ref. 10CFR73.21.8.2.790(a)) MROCZKAE J. Northeast. Nuclear Energy. Co. (subs. of Northeast Utilities) MROCZKAE J. Northeast Utilities B8/03/29. Document Control Branch (Document Control Desk). 2pp. 45047.173-45047.174.

8804080269 Rev 3 to emergency plan implementing procedure (EPIP) Form 4211-1, "Station Emergency Organization Lead Oncall Position Managers." Hev 82 to EPIP form index & 880331 ftr end!
MROCZKAE J. Northeast. Nuclear. Energy. Co. (subs. of . Northeast. Utilities).
MROCZKAE J. Northeast Utilities 68/03/31 8pp. 45123 289 45123 296.

8804250267 Forwards temporary change to physical security plan re-protected area boundary Rev withheld (ref. 10CFR72.790(a))
MROCZKAE J. ROMBERG W.D. Northeast Nuclear Energy Co. (subs. of Northeast titates, MROCZKAE J. Northeast Utitates, 88/04/22. Document Control Branch (Document Control Desk). 2pp. 45281-286-45281-287.

H. General correspondence

8804070291 Comments supporting proposed rule 10CFR50 re leakage testing of containment to permit use of mass point method as alternative method for calculating containment leakage rates Mass point method more accurate for calculating rates MROCZKAE J. Connecticut Yankee Atomic Power Co. 88/03/31. CHILKS J. Office of the Secretary of the Commission. 3pp. 45021:184-45021.186.

I Financial Information

8804140014 Forwards Connecticut Light & Power Co & Western Massachusetts Electric Co "Annual Rept 1987," per 10CFR50 71(b) Nonheast Nuclear Energy Co financial rept will not be available until on or about 880427. GUGLIEUNO, F. J Northeast Utilises 88/04/07. Office of Nuclear Reactor Regulation, Orrector (Post 870411). 1p. 45122 337-45123 050

-8804140017 "Annual Rept 1987"
FOX.B.M., ELLIS.W.B. Connecticut Light & Power Co. (subs. of Northeast Utilities)
87/12/31 43pp 45122.338-45123.019.

-8804140022 "Annual Rept 1987"

FOX,B.M., ELLIS,W.B. Western Massachusetts Electric Co. (subs. of Northeast Unit-bes) 87712/31 31pp. 45123 020-45123 050.

8804250249 Informs that payment of third quarterly installment of 1988 annual fee per IOCFR171 will be wire transferred on 880429 MROCZKAE J., SEARS, C.F. Connecticut Yankee Atomic Power Co. SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities), 88/04/18. Document Control Branch (Document Control Desk). 2pp. 45258.292-45258.293

J. Insurance & Indemnity information

8804070118 Notifies Commission of amount of property insurance coverage currently in loce for facilities Types of coverage & markets listed.

MROCZKA,E J. Northeast. Nuclear. Energy. Co. (subs. of Northeast. Utilities).

MROCZKA,E J. Northeast. Utilities. 88/03/30. WOOD,R. Policy Development & Tech-nical Support Branch (Post 870411). 2pp. 45022 092-45022 093.

P. Operating license stage documents & correspondence

8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl MIRAGLAF J Associate Director for Projects (Post 870411) 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972 107-44972 153.

8804050344 Responds to uili 880225 proposed changes to Tech Spec Tables 2 2-1 & 3.3-4 re steam generator to-to level reactor trip setpoint Understands that util will provide analysis re justification within 30 days of it

8804120247 Responds to NRC 880317 request re physics methodology for PWR reload design Safety review criteria set separately from design review criteria & based upon safety analysis calculations & for Fech Specs MROCZKAEJ. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKAEJ. Northeast Utilities 88:04/104. Document Control Desk). 2pp. 45090 047-45090 048.

8804130218 Submits info provided by util during 880321 meeting w/NRC re qualification of Litton Veam connectors used in various protection & instrumentation sys Connectors will perform intended function Schedula to replace connectors encl MROCZKAE J Northeast Nuclear Energy Co (subs. of Northeast Utilities) MROCZKAE J Northeast Utilities 88/04/04. JOHNSTON,W.V Region 1, Ofc of the Director 45pp 45116-306-45116-350.

8804/080088 Genenc Ltr 88-07 to power reactor licensees & applicants re-modified en-lorcement policy concerning 10/CFR\$0.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl MIRAGLIA, F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164.237.45164:285.

8804200223 Forwards Amend 16 to License NPF-49 & safety evaluation. Amend revises sample plans used for surveillance snubbers as described in Tech Spec 4.7-10.e.2 to remove testing threshold criteria. FERGUSON,R.L. Project Directorate 1-4. 88/04/07, MRCCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 45191:089.45191;101

 -8804200231 Amond 16 to License NPF-49 revising sample plans used for surveillance of snubbers as described in Tech Spec Section 4.7.10.e.2 to remove testing threshold STOLZ,J F. Project Directorate I-4, 88/04/07, 9pp. 45191 091-45191 099

8804120423 Forwards payment on invoice for costs incurred during NRC roview of Revs 8 & 9 to Topical Rapt NU-OA-1. MROCZKA,E J. SEARS,C.F. Connecticul Yanksu Atomic Powor Co. SEARS,C.F. Northoast Nuclear Energy Co. (subs. of Northoast Utitios). 88704708. Document Co-trol Branch (Document Control Desk). 4pp. 45091.001-45091.004

8804190041 Withdraws 880301 request for changes to Tech Spac 6.2.3.4 re part records Tech Spac 6.2.3. "Independent Safety Engineering Group (ISEO)." end MROCZKA.E.J. Northeast Nuclear Energy Co. (subs of Northeast Unites) MROCZKA.E.J. Northeast Unites, 88/04/12. Document Control Branch (Document Control Desk). 2pp. 45208.323-45208-325

-8804190045 Proposed Toch Spec Section 6.2.3, "Independent Safety Engineering Group (ISEG)"
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 88/04/12 Ip 45208.325-45208.325

8804210077 Requests temporary relief from Tech Space 3.0.4 re Limiting Condition for Operation 3.6.3 for return to operation Prompt relief requested in order to minimize Operation 153 of retain to operation from the following the delay of startup of plant-Foe pard.

MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilises)

MROCZKA,E.J. Northeast Utilises, 88/04/14. Document Control Branch (Document Control Branch (Document

8804220097 Application for amend to Licenso NPF-49 allowing plant startup while uting provisions of Tech Spec 3.6.3 Fee paid MNOCZKAE J. Northeast Nocteat Energy Co. (subs. of Northeast Utities, 88/04/15, Document Control Branch (Document Control Desk). 7pp. 45221:185-45221.183

--9804220098 Proposed Toch Spocs, allowing startup of plant while utilizing provisions of Tech Spec 3 63.

Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 88/04/15 2cp 45221.192-45221.193

8804250236 Grants temporary weiver of comphence from Tech Spec 3.6.3, "Containment Isolation Volves," per justification provided in 880414 ftr. & upon guidance pte sented in Generic Lif. 87-09.

BOGER,B.A. Assistant Director for Region I Reactors. 88/04/15 MROCZKA,EJ Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 45213 160-45213-162.

8804270231 Submits comments supporting proposed rule to ensure that presence of NRC inspectors on power reactor sites should not be announced to licensee personnel Licensee feels rule makes sense but not practicable.

MROCXMA.E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). SEARS.C.F. Northeast Utilities. 88/04/18. Docketing & Services Branch. 3pp. 45944-92-4.45944-94. 45244 247 45244 249.

8804280611 Forwards Amend 17 to License NPF-49 & safety evaluation. Amend revises Tech Spec 3/4.4.6, "HCS Leakage," to allow continued operation for up to 30 days w/stated redioactivity monitoring syst inceptrable if certain conditions mol FERGUSON,R.1. Project Directorale 1-4. 88/04/18. MRCCZKA,E. J. Northoast Nuclear Energy Co. (subs. of Northoast Utilities). 2pp. 45268.202-45268.301.

--8804280612 Amend 17 to License NPF-49, revising Tech Spec 3/4.4.8, "RCS Leakage," to allow continued operation for up to 30 days w/ containment almospheric gaseous & particulate radioactivity monitoring sys inoperable when certain conditions STOLZ,J.F. Project Directorate I-4, 88/04/18, 5pp. 45268 294-45268 298

--8804280613 Safety evaluation supporting Amond 17 to Licenso NPF-49
* Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/18
3pp 45268.299.45288.091

8804280285 Forwards "Plant-Specific Details re ATWS Mitigation Sys Actuation Carculary lor Millstone Unit 3 "MAOCZKA,E.J., SEARS,C.F. Northeast Nuclear Energy Co. (subs of Northeast Utilities). MAOCZKA,E.J. Northeast Utilities). MAOCZKA,E.J. Northeast Utilities). MAOCZKA,E.J. Northeast Utilities. B8/04/20. Document Control Branch (Document Control Dask). 2pp. 45288 260-45268 287.

-- 8804280287 "Plant-Specific Details re ATWS Mitigation Sys Actuation Circuitry for Milestone Unit 3. "Clear Energy Co. (subs of Northeast Utilities), 88/04/30 26pp 45268 262-45268 287

8804290282 Advises that Tech Spec rev re specific distance for taking radiation measurements in areas where dose rates exceed 1,000 mrem/h will be processed & submitted to NRC to provide improved & consistent program on high radiation areas. MROCZKA,E.J., ROMBERG.W.D. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA,E.J. Northeast Utilities. 88/04/22. Document Control Branch (Document Control Desk). 2pp. 45282-181-45282-182.

Q. Inspection reports, IE Bulletins & correspondence

8804120293 Notification of Significant Licenses Meeting 88:030 on 880308 in King of Prussla,PA to discuss low temp overpressure transient Agenda encl. MCCARE,E.C. Region 1, Otc of the Director, 88/02/25. Region 1, Otc of the Director. 2pp. 45080,045-45080,046.

8804010269 Forwards Enforcement Conference Insp Rept 50-423/88-03 on 880308. KANE,W F. Region 1, Otc of the Director. 88/03/23. MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 45033;096-45033;143.

--8804010272 Enforcement Conference Insp Rept 50-423/88-03 on 880308. Major areas discussed root cause analysis & corrective actions for overpressure transient that occurred at low temp w/o required overpressure protection sys being in svc. MCCABE.E.C. Region 1, Ofc of the Director. 88/03/14, 46pp. 45033-988-45033-143

- 8904040011 Forwards request for addit info re util responses to IE Bulletin 85:003, "Motor-Operated Valve Common Mode Fallures During Plant Transients Due to Improper Switch Settings "Info requested within 80 days of Itr date. BETTENHAUSENL. Region 1, Ofc of the Director, 887/03/24, MROCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 3pp. 45020-281-45020-283.
- 8803310043 Responds to NRC Bulletin 88-001, "Detects in Westinghouse Circuit Breakers." Two reactor trip breakers & two reactor trip bypass breakers subj to bulletin used at Millistone Unit 3 Main pole shaft weld injays completed by 880225. MROCZKA,E.J. Connecticut Yankee Atomic Power Co. 88/03/25. RUSSELL,W.T. Reg on 1, Ofc of the Oirector. 2pp. 44984:136-44964:137.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-tiouse Reactors" Svc list encl. ROSSICE. Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995-246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees:Lack of Mgt Controls Over Licensed Programs" Svc list encl. CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 88/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44985;247-44995 353
- 8804120354 Provides status of implementation plan to reduce illuminated control room annunciators After Unit 3 refueling outage,17 annunciators eliminated & alarm logic of 2 annunciators modified per Insp. Rept 50-423786-12.
 MROCZKA,E,J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MROCZKA,E,J. Northeast Utilities 88/04/05. Document Control Branch (Document Control Desk). 6pp. 45088-346-45088.351.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svc list encl. ROSSI.C E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051.
- 8804190248 EN-88-027 on 880412.notice of proposed imposition of civil penalty in amount of \$50,000 will be issued based on failure of cold overpressure protection sys to be operable prior to & during pressure transfert when sys could have actuated. LUEHMAN_J, LIBERMAN_J, Of cold Enforcement (Post 870413), 88/04/07, 1p. 45208.054-45208.054.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc was enci. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150
- 8804210159 Responds to NRC 880314 ltr re violations noted in Insp Rept 50-423/88-02 Corrective action cooling flow lineup to pump A corrected & plant heatup procedures revised MROCZKA,E.J., SEARS,C.F., Northoast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA,E.J. Northeast Utilities. 88/04/13. RUSSELL,W.T. Region 1, Olc of the Director 3pp. 45227:194-45227:196.

8804130051 Monthly operating rept for Mar 1988,W/880408 ltr. ELMS,A.L., SCACE,S.E. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). SCACE,S.E. Northeast Utilities. 88/03/31. 4pp 45/32:273-45132:276.

S. Reportable occurrences, LERs & related correspondence

- 8804010001 LER 88-011-00 on 880222 & 29 containment leakage detection sys surveiltances missed Caused by personnel error re transfer of incorrect surveillance frequen-cies during procedural rev.Memo distributed W/860323 tt., JOSEPH,V.R., SCACE,S.E. Northeast Utilities, SCACE,S.E. Northeast Nuclear Energy Co. (subs. of Northeast Utilities), 88/03/23. 6pp. 45008:134-45008:138.
- 8804060055 Part 21 rept re faited Rosemount capacitive-type flow transmitters during first cycle of operation.initially reported on 880324.Caused by loss of oil in sensor module. Affected transmitters replaced.
 MROCZKA.E.J. Northeast Utilities, MROCZKA.E.J. Northeast Utilities,
- 8804070118 Special reption 880304,valve found Improperly locked during NRC insplictor. Caused by personnel error. Valve lineup performed & required to be locked, checked & confirmed to be locked.

 SCACE,S.E. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). SCACE,S.E. Northeast Utilities. 88/04/04. Document Control Branch (Document Control Desk). 2pp. 45076:110-45076:111.
- 8804200366 PNO-1-88-041:on 880414,unidentified leak exceeded 6 gpm limit.Leak iden-tified from PORV block valve packing leakoff line Manual valve in leakoff line shut off.Checks for leaks & high temp investigation continuing. RAYMOND,W., MCCABE,E., BETTENHAUSEN,L. Region 1, Ofc of the Director. 68/ 04/15, 1p. 45221:155-45221:155.
- 8804280295 LER 88-012-00:on 880318.fire boundary door found blocked open by temporary air hose w/o hourly lire watch patrols. Caused by procedural deliciency. Hose removed & door closed to reestablish lire barrier. W/880418 lir.

 MARSHALL,F.M., STETZ,J.P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MARSHALL,F.M. Northeast Utilities. 88/04/18. 4pp. 46251.098-45251:101.

V. Operator Examinations

- 8804250088 Responds to FOIA request for info re-scores of reactor operators & senior reactor operators. Forwards requalification exam summary source sheets listed in enct app w/personal privacy into deleted.

 GHIMSLEY.D.H. Division of Rules & Records (Post 870413), 88/04/19. BOLEY.K. Public Citizen's Critical Mass Energy Project. 2pp. 45213:003-45213:095.
- --8804250167 Package of NRC administered requalification exam results summary.

 NRC No Detailed Atfiliation Given. 87/07/20, 88pp. 45213:007-45213:095.

DOCKET 50-424 ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8803290340 Page 24 of 28 to Roy 12 to Procedure VEGP 91002-C, "Checklist 4 Event Notication Worksheet
 - Georg 8 Power Co. 88/03/04, 2pp. 44945;104-44945;105
- 8803290344 Forwards summary of 880119 meeting w/util at plant site in SALP Hepts 50-424/87-58 & 50-425/87-40 orgata to app to SALP repts,incorporating util response to comment on tire protection & v.ewgraphs used during presentation GHACE_J N. Region 2. Otic of the Director. 88/03/07. HEAD,G F. Georg a Power Co. 40pp. 44961:351-44962-043
- 8804040089 Rev 7 to Emergency Plan Implementing Procedure 91204-C, "Emergency Response Communications
 - Georgia Power Co. 88/03/08 54pp 44969:119-44969.172
- 8804040106 Rev 5 to Emergency Plan Implementing Procedure 91501-C, "Recovery." Goorgia Power Co. 88/03/11, 20pp. 44971:302-44971;321.
- 8803300016 Forwards Rev. 10 to emergency plan,incorporating organizational changes through 880217.
 GUCWALT. Georgia Power Co. 88/03/15. Document Control Branch (Document Control Disk), 8pp 44852-314-44853,124
- --8803300018 Rev 10 to emergency plan.W/one oversize map * Georgia Power Co. 88/03/15, 300pp. 44952 323-44953 124.
- 8803250301 Ack receipt of scope & objectives for rad alogical emergency preparedness exercise scheduled for 880524 COLLINS.D.M. Region 2, Ofc. of the Director. 88/03/18. HEAD,G.F. Georgia Power Co. 2pp. 44945 003-44945 004.
- 8803290347 Revised emergency plan Implementing procedures.Including Rev 5 to 98104-C, "Dutles of Operations Support Cir Managar," Rev 5 to 91101-C, "Emergency Response Organization." & Rev 12 to 91002-C, "Emergency Notifications." W/ 980018 It.
- 8803250137 Forwards rovs to physical security & contingency plan Rovs withhe'd (ref. 10CFR73 21 & 2789) Revised security p'an pages incorporating changes will be pro-vided in upcoming amend.

 GUCWALT. Georga Power Co. 88/03/21. Document Control Branch (Document Control Desk). 2pp. 44961.347-44961.348
- 8804250013 Rev 5 to 91602-C, "Emergency Dri Is & Exercises." BOCKHOLD,G Georgia Power Co. 88/03/21 18pp. 45248:124-45248:141.

GUCWA,L.T. Georgia Power Co. 88/03/18 64pp 44978:344-44979:047.

- 8804250082 Forwards Insp Ropts 50-424/88-14 & 50-425/88-11 on 880222-26 & notice of violation.Concern expressed re implementation of security program that permitted situation Notice of violation withhold (ref 10CFR2 790 & 73 21). STOLRB, P. Rogton 2, Old of the Director, 88/03/30 HEAD,G.F. Georgia Power Co 3pp. 45239-215-45239 218
- --8804250085 Partially Withheld Physical Security Insp. Repts 50-424/88-14 & 50-425/88-11 on 880222-26 Violations noted Major areas inspected mgt effectiveness, security program & physical protection Dola is withheld (ref 10CFR2.790 & 73.21). TILLMAN,A., THOMPSON,D. MCGUIRE,D.R. Region 2, Oto of the Director. 88/03/ 28. 1p. 45239 218-45239 218.
- manning at plant to perform alternate romote shutdown while simultaneously conducting tine lighting activities. List of attendeds also encl.

 NELSON.J. Rogion 2, Old of the Director. 88/03/31. HEAD,G.F. Georgia Power Co.

 17pp. 45022:046-45022:062. 8804070067 Forwards 880210 enforcement conference summary ro adequacy of shift
- 8804250033 Forwards Insp Rept 50 424/88 15 on 880227 0325 No violations or devi-
- ations noted.
 BROWNLEE,V.L. Region 2, Old of the Director, 88/04/12. HEAD,G.F. Georgia Power.
 Co. 2pp. 45254 162-45254;175.
- --8804250034 Insp Rept 50-424/88-15 on 880227-0325 No viciations or deviations noted Major areas inspected plant operations, radiological controls,maint,surveillance,fine protection, security & quality programs. ROGGE_JF., BURGER_C.W., SINKULE,M.V. Region 2, Ofc of the Director, 88/04/11, 12pp. 45254
- 8804250095 Responds to violations noted in Insp. Rept. 50-424/88-13. Corrective actions:health physics staff meeting held on 880224 to discuss events surrounding violation & requirements for proper surveys after resin transfers. GUCWALT. Georgia Power Co. 88/04/14 Document Control Branch (Document Control Desk). 11pp. 45237:114-45237:124.
- 8804260188 Forwards Insp. Rept. 50-424/88-16 on 880307-10 No violations or dovi-ations noted. Util attention to unresolved item identified in insp. invited. HERDT,A.R. Region 2, Old of the Director. 88/04/15 HEAD,G.F. Georgia Power Co. 2pp. 45254-250-45254-280.
- --8804280190 Insp Rept 50-424/88-16 on 880307-10.No violations or deviations orded Major areas inspected areas of safe shuldown of facility w/limited staff in event of main control room fire & equipment actuations.

 HUNT,M.D., RUFF.A.B., TAYLOR,P.A. Region 2, Otc of the Director. 89/04/14 9pp. 45254:252-45254:260.
- 8804260293 Forwards Rev 5 to Emergency Plan Implementing Procedure 91602-C.W/o encl. GUCWA,t..T. Georgia Power Co. 88/04/15. Document Control Branch (Document Control Desk). 2pp. 45260:003-45260:004.

168 **DOCKETED ITEMS**

1. Financial information

- 8804279175 Forwards 1987 annual Fnancial repts for Georgia Power Co & Southern Co. GUCWA,L.T. Georgia Power Co. 88/04/19. Document Control Branch (Document Control Dask) 2pp. 45260-103-45280-220.
- -8804270182 "Georgia Power Co. 1987 Annual Rept." SCHERER,R.W. Georgia Power Co. 87/12/31, 45pp. 45260;112-45260;156.
- -- 8804270183 "Southern Co. 1987 Annual Rept." ADDISON,E.L. Southern Co. 87/12/31, 84pp, 45260:157-45260:220.

J. Insurance & Indemnity Information

8904010263 Submits present levels & sources of insurance for plants, per 10CFRS0.54(w)(4) GUCWAL.T. Georgia Power Co. 88/03/18. Document Control Branch (Document Control B

K. Utility Final Safety Analysis Report (FSAR) & amends

- 8804060098 Forwards Amend 35 to FSAR, including changes to Section 17.1, "QA During Design 8 Const," per 10CFR50.55(f) Description of changes enci. R:CE,P.D. Georgia Power Co. 88/03/30, Document Control Branch (Document Control Desh.) 2pp. 45025 001-45028 031.
- --8804060100 Amend 35 to FSAR for Vogtle Electric Generating Plant.

 * Georgia Power Co. 88/03/30. I,109pp. 45025:003-45028:031.

P. Operating license stage documents & correspondence

- 8803240426 Goneric Ltr 88-06 to all power reactor licensees & applicants re removal of organization charls from Tech Spec administrative control requirements. Svc list encl. MIHAGIA,F J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp, 44972.107-44972;153.
- 8803310019 Application for amend to License NPF-88, revising Tech Spec 3.7,6 to additional stalling that differential pressure requirement of Spec 4.7.6.e.3 may be walved during emergency HVAC testing Fee paid.

 HEAD,G.F. Georgia Power Co. 88/03/23. Document Control Branch (Document Control Desk). 9pp. 44953:244-44953:254.
- -8803310021 Proposed Tech Specs re-control room emergency filtration sys. * Georgia Power Co. 88/03/23, 2pp. 44953;253-44953;254.
- 8804010194 Summary of 880318 meeting w/utils in Rockville,MD re info that would be required in submittal of amenda to licenses & CP held by utils Attendees list & viewgraphs encl. ADENSAM.E.G. Project Directorate II-1, 88/03/25, Project Directorate II-1, 25pp. 44920/08/2/4920:108.
- 8804070017 Forwards addition to Generic Lit 83-28, Item 2 2.1 per NRC request, GUCWA,L.T. Georgia Power Co. 88/03/28. Document Control Branch (Document Control Desk), 4pp. 45022:104-45022:107.
- 8804080081 Forwards notice of consideration of Issuance of amend to License NPF-88 & opportunity for hearing re 880204 request to change Tech Spec 3.6.22 concerning spray add two sys & bases. HOPKINS.JE. Project Directorate If-3, 88/03/29. HEAD,G.F. Georgia Power Co. 2pp. 45019:004-45019:010.
- --8804010148 Notice of consideration of issuance of amend to License NPF-88 & opportunity for hearing Amend revises upper & lower vol limits for sodium hydroxide solution in soray add. Hive tank.

 HOOD,0.8. Project Directorate II-3, 88/03/29. 5pp. 45019:006-45019:010.
- 8804070322 Forwards supplemental summary rept on DCRDR showing increase in human engineering discrepancies as determined by additional operator surveys,per util 880229 commitment. GUCWA,L.T. Georgia Power Co. 88/03/31. Document Control Branch (Document Control Desk). 7pp. 45048:288-45048:294.
- 8604110053 Forwards environ protection plan issued on 870116 for facility for inclusion as App B to OL.
 BAILEY, J.A. Georgia Power Co. 88/04/05, Document Control Branch (Document Control Desk). 1p. 45128:144-45128:159.
- --8804110056 "Environ Protection Plan (Nonradiological),"
 " Georg's Power Co. 87/01/16, 15pp. 45128:145-45128:159,
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50-48, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45184:285,
- 8804130281 Notification of 890427-29 meetings w/util in Waynesboro,GA to discuss draft combined Tech Space for plant Draft agenda encl. HOPKINS,J.B. Project Directorate it-3, 88/04/07. CROCKER,L.P. Project Directorate it-3, 4pp. 45103:146-45103:151.
- 8804140229 Responds to util 880314 ltr Informing NRC of plans to seal & abandon Well 807A.NRC conveys neither approval or disapproval re restoration of Well 807A for site decommissioning. HOPKINSJ.B. Project Directorate II-3. 88/04/08. HEAD,G.F. Georgia Power Co. 2pp. 45118.176.45118:177.
- 8804150168 Discusses 880318 meeting w/util 16 proposal to form operating company to handle operation of subj plants. Summary of meeting issued separately. ADENSAM.E.G. Project Directorate III., 88/04/08. LONG,L.B. Southern Gompany Services, Inc. 19pp. 45141:185-45141:203.

- 8804200164 Advises that Westinghouse "Sensitivity Study & Safety Evaluation," submited w/util 880129 application for temporary exemption from compliance w/ 10CFR50.46 may be regarded as nooproprietary & released to PDR. GUCWALT. Georgia Power Co. 88/04/11. Document Control Branch (Document Control Desk), 1p. 45177.182-45177;182.
- 8804200215 Forwards qualification Into provided by Westinghouse re ATWS mitigation sys actuation circuity sys being installed at facility. GUCWALT. Georgia Power Co. 88/04/11. Document Control Branch (Document Control Dask). 4pp. 45177-248-45177-252.
- 8804210019 Forwards Rev 3 to inservice testing program utilized for Inservice testing of pumps & valvas,for review & approval. Rev Incorporated changes in 871927 fit. GUCWALLT, Georgia Power Co. 88/04/13. Document Control Branch (Document Control Desk). 2pp. 45238 295-45238:304.
- -8804270220 Rev 3 to Inservice Test Program ISI-P-008, "Summary of Changes," * Georgia Power Co -88/04/13, 8pp. 45238:297-45238:304.
- 8804260281 Forwards updated listings of outstanding licensing requests for plant U2 prepared to discuss & provide any add into required by NRC in review of subjissues GUCWALT. Georgia Power Co. 88704/14. Document Control Branch (Document Control Desk). 3pp. 45253:037-45253:039.
- 8804220063 Advises that emend to Tech Spec 4.6.2, "ECCS Subsystems-Tavg Greater Than or Equal to 350 F" necessary Changes consisting of asterisk statement to valves on encl example should be submitted.

 HOPKINS.J.B. Project Directorate II-3. 88/04/15, HEAD,G.F. Georgia Power Co. 4pp. 45201:001-45201.004.
- 8804220230 Forwards Amend 4 to License NPF-68 & safety evaluation. Amend mod-ties Tech Specs to allow preoperational positive pressure testing of emergency HVAC
 - ays. HOPKINS,J.B. Project Directorate il-3. 88/04/16. HEAD,G F. Georgia Power Co. 2pp. 45201:147-45201:159.
- --8804220233 Amend 4 to License NPF-88,modifying Tech Specs to allow preoperational positive pressure testing of emergency HVAC sys. CROCKER,L. Project Directorate II-3, 88/04/16, 7pp. 45201;149-45201;155.
- -8804220236 Safety evaluation supporting Amend 4 to License NPF-69.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/16, 4pp. 45201:166-45201:159.
- 8804280516 Advises that analysis of PTS contained in Amend 25 to FSAR, submitted w/860919 itr.meets requirements of 10CFR50.61, "Fracture Toughness Regulrements for Protection Against PTS Events"
 HOPKINS. JB. Project Directorate It-3, 88/04/21, HEAD,G.F. Georgia Power Co., 1p 45265:040-45265:040.
- 8804280472 Advises that reduced separation distances for cable & raceway configura-tions may involve unreviewed safety question because probability of occurrence of mailunction of equipment important to safety may be increased. HOPKINS.JB. Project Directorate II-3 88/04/22. HEAD,G.F. Georgia Power Co. 2pp. 45271:026-45271:027.
- 8804290136 Requests remittance of fee required for 880115 application for exemption from schedular requirements of 10CFR50.71(e) re submittal of rev to original FSAR. DIGGS.R.M. License Fee Management Branch. 88/04/25. CONWAY,R.E. Georgia Power Co. 1p. 45322:183.45322:183.

Q. Inspection reports, IE Builetins & correspondence

- 8803290344 Forwards summary of 880119 meeting w/util at plant site re SALP Repts 50-424/87-58 & 50-425/87-40,errate to app to SALP repts incorporating util response to comment on fire protection & viewgraphs used during presentation. GRACE_JN. Region 3, Oic of the Director. 86/03/07, HEAD.G.F. Georgis Power Co. 40pp. 44961:351-44962:043.
- 8803310302 Forwards request for addl Info re util 860413.0513.0828, 870304 & 0904 responses to IE Bulletin 85-003, "Motor Operated Valve Common Mode Fallures During Plant Transients Due to Improper Switch Seltings." HERDT.A. R. Reglon 2, Old of the Director. 88/03/24, HEAD,G.F. Georgia Power Co. 3pp. 45001:001-45001:003.
- 8804060283 Ack receipt of 880314 ftr Informing NRC of steps taken to correct violations nated in Insp. Rept 50-424/87-69.

 JULIAN.C.A. Region 2, Ofc of the Director. 88/03/25. HEAD,G.F. Georgia Power Co. 1p. 45007.313-45007.313.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors." Syc list and.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:248.
- 8803220296 NRC Into Notice 88-010, "Matis Licensees:Lack of Mgt Controls Over Ucensed Programs." Svc list encl. CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 870728). 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995 353.
- 8804050360 Forwards Insp Rept 50-424/88-07 on 880125-29 & notice of deviation. JULIAN,C.A. Region 2, Otc of the Director. 88/03/30, HEAD,G.F. Georgia Power Co 2pp. 45045;164-45045:184.
- -8804050368 Notice of deviation from insp on 880125-28.Deviation noted: licensee emergency operating procedures for natural circulation cooldown required operators to use graph that was not self-explanatory. JULIAN,C A. Region 2, Ofc of the Director, 88/03/30, 1p. 45045:166-45045:166.
- -8804050371 Insp. Rept. 50-424/88-07 on 880125-29.Deviation noted Major areas inspected licensed operator training 8 emergency operating procedures. MOORE.P., SHYMLOCK.M. Region 2, Ofc. of the Director, 88/03/29, 18pp. 45045-187-45045-184.

- 8804250082 Forwards Insp Ropts 50-424/88-14 & 50-425/88-11 on 880222-28 & notice of violation Concern expressed re implementation of security program that permitted studion Notice of violation withhold (ref. 10CFR2.790 & 73.21). STOIR1,P. Region 2, Olic of the Director. 88/03/30, HEAD,G.F. Georgia Power Co. 3pp. 45239.215-45239.218.
- -8804250065 Partially Withheld Physical Security Insp Repts 50-424/88-14 & 50-425/88-11 on 880222-26 Violations noted Major areas inspected mgt effectiveness, security program & physical protection Details withheld (ref 10CFR2.796 & 73.21). TILLMAN.A., THOMPSON.D., MCGUIRE, D.R. Region 2, Ofc of the Director. 88/03/28, 1p. 45239.218-45239.218.
- 8804070067 Forwards 880210 enforcement conference summary re adequacy of shift manning at plant to perform offernato remote shutdown white simultaneously conducting fire lighting activities. List of attendees also encl. NELSON,J. Region 2, Oic of the Director. 88/03/31. HEAD,G.F. Georgia Power Co. 17pp. 45022.046-45022.082.
- 8804120027 Ack receipt of 880310 ftr informing NRC of steps taken to correct violations noted in insp Repts 50-424/08-05 & 50-425/08-05. HERDI.A.R. Region 2, Ofc of the Director. 98/03/31. HEAD,G.F. Georgia Power Co. 2pp. 45131:110-45131:111.
- 8804120018 Ack receipt of 880321 litr Informing NRC of steps taken to correct violations noted in lasp Rept 50-424/88-06.
 HERDT_AR. Region 2, Oic of the Director, 88/04/04. HEAD,G F. Georgia Power Co. 2pp. 45135-347-45135
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Molor Control Cir &/or Switchboard Function Due to Faulty Tie Bolts," Svc list encl. ROSSICE. Division of Operational Events Assessment (Post 870411). 88/04/07, Consolidated Edison Co. of New York, Inc. 124pp. 45408:292-45407:051.
- 8804130275 Responds to NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakers." No Westinghouse Models DS-206.DSL-206, DS-416.DSL-416 or DS-420 breakers in Class 15 circuits at Hatch.
 GUCWALT. Georgia Power Co. 88/04/07. Document Control Branch (Document Control Desk). 5pp. 45154:065-45154:069.
- 8804060370 NRC Info Nolice 88-012, "Overgroasing of Electric Motor Bearings" Svc list encl. ROSSIC.E. Division of Operational Events Assessment (Post 870411), 88/04/12, Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150.
- 8804250028 Ack receipt of 880311 revised response to violations noted in Inso Rept 50-424/87-57 & documents meeting w/util on 880325 re Violation 8 in Insp rept Violation occurred as stated in notice of violation. GIBSONA F. Region 2, Oic of the Director. 88/04/12. HEAD,G.F. Georgia Power Co. 3pp. 45251:117-45251:119.
- 8804250033 Forwards Insp Rept 50:424/88-15 on 880227-0325.No violations or deviations noted. BROWNLEE.V.L. Region 2, Ofc of the Director, 88/04/12, HEAD,G.F. Georgia Power Co 2pp. 45254:182-45264:175.
- -8804250034 Insp. Rept. 50-424/88-15 on 880227-0325 No violations or deviations noted Major areas inspected plant operations, actiological controls, maint, surveillance, fire protection, security & quality programs. ROGGE_JF., BURGER_C.W., SINKULE,M.V. Region 2, Ofc of the Director. 88/04/11. 12pp. 45254.164-45254:175.
- 8804250095 Responds to violations noted in Insp Rept 50-424/88-13. Corrective actions health physics staff meeting held on 880224 to discuss events surrounding violation & requirements for proper surveys after resin transfers. GUCWA, I.T. Georgia Power Co. 68/04/14. Document Control Branch (Document Control Desk). 11pp. 45237:114-45237:124.
- 8804280188 Forwards Insp. Right 50-424/88-16 on 880307-10 No violations or deviations noted. Util attention to unresolved item identified in Insp Invited. HERDT.A.R. Region 2, Olf of the Director. 88/04/15. HEAD,G.F. Georgia Power Co. 2pp. 45254-250-45254:260.
- -8804260190 Insp. Rept. 50-424/88-18 on 880307-10.No violations or deviations noted Major areas inspected areas of safe shuldown of facility w/limited staff in event of main control room line & equipment actuations. HUNT,MD, RUFF,A B., TAYLOR,P.A. Region 2, Ofc of the Director. 88/04/14, 9pp. 45254:252-45264:260.
- 8804270236 Forwards response to NRC fir re violations noted in Insp Rept 50-424/68-09 Corrective actions technician involved counseled & hydrogen field feads labeled to identify terminals to which leads are to be connected. GUCWA,L.T. Georgia Power Co. 88/04/18, Document Control Branch (Document Control Desk). 10pp. 45245:269-45245:278.

- 8804040277 Addends to annual rept for 1987, consisting of secondary side water chemistry rept.W/860328 ltr.
 GUCWA,L.T. Georgia Power Co. 87/12/31, 15pp. 44970;278-44970.290.
- 8804250054 "Annual Environ Operating Rept for 1987." W/880415 ftr. GUCWA,L.T. Georgia Power Co. 87/12/31. 13pp. 45239;194-45239:206.
- 8804040037 Forwards "ECCS Outage Data for 1987," per Chapter 13,5ection 13.5.1.1.N of plant FSAR & NUREG-0737,ttern ILK.3.17. GUCWALT. Georgia Power Co. 88/03/26. Document Control Branch (Document Control Desk). 1p. 44970.054-44970.058
- -8804040039 "ECCS Outage Data Rept for 1987."
 * Georgia Power Co. 87/12/31, 4pp. 44970.055-44970.058.
- 8804220023 Monthly operating rept for Mar 1988.W/880415 ltr.
 DILWORTH,S.C., GUCWA,L.T. Georgia Power Co. 88/03/31. 7pp. 45221:206-45221:212.

S. Reportable occurrences, LERs & related correspondence

- 8804080012 Special reption 880128,two motor operated gate valves in RHR sys falled. Caused by overheating of motor operators. Design change for valves implemented to preclude pressure locking in future, Mod successful during valve test. GUCWA,LT. Georgia Power Co. 88/03/31, Document Control Branch (Document Control Desk). 7pp. 45092/212-45092.218.
- 8804080055 LER 87-069-01 on 871120.ptant operated above max power level specified in OL Caused by nuclear instrumentation being allowed to indicate below caforimetric value.Procedures revised & computer point U1118 validated Wh880331 ltr. BURNS.W.E., GUCWA,L.T., Georgia Power Co. 88/03/31. 8pp. 45100.071-45100.076.
- 8804130117 LER 87-021-01:on 870501, control room Isolation in-liated by radiation monitor loss of power. Causad by false signal from Monitor 18E-12116 due to failure of data processing module (DPM). DPM repfaced W/880407 ltr. BURNS,W.E., GUCWA,L.T. Georgia Power Co. 88/04/07. 5pp. 45131.064-45131.068.
- 8804130120 LER 87-005-05:on 870405,control room ventilation isolation signal experienced Caused by Introduction of voltage transferts on 120-y ac vital supply whenever safety leatures sequencer sys re-energized Component replaced.W/880407 ltr.
 BURNS.W.E., GUCWA,L.T. Georgia Power Co. 88/04/07, 11pp. 45142:201-45142:211.
- 8804210277 Part 21 & deficiency reptire damage to emergency diesol generator jacket water HX during flushing Initially reported on 860917.HX repaired & installed in Unit 2.Thermostatic valves being modified.

 RICE, P.D. Georgia Power Co. 88/04/14. Document Control Branch (Document Control Desk), 3pp. 45235-257-45235-259.

V. Operator Examinations

- 8804050360 Forwards Insp Rept 50-424/88-07 on 860125-29 & notice of deviation. JULIAN C.A., Region 2, Otc of the Director. 88/03/30. HEAD,G.F., Georgia Power Co. 2pp. 45045.164-45045:184.
- --8804050371 Insp Rept 50-424/66-07 on 680125-29.Deviation noted.Major areas inspected,ilcensed operator training & emergency operating procedures. MOORE.P., SHYMLOCK,M. Region 2, Otc of the Director. 88/03/29 18pp 46045-167-45045-184.

DOCKET 50-426 ALVIN W. VOGTLE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

- 8803310145 "Inservice Test Program."
 * Georgia Power Co. 88/03/02, 150pp. 44965:119-44966:043.
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re romoval of organization charts from Tech Spec administrative control requirements. Svc list encl. MIRAGLIA.F.J. Associate Director for Projects (Post 870411). 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804010194 Summary of 880318 meeting w/utils In Rockville.MD re info that would be required in submittel of amends to licenses & CP held by utils Attendees list & viewgraphs encl.

 ADENSAM.E.G. Project Directorate II-1, 88/03/25. Project Directorate II-1, 25pp. 44920:082-44920:106.
- 8804040065 Forwards inservice test program of pumps & valves for review & approval.per SER Confirmatory Item 13. BAILEY, J.A. Georgia Power Co. 88/03/25. Document Control Branch (Document Control Desk). 3pp. 46020:320-45020.322.
- 8804070017 Forwards addit Info re Generic Ltr 83-28, item 2.2.1 per NRC request. GUCWA,L.T. Georgia Power Co. 88/03/28. Document Control Branch (Document Control Desk). 4pp. 45022:104-45022:107.
- 8804110216 Summary of 880322 meeting w/util In Rockville,MD to discuss 880116 draft Tech Specs.Attendee list enct. HOPKINS,J.B. Project Directorate II-3. 88/04/04. Project Directorate II-3. 3pp. 45078;185-45078:188.
- 8804110053 Forwards environ protection plan issued on 970116 for facility for Inclusion as App B to OL.
 BAILEY_J.A. Georgia Power Co. 86/04/05, Document Control Branch (Document Control Desk), 1p. 46128:144-45128:159.
- -8804110055 "Environ Protection Plan (Nonradiological)."
 Georgia Power Co. 87/01/16, 15pp. 45128:145-45128:169.
- 8804080008 Generic Lir 88-07 to power reactor licensees & applicants re-modified enforcement policy concerning 10CFR60.48, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc list enci. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804130278 Forwards request for addl info re spent fuel pool storage in order to complete review. Into on occupational rediation exposure radwastes, accident analyses, potential releases of radioactive mails should be provided. HOPKINS.J.B. Project Directorate II-3, 88/04/07, HEAD,G.F. Georgia Power Co. 7pp. 46101:231-45101:237.
- 8804130281 Notification of 880427-29 meetings w/util in Waynesboro,GA to discuss draft combined Tech Specs for plant.Draft agenda encl. HOPKINS,J.B. Project Directorate II-3. 88/04/07, CROCKER,L.P. Project Directorate II-3. 49p., 45103:148-45103:161.
- 8804160188 Discusses 880318 meeting w/util re proposal to form operating company to handle operation of subj plants. Summary of meeting issued separately.

 ADENSAM,E.G. Project Directorate II-1, 88/04/08, LONG,LB. Southern Company Services, Inc. 19pp. 46141:185-45141:203.

8804260281 Forwards updated iistings of outstanding ficensing requests for plant Uhi prepared to discuss 8 provide any additinfo required by NRC in review of subj issues GUCWALT. Georgia Power Co. 88/04/14. Document Control Branch (Document Control Desk) 3pp 45253 037-45253 039.

8804270065 Forwards plant readiness review program review schedule & Identification of technical reviewers responsibilities re Module 177/19 concerning electrical raceways & supports per agreement reached on 880125 w/util.
REYES,L.A. Dwiston of Reactor Projects •1/11 (Post 870411) -88/04/14, LAINAS,G.C. Assistant Director for Region II Reactors. GIBSON,A.F., NRC • No Detailed Affiliation Given. 19 45241:203-45241:203.

8804280074 Notification of 880504 meeting w/util in Rockville,MD to discuss status of HOPKINS, J.B. Project Directorate N-3, 88/04/19, MATTHEWS, D.B. Project Directorate N-3, 3pp. 45276 096-45276 098.

8804280516 Advises that analysis of PTS contained in Amend 25 to FSAP, submitted w/860919 tr.meets requirements of 10CFR50.61, "Fracture Toughness Requirements for Protection Against PTS Events."
HOPKINS, 19. Project Directorate II-3, 88/04/21, HEAD,G.F. Georgia Power Co. 1p. 45265:040-45265.040.

8804280472 Advises that reduced separation distances for cable & receway configura-tions may involve unreviewed safety question because probability of occurrence of malfunction of equipment important to safety may be increased. HOPKINS,1B Project Directorate It-3, 88/04/22, HEAD,G.F., Georgia Power Co. 2pp. 45271-026-45271.027.

E. NRC Safety Evaluation Report (SER), supple & correspondence

8804040065 Forwards inservice test program of pumps & valves for review & approval per SER Confirmatory Item 13
BAILEY/J.A. Georgia Power Co. 88/03/25. Document Control Branch (Document Control Desk), 3pp. 45020-320-45020-322.

F. Security, medical, emergency & fire protection plans

8803290340 Page 24 of 28 to Rev 12 to Procedure VEGP 91002-C, "Checklist 4:Event Notification Worksheet"

Georgia Power Co. 88/03/04, 2pp. 44945.104-44945:105

8803290344 Forwards summary of 880119 meetin, w/uut at plant site re SALP Repts 50-424/87-58 & 50-425/87-40,errata to app to SALP repts,incorporating util response to comment on fire protection & viewgraphs used during presentation GRACE_JN Region 2, Otc of the Director. 88/03/07. HEAD,G.F. Georgia Power Co. 40pp. 44961:351-44962.043

6804040089 Rev 7 to Emergency Plan Implementing Procedure 91204-C, "Emergency

Georgia Power Co. 88/03/08 54pp. 44969.119-44969.172

8803210067 Discusses level one Finding 2RRF-023-001 re security sys design deficten-cy in Module 23.Phase I of readiness review program Finding more generic than Initial-by Indicated. Broadness review being conducted to Identity problem areas. HICE,P.D. Georgia Power Co. 88/03/10. Document Control Branch (Document Con-trol Desk). 2pp. 45191-008-45191.009

8804040106 Rev 5 to Emergency Plan Implementing Procedure 91501-C, "Recovery." * Georgia Power Co 88/03/11, 20pp. 44971:302-44971:321.

6803300016 Forwards Rev 10 to emergency plan,incorporating organizational changes through 880217.
GUCWALT Georgia Power Co. 88/03/15. Document Control Branch (Occument Control Desk) 9pp. 44952:314-44953:124.

--8803300016 Rev. 10 to emergency plan.W/one oversize map. ' Georgia Power Co. 88/03/15, 300pp. 44852:323-44953:124

8803250301 Ack receipt of scope & objectives for radiological emergency preparedness exercise scheduled for 880524 COLLINS.D.M. Region 2, Otc of the Director. 88/03/18. HEAD,G.F. Georgia Power Co 2pp. 44945:003-44945.004.

8803290347 Revised emergency plan implementing procedures.Including Rev 5 to 99104-C, "Duties of Operations Support Ctr Manager." Rev 5 to 91101-C, "Emergency Response Organization" & Rev 12 to 91002-C, "Emergency Notifications." W/ GUCWA,L.T. Georgia Power Co. 88/03/18, 64pp. 44978;344-44979 047.

8803250137 Forwards revs to physical security & contingency plan Revs withheld (ref. 10CFR73.21 & 2.780) Revised security plan pages incorporating changes will be provided in upcoming amount of the pro-GUCWA_L.T. Georgia Power Co. 88/03/21. Document Control Branch. [Document Control Desk). 2pp. 44981.347.44961.348.

8804250082 Forwards Insp Repts 50-424/88-14 8 50-425/88-11 on 880222-26 & notice of violation Concern expressed re implementation of security program that permitted situation. Notice of violation withheld (ref 10CFR2.790 & 73.21). STOHR, J.P. Region 2, Otc of the Director. 88/03/30. HEAD, G.F. Georgia Power Co. 3pp. 45239:215-45239.218.

--8804250065 Partially Withheld Physical Security Insp. Repts 50-424/88-14 & 50-425/88-11 on 880222-26 Violations noted Major areas inspected mgt effectiveness security program 8 physical protection. Details withheld (ref. 10CFR2.780 & 73.21).

TILLMAN.A., THOMPSON.D., MCGUIRE.D.R. Region 2, Ofc of the Director. 88/03/26, 1p. 45239:218-46239-218.

8804250013 Rev 5 to 91602-C, "Emergency Drills & Exercises." BOCKHOLO,G. Georgia Power Co. 88/03/21, 18pp. 45248:124-45248:141.

٠ . . **ز**

8804270175 Forwards 1987 sinual linancial repts for Georgia Power Co & Southern Co GUCWA,L.T. Georgia Power Co. 88/04/19. Document Control Branch (Documer Control Desk). 2pp. 45260:109-45260;220.

-8804270182 "Georgia Power Co. 1987, Annual Rept." SCHERER,R.W. Georgia Power Co. 87712731, 45pp., 46260:112-46260,156

-8804270183 "Southern Co. 1987 Annual Rept." ADDISON,E.L. Southern Co. 87/12/31, 64pp. 45260:157-45260:220.

K. Utility Final Safety Analysis Report (FSAR) & amends

8804080098 Forwards Amend 35 to FSAR,including changes to Section 17.1, "0, During Design & Const," per 10CFR50.55(f) Description of changes encl. RICE,P.D Beargle Power Co. 88/03/30. Document Control Branch (Document Control Branch (Document Control Branch) (Document Control Branch)

-8804060100 Amend 35 to FSAR for Vogile Electric Generaling Plant.
* Georgia Power Co. 88/03/30. 1,109pp. 45025:003-45028:031.

Q. Inspection reports, IE Bulletins & correspondence

8803290344 Forwards summary of 880119 meeting w/util at plant site re SALP Rept 50-424/87-58 & 50-425/87-40,errata to app to SALP repts,incorporating util response to comment on fire protection & viewgraphs used during prosontation GRACE_J.N. Region 2, Ofc of the Director, 88/03/07, HEAD,G.F. Georgia Power Co 40pp. 44961:351-44962.043.

8603290326 Forwards Insp Rept 50-425/88-14 on 880216-19.No violations or dev ations noted.

JULIAN.C.A. Region 2, Ofc of the Director. 88/03/08, HEAD,G.F. Georgia Power Co
2pp. 44975:222-44975:231.

-8603290330 Insp Rept 50-425/86-14 on 880216-17.No violations or deviation noted. Major areas inspected in-depth QA review of civil (concrete & protective cost ing) work activities WRIGHT.R.W., 8 BELISLE,G.A. Region 2, Olc of the Director. 88/03/04. 8pp 44975:224-44975:231.

8803310302 Forwards request for addl into re util 880413,0513,0828, 870304 & 0304 responses to IE Bulletin 85-003, "Motor- Operated Valve Common Mode Falkers During Plant Transients Due to Improper Switch Settings." HERDT.AR. Region 2, Ofic of the Director. 88/03/24, HEAD,G.F. Georg a Power Co 3pp. 45001:001-45001:003.

8804060283 Forwards Insp Rept 50-425/88-13 on 880229-0304 No violations or devi allons noted.

JULIAN.C.A. Region 2, Oic of the Director, 88/03/25, HEAD,G.F. Georg a Power Co 2pp. 45034:091-45034:100.

-8804060288 Insp. Repl. 60-425/68-13 on 880229-0304.No violations noted. Major areas Inspected-electrical work activities.
WRIGHT.R.W., BELISLE.G.A. Region 2, Oic of the Director. 88/03/22 Spp. 45034:093-45034:100.

8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Syc list encl.
ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/03/28
Consolidated Edison Co. of New York, Inc. 121pp. 44995;128-44995 246.

8803220296 NRC Info Notice 88-010, "Mattis Licensees.Lack of Mgt Controts Over L-censed Programs." Svc list enct. CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870729) 88/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353

8804060293 Forwards Insp Rept 50-425/88-15 on 880307-11.No violations or deviations noted. HERDT.A.R. Region 2, Ofc of the Director. 88/03/29, HEAD.G.F. Georgia Power Co 2pp. 45034;161-45034;167.

--8804060298 Insp Rept 50-425/88-15 on 880307-11 No violations noted. Major areas inspected preoperational testing & readiness review, Module 03A, Phase 1. SZCZEPANIECA, JAPE.F. Region 2, Ofc of the Director, 88/03/29, 5pp 45034-163

8804250082 Forwards Insp Repts 50-424/88-14 & 50-425/88-11 on 880222-26 & notce of violation Concern expressed re Implementation of security program that permitted situation. Notice of violation withheld (ref 10CFR2.790 & 73.21). STOHRJ.P. Region 2, Ofc of the Director. 88/03/30, HEAD,G.F. Georgia Power Co 3pp. 45239:215-45239:218.

-8804250085 Partially Withheld Physical Security Insp. Repts 50-424/88-14 & 50-425/88-11 on 880222-26 violations noted Major areas Inspected mgl effectiveness, securify program & physical protection Details withheld (ref 10CFR2.790 & 73 21). TILLMAN,A., THOMPSON,D., MCGUIRE,D.R. Region 2, Otc of the Director 88/03/28, 1p. 45239:218-45239:218.

8804080275 Forwards Insp Rept 50-425/88-10 on 880222-25 & notice of violation HERDT,A,R. Region 2, Olo of the Director, 88/03/31, HEAD,G,F. Georgis Power Co. 2pp. 45128;110-45128;119.

-8804080276 Notice of violation from insp on 880222.25. Violation noted: three cable tray supports had lire equipment supports welded on w/o field change request to permit weld attachment. permit weld attachment. HERDT.A.R. Region 2, Ofc of the Director 88/03/31, 2pp. 45128:112-45128:113.

- -8804080278 to-sp. Rept. 50 425788 10. on. 880222-25 Violations, nated Major areas asported electrical work observation & recents let inceways & histomonthlion procudum mesow B. werk observation for archamont calibration (CONFOS), 1.1 Buyum 2, Ok. of the Parester 199703730, 6pp. 45120-114.
- 8804120027 Ack record of 880/110 ftr informing NEG of stops laken to correct violations roted in they Bopte 50 424788 05 & 50 425788 05 HEHDLA B. Bogon, 2, Ofc of the Director 8870/17.11 FB AD,G.1 Georgia Power Co 2pp 45134 (30-45131 131
- 8804120104 Forwards Insp. Rept. 50. 425788 D1 on 880104-15 & note a of violation HERDT, A.H. Region 2, Ofc. of the Director (18704704) FB AD, G3 , Georgia Power Ca 2pp. 45122 058-45122 076
- --8804120108 Note a of violation from hep-in-880104-15 Valution noted. ASME Class 1 Mod 2-1201 030-W30 inspector B. nei open to control to control to solution folial toles table con-gatud indication 1 inch in longth contrary to conjurance its in the first table of the Director 18704/04 2pp 45122.060 45122.001
- -8804120110 htsp://Hopt. 50.425788.01 on 880104-15 Violations insted Major inteas inspirited sately related in preg. woldments: 8 comparisonts: 8 supports fatheralted to ASME code, Section III, Claris 1-8-2 KERCH, H.W. Hogon, 2, Olic of the Director: 88702724 - 15pp. 45122-082-45122-070
- 8804010256 NHC Into Notice 08 011, "Potential Cosc of Motor Control Cir 87or Switch-board Function Date to Family To Botte "Svc: 54 and ROSSLCE: Dws on of Operational Events Association (Post 870411) 18704707 Cossolidit
- 8004130275 Responds to NRC Bulletin II8 001, "Defects in Westingbress Circuit Break-ers" No Westingbress Models DS 200,DSL 200, DS-416,DSL-416 or DS 420 break-ers at Case II. Circuit at Butch GUCWA, T. Comigns Power Co. 88704707, Document Control Branch (Occument Control Deck). 5pp. 45154-065-45154-069.
- 8804060370 NRC Into Natice 88 012, "Overgreasing of Unisting Major Hearings," Svc. 1st encl BOSSI,C.E. Davision of Operational Evonto Agreement (Post B70411) 109/04/12. Consolidated Edison Co. of New York, Inc. 12.3pp. 45165-020 45165-150
- 8804200540 Responds to violations noted to help Rept 50.425788-07. Corrective actions for boriout roview conducted on all completed high potential high documentation
- packages DICE P.D. Guorgia Power Co. 88704714 Durannent Cuntral Branch (Occument Con-tel Desk). 2pp. 4523: 017-4523: 018
- 8804280057 Forwards Insp. Rept. 50 425708-18 on 800328-31 No violations or devi-Allong noted HEBDT,A.R. Beg on 2, Ofc. of the Director. 88704718. FILAD,CEF. Georgia Power Co. 2pp. 45248.040-45248.055
- -8804260060 Insp. Rept. 50-425760-18 on 880320-31 No violations of deviations noted Major areas inspected prosperational tosting-actualing test procedure review & witnessing SZCZEPANIEC,A., JAPE,C. Hopton 2, OTc of the Director 08704/14. 5pp. 45248.051-45248 055

9. Reportable occurrences, LERs & reinted correspondence

- 8804210277 Part 21 & delic omy rept ro-damago to emirgoncy dioset generator jacket water 10x damig flustrog folkasy reported on 860017743X reported & installed in Unit 2. Usomostat c vulvus bonig motificat RICE,P.D. George Power Co. 880404744 | Discovent Control Dianch (Document Con-trol Dock), 3pp. 45235-257-45236-250
- 8804210281 Interest distressory rept to control mem essential HVAC sys. In tally report ed on 070014 Addi contern detrambed to be becarted resemble made former calculation Carractive action beyond calculation review nivolven light med RICE_PT General Power Co. 18704714 Decument Centrel Brack (Decument Cen-trol Dosk) 2pp 45231 148-45231 149

DOCKET 50-403 UNIV. OF CALIFORNIA AT SANTA DARIDADA RESEARCH

P. Operating license stage documents & correspondence

- 8803250184 Informa of relocation of NERL to Hockville,MDD flicial moiling address still tamains samo & project inemigent have new furnitions & phone minibre. IS Michaels stillead project namager for facility & A Adam's will serve as backup RUBENSTEIN.L.S. Strinsland-callon & Non-Power Renetor Project Oirectorate. 807/03/ 18. Alfaelion Not Assignant Tipp. 448:B-322-44055-324.
- Q. Inspection reports, IE Dutletins & correspondence
- 8804060199 Informs that info provided in response to NRC Bullidin 87-001 being used To determine one map proposed in regions to tens, mineral or color los og save to determine extent of linkulity participat on & unplementation of erosion/curres.on insp programs & to obtain data on observed page wall them of NERSES, Project Directorate 13, 88703/30, HAHRISON,FJ, Pablic Service Co. of New Hompshire, 3pp. 45018 261-45018 281.

DOCKET STN-60-437 FLOATING NUCLEAR PLANT

A. Application/construction stage documents & correspondence

8803240426 Gunoric Ltr 68 06 to all power reactor licensees & applicants ro removal of organization charts from Tuch Spac admiristrative control requirements Sec 1st enct MiRAGLIA.F.J. Associate Director for Projects (Post 870411) 88703722. Consolidated Edison Co. of New York, Inc. 47pp. 44072 107-44072.153

8804080888 Generic Ltr 88 07 to power reactor licenseus & applicants re-mail fed en-forcement pelicy concrining 10CFH50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Flants" Svc 1st end. MITAGLIA F.3. Associate Director for Projects (Post 870411) 88704707. Consolidated Edison Co. of New York, Inc. 49pp. 45164-237-45164-285.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl L to NRC Into Notice 87-044, "Thirable Tube Training in Wosling-house Reactors" Svc list oncl.

 BOSSICE Division of Operational Events Assessment (Post 870411) 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp. 44895-120-44895-246
- 0603220296 NRC Info Notice 88-010, "Matts Licensees Lack at Mat Centrals Over Liconsid Programs" Svc Isl onc) CUNNINGHAM,H E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44885-247-44995-353
- 8804010256 NDC Info Notice 88-011, "Polent al Loss of Motor Contro! Ctr &/or Switch-Doard Function Due to Faulty Tie Bolls "Sychist and, HOSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/04/07 Consolidated Edison Co. of New York Inc. 124pp. 45466 202-45407 051
- 8804060370 NRC Info Notice 88 012, "Overgreasing of Electric Motor Bearings." Svc let out: HOSSICE Division of Operational Events Assassment (Post 870411) 88704/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165-160

DOCKET 60-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

- 8803240426 Generic Ltr 88-06 to 69 power reactor licensees & applicants re-removal of organization charts from Toch Spuc administrative control requirements Svc 1st end MRAGUA,F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44072 107-44872 153.
- 0804070199 Ferwards TVA employed concerns task group subcategory repts
 RUSSELL J.B. Tannussuo Vattry Authority. 887/03/28 Document Control Branch
 (Occimunt Control Desk), 5pp. 45022.145-45024-257.
- --804070203 Rev 3 to Employed Concerns Special Program Subcategory Engineering Hupt 25000, "Civil/Structural Dueign (21500) & Pipe Why Rostraint Design (22700)." BENKERT, J.W. Tonnesson Valley Authority. 88/03/21. 80pp. 45022:150-45022 238.
- --8804070224 Roy 6 to Employee Concerns Special Program Subcategory Rept 80200, KENZIC,L G. Tunnosseo Vallay Anthonty 88/03/18. 152pp. 45022.335 45023-126.
- --8804070234 Nov 6 to Employue Concorns Special Program Subcategory Rept 80400, "Nonconformatic Control & Corrective Action."

 HALVELSON,H.D. Tunnesere Valley Authority 88703714 494pp 45023:127-45024 257
- 8804080172 Forwards SSER NUREG-1231 rd B&W Owners Group plant reassessment program. Overall ovaluation remains toverable. Add improvement in area of Integrated confrot syst non-microar raminar substact Asia ingrovement in the of integration confrot syst non-microar instrumentation syst roview possibile. We uncl. CHUTCHFIELD, Division of Reactor Projects - Milky & Special Projects (Post 870411) 88/03/31 WILGUS,W S. Beboock & Wilsox Operating Plants Owners Group 7pp. 45076 181-45076 187
- 8604070957 Forwarda listing of umployae concern numbers shown on util data base as NRC responsibility for evaluation not excluded in 861231 submittal Requests ack of responsibility. Representation of the Responsibility Responsibility. Representation of Valley Authority 86/04/01. Document Control Branch (Document Control Dusk). 7pp. 45075-030-45075-042.
- 8004080088 Genoric Ltr 8H-07 to power reactor licensons & applicants re-modified en-forcement policy concerning 10CFH50.49, "Environ Quartication of Electrical Egyp-ment Important to Safuly for Nuclear Power Plants" Syc 1st mict. MILIAGLIAF.J. Associate Director for Projects (Post 8/0411) 88/04/07. Connolidated Edison Co. of New York, Inc. 40pp. 45164:237-45164.205
- 8804210055 Forwards response to questions in Section IV of Generic Etr 86-05, "Impli-mentation of TMI Action Itom II K 3.5, "Automatic Trip of Princior Cootant Purings": Undate to titl provious submitted also und GHIDLEY, P. Turminasou Valuy Authority HB/04713, Occument Control Branch (Decu-ment Control Oesk), 10pp. 45257-165-45257-183

F. Security, medical, emergency & fire protection plans

- 8804180257 Forwards Roy 14 to security poisonnel training & qualification plan Rev withfield GRIDLEY,H.L. Tennoseee Velay Authority 88/04/14 Decument Control Branch (Document Control Dest) 2pp. 45195:338 45195:339
- 8804220250 Rovisud omergency plan Implementing procedures, including flav 0 to CECC-EPIP-1. "Emergency Duty Officer Procedure for Notification of Unsaturi Event, Anti-Site Area Emergency & General Emergency." W/880420 ft GRIDLEY, N.L. Tonnesso Valley Authority 88/04/20 400pp 48229 308-45230.322.

Q. Inspection reports, IE Bulletins & correspondence

8803290366 Forwards Insp. Ropis 50-259/87-38.60-260/87-38.50-296/87-38.50-327/ 87-68,50-329/87-98,50-390/87-18,50-391/87-18, 50-439/87-08 & 50-439/87-08 on 87-1005-18 & notice of wighten BAFRIK P. Roglion 2, Ofc of the Director, 88/03/09 WHITE,S.A. Tennossee Valloy Authority, 3pp. 44975-195-44976-208

- —8803290390 Notice of violation from Insp on 871005-18 Violations noted: inadequate day of nuclear engineering training & records, ineffective followup on audit findings & improper correction of OA records.
 BARR.K.P. Region 2, Oic of the Director. 88/03/09. 3pp. 44975:198-44975 200.
- --8803290193 Insp Repts 50-259/87-38,50-260/87-38,50-295/87-38, 50-327/87-68,50-328/87-68,50-380/87-18,50-391/87-18, 50-391/87-08 & 50-439/87-08 Violations noted Major areas inspected allegations & licensee action on identified tierns. WALTON,G A. Region 2, Orts of the Director. 88/03/08. 8pp. 44975-201-44975-208
- 8804010110 Forwards Insp Repls 50-439/87-10 8 50-439/87-10 on 871214-890314 No violations or deviations noted Unresolved Item re evaluation of structural steel weld & concrete repair stee identified in rept will be pursued in future insp. BARRK P. Oft of Special Projects 88/03/22. WHITE, S.A. Tennessee Valley Authority. 2pp. 45008:139-45008:147.
- --8804010115 Insp Repts 50-438/87-10 & 50-439/87-10 on 871214-880314 No violabons or deviations noted Major areas inspected Prase II welding reinsp.structural steel, concrete & NRC Compliance Bulletin 87-002 (tasteners) YORKU, WALTON,G., ELROD,S. Region 2, Ofc of the Director. 88/03/17. 7pp. 45008
- 8803210090 Suppl I to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors." Svc list end. ROSSICE: Division of Operational Events Assessment (Post 870411) 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:128-44995 246
- 8803220296 NRC Into Notice 88-010, "Matts Licensees Lack of Mgt Controls Over Li-2032/299 YNC into Notice Booth, mails closised than only Control of Control o
- 8804010256 NRC Into Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svc Ist encl. ROSSI,C E. Dwison of Operational Events Assessment (Post 670411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406.292-45407.051.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list end: ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150.
- 8804210017 Summarizes review of NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakers." Builtetin not applicable to Browns Ferry nuclear plant Builtetin applica-ble to Watts Bar & Bellefonte nuclear plants. List of commitments encl. GRIDLEY,R. Tennessae Valley Authority 68/04/13. Document Control Branch (Occu-ment Control Desk). 3pp. 45218-150-45219.152
- 8804220032 Forwards response to NRC Bulletin 87-002, "Fastener Testing to Determine Conformance W/Applicable Tech Specs." Encl 4 identifies testeners transferred from storage & Encl 5 contains list of commitments being made by TVA in response. GRIDLEYR, Tennessee Valley Authority. 89/04/15. Document Control Branch (Document Control Desk). 155pp. 45219:172-45220.028
- 8804280635 Responds to NRC 880309 ltr re violations noted in listed insp repts.including 50-438/87-08,50-439/87-08 & 50-327/87-88.Corrective actions data base constructed for training. GRIDLEYR. Tendessee Valley Authority, 88/04/22, Document Control Branch (Docu-ment Control Desk), 10pp, 45331:341-45331:350.

- 8804060383 "Personnel Whole Body Exposure Repts for 1987." W/880401 ltr. GRIDLEY,R. Tennessee Valley Authority. 87/12/31, 7pp. 45047:060-45047:068.
- 8804130358 Forwards weekly schedule of TVA activities for wks of 880411 & 18.
 KELLY,J.L. Ofc of Special Projects, 88/04/08. ZECH,G.G. Ofc of Special Projects, 4pp. 45103;216-45103;219.

U. Congressional/Executive Correspondence

8804280317 Forwards NRR responses to Questions 1 & 3 re Commission sids for permitting restart of power plant after shutdown for safety reasons & Commission requirements for documenting licensing basis for restart decision, respectively. THOMAS, C.O. Policy Development & Technical Support Branch (Post 870411), 887-04/19, REHM, T.A. Ofc of the Executive Director for Operations, 7pp. 45269-209-45369-218. 45269:215

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIA.F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804070199 Forwards TVA employee concerns task group subcategory repts. RUSSELL,J.R. Tennessee Valley Authority. 88/03/28. Document Control Branch (Document Control Desk). 5pp. 45022:1454-5024:257.
- -8804070203 Rev 3 to Employee Concerns Special Program Subcategory Engineering Rept 25000, "Civil/Structural Design (21500) & Pipe White Restraint Design (22700)," BENKERT,J.W. Tennessee Valley Authority. 88/03/21, 89pp, 45022,150-45022,238.
- -8804070224 Ray 6 to Employee Concerns Special Program Subcategory Rept 80200, KENZIE,L.G. Tennessee Valley Authority. 88/03/18. 162pp 45022:335-45023:126.
- -8804070234 Rev 6 to Employee Concerns Special Program Subcategory Rept 80400, "Nonconformance Control & Corrective Action." HALVERSON,R.D. Tennessee Valley Authority, 88/03/14, 491pp. 45023:127-

- 8804080172 Forwards SSER NUREG-1231 re B&W Owners Group plant reassessment program Overalt ovaluation remains favorable. Addl improvement in area of integrated control sys7 non-nuclear instrumentation sys review possible.W/ro enct. CRUTCHFIELD,D. Division of Reactor Projects III,IV.V. & Special Projects (Post 870411), 88/03/31, WILGUS,W.S. Babcock & Wilcox Operating Plants Owners Group 12012-12012-12013-12018 7рр. 45076.181-45076.187.
- 8804070057 Forwards listing of employee concern numbers shown on util data base as NRC responsibility for evaluation not included in 861231 submittal.Requests ack of response billty.

 RUSSELL,J.R. Tennessee Valley Authority. 88/04/01. Document Control Branch (Document Control Desk). 7pp. 45075:036-45075.042.
- 8804080086 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-torcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equi-ment Important to Salety for Nuclear Power Plants." Svc list encl. MIRAGLIAF.J. Associate Director for Projects (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.
- 8804210055 Forwards response to questions in Section IV of Generic Ltr 86.05, "implementation of TMI Action Item II.K.3.5, "Automatic Trip of Reactor Coolant Pumps" Update to util previous submittats also encl. GRIDLEY,R. Tennessee Valley Authority, 88/04/13. Document Control Branch (Document Control Deak), 19pp. 45257:165-45257:183.

F. Security, medical, emergency & fire protection plans

- 8804180257 Forwards Rev 14 to security personnel training & qualification plan Rev withheld. GRIDLEY,R.L. Tennessee Valley Authority. 88/04/14. Document Control Branch (Document Control Desk). 2pp. 45195:338-45195:339.
- 8804220260 Revised emergency plan implementing procedures,including Rev 6 to CECC-EPIP-1, "Emergency Duty Officer Procedure for Notification of Unusual Event Alert Site Area Emergency & General Emergency," W7880420 ltr. GRIDLEY,R.L. Tennessee Valley Authority, 88/04/20, 400pp. 45229:308-45230:322.

Q. Inspection reports, iE Bulletins & correspondence

- 8803290386 Forwards Insp. Repts 50-259/87-38,50-280/87-38,50-286/87-38 50-321/87-88,50-328/87-88,50-390/87-18,50-391/87-18, 50-436/87-08 & 50-439/87-08 on 871005-18 & notice of violation. BARR,K.P. Region 2. Otc of the Director. 88/03/03. WHITE,S.A. Tennessee Varey Authority. 3pp. 44975:195-44975:208.
- -8803290390 Notice of violation from Insp on 871005-18.Violations noted: inadequate div of nuclear engineering training & records, ineffective followup on audit findings & improper correction of QA records. BARR, K.P. Region 2, Ofc of the Director, 88/03/09, 3pp. 44975:198-44975:200
- --880320393 Insp Repts 60-259/87-39,50-260/87-38,60-296/87-38, 50-327/87-68,50-328/87-68,50-390/87-18,50-391/87-18, 50-439/87-08 & 50-439/87-08 Violations noted Mejor areas Inspected ellegations & licensee action on Identified Items. WALTON,G.A. Region 2, Ofto of the Director. 88/03/08. 8pp. 44875:201-44975.206
- 8804010110 Forwards Insp. Repts 50-438/87-10 & 50-439/87-10 on 871214-880314.No violations or deviations noted. Unresolved Item re evaluation of structural steel weld & concrete repair area identified in rept will be pursued in luture insp. BARRI, P. Oto of Special Projects. 88/03/22. WHITE, S.A. Tennessee Valley Authority. 2pp. 45008;139-45008:147.
- --8804010115 Insp Repts 50-438/87-10 & 60-439/87-10 on 871214-880314.No violations or deviations noted Major areas inspected Phase II welding reinsp.structural steel.concrete & NRC Compliance Bulletin 87-002 (flasteners).
 YORK.J., WALTON.G., ELROD.S. Region 2, Ofo of the Director. 88/03/17. 7pp 45008:141-45008:147
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing house Reactors." Svo list encl.
 ROSSI CE. Division of Operational Events Ascessment (Post 870411). 89/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:248.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees:Lack of Mgt Controls Over U-censed Programs." Svc list encl. CUNNINGHAM, R.E. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44895:353.
- 8804010256 NRC Into Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-beard Function Due to Faulty Tie Bolts." Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408:292-45407:051.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list enci.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12.
 Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45185:150.
- 8804210017 Summarizes review of NRC Bulletin 88-001, "Defects in Westinghouse Cu-cuit Breakers." Bulletin not applicable to Browns Ferry nuclear plant.Bulletin applica-ble to Watts Bar & Bellefonte nuclear plants.List of commitments encl. GRIDLEY,R. Tennessee Valley Authority. 89/04/13. Document Control Branch (Docu-ment Control Desk). 3pp. 452(9:150-45219:162.
- 8904220032 Forwards response to NRC Bulletin 87-002, "Fastener Testing to Determine Conformance W/Applicable Tech Specs." Enci 4 identifies testeners transferred from storage 4 Enci 5 contains list of commitments being made by TVA in response GRIDLEY,R. Tennessee Valley Authority, 89/04/16. Document Control Branch (Document Control Desk), 165pp, 46219:172-45220:026.
- 8804280835 Responds to NRC 880308 itr re violations noted in listed insprepts,including 50-438/87-08,60-439/87-08 & 50-327/87-88.Corrective actions date base constructed for training.

 GRIDLEY, R. Tennessee Valley, Authority, 88/04/22, Document Control Branch (Document Control Deak), 10pp, 45331;341-45331;350.

- 8804060383 "Personnel Whole Body Exposure Ropts for 1987." W/880401 tir. GRIDLEY,R Tennessee Valley Authority, 87/12/31, 7pp. 45047.060-45047.066.
- 8804130358 Forwards weekly schodulo of TVA activities for wks of 880411 & 18. KELLY,J,L. Oic of Special Projects 88/04/08. ZECH,G.G. Ofc of Special Projects 4pp. 45103.216-45103.219.

U. Congressional/Executive Correspondence

8804280317 Forwards NRR responses to Questions 1 & 3 re Commission side for permitting restart of power plant after shutdown for safety reasons & Commission requirements for documenting ficensing basis for restart decision, respectively.

THOMASCO Policy Development & Technical Support Branch (Post 870411), 88/04/19, REHM,T A. Ofc of the Executive Director for Operations, 7pp. 45269.209-45269.215.

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8804270113 Forwards 871103 response to request for assistance in reviewing petition (lide under 10CFR2.206 by concerned citizens for listed counties.Recommends that emergency preparedness into handbook not be immediately revised. KRIMM,R.W. Federal Emergency Management Agency. 88/02/26. CONGEL,F.J. Division of Radiation Protection & Ernergency Preparedness (Post 870411). 22pp 45246.253-45246.278.
- →8804270123 Urges thorough review of recommendations made by concerned citizens (e request for action in pobliton filed under 10CFR2.208. CHEMA,T.V. Ollo, State of 87711/12. MURLEY,T. Office of Nuclear Reactor Regulation, Director (Post 870411), 4pp. 45246:275-45246.278
- 8804080115 Temporary Change Notice 6 to revised emergency plan Implementing procedures including Rev 4 to "Emergency Operations Facility Activation" & Rev 4 to EPI-83, "Radiological Surveys for...." W780329 ltr. ANDERSON,J.D. Cleveland Electric Illuminating Co. KAPLAN,A. Commonwealth Ed.son Co. 88/03/29, 44pp. 45084.017-45084:060.
- 8804110173 Forwards master activities plan for Apr-June 1988 & list of activities by priority. KNOP,R.C. Region 3, Oic of the Director, 88/04/05. AXELSON,W.L. Region 3, Oic of the Director, 4pp. 45146.020-46146-023.
- 8804270131 Clarifios position re Issues addressed in response to plant 2.206 polition on emergency into handbook. Existing school evacuation procedures should be reviewed & emergency into signs should be installed now. KRIMM,RW. Federal Emergency Management Agency, 88/04/19. STOHR,J.P. Division of Radiation Protection & Emergency Preparedness (Post 870411). 1p. 452420114. 5624011. 45242 015 45242 015
- 8804270139 Forwards Rev A of NRC Draft Insp Procedure 82412, "Emergency Response Facilities Evaluation," which will be used by team evaluating amergency facilities during with 61 80502-Procedure App 3 documentation should be available. SHAFER,W.D. Region 3, Oic of the Director, 88/04/19, KAPLAN,A. Cleveland Electric Illuminating Co. 36pp. 46242:252-45242:280.

G. Adjudicatory correspondence

- 8804180113 Concerned Cibizens reply to response of Cleveland Electric l'uminating Co-to petition on emergency into handbook." Director's Decision on listed matters to rec-tify deficiencies in handbook requested.W/Corlificate of Svc. KLINE.C. Concerned Citizens of Lake, Geauga & Ashtabula Counties, OH. #288 6051. 88704708 Office of Nuclear Reactor Regulation, Director (Post 870411). 6pp 45127.151.45127:156.
- 804250088 Responds to 880316 order & request that preceeding be terminated. Licensees have withdrawn part of amend request which OCRE opposed & on which OCRE requested hearing & no issues remain. Proceeding should be terminated. ed
 Sit BERG,JE: Cloveland Electric Illuminating Co SitBERG,JE: Shaw, Pittman, Potts
 & Trowbridge, #288 6113, 88/04/18, MARGULIES,MB, CARPENTEH,JH,
 LINENBERGER,G. Atomic Safety and Licensing Board Panel. 3pp. 45209.260
- 8804290036 Order dismissing proceeding.* Licenses withdrew petition re proposed amend to Tech Specs to MSIV leakage control sys. Proceedings terminated by Board upon participant agreement Mycourse of action Served on 880428.

 MARGULIES.M.B. CARPENTER.J.H., LINENBERGER.G. Atomic Salety and Licensing Board Panel. #288 6157. 88/04/26. 3pp. 45256:011-45256.013

I. Financial Information

- 8604070209 Forwards "Annual Financial Rept for 1987,"
 KAPLAN,A. Cleveland Electric Illuminating Co. 86/03/29. Document Control Branch (Document Control Desk), 1p. 45083; (03-45083; 147.
- -- 8804070124 "1987 Annual Rept." GINN,R.M., MILLER,R A. Centerior Energy. 87/12/31. 45pp. 45063:100-45063.102.

J. Insurance & Indemnity information

8804070215 Forwards Endorsemonis 19,20,21 & 22 to NELIA Policy NF:291, Endorsements 13,14 & 15 to MAELU Policy MF:124 & Endorsements 3 to NELIA Policy N:102 & MAELU Policy M:102. EffTLE,F.F. Centerior Energy, 88/03/30. DINITZ,f. Office of Nuclear Reactor Regulation, Director (Post 870411), 14pp. 45029:331:45029:344.

M. Antitrust correspondence

- 8804130404 Responds to 880301 fit to T Murlay expressing concerns re Ohio Edison Co. 870918 application to amond License NPF-59, suspending antitrust conditions Recipionit comments will be considered in roview of application. STELLOY, Ofc. of the Executive Director for Operations 88/04/04 METZENBAUM, H.M. Sonate 10pp. 45104:097-45104:108.
- --8804130409 Opposes Onio Edison Co application for amend to License NPF-58, suspending antitues conditions Approval will remove natural market pressure on util to keep rates low in order to retain & attract customers. METZENBAUM,HM. Sanate 88/03/01 MURLEY,T.E. Office of Nuclear Regulation, Director (Post 870411). 2pp. 45104.107-45104.108.

P. Operating license stage documents & correspondence

- 8803080233 Ack receipt of 880122 patition seeking immediate suspension of Leansee outstanding CP & OL for plant based on alleged deficiences in solution design. Director concluded that seismic dosign & seismic qualification program ade-
- quale,
 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 86
 02 HIATT,S.L. Office of Responsible Energy, 2pp. 44634 277 44634 328.
- -8603060244 Patition for immediate action to refleve undue risk posed by inadequate selsmic design of plant.
 HIATT,S.L. Onlo Cilizons for Responsible Energy. 88/01/22. Office of Nuclear Reactor Regulation, Director (Post 870411). 12pp. 44634;281-44634;292
- -8803080263 "Seismicity & Tectonic Structure in Northeastern Ohio: Implications for Earthquake Hazard to Perry Nuclear Power Plant." AGGARWAL, Y.P. Sensearth, Inc. 87/03/31 36pp. 44634:293-44634-328
- 8803240426 Generic Lir 88-06 to all power reactor licensons & applicants re romoval of organization charts from Tech Spoc administrative control requirements Svc list encl. MIHAGLIAF. J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edson Co. of Now York, Inc. 47pp. 44972.107-44972.153.
- 8804060480 Documents 880328 discussion w/NRC re root cause analysis, conclusions 8 following actions resulting from single MSIV slow opening anomaly. Plant operation resumed & MSIV monthly testing will be continued. KAPLAN,A. Clave'and Electric Illuminating Co. 88/03/28. DAVIS.A.B. Region 3, Otc of the Director. 1p. 45007 081-45037.081.
- 8804080019 Confirms plans for 880415 meeting w/util in Glon Elynill to discuss plant First Quarter 1988 & Mar 1988 performance & frond analysis improvement plans. GREENMAN,E.G. Region 3, Oto of the Director, 88/04/04 KAPL
- 8804110173 Forwards master activities plan for Apr-June 1988 & list of activities by pri-Oilly, Grand St. Of oil the Director, 88/04/05 AXELSON,W.L. Region 3, Ofc of the Director. App. 45148:020-45146 023
- 8804140193 Provides listed Info requested In 880225 ftr re operating nuclear power units located at twolve sites along Groat Lakes. STELLO.V. Otc. of the Executive Director for Operations, 88/04/06, RIDGE,T. House of Rep. 5pp. 45104:138-45104.143.
- 8804080688 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc 1st enct. MIRAGLIA,F. J. Associate Droctor for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285
- 8604120420 Application for amend to Elecase NPF-58, revising Tech Space administrative controls section, clarifying wording in Sections 1.0 & 8.8.4 a correcting typos in Sections 4.7.1 & 4.8.1.1.2.e.2 & detailing toolinotes Fee paid.
 KAPLANIA. Cloveland Electric Tiuminating Co. 88/04/08. Document Control Branch (Document Control Desk). 9pp. 45129:094-45129:122.
- --8804120426 Proposed Tech Specs, revising administrative controls sections.claritying Sections 1.0 & 4.8.4 a correcting typos in Sections 4.7.7.1 & 4.8.1.1.2.9.2 & deleting inapplicable foolnotes.
- Cleveland Electric Illuminating Co. 88/04/08. 20pp. 45129.103-45128:122
- 8804190150 Forwards two-page set of graphs perfaining to plant which was extracted from ropt on performance indicators for operating commercial nuclear power reactors 8.7-yr history of collective radiation exposure for plant. COLBURN, T.G. Project Directorate III-3. 88704708. KAPLAN, A. Cleveland Electric IIIuminating Co. 31pp. 45164:312-45164:342.
- 8864270304 Withdraws porton of 870918 Tech Spec change request re deletion of MSIV loakage control sys & requests again portion of change request that allows 100 sch total MSIV leakage.per NRC 880311 rejection lit. KAPLANA. Cleveland Electic Illuminating Co. 88704718 Document Control Branch (Document Control Desk) 2pp. 45244:215-45244:216.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors," Svc list encl.
 ROSSI,CE. Division of Operational Events Assessment (Post 870411), 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995-126-44995-246
- 8803220298 NRC Info Notice 88-010, "Mails Licensees tack of Mgt Controls Over Licensed Programs." Svc list anci.
 CUNNINGHAM,R E Division of Industrial & Medical Nuclear Salety (Post 870729), 88/
 03/28, Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804010114 Advises that no further action required rejutif 870908 response to NRC Bulletin 87-001, "Thinning of Pipe Walls at Nuclear Power Plants." COLBURN, T.G. Project Directorate (ff. 3, 88/03/29, KAPLAN, A. Cleveland Electric Illuminating Co. 2pp. 44021 358-44021.359.

8804070208 Responds to NRC 671229 ftr re-violations noted in Insp Rept 50-440/87-22 Corrective actions temporary alteration reevaluated & 10CFR50 59 safety evalua-Lon performed.

KAPLAN,A Cleveland Electric Illuminating Co. 88/03/30 Document Control Branch (Document Control Desk). 4pp. 45029;240-45029 243.

- 8804060207 Forwards Insp Rept 50 440/87-25 on 880111-15.25-29 & 0209 & notice of violation.
 MILLER,H.J. Region 3, Ofc of the Director, 88/03/31, KAPLAN,A. Cleveland Electric flurminating Co. 3pp. 45034;139 45034,160
- -8804060212 Notice of violation from insp on 880111-15,25-29 & 0209. Violations noted Rev 1 to Procedure PAP 0906 did not Include criteria to make evaluations for scheduling preventive maint activities & failure to accomplish PMI-0030 as stated. MILLER, H.J., Region 3, Ofc of the Director. 88/03/31, 2pp. 45034;142-45034;143.
- -8804060216 Insp. Rept. 50:440/87-25 on :080111-15,25-29 & 0209 Violations noted Major areas inspected licensee action re allegation & maint activities. PLISCOL R. REYNOLDS,S.A., WALKER,H.A. Region 3, Otc of the Director, 88/03/ 24. 16pp. 45034:144-45034:160.
- 8804060347 Forwards "Motor-Operated Valve Testing & Evaluation at Perry Nuclear Power Plant (IE Bullatin 85-003)," final rept. KAPLAN,A. Cleyetand Electine Huminating Co. 88/03/31. Document Control Branch (Document Control Desk). 1p. 45030.299-45030.317.
- -8804070231 "Motor Valve Testing & Evaluation at Perry Nuclear Power Plant (IE Bullelin 85-003).

Cleveland Electric Fluminating Co. 88/03/31 18pp. 45030 300-45030.317.

- 8804070235 Provides response to NRC Bulletin 88-001, "Defects in Westinghouse Crucuit Breakers." Subj circuit breakers not in use at facility & will not be procured for fulture use.

 KAPLAN,A. Cleveland Electric Illuminating Co. 88/03/3). Document Control Branch (Document Control Desk). 2pp. 45031:007-45031:008.
- 8804110173 Forwards master activities plan for Apr-June 1988 & list of activities by prionly: KNOP,R.C. Region 3, Old of the Director. 8B/04/05. AXELSON,W.L. Region 3, Old of the Director. 4pp, 45146.020-45146.023.
- 8804130344 Forwards request for additinto re-review of responses to Action Item e of IE Bulletin 85-003, "Motor-Operated Valve Common Mode Failures During Plant Transionts Due to Improper Switch Settings," Response requested within 1 month. GREENMAN.E.G. Region 3, Otc. of the Owector. 88/04/05. KAPLAN.A. Cleveland Electric Liuminating Co. 4pp. 45154:061-45154:064.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts," Svc lest each ROS9,C E. Dwiston of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406;292-45407;051.
- 8604060370 NRC Info Notice 86-012, "Overgreasing of Electric Motor Bearings." Svc list encl. ROSSIC.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165:150.
- 8804270139 Forwards Rev A of NRC Draft Insp Procedure 82412, "Emergency Response Facilities Evaluation," which will be used by team avaluating emergency facilities during who is 880502 Procedure App 3 documentation should be available. SHAFER.W.D. Region 3, Oic of the Director. 88/04/19. XAPLAN,A. Clevatand Electric Illuminating Co. 39pp. 45242-252-45242-290.

R. Periodic operating reports & related correspondence

8804190081 Monthly operating rept for Mar 1988 W/880415 ltr. DUNN,G.A. KAPLAN,A. Claveland Electric Illuminating Co. 88/03/31. 6pp. 45208.200-45208.205.

S. Reportable occurrences, LERs & related correspondence

8804140123 LER 86-010-00.on 880310 & 11.RWCU containment isolations occurred due to pump room high differential temp Caused by Inadequate instructions.Roughing Liters in HVAC sys AB replaced.W/880408 ltr.
DUNN,GA., KAPLAN,A. Cleveland Electric Illuminating Co. 88/04/08, 4pp, 45184-033-45184.036.

U. Congressional/Executive Correspondence

- 8804130404 Responds to 880301 ltr to T Murley expressing concerns re Ohlo Edison Co 870918 application to amend License NPF-58, suspending entirust conditions Recipiant comments will be considered in review of application.

 STELLO,V. Old of the Executive Director for Operations. 88/04/04. METZENBAUM,H.M. Senate. 10pp. 45104:097-45104:108.
- --8804130409 Opposes Ohio Edison Co application for amend to License NPF-58, suspending antituest conditions Approval will remove natural market pressure on util to keep rates low in order to retain & attract customers.

 METZENBAUM,H.M. Senate 88/03/01. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 45104:107-45104:108.

V. Operator Examinations

8804110173 Forwards master activities plan for Apr-June 1988 & list of activities by priorly. KNOP.R.C. Region 3, Otc of the Director, 88/04/05 AXELSON,W.L. Region 3, Otc of the Director, 4pp. 45146 020-45146:023.

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

- 8803080233 Ack receipt of 880122 petition, seeking immediate suspansion of licensee outstanding CP & OL for plant based on alleged deticioncies in saisfald design Director concluded that seismic design 8 soismic qualification program ade MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 86/03/ 02. HIATT, S.L. Ohio Citizens for Responsible Energy, 2pp. 44634:277-44634 328.
- -8803080244 Petition for immediate action to relieve undue risk posed by inadequate seismic design of plant.
 HIATT'S.L. Ohio Citizens for Responsible Energy, 88/01/22. Office of Nuclear Resc.
 tor Regulation, Director (Post 870411). 12pp. 44634:281-44634:282.
- --8803080253 "Seismicity & Toctonic Structure in Northoastern Ohio Implications for Earthquake Hazard to Perty Nuclear Power Plant" AGGARWAL,Y.P. Sonsearth, Inc. 67/03/31. 36pp. 44634.293-44634.328,
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants ro removal of organization charts from Tech Spec administrative control requirements. Svc list end MIRAGLIA.F.J. Associate Director for Projecte (Post 970411). 88/03/22 Conscided Edison Co. of New York, Inc. 47pp 44972:107-44972:153.
- 8804110173 Forwards master activities plan for Apr-June 1988 & list of activities by pilonly.

 ANOP,R.C. Region 3, Oic of the Director, 86/04/05, AXELSON,W.L. Region 3, Oic of the Director, 4pp. 45146.020-45146.023.
- 8804140193 Provides listed info requested in 880225 ftr re operating nuclear power units located at twelve sites along Great Lakes.

 STELLO,V Old of the Executive Director for Operations 88/04/06 RIDGE,T. House of Rep. Spp. 45104:138-45104:143.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en forcement policy concerning 10CF/860.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants" "Svc list encl. MITAGLIA,F J. Associate Director for Projects (Post 8704.11), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45164 237-45184:285.

F. Security, medical, emergency & fire protection plans

- 8804270113 Forwards 871103 response to request for assistance in reviewing pell on illed under 10CFR2.206 by concerned citizens (or listed counties.Recommends that emergency preparedness Info handbook not be immediately revised.

 KRIMM.R.W. Federal Emergency Management Agency. 88/02/26. CONGEL.F.J. Division of Radiation Protection & Emergency Preparedness (Post 870411). 22pp. 45246.32.4.5246.32.6.346.31. 45246 253 45246 278
- --8804270123 Urgas thorough review of recommendations made by concerned citizens refequest for action in patition filed under 10CFR2.206. CHEMA,T.V. Ohio, State of 87/11/12. MURLEY,T. Office of Nuclear Reactor Regulation, Director (Post 870411). 4pp. 45246.275-45246.278.
- 8804080115 Temporary Change Notice 6 to revised emergency plan implementing procedures including Rev 4 to "Emergency Operations Facility Activation" 8 Rev 4 to EPI-83, "Radiological Surveys for...," W/860329 lir.
 ANDERSON.J.D. Cleveland Electric Illuminating Co. KAPLAN,A. Commonwealth Edison Co. 88/03/29, 44pp. 45064.017-45064.060.
- 8804110173 Forwards master activities plan for Apr-June 1988 & list of activities by priority.

 NIOP,R.C. Region 3, Otc of the Director. 88/04/05. AXELSON,W.L. Region 3, Ofc of the Director. 4pp. 45146.020-45146;023.
- 8804270131 Clarifies position relissues addressed in response to plant 2.206 petition on emergency into handbook Existing school evacuation procedures should be reviewed & emergency into signs should be installed now. KRIMM,R.W. Federal Emergency Management Agency. 88/04/19. STOHR.J P. Division of Radiation Protection & Emergency Preparedness (Post 870411). 1p. 45042.015.45542.015.
- 8804270139 Forwards Rev A of NRC Draft Insp Procedure 82412, "Emergency Response Facilities Evaluation," which will be used by team evaluating emergency facilities during wk of 880502. Procedure App 3 documentation should be available. SHAFER.W.D. Region 3, Oko of the Director, 88/04/19, KAPLAN,A. Cleveland Electric Illuminating Co. 39pp. 45242:252-45242:290.

G. Adjudicatory correspondence

8804180113 Concerned Citizens reply to response of Cleveland Electric Illuminating Co to petition on emergency into handbook * Director's Decision on listed matters to rectify deficiencies in handbook requested W/Certificate of Svc. Concerned Citizens of Lake, Geauga & Ashilabula Counties, OH. #286 6051. 88/04/08. Office of Nuclear Reactor Regulation, Director (Post 870411). 8pp. 88/04/08. Office of 46127:161-45127:156.

J. Insurance & Indemnity Information

8804070215 Forwards Endorsements 19,20,21 & 22 to NELIA Policy NF:291, Endorsements 13,14 & 15 to MAELU Policy MF-124 & Endorsements 3 to NELIA Policy N-102 & MAELU Policy M-102. ERTLE,R.F. Centerior Energy, 88/03/30, DINITZ,I. Office of Nuclear Reactor Regulation, Director (Post 870411), 14pp. 45029:331-45029:344.

175

O. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors" Svc1st end ROSSICE Division of Operational Events Assessment (Post 870411), 88/03/28 Consolidated Edison Collaboration (Post 870411), 88/03/28
- 8803220296 NRC Info Notice 88:010, "Matts Licensees:Lack of Mgt Controls Over Licensed Programs." Svc Isl encl. CUNN:NGHAM,R.E. Division of Industrial & Medical Nuclear Safety (Post 870/29), 68/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44935.353
- 8804070235 Provides response to NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakers" Subjectuit broakers not in use at facility & will not be procured for
 - future use.
 KAPLAN,A Cleveland Electric Huminating Co. 88/03/31. Document Control Branch (Document Control Desk). 2pp. 45031-007-45031.008.
- 8804110173 Forwards master activities plan for Aprillune 1988 & 1st of activities by pri-
- onty.

 Only R.C. Region 3, Otc of the Director, 88/04/05, AXELSON,W.L. Region 3, Otc of the Director, 4pp, 45148-020-45146-023.
- 8804130344 Forwards request for addl info re review of responses to Addian Item IE B., leth 85 003, "Molor-Operated Valve Common Mode Felkires During Plant Tran-signis Due to Improper Switch Settings." Response requested within 1 month GREENMAN.E.G. Region 3, Ofc. of the Director. 88/04/05. KAPLAN.A. Clove'and Electric Illuminating Co. 4pp. 45154:061-45154.064.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Cir &/or Switch-board Function Due to Faulty Tio Bolts." Svc 1st enct. ROSSI,CE Dwiston of Operational Events Assessment (Post 870411), 88/04/07. Consc dated Edison Co. of New York, Inc. 124pp. 45406 292-45407.051.
- 8804060370 NRC I/do Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc Isst encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consol dated Edison Co. of New York, Inc. 123pp. 45165.028-45165.150.
- 8804270139 Forwards Rev A of NRC Draft Insp Procedure 82412, "Emergency Response Facilities Evaluation," which will be used by team evaluating emergency fact too during which 980502 Procedure App 3 documentation should be available SHAFER, WD Region 3, Olto of the Director, 88/04/19, KAPLAN, A Cleveland Electric Illuminating Co. 39pp. 45242 252-45242.290.

V. Operator Examinations

6804110173 Forwards master activities plan for Apr-June 1988 & 1st of activities by priprity.

KNOP.R.C. Region 3, Old of the Director 88/04/05 AXELSON,W.L. Region 3, Old of the Director 4pp. 45146 020-45146 023.

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

E. NRC Safety Evaluation Report (SER), suppls & correspondence

- 8804270216 Forwards comments & clarification for review of Oct 1987 Suppl 7 to NUREG-0896, "SER re Operation of Seabrook Stations, Units 1 & 2." Items being completed or requiring correction should be interoprotated into next suppl. THOMAS, G.S. Public Service Co. of Now Hampshire 88704/21. Document Control Branch (Document Control Dask), 6pp. 45244;255-45244;260.
- F. Security, medical, emergency & fire protection plans

Branch (Document Control Desk). 5pp. 45053 290-45057:137.

- 8804D80037 Advises that 871 104 Roy 4-amended to station security training & qualification plan consistent w/provisions of 10CFR50.54(p) & acceptable Rev withhold (10CFR2.790(d)).

 BELLAMY, R.R. Region 1, Old of the Director, 88103/28, HARRISON, B.J. Public Serv-
- ice Co. of New Hampshire. 4pp. 45129 222-45129.225.
- 8804070221 Responds to NRC 880318 request for adultintoire public alert & not-lication sys Licenses currently modifying design rept & will include into in App E to facility radiological emergency plas Wone uncodeable oversize drawing W/o encl. THOMAS G.S. Public Service Co. of New Hampstre. 88/04/01. Document Control Branch (Document Control Desk), 24pp. 45163.257-45163:278.
- 8804080122 Forwards Amend 3 to "Seebrook Plan for Massachusetts Communities" & "Seebrook Plan for Massachusetts Communities Implementing Procedures Manual." THOMAS,G.S. Public Service Co. of New Hampshire, 88/04/01. Document Control
- --8804050401 Rev 0 to Amend 3 of "Seabrook Plan for Massachusetts Communities." Public Service Co. of New Hampshire, 88/03/30, 677pp, 45053:295-45055.251.
- --8804060123 Rev 0 to Amend 3 to "Seabrook Plan for Massachusetts Communities Implementing Procedutes Manual."
 ' Public Service Co. of New Hampehire, 88/03/30, 806pp 45055;252-45057;137.
- 8804120232 Forwards Insp Rept 50:443/68-03 on 880216-19.No violations noted. BELLAMY R.R. Region 1, Old of the Director, 88/04/04, HARRISON,R.J. Public Service Co. of New Hampshire, 8pp. 45130.316-45130.326.
- -8804120237 Insp Rept 50-443/88-03 on 880216-19.No violations noted. Major areas inspected action on previously identified Items, emergency response facilities & equipment audits & reviews, training drills & exercises

 TUCCINARDIT. LAZARUS,W. Region 1, Old of the Director, 98/03/29, 5pp. 45130:322-45130.326
- 8804140092 Forwards Encl 2 to Page Amend 3 to "Seabrook Plan for Massachusselts Communities," inadvertently omitted from 880401 emergency plan. THOMAS,G.S. Public Service Co. of New Hampshi've, 88/04/08. Document Control Branch (Document Control Desk) 1p 45147:343-45148.040.

- --8804140094 Encl 2 to Pago Amend 3 of "Seablook Pian for Massachusetts, Communities," inadvertently omitted from previous plan

 * Public Service Co. of New Hampsture. 88/04/08, 59pp. 45147:344-45148:040.
- 8804150142 Hevs 33 & 34 to "Production Emergency Response Menual." W/ 880413 MACDONALD, J.A., THOMAS,G.S. Public Service Co. of New Hampshire. 88/04/13 600ap. 45168-019-45169-200
- 8804200004 Forwards Rev 0 to Amend 4 to "Sopbrook Plan for Messachusetts Communities & Implomenting Procedures Manual," addressing listed comments from FEMA per 10CFR50 4(b)(5) Matrix of FEMA fundings also enct. THOMAS,G.S. Public Service Co. of New Hampshire. 88/04/14. Document Control Branch (Document Control Desk). 8pp. 45176 102-45176 360
- --8804200019 Rev 0 to Amend 4 to "Seabrook Plan for Massachuseits Communities Impfomenting Procedures Manual"

 Public Service Co. of New Hampshire. 88704714, 275pp. 45176 108-45176 360.
- 8804210275 Provides status of util efforts to design & deployment of vehicular efert & notification says Sys currently undergoing testing to establish specific sulup & operallonal procedures
 FEIGENBAUM T.C. Public Service Co of New Hampshire 88/04/15 NERSES,V.
 Project Directorate I-3, 5pp. 45235-247-45235.251.
- 8804280084 Requests date of full scale emergency preparedness exercise be charged to wk of 880626 Proposed date change presently schoduled for while 800523 due to log sites of making changes to plans, mad fring trating modules & sessions. THOMAS GS. Public Source Co. of Now Hampshire. 88/04/21. Document Control Brench (Document Control Brench (Documen

G. Adjudicatory correspondence

- 8604050045 Applicants response to Alty General JM Shannon offsite emergency planning interrogatories & request for production of documents to applicants (Set 3).* Certificate of Sive encli Helaled correspondence THOMAS,G.S., LEWALD,G.H., Public Service Co. of New Hampshire, LEWALD,G.H. Public Service Co. of New Hampshire, LEWALD,G.H. Ropes & Gray, #288, 5982, 88/03/28. Atomic Safety and Licensing Board Panel, 31pp. 44966,199.44966.229
- 8804050052 Applicant response to Now England Coalition on Nuclear Pollution (NECNP) motion to compet applicant to respond (third sot of interrogatories).* NECNP prosent motion to compet must be deried W/Certificate of Svc.

 STEENLAND.D.S. Public Service Co. of New Hampshire. STEENLAND.D.S. Ropes & Gray #288 5568. 88/03/28 Atomic Safety and Licensing Board Panel. 5pp. 44988 233-44966:237.
- 8804050032 NRC Staff responses to Spacoast Anti-Pollution League response to Appeal Board 880129 memorandum & order re innancial qualification on a 8 Commonwealth of MA Atty Gent JM Shannon polition under... * W/Conflicate of Svc BERRY A.B. Assistant Genoral Counsel for Hearings. #288 5999. 88/03/29. Atomic Salety and Licensing Appeal Panol. 30pp. 44866-044-44966.073.
- 8804060088 Applicant repty to brief of Seacoast Ant Pollution Loague re financial qualification rule.* Intervenor brief waiver potition under 10CFR2.768(b) 8 should be don'ed.Cert.4cato of Svc enct.
 LEWALD,G.H. Public Service Co. of New Hampshire. #288-8013. 89/03/20 Atentic Safety and Licensing Appeal Panet. 25pp. 44983.118-44983.142
- 8804050070 Forwards BP Coltor 880311 momorandum requesting ASLP docket be included on syc list to ensure docket room files complete Served on 880331 WOLFE,S.J. Atomic Salety and Licensing Board Panel. #288 6996 88703730. Office of the Gondral Counsel. 2pp. 44966 250-44956 251.
- 8804050084 Order.* Period in which Commission may review ALAB-879 rescheduled to expire on 880331, Served on 880331.
 CHILK,S.J. Office of the Secretary of the Commission. #288 5995. 88/03/30. Commissioners 1p. 44866:076-44866.076.
- 8804050089 Forwards 880329 decision of Supreme Court of NH In Iown of Rya & town of Hampton Felts vs util & State of NH,Dept of Transportation,Rockingham 87-062,up-troiding lecensor right to instalf & metintain stron poles & Stens in towns. D.G.NAN,T.G. Public Service Co. of New Hampshife. #288 5998 88/03/30. Atomic Safety and Licensing Appeal Panel. 6pp. 44966 252-44966 267.
- 8804050047 Order (denying New England Coa'lden on Nuclear Pollution metion to compel of 880322). Instant motion deried Served on 880401 WOLFE.S.J. Atomic Safety and Licensing Board Panel. #288 5969, 88/04/01 New England Coa'lden on Nuclear Pol'ution. 2pp. 44968:220-44966:231.
- 8804050077 Informs that time provided by NRC regulations within which Commission may act to review Appeal Board decision (ALAB 679) has expired Commission declined review Decision became final on 88031. Served on 880401. CHILK, 5. J. Office of the Secretary of the Commission. #288 5970, 88/04/01, Office of the General Counsel. 1p. 44866.141-44966.141.
- 8804110012 Contentions by city of Haverhill for Commonwealth of MA emergency response plan * City demands to be included in state emergency response plan based on city being in 10-mile proximity of plant W/Cert-licate of Svc. AMIRIAN,A. Haverhi I, MA. # 288 6023, 88/04/04, 5pp. 45048 342-45048 346.
- 8604110164 Order.* Time for Commission to review ALAB-863 extended to 80419 Served on 830407.
 CHRLK,S.J. Office of the Secretary of the Commission. #288 6029 88/04/07. Commissionera. 1p. 45050 096-45050:006
- 8804180067 New England Coalition on Nuclear Pollution brief in support of appeal of memorandum & order renewing authorization to operate at low power.* Hecommends that Licensing Board decision be reversed Syc list enct.

 CURREN,D. New England Coalition on Nuclear Pollution. CURREN,D., FERSTER,A. Harmon & Weiss #288 6062, 88/04/07. Atomic Safety and Licensing Board Panel. 26pp. 45128.084-45128:109.

- 8804260059 Forwards Exh.b.t. 1.consisting of transmittal litt that accompanied Amend 3 to Seabrook plan for MA communities. Timely notification of parties to nipjor fevs requested. W/o encl. Related correspondence.
 TRAFICONTE, JC. Massachusetts, Commonwealth of #200 6120 08/04/07 DIGNAN,T.G. Roppes & Gray. 2pp. 45210.099-45210.100.
- 8804180045 Memorandum (svc of protected Info).* Protected Info should be deleted from public filings & or served or sent to Docketing & Svcs Branch or ASLAB.In response to Doughty request for clarification Served on 880411.

 SMITH.I.W. Atomic Safety and Licensing Board Penol. #268 6039 88/04/08 1p. 45127.247.45127.247. 45127 247-45127:247
- 8804180073 NRC Staff response to New England Coahtion for Nuclear Power supplemental memo on environ qualification of HG-58 coastal cable. Coafficate of Svc onct. BERRY.GA. Assistant General Counsel for Hozarngs. #268 6065 88/04/08. Atomic Safety and Licensing Appeal Panel. 22pp. 45127:124-45127:145.
- 8804180092 Motion of Commonwealth of MA alty general for extension of time to amend stren contentions,* Extension until 880415 requested Served on 880411. Granted for Board on 880408 JONAS, S. A. Massactusetts, Commonwealth of. #289 6063, 80/04/08 WOLFE,S.J., LUEBKE,E.A., HARBOUR,J. Atom.: Safety and Licensing Board Panol. 1p. 45127:146-45127:146
- 8804200068 Requests response to whether or not FEMA will be will-drawing 980125 tostimony Decision should be made to proffer O McLoughtin as witness to be deposed by intervenors or to withdraw Related correspondence. SNEIDER, C.S. Massachusetts, Commonwealth of. #288 6079, 88/04/00. FLYNN,II J Federal Emergency Management Agency. 1p. 45160:174-45160:174.
- 880420102 Applicant supplemental response on anviron qualification of FIG-58 conxist cable. Licensing Board decision on 880302 providing support to Appeal Board remaind correct 8 request to reopen record should be denied Certificate of Svc encl STEENLAND, D.S. Public Service Co. of New Hampshire. STEENLAND, D.S. Ropos & Gray. #288 6070. 88/04/08. Atomic Safety and Licensing Appeal Panel. 27pp 45159 297-45159 323.
- 8804200100 Applicant response in opposition to Commonwealth of MA alty general potition under 10CFR2.758 for walver of or exemption from public util exemption from requirement of demonstration of financial qualification. W/Confrication of Society Co., of New Hampshire, LEWALD,G.H. Public Service Co., of New Hampshire, LEWALD,G.H. Ropes & Gray. #288 6071, 88/04/09, Atomic Safety and Licensing Board Panol. 17pp. 45162.088-45162.088
- 8804200052 Forwards contentions of Secoast Anti-Pollution Loaguto (SAPL) on facility plan for Massachusetts communities for firing SAPL served contentions containing protected into only on Board, Appeal Board & counsel for active parties BACKUS, RIA. Backus, Meyer & Solomon, #288 6078, 88/04/11, SMITH, W., HARBOURJ, LINENBERGER, G. Atomic Sefety and Liconsing Board Panel Ip. 45162.118-45162.138
- --8804200062 Seacoast Anti-Pollution Loague (SAPL) contentions an Scattrook p'an for Massachusetts communities.* SAPL (cins in & adopts contentions filed by Common-wealth of MA & town of Amesbury on plan. BACKUS.R.A. Seacoast Anti-Pollution Loague, BACKUS.R.A. Backus, Moyer & Solo-mon. 88/04/11. Atomic Safety and Licensing Board Panel. 19pp. 45102.120-45.162.13
- 8804290308 Appricant response to contentions by city of Havorh II for Commonwealth of MA emergency response plan.* Haveriff! contention should be rejected Applicant has no objection to admission as interested state W/Conflicate of Svc. DIGNAN,T.G. Public Service Co. of New Hampshire. DIGNAN,T.G. Ropos & Gray. #268 6081, 88/04/12. Atomic Safety and Licensing Board Panel. 5pp. 45181:056-4514-050
- 8804290013 Forwards self-explanatory ltr did 880412 to members of Appeal Board w/ attachment to applicant 880411 brief to resolution of official unsecured creditors committee of Public Svc Co of New Hampshire. LEWALDG.H. Ropes & Gray. #288 8148 88/04/12 Docketing & Saw.coe Branch. 5pp. 45255 220-45265 224.
- 8804 180028 Order.' Requests into re util monthly contributive share psyments, including payment status since liting for bankruptcy & justification for util actions. Served on 8904 14.
- BOUT 14... SHOEMAKER,CJ. Alomic Safety and Liconsing Board Panel. #288 6064. 88/04/13. Public Service Co. of New Hampshire. 2cp. 45128.024-45128:025.
- 8804200030 Notice of appearance.* RS H II-Whitton enters appearance as atty for lown of Newbury in proceeding Notice of change of address for lown & Cortificate of Svo
- enc. HYL-WHILTON,R. Newbury, MA. HILL-WHILTON,R. Lagoulis, Clark, Hilf-Whitlon & McGurre. #288 6067. 88/04/13. 4pp. 45183.026-45163.029.
- 8804200053 Town of Newbury contentions re applicant plan for Commonwealth of MA communities.* Plan for commonwealth does not meet requirements that must be reasonable means of execution & relocation.per Rev 1 to NUREQ-0854. WHILTON.R.S. Newbury, MA. WHILTON.R.S. Lagouila. Clark, Hill-Whition & McGuiro. #286-6044.88704713. Atomic Safety and Licensing Board Panet. 37pp. 46182-340-45163:025.
- 8804200073 Contentions of town of West Newbury re Seatrook plan for Commonwealth of MA communities." Plan fails to meet planning stds.per 10CFR50.47(b) & NUREG-0654 FEMA REP-1.Rev 1, Suppl 1. MIZNER.J.H. West Newbury. MA. #268 6085, 88/04/13. Atomic Safety and Licensing Board Panel. 17pp. 45162.332-45162.348.
- 8804200108 Atty General JM Shannon contentions submitted in response to Sentirook plan for Commonwealth of MA communities. Plan falls to most planning stds.por IOCFR50-47[bk]19 & NUREG-9684 II A 3 W/Cortilicate of Svc. TRAFICONTE.J Massachusetts, Commonwealth of #288 6086, 88/04/13. SMTH.LW, LINENBERGER,G. Atomic Selety and Uconsing Board Panel, 215pp. 45163.030-45163.245.
- 8804260124 New England Coatton on Nuclear Pollution contentions on Seabrook Plan for Commonwealth of MA communities.* Wisvo list.

 CURRAN,D. New England Coalition on Nuclear Pollution. CURRAN,D. Hermon & Weiss. #288 6124.

- 8804200250 Advisos that mall citod in NRC bird on color coding of an'e related califes in ESAR Section 8.3.1.3 not introduced as evidence by reopered to receive citod portions.

 RESEJ. Assistant General Counset for Hearings #208 600 HOSENTHALAS, WILBERTHA Atomic Salety and Uconsing Assistant Obs. 45:61.062-45:161.062
- 8804280088 Application for subpounds requiring alteridance & totained named FEMA employees per 100FF12 720(a) & MHC 100FF12 720(b)(2). We supporting documentation & sec 1st Related to RACKUS,R.A. Sencoast Anti-Pollution Leegue BACKUS,R.A. Backus, 45210.241-45210.280
- 8804200083 Continue sequest to torage any further dupos tein exam of the originary planning proceeding Witness may be examined further resument by enotine party or if witness in horangs Notated correspondent to the sequence of the sequenc
- 8804200264 Notice of homing * Haning to issue of shollowing boach for raciological ornargancy at plant will be finite 880502 in Concord.httSeri-SMITH.LW Atomic Safety and Licensery Board Panel #288 6641 (45181-001-45181-961.
- 8804280052 Amended contention of Atty General JM Shannon on execution contents as the state amended contents applicant volicular aloit a notification sys Conflicted of Sys enci STANNON, JM JONAS, S.A. Massachusutts, Commonwealth of #268 15, 11pp. 45210 314-45210.324.
- 8804260007 Soatrook OL case ensite entergency planning & technical wards table of contents & table of authenties for New England Coasts Politicion brief in support of appear of ASLBP 88-558-01-OLB CURRAND. New England Coalition on Nuclear Political Cultifiant. Cultifiant Coalition on Nuclear Political Cultifiant Wess. #288-01-02. B0704/15. ROSENTHALAS Atomic Safety and two Panel 1p. 45210-003-45210-098.
- --8804260076 New England Contition on Nuclear Pollution brief in support momoranthum & order renewing authorization to operate at lew pews brint,consisting of nithologic Contents & faith of authorities.

 CURINAND. Flow England Contition on Nuclear Pollution CURRAYI.

 Walse, 88-04-07. Atomic Safety and Licensing Appeal Panel 599
 45210-098
- 8804280083 Forwards Pages 142 & 159 from contents filed by Aty Stannon due to undvertent misplacement of paragraph. TRAFICONTE_J. Massachusotts, Commonwealth of. #288 6126 68/64/1 8 Services Branch 3pp 45210:158-45210 160.
- 8804260087 Response of FEMA to requests for production of textunents interveners notice of taking depositions.* Declaration of JW Becton ext raspondence.
 BECTON.J.W. Federal Emergency Management Agency #288 612;
 Atomic Safety and Uconsing Board Panel 15pp. 45210.070 45210.092
- --8804260092 Response of FEMA to applicants requests for production of Svc and Related correspondence. PLYNN,11 Federal Emergency Management Agency. 08/04/15 Atomic Licensing Board Panel. 8pp. 45210-085-45210.092.
- 8804200107 Forwards excorpts from Socurities & Exchange Commission utilicash flow problems for Into Form reveals that util may not be shared fund facility financial obligations Svc list and BACKUS RA Seacoast Anti-Pollution Loague. #286 6128 ROSENTHALA 9. MOORE, T.S., WILBER, H.A. Atomic Safety and Lee Panel. 13pp. 45210 281-45210 203.
- 8804290047 Applicant supplemental response to Atty General JM Shar emergency planning interregittedes & request for production of decime cants (Sot 3).* Related correspondence LEWALD,T.G. Public Service Co of New Hampshire. LEWALD,T.G. fin #288.6172. 88704/15. Atomic Safety and Licensing Board Panel 200 46366-129.
- -- 8804290054 Applicante Direct Testimony 8 * Certificate of Svc enct fle aponuonco. * Publia Sorvica Co. of Naw Hampstire. 88/04/16, 130pp. 45256 043 45₹
- 8804260056 Memorandum & order.* Submits correct address of ASISs Commonwealth of MA recent flings using incorrect address Served on 85 SMITILLW. Atomic Safety and Licensing Board Panel #288 6125 65/45211026-45211027.
- 8804280079 Forwards tables inadvertently emitted from New England Coscillar Pollution 880415 brief to ensite emergency planning & technical less pagination of tables corrected. Provious filing should be disregarded CURRAND. New England Coalition on Nuclear Politision CURRAND Wess. #288 6101. 88/04/18. ROSENTHALAS. Atomic Safety and Less Panel 1p. 45210:149-45210:156.
- ***B804280091 New England Coalition on Nuclear Pollution brief in the momorandum & order renowing authorization to operate at low power 'B ing of tablos inadvariently omitted Cortificate of Svc enci.

 CURRAN,D. New England Coalition on Nuclear Pollution CURRANO Wolss. B8/04/07. Atomic Safety and Licensing Appeal Panel 7pt 45210.158.
- 8804260097 Requests table of contents for contentions submitted by Comm. MA alty general in response to Seabrook plan for MA communities 5 profession of each contention. Served on 880421.

 SMITH,I.W. Atomic Safety and Licensing Board Panel #289 5121 TRAFICONTE,J. Massachusetts, Commonwealth of 1p. 45210 068-43219.

- -8804250101 Requests table of contents for contentions submitted by Seacoast Ani-Pollution League in response to Seabrook plan for MA communities & short description of each contention.

 SMITH,I.W. Atomic Safety and Licensing Board Panel. 88/04/18. BACKUS,R.A. Backus, Meyer & Solomon 1p. 45210.067-45210:067.
- -8804260105 Requests table of contents for contentions submitted by town of Newbury in response to Seabrook plan for MA communities & short description of each conten-
- tion SMITH,I.W. Atomic Safety and Licensing Board Panel, 88/04/18. HILL-WHILTON,R Lagouis, Clark, Hill-Whilton & McGuire. 1p. 45210.068-45210:068.
- --8804260110 Requests table of contentions submitted by town of Amesbury in response to Seabrook plan for MA communities & short description of each contention. SMITH,I.W. Atomic Safety and Licensing Board Panel. 88/04/18. BROCK,M.T. Shaines & McEachern. 1p. 45210.069-45210.069.
- 8804290073 NRC Staff response to pelitions filed by city of Haverhill & town of Merrimac,MA.* NRC does not oppose participation by municipalities in proceeding W/ Certificate of Svc.
 TURK,SE. Assistant General Counsel for Hearings. #286 6169. 88/04/19. Atomic Safety and Licensing Board Panel. 4pp. 45256:219-45256:222.

- 8804260064 Advises that time for Commission to review ASLAB Decision ALAB-886 expired Commission decinod review Decision became final agency action on 880404 Served on 880420.
 - GOUND SHOULD BOOKED.
 CHILK,S.J. Office of the Societary of the Commission. #288 8100, 88/04/20. Atomic Safety and Licensing Board Panel. 1p. 45210:136-45210:136.
- 880429082 Application for subpoenss requiring attendance & testimony of FEMA & NRC employees & memorandum of law in support.* Subpoenss requested for M Lawless & F Congel Related correspondence.

 BACKUS,R.A. Seaccast Anti-Pollution League. BACKUS,R.A. Backus, Meyer & Sotomon. #288 6170, 88/04/21. Atomic Safety and Licensing Board Panel. 4pp.
- -8804290092 Memorandum in support of application for subpoenas requiring attendance & testimony of particular named FEMA employees, per 10CFR2.720 (a) & NRC employees, per 10CFR2.720 (h)(2).*
 BACKUS,R.A. Seacoast Anti-Pollution League. BACKUS,R.A. Backus, Meyer & Solomon. 88/04/21. Atomic Safety and Licensing Board Panel. 15pp. 45256:227-45256:241.
- 8804290017 Notifies that New England Coalition on Nuclear Pollution (NECNP) does not Intend to littigate NECNP Contention I.V on adequacy of applicant program for inserv-
- Ice insp of sleam generator tubing.

 FERSTER,A. New England Coalition on Nuclear Pollution. FERSTER,A. Harmon & Welss. #288 6150. 88/04/22. WOLFE,S.J., LUEBKE,E.A., HARBOUR,J. Atomic Safety and Licensing Board Panel. 2pp. 45265:228-46266:229.
- 8804290028 Applicant response to order of 860413.* Quality & safety of operations maint or const has not been compromised in any manner by loss & replacement of 11 vendors, ceasing to do business w/project Certificate of Sva enct. DIGNAN,T.G. Public Service Co. of New Hampshire. DIGNAN,T.G. Ropes & Gray. #288 6149. 88/04/22. 7pp. 45255:321-45265;327.
- 8604290024 Memorandum & order,* Partial Initial Decision,LBP-87-10, 25 NRC 177,reversed to extent that environ qualification of RG58 coaxial cable established Served on 880425
- SHOEMAKER,C.J. Atomic Safety and Licensing Board Panel. #288 6146. 88/04/25. BERRY,G.A. Office of the Genéral Counsel. DIGNAN,T.G., STEENLAND,D.S. Public Service Co. of New Hampshire, 27pp. 45255;280-45255;306.
- 8804290027 Order.* Only express mall addressed to EA Luebke re onsite emergency planning & safety issues will be sent to listed address. Served on 880428. WOLFE, SJ. Afornio Safety and Licensing Board Panel. #288 6147. 88/04/25. 1p. 45265:320-45255:320
- 8804290084 Applicant responses to intervenors contentions on Seabrook plan for Commonwealth of MA communities (SPMC).* Certificate of Svo encl. DIGNAN,T.G. Public Service Co. of New Hampshire. DIGNAN,T.G. Ropes & Gray, #288 6171. 88/04/26. Atomic Safety and Licensing Board Panel. 269pp. 46256:242-
- 8804290098 Order.* Responses to Joint Intervenor 880422 motion for directed certifica-tion shall be in hands of Board by 880502. Evidentiary hearings now scheduled to commence on 880502 suspended pending further order.
- 8804290026 Memorandum.* Suspension of now scheduled evidentiary hearing lifted in part. Hearing may go forward but will not include receipt of evidence from witnesses on behalf of FEMA_pending further order. Served on 880427.
 SHOEMAKER.C.J. Atomic Safety and Licensing Appeal Panel. #288 6168. 88/04/27. 5pp. 45256:315-46265:319.

H. General correspondence

8803310210 Comment opposing proposed rule 10CFR50 re mass point analysis.Proposed rule contrary to ANSI/ANS 56.8-1987 & general rev of App J specifying 24 h min test duration when using mass point analysis may prompt needless connolity, J.W. Public Service Co. of New Hampshire, 88/03/23, Docketing & Services Branch. 1p. 44996;081-44996;081.

I. Financial information

8804010286 Urges Commission to reinstate stay on issuance of OL for plant until signifi-cant issues re lead util interest in voluntary bankruptcy resolved.Served on 880201. HUMPHREY.G.J. Senate. #188 5474. 88/01/29, ZECH.L.W. Commissioners. 1p. 44919:336-44919:336.

8804260107 Forwards excerpts from Securities & Exchange Commission Form 10-K re util cash flow problems,for into Form reveals that util may not be able to continue to fund facility financial obligations Svc list enct.

BACKUS R.A. Seacoast Anti-Pollution League #288 6128. 88/04/15.

ROSENTHAL,AS., MOORE,TS., WILBER,H.A. Atomic Salety and Licensing Board Panel. 13pp. 45210.281-45210.293.

J. Insurance & Indemnity Information

- 8803310276 Forwards Endorsements 1 & 2 to MAELU & NELIA Certificates of Insurance MW-97 & NW-188,respectively Certificates elso end GRILLO.M. Johnson & Higgins Insurance, 88/03/21, DINITZ.I.P. Office of Nuclear Reactor Regulation, Director (Post 870411), 24pp. 45001:004-45001:027.
- 8804050058 Advises that util will continue to provide listed insurance coverage until NRC completes review of util 871001 request for schedular examption from 10CFR50.54(w) THOMAS,G S. Public Service Co. of New Hampshire. 88/03/30, Document Control Branch (Document Control Desk). 2pp. 45032 081-45032 082.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88-06 to all power reactor Leensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list enct. MIRAGLIA.F.J. Associate Director for Projects (Post 870411). 89/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153
- 8804040202 Forwards discussion of post-accident boron analysis,por NUREG-0737, Item II.B.3 Util experience indicates that mannitol fritration method superior to fluoroborato alternative because of simplicity 8 reliability. THOMAS, GS. Public Service Co. of New Hampshire, 88/03/30. Document Control Branch (Document Control Dask), 3pp. 45076:112-45076:114.
- 8804070081 Forwards magnetic date tape containing available validated meteorological data from onsite instrumentation for Apr 1979 Dec 1983 & Oct 1986 June 1987. Tape format developed per NUREG-0800, Section 2.3, App A. THOMAS, G. Public Service Co. of New Hampshire, 88/04/01, Document Control Branch (Document Control Desk), 8pp. 45022:132-45022:137.
- 8804080088 Generic Ltr 88-07 to power reactor l'censees & applicants re modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svo list encl MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 48pp. 45164 237-45164:285.
- 8804210059 Forwards clarifications ra FSAR Section 17.2 concerning changes to operational QA program.
 THOMAS.G.S. Public Service Co. of New Hampshire, 88/04/11. Document Control Branch (Document Control Desk), 11pp, 45235:225-45235:235.
- 8804210089 Forwards marked-up changes to FSAR Chapter 13,Sections 13.1, 13.2.13.3 & 13.4 reflecting organizational changes.
 THOMAS.G.S. Public Service Co., of New Hampshire, 88/04/11, Document Control Branch (Document Control Desk), 92pp. 45237:180-45237:273.
- 8804220246 Notification of 880504 meeting w/util in Rockville,MD to discuss Tech Specs Meeting agenda end: NERSES, Project Directorate 1-3, 88/04/18, WESSMAN,R. Project Directorate 1-3, 6pp. 45200.325-45200:330.
- 8804290189 Requests remittance of fee required for application for approval of mods to util control bldg HVAC (CBA) sys (ref 10CFR170).
 DIGGS.R.M. License Fee Management Branch. 88/04/25. HARRISON,R J. Public Service Co. of New Hampshike. 1p. 45284:359-45284:359.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors." Svc list enct.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 88-010, "Mails Licensees:Lack of Mgt Controls Over Licensed Progrems." Svc list encl. CUNNINGHAM.R.E. Division of Industrial & Medical Nuclear Salety (Post 870729), 887 03/28, Consolidated Edison Co. of New York, Inc. 108pp. 44985;247-44995,353.
- 8804050055 Responds to NRC Bulletin 88-001, "Defects in Westinghouse Circuit Breakers." Five DS-416 circuit breakers inspected found to contain pole shaft welds that did not meet acceptance criteria specified in bulletin. THOMAS,G.S. Public Service Co. of New Hampshire. 88/03/30. Document Control Branch (Document Control Desk). 5pp. 46021:040-45021:044.
- 8804120232 Forwards Insp Rept 50-443/88-03 on 880218-19.No violations noted BELLAMY, R.R. Region 1, Oto of the Director. 88/04/04. HARRISON, R.J. Public Service Co. of New Hampshire. 6pp. 45130:316-45130:326.
- 45130.322-45130:328.
- 8804130430 Forwards request for addl info re first 10-yr interval Inservice insp program.Response requested within 60 days of ltr date. NERSES,V. Project Directorate 1-3. 88/04/04. HARRISON,R.J. Public Service Co. of New Hampshire. 21pp. 45104:112-45104:132.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Cir &/or Switch-board Function Due to Faulty Tie Bolts." Svo list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408.292-45407.051.

- 8804200096 Forwards Safety Insp. Rept. 50:443/88.02 cn. 890202-0328 No. violations
- noted WIGGNS.J.T. Region 1, Ofcicliste Director 88/04/07, HARRISON.R.J. Public Serv-ice Co. of New Hampshire. 8pp. 452/16/012-45216/038
- -8804200099 Salety Insp. Rept. 50:443/88/92 on 680202/0328 No worldors noted Major larges inspected operational safety (consee action on previous insp. had rigs NRC bulletins into notices 8 genero tituters 8 svc water 5,5 corros on HAVERKAMP, 0.R. Region 1. Oto of the Orector 88/04/06 21pp. 45216.018.
- 8804050370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc kst end ROSSICE Division of Operational Events Assessment (Post 870411) 68/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165-150
- 8804250053 Forwards Safety Insp Rept 50-443/88-04 on 880222-26 No violations noted GALLO R M Region 1, Ofc of the Director 88/04/18 HARRISON R J Public Service Co. of New Hampshira 8pp 45254 261-45254 275
- #804260056 Inspired Foliation of the second state of the second s

- 8804150395 Monthly Operating Ropt 68 03 for Mar 1988 W/880411 ftr. NARDONE,P., THOMAS,G.S. Pub c Service Co. of New Hampshire. E8/03/31. 6pp. 45192 237-45192 242.
- 8804220196 Forwards "Annual Environ Operating Rept for 1997" & related affacti-
- THOMAS,G.S. Public Service Co. of New Hampshira. 88/04/18. Document Control Branch (Document Control Besk). 1p. 45267.001-45267.113
- -8805030253 "Annual Environ Operating Right for 1987" "Public Service Co. of New Hampshire. 87/12/31. 3pp
- -880e220207 Technical Hept XVIIII. ("Seatrook Environ Studies,1986" Characterization of Baselina Conditions in Hampton-Seatrock Area, 1975-1986 Preoperational Study for Seatrook Station."
 - * Normandeau Associates, Inc. 87/09/30, 421pp, 45267 005-45268 064
- --8804220213 Final "Determination of Neoplasia in Schi Shell Clams Mya Arenana Near Seabrook Nuclear Plant
 HILLMAN R.E. Battele New England Varne Research Laboratory 87/04/30 9pp 45268 065 45268 074
- --8804220239 "Hatogenated Hydrocarbon Production & Potential of Bioaccumulation at
- DOW, K.W. Yankee Atomic Electric Co. 87/04/24, 39pp. 45268 075-45268.113

T. Hearing transcripts on non-antitrust matters

- 8803240312 Transcript of 880321 hearing in Bethesda,MD, re-off-site emergency Planning Pp 9,777-9,666.
 * Atomic Safety and Licensing Board Panel: 88/03/21, 108pp 44867.324-44888.071
- 8804050324 Transcript of 880401 hearing in Washington DC re-offsite emergency planning Pp 9.667-9.914
 SMITH, I VINENBERGERG Atomic Safety and Licensing Board Panel 88/04/01
 50pg 44970 061-44970.050
- 8804070296 Transcript of 860405 telcon in Washington,DC re-cifis tell emergency planning Pp 9315-72
 - Commissioners 88/04/05 61pp. 45043 328-45044 027

U. Congressional/Executive Correspondence

8804010286 Urges Commission to reinstate stay on issuance of OL for plant until sign ficant issues to lead util interest in voluntary bankruptcy resolved Served on 880201 HUMPHREY,G J. Senate #188 5474 88/01/29 ZECH,L.W. Commissioners to 44919 335,44919 335

V. Operator Examinations

- 8804250088 Responds to FOIA request for info re-scores of reactor operators & serior reactor operators Forwards requalitication exam summary source sheets I sted in enci app w/personal privacy info deleted GRIMSLEY.D.H Division of Hules & Records (Post 870413) 88/04/19 BOLEY.K Public Citizen's Critical Mass Energy Project 2pp. 45213-003-45213-095.
- -8804250167 Package of NRC administered requalification examiresuits summary NRC No Detailed Affikation Given 87/07/20 88pp. 45213 097-45213 095.

DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl MIRAGLIA,F.J. Associate Director for Projects (Post 87041) 86/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972 107-44972 150.
- 8804040202 Forwards discussion of post-accident boron analysis per NUREG 0737,frem II 8 3 Util experience indicates that mannitol intraton method superior to fivoroborate alternativo because of simplicity & reliability.

 THOMAS, C.S. Public Service Co. of New Hampshire 88/03/30. Document Control
- Branch (Document Control Desk) 3pp 45076 112-45076 114

- 8904070051 Forwards magnetic data tape containing available validated meteorologic data from onete instrumentation for Apr. 1979 Doc. 1983 & Oct. 1986 Sec. 1987 Tape format doveloped per NUFICE-0800, Section 2.9.3 App. A. THOMAS, G. Public Servico Co. of New Hampstine 88/04/01. Document Comp. Branch (Document Control Desk). 6pp. 45022 132-45022 137
- 8894080088 Generic Ltt 68-07 to nower roactor Leansees & applicants to modify to forcement policy concorring 10CFR50 49. "Environ Quelification of Electrical Edgment Important to Safety for Nuclear Power Plants." Svc 151 onc. MIRAGELIAF J. Associate Director for Projects (Post 870-411) 68/04/07. Consolitated Edison Co. of New York, Inc. 49pp. 45164 237-45164 295.
- 8804210059 Ferwards clarifications to FSAR Section 17.2 concerning changes to Gaze ational OA program
 THOMASIG S. Public Service Co. of New Hampshire. 88/04/11. Document Core.,
 Branch (Document Control Dask). Tipp. 45/235/225-45/235/235.
- 8804210089 Forwards marked-up changes to FSAR Chapter 13,Sections 13.1,1323) 3 8 13.4 reflecting organizational changes THOMAS,G.S. Public Service Co. of New Hampshire, 86/04/11. Cocument Comp. Branch (Document Control Dosk). 92pp. 45237 180-45237 273

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8804270216 Forwards comments & clarification re-rowew of Oct 1987 Suppl 7 to MUREG-0898, "SER re-Operation of Seabtrook Stations, Units 1 & 2" flems teny completed or requiring correction should be incorporated into next suppl THOMAS, G.S. Public Service Co. of Now Hampshire 88/04/21. Decument Complete Branch (Document Control Desk). Epp. 45244-255-45244-260.

F. Security, medical, emergency & fire protection plans

- 8804070221 Responds to NRC 880318 request for addition or public afert & natioary systicenses currently modifying design rept & will include into in App E to facilities of opea emergency plan Wifer's uncodeation oversize drawing Wife and THOMAS G Public Spories Colon New Hampshire 88/04/01 Desument Control Branch (Document Control Dosk), 24pp. 45163-257-45163-279
- 8804080122 Forwards Amend 3 to "Scabrook Plan for Massachusetts Communities" & "Seatorok Plan for Massachusotts Communities Implumenting Procedures Maria.
 THOMAS,G.S. Public Service Co. of New Hampsture. 88/04/01. Document Corce.
 Branch (Document Control Desk). 5pp. 45053.290-45057.137.
- -- 8804050401 Rev 0 to Amend 3 of "Seabrook Plan for Maskachusetts Communities Public Service Co. of New Hampshire 88/03/30, 677pp. 45053 295-45055 251
- --8804080123 Rev 0 to Amend 3 to "Soabrook Plan for Massachusetts Communities Implementing Procedures Manual."

 * Public Service Co. of New Hampshire 88/03/20 606pp. 45055 252-45057 137
- 8804140092 Forwards Encl 2 to Page Amend 3 to "Septropk Plan for Massachusse"s Communities," inadvertently omitted from 880401 emergency plan THOMAS.G.S. Publ.c Service Co. of New Hampshira 88/04/08 Document Comm Branch (Document Control Dosk) 1p 45147:343-45148-040
- -8804140094 Encl 2 to Page Amerid 3 of "Seabrook Pian for Massachusetts, Communities," Inadvertionity omitted from provious plan * Public Service Co. of New Hampshire 88/04/08, 58pp. 45147/344-45148/040
- 8804200004 Forwards Rev 0 to Amend 4 to "Seabrook Plan for Massachusetts Cor-munities & Implementing Procedures Manual," aildressing "sted comments from FEMA.per 10CFR50 4(b)(5): Matinx of FEMA findings also and THOMAS, G.S. Public, Service Co. of New Hampshire, 80/104/14. Document Control Branch (Document Control Dosk): 6pp. 45176:102-45176:360
- --8804200019 Rev 0 to Amend 4 to "Scebrook Pian for Massachusetts Communicating Procedures Manual"

 1 Public Service Co. of New Hampshire, 88/04/14, 275pp. 45176 108-45176 269
- 8804210275 Provides status of util efforts re-design & deployment of vehicular alen & notification sys Sys currently undergoing testing to establish specific setup 8 operalicnal procedures.
 FEIGENBAUM,T.C. Public Service Co. of New Hampshiro. 88/04/15. NERSES,V. Project Directorate 1-3: 5pp. 45235:247-45235.251.
- 8804280084 Requests date of full scale emergency preparedness exercise he change to which 80026 Proposed date change presently scheduled for which 80023 due to log sites of making changes to plans modifying training modules & sussions THOMAS (35 Public Service Co of Now Hampshire 86/04/21 Document Corted Branch (Document Control Desk), 6pp. 45261:248, 45261-253.

G. Adjudicatory correspondence

- 8804050045 Applicants response to Atty Goneral JM Shannon offis:te emergency planing interrogatories & request for production of documents to applicants (Set 3) * Certificate of Svc end! Related correspondence.

 THOMAS.G S., LEWALD.G.H. Public Service Co. of New Hampshire. LEWALD.G.H. Riches & Gray. #288 5982. 88/03/28. Atomic Safety and Licensing Board Panel 31pp. 44966:139-44966 229.
- 8804050052 Applicant response to New England Coalition on Nuclear Pollution (NECNP) motion to compet applicant to respond (third set of interrogatories). NECNP present motion to compet must be deriled.W/Cert.fcate of Svc.

 STEENLAND,D.S. Public Service Co. of New Hampshire. STEENLAND,D.S. Ropes & Gray #288 5988 88/03/28. Atomic Safety and Licensing Board Panel. 549 44966 233-44966 237.
- 8804050032 NRC Staff responses to Spacoast Anti-Pollution Leaque response to Appeal Board 880129 memorandum & order re-linencial qualification rule & Commonwea'th of MA Alty Geni Jim Shannon patition undor...* W/Certilicate of Sve BERRY_AB. Assistant General Coursel for Hearings. #288 5999 88/03/29, Alomic Safely and Licensing Appeal Panel 30pp. 44966 044-44966 073.

- 8804060088 Applicant reply to brief of Soacoast Anti-Pollution League re linancial qualification rule. Intervenor brief waiver patition under 10CFR2.758(b) & should be denied Certificate of Svc and LEWALOGH. Public Service Co. of New Hampshire. #288 6013, 88/03/29. Atomic Safety and Licensing Appeal Panet, 25pp. 44983,118-44983,142.
- 8804050070 Forwards BP Cotter 880311 memorandum requesting ASLP docket be in-cluded on svc list to ensure docket room hiles complete-Served on 880331. WOLFE, SJ. Atomic Safety and Liconsing Roard Panel, #288 5996, 88703/30. Office of the General Counsel. 2pp. 44966 250, 44966 251.
- 8804050084 Order * Period in which Commission may roview ALAB-879 rescheduled to
- expire on 880331 Served on 880331
 CHILK,S.J. Office of the Secretary of the Commission. #288 5995 88/03/30. Commissioners 1p. 44966 076-44966.076.
- 8804050089 Forwards 880329 doctsion of Suprema Court of NH in Iown of Rye & town of Hampton Fells vs util & State of NH Dept of Transportation, Rockingham 87:062,upholding licensee right to install & maintain siren poles & sirens in towns DIGNAN, T.G. Public Service Co. of Now Hampstire #288 5998. 88/03/30. Alomic Safety and Licensing Appeal Panel. 6pp. 44968 252-44966:257.
- 8804050047 Order (denying New England Coalition on Nuclear Pollution motion to compot of 880322) * Instant motion denied Served on 880401. WOLFE, SJ. Alomic Safety and Licensing Board Panel. #288 5969 88/04/01. New England Coalition on Nuclear Pollution. 2pp. 44966.230-44966;231.
- 8804050077 Informs that time provided by NRC regulations within which Commission may act to review Appeal Board decision (ALAB-879) has expired Commission declined review Decision become final on 880331. Served on 880401. CHILK, S.J. Office of the Secretary of the Commission. #288 5970. 88/04/01, Office of the General Counsel. 1p. 44966 141-44966.141.
- 8804110012 Contentions by city of Haverhill for Commonwealth of MA emergency response plan. City demands to be included in state ornergency response plan based on city being in 10-m to proximity of plant W/Certificate of Svc. AMIRIAN,A. Haverhill, MA. #288 6023. 88/04/04. 5pp. 45048-342-45048:346.
- Time for Commission to review ALAB-883 extended to 8804110184 Order.* 980428. Served on 880407.
 CHILK, S.J. Othico of the Secretary of the Commission. #288 6029. 88/04/07. Commissioners. 1p. 45050.006-45050.098.
- 8804180067 New England Coalition on Nuclear Pollution brief in support of appeal of memorandum & order renowing authorization to operate at low power.* Recommends that Licensing Board decision be reversed Svc list encl.

 CURREN.D. New England Coalition on Nuclear Pollution. CURREN.D., FERSTER.A. Harmon & Weiss. #288 6062. 88/04/07. Atomic Safety and Licensing Board Panel 26pp. 45128.084-45128.109.
- 8804260059 Forwards Exhibit 1,consisting of transmittel fir that accompanied Amend 3 to Seabrook plan for MA communities. Timely notification of parties re-major revs requested W/o encl Related correspondence.
 TRAFICONTE.J.C. Massachusotts, Commonwealth of #288 6120. 88/04/07.
 DIGNAN,T.G. Ropes & Gray 2pp. 45210.099-45210:100.
- 8904180045 Memorandum (svc of protected info).* Protected info should be deleted from public filings & or served or sent to Docketing & Svcs Branch or ASLAB, in response to Doughty request for clarification Served on 8804 45127 247-45127 247.
- 8904180073 NRC Staff response to New England Coalition for Nuclear Power supplemental memo on environ qualification of RG-58 coaxial cable. *Certificate of Sve encl. BERRY, 6. A. Assistant General Counsel for Hearings. #288 6066. 88/04/08. Atomic Safety and Ucensing Appeal Panel. 22pp. 45127:124-45127:145.
- 8804180092 Motion of Commonwealth of MA atty general for extension of time to amend siron contentions.* Extension until 880415 requested Served on 880411 Grantod for Board on 880409. JONAS,S.A. Massachusetts, Commonwealth of. #288 6063, 88/04/08, WOLFE,S.J., LUEBKE,E.A., HARBOUR,J. Atomic Safety and Liconsing Board Panel. 1p. 45127:146-
- 8804200066 Requests response to whether or not FEMA will be withdrawing 880125 testimony. Decision should be made to proffer D McLoughlin as witness to be deposed by intervenors or to withdraw.Related correspondence.

 SNEIDER,C.S. Massachusetts, Commonwealth of. #288 6079, 68/04/08 FLYNN,H.J. Federal Emergency Management Agency, 1p. 45160;174-45160,174.
- 8804200102 Applicant supplemental response on environ qualification of RG-58 coaxial cable Licensing Board decision on 880302 providing support to Appeal Board remand correct & request to reopen record should be denied Certificate of Svc encl. STEENLAND,D.S. Public Service Co. of New Hampshire. STEENLAND,D.S. Ropes & Gray. #288 6070- 80104/08. Atomic Sefety and Licensing Appeal Panel. 27pp. 45159.297-45159.323.
- 8804200100 Applicant response in opposition to Commonwealth of MA atty general petition under 10CFR2.758 for waiver of or exemption from public util exemption from requirement of demonstration of limancial qualification.* W/Certificate of Svc. LEWALD,G.H. Public Service Co. of New Hampshire. LEWALD,G.H. Ropes & Gray. #288 6071. 88/04/09. Atomic Safety and Licensing Board Panel. 17pp. 45162.088-45162-104.
- 8804200052 Forwards contentions of Seacoast Anti-Poliution League (SAPL) on facility plan for Massachusetts communities for filing SAPL, served contentions containing protected into only on Board, Appeal floard & Counsel for active parties.

 BACKUS,RA. Backus, Meyer & Solomon. #288 6078. 86/04/11. SMITH.LW, HARBOUR.J., LINENBERGER.G. Atomic Safety and Licensing Board Panel. 1p. 45182-19. 45182-19. 45182-19. 45162:119-45162:138.
- ---8804200062 Seacoasi Anti-Pollution League (SAPL) contentions on Seabrook plan for Massachusetts communities.* SAPL Joins in & adopts contentions filed by Commonwealth of MA & town of Amesbury on plan.
 BACKUS,RA Seacoast Anti-Pollution League. BACKUS,R A. Backus, Meyer & Solomon. 88/04/11. Atomic Safety and Licensing Board Panel. 19pp. 45162:120-45162. 45162,138.

- 8804200308 Applicant response to contentions by city of Haverhill for Commonwealth of MA emergency response plan. Haverhill contention should be rejected Applicant has no objection to admission as intorested state.W/Cortilicate of Svc. DIGNAN,T.G. Public Service Co. of New Hampshire. DIGNAN,T.G. Ropos & Gray. #288 6081. 88/04/12. Atomic Safety and Licensing Board Panel. 5pp. 45161:056-45161-080.
- 8804290013 Forwards self-explanatory lit dtd 880412 to members of Appeal Board w/ attachment to applicant 880411 brief re-resolution of official unsecured croditors committee of Public Svc Co of New Hampshire.
 LEWALOGH. Ropes & Gray. #288 6148. 88/04/12 Docketing & Services Branch. 5pp. 45255:220-45255:224.
- 8804160028 Order.* Requests into re-util monthly contributive share payments.Including payment status since hiting for bankruptcy & justification for util actions. Served on 800414.
- SHOEMAKER,C J. Atomic Safety and Licensing Board Panol. #288 6064. 88/04/13. Public Service Co. of New Hampshire. 2pp. 45128:024-45128 025. 8804200030 Notice of appearance.* AS Hill-Whitton enters appearance as alty for town of Nowbury in proceeding Notice of change of address for town & Certificate of Svc
- HILL-WHILTON,R. Newbury, MA, HILL-WHILTON,R. Lagguis, Clark, Hill-Whilton & McGuire, #288 6087, 88/04/13, 4pp. 45163-028-45163-029.
- 8804200053 Town of Newbury contentions re applicant plan for Commonwealth of MA communities. Plan for commonwealth does not meet requirements that must be reasonable means of evacuation & relocation.per Rev 1 to NUREG-0654.
 WHILTON,R.S. Newbury, MA WHILTON,R.S. Lagoul's, Clark, Hill-Whilton & McGuire #288 6084, 88/04/13, Atomic Satety and Licensing Board Panel. 37pp 45162:349-45163:036.
- 8604200073 Contentions of fown of West Newbury re Seabrook plan for Commonwealth of MA communities.* Plan fails to meet planning sids.per 10CFR50 47(b) & NUREG-0854 FEMA REP-1,Rev 1, Suppl 1. MIZNER,J.H. West Newbury, MA. #288 6085. 88/04/13. Atomic Safety and Uccessing Board Panel. 17pp. 45162.332-45162.348.
- 8804200106 Atty General JM Shennon contentions submitted in response to Scabrook plan for Commonwealth of MA communities.* Plan fails to meet planning stds.por 10CFR50.47(b)(1) & NUREG-0654 II.A.3 W/Gertilicate of Svc. TRAFICONTE.J. Massachusotts, Commonwealth of #288 6086. 88/04/13. SMITH.J.W., LINENBERGER,G. Atomic Safety and Licensing Board Panel. 215pp. 45163:030-45163:243.
- 8804260124 New England Coalition on Nuclear Pollution contentions on Seabrook Plan for Commonwealth of MA communities.* W/svc list. CURRAND. New England Coalition on Nuclear Pollution CURRAND. Harmon & Welss. #288 6124. 88/04/13, Atomic Safety and Licensing Board Panes 10pp. 45210:284-45210:303.
- 8804200250 Advises that mail cited in NRC brief on cofor coding of safety & nonselety-related cables in FSAR Section 6.3 1.3 not introduced as evidence Record should be reopened to receive cited portions.

 REIS.E.J. Assistant General Counsel for Hearings. #288 6082 88/04/14.

 ROSENTHAL.A.S., WILBER,H.A., Atomic Safety and Licensing Appeal Panel. 1P. 45161 082-45181:062.
- 8804260086 Application for subpoense requiring attendance & lostimony of particular-named FEMA amployees.per 10CFR2.720(a) & NRC employees.per 10CFR2.720(h)(2). W/supporting documentation & svc list Related correspondence BACKUS.R.A. Seacoast Anti-Pollution League, BACKUS.R.A. Backus, Meyer & Sofo-mon. #288 6127, 68/04/14. Atomic Safety and Licensing Board Panel 41pp 45210:241-45210:280.
- 8804200083 Confirms request to forego any further deposition exam of Thomas re off-site emergency planning proceeding Witness may be examined further if deposition is resumed by another party or if witness in hearings. Related correspondence. TURK, SE. Assistant General Courset for Hearings. #288 5080, 88/04/15. FLYNN, H.J., Federal Emergency Management Agency, 1p. 45160-235-45160-235.
- 8804200264 Notice of hearing.* Hearing re issue of sheltering beach population during radiological emergency at plant will be held 880502 in Concord,NH.Scrwad on 860416 SMITH,I.W. Atomic Safety and Liconsing Board Panel. #288 6063. 88/04/15. lp. 45161:061-45161:065.
- 8804280052 Amended contention of Atty General JM Shannon on notification sys for Commonwealth of MA* Atty general submits listed amended contention w/bases on applicant vehicular atert & notification sys.Certificate of Svc encl. SHANNON,JM., JONAS,SA. Massachusotts, Commonwealth of. #288 6102, 86/04/15, 11pp. 46210.314-45210.324.
- 8804280087 Seabrook OL case:onsite emergency planning & technical issues.* Forwards table of contents & table of authorities for New England Coaltion on Nuclear Pollution brilef in support of appeal of ASLBP 88-558-01-OLF.
 CURRAN,D. New England Coalition on Nuclear Pollution. CURRAN,D. Harmon & Welss. #288-8122, 89/04/15. ROSENTHAL,A.S. Atomic Safety and Licensing Appeal Panel. 1p. 45210.093-45210.098.
- --8804260076 New England Coalition on Nuclear Pollution brief in support of appeal of memorandum & order renewing authorization to operate at low power.* Errata to brief consisting of table of contents & table of authorities. CURRAND. New England Coalition on Nuclear Pollution. CURRAND. Harmon & Welss, 88/04/07. Atomic Safety and Licensing Appeal Panel 5pp. 45210:094-45210:094-
- 8804260083 Forwards Pages 142 & 159 from contentions filed by Atty General JM Shannon due to Inadvertent misplacement of paragraph. TRAFICONTE.J. Massachusettis, Commonwealth of, #288 6126, 88/04/15. Docketing & Services Branch. 3pp. 45210.158-45210:160.
- 8804280087 Response of FEMA to requests for production of documents contained in Intervenors notice of taking depositions.* Declaration of JW Becton encl.Related correspondence.

 BECTON.J.W. Federal Emergency Management Agency. #288 6123. 88/04/15. Atomic Safety and Licensing Board Panel. 15pp. 45210.070-45210:092.

- -8804260092 Response of FEMA to applicants requests for production of documents *
- Certificate of Svc and Related correspondence FLYNNIHJ, Federal Emergency Management Agency, 88/04/15, Atomic Safety and Licensing Board Panel, 8pp. 45210,085-45210,092.
- 8804260107 Forwards excerpts from Securities & Exchange Commission Form 10-K re util cash flow problems, for into Form reveals that util may not be able to continue to fund fact by financial obligations Svc list enct.

 BACKUS,R.A. Seacoast Anti-Pallution League #288 6128. 88/04/15

 ROSENTHAL,A.S., MOORE,T.S., WILBER,H.A. Atomic Salety and Licensing Board Reput 1709, 45314, 3914, 4531-209.
 - Panel 13pp. 45210 281-45210 293.
- 8604290047 Applicant supplemental response to Atty General JM Shannon off site emergency planning interrogatories & request for production of documents to applicants (Set 3). Related correspondence.

 LEWALD,T.G. Public Service Co of Now Hampshire LEWALD,T.G. Ropes & Gray. #288 6172 88/04/15 Atomic Safety and Licensing Board Panel 2pp. 45256.041-45256.123
- -8804290054 Applicants Direct Testimony 6.1 Conflicate of Svc encl. Related correspandenca * Public Service Co. of New Hampshire. 88/04/15. 130pp. 45256.043-45256.173
- 8804260058 Momprandum & order.* Submits correct address of ASLB,per towns in Commonwealth of MA recent filings using incorrect address Served on 880419. SMITH, W. Atomic Safety and Licensing Board Pariet. #288-6125-68/04/18, 2pp. 45211-026-45211-027.
- 8804280079 Forwards tables inadvertently emitted from New England Coalition on Nuclear Pollution 880415 brief re onsite emergency planning 8 technical Issues Errors in pagination of tables courcited Previous fring should be disregarded. CURRAN,D. New England Coalition on Nuclear Pollution, CURRAN,D. Harmon & Weiss, #288 8101, 88/04/18, ROSENTHAL,A.S. Atomic Safety and Licensing Appeal Panel 1p. 45210,149-45210,156.
- --8804260091 New England Coalition on Nuclear Pollution brief in su of appeal of memorandum & order randwing authorization to operate at low power.* Biref consisting of tables inactiveriently omitted Certificate of Svc encl.

 CURRAN,D. New England Coalition on Nuclear Pollution. CURRAN,D. Harmon & Weiss. 88/04/07 Atomic Safety and Licensing Appeal Panel. 7pp. 45210:150-45210-156.
- 8804260097 Requests table of contents for contentions submitted by Commonwealth of MA alty general in response to Seabrook plan for MA communities & short description of each contention Served on 880421 SMITH,INL Atomic Safety and Licensing Board Panel. #288 6121, 88/04/18 TRAFICONTE,J. Massachusetts, Commonwealth of. 1p. 45210;066-45210.069.
- --8804269101 Requests table of contents for contentions submitted by Seacoast Anti-Poliution League in response to Seabrook plan for MA communities & short description of each contention.

 SMITH,I.W. Atomic Safety and Licensing Board Panel 88/04/18. BACKUS,P.A. Backus, Meyer & Solomon. 1p. 45210.067-45210.067.
- -8804260105 Requests table of contents for content ons submitted by lown of Newbury in response to Sentirook plan for MA communities & short description of each conten-SMITH,I.W. Atomic Salety and Licensing Board Panel, 88/04/18. Hill-WHILTON,R. Lagoul's, Clark, Hell-Whilton & McGuire. 1p. 45210:068-45210:068.
- --9804260110 Requests table of contentions submitted by town of Amesbury in response to Seabrook plan for MA communities & short description of each contention SMITH.I.W. Atomic Safety and Licensing Board Panel 68/04/18. BROCK,M.T. Shaines & McCachem. 1p. 45210 069-452 to 069.
- 8804290073 NRC Staff response to petitions lifted by city of Haverhill & town of Merrimac, MA * NRC does not oppose participation by municipalities in proceeding W/ Certificate of Svc.

 TURK,S.E. Assistant General Counsel for Hearings. #288 8169, 88/04/19, Atomic Safety and Licensing Board Panel, 4pp. 45256.219.45256.222.
- 8804260064 Advises that time for Commission to review ASLAB Decision ALAB-886 expired Commission declined review. Decision became final agency action on 880404. Served on 880420. CHILK.5. J. Office of the Secretary of the Commission. #288 6100. 88/04/20, Atomic Safety and Licensing Board Panef. 1p. 45210:136-45210:136
- 8804290082 Application for subpoenas requiring attendance & testimony of FEMA & NRC employees & memorandum of law in support.º Subpoenas requested for M Lawless & F Congel Related correspondence.

 BACKUS,R.A. Seacoast Anti-Pollution League. BACKUS,R.A. Backus, Mayer & Solomon. #288 8170, 88/04/21. Atomic Safety and Licansing Board Panel. 4pp. 45265.22.45255.24. 45256 223 45256 241
- --8804290092 Memorandum in support of application for subpoenas requiring attendance & testimony of particular named FEMA employees, per 10CFR2.720 (a) & NRC employees per 10CFR2.720 (n)(2).

 BACKUS,R.A. Seacoest Anti-Pol 88/04/21. Atomic Safety and Licensing Board Panel, 15pp. 45258:227-
- 8604290017 Notifies that New England Coantion on Nuclear Pollution (NECNP) does not intend to higher NECNP Contention I.V on adequacy of applicant program for inservice lapp of steam generator tubing.

 FERSTER, A. New England Coalition on Nuclear Pollution, FERSTER, A. Harmon & Welss. #288 6150. 88/04/22. WOLFE S.J. LUERKE A., HARBOUR, J. Atomic Satoty and Licensing Board Panel. 2pp. 45255 228-45255 229.
- 8804290028 Applicant response to order of 890413.* Quality & safety of operations maint or const has not been compromised in any manner by loss & replacement of 11 vendors, ceasing to do business w/project/Certificate of Svo encl. DIGNAN,T.G. Public Service Co. of New Hampshire, DIGNAN,T.G. Ropes & Gray, #288 6149, 88/04/22 7pp. 45255:321-45255:327.

- 8804290024 Memorandum & order.* Partial Initial Decision,t.8P-87-10, 25 NRC 177 reversed to extent that onviron qualification of RG58 coaxial cable established Served on 880425
 - SHOEMAKER, C.J. Atomic Safety and Licensing Board Panel. #288 6146, 88/04/25.
 BERRY, G.A. Offico of the General Counsel DIGNAN, T.G., STEENLAND, D.S. Pub. 3
 Service Co. of Now Hampshire. 27pp. 45255, 280-45255, 306.
- 8804290027 Order * Only express mail andressed to EA Luebke re onsite emergency planning & safety issues will be sent to listed address. Served on 860426 WOLFE, S.J., Atomic Safety and Licensing Board Panel. #288 6147. 45255 320-45255 320
- 8804290084 Applicant responses to interveners contentions on Seabrook plan for Commonwealth of MA communitios (SPMC) * Certificate of Svc encl. DIGNAN T.G. Public Service Co. of New Hampshito. DIGNAN T.G. Ropes & Gray #288 6171. 68/04/28. Atomic Safety and Liconsing Board Panel. 259pp. 45256242-
- 8804290098 Order.* Responses to Joint Intervenor 880422 motion for directed confica-tion shall be in hands of Board by 880502. Evidentiary hearings now scheduled to commence on 880502 suspended pending further order Sevi
- 8804290026 Memorandum.' Suspension of now scheduled evidentiary hearing litted in part. Hearing may go forward but will not include receipt of evidence from witnesses on behalf of FEMA. pending further order. Sorved on 880427.
 SHOEMAKER.C.J. Atomic, Safety and Licensing Appeal Panel. #288 6168. 88/04/27. 5pp. 45255.315-45255:319.

I. Financial Information

8804280107 Forwards excerpts from Securities & Exchange Commission Form 10 K ro this cash flow problems for Into Form reveals that util may not be able to continue to fund facility tinancial obligations. See list onci.

BACKUS, R.A. Secoast Anti-Pollution League. #288 6128. 88/04/15

BOSENTHAL, A.S. Atomic Safety and Licensing Board Panel. 13pp. 45210/281-

J. Insurance & Indemnity Information

- 8803310275 Forwards Endorsements 1 & 2 to MAELU & NELIA Contricates of Insurance MW-97 & NW-188 respectively Certificates also enct.
 GRILLO,M. Johnson & Higgins Insurance. 88/03/21. DINITZ,I.P. Office of Nuclear Reactor Regulation, Director (Post 870411). 24pp. 45001:004-45001:027.
- 8804050058 Advises that util will continue to provide listed insurance coverage unit NRC completes review of util 871001 request for schedular exemption from 10CFR50 54(w).

 THOMAS.G.S. Public Service Co. of New Hampshire 88/03/30. Document Control Branch (Document Control Desk). 2pp. 45032.081-45032.082.

Q. inspection reports, IE Bulletins & correspondence

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors," Svc list encl.
 ROSSI.C.E. Division of Operational Events Assessment (Post 370411), 66/03/26.
 Consolidated Edison Co. of New York, Inc. 121pp 44995.126-44995:246.
- 6603220296 NRC Into Notice 68-010, "Matts Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list encl. CUNNINGHAM,R.F. Division of Industrial & Medical Nuclear Safety (Post 670729). 68/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svc iist encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407:051.
- 8804050370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc ROSSI, C.E. Division of Operational Events Assessment (Post 870411). 68/04/12. Consolidated Edison Co. of New York, Inc., 123pp. 45165:028-45165:150.

T. Hearing transcripts on non-antitrust matters

- 8804050324 Transcript of 880401 hearing in Washington,DC re offsite emergency planning,Po 9.867-9,914. SMITH,LW, LINENBERGER,G. Atomic Safety and Licensing Board Panel. 68/04/01. 50pp. 44970:001-44970.050.
- 8804070296 Transcript of 880405 telcon in Washington,DC re offsite emergency planning.Pp 9915-72.
 **Commissioners. 88/04/05. 61pp. 45043:328-45044:027.

U. Congressional/Executive Correspondence

8604010286 Urges Commission to reinstate stay on Issuance of OL for plant until significant issues re lead util interest in voluntary bankruptcy resolved Served on 860201. HUMPHREY.G.J. Senate. #188 6474. 88/01/29. ZECH,L.W. Commissioners. IP 44919 335-44919:335

DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 1

A. Application/construction stage documents & correspondence

- 8803080478 Forwards transcript of util 880218 public moeting w/CASE & M Watshire corrective action program for cable tray hangers & conduits & conduit supports,Not color meeting also encl.

 MALLOY,M. Oic of Special Projects 88/03/02 Ofc of Special Projects 213pp 44632 202-44633 054.
- 44632 202-44633 054.

 8803100014 Notifies that 860912 request to use ASME Code Case N-253-2, "Const of Class 2 & 3 Components for Elevated Temp Svc, Section III,Dv 1," acceptable pro-
- vided rules of corlo case governs design & matts selection GRIMILS,CI. Olic of Special Projects, 88/03/03, COUNSIL,W.G. TU Electric (formerly Toxas Uniflues Generating Co.). 4pp. 44661-025-44661-028.
- 8803250223 Forwards proprietary 8 nonproprietary Repts RXE-88-101-P & RXE-86-101-NP,respectively,re-steam generator tube rupture. Requests that proprietary rept be withheld from public disclosure. COUNSIL,W.G., WOODLAND R. TU Electric (formerly Toxas Utilities Generating Co.) 88/03/15. Document Control Branch (Document Control Desk). 3pp. 44916.001-
- --8803250267 Requests for withholding of Rept RXE-86-101-P, "Design Basis Analysis of Postufated Stoam Generator Tubo Rupture Event for Comanche Peak Steam Electric Station Unit 1," from public disclosure WIESEMANN,R A Westinghouse Electric Corp. 88/03/14, MURLEY,T. Office of Nuclear Reactor Regulation, Director (Post 870411), 11pp. 44916-004-44916-014.
- -8803250275 "Design Basis Analysis of Postulated Steam Generator Tube Replure Event for Commitche Peak Steam Electric Station, Unit 1." BOATWRIGHT.W.J. MAIER,S.M., LO.S. TU Electric (formerly Toxas Utrillos Generating Co.) RXE-88-101-NP. 88/03/31. 162pp. 44016-015-44916-175
- 8803240426 Generic Ltr 88-06 to all power roactor licenseos & applicants re-removal of organization charts from Tech Spec admin'strative control requirements Syc 1st encl MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/03/22 Consolidated Erison Co. of New York, Inc. 47pp. 44972:107-44972 153.
- 8804060515 Informs of util Intent to remove tube vibration instrumentation installed in steam generators as part of vibration test program described in util 840312 tr. Approval requested for elimination of vibration to onlitroing program. COUNSIL,W.G., BECK,J.W. TU Electric (formerly Texas Utilities Generating Co.), 887-03/28. Document Control Branch (Document Control Dosk), 2pp 45007:105-45007:106.
- 8804070083 Advises that uill porforming anaylase to validate high energy let impingement loads prosently being ut lized at plant.

 COUNSIL,W.G., BECK,J.W. TU Electric (formorly Toxas Util-tes Generating Co.). 887-03728. Document Control Branch (Document Control Desk). 2pp. 45030-357-45030,356.
- 8804060221 Notification of contract execution,Mod 18,to "Fleview & Evaluation of Comanche Peak Program Plan" Contractor: Teledyne Engineering Svcs.
 HAGEY,H. Contract Administration Branch FIN B-1338, 88/03/20, GRIMES,C I. Old of Special Projects LYONS,J. NRC No Detailed Affiliation Given. 1p. 45018.322-45018.324.
- --8804060233 Mod 18,add.ng Incremental funds,to "Review & Evaluation of Comanche Poak Program Plan"

 1 Taledyna Engineering Services, WIGGINS,E.J. Division of Contracts (Post 870413), FIN B-1338 88/03/29 2pp. 45018 323-45018-324.
- 8804110113 Forwards Securities & Exchange Commission Form 10-K for 1997 & util 1987 annual rept.W/o oncis. COUNSIL,W G., WOODLAN,D R. TU Electric (formerly Texas Utilities Generating Co.). 88/03/31. Document Control Branch (Document Control Desk). 1p. 45077:294-45077:294.
- 8804080088 Generic Ltr 88.07 to power reactor licensess 8 applicants to modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Saloty for Nuclear Power Plants." Svc ilist encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45104:237-45164:285.
- 8804150332 Parilal response to FOIA request for documents Forwards App 8 documents App A 8 documents also available in PDR. GRIMSLEY, D.H. Division of Rullos & Records (Post 870413), 68/04/08, CONNOR, L. Doc-Sparch Associates 4pp. 45149:330-45149:351.
- --8804180282 Comanche Peak Response Team Action Plan Item VII.a 6, "Exit Interviews." Related into onct. BUSH.J.W. 11ASSELJL. TU Electric (formorly Texas Utilities Generating Co.). 85/06/ 21. 8pp. 45149:334-45149:351.
- 8804130238 Forwards response to NRC 870707 request for additinfoire Generic Lir 83-28 concerning vendor interface programs. Procedures to periodically contact vendors of key components to facilitate exchange of current Info provided. COUNSIL,W.G., WOODLAN,D.R. TU Electric (formerly Texas Utilities Generating Co.). 88/04/11. Document Control Branch (Document Control Desk). 3pp. 45146:264-45146:288
- 8804200498 Forwards additinto re applicability of corrective action program at plant, per NRC 880122 request. Explanation of significance of deviations from design requirements identified by CPRT also encil per NRC request. COUNSIL, WG TU Electric (formerly Texas Utilities Generating Co.). 88/04/14. Document Control Branch (Document Control Dask). 8pp. 45239.061-45239:068.
- 8804200444 Forwards "Comanche Poak...Whipjet Program Rept" for review. Approval will allow olimination of pipe breaks & associated dynamic effects for listed sys & acceptance will allow removal of counter productive pipe whip restraints. COUNSIL,W.G. TU Electric (formerly Taxas Utilities Generating Co.). 88/04/15. Document Control Branch (Document Control Dosk). 2pp. 45174:190-45174.346.
- -- 8804200452 "Comanche Poak... Whiptet Program Rept." ** Robert L. Cloud Associates, Inc. 88/04/30. 158pp. 45174:192-45174:346
- 8804260193 Forwards final rovs & instruction sheets for manuals describing use of plant response team checklists. COUNSIL W.G. TU Electric (formerly Taxas Utilities Generating Co.), 88/04/15. Document Control Branch (Document Control Desk), 10pp. 45281:133-45281:190.

- --8804260205 Change Notice 601 to Rev 3 to Procedure CPP-006, "Sample Selection." ZILL,R.D., SCHAUF,J.M. Evaluation Research Corp. 87/12/21, 2pp. 45281:143-45281:144
- -8804260210 Change Notice 001 to Rev 8 to Procedure CPP-010, "Preparation of Deviation Repts" HODGE,D.A Evaluation Research Corp. 88701720, 2pp. 45281 145-45281 146
- --8804280215 Notice of cancellation of Rov 3 to Procedure CPP-018, "OA/QC Interface w/Dosign Adequacy Program" HODGF, D.A., ZILL R D. Evaluation Research Corp. 87/12/15 tp 45281:147-45281:148.
- --8804260219 Change Notice 002 to Rev 1 to Procedure CPP-026, Final Review of Issue Specific Action Plans (ISAP) VII.o & Other Sefected ISAP Working Free HUDSON,D F Evaluation Research Corp. 88/01/13, 2pp. 45281:149-45281:150
- --8804260222 Change Notice 001 to Rev 1 to Procedure CPP.026, "Final Review of Issue Specific Action Plans (ISAP) VII C & Other Selected ISAP Working Files "ZILL,R.D. Evaluation Research Corp. 87/10/14 [3pp. 45281:151-45281.153].
- --8804260226 Rev 3 to Procedure CPP-027, "Rainsp/Documentation Review of Purchased Safety-Related Matl & Equipment 2ILL, R.D. Evaluation Research Corp 87/10/23 17pp, 45281.154-45281:170.
- --8804260230 Notice of cancellation (Rev 1) to Rev 3 to Instruction OI-009, "Document Review of Conduit/R-E CDUT."

 ZILL, R.D., PATTERSON A.A. Evaluation Research Corp. 87/09/30, 2pp. 45281.171-45281.172
- --8804260235 Chango Notice 002 to Rev 4 to Instruction QI-019, "Reinsplot Small Bore Pipe Supports" ZILL,R.D. SCHAUF,J. Evaluation Research Corp. 87/09/29 2pp 45281:173-45281:174
- --8804260237 Change Notice 002 to Rev 1 to Instruction GI-022, "Documentation Review of Piping Sys Bolled Joints/Malls."

 ZILL,R.D., SCHAUF,J.M. Evaluation Research Corp 87/09/22. 3pp 45281:175-45281:177
- --8804260241 Chango Notice 002 to Rev 3 to Instruction QI-027, "Reinsp of Large Bore Rips Supports Rigid." ZILL.R.D., SCHAUF, J.M. Evaluation Research Corp 87/08/29 2pp 45281.178-45281.179.
- --8804260243 Change Notice 002 to Rev 3 to Instruction CI-029, "Roinsplot Large Bore Pipo Supports Non-Rigid." ZILL,RID, SCHAUF, J.M. Evaluation Research Corp 87/09/29. 2pp. 45281:180-45281:181.
- --8804260247 Chango Notice 001 to Revi 4 to Instruction QI-045, "Reinspiol Procedures for Structural Steel," ZILL, R.O., SCHAUF, J.M. Evaluation Research Corp. 87/09/29, 2pp. 45281:182-45281:184.
- --8804260250 Change Notice CD1 to Rev 3 to Instruction QL051, "Refinsp of Pipe Whip Restraints."
 ZILL,R.D., SCHAUF,J.M. Evaluation Research Corp. 87/09/29. 2pp. 45281:185-45281:186
- --8804260263 Change Notice 001 to Rev 2 to Instruction OI-053, "Reinsp of Calegory I Conduit Supports/I-5-COSP,"
 ZILL,R.D., SCHAUF,J.M. Evoluation Research Corp. 87/09/14 2pp 45281:187-45281:188
- --8804260254 Change Notice 002 to Roy 2 to Instruction QI-055, "Roinsplot Instrument Pipe/Tube Supports/I-S-INSP." ZILL, RO. SCHAUF, J.M. Evaluation Rosearch Corp. 87/09/29 2pp 45281:169-45281:190
- 8804210351 Final response to FCNA request for documents re plant. Forwards App D documents App C & D documents available in PDR GRIMSLEY, D. Division of Ruice & Records (Post 870413). 88/04/18. CONNOR, L Doc-Search Associates. 4pp. 45192.204.45192.209.
- --8804210355 Page from draft rept on plant SAFETEAM activity & Oto of Investigations review.

 * NRC No Detailed Affidation Given 88/04/18, 1p. 46192 208-45192:209.
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 8804010162 Forwards SSER 14 to NUREG-0797 rol operation of plant Suppl presents safety evaluation on matters re-corrective action program associated w/design of large 8 small bore piping 8 pipe supports.Corrective action program acceptable.W/o enct. GRIMES.C.1. Ofc of Special Projects. 88/03/99. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.). 1p. 44940.021-44949.021.
- F. Security, medical, emergency & fire protection plans
- 8804040258 Forwards Insp Rept 50-445/68-16 on 880301-02:No violations or deviations noted.
 WARNICK,R.F. Old of Special Projects. 88/03/29, COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.). 4pp. 45072-012-45072-016.
- --8804040261 Partially withheld Insp Rept 50-445/88-16 on 880301-02 (ref 10CFR73.21) No violations or deviations noted Major areas inspected security plan & procedures & vitel area barriers. EARNEST.A.B. YANDELL,L.A. Region 4, Ofc of the Director. 88/03/22. 1p. 45072.016-45072.016

104, "Emergency Proparedness Dirl's & Exercise" & Rev 5 to EFP-206, "Activation of Emergency Operations Faculty (EOF) & EOF Personnel Cures " W/880419 ltr. COUNSIL,W.G., WOCDLAN,D.R. TU Efecinc (formerly Texas Unites Generating Co.) 8870419, 22pg 45244 280-45244:301.

G. Adjudicatory correspondence

8804050044 Advises that Cygra Energy Sycs,Inc documents,notuding N Williams 860217-19 deposition & exhibits,obtained & evaluable for review in titl Datas,TX ofc W/Certificate of Syc Related correspondence.

NEWMAN,JR 10 Electric (formerly Texas Utilities Generating Co.) NEWMAN,JR Newman & Holtzinger. #288 5993. 88/03/30. MCORE,JE Assistant General Counsel for Hearings EttlS,J. Cilizens Association for Sound Energy 5pp. 44965.101-44966.105

8804050085 NRC Staff response in support of applicant motion to consolidate proceedings.* Consolidation would result in efficient use of parties resources Notices of appearance & withdrawaf encl W/Certificate of Svc. MOORE, J.E. Assistant General Counsel for Hearings. #288 5973 88/09/30. Alomic Safety and Urcensing Board Panel. 16pp. 44566 077-44866 092.

8804050109 Forwards Exhibit 18 introduced to record by counsel for colowners during Williams 880218 deposition & Pages 190-195 & 464-465 of transcript,representing entire contents of deposition releasing twiceful cate of Svc NEWMANJIR Newman & Hollzinger. #288 5994. 88/03/30 BLOCH,P.B., JORDAN,W.H. MCCOLLO'A,K.A. Atomic Safety and Licensing Board Panel 35pp. 44968 106-44966 140 44968.106-44966-140.

8804060049 CASE answer to applicant 880008 motion to consolidate proceeding. CASE opposes motion because applicant view of issues in error Certificate of Svo

GARDF,B.P., Government Accountability Project ELLIS,J. Citizens Association for Sound Energy, #288-6010, 88/03/30. Atomic Safety and Licensing Board Panel, 14pp. 44983-040-44983-053.

8804050033 Forwards list of persons appearing at N Whams of CYGNA deposition, clarifying that Etia in transcript not same as J Ellia of CASE, por J Ellis request W/Corthicate of Svc. Related correspondence. NEWMAN, JR. TU Electric (formerly Texas Ullitres Generating Co.). NEWMAN, JR. Newman & Holtzinger. #288 5990 88/03/31. BLOCH, P.B., JORDAN, W.H., MCCOLLOM, X.A. Atomic Safety and Licensing Board Panel. 6pp 44956:166-44966:173.

8804050039 Advises that encil list of documents in SSER 14 identified as not available in PDR being made available in util document room in Dalias,TX,pcr J Moore 880310 it: W/Certificate of Svc NEWMAN,JR, TU Efectic (formerly Texas Utilities Generaling Co.), NEWMAN,JR, Newman & Hollzinger, #286 5991, 68703/31, BLOCH,P.B., MCCOLLOM,K.A., JOHNSON,E.B., Atomic Safety and Licensing Board Panel 3pp. 44966180-44966:187.

8804050092 Notice of availability of documents underlying SSER 14.1 Notice given that documents underlying NRC SSER 14 for facility available for inspile copying in LPDR in Arthoglop, TX & in PDR W/Certificate of Svc Related correspondence.

MOOREJE: Assistant General Counsel for Hearings #288 5974 88/03/31, 3pp 44966 093-44966:095.

8804110026 Memorandum & order.* Util motion to consolidate OL & CP amend cases denied Served on 880407 BLOCITIPB. MCCCILLOM,K A., JOROAN,W H. Atomic Safety and Licensing Board Panel. #288 6032 88704/06. TU Electric (formerly Texas Utilities Generating Co) 3pp. 45049 254-45049:256.

8804110017 Furwards applicant seventh submission in response to Board 870812 request for response to notices of violation & devations Responses cover period of 880225 to 880329. Certificate of Svc end Related correspondence EDGAR, G. L. TU Electric (formerly Texas Utilities Generating Co.). EDGAR, G.L. Newman & Holtzinger. #288 6035. 88704/06. PLOCIT, P.B., JORDAN, W.H., MCCOLLOM, K.A. Atomic Safety and Licensing Board Paner. 4pp. 45048-348-4664-018.

8804110023 Forwards recently issued INPO rapt dealing w/operational aspects of facility 8 ubliresponses re-activities Mattis to be submitted as evidence but are for 8pard into Couldicate of Sycienci.

RIDGARGICAL TU Flectric (formerly Texas Utilities Generating Co.). FDGAR.G.L. Newman & Holtzinger. #288 6038. 88/04/06 BLOCH.P.B. JORDAN,W.H., MCCOLLOM,K.A. Atomic Safety and Licensing Board Panel 185pp 45049-025-

8804180019 Forwards uit 880406 itr transmitting errata to project slatus repts for 'Equipment Qualification' & "Electrical." Related correspondence. WOOLDRIDGE,R.A. Tu Electric (formerly Texas Utritios Generating Co.) WOOLDRIDGE,R.A. Worsham, Forsythe Sampels & Woolndge (formerly Worsham, Forsythe & Sampels). #288 6661. 88704706. BLOCH,P.B. JORDAN,W.H., MCCOLLOM,K.A. Atomic Safety and Licensing Board Panel. 2pp. 45128.027-45138.098.

8604180030 Informs that applicants notified Board & parties of availability in TU Electric document room of matts ret in NAC SSER 14.W/Certificate of svc. EDGAR,G.L. Newman & Hottemper. #288 6060, 88/04/08. BLOCH,P.B., JORDAN,W.H. MCCOLLOM,K.A. Atomic Safety and Licensing Board Panel 6pp. 45128:042-45128 047.

8804200038 Confirms 880411 telcon requesting 10-day extension of time to 880428 for CASE to specify issues of interest re project status repts dealing w/large & small bore piping & pipe supports & NRC Staff SSER 14.Related correspondence. SCHMUTZ,T.A Nawman & Holtzinger #286 6075 88/04/12. ELLIS,J Citizens Association for Sound Energy. 1p. 45160:173-45160:173

880420023 Motion for reconsideration of Licensing Board memorandum & order of 880405 & request for oral argument." Requests that Board schedule oral argument on issues taised by applicant Instant motion Certificate of svc encl.

NEWMAN,J.R. 1U Electric (formerly Texas Utilities Generating Co.). NEWMAN,J.R. Newman & Holkinger. #288 6072 88/04/15. Atomic Safety and Licensing Board Panel. 11pp. 45182:148-45162:156

BBUSZUNUST FIELD SIRU MIGURI IGE FECONSIDERRIAN OF CISHICANON OF OTDER AL RAU Licensing Board order has four consequences which are inconsistent wifers a reconsistent wifers are Commission practice & procedures Certificate of Svc encl. MOORE_IE Assistant General Counse) for Hearings #288 6073 88/04/15 At Salety and Licensing Board Panel. 9pp. 45162-105-45162-113.

8804280073 Forwards initial complaint of J Goose & amended complaint of Real in order to keep Board Informed of potentially significant who proceedings Questions raised to how applicant rainspip organish being implemented ELLIS,J. Citizans Association for Sound Energy #288 6104 88704715 BLOCH, MCCOLLOM,K.A., JORDAN,W.H. Alomic Safety and Licensing Board Panel 145210-301-45211-301-45210-301-452 45210:330-45211:024.

8804260056 Memorandum to parties.* Forwards BP Cotter 880311 memo to partie docket files Parties to proceeding requested to conform to BP Cotter request may be deleted from sec fist.Served on 880421. BLOCH.P.B. Atomic Safety and Licensing Board Panel #288 6103, 88/04/20 45211-028-45211:028.

8804260068 Forwards util 880414 Illr in response to questions arising from 67

804280065 Forwards un addated in the state of the public meeting. Co J ECGAR EDGAR G.L. TU Electric (formerly Texas Utilities Generating Co J ECGAR Newman & Hollzinger. #288 6115. 88704721. BLOCH,P.B., MCCOLLCY JORDAN,W.H. Atomic Safety and Licensing Board Panel. 12pp 45210

8804260140 Answers to ASLB 14 questions (memo,proposed memo of 68041-Action Plan Results Report Ld.1.* Action Plan Results Rept Ld.1. "QC (nsp Qualifications" encl.W/Certificate of Svc. YOUNG.J.E., CHRISTEMSENJ, TU Electric (formerly Texas Utilitias Generaling #288 6114, 88/04/21, 62pp. 45209 318-45210.019.

8804260260 Notice of availability of Issue Specific Action Plan ISAP VII a 9 results working Islas.* Working Islas available for copying at site.Certificate of encl.Related correspondence.
EDGAR,G.L. TU Electric (formerly Texas Utilities Generating Co.), EDGAR Newman & Hotzinger, #288 6116, 88/04/21, 5pp. 45210.081-45210.085

6804260286 Notice of availability of collective significance rept & working f.les * Wo f.les for collective significance rept available at stated address Certificate of Svc Related correspondence.

EDGAR,G.L. TU Electric (formerly Toxas Utilities Generating Co.) EDGAR Newman & Holtzinger, #286 6117, 88/04/22, 5pp. 45210:056-45210:060

8804290129 Forwards applicants answers to Board 14 questions re Action Plan Ro Rept VII.a.9.Checklists used for reinsp/ documentation review for 81 (terms of e-ment & mail not included w/answers due to vol amounting more than 1,000 pp EOSAR.G.L. Newman & Hollzinger #288 6156. 88/04/26. BLOCH, MCCOLLOM.K.A. JORDAN.W.H. Atomic Safety and Licensing Board Panel 45255 145-45255 145.

-9804290146 Answers to Board 14 questions re Action Plan Results (Memo.proposed memo of 860416) regarding Action Plan Results Rept Vil a 9 swers submitted per Board 850414 memorandum.proposed memorandum 8 ords Certificate of Svc.
CHRISTENSEN,J., HANSEL,J.L. TU Electric (formerly Texas Utilities Generating 88/04/28, 16pp. 45255:148-45255:161.

H. General correspondence

8804140002 Notifies of LM Polizzi 870812 ftr to US Dept of Labor ro all discrimination, easignment to position away from site & eventual termination bed of safety concerns raised on job. Violation of 10CFR80 7 may have occurred. EBNETER, S.D. Ofc of Special Projects. 88704/11. COUNSIL, W.G. TU Electric merly Texas Utilities Generating Co.) 9pp. 45120:218-45120:226.

P. Operating license stage documents & correspondence

8804220078 Requests that util submit responses to questions resulting from 8893 meeting re-cable pulling operations & cable splices especially re-differences in tation & insp procedures & personnel training & qualification. GRIMES.C.I. Off of Special Projects. 88/04/15. COUNSIL,W.G. TU Electric (for Texas Utilities Generating Co.). 3pp. 45201.019-45201.021.

Q. Inspection reports, IE Bulletins & correspondence

8803080287 Forwards Insp. Repts 50-446/88-05 & 50-446/88-04 on 880105- 92 notices of violation & deviation. WARNICK.F.F. Oto of Special Projects. 88/03/02. COUNSIL.W.G. TU Electric merty Texas Utilities Generating Co.). 6pp. 44634:004-44634:034

--8803080292 Notice of violation from Insp on 880105-0202.Violation noted depre exceeding 1/32 Inch in depth observed WARNICK R.F. NRC - No Detailed Alfillation Given, 88/03/02. 2pp. 44634

8803080301 Notice of deviation from lnsp on 880105-0202.Dev noted:Nonconformance Rept NCR-87-A00491 & QC hold point not trended a quired by FSAR to identify any trend adverse to quality. WARNICK,R.F. NRC - No Detailed Affiliation Given. 88/03/02. 1p. 44634.412. --8803080301

--8803080311 Insp Repts 60-445/88-06 & 50-446/88-04 on 880105-0202. One vio & deviation noted Major areas Inspected: assessment of allegations, followup on tons/deviations, & corrective action program for small bare piping. LIVERMORE,H.H. Oto of Special Projects, 88/03/02, 22pp, 44634-013-44634 03-

8803080488 Forwards request for addI into re 860514 & 0714 responses to IE Bi 85-003."Motor Operated Valve Common Mode Fallures During Plant Transfert D Improper Switch Settings." Response requested by 860401, GRIMES,C.I. Ofto of Special Projects. 88/03/03. COUNSIL,W.G. TU Electric (for Texas Utilities Generating Co.). 5pp. 44639.032-44639:036.

- 8803300009 Forwards Insp. Repts 50:445/88-11 & 50:446/88-09 on 880203-0301 No worations of deviations roted WARNICK,RF Old of Special Projects 88/03/22 COUNSILW G TU Electric (formerly Towas Utilities Generating Co.), 4pp. 44921 298-44921 317
- -8803300014 Insp Repts 50:445788-11 & 50-446788-09 on 880203 0301 No walations or deviations identified Major areas inspected applicant actions on previous insplindings, followup on violations/deviations & corrective action program LIVERMORE, IFH Oto of Special Projects 88/03/22 16pp 44921302-44921317
- 6804050280 Ack recept of 880115,0216,0315 & 0318 ltrs informing NRC of steps taken to correct vicilations noted in linsp Repts 50-445/87-30 & 50-446/87-22 WARNICK,R F. Ofc of Spocial Projects 88/03/25 COUNSIL,W.G. TU Flectric (formerly Toxas Utilities Generating Co.). 5pp. 44997 172-44997 176
- 8803210090 Supplif to NRC Into Notice 87-044, "Thimble Tube Thinning in Westing-house Reactors" Svellist and ROSSIC E Division of Operational Events Assessment (Post 870411) 68/03/28 Corsolidated Edson Color New York, Inc. 121pp. 44995;126-44995;246
- 880322029B NRC Info Notice 88-010, "Matts Licensees Lack of MgI Controls Over Li-censed Programs" Svc list enci-CUNNINGHAM.A E Division of Industrial 8 Medical Nuclear Safety (Post 870729) 887-03728 Consociated Edison Co. of New York, Inc. 108pp. 44995 247-44995 350
- 8804060515 Informs of util intent to remove tube vibration instrumentation installed in stoam generators as part of witration tost program described in util 840312 th Approval requested for of mination of vibration monitoring program COUNSIL,WIG. BECK,J.W. TU Electric (formorly Toxas Utilities Generating Co.) 68/ 03/28. Document Control Branch (Document Control Dusk) 2pp. 45097.105-46087.46 45007.106.
- 8804040258 Forwards Insp. Rept. 50-445/88-16 on 880301-02 No violations or devialions colod WARNICK,R F. Old of Special Projects. 88/03/29. COUNSIL,W.G. TU Electric (for-marky Texas Unities Concrating Co.). 4pp. 45072 012-45072 016.
- 8804040261 Partially withhe'd Insp. Rept. 50:445/88:16 on 880301-02 (rof 100CFR73.21) No violations or deviations noted Major areas inspected security plan & procedures & vital area barriers EARNESTA.B. YANDELL, LA Region 4, Old of the Director 88/03/22 1p. 45072 016-45072 016
- 8804080063 Ack receipt of 880324 lt/ informing NRC of steps taken to correct violations releat in Insp Ropts 50-445/88 0.1 8 50-446/88-0.1 WARNICK.R.F. Ot of Special Projects 80703/30 COUNSILW 6 TU Effecting (formerly Toxas Utilities Generating Co.), 4pp. 45007 276-45007:279
- 8804060375 Updated response to violations noted in Irisp Repts 50 445/85-13 & 50-446/85-09 Corrective actions Rov 7 to Procedure STA-606 issued on 890227 to most original corrective action response commitment COUNSIL, W.G. TU Electric (formerly Toxes Utilities Generating Co.) 88/03/39. Document Control Branch (Document Control Dask) 1p. 45006-328-45066-328
- 8804060398 Informs that completion of removal of unauthorized spices & wire nots from Unit 1 childrigands rescherblight for completion by 880531 per util 880129 response to violations noted in linsp Repts 50-445/87-11 & 50-446/87-09 COUNSTLWIG. TU Electric (formerly Toxas Utilities Generating Co.) 88/03/30 Decument Control Branch (Document Control Desk). 1p. 45010-225-45010-225.
- 8804060494 Informs that date for complution of training of contractor personnel changed to 880601,per util 880201 response to violation noted in linsp Repts 59 4457 87-27 & 50-446/87-20.

 COUNSIL,W.G. TU Efectine (formerly Texas Utilities Generating Co.) 88703730 Document Control Branch (Document Control Dask). 1p. 45010 299-45010 299.
- 8804060525 Revises date of full compliance for notice of violation noted in Insp Repts 50 445/86 03,50-446/86 02,50-445/86 22 & 50 446/86-00 Corrective actions will be completed no later than 881223 for Unit 1 & common HVAC.

 COUNSIL W.G. TU Electric (formerly Texas Utilities Generating Co.) 88/03/30 Decument Control Branch (Document Control Dosk). 1p. 45008 355-45009 355
- 8904060517 Responds to NRC 880302 ltr re-violations & deviations noted in Insp Repts equipolists Hespionos to NHC BBL302 III fo violations & deviations polled in Insp Hopts 50-445/88-04 Generalization actions Nonconformance. Rept. 85.03838 issued to disposition welling depression. COUNSIL.W.G., WOODLAN,D.R. TU Electric (formerly Texas Utilities Generaling Co.) 88/03/31. Document. Control. Berotating Co.) 45007:107-45007:111.
- 45077 120
- 8804010256 NRC Into Notice 88-011, "Potential Loss of Motor Control Cir &/or Switch-board Function Due to Faulty Tio Bolts" Syc 1st encl. ROSSI/C E Ovision of Operational Events Assessment (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 124pp 45408 292-45407.051
- 8804120431 Forwards Insp. Repts 50-445/88-19 & 50-446/88-16 on 880302-0405 No violations or devalions noted.

 WARNICK,R.F. Otc of Special Projects 88/04/08 COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.), 4pp. 45130 248-45130 260.
- 8804120435 Responds to 890205 NRC Bulletin 88 001 re defects in Westinghouse circult breakers in Crass IE applications to perform short-torin & long-torm insplusing listed additions. Insps will commence when replacement parts onstell COUNSIL, W.G. TU Electric (formerly Texas Utilities Generating Co.). 88/04/08. Document Control Branch (Document Control Branch (Document Control Desk). 3pp. 45091:018-45091:020

- 8004130003 Forwards add info ro IE Buretin 85.003, Molor-Operated Valvo Common Mode Pairbres During Plant Transients Due to Juliproper Switch Soltings," per NRC 880303 roquest COUNST WIG TO Electric (formerly Texas Utilities Generating Co.). 88704708. Document Control Branch (Document Control Desk). 5pp. 45099.316-45099.320.
- 8804130287 Respands to NRC 880208 titlled open state in this Repts 50,4457 87-37 & 50,446787-28 Results of engineering functional evaluation of some identified in CLIG: mes 680208 & 871015 lins schinduled for completion in May 1988 GCUNSIL,WIG TU Electric (terrently Texas Unities Generating Co.) 88704711 Document Control Branch (Document Control Dask), 123pp. 45147-038 45147:158
- 8804190003 Forwards Insp. Repts. 50 445788-18 & 53-446788-15 on 860302-0405 No. violations or doviations noted
 WARNICK,R.F. Ofcol Special Projects 68/04/11 COUNSILW.G. TU Electric (formetly Texas Ultifies Generaling Co.). Spp. 45208:164-45208.181
- --8804190007 Insp. Hepts 50-445/88-18 & 50-446/88-15 on 880302-0505 No violations or deviations rated Mg.or areas inspected action on previous rep. findings, followup on violations/deviations, processing info indices & assessment of allegations. HALE.C.J. LIVERMORE.H.H. Ofc. of Special Projects. 88/04/11 12pp. 45208.169-45208 181
- 8804060370 NHC Info Notice 88-012, "Givergreasing of Efecting Motor Bearings" Svc Test end. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165.028.45165.150.
- 8804280634 Forwards Insp Repts 50-445/88-29 & 50-446/88-25 on 880222- 0329 Rospenso addressing technical open items to inconsistency of design criteria w/FSAN or industry stds & noed for add confirmation of designs & hardware requested. GRIMES.CT. O'c of Special Projects, 88/04/14. COUNSIL.W.G. TU E'cotnic (formerly Texas Ut littles Generaling Co.). Epp. 45269.097.45269.167.
- -8804280640 Insp. Repts 50 445/88-29 & 50-446/88-25 on 880222-0329.Major areas nspected dosign ivalidation inackages in lareas of mechanical & HVAC systemitistic true tural eluctrical instrumentation/controls & systemiciation NORKIN 0.P., LYONSUE Ofc. of Special Projects 88/04/13 66pp 45269.102-
- 8804200397 Forwards Insp Repts 50-445/88-21 & 50-446/88-18 on 880302-0405 No v.clailons of dovalions noted WAFINICK.R.F. Old of Special Projects 88/04/15 COUNSIL,W.G. TU Electric (formarily Toxas Utilitias Generating Co.). 32p. 45231-086-45231-105
- --8804200400 Insp. Repts 50-445/88-21 & 50-446/88-18 on 880302-0405 No vicibilions or divisitions roted Weaknesses noted Major areas inspected actions on Comarcha Peak response team issue, specific action prans & general plant lours. RUNYAN,M.F. LIVERMORE,H.H. Ofc. of Special Projects 88/04/15 17pp 45231-089-45231-105
- 8804200472 Responds to NRC 980317 ltr re-violations noted in ling Repts 50-445/88-12 & 50-446/88-10 Corrective actions Delicioncy Rept C-88-90996 written to docu-ment faction to initiate FSAR change requisit CCUNSIL, WG_TU_Electric (formant Costs) Unities Generaling Co.) 88/04/15 Decu-ment Control Branch (Document Control Desk) 3pp. 45235-089-45235-071
- 8804200478 Submits revised (fate of full compliance to vicibilians noted in Insp Repts 50-445/87-30 & 50-446/87-22 Vendor drawing Shoot 3 discussed in 880216 ft/ will be made inscrive no later than 880815, not 880415 as stated COUNSIL, W.G. TU Electric (formsrly Taxas Utilized Genorating Co.) 89/04/15. Decument Control Branch (Document Control Desk) 1p. 45235 072-45236 072
- 8804200489 Advises that date of full compliance for violations noted in Insp Ropts 50-445/86-22 & 50-446/88-20 revised from 880415 to 880715 Delay necessitated by fact that addit into needed from valve supplier only recently received COUNSIL W.G. TU Electric (termetry Towns United Senerging Co.) 88/04/15 Decument Control Branch (Document Control Dosk) 1p. 45235 110-45235:110.
- 8804280014 Forwards Insp Ropts 50-445/88-22 & 50-446/88-19 cri 880302- 0405 No violations or dovisions inded WARNICK, R.F. Olic of Special Projects. 88/04/20. COUNSIL, W.G. Tu Electric (formerly Texas Utilities Generaling Co.) 4pp. 45248-095-45248-113
- --8804260016 k/sp Repls 50-445/88-22 & 50-446/88-19 on 880302-0405 No violations noted Weaknesses in training programs identified. Major greas inspected MRC building to lowup, monthly maint observation, fuel recept & storage & Reg Guide 1 97 OA BITTERS O., BURRISS P., WIEBE J.S. Ofc. of Special Projects. 887844/20. 15pp 45248:099 45248 113.
- R. Periodic operating reports & related correspondence
- 8804110113 Forwards Securities & Exchange Commission Form 10-K for 1997 & util 1997 annual rept W/o oncis COUNSIL W G., WOODLAN D.R. TU Electric (formerly Texas Utilities Generating Co.) 88/03/3.) Decument Control Branch (Document Control Desk). 1p. 45077-294-45077:294.
- 8804140525 Submits weekly schedule of TVA activities for wk of 880404- 11.Schedule will be updated 8. ssued each Friday to relical activities to: forthcoming 2.wk period KELLY.J.L. Old of Special Projects. 88/03/31. ZECH,G.G. Old of Special Projects. 4pp. 45130-205-45130-208
- 8804130112 Forwards errata to equipment quolification & electrical project status repts previously submitted by 880108 & 0115 lins (CQUNSIL,W G TU Electric (formerly Texas Utilities Generating Co.) 88/04/06 Document Control Branch (Document Control Desk) 7pp. 45122 231-45122 236
- S. Reportable occurrences, LERs & related correspondence

- 8804050340 Interim Deliciency Rept CP 87-122 in nozzle load stresses. Initially reported on 880105 Evaluation continuing Next rept will be submitted by 880414. BECK,J.W., COUNSIL,W.G. TU Electric (formerly Toxas Utilities Generating Co.), 887-03728. Document. Central. Branch. (Document. Control. Desk.). 1p. 45034-035-45034-035.
- 8804060081 Final supplemental Deticiency Ropt CP-79-08 relepace criteria for installation of H.*s concrete drilled in expansion anchors in tally reported on 801210.Corrective actions sthin progress. COUNSIL,W.G., BECKUW TU Electric (formerly Taxas UTI too Generating Co.). 887 03/29 Document Control Branch (Document Centrol Desk). 2pp. 45046-197-45046-198.
- 8804060097 Interim Doliciency Rept CP-87-132 re unqualited Limitorque actuators in tually reported on 880105. Evaluation of completion schedule for ongoing corrective actions continuing Next rept expected by 880607 COUNSIL W.G. TU Electric floring the superior State of Control Press Utilia of Generating Co.) 88703729 Document Control Branch (Document Control Deskil 1p. 45048-102-45048-102.
- 8804080105 Suppremental Deticioncy Rept CP-87-03 re 6.9 kV switchgear installation initially reported on 870316 Compretion of replacement of Jackshafts rescholded for 880429 All other corrective actions for issue continuing on schedule. COUNSIL, W.G. Tut Electric (torredly Texas Utilizes Generating Co.). 88/03/29. Document Control Branch (Document Control Desk). 1p. 45072-040-45072-040
- 8804060188 Supplemental Deliciency Rept CP-82-07 rol detective governor drive couplings on diesel generators Initially reported on 820508 Unit 2 couplings scheduled for complotten by fuol load COUTSNLW G. WOODLAN,D R. TU Electric (termenty Texas Utilities Generating Co.) 68703730. Document. Control. Brench. (Document. Control. Desk). 1p. 45028-359-45028-359.
- 8804080327 Supplemental Deficioncy Rept CP-84-08 re-curtain fire-dampers.in helly reported on 840720 Corrective actions will be completed by 881228 for Unit 1 & common areas & fuel load for Unit 2 COUNSIL, W.G. Tu Electric (formerly Texas Utintes Generating Co.), 88703/30. Document Control Branch (Document Control Desk). 1p. 45047-070-45047:070.
- 8804080376 Suppremental Deficiency Rept CP-83-15 re-bolting mattrused for cable tray clamps fint ally reported on 830712 Issue will be addressed & resolved in Deficiency Rept CP-83-35. Next rept expected by 880427. COUNSIL,W G. 10 Electric (formerly Texas Utilines Generating Co.). 88703730. Document Centrol Branch (Document Centrol Desk). 1p. 45047-098-45047-098.
- 8804080393 Supplemental Deficioncy Rept CP-86.54 re design & installation of control room certing intuatly reported on 861003 Structural mode required as result of design basis consolidation program will be completed by 880601. COUNSIL, W.G. TU Electric (formerly Texas Utilities Ganerating Co.). 88/03/30. Document Control Branch (Document Control Desk), 1p. 45047:097-45047.097.
- 8804060399 Final Deliciency Rept CP-87-118 re postulated failure of nurge regulating volves imitally reported on 880113 installation of pressure reflet devices will be completed by 880630 for Umit 1.8 fuel foad for Umit 2. COUNSIL, W.G. TU Electric (formerly Toxas Utilities Generating Co.). 88/03/30. Document Control Branch (Document Control Desk). 1p. 45047:175-45047.175.
- 8804060405 Supplemental Deficiency Rept CP-85-54 re discrepancies in supplier provided NVAC support documents initially reported on 860926.Const rework of HVAC supports will be completed by 880331 for Unit 1.8 fuel load for Unit 2. COUNSIL,W.G. TU Electric (formerly Texas Util fice Generating Co.). 88/03/30. Document Control Branch (Document Control Desk). 1p. 45047:265-45047.265
- 8804050026 Final Policiancy Rept CP-87-121 re 6.9 kV/480-voll transformer bus bar clearance initially reported on 880108 Preliminary analysis required to demonstrate qualification completed by Westinghouse,Util to implement minor mod COUNSIL.W G. WOODLAN.O.R. TU Electric (formerly Taxas Utilities Generating Co.) 88703731. Document Control Branch (Document Control Desk). 1p. 45017:251-45017:251.
- 8804050027 Final Deficiency Rept CP 86-45 re Seismic Category II sys & components Initially reported on 871018 Unit 1 corrective actions currently scheduled for completion by 861215 Unit 2 corrective actions will be completed prior to leaf load COUNSIL, W.G., WOODLAN, D.R. TU Electric (formerly Texas Unlittee Generating Co.), 88703/31. Decument Control Branch (Document Control Desk). Ip. 45017:253-45017:253.
- 8804050034 Supplemental Delicioncy Rept CP-87-23 re Class 1E conduit Installation runs coupled w/unions not lightened.In liailly reported on 870727 Corrective action currently scheduled not to be completed until 880831 due to time constraints. COUNSIL,W.G., WOODLAN,D.R. TU Electric (formorly Texas Unlities Generating Co.) 88703731. Document Control Branch (Document Control Desk). 1p. 45017:252-45017:252.
- 8804050038 Final Deliciency Rept CP-87-132 re unqualified Limitorque actualors initially reported on 860105 All Class 1E Limitorque actualors will be examined & corrected where necessary under Field Verification Method TE-FVM-EQ-047. COUNSIL,W.G. WOODLAN,D.R. TU Electric (formerly Texas Utilities Generating Co.). 887/03/31. Document Control Branch (Document Control Desk). 1p. 45028-250-45028-250
- 8804080141 Interim Deficiency Rept CP-86-10 re electrical penetration assemblies. Initially reported on 860424 Items I B 1 a . I B 1 c & I B . 4 a from App B of Enforcement Action 86-09 still in progress New complation date expected by 880701. COUNSIL, W.G. TU Effecting (formerly Texas Utilities Generating Co.). 68704704. Document Control Branch (Document Control Desk), 1p. 45092.193-45092:193.
- 8804130202 Final Deficiency Rept CP-88-12 re violation of electrical separation criteria initially reported on 860111. Saloty-related electrical equipment will be reinap & cable redesignation will be completed by 88000 to COUNSIL, W.G. TU Electric (formerly Texas Utilities Generating Co.), 88/04/08 Document Control Branch (Document Control Desk), 2pp. 45137;150-45137;151.

- 8804210188 Interim Deliciency Rept CP-88-28 ra cracks found in several sectors of tube steet utilized in site fabrication of pipe supports Util continuing evaluation of rig process at supplier facility Next rept will be submitted by 880715.
 COUNSIL W.G., MARSHALL, S. Tu Electric (formerly Texas Utilities Generating Co) 88/04/13. Document Control Branch (Cocument Control Desk). 2pp. 45215365-4504638.
- 8804210205 Final Deliciency Rept CP-88-27 re quality code downgrade of Weslinghouse 7300 sys printed circuit cards linitally reported on 880314.Replacement of subjicards will be accomplished prior to 890301.

 COUNSILW G., MARSHALLUS TU Electric (formerly Taxes Utilities Generating Co) 88704/13. Document Control Branch (Document Control Desk). 3pp. 45231:170-45231.172
- 8804210092 Final & Interim Deliciency Rept CP-87-122 rg nozzle load interfaces in tair reported on 871125 Overstress protrems can be diminated by modifying claps Cipmods & romaining corrective action to be completed by 880901 COUNSt., W.G., WOODLAN, D.R. TU Electric (formerly Texas Utilities Generating Co) 88704714, Decument Centrol Branch (Document Control Dosk), 2pp. 4522628345226289
- 8804210145 Final Deliciency Rept CP-86-83 rg use of separation barrier matt (SBM) on power cables & power raceways Initially reported on 870605-SBM from power cables/ raceways removed per NCR CE-87-8577 & Const Procedur
- 8804210161 Interim Rept CP.86-92 & Supplemental Rept CP.87-76 re-splice connections & field drifted cable holes in plants Initially reported on 870429 Corrective action completion dates being evaluated Next rept will be submitted by 803615. COUNSIL, W.G. T.U. Electric (Ionmerly Toxas, Utilities Generating Co.), 88704715 Document Control Branch (Document Control Desk). 1p. 45216:177-45216.177.
- 8804210173 Supplemental Deliciency Rept CP-86-53 re soismic design of conduit Initially reported on 861021 Corrective actions for Unit 1 rescheduled for completion by 880926 COUNSIL.W.G. TU Electric (formerly Texas Utilities Generating Co.). 88/04/15 Decement Control Branch (Document Control Dosk). 1p. 45221-205-45221-205.
- 8804210180 Supplemental Deficiency Rept CP-87-50 re abnormal thrust bearing temps on turbino driven auxiliary feedwater numbs. Naw schedule date for completion is 890515 due to continuing delays in supply of mall & repair instructions COUNSIL, W.G. TU Electric (formerly Texas Utilities Generating Co.). 88/04/15. Document Centrol Branch (Document Centrol Desk). 1p. 45218-163-45219.163
- 8804210239 Final Deficiency Rept CP-86-49 re adapter modules & electrical penetrations. In fally reported on 861010. Unit 1 modules installed & coating engineering verification program modified Unit 2 modules to be completed by unit fuel teload COUNSIL, WG TU Electric (formerly Taxas Utilities Generating Co.) 88/04/15. Document Control Branch (Document Control Desk). 1p. 45231:173-45231:173.
- 8804210249 Final Doticiency Rept (Unit 1) & Interim Doficiency Rept (Unit 2) CP-86-35 re-motor operators in several valves in main steam sys initially reported \$2.880602 Unit 1 design mod to be completed by 880708 Next rept expected by 881231. COUNSIL W.G. TU Electric (formarly Texas Utilities Generating Co.) 88/04/15. Document Control Branch (Document Control Desk). 1p. 45231:147-45231:147.
- 8804210257 Supplemental Deficiency Rept CP-86.51 re anchor bolts supplied by Hill Tensile testing of 1/2 inch diameter holts completed Design aflowables will be revised accordingly 8 included in applicable design documents COUNSIL, W.G. Tu Electric (formerly Texas Utilities Generating Co.): 88/04/15 Decument Control Branch (Document Control Desk). 1p. 45231:174-45231:174
- 8804250099 Suppremental Deficiency Rept CP-84-02 re defective push rods on diesel generators. Includy reported on 840208 New Unit 1 push rods installed & Unit 2 replacement with be compreted after oil flushing & furnover of diesel generators. COUNSIL W G. TU Electric (formerly Texas Utilities Generating Co.). 88/04/18. Document Control Branch (Document Control Desk). 1p. 46224-160-45224-160.
- 8804270001 Final Daticiency Rept CP-87-102 ra cable tray separation criteria Initially reported on 870911.Further evaluation determined that Issue not reportable,per 10CFR50555.W.G. TU Electric (formerly Taxas Utilities Generating Co.) 89/04/22. Document Control Branch (Document Control Desk.). 2pp. 45288;288-45268;289.
- 8804270002 Final Doliciency Rept CP-88-29 re feedwater split-flow bypass valves (FSBVs).In:bally reported on 880323 Westinghouse requested to perform evaluation of FSBV. Corrective actions scheduled for completion by 881031. COUNSIL,W G. TU Electric (formerly Texas Utilities Generating Co.). 88/04/22 Document Control Branch (Document Control Desk). 2pp. 45268-290-45268-291.

T. Hearing transcripts on non-antitrust matters

- 8804110031 Forwards meeting notice & transcript of util & CASE 880225 & 26 meetings re util corrective action program concerning piping & pipe supports.civil/structural & mechanical MALLOY,M. Old of Special Projects, 88703729, WILSON,J.H. Old of Special Projects 4pp. 45076.201-45077:253.
- --8804110033 Transcript of 880225-28 public meetings w/CASE & J Royle.

 * TU Electric (formerly Texas Utilities Generating Co.): 88/02/25. 315pp. 45076:207-45077:253.

V. Operator Examinations

- 8804250088 Responds to FOIA request for Info re-scores of reactor operators & senior reactor operators. Forwards requelification exam summary source sheets listed in encl app w/personal privacy into deleted.
 GRIMSEEY,DH. Dowision of Rules & Records (Post 870413), 88/04/19, BOLEY,K. Public Citizen's Critical Mass Energy Project. 2pp. 45213.003-45213.095.
- -8804250167 Package of NRC administered requalification exam results summary.
 NRC No Detailed Affiliation Given, 87/07/20, 88pp. 45213.007-45213.095.

DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STATION, UNIT 2

A. Application/construction stage documents & correspondence

- 6803060478 Forwards transcript of util 880218 public meeting w/CASE & M Walsh re-corrective action program for cable tray hangers & conduits & conduit supports Notice of meeting also end:

 MALLOY,M. Olic of Special Projects. 88/03/02. Ofc of Special Projects. 213pp.
 44632:202-44633:054.
- 8803100014 Notities that 860912 request to use ASME Code Case N-250-2, "Const of Class 2 & 3 Components for Elevated Temp Svc. Section III, Div 1," acceptable prowided rules of code case governs design & matts selection.
 GRIMES.C.I. Otc of Special Projects, 88/03/03, COUNSIL,W.G. TU Electric (formerly Texas Utilities Generaling Co.). 4pp. 44681:025-44661:028
- 8803240426 Generic Ltr 88-08 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/03/22. Consol dated Edison Co. of New York, Inc. 47pp. 44972:107-44972:163.
- *8804070063 Advises that util performing analyses to validate high energy jet impingament loads presently being utilized at plant. COUNSIL,W.G., BECK,J.W. TU Electric (formerly Texas Utilities Generating Co.), 887-03728. Document Control Branch (Document Control Desk). 2pp. 45030:357-45030:358.
- 8804060221 Notification of contract execution,Mod 18,to "Review & Evaluation of Co-manche Peak Program Plan." Contractor: Teledyna Engineering Svcs. HAGEY,H. Contract Administration Branch. FIN B-1338. 88/03/29. GRIMES,C.I. Ofcot Special Projects. LYONS,J. NRC No Detailed Affiliation Given. 1p. 45018:322-45018.324.
- -8804060233 Mod 18,adding Incremental funds,to "Review & Evaluation of Comanche Paak Program Plan."
 * Teledyne Engineering Services, WIGGINS,E.J. Division of Contracts (Post 870413).
 FIN 8-1338, 88/03/28, 2pp. 45018:323-45018:324.
- 8804110113 Forwards Securities & Exchange Commission Form 10-K for 1987 & util 1997 annual rept W/o encis.

 COUNSIL,W.G., WOODLAN,D.R. TU Electric (formerly Texas Utilities Generating Co.).
 88/03/31. Document Control Branch (Document Control Desk). 1p. 45077:294-
- 8804080088 Generic Lir 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 8B/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184:237-45184:285.
- 8804180332 Partial response to FOIA request for documents.Forwards App B documents App A & B documents also available in PDR.
 GRIMSLEY,D.H. Division of Illules & Records (Post 870413). 88/04/08. CONNOR,L. Doc-Search Associates. 4pp. 45149:330-46149:361.
- --8804180282 Comanche Peak Response Team Action Plan Item VII.a.6, "Exit Interviews." Related into enci.

 BUSH.J.W., HASSEL,J.L. TU Electric (formerly Texas Utilities Generating Co.). 85/06/
 21. 8pp. 45/149:334-45/149:351.
- 8804139236 Forwards response to NRC 870707 request for additinto re Generia Ltr 83-28 concerning vendor interface programs. Procedures to periodically contact vendors of key components to facilitate exchange of current into provided. COUNSIL,W.G., WOODLAN.D.R. TU Electric (formerly Texas Utilities Generating Co.). 88/04/11. Document Control Branch (Document Control Desk). 3pp. 45148:264-
- 8804200499 Forwards addi into re applicability of corrective action program at plant per NRC 880122 request Explanation of significance of deviations from design requirements identified by CPRT also enci per NRC request.

 COUNSIL,W.G. TU Electric (formerly Texas Utilifies Generating Co.). 88/04/14. Document Control Branch (Document Control Desk). 8pp. 45239:061-45239:068.
- 6804260193 Forwards linal revs & Instruction sheets for manuals describing use of plant response learn checklists.
 COUNSIL.W.G. TU Electric (formerly Texas Utilities Generating Co.). 88/04/15. Document Control Branch (Document Control Desk). 10pp. 45281:133-45281:190.
- **8604260205 Change Notice 001 to Rev 3 to Procedure CPP-006, "Sample Selection."
 ZILL.R.D., SCHAUF,J.M. Evaluation Research Corp. 87/12/21. 2pp. 45281:143-45281:144
- ~8894280210 Change Notice 001 to Rev 8 to Procedure CPP-010, "Preparation of Devisiton Repts." HODGE,D.A. Evaluation Research Corp. 88/01/20. 2pp. 45281:146-45281:146.
- ~8804280215 Notice of cancellation of Rev 3 to Procedure CPP-018, "QA/Q0 Interface w/Design Adequacy Process" w/Design Adequacy Program."
 HODGE,D.A., ZILL.R.D. Evaluation Research Corp. 87/12/15, 1p. 45281:147-
- --8804250219 Change Notice 002 to Rev 1 to Procedure CPP-026, "Final Review of Issue Specific Action Plans (ISAP) VII.o & Other Selected ISAP Working Files." HUDSON, 0.F. Evaluation Research Corp. 88/01/13, 2pp. 45281;149-45261;150.

- --8804260222 Chango Notice 001 to Rev 1 to Procedure CPP-028, "Final Review of Issue Specific Action Plans (ISAP) VII C & Other Selected ISAP Working Files." ZILL,R D. Evaluation Research Corp. 87/10/14, 3pp. 45281:151-45281:153.
- --8804260226 Rev 3 to Procedure CPP-027, "Reinsp/Documentation Review of Purchased Safety Related Matl & Equipment" ZILL,R D. Evaluation Research Corp. 87/10/23, 17pp. 45281:154-45281:170
- --8804280230 Notice of cancellation (Rev 1) to Rev 3 to Instruction QI-009, "Document Review of Conduit/R-E CDUT."

 ZILL.R.D., PATTERSON,A.A. Evaluation Research Corp. 87/09/30, 2pp. 45281:171-45281:172.
- -8804260235 Change Notice 002 to Rev 4 to Instruction QI-019, "Reinsp of Small Bore Pipe Supports SCHAUF, J. Evaluation Research Corp 87/09/29, 2pp. 45281:173-
- --8804250237 Change Notice 002 to Rev 1 to Instruction OI-022, "Documentation Review of Piping Sys Botted Joints/Matts."

 ZILL,R.D., SCHAUF,J.M. Evaluation Research Corp 87/09/22, 3pp. 45281:175-45281:177.
- --8804260241 Change Notice 002 to Rev 3 to Instruction QI-027, "Reinsp of Large Bore Pipe Supports Rigid."
 ZILL,R.D., SCHAUF,J.M. Evaluation Research Corp. 87/09/29 2pp. 45281:178-
- -8804260243 Change Notice 002 to Rev 3 to Instruction QI-029, "Reinsp of Large Bore Pipe Supports Non-Rigid" ZILL,R.D., SCHAUF,J.M. Evaluation Rosearch Corp. 87/09/29. 2pp 45281:180-45281:181.
- --8804260247 Change Notice 001 to Rev 4 to Instruction QI-045, "Heinsp of Procedures for Structural Steel." ZILL,R.D., SCHAUF,J.M. Evaluation Research Corp. 87/09/29, 2pp. 45281:182-45281:184.
- -8804260250 Change Notice 001 to Rev 3 to Instruction QI-051, "Reinsp of Pipe Whip SCHAUF, J.M. Evaluation Research Corp. 87/09/29, 2pp 45281:185-ZILL R.D. 46281:186
- --8804250253 Change Notice 001 to Rev 2 to Instruction QI-053, "Reinsp of Category I Conduit Supports/I-S-COSP."

 ZILL,R.D., SCHAUF,J.M. Evaluation Research Corp. 87/09/14, 2pp. 45281:187-45281:188.
- --8804260254 Change Notice 002 to Rev 2 to Instruction QI-055, "Reinsp of Instrument Pipe/Tube Supports/I-S-INSP," ZILL,R.D., SCHAUF,J.M. Evaluation Research Corp. 87/09/29, 2pp. 45281:189-45281:1190.
- 8804210351 Final response to FOIA request for documents re plant. Forwards App D documents App C & D documents available in PDR. GRIMSLEY, D Unisland of Rules & Records (Post 870413). 88/04/18. CONNOR, L. Doc-Search Associates. 4pp. 45192:204-45192:209.
- --8804210355 Page from draft rept on plant SAFETEAM activity & Ofc of Investigations review. * NRC - No Detailed Affiliation Given. 88/04/18. 1p. 45192:208-45192:209.

E. NRC Safety Evaluation Report (SER), supple & correspondence

8604010162 Forwards SSER 14 to NUREG-0797 re operation of plant Suppt presents safety evaluation on matters re corrective action program associated w/design of large & small bore piping & pipe supports.Corrective action program acceptable.W/o enči. GRIMES,C.I. Oic of Special Projects. 88/03/09. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generaling Co.). 1p. 44949.021-44949.021.

F. Security, medical, emergency & fire protection plans

8804270189 Revised emergency plan implementing procedures.including Rev 4 to EPP-104, "Emergency Preparedness Drills & Exercise" & Rev 5 to EPP-206, "Activation of Emergency Operations Facility (EOF) & EOF Personnel Dutles," W/880419 Ir. COUNSIL,W.G., WOODLAND.B. TU Electric (formerly Texas Utilities Generating Co.). 88/04/19, 22pp. 45244:280-46244:301.

G. Adjudicatory correspondence

- 8804060044 Advises that Cygna Energy Svos.Ino documents,including N Williams 880217-19 deposition & exhibits,obtained & available for review in util Dallas.TX oft.W/Certificate of Svo.Related correspondence.

 NEWMAN_J.R. TU Electric (formerly Texas Utilities Generating Co.). NEWMAN_J.R. Newman & Holtzingar. #288 6993. 88/03/30. MOORE_J.E. Assistant General Counsel for Hearings. ELLIS_J. Citizens Association for Sound Energy. 5pp. 44966:101-44084-105. for Hearing 44966 105.
- 8804050085 NRC Staff response in support of applicant motion to consolidate proceedings.* Consolidation would result in efficient use of parties resources.Notices of appearance & withdrawal encl.W/Certiticate of Syo.
 MOORE,J.E. Assistant General Counsel for Hearings. #288 5973. 88/03/30. Atomic Safety and Licensing Board Panel. 16pp. 44986:077-44968:092.
- 8804080109 Forwards Exhibit 18 introduced to record by counsel for co-owners during Williams 880218 deposition & Pages 190-195 & 484-465 of transcript, representing entire contents of deposition re exhibit. W/Certificate of Svc. NEWMAN, J.R. Newman & Holtzinger. #288 5994, 88/03/30, BLOCH, P.B., JORDAN, W.H., MCCOLLOM, K.A., Atomic Safety and Licensing Board Panel. 35pp. 44986:106-44986:140.

GARDE B.P. Government Accountability Project. ELLIS J. Citizens Association for Sound Energy 4288 6010, 88703730. Atomic Safety and Licensing Board Panel 140p. 44983 040-44983 053.

8804050033 Forwards list of persons appearing at N Wilhams of CYGNA deposition clarifying that Errs in transcript not same as J Elis of CASE, per J Elis request W/Certificate of Siz Related correspondence NEWMAN, IR TU Electric (formerly Texas Utities Generating Co.) NEWMAN, I R Newman & Hertinger #288 5930 88/03/31. BLOCKER, JORDAN, W.H., MCCOLLOM, K.A. Atomic Safety and Licensing Board Panel. 6pp. 44988-166-44966-171.

8804050039 Advises that enclified of documents in SSER 14 identified as not available in PDR being made available in util document from in Dallas,TX.per J Moore 880310 its W.Cenficate of Svc.

NEWMAN J.R. TU Electric (formerly Toxas Utilities Generating Co.) NEWMAN J.R.

Newman 8 Hoftzinger #288 5991 68/03/31 BLOCH.P.B. MCCOLLOM.K.A.,

JOHN SON,E.B. Atomic Safety and Licersing Board Panel 9pp. 44966.180-44966.187.

8804050092 Hobbe of availability of documents underlying SSER 14.* Notice given that documents underlying NRC 5SER 14 for facility available for insp & copying in LPDR in Arthogton, TX & in PDR W/Certificate of Svc Related correspondence MOOREJE Assistant General Counsel for Hearings #288 5974, 88/03/31, 3pp. 44966 093 44966 095

8804110026 Memorandum & order.* Ut.I motion to consolidate OL & CP amend cases denied Served on 880407
BLOCH P.B., MCCOLLOM,K.A., JORDAN,W.H. Atomic Safety and Licensing Board Panel. #288 6002. 88/04/05. TU Electric (formerly Texas, Utilities Generating Co.). 3pp. 45049 254-45049 256

8804110017 Forwards applicant seventh submission in response to Board 870912 request for response to notices of violation & deviations Responses cover period of 880225 to 880329 Certificate of Svc encil Related correspondence EDGAR,GL. TU Electric (formetry Texas Utilises Generating Co). EDGAR,GL. Newman & Holtzinger #288 6035 88/04/06 BLOCH,PB, JORDAN,WH, MCCOLLOM,KA Atomic Safety and Licensing Board Panel 4pp. 45048-348-45049.018

8804110023 Forwards recently issued INPO rept dealing w/operational aspects of facility 8 util responses re activities Mails to be submitted as evidence but are for Board info Certificate of Syc encl

no Certificate of overeing the State of the Color of the

8804180019 Forwards util 860406 iti transmitting errata to project status repts for "Equipment Qualification" & "Electrical" Related correspondence. WOOLDRIDGE RA. TU Electric (formerly Texas Utilities Generating Co.). WOOLDRIDGE RA. Worsham, Forsythe, Sampels & Woolndag (formerly Worsham, Forsythe & Sampels) #288 6061 88/04/06. BLOCH/PB. JORDAN,W.H., MCCOLLOM KA. Atomic Safety and Licensing Board Panel 2pp 45128-027-45128-029.

8804180030 Informs that applicants notified Board & parties of availability in TU Efectric document room of matis ref in NRC SSER 14 W/Certificate of svc. EOGAR,G.L. Newman & Holtzinger #288 6060 88/04/08. BLOCH,P.B., JORDAN,W.H., MCCOLLOM,K.A. Atomic Safety and Licensing Board Panel 6pp. 45128 042-45128 047

8804200038 Confirms 880411 telcon requesting 10-day extension of time to 880428 for CASE to spc.cify issues of interest re-project status repts dealing w/large & small bore pping & pipe supports & MRC Staff SSER 14 Related correspondence SCHMUTZ,TA, Newman & Hottzinger, #288 6075, 88/04/12, ELLIS,J. Citizens Association for Sound Energy. 1p. 45160 173.45160 173.

880420023 Mobon for reconsideration of Licensing Board memorandum & order of 880405 & request for oral argument.* Requests that Board schedule oral argument on ssues raised by applicant instant motion Certificate of size enci. NEWMAN.J.R. TIJ Electric (formerly Texas Utilities Generating Co.). NEWMAN.J.R. Newman & Holtzinger #288 8072. 88/04/15 Alomic Safety and Licensing Board Panel 11pp 45162-146-45162.156

8804200031 NRC Staff motion for reconsideration or clanfication of order of 880405. Licensing Board order has four consequences which are inconsistent w/longstanding Commission practice & procedures Certificate of 5xc encil MOORE.J.E. Assistant General Counsel for Hearings. #288 6073. 88/04/15. Atomic Safety and Licensing Board Panel 9pp. 45162.105-45162.113.

8804260073 Forwards initial complaint of J Goese & amended complaint of R Radelich in order to keep Board informed of potentially significant into re-proceedings Questions raised re-how applicant regists program being implemented. ELLIS_I Citizens Association for Sound Energy #288 6104.8870417.5 BLOCH_PB_, MCCQLLOM.K., JORDAN,WH Atomic Safety and Licensing Board Panel. 17pp 45216-320.45211-320 45210 330-45211 024

8804260055 Memorandum to parties.* Forwards BP Cotter 880311 memo to parties re docket files. Parties to proceeding requested to conform to BP Cotter request Cotter may be deleted from svc list Served on 880421 BLOCH-PB Atomic Safety and Licensing Board Panel. #288 6103 88/04/20, 2pp. 45211028-45211029.

6604260065 Forwards util 880414 ftr in response to questions arising from 871209 604200000 POWARLES ON COUNTY TO A STATE OF THE STATE OF T

8804260140 Answers to ASLB 14 questions (memo.proposed memo of 860414) re Action Plan Results Report Id 1." Action Plan Results Report Id 1." Action Plan Results Report Id 1. "OC Inspector Custifications" end Wilderthicate of Svc. YOUNG, J.E., CHRISTENSEN, J. TU Electric (formetly Texas Utilities Generating Co.), #288 6114, 88704721, 62pp. 45208 318-45210 019.

EDGARGL. TU Electric (formerly Texas Unities Generating Co.) EDGARGL Newman & Hoftzinger #288 6116, 88/04/21, 5pp. 45210.061-45210.065

8804260286 Notice of availability of collective significance rept & working liles " Working liles for collective significance rept available at stated address Certificate of Sic erg. Related correspondence.

EDGAR,G.L. TU Electric (formetly Texas Utilities Generaling Co.). EDGAR,G.L. Noteman & Holtzinger. #288 6117. 88/04/22. 5pp. 45210.056-45210.060

8804290129 Forwards applicants answers to Board 14 questions re-Action Plan Rescris Rept Vtl a.9. Checklists used for reinept documentation review for 81 items of esta-ment & mait not included w/answers due to vot amounting more than 1,000 pp EDGAR,G.L. Newman & Hottzinger. #288 6158. BB/04/26 BLOCHIPS MCCOLLOM,K.A., JORDAN,W.H. Atomic Safety and Licensing Board Panet 19 1505-164-64555161 45255:145-45255:161.

--8804290146 Answers to Board 14 questions re Action Plan Results Rept (Memo,proposed memo of 860416) regarding Action Plan Results Rept VII a 9 * Answers submitted per Board 860414 memorandum,proposed memorandum & orde: Wr CHRISTENSEN,J., HANSEL,J.L. TU Electric (formerly Toxas Utilities Generating Co) 88/04/26, 16pp. 45255.146.45265.161.

H. General correspondence

8804140002 Notifies of LM Polizzi 870612 lir to US Dept of Labor re alleged discrimination, reassignment to position away from site & eventual termination because of safety concerns raised on job. Violation of 10CFP50.7 may have occurred EBNETER, SD. Oic of Special Projects. 88/04/11. COUNSIL, W.G. TU Electric little metry Texas Utilities Generating Co.). 9pp. 45120.218-45120.228

P. Operating license stage documents & correspondence

8804220078 Requests that util submit responses to questions resulting from 88/016-18 meeting re-cable pulling operations & cable splices especially re-differences in installation & insp procedures & personnel training & qualification. GRIMES.C.I. Oic of Special Projects. 88/04/16. COUNSIL,W.G. TU Electric (former) Texas Utilities Generating Co.). 3pp. 45201:019-45201:021.

Q. Inspection reports, IE Bulletins & correspondence

8803080287 Forwards Insp Repts 50-445/88-05 & 50-446/88-04 on 880105- 0202 & notices of violation & deviation.

WARNICK,R.F. Ofc of Special Projects, 88/03/02, COUNSIL,W.G. TU Electric (for morely Texas Utilities Generating Co.), 6pp. 44634:004-44634:034.

-8803080292 Notice of violation from Insp on 880105-0202 Violation noted decression exceeding 1/32 inch in depth observed.

WARNICK,R.F. NRC - No Detailed Affiliation Given, 88/03/02, 2pp. 44634-013. 44634:011.

8803080301 Notice of deviation from insp on 880105-0202 Devation noted:Nonconformance Rept NCR-87-A00481 & QC hold point not trended as required by SAR to identify any trend edverse to quality.

WARNICK,R.F. NRC - No Detailed Affiliation Given. 88/03/02 1p. 44634 012-

~8803080311 insp Repts 50-445/88-05 & 50-446/88-04 on 880105-0202. One violation & deviation noted Major areas inspected: assessment of allegations, followup on vide-tions/deviations, & corrective action program for small bore piping. LIVERMORE,H.H. Ofc of Special Projects 88/03/02, 22pp. 44834:013-44634 034

8803080488 Forwards request for additinto re 860514 & 0714 responses to IE Bulletin 85:003, "Motor Operated Valve Common Mode Faltures During Plant Transient Due to Improper Switch Settings." Response requested by 860401. GRIMES.C.I. Oft of Special Projects 88/03/03. COUNSIL.W.G. TU Electric (torn.etly Texas Utilities Generating Co.), 5pp. 44639:032-44639:036.

8803300009 Forwards Insp Repts 50-445/88-11 & 50-446/88-09 on 880203 0301 No violations or devitations noted. WARNICK.R.F. Ofc of Special Projects. 88/03/22. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.), 4pp. 44921:298-44921:317.

-8803300014 Insp Repts 50-446/88-11 & 60-446/88-09 on 880203-0301. No violations or deviations identified Major areas Inspected; applicant actions on provious institutional followup on violations/deviations & corrective action program. LIVERMORE, H.H. Ofc of Special Projects. 88/03/22, 18pp. 44921:302-44921:317

8804050260 Ack receipt of 880115,0216,0315 & 0318 lits informing NRC of steps taken to correct violations noted in Insp Repts 50.445/87-30 & 50-446/87-22. WARNICK.R.F., Oto of Special Projects. 88/03/25, COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.), 5pp. 44997:172-44997:176.

8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing house Reactors." Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/09/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.

8803220296 NRC Into Notice 88-010, "Matts Licensees:Lack of MgI Controls Over U-censed Programs." Svo list enct. CUNNINGHAM, R. Division of Industrial & Medical Nuclear Safety (Post 870729) 88/ 03/28. Consolidated Edison Co. of New York, Inc. 102pp. 44995:247-44995:353.

8804060063 Ack (eceipt of 880024 ftr Informing NRC of steps taken to correct violations noted in Insp Repts 50-445/88-01 & 50-446/88-01. WARNICK, R.F., Old of Special Projects, 88/03/30, COUNSIL, W.G., TU Electric (for merly Texas Utilifities Generating Co.), 4pp. 45007:278-45007:279.



- 8804060375 Upriated response to violations noted in Inso Repts 50:445/85-13 & 50-446/85-09 Corrective actions Rev 7 to Procedure STA-606 issued on 880227 to meet ongraat corrective action response commitment COUNSIL.W.G. TU Electric (formerly Towas Utilities Generating Co.). 88/03/30 Document Control Branch (Document Control Desk). 1p. 45006-328-45006-328.
- 8804060398 Informs that completion of removal of unauthorized splices 8 wire nuls from Unit 1 chiffer panels rescheduled for completion by 880531.pdr util 880129 response to violations noted in Insp Repts 50-445/87-11 8 50-446/87-09 COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.) 88/03/30 Document Control Branch (Document Control Desk). 1p. 45010-225-45010-225
- 8804060494 Informs that date for completion of training of contractor personnel changed to 880601.per util 880201 response to violation noted in linsp Repts 50-445/87-27 & 50-446/87-20.

 COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.) 88/03/30. Document Control Branch (Document Control Desk). 1p. 45010 299-45010 299
- 8804060525 Revises date of full compliance for notice of violation noted in Insp Repts 50-445/88-02,50-446/86-02,50-445/86-02,50-445/86-22 & 50-446/86-20 Corrective actions will be completed no later than 88123 for Unit 1 & common NVAC.

 COUNSIL W.G. TU Electric (formerly Toxas Utifit as Generating Co.) 88/03/30. Document Control Branch (Document Control Dosk). 1p. 45008:355-45008-355.
- 8804060517 Responds to NRC 880302 ltr ro violations & deviations noted in Insp Repts 50 445/88-05 & 50-446/88-04 Corrective actions Nonconformance Rept 98-03838 issued to disposition welding degression.
 COUNSIL WG., WOODLAND R. TU Electric (formerly Texas Utilities Generating Co.) 88/03/31. Document Control Branch (Document Control Desk). 5pp. 45007:107-45007.111.
- 8804110325 Updates 880118 & 0314 responses to violations noted in Insp Repts 60-445/87-31 & 50-446/87-35 Corrective actions:all appropriate Ebasco walkdown personnel retrained on importance of documenting walkdown data completely. COUNSIL, W.G., WOODLAN, D.R. TU Electric (formot) Texas Utilities Generating Co.). 88/03/31. Document Control Branch (Document Control Dask) 8pp. 45077:313-45032-320 45077:320
- 8804010256 NRC Into Notice 88:011, "Potential Loss of Motor Control Ctr &/or Switchboard Function Due to Faulty Tie Boils" Svc list encl.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408-292-45407:051.
- 8804120431 Forwards Insp Repts 50-445/88-19 & 50-446/88-16 on 880302-0405.No violations or deviations noted
 WARNICK,R.F., Olic of Special Projects. 88/04/08. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generaling Co.). 4pp. 45130.248-45130:260.
- -8804120433 Insp. Repts 50-445/88-18 & 50-446/88-16 on 680302-0405 No violations or deviations noted Major greas inspected: applicant actions on previous Insp. Indrings action on 10CFR50.55(p) deficiencies & general plant arcins.

 WAGNER P.C., LIVERMORE,H.H. Ofc of Special Projects. 88/04/08. 9pp. 45130:252-45130.260
- 8904120435 Responds to 880205 NRC Bullotin 88-001 re defects in Westinghouse cir-cuit breakers in Class 1E applications to perform short-torm & long-term insplusing listed additions. Insps will commonce when replacement parts onsite. COUNSIL,W.G. TU Electric (formerly Toxas Utilities Generating Co.). 88/04/08. Docu-ment Control Branch (Document Control Desk). 3pp. 45091:018-45091:020.
- 8804130003 Forwards addl info re IE Bulletin 85-003, "Motor-Operated Valve Common Mode Failures During Plant Transients Due to Improper Switch Settlings," per NRC 880303 request COUNSIL,W.G. TU Electric (formarly Texas Utilities Generating Co.): 88/04/08. Document Control Branch (Document Control Desk). 6pp. 45099:316-45099:320.
- 8804130287 Responds to NRC 880208 ltr re-open items noted in Insp Repts 50-4467-67-37 & 50-446787-28 Results of engineering functional evaluation of items identified in CI Grimes 880208 & 97015 itrs scheduled for completion in May 1988.

 COUNSIL W.G. TU Electric (tomerty Texas Utilities Generating Co.) 88704711. Document Control Branch (Document Control Desk). 123pp. 46147:036-45147:158.
- 8804190003 Forwards Insp Repts 50-445/88-18 & 50-446/88-15 on 880302-0405.No violations noted WARNICK, R.F. Ofc of Special Projects. 88/04/11. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.). Spp. 45208:164-45208:181.
- -8804190007 Insp Repts 50-445/88-18 & 50-446/88-15 on 880302-0505 No violations or deviations noted Major areas inspected action on pravious insp findings followup on violations/deviations, processing info notices & assessment of allegations. HALECJ, LIVERMORE,H.H. Ofc of Special Projects 88/04/11, 13pp. 45208:169-45208:181.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Syc list enci. ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165.150.
- 8804280634 Forwards Insp Repts 60-445/88:29 & 60-446/88:26 on 880222- 0328.Response addressing technical open items re-inconsistency of design criteria w/FSAR or industry stds & need for addr.confirmation of designs & hardware requested.
 GRIMES,C.I. Off. of Special Projects. 86/04/14. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generaling Co.). 5pp. 45269.097-45269:187.
- --8804280640 Insp. Repts 50-445/88-20 & 50-446/88-25 on 880222-0329.Major areas inspected design validation packages in areas of mochanical & HVAC sys.civit/situatural electrical, instrumentation/controls & sys.interaction. NORKIN, D.P., LYONS, J.E. Of of Special Projects. 88/04/13. 66pp. 45269:102-45269:167.
- 8804200397 Forwards Insp Repts 50-445/88-21 & 50-446/88-18 on 880302-0405.No violations or deviations noted.
 WARNICK,R.F. Ofc of Special Projects. 88/04/16. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.). 3pp. 45231:086-45231:105.

- --8804200400 Insp Repts 50 445/88-21 & 50-446/88-18 on 880302-0405.No violations or deviations noted Weaknesses noted Major areas inspected actions on Comanche Peak response learn issue- specific action plans & general plant tours. RUNYAM, M.F., LIVERMORE, H.H. Old of Special Projects. 88/04/15 17pp. 45231:099-45231:105.
- 8804200472 Responds to NRC 880317 ftr re violations noted in Irisp Repts 50 445/88-12 & 50-446/88-10.Corrective actions Deficiency Rept C-88-00906 written to docu-ment failure to initiate FSAR change request. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.), 09/04/15. Docu-ment Control Branch (Document Control Desk), 3ρρ. 45235-069-45235-071

- 8904200476 Submits revised date of full compliance to violations noted in Insp Ricpts 50.445/87-39 & 50.445/87-22.Vendor drawing Sheet 3 discussed in 880216 lir will be made inactive no later than 880815,not 880415 as stated. COUNSIL,W-G TU Electric (formerly Texas Utilities Generating Co.) 88/04/15 Document Control Branch (Document Control Desk). 1p. 45235.072-45235.072.
- 8804200489 Advises that date of full compliance for violations noted in Insp Repts 50-445/88-22 & 50-446/86 20 revised from 880415 to 860715 Datay necessitated by fact that addl info needed from valve supplier only recently received COUNSIL,W.G. TU Electric (formerly Texas Utulias Generating Co.) 88/04/15 Docu-ment Control Branch (Document Control Desk), 1p. 45235:110-45235:110
- 8804260014 Forwards Insp Repts 50-445/88-22 & 50-446/88-19 on 880302-0405 No violations or deviations noted.

 WARNICK,R.F. Ofc of Special Projects. 88/04/20. COUNSIL.W.G. TU Electric (formerly Texas Utilities Generaling Co.). 4pp. 45248.095-45248-113.
- -8804260016 Insp Ropts 50-445/88-22 & 50-446/88-19 on 880302-0405 No violations noted. Weaknosses in training programs identatined. Major areas inspected NRC bullotin followep,monthly maint observation fuel receipt & storage & Reg Guide 1.97 OA. BITTER, S.D., BURRIS, S.P., WIEBE, J.S. Ofc of Special Projects. 88/04/20. 15pp 45248 (199-45248).

- 8804110113 Forwards Securities & Exchange Commission Form 10-K for 1987 & util 1997 ennual rept.W/o encis.

 COUNSIL,W.G. TU Electric (formorly Texas Utilities Generating Co.), 88/03/31. Document Control Branch (Document Control Desk). 1p. 45077:294-45077:294.
- 8804140525 Submits weekly schedule of TVA activities for wk of 880404- 11.Schedule will be updated & issued each Friday to reliect activities for forthcoming 2-wk period KELLY_J.L. Ofc. of Special Projects 88/03/31. ZECH.G.G. Ofc. of Special Projects 4pp. 45130/20545130:208.
- 8804130112 Forwards errata to equipment qualification & electrical project status repts previously submitted by 880108 6 0 1 15 ltrs.
 COUNSIL, W.G. TU Electric (formerly Foxes Utilities Generating Co.) 88/04/06. Document Control Branch (Document Control Desk). 7pp. 45122:231-45122:236.

S. Reportable occurrences, LERs & related correspondence

- 8603250320 Part 21 rept re worm gear component of Type H3BC valve actuators.initially reported on 880317.All safety-related worm gear components will be subjic documented Insp verifying absence of casing porosity. MCQUILLANP.G. Limitorque Corp. 88/03/18. Otc of inspection & Enforcement, Director (820201-870413). Spp. 44961:199-44961:204.
- 8804050340 Interim Deticiency Rept CP-87-122 re nozzte load stresses Initially reported on 880105.Evaluation continuing Next rept will be submitted by 880414.

 BECK_J.W., COUNSIL.W.G. TU Electric (formerly Texas Utilities Generating Co.). 867.
 03/28. Document Control Branch (Document Control Desk). 1p. 45034:035-46034:035
- 8904060081 Final supplemental Deficiency Rept CP-79-08 re space criteria for installa-tion of Hilti concrete drilled-in expansion anchors.initially reported on 801210.Correc-

tive actions still in progress.

COUNSIL,W.G., BECK,J.W. TU Electric (formerly Texas Utilities Generating Co.) 88/
03/29. Document Control Branch (Document Control Desk). 2pp. 45046:197-45046:198

- 8804060097 Interim Deliciency Rept CP-87-132 re unqua'illed Eimitorque actuatora.Initiality reported on 880105.Evaluation of completion schedule for ongoing corrective actions continuing.Next rept expocted by 880607.
 COUNSIL,W.G. TU Electric (formerly Texas Utilities Generating Co.). 88/03/29 Document Control Branch (Occument Control Desk), 1p. 45048:102-45048:102.
- 8804060105 Supplemental Daticiency Rept CP-87-03 re 6.9 kV switchgear Installation. Initially reported on 870316. Completion of replacement of jackshalts rescheduled for 880428 All other corrective actions for issue continuing on schedule. COUNSIL, W.G. 70 Electric (formerly Texas Utilifies Generating Co) 88/03/29. Document Control Branch (Document Control Desk). 1p. 45072.040-45072.040.
- 8804060186 Supplemental Deficiency Rept CP-82-07 rg defective governor drive cou-plings on diesel generators. Initially reported on 820908 Unit 2 couplings scheduled for completion by fuel load. COUNSIL,W.G., WOODLAN,D.R. TU Electric (formerly Texas Utilities Generating Co.). 88/03/30. Document Control Branch (Document Control Desk). 1p. 45028-358-
- 45028:359.
- 8804080327 Supplemental Deficiency Rept CP-84-08 ro curtain fire dampers.initially reported on 840720.Corrective actions will be completed by 881228 for Unit 1 & common areas & fuel load for Unit 2. COUNSIL, W.G., TU Electric (formerly Texas Utilities Generating Co.). 88/03/20. Document Control Branch (Document Control Desk), 1p. 45047:070-45047:070.
- 8804060378 Supplemental Deficiency Rept CP-83-15 re boiting matilised for cable tray clamps.Initially reported on 830712.Issue will be addressed & resolved in Deficiency Rept CP-83-35. Next rept expected by 880427. COUNSIL, W.G. TU Electric (formerly Texas Utilities Generating Co.). 88/03/30. Document Control Branch (Document Control Desk), 1p. 45047:098-46047:098.

- 8804060393 Supplemental Deliciency Rept CP-86-54 reidesign & installation of control room deling initially reported on 861003 Structural mods required as result of design basis consolidation program will be completed by 800001. COUNSE, W.G. TO Electric (formerly Texas Utilities Generating Co.) 88703/30. Document Control Branch (Document Control Desk.) 1p. 45047-097-45047-097.
- 8804060399 Final Daticiency Repli CP 87-116 re postulated facure of introgen purgo regulating valves in taily reported on 860113.Installation of pressure rehet devices will be completed by 866630 for Utu.1.18 Just load for Utu.1.2 COUNSIL, W.G. TU Electric (formerly Texas Uturiles Generaling Co.) 88/03/30. Document Control Branch (Document Control Desk). 1p. 45047.175.45047.175.
- 8604060405 Suppromental Deticiency Rept CP-85-54 re discrepancies in supprior provided HVAC support documents intelly reported on 860926 Constinework of HVAC supports will be compreted by 860331 for Unit 1.8 fuel load for Unit 2 COUNSIL,W.G. Tu Electric (formerly Texas Utifities Genorating Co.) 88/03/30. Document Control Branch (Document Control Desk). 1p. 45047-265-45047-265.
- 8804050026 Final Oel bency Rept CP-87-121 re 6.9 kV/480-volt transformer bus bat clostrance intelly reported on 880106. Profirmany analysis required to demonstrate qualification completed by Westinghouse URL to implement minor mod COUNSTLWIG. WOODLAND.R. TU Electric (formerly Toxas UII: ties Generating Co.). 68/03/31. Document. Control. Branch. (Document. Control. Dosk). 1p., 45017-251-45017-251.
- 8804050027 Final Deficiency Rept CP-86-45 re Seismic Category II sys & components Incha ly reported on 871016 Unit 1 corrective actions currontly scheduled for compretion by 881215 Unit 2 corrective actions will be completed prior to fuel load COUNSTLWIG. WOCDLANIOR TO Electric (formarly Texas Unities Conerating Co.) 88703/31 Document Control Branch (Document Control Dask). 1p. 45017-253-45017-253.
- 8804050034 Supplemental Deficiency Rept CP-87-23 is Class 15 coodult Installation runs coupled w/unicrs not lightlaned initially reported on 870727 Corrective action currently school sed not to be completed until 880831 due to the constraint COUNSIL W.G., WOODLAN,D.A. TU Electric (formerly Toxas Univities Generating Co.) 88703/31. Document Control Branch (Document Control Dask). 1p. 45017:252-45017.252
- 8804050038 Final Dolicioney Riopt CP-87-132 re-unqualified L'initorque actuators Initially reported on 880105 All Class 1E, Limitorque actuators will be overnined & corrected where necessary under Field Verification Method TE-FVM-EQ-047. COUNS'L, W.G., WOODLAN, D.R. TU Electric (formerly Texas Utilities Generating Co.), 88/09/31, Document Control Branch (Document Control Desk). 1p., 45028-250-45028-250.
- 8804080141 Interim Dehorancy Rept CP.88-10 re electrical peneiration assemblies initially reported on 860424 Items I.B.1 a, I.B.1 c, 8, I.B.4 a from App 8 of Enforcement Action 88-09 sith in progress. New composition date expected by 880701. COUNSIC, W.G. TD. Electric (formerly Towas Utilities Generating Co.). 88/04/04 Document Control Branch (Document Control Desk). 1p. 45092.193-45092.193
- 8804130207 Interim & final Deficiency Repts CP-85-36 re Train C conduct supports initially reported on 871105 Design validation process completed for Unit 1.Unit 2 corrective actions will be submitted upon completion of Unit 1. CCUNSIL W.G. 70 Electric (formorly Texas Utilities Generating Co.). 88704/08 (Document Control Brench (Document Control Desk.). 2pp. 45142 243-45142.244.
- 8804210188 Interim Deticiency Riopt CP-88-28 re cracks found in sinveral sections of tube steel utilized in site fabrication of pipe supports. Util continuing evaluation of mfg process at supplier facility Noxi rapt will be submitted by 880715. COUNSILIW G., MARSHALLUS, TU Electric (formerly Texas Utilities Generating Co.). 88764/13 Document Control Branch (Document Control Desk). 2pp. 45215;380-45215;351.
- 8804210205 Final Deficiency Ropt CP-88-27 re quality code downgrado of Westing-house 7300 sys printed circuit cards initially reported on 880314 Replacement of subjicated will be accomplished prior to 890301.

 COUNSIL W G., MARSHALL, JS. TU Electric (formorly Toxas Utilities Generating Co.). 88704713. Document Control Branch (Document Control Desk). 3pp. 45231:170-45231:172
- 8804210092 Final & Interim Deficiency Rept CP-87-122 re nozzle foad interfaces Initially reported on 971125 Overstress problems can be eliminated by modifying clips Clip mod & remaining corrective action to be completed by 880901. COUNSIL,W.G., WOODLAN,D.R. 1U Electric formarty Toxas Utilities Generating Co) 88/04/14, Document Control Branch (Document Control Desk). 2pp. 45228 288-45226 289.
- 8804210145 Final Deliclency Ropt CP-86-83 reluse of soparation barrier matt (SBM) on power cathes 8 power raceways Initially reported on 870605 SBM from power cathes/incoways removed per NCR CE-97-4577 8 Const Procedure CP CPM-10.3 revised COUNSIL,W.G. Tu Electric (formerly Texas Ullities Generating Co.), 88/04/15. Document Control Branch (Occument Control Desk). 1p. 45234:316-45234;316.
- 8804210161 Interim Rept CP-86-52 & Supplemental Rept CP-87-76 re splice connections & field drilled cable hotes in plants Initially reported on 870429 Corrective action completion dates being evaluated Next rept will be submitted by 880615. COUNSTLW.G. TU Electric (formerly Texas Ullifies Generating Co.). 88704715. Document Control Branch (Document Control Deak). 1p. 45216:177-45216.177.
- 8804210173 Supplemental Deficiency Rept CP-86-53 re seismic design of conduit hinkally reported on 861021. Corrective actions for Unit 1 rescheduled for completion by 880925. COUNSIL, W.G. TU Electric (formerly Texas Utilities Generating Co.) 88/04/15, Document Control Branch (Document Control Dask). 1p. 45221:205-45221:205.
- 8804210180 Supplemental Doliciency Rept CP-87-50 re abnormal thrust bearing temps on turbine driven auxiliary feadwater pumps. New schedule date for complotion is 880516 due to continuing delays in supply of mail 8 repair instructions. COUNSIL,W.G. TU Electric (formerly Texas Utilities Generaling Co.): 88/04/15. Document Control Branch (Document Control Desk). 1p. 45219:183-45219 163.
- 8804210239 Final Deliciency Rept CP-86-49 re adapter modules & electrical penetralions Initially reported on 861010.Unit 1 modules installed & coating engineering verification program modified.Unit 2 modules to be completed by unit fuel reload. COUNSIL.W.G. TU Electric (formerly Texas Utifiles Generating Co.), 86704/16. Document Control Branch (Occument Control Desk). 1p. 45231:173-45231:173.

- 8804210249 Final Deficiency Rept (Unit 1) & Interim Deficiency Rept (Unit 2) CP-86-55 re-moto: operators in several valves in main steam sys.Initally reported to 8800602 Unit 1 design mod to be completed by 880708.Next rept expected by 891231. COUNSIL, W.G. TU, E'ectric (formorly Texas Utilities Generaling Co.) 88/04/16. Deciment Control Branch (Document Control Desk). 1p. 45231 147-45231;147.
- 8804210257 Supplemental Deficiency Rept CP-86-51 re anchor bolts supplied by Hiti Tensile testing of 172 inch diameter bolts completed Design alloweblas will be revised accordingly & included in applicable design document. COUNSIL, W.G. 10 Electric (formally Texas Utilities Generating Co.). 88/04/15 Document Control Branch (Document Control Desk). 1p. 45231;174-45231.174.
- 8804250099 Supplemental Deficiency Rept CP-94-02 to detective push rods on desel generators initially reported on 840208 New Unit 1 push rods installed & Unit 2 replacement will be completed after out flushing & turnover of desel generators COUNSIU, W.G. TU Electric (formerly Texas Unities Generating Co.): 68704/18 Desement Control Branch (Document Control Desk). 1p. 45224:160-45224:160.
- 8804270001 Final Det.cency Rept CP-87-102 (e-cable tray separation critera in belty (eported on 870911 Further evaluation determined that issue not reportable,por 10CFR50 55(e). COUNSIL,W-G TU Electric (formerly Texas Ulritres Generating Co.). 88/04/22. Doorment Control Branch (Document Control Dosk). 2pp. 45268-288-45268 289.
- 8804270002 Final Deficiency Rept CP-88-29 to feedwater spit-flow bypass valves (FSBVs) Initially reported on 880323. Westinghouse requested to perform evaluation of FSBV. Controllive actions schedulad for completion by 881031. COUNSHL, W.G. TU Electric (formerly Texas Utrilles Generating Co.). 88/04/22, Doormant Control Branch (Document Control Desk). 2pp. 45268.290-45288:291.

T. Hearing transcripts on non-antitrust matters

- 8804110031 Forwards meeting notice & transcript of util & CASE 880225 & 26 meetings rollul corrective action program concerning piping & pipe supports,civit/etructural & mechanical.

 MALLOY,M. Otc of Special Projects. 88703729. WILSON,J.H. Otc of Special Projects 4pp. 45076 201-45077 253
- --9804110033 Transcript of 880225-26 public meetings w/CASE & J Doyle

 * TU Electric (formorly Texas Utilities Generating Co.) 88/02/25, 315pp. 45076 20745077-253

V. Operator Examinations

- 8804250088 Responds to FOIA request for into re-scores of reactor operators & scritor reactor operators Forwards requalification exam summary source sheets fisted in each app w/personal privacy into deleted.
 GRIMSLEY.D.H. Division of Rules & Records (Post 870413), 88/04/19, BOLEY,K Public Citizen's Critical Mass Energy Project. 2pp. 45213.003.45213.095.
- -8804250167 Package of NRC administered requalification exam results summary.
 NRC No Detailed Affiliation Given: 87/07/20, 88pp. 45213:007-45213:095.

DOCKET STN-50-454 BYRON STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8804140447 Rev 3 to Emergency Plan Implementing Procedure BZP 400-1, "Rote & Stalling of Technical Support Cir (Primary Responsibility Station Director)" & Rev 2 to BZP 400-2, "Role & Stating of Operational Support Cir."

 'Commonwealth Edison Co. 88/03/25, 12pp. 45123-086-45123-097.
- 8804250064 Revised emergency plan implementing procedures including Rev 5 to 82P 600-1, "Emergency Operations Facility Remote Alarm Response (Primary Responsibility-GSEP Coordinator)" & Rev 12 to 82P 600-A2 "Directors Phone Lists." Commonwealth Edison Co. 88703/30, 28pp. 45239 227-45239-253.
- 8804130138 Revised emergency plan implementing procedures including Flev 1 to 82P 100-711, "Operational Support Cir Director," Rev 0 to 82P 100-712, "Operatoral Support Cir Supervisor" & Rev 13 to 82P 600-41, "Prontized Call Listing..."
 **Commonwealth Edison Co. 88/03/31, 24pp. 45151:226-4515:250.
- 8804220035 Forwards Rev 23 to security plan Rov withheld (ref 10CFR73.21). BLISS,H.E. Commonwealth Edison Co. 88/04/18 Document Control Branch (Occument Control Desk). 1p. 45257:239-45257:239

J. Insurance & Indomnity information

8804120216 Forwards Endorsement 20 to NELIA Policy NF-294.Endorsement 15 to MAELU Policy MF-128,Endorsement 30 to NELIA Policy NF-277,Endorsement 22 to MAELU Policy MF-114 & Endorsement 194 to NELIA Policy NF-43.

OSTER,J. Commonwealth Edison Co. 88/04/06, DINITZ,I. Office of Nuclear Reactor Regulation, Director (Post 870411). 13pp. 45090.030-45090.042.

- 8804180277 Forwards notice of consideration of issuance of amends to Licenses NPF-37,NPF-86,NPF-72 & NPF-66 & opportunity for hearing on 880302 request to reduce containment lendon design stresses. MULLER,D.R. Project Directorate III-2, 88/03/18, BUTTERFIELD,L, Commonwealth Edison Co. 3pp. 45149 003-45149.011.
- --8804180283 Notice of consideration of issuance of amends to Licenses NPF-37,NPF-66,NPF-72 & NPF-75 & opportunity for hearing on 880302 request reliev to Tech Spoc 4.6.1.6.1.d to reduce containment tendon design stresses.

 MULLER,D.R. Project Directorate III-2. 88/03/18 6pp. 45149:008-45149.011.

- 8803240426 Generic Ltr 88 06 to all power reactor licensees & applicants re-removal of organization charis from Tech Spoc administrative control requirements Svc list encl MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972.153.
- 8804140541 Forwards Amends 15.15,6 & 6 to Licenses NPF-37,NPF-66,NPF-72 & NPF-75,respectively & safety evaluation. Amends change Tech Specs to add two radiation monitors for each station & edd requirement for sump offluent sampling prior to discharge SANDS,S.P., OLSHAN,L.N., Project Directorate III-2, 88/03/22, BUTTERFIELD,L. Commonwealth Edison Co. 3pp. 45130 068-45130 092
- **8804140543 Amends 15.15.6 & 6 to Licenses NPF-37,NPF-66,NPF-72 & NPF-75,respectively,changing Tech Specs to add two radiation monitors to each station & add requirement for sampling of sump elftrient prior to discharge into circulating water sys.

 **WULLER,D.R. Project Directorate III-2 88/03/22, 18pp. 45130.071-45130.088
- --8804140544 Safety evaluation supporting Amends 15,15,6 & 6 to Licensos NPF-37,NPF-66,NPF-72 & NPF-75,respectively. 'Office of Nuclear Reactor Regulation, Director (Post 870411) 88/03/22 3pp 45130 089-45130 092
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified enforcement policy concurring 10CFRS0-49, "Environ Qualification of Electrical Equipment Important to Safety for Nucloar Power Plants" Sec 18t encl MIRAGLIA, F.J. Associato Director for Projects (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45164-237-45164-285.
- 8804180361 Forwards Amend 16 to Licensos NPF-37 & NPF-66 & Amend 7 to Licenses NPF-72 & NPF-75 & safety evaluation Amends of minate setpoint verification in line actual rigidevice operational tost for reflays from Tech Specs SANDS, S.P., OLSHANL, N. Project Directorate III-2, 89/04/08, BUTTERFIELD,L. Commonwealth Edison Co. 3pp. 45150 232-45150 252
- --9804180387 Amond 16 Liconsos NPF-37 & NPF-66 & Amond 7 to Liconsos NPF-72 & NPF-75, changing Tech Specs to cirrinate solpoint vertication in trip actuating device operational test for relays.
 MULLER, D.R. Project Directorate III-2 88/04/08 18pp. 45150 235-45160 250.
- --8804180397 Safety evaluation supporting Amend 16 to Liconsos NPF-37 & NPF-66 & Amend 7 to Liconsos NPF-72 & NPF-75

 **Office of Nuclear Reactor Regulation, Oirector (Post 870411), 88/04/08, 2pp 45150 251-45150 252
- 8804220004 Forwards Amonds 17,17.8 & 8 to Licenses NPF-37,NPF-86,NPF-72 & NPF-75 respectively & satety evaluation Amends change Tech Specs to separate gaseous waste mgt sys oxygen analyzer into two major components. SANDS, S.P., OLSHAN, L.N. Project Orectorate III-2 88/04/15. BUTTERFIELD, L. Commonwealth Edison Co. 4pp. 45200 246-45200:269.
- --8804220007 Amends 17,17,8 & 8 to Licenses NPF-37,NPF-86,NPF-72 & NPF-75,respectively,consisting of changes to Tech Specs to separate gaseous waste mgt sys oxygen analyzer into two major components MULLER,D.R. Project Directorate III-2 88/04/15. 18pp. 45200:250-45200:267.
- --8804220010 Safety evaluation supporting Amends 17,17,8 & 8 to Licenses NPF-37,NPF-66,NPF-72 & NPF-75,respectively
 * Office of Nuclear Reactor Regulation, Director (Post 870411), 68/04/15 2pp 45200 268-45200 268
- 8604280039 Forwards Rev 50 to CE-1-A, "OA Program for Nuclear Generating Stations," Revs being made to reflect organizational changes.

 MORGAN,W.E. Commonwealth Edison Co. 88/04/18. Document Control Branch (Document Control Desk), 1p. 45261:273-45261:299
- --8804280069 Rev 50 to "OA Program for Nuclear Generaling Stations."

 * Commonwealth Edison Co. CE-1-A R50. 88/04/18 17pp. 45261:274-45261:299.

Q. Inspection reports, IE Bulletins & correspondence

- 8804070082 Responds to violation noted in Insp Repts 50-454/88-02 & 50-455/88-02. Corrective actions procedure implicitly directing covers to be reinstalled for environ qualification of Barton 752 instruments will be revised to include steps BUTTERFIELD,L. Commonwealth Edison Co. 88/03/24, DAVIS,A.B. Region 3, Otc of the Director. 3pp. 45030-354-45030:356.
- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Trinning in Westinghouse Reactors" Svc list encl. ROSSI, C.E. Division of Operational Events Assessment (Post 870411), 88/03/28, Consolidated Edison Co. of New York, Inc. 121pp. 44995;128-44995;246.
- 8803220298 NRC Info Notice 88-010, "Matts Licensees:Lack of Mgt Controls Over Licensed Programs" Svc I.st enct. CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.
- 8804040133 Forwards Sately Insp Repts 50:454/88:05 & 60:455/88:04 on 880113-0317,No violations or deviations noted. WRIGHT.G.C. Region 3, Otc of the Director. 88/03/28. REED,C. Commonwealth Edison Co. 2pp. 44970.263-44970 275.
- --8804040141 Safety Insp Repts 50-454/88:05 & 50-455/88:04 on 880113-0317:No violations or deviations noted Major areas inspected licensee actions on previous insp findings attartup test results evaluation & startup test results verification. DUNLOP, A., HASSE, R.A., RESCHESKE, P.R. Region 3, Ofc of the Director. 88/03/28. 2pp. 44970:265-44970.275.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switchboard Function Due to Faulty Tie Bolts." Svc list encl.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/04/07. Cansolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407:051.
- 8804140023 Corrects types in 880324 response to NRC Bulletin 88-002 re potential for steam generator tube rigiture event caused by propagalling fatigue crack.Enhanced teakage monitoring program required for Zion Units 1 & 2. MCRGAN,W.E. Commonwealth Edison Co. 88/04/08. DAVIS,A.B. Region 3, Ofc of

- 8804140056 Forwards response to NAC Bulletin 88-001 ro Westinghouse Series DS circuit breakers & sately concerns withreaker use. Schedule for short & tong-term Insps on all installed & spare 1E DS 416 & DS-206 breakers at Zion listed MORGANWE Commonwealth Edison Co. 88704/08 DAVIS,A.B. Region 3, Ofc. of the Director. 7pp. 45155-033-45155-039
- 8804150062 Forwards Salety Insp. Ropts 50:454/88-06 & 50:455/88-06 on 880212-0331 No violations noted FORNEY,W.L. Region 3, Otc. of the Oirector, 88/04/11, REED,C. Commonwoalth Edison Co. 2pp. 45155 095-45155 108
- --8804150076 Saloty Insp Repts 50:454/88-06 & 50:455/88-06 on 880212-0331.No viofations noted Major areas inspected ficensee action on previous insp fundings, LERs builletins, genoric five, operations summary, training & surveillance. HINDS,J.M. Reg on 3, Oic of the Director, 88/04/11, 12pp. 45155 097-45155.108
- 8804060370 NRC Info Notice 88-012, "Overgreesing of Efectric Motor Bearings." Svolist enct. ROSSI,C E. Division of Operational Evenis Assessment (Post 870411), 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45185.150.
- 8804250328 Confirms plans discussed on 880414 between H Bliss & G VanSickle ro upcoming 890506 meeting w/util to discuss response to IE Bulletin 85 003, GREENMAN,E G. Region 3, 010 of the Director. 88704718 REED,C Commonwealth Edison Co. 2pp. 45251120-45251121.

A. Periodic operating reports & related correspondence

- 8804260009 "1987 Annual Environ Operating Rept." W/880411 III & perial photographs.
 PLENEWICZ,R. Commonwealth Edison Co. 87/12/31. DAVIS,A.B. Region 3, Ofc. of the Director. 51pp. 45252.109.45252.162.
- S. Reportable occurrences, LERs & related correspondence
- 8804160224 Submits rept addressing one valid test & failure experienced on Diesel Generator 1B Corrective actions taken to increase reliability of diesel generators Major contributor to slow starts has been loss of fuel prime-Summary of all fest enci. PLENIEWICZ,R Commonwealth Edison Co. 88703/15 OAVIS,A.B. Reg on 3, Ofci of the Director, 18pp. 45131:342-45131,359.
- 8804080017 PNO:III.88 029 on 880402, shutdown begun to repair steam generator tube leak Leakage rate from RCS into secondary sys carculated to be 330 gallons per day Other maint & tosting work planned in addition to investigation & repair.

 HINDS.J., FORNEY,W. Region 3, Otc of the Director. 88/04/04 1p. 45092:199-45092.199.
- 8804130197 PNO-III-88-034 on 880406,up to 68 workers received minor exposures to airborno redioactivity,nnnc-pally I-131,during steam generator tubo prugging activities. Cause under investigation. Respirators required to enter containment GREGER, SHAFER, Region 3, Ofci of the Director. 88/04/07. 2pp. 45131.004-45131-005.

DOCKET STN-50-455 BYRON STATION, UNIT 2

- F. Security, medical, emergency & fire protection plans
- 8804140447 Rov 3 to Emergency Plan Implementing Procedure B2P 400-1, "Rolo & Staffing of Technical Support Cir (Primary Responsibility Station Director)" & Rov 2 to B2P 400-2, "Role & Staffing of Operational Support Cir."

 * Commonwealth Edison Co, 88/03/25, 12pp 45123 086-45123 097.
- 8804250064 Revised emorgency plan implementing procedures including Rov 5 to BZP 600-1, "Emergency Operations Facility Remote Alarm Response (Primary Responsibility-GSEP Coordinator)" & Rev 12 to BZP 600-A2 "Directors Phone Lists" Commonwealth Edison Co. 88/03/30, 28pp. 45239 227-45239 253.
- 8804130138 Revised emergency plan implementing procedures including Rev 1 to BZP 100-T11, "Operational Support Cir Director," Rev 0 to BZP 100-T12, "Operational Support Cir Supportsor" 8 Rev 13 to BZP 600-A1, "Prioritized Carl Listing..." *Commonwealth Edison Co. 88/03/31, 24pp. 45151:228-45151:250.
- 8804220035 Forwards Rev 23 to security plan Rev withheld (ref 10CFR73 21). BLISS,H.E. Commonwealth Edison Co. 88/04/18, Document Control Branch (Document Control Desk). 1p. 45257;239-45257.239

- 8804180277 Forwards notice of consideration of Issuance of amends to Licenses NPF-37,NPF-66,NPF-72 & NPF-68 & opportunity for hearing on 880302 request to reduce containment tenden design stresses. MULLER,D.R. Project Directorate III-2, 88/03/18, BUTTERFIELD,L. Commonwealth Edison Co. 3pp. 45149:003-45149 011.
- Edison Co. 3pp. 45149:003-45149 011.

 --8804180283 Nolice of consideration of issuance of amends to Licenses NPF-37,NPF-66,NPF-72 & NPF-75 & apportunity for hearing on 880302 request to revito Tech Spec 4,6.18,1 d to reduce containment lendon design stresses.

 MULLER, D.R. Project Directorate III-2, 88/03/18, 6pp. 45149,006-45149,011.
- 8803240426 Generic Ltr 88-06 to all power reactor liconsees & applicants re-removed of organization charts from Tech Spec administrative Control requirements Svc list end MIRAGLIA.F.J. Associate Director for Projects (Post 870411), 88/03/22, Consolidated Edison Co. of New York, Inc. 47pp. 44972; 107-44972; 153.
- 8804 14054 1 Forwards Amends 15,15,6 & 6 to Licenses NPF-37,NPF-66,NPF-72, & NPF-75,respectively & safety evaluation Amends change Tech Specs to edd two radiation monitors for each station & add requirement for sump effluent sampling prior to discharge. SANDS,S.P., OLSHAN,L.N. Project Directorate III.2. 88/03/22. BUTTERFIELD,L.

- 75, respectively, changing Tech Specs to add two radiation monitors to each station & add requirement for sampling of sump effluent paor to discharge into circulating water
- MULLER, D.R. Project Directorale III-2, 88/03/22, 18pp. 46130 071 45130 088
- --8804140544 Salety evaluation supporting Amends 15,15,6 & 6 to Licenses NPF-37,NPF-66,NPF-72 & NPF-75,respectively. Office of Nuclear Regulation, Director (Post 870411) 86/03/22 3pp.
- 8804080088 Genenc Ltr 68-07 to power reactor licensees & applicants re-modified en-lorcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants," Svc list encl. MIRAGLIA,F. J. Associate Duector for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 48pp. 45184:237-45164:285.
- 8804180361 Forwards Amond 16 to Licenses NPF-37 & NPF-66 & Amend 7 to Licenses NPF-72 & NPF-75 & safety evaluation Amends eliminate selpoint verification in trip actuating device operational test for relays from Tech Specs.

 SANDS,S.P., OLSHANI, N. Project Orectorate 181-2 88/04/08 BUTTERFIELD,L Commonwealth Edison Cq. 3pp 45150:232-45150:252.
- --8804180387 Amond 18 Licenses NPF-37 & NPF-66 & Amend 7 to Licenses NPF-72 & NPF-75,changing Tech Specs to eliminate setpoint varification in tip actuating device operational test for rolays.
 MULLER D.R. Project Directorate III-2 88/04/08. 16pp. 45150:235-45150:250
- -8804180397 Safety evaluation supporting Amend 16 to Licenses NPF-37 & NPF-66 & Amend 7 to Licenses NPF-72 & NPF-75.
 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/08, 2pp. 45150:251-45150.252.
- 8804220004 Forwards Amends 17,17,6 & 8 to Licenses NPF-37,NPF-66,NPF-72 & NPF-75,respectively & safety evaluation Amends change Tech Spocs to separate gaseous waste mgt sys oxygon analyzer into two major components. SANDS, S.P., OLSHANL, N. Project Directorato III-2, 88/04/15, BUTTERFIELD,L. Commonwealth Edison Co. 4pp., 45200 246, 45200 269.
- --8804220007 Amends 17,17.8 & 8 to Licenses NPF-37,NPF-68,NPF-72 & NPF-75,respectively,consisting of changes to Tech Specs to separate gaseous waste mgt sys oxygen analyzer into two major components.

 MULLER,D R. Project Directorate III-2: 88/04/15, 18pp. 45200 250-45200:267.
- -8804220010 Safety evaluation supporting Amends 17,17,8 & 8 to Licenses NPF-37,NPF-66,NPF-72 & NPF-75,respectively * Office of Nuclear Reactor Regulation, Orrector (Post 870411) 88/04/15 2pp
- 8804280039 Forwards Rev 50 to CE-1-A, "QA Program for Nuclear Generating Stations" Revs being made to reflect organizational changes. MCRGANUE. Commonwealth Edison Co., 88/04/18. Document Control Branch (Document Control Desk). 1p. 45261:273-45261:299.
- --8804280069 Rev 50 to "QA Program for Nuclear Generating Stations."
 ' Commonwealth Edison Co. CE-1-A R50, 88/04/18, 17pp, 45261:274-45261:299.

Q. Inspection reports, IE Builetina & correspondence

- 8804070082 Responds to violation noted in Insp. Repts 50-454/88-02 & 50-455/88-02.Corrective actions procedure implicitly directing covers to be reinstalted for environ qualification of Barton 752 instruments will be revised to include steps.

 BUTTERFIELD.L. Commonwealth Edison Co. 88/03/24. DAVIS.A.B. Region 3. Otc of the Director. 3pp. 45030:354-45030:356.
- 8803210090 Suppl 1 to NRC Info Notice 97-044, "Thimble Tube Thinning in Westinghouse Reactors" Svc list encl.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 88/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995.246.
- 8803220296 NRC Info Notice 88-010, "Matis Licensees:Lack of Mgt Controls Over Li-censed Programs," Svc list enct. CUNNINGHAM.R. E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995-247-44995-353.
- 8804040133 Forwards Safety Insp Repts 50-454/88-05 & 50-455/88-04 on 880113-0317.No violations of deviations noted WRIGHT.G.C. Region 3, Oto of the Director, 88/03/29, REED.C. Commonwealth Edison Co. 2pp. 44970 263-44970:275.
- --8804040141 Safety Insp Repts 50-454/88-05 & 50-455/88-04 on 880113-0317 No vio-lations or deviations noted Major areas inspected licenses actions on previous Insp Illindings, startup test results evaluation & startup test results verification DUNIOPA, HASSE, R.A., RESCHESKE,P.R. Region 3, Ofc of the Director. 88/03/28. 2pp. 44970:265-44970.275.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Dure to Faulty Tire Bolls," Svc list encl. ROSSI,C E. Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407:051.
- 6604140023 Corrects typos in 880324 response to NRC Bulletin 88-002 re-potential for steam generator tube rupture event caused by propagating latigue crack Enhanced leakage monitoring program required for Zion Units 1 & 2. MCDRAN,W.E. Commonwealth Edison. Co. 86/04/08. DAVIS,A.B. Region 3, Otc. of the Director. 6pp. 45163:341-45163:346.
- 8804140058 Forwards response to NRC Bullatin 88-001 re Westinghouse Scries DS cir-cuit breakers & safety concerns w/breaker use. Schedule for short & long-term insps on all installed & spare 1c.DS-416 & DS-206 breakers at Zion histed MORGAN,W.E. Commonwealth Edison Co. 88/04/08. DAVIS,A.B. Region 3, Otc. of the Director, 7pp. 45165:033-45165:039.
- 8804160062 Forwards Safety Insp Repts 50-454/88-06 & 50-455/88-06 on 880212-0331 No violations noted, FORNEY,W.1. Region 3, Ofc of the Director. 88/04/11. REED,C. Commonwealth Edison Co. 2pp. 45165.095-45165:108.

- ***Bud 130076 Salety Insp. 146915 30-44788-00 & 60-433781-00 on 860/212-0331 N3 lations noted Major areas inspected: licensee action on previous findings, LERs, bullatins, generic firs, operations summery, training & surveillance.

 HINDS, J. M. Region 3, Ofc of the Director. 88/04/11 12pp 45155:097-45155:108
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings" fist encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411) £87/64 Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150
- 8804250328 Confirms plans discussed on 680414 between H Bliss & G VanS.ck. upcoming 880508 meeting w/util to discuss response to IE Buttetin 85 003 GREENMAN,E G. Region 3, Offic of the Director. 88/04/18 REED,C. Commonwatelson Co. 2pp 45251:120-45251.121.

R. Periodic operating reports & related correspondence

8804260009 "1987 Annual Environ Operating Rept." W/880411 ltr & serial ph graphs
PLENIEWICZ,R. Commonwealth Edison Co. 87/12/31. DAVIS,A.B. Reg on 3, Of the Director, 51pp. 46252:108-45252.162,

DOCKET STN-50-456 BRAIDWOOD STATION, LINIT 1

F. Security, medical, emergency & fire protection plana

- 8804210343 Rov 1 to Emergency Plan Implementing Procedure Bw2P 300 8, "Post cident Release Rate Determination (Primary Responsibility Operations Director) "

 * Commonwealth Edison Co. 88/03/31, 8pp. 45194;261-45194;266.
- 8804200483 Revised controlled procedures Including Rev 4 to BwZP 380-3. F Chem Response to Personnel Injuries (Primary Hesponsibility-Red/Chem Director Rev 2 to BwZP 380-341, "App A.Patlent Radiation & Modical Status Rec
- 804120381 Advises that Allegation Rtitl-88-A-0013 to unmanned watches, considered closed per util 880310 ltr. Understands that permanently inside detection systoperable at time of incident No violation identified FORNEY, W.L. Region 3, Oic of the Director. 88/04/07, REED, C. Commonwolf Edison Co. 2pp. 45135:327-45135:333.

J. Insurance & indemnity information

8804120216 Forwards Endorsement 20 to NELIA Policy NF-294,Endorsement 1: MAELU Policy MF-128,Endorsement 30 to NELIA Policy MF-277,Endorsement 2: MAELU Policy MF-114 & Endorsement 194 to NELIA Policy NF-43 OSTERJ. Commonwealth Edison Co 88/04/06 DINITZ, Office of Nuclear Rea Regulation, Director (Post 870411). 13pp. 45090.030-45090.042.

- 8804180277 Forwards notice of consideration of issuance of amends to Licenses 5 37.NPF-66.NPF-72 & NPF-66 & opportunity for hearing on 880302 request to reconstructions. containment lendon design stresses.
 MULLER,O R. Project Directorate III-2, 88/03/18 BUTTERFIELD.L Commonwe
 Edison Co. 3pp. 45149:003-45149.011.
- -8804180283 Notice of consideration of issuance of amends to Licenses NPF-37,66,NPF-72 & NPF-75 & opportunity for hearing on 880302 request refer to 1 Spec 4.6.1.6.1.d to reduce containment tendon design stresses. MULLER,D.R. Project Directorate III-2. 88/03/18. 6pp. 45149.006-45149.011
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re remove organization charts from Tech Speo administrative control requirements Svc 1 st 6 MIRAGLIAF, J. Associate Director for Projects (Post 870411), 88/03/22. Consolid. Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8604140641 Forwards Amends 15,15,6 & 6 to Ucenses NPF:37,NPF-66,NPF-72 & 6 75,respectively & safety evaluation. Amends change Tech Specs to add two radia monitors for each station & add requirement for sump effluent sampling prior to charge.
 - charge.
 SANDS,S.P., OLSHAN,L.N. Project Directorate III-2. 88/03/22 BUTTERFIEL
 Commonwealth Edison Co. 3pp. 45130 088-45130 092.
- --8804140543 Amends 15,15,6 & 6 to Licenses NPF-37,NPF-66,NPF-72 & NP5,respectively,changing Tech Specs to add two radiation monitors to each stall of add requirement for sampling of sump elfluent prior to discharge into circulating ways. MULLER, D.R. Project Directorate III-2, 88/03/22, 18pp. 45130-071-45130.088
- --8804140544 Safety evaluation supporting Amends 15,15,6 & 6 to Licenses 1 37,NPF-66,NPF-72 & NPF-75,respectively.

 Office of Nuclear Reactor Regulation, Director (Post 870411) 88/03/22 45130.089-45130.092.
- 88040500D2 Confirmatory Action Ltr CAL-RIII-88-05 re identification of deliciencie existing lubricants in motor operated valves at plant. Lists activities to be completed review by util.

 DAVIS.A. 8. Region 3, Oto of the Director, 88/03/23, REED.C. Commonwealth For Co. 2pp. 45021:065-45021:066.
- 8803310262 Summarizes 880326 & 28 telcons w/NRO re ongoing util program to date adequacy of Limitorque operator lubrication. "Lubrication Contamination Evention" providing background to Issue & description of sampling & testing programs of DELGEORGE, L.D. Commonwealth Edison Co. 88/03/29, MURLEY, T.E. Office of clear Reactor Regulation, Director (Post 870411), 19pp. 45000;343-45000;361.



- 8804080088 Ganeric Ltr 88-07 to power reactor licensees & applicants re-modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Svc Ist encl. MIRAGLIA,F. J. Associate Director for Projects (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45164-237-45164-285.
- 8804180361 Forwards Amend 16 to Licenses NPF-37 & NPF-66 & Amend 7 to Licenses NPF-72 & NPF-75 & safety evaluation Amends eliminate subpoint ventication in trip actualing device operational test for relays from Tech Specs. SANDS,S.P., OLSHAN,L.N. Project Directorato III-2, 68/04/08. BUTTERFIELD,L. Commonwealth Edison Co. 3pp. 45150.232-45150:252.
- -8804180387 Amend 16 Licenses NPF-37 & NPF-68 & Amend 7 to Licenses NPF-72 & NPF-75,changing Tech Spacs to eliminate selpoint verification in trip actuating device operational test for relays. MULLERIO R Project Directorate III-2, 88/04/08, 16pp. 45150:235-45150:250.
- ~8804180397 Safety evaluation supporting Amend 16 to Licenses NPF-37 & NPF-66 & Amend 7 to Licenses NPF-72 & NPF-75.

 * Office of Nuclear Reactor Regulation, Director (Post 870411). 88/04/08. 2pp 45150 251-45150 252.
- 8804150084 Forwards amonds & supplemental info to LO DolGeorge 880329 fir to TE Murley re Limitorque operator lubrication. Understands that NRR has load responsibility for review of matter.

 DELGEORGE, LO, Commonwealth Edison Co. 88/04/11, MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 50pp. 45155:114-45155:163.
- 8804220004 Forwards Amends 17.17.8 & B to Licenses NPF-37, NPF-66, NPF-72 & NPF-76, respectively & safety evaluation Amends change Tech Specs to separate gaseous waste mgt sys oxygen analyzer into two major components. SANDS, S.P., OLSHANL, N. Project Directorate III-2 88/04/15. BUTTERFIELD, L. Commonwealth Edison Co. 4pp. 45200.246-45200.269.
- -8804220007 Amends 17,17.8 & 8 to Licenses NPF-37,NPF-66,NPF-72 & NPF-75,respectively,consisting of changes to Tech Specs to separate gaseous waste mgt sys oxygen analyzer into two major components. MULLER,D.R. Project Directorate III-2, 88/04/15, 18pp. 45200:250-45200.267.
- --8604220010 Safety evaluation supporting Amends 17,17,6 & 8 to Licenses NPF-37,NPF-66,NPF-72 & NPF-75,respectively. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/15, 2pp 45290-288-45200-269.
- 8804280039 Forwards Rev 50 to CE-1-A, "QA Program for Nuclear Generating Stations," Revs being made to reflect organizational changes.

 MORGAN,W.E. Commonwealth Edison Co. 88/04/18. Document Control Branch (Document Control Desk), 1p. 45261:273-45261:289
- 8804280069 Rev 50 to "OA Program for Nuclear Generating Stations."
 Commonwealth Edison Co. CE-1-A R50, 88/04/18, 17pp. 45281:274-45261:299.

Q. Inspection reports, IE Bulletins & correspondence

- 8803300105 Forwards Safety Insp Ropts 50-456/87-38 & 50-457/87-36 on 871005-880226 & notices of violation & deviation.

 MILLER,H.J. Region 3, Ofc of the Director. 88/03/18. REED,C. Commonwealth Edison Co. 2pp. 44916-251-44916:281.
- -8803300109 Notice of violation from insp on 871005-1222.880119,0218 & 26.Violations noted failure to follow Electrical Lineup Operating Procedures BwOP OG-E1 & E2 & failure to assure QC Insps property executed.
 MILLER,H.J. Region 3, Ofc of the Director. 88/03/18. 3pp. 44916:253-44816:255.
- --8803300154 Notice of deviation from Insp on 871005-1222,880119,0218 & 26 Deviation notation 871006.hspector determined that hydrogen recombiner B discharge isofation valve 00G066 was left in closed position for 40 days.

 MILLERI,H.J. Region 3, Ofc of the Director, 88/03/18, 1p. 44916:256-44916:256.
- --8803300113 Insp Repts 50-456/87-38 & 50-457/87-36 on 871005-1222, 880119,0218 & 26.Violations & deviations noted Major areas inspected:ficensee action on previous insp indings & review of electrical & instrumentation components. FALEVITS.2, LANDSMAN.R., GARDNER,R.N. Region 3, Oto of the Director. 88/03/17, 25pp. 44916.267-44916:281.
- 8804040223 Forwards Safety Insp Repl 50-456/88-07 on 880301-17.Util will be notified by separate correspondence of NRC decision re enforcement action based on Insp Indings. NORELUS,C.E. Region 3, Ofe of the Director. 88/03/25, REED,C. Commonwealth Edison Co. 2pp. 46075:339-45075:356.
- ~8804040227 Insp Rept 50-456/88-07 on 880301-17. Apparent violation noted failure to have control room ventilation sys operable. Appropriate enforcement action will be determined Major areas inspected licensee actions following startup test. GILLC.F., GREGER, L.R. Region 3, Ofer of the Director. 88/03/25, 16pp. 45075:341-45075:356
- 8804050003 Confirms 880405 meeling w/util re presentation of SALP for plant,per 880323 telcon GREENMAN,E.G. Region 3, Oto of the Director, 88/03/25, REED,C. Commonwealth Edison Co. 2pp. 45021:067-45021.068.
- 8803210090 Suppl 1 to NRC Into Notice 67-044, "Thimble Tube Thinning in Westinghouse Reactors," Svo list encl.

 ROSSI,C.E. Division of Operational Events Assessment (Post 670411). 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 88-010, "Matte Licensees:Lack of Mgt Controls Over Licensed Programs." Svc list encl. CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 870728), 887 03728. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.
- 8804060083 Corrects confirmation of plans discussed on 880323 for 880405 meeting to present SALP rept.Ltr did 880325 incorrect.Meeting scheduled for 2:00 pm. GREENMAN,E.G. Rogion 3, Oto of the Oirector, 88/03/29, REED,C. Commonwealth Edison Co. 2pp. 45007:294-46007:295.

- 8804060165 Forwards Safety Insp. Repts 50-456/88-09 & 50-457/88-10 on 880303-07 No violations noted. HARRISON.J.J. Region 3, Ofc of the Director, 88/03/31. REED,C. Commonwealth Edison Co. 2pp. 45034:191-45034:198.
- --8804060166 Sately Insp Repte 50-456/88 08 & 50-457/88-10 on 880303 07. No violations or deviations noted Major areas inspected: allegation Rill 88-A-0009 NEISLERJ.H., GARDNER,R.N. Region 3, Ofc of the Director, 88/03/28, 6pp. 45034:193-45034:198.
- 8804080010 Forwards Enforcement Conference Rept 50-456/88-12 in Glen Ellyn,IL on 880328.Findings from Insp Rept 50-456/88-07,epparent violations & applicable NRC enforcement policy discussed PAPERIELLO,C.J. Region 3, Of
- --8804060013 Enforcement Conference Rept 50-456/88-12 on 880328 Major areas discussed licenses errors associated w/design change to electrical heaters in control room ventilation sys. GREGER,L.R. Region 3, Oic of the Director. 88/04/04. 6pp. 45092;208-45092;211.
- 8804010256 NRC Info Notice 88:011, "Potential Loss of Motor Control Ctr &/or Switchboard Function Due to Faulty Tio Bolts." Svc list encl. ROSSI, CE. Division of Operational Events. Assessment (Post 870411). 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406.292-45407:051.
- 8804140023 Corrects typos in 880324 response to NRC Bulletin 88:002 re potential for steam generator tube rupture event caused by propagating fatgue crack.Enhanced leakage monitoring program required for Zion Units 1 & 2. MORGAN.W.E. Commonwealth Edison Co. 68/04/08. DAVIS,A.B. Region 3, Ofc of the Director. 6pp. 45163:341-45163:346.
- 8804140056 Forwards response to NRC Bullotin 68-001 re Westinghouse Series DS circuit breakers & safety concerns w/breaker use. Schedule for short & long-term insps on all installed & spare 1E,DS-416 & DS-208 breakers at Zion listed.
 MORGAN,W.E. Commonwealth Ed.son Co. 88/04/08. DAVIS,A.B. Region 3, Ofc of the Director. 7pp. 45155.033-45165:039.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list encl. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150.
- 8804200421 Forwards Salety Insp Repts 50-456/68-11 & 50-457/88-13 on 880314-25 & notice of violation issuance of Severity Level IV violation considered appropriate enforcement action. GREENMAN,E.G. Region 3, Old of the Director, 88/04/14. REED,C. Commonwealth Edison Co. 2pp. 45224:096-45224:104.
- --8804200424 Notice of violation noted in Insp on 880314-25.Violations noted inoparable nonaccessible area exhaust filter planums w/subsequent feiture to place units in applicable operating modes as specified in Tech Spec 3 0 3.

 GREENMAN,E.G. Region 3, Offo of the Director. 88704/14. 1p. 45224:098-45224:098.
- --8804200429 Safety Insp Repts 50-456/88-13 & 50-457/88-11 on 880314-25. Violation noted Major areas inspected events surrounding Inoperability of nonaccessible area exhaust filter planums.
 HINDS_JM. Region 3, Dic of the Director, 88/04/14, 6pp. 45224-099-45224-104.
- 8804250328 Confirms plans discussed on 880414 between H Bliss & G VanSickle re upcoming 880508 meeting w/ui-t to discuss response to IE Bulletin 85-003 GREENMAN.E.G. Region 3, Otc of the Director. 88/04/18, REED,C. Commonwealth Edison Co. 2pp 45251:120-46251:121.

R. Periodic operating reports & related correspondence

8804190114 Monthly operating repts for Mer 1988.W/880408 llr.
PETERSON,M.W., QUERIO,R.E. Commonwealth Edison Co. 88/03/31, 14pp. 45209:217-45209:230.

S. Reportable occurrences, LERs & related correspondence

- 8804010243 PNO-III-88-026:on 880323,licensee began orderly shutdown of Un.1.1 due to identified deficiencies in intericant used in motor-operated Limitorque valves. Deficiencies apply to 253 safety-refated valves in both Units 1.8.2. HINDS.J., FORNEY,W. Region 3, Ofc of the Director. 88/03/24. 1p. 45028.041-45032-45.
- 8804140077 LER 87-031-02.on 870613,1016 & 1228,discovered that Train OA of control room ventilation sys shifted to emergency makeup mode of operation. Caused by noise spikes in monitor pressure switch. Noise suppressing electrocubes put in W/880408 ltr.

 ROUNTREE, R., QUERIO, R.E., Commonwealth Edison, Co. 88/03/30. 4pp. 45163 244-45182-247.
- 8804180374 Summary of Operating Reactors Events Meeting 88-13 on 880329 List of attendees, discussion of events & summary of reactor scrams encl. LANNING,W. Events Assessment Branch. 88/03/31. ROSSI,C.E. Division of Operational Events Assessment (Post 870411). 18pp. 45149:205-45149:222.
- 8804140071 LER 88-004-00:on 880311,annunclator indicated controt rod deviation.Caused by failure of detector/encoder card in digital rod position indicator data A cabinat.Detector/ encoder card replaced 8 sys declared operable W/880408 ltr.

 JAQUEZ,S., QUERIO,R.E. Commonwealth Edison Co. 88/04/04. 4pp. 45158/318-
- 45158:321.

 8804120208 Forwards rept on valid test failure experienced on Diesel Generator 10G01KB.per Tech Spec 6.9.2.
 HUNSADER.S.C. Commonwealth Edison Co. 88/04/06. DAVIS,A.B. Region 3, Ofc of

the Director, 29pp. 45090.001-45090.029.

8804190259 LER 88 006-00 on 880313;partial loss of auxiliary bldg nonaccessible filter plenum position indication occurred. Caused by administrative & mgl. deficiency.Event reviewed w/individuals involved & reviewed w/personnel W/880408 ltt.
REDMOND,L., OUERIO,R.E. Commonwealth Edison Co. 88/04/06 Spp. 45220:205-45200.205 45220 209

DOCKET STN-50-457 BRAIDWOOD STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

- 8604120092 Advises of completion of structural steel tireproofing in lower cable spread ing room on 880330 HUNSADER S.C. Commonwealth Edison Ca. 88/03/31. NURLEY, T.E. Office of Nu-clear Reactor Regulation, Director (Post 870411). 1p. 45135.293-45135.293
- 8804210343 Rev 1 to Emergency Plan Implementing Procedure 8 #7P 300.6, "Post-Accident Release Rate Determination (Primary Responsibility Operations Director)."

 * Commonwealth Edison Co. 88/03/31, 6pp. 45194 261-45194:266.
- 8804200483 Revised controlled procedures including Rev 4 to 8w2P 380-3, "Rad/ Chem Response to Personnel Injunes (Primary Responsibility-Rad/Chiem Director)" & Rev 2 to 8w2P 380-341, "App A Patient Radiation & Medical Status Record Log " GOERING R.J. Commonwealth Edison Co. 88/04/06, 10pp 45180-121-45180-130
- 804120381 Advises that Allegation Rittle8-A-0013 re unmanned fire watches, considered closed per util 880310 its Understands that permanently installed fire detection systoperable at time of incident No violation identified FORKET, W.L. Region 3, Ott. of the Orector, 88/04/07, REED.C Commonwealth Edison Co. 2pp. 45135-327-45135-333

P. Operating license stage documents & correspondence

- 8804180277 Forwards notice of consideration of issuance of amends to Licenses NPF-37.NFF-66.NPF-72 8 NPF-66 & opportunity for hearing on 880302 request to reduce containment tendon design stresses MULLER D. 9. Project Directorate iii-2 88/03/18. BUTTERFIELD, Commonwealth Edison Co. 3pp. 45149 003-45149 011.
- -8804180293 Notice of consideration of issuance of amends to Licenses NPF-37,NPF-68,NPF-72 & NPF-75 & opportunity for licensing on 880302 request relief to Toch Spec 4 6 is 6.1 d to reduce containment tendon design stressos MULLER, DR Project Directorate III 2, 88/03/18, 6pp. 45149.006-45149.011.
- 8803240426 Generic Ltr 88-06 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svo list encl. MIRAGLIA, F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153
- 8804140541 Forwards Amends 15.15.6 & 6 to Licenses NPF-37,NPF-66,NPF-72 & NPF-75,respectively & safety evaluation Amends change Tech Specs to add two radiation monitors for each station & add requirement for sump effluent sampling prior to discharge. 5/AVDS.S.P. Project Directorate III-2, 88/03/22, BUTTERFIELD,L. Commonwealth Edison Co. 3pp. 45130 068 45130 092.
- --8804140543 Amends 15,15,6 & 6 to Licenses NPF-37,NPF-66,NPF-72 & NPF-75,respectively,changing Tech Specs to add two radiation monitors to each station & add requirement for sampling of sumplefficient prior to discharge into circulating water. MULLER D.R. Project Directorate III-2, 88/03/22, 18pp. 45130 071-45130 088.
- -8804140544 Safety evaluation supporting Amends 15.15,6 & 6 to Licenses NPF-37,NPF-66,NPF-72 & NPF-37,espectively. Office of Nuclear Reactor Regulation, Director (Post 870411), 68/03/22, 3pp, 45130-089-45130-092.
- 8803310262 Summanzes 880325 & 28 telegons w/NRC re ongoing util program to validate adequacy of Limitorque operator lubrication "Lubrication Contamination Evaluation" providing background to issue & description of sampling & testing program end. DELGEORGELD. Commonwealth Edison Co. 88/03/28. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 19pp. 45000 343-45000:361.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-torcement policy concerning IOCFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list enct. MIRAGLIAF, J. Associate Director for Projects (Post 87041), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164-285.
- 8804120351 Forwards addit documentation supporting environ qualification of Bunker Ramo containment penetrations,per indication in author 880323 ftr to recipient Evaluation shows that Midland II LOCA test accurately represents unit pa-HUNSABER,S.C. Commonwealth Edison Co. 88/04/07. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 17pp. 45089:303-45089:319
- 8804200154 Requests schedular exemption from 10CFR50.48(i) requirements so NRC concerns w/serviron qualification of Bunker-Ramo penetration equipment do not delay issuance of full power license for unit Safety evaluation enct. HUNSADER.5 C. Commonwealth Edison Co. 88704707. MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 13pp. 45177:169-45177:181.
- 8804180361 Forwards Amend 16 to Ucenses NPF-37 & NPF-66 & Amend 7 to Licenses NPF-72 & NPF-75 & safety evaluation Amends eliminate selpoint verification in trip actualing device operational lest for relays from Tech Specs. SANDS.S.P. Project Directorate IB-2. 86/04/08. BUTTERFIELD,L. Commonwealth Edison Co. 3pp. 45150:232-45150.252.
- -8804180387 Amend 16 Licenses NPF-37 & NPF-58 & Amend 7 to Licenses NPF-72 & NPF-75,changing Tech Specs to eliminate selpoint verification in Irip actuating device operational test for relays. MULLER,D R Project Directorate III-2 88/04/08, 16pp. 45150 235-45160 250.
- -8804180397 Safety evaluation supporting Amend 16 to Licenses NPF-37 & NPF-66 & Amend 7 to Licenses NPF-72 & NPF-75 Office of Nuclear Reactor Regulation, Director (Post 870411). 88/04/08, 2pp. 45150.251-45150.252.

- 8804150084 Forwards amends & supplemental into 10 LO DelGeorge 880329 fit to TE Murley re Limitorque operator lubrication. Understands that NRR has lead responsible. the foreview of matter.

 OF LGEORGE, L.O. Commonwealth Edison Co. 89/04/11. MURLEY, T.E. Office of N., clear Reactor Regulation, Director (Post 870411). 50pp. 45155:114-45155:163
- 8804220004 Forwards Amends 17,17,8 & 8 to Licenses NPF-37,NPF-66,NPF-72 8 NPF-75,respectively & safety evaluation Amends change Tech Specs to separate gaseous waste mpl sys oxygen analyzer into two major components. SANDS,S.P. Project Directorate IB-2, 88/04/15, BUTTERFIELD,L. Commonweath Ed son Co. 4pp. 45200-246-45200-289.
- -880422007 Amends 17,17,8 & 8 to Licenses NPF-37,NPF-68,NPF-72 & N-75, respectively,consisting of changes to Tech Specs to soparate gaseous waste mg sys oxygen analyzer into two major components.

 MULLER,D.R. Project Directorate III-2, 88/04/15, 18pp. 45200 250-45200 267.
- --8804220010 Safety evaluation supporting Amends 17,17,8 & 8 to Licenses NPF. 37,NPF-86,NPF-72 & NPF-75,respectively.

 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/16, 2pp. 45200 268-45200 269.
- 8804220005 Provides addl Info to facilitate NRC review of util 880407 request for schedular exemption from requirements of 10CFR50.49(j) re Bunker-Ramo electrical penetration assembles.
- tration assertiolies. LENTINE,F.G. Commonwealth Edison Co. 88/04/15. MURLEY,T.E. Olfice of Nuclear Reactor Regulation, Director (Post 870411). 21pp. 45220:106-45220:126.
- 8804280039 Forwards Rev 50 to CE-1-A, "OA Program for Nuclear Generating Stations," Revs being made to reflect organizational changes.

 MORGAN.WE. Commonwealth Edison, Co. 88/04/18. Document Control Branch (Document Control Desk), 1p. 45261:273-45261:299.
- 8804280069 Rev 50 to "QA Program for Nuclear Generating Stations."
 Commonwealth Edison Co. CE-1-A R50, 88/04/18. 17pp. 45261:274-45281.299

Q. Inspection reports, IE Bulletins & correspondence

- 8803300105 Forwards Safety Insp. Repts 50-456/97-38 & 50-457/87-36 on 871005-880228 & notices of violation & deviation.
 MILLER.H.J. Region 3. Ofto of the Director. 88/03/18. REED,C. Commonweath Edison Co. 2pp. 44916:251-44916:261.
- --8803300109 Notice of violation from Insp on 871005-1222,680119,0218 & 28 Violations noted failure to follow Electrical Lineup Operating Procedures BwOP OGE1 & E2 & tellives to assure OC Insps propekty executed.

 MILLER,H.J. Region 3, Oic of the Director. 88/03/18. 3pp. 44916.253-44916.255.
- --8803300154 Notice of deviation from insp on 871005-1222,880119,0218 & 26 Devaton noted on 871006 inspector determined that hydrogen recombiner 8 discharge isolation vatve 003066 was left in closed position for 40 days.

 MILLER,H.J. Region 3, Oto of the Director 88/03/18. 1p. 44916-256-44916.258
- --8803300113 Insp Repts 50-456/87-38 & 50-457/87-36 on 871005-1222, 880119.0216 8 28 Violations & deviations noted Major areas inspected licensee action on previous insp indiangs & review of electrical & instrumentation components. FALEVITS,Z., LANDSMAN,R., GARDNER,R.N. Region 3, Ofc of the Director. 88/03/ 17, 25pp. 44918 257-44916 281.
- 8804010250 Confirmatory Action Ltr CAL-Ritt-88-08 on 880323 telcon re identification of deficiencies in existing lubricants in motor-operated valves at plant.Understands util will take listed actions.

 DAVIS.A.B. Region 3, Oic of the Director. 88/03/23. REED,C. Commonwealth Edson Co. 2pp. 45020.011-45020.012.
- 8804050003 Confirms 880405 meeting w/util re presentation of SALP for plant.per B80/23 telcon.
 GREENMAN E.G. Region 3, Otc of the Director, 88/03/26, REED.C. Commonwel® the Edison Co. 2pp. 45021;087-45021;088.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors," Syd list and ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995;246.
- 8803220296 NRC Info Notice 88-010, "Matis Licensees:Lack of Mgt Controls Over to censed Programs." Svc lies enci.
 CUNNINGHAM.R.E Division of Industrial & Medical Nuclear Safety (Post 870729) 88/
 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353.
- 8804040213 Forwards Operational Readiness losp Rept 50-457/88-07 on 880216-0307 8 notice of violation. WRIGHT,G.C. Region 3, Ofc of the Director, 88/03/29. REED,C. Commonwealth Edison Co. 2pp. 45075;357-45076.021.
- --8804040215 Notice of violation from inap on 880216-0307 Violation noted on 880218, deviation rept not initiated after identifying departure from accepted equipment performance re-boric acid recirculation line. WRIGHT,G.C. Region 3, Oto of the Director. 88/03/29, 3pp. 45075.359.45076.001.
- -8804040216 Operational Readiness Insp Rept 50-457/88-07 on 880216-0307. Violations noted Major areas inspected operations, surveillance & testing maint redution controls chemistry controls, nuclear engineering activities & training. LANKSBURY.R.O., BROCHMAN.P.G., LITTLE, B.H. Region 3, Ofe of the Director, 88/03/29, 20pp. 45076:002-45076:021.
- 8804080083 Corrects confirmation of plans discussed on 880323 for 880405 meeting to present SALP repl.Ltr dtd 880325 incorrect.Meeting scheduled for 2:00 pm. GREENMAN,E.G. Region 3, Oto of the Director 88/03/29, REED,C. Commonwealth Edison Co. 2pp. 45007:294-45007:295.
- 8804080165 Forwards Safety Insp Repts 60-456/88.09 & 50-457/88.10 on 880303 D7.No violations noted. HARRISON,J.J. Region 3, Ofc of the Director 88/03/31, REED,C. Commonwealth Edison Co. 2pp. 45034:191-45034:198.



- -8804060168 Safety Insp Repts 50-456/88-09 & 50-457/88-10 on 880303-07. No violations or deviations noted Major areas inspected; allegation Rill 86 A-0009. NEISLERALH, GARDNER,R.N. Region 3, Oic of the Director. 86/03/28. 6pp. 45034.193.45034:198.
- 8804010256 NRC Into Notice 88-011, "Potential Loss of Motor Control Cir &/or Switch-board Function Due to Faulty Tie Botts." Svc list encl. ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408 292-45407.051.
- 8804140023 Corrects typos in 880324 response to NRC Bulletin 88-002 re-potential for steam generator tube rupture event caused by propagating fetigue crack Enhanced leakage monitoring program required for Zion Units 1-8-2. MORGANWE: Commonwealth Edison Co. 88/04/08. DAVIS,A.B. Region 3, Ofc of the Director. 6pp. 45163:341-45163:346.
- 8804140056 Forwards response to NRC Bulletin 88-001 ra Wustinghouse Series DS circuit breakers & safety concerns w/breaker use. Schedule for short & long-term insps on all installed & spare 15,05-416 & DS-206 breakers at Zion listod.

 MORGAN,W.E. Commonwealth Edison Co. 88/04/08. DAVIS,A 8. Region 3, Ofc of the Director 7pp. 45155/033-45165/039.
- 8804180316 Advises that based on review of addl Into provided during 860309 & 16 meeting 8 880328 If.NRC concludes that environ qualification (EQ) has still not been demonstrated for assemblies per insp. conducted on Feb & Mar 1988. MULLER,DR Project Directorate (II-2, 88/04/08, BUTTERFIELD,L. Commonwealth Edison Co. 2pp. 45165 357-45165:358.
- 8804060370 NRC Into Notice 88 012, "Overgreasing of Electric Motor Bearings." Svc ist end. HOSSI, C.E. Division of Operational Events Assessment (Post 870411). 86/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165.150.
- *8804200421 Forwards Safoty Insp Ropts 60-456/88-11 & 50-457/88-13 on 880314-25 & notice of violation Issuance of Seventy Level IV violation considered appropriate en-lorement action. GREENMAN.E.G. Rogion 3, Ofc of the Director. 88/04/14. REED.C. Commonwealth Edison Co. 2pp. 45224.096-45224:104.
- --8804200424 Notice of violation noted in insp on 880314-25. Violations noted inoperable nonaccessible area exhaust filter planums w/subsequent failure to place units in applicable operating modes as specified in Toch Spc 3.0.3.

 GREENMAN,E.G. Region 3, Ofc of the Director. 88/04/14. 1p. 45224:098-45224:098.
- -8804200429 Safety Insp Repts 50-456/88-13 & 50-457/88-11 on 880314-25. Violation noted Major areas inspected events surrounding inoporability of nonaccessible area exhaust filter plenums. HINDS,J.M. Region 3, Old of the Director, 88/04/14, 6pp. 45224:099-45224:104.
- 8804250296 Forwards Safety Insp. Rept. 60-457/88-12 on 860314-25 & notice of violation.insp conducted upon util discovery on 880313 that Unit 2 safety injection pump 8 manual discharge valve locked shut. GREENMAN, E.G. Region 3, Ofc of the Director, 88/04/16. REED,C. Commonwealth Edison Co. 2pp. 45254:129-45254:135.
- --8804250304 Notice of violation from insp on 880314-25. Violation noted: 2B safety Injection pump made inoperable by inadvertent shutting & locking manual discharge valve on 860305-13.

 GREENMAN,E.G. Region 3, Old of the Director, 88/04/15. 1p. 45254:131-45254:131.
- ~8604250305 Safety Insp Ropt 50:457/88-12 on 880314-25.Violation noted. Major areas insported event in which 2B safety injection pump found incapable of performing inheride function when pump manual discharge valve found locked shut. HINDS,J M. Region 3, Oic of the Director. 88/04/12, 4pp. 46254:132-45264:135.
- 8804250328 Confirms plans discussed on 880414 between H Bliss & G VanSickle re upcoming 880506 meeting w/util to discuss response to IE Bulletin 85-003. GREENMAN.E.G. Region 3, Oic of the Director. 88/04/16. REED,C. Commonwealth Edison Co. 2pp. 45251:120-45251:121.
- R. Periodic operating reports & related correspondence
- 8804190114 Monthly operating repts for Mar 1988 W/880406 Hr.
 PETERSON.M.W., QUERIO, R.E. Commonwealth Edison Co. 88/03/31. 14pp. PETERSON M.W. Q 45209:217-45209:230.
- S. Reportable occurrences, LERs & related correspondence
- 8803280134 LER 88-024-00 on 880220 inadequate capacitor connection results in de-graded instrument bus & reactor trip.Caused by preservice installation error by vendor.instrument bus restored to CVT inverter repaired.W/880321 ltr, HILLH, QUERIO,R.E. Commonwealth Edison Co. 88/03/17. 4pp. 44945:023-44945:026.
- 8804010243 PNO-III-88-026:on 880323.licensee began orderly shutdown of Unit 1 due to identified deficiencies in fubricant used in motor-operated Limitorque valves Deficiencies apply to 263 safety-related valves in both Units 1 & 2. HINDS.J., FORNEY,W. Region 3, Ofc of the Director. 88/03/24. 1p. 46028.041-45020/H.
- 8804180374 Summary of Operating Reactors Events Meeting 88-13 on 890329.List of attendees discussion of events & summary of reactor scrams encl. LANNINGW. Events Assessment Branch. 88/03/31. ROSSI.CE. Division of Operational Events Assessment (Post 870411). 18pp. 45149:205-45149:222.
- 8804190251 LER 88-001-00:on 880305, safety injection pump discharge valve locked closed. Caused by miscommunication between licensed operator & second nonlicensed operator roper guidance on use of log reviewed w/personnet.W/880408 ltr. ZAP/NSKI,S.M., QUERIO,R.E. Commonwealth Edison Co. 88/04/07, 4pp. 45215:197-4515.

DOCKET 50-458 RIVER BEND STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8804080189 Ack receipt of 880223 ftr in response to NRC insp on 880111- 15.Ma.nt tests enhance clased-circuit television sys. CALLAN,L.J. Region 4, Otc of the Director. 88703/31. DEDDENS.J.C. Gulf States Utilities Co. 2pp. 45044-258.45044-258.
- ~8804080194 Requests Region IV concurrence to deviate from physical security plan in order to perform certain tests. BOOKER, JE. Gulf States Utilities Co. 88/02/23, MARTIN,R.D. Region 4, Oic of the Director. 1p. 45044:258-45044:258
- 8804110089 Ack receipt of 880225 ftr informing NRC of steps taken to correct violations noted in Insp. Rept 50-458/87-23.Repty responsive to concerns re-security sys maint & vehicle access procedures raised in violation.

 CALLAN, LJ. Region 4, Otc of the Director. 88/03/31, DEDDENS,J.C., Guif States Utilities Co. 2pp. 45077-266-45077-267.
- 8804150277 Forwards response to NRC rept of regulatory effectiveness review conduct-ad by NRR on 880111-15 Response withheld (rel. 10CFR73.2.1). BOOKER,J.E. Gulf States Unifies Co. 8804/12. MURLEY,T.E. Office of Nuclear Re-actor Regulation, Director (Post 870411). 1p. 45192 231-45192 231.

J. Insurance & Indemnity information

- 8804140055 Forwards Endorsements 27 & 19 to NELIA & MAELU Policies NF-286 & MF-119,respectively.
 SAMUELS, J.L. Marsh & McLennan, Inc. 88/03/24. DINITZ, I. Office of Nuclear Reactor Regulation, Director (Post 870411). 3pp. 45163:350-45163:352.
- 8804040081 Forwards Into on util present levels of nuclear property coverage for BOOKER, J.E. Guil States Unities Co. 86/03/29. Document Control Branch (Document Control Desk). 1p. 44971:248-44971:250.
- -- 8804040087 Forwards schedule of nuclear property coverages maintained by utilifor lecity. SAMUELS,J.L. Marsh & McLennan, Inc. 88/03/09. WOOD,R NRC - No Detailed Affile ation Given. 2pp. 44971:249-44971:250.
- 8804120118 Forwards notification of util nuclear liability insurance coverage for facility. BOOKER, J.E. Guit States Utilities Co. 89/03/29. Document Control Brench (Document Control Desk). 1p. 45090-222-45090.223.
- 8804200277 Forwards Endorsement 26 to NELIA Policy NF-286 & Endorsement 18 to MAELU Policy MF-118.
 SAMUELS, J.L. Marsh & McLennan, Inc. 88/04/08. DINITZ,I. Office of Nucloar Reactor Regulation, Director (Post 870411). 5pp. 45174;131-45174.135.
- 8804200020 Forwards Endorsements 1 & 2 to MAELU Certificate MW-89 & Endorsements 1 & 2 to NELIA Cartificate NW-178. SAMUELS,J.L. Marsh & McLennan, Inc. 88/04/13. DINITZ,I. Office of Nuclear Reactor Regulation, Director (Post 870411). 21pp. 45226:147-45228:167.

- 8804060078 Notification of canceled 880329 meeting w/util in Rockvil's MD to discuss itemsee 870805 amend sequest to modify allowable average drywell area temp & main steam tunnel area temp monitoring. PAULSON,W.A. Project Directorate IV. 88/03/10. CALVO,J.A. Project Directorate IV. 3pp. 45018:209-45018:211.
- 8803240428 Generic Ltr 98-08 to all power reactor licensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc Lst encl. MIRAGLIA,F.J. Associate Director for Projects (Post 970411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972.107-44972.153.
- 8804070168 Forwards proposed changes to asiatic clam control program, for review & approval. Review by NRC resulted in discussions re sampling & visual insps of auxiliary bidg unit coolers. BOOKER, J.E. Gulf States Utilities Co. 88/03/30. Document Control Branch (Document Control Desk). 14pp. 45044:185-45044:198.
- 8804120098 Responds to 871123 request to provide revised schedule for restoration of const area & details for abandoning & seeling dewatering wells. Priority given to assuring that status of areas will not affect safe operation of facility. BOOKER, JE. Guif States Utilities Co. 88/03/30. Document Control Branch (Document Control Desk). 2pp. 45079.308-45079:309.
- 8804110330 Notification of 880414 meeting w/util in Rockville,MO to discuss util 870605 license amend request to modify allowable average drywell area temp & main steam tunnel area temp monitoring. PAULSON,W.A. Project Directorate IV. 48704/01. CALVO,J A. Project Directorate IV. 4pp. 45078:178-45078:179.
- 8804120030 Forwards Amend 19 to License NPF-47 & safety evaluation. Amend revises Tech Spec to Increase leak detection setpoints & allowable values for reactor water cleanup sys heat exchanger room temp & decreases RCIC sys isolation PAULSON,W.A. Project Directorate IV. 68/04/05. DEDDENS,J.C. Gulf States Utilities Co. 4pp. 45100:325-45100:338.
- --8804120037 Safety evaluation supporting Amend 18 to License NPF-47.

 * Office of Nuclear Reactor Regulation, Director (Post 870411). 88/04/05. 3pp. 45100:336-45100:338.

- 8804150012 Application for amend to Uconse NPF-47,changing Tech Specs to ravise setpoints and limits re recirculation loop operations to allow single loop operation. Fee paid DEDENS, J.C. Guif States Unities Co. 89/04/06 Document Control Branch (Document Control Desk). 21pp. 45152 263-45152,352.
- -8804150014 Proposed Tech Specs, changing setpoints and limits re-recirculation loop operations to allow single loop operation
 * Gulf States Utilities Co. 68/04/06, 32pp. 45152:284-45152.315
- ~8804150017 "Single-Loop Operation Analysis for River Bend Station, Unit 1." BRANDON,R J., ROBARE, D.J., CHARNLEY, JS General Electric Co. NEDO-31441, 87/05/31, 38pp. 45152 316-45152 352.
- 8804080088 Genoric Ltr 88-07 to power reactor Iconseos & applicants re-modified en-lorcement potcy concerning 10CFR59-49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants" Svc list and. MFAGLIA,F.J. Associate Director for Projects (Post 970411), 88704/07, Consolidated Edison Co. of New York, Inc. 49pp. 45184-237-45184-285
- 8804180326 Advises that 870724 update of implementation status of SPDS human engindering discrepancies acceptable.
 PAULSON,W.A. Project Directorate IV, 88/04/11 DEDDENS,J.C. Gulf States Utilities.
 Co. 4pp. 46149.197-45149.200
- 8804190215 Forwards Amend 20 to License NPF-20 & safety evaluation Amend revises surveillance requirements of Tech Spec Section 4.7.1.2 to reflect upgraded UHS water temp monitoring sys installed during first refueling ourage PAULSON,W.A. Project Directorate IV. 88/04/11. DEODENS.J.C. General Public Utilities Corp. - GPU Service Corp. 4pp. 45165 017-45165 027
- -- 8804190221 Amend 20 to License NPF-47, revising surveillance requirements of Tech Spec 4.7.1.2 to reflect upgraded UHS water temp monitoring sys installed during first reflucting outlage.
 CALVO,J.A. Project Directorate IV. 88/04/11, 5pp. 45165-021-45165.025.
- -8804190223 Safety evaluation supporting Amend 20 to License NPF-47.
 * Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/11, 2pp. 45165.025-45165.027.
- 8804290172 Forwards correction to Amend 19 to License NPF-47,correcting errors in Tech Specs 3/4 3-20,21 & 22. PAULSON,W.A. Project Directorate IV. 88/04/21. DEDDENS,J.C. Gulf States Utilities Co. 4pp. 45322:187-45322.194
- -8804290181 Correction to Amend 19 to License NPF-47,correcting errors in Tech Specs 3/4 3-20,21 & 22.
 * Project Directorate IV. 88/04/21, 4pp. 45322.191-45322.194

O. Inspection reports, IE Bulletins & correspondence

- 8804060084 FOIA request for all documents re Insp Rept 50-458/87-30 conducted dunng Dec 1997.
 PLETTINGER,H A. Affination Not Assigned 88/02/21, GRIMSLEY,D.H. NRC - No Delailed Affination Green. 1p. 45018 212-45018 212.
- 8803300413 Vols 1-5 to "River Bend Station Inservice Insp Plan Summary Rept Refuel Outage RF-1 First Period First Interval."
 SANKIN'CK,M.G., CROUSE,T.C., DIDDENS,J. Guil States Utilities Co. 88/03/22.
 1,475pp. 45001:032-45006 298.
- 8804050234 Forwards Insp Rapt 50-458/88-06 on 880222-26 No violations or deviations noted CALLANUL Region 4, Old of the Director, 88/03/25, DEDDENS,J.C. Gulf States Utilities Co. 2pp. 45017:225-45017:250.
- --8804050263 Insp. Rept. 50-458/88-06 on 880222-26 No violations or dewations noted Major areas inspected licensee chemistry/ red/ochemistry program & water chemistry addochemistry confirmatory measurements. MICROLAS.J.B., WISE.R., MURRIAY,8. Region 4, Otc of the Director, 88/03/21, 24pp. 45017-227-45017-250.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors." Svc list enci. ROSSICE: Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995-128-44995-246.
- 8803220296 NRC Info Notice 88-010, "Matis Licensees.Lack of Mgt Controls Over Licensed Programs "Svc list encl.
 CUNNINGHAM,R E Division of Industrial & Medical Nuclear Salety (Post 970729), 887
 03728. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353.
- 8804060090 Final response to FOIA request for documents re Insp Rept 50-458/87-30,Forwards App B documents Apps A & B documents available in PDR. GRIMSLEY,O.H. Division of Ru'es & Records (Post 870413). 88/03/29. PLETTINGER,H.A. Alfiliation Not Assigned. 3pp. 45018 213-45018:223.
- 8804060099 Hand written notes & news article on plant control room deficiencies.
 Alfihallon Not Assigned, 88/03/29, 6pp. 45018 216-45018,223
- 8804070168 Forwards proposed changes to asiatic clam control program, for review 8 approval Review by NRC resulted in discussions re sampling 8 visual (risps of auxiliary bidg unit coolers BOOKER, JE. Gulf States Utilifies Co. 88/03/30 Document Control Branch (Document Control Desk), 14pp. 45044:185-45044:198
- 8804080189 Ack receipt of 680223 ltr in response to NRC insp on 880111- 15 Maint losts enhance closed circuit felevision sys.

 CALLAN,L J. Region 4, Ofc of the Director, 88/03/31, DEDDENS,J.C. Gulf States Utilities Co. 2pp. 45044.256.45044:258.
- --8804080184 Requests Region IV concurrence to deviate from physical security plan in order to perform certain lests.

 BOOKER, J.E. Gulf States Utilities Co. 88/02/23. MARTIN,R.O. Region 4, Otc of the Director. 1p. 45044:258-45044:258.

- 8804110089 Ack receipt of 880225 lit informing NRC of steps taken to correctly alatons noted in Insp Rept 50-458/87-23 Repty responsive to concerns re-security sysmatric & vehicle access procedures raised in violation.

 CALLANIL J. Region 4, Otc of the Director 88/03/31. DEDDENS, J.C. Guit States littles Co. 2pp. 45077:286-45077:267.
- 8804060322 Forwards Insp. Rept 50-458/88-04 on 880125-0205 No violations of dayalions noted. CALLAN,L.J. Region 4, Oto of the Director. 88/04/01. DEDDENS,J.C. Gulf States Utilities Co. 2pp. 45072 061-45072 069
- --8804060323 Insp. Rept. 50-458/88-04 on 880125-0205.No violations or deviators noted Major areas inspected designs changes & mode. PICK G.A., GAGLIARDO, J.E. Region 4, Ofc. of the Director. 88/03/11 7pc 45072 063-45072 069
- 8804110304 Responds to violations noted in Insp. Rept 50.458/87-28 Corrective action: Administrative Procedure ADM-0003 revised to require initial sign off for actors performed & evaluation stop. BOOKER, J.E. Gulf States Ullitities Co. 88/04/04 Document Control Branch (Document Control Desk) 9pp. 45123.332-45123.330.
- 8804120068 Responds to NRC Bulletin 88-001, "Defects in Westingliause Circuit Break-ers." Util does not utilize any circuit breakers subj to bulletin in Class 1E svc at part. BOOKER, JE. Gulf States Utilities Co. 88/04/04. Document Control Branch (Docu-ment Control Desk). 2pp. 45135-282-45135-283.
- 8804120034 Ack receipt of 880304 ftr informing NRC of steps taken to correct violations noted in Insp Rapi 50-458/87-30.

 CALLAN,L.J. Region 4, Otc of the Director. 88/04/05. DEDDENS,J.C. Gulf States Utilities Co. 2pp. 45131.087-45131:088.
- 8804120040 Requests listed addl into re util 860514 & 1002 response to IE Builet 1 65 003, "Motor Operated Valve Common Mode Failures During Plant Transents Dee 5 Improper Switch Settings."

 CALLAN,L.J. Region 4, Otc of the Director. 88/04/05. DEDDENS,J.C. Gulf States Utilities Co. 3pp. 45147:332-45147:334.
- 8804120147 Forwards Insp Rept 50-458/88-03 on 880125-29 & 0208-12.No violations or deviations noted or the Director, 88/04/06, DEDDENS,J.C. Gulf States Utilities Co. 2pp. 45122:102-45122:121.
- -8804120162 Insp Rept 50-458/88-03 on 880125-29 & 0208-12 No violations or deviations noted Major areas inspected licensee corrective action program BOARDMAN,J.R. Region 4, Ofc of the Director, 88/03/14, 18pp. 45122 104-45122 121
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svc list enc! ROSSI, CE Division of Operational Events Assessment (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407.051
- 8804130402 Responds to NRC Itr re violations noted in Insp Rept 50-458788 01 Corrective actions:wiring associated w/standby gas treatment system & recirculation damper controls mod completed for Div 8 & scheduled for Div A. DEDDENS.J.C. Gulf Power Co. 88/04/08. Document Control Branch (Document Control Desk). 4pp. 45154;359-45154;362.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings" Svo ROSSICE: Division of Operational Events Assessment (Post 870411) 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150
- 8804220279 Forwards response to violations noted in Insp Rept 50-458/88-05 on 880208-12 Response withheld (10CFR73.21). BOOKER,J.E. Gulf States Utilities Co. 88/04/18. Document Control Branch (Document Control Desk). 1p. 45257:214-45257:214.
- 8804250123 Forwards legible copies of Attachments 1-6 of Insp Rept 50-459/88 66,per 880329 telcon.
 CALLAN,L J. Region 4, Ofc of the Director, 88/04/18, DEDDENS,J.C. Gull States Ushilles Co. 2pp. 45237:143-45237:160.
- -8804250130 Attachments 1,2,3,4,5 & 6 to Insp Rept 50-458/88-06.
 * Region 4, Old of the Director, 88/04/18, 16pp, 45237:145-45237:160.

R. Periodic operating reports & related correspondence

- 8804200133 Monthly operating rept for Mar 1988.W/880414 ftr COLE.R.E., BOOKER,J.E. Gulf States Utilities Co. 88/03/31, 5pp 45215.314-45215.318.
- S. Reportable occurrences, LERs & related correspondence
- 8804040212 LER 88 008 00:on 860227 automatic initiation of standby gas treatment sys & reactor bidg annulus mixing fan occurred. Caused by spunous signals from radiation monitor Mods requested to eliminate noise sources W/880328 it.

 ENGLAND, LA, BOOKER, J.E. Gulf States Utilities Co. 88/03/28. 4pp 45075-297-45075-2097. 45075:300.
- 8804050384 LER 88-009-00:on 880301,11,17 & 24 unsealed fire barrier penetrations discovered during Installation of security communications cable for plant mod. Corrective action program to be provided in supplemental rept by 660430.W/ 880331 liv ENGLAND,L.A., BOOKER,J.E., Gulf States Utilities Co. 88/03/31. 6pp. 45034 047-
- 8804200187 LER 87-004-01:on 870206.Div I diesel generator output breaker failed to close Caused by mounting boit failing out of closing spring charging motor. Missing bott identified & replaced & Mod Request 87-0141 Implemented W/880411 ftr. ENGLAND, L.A., BCOKER, J.E. Gulf States Utilides Co. 88/04-11. 4pp. 45235 177-45235:180

- 8804200197 LER 86.051-02 on 860810.RWCU isolation occurred during temp reading surveillance Caused by leaving bypass switch in normal position "Caution" plaque installed near "read-set" switches W/880411 ltr.
 ENGLANDL A. BOOKERJE Gulf States Utilities Co. 88/04/11. 4pp. 45221.048-45221 051
- 8804220137 Special rept on 880324,tomp in north end of main steam tunnel rose above Tech Spec 3/4 7.8 limit of 122 F for more than 8 h Caused by combination of full power opposetion 8 high outside temps Request to change Tech Specs submitted BOOKER.JE Gulf States Utilities Co. 88/04/15. Document Control Branch (Document Control Desk) 3pp. 45281:264-45281:266
- 8804220139 LER 87-008-02 on 870525, Train B of main control room charcoal filtration sys initiated Cavsed by spurious signals from main control room local intake radiation monitor RC notworks installed to suppress noise W/880415 ltr. ENGLANDLA, BOOKERJE Gulf States Utilities Co. 88/04/15 5pp 45220:127-45220 131
- 8804250036 LER 87-033-01:on 871211,loss of Div II reactor protection sys bus occurred due to trip of normal power supply electrical protection assembly breaker Caused by defective logic card.Card replaced.W/860415 ftr. ENGLAND.L.A., 800KER.J.E. Gulf States Utilities Co., 88/04/15, 6pp., 45237;174-45237 179

V. Operator Examinations

44633 247-44633 249

- 8804250058 Requests onclifel matts be provided for reactor 8 sonior reactor operator licens no exams scheduled for wk of 880711. Requirements for administration of written exams & for facility review of exams encl. CALLAN,L.J. Region 4, Ofc of the Director. 88704715. DEDDENS,J.C. Guif States Utilities Co. 11pp. 45252 098-45252:108.
- 8804250088 Responds to FOIA request for info re-scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in end app w/parsonal privacy into deleted.
 GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 88/04/19. BOLEY,K.
 Public Citizen's Critical Mass Energy Project. 2pp. 45213;003-45213.095.
- --8804250 (67 Package of NRC administered requalification exam results summary. NRC No Detailed Affiliation Given, 87/07/20, 88pp. 45213.007-45213.095.

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A. Application/construction stage documents & correspondence

- 8003080071 Requests review of fisted table re TAC work assignments & provision of expected schedule for completion.
 VISSING.G.S. Standardization & Non-Power Reactor Project Directorate, 88/03/03.
 MARCUS.B., LIPINSKI,R., TOMLINSON,E. NRC - No Detailed Affiliation Given. 3pp.
- 8803240426 Generic Ltr 88:06 to all power reactor licensees & applicants re-removal of organization charts from Tech Spec administrative control requirements Svc list and. MIRAGLIA,F.J Associate Director for Projects [Post 870411), 88/03/22 Consolidated Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804080088 Generic Lir 88-07 to power reactor licensees & applicants ro modified en-forcement policy concerning 10CFH50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45184:237-45184:285.
- 8804190254 Forwards SER & Suppl 1 to NUREG-1231 on B&W Owners Group plant assessment program contained in BAW-1919, Rev 5, "B&W Owners Group Safety & Performance Improvement Program (SPIP)," W/o encls. RUBENSTEIN, L.S. Standardization & Non-Power Reactor Project Directorate. BB/04/13. MAZUR, D.W. Washington Public Power Supply System. 4pp. 45165:231-45165-234.
- 8804280114 Discusses util 861001 ltr requesting approval of atternate requirement re-salety of equipment in main steam feedwater isolation areas Util proposal unaccept-able & mod of FSAR to reflect stated conclusions requested RUBENSTEIN,L S. Standardization & Non-Power Reactor Project Directorate. 88/04/ 21. MAZUR.D.W. Washington Public Power Supply System. 4pp. 45276;176-45276;178-45276:179.

G. Adjudicatory correspondence

8804110038 Submits 18th quarterly status rept re const activities at facility. During First Overter 1986, no significant eatety-related const activities performed. No changes enterpated, W/o encl. Related correspondence.

REYNOLOS, N.S. Washington Public Power Supply System. REYNOLOS, N.S. Bishop, Cook, Purcell & Reynolds. #288 603. 88/03/31. BLOCH, P.B., HARBOUR, J., BRIGHT, G.O. Atomic Safety and Licensing Board Panel. 1p. 45050:085-45050:085.

DOCKET 60-461 CLINTON POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plane

- 8804110119 Forwards Rev A to NRC Oraft Insp Procedure 82412, "Emergency Response Facilities Evaluation" to be used by Insp team evaluating emergency facilities an 880425-28.
 SHAFER, W.D. Region 3, Ofc of the Director, 88/04/05, GERSTNER, W.C. Illinois Power Co. 39pp. 45135:001-46135.039.
- 8804260206 Confirms plans for enforcement conference on 880421 in Glen Ellyn,IL to discuss security event reviewed during insp on 880405-08 re inadequate security compensatory megatures. GREENMAN,E.G. Region 3, Ofc of the Director. 88/04/18, GERSTNER,W.C. Illinois Power Co. 2pp. 45259:289-45259.280.

8804270284 Advises that 880303 Ray 7 to plant emergency plan consistent w/provisions of 10CFR50.54(q) 8 acceptable Ray withheld (ref. 10CFR2.790).
SHAFER,W.D. Region 3, Old of the Director 88/04/19. GERSTNER,W.C. Illinois Power Co. 2pp. 45244:228.45244:229.

J. Insurance & Indemnity Information

8804070062 Forwards Endorsement 35 to NELIA Policy NF-261 & Endorsement 16 to MAELU Policy MF-121. TURNER,C.L. Illinois Power Co. 88/03/29. DINITZ,I. Office of Nuclear Reactor Regu-lation, Orector (Post 870411). 3pp. 45098 144-45098.146.

P. Operating license stage documents & correspondence

- 8803240426 Generic Ltr 88.06 to all power reactor licensces & applicants relemoval of organization charts from Tech Spec administrative control requirements Svc list encl. MIRAGUIAF J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972.107-44972.153.
- 8804110253 Supplis 871030 & 880223 requests for amend to License NPF-62, revising lacility onsite organizational chart in Tech Specs. Attached marked-up tigue represents mode discussed in 880229 & 002 telcons. SPANGENBERG,F. Illinois Power Co. 88/03/30. Document Control Branch (Document Control Desk), 1p. 45077.347-45077.348.
- -8804110266 Proposed Tech Spec Figure 6.2.2-1, "Unit Onsite Organization." *Illinois Power Co. 88/03/30, 1p. 45077.348.45077.348.
- 8804110272 Forwards facility master activities plan (MAP) & MAP list of activities for Apr. June 1988. KNOP, R.C. Region 3, Ofc of the Director. 88/04/05 AXELSON, W.L. Region 3, Ofc of the Director. 4pp. 45129:320-45129:323
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-torcement policy concerning 10CFR\$0.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Planis." Svc list encl MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Conscillated Edison Co. of New York, Inc. 49pp. 45164.237.45164.285.
- 8804180464 Forwards errate to Amend 2 to License NPF-62 correcting type in Tech Spec Page 3/4 6-51.

 STEVENS,J.A. Project Directorate III-2, 88/04/11. SPANGENBERG,F. IIIno.s Power Co. 3pp. 45149:294-45149.297.
- --8804180465 Errata to Amend 2 to Licenso NPF-62, correcting typo in Tech Spec Page 3/4 6-51.
 * Project Directorate III-2, 88/04/11, 1p. 45149:297-45149:297.
- 8804220161 Forwards request for addl info re util response to Generic Ltr 83-28,llem 2.2 (Part. 1), "Equipment Classification Programs (Programs for All Other Safety-Related Components)." Response requested within 45 days.
 STEVENSJ. Project Directorate III-2, 88/04/18. SPANGENBERG,F. Illinois Power Co. 5pp. 45201:107-45201:111.
- 8804270178 Forwards addl into relating to questions on pneumatic & hydrostatic testing of containment isolation valves & prossure isolation valves into on stroke times of certain valves to be evaluated by NRC also enci.

 SPANGENBERGF, Illinois Power Co. 88/04/18 Document Control Branch (Document Control Dask), 18pp. 45241;204:45241;222.

Q. Inspection reports, IE Builetins & correspondence

- 8804010124 Forwards request for addlinfo supporting util 860515 & 0910 responses to IE Bulletin 85:003, "Motor-Operated Valve Common Mode Failures During Plant Translents Due to Improper Switch Sottings," Info required within 1 month of lit date. GREENMAN,E.G. Region 3, 01c of the Director, 88/03/25, GERSTNER,W.C. Blinos Power Co. 3pp. 45031;147-45031;149.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Waslinghouse Reactors." Svc Ist end.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/03/28
 Consolidated Edison Co. of New York, Inc. 121pp. 44995:126-44995:246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensons:Lack of Mgt Controls Over Liconsed Programs." Svo list enct. CUNNINGHAM,R.E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03/28. Consolidated Edison Co. of New York, Inc. 198pp. 44995 247-44995.353.
- 8804010282 Confirms plans discussed between F Spangenberg & Knop & Gardner for 880331 enforcement conference at Region III old to discuss findings identified during environ qualification insp. Notice of significant licenson meeting onci. GREENMAN, E.G. Region 3, Ofc of the Director, 88/03/29, GERSTRER,W.C. Illinois Power Co. 2pp. 44845:352-44945:353.
- 8804070074 Forwards two inservice insp program rolled requests to allow procurement of replacement parts from two vendors w/o ASME certification. SPANGENBERG.F. Illinois Power Co. 88/03/30 Document Control Branch (Document Control Desk). 5pp. 45044:132-45044:136.
- 8804060455 Forwards Safety Insp Rept 60-461/88-05 on 860224-26 No violations noted. SHAFER,W.D. Region 3, Old of the Director. 88/04/01 GERSTNER,W.C. Winds Power Co. 2pp. 45072-017-45072-029.
- -8804060462 Selety Insp. Repl. 50-461/68-05 on 880224-26 No violations or deviations noted. Major areas inspected solid radwaste program including organization & mgt controls qualifications & training solid radwaste & transportation activities. SLAWINSKI,W.J., GREGER,L.R., Region 3. Oto of the Director. 88/03/31. 11pp. 45072.019-45072.029.

MAFFRW() H6 Pawer Co 33pp 45135 001 45135 039

- 8804110271 Forwards summary of 871201-02 site visit rainsplot configuration & functional characteristics of seismic instrumentation. STEVENS.J.A. Project Directorate III-2, 88/04/05 SPANGENBERG.F. Illinois Power Co. 6pp. 45079.086-45079.091
- 8804130243 Advises that ubi 870904 response to NRC Bulletin 87-001 being used to determine extention data on observed pipe wall thinking. MULLERDIR Project Directorate III.2 88/04/06. SPANGENBERG,F. IT nois Power Co. 19, 45102-250, 45102-250.
- 8804010256 NRC into Notice 88-011, "Potential Loss of Motor Control Cir &/or Switch-board Function Due to Faulty Tie Boits" Svc list encl ROSSI,CE Division of Operational Events Assessment (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45408 292-45407 051.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list erci. ROSSI,CE. Division of Operational Events Assessment (Post 870411). 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028.45165:150
- 8804200405 Forwards Safety Insp Rept 50-461/88-02 on 880115-0406.No violations NR:GHT.G.C. Region 3, Ols of the Director, 88/04/14, GERSTNER,W.C. 11.nois Power Co. 2pp. 45238 253-45238 258
- --8804200408 Insp. Rept. 50-461/58-02 on 880115-0406 No violations or deviations noted Major areas inspected actions on previously identified item 8 review of startup test results
 BONGIOVANNIA, MAURA F.A., STASEK S. Region 3, Oic of the Director, 88/04/13 4pp 45238 255 45238 258
- 8804260206 Confirms plans for enforcement conference on 880421 in Glen Filyn, It. to discuss security event reviewed during insp on 880405.08 re inadequate security compensatory measures. GREENMAN E.G. Region 3, Ofc of the Director, 88/04/18 GERSTNER,W.C. Illino's Power Co. 2pp. 45259 289-45259 290.

R. Periodic operating reports & related correspondence

Co 1p. 45102 350 45102 350

- 8804190031 "Somiannual Radioactive Effluent Release Rept.Jul-Dec 1997." "Illinois Power Co. 87/12/31, 33pp. 45208 022-45208 053.
- 8804200198 Monthly operating rept for Mar 1988 W/860412 ltr. SPANGENBERG,F. Illinois Power Co. 68/03/31, 6pp. 45215 294-45215.299.

S. Reportable occurrences, LERs & related correspondence

- 8803280053 LER 88-005-00 on 880216.drjwell atmosphere particulate radioactivity monitor alarmed indicating high drywell atmosphere radioactivity level Caused by operator errors Event reviewed w/personnel involved W/880318 III.
 HILLYER,D.W., SPANGENBERG,F. himos Power Co. 88/03/18 Spp. 45092 001-
- 8804010271 LER 88-006-00 on 880229.Dv II containment exhaust process radiation monitor tripped to low-fail condition.Caused by personnel error due to Inadequate accessibility 8 visibility of detector Existing scattolding replaced W/880325 ftr. CAMILLERI,T.J., SPANGENBERG,F. Ill nois Power Co. 88/03/25 5pp. 44945.347-
- 8804150407 LER 88-008-00 on 880320,identified that MSiV leakage rates exceeded Tech Specs Imits Caused by component wear based on svc seen during power as-cension program & imital plant operation Two MSIVs reworked W/890408 fir. MORGENSTERN R. SPANGENBERG,F. Illinois Power Co. 88/04/08, 4pp 45183-112-45183-115.
- 8804200160 LER 88-007-00 on 880314, surveillance testing identified that ventilation fan for Dw II diesol generator lailed to trip during carbon dioxide Initiation Caused by failure to understand sys Dosign changes impl
- 8804210202 PNO-III-88-037 on 880412 approx 1,000 gallons of radioactive water drained from RHR sys piping into equipment room Spill occurred when RHR valves returned to normal positions after leak rate lesting Cleanup of rooms & equipment inf GREGERA, SHAFER,W. Region 3, Otc of the Director, 88/04/13, 1p. 45231:169-
- 8604260197 Special rept.on 880329,discovered failure of wind velocity & direction sensors on facility meteorological tower.Caused by inadvertent exposure of sensors to weather.Sensor assembly, including retaining device replaced SPANGENBERGF, Illnois Power Co. 88/04/15. DAVIS,A B. Region 3, Oic of the Director. 2pp. 45252:171-45252.172.

DOCKET STN-50-470 CESSAR SYSTEM 80

K. Utility Final Safety Analysis Report (FSAR) & amends

- 8804200529 Forwards draft revs to C-E Chapters 1,4,5 & 9 to C-E std SAR.Meeting to resolve issues re schedule & composition of submittals as part of draft licensing review bases & related issues, equiested SCHERER.A.E. Combustion Engineering, Inc. 88/04/11. MIRAGLIA.F.J. Associate Director for Projects (Post 870411). 18pp. 45180.131-45182:228.
- -- 8804200542 "CESSAR-DC Submittal Group 8 Revs to Chapters 1.4.5 & 9."

 'Combustion Engineering, Inc. 68/04/11, 750pp. 45180:149-45182:228.

- 8804080196 Forwards Insp. Ropt. 50-482/88-10 on 880216-19 & violation Notice of violation withhold (rof 10CFR73.21).

 CALLAN, L.J. Region 4, Otc of the Director. 88/03/28 WITHERS, B.D. Wolf clear Operating Corp. 3pp. 45044-259-45044:262.
- --9804980219 Partially withhold Insp. Rept. 50-482/B8-10 on 8802 10CFR/3 21) Violations noted Major areas inspected physical security pla menting procedures security organization, physical barriers & vital areas. KELLY_JR. EVERETT.R.J. Region 4. Oic of the Director. 88/03/21. 1p. 45044 262.
- 8804080431 Forwards supplemental response to violations noted in Insp Ris 87-34 Response withhold. BALLEY, J.A. Wo'l Creek Nuclear Operating Corp. 88/03/29. Document Cor (Document Control Desk). 1p. 45115-030-45115-030.
- 8804080077 Responds to NRC 880307 ftr re violations noted in Insp Rept BIADBODY Registration of the State of the St
- 8804120353 Confirms that procedure rave necessary to implement Amend aud Louss Commission in procedure rate necessary to implement Amend.

 ed & amend implemented Amend revised Tech Specs in order to remove protection requirements & place requirements in updated SAR & in plant, WITHERS.B.D. Wolf Creek Nuclear Operating Corp. 88/04/06 Docum. Branch (Document Control Dosk). 2pp. 45088:359-45088.360.
- 8804130042 Revised emergency plan implementing procedures including Re 01-1.1, "Wolf Creak Generation Station (WCGS) Diganization," Rev 2 to "Control Room Organization" & Rev 10 to EPP 01-1.1, W880407 III. WITHERS,8 D Wolf Creek Nuclear Operating Corp. 88/04/07, 300pp. 45137.011.

I. Financial Information

- 8804180420 Forwards "Kansas Gas & Eloctric Co. 1997 Annual Rept to Str. "Kansas City Power & Light Co. 1987 Annual Rept" & "Kans Cooperative, Inc. 1987 Audited Financial Into: WITHERS, B.D. Wolf Croek Nuclear Opporating Corp. 88/04/11. Document (Oocument Control Desk). 1p. 45153.249-45183:329.
- -8804180432 "Kansas Gas & Electric Co Annual Rept for 1987." CADMAN,W.K. Wolf Creak Nuclear Operating Corp. 87/12/31, 45pp 45153;294.
- --8804180439 "Kansas City Power & Light Co Annual Rept for 1987." DOYLE, A.J., JENNINGS, A.D. Kansas City Power & Light. 67/12/31, 35pp.

J. Insurance & Indemnity Information

- 8804080239 Submits present level of onsite property damage insurance maplent.per 10CFR50.64(w)(2). WITHERS.B.D. Wolf Creek Nuclear Operating Corp. 86/03/28. Docum Branch (Document Control Desk). 1p. 45064:230-45064:230.
- 8804200319 Forwards listed documents as proof of linancial prol 10CFR140.15 Util purchased master worker policy from MAELU Endorsement 1 to MAELU Certificate MW-88 8 Endorsement 10 Policy 118 also enci.
 WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 88/04/12. MURLEY, Nuclear Reactor Regulation, Director (Post 870411). 28pp. 45174:137-451

P. Operating license atage documents & correspondence

- 8804280203 FOIA request for into re death of T Archart at facility. LYKINS R.D. Bryan, Lykins, Heitmanek & Wulz. 88/01/25. GRIMSLEY.D Rules & Records (Poet 870413), 2pp. 45276:245-45276:246
- 8803240428 Generic Lir 68-06 to all power reactor licensess & appl.canls rorganization charts from Tech Spec administrative control requirements in MIRAGLIAF. J. Associate Director for Projects (Post 870411), 88/03/22.1
- 8804180364 FOIA request for documents re rept by NRC Ofc of investig leged mail false statements by unit mgt at facility.did 671110. WENSKEP, Kaness City Star/Kaness City Times, Kaness City, MC GRIMSLEY,D. Division of Rules & Records (Post 870413). 1p. 45160.97
- 8804060425 Application for amend to License NPF-42, revising Tech Special 3/4.6.1.2 addressing containment leakege & containment leakege with the part of the part
- 8804060430 Proposed Tech Specs 3/4.6.1.2 & 3/4 6.3 addressing conta age & containment isolation valves, respectively.
 *Wolf Creek Nuclear Operating Corp. 88/03/28, 3pp. 45072:113-45072.
- 8804280208 First partial response to FOIA request for documents re lac App B document App A & B documents also available in PDR. GRIMSLEY.D H. Division of Rules & Records (Post 870413), 88/03/30. Bryan, Lykins, Hejimanek & Wuiz. 3pp. 45276:247-45276:251.

- 8904110316 Summary of 880316 meeting w/ut is re-contemment tendon Tech Specs for facilities, Attendance list & ficensees prosentation encl DCK.G.F. Project Directorate IV. 88/04/01 Project Directorate IV. 33pp. 45078 297 45078 329
- 8804120353 Confirms that procedure ravs necessary to implement Amond 15 compreted & amend implemented Amend revised Toch Spacs in order to remove certain fre protection requirements & place requirements in updatert SAR & in plant procedures WITHERS 0 Wolf Crock Nuclear Operating Corp 88/04/06 Document Control Branch (Document Control Desk). 2pp. 45088-359-45088-360
- 8804080088 Goneric Ltr 88-07 to power reactor licensees & applicants re moditiod en-lorcament policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants" "Svc list enct M:PAGLIA,F J. Associate Director for Projects (Post 870411) 88/04/07. Consultated Edison Co. of New York, Inc. 49pp. 45164.237-45164.285
- 8904200298 Ack recept of 890311 OA program description Chapte: 17.2 of updated safety analysis rept. Rev. 1,dtd. 880311. Submittal satisfies requirements of 10CFR50,App B & acceptable.
 CALLAN,L. J. Region 4, Oic of the Director, 88/04/11, WITHERS,B.D. Wolf Croek Nuclear Operating Corp. 2pp. 45177.326-45177.327.
- 8804180369 Final response to FOIA request for documents Releasable portions of records identified on App A available in LPDRs in file folder FOIA-87-800 under name Hays & PDR Portions of App A documents withheld (ref FOIA Examptions 6 & 7) GRIMSLEY_DH Division of Roles & Records (Post 870413) 80704/13 WENSKE,P. Kansas City Star/Kansas City Times, Kansas City, MO. 3pp. 45150 071-45150 073
- 8804210331 Forwards response App C of technical evaluation rept for fat tity inservice testing program (IST) & supplemental into on rolled requests associated w/IST wiTHERS.B.D. Wolf Creek Nuclear Operating Corp 88/04/14.

Q. Inspection reports, IE Bulletins & correspondence

- 8803300124 Forwards Insp Rept 50-482/88-11 on 880222-26 & notice of violation CALLAN, L.J. Region 4, Otc of the Director, 88/03/23 WITHERS, B.D. Wolf Creek Nuclear Operating Corp. 2pp. 44921:244-44921:252.
- ~8803300126 Notice of violation from insp on 880222-26 Violation noted entries not made in pump & valve event log re elect range results obtained on 870331 & 0630 for containment spray Pump PENO1A.

 * Region 4: Oto of the Director: 88/03/23 | 1p | 44921:246-44921:246
- -6603300127 Insp. Rept. 50-482/88-11 on 880222-26 Violation noted Major areas inspected inservice testing of pumps & valves program & organization, procedure & records test witness & personnel qualification & training. STEWART, R.C., MCRELL, W.M., BARNES, J. Region 4, Oic of the Director. 88/03/15 6pp. 44921-247-44921-252.
- 8803210090 Suppl 1 to NRC Into Notice 87-044, "Thimble Tube Thinning in Westinghouse Reactors" Svc list enct.

 ROSSI,C.E. Division of Operational Events Assessment (Post 670411). 68/03/28.
 Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44985.246
- 8803220298 NRC Info Notice 88-010, "Matis Licensees Lack of Mgt Controls Over Li-censed Programs." Svc list encl. CUNNINGHAM, R E Division of Industrial & Mod.cal Nuclear Safety (Post 870729), 887 03/28. Consolidated Ed son Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804080198 Forwards Insp. Rept. \$0.482/88-10 on 880216-19 & notice of violation withheld (ref. 10CFR73.21). CALLAN,L.J. Region 4, Ofc of the Director. 88/03/28. WITHERS,B.D. Wolf Creuk Nuclear Operating Corp. 3pp. 45044:259-45044:262.
- --8804080219 Partially withhold Insp. Rept. 50:492/88-10 on 880218-19 (ref. 10CFR73.21). Violations noted. Major areas inspected physical security plan & implementing procedures security organization, physical barriers & vital areas KELLY, J. A., EVERETT, R.J. Region 4, Old of the Director. 88/03/21, 1p. 45044:262-45044-282.
- 8904060431 Forwards supplemental response to violations noted in Insp Rept 50-482/ 87-34-Response withheld. BAILEY_JA, Wolf Creek Nuclear Operating Corp. 88/03/29. Document Control Branch (Document Control Desk). 1p. 45115-030-45115-030.
- 8804060265 Responds to NRC 880301 lir re violations noted in Insp Rept 50-482/87-33 Corrective actions reported bity evaluations conducted as required & rept made per 18CFR50-72(b)(2)(v).
 WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 88/03/31. Document Control Branch (Document Control Desk), 2pp. 45007:318-45007:320.
- 88D4060077 Responds to NRC 880307 ltr ra violations noted in Insp Rept 50-482/88-05 Incident violewed as inappropriate to be Issued as violation since util reported incident,per appropriate requirements Details withheld (ref 10CFR73.21). WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 88/04/01. Document Control Branch (Document Control Desk). 1p. 45048.074-45048.074.
- 8804140456 Forwards "Inservice Insp Rept for Refueling Outage 2,Period 1,Interval 1." BAILEY, J.A. Wolf Creek Nuclear Operating Corp. 88/04/04. Document Control Branch (Document Control Desk). 1p. 45100:163-45100;234.
- --8804060107 "Inservice Insp Summary Rept for Refueling Outage 2, Period 1,Interval 1," describing insp & testing of Class 1 & 2 components & piping * Wolf Creek Nuclear Operating Corp. 88/03/30, 71pp. 45100:164-45100:234.
- 8804130425 Responds to NRC 880307 ltr re violations noted in Insp Rept 50-482/88-04.Corrective actions:Procedure QCP 7.1 will be revised to clarify when indirect physi-cal insp methods may be employed due to nature of items & packaging requirements. WITHERS.B.D. Wolf Creek Nuclear Operating Corp. 88/04/08. Document Control Branch (Document Control Desk). 4pp. 45116.363-45116.356.
- 8804140086 Ack receipt of 880128 & 0329 tirs informing NRC of steps taken to correct violations noted in Insp Rept 50-482/87-34. Util maint program may need to be modified periodically to ensure high level performance of sys. CALLANL J. Region 4, Otc of the Director. 88/04/06. WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 2pp. 45155.092-45155:094.

- 8804010258 NRC Into Notice 88:011, "Potential Loss of Motor Control Cir 8/or Sw.tch-board Function Due to Faulty Tre Bolts " Svo Island: ROSSI/GE Division of Opporational Events Assessment (Post 870411) 88/04/07 Consolidated Edison Co. of New York, Inc. 124pp. 45406 292-45407 05)
- 8804140015 Forwards Insp Rept 50-482787-24 on 871019-23 & notice of violation Insp included reviews of Implamentation of equipment qualification correction action com-mitments durint ed in SER (NUREG-0881). CALLANLL J Region 4, Ote of the Director, 88/04/08 WITHERS,8.D Wolf Creek Nu-clear Operating Corp. 3pp. 45151:318 45151:358
- --8804140030 Notice of violation from inspirent 871019 23. Violation noted tuit did not adequately support qualification of Rayottem installor spire configuration or establish similarly between tested & installed spires, por NURG-04588 * Region 4. Old of the Outcott 88/04/08 3pp. 45151.321-45151.323.
- --8804140033 insp Rept 50-482/87-24 on 871019-23 Violations noted Major areas inspected implemental on of equipment qualification commitments identified in SER (NUREG-0881) 8 Soppls 4 85 JOHNSON.A.R. IRELAND.R.E. Region 4, Old of the Oirector. 88/04/05. 33pp 45151 324-45151.358
- 8804180410 Advises that util will respond to SSOMI Insp Ropt 50-482/87-32 on or before 880429 due to length & complex nature of rept 8AILEY_JA Well Croek Nuclear Operating Corp 88/04/08 Document Control Branch (Document Control Desk). 1p 45145-351-45145.35
- 8604150266 Ack receipt of 880318 ftr informing NRC of steps taken to correct violations noted in Insp Rept 50-482788-06 Response deals only w/specific procedural deficiencies identified 8 does not address larger Issue of other procedure problems CALLAN,L.J. Region 4, Oto of the Director 88704711 WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 2pp. 45138.121-45138.122
- 8804080370 NRC into Notice 88 012, "Overgrossing of Electric Motor Bearings." Svc. list enci ROSSI,C E. Division of Operational Events Assessment (Post 670411). 86/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150
- 8804200288 Responds to NRC 880202 lit re unresolved item concerning heat shrink-able tubling identified in this Ropt 50-482/87-37. Instrumentation cable splices, control cable splices 8 power cable splices 8 motor connections addressed. WITHERS B.D. WOII Creek Nuclear Operating Corp. 88/04/12. Document Control Branch (Document Control Desk). 8pp. 45177 283-45177 290
- 8804210337 Ruspends to NRC 880317 ltr re violations noted in Insp. Rept 50-482/87-31 Ruquesis miligation of proposed dwit ponalty. Corrective actions rolucting outage 2 suspended meetings project bindings mandated & Procedure ADM 08-201 revised WiTHERS.B O. Wolf Creek Nuclear Operating Corp. 88704/14 LIEBERMAN,J. Ofc of Enforcement (Post 870413). 28pp., 45227:017-45227:044.
- 8804280038 Forwards Insp. Rept 50-402748-09 on 0.80314-18 & notice of violation CALANIL J. Region 4, Otc of the Director, 80704/15 WITHERS,B D. Wolf Creek Nu-clear Operating Corp. 2pp. 45255-202-45254:213.
- -8804260041 Notice of violation from inspiron 880314-18 Violation colled high radiation area greater than 1,000 mitom/hr near portable deministrator radiation source located at low level drum storage area of radwaste bidg not provided w/locked door 1 Region 1, Oto of the Director, 88704715, 1p. 45254-204-45254-204.
- --8804260046 Insp. Rept. 50-482/88-09 on 880314-18.Violation noted Major areas inspected solid radivaste program,transportation activities & low level radivaste storagg facilities BACR, R.E., MURRAY, B. Region 4, Ofc of the Director, 88/04/11, 9pp. 45254-205-45254-213
- 8804270151 Responds to NRC 880318 lit re violations noted in Insp Rept 50-482/88-O1. Corrective actions: upon notification by resident reactor inspector, duly shift supervisor had test llanges removed from FIHB sys valves.

 WITHERS.B.D. Wolf Creek Nuclear Operating Corp. 80/04/18 Document Control Branch (Occument Control Desk), 3pp. 45241/223-45241/225.

R. Periodic operating reports & related correspondence

8804200204 Monthly operating rept for Mar 1988.W/880413 ltr.
WILLIAMS,M.G., WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 88/03/31, 7pp 45220 278 45220 284

S. Reportable occurrences, LERs & related correspondence

- 8804050361 LER 87-010-02 on 870216, stuations re-breached fire-barriers discovered on solverial occasions during Feb & Mar 1987, Involving the prescript ins barriers discovered in solverial occasions during Feb & Mar 1987, Involving the pronorbation seals & holes in walfs Caused by personnel error Fro watch established W/880330 ltr. WILLIAMS,M.G., WITHERS.B.O. Wolf Creek Nuclear Operating Corp. 88/03/30, 10pp. 45045-193-45045-202.
- 8804280208 First partial response to FOIA request for documents re facility.Forwards App B document App A & B documents also available in POR. GRIMSLEY,DH. Division of Rules & Records (Post 870413), 89/03/30. LYKINS,R D. Bryan, Lykins, Hejlmanek & Wulz. 3pp. 45276 247-45278:251.
- -8804280216 "Event Followup Rept 87-160." FIELDS.N. NRC No. Octalied Affiliation Given. 87/11/11. 2pp. 45276 250-45276 251
- 8804080225 Part 21 rept to inconsistencies in Gou'd,Inc contilicate of compliance re-ceived w/Class 1E fuses procured from Planned Maint Sys due to fuses not being qualified for certain specs initially reported on 880329.Fuses remain on hold. WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 88/04/01. MARTIN,R.D. Region 4, Ofc of the Director. 2pp. 45098:197-45093:198
- 8804200312 LER 88-005-00 on 880328,control room ventilation isolation signals occurred.Caused by spurious spike on chlorine manifor.Monitor replaced & taken to instrumentation 8 control shop for further troubloshooting W7800414 ltr. WILLIAMS,M.G. WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 88/04/14, 6pp. 45221:127-45221:132.

DOCKET STN-50-483 CALLAWAY PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8804080002 Forwards Addendum 88:01 to physical security plan Addendum explains temporary security measures to be taken during const of svc bldg Addendum withheld (ref 10CFR73.21). SCHNELL,D.F. Union Electric Co. 86/03/25, BELANGER,J.L. Region 3, Ofc of the Director, 3pp. 45033.089.45033.091.

8804130122 Rev 6 to Emergency Plan Implementing Procedure EIP-ZZ-00213, "Technical Assessment **
• Union Electric Co. 88/03/31, 35pp, 45147,001-45147:035.

- 8804200302 Rev 8 to Emergency Pfan Implementing Procedure EIP-ZZ-00101, "Classification of Emergencies." DAMPF, J.F., Union Electric Co. 88/04/11, 38pp. 45225;318-45225;352.
- 8804210016 Confirms that procedure revs necessary to implement Amend 30 to Li-cense NPF-30 completed & amend implemented. SCHNELL,D.F. Union Electric Co. 88/04/12. Document Control Branch (Document Control Obsk). 3pp. 45219:090-45219,092.
- 8804250213 Advises that Addendum 88-01 to security plan,transmitted by 880325 lit, meets provisions of 10CFR50.54(p) & acceptable. Ends will be withheld from public disclosure, per 10CFR7321.

 MALLETT,B S. Region 3, Otc of the Director, 88/04/13. SCHNELL,D.F. Union Electric Co. 3pp 45253 034-45253.036.

1. Financial information

8804050173 "Uzkon Electric 1987 Annual Rept." W/880325 ftr. CORNELIUS,W.E., SCHINELL,D.F. Uzkon Electric Co. 87712/31, 47pp. 45048/295-45048/341.

J. Insurance & Indemnity Information

- 8804070069 Forwards rept of present level of insurance & sources of insurance per FOCERSD 54(w).
 SCHNELL, D.F. Union Electric Co. 88/04/01, Document Control Branch (Document Control Dask). 4pp. 46024.258-45024-261.
- O. Advisory Committee on Reactor Saleguards reports & correspondence
- 8804140216 Submits summary of actions discussed at ACRS 335th meeting on 880310-12 in Washington,OC,including ACRS repts/ recommendations,other actions,agroements,assignments & requests & future agenda. KERR,W. ACRS Advisory Committee on Reactor Safeguards, 88/03/24, ZECH,L.W. Commissioners, 4pp. 45118:172-45118.175.

P. Operating license stage documents & correspondence

- 8803240425 Generic Ltr 86:06 to all power reactor beanses & applicants re removal of organization charts from Tech Spec administrative control requirements. Sec fist encl. MIRAGLIA, F.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of Now York, Inc. 47pp. 44972:107-44972.153.
- 8804040119 Application for amend to License NPF-30,increasing flow variations allowed In Tech Spac for control room emergency vanishation sys, filtration air handling units, pressurization sir handling units & pressurization filter units Fee paid. SCHNELL, DF. Un on Electine Co. 88/03/25. Document Cantrol Branch (Document Control Dask) 12pp. 44971:346-44971;360.
- --8804040121 Proposed Tech Specs 3/4.7.6 Increasing allowed flow variations of con-Irol room emergency ventilation sys.
 * Union Electric Co. 88/03/25 3pp. 44971:358-44971:360.

- 8804050243 Informs that NRC finds insufficient data to demonstrate that leak chase channel sys can be qualified as integral part of containment liner plate per 870710 request. Util should have complete documentation of leak test procedures & results. ALEXION.T.W. Project Directorate III-3, 88703730. SCHNELL, D.F. Union Electric Co. 3pp. 44987:129-44997:133.
- 8804120394 Forwards Amend 35 to License NPF-30 & safety evaluation. Amend revises license & Tech Specs to support increase in authorized core thermal power from 3.411 MWI to 3.555 MWI. ALEXION,T.W. Project Directorate III-3, 88/03/30. SCHNELL,D.F. Union Electric Co. 2pp. 45091:266-45091:302.
- --8804120396 Amend 35 to License NPF-30,revising license & Tech Specs to support increase in authorized core thermal power from 3,411 MWI to 3,565 MWI MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/30, 19pp, 45091:268-45091:286.
- -8804120399 Safety evaluation supporting Amend 35 to License NPF-30.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/30, 14pp. 45091:287-45091:300.
- --8804120403 Notice of issuance of Amend 35 to License NPF-30.Amend revises IIcense & Tech Specs to support increase in authorized core thermal from 3,411 MWt to 3,585 MWt ALEXION,T.W. Project Directorate III-3, 88/03/30, 2pp, 45091:301-45091;302.
- 8804110316 Summary of 880318 meeting w/utils re-containment tendon Tech Specs for facilities Attendance Lst & Vicensees presentation encl. DICK,G.F. Project Directorate IV. 88/04/01. Project Directorate IV. 33pp. 45078;297-
- 8804080088 Generic Ltr 68-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.48, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svo list encl. MIRAGUA,F. J. Associate Director for Projects (Post 870411), 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.

- 8804210071 Forwards Rev. 10 of facility pump & valve inservice testing program Ricial requests P03 & P09 resubmitted in revised form for NRC staff review & approval NRC staff approval of submitted requested by 880601 Fee paid SCHNELL.D.F. Union Electric Co. 88704/12. Document Control Branch (Document Control Desk). 5pp. 45238:339-45238.355
- ~8804270282 Rev 10 to "Inservice Testing Program Class 1,2 & 3 Pumps" ROESNER,G.J., WITT,W.A. Union Electric Co. 88/03/31, 12pp. 45238.344-45238.355
- 8804210028 Supplemental application for among to License NPF-30, defelling organization charts from Tech Spacs.
 SCHNELL,D.F. Union Electric Co. 89/04/13 Document Control Branch (Document Control Desk). 6pp. 45231:182-45231:194.
- --8804210038 Proposed Tech Specs, deleting organization charts from Tech Specs * Union Electric Co. 88/04/13, 7pp. 45231:188-45231.194
- 8604220281 Informs of planned,but not guaranteed completion of review of Westinghouse Topical Rept WCAP-10851 re-revised fuel rad design methodology,in time for util Cycle 4 rolload.
 PERKINS,K.E. Project Directorate III-3, 88/04/13, SCHNELL,D.F. Union Electric Co 2pp. 45200.336.45200.337.

- 8804250308 Summary of 880407 meeting w/util 8 Westinghouse re-reload for Cycle 4.Meeting attendees 8 nonproprietary presontation encl. ALEX/ON,T.W. Project Directorate III-3 88/04/13. Project Directorate III-3 17pp 45213:171-45213:187.
- 8804200385 Informs of D Shepard participation in tabletop rowew of simulator certification during with oil 860425,per 880413 folicon.
 BURDICK,T.M. Region 3, Otc of the Director, 88704/15, WEINS,L. Operator Liconsing Branch. 1p. 45226/229-45226/229.
- 8804280010 Forwards Phase 1 survey & mgt plan correspondence chronology re cultural resources requirements for review & recommendations Determination whether sies eligible for inclusion on Natl Register of Thistoric Places requested PERKINS K.E. Project Directorate III-3 88/04/18. Interior, Dept. of. Epp. 45266 (EC-45266:184
- --8804280140 Responds to 850619 request to review "Phase I Cultural Resource Survey & Assessment..." & "Cultural Resource Mgt Plan for Residual..." Repis tacks sufficient discussion to research values of identified archeological sities RUDY.J.F. Interior. Dept of 85/08/15. YOUNGBLOOD.8.J Licensing Branch 1. 1p 45277.108-45279.136

Q. Inspection reports, IE Builetins & correspondence

- 8804200458 Responds to NRC Bulletin 67-002, "Fastener Testing to Determine Conformance W/Applicable Matt Specs" Info late due to scheduling detays at testing fa-
- SCHNELL, D.F. Union Electric Co. 88/02/17. DAVIS, A.B. Region 3, Orc of the Director. 63pp. 45175,040-45175-102.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thenning in Westing house Reactors." Svc list encl. ROSSI, CE Division of Operational Events Assessment (Post 870411) 88/03/28 Consolidated Ecison Co. of New York, Inc. 121pp. 44995.126-44995 246
- 8803220296 NRC Info Notice 88-010, "Matts Licensees:Lack of MgL Controls Over to Censed Programs." Svc hat encf.
 CUNNINGHAM,R E Division of Industrial & Modical Nuclear Safety (Post 870729) 89/
 03/28 Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353
- 8804150408 Forwards addl into re Relief Requests G through N to plant inservice insp program phan as result of observations made during Refuel II
 SCHNELL,D.F. Union Electric Co. 88/04/01. Document Control Branch (Cocument Control Desk) 16pp. 45138 314-45138.329.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Cir &/or Switchboard Function Due to Fautly Tre Botts." Svc list oncl. ROSSI.CE. Division of Operational Events Assessment (Post 870411) 88/04/07 Consolidated Edison Co. of New York, Inc. 124pp. 45406-292-45407:051.
- 8804150412 Forwards response to NRC Bulletin 88-001 re defects in Westinghouse Cir-cuit breakers in Class 1E svc.All required long-term & short-term insps completed SCHNELL,D.F. Union Electric Co. 88/04/11. Document Control Branch (Document Control Dask): 11pp. 45138;184-45138;194.
- 8804200507 Forwards Relief Requests G to N re plant inservice insp program plan.Requests being submitted as result of observations made during Refuel II & addition to previously submitted relief requests SCHNELL, D.F. Union Electric Co. 88/04/11. Document Control Branch (Document Control Desk). 17pp. 45174:354-45175.010.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc ROSSICE, Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165.028-45165:150.

R. Periodic operating reports & related correspondence

8804190100 Monthly operating rept for Mar 1988.W/880407 ltr.
MOOSE,J.M., BLOSSER,J.D. Union Electric Co. 88/03/31 7pp. 45209:152-

S. Reportable occurrences, LEAs & related correspondence

8804070171 Forwards NRC ltr to Nuclear Data,Inc & licensee LER documenting software deficiency re-control of radioactive liquid wastes No further action planned since vandor affectively modified Part 21 reporting/notification sys.

CUNNINGHAM, L.J. Radiation Protection Branch. 88/03/28. BELLAMY,R.R. Region 1, Otc of the Director. COLLINS,D.M. Region 2, Otc of the Director. SHAFER,W.D. Region 3, Ofc of the Director. 1p. 45043:251-45043.259.

- -8804070177 Responds to conversation re Nuclear Date Sys prompt notification sys mat have softwere that might cause public reportability.per 10CFR21 Steps taken to modify internal procedures to notify all power plant customers. SAMSKY, D. Nuclear Data, Inc. 88/03/18 WIGGINTON,J. NRC No Detailed Affination Given. 1p. 45043 252-45043-259.
- 8804140098 LER 86-007-02 on 860318,fire harner penetrations identified which did not have internal conduct seals installed Caused by deficiency in const program Missing conduct seals installed W/860408 ltr CAMPBELL, W.R. BLOSSER, J.D. Union Electric Co. 88/04/08 11pp 45158 303-

DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

E. NRC Safety Evaluation Report (SER), supple & correspondence

- 8804080171 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SOUTH TEXAS PROJECT, UNITS 1 AND 2 Dockol Nos 50-498 And 50-499. (Housion Lighting And Power Company)

 1 Division of Reactor Projects III, IV.V. & Special Projects (Post 870411) NUREG-0781 SOS 88/03/31. 53pp 45040 044-45040 136
- 8804150212 Forwards Suppl 5 to NUREG-0781, "SER ro Operation of South Texas Project Units 1 & 2," for into & use. CALVO,J A. Project Directorate IV 88/04/06. GOLDBERG,J H. Houston Lighting & Power Co 97pp. 45140 122-45140,218.

F. Security, medical, emergency & fire protection plans

- 8804130034 Revised emergency plan implementing procedures, including Rev 8 to OEPP01-ZA-0001, "Emergency Classification," Rev 3 to OEPP01-ZA-0008, "Ollsite Ooso Projections" & Rev 1 to OEPP02-ZA-0004, "Emergency Plan" W/880330 ltr KINSEY,W. MCBURNETT,MA Houston Lighting & Power Co 88/03/30 75pp. 45137-249-45137.323.
- 8804060005 Forwards response to notice of violation & proposed imposition of civil penalty. Util concurs that items noted were violations of NRC requirements withhold exceptions Encl withheld.

 VAUGITHN.G.E. Houston Lighting & Power Co. 88/03/31. Document Control Branch (Document Control Dosk). 2pp. 45032 292-45032 293.
- 8804120116 Forwards Insp Ropts 50-499/88-15 & 50-499/88-15 on 880222-26 No vio-Talions for deviations noted

 CALLAN,L.J. Region 4, Ofc of the Director. 88/04/05. GOLDBERG,J.H. Houston Lighting & Power Co. 3pp. 45122 050-45122:053
- -8604120119 Partially withhold Insp Flepts 50-498/88-15 & 50-499/88-15 on 880222-26 (ref. 10CFR73.21) No violations or devalions noted Major areas inspected Leensee records & ropis, emergency power supply, Ighting & compensatory measures EARNEST, A.B. Region 4, Otc of the Director. 88/03/28. 1p. 45122.053-45122:053.
- 8804210014 Responds to NRC 880316 ftr re-violations noted in Insp Repts 50-498/68-C8 & 50-499/68-01 Corrective actions now & rovised emergency plan implementing procedures issued since iconse obtained submitted to NHC VAUGHN,G.E. Houston Lighting & Power Co. 88/04/11. Document Control Branch (Document Control Dosk). 4pp. 45235-200-45235-203.
- 8804290302 Forwards objectives for 880713 graded emergency proparedness exercise at plant.
 VAUGHN,G E. Houston Lighting & Power Co. 88/04/25. Document Control Branch (Document Control Dask), 8pp. 45283:091-45283-098.

G. Adjudicatory correspondence

8804260051 Informs that time provided within which Commission may act to review Director's Decision DD-88-03 expired Commission declined review Decision became tinal agency action on 880412.Served on 880420 CHILK,S.J. Office of the Societary of the Commission #288 6109. 88/04/20. GARDE,B.P., CONDIT,R.E., Government Accountability Project. 1p. 45210-325-4 45210 325

H. General correspondence

- 8804010010 Advises that mailing address changed as listed COY,P. Citizens Concerned About Nuclear Power, Inc. 88/03/28. CALVO,J.A. Project Directorate IV. 1p. 45074.001-45074.001.
- 8804070204 Requests that encl svc list be used for NRC correspondence w/util re lacitiles List replaces provious requests from util for distribution of correspondence MCBURNETT,M.A. Houston Lighting & Power Co. 88/03/30. Document Control Brench (Document Control Desk). 3pp. 45029-237-45029-239.
- 8804130160 Notifies of changes in permanent assignments of listed senior reactor oper-MCBURNETT,M.A. Houston Lighting & Power Co. 88/04/05. Document Control Branch (Document Control Desk). 2pp. 45137:104-45137:105.

J. Insurance & Indemnity Information

- 8803300258 Submits description of nuclear property insurance currently in force for fa-
- clity, MCBURNETT,M.A. Houston Lighting & Power Co. 88/03/24. Document Control Branch (Document Control Desk). 3pp. 44962:111-44962:113.
- 8804150356 Submits correction to dollar value for Item 1.b of util 880324 ltr reporting plant nuclear insurance protection.per 10CFR50.54(w)(2). MCBURNETT.MA. Houston Lighting 8 Power Co. 88/04/08. Document Control Branch (Document Control Desk). 3pp. 45138:294-45138:296.

8804270243 Forwards Amend 2 to Indomnity Agreement B-108, provided for NRC use in response to reguest contained in fir transmitting License NPF-76 MCBURNETT,MA Houston Lighting & Power Co. 88704/19. Document Control Branch (Document Control Dosk) 3pp. 45244;244-45244;246.

P. Operating license stage documents & correspondence

- 8804120189 FCIA request for records to be available at PDR re-satety allegations concering facility.

 DAY,B. Austin, TX. 88/02/10. GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 2pp. 45101:030-45101.031.
- 8804120084 FOIA request for documents & Info generated ra listed items, including Safety Significance Assessment Team Insp & roview of allegations. CONDIT R E Government Accountability Project 88/03/01 GRIMSLEY,D. Division of Rules & Records (Past 870413). 2pp. 45100 301-45100 302
- 8803280063 Forwards Director's Decision DD-68-03 denying GAP 690126 request per 10CFR2.206,to delay Commission licensing actions on plant W/o FA notice of deci-MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), #388 578, 18703/18 GARDE,B.E., CONDIT,R.E. Government Accountability Project 4pp. 48215-007-45215.173.
- --8804250297 Notice of Issuance of Director's Dacision DD-88-03 denying GAP requests to delay licensing actions on unit NUREG-1306, "NRC Salety Significance Assessment Toam Rept on Allegations to South Toxes Project, Units 1 & 2," and MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/18 100pp, 45215:024-45215:173
- 8803300269 Application for amend to License NPF-71, replacing Table 4.3-2, Note 4 re sleve roley quarterly test exemptions for accumulator discharge isolation visives & 48-inch purge supply & exhaust valves Foe paid. VALG
- --8803300274 Proposed Tech Spec Table 4-3-2, "ESF Autuation Sys Instrumentation Surveillance Requirements," reflecting replacement of Note 5 w/Note 4 re slave relay quarterly test exemptions for accumulator discharge isolation valves. * Howston Lighting & Power Co. 88/03/18, 8pp. 44953,171-44953,178
- 8803240426 Genoric Ltr 88-06 to all power reactor licensees & applicants re-removal of organization charts from Tech Spec administrative control requirements Svc list encl MIRAGLIA F.J. Associatio Director for Projects (Post 870411) 88/03/22 Consolidated Edison Co. of New York, Inc. 47pp. 44072:107-44972 153.
- 8803300228 Forwards change in Initial test program re-performance l'ux mapping in zoro power physics test range,instead of currently specified 3% to 5% power range Change affects (initial Startup Test Descriptions 1 & 17. MCBURNETT,MA Houston Lighting & Power Co. 88/03/24. Document Control Branch (Document Control Dosk). 8pp. 44962 100-44962 107.
- 8804050411 Staff requirements memo re 980321 discussion/possible vote on full power OL for plant On 880322,NRC issued full power OL. CHILK,S.J. Office of the Secretary of the Commission 98/03/29 STELLO,V. Otc of the Executive Director for Operations 1p. 44998,344-44996,344.
- 8804130278 Ack receipt at 880321 ltr,supporting NRC granting of full power OL to util ZECH L.W. Commissioners 88/03/29 SWEENEY,M House of Rep. 1p 45103:144-
- --8804130280 Informs of support w/o qualification of NRC granting full power OL to util SWEENEY,M. House of Rep. 88703/21. ZECH,L.W. Commissioners. 3pp. 45103.145-
- 8804080208 TECHNICAL SPECIFICATIONS FOR SOUTH TEXAS PROJECT, UNIT 1 Ockst No. 50-498 (Houston Lighting And Power Company)

 'Division of Reactor Projects III.IV.V & Special Projects (Post 870411) NUREG-1305-88703/31. 445pp -45035-318-45037.043
- 8804280527 NRC SAFETY SIGNIFICANCE ASSESSMENT TEAM REPORT ON ALLE-GATIONS RELATED TO THE SOUTH TEXAS PROJECT, UNITS 1 & 2 Division of Reactor Projects III, IV, V & Spacial Projects (Post 870411) NUREG-1308, 88703/31, 152pp 45274,151-45274,301
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-torcoment policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Impuriant to Safety for Nuclear Power Plants" Svc list enct. MRRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/04/07. Consol dated Edison Co. of New York, Inc. 49pp. 45164 237-45164:285.
- 8804120095 Partial response to FOIA request for documents-forwards App & documents-App A & B documents available in PDR.App C documents completely with-held (rol FOIA Exemption 5).
 GRIMSLEY,D H. Division of Rules & Records (Post 870413) 88/04/07 CONDIT,R Government Accountability Project, 6pp. 45100 303-45100-324.
- --6804120107 Informs of arrangements being made to send team of qualified individual's to GAP ofcs in order to review certain files to values allegations of safety defects at plant.Retated into encl.

 BRIGGS,W.H. NRC - No Oblated Affiliation Given 87/12/07. CONDIT,R E. Government Accountability Project 6pp. 45100:309-45100:314.
- --8804120117 Forwards GAP draft 860125 petition requesting that Commission delay voting on full power OL for plant until there has been complete investigation of all allegations re plant & public release of rept disposing of each allegation CHANDLER, L. J. Assistant General Counsol for Enforcement, 88702709, MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), Spp. 45100.318, 45100.319.
- --8804120123 Confirms 871104 telcon re agreement to set up meeting in order to provide NRC w/info about safety ellegations at plant. Meeting schaduled for 871112. REHM_T.A. Oite of the Executive Director for Operations. 87/11/09, GARDE,8.P. Government Accountability Project. Spp. 45100:320-45100.324.

- 8804120203 Partial response to FCIA request for documents Forwards. App. B. documents relatings one at facility Apps. A. & B. documents available in PDR App. C. documents completely withher'd test FCIA Exemption 51.
 GRI MSIECYDH. Drawson of Rules & Poccids (Post 870413). 88/04/07. DAY,8 Austin, TX. 6pp. 45101.032-45101.053.
- -8804120211 Ack receipt of 871204 fir to U Calvoire allegations at facility NAC intends that in that renew at GAP with include examilor all parts of recipion likes that NAC.

deems necessary
REHMTIA Cloid the Executive Director for Operations 87/12/08 GARDER P. Government Accountability Project 2pp 45101 038-45101 053

- 8804200513 Advises that 880218 Rev 21 to OA program description for design & const of prant satisfies requirements of 10CFR50, App 8 8 acceptable CALLANL J. Region 4, Clor of the Director, 88/04/13 GOLDBERG, J.H. Houston Lighting & Power Co. 2pp. 45175 011 45175 012
- 8804260100 Ack reccipt of 680130 Prins dissatisfaction w/NRC review of allegations re-salory of prant NRC upan mously found that sufficient ray awild GAP affections con-ducted before authorizing full power License NUREG-1306 encl W/o rept MURLEYTE Office of Nurbar Aecaron Registation, Director (Post 870411), 88/04/ 15 MALONER Afficial on Not Assigned 6pp 45232 173-45232 180
- ~8804260108 Requests full investigation of all 400 safety violations a legations made toward plant before granting OL MALONE,R Affalica Not Assigned 87/01/30 NRC No Detailed Affiliation Given. 2pp. 45232 179-45232 180
- 8804260011 Partial response to FO:A request for documents Forwards App D & E documents also available in PDR App F documents withheld (ref FO:A Exemption 5).
 GRI-MSLEY,DH Division of Rules & Records (Post 870413) 88/04/18 DAY,B. Austin, TX 9pp 45232 276 45233 049
- --8804260037 Responds to 670811 lir requesting NRC to make available for deposition ViSierlo,R Mann,B Hayes & Siconnety te enforcement of B Garde subpoena Rejects request 8 informs of 670814 US petition to enforce subpoena Petition end? PARLERING Ciffice of the General Counsel 67/08/19 CONDIT,R E Government Accountable by Project 44pp 45/23/287-45/233/043
- --8804260120 Clarifies statements made to J Pierobon re GAP allegations in Houston Chronicle rept on safety issues about facility. Misunderstanding could have been avoided if Garde had returned 871/12/14. Public Affairs. 2pp. 45233.044-45233.047.
- -8804260126 Discusses notice of appeal fred on behalf of NRC on 871224 to Garde subpoena Informs that GAP staff & allegers involved skeptical of NRC motives & goals but hope NRC polices will not affect thorough review of allegations. KENNEDVI. Government Accountability Project. 88/01/12 BRIGGS,WIH Solvicitor. 2pp. 45233-048-45233-049.
- 8804278174 Requests meeting to discuss deterral of shutdown from outside control room 8 loss of offsite power tosisteactor protection sys design problem 8 proposed modito correct design.

 MCBURNETT,MIA Houston Lighting 8 Power Co. 88/04/18. Document Control Branch (Document Control Desk). 3pp. 45241:168-45241.168.
- 8804270272 Forwards NUREG-1306, "NRC Salety Significance Assessment Team Rept on Avegations is South Texas Project Umits 1 & 2," for info & use. CALVO, J.A. Project Directorate: IV. 88/04/18. GOLOBERG, J.H. Houston, Lighting & Power Co. 6pp. 45243-067-45243-226.
- 8804260172 Forwards interpretation of ASME Code Section XI evaluation criteria for acceptability of feakage. Util evaluation concluded that essential cooling water sys acceptable for conclude operation.

 MCBURNETT, M.A. Houston Lighting & Power Co. 88/04/20 Document Control Branch (Occument Control Desk). 4pp. 45232.034-45232.037
- 804290280 Responds to 880325 Notice of Violation 8804-01 per 10CFR2-201 Corrective actions taken applicable procedures for filling steam genera-tors revised & operators trained & confirmatory testing completed on revised proce-

VAUGHN.G.E. Houston Lighting & Power Co. 88/04/23. Document Control Branch (Document Control Dest). 6pp. 45282.172-45282.177

Q. Inspection reports, IE Bulletins & correspondence

- 8804120084 FOIA request for documents & info generated rellisted items, including Safety Significance Assessment Team insp & review of allegations. CONDIT R.E. Government Accountability Project 88/03/01 GRIMSLEY,D. Division of Rules & Records (Post 870413). 2pp. 45100.301-45100.302.
- 8803300135 Ack receipt of 880226 ltr informing NRC of steps taken to correct devi-ations noted in Insp Repts 50 489/87-77, 8.50-499/87-77. CALLAN,LJ Region 4, Oit of the Director 88/03/22 GOLDBERG,J H Houston Lighting & Power Co. 2pp. 44945 289-44945 299.
- 8803300203 Forwards Insp Repts 50 498/88 02 & 50 499/88 02 on 880104 29 No violations or deviations noted two unresolved items identified in Paragraphs 6 & 7 of
- CALLAN,L.J. Region 4, Ofc of the Director, 88/03/22, GOLDBERG,J.H. Houston Ughting & Power Co. 2pp. 44961:253-44961:268
- -8803300208 Insp Ropts 50-498/89-02 & 50-499/88-02 on 880104-29 No violations or deviations noted Major areas inspected allegations, HVAC, duct sealant mail, NSSS equipment in Unit 1, efective cable & battery room mods. GILBERTLD. SIMGHA, VICKREY.R.B. Region 4, Ote of the Orector. 88/03/11, 14pp. 44961 255-44961 268.
- 8803300181 Forwards Insp Repts 50-498/68-12 & 50-499/68-12 on 880208- 25 No violations or deviations noted.

 CALLAN, L.J. Region 4, Ofc of the Director, 88/03/23. GOLDBERG, J.H. Houston Lighting & Power Co. 3pp. 44975.308.44875.318.

- --8803300187 Insp. Repts 50-498/88-12 & 50-499/88-12 on 880208-25 No volators noted Major areas inspected startup testing phase, including hot precritical lests identified in Table I.
 JCHNSON, A.R., IRELAND, R.E., Regun. 4. Oic of the Director, 88/03/18, 12pp, 44975-309-44975-318
- 8803300264 Responds to NRC 880223 lit re violations noted in linsp Rept 50.49240.
 75 Corrective actions toxic gas monitors reprogrammed such that operators will not be required to man pulate syst to puriform channel chocks.
 VAUGHNG E. Houston Lighting & Power Co. 88703/24. Document Control Branch (Document Control Desk). 5pp. 44962-114-44982-118.

- 8894080057 Ack receipt of 880301 itrinforming NRC of steps taken to correct violations noted in linsp Repts 50.498/88-01 & 50-499/88-01 CALLANL J. Rogich 4. Ofc. of the Director 88/03/24. GOLDRERG, J.H. Houston Lighting & Power Co. 2pp. 45007, 113-45007, 129.
- 6804070031 Forwards Insp Repts 50-498/88-04 & 50-499/88-04 on 880101-31 & noice of violation CALLANIL J. Region 4, Oic of the Director 88/03/25. GOLOBERG,J.H. Housen Lighting & Power Co. 3pp. 45022.111-45022.128
- --8804070040 Natice of violation from inspiral 880101-31 Violation noted talurato provide adequate procedura that spocified tamp/ prossure limits when giving directors for raising steem generator water level.

 * Region 4, Orc of the Director 88/03/25, 1p. 45022-114-45022-114.
- -8804070045 Insp. Ropts. 50-498/88-04. 8. 50-499/88-04 on 860101-31. Violation noted Major areas inspected.Unit 1 main feedwater hydraulic transients,Unit 2 standby diesel generator initial start, infonthly survioritance observations & site tours. CARPENTER,O.R., HILOEDANND,E.P., BESS J.E. Regron. 4, Ofc. of the Director. 88/03/21, 12pp. 45022.115-45022.126.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thrmble Tube Thinning in Westing-house Reactors" Svc list encl ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/03/28 Consolidated Edison Coll of New York, Inc. 121pp 44995;126-44995;246
- 8803220298 NRC Info Notice 88-010, "Matts Licensees Lack of Mgt Controls Over to 2003/2028 NRC Into Notice do-Critic Malis Electrised Early of Migr Contains Ova Consed Programs." Svc I st encl CUNNINGHAM,R E. D. vis on of Industrial & Medical Nuclear Safety (Post 870729) 88/ 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44895:353.
- 8804040054 Forwards response to NRC Compliance Bulletin 88-002, 'Rapidly Propagating Fatigue Cracks in Steam Generator Tubes.' Supplemental rept will be submitted on or before 890101 GOLDBERG, JH. Houston Lighting & Power Co. 88/03/28 Document Control Besk). 6pp. 45031 273-45031-278.

- 8804050198 Forwards Insp. Repts 50-498/88-16 & 50-499/88-16 on 880224-0303 & notice of violation
 CALLAN,L.J. Region 4, Ofc. of the Director. 88/03/28. GOLDBERG,J.H. Houston
 Lighting & Power Co. 3pp. 450/6 029-450/6 038.
- -8804050224 Notice of violation from insp on 880224-0303. Violation noted electrical field jumpers instalted w/o temporary altoration lags.contrary to Startup Administrative Instruction,SAI-14,Rev 5, "Temporary Alteration Control."

 * Region 4, Otc of the Director 88/03/28, 1p. 45076 032-45076:032.
- --8804050227 Insp. Repts. 50-498/88-16 & 50-499/88-16 on 880224-0303 Violation noted Major areas inspected Unit 2 preoperational RCS cold hydrostatic test & review of sefected preoperational hest procedures. HUNNICUTT.D.M., GARRISON.D.L., SEIDLE,W.C. Region 4, Ofc of the Director. 88/03/21, 7pp. 45076.033-45076.039.
- 8804060473 Responds to NRC Bullatin 88-001, "Defects in Westinghouse Circuits Breakers." Results of insps listed List of Westinghouse Series DS circuit breakers by Septication and a special property of the septication of the septication and s

- 8804130311 Ack receipt of response to NRC Bulletin 87-001, "Thinning of Pipe Walls 8t Nuclear Power Plants" Info being used to determine extent of Industry participation & implementation of eroslun/corrosion insp program & to obtain data. KADAMBIN P. Project Directorate IV. 88/03/29, GOLOBERG,J.H. Houston Lighting & Power Co. 4pp. 45101.240-45101.244.
- 8804060005 Forwards response to notice of violation & proposed imposition of civil penalty. Util concurs that items noted were violations of NRC requirements withree Pentary On Control State India Note Co. 88/03/31, Occument Control Branch (Document Control Desk). 2pp 45032 292-45032 293
- 8804120116 Forwards Insp Repts 50-498/88-15 & 50-499/88-15 on 880222-26 No violations or deviations noted CALLAN, U.J. Region 4, Otc. of the Director. 88/04/05. GOLDBERG, J.H. Houslon Lighting & Power Co. 3pp. 45122.050.45122.053.
- --8804120119 Partially withhold Insp Repts 50-498/88-15 & 50-499/88-15 on 880222-26 (ref. 10CFR73 21) No violetions or deviations noted Major areas Inspected licensee records & repts, emergency power supply-lighting & compensatory measures EARNEST, A.B. Region 4, Ofc of the Director, 88/03/28, 1p. 45122 053-45122.053.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switchboard Function Due to Faulty Tie Bolts." Svc list encl.
 ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/04/07.
 Consolidated Edison Co. of New York, Inc. 124pp. 45405.292-45407.051.
- 8804150368 Responds to violations noted in Insp. Rept. 50-498/88-09. Corrective actions:evaluation of maint work request generation & approval process performed, cases where testing frequency changed ventred & 1TSP03-CV-0001 generated. VAUGHN,G.E. Houston Lighting & Power Co. 88/04/08. Document Control Branch (Document Control Desk). 12pp. 45138:297-45138.308.

201

- 8804210014 Responds to NRC 880316 ltr re violations noted in Insp Repts 50-498/88-08 & 50-499/88-01 Corrective actions new & revised emergency plan implementing procedures issued since license obtained submitted to NRC VAUGHN,G E. Houston Lighting & Power Co. 88/04/11. Document Control Branch (Document Control Desk). 4pp. 45235.200-45235.203
- 8804060370 NRC Into Notice 88-012, "Overgreasing of Electric Motor Bearings." Sve list enct. ROSSI.C.E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165:150.
- 8804210154 Responds to deviation noted in Insp Rept 50-498/88-05 Corrective action emergency operating procedures revised to reflect use of reactor vessel head vent sys during natural circulation cookdown situations. VAUGHN.G.E. Houston Lighting & Power Co. 88/04/14. Document Control Branch (Document Control Desk). 4pp. 45219:165-45219.168.
- 8804210215 Responds to NRC request for addition or NRC Bulletin 85-003, "Motor-Operated Valvo Common Mode Failuros During Plant Translants Due to Improper Switch Settings " Supplemental rept will be submitted by 880614. GCL-08ERGJ.H. Houston Lighting & Power Co. 88/04/14. Document Control Branch (Document Control Desk). 8pp. 45235 181-45235:186.
- 8804220001 Responds to violations noted in Insp Ropt 50-498/68-07. Corrective actions lockable 1 h fire rated filing cabinal provided log established to track removal of Tech Spec surveillance packages & records custodian designated GDLDBLTG.J.H. Houston Lighting & Power Co. 88/04/15. Document Control Branch (Document Control Dosk). 4pp. 45226.324-45226.327.
- 8804250076 Responds to NRC 880318 fir re-violations noted in Insp Repts 50:498/88-07 & 50:499/88-07. Corrective actions: filter mail used in penetration sleeve welds in compliance wigeneral intent of Code & mosts Bechtel spec. GOLDBETRG.J.H. 10uston Lighting & Power Co. 88/04/15. Document Control Branch (Document Control Desk). 8pp. 45237.131-45237.138.
- 8804270148 Forwards response to outstanding operation readinoss insplissus in Insp. Repts 50-498/87-45 & 60-498/88-01. Rev to 1POPQ4-ZO-0001 ra control room evacuation approved w/changes after training drill Shifts briefold re-change. VAUGHNGE: Houston Lighting & Power Co. 88/04/15. Document Control Branch (Document Control Dosk). 14pp. 45241:144-45241:157.

R. Periodic operating reports & related correspondence

- 8803210478 Monthly operating rept for Feb 1988.W/880315 ftr. FISHER.D., NESRSTA.J.J., MCBURNETT,M.A. Houston Lighting & Power Co. 88/02/29, 7pp. 45191.001-45191.007.
- 8804190059 Monthly operating ropt for Mer 1986 W/880412 ltr. NESRSTA,J.J., MCBURNETT,M.A. Hausten Lighting & Power Co. 88/03/31. 7pp. 45208:2304-45208:2306

S. Reportable occurrences, LERs & related correspondence

- 8803290289 LER 88-016-00.on 880206,two MSIVs declared inoperable when duty shift supervisor learned that packing adjustments performed Addi requirements for containment isolation valves not carried out until 880207 W/880322 ltr.

 AYALA, C.A., VAUGHN, G.E. Houston Lighting & Power Co. 88/03/22. 7pp. 44920-027-44020-033
- 8804010088 LER 88-022-00:on 880228 reactor trip occurred due to unanticipated safety injection signal. Caused by spurious input to protection channol during surveillance test Circuit cards replaced & investigation in process. W/880324 Itr.

 AYALA, C.A., VAUGH, G.E. Houston Lighting & Power Co. 88/03/24. 6pp. 44983.001-44983.006.
- 8804010074 LER 86-021-00 on 880224.ESF actuation occurred. Caused by Inverter failure Falled dc to dc converter assemblies from Inverter returned to vendor for fallure analysis Flev to rept will be submitted by 880617.W/880325 ltr.

 AYALA,C.A., VAUGHN,G.E. Houston Lighting & Power Co. 88/03/25. 5pp. 44999:044-44999-048.
- 8804120346 LER 88:008:01:on 880120,safety-related electrical cable splices incorrectly installed Caused by personnel not following correct cable splice detail sheet. Procedures revised w/detailed instructions. W/880330 ltr.

 AYALA, C.A., VAUGHN, G.E. Houston Lighting & Power Co. 88/03/30, 7pp. 45130:355-45130.381.
- 8804040240 PNO-IV-88-024.on 880330,reactor trip & safety Injection occurred due to loss of offsite power.Caused by troubloshooting work on main generator control circuits to determine cause of main generator output breaker trip. CONSTABLE.G.L. Region 4, Ofc of the Director. 88/03/31. 2pp. 45075:308-45076:307.
- 8804130136 LER 88-014-01:on 880204 reactor protection sys actuation occurred. Caused by software design error in qualified display processing sys (QDPS) temp avoraging sys ODPS modified to prevent recurrence. W/880407 lfr. AYA1 A, C., VAUGHN, G.E. Houston Lighting & Power Co. 88/03/31, 8pp. 45132:267-45132-272.
- 8804130167 Final special reption 880116,two diesel generator nonvalid failures occurred. Caused by failure of diaphragm in test mode trip pilot valve. Test mode trip pilot valve replaced & factory diaphragm installation procedure obtained. VAUGHN.G.E. Houston Lighting & Power Co. 88/04/04. Document Control Branch (Document Control Deak). 9pp. 45142:192-45142.200.
- 8804130127 LER 88-023-00:on 880311, frequency of required surveillance test on essential cooling water screen wash booster pump not doubled as required. Caused by inadequate procedure Procedure revised to define surveillance frequency Info.W/880407 ltr.

 AYALA,C.A. VAUGHN,G.E. Houston Lighting & Power Co. 88/04/07. 5pp. 45142:245-45142:249
- 8804200201 LER 87-026-01-on 871212_discovered that degraded undercottage coincident w/safety injection not tosted Caused by personnel misinterpretation of trip actuation devise operational test requirements.W/880413 lt. AYALA.C., VAIGHN.G.E. Houston Lighting & Power Co. 88/04/13. 8pp. 45221:106-45221:115.

- 8804200218 LER 88-024-00 on 880316 discovered that resulting safeguards tost cabinet master roset would reset & block safety injection actuation on fram A,B or C Caused by design error.Design change issued to modify circulty W/880414 ltr AYALA,C, VAUGHIN,G E. Houston Lighting & Power Co. 88/04/13. 5pp. 45226-230-45226-234.
- 8804210332 Special rept on 880316, nonvalid failure of Standby Diesol Generator 13 occurred while performing operability surve l'ance testing. Engineering evaluation intrieted to consider mods to relay circuity. Rept expected by 880701. VAUGHN.G.E. Houston Lighting & Power Co. 88/04/15. Document Control Branch (Document Control Desk). App. 45235:311-45235:314.
- 8804260227 LER 88-025-00:an 880323,ESF actuation of control room ventilation sys to recirculation mode occurred Probable cause due to actuation of control room ventilation radiation monitor. Continued testing will be performed.W/880419 ltr. AYALA,C, VAUGHN,G E. Houston Lighting & Power Co. 88/04/19, 5pp. 45258.350-45258:354

V. Operator Examinations

- 8804120254 Forwards 871208 lir & Rev 1 to Interrepartmental Procedure IP-8 9O, "Licensed Operator Requalification," for review & approval of requalification program. MCBURNETT,M.A. Houston Lighting & Power Co. 68/04/04. Document Control Branch (Document Control Desk). 2pp. 45080-019-45080-044.
- --8804120259 Forwards Rev 1 to IP-8.90, "Licensed Operator Requalification," tor review & approval Rev reflects recent changes made in 10CFR55. VAUGHN, 6 E. Houston Lighting & Power Ce. 87/12/08. Document Control Branch (Document Control Desk). 5pp. 45080/021-45080.044
- --8804120264 Draft Rev 1 to IP-8 90, "Licensed Operator Requalification." Houston Lighting & Power Co. 67/12/08, 22pp. 45080.026-45080.044

DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

A. Application/construction stage documents & correspondence

- 8804120189 FOIA request for records to be available at PDR re-safety allegations concerning facility.

 DAY.B. Austin, TX. 88/02/10. GRIMSLEY,D.H. Division of Rules & Records (Post 870413), 2pp. 45101:030-46101:031.
- 8804120084 FOIA request for documents & info generated re listed items, including Safety Significance Assessment Team insp & review of allegations. CONDIT.R.E. Government Accountability Project. 88/03/01. GRIMSLEY,O. Dw.sion of Rules & Records (Post 870413). 2pp. 45100 301-45100.302.
- 8803280063 Forwards Director's Decision DD-88-03, denying GAP 880126 request, por 10CFR2.206, to delay Commission Ilicansing actions on plant. W/o FA notice of decision. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), #388 5887, 88/03/18. GARDE,B.E., CONDIT,R.E. Government Accountability Project, 4pp. 45215-007-45216-173.
- --8804250297 Notice of Issuance of Director's Decision DD-88-03.denying GAP requests to delay licensing actions on unit NUREG-1306, "NRC Safety Significance Assessment Team Rept on Allogations re South Texas Project, Units 1 & 2," enci MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), B8/03/18, 100pp. 45215:024-45215:173.
- 8803240426 Generic Ltr 88-08 to all power reactor licensees 8 applicants re removal of organization charts from Tech Spec administrative control requirements Svc list encl MIRAGLIA,F.J. Associate Director for Projects (Post 870411). 88/03/22 Consol dated Edison Co. of New York, Inc. 47pp. 44972-107-44972:153.
- 8804280527 NRC SAFETY SIGNIFICANCE ASSESSMENT TEAM REPORT ON ALLE-GATIONS RELATED TO THE SOUTH TEXAS PROJECT, UNITS 1 & 2. * Division of Reactor Projects - III,IV.V & Spocial Projects (Post 870411). NUREG-1308. 88/03/21. 162pp. 45274:151-45274:301.
- 8804190258 Forwards Rev 0 to "Unit 2 Pump & Valve Inservice Test Plan" Valve stroke time criteria will be incorporated into subsequent revs as baseline data obtained Plant mode affecting plan will be provided in subsequent revs. BAILEY_JN. Houston Lighting & Power Co. 80/04/04. Document Control Branch (Document Control Dosk). 2pp. 45217:001-45217:240.
- --8804190262 Rev 0 to "Unit 2 Pump & Valve Inservice Test Plan." BAKER,D.E. Houston Lighting & Power Co. 88/03/26. 179pp. 45217.003-45217.240.
- 8804290284 Application for license to receive possess, return & store unimadiated fuel assemblies required for operation per 10CFR60 requirements. VAUGHN,G.E. Houston Lighting & Power Co., 88704705. THOMPSON,H. Office of Nuclear Material Safety & Safeguarde, Director. 42pp. 45322:231-45322:273.
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified enforcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Pfants." Svc list oncl. MIRAGULA, J. Associate Director for Projects (Post 870411), 86/04/07. Consolidated Edison Co. of New York, Inc. 49pp. 45184:237-45164:285.
- 8804120096 Partial response to FOIA request for documents.Forwards App B documents.App A & B documents available in PDR.App C documents completely withheld (rel FOIA Examption 5). GRIMSLEY,D.H. Division of Rules & Records (Post 870413), 88/04/07, CONDIT,R. Government Accountability Project, 6pp. 46100:303-46100.324.
- ~8804120107 Informs of arrangements being made to send team of qualified individuals to QAP pics in order to review certain files re various allegations of safety defects at plant. Related into encl.
 BRIGGS.W.H. NRC No Detailed Affiliation Given. 87/12/07. CONDIT.R.E. Government Accountability Project. 8pp. 46100:309-45100:314.

- -8804120117 Forwards GAP draft 880126 petition requesting that Commission delay voting on full power OL for plant until there has been complete investigation of all allegations to plant 8 public release of repit disposing of each aflegation. CHANDLERL J Assistant General Counsel for Enforcement 88702709 MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) Spp. 45100:315-45100.319.
- --8804120123 Confirms 871104 telcon relagreement to set up meeting in order to provide NRC w/info about safety allegations at plant Meeting schedulad for 871112 REHMT.A Ofc of the Executive Director for Operations 87/11/09. GARDE,8 P. Government Accountability Project, Spp. 45100 320 45100 324.
- 8804120203 Partial response to FOIA request for documents Forwards App B documents re allegations at facility Apps A & B documents available in PDR App C documents completely withheld (ref FOIA Exemption 5) GRIIMSLEY,O.H. Division of Rules & Records (Post 870413) 88/04/07. DAY,B. Austin, TX. 6pp. 45101.032-45101.053.
- --8804120211 Ack receipt at 871204 ltr to J Calvoire ellegations at facility.NRC intende that initial review at GAP will include exam of all parts of recipient files that NRC deems nocessary.
 REHM,T A: Ofciof the Executive Director for Operations, 87/12/08, GARDE,B P. Government Accountability Project, 2pp. 45101.038-45101.053.
- 8804200513 Advises that 880218 Rev 21 to OA program description for design & const of plant satisfies requirements of 100FR50, App B & acceptable. CALLAN, LJ. Rog on 4, Otc of the Director, 68/04/13. GOLDRERG, JH. Houston Lighting & Power Co. 2pp. 45175.011-45176.012.
- 8804260100 Ack receipt of 860130 ftr re-dissatisfaction w/NRC review of allegations resafety of plant/NRC unanimously found that sufficient review of GAP allegations conducted before authorizing full power license NUTIRE-1306 enc.W/o rept. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/ 15, MALONE,R. Affiliation Not Assigned, 6pp. 45232:173-45232 180.
- -8804260108 Requests full investigation of all 400 safety violations allegations made toward plant before granting OL MALONE A. Afrillation Not Assigned 87/01/30. NRC No Detailed Affiliation Given 2pp. 45232 179-45232 180.
- 8804280011 Partial response to FOIA request for documents Forwards App D & E documents also evaliable in PDR. App F documents withheld (ref.FOIA Exempting 5)
- (ref FOIA Exemption 5).
 GRIMSLEY, DH Division of Rules & Records (Post 870413). 8B/04/18. DAY, B. Austin, TX. 9pp. 45232:278-45233 049.
- ~8804260037 Responds to 870811 ltr requesting NRC to make available for deposition V Stello.R Martin,B Hayes & S Connelly re enforcement of β Garde subpoena.Rejects request & informs of 870814 US patition to enforce subpoena Patition enci. PARLER,W.C. Office of the General Counsel \$7708/19. CONDIT,R E. Government Accountab.http Project. 44pp. 45232 287-45233.043.
- --8804260120 Clarifies statements made to J Pierohon to GAP allegations in Houston Chronicle reption safety rissues about facility. Misunderstanding could have been avoided it Garde had returned 871214 call. INGRAM,F. Public Affers. 87/12/14. Public Affairs 2pp. 45233.044-45233.047.
- --8804260126 Discusses notice of appoal filed on behalf of NRC on 871224 re Garde subpoena Informs that GAP staff & allogers Involved skeptical of NRC motives & goals but hope NRC politics will not affect thorough review of allegations. KENNEDYJ. Government Accountability Project. 88/01/12. BRIGGS.W.H. Solicitor. 2pp. 45233 048-45233 049.
- 8804270272 Forwards NUREG-1306, "NRC Safety Significance Assessment Team Ropt on Allegations re South Texas Project, Units 1 & 2," for Into & use. CALVOUA Project Directorate IV. 88704718. GOLDBERGUH. Houston Lighting & Power Co. 8pp. 45243-067-45243-226.

E. NRC Safety Evaluation Report (SER), supple & correspondence

- 8804080171 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SOUTH TEXAS PROJECT, UNITS 1 AND 2. Docket Nos. 50-498 And 50-499. (Houston Lighting And Power Company)

 * Division of Reactor Projects III, IV, V & Special Projects (Post 870411). NUREG-0781 S05. 88/03/31. 53pp. 45040.044-45040.136.
- 8804150212 Forwards Suppl 5 to NUREG-0781, "SER re Operation of South Texas Project,Units 1 & 2," for into & use CALVO.JA. Project Directorate IV. 89/04/06. GOLDBERG.J.H. Houston Lighting & Power Co. 97pp 45140 122-45140 218.

F. Security, medical, emergency & fire protection plans

- 8804130034 Revised emergency plan implementing procedures including Rev 8 to OEPP01-ZA-0001, "Emergency Classification," Rev 3 to OEPP01-ZA-0008, "Offsite Dose Projections" & Rev 1 to OEPP02-ZA-0004, "Emergency Plan." W/880330 ltr KIMSEY,W., MCBURNETT,M.A. Houston Lighting & Power Co. 88/03/30 75pp 45137-249-45137:323.
- 8804120116 Forwards Insp Repts 50:498/88-15 & 50:499/88-15 on 880222-26.No violations or devisions notice. CALLANI, J. Regton 4, Old of the Director, 88/04/05. GOLDBERG,J.H. Houston Ugliking & Pawer Co. 3pp. 45122 050-46122.053.
- --8804120119 Partially withheld Insp Repts 50:498/88-15 & 50:499/88-15 on 880222-28 (ref. 10CFR73.21).No. violations or deviations noted Major areas inspected licensee records & repts, emergency power supply, lighting & compensatory measures. EARNEST.A.B. Region 4, Otc of the Director. 88/03/28, 1p. 45122:053-45122.053.
- 8804210014 Responds to NRC 880316 ftr re violations noted in Insp. Repts 50-498/88-08 & 50-498/88-01 Corrective actions new & revised emergency plan implementing procedures issued since license obtained submitted to NRC.

 VAUGHN,G E. Houston Lighting & Power Co. 88/04/11. Document Control Branch (Document Control Desk). 4pp. 45235/200-45235.203.

8804290302 Forwards objectives for 880713 graded emergency proparedness exec at plant VAUGHN,G.E. Houston Lighting & Power Co. 88/04/25. Document Control Bial (Document Control Desk), 6pp. 45283.091-45283-096.

H. General correspondence

- 8804010010 Advises that mailing address changed as listed.
 COY.P Crizens Concerned About Nuclear Power, Inc. 88/03/28 CALVOJ A Prej.
 Directorate IV. 1p. 45074.001-45074.001.
- 8804070204 Requests that encl svc list be used for NRC correspondence w/utitac-lities List replaces previous requests from util for distribution of corresponden MCBURNETT,M.A. Houston Lighting & Power Co. 88/03/30 Document Cor Branch (Document Control Desk). 3pp. 45029:237-45029:239.
- 8804130160 Notifies of changes in permanent assignments of listed senior reactor of ators.

 MCBURNETT,M.A. Houston Lighting & Power Co. 88/04/05 Document Control Desk). 2pp. 45137:104-46137:105.

Q. Inspection reports, IE Bulletins & correspondence

- 8804120084 FOIA request for documents & info generated relisted items, inclus Safety Significance Assessment Team insp & review of affogations CONDT R.E. Government Accountability Project. 88/03/01. GRIMSLEY,D Division Rules & Records (Post 870413). 2pp. 45100.301-45100.302.
- 8803300135 Ack receipt of 880226 ltr informing NRC of steps taken to correct d ations noted in Insp Repts 50-498/87-77 & 50-499/87-77. CALLAN,L.J. Region 4, Ofc of the Director. 88/03/22. GOLD9ERG,J.H. Hous Lighting & Power Co. 2pp. 44945 289-44945:299.
- 8803300203 Forwards Insp Repts 50-498/88-02 & 50-499/88-02 on 880104-28 No lations or deviations noted. Two unresolved items identified in Paragraphs 6 & Tepl. CALLAN, L.J. Region 4, Ofc of the Director, 88/03/22 GOLDBERG, J.H. Hows Lighting & Power Co. 2pp. 44961:253-44961:268.
- 8803300181 Forwards Insp Repts 50-498/88-12 & 50-499/88-12 on 880208- 25 No lations or deviations noted CALLAN,L.J. Region 4, Otc of the Director, 88/03/23. GOLDBERG,J H. Hous Lighting & Power Co. 3pp. 44975:306-44975.318.
- --8803300187 Insp Repts 50-498/88-12 & 50-499/88-12 on 880208-25 No vicial noted Major areas inspected startup testing phase, including hot precritical tests (of field in Table I. JOHNSONA.R., IRELAND,R.E. Region 4, Ofc of the Director. 88/03/18 10 44975:309-44975:318.
- 8804060057 Ack receipt of 880301 ltr informing NRC of steps taken to correct violatinated in Insp Repts 50-498/88-01 & 50-498/88-01.
 CALLAN.L.J. Region 4, Oto of the Director, 88/03/24. GOLDBERG,J.H. Houselighting & Power Co. 2pp. 46007:113-45007:129.
- 8804010077 Notification of 880405 meeting w/util in Rockville,MD to discuss liced feedback on proposals to meet requirements of IE Bulletin 79-14. KADAMBIN.P. Project Directorate IV. 88/03/25. CALVO,J.A. Project Directorate 5pp. 44920.357-44920.362.
- 8804070031 Forwards than Repts 50-498/88 04 & 50-498/88-04 on 880101-31 & no of violation.
 CALLANL J. Region 4, Ofc of the Director 88/03/26 GOLDBERG.J H. Host Lighting & Power Co. 3pp. 45022:111-45022:126.
- --8804070045 Insp. Repta 50-498/88-04 & 50-499/88-04 on 880101-31 Viola noted Major areas Inspected Unit 1 main teedwater hydraulic transients Unit 2 standlesel generator initial start, monthly surveillance observations & site tours. CARPENTER, D.R. HILDEBRAND, E.P., BESS, J.E. Region 4, Ofc of the Director. 03/21, 12pp. 45022:115-45022:126.
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in West touse Reactions." Svc list encl. ROSSIC.E. Division of Operational Events Assessment (Post 670411). 88/03 Consolidated Edison Co. of New York, Inc. 121pp. 44895:126-44995 246
- 8803220296 NRC Info Notice 88-010, "Matts Licensees:Lack of Mgt Controls Overcensed Programs." Svc list encl. CUNNINGHAM, R. E. Division of Industrial & Modical Nuclear Safety (Post 870729) 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995:353
- 8804050198 Forwards Insp. Repts 50-498/88-16 & 50-499/68-16 on 980224-030 notice of violation. CALLANI, J. Region 4, Ofc of the Director, 88/03/28, GOLDBERG, J.H. Houselighting & Power Co. 3pp. 45076:029-45076:039.
- --8804060224 Notice of violation from Insp on 680224.0303. Violation noted:e'ect field jumpers Installed w/o temporáry alteration tags.contrary to Startup Administra Instruction,SAI-14,Rev 5, "Temporary Alteration Control."

 * Region 4, Oto of the Director, 68703/28, 1p. 45076.032-45076.032.
- --8804050227 Insp. Repls 50-498/88-16 & 50-499/88-16 on 880224-0303. Viola noted Major areas inspected: Unit 2 preoperational RCS cold hydrostatic test 8 rerol selected preoperational lest procedures. HUNNICUTT, D.M., GARRISON, D.L., SEIDLE, W.O: Region 4, Ofc of the Director 03/21, 7pp. 45076:033-45076:039.

203

- 8884060473 Responds to NRC Bulletin U8:001. "Defects in Westinghouse Circuits Breakers" Results of insps 1 sted List of Westinghouse Sories DS circuit breakers by
- GOLUBERG J.H. Houston Lighting & Power Co. 88/03/29 (Jacument Control Branch (Occurrent Control Desk). 7pp. 45092-339-45092-345
- 8804130311 Ack receipt of response to NRC Bulletin 87-001, "Thinning of Pipo Walls at Naclear Power Plants" Into being used to determine extent of industry participation & implementation of erosion/corrosion inspiprogram & to obtain data KADAMBIN P Project Directorate IV. 887/03/29, GOLDBERG J.H. Houston Lighting & Power Co., 4pp. 45101,240-45101,244
- 8884120116 Forwards Insp Repts 50-498788-15 & 50-499788-15 on 880222-26 No vio-
- lations or deviations noted CALLAN,L.J. Region 4, Ofc. of the Director 88/04/05 GOLDBERG,J.H. Houston Lighting & Power Co. 3pp. 45122 050-45122 053
- --8804120119 Partially withhold Insp Ropts 50:498/86-15 & 50:499/88-15 ori 890222-26 (ref. b0CFR/2.21) No. violations or deviations roted Major areas inspected Leceiseo records & repts, emorgency power supply; glitting & componsatory measures EARNEST.A B. Region 4, Ofc of the Director BB/03/28, 1p. 45122.053:45122:053.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switchboard Function Due to Faulty Tre Bolts "Svc list encl.

 ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/07
 Consolidated Edison Co. of New York, Inc. 124pp. 45406;292-45407.051.
- 8804210014 Responds to NRC 880316 fit re-violations noted in Insp Repls 50-498/88-06 & 50-499/88-01 Corrective actions new & revised emortiescy plan implementing procedures issued since I conse obtained submitted to NRC VAUCHN, GE Houston Lighting & Power Co. 88/04/11. Document Control Branch (Document Control Dask). 4pp. 45235 200-45235-203
- 8804060370 NRC into Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc ROSSICE Ovision of Operational Events Assessment (Post 870411) 88/04/12 Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165.150.
- 8804250078 Responds to NRC 880318 fir re-violations noted in Insp Repts 50-498788-07 & 50-499/88-07 Corrective actions litter matt used in penutration sleave wilds in compliance wigeneral intent of Code & meets Bechiel spec GCI DBERG.J.H. Houston Lighting & Power Co. 88/04/15. Decument Control Branch (Uccument Control Desk). 8pp. 45237 131-45237 138
- 8804270006 Discusses highlights from 880405 meeting re as-built reconcliation program Adequate into provided for NRC to contirm that design & const program incorporated liabures per IE Bullotin 79-14
 BAILEY_J N Houston Lighting & Power Co. 88704/18 Gocument Control Branch (Document Control Dask). 28pp. 45319.113-45319.140

V. Operator Examinations

- 8804120254 Forwards 871208 ftr & Rov 1 to Interdepartmental Procedure IP-8 90, "U-censed Operator Requalification," for review & approval of requalification program MCGURNETT,M A Houston Lighting & Power Co. 88/04/04 Document Control Branch (Document Control Desk). 2pp. 45080 619-45080.044.
- ~8804120259 Forwards Rov 1 to IP-8.9O, "Liconsed Operator Requaltication," for rov.cw & approval Revirellects recent changes made in 10CF455. VAUGHN,G.E. Houston Lighting & Power Co. 87/12/08. Document Control Branch (Document Control Dask) 5pp. 45080.021-45080.041.
- --8804120264 Draft Roy 1 to IP-8 9Ω, "Ucensed Operator Requalification," Houston Lighting & Power Co. 87/12/08, 22pp. 45080 026-45080 044

DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

8804140193 Provides listed into requested in 880225 ftr re-operating nuclear power units located at twelve sites along Groat Lakes.

STELLO,V. Oic of the Executive Director for Operations 88/04/08 RIDGE,T House of Rep. Spp. 45104.138-45104:143

DOCKET 50-501 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3

A. Application/construction stage documents & correspondence

8804140193 Provides Isted Info requested in 889225 fir re operating nuclear power units located at twelve sites along Great Lakes
STELLO,V Ofc of the Executive Director for Operations 88/04/06 RIDGE,T. House of Rep. 5pp. 45104:138-45104.143.

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A. Application/construction stage documents & correspondence

- 8803240426 Generic Ltr 88:06 to all power reactor licensees 8 applicants re-removal of erganization charts from Tech Spec administrative control requirements Svc 1st erect MIHAGLIA.F.J. Associate Director for Projects (Post 870411) 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972.107-44072.153.
- 8804080086 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 10CFR50.49, "Environ Qualification of Electrical Equip-ment Important to Safety for Nuclear Power Plants" See isls end: MRAGLIA,F.J. Associate Director for Projects (Post 670411), 88/04/07. Consolidated Edison Ca. of New York, Inc. 49pp. 45164:237-45184.285.

Q. Inspection reports, IE Bulletins & correspondence

- 8803210090 Supplit to NRC Info Notice 87 044, "Thimbte Tube Thinning in Westing-house Reactors" Svc list end ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/03/28 Consolidated Edison Co. of Now York, Inc. 121pp. 44995, 126-44995, 246
- 8803220296 NHC Info Notice 68-010, "Matts Licensees Lack of Mgt Controls Over Liconsoit Programs " Svc list eccl CUNNINGHAM,R E Division of Industrial & Medical Nuclear Safety (Post 870729), 887 03728 Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995 353
- 8804010256 NRC Into Notice 88 011, "Potential Loss of Moter Control Cir 8/cr Switch-baard Function Due to Faulty Tre Botts." Svc institute HOSSI.C.E. Dusson of Operational Events Assessment (Post 870411) 88/04/07 Corso
- 8804080370 NRC Info Notice 88-012, "Overgreasing of Efective Motor Bearings." Svc ROSSI,C.E. Division of Operational Evants Assessment (Post 870411) 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165-150

DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

- 8804150283 Forwards results & conclusions of regulatory affectiveness review on 880223-0302 Response re Identified weakness requested within 45 days of litracept. Encis withheld (ref 100FR73 21)
- CRUTCHFIELD.D. Division of Reactor Projects III.IV.V. & Special Projects (Post 870411) 88/04/12 VAN BRUNT,E.E. Anzona Muclear Power Project (formerly Anzo-na Public Service Co.), 4pp. 45192/270 45192/273
- 8804220254 Ack requipt of end JG Hayries 880317 für re scope & objectives for 1988 annual emergency preparedness exercise. Cortain flems on objectives six clarified per 886407 felcen between G Brown & H Bieling Scope & objectives acceptable FISH,R. Region 5. Otc of the Crector. 88704/15 VAN BRUNT, EE. Arizona Nuclear Power Project (formerly Anzona Public Service Co.). 2pp. 46257.196-45257 205
- --8804220255 Forwards, for review & comment, draft objectives & extent of play for 1988 with annual emergency plan exercise scheduled for 890606 Draft submitted per NRC 830803 ftr unit & util Atim in strative Control Manual EXCO 06 HAYNESULG. Arrona Nuclear Power Project (formorly Arrona Public Service Co) 88/03/17. MARTINUS B. Rogion 5, Ofc of the Director 8pp. 45257:198-45257.205

G. Adjudicatory correspondence

- 8804260033 Informs that time provided within which Commission may act to review Di-rector's Decision DD-88-02 expired. Commission declined review Decision became final agency action on 880408. Served on 880420. CHILK, S.J. Office of the Secretary of the Commission #288 6110 88/04/20 SCOTF, M.L. Coalition for Responsible Energy Education. 1p. 45211:120-45211:120
- J. Insurance & Indemnity Information

44961:321-44961.326

8804060463 Lists present level of financial protection for plant per 10CFR50.54(w)(4) VAN BRUNT E E Arzona Nuclear Power Project (formerly Arzona Public Service Co) 887/03/24. Document Centre Branch (Decument Centre) Desk). 1p. 45010.214-45010 214

P. Operating license stage documents & correspondence

- 8804010251 Forwards Vols I-III of CEN-369(V), "Heciprocating Charging Pump Test Rept." 8 CEN-370(V), "Charging Pump Gas Binding & Cracked Block Evaluation Hept." por Condition 3 a of License NPI-51 & 851128 commitment VAN BRUNITEE Anzona Nuclear Power Project (formally Anzona Public Service Co.), 88703/02 Document Control Branch (Document Control Desk) 2pp 45015 191-45016 172
- --8804010257 "Charging Pump Gas Binding & Cracked Block Evaluation Ropt."

 * Combustion Engineering, Inc. CEN-370(V) 88/02/29, 62pp 45015 193-45015 255
- --88040 10259 Vols Hill of "Reciprocating Charging Pump Test Rept" Combustion Engineering, Inc. CEN 369(V), 88/02/29, 277pp, 45015 256-45016.172
- 8803300130 Application for amends to Licensos NPF-41,NPF-51 & NPF-74, rov.sing Surveillance Requirement 4.5.2 h to change total injection foop flow to 4,800 gpm & njection leg max deviation to 200 gpm vAN BRUNT, E. Artzona Nuclear Power Project (formerly Arizona Public Serv.co Co.) 88/03/16 Document Control Branch (Document Control Dosk) 7pp 44961:314-44981:326
- 44961 326
- --0803300133 Proposed Tech Spacs,ravising Survoitance Requirement 4.5.2 hito change total injection toop flow to 4,800 gpm & injection leg max devation to 200 Auzona Nuclear Power Project (formerly Auzona Public Service Co.) 88/03/16 6pp
- 8803300116 Application for amonds to Licenses NPF-41,NPF-51 & NPF-74, adding Iscense condition for reactor coplant pump vibration monitoring program VAN BHUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.) 88/03/18 Document Control Branch (Document Control Desk) 7pp. 44961-225, 44961-237.
- -8803300123 Proposed Tech Specs adding license condition for reactor coolant pump words on monitoring program.
 * Anzona Nuclear Power Project (formerly Arizona Public Service Co.) 88/03/18 6pp.
 44961:232-44961:237.

- 8803240426 Generic Ltr 88-06 to ah power reactor licensees & applicants re-removal of organization charts from Tech Spec administrative control requirements Svc list encl MIRAGLIA F.J. Associate Director for Projects (Post 870411) 88703722 Consolidated Edison Co. of New York, Inc. 47pp. 44972 107-44972.153
- 8804040128 Forwards revised pages of FSAR re QA program. Change will enhance operation & availability of radwasts migt sigs by providing practical approach to procure-ment & installation of nonchical instrumentation & sampling components. VAN SRUNTEE, Azona Nuclear Power Project (formerly Arizona Public Service Co) 88/03/24 Document Control Branch (Document Control Dask), 7pp. 44970:256-
- 8804050097 Provides proposed changes to previously acceptable commitments re-reactor coolent pump shall vibration monitoring program, including reducing number of required monitoring channels per pump from 2 to 1. LICHTRALE A. Project Directorate V. 88/03/25. VAN BRUNTLE E. Anzona Nuclear Power Project (formerly Arizona Public Service Co.). 4pp. 45029 156-45029:159.
- 8804060465 Informs that u.i. will respond to NRC 680223 request for addl into re-sponse to Generic Ltr 86 06 by 680830. VAN 68UNT.E.E. Airzona Nuclear Power Project (formerly Arizona Public Service Col. 88/03/28. Document Control Branch (Document Control Dosk). 2pp. 45074:150-46074:151.
- 8804076002 Updates status of scram reduction program Program being extended to fully utilize balance-of-plant simulation model to evaluate Category 2 scram initiators Category 3 initiators eliminated from further review.

 VAN BRUNT,E.E. Anzona Nuclear Power Project (formerly Arizona Public Service Co.), 88/03/28. Document Control Branch (Document Control Desk). 2pp. 45048.284-4504.986.
- 8804130360 Application for amends to Liconses NPF-41,NPF-51 & NPF-74, changing monitoring requirements for hydrogen & oxygen in waste gas holdup sys Fee paid. VAN BRUNT,E.E. Anzona Nuclear Power Project (formerly Anzona Public Servico Co.) 88/04/96. Document Control Desk). 8pp. 45146:341-
- -8804130363 Proposed Tech Specs, modifying requirements for hydrogen & oxygen waste gas holdup sys.
 * Arizona Nuclear Power Project (formerly Arizona Public Survice Co.). 88/04/08. 9pp. 45146 349 45146 357
- 8804080088 Generic Ltr 88-07 to power reactor licensees & applicants re-modified en-forcement policy concerning 190FF950.49, "Environ Qualification of Electrical Equip-ment Important lo Safety for Nuclear Power Plants" Svc list and: MIRAGLIA,F J. Associate Director for Projects (Post 870411) 88/04/07, Consolidated Edison Co. of New York, Inc. 49pp. 45164 237-45164:285.
- 8604130368 Application for amends to Licenses NPF-41,NPF-51 & NPF-74, allowing use of filler rods or vacancies in fuel assemblies. Fee paid.

 VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service
 Co.), 88/04/08. Document Control Branch (Document Control Desk). 5pp. 45151:053-
- -8804130369 Proposed Tech Spocs, allowing use of filler rods or vacancies in fuel assemblies.
 * Arizona Nuclear Power Project (formerly Arizona Public Service Co.), 88/04/08, 3pp.
- 45151:058-45151:060 8804150130 Notification of 880414 meeting w/util & BNL In Rockville,MD to discuss vibration monitoring program for reactor coolent pump shafts & status on plant shaft evaluations Agenda encl.
 LICTRA,E,A. Project Directorate V. 88/04/08. KNIGHTON,G.W. Project Directorate V.
- 5pp. 45133 332-45133.336.
- 8804210437 Forwards notice of consideration of Issuance of emends to Licenses NPF-41,NPF-51 & NPF-74 & proposed NSHC determination & opportunity for hearing on 890408 request re design description of fural assemblies. LICITRA,E A. Project Directorate V. 88/704/13, VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.) 3pp. 45191:160-45191:169.
- --8804200500 Notice of consideration of Issuance of amends to Licenses NPF-41,NPF-51 & NPF-74 & proposed NSHC determination & opportunity for hearing.Amends revise Tech Specs re design description of fuel assemblies. LICITRA,E.A. Project Directorate V. 88704713: 7pp. 45191:163-45191:169.
- 8904280581 Forwards safety evaluation supporting util natural circulation cooldown capability.Test results combined w/ supporting analysis demonstrate that plant meets requirements of 8TP RSB 5-1 for Class 2 plant LIGITRA.E.A Project Directorate V. 68/04/18. VAN BRUNT.E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 4pp. 45268:353-45268.359.
- --8804280571 Safety evaluation re util natural disculation cooldown capability. Plant meets requirements of BTP RSB 5-1 for Class 2 plant.
 NRC No Detailed Affiliation Given. 88/04/18, 3pp. 45266, 357-45268;359.

Q. Inspection reports, IE Bulletins & correspondence

- 8804040003 Forwards Enforcement Conference Repts 50-528/88-11, 50-529/88-11 & 50-530/88-11 on 880229.Concerns summarized, Actions described to improve utilization of simulator & to more closely follow backlog of maint litems found positive. MARTIN,J.B. Region 5, Otc of the Oirector, 88/03/18, VAN 8RUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.), 3pp. 44971:251-44971:288,
- -8804040090 Enforcement Conference Repts 60-528/88-11,60-529/88-11 & 50-530/ 88-11 on 880229.Major areas discussed/licenses inadvertent rendering of steam driven auxiliary teedwater pumps in Units 1 & 2 Inoperable.

 RICHARDS.S.A. Region 5, Ofc of the Director. 88/03/18 34pp. 44971:254-44971:288
- 8804060501 Forwards Insp Repts 50-528/88-09,50-529/88-09 & 50-530/88-09 on 880222-25 & 0229-0303. No violations noted.
 WENSLAWSKI,F.A. Region 5, Ofe of the Director. 88/03/22. VAN BRUNT,E.E. Arizona Nuclear Power Project (formerty Anizona Public Service Co.). 2pp. 45010:290-45010:298.

- --8804060509 Insp Ropts 50-528/88-09,50-529/88-09 & 50-530/88-09 on 880222-25 & 0229-0303 No violations or deviations noted Major areas inspected transportation,maintaining occupational exposures ALARA & radiation movement NORTH, H.S., YUHAS, G.P. Region 5, Ofc of the Director, 88/03/22, 7pp. 45010 232-
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Trimble Tube Thinning in Wesinghouse Reactors" Svc list enci.
 ROSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/03/28.
 Consol'dated Edison Co. of New York, Inc. 121pp. 44995.126-44995-246
- 8803220298 NRC Into Notice 88-010, "Matts Licensees Lack of Mgt Controls Over Li-censed Programs." Svc list encl. CUNNINGHAM, R E Division of Industrial & Medical Nuclear Safety (Post 870729) 887 03/28. Consolidated Edison Co. of New York, Inc. 108pp. 44995:247-44995 353.
- 8804050020 Ack receipt of 880310 lit informing NRC of steps taken to correct violators noted in Insp. Repris 50-529/87-39, 50-529/87-39, 8-50-530/87-40
 KIRSCH.D.F. Region 5, Ofc of line Director, 88/03/28, VAN BRUNT, E.E. Anzona NJ clebi Power Project (formerly Arizona Public Service Co.). 1p. 45032.122 45932.124
- 8804190104 Forwards Special Team Insp Ropt 50:528/88:01 on 880104:0212 & notice of violation Number & types of problems noted is indicative of need for add & botts focused mgt stitentian to design-related activities MARTIN.J.B. Region 5:0fc of the Director. 88/03/30. VAN BRUNT,E.E. Arizona Nuclear Power Project (formetly Arizona Public Service Co.). 6pp 45198:320-45197:025
- ~8804190112 Notice of violation from insp on 880104-0212.Violation noted contrary to American Air Filter Co Drawing MC-134-942G Rov Glaccess door was missing to motor driven auxiliary feedwater pump room air handling unit. MARTINJB. Region 5, Otc of the Director. 88/03/20. Spp. 45196-326-46196.331
- --8804190113 Insp. Rept. 50-528/88-01 on 880104-0212 Violations noted Major areas inspected engineering maint, surveillance testing, operations & OA & administration. MENDONCA, M., PARKHILL, R., NARBUT, P. Region 5, Otc. of the Director, 88/03/30, 54pp. 45198-332-45197-025.
- 8804190164 Forwards Insp. Repts 50.528/88-08,50.529/88-08 & 50.530/89-00 on 880223-24,29 & 0301-03 & notice of violation.

 WENSLAWSKI,F.A. Region 5, Otc of the Director, 88/03/30, VAN BRUNT,E.E. Arzona Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 45209-198-
- --8804190157 Notice of violation from insp on 880224-26 & 0229-0303. Violations noted.gamma emitter analysis of gas grab sample from Waste Gas Decay Tank B did not achieve required lower limit of detection for Kr-87, Kr-88 & Xe-138. WENSLAWSKI,F A Region 5, Ofc of the Director. 88/03/30. 2pp. 45209:193
- --8804190160 Insp Repts 50.528/88-08,50.529/88-08 & 50.530/88-05 on 880223-24 & 0229-0303. Violation noted Major areas inspected. OA for rad ochemical analyses, chemistry control & analysis, onsite followup of items & plant tours. TENBROCK,W.K., YUHAS,G.P., Region 5, Old of the Director, 88/03/30. 6pp 45209.200-45209:207.
- 8804190162 Forwards Insp. Repts. 50-528/88-02;50-529/88-02. & 50-530/88-02 on 880117-0305 Enforcement action re violations will be subj of separate (fir. KIRSCH, D.F. Region 5, Otc. of the Director. 88/04/01 VAN BRUNT E.E. Arizona Nuclear Power Project (formarly Arizona Public Service Co.). 3pp. 45196:294-45196:314
- -8804190164 Insp Repls 50-528/88-02:50-529/88-02 & 50-530/68-02 on 880117-0305 No violations noted Major areas inspected review of prant eclivities.plant tours housekeeping surveillance testing & essential cooling pump room alarms. POLICH, T., BALLJ., FIORELLI,G. Region 5, Otc of the Director. 88/04/01. 18pp. 45196-297.45196-39. 45196-207-45196:314
- 8804200488 Forwards corrected pages to Meeting Repts 50-528/88-11, 50-528/88-11 & 50-530/88-11. FAULKENBERRY, B. Region 5, Old of the Director, 88/04/01, VAN BRUNT, E.E., Anzona Nuclear Power Profect (formerly Arizona Public Service Co.). 1p. 45239-088
- -8804200505 Corrected Pages 1 & 5 to Enforcement Conference Repts 50-528/88-11 EC, 50-529/88-11 EC, 8 50-530/88-11 EC, * Region 5, Old of the Director, 88/04/01, 3pp. 45239,089-45239.091.
- 8804130088 Forwards Insp Repts 50-528/87-45,50-529/87-44 & 50-530/87-43 on POPULATION PROPERTY OF THE PRO
- --8804130098 Insp. Repts 50.528/87-45,50-529/87-44 & 50.530/87-43 on 871109-13 No violations noted Major areas inspected util OA program particularly in areas of 10CFR21 reportability requirements & control of purchased mails & svcs. PRESCOTT,P. Division of Reactor Inspection & Safeguards (Post 870411). STONEJ. Vendor Inspection Branch. 88/03/22. 9pp 45102:020-45102.028.
- 8804130372 Discusses i£ Into Bulletin 88:001, "Defects in Westinghouse Circuit Breakers." Units 1 & 2 Insps found no breakers w/ defects & Unit 3 reactor trip breakers in commercial operation for 4 months, VAN BRIVIT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Serv.ce Co.), 88/04/06. Document Control Branch (Document Control Desk) 5pp. 45:192:226-45.1929.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Due to Faulty Tie Bolts." Svc list enct. ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407:051.
- 8804190010 EN-88-029 on 880413 notice of proposed imposition of civil penalty in amount of \$100,000 will be issued to licensee, based on violation of requirements re improper engineering & review & failure to follow procedures LUEHMAN,J. LIEBERMAN,J. Ofc of Enforcement (Post 870413). 88/04/08. 1p. 45199,075-45199.075.

- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc.
- list and. ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/04/12. Consolidated Edison Co. of Now York, Inc. 123pp. 45165-026-45165-150
- 8804200108 Discussos insps on 880127-29 & 0117-0305 & forwards notice of violation & proposed imposition of civil penalty. Encourages utili to increase mg: attention on personnel performance to ensure clear understanding of fundamenta's WARTIN,J B. Region 5, Oic of the Director, 88/04/13 VAN BRUNT,E.E. Arizona Nu-clear Power Project (formerly Arizona Public Service Co.), 4pp. 45215-300-45215:308.
- -8804200112 Notice of violation & proposed imposition of civil penalty in amount of \$50,000 Violation noted plant operated w/only two operable independent steem generator aux liary teedwater pumps w/o meeting Tech Spec action requirements MARTIN, J.B. Region 5, Ofc of the Director 88/04/13 5pp. 45215304.45215308.

R. Periodic operating reports & related correspondence

8804220055 Monthly operating repts for Mar 1988 W7880415 ftr COLVILLE,J.M., HULL,J.L., HAYNES,J.G. Arizona Nuclear Power Project (formerly Ali-zona Public Servico Co.). 88/03/31. 19pp. 45231:200-45231.218

S. Reportable occurrences, LERs & related correspondence

- 8803310049 Summarizes LER numbers utilized for 1987 reporting period VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.), 88703724 Document Control Branch (Document Control Desk) 1p. 44984:135-44964.135
- 8804060158 LEH 68-004-00 on 880229,Mode 4 entered w/HPSI injection pumps inoporable.Caused by procedural inadequacy Procedure revised to include staps to ensure that HPSI pumps returned to operable status prior to entering Mode 4 W/ BR0330 IIr. BR0330 IIr. SHRIVER,T D., HAYNES,J.G. Arizona Nucloar Power Project (formerly Arizona Public Service Co.) 88/03/30 Spp. 45947.071.45047.075.
- 6804120437 Special Rept 1-SR-88-003:on 880304,output breaker on diosel generator 8 did not close properly during surveillance testing Cause undetermined Evaluation Independent of determine cause of improper breaker operation.

 HAYNES-J.G. Arzona Nuclear Power Project (formorly Arizona Public Service Co.)

 88704704. Document Central Branch (Document Central Desk). 3pp. 45091:021-45091

45091.023

- 8804140143 Special Ropt 1-SR-88-002 on 880314,72 h Lmit for returning containment area importor to six exceeded Cause undotermined. Containment area importor RU-149 not returned to operable status pending evaluation of data. HAYNES,J.G. Arizona Nuclear Power Project (formerly Arizona Public Sorvice Co.). 88/04/08, Document Control Branch (Document Control Desk). 2pp. 45183:110-45183:111.
- 8604180445 LER 87-025-02 on 871127 turbine driven auxiliary feedwater pump did not achieve rated speed during monthly operability aurvoillance tost Caused by valves roluming to operable status contrary to Toch Spoc 3.6 3.W/880412 ltr. SHRIVER,T.D., HAYIES,J.C. Arzona Nuclear Power Project (formerly Anzona Public Servico Co.). 88/04/12 βpp. 45196.240-45196.247.
- 8804190029 Special Rept 1-SR-88-004:on 880407, loos o part dotection instrumentation declared inoperable for more than 30 days. Caused by breakup of signal coming from sensor Work control document prepared & will be schedured for next outage. HAYNES.J.G. Arizona Nuclear Power Project (formerly Arizona Public Servico Co.). 88/04/12. Document Control Branch (Document Control Dask). 2pp. 45208:161-45208:162.
- 8804200301 LER 88-002-00 on 880122,HI log power trips sot contrary to Tech Spec Table 2.2 1.Error discovered 880317.Ceuse under Investigation.Trip sotpoints con-servatively reset.W/880410 ltr. SHRIVER,T.D., HAYNES,J.C. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 88/04/18. 6pp. 45239:110-45239:114
- 8804210311 Corrected LER 88-002:00 on 880122 preliminary calculations indicated that high log trip scholms may have been set contrary to allowable scipp int.Cause still under invostigation.Trip sciplonter sector W/880418 fir. SHRIVER,T.D., HAYNES,J.C. Artzona Nuclear Power Project (formerly Arizona Public Service Co.). 88/04/18. 5pp. 45235/304-45235/308.

8804260007 LER 88-008-00 on 860320, survoillance interval for incore detector sys axceeded. Caused by cognitive personnel error & inadequate programmatic controls individual involved will be counseled &/or disciplined & controls reviewed. W/

SHRIVER, T.D., HAYNES, J.G. Arizona Nuclear Power Project (formarly Arizona Public Service Co.). 68/04/16. 6pp. 45268 355-45258 360.

V. Operator Examinations

- 8804250068 Responds to FOIA request for infoire scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets listed in encl. app w/personal privacy into deleted. GRIMSLEY.DH. Division of Rulos & Records (Post 870413) 86/04/19. BOLEY,K. Public Citizon's Critical Mass Energy Project. 2pp. 45213:003-45213:095.
- -8804250167 Package of NRC administered requalification exam results summary.
 NRC No Detailed Athlation Given, 87/07/20, 88pp. 45213,007-45213 095

DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8804150263 Forwards rosults & conclusions of regulatory offectiveness review on 880223-0302.Response re identified weakness requested within 45 days of itr receipt Encis withheld (ref. 10CFR73.21).
CRUTCHFIELDD. Division of Reactor Projects - III,IV,V & Special Projects (Post B70411), 88/04/12 VAN BRUNT,E.E. Arrona Nuclear Power Project (formerly Anzona Public Service Co.), 4ρp. 45192-270-45192-273.

- 8804220264 Ack rectipt of encl. JG Haynes 880317 ltr raiscope & objectives for 1808 annual emergency preparedness exercise. Certain demsion objectives hist clarified per 880407 taticon between G Brown & H Bieling Scope & objectives acceptable FISH, H. Region 5, Otc of the Director, 8670475, VAN BRUNTE, E. Arzona Nuclear Power Project (formerly Auzona Public Service Co.), 2pp. 45257 186-46257,205
- --8804220255 Forwards, for ray ew & comment, draft objectives & extent of play for 1968 ut annual emergency plan exercise scheduled for 880808 Oreft submitted per NRC 830803 In ut I & ut I Administrative Control Magnual Except On HAYNESJIG Aircone Nuclear Power Project (formerly Aircone Public Service Co) 89/03/17 MARTIN J.B. Region 5, Ofc of the Director, 8pp. 45257-198-45257 205

J. Insurance & indemnity information

8804060463 Usis present level of financial protection for plantiper 10CFR50.54(w)(4) VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.) 88703724. Document Control Branch (Document Control Dosk). 1p. 45010.214-

P. Operating license stage documents & correspondence

- 8804010251 Forwards Vo's I-III of CEN-368(V). "Reciprocating Charging Pump Test Rept" & CEN-370(V), "Charging Pump Gas Binding & Cracked Block Evaluation Rept." per Condition 3 s of License NPF-51 & 851129 commutment. VAN BRUNT,E.E. Anzona Nuclear Power Project (formerly Anzona Public Scruco Co.), 88703/02 Document Control Branch (Document Control Cesk), 2pp. 45015-191-45016-19.
- --8804010257 "Charging Pump Gas Binding & Cracked Block Evaluation Repli"
 * Combustion Engineering, Inc. CEN-370(V). 88/02/29 62pp 45015-183-45015-255
- --8804010259 Vols I-III of "Red-procesting Charging Pump Test Rept."
 Combustion Engineering, Inc. CEN-369(V), 86/02/29, 277pp, 45015-258-45016-172.
- 8803300130 Application for amonds to Liconsos NPF-41,NPF-51 & NPF-74, rowsing Surveillance Requirement 4.6.2.h to change total injection loop flow to 4,800 gpm & injection leg max devial on to 200 gpm.

 VAN BRUNT,E.E. Anzona Nuclear Power Project (formerly Anzona Public Service Co.), 88/03/18. Document Control Branch (Document Control Desk), 7pp. 44981-314-44981-36.
- 44961:326. --8803300133 Proposed Tech Specs, revising Surveillance Requirement 4.5.2.h to change total injection loop flow to 4,800 gpm & injection leg max deviation to 200

Arizona Nuclear Power Project (formerly Arizona Public Servicu Co.), 68/03/16. 6pp. 44961.321-44961;326.

- 8803300116 Application for amends to Licenses NPF-41,NPF-51 & NPF-74, adding trense condition for reactor coolant pump vibration monitoring program VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Survice Co.), 88703/18. Decument Control Branch (Document Control Desk), 7pp. 44961 225-44961 237.
- --8803300123 Proposed Tech Specs adding Idense condition for reactor coofant pump vibration monitoring program,
 * Arizona Nuclear Power Project (formerly Arizona Public Service Co.) 68/03/18, 6pp
 - 44981-232.44081-237
- 8803240426 Goneric Ltr 88:06 to all power reactor I-censees & applicants to removal of organization charts from Tech Spec administrative control requirements Svc fist end MIRAGLIA,F.J. Associate Director for Projects (Post 870411), 88/03/22 Conscideled Edison Co. of New York, Inc. 47pp. 44972:107-44972:153
- 8804040128 Forwards revised pages of FSAR re OA program. Change will enhance op-eration & availability of radwaste rigit sys by providing practical approach to procure-ment & installation of renomical instrumentation & sampling components. VAN BRUNT,E.E. Arizona Nuclear Power Project (formorly Arizona Public Service Co.), 68/03/24. Document Control Branch (Document Control Desk) 7pp. 44970 258-44970 262.
- 8804050097 Provides proposed changes to previously acceptable commitments re-reactor coolant pump shall valual monitoring program,including reducing number of required monitoring channels per pump from 2 to 1.

 LICITRA,E.A. Project Directorate V. 88/03/25. VAN BRUNT,E.E. Arizona Nuclear Pawer Project (formedly Arizona Public Service Co.). 4pp. 46029:158-45029:159

- 8804080465 Informs that util will respond to NRC 680223 request for additinte re-sponse to General Lit 68-06 by 680830. VAN BRUNTLE E. Anzona Nuclear Power Project (formerly Arizona Public Serv.co Co.), 88/03/28, Document Control Branch (Document Control Cests), 2pp. 45974:150-
- 8804070002 Updates status of scram reduction program. Program being extended to fully utilize balance of plant simulation model to evaluate Category 2 scram initiators. Category 3 initiators eliminated from further review.

 VAN SRUNTLE. Airzona Nuclear Power Project (formerly Anzona Public Senice Co.), 88/03/28, Document Control Branch (Document Control Drisk). 2pp. 45048-284-45048:285.
- 8804130360 Application for amends to Liconses NPF-41,NPF-51 & NPF-74, changing monitoring requirements for hydrogen & oxygen in waste gas holdup sys. Fee paid. VAN BRUNT,E.E. Arizona Nuclear Power Project (formetly Arizona Public Servica Co.), 88/104/06, Document Control Branch (Document Control Desk) 8pp. 45146.341-
- --8604130363 Proposed Tech Specs modifying requirements for hydrogen & oxygen waste gas holdup sys.

 Arizona Nuclear Power Project (formerly Arizona Public Sqivice Co.), 88/04/06, 9pp.
 45146:348-45146:357.

- 8804130368 Application for amends to Lincenses NPF-41,NPF-51 8 NPF-74, allowing use of liver roots or vacancies in fuel basembles. Fee paid VAN BRUNTEE. Anzona Truclear Power Project (formerly Anzona Public Service Co.) 68764708 Document Control Branch (Document Control Desk). Spp. 45151.050-45151.050
- 45151 060 -8804130369 Proposed Tech Specs,allowing use of filter rods or vacancies in fuel as
 - sembles Anzona Nuclea: Power Project (formerly Anzona Public Service Co.). 88/04/08. 3pp. 45151-058-45151-060
- 8804150130 Notification of 880414 meeting w/ut I & BNL in Rocky, le.MD to discuss vibration monitoring program for reactor coolant pump shalfs & status on plant shalt earliest ons Agenda end LICHTHAE A Project Directorate V 68/04/03 KNIGHTON,G W Project Directorate V 5pp 45133332-45133336
- 8804210437 Forwards notice of consideration of issuance of amends to Licenses NPF-41 NPF-51 & NPF-74 & proposed NSFIC determination & opportunity for hearing on 630408 request reidesign description of fuel assembles LICHTRA EA Project Directorate V. 88703/1/3 VAN SRUNTLEE Anzona Nuclear Power Project (Jornally Anzona Public Service Co.) 3pp. 45191-160-45191-169
- -8804200500 Notice of consideration of issuance of amends to Eucenses NPF-41 NPF-51 & NPF-74 & proposed NSHC determination & opportunity for hearing Amends revise Tech Specs to design description of fuel assembles LICHTAN, E.A. Project Directorate V 68/04/13 7pp 45191 183-45191.169
- 8804280561 Forwards safety exalusion supporting out natural circulation cooldown capability Tost results combined w/ supporting analysis demonstrate that plant meets requirements of BTP RSB 5.1 for Class 2 plant LICHTPA EA. Project Directorate VI 68704/18 VAN BRUNTLE E. Arzona Nuclear Power Project (formerly Arzona Public Service Co.). 4pp. 45268 353-45266 359
- -8804280571 Safety evaluation rejut1 natural circulation cooldown capability Plant meets requirements of BTP RSB 5-1 for Class 2 plant 1. NAC No Detailed Athation Given, 88704718, 3pp. 45266,357-45266,359.

Q. Inspection reports, IE Bulletins & correspondence

- 8884040083 Forwards Enforcement Conference Repis 50:528/88-11, 50:529/88-11 8 50 S00/88-11 on E00229 Concerns summarized. Actions described to improve utiliza-tion of simulator 8 to more closely follow backing of maint items found positive MARTIN J.B. Region S. Ot coll the Director 680/03/18 VAN BRUNT, E. P. Arizona Nu-clear Power Project ("officerly Arizona Public Service Co.). 3pp. 449/1.251.44971.288
- -8804040090 Enforcement Conference Repts 50:528/68:11,50:529/89:11 & 50:530/ 69:11 on 860220 Major areas discussed/licensee inadvertient rendering of steam dimenially half feedward pumps in Units 1 & 2 inoportable RICHARDS,S.A. Region 5, Ofic of the Director 88/03/18 34pp 44971:254-
- 8804060501 Forwards Insp. Repris 50:526/88.09.50.529/88.09.8.50.530/88.09. on 650222.25.8.0229.0333 No vicilators noted WENSLAWSKIF A. Region 5, Old of the Director, 88/03/22. VAN BRUNT,E.E. Anzona Nuclear Power Project (former), Arizona Public Service Co.). 2pp. 45010.280-45010.298
- -8804060509 tosp Repts 50-528788-03-50-529788-09-& 50-530788-03-on-880222-25-& 0229 0303 No violations or deviations noted. Major areas inspected fransportation maintaining occupational exposures ALARA & radiation moni-
- toring sys NORTH, H.S., YUHAS,G.P. Region 5, Ofc at the Director 88/03/22, 7pp, 45010, 292-
- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thimble Tube Thinning in Westing-house Reactions" Size list encl ROSSICE To Protion of Operational Events Assessment (Post 870411) 88/03/28 Conscitated Edison Co. of New York, Inc. 121pp. 44995 126-44995 246
- 8803220296 NRC Info Notice 88:010. Matts ticensess tack of Mgt Controls Over Li-censed Programs 1 Stoll stienci CUNN NGHAM RE Division of Industrial & Medical Nuclear Salety (Post 870729) 887 03728 Consolidated Edison Co
- 8804050020 Ack receipt of 880310 fit informing NRC of steps taken to correct violations noted in linsp Repts 50 528/87-39 50-529/87-39 & 50-530/87-40 KIRSCHLD F Region 5, Otto of the Director 880/37/28 VAN BRUNTLE E, Arizona Nacidear Power Project (formerly Arizona Public Service Co.) in 45032/122-45032/145
- 8804 190154 Forwards Insp. Repts. 50.528 / 88 · 08.50.529
- ~8804190157 Notice of violation from insp on 880224-26 & 0229.0303 Violations noted garminal emitter analysis of gas grab sample from Waste Gas Dacay Tank B d d not achieve required lower limit of detection for Kr-87 Kr 88 & Xe-138.

 WENSLAWSKIFA Region 5, Otc of the Director 88/03/30, 2pp 45209.198-
- ~8804190160 Insp Repts 50.528/88-08.50.529/88-08-8-50.530/88-05-on-880223-24-& 0229-0303 Violation indied Major areas inspected. OA for tadicchemical analyses chemistry control & analyses, on site to lowup of tierns & plant fours TENBROCK, W.K. YUMAS,G.P. Region 5, Otc of the Director 88/03/30 8pp. 45209-200-45209-207
- 8804190162 Forwards Insp. Repts. 50-528/88.02.50-529/88.02.8-50-500/88-02 on 880117-0305 Enforcement action re-violations will be subj. of separate fit. KriRSCH.D.F. Region 5. Ofc. of the Orector. 88/04/01. VAN BRUNT,6 E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 3pp. 45196-234-45196-314

- -8804190164 Insp. Hepts 50.528788 62.50.529788 02.60.0005 No. worstons inspected review of plant acts tours, howevering surveillance testing 8 essential county pump rechains POLICHUT, BALLIU, FIORELLIG Region 5, Otc. of the Durictor 68/04/645196 287-45196-314
- 8804200468 Ferwards corrected pages to Meeting Repts 50-528/88-11, 50 s
- 8 50 530 98-11 FAULKENBERRY B. Rugion S. Old of the Director 88784701 VAN 99th 1.5 na. Nuclear Power Project (forming Anzona Public Service Co.) ip 4 45233 091
- --8804209505 Corrected Pages 1 & 5 to Enforcement Conference Repis 59 (EC.50 529/89-11 EC & 50/530/88-11 EC
 - Region 5, Old of the Director 88/04/01 3pp 45239 089-45239 091
- 8804130086 Forwards Insp. Repts 50.528787.45.50:529787.44 & 59.559 871109-13 No violations coled Howover due to several unusual evensapy repair of such magnitude requires more comprehensive review of parts to CRUTCHETE, D.D. Duvision of Nusulo Projects NUNV & Special Pro-8704111 88704705 VAN BRUNT, E.E. Anzorin Nuclear Power Project from an Exit Severa Co. Ser. 4510-2115-45102-328 na Public Service Co) 5pp 45102 015-45102 028
- Vendor Inspection Branch, 88/03/22, 9pp. 45102 020 45102 028
- 8804130372 Discusses IE Into Bulletin 88 001, "Defects in Westinghouse Caters" Units 1 & 2 inspectiound no tircakers w/ defects & Unit 3 readic topic commercial operation for 4 months VAN BRUNT,F.E. Arizona Nictear Power Project (formerly Arizona Pul/Co.) 8804709 Document Centrol Branch (Document Centrol Desk) 5pp. 4 45192 230
- 8804010256 NRC Info Notico 88 011, "Potential Loss of Motor Centrol Crist board Function Due to Faulty Tio Brits." Svc list onc! ROSSLC E. División of Operational Events Assessment (Post 670411) Consolidated Edison Co. of New York. Inc. 124pp. 45406 292-45407 051
- 8804190010 EN 88-029 on 880413, notice of proposed imposition of estiamount of \$100,000 wit he issued to accessed, tristed on violation of requiring appar angineoring & review & future to follow procedures LUFHMAN, LIEBERMAN, Otc. of Enforcement (Post 870413) 68/6-45199.075-45190.075
- 8804060370 NRC Into Natina 88-012, "Overgrassing of Electric Motor Bear ROSSICE Division of Operational Events Assessment (Post 870411) Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165-150
- 8804200108 Discussos insps on 880127-29 & 0117-0305 & forwards not tell & proposed imposition of civil ponally Encourages tall to increase mgl a personnal performance to on-size clear encourages and to increase mgl a personnal performance to on-size clear encouraged and AVAP IN UNITED AND THE Proposition of the property of t
- --8804200112 Notice of violation & proposed imposition of civil penalty in \$50,000 Wiglation noted plant operated wiznity two operation intepercent crafts aroundary feetwater pumps who medius) tech Specialtics action reg

R. Periodic operating reports & related correspondence

- 8804220055 Monthly operating repts for Mar 1988 W/880415 ltr. COLVILLE, J.M., HULL, J.L., HAYNES, J.G., Arizona, Nuclear Power Project (*) zona Public Service Cn.). 88/03/31, 19pp. 45231, 200-45231, 218
- S. Reportable occurrences, LERs & related correspondence
- 8803310049 Summarizes LER numbers utilized for 1987 reporting period VAN BRUNT, E. Anzona Nuclear Power Project (formerly Autora Put Co.) 8803/24. Document Control Branch (Cocument Control Desk) 19 44964.135
- 8804060478 Special Repl 2-SR-88-001 on 880311,rad oactive gaseous efform HU-144 & RU-143 rendered inoperable for greater than 72 h Caused by replacing of components to correct high voltage failure HAYNES, IG Arizona Nuclear Power Project (formerly Arizona Public S 88/04/05. Document Control Branch (Document Control Desk) 309-45092-046
- 8804130036 LER 87-021-01.on 871202 post-accirlont sampling sylinoperable Caused by personnul arror Appropriate functional & surveit-antipleted & sys decalled operatio-W/ 880407 ltr SHRIVER,T.D., HAYNES,J.C., Arrora Nuclear Power Project (formerly An Service Co.), 88/04/07, 6pp. 45151-022-45151:027
- 8804190033 LER 88-008-00 on 880319.balance-of-plant ESF actual on occu-bidg essential ventilation sys Train A. Caused by radiation levels incre-atam/trip scippini for monitor RU-131 Scippini raised W7880407 ftr SHRIVER.T.D., HAYNES, JG., Arrona Nuclear Power Project (formerly Ar Service Co.) 88/04/07, 6pp. 45208-207-45208-217.
- 8804140106 LER 88-005-01 on 880221 inadvertiont safety injection from satianks accurred as result of low pressuraer pressure signals not be bypassed Caused by personnol error. Disciplinary measures taken W re604 SHRIVER, L.D., HAYNESJ G. Arzona Nuclear Power Project (formerly Ar Service Co.) 88/04/08 5pp 45151.357-45151.361

V. Operator Examinations

- 8804250088 Responds to FOIA request for infoiro scores of reactor operators & senior reactor operators Forwards requal-lication exam summary source sheets listed in enclupp w/pcrsenal privacy infoideceted GRIMSLEY,O H. Division of Rives & Records (Post 870413) 88/04/19 BOLEY,K Fublic Critical Mass Energy Project 2pp 45213-003-45213-095
- --8804250167 Package of NRC administered requalification examinesu. Is summary
 NRC No Detailed Affication Given 87/07/20 88pp 45213-037 45213-095

DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

- 8804150283 Forwards results & conclusions of regulatory effectiveness review on 890223-0302 Response re-identified weakness requested within 45 days of lit receipt Encis withheld (ref 10CFR73-21)
 - RECEPTER MAINTENER (16) 10C-17/3/21)
 CRUTCHFIELD D. Division of Reactor Projects + 111,1V,V & Special Projects (Post 8/70411) 88/04/12. VAN BRUNT, E.E. Arizona Nuclear Power Project (formerly Arizonal Victor) na Public Scryice Co) 4pp 45192 270 45192.273.
- 8804220254 Ack recoipt of encl JG Haynes 680317 ltr re scope & objectives for 1988 504320234 ACK recognition entoring registrations of the Scope at Objectives for 1996 annual emergency proparedness overcise. Cortain idems on objectives its claimled per 880407 recon between G Brown & H Bieling Scope & objectives acceptable. FISHLR, Region 5, Office of the Chector. 88/04/15 VAN BRUNT, E.E. Arizenia Nuclear Power Project (formerly Arizona Public Service Co.). 2pp. 45257 196-45257 205.
- -8804220255 Forwards, for review & comment draft objectives & extent of play for 1988 util annual emergency plan exercise scheduled for 880606 Draft submitted per NRC 830803 fir did & util Administrative Control Manual Ex HAYNESJG Anzona Nuclear Power Project (formuly Anzona Public Service Co.) 89/03/17 MARTIN.J.B. Region 5, Ofc of the Director Bpp. 45257.198-45257.205

J. Insurance & Indemnity Information

- 8804060463 Lists present level of linancial protection for plant.pdr 10CFR50.54(w)[4] VAN BHUNTEE Arizona Nuclear Power Project (formerly Arizona Public Service Co.) 88/03/24 Document Control Branch (Document Control Desk) 1p 45010.214-45010214
- P. Operating license stage documents & correspondence
- 8804010251 Forwards Vols Hill of CEN-369(V), "Rec-proceding Charging Pump Test Rept" & CEN-376(V), "Charging Pump Gas Binding & Cracked Block Evaluation Rept." per Condition 3 a of Licenso NPF-51 & 851129 commitment VAN BHANT, E. Anzona Nuclear Power Project (formerly Anzona Public Service Co.) 88703702 Document Control Branch (Document Control Desk) 2pp 45015 191-
- --8804010257 "Charging Pump Gas Blinding & Cracked Block Evaluation Rept"

 * Combustion Engineering, Inc. CEN-370IV) 88/02/29 62pp 45015 183-45015 255
- --8804010259 Vols I-lif of "Reciprocating Charging Pump Tost Ropt."
 Combustion Engineering, Inc. CEN-369(V) 88/02/29 277pp, 45015 256-45016 172
- 8803300130 Application for amonds to Licenses NPF-41,NPF-51 & NPF-74, revising Surveillance Regularement 4.5.2 h to change total injection loop flow to 4,000 gpm & rigid on tog max deviation to 200 gpm & YAN BRUNT, E. Anzona Nuclear Power Project (formerly Arrzena Public Service Co.) 88703/16 Document Control Branch (Document Control Dosk), 7pp. 44961-314-4561-3205.
- --8803300133 Proposed Tech Specs,rovising Surveillance Requirement 4.5.2 hi to change total injection loop flow to 4,800 gpm & injection log max doviation to 200
- Gpm Arizona Nuclear Power Project (formariy Arizona Public Service Co.) 88/03/16 6pp 44961 321-44961 326
- 8804040062 Provides justification for deletion of loss of offsite power (LOP) test as supplite 870831 submitted re-mod of initial test program. Reasons that LOP test not conducted at greater than 10% power stated YAN 8RUNT, E. E. Arzona Nuclear Power Project (formerly Anzona Public Service Co.) 88/03/17 Document Control Branch (Document Control Desk) 33pp
- 44969 037-44969 069
- 8803300116 Application for amends to Uccenses NPF-41,NPF-51 & NPF-74, adding li-cense condition for reactor coolant pump vibration monitoring program VAN_BRUNI_EE Airzona Nuclear Power Project (formerly Anzona Public Servicu Co.), 88703/18. Document Control Branch (Document Control Desk) 7pp 44961 225-
- --8803300123 Proposed Tech Specs adding license condition for reactor coolant pump vibration monitoring program
 Arizona Nuclear Power Project (formerly Arizona Public Service Co.) 88/03/18 8pp
- 44961 232-44961 237.
- 8803240426 Generic Lir 88-06 to all power reactor ficensees & applicants re removal of organization charts from Tech Spec administrative control requirements Svc I st encl. MiRAGLIAF J. Associate Director for Projects (Post 870411), 88/03/22. Consolidated Edison Co. of New York, Inc. 47pp. 44972-107-44972. 153.
- 8804040128 Forwards revised pages of FSAR to OA program Chango will enhance operation & availability of radwaste mgt sys by providing practical approach to procure-ment & installation of nonclinear instrumentation & sampling components VAN BRUNT & E. Anzona Nuclear Power Project (formerly Arizona Public Servica Co.) 88/03/24 | Document Control Branch (Document Control Desk.) 7pp. 44970.256-44970 262.
- B804050097 Provides proposed changes to previously acceptable commitments re-reac-tor coolant pump shalt vibration monitoring program, including rectucing number of re-quired monitoring channels per pump from 2 to 1 LICHTRAE A Project Directorate V. B8703725. VAN BRUNT, E.E. Anzona Nuclear Power Project (formatly Arizona Public Servica Co.), 4pp. 45029,156-45029 159.

- 8804060465 Informs that unit will respond to NRC 880223 request for addition or response to General thirds-of-by-886630 VAN BRUNT, E.E. Anzonal Nuclear Power Project (formerly Anzonal Public Service Co.) 88703728 Document Control Branch (Document Centrol Bosh), 2pp. 45074 150-
- 8804070002 Updates status of scram reduction program Program being extended to fully sittle balance-of-plant simulation model to evaluate Category 2 scram interes. Category 3 intrators even nation from further review WAN BRUNT, E.E. Anxiona, Nuclear, Power Project (formerly Anxiona, Public Service Co.) 88703/28 Document Centro Branch (Document Centro) Dock. 2pp. 45048-284-
 - 45048 285
- 8804130360 Application for amenus to Licenses NPF-41,NPF-51 & NPF-74, changing moralding requirements for hydrogen & oxygen in waste gas holdup sys. Fee paid VAN BRUNT, E.E. Arizona Nuclear Power Project (formarly Arizona Public Schwie Co.) 89/04/06 Document Centrol Branch (Choumant Centrol Desk). 8pp. 45146,341-45146,357.
- --8804130363 Proposed Tech Specs, modifying requirements for hydrogen & oxygen * Anzona Nucrear Power Project (formerly Anzona Public Service Co.) 88/04/66 9pp 45146.349.45146.357
- 8804150023 Forwards Hev 0 to "Palo Verde Nuclear Generating Station, Unit 3 Station Rept." Rept contains test results of fuol load,post-core that functional testing-initial criticality 8 low power physics testing 8 power ascens on testing.
 VAN BRUNT, E.E. Anzona, Nuclear, Power, Project (Icimority Anzona, Public Service Co.), 88/04/06, Document Control Branch (Document Control Desk), 1p. 45153 (20-4), 62-43.
- --8804150026 Rev 0 to "Pala Verde Nuclear Generating Statisch,Unit 3 Startup Rept." 1 Autoba Nuclear Power Project (formerly Arizona Public Service Co.) 88704/06 92pp 45153 121-45153 212
- 8804080088 Gonero Ltr 88.07 to power reactor Leonsees & applicants no modified en loccement policy concerning 1005f18649. "Environ Quartication of Electrical Equip-ment Important to Safety for Nuclear Power Plants." Svenst and MIRAGLANF J. Associate Director for Projects (Post 8704.11), 88704707. Consolidated Edison Co. of New York, Inc. 49pp. 45164 237-45164-285.
- 8604130351 Application for amond to License NPF-74 changing Tech Specs to increase negative moderator temp coefficient lumit Fee pard.

 VAN BRUNT,E E. Arizona Nuclea: Power Project (formerly Arizona Public Service Co.) BB/04/07. Document Control Branch (Document Control Desk). 5pp. 45142:167-
- --8804130355 Proposed Tech Spec Figure 3.1-1, "Allowable MTC Modins 1 & 2, Palo Verdo Unit 3.Cyclo 1 Average Moderator Temp"

 * Anizona Nuclear Power Project (formedly Anizona Public Service Co.) 88/04/07 1p 45142 172-45142 172.
- 8804130368 Application for amonds to Eucerises NPF-41,NPF-51 & NPF-74, allowing use of filter rids of vacancies in fuel assemblies. Fee paid VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.) 88704708 Deciment Control Branch (Document Control Desk). Epp. 45151.053-
- -8804130369 Proposed Tech Specs, allowing use of lifter rods or vacancies in fuel assembles.
 * Anzena Nuclear Power Project (formerly Anzena Public Service Co.): 88/64/68.3pp.
- 45151.058-45151.060
- 8804150130 Natification of 880414 moeting w/util 8 BNE in Rockvillo MD to discuss vi bration monitoring program for reactor coolent pump shafts & status on plant shaft evaluations Agenda and LICITRA,E A Project Directorate V 88/04/09 KNIGHTON,G W Project Directorate V 5pp 45133 332 45133 336
- 8804210437 Forwards notice of consideration of assuance of anient's to Licerises NPF-41.NPF-51 & NPF-74 & proposed NSHC determination & opportunity for hoaning on 890408 request to description of fluor assemblies LICTITRAE & Project Oroctorate V 88744/13 VAV 9RUNT.E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Coli 3pp. 45191/160-45191/169.
- -8804200500 Notice of consideration of tissuance of amonds to Licensos NPF-41,NPF-51 & NPF-74 & proposed NSFC (determination & opportunity for hearing Amends rovise Tech Specs to dos go description of fuel assembles. LICITEA,E A Project Directorate V, 88/04/13 7pp 45191 163-45191 169.
- 8804280561 Forwards safety evirtual on supporting util natural circulation cooldown capability. Test results combined w/ supporting analysis demonstrate that plant moets requirements of BTP RSB 5-1 for Crass 2 plant. ICC
- --8804280571 Salety evaluation re util natural circulation ecoldown capability Plant meets requirements of BTP RSB 5-1 for Class 2 plant
 * NRC No Detailed Africation Given, 88/04/18 3pp. 45266 357-45266 359

O. Inspection reports, IE Bulletins & correspondence

- 8804040083 Forwards Enforcement Conforence Repts 50-528/88-11, 50-529/88-11 3-50-530/88-11 on 880229 Concorns summarized. Actions described to improve utilization of simulator & to more closely follow backleg of maint items found positive MARTIN, J.B. Region 5, Otto of the Director, 88/03/18 VATS BRUNT, E.E. Arizona Nuclear Power Project (termarky Arizona Public Service Co.), 3pp. 44971-251-44971-288
- --8804040090 Enforcement Conference Repts 50-528/88-11,50-529/88-11 & 50-530/ 88-11 on 880229 Major areas discussor licensee inadvortent rendering of stoam driven auxiliary feedwater pumps in Units 1 & 2 irroporable RICHARDS,SIA Hegon 5, Ofc of the Director, 88/03/18 34pp. 44971:254-4421. 44971.288

- 8804060501 Forwards Insp Repts 50.528/88-09.50.529/88-09.8 50.530/88-09 on 880222-25.8 0229-0303 No violeitons noted.
 WENSLAWSKI,F.A. Region 5, Obt oil the Director, 88/03/22 VAN BRUNT,E.E. Arizona Nudgar Power Project (formerly Anzona Public Service Co.). 2pp. 45010-290-
- --8804050509 Insp Ropts 50-528/88 09,50-529/88-09 & 50-530/88-09 on 980222-25 & 0229 0303 No violations or deviations noted Major areas inspected transportation,maintaining occupational exposures ALARA & radiation monitoring sys. NORTH,H S., YUHAS,G P. Region 5, Ofc of the Director, 88/03/22, 7pp. 45010 292-45010 298.
- 8803210090 Suppl 1 to NRC Into Notice 87:044, "Thimble Tube Thinning in Westinghouse Reactors," Svc fist enc!. ROSSI.C E. Division of Operational Events Assessment (Post 870411), 88/03/28. Consolidated Edison Co. of New York, Inc. 121pp. 44995;126-44995;246.
- 8803220296 NRC Info Notice 88-010, "Matts Licensees.Lack of Mgt Controls Over Li-8032/2029 NAC Hild Holder Station, Mislis Cabacter Selety (Post 870729), 887 CUNNINGHAM,R E Division of Industrial & Medical Nuclear Selety (Post 870729), 887 03728. Consolidated Edison Co. of New York, Inc. 108pp. 44995;247-44995;353.
- 8804050020 Ack receipt of 880310 ftr informing NRC of steps taken to correct violations noted in finsp Repts 50-529/87-39, 50-529/87-39 & 50-530/87-40. KIRSCH,D.F. Region 5, Old of the Director, 88/03/28, VAN BRUNT,E.E. Arizona Nuclear Power Project (formetly Arizona Public Service Co.). 1p. 45032.122-45032:124.
- 8804190154 Forwards Insp Repls 50-528/88-08.50-529/88-08 & 50-530/88-08 on B80223-24.29 & 0301-03 & notice of violation.
 WENSLAWSKI,F.A. Region 5, Olc of the Director. 88/03/30. VAN BRUNT,E.E. Arizona Nicelear Power Project (formerly Arizona Public Service Co.). 2pp. 46208:196-45209:207.
- --8804190160 Insp. Repts 50-528/88-08.50-529/88-08. \$ 50-530/88-05 on 880223-24 & 0229-0303 Violation noted Major areas inspected: QA for radiochemical analyses, chemistry control & analysis, onsite followup of items & plant tours. TEINBROK,W.K., YUHAS,G.P. Region 5, Ofc of the Director. 88/03/30. 8pp. 45209 200-45209.207.
- 8804190162 Forwards Insp. Repts 50-528/88-02.60-529/88-02 8 50-530/88-02 on 880117-0305.Enforcement action re violations will be subj. of separate lir. KIRSCH.D.F. Region 5, Old of the Director. 88/04/01, VAN BRUNT.E.E. Arizona Nuclear Power Project (formetly Arizona Public Service Co.). 3pp. 45198:294-45198:314.
- --8804190164 Insp Repts 60-526/88-02,60-529/88-02 & 50-530/88-02 on 880117-0305 No violations noted Major areas inspected review of plant activities, plant fours housekeeping survoillance tosting & essential cooling pump room elarms. POLICHT, BALLJ, FIORELLI,G. Region 5, Otc of the Director. 88/04/01. 18pp. 45196 297-45196 314.
- 8804200468 Forwards corrected pages to Meeting Repts 50-528/68-11, 50-529/88-11 & 50-530/88-11.
 FAULKENBERRY, 6. Reg on 5, Old oil the Director, 88/04/01, VAN BRUNT, E.E. Arizona, Miclear Power Project (formerly Arizona Public Service Co.). 1p. 45239.088-
- 45239,091.
- --8804200505 Corrected Pages 1 & 5 to Enforcement Conference Repts 50-528/88-11 EC,50-529/88-11 EC & 50-530/88-11 EC.

 * Reg on 5, Ofc of the Director, 88/04/01, 3pp. 45239.089-45239.081.
- 8804130088 Forwards Insp Repts 50-528/87-45.50-529/87-44 & 50-530/87-43 on 671109-13 No violations noted However, due to several unusual events, apparent that repair of such magnitude requires more comprehensive review of parts to be reused CRUTCHFIELD,D. Division of Reactor Projects (III)/LV & Special Projects (Post 870411), 86/04/05, VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.), 5pp. 45102.015-45102:028.
- --8804130098 Insp. Repts 60-528/87-45,50-529/87-44 & 50-530/87-43 on 871109-13.No violations noted Major areas Inspected util QA program particularly in areas of 10CFR21 reportability requirements & control of purchased matis & svcs. PRESCOTT,P. Division of Reactor Inspection & Safeguards (Post 870411). STONE,J. Vendor Inspection Branch. 89/03/22. 9pp. 45102.020-45102.028.
- 8804130372 Discusses IE Info Bulletin 88-001, "Defects In Westinghouse Circuit Breakers." Units 1 & 2 Insps found no breakers w/ defects & Unit 3 reactor trip breakers in commercial operation for 4 months.

 VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.). 88/04/06. Document Control Branch (Document Control Deak). 5pp. 45192:226-45192.230.
- 8804010256 NRC Info Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switch-board Function Oue to Faulty Tie Boils." Svo list encl. ROSSI,C E. Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406:292-45407:051.
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc list enct. ROSSI.C E. Division of Operational Events Assessment (Post 670411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45186:028-45165;150.
- R. Periodic operating reports & related correspondence
- .8804220055 Monthly operating repts for Mer 1998.W/680415 ftr, COLVILLE J.M., HULL J.L., HAYNES J.G. Arizona Nuclear Power zona Public Service Co.). 88/03/31, 19pp. 45231:200-45231:218. wer Project (formerly Ari-
- S. Reportable occurrences, LERs & related correspondence
- 8803310049 Summarizes LER numbers utilized for 1987 reporting period.

 VAN BRUNT,E.E. Arizona Nuclear Power Project (formerly Arizona Public Service Co.), 88/03/24. Document Control Branch (Document Control Desk), 1p. 44984;135-44984-135

8804210329 Special Rept 3-SH-88-002 on 880328 radiation monitoring unit incrorable for greater than 72 h due to unsatisfactory performance of source check Caused by excessive high voltage from faulty high voltage board Detector replaced. HAYNES_J.G. Arizona Nuclear Power Project (formerly Arizona Public Service Co) 88704/18. Document Control Branch (Document Control Desk). 2pp. 45235353-45235310.

V. Operator Examinations

- 8804250088 Responds to FOIA request for into re-scores of reactor operators & senior reactor operators. Forwards requalification exam summary source sheets listed in and app w/personal privacy into deleted.

 GRIMSLEY D.H. Division of Rules & Records (Post 870413) BB/04/19. BCLEY,K Public Citizen's Critical Mass Energy Project. 2pp. 45213 003-45213 095.
- --8804250167 Package of NRC administered requal/fication exam results summary.
 NRC No Detailed Alfification Given, 87/07/20, 88pp. 45213:007-45213:095

DOCKET 60-537 CLINCH RIVER BREEDER REACTOR

A. Application/construction stage documents & correspondence

- 8803240426 Generic Ltr 88-96 to all power reactor licensees & applicants renominal of organization charts from Tech Spec administrative control requirements. Svc "strong MIRAGLIAF.J. Associate Director for Projects (Post 870411), 88/03/22. Consolidate Edison Co. of New York, Inc. 47pp. 44972:107-44972:153.
- 8804080088 Generic Ltr 88:07 to power reactor licensees & applicants re modified en-forcement policy concerning 10CFR60.49, "Environ Qualification of Electrica! Equip-ment Important to Safety for Nuclear Power Plants." Svc list encl. MIRAGLIA.F.J. Associate Director for Projects (Post 870411), 88/04/07. Consol dated Edison Co. of New York, Inc. 49pp. 45164:237-45164:285.

DOCKET 50-538 MEMPHIS STATE UNIV. RESEARCH REACTOR

P. Operating license stage documents & correspondence

- 8803250248 Informs of NRC relocation to stated address Mailing address unchanged A Adams project manager & TS Michaels back-up project manager. RUBENSTEINLES. Standardization & Non-Power Reactor Project Directorate 68/03/18. Affiliation Not Assigned. 3pp. 44859.080-44859.082.
- 8804120140 Forwards final survey rept indicating that residual radioactivity readings less than in Reg Guide 1.86,Table 1 & less than 5 uR/h at 1 meter.Requests final survey of facility to verify reg guide requirements.W/o encl.
 RUBENSTEINL.S. Standardization & Non-Power Reactor Project Directorato 68/04/05. COLLINS.D.M. Region 2, Ofc of the Director. 2pp. 45091:360-45091:361.

DOCKET 50-601 RESAR SP/90

A. Application/construction stage documents & correspondence

- 8804080016 Forwards proprietary draft SER re PRA for Westinghouse RESAR SP/90.Open issues noted which may or may not be resolvable during preliminary design approval stage of review.Draft SER withhold (ref 10CFR2.790).
 RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate 88/03/21, JOHNSON,W.J. Westinghouse Electric Corp. 3pp. 45064:357-45064:359.
- 8803290356 Forwards nonproprietary & proprietary Into on Amend 1 to RESAR-SP/90 PDA Module 12, "Waste Mgt" & 880322 application for withholding proprietary in'o from public disclosure per 10CFR2.790(b)(1). JOHNSON,W.J. Westinghouse Electric Corp. 88/03/22. RUBENSTEIN,L. Standardization & Non-Power Reactor Project Directorate. 2pp. 44982:044-44962.064.
- --8803280358 Application for withholding proprietary Amend 1 to RESAR-SP/93 PDA Module 12, "Waste Mgt," from public disclosure per 100FR2 780(b)(1). WIESEMANN,R.A. Westinghouse Electric Corp. 86/03/22. RUBEN/STEIN,L. Stendardization & Non-Power Reactor Project Directorate. 19pp. 44962:046-44962 064.
- 8604010131 Forwards proprietary & nonproprietary Amend 2 to RESAR-SP/90 PDA Module 2, "Regulatory Conformance." Proprietary version withheld (ref 10CFR2.790) JOHNSON,W.J. Westinghouse Electric Corp. 88/03/23. RUBENSTEIN,L. Standard zation & Non-Power Reactor Project Directorate, 2pp. 45020-244-45020:264.
- --8804010133 Requests that proprietary Amend 2 to RESAR-SP/90 PDA Modulo 2. "Regulatory Conformance" be withheld from public disclosure (ref 10CFR2.790). WIESEMANN,R.A. Westinghouse Electric Corp. 88/03/23. Standardization & Non-Power Reactor Project Directorate. 19pp. 45020:248-45020:264.
- 8804070238 Forwards nonproprietary & proprietary Amend 2 to RESAR-SP/90 PDA Module 13, "Auxillary Sys." Proprietary amend withheld (ref. 10CFFI2,790). JOHNSON,W.J. Westinghouse Electric Corp. 88/03/24, RUBENSTEIN,L. Standard zation & Non-Power Reactor Project Directorate. 2pp. 45031:013-45031:052.
- --8804070243 Requests that encl proprietary Amend 2 to RESAR-SP/90 PDA Modu'o 13, "Auxiliary Sys," be withheld (ref 10CFR2 790). WIESEMANN, R.A. Westinghouse Electric Corp. 88/03/24. RUBENSTEIN,L. Standard-ization & Non-Power Reactor Project Directorate. 38pp. 45031:016-45031:052.
- 8804220166 Forwards proprietary & nonproprietary versions of 880406 presentation of RESAR-SP/90-PDA Probabilistic Salety Study (Module 18).

 JOHNSON,W.J. Westinghouse Electric Corp. 88/04/04. RUBENSTEIN.L. Standard-valion & Non-Power Reactor Project Directorate. 2pp. 46280:272-45281:032.

209

- --8804220191 Requests withholding proprietary version of Westinghouse 880406 presentation of SP/90 PRA to ACRS Subcommittee on Westinghouse Advanced Plants (ref 10CFR2:790(b)(1)). Affidavit & nonproprietary version of presentation enci. WIESEMANN,R.A. Westinghouse Effecting Corp. 88/04/04. PUBENSTEINL: Standardization & Non-Power Reactor Project Directorate. 119pp. 45280.274-45281.032
- 8804190116 Notification of 880421 meeting w/Westinghouse in Rockville,MD to discuss concerns resulting from review of reactor sys of RESAR SP790. KENYON,TJ. Stendardization & Non-Power Reactor Project Directorate 88/04/13. RUBENSTEIN,L.S. Stendardization & Non-Power Reactor Project Directorate, 2pp. 45164:300-45164:301.

8804200460 Forwards request for addit info re RESAR SP/90.Resolvability of issues during PDA phase of review concluded Meeting between NRC & Westinghouse to discuss & resolve issues prior to issuance of linal SER proposed. KENYON,T J. Standardization & Non-Power Reactor Project Directorate. 88/04/14. JOHNSON,W.J. Westinghouse Electric Corp. 7pp. 45191:119-46191:125.

8904200493 Forwards rev to 870619 review schodule for RESAR SP/80, adjusting dates for remaining intermediate milestones. Issuance of final SER & PDA decision in Oct 1988 & by Dec 1988 still intended.

RUBENSTEIN, L.S. Standardization & Non-Power Reactor Project Directorate. 88/04/14. JOHNSON,W.J. Westinghouse Electric Corp. 4pp. 45191:012-45191:015.

8804220016 Forwards request for additinfo on RESAR SP/90 re radiological consequences of design basis accident to complete review. Response requested within 30 days of fit date.

KENYON, T.J. Standardization & Non-Power Reactor Project Directorate. 88/04/14.

JOHNSON,W.J. Westinghouse Electric Corp. 4pp. 45201:047-45201:050.

8804220024 Requests draft SER discussing acceptability of applicable design-specific resolutions of listed generic Issues no later than 880516. RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate. 88/04/14. CHENG,C.Y. Materials Engineering Branch. MARSH,T. Mechanical Engineering Branch. BAGCHI,G. Structural & Geosciences Branch. 4pp. 45200.276-45200.279.

8804280334 Summary of 880331 meeting w/BNL & Westinghouse in Monroeville,PA to discuss PRA for RESAR SP/90.List of attendees & agenda followed during meeting

BRC, KENYON,T.J. Standardization & Non-Power Reactor Project Directorate, 88/04/21, Standardization & Non-Power Reactor Project Directorate, 6pp. 45265:117-45265:122

DOCKET 50-802 UNIV. OF TEXAS RESEARCH REACTOR

A. Application/construction stage documents & correspondence

6803250248 Informs of NRC relocation to stated address Mailing address unchanged. A Adams project manager & TS Michaels back-up project manager. RUBENSTEINLS. Standardization & Non-Power Reactor Project Directorate. 88/03/ 18. Affiliation Not Assigned. 3pp. 44859:060-44859:062

F. Security, medical, emergency & fire protection plans

- 8803310127 Forwards Insp Repts 50-192/88-01 & 50-802/88-01 on 880209-10 & notice of violation.
 CALLAN,L J. Region 4, Ofc of the Director. 88/03/24. KLEIN,D.E. Texas, Univ. of, Austin, TX. 2pp. 44976:120-44976:129.
- -8903310134 Insp. Repts 60-192/88-01 & 50-802/88-01 on 880209-10. Violations noted Major areas inspected review & audit, experiments health physics, emergency plan organization logs & records procedures & requalification training. PICK,G.A. Region 4, Ofc of the Director. 88/03/14. 8pp. 44978:124-44978:129.

Q. Inspection reports, IE Bulletins & correspondence

- 8803310127 Forwards Insp Repts 50 192/88-01 & 50-802/88-01 on 880209-10 & notice of violation.

 CALLAN, L.J. Region 4, Ofc of the Offector, 88/03/24, KLEIN, D.E. Texas, Univ. of, Austin, TX. 2pp. 44976:120-44976:129.
- --8803310134 insp Repts 50-192/68-01 & 50-802/88-01 on 880209-10. Violations noted Major areas inspected review & audit, experiments health physics emergency plan organization logs a records procedures & requalification training. PICK,G.A. VICKREY,R.B., GAGLIARDO.J.E. Region 4, Ofc of the Director. 88/03/14. 6pp. 44978:124-44978:129.

V. Operator Examinations

- 8803310127 Forwards Insp Repts 50-192/88-01 & 50-602/68-01 on 880209-10 & notice of violation.
 CALLAN,L.J. Region 4, Ofc of the Director. 88/03/24. KLEIN,D.E. Texas, Univ. of, Austin, TX 2pp. 44976:120-44976:129.
- --\$803310134 Insp Repts 50-192/88-01 & 50-802/88-01 on 880208-10. Violations noted Major areas inspected review & audit, experiments, health physics, emergency plan organization, logs & records, procedures & requalification training. PICK,G.A. Region 4, Oto of the Director. 88/03/14, 5pp. 44976:124-44976:129.

DOCKET 50-603 ALCHEMIE CENTRIFUGE ENRICHMENT PLANT

A. Application/construction stage documents & correspondence

8904110254 Requests addl into re disposal of centrifuge machines in order to complete review re application for CP & OL.Info should be signed by DOE. CLARIK.A.Y. Fuel Cycle Safety Branch. 88/04/04, PFEIPER,W.A. All Chemical Isotope Enrichment, Inc. 1p. 45076;357-45078;357.

F. Security, medical, emergency & fire protection plans

8804250242 Forwards Section 19.0 of Rov 1 to security plan Title changed from "Non-profileration Conficts" to "Sateguards " Enct withhold per 10CFR2.780(d) BELL, D. L. All Chemical Isotope Enrichment, Inc. 88/04/14, THOMPSON, H.L. Office of Nuclear Material Safety & Safeguards,Orector. 2pp. 46213 163-45213.163.

M. Antitrust correspondence

8804060220 Forwards into in response to Mar 1988 inquiry re supplemental anti-trust info Encl supplements DOJ review of DOE surplus equipment to Archem'E. BELLO.L. All Chemical Isotope Errichment, Inc. 68/03/22, ThOMPSON

DOCKET 50-804 ALCHEMIE CENTRIFUGE ENRICHMENT PLANT

A. Application/construction stage documents & correspondence

- 8804110157 Responds to NRC 880323 request for addl into re licensee request for ex-emption from requirement of obtaining CP prior to starting constractivities on tempo-rary storage area Ltr from town of Oliver Springs confirming development and: BELL,D.L. All Chemical Isotope Errichment, Inc. 88/03/31, THOMPSON.H.L. Office of Nuclear Material Safety & Safeguards,Director. 2pp. 45071:310-45071:313.
- --8804110171 Responds to 880323 lir re issue of industrial park All Chemical Isotope Enrichment,inc commitment to locate facility in industrial park largest to date 5 to selected by AlChemiE w.ii be developed independent of decisions ELLIOT (I.H.L. Oliver Springs, Th. 88703/30, CLARK,A.T. NRC No Detailed Alfillation Givon, 1p. 45071;312-45071;313
- 8804110254 Requests addl into re disposal of centrifuge machines in order to complete roview re application for CP & OL Info should be signed by DOE. CLARK A.T. Fuel Cyclo Sately Branch. 88704704 PFEIFER.W.A. All Chemical Isotopo Enrichment, Inc. 1p. 45078 357-45078 359.

F. Security, medical, emergency & fire protection plans

8804280339 Forwards Roy 1 to Section 19.0 of security plan, incorporating DOE requirements in Rept K/197180, "Rept of Special Team on Conceptual Safeguards & Security Plan tor Pending Operation of CPDF." Encl withhald (ref 10CFR2,790) BELL,D.L. All Chemical Isotopo Enrichment, Inc. 88/04/14, THOMPSON,41 L. Office of Nuclear Material Safety & Safeguards,Director, 2pp. 45232:261-45232.261.

M. Aniltrust correspondence

8804050220 Forwards into in response to Mar 1988 inquiry re supplemental anti-trust into Enct supplements DQJ review of DQE surplus equipment to Atchemie. BELL,DL. All Chemical Isotope Enrichment, Inc. 88/03/22. THOMPSON

DOCKET STN-50-606 GE ADVANCED BWB DESIGN

A. Application/construction stage documents & correspondence

- 8804080396 Requests support in resolution of matter of log to be incurred by GE in certification of advanced BWRGE concerns would be resolved at Commission would confirm that review & fee both capped at present level & deterred WOLFE,B. General Electric Co. 88/03/24. ZECH,L.W. Commissioners. 3pp. 45008
- 8804050408 Advises that into on advanced BWR fuel design in Chapter 4 of supplemental SAR will be withheld from public disclosure (ref 10CFR2.790),per 870929 re-

quest. SCALETTI.D.C. Standardization & Non-Power Reactor Project Directorate. 88/03/29. ARTIGAS,R. General Electric Co. 2pp. 45029:177-45029:178.

8804110232 Submits daily highlight Informs of DOE plan to support GE in providing bat-ance of plant scope for advanced BWR.per Chairman request during 880128 Commis-

slon meeting SCALETTI,DC Standard-zation & Non-Power Reactor Project Directorate 88/04/01, MURLEY,T, SNIEZEKJ, MIRAGLIA,F, NRC - No Detailed Affiliation Given. 2pp 45078:393-45078.334.

K. Utility Final Safety Analysis Report (FSAR) & amends

8803310018 Forwards Rev A to Amend 1 to Chapters 1,2 & 3 of 23A6100AC, "Advanced BWR SSAR." Replacement of overhead HPCS sparger w/high pressure (flooder spargers initiated w/encl.Chapters 4,5,8 & 15 to be updated when 7-9 & 11-13 submitted.

submittee. ARTIGAS,R. General Efectric Co. 88/03/28. RUBENSTEIN,L. Standardization & Non-Power Reactor Project Directorate. 2pp. 44953:260-44955:192.

--8803310029 Rev A to Amend 1 to Chapters 1-3, "Advanced BWR SSAR, * General Electric Co. 20A6100AC, 88/03/29, 850pp, 44953:262-44955; 192.

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0008 BATTELLE MEMORIAL INSTITUTE, COLUMBUS, OH

8804280181 Discusses 21 planned shipments of radwaste between 880420- 1231 Shipments should be similar, except for variation in total curie quantity in each shipment, EMSWILER.T.R. Battelle Memortal Institute, Columbus Laboratories. 88/04/07. DAVIS,A B. Region 3, Ofc of the Director, 2pp. 45261.304-45261:305.

DOCKET 76-0027 BABCOCK & WILCOX CO., LYNCHBURG, VA

- 8604010007 Forwards Insp Rept 70 0027/88-01 on 880125-27.No violations or deviations noted COLLINS.D.M. Rog on 2. Ofc of the Director 88/03/24 TETRAULT,R E. Babcock & Wilcox Co. 2pp. 45916 184-45016 192
- --8804010008 Insp Ropt 70-0027/88-01 on 880125-27 No violations & devations noted Major aroas inspected rail ation protection program areas including rail ation protection organization & staff changes & radioactive contamination control KUZO.GB. HOSEY,C.M. Region 2. Qfc of the Director 68/03/14 7pp 45616 186-45018 192.
- 8804010094 Oricussos Mgt Meeting Rept 70:0927/88:09 on 880128 Meeting beneficial & provided for better understanding of issues discussed Mooting summary,attendance Ist, performance improvement plan lost & stides and GRACE, J.N. Rogion 2, Ote of the Director 88/03/24. TETRAULT, R.E. Babcock & Wilcox Co. 67pp. 45020-162-45020-239
- --8804010095 "Performance Improvement Plan" THENT, R K. Babcock & Wilcox Co. 88/01/28, 11pp. 45020;229 45020 239.
- 8804120067 Forwards Insp Rept 70:0027/88-08 on 880216:19 & 0307-11 No violations or doviations noted CLINE: WE Region 2. Oto of the Director 88/03/29. TETRAULT,RIE Babcock & Wilcox Co 2pp 45132:156-45132:165
- -- 8804120086 Insp Rept 70 0027788 08 on 880216 19 & 0307-11 No violations or deviations noted Ma,or areas inspected incident response, facility operations, nuclear criticality safety, rediation protection, emergency preparedness 8 mail control LEE, T.D., MCALPINE, E.J. Region 2, Old of the Director 88/03/29 Gpp 45132 160-45132 165.
- 8804050098 Advises that temporary License Condition TCIMC&A) 2 to Arnerd SG-1 to License SNM-42 sever affective immediately, to read as stated, per 880314 request for examption from requirement that all tioms on inventory to measured.

 BURNETT, R.F. Dw.son of Sategoards & Transportation (Post 870413) 88/03/30 BOYD, C.C. Babcock & Wilcox Co. 1p. 45020 160 45029 160
- 8804120347 Responds to 871111 request for finited exemption from 10CFR70-58(i)(2) & License Condition 7.1 to stere two kg U-235 in contaminated of or organics indefinition 8 stere new License Condition 7.3 to Amond SG-11 to License ShiM-42. BUTINETT,R.F. Division of Saleguards & Transportation (Post 870413) 88/04/04 BOYD,C.C. Babcock & Wicox Co. 1p. 45101.007-45101.007.

DOCKET 70-0036 COMBUSTION ENGINEERING, INC., WINDSOR, CT

- 8804110085 Forwards application for amend to License SNM-33 to increase U-235 en-inchingni I mit to 5.0%. Foe paid ESKRUQGE,H.E. Combuston Engineering, Inc. 87/12/28. BIDINGER,G. Medical, Academic & Commorcial Uso Salety Branch, up. 45074-089-45071-119
- --8804110095 Application for amend to License SNM-33,increasing U-235 enrichment Combustion Engineering, Inc. 88/12/28, 30pp. 45071:090-45071:119.
- 8804140263 Forwards overview of present organizational structure of licensee nuclear fuel mlg operation, in charitation to 880202 organizational changes Partinent into of various ficonses also encil.

 SCHERERIAE: Combustion Engineering, Inc. 88/03/28, CUNNINGHAM, R.E. Office of Nuclear Material Safety & Safeguards, Director, 9pp. 45118-246-45118-254.
- 8804140062 Forwards draft agenda for 880414 meeting in Hematic par discussion to discuss 871228 license amend application to U enriched to 5 W/O U-235 BIDINGER,G.H. Fuel Cycle Safety Branch 88704703 SCHERER,A E. Combustion Engineering, Inc. 3pp. 45120 357-45120 359.

DOCKET 70-0135 BABCOCK & WILCOX CO., APOLLO, PA

- 8804050093 Forwards "B&W PA Nuclear Svc Operation Apollo Site Characterization Pran, Summary Rept, Offerto Survey Hosulle, Stanford Lumber Co Property." Review of offerte 8 acts that Area 1 moets critical for unrostricted use requested. CULUERSON, DG. Babrook & Wicox Co. 09/00/25, POUSEL. Office of Nuclear Matonal Safety & Safeguards, Director. 2pp. 45029:147-45029.155.
- Site Characterization
- 8804120408 Ack receipt of 880222 request that NRC conduct "cause & effect" studies of Apollo,PA area in order to determine relationships between health & safety problems in community & facility.News criticles encil. CONGET,F.J. Region 1, Oic of the Director, 88703/31 VIROSTEK,C Affiliation Not Assigned 7pp. 45080:345-45080.351.

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC., ERWIN, TN

- 8804190324 Forwards quarterly right on status of decommissioning activities that will be undertaken between 880101 & 901231, per 880316 Pu commissioning update most ng Related into Including well driling/const specs & agenda also encil LONG, J.A. Nuclear Fuot Services, Inc. (subs. of Getty Oil Co.) 88/04/07. ROUSE, L.C. Ovision of Industrial & Medical Nuclear Safety (Post 870729) 113pp. 45155301-45156-144
- --8804190402 "Hydrology Project Plan, Nuclear Fuel Svcs Facility, Erwin, TN."

 * GcoToch, Inc. * Nuclear Assurance Corp. 88/02/11, 90pp. 45156 056-45156:144.
- 8804080229 "Groundwater Monitoring 1987 Annual Summary NFS-Erwin" W/880328 III. LONG. J.A. Nuclear Fuet Services, Inc. (subs. of Getty Oil Co.): 87/12/31 GRACE. J.N. Roglon 2. Ofc of the Director, 22pp. 45048.103-45048:124.
- 8804250053 Forwards Insp Rept 70-0143/87-45 on 871213-18 No violations or deviations noted.

 CLINE, W.E. Region 2, Oic of the Director, 88/01/21, LONG, J.A. Nuclear Fuel Services, Inc. (subs. of Golly Oil Co.), 2pp. 45238 279-45238 281.

- --8804250056 Partially withhe'd Physical Security Insp Rept 70-0143/87-45 on 871213-18 No deviations noted Major areas inspected mot effectiveness security program auditions keys & access control Details withheld (ref. 10CFR95).
 THOMSOND H., MCGUIRE, D.R., Region 2, Ofc. of the Director, 88/01/20, 1p 45238 281-45238 281
- 8804060274 Forward Insp. Rept. 70-0143/88-09 on 880222-26 No. violations on dowations noted CLINE,WE. Region 2, Ofc of the Director 88/03/25, LCNG,J.A. Nuclear Fuel Services, Inc. (subs. of Gotty OTCo.), 2pp. 45046 109-45046 121
- -8804060278 Insp. Rept. 70-0143788-09 on 880222-26 No. violations or deviations. noted Major areas inspected operator training & retraining operations reviews & maint KASNICKI,D.A., MCAPLINE.E.J. Region 2, Old of the Director 88/83/25 +1p 45046:111-45046:121
- 8804060364 Forwards Insp Rept 70:0143/66:06 on 660216:19 No violations or devi ations noted.

 CLINE W E. Region 2, Ofc of the Director 88/03/25 LONG, J.A. Nuclear Firet Services, Inc. (subs. of Getty Cir. Co.). 2pp. 45076-043-45076-045
- -8804060368 Partially withheld Insp. Rept. 70:0143/88:06 on 880216:19 (ref. 10CFR95) No violations or deviations noted Major areas inspected security plan organization, records maint locks, barriers power supply lighting & assessment TORN, W.J., MCGUIRE, D.R. Region 2, Old of the Director, 88/03/21, 1p. 45076,045-
- 8904080365 Advises that listed changes should be made to radiological confingency plan Rev 5.submitted w/8804.12 ltr. KNIGHT.8 E. Nuclear Fuel Services, Inc. (subs. of Getty O.I. Co.). 88703/28 ROUSE,L.C. Fuel Cycle Safety Branch. 3pp. 45019.333-45019.335
- 8804080226 Ack receipt of 880318 ffr Informing NRC of steps taken to correct violations noted in Insp Rept 70-0143/87-42 GRACEJ N. Region 2, Ctc of the Oirector, 88/03/29 LONG,J.A. Nuclear Fuel Services, Inc. (subs. of Gelty Oil Co.) 1p. 45099 179-45099.179
- 8804080352 Forwards Insp Rept 70:0143/88:10 on 880229:0304 No violations or deviations noted.

 CLINE,W.E. Region 2, Old of the Director 88/04/04, LONG,J.A. Nuclear Firet Services, Inc. (Subs. of Getty OTCo.). 2pp. 45072.070-45072.072.
- --8804060355 Partially withhold Insp Hept 70-0143/88-10 on 880229 0304. No violations or deviations noted Major areas inspected measurement control & statistics. JONES.D.W., MCALPINE.E.J. Region 2, Ofciol the Director 88/04/04, 1p. 45072-072-45072 072
- 8804190005 Forwards Insp Rept 70-0143/88-11 on 880229-0304 & 14-25 No violations or deviations noted.
 CLINE.W.E. Region 2, Oic of the Director. 68/04/07 LONG.J A Nuclear Fuel Services, Inc. (subs. of Getty O.I.Co.). 2pp. 45196.261-45196.263
- -8804190006 Insp Rept 70:0143/88-11 on 880229:0304 & 14-25 No violations or dovi ations noted Major areas inspected previous insp findings tacility operations & nuclear criticality safety. Details withheld (ref. 10CFR2 790)

 LEET D. MCALPINE, E.J. Region 2. Old of the Director 88/04/07 1p. 45196 263-
- 8804200455 Trip rept of 880318 visit to Erwin,TN re decommissioning plan for Pullacility & groundwater monitoring program for decommissioning of pands List of attendees SOONG,S Fuel Cycle Safety Branch. 88/04/13. SWIFT,J.J. Fuel Cycle Safety Branch. 4pp. 45179:226-45179,229.
- 8804280293 Forwards Amend 2 to vendor escrow agreement per telcon LONG.J A. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 88/04/14. ROUSE,L Fuel Cycle Safety Branch, 5pp. 45265,108-45265 112
- 8804220067 Advises that Condition 29 of License SNM-124 amended to incorporate changes made to radiological contingency plan,in accordance w/880112 & 0328 request ROUSE, L.C. Fuet Cycle Safety Branch, 88/04/15, KNIGHT, B. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.), 2pp. 45201-083-45201-086.
- --8804220099 Safety evaluation re-licensee 680112 & 0328 submittat of changes to ra-diological contingency plan as required by License Condition 29 of license Recommonds issuance of license amend be granted SOONG.A.L. Fuel Cycle Safety Branch. 88/04/15. 1p 45201-085-45201.085.
- --8804220105 Discusses categorical exclusion for radiological contingency plan review of licenses 880112 & 0328 submitted of changes. Environ assessment or EIS univer-ROUSELL C. Fuel Cycle Safety Branch. 88/04/15. Fuel Cycle Safety Branch. 1p. 45201.086 45201.086
- 8804280508 Forwards hazardous waste notification form & hazardous waste streams repls for two waste streams generating mixed waste as defined by NRC/EPA guidelines.in response to DS Hate 880307 fit to BF. Knight. LONG, JA. Nuclear Fuel Services, Inc. (subs. of Gelty Oil Co.). 88/04/15. HALE, D Fennessee, State of. 9pp. 45271:045-45271:053.
- 8804290292 Ack receipt of 880303 ftr which transmitted Flov 113 to Section 4.0 of FNMCP.Review found change consistent w/ 10CHR70-32(c) & acceptable. CLINE,W.E. Region 2. Ofe of the Director, 88/04/21, LONG,J.A. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.), 1p. 45283-072-45283-072.
- 8804280641 Expresses appreciation for having meeting at facility on 880318 re-status of licensee angoing projects concerning decommissioning of holdings poinds & Pularcility Maeting beneficial & well organized firing rept encl.

 SOONG, Fuel Cycle Safety Branch, 88/04/25, KNIGHT, B. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.), 1p. 45263:291-45263:295.

DOCKET 70-0364 BABCOCK & WILCOX CO., APOLLO, PA

8804120408 Ack receipt of 880222 request that NRC conduct "cause & effect" studies of Apollo,PA area in order to determine relationships beliween health & safety prob-lems in community & facility News articles enci CONGELF J. Region 1, Ofc. of the Orector. 88/03/31. VIROSTEK.C. Affiliation Not Assigned 7pp. 45090.345-45090.351.

DOCKET 70-0371 UNC NAVAL PRODUCTS, INC., UNCASVILLE, CT

- 8804120363 Ack receipt of 870612 lit informing NRC of actions planned to observations 8 recommendations made during operational stately review BELLAMY,R R. Region 1, Otc of the Director 88/04/04 KAUFMAN,N.C. United Nu-
- -8804120373 Responds to NHC 870206 ltr re-violations noted in hisp Rept 70 03717 86-11 Recommendations for strengthering program addressed.

 KAUFMAN,N.C. United Nuclear Corp. (subs. of UNC Resources, Inc.) 87/08/12.

 MARTIN,T.T. Region 1, Old of the Director, 11pp. 45089-286-45089 296.
- 8804120263 Forwards Salety Insp 70-0371/88-02 on 880229-0318 Violations & unrosolved items identified Enforcement conference scheduled for 880419. CONGEL.F. J. Region 1, Old of the Director, 88/04/07, KAUFMAN,N, UNC Resources, Inc. 2pp. 45130.261-45130.278
- -8804120270 Insp Hopt 70-0371/88-02 on 880229-0318 Violations & unresolved Items noted.Major areas inspected ratifation protection program status of previously identi-tied items, ratiwaste mightraining & implementation LOESCH.R. GRESICK.J. THOMAS.W. Region 1, Ofc of the Director. 88/04/05 18pp 45130:263-45130:278
- 8804250197 Forwards Safeguards Insp Rept 70-0371/88-05 on 880321-25.No violations noted. BELLAMY,R.R. Region 1, Old of the Director, 88/04/18, KAUFMAN,N.C. United Nuclear Corp. (subs. of UNC Resources, Inc.). 2pp. 45254:176-45254:180.
- -8804250198 Insp Rept 70-0371/88-05 on 880321-25 No violations noted. Major areas inspected lacility operations internal controls & physical inventory. DELLA RATTA.A., KEIMIG.R.R. Region 1, Old of the Director. 88/04/15, 3pp. 45254 178 45254 180

DOCKET 70-0600 SEATTLE UNIV., SEATTLE, WA

8804040113 Safety insp on 880314 of License SNM-589 Insp findings no violations Region 5, Ofc of the Director. * Seattle Univ., Seattle, WA. 88/03/14. 1p 44970 359 44970 359

DOCKET 70-0687 CINTICHEM, INC., TUXEDO, NY

- 8804080159 Advisos that 871109 & 880217 rovs to physical security plan consistent w/ 10CFR50 54(p) & 70 32(e) & acceptable. Hevs withheld (ref 10CFR73 21) BELLAMY, R.R. Region 1, Otc of the Director. 88/03/31. MCGOVERN, J.J. Cintichem. Inc. 2pp. 45099 130-45099 131.
- 8804250188 Ack receipt of 871221 litrinforming NRC of steps taken to correct violations noted in Insp Rept 70-0687/87-04. CONGEL,F.J. Region 1, Old of the Director, 88/04/16, MCGOVERN,J.J. Cintichem, Inc. 2pp. 45239:184-45239.193.

DOCKET 70-0734 GA TECHNOLOGIES, INC., SAN DIEGO, CA

- 8804290055 Advises that fee required for 871221 application for amond to License SNM-696 W/o stated encl. JACKSON,G. License Fee Management Branch 88/02/04. ASMUSSEN,K.E. GA Technologies, Inc./General Atomic Co. 1p. 45322:282-45322.285.
- -8804290051 Application for amend to License SNM-606, exempting NRC licensed reactor operators from religioning requirements of license Fee paid.

 ASMUSSEN,K.E. GA Technologies, Inc./Goneral Atomic Co. 87/12/21, HOUSE,L.C. Fuel Cycle Safety Branch. 3pp. 45322-283-45322-285.
- 8804110107 Application for amend to License SNM-896,changing company name to General Atomics Fee paid
 ASMUSSEN.K.E. GA Technologies, Inc /General Atomic Co. 88/03/09. ROUSE,L.C. Fuel Cycle Safety Branch. 2pp. 45078:273-45078.274.
- 8804040112 Forwards Safety Insp Rept 70-0734/88-02 on 880222-28 & notice of viola-
- NONTGOMERY, J.L. Hegion 5, Old of the Dwoctor, 88/03/17, RADEMACHER, R.N. GA Technologies, Inc./General Atomic Co. 2pp. 44972.001-44972.019.
- --8804040115 Notice of violation from Insp on 880222-26. Violation noted: required inventories for health physics van.containing essential emergency response equipment not conducted since Sept 1987 & equipment not secured to provent piller-
- ing MONTGOMERY.J.L. Region 5. Otc of the Director 88/03/17. 2pp. 44872.003-
- -8804040118 Safety Insp. Rept. 70-0734/88-02 on 880222-26 Violation noted. Major areas. Inspected mgt. organization. & controls, criticality safety, operations review, radiation profession. Iransportation of radioactive matis & environ programs, BROCK, BL., PRENDERGAST.K., THOMAS,R.D., Region 5, Ofc of the Director, 887-03/16. 15pp. 44972-005-44972-019.
- 8804110088 Application for amend to License SNM-698 authorizing change of company name to General Atomics 8 revising three pages of license which were affected by name change.

 ASMUSSEN,K.E. GA Technologies, Inc./General Atomic Co. 88/03/22. RQUSE,L.C. Fuel Cycle Salety Branch. /pp. 45071:120-45071:128

- 8804150089 Ack receipt of 880128 ftr transmitting change to GA Category II & III physical protection plan & informs that changes acceptable. Encl to licenses its withheld (ref. 10CFR2 790).
- MONTGOMERY, J.L. Crinco of Nuclear Material Salety & Safeguards, Director, 887637 30 ASMUSSEN, K.E. GA Technologies, Inc. (General Atomic Co., 2pp., 45133,222-
- 8804180176 Forwards Final Rept ORAU 88/C-129, "Followup Confirmatory Survey of Phase 1 Decommissioning Former Waste Processing Facility GA Technologies San Diego,CA."
 COTTEN,P.R. Oak Ridge National Laboratory FIN A-9076 88/04/13 THOMAS,B. Region 5, Olc of the Director. 2pp. 45149 164-45149 196
- --8804180187 Final "Followup Confirmatory Survey of Phaso I Decommissioning Former Waste Processing Facility GA Technologies San Diego,CA" COTTEN/PR Oak Rindge Associated Univs FIN A-9076 ORAU 88/C-129 88/03/31 Region S, Otc of the Director, 31pp. 45149 188 45149 199
- 8804180456 Forwards trief rept, "Confirmatory Survey of Phase II Decommissioning Former Waste Processing Facility GA Co. San Diego, CA "
 COTTEN/LR Oak Ridge Associated Univs. 88/04/13, THOMAS,8 Region 5, Ofc of the Director 2pp. 45149 226-45149.292
- --8804180460 "Confirmatory Survey of Phase II Commissioning Former Waste Processing Facility GA Co.San Diago,CA." Enal rept. COTTEN,P.R. Oak Ridge Associated Univs. FIN A-9076 ORAU 88/C-44. 88/03/31 Region 5, Oto of the Director. 65pp. 45149 228-45149 292.
- 8804270227 Responds to AR0317 lit re-violation noted in Safety Insp Rept 70-734/89-
- 8804270037 Advises that 880311 change to Category I shutdown facility physical protection plan consistent w/provisions of 100CF R7032(o) & acceptable MIDNTGOMERIY.JI. Region 5, Oto of the Director 88704720 ASMUSSEN,K E. GA. Technologies, Inc./General Atomic Co. 1p. 45245 346, 45245 347.
- --8804270044 Discusses saleguards review reptire libenseo Category I shutdown facility physical protection plan rev Change considered cosmetric in nature & acceptable. NORDERHAUGLI RIRGGIN 5, Olicio the Director 88/04/20
- 8604270097 Ack roce ptiol 860311 ftrire changes to licensee Category (f. & fili physical protection plan Changes consistent w/ provisions of 10CFR70 32(e) & acceptable for inclusion into plan.

 MONTOGMERY J L. Region 5, Ofc of the Director, 88/04/20, ASMUSSEN,K.E. GA

Technologies, Inc /General Atomic Co. 1p. 45244 358-45244 359.

DOCKET 70-0754 GENERAL ELECTRIC CO., PLEASANTON, CA

- 8804080205 Requests confirmation of GE interpretation that License Condition 7.2.4 permits planned addition of depreted U to mall to reduce enterminate to 3.95% & ship U to SE Wilmington,NC facility.

 CUNNINGHAM G.E. Gengal Electric Co. 88/03/21, ROUSE,L.C. Fuel Cycle Salely Branch 8pp. 45076 188-45076
- 8804220029 Confirms that License Condition 7.2.4 of License SNM-960 covers blending activit os as proposod in 880028 ltr.
 ROUJSELC Fuel Cycle Safety Branch 88/04/15 CUNNINGHAM,G.E. General Electric Co. 1p. 45201:045-45201.046

DOCKET 70-0824 BABCOCK & WILCOX CO., LYNCHBURG, VA

- 8803280256 Forwards Insp. Rept. 70.0824/88-01 on 680203-05 No violations or deviations noted Rapt documents draft commitment made by liconsco representative COLLINS,D.M. Region 2, Otc. of the Director. 88/03/10. TRENT,L.K. Babtock & Wilcox Co. 2pp. 44921:131-44921:140.
- --8803280258 Insp. Rept. 70.0824/88-01 on 880223-05 No volations. & deviations noted Major eras inspected argas of redistron protection, solid westerngt transportation of red-active mails, following on previous enforcement Issues COLLINS.T.R., HOSEY,C.M. Hagian 2, Otc. of the Director. 88/03/07, 8pp. 44921 133-44921:140
- 8804140361 Forwards replacement pages for 871208 application for amond to Licenso SNM-778 reladd storage factify for waste generated in hot cods OLSEN, A.F. Babcock & Wilcox Co. 88/03/30 ROUSE, L.C. Division of Industrial & Medical Nucloar Safety (Post 870729), 13pp, 45130 001-45130-014
- 8804270279 Informs that elevated reading in cab of transport vehicle of 2.3 mR/hr de-lected during routine survey of truck delivering radioactive mail. Shipper was Duke Power Co.Occine Nuclear Station Ltnl 2 for shipment received on 880308 OLSENA F. Babcock & Wilcox Co. 88/04/08. Region 2, Otc of the Oirector 1p 45244:213-45244:213

DOCKET 70-0925 KERR-MCGEE NUCLEAR CORP., OKLAHOMA CITY, OK

- 8804010136 Forwards addl into re application for amend to License SNM-928 for onsite disposition of contaminated soil at Cimarron lactify.per NRC 871229 request Wione
- oversize traviling
 STAUTER.J.C. Sequeyah Fuels Corp. (subs. of Kerr McGee Nuclear Corp.) 88/03/21
 SWIFT.J.J. Office of Nuclear Material Safety & Safeguards,Director. 55pp. 44948-308-44948-002

DOCKET 70-1068 FLORIDA, UNIV. OF, GAINESVILLE, FL

8604280669 Application for amend to License SNM:1050,extending expiration for four months under storage only condutions established by Amend 5. VERNETSON,W.G. Flonda, Univ. of, Geinosville, FL. 88/03/28. NRC - No Detailed Atfiliation Given 3pp. 45322 201-45322 203

8804110305 Issues Amend 10 to License SNM-1050,authorizing movement of SPERT fuel for NDE testing purposes & changing storage location of SPERT fuel Dates of 880202 & 26 incorporated into Condition 8 & Conditions 12 & 13 added ROUSEL, C. Fuel Cycle Salary Branch. 88/04/05. VERNETSON,W.G. Flonda, Univ. of, Gainesville, FL. 1p. 45078.064-45078.092

--8804110314 SER re 880226 application for amend to Ucanso SNM-1050 authorizing movement of SPERT fuel rods for NDE testing purposes & changing storage location of fuelt issuance of amend recommended. MCCAUCHEY.D.A., SWIFT, J.J. Fuel Cycle Safety Branch. 68/04/05. 4pp. 45078-085-

DOCKET 70-1100 COMBUSTION ENGINEERING, INC., WINDSOR, CT

8804140263 Forwards overview of present organizational structure of licensee nuclear fuel mtg operation in clantication to 880202 organizational changes Pertinent into ot vanous licenses also encl.

SCHERER, A.E. Combustion Engineering, Inc. 88/03/29. CUNNINGHAM,R.E. Office of Nuclear Material Saloty & Safeguards, Director. 8pp. 45118 246-45118 254.

8804150157 Submits clarifications to 880202 fir re-organizational changes & appropriate communication channels between organizations Organizational chart & other pertinent

SCHERER, A.E. Combustion Engineering, Inc. 89/03/29, CUNNINGHAM, R.E. Division of Fuel Cycle, Medical, Academic & Commercial Use Safety 870413-870728, 10pp. 45134:349-45134:358.

8804120193 Forwards Safeguards Insp Rept 70-1100/88-04 on 880229-0304 No violations noted BELLAMY,R.R. Region 1, Ofc of the Director, 88/04/04, MCGILL,P. Combustion Engineering, Inc. 2pp. 45132.036-45132.042.

-8804120198 Insp. Repl. 70.1100/68-04 on 880229-0304.No violations noted. Major areas inspected nuclear matt control & accounting, including faculty operations & internal control & physical inventory.

DELLA RATTA,A, KEIMIG,R.R. Region 1, Otc of the Director. 88/04/01. 3pp. 45132:040-45132.042.

8804190341 Ack receipt of 870217 ftr informing NRC of steps taken to correct violations noted in Insp. 70-1100/86-04.

CONGEL, F.J. Region 1, Oic of the Director, 88/04/12, MCGiLL,P.L. Combustion Engineering, Inc. 2pp. 45225:269-45225:273.

-8804190342 Responds to NRC 870121 ltr re violations noted in Insp 70-1100/66-04 Corrective actions revs to maint test procedures implemented to require losting virgin powder area door for both line alarm & power failure condition. LICHTENBERGER Combustion Engineering, Inc. 87/02/17. MARTIN,T.T. Region 1, Orc of the Orector, 3pp. 46225:271-45225.273.

DOCKET 70-1113 GENERAL ELECTRIC CO., WILMINGTON, NO

8804110101 Application for amend to License SNM-1097, authorizing transfer of test quantities of carcium fluoride containing low level amounts of U to vendors for evaluation of potential usage Fee paid WINSLOW, T.P. General Electric Co. 88/03/21, ROUSE, L.C. Office of Nuclear Material

Safety & Safeguards, Director. 12pp. 45071:127-45071:139.

8804010097 Forwards Insp Rept 70-1113/88-02 on 880222-26.No violations or devi-

ations noted. CLINE.W.E. Region 2, Oic of the Director, 88/03/22 LEES,E.A. General Electric Co. 2pp. 45033 092-45033 095.

-8804010100 Partially withheld Insp. Rept. 70-1113/88-02 on 880222-26 (ref. 10CFR2.790(d) & 10CFR73.21).
BATES, J.W., MCALPINE, E.J. Region 2, Ofc of the Director. 88/03/22, 1p. 45033:094-

8804260112 Forwards Insp Rept 70-1113/68-05 on 880328-30 No violations or devi-

ations noted. CLINE.W.E. Region 2, Oic of the Oirector, 88/04/18, LEES,E.A. General Electric Co. 2pp. 45268-170-45266:173.

8804260113 Partially withhold Insp. Rept. 70-1113/88-05 on 880328-30 ref. (10CFR2.790(d) & 73.21).No violations or deviations noted.Allegation could not be

TOBIN,W.J., THOMPSON,D.H., DEMIRANDA,O. Region 2, Ofc of the Director. 88/04/ 15. 1p. 45268 172-45268 173.

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP., COLUMBIA, SC

8804280009 Forwards update of physical security plan for fuel mfg plant in Columbia, SC. Encl withheld (ref. 10CFR2,790(d)). NARDI,A. J. Westinghouse Electric Corp. 88/04/01, STOHR,J.P. Region 2, Ofc of the Director. 2pp. 45283-013-45283-014.

8804280015 Forwards rev updaling fundamental nuclear mail control plan for commer-cial nuclear fuel div fuel mfg plant located near Columbia, SC.Encl withhald (ref 10CFR2,790(d)). NARDI,A J. Washinghouse Electric Corp. 88/04/01. STOHR,J.P. Region 2, Ofc of the Director, 2pp. 45266:185-45266:186.

8904290287 Ack receipt of 880401 ltr transmitting Rev 11 to plant physical security plan. Changes found consistent w/provisions of 10CFR70.32 & acceptable for inclusion into plan.

CLINE,W.E. Region 2, Ofc of the Director. 88/04/28. LOCH,E.P. Westinghouse Electric Corp., 2pp. 45283:097-45283.098.

DOCKET 70-1201 BABCOCK & WILCOX CO., LYNCHBURG, VA

8804280146 Forwards application for renowal of License SNM-1168 for 10- yr period Listed documents not included w/renewal but incorporated by ref to address mail & accountability & physical security requirements Fee paid WATTERS.J.P. Babcock & Wilcox Co. 88/04/11. ROUSE, L.C. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 45264:106-45265-035.

-8604280149 Application for renewal of License SNM-1168 for 10-yr period.

Beboock & Wilcox Co. 88/04/11, 300pp. 45264:110-45265.035.

8803280227 Forwards Insp. Rept 70-1201/88-01 on 880201-03 & notice of violation. COLLINS.D.M. Region 2, Ofc of the Director. 88/03/08. ALTO,R.A. Babcock & Wrcox. Co. 2pp. 44921:119-44921:130.

-8803280233 Notice of violation from Insp on 880201-03 Violation noted: during penod of 871203-09 & 880129-0203, radiation levels at unrestricted area fence in vicinity of Bidg ECHO-330 1.0 & 0.7 m/h respectively. COLLINS,D.M. Region 2, Ofc of the Director, 88/02/08, 2pp. 44921;121-44921;122.

--8803280237 Insp. Rept. 70-1201/88-01 on 880201-03-Violation noted Major areas inspected areas of radiation protection program, solid radwaste mgt, transportation of radioactive matts. & IE Into notices.

COLLINS_T.R. H

8804080212 Responds to violations noted in Insp Rept 70-1201/88-01 on 880201-03 Corrective actions physical harrier (fence) installed on 880203 to increase distance of restricted area boundary from ECHO-330 bildg. ALTO,R.A. Bebcock & Wilcox Co. 89/03/26. STOHR,J.P. Region 2, Ofic of the Director. 3pp. 45116:270-45116:272.

8804190329 Forwards revised Page 28 to Section V of 880210 submittal re amend to License SNM-1168 to accommodate short term fuel assembly downloading activities at facility Rev based on concerns noted by NRC.
WATTERS,J.P. Babcock & Wilcox Co. 88/04/11. ROUSE,L.C. Fuel Cycle Safety Branch. 1p. 45164:359-45164:361.

~8604200235 Rev 3 to Section V,Page 28 of nuclear safety Tech Specs. *Bebcock & Wilcox Co. 88/04/11, 2pp. 45164:360-45164:361.

DOCKET 70-1257 ADVANCED NUCLEAR FUELS CORP., RICHLAND, WA

8804010143 Application for amend to License SNM-1227.updating desimetry requirements to place licensee in compliance w/rev to 10CFR20.202,to update safeguards rels, modify treatment of HEPA filter sys & correct typo in in vivo exam program. MALODY, CW. Advanced Nuclear Fuels Corp. (formerly Exxon Nuclear Co., Inc.), 88/02/26. ROUSE,L.C. Fuel Cycle Safety Branch. 8pp. 44949.010-44949.017.

DOCKET 70-1308 GENERAL ELECTRIC CO., SAN JOSE, CA

8804270323 "1887 Annual Rept." W/880407 ltr.
SCHMID,S.P. General Electric Co 87/12/31. CUNNINGHAM,R.E. Office of Nuclear Material Safety & Safeguards,Director. 64pp. 45263:104-45283:167.

8804150363 Provides into re fuel in storage for First Quarter 1986 Changes from last quarter reflect receipt of 36 BWR assemblies from Cooper Station. SCHMD,S.P. General Electric Co. 88/04/03. ROBERTS,J.P. NRC - No Detailed Affiliation Given. 2pp. 45133.092-45133.093.

DOCKET 70-1359 IRT CORP., SAN DIEGO, CA

8804120041 Requests extension of time to complete enswers to NRC 871109 questions re license renewal application Answers will be submitted by 880506.

MASCHKA,P.R. International Research & Technology Corp.
PENNINGTON,W.S. Fuel Cycle Safety Branch. 2pp. 45089:218-45089:219.

DOCKET 70-2932 TEXAS UTILITIES GENERATING CO., DALLAS, TX

8804110111 Forwards Amend 1 to License SNM-1912,reflecting revised ownership inlerests as described
BECK,J.W. TU Electric (formerly Texas Utilities Generating Co.). B8/03/25.
ROUSE,L.C. Office of Nuclear Material Safety & Safeguards,Director. 3pp. 45078 006-

45079,068

-8804110116 Application for amend to License SNM-1912,reflecting revised ownership interests as described below.Agreement between Texas Municipal Power Agency & TU Electric encl. COUNCIL, W.G. TU Electric (formerly Texas Utilities Generating Co.). 88/03/25. NRC - No Detailed Affiliation Given. 60pp. 45079:009-45079:088.

DOCKET 70-3051 TRANSNUCLEAR, INC., AIKEN, SC

8804280579 Notifies of Impending change in shareholding of Transnuclear,Inc.per 880219 alfidavit.
HANSON,A.S. Transnuclear, Inc. 88/04/06. SHEA,J R. International Programs. 1p. 45262:359-45262:359.

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL

UNDER CERTAIN CONDITIONS

DOCKET 71-0202 PACIFIC GAS & ELECTRIC CO.

8804270249 Summary of 871216 meeting w/TN,EG&G,Sandia,DOE & ORNL in Silver Spring,MD to preliminary criticality analysis of checker boarded fuel basket of Model TN-BRP cask & lesser related topics Viewgraphs encl.

DDEGAARDEN,R11. Division of Safeguards & Transportation (Post 870413), 88/03/30. Division of Safeguards & Transportation (Post 870413), 10pp. 45243:233-45243:242.

DOCKET 71-0240 POWER AUTHORITY OF STATE OF NEW YORK

8884280258 Requests registration as user of Models CNS 1-13C.CNS 1-13G, CNS 3-55, CNS 8-120A & CNS 8-120B BRONS, J.C. New York Power Authority (formerly Power Authority of the State of New York) B8/04/11. MACDONALD, C.E. Transportation Branch. 4pp. 45269:187-45269:190

DOCKET 71-0404 CTI, INC.

8804050169 Advises that company has changed mailing address to listed address.
WATSON,S.N. CTI, Inc. (tormerly Alaska Welding Center). 88/03/18
MACDONALD,C.E. Transportation Branch. 1p. 44997:061-44997:063.

DOCKET 71-0420 RADIATION TECHNOLOGY, INC.

- 6804150221 Forwards QA program approval for radioactive matt package: 9429,Rey 4,replacing existing QA program description commitment. MACDONALD,CE. Transportation Branch. 88/04/12. VARAKLIS,T. Radiation Technology, Inc. 1p. 45149.001-45149.002.
- ~8804150222 QA program approval for radioactive matt package.0420,Hev 4. MACDONALD,C E. Transportation Branch. 88/04/12. 1p. 45149.002-45149.002.

DOCKET 71-0423 HAH X-RAY SERVICES, INC.

- 8804150140 Forwards QA program appoval for radioactive mail package: 0423,Rev 3 Amend includes coverage of Monroe X-Ray Co,Inc., per 880331 request MACDONALD,C.E. Transportation Branch. 88/04/12. HEAD,K.Y. H8H X-Ray Services, Inc. 1p. 45134:347-45134:348.
- --8604150144 QA program approval for radioactive mail package.0423,Rev 3. MACDONALD,C.E. Transportation Branch. 88/04/12. lp. 45134:348-45134:348.

DOCKET 71-0448 MET LAB, INC.

- 8803080022 Requests toe for 870225 application for amond to QA approval for radioactive matt package:0448.W/o 19CFR170.

 JACKSON,G. License Fee Management Branch (881123-870413). 87/03/10. WARD,O.W. Met Lab, Inc. 1p. 44633:229-44633:231.
- --8803080025 Application for amend to QA program approval 0448 requesting exemption from regulatory requirement in 10CFR71.137 re audit personnel responsibilities. WARD.O.W. Met Lab, Inc. 87/02/25. MACDONALO,C.E. Transportation Certification Branch 2pp. 44633:230-44633:231.

DOCKET 71-0460 UNIV. OF VIRGINIA

8603080467 Clarifles & redefines request minde in Jan 1988 that NRC view 860205 QA/ QC Plan as into Item.Licensee will abide by NRC approved App I pending approval of revised plan. MULDER,RU. Virginia, Univ. of, Charlottesville, VA. 88/03/02. Document Control Branch (Document Control Desk). 2pp. 44673:325-44673.326.

DOCKET 71-0490 INSPECTION SERVICES CORP.

- 8804120267 Forwards OA program approval for radioactive mall package: 0490,Rev 2. MACDONALD,C.E. Transportation Branch: 88704705. LAWRENCE,G. Inspection Services Corp. 1p. 45089:189-45089:190.
- -8804120275 GA program approval for radioactive matt package:0490,Rev 2. MACDONALD.C.E. Transportation Branch. 88704705, 1p. 46089:190-45089:190.

DOCKET 71-0498 GEARHART-OWEN INDUSTRIES

8804060106 Advises that OA program approval for redioactive mati package:0498 expires on 880630.Renewal must be requested within 30 days of expiration. If renewal not desired,NRC should be so notified.

MACDONALD.C.E. Transportation Branch. 88/03/31. Gearhant Industries, Inc. 1p. 45018:255-45018:255.

DOCKET 71-0500 E.I. DU PONT DE NEMOURS & CO., INC.

8804060087 Advises that OA program approval for radioactive matt package:0500 expires on 880330.Renewal must be requested within 30 days of expiration.If renewal not desired,NRC should be so notified.

MACOONALD.C.E. Transportation Branch. 88/03/31. E.t., du Pont de Nemours & Co., Inc. 1p. 45029:043-45029:043.

DOCKET 71-0545 TEXAS NUCLEAR CORP.

- 8804150375 Forwards revised "OA Program Description," revised master index for OA procedures 8 new Tab B to replace current copy, per 880321 telcon. JOHNSON,T. Taxes Nuclear Corp. (subs. of Ramsey Engineering Co.). 88/03/25 GORDON,L. Transportation Branch. 2pp. 45133.094-45133.119.
- --8804150362 Revised OA program description for Texas Nuclear.
 Toxas Nuclear Corp. (subs. of Remsey Engineering Co.). 88/03/25 24pp. 45133.086-45133.119.
- 8804150153 Forwards QA program approval for rad oactive mall package: 0545,Rev 0 MACDONALD,C.E. Transportation Branch, 88/04/12, JOHNSON,T. Texas Nuclear Corp. (subs. of Ramsey Engineering Co.), 1p, 45134,001-45134;002.
- -8804150162 OA program approval for radioactive matt package 0545,Rev 0. MACDONALD,C.E. Transportation Branch. 88/04/12. 1p. 45134.002.45134.002.

DOCKET 71-0598 KANSAS GAS & ELECTRIC CO.

- 8804290006 Forwards QA program approval for radioactive mail package: 0598,Rev 1. MACDONALD,C.E. Transportation Branch: 88704725, BAILEY,J.A. Wolf Creek Nuclear Operating Corp. 1p. 45324;183-45324;184.
- --9804290008 QA program approval for radioactive mail package.0599,Rev 1. MACDONALD,C.E. Transportation Branch 88/04/25. 1p. 45324:184-45324:184.

DOCKET 71-0641 UNITED STATES TESTING CO., INC.

- 8804080113 Forwards QA program to replace radiation safety program U.S.T.-985 submitted on 87 1020. GREEN,R.E. United States Testing Co., Inc. 88/03/22. GCRDON,L. Transportation Branch. 2pp. 45019 226 45019.235.
- -8804060519 Rev 0 to "QA Program (10CFR71) for industrial Rati ography & Sealed Sources."
- * United States Tosting Co., Inc. 88/03/22. 6pp. 45019:228-45019:235.
- 8804150184 Forwards QA program approval for radioactive mail package. 0641,Rev 0. MACDONALD.C.E. Transportation Branch. 88/04/12. GREEN.R.E. United States Testing Co., Inc. 1p. 45141:183-45141:184.
- --8804150187 QA program approval for radioactive mall package.0641,Rev 0. MACDONALD,C.E. Transportation Branch. 88/04/12, 1p. 45141:184-45141;184.

DOCKET 71-0651 WESTINGHOUSE ELECTRIC CORP.

- 8804140262 Requests approval for enc) Rev 1 to NWD-TR-005, "OA Program Plan for Nuclear Waste Dept." Attachment describes changes which have been made to program to resolve NRC comments note in 880317 lir. COST.R. Wastinghouse Electric Corp. 887/03/22. MACDONALD,C.E. Transportation Branch. 4pp. 45118:188-45118:245.
- ***8804140269 Rev. Lto, "QA Program Plan for Nuclear Waste Dept."

 HAMILTON,W.H., COST,R.R. Westinghouse Electric Corp. NWD-TR-005 R01, 88/03/31, 56pp. 45116;191-45116;246.
- 8804050140 Forwards QA program approval for radioactive mail package: 0651,Rev 0. MACDONALD,C.E. Transportation Branch, 88/03/30, COST,R.R. Westinghouse Electric Corp. 1p. 45029.076-45029.079.
- --8804050143 QA program approval for radioactive mail package.0651,Rev 0 MACDONALD,C.E. Transportation Branch. 88/03/30. 1p. 45029:077-45029:079

DOCKET 71-0652 SAMSON INSPECTION & TECHNICAL SERVICES, INC.

- 6804050098 Application for QA program for radioactive matt package: 0852,Fee patd. HOPKINS,JA JEBCO Selamic, Inc. 68/03/22. MACDONALD,C.E. Transportation Branch. 1p. 44998:360-44996:357.
- -8804050102 Forwards completed Form 313 w/supptemental into including resumes for radiation safety officer & assistant officer & radiation safety manual excluding Part IV.W/o encis.

 HOPKINS J.A. JEBCO Seismic, Inc. 88/03/22. Region 3, Oto of the Director. 2pp. 44998.351-44996:352.
- --8604050105 Rev 0 to QA program for Type B quality shipments of radioactive matf.

 * JEBCO Selsmio, Inc., 88/01/31, 5pp. 44998:353-44998:357.

DOCKET 71-0853 BRAN-SHON, INC.

- 8804280088 Application for rev to QA program approval for radioactive matipackage:0653 Revised QA program enct. MEDAL,M.J. Bran. Shon, Inc. 88/04/14. GORDON,L. Office of Nuclear Material Safety & Safeguards,Director. 1p. 46322:204-46322:208.
- --8804280093 Revised "OA Program." Bran-Shon, Inc. 88/04/14. 4pp. 45322:205-45322:208.

DOCKET 71-0664 POWER INSPECTION, INC.

8804290078 Advises that review of QA program description attached to 880307 itr revealed deliciency of commitment Sample QA program for industrial radiography sealed sources enci.

GORDONL. Transportation Branch. 88/04/25. KUMER.K. Power Inspection, Inc. 1p. 45322:213-45322:214.

DOCKET 71-3001 MODEL: S-B/23, STUDSVIK ENERGITEKNIK AB

8804150218 Forwards add into re evaluation of Swedish Transport Package S-B/23 for spant MTR firef.per NRC 871222 request MCLAUGHLIN,J Transnuclear, Inc. 88/03/23. MACDONALD.C.E. Transportation Branch 6pp. 45148-349-45148-354.

DOCKET 71-3003 MODEL: TN-1, TRANSNUKLEAR GMBH

8904150058 Requests NRC assistance in performing criticality review of Gorman D/ 4004/B(U)F certificate for TN1 package Packaging used for transport of traditated MTR-type fuel bloments. Translation and: WANGLER,ME. Transportation, Dept. of 68/03/29. MACDONALD,C.E. Transportation Branck. 11pp. 45139:120-45139.130

DOCKET 71-4986 MODEL: RA-2, RA-3, RA-J, GENERAL ELECTRIC CO.

8804 140199 Requests authorization for shipment of 52 unused Dairyland LaCrosse fuel assemblies in GE RA-3 packaging.Critically safety of RA-3 packaging containing two unused LeCrosse fuel assemblies evaluated in each repl. Fee paid NOLAND. Transportation for 88703/17. MCDONALD,C.E. Transportation Branch 4pp, 45118.149-45118.167.

--8804140196 "Crucality Evaluation of Uniradiated LaCrosse BWR Fuel Assemblies in GE RA-3 Shipping Packaging." * Transnuclear, Inc. 88/03/16 15pp 45118 153-45118.167.

8804190321 Informs that Certificate of Compliance 4886 for Model RA-3 package is amended to authorize additionatins as Island.por 860317 application per 10CFR71. MACDONALD.C.E. Transportation Granch. 88/04/13. NOLAN,D. Transportation 4pp 43185.245.45105.246.

DOCKET 71-5450 MODEL: RCC, -1, -2, -3, -4, WESTINGHOUSE ELECTRIC CORP.

8804280108 Flaquests registration as user of Models RCC.RCC-1,RCC-2, RCC-3 & RCC-4.
BALEY,J.A. Wolf Creek Nuclear Operating Corp. 87/09/15. THOMPSON,H.L. Office of Nuclear Material Safety & Safeguards,D.tector. 3pp. 45266 235-45266.237.

8804290154 Natification of registration as user of Model 5450 in response to 870915 request MACDONALD,C.E. Transportation Branch, 68/04/25, BAILEY,J.A. Wolf Creek Nuclear Operating Corp. Ip. 45322 225-45322 225

DOCKET 71-6926 MODEL: GE-100, GENERAL ELECTRIC CO.

8804210480 Forwards request for addl Info re 871119 application for renewal of Certificate of Compilance 5926.Application should contain maint procedures for Model 100 packaging MACDONALD,C.E. Transportation Branch 88/01/26. CUNNINGHAM,G.E. General Electric Co. 2pp. 45191:175-45191:176.

DOCKET 71-5971 MODEL: 200, GENERAL ELECTRIC CO.

8804120405 Provides follow-up of verbal rept marte to NRC on 880325 re minor keense violation of Tech Spees Section 6.2.2 (4](a) & Operating Procedure #41,Section III A & C concerning Improper handling of irratiated vogetation semple on 880325 ORLOSKY,P.M. Buffa'o Materialis Research Center. 88/03/31. Document Control Branch (Occument Control Desk), 4pp. 45100.003-45100.006.

DOCKET 71-8078 MODEL: 927A1 & 927C1, COMBUSTION ENGINEERING, INC.

8804120019 Summary of 871018 meeting w/C-E in Silver Spring,MD re Models 927A1 8 927C1 packages. ODEGARDEN,RH Transportation Branch 88/03/30. Transportation Branch 1p. 45089,202-45089 202.

DOCKET 71-6717 MODEL: 6717-8, GAMMA INDUSTRIES, INC.

8804950257 Requests registration as user of Certificates of Compliance 6717,8126,9133 & 9135
MACDONALD,C.E. Transportation Branch 88/03/30 GARDUNO,M.B. Construction Materials Testing, Inc. 1p. 45020:097-45028:097.

8804050363 Notification of registration as usor of Contilicates of Compliance 0717,9126,9133 & 9135.por 890226 request.
MACDONALD,C.E. Transportation Branch 68703730 GARDUNO,M.6. BC Industries, Inc. (formerly Construction Materials, Inc.), 1p. 44997;227-44997.227.

DOCKET 71-9001 MODEL: IF-300, GENERAL ELECTRIC CO.

8804190125 Advisos that Certificate of Compilance 9001 for Model IF-300 amended to authorize contents of two 8x8 8WR fuel assembles w/burnup of 35.4 MWd/kgU & cooling time of at least 5 yrs, per GE 880304 request Approval record and. MACDONALD.CE. Transportation Branch 88/04/19 INGELS.T.E. General Electric Co. 2pp. 45164:302-45164:303.

DOCKET 71-9006 MODEL: AI 600 SU, TECH/OPS, INC.

6804110224 Notification of registration as user of Certificates of Compliance 9008,9007,9032 & 9156. MACDONALD.CE. Transportation Branch. 68/04/04 SWINEY.D.L. S&ME, Inc. (formetly Soil & Material Engineers, Inc.) 1p. 45078:332-45078.332. DOCKET 71-9007 MODEL: 520, TECH/OPS, INC.

8804110224 Not/fication of registration as user of Certificates of Compliance 9006,9007,9032 & 9158 MACDONALD.C E. Transportation Branch 88/04/04 SWINEY,D.L S&ME, Inc. (formerly Soil & Material Eng.negrs, Inc.) 1p 45078:332-45078:332

DOCKET 71-9010 MODEL: NUI-1/2, NUCLEAR ASSURANCE CORP.

8804050180 Summary of 880322 meeting w/Nuclear Assurance Corp in Rockville,MD re submitted of dry spent fuel storage cask topical rept. ROBERTS.J.P. Fuel Cycle Safety Branch 88703725. ROUSE,L.C. Fuel Cycle Safety Branch. 1p 44997.067-44997.067.

DOCKET 71-9015 MODEL: TN-8, -8L, TRANSNUCLEAR, INC.

8804180173 Requests registration as user of Models TN-8 & TN-8L under Certificate of Compliance 9015 & Models NUPAC 14/210L, NUPAC 14/210H,CNSt 14:215H,Senes A,NUS 14:195L 8,NUS 14:195H under Certificate of Compliance 9176 MHOCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Ublities), MHOCZKA,E J. Northeast Utilities 88/03/30, MCDONALD,C E. Transportation Certification Branch, 3pp. 45149.311-45149.313.

8804250357 Notification of registration as user of Certificate of Compliance 9015 Unit previously registered as user of Certificate of Compliance 9178 No other action necessary MACDONALD.C E. Transportation Branch, 88/04/19 MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 1p. 45213-192-45213:192.

DOCKET 71-9032 MODEL: 650, TECH/OPS, INC.

8804110224 Notification of registration as user of Certificates of Compliance 9005,9007,9032 & 9156.

MACDONALD,CE Transportation Branch. 88/04/04. SWINEY,D.L. S&ME, Inc. (formerly Soil & Material Engineers, Inc.). 1p. 45078:332-45078.332

DOCKET 71-9036 MODEL: C-1, SOURCE PRODUCTION & EQUIPMENT CO., INC.

8804180401 Requests registration as user of Models SPEC 2-T,SPEC C-1, IR 100 & IR 50,per 10CFR71.12(c)(3).
MUNROJJ. RTS Technology, Inc. 88/04/07. MACDONALD,C.E. Transportation Branch. 2pp. 45149:223-45149:224.

8804270320 Confirms registration as user of Certificates of Compliance 9036,9056,9156 8 9157,per 890407 reguest. MACDONALD,C.E. Transportation Branch. 88/04/19, MUNRO,J.J. HTS Technology, Inc. 1p, 45324;175-45324;175.

DOCKET 71-9056 MODEL: SPEC 2-T, SOURCE PRODUCTION & EQUIPMENT CO.

8804180401 Requests registration as user of Models SPEC 2-T,SPEC C-1, IR 100 8 IR 50,per 10CFR71.12(c)(3). MUNRO,J.J. RTS Technology, Inc. 88/04/07. MACDONALD,C.E. Transportation Branch. 2pp. 45149 223-45149.224.

8804270320 Confirms registration as user of Certificates of Compliance 9036,9056,9156 & 9157,per 880407 request. MACDONALD,C.E. Transportation Branch. 88/04/19. MUNRO,J.J. HTS Technology, Inc. 1p. 45324:175-45324:175

DOCKET 71-9057 MODEL: FPD-100, GA TECHNOLOGIES, INC.

8804270320 Confirms registration as user of Certificates of Compliance 9036,9056,9156 & 9157,por 880407 request.
MACDONALD,C.E. Transportation Branch. 88/04/19. MUNRO,J.J. RTS Technology, Inc. 1p, 45324;175-45324;175.

DOCKET 71-9079 MODEL: NUPAC 14D-2.0, WESTINGHOUSE-HITTMAN NUCLEAR

8604140062 Notifies that thit will be utilizing new contractor LN Technology located in Columbia,SC for transportation of radioactive matts,effective 880401.Casks noted in 880410 fit should conflinue to be recognized as approved shipping casks. SORENSEN,G.C. Washington Public Power Supply System. 88/03/25. MACDONALD,C.E. Office of Nuclear Material Safety & Safeguards,Director. 3pp. 45120.354-45120 356.

8804150252 Application for renowal of Certificate of Compliance 9079 for Model NuPac 1402.0 cask. "Consolidated SAR for NUPAC 140-2.0 Casks" oncl Fee paid. TEMUSC J Nuclear Packaging, Inc. 88/03/30. MACDONALD. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 45133 004-45133.084.

--9804150253 "Consol dated Safety Analysis Rept for NUPAC 14D-2.0 Casks " Nuclear Packaging, Inc. 88/01/31, 78pp. 45133,006-45133,084.

DOCKET 71-9080 MODEL: HN-600 & NUPAC 100, WESTINGHOUSE-HITTMAN NUCLEAR

8804140062 Notifies that util will be utilizing new contractor LN Technology located in Columbia, SC for transportation of radioactive matis, effective 880401.Casks noted in 880410 it is should continue to be recognized as approved shipping casks. SCHENSEN.G.C. Washington Public Power Supply System. 88/03/25. MACDONALD.C.E. Office of Nuclear Material Safety & Safeguards, Director. 3pp. 45120:354.45120.356.

DOCKET 71-9102 MODEL: NPI-20WC-6, NEUTRON PRODUCTS, INC.

8804150128 Application for runowal of Certificate of Compliance 9102 for Model NPI-20WC-6 Fee pad SCHWCERERIF Neutron Products, Inc. 88/03/31 MACCONALD.C.E. Office of Nu-clear Material Safety & Safeguards, Director. 2pp. 45133-330-45133-331

DOCKET 71-9126 MODEL: 20, 20A, 50, 50A, GAMMA INDUSTRIES, INC.

8804050257 Requests rogistration as user of Certificates of Comptance 6717,9126,9133 & 9135
MACDONALD.C E Transportation Branch 88703730 GAROUNO.M B Construction Materials Testing, Inc. 1p. 45029 097-45029 097

8804050383 Notification of registration as user of Certificates of Compliance 6717,9126,9103 & 9105,per 880226 request MACDONALD,CE Transportation Branch 88700700 GARDUNO,M 8 BC Industries, Inc. (formerly Construction Materials, Inc.), 1p. 44997 227-44997 227

DOCKET 71-9133 MODEL: C-10, GAMMA INDUSTRIES, INC.

804050257 Requests registration as user of Certificates of Compliance 6717,9126,9133 & 9135 MACDONALD,CE Transportation Branch 88/03/30 GARDUNO.M 8 Construction 8804050257 Materials Testing, Inc. 1p. 45029 097-45029.097

B804050363 Noticetion of registration as user of Certificates of Compliance 6717,9126,9133 & 9135,per 880226 request MACDONALD.CE: Transportation Branch 88/03/30 GARDINO.M 8 BC Industries, Inc. (formerly Construction Materials, Inc.) 1p. 44997-227-44997-227

DOCKET 71-9135 MODEL: CENTURY S & SA, GAMMA INDUSTRIES, INC.

8804050257 Hoquesis registration as user of Certificates of Compliance 6717,9126,9133 & 9135 MACDONALO.C.E. Transportation Branch 89/03/30 GARDUNO,M.B. Construction Materials Testing, Inc. 1p. 45029.097-45029.097.

8804050363 Notification of registration as user of Contilicates of Compliance 6717.9126.9133 & 9135.por 880226 request MACDONALD.CE Transportation Brench. 88/03/30 GARDUNO.M.B. BC Industries. Inc. (formerly Construction Materials, Inc.) 1p. 44997 227-44997 227.

DOCKET 71-9147 MODEL: 850, TECH/OPS, INC.

8804180246 Responds to 870324 request for add info re application for Certificate of Compliance 9147 Structural & shielding concerns answered by satisfactory completion of 30 ft drop lest indicating no loss of shielding ROUGHANC M. Amerisham Corp. 88/03/30. MACDONALD,C. Office of Nuclear Material Safety & Safeguards, Director. 15pp. 45150-317-45150-331.

DOCKET 71-9151 MODEL: HN-100 SERIES 3, WESTINGHOUSE-HITTMAN

8804140062 Nohles that will be ublizing now contractor LN Technology located in Columbia, SC for transportation of radioactive matts, effective 880401. Casks noted in 880410 fit should continue to be recognized as approved stripping casks SORENSEN.G.C. Washington Public Power Supply System 88/03/25 MACDONALD.C.E. Office of Nuclear Material Safety & Safeguards, Oiroctor 3pp 45100, 364, 46120, 365 45120 354 45120 356

DOCKET 71-9152 MODEL: CNS 1-13C II, CHEM-NUCLEAR SYSTEMS, INC.

8804120261 Forwards request for addl into re 880226 application requesting renewal of Certificate of Compliance 9152.

MACDONALD,C.E. Transportation Branch. 88/04/06. MAUK,C.J. Energy, Dept. of 3pp. 45089 273-45089.275.

DOCKET 71-9156 MODEL: IR-50, INDUSTRIAL NUCLEAR CO.

8804110224 Notification of registration as user of Certificates of Compliance 9006,9007,9032 & 9156.

MACDONALD.C.E. Transportation Branch, 88/04/04, SWINEY.D.L. S&ME, Inc. (formerly Soil & Material Engineers, Inc.), 1p. 45078 332-45078 332

8804180401 Requests registration as user of Models SPEC 2-T.SPEC C-1, IR 100 & IR 50.per 10CFR71.12(c)(3).
MUNRO_JJ. RTS Technology, Inc. 88/04/07, MACDONALD,C.E. Transportation Branch 2pp. 45149 223-45149 224

8804270320 Contirms registration as user of Certificates of Compliance 9036,9056,9156 804270320 Committe requests & 9157.per 880407 requests MACDONALO.C.E. Transportation Branch 88/04/19, MUNHO.J.J. RTS Technology, Inc. 1p 45324:175-45324:175.

DOCKET 71-9157 MODEL: IR-100, INDUSTRIAL NUCLEAR CO.

8804180401 Requests registration as user of Models SPEC 2-T.SPEC C-1, IR 100 & IR 50.par 10CFR71.12(c)(3).
MUNRO_J_J_RTS_Technology, Inc. 88/04/07. MACDONALD.C.E. Transportation

DOCKET 71-9167 MODEL: 3206B, 3227B & 3218, AMERSHAM CORP.

8804060179 Forwards Certificate of Comphanco 9167 Rev 2 for Models 3206B 3227B & 3218.pcr 690301 application Certificate supersedes 930906 Certificate of Compliance.Hev 1 in entirety MACDONALD,C.E. Transportation Branch, 88/03/31 ALLEN,K.A. Amersham Corp. 2pp. 45019-295-45019-200

~8894060164 Certificate of Compliance 9167.Hev 2,for Models 32068,32278 & 3218 Approval record encl MACDONALD,C E. Transportation Branch, 88/03/31, 4pp, 45019,297,45019,300

DOCKET 71-9168 MODEL: CNS 8-120B, CHEM-NUCLEAR SYSTEMS, INC.

8804140295 Requests registration as user of Model CNS-8-1208 COSTLEY,W. Neutron Products, Inc. 88/03/31, MACDONALD,C.E. NAC - No Cotafed Althation Given, 2pp. 45117 363-45117.361.

8804190052 Notification of registration as user of Certificate of Compliance 9168,per 890331 request MACCONALD.C F Transportation Branch 88/04/13 COSTLEY.W.J Neutron Prod ucts, Inc. Ip. 45164 286-45164 286

DOCKET 71-9176 MODEL: NUPAC 14/210L & 14/210H, NUCLEAR PACKAGING,

8804180173 Requests registration as user of Models TN-8 & TN-8L under Certificate of Comphance 9015 & Models NUPAC 14/210L, NUPAC 14/210H,CNSI 14-215H,Series A NUS 14-195L & NUS 14-195L WUS 14-195L MUS 14-195L Open 1976 Unificate of Comphance 9176 MROCZKA,E J Northoast Nuclear Energy Co (subs. of Northeast Unifies) MROCZKA,E J Northoast Unifies 88/03/30, MCDONALD,CE Transportation Certification Branch 3pp. 45149 311-45149 313.

8604250357 Notification of registration as user of Cartilicate of Compliance 9015.Util previously registered as user of Certificate of Compliance 9176 No other action neces-Sary.

MACDONALD.C.E. Transportation Branch, 88/04/19, MROCZKA,E.J. Northoast NJ-clear Energy Co. (subs. of Northeast Utilios), 1p. 45213 192-45213 192.

DOCKET 71-9183 MODEL: NAC-1, NUCLEAR ASSURANCE CORP.

8804200580 Summary of 870024 meeting w/DOE & Nuclear Assurance Corp in Silver Spring,MD to two unrotated incidents w/Model NAC-1 cask ODEGAARDEN,B.H. Transportation Branch 87/12/30, Transportation Branch 2pp. 45191 051-45191 052

DOCKET 71-9193 MODEL: NES-5, NUCLEAR ENERGY SERVICES, INC.

8804180403 Forwards Rov 8 to "SAR to Model NES-5 Package to IOCFR71 Type B(U) But Ibuda Coverage Services, Inc. 88/03/24 MACDONALD.C.E. NRC - No. De-lared Allivation Given 1p. 45166 090-45168.097

-8804190074 Rev 8 to "SAR for Model NES-5 Package to 10CFR71 Type B(U) Packaging Requirements."
* Nuclear Energy Services, Inc. 85/03/31, 7pp. 45166 091-45166 097.

8804070078 Forwards Rev 5 to Certificate of Compliance 9193 for Model NES-5 shipping package MACDQNALD,C.E. Transportation Branch 88/03/31, MAY,J.R. Nuclear Energy Services, Inc. 2pp. 45029 191-45029 196

8804070080 Certificate of Compliance 9193,for Model NES-5 shipping container Approval record encl MACDONALD,C E. Transportation Branch 88/03/31 4pp 45029.193-45029.196 --8804070080 Certificate

6804 190075 Notitios that 880324 fit not accompanied by application lee & not accepted for review Subj. fit presents no new into & is not required in support of 880331 certificate of compilance. Revised pages have no rev number or date Lir destroyed MACDCDNALO.CE Transportation Branch. 88/04/13. ELY.P. Nuclear Energy Services, Inc. 1p. 45164:289.45184:289.

8804190347 Advises that application fee not accompanied w/880324 ltr & not accepted for roview Lit does not appear to present any new into 8 not required in support of Certificate of Comprance 9193.flev 5.Copies of 880324 fit destroyed MACDCNALD.C.E. Transportation Branch. 88/04/13. ELY.P. Nuclear Energy Services (NES) Manufacturing. 1p. 45185.260-45185:260.

DOCKET 71-9202 MODEL: TN-BRP, TRANSNUCLEAR, INC.

8804250230 Summary of 880127 meeting w/DOE in Rockville,MD re Model TN-BRP & TN REG casks
ODEGAARDEN,R H. Transportation Branch 88/03/30 Division of Saleguards & Transportation (Post 870413), 40pp. 45213.120-45213.159

DOCKET 71-9208 MODEL: NUPAC 10-142, NUCLEAR PACKAGING, INC.

8804180215 Requests registration as user of Model 10-1428.

KEISER,H.W. Pennsylvania Power & Light Co. 88/03/30, MACDONALD,C.E. Transportation Branch. 2p. 45148:355-45148:356

8804220258 Notification of registration as user of Certificate of Compliance 9208,pcr 860330 request.
MACDONALD,CE. Transportation Branch 88/04/19 KEISER,H.W. Pennsylvania

DOCKET 71-9212 MODEL: 72-B, NUCLEAR PACKAGING, INC.

8804200586 Summary of 871106 meeting w/Nuclear Packaging Inc,DOE, Sandia & Waste Isolation Pilot Plant in Silver Spring,MD re-Model 72-8 & TRUPACK II package

designs
ODEGAARDEN,R.H. Transportation Branch. 87/12/30. Transportation Branch. 3pp 45191.053-45191 055.

DOCKET 71-9213 MODEL: TN-GEMINI, TRANSNUCLEAR

8804250113 Summary of 880204 meeting w/Transnuclear Inc.in Rockville,MD re Model IN GEMINI package design Viewgraphs and ODEGAARDEN, BH Transportation Branch, 88/03/30, Transportation Branch, 5pp 45213 09B-45213 102

DOCKET 71-9216 MODEL: CNS 1-13G, CHEM-NUCLEAR SYSTEMS, INC.

8804050187 Not lication of registration as user of Certificate of Compliance 9216.per MACDONALD, C.E., Transportation Branch, 88/03/30, BIRD, R.G., Boston Edison Co. 1p. 44997.075-44997.075

DOCKET 71-9218 MODEL: TRUPACT-II, ENERGY, DEPT. OF

8804060232 "TRU Waste Comphance Program For WIPP-WAC (U)."
"Westinghouse Electric Corp. 87/07/31 160pp. 45011:245-45012.044

8804200586 Summary of 871106 meeting w/Nuclear Packaging,Inc,DOE, Sandia & Waste Isolation Pilot Plant in Silver Spring,MD re Model 72-B & TRUPACK II package designs. ODEGAARDEN,R.H. Transportation Branch 87/12/30 Transportation Branch 3pp.

45191.053.45191.055.

8804120014 Summary of 871215 meeting w/DOE,Westinghouse,Sandia,Blate of NM & NijPac in Silver Spring,MD re classification of transuranic waste.

ODEGARDEN,R.H. Transportation Branch 88/03/30, Transportation Branch, 2pp. 45089.276-45089 277.

DOCKET 71-9222 MODEL: HN-215H, WESTINGHOUSE HITTMAN NUCLEAR, INC.

8804060256 Requests registration as user of Westinghouse Hittman Nuclear Inc radio-active matts shipping cask Model HN-215H, per 10CFR71.12. WHITTIER.G.D. Meine Yankee Atomic Power Co. 88/03/21, MACDONALD.C.E. Transportation Branch 2pp. 45017.254-45017.255.

8804050397 Forwards Rev 0 to Certificate of Compliance 9222 for Model HN-215H,per

B70713 application.
MACDONALD,C.E. Transportation Branch. 88/03/31. ROY,B.A. Hittman Nuclear & Development Corp. (subs. of Hitlman Corp.) 1p. 44986:345-44936.349.

-8804050400 Certificate of Compliance 9222, Rev O, for Model HN-215H. Approval

MACDONALD, C.E. Transportation Branch. 88/03/31. 4pp. 44996:348-44996:349.

8904280195 Requests registration as user of Model HN 215H.
KNAPP,W.J. Philadelphia Electric Co. 88/04/11 MACDONALD,C.E. Transportation Branch. 2pp 45266-238-45286 239.

8804 (90167 Informs of reg-stration as user of Certificate of Compliance 9222 per 880321 request 8 10CFR71.12 MACDONALD.CE Transportation Branch 88/04/13, WHITTIER,G.D. Maine Yankee Atomic Power Co. 1p 45165:310-45165310.

8804290286 Notification of registration as user of Certificate of Compliance 9222 in re-

sponse to 880411 request.

MACCIONALO,C. Transportation Branch. 88/04/25. KNAPP,W.J. Philadelphia Electric Co. 1p. 4529::214-45322.274.

DOCKET 71-9224 MODEL: HN-190-2, WESTINGHOUSE HITTMAN NUCLEAR, INC.

8804190267 Application for renewal of Certificate of Compliance 9079, changing model from HN-100 Series 2 to HN-190-2 to reflect volumetric capacity of cask.SAR and Application resulted in issuance of Certificate of Compliance 9224. ROY,B.A. Westinghouse Hitman Nuclear, Inc. 88/03/31. MACDONALD,C.E. Transportation Branch. 3pp. 45184:173-45184:236.

--8804190277 Rev 0 to "SAR for HN-190-2 Radwaste Shipping Cask." W/three oversize drawings.

* Westingflouse Hittman Nuclear, Inc. STD-R-02-017 RG0. 68/03/31. 61pp
45164:176-45164 236.

LICENSING OF INDEPENDENT SPENT FUEL STORAGE

DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO.

8804270323 "1987 Annual Rept." W/880407 ftr. SCHMID,S.P. General Electric Co. 87/12/31. CUNNINGHAM.R.E. Office of Nuclear Material Safety & Safeguards,Director, 64pp. 45263:104-45263:167.

8804150363 Provides into re fuel in storage for First Quarter 1988. Changes from last quarter reflect receipt of 36 BWR assemblies from Cooper Station. SCHMID, SP. General Electric Co. 88/04/03. ROBERTS,J P. NRC - No Detailed Affidation Given. 2pp. 45133.092-45133:093.

DOCKET 72-0002 VIRGINIA ELECTRIC & POWER CO.

8804120291 Advises that 880308 Rev 12 to Surry ISFSI guard training & qualification plan consistent w/provisions of 10CFR72 84(b) 10CFR72 84(b) & acceptable. CLINE.W.E. Region 2, Ofc of the Director. 88/04/06. STEWART.W.L. Virginia Power (Virginia Electric & Power Co.). 3pp. 45146:013-45146.015.

DOCKET 72-0003 CAROLINA POWER & LIGHT CO.

8804130328 Forwards Amend 3 to "ISFSI SAR," Justification for each change also encl. LOFLIN,L.1. Carolina Power & Light Co. 88/03/15, ROBERTS,J.P. Office of Nuclear Material Safety & Safeguards, Director. 8pp. 45103:190-45103:197.

DOCKET 72-0004 DUKE POWER CO., 50-269

8804040024 Application for amends to Licenses DPR-38, DPR-47 & DPR-55 to permit operation of ISFSI for temporary storage of spent fuel until Federal govt provides permanent storage facilities Fee paid.

TUCKER, IH. B. Duke Power Co. 88/03/31. Document Control Branch (Document Control Desk). 11pp. 45233.050-46233:195.

--8804040025 Proposed Tech Specs re spent fuel storage facility.
Ouks Power Co. 88/03/31, 7pp. 45233:060-45233:067.

--8804040029 Forwards application to construct & operate ISFS) for temporary storage of spent fuel.per 10CFR72.SAR & environ rept also encl.Fee paid. TUCKER,H B. Duke Power Co. 88/09/31. Office of Nuclear Material Safety & Safeguards,Director. 5pp. 45233:058-45233:195.

-8804040049 Application for license to construct & operate dry cask ISFSI at Oconee

Nuclear Station

* Duke Power Co. 88/03/31, 23pp. 45233:073-45233:195.

-8804040053 "ISFSI Environ Rept,"

Duke Power Co. 88/03/31. 215pp. 46233:196-45234;060.

-8804040059 "ISFSI SAR." Duke Power Co. 88/03/31, 265pp. 45234:051-45234:315.

8904130203 Notification of 881218 meeting w/ut/l in Silver Spring,MD to discuss util plans for expansion of spent fuel storage lacilities under 10CFR72 & Oconee Nuclear Station_Ltst of attendees & agenda encl.

ROBERTS,J.P. Advanced Fuel & Spent Fuel Licensing Branch. 87/01/07.

ROBERTS.J.P. Advanced Fuel & Spent Fuel Licensing Branch. 87/01/07. ROUSE,L.C. Advanced Fuel & Spent Fuel Licensing Branch. 10pp. 45101:202-45101-211.

NONDOCKETED ITEMS

10CFR COMMISSION MEETING RECORDS

- 8804010168 Transcript of 880323 affirmation/discussion & vote public meeting in
 - Commissioners, 88/03/23, 8pp. 44948 279-44948 286.
- 8804010220 Staff requirements memo re 870317 briefing of Commission in Washington,DC by GPU & GPUN on cleanup program of TMI 2.No requirements placed on staff CHILK, S.J. Office of the Secretary of the Commission. M680317A. 88/03/23. Office of the Secretary of the Commission. 1p. 44919.336. 44919.336.

8804040262 Statt requirements memo on 880322 affirmation/discussion & vote in Washington,DC re facility restart Commission authorized NRC to permit util to restart upon resolution of RTD issue & other prerequisites CHILK,SJ Office of the Secretary of the Commission. M880322C. 88/03/30. STELLO,V. Ofc of the Executive Director for Operations. 1p. 44974 256-44974 256.

- 8804050155 Staff requirements memo re Commission 880318 briefing by Olc of Governmental & Public Affairs (GPA) & EDO concorning NRC intl agreements & coordination of research activities. GPA & EDO should coordinate intl activities better. CHILKSJ. Office of the Secretary of the Commission M880318. 88703731. STELLO,V. Otc of the Executive Director for Operations. DENTON, H. Office of Governmental & Public Affairs (Post 670413). 2pp. 45009:359-45009.360.
- 8804050248 Statt requirements memo re 880314 briefing in Washington,DC concerning efforts to develop policy statement identifying radiation risk or dose level below which govi regulation would be limited or unwerranted Options paper requested. CHILK,S.J. Office of the Secretary of the Commission. MB80314. 88/03/30. STELLO,V. Oic of the Executive Director for Operations. 3pp. 44997:180-44997:182.
- 8804050411 Statt requirements momo re 880321 discussion/possible vote on full power OL for plant On 880322.NRC issued full power OL. CHILK,S.J. Office of the Secretary of the Commission. M880321A. 88/03/29. STELLO, V. Ofc of the Executive Director for Operations. 1p. 44996-344-44996.344.
- 8804080133 Staff requirements memo re Commission 880322 briefing on status of pro-posed rulemaking on basic OA in radiation therapy & related activities Agreement States should be contacted to obtain Info re medical misa
- 8804110079 Stall requirements memo re 880323 affirmation/discussion & vote in Washington,DC on SECY-88-43 concerning proposed linal rule revising agency procedures governing ax parte communications & separation of functions CHILKS.J. Office of the Socretary of the Commission. M880323. 88/04/04. PARLER,W C. Office of the General Counsel, Ip. 45071.088-45071:088.
- 8804120099 Transcript of 880331 affirmation/discussion & vota (public meeting) in Weshington, DC.Pp 1.4
 * Commissioners. 88/03/31 7pp. 45081:352-45091:359.
- 8804120113 Transcript of 880331 public meeting in Washington, DC re-briefing on pro-posed final rule on station blackout. Pp 1-73. Supporting documentation and. * Commissioners. 88/03/31. 85pp. 45089.088-45089:175.
- 8804120236 Statt requirements memo on 880331 alfirmation/discussion & vote in Washington.DC re SECY-88-066 concerning Commonwealth of PA 680122 second patition for hearing on facility.

 CHILK,S.J. Office of the Secretary of the Commission. M680331C. 88/04/07. PARLER,W.C. Office of the General Counsel. 1p. 45160-300-45100-300.
- 8804120430 Transcript of 880331 NRC public meeting in Washington,DC re-briefing on high priority AEOD issues.W/viewgraphs.
 * NRC No Detailed Alfillation Given. 88/03/31, 87pp. 45091:178-45091:281.
- 8804140322 Staff requirements memo re 880331 brioling on AEOD priority issues & co-ordination of findings within NRC.NRC must focus on mechanisms for integrating & coordinating AEOD recommendations w/other NRC olcs. CHILK,S.J. Office of the Secretary of the Commission. M8803318. 88/04/08. STELLO,V. Ofc of the Executive Director for Operations. 1p. 45118:046-45118:046.
- 8804140475 Staff requirements memo re briefing in Washington,DC on SECY-88:22 concerning proposed rule on station blackout.

 CHILK,S.J. Office of the Secretary of the Commission. M880331A. 88/04/08.

 STELLO,V. Otc of the Executive Director for Operations. 1p. 45130:153-45130:153.
- 8804150113 Transcript of 880407 meeting w/NRC Advisory Committee on Medical Uses of Isotopes & Industry Scientific Committees in Washington, DC.Pp 1-84. **Commissioners. 88/04/07. 90pp. 45133:228-46133:315.
- 8804150248 Transcript of 880406 briefing on basic safety principles for nuclear power plants in Washington, DC.Pp 1-41. Viewgraphs enct 'Commissioners. 88/04/06. 76pp. 45149.021-45149.098.
- 8804200374 Staff requirements memo concerning 880406 briefing re Intl Nuclear Safety Advisory Group rept. "Basic Safety Principles for Nuclear Power Plants." Staff review of rept & recommendations for Commission action, if needed, requested. CHILK, S.J. Office of the Secretary of the Commission. M880406. 88/04/15. STELLO,V. Ofc of the Executive Director for Operations. 1p. 45191:112-45191:112.
- 8804280281 Statt requirements memo re 880314 briefing on status of efforts to develop de minimis policy NRC requested to submit options paper on policy by 880801. CHILK,S.J. Office of the Secretary of the Commission. M880314. 88/04/22. STELLO.V. Ofc of the Executive Director for Operations. 1p. 45265:101-45265:104.
- 8804280369 Discusses NRC briefing by licensee re-readiness for restart. Licensee com-mitted to listed action per Commission request. CHILK,S.J. Office of the Secretary of the Commission, 88/04/22. Office of the Secre-tary of the Commission, 2pp. 45263:360-45283:361.

- 8804290236 Stalt requirements memo re 880407 briefing on proposed basic OA rule w/ representatives of NRC Advisory Committee on Medical Uses of Isotopos & Industry Scientific committees.
 - STELLO,V. Ofc of the Secretary of the Commission. MB80407. 89/04/22. STELLO,V. Ofc of the Executive Director for Operations. 2pp. 45284.357-45284:358

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

- 8804010196 Transcript of ACRS Subcommittee on Instrumentation & Control Sys 880324 hearing in Washington, DC.Pp 1-271. Supporting documentation enct.

 * ACRS Advisory Committee on Reactor Sateguards. 88/03/24, 306pp 44947:310-44948:255
- 8804110185 Transcript of ACRS Human Factors Subcommittee meeting on 880328 in Washington, DC Pp 1-254. Supporting documentation encl
 * ACRS Advisory Committee on Reactor Safeguards, 88/03/28, 296pp, 45050.097-
- 8804110203 Transcript of ACRS 880330 hearing in Culver City.CA re structural angineering Pp 1-182 Supporting documentation enct.

 * ACRS Advisory Committee on Reactor Safeguerds, 88703/30, 162pp, 45051:033-
- 8804130114 Transcript of ACRS 880406 meeting in Washington.OC re advanced PWRs.Pp 1-133 Introductory statement by advanced PWR subcommittee chairman,880408 and: ACRS - Advisory Committee on Reactor Safeguards, 88/04/06, 137pp. 45123.340-
- 8804130232 Forwards ACRS documents for listing on accessions list. Documents should be forwarded to PDR.

 BARNARDE. ACRS Advisory Committee on Reactor Saleguards. 88/04/08.

 MCKNIGHT,J. Document Control Branch (Document Control Desk). 3pp. 45117.323-
- 8804130256 Comments on 871021 final rept NSAC-113, "EPRI/Westinghouse Owners Group Analysis of DHR Risk at Point Beach," per NRC request Resources did not permit exam of plant,review of training procedures & emergency guidelines DAVIS, Pr. Affiliation Not Assigned 88/01/11, 80EHNERT, P. ACRS Advisory Committee on Reactor Safeguards, 14pp. 45117-326-45117-339.
- 8804130272 Discusses peer review of CSAU methodology on 880112-13 in 8ethesda.MD.CSAU methodology does not require documentation supporting "phe-nomens selection" nor max & rinin values of needed parameters that will be required CATTON,I. ACRS Advisory Committee on Reactor Safeguards. 88/21/18 8OEHNERT.P. ACRS Advisory Committee on Reactor Safeguards. 49p. 45117.340-45117:343
- 8804130274 Forwards commentary on Structural Engineering Subcommittee meeting in Albuqerque,NM Expresses disappointment in outcome of model test Experimental instrumentalitin with done but use & purpose lost in maze of detail. BENDER,M Queryletch Associates, 88/01726, IGNE,E.P. ACRS Advisory Committee on Reactor Saleguards, 4pp. 45117.344-45117.347.
- 8804130290 Summary of Q/A subcommittee meeting in Los Atamos on TRAC. TRAC primarily concerned w/numerical analysis & w/ computation. Further work on TRAC would not be useful & program should be terminated.

 PLESSETIMS. California institute of Technology, Pasadena, CA. 88/01/27.
 BOENNERT,P. California institute of Technology, Pasadena, CA. 1p. 45117:348-45117:348.
- 8804130300 Comments on last wk waste mgt subcommittee meeting Meeting in general excellent & presentation good Document line summary of current activities & effects of new legislation. KRAUSKOPF.K.B. Affiliation Not Assigned. 88/01/30. MERRILL,O.S. ACRS Advisory Committee on Reactor Safeguards. 3pp. 45117:349-45117:351.
- 8604130313 Extends rept submitted on 871206 that constituted opinion on effects of TVA corporate reorganization & suggestions on NRC & ACRS future involvement in managenia/rogafizational aspects of nuclear power.

 HAGEDORN.H.J. ACRS Advisory Committee on Reactor Safeguards. 88/02/07.

 WYILE C.J. ACRS Advisory Committee on Reactor Safeguards. 4pp. 45117.352-45117.352 45117:356
- 8804130329 Comments on into presented by NRC & TVA at 880202:03 meetings of ACRS Subcommittee on TVA Organizational Issues & selected documents distributed to subcommittee since 871104 meeting in Washington, DC.
 BARTON,P.H. ACRS Advisory Committee on Reactor Saleguards 88/04/13.
 WYLIE,C.J. ACRS Advisory Committee on Reactor Saleguards, 4pp. 45117:358-45117:359.
- 8804130341 Comments on DOE responses to eight questions posed during meeting w/ DOE in Las Vegas,NM in Juliper 880128 request. KRAUSKOPF,K.B. Stanford Univ., Stanford, CA. 88/02/12. MERRILL.Q.S. ACRS Advisory Committee on Reactor Safeguards. 2pp. 45117:319-45117:320.
- 8804130348 Comments on questions generated during 870729 meeting of ACRS Sub-Committee on Weste Mgt.
 TRIFUNAC.M.D. Southern Celifornia, Univ. of, Los Angeles, CA 88/02/29.
 MOELLER.D.W. ACRS - Advisory Committee on Reactor Safeguards. 2pp. 45117:321-
- 8804130364 Advises that combination of intensive geologic mapping, reflection & refrac-tion selsmic surveys,dating of fault movements & enalysis of current & past earth-quake data reduces chances of underrestmating earthquake damage MAXWELLJ.C. Maxwell, J.C. 88/03/07. IESSS.C.P. ACRS Advisory Committee on Reactor Safeguards, 3pp. 45130:085-45130.067.

- 8804130393 Comments on Westinghouse arguments re plant steam generator tube source we will be a converged to the con
- 8804130400 Summarizios NUREG-1150 Peer Review Committee 860218-19 meetings. CATTON, LACRS Advisory Committee on Reactor Safeguards 88/03/09 HOUSTON, D. ACRS Advisory Committee on Reactor Safeguards, 2pp. 45117-298-
- 8804130417 Advisos that listed lessons being learned from code scaling applicability 8 uncertainty effort 8 will be compiled in special document for future guidance Commonts by members of peor review group enct. CATTON, I. ACRS. Advisory Committee on Reactor Sateguards, 88/03/09. BQEHNERT, P. ACRS. Advisory Committee on Reactor Sateguards, 2pp. 45117.300. 45117.300.
- 8804130422 Forwards draft comments as following to metal components subcommittee meeting on 880218 Strongly andorses Rev 2 to Reg Guide 1.99.

 ODETTE,G.R. California, Univ. of, Santa Barbare, CA. 88/03/10. SHEWMON,P. ACRS Advisory Committee on Reactor Safeguards. 14pp. 45117:303-45117.318
- 8804130428 Comments on OA reptire ACRS Thermal Hydraulic Phenomene Subcommittee meeting on 889120-21 in Los Alamos,NM.Overall quality of technical work disappointing. Major fault lies in basic approach to model detailed physical phenom-
 - TIEN.C. California, Univ. of, Berkeley, CA. 88/03/17, BOSHNERT,P. ACRS Advisory Committee on Reactor Safeguards, 2pp. 45117;317-45117;318.
- 8804130431 Summary of ACRS Subcommittee on Safety, Philosophy, Technology & Cri-30413431 Summary of Archa Subcommittee on Salety, Finiscopy, Today of the requirements for adoquate protection as applied to proposed backlit rule, Viewgraphs encl.

 **ACRS - Advisory Committee on Reactor Saleguerts 87/10/16. ACRS - Advisory Committee on Reactor Saleguerts 87/10/16.
- 8804130433 Summary of ACRS 332nd meeting on 871203-04 in Washington,DC * ACRS Advisory Committee on Reactor Saleguards, 88/04/13, ACRS Advisory Committee on Reactor Saleguards, 46pp 45117:233-45117:278
- 8804130436 Summary of ACRS Reactor Operators Subcommittee meeting on 680105 in Washington DC re-inservice testing at nuclear reactors.

 * ACRS - Advisory Committee on Reactor Safeguards, 88/02/01, ACRS - Advisory Committee on Reactor Safeguards, 7pp 45117:226-45117:232.
- 8804130437 Summary of ACRS 333rd meeting on 880107-08 in Washington,DC.

 * ACRS Advisory Committee on Reactor Safeguards, 88/04/13 ACRS Advisory Committee on Reactor Safeguards, 45pp 45117:182-45117:225.
- 8804130438 Summary of ACRS Thermal Hydraulic Phenomena Subcommittee meeting on 850120-21 in Los Alamos,NM re-review of documentation developed by LASL to support TRAC PFI Thermal Hydraulic Code.

 **ACRS - Advisory Committee on Reactor Safeguards 88/02/18. ACRS - Advisory Committee on Reactor Safeguards 79pp 45117:102-45117:181.
- 890122 in Albuquerque NM re review of test results of 1.6 scale model reinforced concrete containment tests 8804140059 Summary of ACRS Subcommittee on Structural Engineering meeting on
- ACRS Advisory Committee on Reactor Safeguards. 88/02/10. ACRS Advisory Committee on Reactor Safeguards. 15pp. 45121.001-45121.015.
- 8804140066 Summary of ACRS DHR Sys Subcommittee meeting on 880128 in Washington,DC re-review of NRC staff resolution position for USI A 45, "Shuldown DHR Requirements."
- (JHR Requirements. * ACRS Advisory Committee on Reactor Safeguards. 89/02/10. ACRS Advisory Committee on Reactor Safeguards. 29pp. 45121.016-45121.044.
- 8804140073 Summary of ACRS Subcommittee on Safety Research Program meeting on 880129 in Washington,DC re proposed methodology to be used by RES staff in prontizing NRC research activities.

 * ACRS Advisory Committee on Reactor Safeguards 88/02/10. ACRS Advisory Committee on Reactor Safeguards 43pp. 45121:045-45121-087.
- 8804140084 Summary of ACRS Subcommittee on Generic Items meeting on 880129 in Washington OC re-procedures being used by staff in defining/modifying scope of generic issues & USIs
- nenc issues & USIs.
 * ACRS Advisory Committee on Reactor Safeguards, 88/02/12, ACRS Advisory Committee on Reactor Safeguards, 21pp. 45118-300-45118-320.
- 8804140090 Summary of ACHS Subcommittee on TVA Organizational Issues meeting on 880202-03 in Chattanooga,TN re-review of TVA mgt reorganization 8 issues re-restart of Unit 2.
- * ACRS Advisory Committee on Reactor Saleguards, 88/03/12 ACRS Advisory Committee on Reactor Saleguards, 10pp. 45118:321-45118:330.
- 8804140100 Summary of ACRS Subcommittee on Safety Philosophy, Technology & Criteria meeting on 880208 in Washington, DC re-proposed implementation plan for safety goal policy statement Agenda & stides from presentation enct.

 **ACRS Advisory Committee on Reactor Safeguards, 89702/17, ACRS Advisory Committee on Reactor Safeguards, 89702/17, ACRS Advisory Committee on Reactor Safeguards, 12pp. 45118 331-45118.342.
 - - ery of ACRS Subcommittee on Human Factors seminar on 880210 in human factors.
 - y Committee on Reactor Safeguards 88/03/28, ACRS Advisory other Safeguards, 15pp. 45118,343-45118,357,
 - 0211-13 in Washington,DC re pro-& equipment to support advisory idwaste mgt disposal, ards. 88/02/09. ACRS Advisory 4.45120.297
 - eting on ament of Muctures

- 8804140154 Suminary of ACRS Combined Scram Sys Reliability & Core Performance Subcommittees meeting on 880219 in Washington,DC re review of LWR plant operations impact on occo reactivity control operational limits & ATWS analyses | ACRS Advisory Committee on Reactor Safeguards, 88703701, ACRS Advisory Committee on Reactor Safeguards, 88703701, ACRS Advisory Committee on Reactor Safeguards, 33pp. 45118:102-45118:134.
- 8804140163 Summary of ACRS Subcommittee on Diablo Canyon meeting on 880223-24 in Burlingame,CA re review of Diablo Canyon long term seismic program * ACRS Advisory Committee on Reactor Safeguards 88/04/07. ACRS Advisory Committee on Reactor Safeguards. 11pp. 45118:135-45118:145
- 8804140205 Submits summary of actions discussed at ACRS 334th meeting on 880211-13 in Washington,DC,including ACRS repts/ recommendations,other actions,agreements,ass,gninents & requests. KERR,W. ACRS Advisory Committee on Reactor Safeguards 88/02/29 ZECH,L W Commissioners, 4pp. 45118:168-45118:171.
- 8804140215 Submits summary of actions discussed at ACRS 335th intecting on 880310-12. In Washington,DC,including ACRS repts/ recommendations,other actions.agreements.assignments & requests & luture agenda. KERH,W. ACRS Advisory Committee on Reactor Safeguards. 88/03/24, 2ECH,L W Commissioners. 4pp. 45118.172-45118.175
- 8804180267 Transcript of ACRS 336th meeting on 880408 in Washington,DC Pp. 167-291 Supporting documentation encl
 * ACRS - Advisory Committee on Reactor Safeguards, 88/04/08, 273pp. 45126,305 45127:123
- 8804180270 Transcript of ACRS 336th meeting on 880407 in Washington DC Pp 67-166 Supporting documentation encl.
 * ACRS - Advisory Committee on Reactor Safeguards, 88/04/07, 110pp. 45126:194-45126 304
- 8804180284 Transcript of ACRS 336th meeting on 880407 in Washinton,DC Pp 1-66 * ACRS Advisory Committee on Reactor Safeguards, 88704707, 69pp. 45126,125-45126;193.
- 8804210316 Summarizes ACRS 336th meeting on 880407-09 re proposed rule on fil-ness for duly program.Endorses random chemical testing of body fluids as element in effective Miness for duly programs Recommends that rule be issued for public com-KERR.W. ACRS - Advisory Committee on Reactor Saleguards, 88/04/12, ZECH,L.W. Commissioners, 3pp. 45268,344-45266,346.
- 8804210338 Submits comments relatifectiveness of programs religeneric issues & USIs per B60918 request. KERH,W. ACRS - Advisory Committee on Reactor Sateguards 88/04/12 ZECH,L.W. Commissioners 7pp. 45324:340-45324:346.
- 8804210349 Summanzes ACRS 338th meeting on 880407-09 re updated policy state-ment on training & qualification of nuclear power plant personnel.Endorses NRC pro-posal to issue proposed policy statement for public comment. KERR,W, ACRS Advisory Committee on Reactor Safeguards. 88/04/12. ZECH,L W Commissioners 1p. 45264.080-45264.080.
- 8604210397 Informs of plans to review several nuclear power plants that have either been shut down for extended period & now being considered for restart or been de-layed in Initial startup for longer period than usual. KERR,W. ACRS - Advisory Committee on Reactor Safeguards. 88/04/12. ZECH,L.W. Commissioners. 1p. 45266.347-45266.347.
- 8804210423 Forwards ACRS Waste Mgt Subcommittee rept of Q-first technical position being developed by NRC on "Items & Activities in High Level Waste Goologic Repository Program Subj to OA Requirements" presented at ACRS at 336th meeting FRALE/R.F. ACRS Advisory Committee on Roactor Saleguards 88/04/12 STELLO,V. OIc of the Executive Director for Operations. 2pp. 45266:174-45266:175.
- 8804220204 Discusses 336th meeting of ACRS on 880407-09 re proposed resolution of USI A-47, "Safety Implications of Control Sys." Disagrees that NRC recommendations constitute resolution of USI A-47 as originally defined.
 KERRW. ACRS Advisory Committee on Reactor Safeguards. 88/04/12. ZECH,t.W. Commissioners. 3pp. 45266:341-45266:343.
- 8804280175 Discusses Interim comments resulting from several meetings w/RES to discuss means of "floshing out" May 1987 rept re plans for implementing safety goal policy councisted by Commission in 1986. KERR.W. ACRS Advisory Committee on Reactor Safeguards. 88/04/12. ZECH.L.W. Commissioners 5pp. 45262:342-45262 346.
- 8804280410 Forwards encl listed documents for transmillal to PDR.W/o encl. BARNARO E. ACHS - Advisory Committee on Reactor Safeguards. 88/04/20. MCKNIGHT, J. NRC - No Detailed Affiliation Given, 2pp. 45263:102-45263:103.
- 8804280432 Provides anecific recommendations re means by which Commission may structure resources to recove best available advice on radwaste issues.

 KERR,W. ACRS - Advisory Committee on Reactor Saleguards. 87/11/10. ZECH,L,W.

 Commissioners. 6pp. 45266.076-45266.081.
- 8804280468 Responds to 880114 ltr requesting meeting w/ACRS to clarify understanding of remarks included in transcript of ACRS 332nd meeting ACRS meetings open to public & provide for comments to be submitted for consideration. KERRW, ACRS Advisory Committee on Reactor Safeguards, 88/02/17, FREEMAN,H, RISACHER,B.A. Harford County,MD, 2pp. 45283:100-45263.101.
- 8804280555 Notification of 880505-07 meeting w/Sandia Natl Lab & B&W to Washington,DC to discuss listed items of Interest Notice of meeting published in 890322 FR. HOYLE J.C. ACRS - Advisory Committee on Reactor Saleguards 88/04/20. Spp. 45265 070-45265 074.

ADVCM NRC ADVISORY COMMITTEE

8804280273 Notice of establishment of Advisory Committee on Nuclear Wosto.Committee will provide advice & recommendations on topics, issues & activities for regulation of nuclear wasto.

IICYLE.J.C. High Lovel Wasto Licensing Support System Advisory Committee 88/04/20 Ip. 45265.090-45265.090

COMMISSION NRC COMMISSIONERS

- 8803180190 Forwards ropt for CY87 on all changes to sys,components, structures,procedures,organization or design of operating plants where such changes imposed by Commission or stall. ZECILL.W. Commissioners. 61-87-02. 88703709. REVILL,T. House of Rep., Appropriations. 6pp. 45101:111-45101.118
- 8804050343 Forwards response to 880217 fit expressing concern re-both process NRC adopted to reach decision on restart of plant & possible turning of that decision NRC taking necessary steps to assure that plant will not restart unless licensee ready. ZECH,L.W. Commissioners, 88/03/29. KENNEDY,E.M. Senate, Labor & Human Resources, 8pp. 45029:126-45029:135
- --8804050365 Expresses concerns that Commission may be considering timetable for deciding whether plant should be allowed to restart which does not give adequate consideration to targe number of rollovant factors involved. KENNEDY.E.M. Senate, Labor & Human Resources. 88/02/17. ZECH,L.W. Commissioners, 4pp. 45029.132-45029.135.
- 8804060230 Wookly info ropt for wk ending 880325 RICIMAT.A. Ofc of the Executive Director for Operations, 88/03/30, 27pp, 45029,008-45029 034.
- 8804120055 Wookly info rapt for wk anding 880401.
 RELIMITA Ofc of the Executive Director for Operations 88/04/07, 30pp. 45089:228-45089:257.
- 8804130016 Rusponds to 880212 request for NRC views on concerns raised by DOJ re Appalachian states low tovol radiwaste compact. Commission responses to questions enclosed. ZECHLL.W. Commissioners. 88/03/14. BIGEN.J.R. Senate, Judiclary. 45pp. 45101:245-45101:200.
- 8804130033 Responds to 880104 request for NRC views on H.R.3836, "Nuclear Waste Transportation Act of 1987," Commission believes subj. legislation would not significantly improve radwaste or sport fuel transportation safety. ZECH,L.W. Commissioners. 88/03/14, HOWARD,J.J. House of Rep. 15pp. 45101:291-45101:342.
- --8804130043 Forwards NRC responses to post-hearing questions from Subcommittee on Surface Transportation for inclusion in 870421 Hazardous Transportation Act hearing record. BRADBURNE,J.C. Congressional Allairs 87/07/13 HOLLINGS,E.F. Senate, Com-morco, Science & Transportation, 30pp. 45101:307-45101:336.
- --8804130050 Forwards questions propared as followup to 870421,24 & 0512 Transportation Subcommittee their parties on Hazardous Malls Transportation Act & requests five copius of responses by 870622.
 HOLLINGS,E.F. Sonato, Commerce, Science & Transportation, 87/08/05. STELLO,V. Old of the Executive Director for Operations, 6pp. 45101,337-45101,342.
- 8804130062 Rosponds to 880209 itr re compliance w/Public Law 100-202, Section 630 & repts that no appropriated funds for NRC used, subsequent to 871222 to implement or enforce agreements in Stat Forms 189,189-A or 4193.

 ZECHIL,W. Commissioners, 88/03/14 BROOKS,J. House of Rep., Government Operations. 4pp. 45101:343-46102:010.
- --8604130071 Informs that 871222 Public Law 100:202, Section 630 places limitations on implementation & enforcement of SF 189 & advises that use of & ref to form SF 189 in employment correspondence & brindings must cease until further notice BRADY, B.J. Division of Security (Pro 870413), 88/02/01, GODY, A.T. Region 1, Old of the Director, MALEY, B.J. Region 2, Old of the Director, ROY, G.W. Region 3, Old of the Director, 1p. 45101:347-45101:347.
- --8804140129 Advisos that use of SF 189-A, "Classified Info Non-disclosure Agreement (Industrial/Commercial/Non-Bovt)," must coase until turther notice 8 that any existing executed SF 189-As should be forwarded to Div of Security.

 BIADY,FI J. Division of Security (Pro 870413), 88/02/01, CROWLEY,E G. Ace-Federal Rependers, Inc. RAWLES,R.C. AT&T. FELLER,J. AT&T. Communications, 3pp. 45101:348-45101;350.
- -- 9804140142 Provides guidelines re execution of 861231 final rule revite 10/CFR25 & IOCFR95 pending outcome of into Security Oversight Ofc request for opinion of Alty General re Impact of subj legistation on SF 189-A agreement. BRADY,R J. Division of Security (Pre 870413). 88/02/01, RAE,S J. Baltimore Gas & Electric Co., RAVENSCRAFT,N. Ediow International Co., GALLI,A. GA Technologies, Inc./General Atomic Co., 4pp. 45101:351-45101:354.
- ~8604130092 Suppl Instructions to Public Law 100-202, Section 630 Advises to notify affected amployees that until further notice, form SF 189 or SF 189-A signed on or after 871222 voldable at beheat of signed but must sign nondisclosure agreement, GABFINKEL, S. Congral Sarvices Administration, 88/01/27, STELLO, V. Ofc of the Exocutive Director for Operations, 1p. 45101:355-45101:355.
- -8804130103 Provides last minute rider to Continuing Resolution for FY88 (Public Law 100-202, Section 630). Informs of plan to seak opinion of Atly General on impact of seulo (egistation on SF 169 & SF169-A & givos interim instructions.

 GARFINKEL, S. General Services Administration. 87/12/29. STELLO, V. Ofc of the Executive Offector for Operations. 14pp. 45101:358-45102.008.
- --8604130111 Provides guidalines in use of Form 4193,SCI Non-disclosure Agreement, from Ofo of General Counsel, pending receipt of documentation of legisla-tive intent. MORONEY,R.F. Central Intelligence Agency, 87/12/30. PILGER,L. NRC - No Detailed Atlaikation Given, 1p. 45102:008-45102:009.

- -8804130118 Requests into re NRC implementation of 871222 enacted Public Law 100-202 Requests for response & copies of orders, directives instructions & memoran-da that NRC created or received re subj law by 880219 BROOKS.J. House of Rep., Government Operations 88/02/09 ZECHEW Commis-sioners 1p. 45102-010 45102-010
- 8804130133 Responds to 880222 tri.forwarding JD Hawkins Itr Informs that amended Atomic Energy Act of 1954 governs NRC licensing procedures 8 that NRC may rich legally take financial hardships into consideration in making keensing decisions. PARLER, W.C. Office of the General Counsel 88/03/16 CHILEST Senate 2pp 45101.150-45101.151
- 8804130149 Responds to 880114 request for clanfication of NRC position on resident inspectors mandatory relocation & how that position evolved since 1983 US GAO rept re NRC needs in manutarming resident inspectors objectivity. ZECH,L.W. Commissioners 88/03/17 SIMORSKI,G House of Rep DURENBERGER,D. Senate 2pp 45101.189.45101:198
- --8804130172 Requests clarification re NRC position on mandatory relocation of resident inspectors & for new info developed since 1983 which caused MRC reversal of publicly stated position in this to US Congress & reasons for revorsal SIKORSKI,G. House of Rep. Energy & Commerce 88/01/14 KAMMERER C Congressional Attairs 2pp 45101 193-45101 195
- -8804130178 Requests explanation re NRC decision to rotate resident inspectors 8 how NRC plans to ameliorate hardship imposed by decision on inspectors
 DURENBENGER,D Senate, Environment & Public Works 88/01/25 KAMMERER C Congressional Allairs 1p 45101.196-45101:198
- 8804130206 Provides clarification to NRC 880217 response to 871222 fir re suggestion to amend Atomic Energy Act to provide for certain decisions on nuclear power plants emergency planning to be made provide constituent issuance ZECH.L.W. Commissioners 88/03/21 DOLERJ Senato 1p 45101 212 45101 213
- 8804130222 Responds to questions in 880315 by re NRC investigation of S WHITE manager of Ofc of Nuclear Power at TVA & discusses role of Ofc of Investigations in subjicase Assures that NRC made no attempts to dismiss Ofc of Investigation rept.
 ZECH.L.W. Commissioners 88/03/22 GEJDENSONS. House of Rep. Interior & Insular Allairs 8pp 45101 220 45101-230
- --8804130233 Requests answers to questions made by Subcommittee on general oversight. 8 investigations re alleged NRC attempt to dismiss. Ofc. of *Investigation rept about credit hity of S.Witte, director of TVA nuclear program GEUDENSON,5. House of Rep., Interior & Insular Affairs. 88/03/15. ZECHILW. Commissioners. 3pp. 45101-228-45101:230.
- 8804130247 Ack receipt of 880222 request for Natil Congress of American Indians per-licipation on NRC High Level Waste Licensing Support Sys Advisory Committee Request forwarded to HS Bellman, advisory committee facilitator ZECF1, LW. Commissioners. 88(03)/23 HARJO.S S. National Congress of American Indians. 3pp. 45103.001-45103.015.
- -- 8803160284 Requests continued tribal representation on NRC Advisory Committee for Negotiated Rulemaking
 HARJO,S S National Congress of American Indians 88/02/22 ZECH L.W Office of
 the Secretary of the Commission, 4pp. 45103 004-45103 016
- 8804130278 Ack receipt of 880321 tir, supporting NRC granting of full power OL to util ZECH, L.W. Commissioners. 88/03/29 SWEENEY, M. House of Rep. 1p. 45103.144-45103.147.
- -8804130280 Informs of support w/o qualification of NRC granting full power OL to util SWEENEY,M. House of Rep. 88/03/21, ZECH,LW. Commissioners. 3pp. 45103 145-45103:147.
- 8804130283 Responds to 860303 request for comments on INPO draft. Principles for Enhancing Professionalism of Nuclear Personnel." NRC agrees w/8 endorses subj ZECH.L.W. Commissioners. 88/03/31, PATE,2 T. Institute of Nuclear Power Operations. 1p. 45103.152-45103.159
- ~8804130284 Forwards draft of "Principles for Enhancing Professionalism of Nuclear Personnel," for comments & suggestions. PATE, ZT. Institute of Nuclear Power Operations 88/03/03 ZECH, L.W. Commissioners. 7pp. 45103.153-45103.159.
- 8804130357 Advises that temporary waiver of compliance not issued in conjunction w/ emergency licensing amend granted for plants for first time.per guidance from HR Denton 870227 memo. Twelve waivers have been issued since Sholly rule in effect STELLOY. Old of the Executive Director for Operations. 88/04/06 ROBERTS.T M Commissioners. 2pp. 45117 016-45117 017.
- 8804200407 Weekly info rept for wk ending 880408. REHM,T.A. Ofc of the Executive Director for Operations, 88704714, 31pp, 45179,230-
- 8804210195 Forwards responses to questions in 880303 ftr Commissioner Bernthal does not concur w/responses to Questions 7 & 10.
 ZECH,L.W. Commissioners. 88/03/17. SIMPSON,A.K. Senete, Environment & Public Works. 37pp. 45191:180-45191-251.
- --8804210214 Requests NRC analysis of constitutionality of legislation to reform & reorganize NRC, documents re NRC correspondence w/ OMB since 871101 on NRC reorganization & reform & response to listed questions
 SIMPSONAK Senate, Environment & Public Works 88/03/03 ZECH,L.W Commissioners, 35pp. 45191:217-45191:251.
- 8804280518 Weekly into repl for wk ending 880415 REHM T.A. Old of the Executive Orector for Operations 88/04/20 28pp 45270 354. 45271.021

CONTRACT NRC CONTRACTS AND MODIFICATIONS

- 8804010193 Noblication of contract execution "Comprehensive Aging Assessment of Cricuit Breakers/Refays Phase II," awarded to Wy'e Labs.
 MEARSE SD Contract Neepolation Branch: 2 FIN D-2004. NRC 04-88-083. 88/03/22.
 GUSTAVER Office of Nuclear Regulatory Research. Director (Post 860720).
 AGGARWAL,S NRC No Detailed Affiliation Given. 1p. 44949-030-44949.149.
- --8804D1D195 Contract: "Comprehensive Aging Assessment of Circuit Breakers/Retays Phase II." awarded to Wylo Labs SMTHEW Wyle Laboratories THOMPSON,R 0. Division of Contracts (Post 870413) FIN D-2004 NRC-04-88-083 88/03/22
- 8804040229 Notification of contract execution. Mod 12.16 "Program to Support Operator Licensing Activities Contractor Sonalysis,inc
 BELLS Contract Administration Branch, FIN D-1332, NRC-03-86-054, 88/03/28,
 BAJWA-SS, Planning, Program & Management Support Branch, (Post 870411)
 PULSIPHER,K, NRC - No Detailed Affiliation Given, 1p. 44974 257-44974 258
- --8804040237 Mod 12.providing incremental funding for FY88.to "Program to Support Operator Licensing Activities" Sonalysts, Inc. WIGGNS,E J. Davision of Contracts (Post 870413) FRN D-1332. NRC-03 86-054 88/03/28 1p. 44974:258-44974.258
- 8804050078 Not-fication of contract execution Mod 6.to "Technical Assistance for Vendor & Contractor Insps." Contractor SMC O'Donnell & Assoc. Inc VELEZ.P. Contract Administration Branch. FIN B-8727. NRC-05-66-166. 88/03/24 BALWAS.S. Planning. Program & Management Support Branch. (Post 870411). BERKSON,H. NRC No Detailed Affiliation Given. 1p. 44996-358-44998-360.
- --8804050090 Mod 6 providing incremental funding which increases amount obligated & designating new project manager,to "Technical Assistance for Vendor & Contractor Insps: SCM O'Donne'l & Associates, Inc. (Iormerly O'Donneli & Associates, Inc.). WIGGINS, E. J. Division of Contracts (Post 870413). FIN 8-8727. NRC-05-86-166-887-03/24. 2pp. 44996-359-44996-369.
- 8804050252 Notification of contract execution,Mod 7.to "Development of NRC Simulation Facility Evaluation Program" Contractor: Micro Analysis & Design FIELDS.J.A. Contract Administration Branch NRC-03-85-054. 88/02/18. RUSSELL,W.T. Division of Licensee Performance & Quality Evaluation (Post 870411). PULSIFER,K. NRC No Detailed Affiliation Given 1p. 44997;163-44997:165
- ~8804050255 Mod 7,modifying Section G.6, "Travel Relimbursement," to incorporate travel regulations in accordance w/federal travel regulations. LAUGHERY.K.R. Micro Analysis & Design. WIGGINS.E.J. Division of Contracts (Post 870413). NRC 03-65-054. 86/02/19. 2pp. 44997-164-44997.165
- 8804050270 Notification of contract execution.Mod 7,to "Phase II Plant Input & Development." Contractor.Scientech.Inc.
 HAGEY,H. Contract Administration Branch. FIN D-1655. NRC-04-85-124. 88/03/25.
 GUSTAVE,R. Program Management, Policy Development & Analysis Staff (Post 8704/3). TOYMASSIAN,H. NRC. No. Detailed Affiliation Green. 1p. 44997:177-4907-138.
- -8804050284 Mod 7,changing project officer,fo "Phase II Pfant Input & Development."
 Scientech, Inc. WIGGINS,E J. Division of Contracts (Post 870413). FIN D-1655. NRC-04-85-124, 88/03/25 1p. 44997-178, 44997-178.
- 8804050291 Notification of contract execution, Mod 7.to "Facility Sys Analysis Support." Contractor: SAIC. WEEHAN B. Contract Administration Branch, FIN 0-1011, NRC-02-85-007, 88/03/25, BAJWA,S.S. Planning, Program & Management Support Branch (Post 870411), WEST,K.S. NRC - No Data-led Affrication Given, 1p. 44997:205-44997:207.
- --8804050297 Mod 7.correcting contractors address, exercising option to extend period of performance for 1 yr & increasing ceiling of contract, to "Factity Sys Analysis Support" * Science Applications International Corp. (formerly Science Applications, Inc.). WIGGINS,E J. Division of Contracts (Post 870413). 88/03/25. 2pp. 44997:206-
- 8804050307 Not-fication of contract execution Mod 1,to "Scintillation Fiber Detection for In Viva Endescopic Internal Dosimetry." Contractor Ctr for Planning & Research, Inc. DORSEY,M. Contract Administration Branch. NRC-0-87-385 88/03/25, GUSTAVE,R. Office of Nuclear Regulatory Research, Director (Post 880720). NELLIS,D. NRC No Detailed Affiriation Given. 1p. 44997-218-44997:220.
- -8804050314 Mod 1, extending contract to 880430 as required to complete work per contractor 880202 ltr.to "Scintillation Fiber Datection for In Viva Endoscopic Internal Dosimetry." LAURING.R.K. Center for Planning Research,Inc. WIGGINS,E.J. Division of Contracts (Post 870413). NRC-04-87-365, 88/03/25, 2pp. 44997:219-44897:220.
- 8804050312 Notification of contract execution Mod 10.to "Conventional Sys Development" Contractor Mathiech, Inc. VELEZ,P.A. Contract Administration Branch FIN 0-1403. NRC-33-86-263, 88/03/25. SCOTT.S. Division of Computer & Telecommunications Services (Post 870413). OOLLECK,A NRC No Detailed Affiliation Given 1p. 45029.122-45029.123.
- --8804050329 Mod 10.increasing funds to "Conventional Sys Development."
 * Mathtech, Inc. WIGGINS,E.J. Division of Contracts (Post 870413). FIN D-1403. NRC-33-86-263, 88/03/25. 1p. 45029:123.45029:123.
- 8804050333 Notification of contract execution, Mod 2.to "General Modelling of Condensation for Reactor Applications (SIBR Phase II)." Contractor:Creare.Inc. MEEHAN, B. Contract Administration Branch. NRC-40-86-127. 88/03/29. GUSTAVE, P. Program Management, Policy Development & Analysis Staff (Post 870413). TROUTMAN,C. NRC No Detailed Affiliation Given. 1p. 44997:221-44997:222.
- ~8804050336 Mod 2,extending period of performance,to "General Modeling of Condensation for Reactor Applications (SBIR Phase II)"
 HICKIN,IA. Creare, Inc. WIGGINS.E. J. Division of Contracts (Post 870413). NRC-04-88-127, 88/03/29 1p. 44897:222-44997:222

- 8804050387 Notification of contract execution Mod 6.to "Technical Assistance in Dovi oping & Implementing & Procedures for Insp of Operating Reactors During Dutages Contractor: Parameter,Inc. HAGEY,H. Contract Administration Branch. FIN 8-8746. NRC-05-86-158, 88/03/2 8AJWA,S.S. Planning, Program & Management Support Branch (Post 8704): WEST,S. NRC No Detailed Affiliation Given. 1p. 45029:141-45029:143.

 - -8804050381 Mod 6,changing name of project officer & providing incromental functing, "Technical Assistance in Developing & Implementing & Procedures for Insp of Operating Reactors During Outages."

 Parameter, Inc. WIGGINS,E. J. Division of Contracts (Post 870413). FIN B-874 NRC-05-88-158, 88/03/25, 2pp. 45029:142-45029:143.
 - 8804050399 Notification of contract execution, Mod 6, to "Shuttle Bus Svcs Contractor Ariport Connection, Inc.
 MEEHAN,B. Contract Administration Branch. FIN D-2326. NRC-10-88-224. 88/03/2
 MATTIA,M.J., QUEEN,D. NRC - No Detailed Affiliation Given. 1p. 45029:16
 - -8804050404 Mod 6,amending shuttle bus svc schedule to delete Willste stop & ac express schedule,provide additions & extend svc for two months, to "Shuttle Bours". BUCKINGHAM, M.E. Airport Connection, Inc. WIGGINS, E.J. Division of Contracts (Po. 870413). FIN D-2326. NRC-10-86-224. 88/03/21. 9pp. 45029:184-45029:172.
- 8804050419 Notification of contract execution, Mod 10,to "Technical Assistance in Suport of NRC Licensing Activities." Contractor Science Applications Intl Corp. FIELDS, J.A. Contract Administration Branch. FIN D-2109. NRC-03-87-029. 89/03/2 BAJWA,S.S., WEST,S. Office of Nuclear Reactor Regulation, Director (Post 870411 CORLEY,D. NRC No Octaled Affiliation Given. 1p. 45029:186-45029:190.
- --8804050428 Mod 10,meking administrative changes & providing addit funds, to "T-chincal Assistance in Support of NRC Licensing Activities."
 Science Applications International Corp. (formerly Science Applications, Incremental Provided Pro
- 8804060019 Notification of cooperative agreement,Mod 1,to "Maint & Operation LPDR." Contractor:Pottstown Public Library.
 SMITH.P. Contract Negotiation Branch-1. FIN D-2418. NRC-10-87-332. 88/04/0 GRIMSLEY.D.H. Division of Rutes & Records (Post 870413). 1p. 45018:00 45018:007.
- --8804060025 Mod 1, extending period of performance, to "Maint & Operation of LPDR ARNOLD, K.M. Polistown, PA SMITH, P. Division of Contracts (Post 870413). FIN 12416. NRC-10-87-332. 88/04/01. 2pp. 45018.006-45018:007.
- 8804060134 Notification of contract execution,Mod 2,to "ITS End User Support Sw. (Interm)." Contractor:Wordpro,Inc. VELEZ,P.A. Contract Administration Branch. FIN D-1399. NRC-39-88-214. 88/03/2 SCOTT,R.S. Division of Information Support Services (Post 870413). VANOUSER, NRC No Detailed Atfillation Given. 1p. 45019:261-45019:252.
- --8804060138 Mod 2.increasing funds,to "ITS End User Support Sycs (Interim)," Wordpro, Inc. WIGGINS,E.J. Division of Contracts (Post 870413). FIN D-1399. NRG 39-88-214. 88/03/29. 1p. 45019:252-45019:252.
- 8804060193 Notification of contract execution, Mod 7,to "Technical Support Sycs for Data Telecommunication Equipment." Contractor: SBA. Subcontractor: Pailen John so VELEZ.P. Contract Administration Branch. FIN D-1869. NRC-10-85-263. 88/03/2 EYSYMONTT, G.P. Division of Computer & Telecommunications Services (Po 870413). BROWNELL, B. NRC - No Detailed Affiliation Given. 1p. 45019:30:
- -8804080200 Mod 7 providing incremental funding to, "Technical Support Svcs for Dai Telecommunication Equipment,"

 * Small Business Administration. * Pellen-Johnson Associates, Inc. WIGGINS.E. Div. slon of Contracta (Post 870413). FIN D-1869. NRC-10-85-263. 88/03/29. 45019:304-45019:304
- 8904080221 Notification of contract execution, Mod 18 to "Review & Evaluation of Comenche Peak Program Plan." Contractor: Teledyne Engineering Svos. HAGEY,H. Contract Administration Branch. FIN 8-1338. NRC-03-85-067. 88/03/2: GRIMES,CI. Ofc of Special Projects. LYONS,J. NRC No Detailed Affeliation Giver 19. 45018:322-45018:324.
- --8804060233 Mod 18.adding incremental funds to "Review & Evaluation of Comanch Peak Program Plan."

 **Teledyne Engineering Services, WIGGINS.E.J. Division of Contracts (Post 870413 FIN B-1338, NRC-03-85-067, 88/03/29, 2pp. 45018:323-45018:324.
- 8804080259 Notification of contract execution Mod 2.to "Evaluation of Integral Effector Fuel Element Thermal Analysis Methodologies." Contractor:Texas A&M Resource Foundation.
 VELEZ,P.A. Contract Administration Branch. NRC-04-87-109, 88/03/29. GUSTAVE. Program Management, Policy Development & Analysis Staff (Post 870413). SCOTT, NRC No Detailed Attiliation Given. 1p. 45018:334-45018:335.
- -8804060270 Mod 2,extending expiration date to 880531, to "Evaluation of Integral Elects of Fuel Element Thermal Analysis Methodologies."

 TREAT, J. Texas A&M Univ., College Station, TX, WIGGINS,E.J. Division of Contrac (Post 870413). NRC-04-87-109, 88703/24. 1p. 48018:335-45018:335.
- 8804080266 Notification of contract execution, Mod 19, to "Integral Sys Test Progra Once-Through Integral Sys & Multiloop Integral Sys Test Component: Contractor: B&W.
 BELLS. Contract Administration Branch. FIN 0-1734. NRC-04-83-168 86/03/2 GUSTAVE R. Office of Nuclear Regulatory Research. Director (Post 860720). LEE NRC No Detailed Athillation Olivers. 1p. 45019:178-45019:210.

- -8804060275 Mod 19 incorporating owners group into cost sharing Phase IV changing statement of work & cost sharing ratios Phase IV & extending period of performance to "Integral Sys Test Program-Once Through Integral Sys & Mu't poop In-
- togral...

 10gral...

 10gral...
- 8804060332 Notification of contract execution, Mod 5, to "Virginia Regional Se smographic Network." Contractor Virginia Polytechnic Inst & State Univ.
 MEEHAN,B. Contract Administration Branch. NRC-04-85-121. 88/03/29. GUSTAVE,R.
 Program. Management, Policy Development. & Analysis. Staff. (Post. 870413).
 MCMULLEN,R. NRC No Detailed Affiliation Given. 1p. 45017-270-45017-272.
- -8804060335 Mod 5.deleting Subsection G.2, "Overhead" & adding new Subsection G.2, "Induct Rates & Fringe Benefits Rates," to "Virginia Regional Seismographic STEISS.A.W Virginia Polytechnic Institute & State Univ. Blacksburg. VA. WIGGINS.E.J. Division of Contracts (Post 870413) NRC-04-85-121. 88/03/29 2pp 45017-271-45017 272
- 8804060402 Notification of contract execution, Mod 9,10 "Document Distribution Svcs "Contractor GPO.
- VELEZ,P. Contract Administration Branch. FIN D-1872. NRC-10-85-264, 89/03/29. SCOTT,S. Division of Information Support Services (Post 970413). BLANTON,J. NRC-No Deta:led Affikation Given. 1p. 45019.001-45019.003.
- -8804080407 Mod 9,Increasing total amount obligated to, "Occument Distributing
- Overnment Printing Office, WIGGINS,E J. Division of Contracts (Post 870413) FIN 0-1872, NRC-10-85-284, 88/03/29, 2pp. 45018 002-45019.003.
- 8864120010 Noblication of grant execution "Downhale Strong Motion Studies of Fmax & Significance for Embedded Structures" awarded to Regents of Univ of CA. SMITH.P.A. Diversion of Contracts (Post 870413). FIN G-1131. NRC-04-88-138-88/03/29 GUSTAVE.R.P. Program Management, Policy Development & Analysis Statt (Post 870413). MURPHY,A. NRC No Dotated Affiliation Given. 1p. 45089-059-45089:081.
- --8804120038 Grant. "Downhole Strong Motion Studies Studies of Fmax & Significance for Embedded Structures," awarded to Regents of Univ of CA MACMILLAN,S. Certornia, Univ. of, Santa Berbara, CA THOMPSON,R D. NRC No. Detected Affirmtion Given: FIN G-1131. NRC-04-88-138. 88/03/29. 2pp. 45089.060-
- 8804130143 Notification of contract execution. "Operation & Maint of NUDOCS," awarded to contractor:SBA & subcontractor: Statistica.inc.
 FLEENOR.C.M. Contract Negotiation Branch-1. FIN D-1874. NRC-39-88-211. 88/03/
 28. SCOTT, R.S. Division of Information Support Services (Post 870413).
 COLLINS,M.D. NRC No Dotalled Affiliation Given. 1p. 45101:162-45101:188.
- 8804130148 Ltr contract. "Operation & Meint of NUDOCS," awarded to contractor.58A & subcontractor.5ttatistica,inc. SMITH,LP. Small Business Administration BOSE,D.D. Statistica, inc. HAGAN,T.F. D. vision of Contracts Post 870113). FIN D-1874. NRC-39-88-211. 88/03/28. 36pp. 45101:153-45101:188.
- 8804140495 Notilication of contract execution, Mod 14.to "Technical Assistance in NRC Insp & Enforcement Operations." Contractor Parameter, Inc. BAZIN, J. Contract Administration Branch Fills 8745, NRC-05-85-157, 88/03/28, BAJWA,S.S. Office of Nuclear Republishon, Director (Post 870411), WEST,K.S., BERKSON,H. NRC. No Detailed Alfiliation Given, 1p. 45130:146-45130-148.
- ~8804140507 Mod 14.Increasing colling amount 8 providing incremental funds to "Technical Assistance in NRC Insp & Enforcement Operations."
 LOFY, RA Paramoter, Inc. WIGGINS, E. J. Division of Contracts (Post 870413), FIN 8-8745, NRC-05-85-157-88/03/28, 2pp. 45130:147-45130.148
- 8804150063 Notification of contract execution, Mod 4,to "Northeastern Seismic Research Program Task 5." Contractor:Research Foundation of State Univ of New York. Nork. Sectl. S. Contract Administration Branch. FIN D-1610. NRC-04-85-113. 88/03/30. GUSTAVE.R. Program Management. Policy Development. & Analysis Staff (Post 870413). ZURFLUEH,E. NRC - No Detailed Affiliation Given. 1p. 45139-131-45139,136
- --8804150074 Mod 4.exercising option for first yr extending duration of contract penod, providing funding, changing project officer & increasing calling, to "Northeastern Seismic Research Program Task 5." WINTERS, P. A. New York, State Univ. of, Albany, NY, WIGGINS, E.J. Division of Contracts (Post 870413). FIN D-1610. NRC-04-85-113. 88/03/30. Spp. 45139-132-45139.136.
- 8804150065 Notification of contract execution,Mod 4,to "Operating Reactor Plant Specific Roviews." Contractor SBA. Subcontractor:Viking Sys (nt) HAGEY.H. Contract Administration Branch. FIN D-1762. NRC-03-87-028. 88/03/30. 8AJWA,S.S. Planning, Program & Management Support Branch (Post 870411). POSLUSNY,C. NRC No Detailed Attiliation Given. 1p. 45133:195-45133:196.
- --8804150079 Mod 4,Increasing lunding to, "Operating Reactor Plant Specific Reviews."
 Small Business Administration. Viking Systems International, WIGGINS,E. Division of Contracts (Post 870413). FIN D-1762. NRC-03-87-028, 88/03/30. 1p. 45133:196-
- 8804150067 Notification of cooperative agreement: "Maint & Operation of LPDH," 804150067 Notification of cooperative agreements. American Ballotte awarded to Hope College. SMITH,P. Contract Negotiation Branch-1. FIN D-2416. NRC-39-88-23B. 88/04/11. GRIMSLEY,H. Division of Rules & Records (Post 870413). SOUDER,J. NRC - No Detailed Affiliation Given: 1p. 45133:172-45133:194.
- --8894150082 Cooperative agreement: "Maint & Operation of LPDR," awarded to Rope College.
 JUTH,C.L. Hope College, Holland, Ml. SMITH,P. Division of Contracts (Post 870413).
 FIN 0-2416, NRC-39-88-238, 68/04/11, 22pp. 45133:173-45133:194.

- 8804150069 Notification of grant execution, Mod 1, to "Seventh Inti-Congress on Aerosols in Medicine (ISAM)." Grantee Univ of Rochester Medical Cit.
 HAGEY.H. Contract Administration Branch FIN G-1121 NRC-G-04-87-094 88/03/31
 GUSTAVE.R.P. Office of Nuclear Regulatory Research Director (Post 860720)
 ROECKLEIN,A. NHC No Detailed Afficiation Given 19 45134-018 45134-019
- -- 8804150151 Mod 1 changing project officer to "Seventh Intil Congress on Aerosols in Medicine (ISAM). "Rochester, NY. WIGGINS.E. D.vision of Contracts (Post 870413). Fin G-1121. NRC-G-04-87-094. 88/03/31 1p. 45134.019.45134.019
- 8804150076 Notification of contract execution.Mod 1.to "Test Specimens From Damaged TMI-2 Reactor Bottom Head " Contractor MTR Associnc HAGEY.H. Contract Administration Branch. FIN D-2072. NRC-04-88-086 88/03/31. HOUSTON.R.W. Division of Reactor Accident Analysis (Post 870413). VANHOUTEN.R. Office of Nuclear Regulatory Research, Director (Post 860720) 1p 45134-015-45134-017
- 8804150086 Notification of contract execution Mod 1.to Research Provilization Contractor SBA Subcontractor Scientech,Inc HAGEY,H. Contract Administration Branch FIN D-2064, NRC-04-87-089 88/03/28 GUSTAVER, Program Management, Policy Development & Analysis Staff (Post 870413) PITTMAN,J. NRC - No Detailed Affiliation Given, 1p. 45133:206 45133-209
- -8804150094 Mod 1,providing incremental funds to Tasks III & IV.to "Research Prioriti-BAKER, J. Smell Business Administration GBARRONDO, L.J. Scientoch, Inc. WIGGINS, E.J. Division of Contracts (Post 870413) FIN 0-2064 NRC-04-87-089 887 03728. 3pp. 45133.207-45133.209.
- 8804150161 Notification of contract execution,Mod 20,to "Integral Sys Test Program Once-Through Integral Sys & Multiloop Integral Sys Tost Components" Contractor 88W.
 BELL,S. Contract Administration Branch. FIN D-1734 NRC-04-83-168 88/03/22 GUSTAVE.R. Office of Nuclear Regulatory Research, Director (Post 860720) LEE.R. NRC No Detailed Affiliation Given 1p 45134-359-45134-360.
- --8804150175 Lir Contract NRC-04-83-168,Mott 20,providing incremental funding to "Integral Sys Test Program Once-Through Integral Sys & Mu**loop Integral Sys Test Components."

 LIKASIK,M Babcock & Wilcox Co. FIN D-1734. NRC-04-83-168 88/03/04 CURÁSIKM Babcock & Wilcox Co. FIN D-1734. NRC-04-83-158 88/03/04 WIGGINS,E.J Division of Contracts (Post 870413). 1p. 45134-350-45134-360.
- 8804150179 Notification of contract execution, Mod 10.to 'Operation & Meint of Info Technology Svcs Training Lab " Contractor: Graduate School USDA VELEZ,P. Contract Administration Brench, NRC 10-86-213, 87/09/24 GOLDMAN,P.J. VELEA F. CONTROL ROMAINSTERION BIBRON. NRC-10-86-213. B7/09/24. GOLDMAN,P.J. OILC of Personnel (Post 870413). MTCHEM,B. NRC - No Detailed Atlifation Given 1p. 45140239-45140223.
- --8804150186 Mod 10.providing scope of work clarification for Sinet Training under Section C.1.2,Tesk 3,Paragraph b of contract & increasing ceiting amount,to "Operation & Maint of Info Technology Svcs Training Lab"
 POOLE,G.R. Agriculture, Dept. of, Graduate School, Washington, DC, WIGGINS,E.J. Division of Contracts (Post 870413), NRC-10-86-213, 87/89/24, 4pp. 45140-220-45140-220. 45140-223
- 8804150182 Notification of contract execution Mod 3,to "Operation of Cir for Nuclear Waste Regulatory Analyses FFRDC." Contractor Southwest Research Inst MACE M. Contract Negotiation Branch 1. NRC 02-88-005. 88/03/23. FUNCHES J L Program Management. Policy Development & Analysis Staff (Post 670411) BUNTING, J.O. NRC No Detailed Affiliation Given. 1p. 45140 224-45141 182.
- --8804150192 Mod 3.providing administrative changes,to "Operation of Ciritor Nuclear Waste Regulatory Analyses FFREC." CHATTEN.R.E. Southwest Research Institute MACE.M.H. Division of Contracts (Past 870413). NRC 02-88-005, 88/03/23, 31pp. 45140-225-45140-265.
- --8804150199 Notification of contract execution.Mod 4.to "Operation of Cir for Nuclear Waste Regulatory Analyses FFRDC." Contractor Southwest Research Inst. MACE.M Contract Negotiation Branch-1. FIN D-1070-8. NRC-02-88-005. 88/03/23 FUNCHES.Jt. Program Managament, Policy Development & Analysis Staff (Post 870411), BUNTING.J.O. NRC No Detailed Attribution Given 1p 45140-256-45140-258
- --8804160202 Mod 4,providing Incremental funding in stated amount,to "Operation of Cit for Nuclear Waste Regulatory Analyses FFRDC."

 Southwest Research Institute, MACE.M.I. Division of Contracts (Post 870413) FIN D-1070-8. NRC-02-88-005. 88/03/23. 2pp. 45140 257-45140 258
- 8804150193 Notification of contract execution Mod 11.to "Program to Support Operator Licensing Activities." Contractor: Sonalysis.inc.
 BELL,S. Contract Administration Branch. FIN D-1322. NRC-03-88-054. 88/03/11.
 BAJWA,S.S. Planning, Program & Management Support Branch (Post 670411).
 PULSIPHER,K. NRC No Detailed Affiliation Given. 1p. 45148-337-45148-338
- --8804150196 Mod 11, making changes to individuals listed under Section H.1.key personnel clause, to "Program to Support Operator Licensing Activities." PETERSEN,L.R. Sonalysts, Inc. WIGGINS,E.J. Division of Contacts (Post 870413). FIN D. 1322. NRC-03-86-054. 86/03/11. 1p. 45148-338-45148-338
- 8804150195 Forwards NRC safety assurance definitions reviewed & concurred in by mgt in RES to be used as basis for continued work under Contract NRC-04-87-089 PTTMANJ.W. Office of Nuclear Regulatory Research, Director (Post 860720), NRC-04-87-089, 98/04/07, YBARRONDO,L.J. Scientech, Inc. 10pp. 45148.339-45148.348.
- 8804150210 Notification of contract execution, Mod 5.to "Operation of Cir for Nuclear Waste Regulatory Analyses FFRDC." Contractor, Southwest Research Inst. MACE, M.H. Contract Negotiation Branch 1, FIN D-1035-8 NRC-02-88-005-89/03/31, FUNCHES, J.L. Program Management, Pottor Development & Analysis Staff (Post 870411), BUNTING, JO. NRC No Detailed Afficient Green, 2pp. 45140:259-45140:261

-8804150228 Mod 1,providing incremental funding in stated amount to "Operation of Citritor Nuclear Regulatory Analyses - FFRDC:" Scullwest Research Institute - HAGAN T.F. Division of Contracts (Post 870413) FIN B-6666, NRC 02-88-005-88/01/27, 2pp. 45140-262-45141-182

8804150237 Notification of contract execution Mod 5,to "Continuity of Govt Programs" Contractor Sys Research & Applications Corp. HAGEY,H. Contract Administration Branch FIN B-8761. NRC-05-86-154—88/03/30. SPESSARO,R.L. Office for Analysis & Evaluation of Operational Date. Director WIESS,B. NRC - No Detailed Affikation Given. 1p. 45139.064-45139.066.

--8804150240 Mod 5 providing incremental lunds to "Continuity of Govt Programs"

Systems Research & Applications Group WIGGINS,E J. Division of Contracts (Post 870413). FIN B-8761. NRC-05-86-154, 88/03/30, 2pp. 45139-065

8804 (\$0263 Notification of confract execution Mod 11 to "Conventional Sys Development "Contractor Mathioch,Inc. VELEZ,P Contract A

VELEZ.P. Control: Administration Branch. FIN 8-1403 NRC-33-86-263. 83/04/05. EYSYMONITIG. Division of Computer & Telecommunications Services (Post 870413). DOLLECK,A. NRC - No Detailed Alfiliation Given. 1p. 45133-085-45133-087.

--8804159268 Mod 11.correcting clorical error on 880325 Mod 10 & providing incremental funding, to "Conventional Sys Development."

* Mathlech, Inc. BELL, S. Division of Contracts (Post 870413), FIN 8-1403, NRC-33-86-263

8804150310 Not-lication of contract execution Mod 5.to "Support Svcs for Evaluation of Sovero Accident Phenomena." Contractor, Battolle Columbus Labs HAGEY,H. Contract Administration Branch FIN D-1595 NRC-04-87-066 88/04/04 GUSTAVE,R. Program Management, Policy Development & Analysis Staff (Post 870413) WALKER,T. NRC - No Detailed Affiliation Given 1p. 45133-088-45133-089.

-8604150336 Mod_5 increasing obligation amount to "Support Svcs for Evaluation of

Severe Acadent Phonomena.

* Battelle Memorial Institute, Columbus Lahoratories BELLS. Division of Contracts (Post 870413). FIN D-1595, NRC-04-87-866-88/04/04. 1p. 45133-089-45133-089

8894150329 Not fication of contract execution Mod 3.to "Application of Methodology to Evaluate Aging & Svc Effects on Plant Performance (SBIR Phase II) " Contractor SEA Consultants, Inc.

ARCOTTO, G. Division of Engineering (Post 870413), VORA, J. NRC - No Detailed At-il ation Given 1p. 45133 090 45133.091.

-- 8804150346 Mod 3.granting no cost extension for 45 days,to "Application of Methodology to Evaluate Aging & Svc Effects on Plant Performance (SBIR Phase II)."

* SEA Consultants, inc. WiGGINS.E.J. Division of Contests (Post 670413). FIN 0-1701. NRC-04-86-125, 88/04/05. 1p. 45133.091-45133.091

8804180307 Notification of contract execution: "Lateral Files for One White Flint North," awarded to ACS Old Furnium
FLEENOR, C. M. Contract Negotiation Branch-1 FIN B-2468 NRC 39-88-248, 88/04/
05 SPRINGER, M. L. Old of Consolidation (Post 870413), PLEASANT, E. NRC - No De-

lailed Affiliation Green. 1p. 45150 280-45150 316

-- 8804180308 Contract, "Lateral Files for One White Flint North," awarded to ACS Oto MURPHY, A.G. ASC Office Ferniture, HAGAN, T.F. Division of Contracts (Post 870413) FIN B-2468, NRC-39-88-248, 88/04/05, 38pp. 45150 281-45150 316

8804190147 Notification of contract execution,Mod 2,to "Severe Accident Phenomena Nati Corpulation in RCS" Contractor Fluid Physics IND HAGEY,H. Contract Administration Branch. NRC-04-87-369. 88/04/08. GUSTAVE,R Program Management, Policy Development & Analysis Statt (Post 870413). HAN,J NHC - No Detailed Affiliation Given 1p. 45165 298-45165 297.

--8804190152 Mod 2-providing 2-month extension until 880530 at no addit cost,to "Severe Accident Phenomena Natil Circulation in RCS." TRACLR M. Fluid Physics IND. BELLS. Division of Contracts (Post 870413) NRC-04-87-369 88704708. 1p. 45165-987-45165-297.

8804190174 Notification of contract execution.Mod 6.to "Mandatory Supervisory Development Program Training" Contractor USDA Graduate School VELEZ,P. Contract Branch NEC-10-87-207 88/04/13 GOLDMAN.P.J., SPECTOR.A NRC - No Detailed Affiliation Green 1p 45164.347. 45164-348

-6804190179 Mod 6 increasing funding to "Mandatory Supervisory Development Program Training"

* Agriculture, Dopt of, Graduale School, Washington, DC BELL,S. Division of Contracts (Post 870413) NRC-10-87-207. 88/04/13 1p. 45164.348-45164.348

8804190346 Notification of contract execution: Keying of Occupational Radiation Expo-sure Info," awarded to OCR Sycs.inc.
MEARSE.SD Contract Negotistion Branch-2 FIN D-2065. NRC-04-88-078, 88/04/08 GUSTAVE.R. Program Management, Policy Development & Analysis Staff (Post 870413) BROOKS,B. NRC - No Detailed Affiliation Given. 1p. 45156:145-45156-307.

--8804190348 Contract: "Keying of Occupational Radiation Exposure Info." awarded to OCR Sycs, Inc BOYEJA,R.K. OCR Services, Inc. THOMPSON,R.D. Drinsion of Contracts (Post 870413) FIN D-2085, NRC-04-88-078, 88/04/08, 162pp, 45158,146-45158,307

8804200279 Notification of contract execution,Mod 8,to "Data Entry Support Svcs for Region III "Contractor.NORCOM Intl Corp.
BAZIN.J Contract Administration Branch. NRC-30-86-360. 88/04/13, ROY,G. Region 3, Ofc. of the Director, STAHULAK.M. NRC - No Defailed Affiliation Given. Ip. 45179.312-45179.313.

--8804200289 Mod 8,changing mailing address to "Data Entry Support Sycs for Region

Norcom International Corp. (formerly Noriega Communications Corp.). BELL.S. Division of Contracts (Post 870413). NRC 30-86-360. 68/04/13. 1p. 45179.313-45179 313

45179 309 45179 311

--8804200310 Mod 5.rewsing list of deliverables & changing project officer,to "Field Observations of Northbeast Northcolnics". LEWS.JP. Cosimba Univ., Now York, NY. WIGGINS,E.J. Division of Contracts [Post 870413]. NHC-04-85-111-88/04/12, 2pp. 451/9 310-45178 311.

8804200381 Noblication of contract execution,Mod 22 to "Technical Assistance for Fa-crities Requiring Special Assistance." Confractor Paramoter,Inc. MEEFIANTB D. Contract Administration Branch. FIN D-2101 NHC-05-86-156, 687047. 12 RICHARDSON,S.D. Ofto of Special Projects. CORLEY,D.J. NRC - No Datalled At-Litation Given. 1p. 45179-174-45179-175.

-- 8604200362 Mod 22, adding incremental funding to "Technical Assistance for Facilities Reguing Special Assistance " * Parameter, Inc. BELL.S D vision of Contracts (Post 870413) FIN D-2101, NRC-05-86-156 88/04/12, bp. 45179 175-45179 175

8804200398 Notification of contract execution,Med 6,to "Preventive, Remedial & On-Call Maint of Data General Computers & Peripheral Equipment " Contractor,Computer

Egineering Assoc, Inc.
VELEZ,P. Centract Administration Branch FIN 8-1663 NRC-33-86-276 88/04/05
SCOTT,S. Division of Information Support Services (Post 870413) SEEMERMAN J.
NRC - No Dela/ed Afficial on Given 1p. 45179.261-45179.274.

--8804200401 Mod 6 modifying equipment list to add new equipment to Sys C.D.F. & G. & increasing contract colling amount to "Preventive, Romed at & On-Call Maint of Data General Computers & Per Peral Equipment" KEYS, PR. Computer Engineering Associates, Inc. WIGGINS, E.J. Division of Contracts (Post 870413) FIN B-1663. NRC-33-86-276. 88/04/05. 13pp. 45179.262-45179.274.

8804200414 Not fication of contract execution,Med 4 to "Improved Methods of Characterization & Modeling Contaminant Transport Around High Level Hadwaste Sites."

Contractor Univ of Arizona DORSEY,M. Contract Administration Branch. FIN D-1672. NRC 04-86-123. 89/04/12. GUSTAVE,R. Program Management, Policy Development & Analysis Staff (Post 870413). RANDALL,J. NRC - No Datated Affination Given: 1p. 45191-113-45191-114.

-9804200425 Mod 4 providing incremental funding to "Improved Methods of Characterization & Modeling Contaminant Transport Around High Level Radwista Stos" Anzona, Univ. of, Tucson, AZ BELLS, Division of Contracts (Post 870413). FIN D-1672 NRC-04-86-123 88704/12 bp 45191.114-45191.114.

8804200445 Notification of contract execution. Mod 9,to "Archival Storage & Rolated

Sves "Contractor Data Base Coline
DORSEY,M Contract Administration Branch NRC-10-86-256-88704705, MAGEE,W A
Downson of Information Support Services (Post 870413) WADE,R NRC - No Detailed
Afficiation Given 1p. 45179 211-45179 212

~8804200449 Mod 0.correcting certing amount to "Archival Storage & Related Svcs "
Data Base, inc. WIGGINS,E.J. Division of Contracts (Post 870413), NRC-10-80-256
88/04/05, 1p. 45179-212-45179-212

8804200451 Noblication of cooperative agreement,Mod 1,10 "Maint & Operation of LPDR" Cooperator Arkansas Tech Uriiv.
HOYLE A Cantract Negotiation Branch-2. FIN D-2416 NRC-10-87-333 88/04/04 GRIMSLEY,DH Division of Rules & Records (Post 870413). SOUDER,J NRC - No Detailed Aftiliation Given 1p. 45191:115-45191.118.

--8804200462 Mod 1,stating payment instructions,to "Maint & Operation of LPDR" VAUGHN,W.A. Arkansas Tech Univ., Russellvile, AR. HOYLE,A. Division of Contracts (Post 870413). FIN 0-2416. NRC:-10-87-333. 88/04/04. 2pp. 45191.117-45191:118.

8804200461 Notification of contract execution, Mod 5, to "Cooperative Human Reliability Evaluation Program Contractor NUS Corp
MEEHAN,B Contract Administration Branch FIN D-1812 NHC-04-86-104 88/04/11
GUSTAVE,R Program Management, Policy Devalument & Analysis Staff (Post 870413). RYAN,T.G NRC No Detailed Aff

--8804200475 Mod 5,providing incremental funding raising contract coiling & revising Task 7.16 "Cooperative Human Reliability Evaluation Program" EDMONSONL R. NUS Corp. WIGGINS, E. J. Division of Contracts (Post 870413) FIN D-1612 NRC-04-86-104 88/04/11. 3pp 45179-214-45179-218

8804200465 Notification of contract execution, Mod 1,10 "Access to INPO NPRDS."

Contractor INPO.
VELEZ,P A Contract Administration Branch FIN D-1894 NRC-33-87-229 88/04/06
AMENTA,J A Office of Administration & Resources Management, Director (Post 870413). SCOTT,S. NRC - No Detailed Altherium Given 1p 45191-126-45191 129

--8804200469 Mod 1,exercising first option of period & providing addit funds for additions of access to NRRDS,to "Access to INPO NIPROS."
VER STEEG.C.J. Institute of Nuclear Power Operations. WIGGINS,E.J. Division of Contacts (Post 8/0413). FIN D-1894. NRC-33-87-229. 88/04/06. 3pp. 45191.127-

8804200482 Notification of contract execution, Mod 20,to "Technical Assistance for Fa-citities Requiring Special Assistance," Contractor Parameter, Inc. MEEHAN,B. Contract Administration Branch, FIN 0-2102, NRC-05-86-158, 88/04/12 AXELROD,JA Otto of Special Projects, CORLEY,D.J. NRC - No Detailed Alfillation Given 1p. 45191,010-45191.011

-- 8804200485 Mod 20, adding incremental funding to "Technical Assistance for Facilities

Requiring Special Assistance."

* Parameter, Inc. BELL.S. Division of Contracts (Post 870413). FtN D-2102. NRC-05-86-156, 88/04/12. 1p. 45191.011-45191:011.

8804200494 Notification of contract execution: "Equipment in Support of Video Telecon-terencing Pilot Program," awarded to Concept Communications, Inc. FLYNN,M.J. Contract Negotiation Branch-1, FIN B-8155, NRC-39-88-180, 88/03/28 AMENTA.J. Deputy Director for Information Resources Management (Post 870413) KIRKJ, NRC - No Detailed Alfiliation Given, 1p. 45191-016-45191-048.

- --8804200504 Contract "Equipment in Support of Video Teleconferencing Plot Program," awarded to Concept Communications.Inc.
 HAYNES,L'S Concept Communications. Inc. HAGANIT F. Division of Contracts (Post 870413) FIN 8-8155 NRC-39.88-180-88/03/28-32pp. 45191.017-45191.048
- 8804200566 Notification of contract execution, Mod 8,to "Classified Waste Paper Dostruction Project." Contractor Simkins Industries Inc.
 DORSEY M. Contract Administration Branch. NRC-10-82-403-88/03/18-BRADY,R-J.
 Division of Security (Post 8/0413). BURNSIDE,W. NRC-. No Detailed Affination Given1p. 45179 217-45178-218
- -8804200570 Mod 8,6xtending period of performance,to "Classified Waste Paper De-Struction Project: RUSSELLV Smikins Industrios, Inc. WIGGINS.E.J. Division of Contracts (Post 870413) NRC-10-82-403-88/03/18-1p-45179.218-45179.218
- 8804200577 Notification of contract execution Mod 8 to "Development of NRC Simulation Facility Evaluation Program" Contractor: Micro Analysis & Design FIE(DS, J.A. Contract Administration Branch NRC 03-85-054, 88704/14 ROE, J.W. Division of Licensee Performance & Quality Evaluation (Post 8704/11) PULSIFER, NRC No Datasted All.hation Given 1p. 45191-049-45191-050
- -8804200583 Mod 8,extending contract at no additional to "Development of NRC Simu-LAUGHERY,K.R. Micro Analysis & Dosign. BELL,S. Division of Contracts (Post 870413) NHC 03-85-054 88/04/14 1p. 45191.050 45191.050
- 8804210181 Notification of contract execution, Med 21.16 "Technical Assistance for Fa-Chilos Requiring Special Assistance "Contractor Parameter Inc.

 MEEHAN,B.O. Contract Admiristration Branch: Fix 0-2101, NRC-05-86-156, 89/04/
 12 RICHARDSON,S.D. Otc of Special Projects. CORLEY,D.J. NRC - No Defailed Al-
- -8804210190 Mod 21 providing incremental funding to "Technical Assistance for Facrities Requiring Special Assistance."
 Parameter, Inc. BELL'S Division of Confracts (Post 870413). FIN D-2101, NRC-05-86-156, 88704/12, 1p.
- 8804210197 Notification of cooperative agreement "Maint & Operation of LPDR," awarded to North Control Michigan Collego RUNION,O. Contract Regolaritor Branch: 2 FIN D-2416, NRC 39-89-237, 88703/31 GRIMSECY,O H. Division of Rules & Records (Post 870413) SOUDER,J NRC No Dataled Atlitation Given: 1p. 45200-227-45200-234
- -8804210210 Cooperative agreement. "Maint & Operation of LPDR," swarded to North Central Michigan College
 GRANDSTAFF,E. North Central Michigan College, Potoskey, MI RUNION,D Division
 of Contracts (Post 870413) FIN D-2416 NRC-39-88-237 88/03/31, 7pp 45209-228-45200 234
- 8864210306 Notification of contract execution,Mod 7,to "Georgia/Alabama Regional Sesmographic Network." Contractor:Georgia Toch Research Corp.Georgia Institutional Institution of Technology. Technology: MEEHAN,B. Contract Administration Branch, NRC-04-85-122, 88/04/07, GUSTAVE,R.
 - Program Management, Policy Development & Analysis Staff (Post 870413). ZURFLEUTH,E NRC No Detailed Affiliation Given 1p. 45192.108-45192.110.
- ~8804210309 Mod 7,defeting Section G 2 to "Georgia/Alabama Regional Seismographi
- c Notwork." LINDBERG,B J. Georgia Institute of Technology, Atlante, GA. WIGGINS,E. Division of Contracts (Post 870413), NRC-84-85-122, 88704/07, 2pp. 45192-109-45192.110
- 8804220061 Notification of contract execution, Mod 6.to "Support Svcs for Evaluation of Severe Accident Phonomena." Contractor Batelle Columbus Lebs.
 HAGEY,H. Division of Contracts (Post 870413), FIN D-1595. NRC-04-87-066, 88/04/18, GUSTAVE,R. Program Management, Potcy Development & Analysis Staff (Post 870413), WALKER,T. NRC No Defailed Affiliation Given 1p. 45200 357-45200 359
- --9804220068 Mod 6,changing key personnel in Suction H.1 8 providing incremental lunds,to "Support Svcs for Evaluation of Sovere Accident Phenomena".

 *Baltelle Memoral Institute, Columbus Laboratorics, WIGGINS,E D. Division of Contracts (Post 870413). FIN D-1595. NRC-04-87-086 88/04/18. 2pp 45200 358-
- 8804220069 Notification of contract execution, Mod 2,to "Research Prioritization"
- Contractor Scionicch.inc.
 HAGEY,H. Contract Adm.nistration Branch. FIN ID-2064, NRC-04-87-089, 88/04/18, CUSTAVE,R. Program Management, Policy Development, 8 Analysis Staff (Post 870413), PITTMANJ, NRC No Detailed Affiniation Given 1p. 45201.016 45201.018.
- -8804220072 Mod 2.providing incremental funds to perform work under Task IV,to "Re-
- search Prioritization."
 Scientecti, Inc. WIGGINS,E.J. Division of Contacts (Post 870413). FIN D-2064. NHC-04-87-089. 88/04/18. 2pp. 45201:017-45201:018.
- 8804220117 Notification of contract execution, Mod 9, to "Teleprocessing Svcs Support"
- --8804220121 Mod 9.increasing funds & calling & extending period of performance.to "Foloprocessing Svcs Support" GUGLIELMO.F. Justico. Dept. of. WIGGINS.E.J. Division of Contracts (Post 870413) FIN D-1378 NRC-33-86-265.
- 8804220127 Notification of contract execution, Mod 7, to "Technical Assistance for B04220127 Notification of contract systemicity of the contract of Wester Sves, Inc.
 DORSEY.M. Contract Administration Branch. FIN B-8762 NRC-05-86-155. 88/04/05
 BAJWA,S. BERRSON,H. Office of Nuclear Reactor Regulation, Director (Post 870411). BAILEY,H. Ofc. of the Executive Director for Operations. 1p. 45201:105-45201:106.
- --8804220129 Mod 7,increasing funds to "Technical Assistance for Design Insp Svcs."
 Wester Services, Inc. WIGGINS E. Division of Contracts (Post 870413). FIN B-8762. NRC-05-86-155. 88/04/05. 1p. 45201:106-45201:106.

- 8804220156 Notification of contract execution,Mod 3 to "Sys for Generating Long Streamflow Records for Study of Flooris of Long Return Period" Contractor Lins'oy,Kraege: Assoc,Ltd
 - Program Management, Policy Development & Analysis Stall (Post 670413) NICHOLSON,T NRC No Obla/fed Affiation Given 19 45201 114-45201 115
- -8804220162 Mod 3 adding 4-month no cost extension to contract period of performance to, "Sys of Generaling Long Streamflow Records for Study of Floods of Long ance to, "Sys Return Penod KRAEGER,B.A. Linsley, Kraeger & Associates Ltd BELLS Division of Contracts (Post 870413) NRC-04-95-143-88/04/08-1p. 45201-115-45201-115
- 8804270247 Notification of contract execution, Mad 3,to "ITS End User Support Sycs (Interim)** Contractor Wordpround VELEZIP Contract Administration Branch FIN D-1399 NRC-39-88-214 88/04/18
- SCOTTIRIS Division of Information Support Services (Post 670413) VANDUSERIK NRC No Detailed Affiliation Given Tp. 45324,347-45324,349
- ~8804270253 Mod 3,extending expiration date,increasing contract ceruing & obtigated amounts & charging key personnol clause.to "TIS End User Support Svcs (Interim)" HOWARD.J.L Wordpro, Inc. WIGGINSE J. Division of Contracts (Post 870413) FIN D-1399 NRC-39-88-214, 88704718 2pp 45324 348-45324 349.
- 8804280070 Notification of centract execution. "Technical Support for NDE Van," awarded to TET.Inc.
 - DEMARCO D Craision of Contracts (Post 870413). FIN B 8370 NHC-28 88-269 887-04/15 JCHNSTON,W V. Region 1, Old of the Director STROSNIDER, J NRC No Detailed Allifation Given 1p. 45275 391-45276 887
- -8804280087 Contract "Technical Support for NDE Vers," awarded to TET, Inc. PAYNE, D.F., TET, Inc. THOMPSON.R.D. Division of Contracts (Post 870413). FIN B-8370 NRC-28-88-269-88/04/15, 147pp. 45275-302-45276-087.
- 8804280245 Notification of contract execution.Mod 10,10 "Tremal Mixing" Contractor.Univ of California Santa Barbara VELEZ P.A. Contract Administration Branch NRC-04-86-111, 88704/11 SHERONB.W. Division of Reactor & Plant Systems (Post 870413) TOVMASSIAN.H. NRC No Detailed Afficiation Given 1p. 45266-335-45266-336
- --8804280264 Mod 10.extending period of hertormanco to 880715.to "Thermal Mixing" MCAMILLAN.S. California, Univ. cf., Santa Barbara, CA. WIGGINS,E.D. Division of Contracts (Post 870413). (ARC-04-86-111. 88/04/11. 1p. 45266-336-45266-336
- 8804280283 Notification of contract execution Nod 9,to "Thorma! Mixing" Contractor Univ of California, Santa Barbara VELEZ P.A. Contract Admiristration Branch NRC-04-86-111, 88/04/21, SHERON B.W. Office of Nuclear Regulatory Research, Oirsctor (Post 860720) TOVMASSIAN,H, NRC No Detailed Affiliation Given 1p. 45269-203-45269-205
- --8804280340 Mod 9 modeling period of performance & incorporating within scope change,to "Thormat Mixing" MACMILLANS California Univ. of, Santa Barbara, CA. WIGGINS,E.J. Division of Contracts (Post 870413), 88/04/21, 2pp, 45269 204-45269 205
- 8804289309 Notification of contract execution, Med 6,to "Lease of Truck, Van W/Cab." Contractor Ryder/Jacobs Leasing
 HAGEY,H. Contract Authinistration Branch. FIN D-2324. NRC-10-84-218. 88/04/19
 MATTIA.M.J. D.viscon of Faculties & Operations Support (Post 870413). SMALLEY,M.
 NRC - No Dotated Athlaton Gwon 1p. 45324-048-45324-047.
- --B804280322 Mod 6 extending period of performance to "Leaso of Truck, Van W/Cab" SMALLEY M. Ryder/Jacobs. Loasing. (crme::y. Jacobs. Leasing). WIGGINS, E.J. Dwison of Contracts (Post 870413). FIN. D-2324. NRC-10.84-218. B8/04/19. Lp. 45324.047. 45324.047.
- 8804280315 Notification of contract execution,Mod 9,to "Radiation Monitoring Program Requirements" Contractor Colorado Dept of Health KNOX.E. Contract Administration Branch FitN 8-8501 NRC-31-83-668 88/03/07 MEYER DM Region 4, Cit of the Director NICHOLAS.) B NRC No Detailed Affin
- --8804280333 Mod 9 providing CY88 lunds & incorporate revised Attachment A.Io "Radiation Monitoring Program Requirements" THIELENIL Cotorado, State of WIGGINS,E.J. Division of Contracts (Post 670413) FIN 8-8501 NRC-31-83-668 88/02/08 2pp. 45265-115-45265-116
- 8804280343 Notification of contract execution Med 9.to "Update of NRC Rules & Regulations" Contractor SBA Subcontractor Metrolec, Inc.
 MEELHAN B. Contract Administration Branch, FIN D-2418, NRC-10-85-248, 88/64/14.
 GRIMSLEY, DH. Dwisson of Rules & Records, (Post 870413) MEYER, DI. NRC Na
 Detailed Affination Grvon, 1p. 45269-220-45269-227.
- --8804280382 Mod 9,revising wage determination & exercising option to extend contract only riper 880122 technical proposal, revised on 850224,for "Update of NRC Rufes & Regulations"

 SWAILES,M.P. Small Business Administration NELSON J.E. Metrolec, Inc. WIGGINS, E. J. Ovision of Contracts (Post 870413). FIN D-2418 NRC-10-85-248 88/04/14. 6pp. 45269-221-45289-227.
- 8804280420 Notification of contract execution, Mod 5.to "Lease of Truck Van W/Cab."
 - Contractor Ryder/Jacobs Leasing
 HAGEY,H Contract Administration Branch FIN D-2324 NRC-10-84-218 89/04/19
 MATTIALM J. Division of Facilities & Operations Support [Post 870413] QUEEN.D
 NRC No Detaced Alliation Given 1p. 45270-294-45270-295.
- -8804280451 Mod 5,extending period of performance for one month at no additional cost to "Lease of Truck, Van W/Cab."

 SMALLEY,M Rydor/Jacobs Leasing (formerly Jacobs Leasing) WIGGINS,E Contract
 Administration Branch, FIN D-2324, NRC-10-84-218, 88/04/19 1p. 45270.295-45270 295.

8804280429 Not fication of contract execution Mod 3 to "Survey of State & Tribal Errer-gency Response Capabilities for Radiological Transportation Incidents" Contractor Indiana Univ Foundation BAZINJ, Contract Administration Branch, FIN D-1054-7, NRC-02-87-001, 88/04/21.
TEN EYCK,E O Division of Safeguards & Transportation (Post 870413), GOADON,L
NRC - No Detailed Altihation Given, 1p. 45286 073-45266 074

-8804280435 Mod 3,detelling Task II, "Emergency Response Plan Review From Statement of Work," to "Survey of State & Tribal Emergency Response Capabilities for Radiological Transportation Incidents." FARCUHARI,WE Indigna Univ. Foundation, Indianapolis, IN. WIGGINS.E.J. Division of Contracts (Post 870413). FIN D-1054-7, NRC-02-87-001, 88704/21. 1p. 45266.074-45266.074.

8804280459 Notification of contract execution,Mod 17.to "Degraded Piping Program - Phase II." Contractor Batteite Columbus Dv.
HAGEY,H. Contract Administration Branch. FtN 8-8134. NRC-04-84-103 88/02/17.
GUSTAVE,R. Program Management, Policy Development & Analysis Staff (Post 870413). MAYFIELD,M. NRC - No Detailed Alfihation Given 1p 45284-093-45384-064.

-8804280471 Mod 17 providing incremental funds to "Degraded Piping Program -

**Battelle Memonal Institute, Columbus Laborationes WIGGINS,E.J. Division of Contracts. (Post. 870413). FIN. B-8134. NRC-04-84-103. 88/02/17. 2pp. 45284.094-

8804280495 Notification of contract execution, Mod 11, to "Ofc Moving Svcs." Contractor SBA Subcontractor Alliance Moving & Storage, Inc. HAGEY, H. Contract Administration Branch. NRC 10-86-255. 88/03/08. MATTIA, M. J. Division of Facilities & Operations Support (Post 870413). ESTEP, G. NRC - No De-tailed Affiliation Given. 1p. 45265-036-45265.038.

--8804280501 Mod 11 increasing contract calling to "Otc Moving Svcs." SWAILES,M.P. Small Business Administration RILEY,J.A. Alliance Moving & Storage, Inc. WIGGINS,E.J. Division of Contracts (Post 870413). NRC-10-86-255. 88/03/08. 2pp. 45265-037-45265-038.

of contract execution, Mod 4, to "Microcomputer." Notification Contractor-Gov Technology Svc,Inc.
VELEZ.P. Contract Administration Branch, NRC-33-87-252, 88/04/21, SCOTT,S. Division of Computer & Telecommunications Services (Post 870413), GIANIOS,C. NRC-No Detailed Affiliation Given. 1p. 45265-076-45265-077.

--8804280574 Mod 4,modifying Section B i & C 2.1 to decrease contract ceiling amount,to "Microcomputer." WILLIAMS,G Government Technology Services, Inc. WIGGINS,E.J. Division of Contracts (Post 870413). NRC-33 87-252; 88/04/21. 2pp. 45285.076-45255 077.

8804280590 Notification of contract execution Mod 4.to "Technical Assistance in Devalopment of Engineering Critoria & Requirements for Afternative Near-Surface Mothods, "Contractor USAE Waterways Experiment Station.

KNOX,E. Contract Administration Branch. Fith 0-1071-8. NRC-02-87-006. 88/04/13. FUNCHES,JL. Program Management, Policy Devalopment & Analysis Stati (Post 8704.13). KANE,J. NRC - No Detailed Affiliation Given. 1p. 45264.071-45264.074.

-- 9804280596 Mod 4.adding Tasks 4 & 5.extending period of performance & increasing obligated amount,to "Technical Assistance in Development of Engineering Criteria & Requirements for Alternative Near-Surface Methods for Disposal..."
TRAXLER.G. Army, Dept. of, Army Engineer Waterways Experiment Station. WIGGINS.E.J. Division of Contracts (Post 870413). FIN D-1071-8. NRC-02-87-006. 88/04/13. 3pp. 45254.072-45264.074.

8804280607 Notification of contract execution, Mod 5,to "Sealing of Boreholas & Shafts in Salt." Contractor, Univ of Arizona DORSEY, M. Contract Administration Branch. FIN D-1192. NRC-04-86-113. 88/04/20. GUSTAVE, F. Program Management, Policy Development & Analysis Staff (Post 670413). PHILLIP, J. NRC - No Detailed Alfiliation Green. 1p. 45265 078-45265 079.

--8604280609 Mod 5 deobligating funds to "Seating of Boreholes & Shafts in Saft."
Arizona, Univ. of, Tucson, AZ, WIGGINS, EJ, Division of Contracts (Post 870413).
FIN D-1192, NRG-04-86-113, 88/04/20, 1p. 45265 079-45265,079.

8804280615 Notification of contract execution,Mod 1,to "Prediction of Check Valve Performance & Degradation in Nuclear Power Plant Sys." Contractor.Kalsi Engmeening.Inc.

DORSEY.M Contract Administration Branch. NRC-04-87-375, 88/04/20. GUSTAVE,R. Program Management, Policy Development & Analysis Staff (Post 870413), FARMER.W.S. NRC - No Detailed Affiliation Given, 1p. 45269-094-45269-096.

--8804280619 Mod 1,extending contract for 30 days at no additions to, "Prediction of Check Valve Performance & Degradation in Nuclear Power Plant Sys." KALSI,MS. Kalsi Engineering, Inc. WIGGINS,E. Dwisson of Contracts (Post 870413). NRC-04-87-375, 88/04/20, 2pp. 45269.095-45269.096.

8604260643 Notification of contract execution, Mod 3, to "Improved Methods of Characterizing & Modeling Contaminant Transport Around High Level Radwaste Sites." Contractor Univ of Atizona. DCRSEY-M. Contract Administration Brench. FIN D-1672. NRC-04-86-123. 88/04/20. GUSTAVE.R. Program Management, Policy Development & Analysis Staff (Post 870413). RANDASI. J. NRC - No Detailed Athibation Given. 1p. 45269:188-45269:170.

-3804280647 Mod 3,increasing funding & contract ceiling,to "Improved Methods of Characterizing & Modeling Contaminant Transport Around High Level Radwaste Sites." Sites."

KLEESPIE, J.M. Arizona, Univ. of. Tucson, AZ WIGGINS, E.J. Division of Contracts (Post 870413). FIN D 1872. NRC-04-86-123. 88/04/11. 2pp 45269-169-45269.170.

8604280663 Notification of contract execution,Mod 11,to "Technical Assistance in Support of NRC Licensing Activities." Contractor:Science Applications Intl Corp. FIELDS.J. Contract Administration Branch. FIN D-1311. NRC-03-87-029. 88/04/20. 8AJWA.S.S., WEST,S. Office of Nuclear Reactor Regulation, Director (Post 870411). CORLEY.D. Ofc of Special Projects. 1p. 45263-296-45263-299.

-8804280868 Mod 11,providing addl funds,to "Technical Assistance in Support of NRC

Uconsing Activities:

Science Applications International Corp. (formerly Science Applications, Inc.).
WIGGINS, E.J. Division of Contracts (Post 870413), FIN D-1311. NRC-03-87-029. 887-04/20, 3pp. 45263:297-45263:299.

8804290067 Natrication of contract execution Mod 10.to "Technical Assistance in Geo-physical Methods for Site Charaterization." Contractor.Weston Geophysical Corp-MEEHAN,B. Contract Administration Branch. NRC-02-84-001. 88/04/19. ROE.J.W. Program Management. Policy Development & Analysis Staff (Post 870413). IBRAHIM,AB, NRC - No Detailed Affitiation Given. 1p. 45279.197-45279.199.

-8804290072 Mod 1,revising Task 2 of statement of work,to "Technical Assistance in Geophysical Mothods for Sire Charatorization." FANNON,M. Weston Geophysical WIGGINS.E. Division of Contracts (Post 870413), NRC-02-84-001, 88704/19, 2pp. 45279-198-45279-199.

8804290099 Notification of contract execution.Mod 4.to "Presentation of 2-Day Course Entitled, Regulatory Process." Contractor: Regulatory Group.
MEEHAN.B. Contract. Administration Branch. NRC-10-86-216. 88/04/19.
GOLDMAN.P. Ofc of Personnel (Post 870413). BASSIN,C. NRC - No Detailed Affiliation Given. 1p. 45322-215-45322-217.

--8804290103 Mod 4 extending period of performance to 880531 at no additional cost to govi,to "Presentation of 2-Day Course Entitled, Regulatory Process."
EMERY, F.J. Regulatory Group, Inc. WIGGINS, E.J. Division of Contracts (Post 870413). NRC-10-86-218. 88/04/19. 2pp. 45322.216-45322.217.

8804290190 Notification of contract execution,Mod 6.to "Field Observations of Northeast Neotectonics." Contractor Trustees of Columbia Univ. DCRSEY,M. Contract Artministration Branch. FIN D-1581. NRC-04-85-111, 88/04/18. GUSTAVE,R. Program Management, Policy Development & Analysis Staff (Post 870413) MCMULLEN,R. Office of Nuclear Regulatory Research, Director (Post 860720) 1p. 45284:354-45284:356.

-8604290228 Mod 6,adding incremental funding to "Field Observations of Northeast

Neotectonics."
* Columbia Univ., New York, NY, WIGGINS,E.J. Contract Administration Branch. FIN D-1581, NRC-04-85-111, 88/04/18, 2pp. 45284:355-45284:356.

8804290191 Notification of contract execution,Mod 6.to "Virginia Regional Seismographic Network." Contractor Virginia Polytechnic Inst & State Univ. MEEHAN,B. Contract Administration Branch. FIN D-1597. NRC-04-85-121. 88/04/19. GUSTAVE,R. Program Management, Policy Development & Analysis Staff (Post 8704/3). MCMULLEN,R. NRC No Detailed Affiliation Given. 1p. 45324:279-45324.20 45324 281.

--8804290196 Mod 6,extending period of performance for 1-yr period & ratering celling.to "Virginia Regional Seismographic Network." STEISS,A.W. Virginia Polytechnic Institute & State Univ. Blacksburg, VA. WIGGINSE, J. Division of Contracts (Post 870413). FIN D-1597, NRC-04-85-121, 887 04/19, 2pp. 45324:280-45324:281.

FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

8804050101 Denies 880322 appeal to DH Grimstey 871216 denial of FOIA request for records re V Stello 870113 memorandum to S Hayes Denied records may interfere w/ ongoing enforcement proceeding Decision final. STELLO.V. Of

8804050107 Appeals 880114 denial of request for records described in App A & B. CONNOR,L. Doc-Search Associates. 88/02/11. GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 1p. 45009:354-45009:358.

8804060082 FOIA request for documents re New England Nuclear Co violation of NRC rules, regulations & guidelines concerning interstate packaging, shipping & classification of radioactive mati during 1981 & 1982.

HEIKE, PR. Affiliation Not Assigned, 88/03/01, NRC - No Detailed Affiliation Given. 2pp. 45018 200-45018 201.

8804060068 Final response to FOIA request re documents. Forwards document listed in App A.Document also available in PDR.
GRIMSLEY.D.H. Division of Rules & Records (Post 870413). 88/03/29. HEIKE,P.R. Affiliation Not Assigned. 2pp. 45018:202-45018:208.

8804060084 FOIA request for all documents re Insp Rept 50-458/87-30 conducted during Dec 1987.
PLETTINGER,H.A. Affiliation Not Assigned. 88/02/21, GRIMSLEY,D.H. NRC - No Detailed Affiliation Given. 1p. 45018.212-45018:212.

8804060090 Final response to FOIA request for documents re finsp Rept 50-458/87-30.Forwards App B documents Apps A & 8 documents available in PDR, GRIMSLEY,D.H. Division of Rules & Records (Post 870413), 88/03/29. PLETTINGER,H A. Affiliation Not Assigned. 3pp. 45018:213-45018:223.

--8804060099 Hand written notes & news article on plant control room deficiencies, Altihation Not Assigned, 88/03/29, 6pp. 45018:216-45018:223.

8804060122 Final response to FOIA request. No records subj to request located.
GRIMSLEY, D.H. Division of Rules & Records (Post 870413), 88/03/29, CONNOR, L. Doc-Search Associates, 1p. 45018;226-45018;229.

8804060128 Partial response to FOIA request for documents App M documents withheld (ref FOIA Exemption 5).
GRIMSLEY,D.H. Division of Rules & Records (Post 870413), 88/03/30. WEISS,E.R. Harmon & Weiss. 3pp. 45019:243-45019.247.

8804060152 Appeals denial of FOIA request for rept entitled, "Visit to Mohave Generating Station to Review Steam Line Rupture." Contends that NRC has not met burden of describing matters delated or explaining reasons for detetions. ZEMAN,J.S. Haight, Dickson, Brown & Bonesteel 88/02/17. Oic of the Executive Director for Operations. 2pp. 45018:249-45018.254.

8804060180 Responds to appeal re denial of FOIA request for rept entitled, "Visit to Mohave Generating Station to Review Steam Line Rupture." App A document denied (ref FOIA Exemption 4), STELLOY, Olivision of Rules & Records (Post 870413) 88/03/29. ZEMAN,J.S. Halght, Oickson, Brown & Bonesteel. 2pp. 45018.255-45018:256.



- 8804060264 Denies 880201 appeal of DH Grimsley 880127 denial of FOIA request for withheld into re. JC Haynes case.No legitimate public interest in release of subjinto, outweighing privacy of individuals.info withheld per FOIA Exemptions 6 & 7. STELLO,V. Oft of the Executive Director for Operations 88/04/01. EPSTEIN.K.C. Plain Dealer, Cloveland, OH. 2pp. 45018.336-45018.337.
- 8804060273 Appeals DH Grimsley 870127 denial of portion of FOIA request for docu-ments re JC Haynes case. EPSTEIN,K C. Plain Dealer, Cleveland, OH. 88/02/01, NRC No Detailed Affiliation Given. 1p. 45018.338-45018:345.
- 8804060310 Appeals denial of FOIA request for App B documents withhold in entirety (let FOIA Exemption 7) Meeting w/Oic of Administration,Div of Rules & Records & OGC to discuss ments of appeal requested CONNOR,L. Doc.Search Associates, 89/02/11, GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 1p. 45017:257-45017:257.
- 8804060316 Responds to 880211 appeal of FOIA request for author 880501 memo, denied by DH Grimsloy 880111 response Document encl. STELLO,V. Oto of the Executive Director for Operations, 88/03/29 CONNOR,L. Doc-Search Associates, 1p. 45017.258-45017.266
- --9804060331 Documents simultaneous 870430 to/cons w/S White & Fouchard. STELLO,V. Ofc of the Executive Director for Operations, 87/05/01. Ofc of the Executive Director for Operations, 1p. 45017:259-45017:266.
- 8804060361 FOIA request for R Fraley 850928 memo & minutes of 99th ACRS meeting on 68071-13 & 21.

 SCHADRACK,M.A. O'Melveny & Myors 88/03/16 NRC - No Detailed Affiliation Given 4pp. 45019.011-45019.014.
- 8804060359 FOIA request for Stello 870908 memo to Commission,w/oncl,re assess-ment of NRC Const Insp Program at River Bond & all periodic regional insp program assessment repts written since 1890. CONNOR,L. Doc-Search Associates. 88/01/18. Division of Rules & Rocords (Post 870413). 1p. 45029.001-45029.001
- 8804060377 Final response to FOIA request for documents.Forwards App A documents App Λ documents also available in POR Bill for fees associated w/request will be sent.
 GRIMSLEY, D.H. Division at Rules & Records (Post 870413). 88/03/30.
 SCHADRACK, M.A. O'Melveny & Myers. 2pp. 45019:015-45019:170.
- -8804060404 Discusses questions relsed by ASLB during Malbu hearing re-seismic design & quotes statements from draft USC&GS rept. Draft minutes of ACRS 99th meeting on 680711-13 in Washington, DC encl. FRALEY, R.F. ACRS Advisory Committee on Reactor Safeguards. 65/09/28. ACRS Advisory Committee on Reactor Safeguards. 154pp. 45019:017-45018.170.
- 8804060385 Partial response to FOIA request for documents re NRC regional Insp programs. GRIMSLEY,D.H. Division of Rules & Records (Post 870413), 88/03/28. CONNOH,L. Doc-Search Associatos. 2pp. 45028.002-45029.007.
- ~8507030700 Forwards program assessment of regional lnsp activities over past yr. Assessment attempts to most both quantitative & subjective info. Requests leed-back re improvement of process.

 PARTLOW.J.G. Div of Inspection Programs,IE (850212-870413). 85/06/26.

 DENISE, BANGART,R.L. Region 4. Ofc of the Director. 4pp. 45029.004-45029.007.
- 8804070117 FOIA request for rept dtd 870901 re aflagations about incident at plant on 861231 concorning ordering of plant manager back into plant after drinking at new y/s eve party.

 MAXWELL.B. Cosmos Broadcasting Corp. 88/03/07, NRC - No Detailed Affiliation Given. 2pp. 45043-286-45043-287.
- 8804070123 Final response to FOIA request. Records requested under FOIA 87-612 & this request still being withhold due to ongoing Investigation.
 GRIMSLEY, D.H. Division of Rules & Records (Post 870413). 88/03/29. MAXWELL, B. Cosmos Broadcasking Corp. 1p. 45040:288-45043:288.
- 8804080135 FOIA request for all records re nuclear accident in 1957 at Windscale plant in England Plant since renamed Sellafield.
 GOLDMAN,P.A. Public Citizen Litigation Group, 88/03/08. BERNTHAL,F.M. Commissioners. 1p. 45078; 166-45078; 166.
- 8804080137 Final response to FQIA request.App A document end & available in PDR. GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 88/04/04. GOI.DMAN,P.A. Public Critzen Litigation Group, 2pp. 45078:167-45078:170.
- --8804080138 Responds to 760330 request for into re fires at Windscale & Hinkley Point on 571010 & 560721, respectively Pries at Windscale not modified & restarted due to fact that new Calder Hall reactors producing Pu. CAMPBELL,J.J. United Kingdom, Govt. of. 78/04/02, LAFLEUR,J.D. Office at International Programs, Director (Pre 870413). 2pp. 45078:169-45078:170.
- 8804110257 FOIA request for D Beckman employment dates as NRC resident inspector at plant.

 ZLATOS,B. Pittsburgh Press Pittsburgh,PA 88/04/11. NRC - No Detailed Affiliation Given. 1p. 45078;171-45078;171.
- 8804110274 Final response to FOIA request.Forwards App A document. Document par-billy withheld (ref FOIA Exemption 6).Beckman was resident inspector at facility from late 1970 until 1982. GRIMSLEY, D.H. Division of Rules & Records (Post 870413). 88/04/05. ZLATOS.B. Pittsburgh Press Pritsburgh,PA, 3pp. 45078:172-45078:176.
- -8604110293 Partially deleted computer printout of DA Beckman svc record as of 880325. * NRC - No Detailed Attiliation Given, 88/04/05. 1p. 45078:175-45078:175.
- 8804120002 Final response to FOIA request for documents No addit records located. QRIMSLEY, D.H., Division of Rules & Records (Post 870413), 88/04/05. CONNOR, L. Doc-Search Associates. 1p. 45089:057-45089:058.
- 8804120084 FOIA request for documents & Info generated re listed items, including Safety Significance Assessment Team insp & review of allegations. CONDIT.R.E. Government Accountability Project. 89/03/01. GRIMSLEY,D. Division of Rules & Records (Post 870413). 2pp. 45100:301-45100:302.

- 8804120095 Partial response to FOIA request for documents Forwards App B documents App A & B documents available in PDR App C documents completely with held (ref FCIA Exemption 5) GRIMSLEY, D.H. Dwisson of Ru'es & Records (Past 870413) 88/04/07 CONDIT, R Government Accountability Project 6pp. 45100.303-45100.324
- -9804120107 informs of arrangements being made to send team of qualified individuals to GAP otes in order to review certain tiles re various s'legations of safety defects at plant Related info end BRIGGS.W.H. NRC - No Detailed Affrication Given, 87/12/07 CONDIT.R.E. Govern-
- ment Accountability Project 8pp. 45100 309-45100:314 --8804120117 Forwards GAP draft 880126 polition requesting that Commission delay voting on full power OL for plant until there has been complete investigation of all elegations re-prant 8 public release of rept disposing of each slegation. CHANDLERILL JASS stant General Counsol for Enforcement, 88/02/08, MURLEY.T E Office of Nuclear Reactor Regulation, Director [Post 870411], 5pp. 45100-315-45100-316.
- --8804120123 Contirms 871104 telcon rollagreement to set up meeting in order to provide NRC w/into about safety allegations at plant Meeting scheduled for 871112. REHM,T.A. Oftio filthe Executive Director for Operations 97111/09. GARDE.8 P. Government Accountability Project. 5pp. 45100 320-45100 324.
- 8804120189 FOIA request for records to be available at PDR re-safety allegations concerning lackly.
 DAY, 6. Austin, TX. 88/02/10. GRIMSLEY, D.H. Division of Rules & Records (Post 870413) 2pp. 45101:030-45101.031.
- 8804120203 Partial response to FOIA request for documents Forwards App B documents re allegations at facility. Apps A & B documents avariable in POR App C documents completely withheld (ref. FOIA Exemption 5)
 GRIMSLEY.D.H. Division of Rules & Records (Post 870413), 88/04/07. DAY, B Austin, TX. 6pp 46101:032-45101:053.
- ~8804120211 Ack receipt of 871204 fit to J Calvo re allegations at facility.NRC intends that initial review at GAP will include exam of all parts of recipient files that NRC deems necessary. REHM,T.A. Ofc of the Executive Director for Operations 87/12/08. GARDE,B.P. Government Accountability Project. 2pp. 45101.038-45101.053.
- 8804120235 Appeals denial of 880201 ftr to release documents described in App B.Response requested within 20 working days CONNORL Doc-Search Associates 88/02/11. GRIMSLEY, D.H. Division of Rules & Records (Post 870413). 1p. 45100.284-45100.284.
- 8804120245 Responds to 880211 appnal to Grimstey 880201 derial of documents. Forwards App A, "Chronological Listing of Significant Events" but App B sith being withheld (ref FOIA Exemption 5).
 STELLOV Off of the Executive Director for Operations 88/04/07. CONNOR, L DocSearch Associates, 3pp. 46103.285.45100:299.
- --8804120286 Package of chronological listing of significant events

 NRC No Detailed Affiliation Givon, 86/04/07, 8pp. 45100 263-45100:299.
- B804120467 Appeals denial of FOIA request for documents described in App B of FOIA Requests 87-783 & 87-858 Meeting w/Ofc of Admin & Otc of General Counsel to dis-curse postition of penalty requested. cuss merits of appeal requested.

 CONNOR,L. Doc.Search Associates 88/02/11. GRIMSLEY,D31 NRC - No Detailed Allitiation Given. 2pp. 45101:096-45101.097.
- 8804120472 Final response to 880211 appeal re denial of documents identified on App B of FOIA Responses 87-783 & 87-858 NRC Initial determination denying mails af-timed (ref FOIA Exemption 5). CHILK,S.J. Office of the Secretary of the Commission, 88/04/04, CONNOR.L. Doc-Search Associates, 1p. 45101:098-45101:110.
- 8804130115 FOIA request for all documents re threats NRC Intel igence Assessment Team 8/or Into Assessment Team considered against nuclear facilities in States of OH 8 MI. MAXWELL,B. Cosmos Broadcasting Corp. 88/01/04. Freedom of Information & Privacy Acts Branch. 2pp. 45102:029-45102:030.
- 8804130119 Partial response to FOIA request for documents Forwards documents listed in App A_Documents also avertable in PDR. App 8 document withheld (ref FOIA Ex-
- emption 5).
 GRIMSELY, D.H. Division of Rules & Records (Post 870413), 88/04/05, JORDAN,8 institute of Nuclear Power Operations, 4pp. 45102.050-45102.101.
- --8803100052 Forwards proposed rev to memorandum of agreement (MOA) between INPO & NRC & apps to that agreement. Altechment 1 provides summary of major change App 4, "Coordination Pian for incident investigation Activities" is new app. CONWAY, W.F. Institute of Nuclear Power Operations. 87/07/23. TAYLOR, J.M. Otc of the Executive Director for Operations. 18pp. 45102:075-45102 101.
- --8804130148 Informs of process of developing guidefines for code of conduct or key operating principles for operators Complete set of guidefines will be distributed at 87105 & 06 conference Comments requested by 871012 PATE, 27. Institute of Nuclear Power Operations. 87/09/04 STELLO,V. Oic of the Executive Director for Operations. 10pp. 45102.054-45102.063.
- --8804130156 Ack receipt of 870904 fit ro development of codes & ethics & operating principles for nuclear power plant operators. Concept of operator development & ownership of any code of ethics endorsed.

 STELLOY. Ofc of the Executive Director for Operations 87/10/07, PATE,Z.T. Institute of Nuclear Power Operations. 1p. 45102:064-45102:064.
- --8804130161 Forwards draft paper for discussion re use of performance indicators. PATE,Z. Institute of Nuclear Power Operations. 87/04/07. STELLO,V. NHC No Detailed Affiliation Given. 3pp. 45102.065-45102.067
- -8804130167 Forwards App 5 to coordination plan for NRC/INPO use of performance Indicators,per 870413 discussion.

 PATE,Z.T. Institute of Nuclear Power Operations. 87/04/14. STELLO,V. Ofc of the Executive Director for Operations. 4pp. 45102.088-45102.071.

- --8804130173 Forwards 871250 ftr to INPO members informing of application guidelines on check valves recently developed by EPRI. Guidelines recommended to address SOER 86.3, "Check Valve Feiture or Degradation." CONWAY,W F. Institute of Nuclear Power Operations 87/12/30, STELLO,V. Ofc. of the Executive Director for Operations. 3pp. 45102,072-45102,074.
- 8804130125 Partial response to FOIA request for documents re into Assessment Team notification & alleged valve tampering. App A documents available in PDR Forwards. App B documents also available in PDR GRIMSLEY,D H. Division of Rules & Records (Post 870413), 88/04/04 MAXWELL,B Cosmos Broadcasting Corp. 3pp. 45102 031-45102 048.
- --8804130141 Handwritten note re Info Assessment Team notification of 870413 telcon from individual fixed from plant on 870220 for sabotage/tampening w/salcty-related vatve individual denied allegation. MCPEEK.G. NRC No Detailed Affiliation Green. 87/04714. PARTLOW.J., GRIMES,B., ERICKSON,B. NRC No Detailed Affiliation Green. 2pp. 45102 034-45102 035.
- -8804130151 PNO-III-87-101 on 870726.licenses received bomb threat from caller angry because place of residence lost power during storm Security personnel not fed & search procedures implemented No bomb discovered.

 CREED_J_ AXELSON,W. Region 3, Otc of the Director. 87/07/27 1p 45102 036-
- -8804130164 Forwards J Davidson 871015 memo forwarding FBI communication in-forming NRC that FBI would not investigate alledged valve tampening incident Util & alleger have not settled labor gnevance.
 WEIL,G.H. Region 3, Olic of the Director, 87/10/23. PAWLIK,E.T. Region 3, Olic of the Director 19, 45102:037-45102:00
- --8804130165 Forwards FBI communication to be disseminated only to NRC employees wineed to know.W/o FBI communication.Records of 860610,0926,1212,870404 & 0929 tolcons & Region III repts of 860610,870318 & 0929 events en
- 8804130137 FOIA request for documents re correspondence between NRC & INPO from 870101-880131. JORDAN,B. Institute of Nuclear Power Operations 88/02/04, NRC - No Detailed Af-filiation Given, 1p. 46102:049-45102.049.
- 8804130212 Partial response to FOIA request for documents Forwards App N documents to CRIGR meetings App N documents available in PORI App O documents with-held in entrety (ref FOIA Exemption 5). GRIMSLEY.D.H. Division of Rulos & Records (Post 870413). 88/04/05. WEISS,E.R. Harmon & Weiss. App. 45102:102-45102.337.
- --8405160276 Advises that NUREG-0801, "Evaluation Criteria for Detailed Control Room Design Reviews," will be issued in final form, incorporating public comments & consistent w/requirement of NUREG-0737, Suppl 1. DENTON H.R. Office of Nuclear Reactor Regulation, Director (pre-851125), 84/04/25. DIRCKS,W J. Oic of the Executive Director for Operations 2pp. 45102.129-45102:135
- --8408060365 Advises that proposed NUREG-0801, "Evaluation Criteria for Detailed Control Room Design Reviews," should be issued as app to Chapter 18 to SRP, in continuing w/policy of not using NUREG repts to promulgate regulatory guidance. DIRCKS,W J. Otc of the Executive Director for Operations, 84/07/12, DENTON,H R. Office of Nuclear Heactor Regulation, Director (pre-851125) 1p. 45102:127-45102.127.
- --8602100002 Lists cuncerns on GDC 4 package for distribution to CRGR members during CRGR Meeting 84 DBA containment temp & pressure as function of break size should be reviewed. J Scinto comments to J Sniezak encl ROSS, D.F. Ciffice of Nuclear Regulatory Research, Director (Pre 860720), 86/01/27, SCHWINK,W. Committee to Review Gonaric Requirements, 54pp. 45102 283-45102
- --8603120377 Requests additinto to continue CRGR review of NUREG-0313, Rev 2 re BWR pipe cracking & long-term resolution Regulatory analysis of proposed resolution/ implementation should be available for review by committee W Dircks 840712 memo SNIEZEK.J.H. Regional Operations & Generic Requirements, EDO (Pre 870413), 867-03/05. DENTON,H.R. Office of Nuclear Reactor Regulation, Director (851125-870411) 1p. 45102:126-45102:126.
- --8603120387 Comments on publication of NUREG-0801, "Evaluation Criteria for DCRDR," per end recipionit 840425 memo Meeting should be field to discuss NUREG 8 relationship to industry Nuclear Util Task Action Committee documents DIRCKS,W.J. Oic of the Executive Director for Operations, 84/05/07, DENTON,H.R. Office of Nuclear Reactor Regulation, Director (pre-851125), 1p. 45102.128-45102.138 Office of 45102:128
- --8609170458 Summary of CRGR Meeting 91 on 860723 re proposed revs to 10CFR50.46 (ECCS rule).App K & related draft reg guide. Attendees list & supporting documentation encl.
 SNIEZEK,J.H. Committee to Review Generic Requirements, 86/09/09, STELLO.V
- Ofc of the Executive Director for Operations 90pp. 45102 177-45102 282.
- ---8609180240 Forwards summary re proposed generic litr to BWR hoenseds transmitting technical findings related to MSIV leakage & MSIV leakage control sys Review re resolution of Generic Issue C-8 schoduled for CRIGH Meeting 96 on 860917. TAYLOR,M.A. Regional Operations & Generic Requirements, EDO (Pre 870413), 867-09112. BERNERO,R.M. Office of Nuclear Repolar Regulation, Director (851126-870411), 16pp. 45102:140-45102:176.
- --8804130224 Forwards proposed draft testimony on backfit to be given by chairman at 871014 hearing of House Subcommittee on General Oversight & Investigation.Committee on Interior & Insufar Affairs.

 JORDAN,E.L. Office for Analysis & Evaluation of Operational Data, Director. 87/10/05. REHM,T.A. Ofc of the Executive Director for Operations. 1p. 45102:108-45102:108 45102:108
- --8804130239 Testmony of LW Zech to House of Representatives, Subcommittee on General Oversight & Investigations, Committee on Interior & Insular Atlairs re backfit, ZECH, L.W. Commissioners. 87/10/09, 11pp. 45102:109-45102:119.

- --8804130248 Forwards summary & issue identification for CRGR Meeting 84 on 860122 re proposed broad-scope rule to modify GDC 4 of 10CFR50. CONRAW, Regional Operations & Generic Requirements, EDO (Pro 870413) 86/01/17. BERNERO, R. Office of Nuclear Reactor Regulation, Director (851125-870411) JORDANE, Div. of Emergency, Preparednoss & Engineering Response, IE(850212-870413). CUNNING/HAM,F. Office of Nuclear Material Safaty & Safaguards, Director 500. 45102:120-45102:125
- --8804130258 Forwards summary & Issue Identification for CRGR Meeting 98 on 861016 re-proposed deterred plant policy.
 POLK.P.J. Regional Operations & Generic Requirements. EDO (Pre 870413), 86/10/01. BERNEHO.R.M. Division of Boiling Water Reactor (BWR) Licensing (851125-870411). STAROSTECKI.R. Div of Emergency Preparedness & Engineering Response,IE(850212-870413). CUNNINGHAM.R.E. Division of First Cycle & Material Safety (Pre 870413), 4pp. 45102:136-45102:139.
- 8804140209 FOIA request for listed Commission papers & NRC responses to SECY-87-186 dtd 870728 & SECY-87-186A dtd 871005. ASHBAUGH,C E. Nuclear Theory & Technologies. 88/02/15. NRC No Detailed Athin-ation Given 1p. 45150-022-45150-022.
- 8804140222 Final response to FOIA request.Forwards App A document.App B & C documents partially & completely withheld, respectively (ref. FOIA Exemption 5) App A & portions of App B documents available in PDR Requester will be billed stated amount.
 GRIMSLEY,D.H. Division of Rules & Records (Post 870413) 88704/08.
 ASHBAUGH,C.E. Nuclear Theory & Technologies 5pp. 45150.023-45150.069.
- --8804140229 Advises that Commission approved Option 3(b) which would allow issuance of Inferim licenses for distribution of irradiated generations.gen 10CFR32 11,w/exception from portion which prohibits application of products to human beings.

 BATES,A L. Office of the Secretary of the Commission. 87/11/24. STELLO,V. Otc of the Executive Director for Operations 2pp. 45150.028-45150.029.
- --8804140238 Partially withheld memo forwarding,for signature,Commission into paper describing NRC plans to stop distribution of radioactive goms in US issue involves research reactor Leonsees & foreign reactors THOMPSON,H.L. Office of Nuclear Material Safety & Safeguards,Director, 87/07/22. STELLO,V. Ofc of the Executive Director for Operations, 1p. 45150.030-45150.030.
- --8804140243 Partially withheld Commission paper informing of NRC plans to halt distribution of radioactive gams from domestic & foreign reactors to unkneeded persons in USOIc of General Counsel has no legal objection.

 STELLOY Old of the Executive Director for Operations. 87/07/28 8pp 45150 031-45150 038
- --8804150339 SECY-87-186A Partially withheld paper recommending position NRC should take re distribution of radioactive gems (tradiated in reactors to unlicensed persons STELLOV Oic of the Executive Director for Operations, 87/10/05, 31pp. 45150.039
- 8804140340 FOIA request for correspondence between NRC & Duquesne Light Co ro NRC inquiry into 801224 memo by B Gupta to C McCullough concerning work done by Schneider, Inc. at plant. BRELISM. Pittsburgh Press Pittsburgh, PA. 88/03/28, Office of Administration & Resources Management, Director (Post 870413), 1p. 45118:047-45118.047.
- 8804140342 Final response to FOIA request for documents App A document forwarded & available in PDR. GRIMSLEY, D.H. Division of Rules & Records (Post 870413). 88/04/08. DEARIE, K.A. Microform, Inc. 2pp. 45118:084-45118:087.
- 8804140345 Final response to FOIA request Encl app document available in PDR GRIMSLEY, D.H. Division of Rules & Records (Post 870413). 8J/04/11. BRELIS,M Pittsburgh Press Pittsburgh,PA. 2pp. 46118.048 45118.055.
- 8804140354 FOIA request for all records including preparatory mails & contemporane-ous notes & info submitted by util re-880114 meeting involving NRC & util concerning BELAIR.R.R. Kirkpatrick & Lockhart BELAIR.R.R. Sutfolk County, NY. 88/01/27. NRC - No Detailed Athliation Given. 2pp. 45104:155-45104:168.
- 8804140365 Partial response to FOIA request App A document available in PDR App B document completely withheld (ref FOIA Exemption 5).
 GRIMSLEY, D.H. Ovision of Rules & Records (Post 870413). 88/04/08. BELAIR, R.R. Kirkpetrick & Lockhart. BELAIR, R.R. Suffolk County, NY. 4pp. 45104:157-45104:160.
- 8804140424 FOIA request for abstract of bids for Solicitation Number RS-ARM-88-169 (bid opening date 870824).

 DEARIE,K.A. Microform, Inc. 88/03/31. DEMARCO,D. Division of Contracts (Post 870413). 1p. 45118-083-45118-083.
- 8804140450 FOIA request for all concurrence sheets, drafts, revs. annotated copies & addit documents re SECY-82-414 as well as Commission Request COMJA-82-5, contained in SECY-82-414. WEISSMAN,S California, State of. 88/02/08. GRIMSLEY, D.H. Division of Rules & Records (Post 870413). 1p. 45130:149-45130:149.
- 8804140453 FOIA request for documents re U mining 8 milling site in Jaduguda,India KELLER,C.L. Fund for Peace (National Security Archive). 88/02/05. ROBINSON,L.L. Freedom of Information & Privacy Acts Branch. 3pp. 45130:103-45130:105.
- 8804140462 Pertial response to FOIA request for documents.App A document totally withheld (ref FOIA Exemption 5).
 GRIMSLEY.D.H. Division of Rules & Records (Post 870413). 88/04/08. WEISSMAN,S. Cellfornia, State of. 3pp. 45130;150-45130;152.
- 8804140463 FOIA request for documents re Indian nuclear reactors, Madras I & II.Narora I & II & Kakrepar I & II.

 KELLER.C.L. Fund for Peace (National Security Archive). 68/02/04. ROBINSON,L L.
 Freedom of Information & Privacy Acts Branch, 3pp, 45130:140-45130:142.
- 8804140469 FOIA request for documents re Indian nuclear power plants, Tarapur I & II & Rejasthan I & II. KELLER C.L. Fund for Peace (National Security Archive), 88/02/03, ROBINSON,L.L. Freedom of Information & Privacy Acis Branch, 3pp, 45130:137-45130:139.

- 8804140476 FOIA for documents re-Indian nuclear fuel fabrication facilities located in
- Hyderabad & Trombay KELLER C.L. Fund for Peace (National Security Archive) 88/02/10 ROBINSON,L.L. Freedom of Information & Privacy Acts Branch 3pp. 45130 134-45130 136
- 8804140481 FC/A request for order amending 870818 order imposing civil monetary penalty re EA-87-028 concerning Rackation Stontzers,tinc,License 04-19644-01,Docket 50-19025
 ALBRECHT,K. Food Irradiation Response EA-87-028
 - Detailed Affiliation Given 1p. 45130 093-45130 093
- 8804140483 FOIA request for documents to Indian heavy water production facilities, Nangal, Baroda, Tulicorin, Ta'Cher, Kota, Thai Vaishot & Manuguru KELLED, CL Fund for Peace (National Security Archyo), 88707/99, ROBINSON, U. Freedom of Information & Privacy Acts Branch, 3pp. 45130, 131-45130, 133
- 8804140492 FOIA request for documents to U purification lacity located in Hyderabad, India KFILER C L Fund for Peace (National Security Archive) 88/02/08 HOBINSON.L L Freedom of Information & Privacy Acts Branch. 3pp 45130 128-45130 130
- 8804140496 Final response to FOIA request for order amending 870818 order imposing civ.l monetary panalty & as well as listing of info in PDR folders FOIA-85-339 & FOIA-87-709 under furifly & Devic respectively App A documents in FOR & and. GRIMS; EV.D.H. Division of Rules & Records (Post 870413) 88/04/08. ALGRECHT, K. Food finaliation Response. 2pp. 45130-034-45130-039.
- --8802090430 Forwards order amonding 870818 order imposing crul inchetary punalty in amount of \$5,000 Violations E. & Fracognized as separate violations w/o crul penalty per recipient 871223 fit & NRC re-evaluation TAYLOR, JM Copuly Executive Director for Regional Operations, EDO (Post 870413) EA-87-028 88/02/08, CHIN,A. Radiation Sterilizers, Inc. 1p. 45130-036-45130-039
- -8802090446 Order amunding 870818 order imposing civil monetary penalty. Violations F. & Hiremilled & technique ordered to pay \$5,000 civil penalty within 30 days. TAYLORUM Deputy Executive Director for Regional Operations, EDO (Post 870413) EA-87-028 88/02/08 3pp. 45130.007-45130.009.
- 804140500 FOIA ruquosi loi documents io Indian U reprocessing facilities.Trombay.Taraput.Kalpakkam KELLER.C.L Fund far Poaco (National Security Archivo), 89/02/11, FIOBINSON,L L Freedom of Information & Privacy Acts Branch. 3cp. 45130-125-45130-127 documents to Indian U reprocessing
- request for documents re 804140512 FULL request for obcurrents re-initial research reactors Aspara, Crus, Zerhan, Purrima, Purrima II & Chruva (tormally R-5) located in Trombay & FBTR research reactor located in Kalpakkem KELLER.C.L. Fund for Peace (National Security Archive) 88/02/12 ROB/NSON, L. Freedom of Information & Privacy Acts Branch. 3pp. 45130-122-45130-124
- 8804140522 FOIA request for documents re Pakistani U conversion facility & U mining site & mills operating in Dera Ghazi Khan from 1970 to present Copyrighted matt encl KELLER.C.L. Fund for Poace (National Security Archive) 88/03/02 ROBINSON.L. Freedom of Information & Privacy Acts Branch 4pp 45130 114445130 117
- 8804140529 FOIA request for documents re Pakistani heavy water facilities in Multan & Karachi Irom 1970 to prosent Copyrighted mall encl.

 KELLER,C.L. Fund for Peace (National Security Archive) 88/03/04 ROBINSON,L.L.

 Freedom of Information & Privacy Acis Branch. 4pp. 45130,118-45130,121.
- 8804140532 FOIA request for documents to KANUPP nuclear power reactor located in Karachi, Pakistan & PAAR research reactor located in Hawp'pindi, Pakistan from 1965 keller, Copyrighted mall encl KELLER,C.L. Fund for Peace (National Security Archive) 88/03/08. ROBINSCN,L.L. Freedom of Information & Privacy Acts Branch. 4pp. 45130 110-45130 113
- 8804140535 FOIA request for documents re Pakistani fool fabrication facility located in Chashma/Kundian from 1970 to present Copyrighted matterol KELLER,CL Fund for Peace (National Security Archiva) 88/03/07 ROBINSON,L L Froedom of Information & Privacy Acts Branch. 4pp. 45130.106-45130 109
- 8804140538 Responds to FOIA request for documents re nuclear facilities in India & Pakistan Request does not reasonably describe records sought & fai's to most fitreshold requirements of 5 USC 552(a)(3) GHIMSLEY.O.H. Division of Rules & Records (Post 870413). 88/04/07 KELLERIC Fund for Peace (National Security Archive), 3pp 45130,100-45130,102
- 8804150332 Partial response to FOIA request for documents Forwards App B documents App A & B documents also available in PDR. GRIMSLEY, D.H. Dwison of Rufes & Records (Post 870413), 88/04/08. CONNOR, L. Doc-Search Associates. 4pp. 45149-3304-45149-351.
- -- 8804180282 Comanche Peak Responso Team Action Plan Item VII a 6, "Ext Interviews." Related into encl.

 BUSH,J.W., HASSEL,J.L. TU Electric (formerly Toxas Utrities Generating Co.) 85/06/21. 8pp. 45149 334-45149:351.
- 8804150433 Final response to FOIA request for documents No addi records located GHIMSLEY, D.H. D.vislon of Rules & Rocords (Post 870413), 88/04/11 CCNNOR, L. Doc-Search Associates 1p. 45133:170-45133:171.
- 8804180158 FOIA request for all correspondence hetween NRC & F Lindemann between Sept 1987 & Fob 1988 re application for amend to License 49-10982-02 & all correspondence between NRC & JO Yate for same time interval. LANDRETH,K Memorial Hosp. of Sheridan County, Sheridan, WY (formerly Memorial Hosp. of Sher. 88/02/18. CAIN,C Region 4, Ofc of the Director. 1p. 45149 117-45149:117.
- 8804180160 Final response to FOIA request Forwards App A documents GHIMSLEY,D.H. Division of Rules & Records (Post 870413). 83/04/12. LANDRETHIK. Memorial Hosp of Sheiidan County, Sheridan, WY (formerly Memorial Hosp, of Sher, 4pp. 45149 118-45149:163.
- --8804180165 Application for amend to License 49-10982-02 adding FA Matthews & K Landreth Training & experience form, proceptor statement & related into encl. YALE, J.O. Memorial Hosp. of Sheridan County, Shendan, WY (formerly Memorial Hosp. of Sheridan County, Shendan, WY (formerly Memorial Hosp. of Sher. 17368 87/09/04. CAIN.C. Region 4, Olc of the Director. 6pp. 45149 122-45149:138

- +8804180186 Requests add'info & comments on 8709J4 application for amond to Lie cense 49:10382102 Matthows cert callon sufficient to authorize use of mails for therapy but not diagnostic purposes Hesponse within 30 days requested CAINCL Region 4, Old of the Orector 461648 87/09/16, YALEJIO Memorial Hosp of Shandan County, Sheridan, WY (formerly Memorial Hosp, of Shandan County, Sheridan, WY (formerly Memorial Hosp, of Shandan County, Sheridan, WY) 45149 139-45149 139
- --8904180200 Informs that approval cannot be given for Kill andreth application for use of medical by product mail. Landreth not hoard collised or oligible in randology, to best of author knowledge LINDEMANN F.C. Northern Wyoming Diagnostic Radiology, Inc., Shefidan, WY, 877 09/27, CAING L. Region 4, Old of the Duractor 1p. 45149 140-45149 140

- --8804180205 Forwards response to request for add info necessary for inclusion of Matthews & Landreth in license Wilson & Wenzol will expedite info to Landreth to recicient ofc.
 - YALE, O. Memieral Hosp of Sheridan County, Sheridan, WY (formerly Memorial Hosp of Sher 461648 87/10/02 CAIN,C Region 4, Ofc of the Director 1p. 45149 141-45149,141
- --8804180209 Discusses c'inicel radioisotope training of FA Motthews trom 650701-710701 Preceptor slatement encl HICOK.W.F. Q&R Clinic, Bismarck, ND 461648-87710715 CAIN.C.t. Region 4, Okt of the Director 2pp 45149 142-45149 143.
- --8804180223 Responds to 870916 request to JO Yale for amend of preceptor statement to clearly specify numbers of hours of supervised work experience & supervised clinical experience FA Matthows 870927 fir to Yale & Landroth 871002 fir to Yale
- enci.
 LINDEMANN,F.C. Memonal Hosp of Sheridan County, Sheridan WY (formerly Memo-ral Hosp of Sher, 87/09/25 CAIN,C.L. Region 4, Ofc of the Director, 7pp. 45149.144-45149.150.
- --8804180238 (nforms of essurance that Lindomann is racial on safety officer.Lindemann meeting whatly for advice remaining as 8 liability for post on as radiation safety officer.Landreth will cooperate wired aften safety program YALEU O Memorial Hosp of Shendan County, Shoridan, WY (formerty Memorial Hosp of Sher 481648, 87/11/23 CAIN.C. Region 4, Ofc of the Orector 1p 45149.151-45149.151.
- --8804180251 Requests any addition of regulations side or rules that deal specifically whole of radiation safety officer as applicable to responsibilities of author & supervisees is Landreth practice of inc. Car. modicine studies who leanse discussed LINDEMANNEC Northarn Wyoming Diagnostic Radiology, Inc., Sheridan, WY 87/12705 CAIN.C.L. Region 4, Otc of the Director 2pp. 45149-152-45149.153
- --8804180264 Supplemental application for amond to License 49-10382-02, adding Mathews & Landreth for both thorapy & diagnostic procedures Meino of agreement between hosp & Lindemann re-continuation as radiation safety of
- --8804180278 Discussos potuntial violation of NRC regulations relabilitation users by party in question Society of Nuclear Methone recommendations re-credentialing & definedation discussed LINDEMANIN,F.C. Northern Wyoming Diagnostic Radiology, Inc., Sheridan, WY 887 01710, CAIN,C.L. Ragion 4, Ofciol the Director, 2pp. 45149,156-45149,157
- --8804180289 Responds to 870927,1205 & 880110 ltrs expressing double to qualifica-tions of K Landreih.issuance of amond to License 49-10982-02 within 10 days of fir date intended due to provide justification for denial of application. FISHER, Wit. Region 4, Old of the Director 88/01/26 LINDEMANN F.C. Northern Wydming Diagnostic Radiology, Inc., Sheridan, WY, 3pp. 45149, 158-45149, 160
- --8804180293 Ack recept of 880126 ftr & quoted retire 10CFR35.25. Inhat raising of question by NRC questioned LINDEMANN.F.C. Northern Wyoming Diagnostic Radiclogy, Inc., Sheridan, WY, 887-01731, FISHER,W.L. Region 4, Otc of the Director to 45149 161-45149 161.
- --8804180295 Forwards Amend 4 to License 49:10992:02 W/o encl CAIN,C.L. Hegion 4, Old of the Director 88/02/09, YALE,J.O. Memonal Hosp of Sheridan County, Shondan, WY (formerly Memonal Hosp of Shor, 2pp 45149.162-45149,163,
- 8804180191 Final response to FOIA request for documents No agency records subjite request located GRIMSLEY,DH Division of Rules & Records (Post 670413) 68/04/12 BOLEY,K Public Citizen's Critical Mass Energy Project. 1p. 45192 210-45192.210.
- BB041B02B8 FOIA request for 1 stod documents including all concurrence shoets drafts & revs of SECY 81-836, SECY 81-836A & H. Denton 811119 lit WEISSMAN,S. Cablorna, State of 89/02/08. GRIMSLEY, D.H. D.vis'on of Ru'es & Records (Post 870413). 2pp. 45149-354-45149-355.
- 8804180297 Partial response to FOIA request App A documents totally withheld (ref FOIA Exemption 5).Documents subj to Category F of request,per 880408 telcon be-tween N Brown & Holmes (Post 870413). 86/04/12 GRIMSLEY D.H. GRIMSLEY D.H. Division of Rules & Records (Post WEISSMAN, S. California, State of 3pp 45149 356-45149 358.
- 8804180311 FO!A request for record of number of FO'A & Privacy Act (PA) requests received by NRC each yr,vol of records processed by NRC & number of FO'A cases in higation on each of yr which NRC is defendant. FENSTERWALD,B Athiliation Not Assigned 88/03/21. ROBINSON,L, NRC · No Detailed Afficiation Green. 3pp. 45150.006-45150.008.
- 8804180337 FOIA request for info on educational fevels of persons halding positions of reactor operator & senior reactor operator for each & every commercial nuclear gen-
- erating factify.

 BOLEY K. Public Critizen's Critical Mass Energy Project. 87/12/11. GRIMSLEY,D. Division of Rules & Records (Post 870413). 2pp. 45150-002-45150-003.

- 8804180348 Responds to FOIA request for 13 categories of records from 1967 to present re NHC processing of FOIA & Privacy Act request No records subj to Category 5 of request Forwards record listed on app.
 GRIMSLEY,D H. Freedom of Information & Privacy Acts Branch, 88/04/08.
 FENSTERWALD,B., LESAR,J.H., FITZGIBBON,A.L. Affiliation Not Assigned 3pp. 45150 009 45150 021
- --8804180453 Records of statistics on number of days to process FOIA requests (1978-1984, 1986-1987).

 ** NRC No Deta-led Affiliation Given, 88/04/08, 10pp, 45159 012-45150 021.
- 8804180357 First partial response to FO'A request for documents App A document, consisting of SECY-87-101 available in PDR. GRIMSLEY, D.H. Division of Rules & Roccrits (Posts 870413) 88/04/13. BOLEY, K. Public Citzen's Critical Mass Energy Project 2pp. 45150-004-45150.005.
- 8804180364 FOIA request for documents re-rept by NRC Ofc of Investigations on alleged mail false statements by willingt at lacility,did 871110.
 WENSKEP, Kansas City Star/Kansas City Times, Kansas City, MO 88/03/24.
 GRIMSLEY,D. Division of false & Records (Post 870413). Ip. 45150.070-45150.070.
- 8804180389 Final response to FOIA request for documents fieleasable portions of records identified on App A available in LPDRs in the torder FOIA-87-800 under name Hays & PDR-Portions of App A documents withhold (rof FOIA Exemptions 8 & 7) GRIMSUEY,D H. Division of Rules & Records (Post 870413) 88/04/13 WENSKE,P. Kansas City Star/Kansas City Timos, Kansas City. MO. 3pp. 45150.071-45150.073.
- 8804190030 Final response to FOIA request Records in App F completely withheld (ref FOIA Exemption 5) GRIMSLEY DH Division of Hules & Records (Post 870413) 88/04/13. KOL (HAUS C.) Hothaus, C.J. 3pp. 45156:308-45156:311.
- 880419003B FOIA request for documents on NRC/IDCOR meeting on 870910 re individual plant evaluation (IPE) program & all records in NRC possosion re IPEs SHOLLY,S.C. MHB Technical Associates. 87/10/15. GRIMSLEY,D.H. Division of Rules & Records (Post 870413). 2pp. 45156.312-45156.313.
- 8804190040 FOIA request for contract between Northeast Util & Burns Intl Security from Dec 1984 to present w/any revs or mods
 PATTELSDOREEH Athibation Not Assigned, 88/03/24 NRC No Detailed Athibation Gwon 1p 45158 263
- 8804190050 Final response to FOIA request for documents on NRC/IDCOR meeting on B70910 re individual plant evaluation Forwards documents listed in App B.Apps A & B documents available in PDR.App C documents totally withhold (ref FOIA Exemption GRIMSLEY,D H. Division of Rules & Records (Post 870413), 68/04/13, SHOLLY,S.C. MHB Technical Associates 11pp, 45156 314-45156 262.
- ••8609190081 Forwards prefirminary review of IDCOR 860502 draft, "Individual Pfant Exam Methods (IPEM)." IPEM has potential to be effective alternative for individual plant exams Areas needing addl into or mods listed. SPEIS.T.P. Division of Safety Review & Oversight (851125-870411). 86/09/09. BUHL, A Industry Degraded Core Rulemaking Program. 41pp. 45158:197-45158.237.
- --8703310385 Forwards NRIft position paper relissue of direct containment handling,per resolution of IDCOR/NRC technical issues. Position paper relessential equipment performance will be forwarded when available. SPEIS,T.P. Drusion of Safety Review & Oversight (851125-870411). 87/03/11: BUHL,A International Technology Corp. 6pp. 45158 238-45158 262.
- --8604190060 Forwards response to NRC comments on individual plant evaluation methodology per 860909 request Revised version of methodology will be provided by middle of Dec. BUHL, AR Industry Oegraded Core Rutemaking Program. BUHLAR International Technology Corp. 86/12/10. SPIRS,T.S. Division of Safety Review & Oversight (851125-870411) 48pp. 45156.325-45157:010
- -8804190069 Forwards response to BNL comments on IDCOR model of Mark I containment response to direct contact w/molten care debris.
 BUHLAR: Industry Degraded Core Rulamaking Program. BUHLAR: International Tochnology Corp. 8707/07/09. BECKJORD_E S. Office of Nuclear Regulatory Research, Director (Post 860720). 8pp. 45167.011-45157.018.
- --8804190077 Forwards revs to IDCOR individual plant evaluation PWR sys methodology PWR sys methodology considered to be final w/ integration of revs. BUHL, A.R. Industry Degraded Core Rulemaking Program. BUHL, A.R. International Technology Corp. 87/03/09. SPEIS, T.P. Division of Safety Review & Oversight (851125-870411). 496pp. 45157:018-45158:196.
- 8804 190053 Final response to FOIA request No documents responsive to request local-GRIMSLEY,D.H. Division of Rules & Records (Post 670413). 88/04/13, RATTELS-DORFER Alfiliation Not Assigned. 1p. 45158-264-45158-264
- 8804190064 Appea's denial of FOIA request for documents. Meeting w/Div of Rules and Records and OIc of General Counsel requested.

 CONNOR, L. Doc Search Associates 88/02/11. GRIMSLEY, D.H. NRC No Detailed Affiliation Given, 1p. 45165:274-45165:274.
- 8804190078 Responds to appeal re denial of FOIA request for documents. Forwards partially withhe'd Documents C-3 & C-7 (ref FOIA Exemption 5). Other documents withheld (ref FOIA Exemption 5). CHILK,5,3. Office of the Sec
- -8804190115 Partially withheld agenda for 860130 senior manager team meeting to discuss. Intimidation and harassment (saues & Ofc of Inspector & Auditor Itr followup:Partially withheld revised agenda for TVA senior mgt team meeting also encl. NRC No Detailed Affiliation Given. 86/01/30. NRC No Detailed Affiliation Given 2pp. 45165:277-45165:286.
- 8804180191 Final response to FOIA request for documents including ZT Pate 870319 ftr to U. Zech Forwards documents listed in App C.App C documents being placed in PDR App D documents withheld (ref FOIA Exemption 5). GRIMSLEY.D.H. Division of Rules & Records (Post 870413), 88/04/14. JORDAN,B. Inside N.R.C. (McGraw-Hill Publication). 4pp. 45168:069-45166:089.

- -8804 19019/ FORWARDS INPO 1986 ADDUAL MADIL TERFIOLOGICUS SECTION ITOSTIALEO INCUSTI progress as measured by key indicators of nuclear plant performance.
 PATE, Z.T. Institute of Nuclear Power Operations. 87/03/19. ZECH, L.W. Commissioners 1p. 45186.074-45186-074.
- ers. 2pp. 45166:075-45166:076.
- --8804190244 Submits followup to 870514 ftr for NRC consideration.NRC initiative area where INPO had taken aggressive action, has potential to cause utils to be les receptive & less aggressive in responding to future INPO initiatives. PATE.2.1. Institute of Nuclear Power Operations. 87/05/21. ZECH,L.W. Commission etc. 1p. 45166.077.46166.077.
- --8804190255 Forwards excerpted version of M Carr remarks from committee on safe of nuclear installations conference in Orlando, FL on Apr 22.INPO would like to publis remarks in Jul Issue of Nuclear Professional. CONWAY.W.F. Institute of Nuclear Power Operations. 87/06/03. CARR.K.M. Commissioners. 1p. 45166:078-45186.078.
- -8804190260 Notifies that 1987 CEO Conference will be held in Atlanta GA on 87110: 06 under theme "Evaluating Progress" Registration matts will be sent in Sept. PATE, Z.T. Institute of Nuclear Power Operations. 87/06/15. ROBERTS, T.M. Commissioners. 1p. 45166,079.45166.079.
- --8804190263 Notifies that 1987 CEO Conference will be held in Atlanta, GA on 871101 06, under theme "Evaluation Progress." Registration malls will be sent in Sopt PATE, Z.T. Institute of Nuclear Power Operations. 87/08/15. CARR, K.M. Commission gr. 1p. 45186.080-45186.080.
- --8804 190276 Forwards registration matls for 1987 CEO conference in Atlanta, GA of 871 105-06, under theme "Evaluating Progress." Preliminary agenda also encl. PATE, 2.T. Institute of Nuclear Power Operations. 87/09/18. CARR, K. Commissioner 3pp. 45166 081-45166 083.
- -8804190283 Forwards proceedings from 871104-06 1987 CEO Conference, "Evaluating Progress." in Atlanta GA. PATE.Z.T. Institute of Nuclear Power Operations. 88/01/08. ROBERTS,T.M. Commisioners. 1p. 45156:084-45186:089.
- 8804190231 FOIA request for documents re ACRS subcommittee meetings on 750218 19 re plant. STEWART.M.E. Pacific Gas & Electric Co. 88/02/22, NRC · No Detailed Affiliatio Givon 2pp. 45165:161-45165:218.
- 8804190240 Final response to 880211 appeal re denial of FOIA request focuments. Determines that Document B-2 should be released Document. Document B-1 remains withheld in entirety (ref FOIA Exemption 7). CHILK.S.J. Office of the Secretary of the Commission. 88/04/13. CONNOR.L. Do Search Associates. 1p. 45166:062-45186:068.
- -8804190256 Forwards request for Investigation by Ofc of Investigations per 86100 commitment to inform Commission of referrals for investigation of senior level u mgt.W/o encl. STELLO,V. Ofc of the Executive Director for Operations, 87/01/14, ZECH, ROBERT ASSELSTINE Commissioners, 1p. 45168.083-45188:088.
- 8804190242 Responds to FOIA request for documents re ACRS meeting of plant. Forwards DJ Skovholt 750324 memo to F Schroeder concerning plant pre-ACR SER supplis Charges for search, review & reproduction provided. GRIMSLEY, D.H. Division of Rules & Records (Post 870413). 88/04/1 STEWART, M.E. Pacilic Gas & Electric Co. 1p. 45165:217-45165:230.
- --9804200153 Forwards list of plant open items resulting from ACRS subcommitte 750218 & 19 meetings & list of actions requested from review branches for used preparing SER suppliphor to next ACRS meeting. SKOWHÖLT.D.J. Division of Reactor Licensing (NRR-1975 only). 76/03/2 SCHROEDER,F. Division of Technical Review (NRR-1975 only). 13pp. 45165:21 45186-2021.
- 8804200473 Partial response to FOIA request re lire protection.Forwards App documents App D & E documents available in PDR.App F document completely with held (ref FOIA Exemption 5).
 GRIMSLEY, D.H. Division of Rules & Records (Post 870413). 88/04/14. JONES, C. Affiliation Not Assigned. 5pp. 45208.037-45207.042.
- --8411130333 Forwards revs to App R questions & answers posed by industry & dramemo re comparison of fire protection requirements for operating reactors & new term O.s. ROSA,F. Fire Protection Review Group, 84/10/30, VOLLMER,R.H. Fire Protection Review Group, 67pp, 45208:087-45208:153.
- -8605140252 Forwards Generic Ltr 86-10 re implementation of fire protective requirements, to clarify & assist w/final resolutions of issues.NRR divs responsible tre-review of scheduling & identification of problems. EISENHUT, D.G. Office of Nuclear Reactor Regulation, Director (851125-870411). G 86-10.86/04/25. Office of Nuclear Reactor Regulation, Director (851125-870411). I 45208:183-45208:239.
- --8804200491 Forwards IE enforcement guidance memo providing guidance on enforcement action for violations of fire protection requirements.

 MURLEY,T.E. Region 1, Ofc of the Director. EGM-86-04, 86/08/26, Region 1, Ofc the Director. 31pp. 45206:247-45207:042.
- --8604200497 Forwards outline of topics discussed during NRC Fire Protection Poli Steering Committee 841002 meeting re fire protection licensing & Inso Issues. MILLER W.H., MADDEN,P.M., WISEMAN,G.B. Region 2, Oto of the Director. 84/1 18. Region 2, Oto of the Director. 9pp. 46208:078-45208:088.
- --8804200526 Summarizes differences which exist between fire protection requirement applied to near-term OL & operating reactors, per NUREG-0800,5RP 9.5.1. CONLON,T.E. Fire Protection Review Group, 84/11/07. ROSA,F. Fire Protecti Review Group, 18pp. 45206:154-45206:169.

- --8804200587 Forwards comments on Roy 2 to Tomporary Instruction 2515/62 re :nsp of safe shutdown,emergency Lighting 8 oit collection at all nuclear power plants OLSHINSKI,J A. Region 2, Ofc of the Director. 85/01/10, GRACE,J.N. Div of Quality Assurance,Safeguards & Inspection Programs.IE (930103-850212), 4pp. 45206.170-45206 173
- -8804200575 Provides status of Region II safe shutdown insp program. GRACE.J.N. Region 2, Ofc of the Director. 85/05/13. TAYLOR,J.M. Ofc of Inspection & Enforcement, Director (820201-870413). 2pp. 45206:174-45206.175.
- --8804200579 Advises that Fire Protection Steering Committee has recommended that each region make one 10CFR50.App R-type insplict of each facility to assess status of compliance w/ 10CFR50 48 Program listed CONLON.T.E. Region 2, Oto at the Director, 84/11/06, HERDT,A.R. Region 2, Oto of the Director, 3pp. 45206-176-45208-178.
- --8804200581 Forwards revised enforcement guidance is the protection requirements for comment by 860421.

 VOLLMER.R.H. Otc. of Inspection & Enforcement, Director (820201-870413) GL-85-01 86/04/17. MURLEY, T.E. Region 1, Otc. of the Director. GRACE.J.N. Region 2, Otc. of the Director. KEPPLER.J.M. Region 3, Otc. of the Director. 4pp. 45206-178-45206-179. 45206 182.
- --8804200589 Forwards comments on Insp Procedure 64100 re-post-sale shutdown insp procedure per 861001 request Encl comments should be incorporated into line. procedure GIBSON.A.F. Region 2, Otc of the Director 86/10/29, PARTLOW,J.G. Div of Inspec-tion Programs,IE (850212-870413), 7pp. 45206 240-45206:246.
- 8894210020 FOIA request for documents did or received after 860630 that comprise, teter or relate to any bids or proposals for provision of reporting sizes made by or on behalf of, or contracts forwarded to Acma or Hantage Reporting.

 BIRD.C.C. Papper, Namiton & Sheetz. 87/08/06 NRC No Detailed All Jation Given. 2pp. 45199.227-45199:228.
- 8804210025 Parial response to FOIA request for documents Forwards App B documents also available in PDR App C documents withheld (ref documents App & occuments also systems in PDR App C documents within the FOIA Exemption 4).
 GRIMSLEY, D.H. Division of Rutes & Records (Post 870413). 88/04/04, BIRD, C.C. Pepper, Hamilton & Sheetz. 6pp. 45189:229-45200:228
- -8804210031 Request for Procurement Action ASB-87-342,"ASLBO Stonographic Reporting Svcs." Supporting documentation enct. COTTER,B.P. Atomic Safety and Licensing Board Panel. FIN 8-8184-87/03/12. 32pp 45199 235 45199:266
- --8804210065 Forwards minutes for Senior Contract Review Board Meeting 120 on 870519 re approval of FIN 8-8183, "Stanographic Reporting Contract." Supporting documentation encl. documentation enci.
 TAYLOR, J.M. NRC. No. Dotaled Affiliation Given. FIN B-8183 87/05/26
 MCDONALD.W.G. Olice of Administration & Resources Management, Director (Post
 870413). JORDAN, E. Olfice for Analysis & Evaluation of Operational Data, Director.
 NORTY, P.G. Deputy Director for Administration (Post 870413). 26pp. 45109:267-
- --8804210076 Forwards paper describing stonographic reporting svcs for NAC head quarter ofcs,except Commissioners ofcs,for Chairman Zech approval W/o encl Handwritten note encl. MCDONALD,W.G. Office of Administration & Resources Management, Director (Post 870413). 87/06/08. STELLO,V. Ofc of the Executive Oirector for Operations. 2pp. 45199:293-45199:294.
- --8804210083 Forwards GAO decisions to Solicitation RS-ASB-87-342 te nonresponsiveness of bid in which bond expires short of required acceptance period. HENRY, R.K. Dickslein, Shapiro & Morin. 87/07/16. FLEENOH,C. Division of Contracts (Post 670413). 33pp. 45199:295-45199-327.
- --8804210091 Protests decision to make award to Ann Riley & Associates, Ltd or Hentage Reporting Corp.Riley bid nonresponsive because of refignce upon defective bid band which expires shard of mandatory bid acceptance period Related into encl. HENRY,R.K. Dickstein, Shapiro & Morin. 87/07/20. HAGAN,T. Division of Contracts (Post 870413), 4pp. 45199:328-45199:331.
- --8804218124 Requests Ace Federal 870716 ltr & corresponding ocumentation, Riley bid quantantee & any other correspondence to protest or subsequent responses to protest Supporting documentation & 870724 & 27 FAXs encl. BENSON, T.A. Heritage Reporting Corp. 87/07/22. HAGAN, T. Division of Contracts (Post 870413), 18pp. 45199 332-45199.349.
- --8804210143 Forwards Heritage bid submitted in response to NRC Solicitation RS-ASB-87-342 inadvertionity omitted from 870724 into forwarded w/protest from ACE Federal Reporters Related into encl.W/o bid FLEENOR,C. NRC No Datailed Affiliation Given. 87/07/27. ROSE,S. NRC No Datailed Affiliation Given. 3PP. 46199.350-45199:352.
- →8804210155 Forwards Memorandum of Law addressing protest against Ann Riley & Assoc,Lid Profess w/o merit.Handwritten notes encl.
 GALLO,J. Isham, Lincoln & Beals, 87/07/30, HAGAN,T. Division of Contracts (Post 870413), 82pp. 45199.353-45200.073.
- -8804210169 Notities that bid "Solicitation RS-ASB-B7-342,NRC Headquarters Stenographic Reporting Svcs (Excluding In-Town Requirements of Commissioner Ofcs)" found to be nonresponsive due to defective bid guarantee. HAGAN,T.F. Division of Contracts (Poet 870413), B7/08/10. RILEY,A Ann Riley & Associates. 1p. 45200.074-45200.074.
- --8804210184 Notifies that on 870810,NRC found bid submitted by Ann Rilley & Assoc,Ltd to be nonresponsive due to defective bid quarantee Subj protest moot. HAGAN,T.F. Division of Contracts (Post 870413), 87/08/10, BENSON,T.A. Hendage Reporting Corp. 1p. 45200.075-45200.075.
- -8804210204 Notifies that Contract NRC-21-85-401 expires on 870814. Pending protest under Solicitation RS-ASB-87-342 company offers to extend performance under present contract through 871004. Fletated Info encl. MEHOLICK, J.J. Acc-Federat Reporters, Inc. NRC-21-85-401. 87/08/10. FLEENOR, C. Division of Contracts (Post 870413). 24pp. 45200.076-45200:099.

- --8804210234 Informs that in event that GSBCA rules to suspend performance under centract IRC-21-87-342 on 870821, Hentage Reporting Corp prepared to continue parformance under sole source contract or purchase order-Work orders end BENSON,T A Heritage Reporting Corp NRC-21-87-342-87/08/18 FLEENOR,C Division of Contracts (Post 870413), 14pp. 4\$200,100-45200,113.
- -9804210244 Profusts any consideration of Abe-Federal Reporters bid re-solicitation of award of Contract NRC 21-87-342. Supporting documentation end BENSON,TA. Horitage Reporting Corp. NRC-21-87-342 87/68/20 HAGAN,T.F. Division of Contracts (Post 8704.13): 113pp. 45200.114-45200.226.
- 8804210030 FO:A request for documents re-criminal records of reactor operators 8 senior reactor operators currently employed at each 8 every commercial nuclear power generating facility.

 BOLEY,K Public Citizen's Critical Mass Energy Project, 87/12/11, GRIMSLEY,D Division of Rules 8 Records (Post 870413), 2pp. 45192 211-45192 212.
- 8804210351 Final response to FOIA request for documents re-plant. Forwards App.D. documents App.C. & D. documents awai/able in PDR. GRIMSLEY.D. Division of Rufes & Records (Post 870413) 88/04/18, CONNOR,L. Doc-Search Associatios. 4pp. 45192-204-45192-209
- --8804210355 Page from draft rept on plant SAFETEAM activity & Old of Investigations * NRC - No Ontalled Affiliation Given, 88/04/18 hp. 45192 208-45192 209
- 8804220149 Partial response to FOIA request for documents Addi documents subjillo request processed under previously tried request,FOIA-88-107 W/o ref most recent partial response to request under FOIA-88-107.

 GRIMSLEY,D. Division of Rulps & Records (Post 870413) 89/04/19 CONDIT.R Government Accountability Project 1p. 45200-280-45200-282
- 8804220155 FOIA request for outstanding items list for restart of Pigrim Nuclear Power Station in Plymouth, MA GOLDEN, W.B. Massachusetts, Commonwealth of 88702/11 Region 1, Ofc of the Director. 1p. 45201;160-45201:160.
- 8804220169 Final response to FOIA request for outstanding items list of open NRC Inspitems, for restart of Pitgirm nuclear power. Station Forwards, App A. document App A. document also sysalable in PDR.
 GRIMSLEY,D. Division of Ruses & Records (Post 870413), 88/04/19. GOLDEN,W.B. Massachusetts, Commonwealth of, 2pp. 45201.161-45201.169.
- --8804250069 "Outstanding flems List"
 * NRC No Detailed Aff aton Given 88/03/02, 7pp 45201:163-45201:169.
- 8804250088 Responds to FOIA request for infoire scores of reactor operators & senior reactor operators Forwards requalification exam summary source sheets I stad in end app w/personal privacy info deleted.

 GRIMSLEY_D11 Division of Rufus & Records (Post 870413) 88/04/19. BOLEY,K Public Citizen's Critical Mass Energy Project. 2pp. 45213 003-45213 095.
- -8804250187 Package of NRC administered requalification oxam results summary
 NRC No Detailed Affiliation Given 87/07/20, 88pp. 45213 007-45213 095
- 8804250313 FOIA request for documents re-dumping of chemical wastes & other toxic matt in dumping areas on or abutting property owned by Boston Edison in towns of Plymouth & Kingston, MA.

 NICKERSON, J.M. Athliation Not Assigned, 88/02/04, ROBINSON, L.C., NRC No Detailed Athliation Given 1p. 45213:188-45213:188.
- 8804250340 Requests to rescope FOIA Request 66-84 re-mail limited directly to plant. NICKERSON,J. Affirigtion Not Assigned 68/02/29. ROBINSON,L.t., NRC No Detailet/Affiliation Given. 1p. 45213:169-45213.169.
- 8804250350 Final response to FOIA request for records re-Boston Edison App A docu-ments located in PDR. GRIMSLEY, D.H. Division of Rules & Records (Post 870413) 88/04/19. NICKERSON, J. Affiliation Not Assigned 2pp. 45213:190-45213 191
- 8804260011 Partial response to FOIA request for documents Forwards App D & E documents also evallable in PDR. App F documents withheld (rof FOIA Exemplion 5).
 GRIMSLEY,D H Division of Fluies & Records (Post 870413) 88/04/18. DAY,B
 Austin, TX. 9pp. 45232 276-45233:049.
- --8804280037 Responds to 870811 ltr requesting NRC to make available for deposition V Stello,R Martin,B Hayes & S Connelly re-enforcement of 8 Garde subposite Rejects request & informs of 870814 US petition to enforce subposite Petition enci. PARLER,W.C. Office of the General Counset, 87/08/19. CONDIT,R.E. Government Accountability Project, 44pp. 45232 287-45233.043.
- --8804250120 Clarifies statements made to J Pierobon re GAP s'legations in Flouston Chronicle rept on safety issues about facility. M-sunderstanding could have been avoided it Garde had returned 871214 call. INGRAM,F. Public Alfeirs 87/12/14. Public Affairs 2pp. 45233:044-45233 047.
- --8804280126 Discusses notice of appeal filed on behalf of NRC on 871224 to Garde subpoens informs that GAP staff & allogors involved skept.cal of NRC matives & goals but hope NRC politics will not affect thorough review of allogations. KENNEDY.J. Government Accountability Project. 88/01/12. BRIGGS,W.H. Solicitor. 2pp. 45233.048-45233.049.
- 8804260069 Final response to FOIA request for documents App Y documents end & available in PDR & LPDR.App Z documents partially withhold (ref FOIA Exemptions 6 & 7). App AA occuments lotally withhold (ref FOIA Exemptions 7). GRIMSLEY, D. Dwiston of Rules & Records (Post 870413) 89/04/19. GARDE.B.P. Government Accountability Project 5pp 45232:135-45232:172.
- -8804260106 Partially deleted memo re 840120 allegation of drug use at plant. Writer received telegrome call stating that two individuals bregged about shooting up w/here-ing in "Blue Room" at Plant SHACKLETON.O.C. Region 5, Old of the Director, 84/01/28. Region 5, Old of the Director, 3pp. 45232:142-45232:144.

- --8804260133 Parts by deleted Rept of Inquiry OS-83-018 re all egation of fals feation wilding exams by inconverters from Fresho Uncon Further investigation unwarranted,based on failure to certifirm that stand-in welder took tests Related into POWER E.J., SMACKLETON, O.C. Region 5, Old of the Director 83/12/15 26pp 45232 145-45232 172.
- 8804260168 Appeals denial of FOIA request for documents in App O follo withheld con-sists of interagency 8 intrinagency records that are not available through discovery during 31 gation. RAUMANL, Government Accountability Project. 88/01/05. STELLO.V. Ofc of the Ex-ecutive Director for Operations. 1p. 45232 181-45232 181.
- 8804260224 Responds to appeal re denial of FOIA request for documents re SER (NUREG 0675), Suppl 21 concerning operation of plant Forwards Documents 1,3,4,5 & 6 of end app Document 2 withheld (ref FOIA Exemption 7) STELLOV. Ofc of the Executive Director for Operations 68/04/19 BAUMAN.t Government Accountability Project 2pp 45232,182-45232;260
- --8804260412 List of predecisional or sensitive allegations, ncluding passing contrationd, anti-nuclear demonstration, DAVGC allegations, guard qualification noncerns & welfor qualification.

 * NRC No Dataled Affiliation Given 88/04/19 1p 45232 184-45232 260
- 8804280143 FOIA request for documents re OA insplactivities & any supporting clarifi-cation & documentation of rankings from 1982 to present to placed in PDR. CONNORL Dec-Search Associates 87/12/23 Oivision of Rules & Records (Post 870413) ip 45266 083-45266:083
- 8804280153 Partial response to FOIA request for documents Records related to request identified in dividesponse to recipient for FOIA-87-866 & FOIA-88-042 & available for review in PDR GRIMSLEY,D. Dryision of Rules & Records (Post 870413) 88/04/21 CONNOR,L Doc-Search Associates 1p. 45266-084-45266-084.
- 8804280154 Final response to FOIA request Computer printent from 766 sys to non-compliance cited in reactor inspiragits issued in CYB7 encl W/o ercl. GRIMSLEY,D.H. Division of Rules & Records (Post 870413) 88/04/25. GRABER,L. NUS Corp. 1p. 45276 213-45276 214.
- 8804280159 FOIA request for listing of noncompliance cited in reactor inspirepts issued in CV87.Sample printout encl. GRABERL NUS Corp. CD-US-88-247 88/03/24. Drivision of Rules & Records (Post 870413) 2pp 45276:212-45276:212
- 8804280167 FOIA request for documents re-stated Kerr-McGee property YOUNG,P W. Burdit, Bowles, Radzus & Ruberry, Ltd. 88/04/12. NRC No Detailed Althalion Given. 1p. 45322 184-45322 184
- 8804280179 Responds to FCIA request for documents to stated Kerr-McGee property-Voluminous file of related info available in PDR. GRIMSLEY,O H. Division of Rules & Records (Post 870413) 88/04/19 YOUNG.P.W. Burditt, Powles, Radzius & Ruberry, Ltd. 2pp. 45322185 45322186
- 6804280203 FOIA request for info re death of T Archart at facility.

 LYKINS,R D. Bryan, Lykins, Hejtmanek & Welz, 68/01/25 GRiMSLEY,D Division of Rules & Records (Post 870413) 2pp. 45276/245-45276 246.
- 860428020B First parkal response to FOIA request for documents relacing Forwards App B document.App A 8 B documents also available in PDR. GRIMSLEY,OH Dwiston of Rulos & Records (Post 870413) 88703/30. LYKINS.R.D Bryan, Lykins, Hejimanek & Wulz | 3pp 45276:247-45276:251.
- --8804280216 * Event Fol'owup Rept 87-150 **
 FIELDS,N. NRC No Datailed Affilia! on Given 87/11/11 2pp 45276 250-45276 251
- 8804280240 Final FOIA response to request for documents re HFP RS-RES-83-025 Forwards App A nonproprietary document GRIMSLEY, D. Division of Hules & Records (Post 870413), 88/04/21 LENZ, B. Washington Management Group, Inc. 2pp 45275:117-45275:275,
- --8604280248 Nonproprietary "Structural Integrity of LWR Boundary Components II," technical proposal Info deleted. hatcorials Engineering Associates, Inc. RS-RES-83-025 83/09/30. 175pp 45275:110-45275-275
- 8804280278 FOIA request for documents relisted licenses.
 ALBRECHT_K. Food Irradiation Response 87/01/27. ROBINSON,L.L. Division of Rules & Records (Pre 870413): 1p. 45265-091-45265-091.
- 8804280287 Final response to FOIA request for documents.Forwards App A documents Document partially withheld (ref. FOIA Examples 6) App A documents available in PDR.
 GRIMSLEY,DH. Division of Rules & Records (Post 870413) 88/04/20. ALBRECHT,K
 Food Irradiation Response. 2pp. 45265:092-45265:095
- --8108260077 Discusses IE insp of License 46 06377-01 on 810722 & forwards notice uf violation
 BOOK.H.E. Rad-ological Safety Br.Div of Technical Inspection.R5 61/08/21
 SPINELLIJ, Commerce, Dept. of, National Oceanic & Almospheric Administration.
 2pp. 45265 096-45265 099.
- --8108260083 Notice of violation from inspiron 810722 Noncompliance noted, required documents not posted & wrong caution sign posted. PANGLIF. Radiological Safety Br.Dw of Technical Inspection,RIS. 81/08/21. 2pp. 45265.098-45265.099.
- --8109180254 Ack raceipt of 810903 ltr informing NRC of steps taken to correct violations noted in IE insp of treasse 48-06377-01.

 BOOK.H.E. Radiological Safety Br.Div of Fechnical Inspection.R5. B1/09/14 SPINELLI,J Commerce, Dept. of . 1p. 45265:100-45265.100.
- --8804280299 Ack receipt of 720428 ftr re-release of C-14 incidental to use of mail in uCl amounts for primary productivity studies at sea FR publication amending 10CFR20 enct.W/o enct.
 BRINKMAN.R E. Atomic Energy Commission, Directorate of Licensing, 72/05/30, LARRANCE, J. Contimerce, Dept. of, 1p. 45265.084-45265.094.

- -8804280319 Forwards 30 day rept to theurit contamination situation experienced by CC Dept of Commerce under License 46-06377-01 Rept raises generic uses on netwing building building of intum in labs W/o rept BOOK HE Region 5, Otc of the Director 76/01/22 ROY,G W Otc of Inspection 8 Enforcement, Otc of the Director 19 45265-095-45205-095
- 8804280347 FOIA request that listed documents re-proposed rule to be issued wiffina policy statement on license renewal be placed in FCR DAYP, NUS Corp. CD-LIS69283 88/04/07 Drivision of Rules & Records (Posl 870413) 1p 45324 037-45324 037
- 8804280358 Final response to FC(A request for documents re-proposal on Teense innewal Ferwards App A document No documents lound on request Item 2 GRIMSLEY D. Division of Rules & Hecords (Post 870413) 88/04/19. GRABERL NUS Corp. 2pp. 45924-038-45924-043
- -8801290130 Proposes ray to schedule for development of nuclear power plant licensor renewal policy to prepare proposed policy statement & proposed rule by end of CY88 GILLESPEEF P Program Kanagement, Policy Development & Analysis Staff (Post 870411), 88/01/25 BECKJORDE.S Office of Nuclear Regulatory Research, Director (Post 860720), 1p. 45324-040-45324-040.
- 8804280395 Final response to FCIA request for documents No addit records subjito recuest located GRIMSLEY,D Division of Rules & Records (Post 879413) 88/04/21 HIATT,S On Citizens for Responsible Energy, 1p. 45269 343-45269 345
- 8804280412 Final response to FOIA request for documents Fotwards App C documents Documents partially withheld (ref FOIA Exemptions 7.6 & 3) GRIMSLEY,D Division of Rules & Records (Post 870413) 88/04/21 MAXWELL,B Cosmos Broadcasting Corp 3pp 45269 346-45270 006
- --8804280437 Partially withheld Insp Rept 87010 response Deliciencies re security dop & valve tempering discussed Related into enct * Consumers Power Co. 87/10/08 12pp 45269 351-45270 006
- 8804280460 FOtA request for technical proposal & statement of work re NRC 03-87 USS STEGER,W.A. Consad Research Corp. NRC-03-87-086 87/06/16 D.vision of Contracts (Post 870413) 1p. 45271-022-45271-022
- 8804280468 Final response to FOIA request for proposal under RS-ORM-87-223 App A records available in PDR. GRIMSLEV.OH Drivs on of Rules & Records (Post 870413). NRC-04-87-086-88/04/25 STEGER.W. Consad Research Corp. 3pp. 45271 023-45271 025
- 8804280499 FOIA request for documents re-stated contract & Soficitation RS-ORM-87 223, "Cost Analysis of Proposed Changes in NRC Requirements Having Economic Impact: Impact The Management of Paytheon Co. MARGARITHS.P.J. United Engineers & Constructors, Inc. (subs. of Raytheon Co.) MAC-04-87-086 87/05/18 THOMPSON.R.D Division of Contracts (Post 870413) 1p 45271:087-45271;067.
- 8804280504 Final response to FCIA request for nonproprietary Proposal RS-ORM-87 223 Forwards App A documents Documents available in PDR GRIMSLEY, D.H. Division of Rutes & Records (Post 870413). 88/04/25 MARGARTIS P J United Engineers & Constructors, Inc. (subs. of Ray(Neon Co.) 2pp 45271:068-45271:135.
- --8804280509 "Cost Analysis of Proposed Changes in NRC Requirements Having Eco-nomic Impact," proposel Info deleted.
 * Science & Engineering Associates, Inc. RS-ORM 87-223, 86/12/23 52pp 4221 070-45271.121.
- --8804280511 Forwards discussion on technical proposal addressing points raised a 870218 meeting Cost proposal presented separately. Into deleted WOODS,G.R. Science & Engineering Associates, Inc. 87/02/26 HAWKINS,D. Division of Contracts (Pie 870413). 14pp. 45271.122-45271:135.
- 8804280627 FOIA request for documents re H Myters correspondence from 1984-1987 CONNOR L Doc-Scarch Associates 67/10/23 GRIMSLEY,D11 Division of Rules 8 Records (Post 870413) 1p 45279 138-45279 138
- 8804280630 Supplemental FOIA request for documents re H Myers correspondence from 1984-1987. CONNOR, L. Doc. Search Associates, 87/12/07, GRIMSLEY, D.H. Division of Bules & Records (Post 870413), 1p. 45279:137-45279:137
- 8804280636 Partial response to FOIA request for documents Forwards App Codeciments Bocoments also available in PDR GRIMSLEY, D.H. Division of Rules & Records (Post 870413) 88/04/22 CONNOH, L Doc-Search Associates 2pp 45279.139-45279.196
- 8804280639 Forwards comments to be served in facility restar proceeding Subcommittee on Energy & Environ requests documents be provided to Commission. KAMMEREH.C. Office of Congressional Affairs (pre 870413) 84/03/01. PALLADINO GILINSKY, ROBERTS Commissioners 1p. 45279:141-45279 141.
- -8804280650 Responds to Commission request for comments on list of TMI integritissues, including Keaton rept & Hartman allegations.
 MYERS,H. NRC No Detailed Attiliation Given. 84/02/21 KAMMERER,C NRC Ni Detailed Affiliation Given. 5pp. 45279 142-45278 146.
- -8804280657 Forwards into for record of 8 10625 meeting of TMI-1 subcommittee of Abbott memo concerning facility accident ISE conclusion is open to interpretation the into intertuonally withheld UDALL,M.K. House of Rep., Interior & Insular Affairs 81/07/06. MOELLER,D.W. ACRS - Advisory Committee on Reactor Safeguards 7pp 45279:147-45279 169
- --8804280661 Oscusses subj of info intentionally or willfully withheld during facilit accident Record shows NRC statements logically inconsistent w/one another MYERS,H. NRC No Detailed Affiliation Given 82/03/08 DIRCKS,B., HALLER,NRC No Detailed Affiliation Given. 4pp. 45279.169-45279:191

- -9804280654 Comments on statements made at 811221 Commission meeting re-info flow drifting facility accident Inconsistences highlighted MYERS/F NRC No Dota for Affiliation Given 82/01/411 DIRCKS.B. HALLER,N NRC No Dotared Affiliation Given 5pp 45279 192-45270 196
- 8804280639 Forwards comments to be sorved in facility restant proceeding Subcommittee on Energy & Environ requests documents be provided to KAMMERER,C Office of Congressional Affers (pre 870413) 84/03/01 PALLADINO. GILINSKY, ROBERTS Commissioners, 1p. 452/9 141-45270 141.
- =8804280650 Responds to Commission request for comments on list of TMI integrity issues, including Keaton rept & Hartman alterations MYERS.H. NRC No Detailed Affidation Given 84/02/21 KAMMERER,C. NRC No Detailed Affidation Given 5pp. 45279 142 45279,146
- -- 8804280667 Forwards into for record of 810625 meeting of TMI-1 subcommittee on Abbott morno concerning facility accident I&E conclusion is open to interpretation that Info intertrionality withhold.

 UDALLMIK House of Rep. Interior & Insular Alfairs, 81/07/06 MORLLER,DW. ACRS Advisory Committee on Reactor Safeguards, 7pp. 45279,147-45279,168.
- --8804280661 Discusses subject into intentionally or willfully withhold during tacisty accelent Record shows NRC statements logically reconsistent widne another. MYERS,H. NRC. No Detailed Affiliation Given #2/03/08. DIRCKS,B. HALLER,N NRC No Detailed Affiliation Given #29. 45278 169-45278 191.
- -8804280664 Comments on statements made at 811221 Commission meeting re-info-flow during facility acculont inconsistencies highlighted.
 MYERS,H. NRC. No Defauled Affiliation Given 82/01/11. DIRCKS,B. HALLER,N.
 NDC. No. Defauled Affiliation Given 5pp. 45278.182-45279.196
- 8804280670 Partial response to FOIA request for documents App B documents available in PDI3 Records requested identified in response to FOIA 87-866 GRIMSLEY,O Division of Bules & Records (Post 870413). 88/04/21. CONNOR,L Dec Search Associates 2pp. 45263 034-45263 052
- --8507030703 Forwards program assessment of regional insplactivities over past yr Assessment attempts to mosh both quantitative & subjective into Regiests feed-back to Improvement of process PARTLOW J.G. Div. of Inspec
- --8507100054 Forwards grogram assessment of regional insplications over past yr Assessment attempts to bring together both quantitative & subjective into Suggostions on improvements requested. PARTLOW, J.G. Otc. of Inspection & Enforcement, Director (820201-870413) 857067 26 NORELIUS, C.E. Region 3, Otc. of the Director 4pp. 45263 044-45263 047.
- --8507100084 Forwards program assessment of regional insplicativities over past yr Assessment attempts to bring together both quantitative & subjective into Supgostions on improvements requested PARTLOW_JG Olic of Inspection & Enforcement, Director (82020)-870413) 85/08/ 26 WALKER,R., BEMIS,P., STOTIR,J.P. Region 2, Olic of the Director, 4pp. 45203-040-45203-9043.
- --8507100091 Forwards program assessment of regional hasp activities over past yr Assessment attompts to bring together both quantitative & subjective into Suggestions on Improvements requested.

 PARTLOW.J.G. Ofc of Inspection & Enforcement, Director (820201-870413), 86/08/ 26. STARIOSTECKLR. Region 1, Ofc of the Director, 5pp. 45263-048-45263-052.
- 8804290089 Partial rusponse to FOIA request re-cost analysis for medical svcs issue,cost tenefit analysis & background info for CRGR review of USI A-49 final resolution App P documents in PDR App O documents in PDR & forwarded GRIMSLEY.D. Division of Rufes & Records (Post 870413) 88/04/21 WEISS,E.H. Harmon & Wolss. 3pp. 45322:289-45322-313.
- --8804290 100 Forwards proposed IE Bulletin 86-002, "Unreliable Behavior of Static O-Ring Differential Pressure Switches" & supporting into for CRGR review Safety significance of sublywarrants expedited review action Recommends meeting.

 TAYLOFI, JM. Oto of Inspection & Entercoment, Director (80201-970413) IEB-86-002, 864/07/08 SKHEZEK, J.H. Committee to Review Generic Requirements 50pp. 45322 204-45322.343
- 8804290121 FOIA request for winning Proposals NRC-26-87-418 & NRC-26-87-419 sub-mitted by Sonalysts, Inc & Roy F Woston, Inc., respectively. IENZLEH,P.W. Resource Technical Sorvices, Inc. 87/11/03. HOBINSON,L. NRC -No Dotalled Alfiliation Given. 1p. 45324.048-45324.048.
- 8804290137 Final response to FOIA request for contract Proposels NRC-26-87-418 & NRC-26-87-419 submitted by Sonelysts, Inc & Roy F Weston, Inc respectively Forwards nonproprietary App A document Document also available in PDR. GRIMSELEY, D. Division of Rulus & Records (Post 870413) 88/04/21. HENZLER, P.W. Resource Technical Services, Inc. 3pp. 45324-049 45324:174.
- --8804290145 Nonpropriotary Part 1 technical & mgt proposal, "Specialized Technical Training in Specialized Equipment, Sys. Training Insp. Techniques & Practical Engineering Applications at Nuclear Power Plants."

 *Sonalysis, Inc. PS-01E-87-128, 87/03/19, 123pp. 45324:052-45324:174.
- 8804290229 FOIA request for business & mgt & technical portions of Science Applica-tions Intl Corp successful proposal in response to Solicitation RS-NRR-86-051, "Tech-nical Assistance in Support of NRC Reactor Licensing Activities." GROCHOWSKLT. UNIC Engineering Sorvices, Inc. 87/06/22. ROBINSON.L. Division of Rules & Records (Post 870413). 1p. 45284:062-45284:062
- 8804290240 Final response to FOIA request re proposal under REP RS NRR-86-051.Forwards documents listed in App A Documents also available in PDR. GRIMSLEY,D.H. Division of Rules & Records (Post 870413) 88/04/25 GROCHOWSKI,T. UNC Engineering Services, Inc. 2pp. 45284:063-45284:347.
- ---8804290267 Salicitation after & award of "Technical Assistance in Support of NHC Reactor Liconsing Activities" to Science Applications Intl Corp. LEVICK.M.L. Science Applications International Corp. (formetly Science Applications International Corp. (formetly Science Applications, Inc.). * Contract Administration Branch. 86/10/30. 155pp

- -- 8804290271 Part III of "Technical Assistance in Support of MRC Relator Licensing adovatezer i real in our common inspirance in Support of 1945, Heistor Lookes (Activities," lechnical proposal * Science Applications International Corp. (formerly Science Applications, Inc.). FIS NRR-86-051-86/10/30

GEN TEC IS GENERIC TECHNICAL ISSUES

- 8804010081 Discusses seamic qualification into for valves associated what associated to see that the discussed in util 871120 linuth, will seamically craduate any required an operated valves under resolution of USI A-46.

 ANDREWS.HIL Omaha Public Power District EC 87.603 67711725 CALVOUIA Project Directorate IV. 2pp. 45001 030 45001 001
- 8804010172 Discusses proposed actions & general consensus on Generic Issue 124 reliability Unit will provide assurance that according to the maintained & pleased that regional treatment of sefery is accorded. WILGUS.WIS Florida Power Corp (subsidiffication of Florida Progress Corp.) 3F0389-22-88, 03725 | Document Connot Branch (Document Control Cosk) 4pp. 45058-1144-8668-117
- 8804050377 Forwards Insp Repta 50 321/88 03 & 50 366/88 03 on 859201 05 for vio lations or deviations noted HERDT.A.R. Region 2, Oto at the Director, 88703/31; HEAD,G.F. Georg.a.P.JACT.Co. 2pp. 45034-053-45034-054
- -8804050385 Insp. Repts 50:321788:03 & 50:366788:03 on e80201.05 No worship noted Major lareas inspected seismic analysis for as burn safety related piping 5y8 & Mark I containment forgiterm program mod CHOURC, BLAKE R.P., CARRION, R.P. Region 2, Glo of the Director 59 556789-05 88703723 10pp 45034-055-45034-064
- 8804070175 Forwards further progress re USI A-46 Generic Ltr 87:02. Verification of Seismic Adequacy of Mechanical Equipment in Operating Reactors." Results of site specific value/impact analyses in hand & meet writte schedulid CONWAY,W.F. Florida Power & Light Co. GL-87-02 88/03/31. Decument Control Branch (Document Control Desk). 1p. 45024-355-45024-355.
- 8804110108 Responds to Generic Ltr 88-03 re resolution of Generic Safety Issue 93 "Steam Binding of Auxhlany Feedwater Pumps". Uth maintains procedures for recognizing steam binding & restoring feedwater syst to operable status. TIERNAN, J.A. Baltimore Gas & Electric Co. 60, 68-03, 89,037.31. Document Control Branch (Document Control Desk). 2pp. 45084-360-45084-361.
- 8804120113 Transcript of 880331 public meeting in Washington, DC raitneting on pro-posed final rule on station blackout Pp 1-73. Supporting documentation enci * Commissioners. 88703/31. 85pp. 45089.088.45069.175
- 8804130212 Partial response to FOIA request for documents Forwards App N documents re CRGR meetings App N documents available in PDR App O documents with held in entirety (rol FOIA Exempt on 5) GRIMSLEY, D.H. D. Wision of Hules & Records (Post 870413) 68/04/05 Wielschild Harmon & Weiss 4pp 45102 102 45102 125
- --8602100002 Lists concerns on GDC 4 package for distribution to CRGR members during CRGR Meeting 84 DBA contention temp 8 pressure as function of break size should be reviewed. J Scrinto comments to J. Sniezek cnd: ROSS, DF. Office of Nuclear Regulatory Research, Director (Fre. 860720). 867-01/27 SCHWINK, W. Committee to Review Generic Requirements. 54pp. 45102-263-45102-263.
- 8804140381 Summary of CRGR Meeting 130 on 860309 to proposed draft resolution of USI A-40, "Seismic Design" & proposed generic lit that would allow lizensees to remove organization charts from plant Tech Specs W/o encis JORDAN,E.L. Committee to Review Generic Requirements 88/03/23 STELLO.V. Old of the Executive Director for Operations, 2pp. 45118 060-45118 061
- 804180463 Summary of 880406 meeting w/NUMARC.ut/s,Science Applications,Inc.EPRI,Sandia,Trident Engineering & Devontie in Rockvite,MD re-omorgency diesel generator reliability programs SERKIZ,A W Reactor & Plant Safety Issues Branch 88/04/12 KNIEL,K Reactor & Plant Safety Issues Branch, 165pp. 45150-074-45150-230. 8804180463
- 8804220204 Discusses 336th meeting of ACRS on 860407-03 re proposed resolution of USI A-47, "Satety Implications of Control Sys." Disagrees that NRC recommendations constitute resolution of USI A-47 as originally defined KERRW ACRS Advisory Committee on Reactor Saleguards 88/04/12 ZECH, LW Commissioners 3pp. 45266 341-45266 343
- 8804220252 Responds to util 880323 fit realf rming commitment to check auxiliary feed-water piping temp once per shift per Generic Ltr 88-03 Commitments acceptable Generic Issue 93 considered resolved WAGNER, D.H. Project Directorate III.3 GL-88-03 88/04/12 FAY, C.W. Wisconsin Electric Power Co. 2pp. 45200-331-45200-332.
- 8804250106 Forwards rept to BWR overlift events that have resulted in steam lines flooding.in consideration of resolving USI A-47, "Safety implications of Control Sys" W/o rept. ROSENTHALUE Reactor Operations Analysis Branch 88/04/15 SZUKIEW-CZ.A J Engineering Issues Branch 2pp 45213 096-45213 097
- 8804250368 Forwards rept to BWR overfill events resulting in steam line flooding for consideration in USI A-47, "Safety Implications of Control Sys" KAUFFMAN, JV Reactor Operations Analysis Branch AEOD/E801 58/04/15 ROSENTHAL JE Reactor Operations Analysis Branch 7pp 45213.193.45213.199
- 8804270261 Notifies that BWR Owners Group "Guidelines for Permanent BWR Hydrogen Water Chemistry (HWC) Installations-1987 Rev," resolves Generic Issue 136, "Storage & Use of Large Quantities." & acceptable for ref in HWC installation, ABELSON,H Project Directorate 1-2 88/04/18 BRONS,J.C New York Power Authority (formetly Power Authority (formetly Power Authority (formetly Power Authority of the State of New York) 3pp. 45243 001-45243 003

- 8804270304 Withdraws portion of 870918 Tech Spec change request re detehon of MSIV leakage control sys & requests again portion of change request that allows 100 solin total MSIV leakage,per NRC 880311 rejection Itr. KAPLAN,A, Cleveland Effectio, Itium nating Co. PY-CEI/NRR-0829, 88704/18. Document Control Branch (Document Control Desk). 2pp. 45244-215-45244-216.
- 8804280386 NUREG/CR-5078 VOL A RELIABILITY PROGRAM FOR EMERGENCY DIESEL GENERATORS AT NUCLEAR POWER PLANTS Program Structure. LOFGREN, E.V., DEMOSS, G.M., FRAGOLA, J.R., Sandia National Laboratories FIN A-1806. SAND87-7176 88/04/30 Division of Reactor & Plant Systems (Post 870413). 175pp. 45271.304-45272 098.
- 8804290089 Partial response to FOIA request re-cost analysis for medical sycs issue, cost benefit analysis & background into for CRGR review of USI A-49 final resolution App P documents in FDR App O documents in PDR & forwarded GRIMSLEY,D Dwisen of Rules & Records (Post 870413), 88/04/21, WEISS,E.R. Harmon & Weiss, 3pp. 45322:289-45322:343.

IAE INSPECTION AND ENFORCEMENT

- 8803210090 Suppl 1 to NRC Info Notice 87-044, "Thirth's Tube Thinning in Westinghouse Reactors." Svc list end ROSSICE Division of Operational Events Assessment (Post 870411) 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp 44935.126-44995-248.
- 8803220296 NRC Into Notice 88:010, "Mails Licensees Lack of Mgt Controls Over Liconsed Programs." Svc list enct. CUNNINGHAM,R E Division of Industrial & Medical Nuclear Salety (Post 870729), 887 03728. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247:44995:353
- 8803290137 PNO-IV-88-022 on 880314, State of TX notified region of radiography camera falling off back of truck, jarnmed under following car, dragged for some distance 8 resulted in source being ejected from camera No significant exposures noted. DODA, BJ. Region 4, Old of the Director 88/03/22, 1p. 44921:199-44921:199.
- 8803290205 PNO I-88-035:on 870324,Troxfor Model 34118 moisture density gauge damaged in the Licensee has made contact w/Troxfer to obtain another that the traction of device to mig Gauge has been placed in drum toping age. MILLERJ, WHITE,J Region 1, Ofc of the Director, 88/03/24, 2pp 44916.248-44916.249.
- 8803290351 PNO-V-88-023 on 880323,undervoltage attachment of CRD breaker falled to operate interference of undervoltage attachment trip lever w/exterior label plate, noted. Investigation continuing.
 MILERIL D'ANGELO,T. Region 5, Ofc of the Director 88/03/24, 1p 44952.235-4663.235
- 8803290354 PNO-V-88 022.on 880316,reactor shutdown Caused by increased steam generator tube leak to 200 galions per day Oulage should take 3-4 wks Unit should be back on line approx mild-Apr 1888 JOHNSON,P.H., TATUM,J. Reg.on 5, Otc of the Director, 88/03/16, 1p. 44920.023-44000.020
- 8803290359 PNO-III-88-020 on 880310,sample results from Unit 1 sump indicated small amount of reactor coofant leakage showing measurements of less than 0.1 gpm-Visual inspiravealed misting in reactor head Region III monitoring situation. FARBERIM, JACKIW,N. Region 3, Ofc of the Director 88/03/11, 1p. 44916.250-4418-250.
- 8803300026 PNO-III-88-025A State of IA informed Region III that J Deere Co had only 14 Inform-filled exit signs, not 20 to 30 as previously reported One sign recovered by State of IA inspector displatched to scene. ADAM,W.J., MALLETT,B. Region 3, Oic of the Director. 88/03/24, 1p. 44820.048-44920.048
- 8803300035 PNO-III-88-025;EPA in Kansas City Informed Region III that 20 to 30 luminascent exit signs containing 25 CI radioactive tritium gas crushed during razing of tridg in Dubuque,IA.

 ADAM,W.J., MALLETT,B. Region 3, Ofc of the Director, 88/03/23, tp. 44921:253-
- 8803310033 EN-85-026:on 880329,notice of violation & proposed imposition of civil penalty in amount of \$50,000 will be issued Action based on several examples of failure to satisfy fire protection requirements.

 WONG,H., LIFBERMAN,J. Ofc of Enforcement (Post 870413). EA-88-044, 88/03/24, 1p. 44953:242-44953:243.
- 8803310045 EN-88-024:on 880329,notice of violation & proposed imposition of civil penalty in amount of \$500 will be issued Action based on improper disposal of radwaste matts & three examples of failure to perform surveys.

 JOHANSEN,J. LIEBERMAN,J. OIC of Enforcement (Post 870413). EA-87-241, 88/03/24, §p. 44953-241-44953.241.
- 8803310110 PNO-IV-98 023 on 880324 licensee notified region of two sources containing Cs-137 being thrown from vehicle that ran off road in Basin,WY.Caused by intoxicated driver.Container found.No confamilation dotected. WILBORN,L. Region 4, Oic of the Director. 88/03/24, 1p. 44983:007-44983.007
- 8804010243 PNO-III-88-026:on 880323 licensee began orderly shutdown of Unit 1 due to identified deficiencies in fubricant used in motor-operated Limitorque valves Officiencies apply to 263 safety-related valves in both Units 1 & 2. HINDS.J., FORNEY,W. Region 3, Ofc of the Director. 88/03/24. 1p. 45028.041-45028-041.
- 8804010258 NRC Into Notice 88-011, "Potential Loss of Motor Control Ctr &/or Switchboard Function Ove to Faulty Tie Bolts." Svc list end, ROSSI,C.E. Division of Operational Events Assessment (Post 870411), 88/04/07. Consolidated Edison Co. of New York, Inc. 124pp. 45406-292-45407:051.
- 8804040201 PNO-III-88-0188 on 880316, augmented insp. team dispatched to site to review events ris 880309 dual recirculation pump trip followed by loss of leadwart healing resulting in feactor scram. Unit restarted on 880318 w/o juriner problems. RING,M., FORNEY,W. Region 3, Ofc of the Director. 88/03/25. 2pp. 45079:105-45079:106.

- 8804040240 PNO-IV-88-024 on 880330, reactor trip & safety injection occurred due to loss of offsite power. Caused by troubleshooting work on main generator control circuits to determine cause of main generator output breaker trip.

 CONSTABLE,G.L. Region 4, Ofc. of the Director. 88/03/31, 2pp. 45075:306-45075:307.
- 8804050383 PNO I-88-036 an 880222 & 0321 discovered that licensee conduct & documentation of licensed operator qualification training did not meet requirements of 10CFR55 59 & approved training procedures Continuatory action Its will be issued. LANGE, D. Region 1, Otc of the Director. 88/03/28. 1p. 45034:048-45034:048.
- 8804060080 PNO I-88-037 on 880330.licensee reported their of portable nuclear gauga containing 7.3 mCr Cs-137 & 40 mCr Am-241/Be from secured trailer in Sweetwater,TN that occurred on 880329.Local law enforcement agencies notified. PELCHAT,J, WHITEJ, MILLER,M Region 1, Ofc of the Director, 88/03/30. 1p. 45072.106-45072.106
- 8804060242 PNO-III-88-027:on 880330,FEMA informed NRC that offsite radiological emergency plan inadequate FEMA review revealed that areas of Cedar Rapids & Mazion,IA beyond identified 10- mile EPZ not included in offsite emergency planning effort.
 - SNELL,W., SHAFER,W. Region 3, Ofc of the Director. 88/04/01. 1p. 45034:101-45034:101.
- 8804060301 PNO-II-BB-020.on 880327,loss of power to vital bus III experienced Operator manually tripped reactor then tripped reactor coolant pump.Unit later experienced automatic satety injection.Unit stabilized in hot shutdown CANTRELL,F.F. Reg on 2, Otc of the Director. 88/03/29. 2pp. 45034:183-45034:184.
- 8804060325 PNO-II 88-015B on 880229, iconsee informed NRC that 1 MWI pool reactor had been shutdown due to primary coolant leak outside containment. Two leaks identified Util plans to isolate leak & test further to assure that leak is in liner. FREDRICKSON,P. Region 2, Ofc of the Director. 88/03/24, 2pp. 45071:360-45071:361.
- 8804080334 EN-88-026 on 880405 notice of violation & proposed imposition of civil penalties in amount of \$2,500 will be Issued to licensee Action based on several violations, Including cumulative radiation exposure.
 FLACK_E, LIEBERMAN_J. Oic of Enforcement (Post 870413), EA-88-054, 88/03/31, 1p. 45071:359-45071;359
- 8804060337 EN-87-075C on 880405 notice of violation & proposed Imposition of civil penaltiles in amount of \$4,200 will be issued to licensee Action based on several violations, including failure to administer periodic training. FLACK, E., LIEBERMAN, J. Otc of Enforcement (Post 870413), EA-87-128, 88/04/05. 1p 45072.045-45072.045
- 8804060370 NRC Info Notice 88-012, "Overgreasing of Electric Motor Bearings." Svc Island.
 - nst unct ROSSI,C E. Division of Operational Events Assessment (Post 870411), 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165:028-45165:150.
- 8804060447 PNO-III-88-026 on BB0331 licensee reported that industrial level gauge containing sealed radiation source containing 50 mCi Cs-137 not located Gauge discovered missing on 86030. Licensee continuing search State of OH notified. WIEDEMAN,D., MALLETT,B. Region 3, Ofc of the Director, 88/04/01, 1p. 45072.073-
- 8804070246 PNO:1-88-038 on 880330 reactor manually tripped following loss of turbine generator hydraulic control oil pumps Util will remain shutdown for 2 wks to repair steam generator tube leakage. State of NJ notified.

 80RCHARDT,W., SWETLAND,P. Region 1, Ofc of the Director, 88/03/31, 1p. 45072;242-45072:242.
- 8804070248 PNO-I-88-039:on 880329,uninterruptable power supply (UPS) B declared out of svc due to blown fuse & fallod circuit cards. On 880331,valve CS-11B declared inoperable & reactor shutdown initiated. Repairs & post-maint of UPS B completed. GRANT.O., HAVERKAMP.D. Region 1, Ofc of the Director. 88/04/01. 2pp. 45072:240-45072:241.
- 8804070338 PNO-V-88-024:util received final authorization from NRR to restart facility on 880300 Enhanced operational readiness insplicam & resident insplication between the reactor startup which will require 6-10 hit ocomplete.

 MILLER,L. Region 5, Ofc of the Director. 88/03/30. 1p. 46021:264-45021:254.
- 8804080017 PNO-III-88-029.on 880402.shutdown begun to repair steam generator tube leak Leakage rate from RCS into secondary sys calculated to be 330 gallons per day. Other maint 8 testing work planned in addition to investigation & repair. HINDS_J., FORNEY,W. Region 3, Ofc of the Director. 88/04/04, 1p. 45092:199-45092:199.
- 8804080174 NUREG 1310 NATURALLY OCCURRING AND ACCELERATOR-PRO-DUCED RADIOACTIVE MATERIALS 1987 Review. AUSTIN.J.H. Office of Nuclear Material Safety & Safeguards, Director, 88/03/31, 74pp. 45201:180-45206:038.
- ••8604140383 PNO III: 87-123 on 870908 Region III notified by State of MO that scrap dealer in Sikeston MO detected redioactive contamination in two rail car loads of aluminum mall received from United Technology, Inc. Related info encl. WIEDEMAN, D., MALLETT, B. Region 3, Ofc of the Director. 87/09/11, 21pp. 45203.008-45203.028.
- 8804080211 PNO-III-88-030:on 880404.supervisor discovered two pieces of foam mattinside bearing housing on turbine-driven auxiliary leedwater pump.FBI notified of tampering Region III plans to issue confirmatory action ltr. CREED.J. MALLETT.B., BURGESS,B. Region 3, Ofc of the Director. CAL, 88/04/05. tp. 45098:182-45098:182.
- 8804110081 EN-87-089A:on 880407 order imposing civil penalty in amount of \$7,500 issued to licensee. Action based on radiological overexposure to radiographer & demonstrated need for improvement in mgt control over personnel exposures. FLACK.E., LIEBERMAN.J. Ofc of Enforcement (Post 870413). EA-87-145, 88/04/07. 1p. 45142.064-45142.064.

- 8804110265 PNO-IV-88-025 on B80404/following manual reactor scram, unplanned re-lease of noble gas occurred when refiel velve opened to relieve pressure in vent line between the core support floor & waste gas sys WESTER
- 8804130125 Partial response to FOIA request for documents re info Assessment Team notification & alleged valve tampering App A documents available in PDR.Forwards App B documents. App B documents also available in PDR G
- ~8804130151 PNO-III-87-101:on 870726 licensee received bomb threat from caller angry because place of residence lost power during storm. Security personnel notified & search procedures implemented. No bomb discovered. CHEED, J., AXELSON, W. Region 3, Oic of the Director. 87/07/27, 1p. 45102-036-45102-036.
- 8804130187 PNS-1-88-001:on 880406 handgun detected during routine x-ray machine search at protected area entrance point. Worker access badge temporarily withdrawn pending investigation. Licensee believes incident unintentional. BAILEY.R., KEIMIG.R. Region 1, Otc of the Director. 88/04/06 1p. 45154:070-45154:070.
- 804130193 PNO-III-88-033 on 880331, low level contamination found on ovens, floors, hoods & walls & one employee found w/external contamination. Individual successfully decontaminated. Decontamination of three areas began on 880401. ADAM.W. MALLETT.8. Region 3, Ofc of the Director. 88/04/07. 1p. 45154:072-45154:072.
- 8804130197 PNO:III-88-034:on 880406;up to 68 workers received minor exposures to airborne radioactivity,principally 1-131,during steam generator tube plugging activities Cause under Investigation Respirators required to enter containment. GREGERR, SHAFER,W. Region 3, Otc of the Director. 88/04/07. 2pp. 45131.004-45131.005
- 8804130266 EN-88-030:on 880411 order continuing suspension of license & order to show cause why license should not be revoked & notice of violation issued. CANT,G. Ofc of Enforcement (Post 870413). LIEBERMAN,J. Ofc of Special Projects. EA-88-069. 88/04/11, 1p. 45164:155-45154:155.
- 8804140038 PNO-III-88-032:on 880406,two patients received less than prescribed radiation doses in radiation therapy.Caused by error in applying formula used to calculate exposure period. Treatment records of other patients being reviewed WIEDEMAN,D., MALLETT,B. Region 3, Olc of the Director, 88/04/08. 1p. 45152:145-
- 8804140041 PNO-III-88-031:on 880405.grand jury Indicted licensee & corporation radiation safety officer.Count 1 of Indictment alleges that in 1985 Irwin & licensee created exposure record for employee, falsely backdating record to 840812.

 MARABITO.R., WIEDEMAN,D. Region 3, Old of the Director. 88/04/08. 1p. 46152 148 45 152 148
- 8804140043 PNO-IV-88-028 on 880407 unplanned release of 157 mC; noble gas occurred Caused by failure of flexible joint in circulating water pump (CWP) pump pit resulting in flooding of CWP & motors Cooldown Intitlated.

 WESTERMAN,T.F. Region 4, Ofc of the Director. 88/04/07, 2pp 45147:319-
- 8804140370 PNO-I-88-040:on 880408, during planned maneuver to correct unidentified primary sys leakage.control rods CEA-44 & CEA-4 dropped into core.Containment opened on 880409 to identify teakage.Facility shut down in excess of 48 h. RAYMOND,W., MCCABE,E., BETTENHAUSEN,L. Region 1, Ofc of the Director. 88/04/11. 2pp. 46158:326-45158:326.
- 8804190010 EN-88-029:on 880413,notice of proposed Imposition of civil penalty in amount of \$100,000 will be issued to licensee, based on violation of requirements re improper engineering & review & failure to follow procedures.

 LUEHMANJ, LIEBERMANJ, Ofc of Enforcement (Post 870413), EN-88-062, 88/04/08, 1p, 45199-075-45199-076.
- 8804190035 EN-88-028:on 880413,notice of violation & proposed imposition of civil penalty in amount of \$2,500 will be issued to licensee based on licensee not having authorized physician to use & supervise use of licensed mail.

 JOHANSENJ, LIESERMANJJ. Of of Enforcement (Post 870413). EA-87-125. 88/04/08. 1p. 45208:206-45208:206.
- 8804190094 PNO-II-88-022 on 880405 low levels of radioactive mail detected in demin-eralizer beds for plant makeup water. Caused by concentrating effect of radionuclides. Licensee currently storing spent demineralizer beds onsite until NRC approva. KAHLE,J. Region 2, Oto of the Director. 88/04/08, 1p. 45209:173-46209:173.
- 804190097 PNO:II-88-021:on 880404,licensee commenced controlled shutdown.Caused by unidentified reactor coolant leakage approaching Tech Spec limit of 5 gallons/minute over 24 h. Licensee plans 7-day outage to correct eiutation. PATTERSON,C. Region 2, Otc of the Director, 88/04/05, 1p. 45208;159-45209;159.
- 8804190103 PNO-II-88-017A:on 880409.State of AL Issued press release on stolen Trokler gauge.Device recovered.leak tested & returned to svc. WOODHUFF.R.L., TROJANOWSKI,R. Region 2, Ofc of the Director. 86/04/11. 1p. 45208:163-45208:163.
- 8804190248 EN-88-027:on 880412 notice of proposed imposition of civil penalty in amount of \$50,000 will be issued based on tallure of cold overpressure protection system to be operable prior to & during pressure transient when sys could have actuated. LUEHMANJ, LIEBERMANJ, Off of Enforcement (Post 870413). EA-88-081, 98/04/07, 1p. 45208:054-45208:054.
- 8804200386 PNO-1-88-041:on 880414,unidentified leak exceeded 6 gpm limit. Leak identified from PORV block valve packing leakoff line. Manual valve in leakoff line shut off. Checks for leaks & high temp investigation continuing.

 RAYMOND,W., MCCABEE, BETTENHAUSEN,L. Region 1, Ofc of the Director, 88/04/16, 1p. 45221:156-45221:165.
- 8804210194 PNO-III-88-035:on 880303.Univ of Toledo notified NRC that extensive radium contamination found in crawl space which had been locked & posted News media carried repts of INRO insp findings.Independent evaluation suggested. WIEDEMAN.D., MALLETT,B. Region 3, Ofc of the Director. 88/04/11, 2pp. 45216:175-45216:176.

- 8804210202 PNO-III-88-037.on 880412.approx 1,000 galfons of radioactive water drained from RHR sys piping into equipment room. Split occurred when RHR valves returned to normal positions after leak rate testing Cleanup of rooms & equipment infitaled. GREGER,R., SHAFER,W. Region 3. Ofc of the Director. 88/04/13. 1p. 45231:169-
 - 45231.169
- 8804210207 PNO III-88-038 on 860208 contaminated devices & work ereas found at food processing plant. Conveyor belt contaminated w/ Po-210 removed & packaged for shipment to 3M for disposal Region III to assist State of IL w/analysis of samples. ADAMW, WIEDEMAND. MALLETT.B. Region 3, Ofc of the Director. 88/04/15. 1p. 45254:331-45254:331.
- 8804210211 PNO-OSP-88-004A on 880408 calculated unidentified leak rate of 1.09 gpm obtained exceeding Tech Specilim tof 1 gpm. Differential pressure transmitter reactor coolant seel return line isolated Plant currently in Mode 5 for repairs. RICHARDSON,S. Ofc of Special Projects. 88/04/12, 4pp. 45231:165-45231:168.
- 8804280222 Discusses review of responses to NRC Bulletin 88-003, "Inadequate Latch Engagement in HFA Type Latching Relays Mtg by GE." Project managers should review icensee responses to assure that appropriate confirmation received Bulletin
- RIVENBARK,G. Project Directorate I-2. IEB-88-003. 88/04/20, NRC No Detailed Af-Iliation Qiven 2pp. 45263 016-45263.026.

MISC PUBLIC DOCUMENT ROOM MISCELLANFOUS

- 8804120201 Forwards lifth "Annual Rept of ASLBP for FY86."
 COTTER.B.P. Atomic Safety and Licensing Board Panel 88/03/31. ZECH Commissioners. ROBERTS, ASSELSTINE NRC No Detailed Athilation Given. 1p. 45091:307-45091:351.
- 8804140362 Summary of 880119 meeting w/Nuclear Assurance Corp in Rockville,MD re design of new legal weight truck cask.
 ODEGAARDEN,R.H. Division of Safeguards & Transportation (Post 670413), 68/03/ 30. Division of Safeguards & Transportation (Post 870413). 4pp. 45118.056-
- 8804180309 Forwards NRC entercement program,per 880322 meeting to discuss enforcement programs of DOT & NRC.Civil penalty actions processed in 1986 & 1987 by US Coast Guard Involving radioactive mail requested.

 LIEBERMAN.J. Otc of Enforcement (Post 870413), 88/04/04. HUGHES,S.V. U.S. Coast Guard, Transportation, Dept. of. 1p. 45148-360-45148-380.
- 8804200517 Summary of 880322 meeting w/Nuclear Assurance Corp In Rockville,MD re design of new legal weight truck cask.

 ODEGARDEN,R.H. Transportation Branch 88/03/30, Transportation Brench. 2pp. 45192.088-45192.093.
- 8804200528 Summary of 871120 meeting w/Nuclear Assurance Corp in Silver Spring,MD re-design of new legal weight truck cask.

 ODEGARDEN,R.H. Transportation Branch. 88/03/30. Transportation Branch. 2pp. 45191.358-45191:361.
- 8804210177 Summary of 871026 meeting w/Virginia Power Co.GNS & GNSI/ CNSI in Silver Spring.MD re feasibility of obtaining certificate of compliance for transportation of spent fuel in casks made from nodular cast from.

 LEE_H.W. Transportation Branch. 88/04/04, Transportation Branch. 3pp. 45191:177-45191:179.
- 8804280648 Ack receipt of 680303 memo suggesting several initiatives to improve matl licensing & inap program Agrees that Region IV could initiate pilot programs & rept conclusions in early 1989.

 THOMPSON.H.L. Office of Nuclear Material Safety & Safeguards, Director. 88/04/13.

 MARTIN,R.D. Region 4, Old of the Director. 4pp. 45269.171-45269:174.
- 8904290655 Provides background values for Po-210 in urine,per request. Into has been synthesized from discussions w/N Cohen of New York Univ.J. Mulier of Controls for Environ Pollution & data reported by Atomic Energy Control Board, Canada COOL.D.A. Operations Branch. 88/04/06. WHITE.J. Region 1, Oic of the Director. 1p. 45269:176-45269:176

NUREG NUREG REPORTS AND RELATED CORRESPONDENCE

- 8803080019 Forwards safety evaluation approving capability of primary sys safety & relief valves & associated block valves.per TMI Action Item II.O.I.Conclusions pred cated upon successful completion of valve lest program.

 JAFFE,D.H. Project Orrectorate I-4. TAC 4594. 88/03/01. MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 30pp. 44633:193-44633:222.
- 8803100025 Forwards request for additinto re 870908 request for exception to one of four criteria for radiolodine & particulate sampling requirements of NUREG-0737, Item III.F.1 concerning design basis shielding envelope.
 HOOD, D.S. Project Directorate II-3, TAC 66897, 88/03/07, TUCKER, H.B. Duke Power Co. 3pp. 44661:356-44661:360.
- 8803250156 Forwards draft Rev B to IE Insp Procedure 92412, "Emergency Response Facilities Appraisal." ERF appraisal will be conducted using team approach per recommended insp assignment matrices in procedure. COLLINS,D.M. Region 2, Ofc of the Director. 88/03/16. STEWART,W.L. Virgin'a Power (Virginia Electric & Power Co.). 39pp. 44914:228-44914:266
- 8803280063 Forwards Director's Decision DD-88-03 denying GAP 880126 request, per 10CPR2.208, to delay Commission licensing actions on plant W/o FR notice of decialon. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). #398 5887. 2.206. 88/03/18. GARDE,B.E., CONDIT,R.E. Government Accountability Project 4pp. 45215.007-45215:173.
- --8604250297 Notice of issuance of Director's Decision DD-86-03,denying GAP requests to delay licensing actions on unit, NUREG-1306, "NRC Safety Significance Assessment Team Rept on Allegations ro South Texas Project,Units 1 & 2," enct. MURICEYT.E. Office of Nuclear Reactor Regulation, Director (Post 870411). OO-88-03. 88/03/18, 100pp. 45215:024-45215:173.

- 8803290097 Forwards Rev 7 to util 830414 response to Suppl 1 to NUREG 0737, ricluding solutions to human engineering discrepancies. TUCKER, Hill Duke Power Co. 88/03/15 Document Control Branch (Document Control Desk). 13pp. 44945 237-44945 249.
- 8803300015 Forwards prophetary NEDC-30793-P. "Feetiwater Nozzlu Fracture Muchanics Analysis to Show Compliance w/ NUREG-0619," & discription of proposed inspiring for feedwater nozzlos & discussion of program justification BRONS, JC. New York Power Authority (formerly Power Authority of the State of New York) JPN 88-010-88703/25 Document Control Branch (Occument Control Dask) 9pp. 44962-085-44962-072
- 8803300375 Responds to 880222 fit re low level raulwaste disposal practices into provided includes estimated porosity of 26% reported in Table 2.1 of NUREG/CH-4756/we different types of comunis & waste so unification processes GREEVES.J.T. Unission of Low Level Waste Management & Decommissioning (Post 870413) 88/03/11 RICEY.J.L. Alfikation Not Assigned, 15pp. 44945-300-44945-315
- 8803300434 Requests NRC concurence w/util position that a'll induction heating stress mprovement treated works at plant can be placed in Category B classification of NUREG-0313,Rev 2 & Generic Ltt 88 01. LEONARDJ D Long Island Lighting Co. Gt. 88 01. 88703728. Document Control Branch (Cocument Control Dest). 2pp. 44967-246. 44967-247.
- 8803310035 Discusses mitigative actions,we'd overlay upgrades & IGSCC insps per-formed during Reload 7 outago lipidated classification of sive sensitive weldments into 7 outropries per NUHEG-0313, Rev 2 also included LOPLIN,LI Ficardina Power & Light Co. NLS-88-073 88/03/25 Document Control Branch (Document Control Desk) 20pp 44982 207-44992 324
- 8803310168 Comment opposing Rev 1, Suppl 1 to NUREG-0654/FEMA-REP-1. Requirement should be stated for licensee to identify duties that will be done by people not paticipating -in planning or dills HOTCHKISS,W attlation Not Assigned 52FR45866 00023 88/03/18. MEYER,D. NRC - No Detailed Africation Given 2pp 44962/130 44962/131.
- 8804010063 Forwards Insp Rept 50:416/87:32 on 871214-18 & notice of violation. HERDT,A.R. Region 2, Otc of the Director, 88/03/25 KRNGSLEY,O.D. System Energy Resources, Inc. 2pp. 45028:146-45028.170
- --8804010067 Insp. Rept. 50.416/87-32 on. 871214-18 Violations noted Major areas inspected environ quartication of electrical equipment in promontation of 10008850.49 requirements & electrical equipment within scope of 1000850.49 RUFF, A. CONLON,T.E. Region 2, Ofc. of the Director. 88/03/24, 20pp. 45028.151-45028.170.
- 8804010081 Discusses seismic qualification info for valves associated w/air asccumula-tors discussed in util 871120 fir Util will seism cally evaluate any required air operatud valves under resolution of USI A-46 ANDREWS.H.L. Omaha, Public Power, District, Gt-87-02, B7/11/25, CALVO, J.A. Project Oirectorato IV, 2pp. 45001,030-45001,031.
- 8804010092 NUREG/CR-5041 VO2 RECOMMENDATIONS TO THE NRC FOR REVIEW CRITERIA FOR ALTERNATIVE METHODS OF LOW-LEVEL RADIOACTIVE WASTE DISPOSAL Task 26 Earth Mounded Concrete Bunkers. DENSON, R.H., BENSOT, ETT, R.D., WAYSLEY, R.M. Army, Dopt of, Army Engineer Waterways Experiment Station, FIN D-1071, 88/01/31, Division of Low Level Waste Management & Denson, R.D., Programment Station, FIN D-1071, 88/01/31, Division of Low Level Waste Management & Denson, R.D., Programment & Den agement & Decommissioning (Post 870413) 118pp. 44950 219 44950 336
- 8804010116 NUREGYCR-5065 TIME: AND VOLUME-AVERAGED CONSERVATION EQUATIONS FOR MULTIPHASE FLOW USING MASS-WEIGHTED VELOCITY AND HITERNAL ENERGY.
 SHAW.T., CHAO.B.T., SOO,S.L. Argonne National Laboratory. FIN A 2255. ANL-87-51. 88/01/31. Division of Reactor Accident Analysis (Post 870413). 84pp. 44950.125-
- 6804010162 Forwards SSER 14 to NJREG-0797 re operation of plant Suppl presents salety evaluation on matters re corrective action program associated w/design of large & small bare piping & pipe supports Corrective action program acceptable W/o GRIMES C+ Otc of Special Projects 88/03/09 COUNSIL,W.G. TU Electric (formerly Toxas Utilities Generaling Co.), 1p. 44949.021-44949.021.
- 8804010163 Furwards request for additinfo re util responses to Generic Lir 86:05 on implementation of NUHEG-0737,tem ILK-3.5 conerning reactor coglant pump trip Response requested within 60 days.

 SILVER,H. Project Directorate II-2 TAC 49668 88/03/28 WILGUS,W.S. Florida Power Corp (subs. of Florida Progress Corp.), 5pp. 44949-022-44949-027
- 8804010215 NUREG/CA:4785 REVIEW AND EVALUATION OF DESIGN ANALYSIS METHODS FOR CALCULATING FLEXIBILITY OF NOZZLES AND BRANCH CON-
- MECTIONS
 MOORE.S.E., RODABAUGH.E.C., MOXHTARIAN,K. Oak Ridge National Laboratory, FIN B-0474 ORNL-5339 B7/12/31 Division of Engineering (Post 870413) 108pp
- 8804010223 NUREG/CR-5018 URANIUM OXIDE IRON OXIDE MIXED AEROSOL EX-PERIMENTS IN STEAM-AIR ATMOSPHERE'S NSPP Tests 611,612,613 And 631,Data Record Report.
 TOBIAS.M.L., ADAMS.B.E. Oak Ridge National Laboratory. FIN B-0121 ORNL/TM10588 98/01/31 Division of Reactor Accident Analysis (Post 870413) 63pp
 44974 192-44974/255.
- 8804010249 Establishes guidelines between NRR & RES for technical review of slid plant designs, namely. Westinghouse RESAR SP/90, GE advanced BWR, C-E Sys 80 & EPRI advanced twR requirements document Four criteria for new design listed MURLEY, T.F. Office of Nuclear Reactor Regulation, Director (Post 870411) BECKJOHD, E.S. Office of Nuclear Regulatory Research, Director (Post 860720) 88/ 03/14. STELLOV. Ote of the Executive Director for Operations. 4pp. 44949.160-44049.174
- --8804010254 Documents transfer of responsibility for standardization & advanced reactor policy issues from NIRB to RES, consistent w/NUREG 0325 BECKJORD, E.S. Office of Nuclear Regulatory Research, Director (Post 860720), 87/05/22. MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 5pp 44949 154-44949 158.

THICK PRESSURE VESSELS PTSE-2 Investigation Of Low Training Resistance At Warin Prestressing

BRYAN,HH, BASS BR, BOLT SE, Oak Ridge National Laboratory, FIN 8-011

ORNL-6377, 87/12/31, Division of Engineering (Post 870413), 306pp. 44949,17 44950 124.

8804010275 NUREG/CR 4888 PRESSURIZED THERMAL SHOCK TEST OF 6 INC

- 8804010277 Forwards request for addl info re control room habitability sys 6valuation SILVER.H. Project Directorate II.2 FAC 64805 88703729 WILGUS.W.S. Florid Power Corp (subs. of Florida Progress Corp.) 9pp. 44948 259 44948 267
- 8804040037 Forwards "ECCS Outage Data for 1987," per Chapter 13,Section 13.5.1.1 N of plant FSAR & NUREG-0737,Item II K.3.17 GUCWALT. Georgia Power Co. SL-4429, 89/03/28 Document Control Branch (Dourent-Control Desk), 1p. 44970-054-44970-058.
- 8804040063 Provides addlinto to draft supplement of FES to reinfecommissioning Rare Earths facility Ropt by Senes Consultants Limited to NRC estimates of dosh general public during sit action period end.

 MESERVE,R.A. Kerr-McGee Chemical Corp. (subs. of Korr-McGee Corp. MESERVE,R.A. Covangion & Burling 29155 88703723 SWIFT,J.J. Fuel Cycle Safe Branch 6pp. 44972 202-44972 209
- 8804040067 Responds to NRC 871020 request for addlintoire NUREG-0737, Ite II D.1, "Parformance Testing of Rorol & Safety Valves." Submittal of response fillens 6.9 reschedular for 880601.
 SMEDLEYRIW Consumors Power Co. 88703729. Document Control Branch (Document Control Desk.). 5pp. 45020-309-45020-313.
- 8804040104 Forwards Rev 5 to diffsite dose calculation manual,per 871123 request Re addresses all but three discrepancies noted in technical evaluation rept Discrepancies not addressed, restated,followed by util response GALLAGHER, JW Prividelph a Efectic Co 88703730 CtARK,H J Project Directora 1-2, 3pp 44970 096-44970.229.
- 8804040202 Forwards discussion of post-accident boron analysis,per NUREG-0737,file it B 3.0t1 experience indicates that marchiol tritration method superior to Illuoroboro alternative because of samplicity & reliability
 THOMAS,G.S. Public Service Co. of New Hampshire, NYN-88037, 68703730, Document Control Branch (Document Control Desk), 3pp. 45076,112-45076,114
- 8804050160 NUREG/CR-5058 PRA APPLICATIONS PROGRAM FOR INSPECTION A ARKANSAS NUCLEAR ONE UNIT LDocket No. 50-313.(Aikansas Power and Lig Company)
 VO.T.V. HARRIS,M.S. GORE,B.F. Battello Memonal Instituto, Pacific Northwest Lai oratorios, FIN B-2602, PNL-6394, 88/03/31, Region 1, Ofc of the Director, 74p 44972 032-44972,106
- 8804050264 NUREG/CR-5050 ANNOTATED BIBLIOGRAPHY OF RELIABILITY AN RISK DATA SOURCES
- HESTER, OV. BROWNS R., GENTILLONC D. EGBG Idaho, Inc. (subs. of EGBC Inc.). FIN A-6237. EGG-REO-7827. 88/03/31 Division of Safety Programs (Po. 870413) 195pp. 45009.050-45009.244
- 8804050313 Forwards second rovised prehiminary SER re plant performant plan, adding new or modified sections concerning design control crist 8 obclinical calculations & App Riper 880121 & 0217 litris Final evaluation will be issued as NUHEC 1732. EBNETER,S.D. Otc of Special Projects, 88/03/25, WHITE,S.A. Tunnessee Valley Atthough, 361pp. 44998.001-44998.361.
- 8804060112 NURIEG 0430 V08 NO1 LICENSED FUEL FACILITY S1ATU REPORT Inventory Difference Data January-June 1987 (Gray Book II) * Office of Nuclear Material Safety & Saleguards.Director. 88/03/31. 17p 45029 197-45029 212
- 8804060248 Application for amends to Licenses NPF-4 & NPF-7,changing Tech Sp. Tables 3.3-10 & 4.3-7 to include incore thormocouples in accident monitoring instrumentation.per NUREG-0737,ttem file 2.8 Generic Ltt 83-37.Feb paid. STEWART.W.L. Virgina Power (Virgina Electric & Power Co.) GL-83-37. 88/03/3/Document Control Desk). 3pp. 45034-080-45034-090.
- 8804060455 Forwards Safety Insp. Rept. 50.481/88-05 on 880224-26.No violation noted SHAFFR,W.D. Hegion 3, Old of the Director, 88/04/01, GERSTNER,W.C. Illino Power Co. 2pp. 45072-017-45072-029
- -8804060462 Salety Insp Rept 50-461/88-05 on 880224-26 No violations or deviation noted Major areas inspected solid radwaste program including organization & microhisiguatrications & training solid radwaste & transportation activities SI AWINSKI W J. GHEGER, R. Region 3, Otc. of the Director. 88/03/31. 45072 019 45072 029.
- B804080515 Informs of util intent to remove tube wbration instrumentation installed steam generators as part of vibration test program described in util 84031 lit Approval requested for element-on of vibration monitoring program COUNSILW G. BECK_JW TU Electric (formerly Texas Utilities Generating Co.) TX. 88341. 88/03/28 Document Control Branch (Document Control Dosk). 2p. 45007:105-45007.106
- 8804070051 Forwards magnetic data tape containing available validated meteorologic data from onsite instrumentation for Apr 1979 Dec 1983 & Oct 1986 Jun 1987. Tape formal developed per NUREG 0800, Section 2.3.3, App A THOMAS,G. Public Service Co. of New Hampshire. NYN 88041, 88704701. Documer Control Branch (Document Control Desk). 6pp. 45022,132-45022,137.
- 8804070170 Informs of selection of Westinghouse sleam generator low level ATW mitigation sys design for installation at facility during 1989 refueling outage NRC approval by 880603 requested Additinto and Wyseven oversize drawings HINT2.0 C. Wisconsin Public Service Corp. GL-85-06. 88703/31 Document Control Branch (Document Control Desk). 27pp. 45044.081-45044:107.

MIMAGENTI J. ASSOCIBIO EXPORTOL IOL PROJECTS (PGSL BAUALL). 2200. ADDIES CAL-

8804060085 Responds to CM Cottins #80219 ftr re FEMA analysis of prompt alert & notification sys for facility Details of util roylew of FEMA ftr & questions to FFMA Survey end MCDONALD R.P. Alabama, Power Co., NT-88-0163, 88/03/31, Decument Control

Branch (Occument Control Desk), 26pp, 45098 279-45098 384

- 8804080121 NUREGICE 5032 MODELING TIME TO RECOVERY AND INITIATING EVENT FREQUENCY FOR LOSS OF OFFSITE POWER INCIDENTS AT NUCLEAR POWER PLANTS
 - DMAN R 1 (FGRAS C Sandia National Eaboratories FIN A-1393 SAND87-2428 807 03/31 Dysion of Reactor Accident Auglysis (Post 870413) 61pp 45038 095-45038 155
- 8804080125 NUREG 0020 V12 NO2 LICENSED OPERATING REACTORS STATUS SUMMARY REPORT Data As Of January 31,1988 (Gray Book I) SCHWARTZ I Division of Computer & Telecommunications Services (Post 870413) 80/03/31 499pp 45038 189-45039 327
- 8804080131 NUREG/CH 3950 V04 FUEL PERFORMANCE ANNUAL REPT FOR 1986 BAILEY,W.J. Batto e Memorial Institute, Pacific Northwest Laboratories WU.S. NRC No Detailed Affiliation Gwen FIN B-2997 PNL-5210, 88/03/31, Dwision of Engineering & Systems Technology (Post 870411), 183pp. 45034 199-45035 021
- 8804080134 NUREG/CR-4667 V84 ENVIRONMENTALLY ASSISTED CRACKING IN LIGHT WATER REACTORS Semannual Ropt October 1986 March 1987. SHACK W.J., KASSNER, I.F., MAIYA, P.S. Argorne Nathmal Laboratory, FIN A-2212, ANJ-87-41 887/27/9 Division of Engineering (Post 370413) 77pp. 45339-328-45040 043
- 8804080136 Proposes standardized test procedure for compression testing of bitimen solid held low lovel radwaste Molhods of interpretation as outlined in NUREG/CR-3029 discussed Test Procedures D 1074-83 & D 695-85 encl SIMPSON-S1 Associated Technologies, Inc. CH-171-034 88/03/21 TOKAR,M. Technical Branch. 22pp. 45073.316-45073.337
- 8804080170 NUREG/CR-4860 ROLFLAW DENSITY EXAMINATIONS OF A CLAD BOILING WATER REACTOR PRESSURE VESSEL SEGMENT. CCOK,K.V., MCCLUNG,R.W. Oak R.dyo National Laboratory FIN B 0119 ORNL/TM-10364-86/02/29 Division of Engineering (Post 8704.13), 34pp. 45038;156-45038.188
- 8804080171 NUREG-0781 S05 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SOUTH TEXAS PROJECT UNITS 1 AND 2 Docket Nos 50-498 And 56-499 Hecusion Lighting And Power Company)

 Docket of Heactor Projects III, IV. V & Special Projects (Post 870411). 88/03/31 53pp 45040 044-45040 136
- 8804080172 Forwards SSER NUREG-1231 re B&W Owners Group plant reassessment program Overall evaluation from an Envirable Additing rounding plant adaption in program Overall evaluation from an Envirable Additing rounding that area of integraled control syst non-nuclear instrumentation syst roview possible W/o end!
 CRUTCHFIELD D. Division of Reactor Projects - III,IV,V & Spacial Projects (Post 870411) 86703/31 WILGUS,W S. Batcock & Wilcox Operating Plants Cwiters Group 7pp. 45076-181-45076-187
- 8804080174 NUREG-1310 NATURALLY OCCURRING AND ACCELERATOR-PRO-DUCED RACIOACTIVE MATERIALS 1997 Roview AUSTIN, J.H. Office of Nuclear Material Safety & Safeguards, Director. 88/03/31, 74pp 45201 180 45206 036
- --8804140067 Artyises that encl documents rel in NUREG-1310 should be made available to public in PDR able to Nuclear Material Safety & Safeguards, Director, 88/03/16 Document Control Branch (Document Control Dask), 2pp. 45201:234-45201 235.
- --8804140075 Notities of Atomic Energy Control Board into that I censes issued to authorize exports of Co-57,Ga-65,In-111,I-120 & TI-201,por NRC request into on whether & in what amounts isotopes exported unavailable Related into onci MCGEE, I D. Canada. Goyt. of 87/12/29. AUSTIN,J.H. NRC No Detailed Attration Given. 12pp. 45201,236-45201,248.
- --8804140096 Forwards 1st of cyclotrons installed w/dates of commissioning Growth of cyclotrons will be expanding during next 5-10 yrs as positron emission temography becomes more widespread diagnostic modality Related into encl HALLIDAY, K.B. CTI Group, Inc. 87/11/10. AUSTINJ INRC No Data-lud Affilation Given 33pp. 45201.249-45201.281.
- --8804140108 PNL-5948 "List of DOE Rad-oisotope Customers w/Summary of Radio-sotope Shipmonts,FY85 " BAKER,D.A. Battelle Memorial Instituto, Pacific Northwest Laboratorios UC-23 86/ 08/31 53pp. 45201-282-45201 334
- -8804140121 Responds to 871104 fit re-transfer of radio-sotopes from Switzerland to US Stated Swiss research facilities produce redicisotopes through accelerator/cyclo-tice on regular basis Quantity of H-3 & C-14 exported stated HERTIG.HP. Switzerland, Govt of 87/11/19 AUSTIN, J.H. Ollice of Nuclear Material Safety & Sateguards Director. 2pp. 45201-335-45201-336
- --8804140130 Forwards toxt of response received from Ollawa re request for info on Canadian experts of radiosolopes.per 871214 telcon MCGEE.T.D. Canadia, Govt. of 87/12/14 AUSTIN.J.H. NRC No Ostaled Affiliation Given 2pp 45201 337-45201 338
- --88041401412 "Natural Radioactivity Contamination Problems" STANTON JR Conference of Radiation Control Program Directors, Inc. BOHLINGER I. H. Louisiana, State of HENDRICKS, D.W. Environmental Protection Agency 81/08/31 133pp 45201-339-45202.110.
- -- 8804140149 Discusses two incidents pointing to value of radiation monitoring of trucks entering or leaving scrap metal processing facility appreciation for two processors taking appropriate precoutionary measures expressed.

 MILLER.VL Medical, Academic & Commercial Use Safety Branch 87/08/12

 CUTLER.H Institute of Scrap Iron & Steel, Inc. 2pp. 45202:111-45202.112

- -8804140186 MORP 66:7 "Review & Arialysis of Placium Incidents" ROBINSON,F.W., VILLEORTH,J.C., WOLD,G.J. Health & Human Services, Dept. of, U.S. Public Health Service, 68709730, 19pp, 45202 131-45202.149
- --8804140204 Speech entitled "Diagnosis 8 Treatment of Metastatic Tumors W/Raulo-labeled Monoclonal Antibodies Experience w/Lymphoma, Metanoma & Colon Chinese (Chinese Colon Chinese) LARSON,S M. Health & Human Services, Dept. of, U.S. Public Health Service, 86/12/ 31, 400pp, 45202,150,45203,250
- --8804140276 Forwards descriptions of naturally-occurring 8 accelerator produced radio-active mall incidents during past 5 yrs, received from state radiation centrely programs, por request, Abstracts also end Addirepts to be sent as received HARDIN,CIMI Conference of Radiation Control Program Directors, Inc. 87711725 AUSTRIJIE Office of Nuclear Material Safety 8 Safeguards, Director 21pp 45202-279-45202-299
- --8804140351 "Radium Incident Rept,Feb-June 1956" HOBINSON,E W. Health & Human Gervices, Dept. of. U.S. Public Pealth Service Eff. 06/30 | 10pp | 45202:300-45202-309
- ---8804140353 "Radium Incident Rept for Dag 1966". Jul 1967 " HOBINSON,E.W. Hogith & Human Services, Dept. of, U.S. Pubric Health Service, 677 07/31 2Cpp 45202 310 45202 328
- **8804140355 * Radium thuldent Rept for Aug-Doc 1967. *
 **ROBINSON E W. Health & Puman Services, Dept. of, U.S. Public Health Service 67/12731 6pp. 45202 329 45202 334
- -8804140356 "Redum Incident Rept, Jan Juno 1968" ROBINSON E.W.: Hoalth & Human Services, Dept. of, U.S. Public Health Service, 697 06/30 9pp 45202 335-45202 343
- +8804140363 "Hadium Incident Rept., full 1968 Dec. 1969." Related documentation enci CONLON,F.B. Health & Human Services, Dept. of, U.S. Pub ic Health Service, 69/12/ 31, 23pp. 45202,344-45203,005
- --8804140383 PNO III-87-123 on 870909;Region III notified by State of MO that scrap doaler in Sikestarr,MO dotected radioactive containingt on in two rail car loads of all-minum malt recovered from United Technology Inc. Related into encl WIEDEMAND, MALLETTB Region 3, Old of the Director 87/09/11 21pp 45203 CC6 - 15203 026
- --8804140410 Commonts on enclidate relidações circasam instrations involving accelorator produced isotopes reported to NRC for Jain 1981 Dec 1986 Annual error rate for diagnostic insactionestiquions stated. PETILIDHNIS, Office for Analysis & Evaluation of Operational Data, Director AECD/C505-87/12/22 AUSTINIJ. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 45203-037-45203-038.
- --8804140439 Submits Ictiowup of FDA 971214 meeting reladvorse reactions reported in association w/patient exposure to radiophares produced by cyclutens-specifically galfum, thi 111.1123 & thalfum Related nilo encling ARROWSMITH, JB Food & Drug Administration, 87712715 AUSTIN, 111 Office of Nuclear Material Salety & Saleguards, Director 141pp 45203 039-45203 179
- --8804150011 Expresses appreciation for opportunity to meet w/NRC & discuss activities of Conference Objectives of Conference & task forces active during past yr Island & tast of specific workshops conducted at fast annual meeting end W/o end HARDIN,C W. Conference of Fladiation Control Program Directors for 75/05/20 KENNEDY,B T. NRC No Detailed Affiliation Given 2pp. 45203 180-45203 181
- --8804150045 NIOSH Technical Into, "Evaluation of Occupational Hazards From Indus-tiral Radiation Survey of Selected States"

 COHEN, S.C., KINSMAN,S., MACCABEER D. Health & Human Services, Dept. of, U.S. Public Health Service 76/12/31, 00pp. 45203:182-45203.267
- --8804150064 Requests staff preparation of proposed fit to stafed recipients to naturally-occurring & accelerator produced radioactive mattapproved by Commission subjito mods and cated an erclistor chairman signature. CHILK, S.J. Office of the Secretary of the Cummission 79/07/12 GOSSICK, L.V. Ofciot the Executive Director for Operations. Upp. 45203-268-45203:278.
- --8804150099 Forwards SECY-78-211, "Final Recommendations of Task Force on Regulation of Naturally Occurring & Accelerator Produced Radioautive Matis (NARM)." Chairman Hendrib & Commissioner Kennody non-concurred in recommendations of staff
 CHILK.S.J. Office of the Secretary of the Commission 78/06/30 GOSSICK.L.V. Ofc
 of the Executive Director for Operations, 2pp. 45203-277-45204-044
- --8804150227 "Comphance by States w/Consumer Paliont Radiation Health & Saledy Act of 1981 Annual Rupt for 1986" "Health & Human Services, Dept. of, U.S. Public Health Service 86/09/10 3pp 45204.045-45204-047.
- --8804150271 "Rept on Identification of Federal Radiation Issues"
 Committee on Interagency Radiation Research & Policy Coordination 86/03/31
 14pp 45204 046-45204 111
- --8804150287 RPC-69-001 "Progress Rept & Protentiary 1981-83 Agonda"
 President of U.S. & Executive Offices, 80/09/39, 51pp, 45204 112-45204-178
- --8804150322 Marked-up * Inclusion of Naturally Occurring 8 Accelerator Produced Radioactive Matts in EPA Low Level Radwaste Std ** Related documentation end. BANDHOWSKI,M S. GRUHLKE J.M. Environmental Protection Agency 86/09/22 46pp. 45204-179-45204;224.
- --8804150337 Forwards listing of radiopharms official in USP XXI 8 supple JOHNSON,F.N. United States Pharmacepe at Convention, Inc. The AUSTIN.J.H. NRC No Detailed Affhation Given 2pp. 45204 225-45204 226

- ~8804150359 Forwards summary inspirepts of health svcs industry.Std Industrial Classification. Code: 80 for FY82-86. & rept for FYs of inspired where foreigng Radiation Std,1910.096 cited.per teleon 870827 request.

 KATALINAS,JA Labor, Oppt of, Occupational Safety & Health Admin. 87/10/05 AUSTIN,J. NRC No Detailed Affiliation Given. 33pp. 45204 227-45204;243.
- --8804150369 Forwards two I stings of insps w/1910.096 cited consisting of Std Industrial Class lication (SIC) 7000.8999 from Oct 1984 June 1987 & all SICs from Oct 1981 Sept 1986, per 871013 & 28 telicon requests Related documentation and:
 KATALINAS.JA. Labor, Dept. of, Occupational Safety & Health Admin, 87/11/04.
 AUSTIN,J. NRC No Detailed Affiliation Green 73pp. 45204.244-45204;283.
- -8804150383 Advises of agreement w/stated recommendations noted in draft Commission paper submitted w/871231 memo re naturally occurring & accelerator produced radioactive mat's Resource estimates & recommendations reasonable Related info
- enci LOACH,R E Program Analysis Branch, 88/01/21, AUSTIN,J.H. Office of Nuclear Ma-terial Safety & Safeguards,Director, 29pp. 45204,284-45204;292.
- -8804150390 "Agreement State Program State Perspective." 8ROWN.H. National Governors' Association, 63/01/31, 160pp. 45204 293-45205 092
- -8804150403 Advises that B Dornsife of Commonwealth of PA radiation control agency to send info on radium 8 other naturally occurring 8 accordance reproduced radioactive mat's problems 8 related info Related documentation encl DEVINE,T. Conference of Radiation Control Program Directors, Inc. 87/09/01. AUSTIN,J.H. Office of Nuclear Material Safety 8 Safeguards, Director. 100pp. 45205-093-45205 193
- -8804180119 Notifies of position of Conference of Radiation Program Directors on naturally occurring & accelerator produced radioactive matl (NARM) NARM radioactive matl not adequately or uniformly regulated in US. STRONG,T.R. Conference of Radiation Control Program Directors, Inc. 87/08/26. DENTON,H.R. Office of Governmental & Public Affairs (Post 870413). 23pp. 45205 194-45205 216
- -8804180136 Comments on rept. "Regulation of Naturally Occurring & Accelerator Produced Rad oactive Matts-Task Force Review." Inclusion of all radioactive mall under authority of one agency appears logical Related into encl. Htt.E.J.P. Food & Drug Administration. 42FR37458 00015, 77709/22. Docketing & Services Branch. 116pp. 45205.217.45206.036.
- --8804190166 Paper summarizing results of EPA studies underway to evaluate naturally occurring organic mattrix in emissions from mineral extraction industries, probably presented at 870521 conference meeting.

 HENDRICKS,D.W. Don Hendricks & Associates, Inc. 87/05/21. 8pp. 45202:251-
- →9804190170 Paper entitled "Naturally Occurring Radioactivo Mail," presented at 18th annual Nati Conference on Radiation Centrol on 860520 in Charleston,WV. BAILEY,E D. Texas, State of. 66/05/20. 8pp. 45202:259-45202:266.
- -8804190173 Speech entitled "Naturally Occurring Radioactive Matt. EPA Point of View." probably presented at 870521 conference meeting GALPHY.E.L. WINDHAM.S.T. Environmental Protection Agency. 87/05/21, 12pp. 45202-267-45202-278
- -8804210509 Forwards Itrs providing additinto re naturally-occurring & accelerator produced redicactive mati incidents, bickeding State of MS_Dept of Health 671123. State of OH_Dept of Health 871123. State of OH_Dept of Health 871120 & State of Montana 871123 Itrs. HARDINC Conference of Rad ation Control Program Directors, Inc. 87/12/07. AUSTIN NRC No Detailed Affiliation Given. 7pp. 45203.027-45203.033.
- -8804210512 Forwards State of New York, Dept of Health 871118 & State of WA, Dept of Social & Health Svcs 871125 firs re naturally occurring & accelerator produced ra-
- di doctive thall incidents.

 HARDIN.C. Conference of Radiation Control Program Directors, Inc. 87#12/07. NRC No Detailed Affiliation Given. 3pp. 45203:034-45203:038.
- 8804080179 NUREG-0304 V12 N04 REGULATORY AND TECHNICAL REPORTS (A8-STRACT INDEX JOURNAL). Annual Compilation For 1987. ' Division of Publications Services 88/03/31, 171pp. 45040:137-45040:307.
- 8804080191 NUREG-1303 INCIDENT INVESTIGATION MANUAL. Office for Analysis & Evaluation of Operational Data, Director, 69/02/29, 235pp. 45037:220-45039.094.
- 8804080200 NUREG-1309 THE U.S. NUCLEAR REGULATORY COMMISSION PRO-GRAM WITH STATE AND LOCAL GOVERNMENTS AND INDIAN TRIBES. DROGGITIS,S.C. State, Local & Indian Tribe Programs. 88/03/31. 50pp. 45037:170-
- 8804080208 NUREG-1905 TECHNICAL SPECIFICATIONS FOR SOUTH TEXAS PROJECT, UNIT 1. Docket No. 50-498 (Houston Lighting And Power Company)

 ' Division of Reactor Projects III, IV, V & Special Projects (Post 870411): 88/03/31. 446pp. 45035:318-45037.043.
- 8804080214 NUREG.1231 S01 SAFETY EVALUATION REPT RELATED TO BABCOCK AND WILCOX DWNERS GROUP PLANT REASSESSMENT PROGRAM. SIEGEL,BL. Office of Nuclear Reactor Regulation, Director (Post 870411). 88/03/31. 126pp. 45037.044-45037:169.
- 8804080218 NUREG/CR-5107 HYDROGEOLOGIC CHARACTERIZATION OF BASALTS. The Northern Birn Of The Columbia Plateau Physiographic Province And Of The Cresion Study Area Eastern Washington.
 STEELE.T.D., PASCHIS,JA, KOENIG,R.A. In-Słu, Inc. FIN D-1163, 88/03/31. Division of Engineering (Post 870413), 242pp. 45042:104-45042.345.
- 8804080227 NUREG-1249 VO1 NRC MODEL SIMULATIONS IN SUPPORT OF THE HY-DROLOGIC CODE INTERCOMPARISON (HYDROCOIN) STUDY.Level 1 Code Verili-
- Division of Engineering (Post 970413), 88/03/31, 184pp. 45042:346-45043:169.
- 8804080230 NUREG-1286 S01 SAFETY EVALUATION REPORT RELATED TO THE RESTART OF RANCHO SECO NUCLEAR GENERATING STATION UNIT 1.FOLLOW-ING THE EVENT OF DECEMBER 26,1965. Docket No. 60-312 (Sacramento Municipal
- Utility District)

 Division of Reactor Projects III,IV,V & Special Projects (Post 870411), 88/03/31, 233pp. 45041;231-45042:103.

- 8804080232 NUREG/CR-2000 V07 N2 LICENSEE EVENT REPORT (LE COMPILATION For Month Of February 1988.

 Oak Rége National Laboratory FIN A-9135 ORNL/NSIC-200 88/03/31. Office Analysis & Evaluation of Operational Data, Director 152pp. 45041-079-45041.230

 - 8804080236 NUREG/CR:4740 NUCLEAR PLANT-AGING RESEARCH ON REACTO PROTECTION SYSTEMS. MEYERILC. EG&G Idaho, Inc. (subs of EG&G, Inc.) MEYERILC Idaho National E-gincering Laboratory. FIN A-6389. EGG-2467. 88/01/31 Division of Eng.neering (Pc 870413). 131pp. 45040.308-45041 078.
 - 8804089287 NUREG/CR-4999 ESTIMATION OF RISK REDUCTION FROM IMPROVE PORV RELIABILITY IN PWRS.Final Report HSU.C., PERKINS.K., YOUNGBLOOD.R. Brookhaven National Leboratury. FIN 3807. BNI-NUREG-52101. 88/03/31. Division of Reactor Accident Analysis (Po 870413) 82pp. 45066-344-45067-064.
 - 8804080272 NUREG/CR-4918 V02 CONTROL OF WATER INFILTRATION INTO NE. SURFACE LLW DISPOSAL UNITS Task Roport A Discussion SCHULZ, RK. California, Univ. of, Berkeley, CA. RIDKY, R.W. Maryland, Univ. of, Clega Park, MD. O'DONNELL, E. NRC No Detailed Affiliation Given Fin B-8958. 6 03/31. Division of Engineering (Post 870413). 33pp. 45066-311-45066-343.
 - 8804080274 NUREG/CR-5029 MELT PROGRESSION IN SEVERELY DAMAGED R ACTOR CORES

 DOSANJH,S.S. Sandia National Laboratories, FIN A-1342, SAND87-2384, 87/12/3

 Division of Reactor Accident Analysis (Post 870413), 82pp. 45066,229,45066;310.
 - 8804030282 NUREG/CP 6092 PROCEEDINGS OF THE SEMINAR ON LEAK-BEFOR BREAK.Progress in Regulatory Policies And Supporting Research KASHIMA,K. Central Research Institute, Celumbus Leboratories. FIN D-1658 88/03/31. Division Engineering (Post 870413). 538pp. 45065 050-45086-228
 - 8804110030 Response of NRC Staff to Board 860317 order requesting clarifying info RJ Clark affidavit answering five questions in ASLB 880317 order enct. WEISMAN.R.M. Assistant General Counsel for Enforcement. #288 6018 OLA 86/0 04 lp. 45049 258-45049 276.
 - --8804110035 Alfidavit of RJ Clark In response to ASLB 880317 questions * Provid NRR answers to first five questions in ASLB 880317 order. Question 6 left for licens to answer Wifecriticate of Svc. CLARK.R.J. Office of Nuclear Reactor Regulation, Director (Post 870411). 87-550-6 LA. 88/04/04, 18pp. 45049:259-45049 276.
 - 8804110156 Summary of 880210 & 11 meetings w/util re licensing actions, include status of completion of license conditions, Rev 2 to updated FSAR & Implementat dates for Safety Issues Mgt Sys. Attendance list agenda, handout & data enct KINTER, LL. Project Directorate II-1. IEIN-86-081, 88/03/30. Project Directorate II-57pp. 45078:194-45078:250.
 - 8804110195 NUREG-0750 V27 N01 NUCLEAR REGULATORY COMMISSION SUANCES FOR JANUARY 1988 Pages 1-39.
 Division of Publications Services, 88/03/31, 46pp. 45071;246-45071;291.
 - ## 8804110197 NUREG-0750 V26 N06 NUCLEAR REGULATORY COMMISSION SUANCES FOR DECEMBER 1987. Pages 449-530.

 * Division of Publications Services. 88/03/31. 89pp. 45071:156-45071:245.
 - 8804110204 NUREG-0940 V06 N04 ENFORCEMENT ACTIONS:SIGNIFICANT AT TIONS RESOLVED Quarterly Progress Report,October-December 1987.

 * Old of Enforcement (Post 870413), 88/02/29, 125pp. 45070.180-45071:043.
 - 8804110207 Forwards safety evaluation supporting util responses to NUREG-0737,lt II.D.1, "Performance Testing of Relief & Safety Valves." Approval based on util comitment to provide results of in-plant tests of block valves. WANG, A.B. Project Directorate 1-4. IEB-85-003. 89/03/30. MROCZKA,E.J. Connecut Yankee Atomic Power Co. 27pp. 45071:314-45071:340.
 - 8804110261 Forwards safety evaluation accepting third vent path of containment alm pheric dilution sys to satisfy requirements of NUREG-0737, item II.E.4.1. ZECH.G.G. Ofic of Special Projects. TAC R00002. 88/03/31. WHITE,S.A. Tenness Valley Authority. Spp. 45079:001-45079:005.
 - 8804110297 Forwards Rov 8 to response to Suppl 1 to NUREG-0737, including revise writers guide for emergency & abnormal procedures for facility. App 2, "Abnormal Forcedure Outline," not included & will be updated & provided in subsequent rev. TUCKER. H.B. Duke Power Co. 88/04/05. Document Control Branch (Document Cotrol Branch (Document Cotrol Desk). 2pp. 45135:109-45135:222.
 - --8804110300 Rey 8 to "Writers Guido for Emergency & Abnormal Procedures." * Duke Power Co. 88/03/09, 112pp. 46135;111-45135;222.
 - 8804120271 Requests deletion of Chapters 3.4,5 & 10 from final version of rev NUREG/CR-3984, "Techniques for Estimating Probabilities of Events & Processes fecting Performance of Geologic Repositories Literature Review."

 GALSON,D.A. Operations Branch. FIN A-1165. 88/03/24. CRANWELL,R.M. Ser National Laboratories. 2pp. 45080.079-45080.080.
 - 8804120459 Discusses requirements of NUREG-0737, Item II.K.3.17 re rept of EC outages. Reporting of ECCS equipment failures provide NRC w/batter reporting sy obviates FSAR ECCS outage 5-yr reporting commitment. CONWAY,W.F. Florida Power & Light Co. L-88-161. 88/04/08. Document Con Branch (Document Control Desk). 2pp. 45090.161-46090.162.
 - 8804130061 Advises that HEO M-1-0018 should be canceled due to list reasons Rearrangement of annunciator & status light sys windows constitutes grepotential for operator error. Util will implement only Items 1 & 3 of annunciator mt TUCKER,H.B. Duke Power Co. 88/04/05. Document Control Branch (Document Cortol Deak). 4pp. 45100:029-45100.032.
 - 8804130212 Partial response to FOIA request for documents. Forwards App N doments re CRGR meetings. App N documents available in PDR. App O documents wheld in entirely (ref FOIA Exemption 5).
 GRIMSLEY, D.H., Division of Rules & Records (Post 870413). 88/04/05. WEISS, Harmon & Weiss. 4pp. 45102:102-45102:125.

- -8603120377 Requests addl Info to continue CRGR review of NUREG-0313, Rev 2 re BWR pipe cracking & long-term resolution Regulatory enablysis of proposed resolution implementation should be available for review by committee W Dircks 840712 memo SNEZEKJH, Regional Operations & Generic Requirements, EDO (Pre 870413), 867-93/05, DENTON,HR Office of Nuclear Reactor Regulation, Director (851125-870411), 1p. 45192-126-45102-126
- --8405160276 Advises that NUREG-0801. "Evaluation Criteria for Detailed Control Room Draign Rovlows," will be Issued in Israil form, incorporating pubic comments & consistent w/requirement of NUREG-0737, Suppl 1. DENTON, FLR. Office of Nuclear Reactor Regulation, Director (pre-851125) 84/04/25 DRICKS, W.J. Olic of the Executive Director for Operations. 2pp. 45102:129 45102:135
- -8408060365 Advises that proposed NUREG-0801, "Evaluation Criteria for Detailed Control Rossin Dustin Reviews," should be issued as app to Chapter 18 to SHP, in confiniting wypolicy of not using NUREG repts to promulgate requisitory quidance. DIRCKS,W.J. Otc of the Executive Director for Operations, 8470712, DENTON,H.R. Office of Nuclear Reactor Regulation, Director (pre-851125), 1p. 45102.127-45102.127.
- --8809180240 Forwards summary re proposed generic lir to BWR Licensees transmitting tochnical findings related to MSIV loakage & MSIV loakage control sys Review re resolution of Generic Issue C-8 scheduled for CRGR Meeting 96 on 860917.

 TAYLORI,M.A. Regional Operations & Generic Requirements, EDO (Pre 870413), 88709172 DERNERO,R.M. Office of Nuclear Regulation, Oractor (851125-870411), 18pp. 45102:140-45102:178
- -8405160276 Advises that NUREG-0801, "Evaluation Criteria for Detared Control Room Desligh Reviews," will be issued in final form, incorporating public comments 8 consistant w/roquiroment of NUREG-0737, Suppl 1. DENTON,11R. Office of Nuclear Reactor Regulation, Director (pre-851125), 84/04/25 DIRCKS,W.J. Olic of the Executive Director for Operations. 2pp. 45102-129-45102:135.
- -8408060365 Advisos that proposed NUREG-0801, "Evaluation Critera for Detailed Control Room Doslgn Reviews," should be issued as app to Chapter 18 to SRP.in continuing w/policy of not using NUREG repts to promulgate regulatory guidance. UIICKS,W.J. Otc of the Executive Director for Operations 84/07/12 DENTON H.R. Office of Nuclear Reactor Regulation, Director (pre-851125). 1p. 45102-127-45102-127.
- -8603120387 Commonts on publication of NUREG-0801, "Evaluation Criteria for DCRDR," nor onci recipient 840425 mome Meeting should be held to discuss NUREG & relationship to Industry Nuclear Uni Task Action Committee documents. OIRCKS,W.J. Ofc of the Executive Director for Operations. 84705/07. DENTON,H.R. Olinco of Nuclear Regulation, Director (pre-851125) ip 45102.128-45.103.108 Office of 45192:128.
- -8609180240 Forwards summary re proposed generic litr to BWR Leansees transmitting luchnical findings related to MSIV leakage & MSIV leakage control sys Review re resolution of Generic Issue C-8 schoduled for CRGR Meeting 86 on 860917.

 AYLORI M.A. Replanal Operations & Generic Requirements, EDO (Pre 870413) 86/09/12. BERNERO,R.M. Office of Nuclear Reactor Regulation, Director (851125-870411). 18pp. 45102.140-45102:178.
- 8804130400 Surinmarkios NUREG-1150 Poer Roview Committee 880218-19 meetings CATFON,I. ACRS Advisory Committee on Reactor Safeguards, 88/03/09 110USTON,D. ACRS Advisory Committee on Reactor Safeguards, 2pp. 45117-298
- 8804140015 Forwards Insp Hopt 50 482/87-24 on 871019-23 & notice of violation insp included reviews of implementation of equipment qualification correction action commitments Identified in SER (NUREG 0881). CALLANI, J. Region 4, Oto of the Director, 88/04/08, WITHERS,B.D. Wolf Creek Nuclear Operating Corp. 3pp. 45151:318-45151.356.
- -8804140030 Notice of violation from Inso on 871019-23.Violation noted, util did not adequately support qualification of Raychem installed splice configuration or establish similarity between tested & installed splices per NUREG-0588

 * Region 4, Old of the Director, 88/04/08 3pp. 45151:321-45151.323.
- --8804140033 Insp Ropt 50-482/87-24 on 871019-23 Violations noted Major areas inspected implementation of equipment qualification commitments identified in SER (NUREC 0.081) 8 Supplis 4 8 5 JOHNSON A.R. IRELAND.R.E. Region 4, Otc of the Director. 88/04/05 33pp 45151:324-45161:358.
- 8804140524 Forwards SER & contractor technical evaluation rept re util 841130 & 861215 submittels of DCRDR program plan & DCRDR summary rept,respectively. Submittels acceptable. INALL.AR. Project Directorate III-3. TAC 56120. 88/04/96. LIU,L. Iowa Electric Light & Power Co. 2pp. 45130:186-45130.204.
- ~8804140526 SER accepting util 861215 submittal of DCRDR summary rept.
 * Human Factors Assessment Branch, 88/04/06, 2pp. 45130,186,45130,169.
- 8804150093 Advisos that emergency planning zone raduction requests shall remain an plant active docket file, but no further review offerts until notice given to NRC to reacti-
- vBlo review. VANGA.S.A. Division of Reactor Projects I/II (Post 870411), TAC 60176-88/04/11. TIERNAN,J.A. Baltimoro Gas & Electric Co. 3pp. 45134-020-45134-022.
- 8804150212 Forwards Suppl 5 to NUREG-0781, "SER re Operation of South Texas Project.Units 1 & 2," for into & use. CALVO,J.A. Project Directorate IV. 88/04/08. GOLDBERG,J.H. Houston Lighting & Power Co. 97pp. 45140:122-45140:218.
- 8804150328 Informs of rev to shift technical advisor (STA) training program onginally provided to NRC in util 810130 ftr. Flev due to completion of STA task list for accredited STA program. MUSOLIF. D. Northern States Power Co. 88/04/08. Document Control Branch (Document Control Desk). 1p. 45138 204-45138-204.
- 8804150362 Informs of rev to shift technical advisor (STA) training program originally provided to NRC in util 810130 ltr.Rev due to completion of STA task list for accredited STA program.

 MUSOLF,D. Northern States Power Co. 88/04/08. Document Control Branch (Document Control Desk). 1p. 45138.205-45138.205

- 8804180155 Forwards safety evaluation supporting util 840229 & 870707 litts re-natural circulation cookflown tests performed at plant util demonstratos conformance w/Technical Post on RSB 5-1. Test give receit Post on RSB 5-1. Test give receit Post on RSB 5-1. Test give Requirements of RHR Syst WIGGINTON.DL Project Directorate IV. TAC 61525 86/04/09 DEWEASE J.G. Louisiana Power & Light Co. 4pp. 45149 097-45149 116
- --8804180171 Safety evaluation suporting natural circulation cooldown tests performed at plant.per util 840229 8 870707 lirs.per Suppl 1 to NUREG-0787.

 Office of Nuclear Reactor Regulation, Director (Post 870411) 88/04/08 3pp 45149 101-45149 102
- ~8804050231 * Technical Evaluation Rept for Natural Circulation.Boron Miking & Cooldown at Waterford Unit 3."

 JOJH PERKINSK R. Biookhaven National Laboratory, Fift A 3843 88/03/31 Citics of Nuclear Reactor Regulation, Director (Post 870411), 21pp. 45149 104. 45149 116
- 804180463 Summary of 880406 meeting w/NUMARC.stls.Science Applications.Inc.EPRI.Sandia.Trident Engineering & Devorrue in Rockyte.MD re embagency diesel generator rehabitity programs SERKIZ.A.W. Reactor & Pient Safely Issues Branch 88/04/12 KNIEL.K. Reactor & Plant Safety Issues Branch 165pp 45150 074-45150 230 4804180463
- 8804190050 Final response to FOIA request for documents on NRC/IDCCR meeting on 870910 ro individual plant evaluation Forwards documents hated in App B Apps A & B documents available in PCR App C documents totally withheld (ref FOIA Exemption
- 9): GRIMSLEY,DH Division of Rules & Records (Post 870413) 88/04/13 SHOLLY,S C MHB Technical Associates 11pp 4\$158.314.45158.262
- --8804190077 Forwards revs to IDCOR individual plant evaluation PWR sys methodology considered to be final w/ integration of revs BUHLAR Indivistry Degraded Core Retemaking Program BUHLAR International Technology Corp 8/70/20/9 SPEIS.F.P. Division of Safety Review & Oversight (851125-870411) 498pp 45157-019-45158-196
- 8804190126 Forwards request for additinfolre implementation of reactor coolant pump implementati
- 8604190203 Forwards portion of official transcript from 880324 public meeting re-sting of low fevel radwaste facility,per Suppl 1 to NUREG-0904 into confirms that subjective native is not awaitable from either legal or practical perspective MESERVER A. Covington & Burling 29203. 88/04/08. SWIFT, J.J. Fuel Cycle Safety Branch. 7pp. 45164:352-45164:358
- 8804190230 Forwards safety evaluations accepting util final low pressure turbine disc inspireprisper util 860820 & 870323 Itrs Leonse Conditions 2C(15) & 2C(13) complete full commitment to implement mig inspirecommendations acceptable HICKMAN, DE Project Directorate V. TAC 51655-88/84/12 BASKINK P. Squithern California Edison Co. COTTON, G.D. San Diego Gas & Electric Co. 3pp. 45155-274-45155-287.
- -8904190246 Safety evaluation accepting util insp of low pressure turbine rotors Based on info provided in util 860620 ftr,NRC concludes that License Condition 2 C(15) ccm-
- pleto **Office of Nuclear Reactor Regulation, Orector (Post 870411) 88/04/12: 5pp. 45155.277-45155.281.
- --8804190249 Safety evaluation accepting util insplof low pressure turbine rotors Results of exam show no evidence of stress corrosion cracking in disc bote region and dowell holes NRC concludes that License Condition 2 C[13] complete

 * Office of Nuclear Reactor Regulation, Director (Post 870411) 88/04/12 6pp 45155 282-45155 287
- 8604190254 Forwards SER & Suppl 1 to NUREG-1231 on B&W Owners Group plant assessment program contained in BAW-1919 Rev 5, "B&W Owners Group Safety & Parlormance Improvement Program (SPIP)," W/o encls. RUBEINSTEIN,LS Standerdigation & Non-Power Reactor Project Directorate 88/04/13, MAZUR,DW. Washington Public Power Supply System 4pp 45165231-45165 45165 234
- 8804200053 Town of Newbury contentions re applicant plan for Commonwealth of MA communities 1 Plan for commonwealth does not meet requirements that must be reasonable means of evacuation & relocation.per Rev 1 to NUREG-0654 WHILTON,RS Legouits, Clark, Hill-VT-lion & McGuire. #288 6084, OL 88/04/13 Atomic Safety and Licensing Board Panel. 37pp 45162.349-45163 025
- 8804200073 Contentions of town of West Newbury re Seabrook plan for Commonwealth of MA communities.* Plan fails to meet planning stds.per. 10CFR50.47(b) & NUREG-0654 FEMA REP. 1.Rev. 1. Suppl. 1. MIZNER_JH. West Newbury, MA. #288.6085. OL. 1. 88/04/13. Atomic Safety and Licensing Board Panel. 17pp. 45182.332.45162.348.
- 8804200106 Atty General JM Shennon contentions submitted in response to Seabrook plan for Commonwealth of MA communities.* Plan laits to meet planning stds per 10CFR50.47(b)(1) & NUREG-0854 II.A 3 W/Contilicate of Svc. TRAFICONTE.J. Massachusetts, Commonwealth of. #288 6088 OL. 88/04/13 SMTH.LW., LINENBERGER,G. Atomic Safety and Licensing Board Panel. 215pp. 45163-030-45183-243.
- 8804200473 Partial response to FOIA request re fire protection Forwards App E documents App II & E documents available in PDR App F document completely with-held (rel FOIA Examption 5).
 GRIMSLEY, 0 H Division of Rules & Records (Post 870413) 88/04/14. JONES, C.R. Athikation Not Assigned 5pp. 45208.037-45206.043
- --8804200526 Summarizes differences which exist between fire protection requirements applied to near-term OL & operating reactors, per NUREG-0800,SRP 9.5.1. CONLON.T.E. Fire Protection Review Group, 84/11/07, ROSA,F. Fire Protection Review Group, 16pp, 45206-154.45206.169.

- 8804200539 Forwards addi into re small break LOCA Model NULAPSS,por 880317 for lock from NUREG 0065 into re response of clad swell & rupture model in analysis & into reguested in 880317 conterence call encl.
 MROCZKAEJ., SEARS,CF. Contracticul Yankee Atomic Power Co. MROCZKAEJ.
 Northeast Utili qs. 812882 88704715. Document Control Branch (Document Control Desk) 15pp 15239 096-1529 109
- 8804210033 Discussos NUREG 0737, Itom II.E 1.2, "Automatic Bus Transfer Feature of Auxiliary Feedwater Sys Testing of Molded Case Circuit Broakers." Util continues to have reservations to impact of instantaneous trip testing on crucult breaker. R CHEV.R B. Carotina Power & Light Co. NLS-88-086 88/04/11. Document Centrol Branch (Document Control Dosk). 2pp. 45194.165.45194.166
- 8804210061 Forwards proprietary NEDC-30844A, "BWR Owners Group Response to NRC Generic Lir 83-28, item 4-5-3" & NEDC-30851P-A, "Tech Spec Improvement Analyses for BWR Reactor Protection Sys" All davit end Repts withheld (ref. IOCFR2 790).

 KLAPPROTH, J. F. General Electric Co. OG9-294/32D/OG1 88/04/04 Document Control Branch (Document Control Desk) App. 45194-161-45194-164
- 8804210376 Forwards Technical Evaluation Rept EGG NTA-7883, "TMI-Action NUREG-0737 (1D.1) Rotied & Safety Valve Tresting, Waterford Scient Electric Station.Unit 3." Ult response acceptable based on results of review WigG-NTON DIL Project Directorate IV. TAC 61805-88/04/05 DEWEASE J.G. Louisiana Power & Light Co. 4pp. 45191-294-45191-317.
- --8710140348 EGG-NTA-7863 "TMI Action NUREG-0737 (*10.1) Retief & Salety Valve Toslarg Waterford Steam Electric Station,Unit 3," technical evaluation rept PACE NE, INSWANC P EG&G Idaho, Inc., (subs. of EG&G, Inc.) PACE NE, Idaho National Engineering Laboratory, FIN A-6492 87709/30 NRC No Deta red Alfrahon Given 20pp. 45191:298-45191-317.
- 8804210396 Forwards request for additinfo re review of response to Generic Lif 86-06 concerning reactor coolant pump trip. Response requested within 60 days of itr re-WAMBACH,T.V. Project Directorate III-1 TAC 49700, 88704715, BERRY,K.W. Consumors Power Co. 4pp. 45192:159-45192:162,
- 8804220042 Commont supporting draft NUREG-1293 re QA guidance for low level rad-waste dispose! fact ty Proposed NUREG will have minimal impact on util programs Uli-in general agreement w/ NUREG. GRIDLEY,R Tennessee Val
- 8804220063 Advises that amend to Tech Spac 4.5.2, "ECCS Subsystems-Tavg Greater Than or Equal to 350 F" necessary. Changes consisting of esterisk statement to valves on enclipage to setting the submitted.

 HOPKINS.J.B Project 0 rectorate II-3 TAC 66461. 68/04/15 HEAD, G.F. Georgia Power Co. 4pp. 45201:001-45201:004.
- 8804220133 Requests that util remit fee for 860226 application for approval of alternate method of satisfying NUREG-0737, them II 8.3 re Criterion 4 by removal of dissolved gas monitoring portion of post-accident sampting sys DIGGS RM. Treense Fee Management Branch. 88/04/15. MUSQLF,D.M. Northern States Power Co. 1p. 45201.022-45201.022.
- 8804220167 Advises that roview of 871224 & 880204 hrs re-issue of whether or not license amend required for spent fuel transshipment from plant completed Two criteria of 10CFR50 59 for unroviowed safety question met.
 MIRACLIA.F.J. Associate Director for Projects (Post 870411). TAC 60869 68/04/14.
 BASKIN,K.P. Southern Carlfornia Edison Co. 3pp. 45201.116 45201:118
- 8804220204 Discusses 336th meeting of ACRS on 880407-09 re proposed resolution of USI A-47, "Safuty Implications of Control Sys." Disagrees that NRC recommendations constitute resolution of USI A-47 as one-naily defined KERRW. ACRS Advisory Committee on Reactor Safeguards 88/04/12 ZECH, W. Commissioners. 3pp. 45266 341-45266 343.
- 8804260100 Ack receipt of 880130 ftr re-dissatisfaction w/NRC review of allegations re-safety of pfant NRC unanimously tourid that sufficient review of GAP aflegations con-ducted before authorizing full power license.NUREG-1306 encl Wio rept. MURIEFY.F.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/ 15, MALONE,R. Althation Not Assigned 8pp. 45232.173 45232.180.
- 8804280310 Informs that util conducting review of vondor supplied info to 870731 request for addl info on NUREG-0737, Item III D.1, "Performance Tosting of Relief & Safety Valves." TUCKER H B. Duke Power Co. 68/04/15 Document Control Branch (Document Control Desk) 1p. 45253 063-45253.063.
- 8804270216 Forwards comments & clarification re review of Oct 1987 Suppl 7 to NUREG-0806, "SER re Operation of Seabrook Stations Units 1 & 2" Items being completed or requiring correction should be incorporated into next suppl THOMAS G.S. Public Service Co. of New Hampshire. NYN-88056, 88/04/21. Docu-ment Control Branch (Document Control Desk). 6pp. 45244-255-45244-260.
- 6804270272 Forwards NUREQ-1306, "NRC Safety Significance Assessment Team Rept on Allegations for South Texas Project.Units 1 & 2," for info & use. CALVO,J A. Project Directorate IV 68/04/18. GOLDBERG,J H. Houston Lighting & Power Co. 6pp. 45243 067-45243 226.
- 8804279303 Responds to 680321 fir to Zech expressing concerns re SMUD ability to operate facility w/o adversely affecting hoalth 8, safety of general public in view of referendums schoduled to apppear on 880807 ballot for SMUD ratepayers MUPILEY.T.E. Office of Nuclear Reactor Republic, Director (Post 870411), 86/04/18, CONNELLY,L.G. California, State of, 8pp. 45266 161-45266 170
- 8804270304 Withdraws portion at 870918 Tech Spec change request re deletion of MSIV leakage control sys & requests again portion of change request that allows 100 soft total MSIV leakage.per NRC 860311 rejection fit. KAPLANIA. Claydand Electica Illiummating Co. PY-CEI/NRR-0829, 88704/18. Document Control Branch (Document Control Desk). 2pp. 45244:215. 45244.216.
- 8804280072 Provides list of augmented insps conducted at lacisty & discusses conformance w/applicable regulatory guidance.
 BIRD,R.G. Boston Ed son Co. BECO 88-071. 88/04/15 Document Control Branch (Document Control Desk) 2pp. 45261:324-45261:325

- 8804280308 NUREG 0090 V10 N03 REPORT TO CONGRESS ON ABNORMAL OCCURRENCES.July-September 1987.
 * Office for Analysis & Evaluation of Operational Data, Director 88/03/31 45pp 45270.244-45270.267.
- 8804280329 NUREG-0090 V10 N04 REPORT TO CONGRESS ON ABNORMAL OCCURRENCES October-December 1987.

 **Olfice for Analysis & Evaluation of Operational Data, Director 88/03/31 34pp 45270:2413-45270:2413-45270:243-
- 8804280348 NUREG CEB3 S03 DRFT PROGRAMMATIC ENVIRONMENTAL IMPACT STATEMENT RELATED TO DECONTAMINATION AND DISPOSAL OF FADIOACTIVE WASTES RESULTING FROM MARCH 28, 1979 ACCIDENT.THREE MILE ISLAND NUCLEAR STATION.UNIT 2.DOCKOT NO 50.320 (GPU Nuclear Incorporated) Office of Nuclear Reactor Regulation, Director (Post 870411) 88/04/30 100,pp. 45270 000 45270 212
- 8804280386 NUREG/CR-5076 V01 A RELIABILITY PROGRAM FOR EMERGENCY DIESEL GENERATORS AT NUCLEAR POWER PLANTS Program Sircuture. LOFGRENE V. DEMOSS, GM., FHAGOLA JR. Serd a National Laborationes F.N. A-1806. SAN087-7176 88/04/30 D.v.s.cn of Reactor & Plant Systoms (Post 870413). 175pp 45271 304-45272 098
- 8804280390 NUREG 0713 V07 OCCUPATIONAL RADIATION EXPOSURE AT NUCLE-AR POWER REACTORS AND OTHER FACILITIES 1985 Eighteenth Annual Report BHOOKS,B. Division of Regulatory Applications (Post 870413). 88/04/30. 172pp 45271:136:45271:303
- 8804280442 Forwards SER & SSER 1 (NUREG-1231) on 88W Owners Group Plant re-assessment program contained in BAW-1919,Rev 5, "B&W Owners Group Safety & Performance improvement Program (SPIP)." Overall evaluation favorable W/o end KN'GHTON,G W. Project Directorate V 88704/19. ANDOGNINI,G C. Sacramerito Mu-nic pal Utility District. 3pp. 45264.081-45264:083.
- 8804280444 NUREG/CR-5067 EARLY AND CONTINUING EFFECTS OF COMBINED ALPHA AND BETA IRRIADIATION OF THE LUNG Phase II Report. SCOTTIB R, HAHMFF, SNIPES MB Lovelage B gomed & Environmental Research Institute FIN A-1203 LMF-119 88/03/31. Division of Regulatory Applications (Post 870413), 41pp 45269 001-45269,042-
- 8804280464 Approves request for exception to location requirement for tochnical support center (TSC) 8 retraction of commitment to provide afternate TSC near control room Stated emergency preparedness inspirable also reviewed TAMP.PS Project Directorate 1-4 TAC 62877 88/04/20, SIEBER, J.D. Duquesne Light Co. 2pp. 45263 032-45263 033.
- 8804280486 Informs that date of listed SIMS generic items for implementation complete earlier than imposition complete due to NUREG-0737 post-implementation review TRAMMELL.C.M. Project Directorate V 88/04/21 Project Directorate V. 2pp. 45204:104-45204:105
- 8804280505 NUREG/CR-4971 RESULTS OF SEMISCALE MOD-2C FEEDWATER AND STEAM LINE BREAK (S-FS) EXPERIMENT SERIES Main Stoom Line Break Accident BOUCHEAT J. EG&G Ideho, Inc. (subs. al EG&G, Inc.) FIN A:0038 EGG:2516, 887 03/31. Office of Nuclear Regulatory Rosearch, Director (Post 860720) 113pp 45274:302-45275.053
- 8804280516 Advises that analysis of PTS contained in Amend 25 to FSAR, submitted w/660919 ltr.ineets requirements of 10CFR50.61, "Fracture Toughness Requirements for Protection Against PTS Events."

 HOPKINS.J.B. Project Directorate III:3 TAC 67847, 88/04/21, HEAD,G.F. Georgia Power Co. 1p. 45265:040-45265.040.
- 8804280527 NUREG-1306 NRC SAFETY SIGNIFICANCE ASSESSMENT TEAM REPORT ON ALLEGATIONS RELATED TO THE SOUTH TEXAS PROJECT, UNITS 1 8.2.

 1. Division of Reactor Projects (1997)
- Division of Reactor Projects III,1V,V & Special Projects (Post 870411), 88/03/31, 152pp 45274 151-45274:301.
- 8804280588 AUREG/CR-4763 SAFETY-RELATED EQUIPMENT SURVIVAL IN HY-DROGEN BURNS IN LARGE DRY PWR CONTAINMENT BUILDINGS KING 08, N/COLETTELY F., DANDINIV.J Sandia National Laboratories FIN A-1270 SAND86-2280 88/03/31. Dryslon of Engineering (Post 870413), 299pp. 45272 089-45273 037
- 8804280623 NUREG-0540 V10 N02 TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE February 1-29,1988.

 * Division of Publications Sorvices 88/04/30, 350pp. 45273,038-45274 023.
- 8804280633 NUREG/CR-5019 NEUTRON EXPOSURE PARAMETERS FOR THE MET-
- ALUNGICAL TEST SPECIMENS IN THE FIFTH HEAVY-SECTION STEEL TECH-NOLOGY IRRADIATION SERIES CAPSULES. WILLERLE, BALOWIN,C.A., STALLMANN,F.W. Oak Ridge National Laboratory, FIN B-0118, ORNL/TM-10582, 88/03/31, Division of Engineering (Post 870413), 135pt 45274 024 45274 150
- 8804290064 Requests addl into re SPDS to ensure compliance w/ NUREG-0737, Suppl 1, Including discussion of SPDS response times description of SPDS keyboard in accessing displays a into relocation of SPDS terminals in control room LONG.W.O. Project Directorate W. TAC 51232, 88704722, TREVORS,G.A. Nebraska Public Power District, 10pp. 45268:302-45268.359.
- 8804290185 NUREG-0837 V07 N04 NRC TLD DIRECT RADIATION MONITORING NETWORK.Prograss Report, October-December 1987. STRUCKMEYER,R Region 1, Ofc of the Director, 88/04/30, 323pp. 45283.099-
- 8804290204 NUREG:0750 V26 IDT INDEXES TO NUCLEAR REGULATORY COMMISSION ISSUANCES. July-September 1987.
 * Division of Publications Services. 88/03/31, 50pp. 45324:282-45324.325.

ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS

- 8803100156 Submits NRR Old Lift 109 reiinterlade w/Commissionars olds, including no ubcotton pd Commissionars olds & communication re travel & request for info MURLEY, F.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/07/Olficer of Nuclear Reactor Regulation, Director (Post 870411), 4pp. 44662 128-4446(2-13).
- 8803100160 Forwards Commission blweckly notice of applications & amends to Otsinvolving NSTCs.published in FR on 880210,for into Wide end MURLEY, I.C. Office of Nuclear Reactor Regulation, Director (Post 870411) 88/03/ 61 BREAUX J.B. Senato, Environment & Public Works, UDALL,MK House of Republicing & Insular Affairs, SNARP,PiR House of Rep., Education & Labor 2pp. 44662,115-44662-117
- 8803210090 Surpt 1 to NRC Into Notice 87-044, "Thimble Tube Thining in Westingtiouse Houctors," Svc tist and ROSSIGE Division of Operational Events Assessment (Post 870411). 88/03/28 Consolidated Edison Co. of New York, Inc. 121pp. 44995-126-44995.246
- 8803220296 NRC Into Notice 88-010, "Matts Licensees Lack of Mgt Controls Over Licensed Programs" Social encl. CLINNING IAM.R.E. Division of Industrial & Medical Nuclear Safety (Post 670729) 887-00728. Consolidated Edison Co. of New York, Inc. 108pp. 44995 247-44995-353.
- 0004010249 Establishos gurtolines hotween NRR & RES for technical review of sid prant dissigns, namely, Westinghouse RESAR SP/90, GE advanced BWR, C/E Sys 80 & EP/11 anivament CWR requirements document Four criteria for new design isted MURLEY, TE. Office of Nuclear Reactor Regulation, Ozector (Post 870411) BLCKJCHD, E.S. Office of Nuclear Regulatory Research, Director (Post 860720) 88/ 03/14, STFLLO, V. Olic of the Executive Director for Operations 4pp. 44949 150-44949 174.
- --8804010254 Documents transfer of responsibility for standardization 8 advanced reactor policy issues from NRR to RES, consistent w/NUREG-0325 BECKGOIID,E.S. Office of Nuclear Regulatory Research, Director (Post 860720) 877-05722 NURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 5pp. 44(140.154-44049):158
- --88040 10261 Forwards revised Std Plant Review Program Plan Four standardization projects & expected Westinghouse indivanced passive plant design 1 stell issuance of revision (program plan constitutes completion of Task Assignment 3 per 871116 memo CHUTCHFIELD,D. Division of Reactor Projects III,IV,V. & Special Projects (Post 870411), 88761725 MURIEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 44849:159-44949:174.
- --8804010267 "Std Plant Review Program Plan"

 * Standardization & Non-Power Reactor Project Directorate 88/01/31, 14pp
 44/949 161-44/949 174.
- 8804010256 NRC Into Notice 88-011, "Potential Lose of Motor Contro! Cir &/or Switchbigard Function Due to Faulty Tig Bolts." Svc.1st encl HOSSI,C.E. Division of Operational Events Assessment (Post 870411) 88/04/07 Cons
- 8804040022 Forwards list of 1987 LERs & proposed forwarding memo for Public Citizen Commits to forwarding revised list by June 1988 & advises of addressing future similar requests to NRC FOIA channols. IROSENTIAL.JE. Reactor Operations Analysis Branch. 88/03/22 INGRAM.F. Office of Governmental & Public Affairs (Post 870413). 45pp. 44972.154-44972.201.
- --9804040026 Forwards K Boloy 880205 fir to J Fouchard requesting listing of all LERs for CYR7 for uniqual nuclear power safety rept INGRAM,F Office of Governmental & Public Attains (Post 870413) 88/02/09. BIGHE/P Office for Analysis & Evaluation of Operational Data, Director 1p 449/2 200-44072 200.
- --0804040031 Requests list of LERs for 1987 & corresponding severity ratings for annual nucleur power safety rept to be issued in summer.

 I/OLEY,K. Pikhic Chizen's Chizeal Mass Energy Project 88/02/05. FOUCHARD,J Office of Governmental & Public Affairs (Post 870413), 1p. 44972 201-44972 201.
- 880.4050267 Summary of Operating Roactor Events Moeting 88.012 on 880322 List of attended, discussion of events & rept-to-date of long-term followup assignments & summary reactor scrams and LANNING.W. Events Assessment Branch. OREM-88-012. 88/03/29 ROSSIC E. Division of Operational Events Assessment (Post 870411). 13pp. 45017.292.45017.304
- 8804050272 Notrication of date & room change from 880405 to 880407 for meeting w/ BWR Owners Group in Rockvillo,MD to discuss diversity requirements for ATWS rule {10CF:4150.62} implementation. CLLLC Instrumentation & Control Systems Branch 88/03/29, NEWBERRY,S Instrumoration & Control Systems Branch 29p. 45029.161-45029 162.
- 8804060370 NRC Injo Notice 88-012, "Overgreasing of Electric Motor Boarings." Svc list onci. INOSSI.C.E. Division of Operational Events Assessment (Past 870411) 88/04/12. Consolidated Edison Co. of New York, Inc. 123pp. 45165-028-45165-150.
- 8804070027 Updatos status of offsite radiological emergency planning 8 preparedness for plant 8 summarizes 880308 meeting re discussion of all unresolved planning inadioquacios noted to date 3D Overstreet 880307 its to G Peterson end. PETERSON,G C. Federat Emergency Management Agency, 88/03/30. STELLO,V. Ofc of the Executive Director for Operations. 22pp. 45234:355-45235-016.
- --8804+10028 "Interim Evaluation of Linn County Radiological Emergency Plans for Duano Arnold Energy Ctr."

 * Fodoral Emergency Management Agency, 88/03/07, 98pp. 45072.132-45072.229.
- 8804130119 Partral response to FOIA request for documents Forwards documents listed in App A Documen(s also available in PDR. App B document withheld (ref FDIA Fxomption 5).

 GRIMSELY.D.B. Division of Rules & Records (Post 870413) 88/04/05 JORDAN.B. Institute of Nuclear Power Operations 4pp 45102.050-45102:101.

- --8803100052 Ferwards proposed revito incinerandom of agreement (MOA) schools INPO & NRC & apps to that agreement Machitien 1.1 troubles schools change App 4. "Coordination Plan for Incident Investigation Activities on the Executive Of Nuclear Power Operations 87:07/23 TAYLOR (M. Coordination Executive Director for Operations 18pp 45102.075.45102.001)
- #8804130146 Informs of process of developing guidelines for corte of conductor kill, operating principles for operators Complete set of guidelines will be during thin 871105 & 06 conference Comments requested by 871012

 PATE 2.1 Institute of Nuclear Power Operations 67709-04 STECLIO VICTORINE Executive Director for Operations 10pp 45102 054-45102 063
- #8804130156 Ack receipt of 870904 ftr to development of codes & sittles & coresting principles for nuclear power plant operators. Concept of operators development & call service and state and state of any code of ethics endorsed. STELLO, V. Oto of the Executive Director for Operations. 57/10:161. PATE 2.1 in a cited Nuclear Power Operations. 1p. 45102.064.45102.064.
- ~8804130161 Forwards draft paper for discussion reluse of performance in 1031 to PATE.2. Institute of Nuclear Power Operations 97/04/07 STEELO VILIPO 1-70 Co. dated Affication Given 3pp. 45102 065 45102 967
- #804130167 Forwards App 5 to coordination plan for NRCHINFO use of performance and cators per 870413 discussion
 PATE, 21 Institute of Nuclear Power Operations 67/04/14 STELLO victorial processors 4pp 45102 068-45102 071
- -8804130173 Forwards 871230 ftr to "NPO members informing of application by 5 miles on check valves recently developed by EPRI. Guidelines recommended to a the SOER 86.3, "Check Valve Failure or Degraphson."

 CONWAY,W.F. Institute of Nuclear Power Operations 87/12/39 STELVO V. Cft. of the Executive Director for Operations. 3pp. 45102.072.45102.074
- 8804130371 Forwards NRC response to data requirements contained in Applitic CMS Circular A130 & responses to questions from recipiont 870511 inche proving 40 valley Act gludance in MCDONALD, W.G. Office of Administration & Resources Management in Circular (Post 870413) 87/06/26 GRAMM, W.L. Office of Management & Budget 5pp 45117/015 45117/015
- 8804140241 Forwards "1978 Annual Rept of NRC on Administration of Fritage, Act of 1974."

 1974."

 FELTONUM Division of Rules & Records (Pre 870413) | 79705-01 | HAASE WW Office of Management & Budget | 7pp | 45118 178 45115 184
- 8804140537 Advises of intent to issue revised Manual Chapter 0514
 Mgl. of Plant Specific Backfitting of Nuclear Power Plants after role that adopted Manual encl.
 STELLOV Otc. of the Executive Director for Operations 87/11/13 JCROAMSEL Office for Analysis & Evaluation of Operational Date, Director 29pp 45130,212-45130,245.
- 8804150039 Forwards completed data forms rail NRC administration of Privacy Actinologing into concerning NRC sys of records & processing of Privacy Actinologists in 1981 in response to 820216 membine FELTON JM Division of Rules & Records (Pre 870413) 82703725 TOZZ 10 Office of Management & Budget 15pp 45139 105-45139 119
- 8804150261 Summary of 880317 meeting wilNUMARC EPRI & INPO reindustry, status of erosion/comosion tust of attendees & viowgraphs end MCCRACKENCE Chemical Engineering Stanch 56/04/06 RICHARDSCN JE Assistant Director for Engineering 15pp 45139/067-45139/681
- 8804180145 Trip rept of 880105 INPO/NRC mgt meeting to exchange into reiphons for review evaluation & dispersional on of operating events related into to I conserve five listed INPO requests under consideration to increase contribution. BERLINDER, C.H. Generic Commitmications, Branch. 88:03730 MARTIN, F.T. Associate Director for Inspection & Technical Assessment (Post 870411). 25p. 45143-372. 45149-353.
- 8804180265 Discusses projected computer requirements of PDSNP por complicted analysis identifying tasks for development of SERs for next generation of plants & possing of class field porting reviews for Navy Suggested configurations end HUBENSTEINLS. Standardization & Non-Power Reactor Floyect Directorie 28:003-28 CRUTCHFIELDID Division of Reactor Projects PTIVIV & Special Projects (Post 870411), 3pp. 45149-359-45149-361.
- 8804180312 Forwards NRC enforcement program per 880322 meeting NRC has adopted DOT transportation requirements & considering revising enforcement program for transportation violations. W/o end.

 IEEERMANJ, Or of Enforcement (Post 870413), 88/04/04, HOROWITZ A. Fuderal Awation Administration. Ip. 45150,001-45150,001.
- 8804180374 Summary of Operating Reactors Events Meeting 88-13 on 860320 Cist of attendeds,discussion of events 8 summary of reactor scrams enci. LANNING-W Events Assessment Branch OREM 88-013-88-03/31 ROSS: CE Dission of Operational Events Assessment (Post 870411) 18pp 45149-265-45149-222
- 8804180457 Summarizes 880322 meeting w/DOT to discuss chlorocement programs NRC has adopted DOT transportation requirements 8 considering rules and enforcement programs for transportation violations NRC enforcement program end LIEBERMANIJ. Oic of Enforcement Post 870413) 68104704 MARKMATIK Transportation, Dept. of, Foderal Highway Administration 1p. 45150 231-45150 231
- 8804180459 Requests civil penalty actions processed in 1986 & 1987 myolying ratioactive mait NRC adopted DOT transportation requirements & considering revising enforcement program for transportation violations W/o stated enct LICBERMANL DIC of Enforcement (Fost 870413) 88704704 CHASE M. Federat Ratioad Administration. 1p. 45149 293-45149 293
- 8804190213 Forwards response to 871012 concerns raised by test research & training reactors on effect of 10CFR55 changes NRC intends to have long-term recensed personnel participate in NRC administered exams per 10CFR55 STELLOV Olf of the Executive Director for Operations 88/04/11 RABY,T M. Commerce, Dept. of, National Burgau of Standards. Spp. 45166.013.45166.061

- -8804190217 Expresses concern releacht revs to 10CFR55 on test 8 research reactors & manner in which regions intend to apply roy to nonpower reactors Addi com-
- PABY,T.M. Commerce, Dept. of National Buroau of Standards, 87/10/12, STELLO,V Otc of the Executive Director for Operations, 3pp. 45166-018-45166-061
- -8804190222 "Discussion of Problems w/New 10CFR55 as Applied to Nonpower Reactors & Just Reation for Relief"
 WHITEMORE,W.L. GA Technologies, Inc./General Atomic Co. 87/10/12. 40pp. 45166.061.
- 8604210394 Summary of Operating Reactors Events Meeting 86-15 on 680412.List of attendens & viewgraphs encl.

 LANNING,W Division of Operational Events Assessment (Post 670411). OREM-88015 88/04/15 ROSSIC E Division of Operational Events Assessment (Post 870411) 20pp. 45192 139-45192 158
- 8804250010 Forwards proposed notice amending 10CFR140.91 to make certain changes in NEUA policy Proposed nilo has 30-day commant period. THOMAS,C.O. Policy Development & Technical Support Branch (Post 870411), 68/04/14, MEYER,D.L. Rules & Procedures Branch. 2pp. 45292.267-45292.275.
- -8804250016 Advises that amends to 10CFR140 re changes to NELIA policy approved by all Commissioners.
 CHILK,S.J. Office of the Secretary of the Commission 88/04/07. STELLO,V. Ofc of the Executive Director for Operations, 7pp. 45232 269-45232 275.
- 8804250106 Forwards rept re 8WR overfit events that have resulted in steam lines flooding in consideration of resolving USI A-47, "Safety Implications of Control Sys." ROSENTHAL J. E. Reactor Operations Analysis Branch, 88/04/15 SZUKIEWICZ, A.J. Engineering Issues Branch, 2pp. 45213-096-45213-097.
- 8804250117 Forwards rept of BWR overfit events that have resulted in flooding of steam lines Study found that little actual damage expenenced,per event Regional personnet should monitor ticense actions prior to restart following events. NOVAK,T.M. Division of Salaty Programs (Post 870413) 88704715 KANE,W.F. Region 1, Otro of the Director, REYESL Region 2, Otro the Director, NORELIUS,C Region 3, Otro of the Director, ip 45213 103-45213 103.
- 8804250358 Forwards rept re BWR overful events resulting in steam the flooding for consideration in USI A-47, "Safety Implications of Control Sys." KAUFFMAN_J.V. Reactor Operations Analysis Branch AEOD/E801. 88/04/16 ROSENTHAL_J E. Reactor Operations Analysis Branch 7pp. 45213:193-45213.199
- 8804260137 Forwards AEOD engineering evaluation rept on BWH overfill events resulting in floodings of steam lines. Little damage experienced as result of flooding events NRC should monitor licenses actions prior to plant restant Wto stated enci ROSENTHAL JE. Office for Analysis & Evaluation of Operational Data, Director. AEOD/E801. 88/04/15. ROSSIC E. Division of Operational Events Assessment (Post a2011) 2nd A523-265. A523-266. 870411). 2pp 45232-265-45232-266
- 8804270040 Forwards Regulatory History AC12-1 re proposed rule 10CFH34, "Safety Requirements for Industrial Radiographic Equipment," NELLIS.D.O. Radiation Projection & Hoalth Effects Branch, 53FR8460, 88704713 EXUMP, Document Control Branch (Document Control Desk) 15pp 45356-353-353 45357 D11
- -8604280632 Forwards suggested approach to reducing incidence of overexposure of industrial radiographers to encourage continuation of NRC efforts to determine means for reducing overaxposure occurrences
 MILLS,W.A. Environmental Protection Agency. AC12-1 48: 77/09/07. MINOGUE,R.B.
 Office of Standards Development, Director. 3pp. 45357.119-45357;121.
- -6804280665 Ack receipt of 770907 itr listing suggestions to reduce frequency of rediation overexposures among industrial ractiographers NRC presently working in several areas to improve radiography safety. MiNOGUE, R.B. Office of Standards Development, Director, AC12-1-54, 78/02/14, MILLS,W.A. Environmental Protection Agency, 3pp., 45357:141-45357,143.
- 8804270113 Forwards 871103 response to request for assistance in reviewing petition filed under 10CFR2.206 by concerned citizens for listed countles, Recommends that emergency preparedness info handbook not be Immediately revised. KRIMM.R.W. Federal Emergency Management Agency. 2.206. 88702/26. CONGEL,F.J. Division of Radiation Protection & Emergency Preparedness (Post 870411), 22pp. 45246.253.45246.278.
- 8804280302 Ack receipt of 880228 comments re 871203 DOE position paper re disposed of slightly confaminated bldg & equipment debris at U mill tellings remedial action sites DOE accepts approach of avaluation on site-by site basis.

 ARTHUR,WJ. Energy, Dept. of. 88703727, LOHAUS,P.H. Operations Branch 1p. 45285-113-45285-113
- 8804280425 Requests branch engineer to serve on new working group to develop new ANSI/ANS-15.20 criteria for reactor control & safety sys of research reactors std RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate, 88/04/19. NEWBERRY,S. Instrumentation & Control Systems Branch. 2pp. 45270.007-
- 8804290482 Forwards Commission biweekly notice of applications & amends to OLs involving no alignificant hazards considerations published in FR on 880308, for Info.W/o stated encl
 - MURIEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 88/03/ 24. BREAUX,J.B. Senate, Environment & Public Works, UDALL,M.K. House of Rep., Interior & Insular Affairs, LUJAN,M. Hause of Rep., 2pp., 45264,061-45264;062,
- 8804280562 Forwards mome from G LaRouche requesting NRC to submit requirements re mapping digital cartographic data, aerial photography & special products for geological survey annual solicitation.

 HICKEY,J.W.N. Operations Branch. 88/04/01. JOYNER,J.H. Region 1, Ofc of the Director. CLINEW.E. Region 2, Ofc of the Director. 1p. 45263.001-45263.010.
- --8804280138 Notifies of USGS annual solicitation of federal agency requirements for mapping & digital catographic for OMB Circular A-15 coordination responsibilities instructions for making needs known on status maps end

- 8804290001 Forwards 880326 memo re projected computer requirements per 880330
- request is microcomputers.

 RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate. 88/04/

 95 CRUTCHFIELD,D. Division of Reactor Projects III,IV.V & Special Projects (Post 970411) 2pp 45322 275 45322:279.
- 8804290003 Submits biweekly status of accelerated emergency operating procedures insp program for period ending 880401 REGAN.WH Human Factors Assessment Branch 88/04/05. ROE.J.W. D.vislon of Liverschool Control of Control censes Performance & Quality Evaluation (Post 870411), 6pp. 45324;177-45324;182.

PR PROPOSED RULE

- 8603310195 Comment supporting proposed rule 10CFR50,App J re mass point method of data analysis. Recommends lest duration criteria in ANSI/ANS.58.8-1987,Section 5.4 be accepted in revised regulations.

 FAY,C.W. Wisconsin Electric Power Co. 53FR5885 00006 88/03/18. CHILK.S. Office of the Secretary of the Commission. 2pp. 44964.061-44964.062.
- 8803310201 Commont supporting proposed rule 10CFHS0,App J re alternative method for toakage rate tosting Chango would remove util of burden of seeking exemption to App J in order to employ more state-of-the-art statistical analyses. EDWARDS,O.W. Yankoe Atomic Electric Co. 53FR5985 00005, 88/03/23. Docketing & Services Branch. 1p. 44982:360-44982:360
- 8803310206 Comment on proposed rule 10CFR\$0,App J re primary reactor containment leakage leating for water-cooled power reactors. Util endorses addition of mass point methodology to acceptable leakage rate calculational methods. CONWAY,W.F. Florida Power & Light Co 53FR5985 00004. 88/03/25 Docketing & Services Branch, 1p. 44964:074.44864:074.
- 8803310210 Comment opposing proposed rule 10CFR50 re mass point analysis Proposed rule contrary to ANSI/ANS 56 8-1987 & general reviot App J specifying 24 h min test duration when using mass point analysis may prompt needless exemptions.

 CONNOLLY,J.W. Public Service Co. of New Hampshire, 53FR5985 00003, 88/03/23.

 Dockoling & Services Branch 1p. 44996,081, 44996,081.
- 8803310234 Comment on proposed rule 10CFR34 re safety requirements for Industrial radiographic equipment Review of matter of const. & design for source assembly
- noeded WONG,KS California, State of 53FR8460 00001, 88/03/17, Docketing & Services Branch 2pp. 44967:262-44967:263
- 8803310238 Comments on proposed rule 10CFR50 re altenative method for teakage rate testing OCRE supports proposed rule & recommends prompt approval in interest of public safety.

 HATT, St., Otho Citizens for Responsible Energy, 53FR5985 00002, 88/03/16, Docketing & Services Branch, 1p, 44983 254-44983,254.
- 8804070138 Comment on proposed rule 10CFR50, App J re alternative method for leakage rate testing. Requiring min test duration of 24 h when using mass point analysis technique appears to be w/o basis. THOMAS, G.S. Public Service Co. of New Hampshire, 53FR5985 00008, 88/03/29, Docketing & Services Branch, 1p. 45044:159-45044:159
- 8804070291 Comments supporting proposed rule 10CFR50 re leakage testing of containment to pormit use of mass point method as alternative method for calculating containment leakage rates. Mass point method more accurate for calculating rates. MRIOCZKAE J. Connecticut Yankee Atomic Power Co. MRIOCZKAE J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MRIOCZKAE J. Northeast Utilities. 53FR5985_00008_88/03/31. CHILKS.J. Office of the Secretary of the Commission. 3pp. 45021:184-45021:186
- 8804070329 Comment supporting proposed rule 10CFH50 raiuse of mass point method when coupled w/test duration of at least 24 h. Util recommends that proposed rule andorse test lime duration & number of data points required per rel std.

 TUCKER,H.B. Duke Power Co. 53FR5985 00007, 88/03/22, Docketing & Services Branch 2pp 45021:241-45021;242.
- 8804080052 Requests that recipients of proposed rule 10CFR62 (52FR47578) re-criteria & procedures for emergency access to nonfederal & regional low level waste disposal facilities disregard Comments 22,23 & 24.Comments do not apply to rule.

 **Docketing & Services Branch. 88/04/01. Affiliation Not Assigned. 1p. 45044:250-45044:250.
- 880408D174 NUREG-1310 NATURALLY OCCURRING AND ACCELERATOR-PRO-DUCED RADIOACTIVE MATERIALS 1987 Review. AUSTIN,J.H. Office of Nuclear Material Safety & Safeguards, Oirector, 88/03/31, 74pp. 45201.180-45206:036
- --8804180138 Comments on rept, "Regulation of Naturally Occurring & Accelerator Produced Radioactive Matts--Task Force Review," Inclusion of all radioactive matt under authority of one agency appears logical Related into encl. HILE_JP. Food & Drug Administration. 42FR37458 00015. 77/09/22. Docketing & Services Branch. 116pp. 46205:217-45208 036.
- 8804110066 Comments on proposed rule 10CFR73. Suggests that licensees arrange for NRC to observe one quarterfy shift exercise on annual basis & that rifles be located at strategic locations throughout facility rather than carried by security. BOYD.C.C. Bebcock & Wilcox Co. 52FR49418 00002 88/03/28. Docketing & Services Brench. 2pp. 45073:255-45073:258.
- 8804110092 Comment on proposed rule 10CFR73 re upgrading safequards requirement at facilities possessing formula quantities of strategic SNM Frequency of facilical response exercise should be once every 4 months rather than quarterly.

 ASMUSSEN,K.E. GA Technologies, Inc /General Atomic Co. 62FR49418 00003 88/03/29. Docketing & Services Branch, 5pp. 45073:257-45073:281.
- 8804270040 Forwards Regulatory History AC12-1 re proposed rule 10CFR34, "Safety Requirements for Industrial Radiographic Equipment." NELLIS,D.O. Radiation Protection & Health Effects Branch. AC12-1. 88/04/13. EXUM.P. Document Control Branch (Document Control Desk). 15pp. 45356:353-

- -8003130173 Discusses concern re-industrial radiographic exposure devices & requests assistance in identifying addl safety design areas to help reduce exposure to radio-Oranhors
 - graphiers
 JONES.R.J. Assistant Director for Materials Safety Standards. AC12-1.56. 80/02/06
 NUSSBAUMER.D.A. Assistant Director for Material Safety & Licensing. PUHPLE.R.
 Assistant Director for Radiol Hoalth & Safeguards. Standards. SNIEZEK.J.H. Div. of
 Fuel Facilities, Materia's & Safeguards. IE (Pre. 830103). 2pp. 45357.146-45357.147
- -8009190791 SECY-80-324 Discussos new program to improvo radiation safety in industrial radiography operations
 DIRCKS.W J. Olic of Nuclear Material Safety & Safeguards.Director AC12-1 53 807
 07709 6pp 45357 135-45357 140.
- --8101210084 Forwards for review & commont proposed amonds to 10CFR34, "Radiagraphy Reguration Safety Features for Radiagraphic Equipment." Response due 810106 W/o enct.

 JONES,R.J. Assistant Director for Materials Safety Standards. AC12-1.44, 80/12/24.

 CUNNINGHAM,R.E. Division of Fuel Cyclo. & Material Safety (Pre. 870413).

 SNIEZEK.J.H.D.v. of Fuel Facility & Materials Safety, IE. CUNNINGHAM,G.H. Regulations Division. 2pp. 45357-109.45357-110.
- ~8104020605 Requests assistance in reviewing encl proposed amends to 10CFR34 on design of radiographic exposure devices W/o encl SMITLR G. Office of Standards Development, Director AC12-1 41 81/03/09 DAVIS,J G. Office of Nuclear Material Safety & Safeguards,Director STELLQ,V. Ofc of Inspection & Enforcement, Director (820201-870413). SHAPARI,H.K. Office of the Executive Legal Director (Pre 860701) 2pp. 45357.103-45357.104
- --8305020041 Summarizes 830412 meeting re-status of program to improve safety of rad ography operations Withdrawal of rulomaking on rad ography design recommended Orall Commission paper will be prepared SOLBERGO. Transportation & Materials Risk Branch AC12-1 43 83/04/20 ERNST,M., BUCHBINDER,B. SMITH,O Office of Nuclear Regulatory Research, Director (Pre-860720), 2pp. 45357-107-45357.108
- --8401200070 Submits key points to road for radiography equipment design rulomaking OPE interested due to frequent appearance of radiography incidents in ropts to Congress SOLBERG D.E. Reactor Risk Branch. AC12-1.39. 84/01/11. BEHNERO,R.M. Accident Source Term Program Office. 5pp. 67126-156-67126-158.
- --8503190151 Requests comments on initiation of new rulemaking action re 10CFR34, "Safety Requirements for Industrial Radiographic Exposure Devices," included as Ecolic Interest Control form package. W/o encl GOLLERIK II. Division of Radigition Programs & Earth Sciences (840429-860720) AC12-1 34 85/03/96 KERRIG W. Office of State Programs, Director (Pre 870413) 200 45357 UR3.4537-084 2pp. 45357 U83-45357-084.
- --8503260124 Requests concurrence w/draft recommendations from director of RES to EDO concurring inflation of new rutemaking action by RES re 10CFR34 concorring safety requirements for industrial radiographic exposure devices GOLLER,K.R. Division of Rediaben Programs & Earth Sciences (840429-860729). AC12-1-37. 85/03/08. CUNNINGHAM,R.E. Office of Nuclear Material Safety & Safeguards,Droctor. 2pp. 45357.087-45357.088.
- --8701070480 Agrees w/issuance of amond to 10CFR34, "Safety Requirements for in-dustrial Radiographic Exposure Devices," for comment w/listed recommendation Proposed rule rices not address use of question bank by radiography personnel
 SJODLOM,G Salequards & Malerials Program Br, Div of Inspection Programs,IE
 (850212-870413) AC12-1 25. 86/12/30 ALEXANDER,R E Salety Research Application Branch 2pp. 45357 055-45357.056.
- --8702050186 Commonts on regulatory analysis of proposed amond to 10CFR34 resaftely requirements for industrial radiographic exposure devices Benefit of avoiding overcoxposures evertated.
 SPEIS.T.P. Division of Setely Roview & Oversight (851125-870411). AC12-1-67. 877 01728 GOLLER,K.R. Division of Regulatory Applications (860720-870413). 2pp 45357-149-45357-149.
- ~8710280311 Forwards AEOD comments on review oa amend of 10CFR34, "Safety Requirements for Individual Rediagraphic Exposure Devices." Concurrence subj to rev of number of incident repla received annually from licensees. NOVAK,T M. Division of Safety Programs (Post 870413). AC12-1 58. 87/10/20, MORRIS.B M. Division of Regulatory Applications (Post 870413). 2pp. 45357:150-1501.
- -8711030480 Advises that NRR has no objection to recipient proceeding w/amend to 10CFR34, "Safety Requirements for Industrial Radlegraphic Exposure Devices" Requirement for both pockol & alarm dos maters acceptable. MURLEY,T.E. Office of Nuclear Reactor Regulation, Ciractor (Post 870411) AC12-15, 87110/30, MORRIS,B.M. Division of Regulatory Applications (Post 870413) 3pp 46357:152-45357171.
- --8802170349 SECY-88-010 Requests Commission approval for publication of proposed amonds to 10CFR34, "Safety Requirements for Industrial Radiographic Equipment." Amond will require safety performance slids for radiographic equipment. STELLOV Oic of the Executive Director for Operations. AC12-1 05 88/01/13. 5pp. 45357:012-45357.010.
- -8804270082 Roquests Implementation of listed Commission action re end documents, per proposed rute on safety requirements for industrial radiography equipment. Marked-up FR notice showing Commission requested changes enci for Diceston and Control of the con of Socrotory MORRIS,B.M. Division of Regulatory Applications (Post 870413). AC12-1 01. 88/03/ 03. MEYER,D.L. Rulos & Procedures Branch. 1p. 45357.008-45357.008.
- ***8804270066 Prose release discussing NRC proposal to establish new regulatory requirements for industrial radiographic exposure equipment.
 * Office of Governmental & Public Affairs (Post 870413) AC12-1 02. 88/03/16 1p. 45357.000. 45357.009.

- ~8804270071 Forwards public announcement & proposed rule amending 10Cl R34 Proposed amends would establish new regulatory requirements for industrial radiographic equipment & require radiographics to wear alarm dosimeters for added
- rabiographic equipment a registrict and second and protection protection BECKJORD.E.S. Office of Nuclear Regulatory Research, Director (Post 860720) AC12.1 0.03 88/03/11 UDALL.M.K. House of Rep., Interior & Insular Affairs SHARP.P.B. House of Rep., Energy & Commerce BREAUX.J.B. House of Rep., Environment & Public Works, 1p. 45357.010-45357.010
- --8804270076 Advises that Commission approved publication of proposed amends to 10CFR34. "Safety Requirements for Industrial Radiographic Equipment." Enclicational correction should be made W/o enclicational CHILK, S.J. Office of the Secretary of the Commission AC12-1 04 88/02/22 STELLO.V. Office of the Executive Director for Operations. 1p. 45357
- --8804270081 Ferwards, for signature, Commission paper recommending amend to 10CFR34 to specify additisately requirements for industrial radiographic equipment & requirement for industrial radiographers to wear alarm dos
- --8804270093 Concurs w/871002 proposed rule package rairov to 16CFR34 re-safety requirements for industrial radiography exposure devices. CUNNINGHAMIR E. Division of Industrial & Modical Nuclear Safety (Post 870729) AC12-1 07. 87/12/23 MORRIS BM. Division of Regulatory Applications (Post 870413) 1p. 45357.019.45357.019.
- --8804270100 Comments on proposed radiography rule religional requirements for industrial radiographic exposure devices per 871202 request. Location of environ assessment should be included under "addresses" caption of preamble of FR notice SMITH, M. Office of the General Counset ACI2-1 08. 87/12/07. MELLISID. Radiation Protect on & Health Effects Branch. 2pp. 45357 020-45357 021.
- --8804270103 Advises that J Lubenau left message on 871020 that State, Local & Indian Tribe Programs concurs in radiography rule package wind comments NELLIS.D NRC No Detailed Affination Given AC12-1 09 87/11/04 NRC No Detailed Affination Given to AC12-1 09 87/11/04 NRC No Detailed Affination Given 1p 45357 022-45357 022
- ***804270111 Forwards specific comments on proposed rule 10CFR34 re-salety re-quirements for industrial radiography exposure devices Revs needed before rulemax-ing will be recommended for release for public comment CUNNINGHAM.R.E. Drisson of Industrial & Medical Nuclear Safety (Post 870729) AC12-1 to 87710730. MORRIS&M Drisson of Regulatory Applications (Post 870413) 1p. 45357.023.45357.023
- --8804270119 Forwards marked-up package of comments concurring w/proposed rule that would amend 10CFR34 re-satety requirements for radiographic exposure devices MCDONALD,W.G. Office of Administration & Resources Management, Director (Post 870413) ACI2-1 11. 871/01/20. MORRIS,8.M. Division of Regulatory Applications (Post 670413) 2pp. 45357.024-45357.025.
- --8804270129 Comments on proposed amend of 10CFR34 re-safety requirements for industrial red ographic exposure devices Ref to 10CFR34 43(a) should be changed to 10CFR34 43(b) in last paragraph at Page 6 of Encl A TREBY S A Assistant General Counset for Rulemaking & Fuel Cycle AC12-1 12 87/10/20 MORRISB M Division of Regulatory Applications (Post 870413). 2pp 45357 026-45357.027.
- --8804270137 Concurs w/proposed amend to 10CFR34 re-safety requirements for in-dustrial rad ographic exposure devices Pocket dostmeters should be worn along w/ alarm dostmeter Alarming dostmeter not to be substituted for pocket dostmeter MONTGOMERY_IL Office of Nuclear Material Safety & Safeguards_Director AC12-1 13. 87/10/20. ALEXANDER,R.E. Radiation Protection & Health Effects Branch 1p 45357.028-45357 028
- -9804270144 Concurs w/proposed changes to 10CFR34 & offers comments. Radio-graphers should be required to use pocket & alarm dosimeters until Region has had more field experience w/ afarming dosimeter. FISHER,WL Region 4, Otro of the Director AC12-1 14, 87/10/26 ALEXANDER.R.E. Radiation Protection & Health Effects Brench. 1p. 45357 029-45357.029.
- --8804270158 Offers no recommendations for changes to 871002 document proposing amend to 10CFR34 re-safety requirements for industrial radiographic exposure devices Supports proposed amend which would require additionally requirements MALLET, B.S. Region 3, Ofc of the Director. AC12-1 15. 87/10/19. ALEXANDER, R.E. Radietion Protection & Health Effects Branch 1p. 45357.030-45357.030.
- -8804270170 Comments on proposed amend to 10CFR34. Issue of requiring pocket & alarm dosimeters needs further specificity in rule. New licensees should not be required to purchase pocket dosimeters since alarm dosimeter could replace pocket. one CLINE,W.E. Region 2, Ofc of the Director. AC12-1-16 B7/11/05 ALEXANDER,R.E. Raciation Protection & Health Effects Branch. 1p. 45357.031-45357.031.
- -8804270192 Concurs w/amend to 10CFR34 re safety requirements for industrial radiographic exposure devices. Region does not believe that proposed 10CFR34 33 achieves purpose stated in background of Encl A & recommends that 10CFR33 be dropped JOYNER, J.H. Region 1, Old oil the Director AC12-1 17, 87/11/06, ALEXANDER, R.E. Radiation Protection & Health Effects Branch, 2pp. 45357-032-45357-033.

- --8804270213 Requests review of encil documents re-proposed amend to 10CFR34 re-safety requirements for industrial radiographic exposure devices & requirements for radiographics to wear alarm dosimeters Complet on requested by 871020. ALEXANDER, R.E. Radielium Protection & Health Effects Branch. AC12-1-19, 87/10/02 TAYLORIJ M. Ofc. of tine Executive Director to Operations. JOYNER, J.H. Region 1, Ofc. of tine Director, KLINE, W.E. Region 2, Ofc. of the Director. 3pp. 45357,038-45357,040. 45357 040
- --8804270218 Concurs in proposed relembing for safety performance slds for radio-graphic exposure devices & requirement of wearing pocket afairm dosimitiers Agreement State comments ont? NUSSBAUMERIDIA Assistant Director for State Agreements Programs AC12-1 20 87/03/11 NELLISIDIO. Safety Research Application Branch 2pp 45:357-041-
- --8804270248 Recommends adoption of Alternative 3 re proposed changes to 10CFR34 re industrial ratinggraphy safety requirements. Of wholeheartedly endorses proposed changes as bonolicial to industry TOPFAN, W.C. Maing, State of AC12-1 21, 87/02/10 Docksting & Services Branch tp. 45357:050-45357.050
- --8804270264 Forwards marked up package of commonts relamend to proposed rule 10CFR34 to add sately performance requirements for recognative exposure devices 8 to require radiographics to wear a form destinators W/o encl. GREMSLEY.D.H. Division of Rufos 8 Records (Pre 870413). ACI2-1 22, 87/01/14 ALEXANDER.R.E. Safely Research Application Branch. 2pp. 45357.051-45357.052.
- --8804270269 Commonts on amond to 10CFFI34 re-safety requirements for industrial ra-diographic exposure devices Recommends that farures of equipment meet perform-ance stds in field be reported to NRC HELTEMES.C.J. Office for Analysis & Evaluation of Operational Data, Director AC12-J. 23 87/01/20 ALEXANDER.R.E. Safety Research Application Branch 1p. 45357:053-45357.053
- --8804270278 Comments on proposed amend to 10CFR34 ro safety requirements for industrial radiographic exposure devices.per 861219 request Regulatory analysis does not adequately support proposed rulemaking MILLER,VL. Materials Licensing Branch. AC12-1. 24, 87/01/16. ALEXANDER,R.E. Safety Research, Application Branch. 1p. 45357-054-45357.054.
- ***8804270313 Requests assistance in reviewing encl documents re proposed amend to 10CFR34 to safety requirements for industrial radiographic exposure devices Completion requested by 870120.

 ALEXANDERIR E Soldy Research Application Branch. AC12-1 26. 86/12/19. CUNNINGHAM,R E Division of Fuel Cycle & Material Safety (Pro 870413). SPEIST P. Division of Safety Review & Oversight (851125-870411) PARTICIONU,G. Otto Inspect on & Enforcement, Director (920201-870413). 2pp 45357 057-45357,058.
- -- 8804280130 Requests section be added to 10CFR34 to require radiography licensees to replinto or equipment, working conditions, worker training & worker observance of operating procedures, per 861007 discussion. CARRICO.8 Materials Licensing Branch AC12-1 27. 86/10/17, NELLIS,D. NRC - No. Detailed Affiliation Given 2pp. 46357:059-45357:060.
- -8804280139 SECY-88-197 Provides Commission w/info re status of efforts to improve safety in industrial radiography operations STELLOV, Olfic of the Executive Director for Operations, AC12-1-28 86/07/02 6pp 45957-081-45357-086
- --8804280168 Summary of Radiography Steering Committee meeting on 860115-16 in Auslin,TX re slatus of Initiatives to Improve safety requirements (or industrial radiography operations described in SECY-85-354 CHAPELL,DR Division of Fuel Cycle & Material Safety (Pre 870413). AC12-1 29. 867-06703. METZGER,J.R. Old of Inspection & Enforcement, Director (820201-970413). NELLS,D.O. Office of Nuclear Regulatory Research, Director (Pre 860720) THOMASSON,N.W. Office of Policy Evaluations. 5pp. 45357-067-45357-071.
- --8804280249 Recommends that NRC begin new RES-sponsored rulemaking based on review of proposed rulemaking eartifed, "Safety Requirements for Industrial Radio-graphic Exposure Devices" Costs as result of rulemaking will probably be small. MINOGUE,RIB, Office of Nuclear Regulatory Research, Director (Pro 860720) AC12-1 31, 85/11/12, DIRCKS,WIJ. Ofci of the Executive Director for Operations 3pp 45357,074-45357:076.
- --8804280279 Summary of Radiography Steering Committee maeting on 850808 in Silver Spring, MD ro Western Stress radiography incident in State of WY. CHAPELL D.R. Steering Committee on Hadiography Safety, AC12-1 32 65/09/11 NRC No Detailed Alfiliation Given, 3pp. 45357:077-45357.079.
- --8804280352 Discussos European design & performance requirements for industrial ra-diography equipment Europeans adopt ISO 3999 apparatus for gamma radiography spac as design requirements CUNNINGHAM.R.E. Division of Fuel Cycle & Material Safety (Pre 870413). AC12-1 33, 85/05/07, CHAPELL.D.R. Division of Fuel Cycle & Material Safety (Pre 870413). 3pp. 45357.080-45357:082
- --8804280423 Comments on new rulemaking action for industrial radiography exposure devices Results of program could onhance regulatory basis for proposed rulemaking on subjilot radiation safety performance slds for radiographic equipment. KERRIG W. Othco of State Programs, Director (Pre 870413). AC12-1 35, 85/03/20 GOLLERIKIR Division of Radiation Programs 8 Earth Sciences (840429-860720) 2pp. 45357:085-45357:086
- --8804280487 Summary of Radiography Steering Committee meeting on 850123-24 in aguragurar summary of Had ography Stearing Committee freeling on \$5012.44 in Bation Rouge, LA rouse of large sources of radiation, nature of work & overexposure history, per industrial rad ography.

 CHAPELL, D.R. Division of Fuel Cycle & Material Safety (Pre 870413). AC12-1 38 85/02/22. PARTLOW, J.G. Otto of Inspect on & Enforcement, Director (820201-870413). THOMASSON, M.W., GOLDSMITH, R. Office of Policy Evaluations. 7pp. 45357.089-45357.089 45357 095
- -8804280517 Provides comments on draft Commission paper on industrial 8804280617 Provides comments on craft Commission paper on incusting radiography Commission members significant differences in views re draft warrants discussion Moeting of steering committee suggested for early Jan 1984. KERR.G.W. Olice of State Programs, Director (Pre 870413), AC12-1 40, 83/11/25. CUNNINGHAM.R.E. Division of Fuel Cycle & Material Safety (Pre 670413), 2pp. 45357:101-45357:102.

- -8804280583 Requests endorsoment for assuance of rog guide for design slds for rad-ography equipment Regiguite would be essentially same as proposed amend to 10CFR34.RES wit proceed whappropriate task initiation if committee agrees MALAROUSC Office of Nuclear Regulatory Research, Director (Pro 860720). AC12-1 42. 81/10719. CARTER, F. Steering Committee on Hadiography Safety 2pp 45357.105.45357:106.
- --8804280599 Requests review & comment of encl proposed amends to 10CFR34 re design radiographic exposure devices. JONES,R.J. Office of Standards Development, Ciroctor AC12-1 45 80/12/24 CUNNINGHAM,R.E. Division of Fuel Cycle & Material Safoty (Pre 870-113) SNIEZEK,J.H. Olic of Inspection & Enforcement, Director (820201-870413) CUNNINGHAM,G.H. Regulations Division. 3pp. 45357-111-45357-113
- -8804280608 Summary of 800304 meeting re-interofc program to reduce exposure to radiographers.
 CARTERT.F. Division of fuel Cycle & Malerial Safety (Pre 870413). AC12-1 46, 807, 03/14. ARLOTTO,G.A. Division of Engineering Standards. CUNNINGHAM,G.H. Regulations Division. GOLLER,K.R. Division of Siling, Health & Safeguards Standards. 4pp.
- --8804280626 Agrees w/approach to task re plans for development of sids & specs for radiography devices Specific items for consideration Listed SNIEZEK, JH. Ofc. of Inspection & Enforcement, Director (820201-870413). AC12-1 47. 80/02/29. JONNES,R.J. Assistant Director for Materials Safety Standards. 1p. 45357.118.45357.118.
- --8804280632 Forwards suggested approach to radicing incidence of overexposure of industrial radiographors to encourage continuation of NRC efforts to determine means for reducing overexposure occurrences. MILLS,W A. Environmental Protection Agency. AC12-1 48, 77709707. MINOGUE,R B. Office of Standards Development, Director. 3pp. 45357:119-45357:121.
- --8804280637 Advises that amends to 10CFR32 & 34 unnecessary & not recommended in SECY-77-34, "Action Plan to Heduce Radiography Overexposures" MINOGUE R.B. Office of Standards Development, Director. AC12-1 49, 77/03/16 ROWDEN, GILINSKY, KENNEDY Commissioners 2pp 45357 122-45357 123
- --8804280645 SECY-77-034 Rosponds to Charman request for staff to prepare coordinated NRC action plan for remedying problem of radiography overexposures

 MINDGUE,R.B. Office of Standards Development, Director. AC12-1 50, 77701/25, 1p.

 TOTAL CONTROL OF STANDARD CONT 45357.124-45357.124
- --8804280649 SECY-76-146 Responds to Charman request for review of current level of protection associated w/portable radiography units per personnel overexposures Forwards appropriate recommendations for changes in NRC regulatons.
 MINOGUE,R.B. Office of Standards Development, Director AC12-1 51 76/03/15 2pp 45357.127-45357-128
- --8804280658 Informational fir to all radiography licensees re radiation incidents in radiography operations. List of incidents that occurred during licensed radiography encliptics. PA Atomic Energy Commission. AC12-1. 52. 65/06/14. Atlifation Not Assigned 6pp. 45357:129-45357-134.
- --8804280665 Ack receipt of 770907 fir listing suggestions to reduce frequency of radiation overexposures among industrial radiographers NRG presently working in soveral areas to improve radiography safety.
 MINDGUE, B.B. Office of Standards Development, Director. AC12-1. 54, 78/02/14, MILLS,W.A. Environmental Protection Agency, 3pp. 45357-141-45357:143.
- --8804280668 Advises that present schedule calls for publication of advance notice of rulemaking on design requirements in Feb 1978 & publication of proposed amonds in Aug 1978
 SMITH_D.A. Transportation & Product Standards Branch AC12-1 55. 78/02/09. SMITH D.A. Transportation & Product Standards Branch AC12-1 55, 78/02/09. Transportation & Product Standards Branch 2pp. 45357 144-45357 145
- -8805030070 Offers no further comments on proposed changes to 10CFR34 re-industrial ractography safety requirements Concurs w/ inclusion of safety requirements for ractographic exposure devices & for ratiographers to wear alarm dos-meters SHEALY.H.G. South Carovins, State of AC12-1 60. 87/02/02. NUSSBAUMER.D.A. Assistant Director for State Agreements Programs 1p. 45357.042-45357.042.
- -8805030121 Concurs w/proposed amends to 10CFR34 to include safety performance 3809330121 Concurs wripposed amends to 10cm34 to include salery partitioning requirements for radiographic styposure devices & to require radiographers to wear dosmeters. Experiences w/ use of Zelex Model 504 digital ararm dosimeters listed HLL,T.E. Georgia, State of. AC12-1.61. 87/02/13. NUSSBAUMER,D.A. Assistant Director for State Agreements Programs. 1p. 45357.043-45357.043.
- 8805030128 Concurs w/proposed additions to 10CFH34 to require safety performance stds for radiographic exposure devices 8 radiographers to wear packet alarm dosi
 - meters. EURF.J A Iowa, State of AC12-1 62 87/02/24 NUSSBAUMER,D A Office of State Programs, Director (Pre 870413). 1p 45357.044-45357.044
- --8805030139 Concurs w/proposed changes to 10CFR34 re-industrial radiography safety requirements
 BLANTON,R.L. Arizona, State of AC12-1 63, 87/03/03, NUSSBAUMER D.A. Assistant Director for State Agreements Programs 1p. 45357 045-45357 045
- --8805030151 Responds to NRC 870115 llr to all Agreement States re proposed changes to 10CFR34 re safety requirements for radiocactive exposure devices & requirement for radiocactive exposure devices & requirement for radiocactive radiocactive states of ACI2-1 64 87702/27. NUSSBAUMER,D.A Assistant Director for State Agreements Programs, 1p. 45357-046-45357-046.
- -8805030161 Comments on proposed amends to 10CFR34 Amends will contribute to greater degree of salety.
 MOUNT,D.K. North Dakota, State of AC12-1 65. 87/03/03 NUSSBAUMER,D A. Assistant Director for State Agreements Programs 1p. 45357-047-45357.047.
- --8805030170 Offers no comments re-proposed changes to 10CFR34 re-industrial radiography safety requirements in response to NRC 870115 ftr Changes should be adopted & implemented as written. BORCHERT.M.R. Nebraska, State of AC12-1 66, 87/03/06 NUSSBAUMER,D.A. Assistent Director for State Agreements Programs 1p. 45357-048-45357.049.

PRM PETITION FOR RULEMAKING

- 8803310185 Comment opposing potition for rulomaking PRM-50-48 religion of re-suarch reactor Urgos potition by denied or modified to include reasonable power level as three-hold-for classification as testing facility. HIATT,SIL Othio Citzons for Responsible Energy 53FR8159 00001 88/03/15 NRC -No Dotal of Affiliation Given 1p. 44983 257-44983 257
- 8803310243 Comment supporting position for rulemaking PRM-50-48 re application of research reactor regulations Action will assist research reactor side & comments confusion w/power reactor regulations RECHARDS,W.J. American Nucleur Society 53FR6159 00002 88/03/21 Dockoting & Survices Branch: 1p. 45020 001-45020 001

- 8803310250 Comments supporting polition for rulemaking PRM:31-4 re-inclusion of P:32 on in-vitro-gomeral liconses granted under 10CFR31.11(a) LASH.TR Illinos, State of SSFR2653 00003, 88703/21, Dockeling & Serv.cos Branch 2pp 44993.283-44983.284
- 89D4070048 Comment on potrion for retemaking PRM-31-4 to FR natice on polition for in vitre general scense General licenses should be defeted from regulations. FIAZEE, AJ Colorado, State of 52FR2653 00004 88/03/08 NUSSBAUMER, D.A. Assistant Director for State, Local & Indian Relations. 1p. 45022 131-45022 131.
- 8804070098 Commont supporting Univ of Missouri petition for rulemaking PRM 50-48 US Air Force than interest in establishing clear distinction between terms "research reactor," 8 "tusing reactor," http://disting.com/press
- 8804080173 Polition for rulemaking PRM 31-4 re addition of 160 mCi P-32 to in vitro general licensus specified in TOCFR31.11 P-32 should not be added to general license dun to listed reasons. NASHJID Floods, State of 53FR2853 00005 88703718 NUSSBAUMER D.A. State Local & Indian Tribo Programs, 4pp. 45063.148-45063-151

PROJ PROJECTS - PREDOCKET LICENSING

- 8803250248 Informs of NRC relocation to stated address Matting address unchanged A Adams project manager. RS Michaels back-up project manager. RUBENSTEINLES. Stendardzation & Non Power Reactor Project Directorate. 88/03/18. Althation Not Assigned 3pp. 44659-060-44659-062.
- 8804010187 Forwards safety evaluation of recommended mod to Rog Guide 1.76, "Dosign Briss Tornado for Nuclear Power Plants" NRC interim position constitutes conservative reduction of design basis winds for use by EPRI until rev available. RUBENSTEINL S. Standardzation & Non-Power Reactor Project Directorate 88/03/25. KINTNER,E E. ALWRI Utility Stearing Committee 2pp. 44949.003-44949.009.
- --8804010192 Safety evaluation re recommended mod to Reg Guide 1.76, "Tornado Dusign Bassa for Advanced Leght Water Reactor." Tornado design criteria in Table 2 acceptable on interim basis for advanced LWRs until reg guide revised. Office of Nuclear Reactor Regulation, Director (Post 870411) 88703725. Spp. 44040.005-44040.009.
- 8004010203 (Requests that new rept docketed under Project M-49 be redesignated as NOH 002 MCCONAGHY,W J. Nutoc, Inc. OUK.03 075 88/03/18 ROBERTS,J. Fuel Cycle Safuty (franch: 2pp. 44919:350-44019:360.
- 8004050256 Requests written response to comments & questions contained in 880309 lit.per 880317 & 18 meetings on fuel Issues & issues of graph to fire,augmentation of Amond 8 responses & reactor vessel performance,respectively.

 MORRISTUM Division of Regulatory Applications (Post 870443) 88/03/29 NULTON,D Energy, Dept of: 6pp. 44097 166-44997:171
- 8804050431 Forwards safety evaluation of Nuclear Assurance Corp rept. Hov. 2, "Top-ciil SARI for Nuclear Assurance Corp Storage/ Transport Cask for Use at ISFSI." Cask modis requirements of 100FR72. IODE:IFTS.J.P. Fucl Cyclo Safety Branch. 88703729. VIEBROCK,J.M. Nuclear Assurance Corp. 8pp. 45009:245-45009.333.
- --8804050433 Topical rept evaluation of Rev 2 to "Topical SAR for Nuclear Assurance Corp Storago/Trinspoil Cask." Rept acceptable.
 Office of Nuclear Material Safety & Safeguards, Oirector. 88/03/31. 63pp. 45000 251-45009 333
- 8804060148 fforwards propriotary Amend 0 to HTGR-86-024, "Proliminary Safety Info Document for Std MHTGR," addressing action Items & clantications from NRC/DOE 860317 & 18 mootings on subcotert areas identified in encl to Morris 860328 memo. WALKER,LP Gas-Cooled Rector Associates, 88704701, MCKNIGHTJ, WILLIAMS,P. NRC No Dotated Athitiation Given EL-ZEFTAWY,M.M. ACRS Advisory Committee on Reactor Safeguards 8pp. 45021-076-45021.083.
- 8804080166 Forwards draft "Process Control Plan For Deconfaminated Supernated Compant Splitdhication." Rowwo of oncl requested so as to be able to prepare final version well in advance of ratioactive operation scheduled for June 1988. BIXBY.W.W. Energy, Dept. of 29250 88/03/28. KNAPP.M. NRC - No Detailed Alfridation Given. 2p. 45/138/337-46/139/060
- -- 8804080100 WV()(1-087 DRFT Draft "Process Control Plan For Decontaminated Superintlant Comont Solidification."

 * Energy, Dopt of 88/04/30, 81pp, 45138 339-45139,060
- 8804110323 Forwards responses to Questions 36 & 40 in resolution of NRC comments to advanced LWR low temp everpressure protection requirements. KINTNETI,E E. General Public Utilifies Corp. GPU Service Corp. 88/03/28 RUBENSTEINL, S. Standardization & Non-Power Reactor Project Directorate, 5pp. 45077 334-45077.338
- 8804110332 Summarizos Rogion I Monitoring Team ropi on preoporational assessment of Weat Valley Domonstration Project,conducted during wk of 880104. CUNNINGHAM.R.E. Division of Industrial & Med cal Nuclear Safety (Post 870729) 88704704. CONGEL,F.J. Region 1, Ofc of the Director. 1p. 45077.360-45077:360.

- B804130401 Forwards SSR on Louid waste treatment sys Operation of Louid waste treatment sys as described in SAR will present no significant risk to public health & safety Fuel Cycle Safety Branch 88/04/06 BIXBY,W.W. Energy, Dept. of, Idaha Operations Office 2pp 45104.049-45104.096
- --8804130403 "SER on West Valley Damonstration Project Equid Waste Treatment
- 8804140151 Advises that papers presented on behalf of project at Waste Mgi. '88 in Tucson in early Mar will be received & forwards replis that have been published in open literature within last yr. BYXBY.W.W. Energy, Dept. of. 20198-88/03/23. HUATIR D. NRC No Detailed All'Ivalion Given. 2pp. 45119:001-45120:217.
- --8804140167 Speech entitled "Structural Thermodynamic Model for Durabilly & Viscosily of Nuclear Waste Grassas," presented at 871130-1205 meeting in Boston,MA, FENG.X., BARKATT,A. Catholic Univ. of America, Washington, DC 29198-87711/30 15pp 45119-002-45119-016
- --8804140177 "Influence of Waste Variability on Properties & Phase Stability of West Valley Rod Glass," progress rept for 851001-860930 MCP/ERSOND_ JOSEPHI, MATHURA West Valley Nuclear Services Co., Inc. 87/09/30 284pp 45119017-45119.301.
- -8804140185 "Ref Vitt callon Process & Equipment Description w/ Results From Checkout Testing: BARNES.S M., PETKUS L.L., MURAWSKI,T.F., West Valley Nuclear Services Co., Inc. 86/11/24, 23cp. 45119-302-45119-324
- --8804140192 "Preliminary Results of Durability Testing w/Boros licate Glass Composilions."

 ADEL-HADADI,M, ADIGA,R, BARKATT,A. West Valley Nuclear Services Co. Inc. 87/
 01/28 151pp 45119 325-45120 115
- -8804.140197 Draft "West Valley Strategy for Production of Qualified Waste Form." EISENSTATT, L.R., ROUTLIK R. West Valley Nuclear Services Co., fnc. 887/03/23, 10pp, 45120, 116-45120;125.
- --8804140200 "Three Yr Progress of West Valley Demonstration Project Vinfication Sys."
 BARNES,S.M., POPE,J.M. West Valley Nuclear Services Co., Inc. CHAPMAN,C.C.
 Batter'o Memorial Institute, Pacific Northwest Laboratories 88/03/23 (4pp)
 45120.126-45120.139
- --8804140206 "Overview of Waste Mgt Sys At West Varley Demonstration Project" MCINTOSH,T W., BIXBY,W W. Energy, Dept. of KRAUSS,J E. West Valley Nuclear Services Co., Inc. 88/03/23 (Dgp. 45120 140)-45120 149.
- --8804140210 "West Valley Glass Product Qualification Durability Studies Effects of Camposition,Redox State.Heat Freatment & Groundwater" REIMUS,M.A., PIEPEL.G.F., MELLINGER,G.B. Battello Momonal Institute, Pacific Northwest Laborationes 88/03/23, 21pp. 45120.150.45120.170.
- --8804140214 * Crystelization Rehavior of Fully Simulated West Valley Borosticate Glass "
 JOSEPH,I, MATHURA, CAPOZZI,C Alfred Univ., Alfred, NY, 68/03/23 10pp. 45120 171-45120 180
- --8804140218 "Process Model for West Valley Waste Vitrification."
 PEGG,I.L., FREEBORN.W.P., MACEDO,P.B. Cathoric Univ. of America, Washington, DC 88/03/23 13pp 45120 181-45120.193.
- -8804140224 "Composition Models for Viscosity & Chemical Durability of West Valley Related Nuclear Waste." FENG.X., SAAD.E.E., FREEBORN.W.P. Catholic Univ. of America, Washington, DC. 88703723 9pp. 45120 194-45120 202
- --8804140226 "Development of QC & Predictive Leach Tests for West Valley Glasses" BARKATT, A., ADIGA R., ADEL-HADADI, M. Catholic Univ. of America, Washington, QC, 88/03/23, 15pp. 45120 203-45120 217.
- 8804140422 Forwards request for addl info re Chapter 5, advanced LWR requirements document. Hesponse to encl questions & answers requested by 860426.

 LEECH.P.H. Standardzation & Non-Power Reactor Project Oirectorate, 88/04/04.

 KINTNER,E.E. General Public Utilities Corp. - GPU Service Corp. 10pp. 45118 073-45118 092
- 8804150037 Informs that author unable to continue as member of operational readiness Toylew board due to other commitments WALTER, H.F. Energy, Dept. of 29196 88/04/05 Energy, Dept. of 29p 45134 013-
- 8804150145 Provides initial response to 880127 questions on EPRI advanced LWR requirements document re implementation of public safety criteria PRA key assumptions & groundfules will be submitted in Sept 1988 to provide mere detail. KINTNER,EE. General Public Utilities Corp. GPU Service Corp. 88/04/06 RUBENSTEIN,L S. Standardization & Non-Power Reactor Project Directorate 4pp 45131:185-45131:188.
- 8804150231 Reguests comments on 880325 meeting its SAFR PRA & bounding events by 880515 Attendoe list & meeting summary enc).
 MORRIS,B M Division of Regulatory Applications (Post 8/0413). 88/04/11
 NULTON,D. Energy, Dept of 9pp 45149 012-45149 020
- 8804 180335 Forwards review status rept of advanced reactor severe accident program-topic papers Flow chart showing proposed method of handling topic papers enct. RUBENSTEINLS Standardzation & Non-Power Reactor Project Directorate 88/04/ 12. MAUCKJ, STEWAHTJ, ROSA,F. NRC No Detailed Alfelistion Given, 9pp. 45150 253 45150 261
- 8804 190354 Notices of NRC 880503-04 visit to plant to review activities underway re low level figurd waste treatment. Provisional agenda encl. BIXBY W.W. Energy, Dept. of. 29245-88/04/14 KNAPP,M. NRC No Detailed Affi-

- 8804200002 Provides supplemental response to NRC 871009 & 880204 tirs re supernatant treatment sys Matrix listing issues posed to assure that questions resolved or reguing additing dealt w/accordingly end.
 - during addl into dealt w/accordingly encl BXBY,W.W. Energy, Dept. of, Idaho Operations Office, 29192, 88/03/28, HURT,R.D. NRC - No Deta led Affration Given, 33pp. 45191,056,45191,088.
- 8804210448 Forwards request for addit into re Amend 12,Chapter 1 of Sys 80 + CESSAR-DC transmitted by 870911 itr.Requests into within 90 days of itr date. VISSING.G.S. Standardization 8 Non-Power Reactor Project Directorate 88/04/13. SCHERER,A.E. Combustion Engineering, Inc. 5pp. 45200-235 45200-238.
- 8804280138 Forwards controlled Rev 10 to Safeguards & Security Plan WVDP-006 Ack of recept requested by 880330 on encil form W/o encil BONENBERGER,D. West Valley Nuclear Services Co., Inc., 29217, 88/03/17. West Valley Nuclear Services Co., Inc., 29217, 88/03/17.
- 8804280275 Forwards comments on vendor 880119 & 0302 submitte's re CESSAR-DC Sys 80 + design Response requested within 45 days of lir date. RUBENSTEIN,L.S. Standardization & Non-Power Reactor Project Directorate 88/04/14, SCHERER,A.E. Combustion Engineering, Inc. 8pp. 45284-049-45284-058.
- 8804280454 Forwards ropt propared in response to requirement in House Ropt 97-177, summarizing status progress & expend tures of West Volley Demonstration Project for quarter ending 871231.

 BUNCH.DF. Energy, Dept. of 29246, 88/04/05 ROE,R A. House of Rep., Science, Space & Technology (formerly Science & Tochnology). 8pp. 45270 342-45270,349.
- 8804280481 Requests detailion of Ref 1 & Ref 4 on Pages 5-24 of SER before public release, based on licensee limited proprietary review AGARWALB K. FW Energy Applications, Inc. 24243, 88/04/18 ROBERTS, J.P. Firet Cycle Safety Branch. 2pp. 45253-011-45263-012.
- 8804280588 Discusses West Valley demonstration project tow level cement waste form West Valley Nuclear Svc 880411 supporting position that cement can be used as waste binder to produce acceptable waste form enci. BIXBY.W.W. Energy, Dept. of. 24247. 88/04/12, KNAPP,M. NRC No Detailed Alfilliation Grven. 10pp. 45283 078-45263 087.
- 8804280594 Commends DOE & consultants for highly informative well organized briefing presented on 880324 to Div of Low Level MgI & Decommissioning for West Valley waste coment solid-fication program.

 KNAPP,M R. Division of Low Level Waste Management & Decommissioning (Post 8704.13) 29244. 88704/13. BIXBY.W.W. Energy, Dept. of, Idaho Operations Office 3pp. 45263:070-45263:072
- 8804280658 Summary of 880414 meeting w/GE of United Kingdom & FW Energy Applications, Inc. in Rockville,MD re-site-specific implications of FW Energy Applications, Inc modular vau't dry store dosign topical repl. Attendance List encl. ROBERTS, J.P. Fuel Cycle Safety Branch. 3ρp. 45263-097-45263:099.

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

- 8803250320 Part 21 rept re worm gear component of Type H3BC valve actuators initially reported on 880317.4ll safety-related worm gear components will be subjic documented inspirentlying absence of casting procestly. MCOUILLAN, P.G. Limitorque Corp. PT21 88-018-000, 88/03/18. Otc of Inspection & Enforcement, Director (820201-870413), 6pp. 44961:199-44961 204.
- 8803290224 LER 67-070-03 on 871021,d scovered voltage regulator problem on emergency desail generator (D/G) 2A-A-Caused by refays in D/G output breaker closing permissive circuit Defective regulator repaired Also reportable per Part 21.W/880322 ltr.
 - LONG, J.L. Tennossee Valley Authority, 88/03/22, 5pp. 44921;144-44921;148.
- 8804060055 Part 21 rept re-failed Rosemount capacitive-type flow transmitters duting first cycle of operation Initially reported on 880324 Caused by loss of oil in sensor module. Affected transmitters replaced.

 MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).

 MROCZKA,E.J. Northeast Utilities. PT21 88-020-000, 88703/25 RUSSELL,W.T. Region 1, Oic of the Oirector. 3pp. 45034.188-45034:190.
- 8804080420 Part 21 rept re broken/cracked springs in plant pressure valves.Megnet/c particle exam of springs from 18 valves on Unit 2 performed in Jan 1988 & spring from valve 85 02693 rejected for linear indication insp completed. BRUNSON,B.G. Dresser Industries, Inc. 88/03/30. CILIMBERG,R t. NRC No Detailed Affiliation Given. 1p. 45077.254-45077.254.
- 8804070054 Discusses 880314 telcon clarifying interpretation of applicability of 10CFR21.Licensee products & services not unique to nuclear industry & may be excluded from scope of Part 21 suppl.irs.Part 21 can be satisfied upon request. LEMGRUBER,E., HUNTING K. Team, Inc. 88703/22. STONE,J. Vendor Inspection 8ranch 2pp. 45078-248-45075:249.
- 8804080225 Part 21 rept re inconsistencies in Gould Inc cartificate of compliance received w/Class 1E tuses procured from Planned Maint Sys due to fuses not being qualified for certain specs. Initially reported on 88032
- 8804080243 Supplements 871016 ltr re W-2 cell switch failure Recommends that switch operability be determined by continuity check of spare set of contacts whenever breaker is removed from connected position.

 JOHNSON,W.J. Westinghouse Electric Corp. NS-NRC-88-E300. 88/03/23.

 TAYLOR,J.M, NRC No Detailed Affiliation Given: 1p. 45064:231-45064:231.
- 8804110193 Part 21 rept re environ qualification of torque switches designed by Limitorque Corp.Initially reported on 880330. Design not qualification tested for nuclear safety-related svc.Untested forque switches will be replaced.

 ALEXICH.M.P. Indiana Michigen Power Co. (formerly Indiana & Michigan Electric Co.).

 AEP.NRC.0971E. 88/04/04. MURLEY, T.E. Document Control Branch (Document Control Desk). 4pp. 45135-105-45135:108.
- 8804120445 Forwards mailing list used for distribution of NRC generic communication,per licensee 880318 request. STONE.J.C. Vendor Inspection Branch. 88/04/07, MCQUILLAN,P.G. Limitorque Corp. 6pp. 45091:026-45091:030.

- 8804210136 LER 88 602-00 on 880323,trip breaker failed to open when reactor protection sys Channel D tripped Caused by armsture button improperly mounted due to mig defect supplied by GE-Maint procedure for trip breaker ravised W/880407 tr. RUTTER, ANDOGNINI,G. C. Secramento Municipal Utility District. GCA 88-223. 88/ 04/07 4pp. 45231:178-45231:181
- 8804210277 Part 21 & deficiency rept to damage to emergency diesel generator lacket water HX during flushing initially reported on 860917 HX repaired & installed in Unit 2. Thermostatic valves being modified.

 RICE,P.D. Georgia Power Co. GN:1439-88/04/14. Document Control Branch (Document Control Desk) 3pp. 45235:257-45235:259.
- 8804260147 Part 21 & deficiency rept reledge distance testing of Hitti kwik bolt Initially reported on 880314. Tests results of Hitti kept WENT-57-87-E Indicates that design calculations besed on EAMI recommended guidelines may be unconservative. POPARAD,C J Hitti Fastening Systems. PT21 88-017-000 88/03/18. MARTIN,R D. Region 4, Oic of the Director. 8pp. 45231:332-45232:004.
- -- 8804250151 WENT 57-67-E "Edge Distance Testing of Hilli Kwik-Balt" 1-Hilli Festening Systems, 88703/18, 26pp. 45231:338-45232:004.
- 8804270024 Notification of 880412 meeting w/Hilti in Rockville,MD to discuss Hilli 10CFR21 980318 notification re possible nan-conservative assumptions in EAMI recommended edge distance guidelines. BERLINGER,CH. Generic Communications Branch. 88/04/05. HOSSI,C,E. Division of Operational Events Assessment (Post 870411). 1p. 45243.243-45243-243.

QA999 QUALITY ASSURANCE INSPECTIONS

- 8804040034 Ack receipt at 880315 ftr informing NRC at steps taken to correct violations noted in Insp Rept 99901075/88-01 on 860222. STONE_JC. Vendor Inspection Branch. 88/03/29. HOOPER,M. Circleville Metal Works, 3pp. 44970.051-44970.053.
- 8804050134 Forwards Insp Rept 99900399/88-01 on 880224-25.No violations noted STONE.J.C. Vendor Inspection Branch. 88/04/01. GALKIN,I.S. American Insulated Wire Corp. 2pp. 45017;183-45017;189.
- --8804050142 Insp Rept 99900399/88-01 on 880224-25.No violations or nonconformances noted Major areas inspected mtg.test & QA records to verify implementation of proper control during phases of mtg of silicone rubber insulated cables. MOIST,R.N., POTAPOVS,U. Vendor Inspection Branch. 88/03/31. 5pp. 45017.185-45017:189.
- 8804060048 Ack receipt of NRC 880317 ltr.Response will be sent within 30 days. RUDIS,M.A. Rockwell Engineering Co., Inc. 88/03/24, STONE,J.C. Vendor Inspection Branch, 1p. 45073:341-45073:341.
- 8804060167 Summary of 880329 meeting w/B&W to discuss B&W OA logical rept Organization chart onct. SPRAUL_J.G. Quality Assurance Branch. 88/03/31. ROE_J.W. Division of Licensee Performance & Quality Evaluation (Post 870411). Spp. 45019:258-45019:263.
- 8804060382 Confirms 880326 telcon re Insp 99900100/88-01 scheduled for 880502-08 at Lynchburg.VA plant.Listed engineering issues will be discussed.Including environ qualification testing of current configuration of Peerless motors. STONE_JC. Vendor Inspection Branch. 88/04/04. DENHAM,F.K. Limitorque Corp. 3pp. 45074:148-45074:148.
- 8804120445 Forwards marking list used for distribution of NRC generic communication,per licensee 880318 request. STONE,J.C. Vendor Inspection Branch. 88/04/07. MCQUILLAN,P.G. Limitorque Corp. 5pp. 45091:026-45081:030.
- 8804140323 Requests that Circleville Metal Works Itr responding to Items of nonconformance noted during insplot febrication of LHRL-120 spent fuel transportation cask & NRC response itribe forwarded to Australian Dept of Transportation.

 STONE, J.C. Vender Inspection Branch. 88/04/04. REESE, D. Australia, Govt. of. 3pp. 45118:039-45118.045.
- --8804140348 Forwards Circleville Metel Works Itr to NRC describing corrective actions taken in response to items of nonconformance identified during insplot fabrication of LHRL-120 spont fuel transportation cask. STONE_JC. Vendor inspection Branch. 88/04/04. CHAPMAN,J. Australia, Govt of. 1p. 45118:042-45118:044.
- --8804140358 Ack roceipt of 880315 ftr informing NRC of steps taken to correct nonconformances noted in Insp 89901075/88-01. STONE,J.C. Vandor Inspection Branch. 88/03/29. HOOPER,M. Circle Seal Controls. 10. 45118:045-45118.045.
- 8804190024 Forwards Insp. Rept. 99900735/88-01 on 880307-11 & notice of nonconformance.Lack of control over nonconforming mall & Improper upgrading of mall indicates GA breakdown in listed areas. STONE, J.C. Vendor Inspection Branch. 88/04/15. GOIN,T.A. Southern Boll & Fastener Corp. 4pp. 45208:055-45208:069.
- --8804190027 Notice of nonconformance from Insp on 880307-11. Nonconformance noted:matt being upgraded for Westinghouse purchase orders lacked required number of tensile tests needed to meet ASME Boiler & Pressure Vessel Code.

 * Vendor Inspection Branch. 68/04/15. 3pp. 45208.059-45208.061.
- --8804190034 Insp Rept 98900735/88-01 on 880307-11.Noncompliance noted Major areas inspected QA program & Implementation.Including procurement program callbr sys.NDE program.neat treating program.upgrading of ASME matl & nonconforming item control.
 ABBATE.C.M., BAKER,E.T. Vendor Inspection Branch. 88/04/15. 8pp. 45208.082-4500.082
- 8804200242 Questions vendor survey necessity to support validity of certificate of conformance required of vendors of sld commercial products under nuclear OA program. LAMBERT,W.H. Cooper Bessemer Corp. OCG-4577, 88/03/31, PRESCOTT,P, NRC-NO Detailed Athilation Given. 1p. 45171:181-45171:181.

- 8804220148 Discussos review of 880115 ftr re 10CFR21 & applicability to items purchased for use in nonsately-related equipment Imposing App B of 10CFR50 for purchase of oquipment for use in nonsafety-related sys would not impose 10CFR21 STONE U.C. Vendor Inspection Branch 88/04/14 MARSH,R N. Flonda Power & L.ght. Co. 1p. 45109.211-45199.211.
- 8804270330 Ack receipt of 870327,0602 & 880414 ltrs informing NRC of actions taken to correct violations & nonconformaticos noted in Insp. Rept. 99901070/86-01 STONEUIC. Vondor Inspection Branch. 88/04/21. MCROBERTS,W.A. Ladish Co. 1p. 45041442-45041442 45241:143-45241:143

REGGD REGULATORY QUIDES

45000:112

- 8804010187 Forwards safety evaluation of recommended mod to Reg Guide 1.76. Design Basis Tornado for Nuclear Power Plants," NRC interim position constitutes conscribitor orduction of design basis winds for use by EPRI until rev available RUBENSTEIN,L.S. Standardization 8. Non-Power Resolve Project Directorate, 88/03/25 KINTNER,E.E. ALWR Utility Steering Committee 2pp. 44949.003.44949.009
- --8804010192 Safety evaluation re recommended mod to Reg Guido 1.76, "Tornado Dos gn Basis for Advanced Light Water Reactor." Tornado design criteria in Table 2 acceptable on inform basis for advanced LWRs unit reg guide revised.

 * Office of Nuclear Reactor Regulation, Director (Post 870411). 88/03/25 Spp 44949 005-44949 009.
- 8804040062 Provides justification for detetion of loss of offsite power (LOP) test as supplite 870831 submitted rolmod of initial test program. Reasons that LOP test not confluctorf at groater than 10% power stated VAN BRUNT, E.E. Anzona Nuclear Power Project (formerly Anzona Public Serv.ce Co.). 161-00887-EEVB/. 98/03/17 Document Control Branch (Document Control Dosk). 33pp. 44969.037-44969.069
- 8804050331 Forwards NEDO 31558, "Position of NRC Reg Guide 1,97,Rev 3 Requirements for Post-Accident Neutron Monitoring Sys."

 JANECEK, P.F. BWR Owners Group, BWROG-8817/BWR1, 88/01/01, MURLEY, T.E. Office of Nuclear Reactor Regulation, Director (Post 870411) 2pp 45028:183-45028:241.
- --8804050342 NEOO 31558 "Position of NRC Reg Guide 1,97,Rev 3 Requirements for Post- Accident Neutron Monitoring Sys."
 BWR Owners Group 88703/14: 575p. 45028:185-45028:241.
- 8804070202 Forwards responses to concerns raised by EGG-NTA-7277, "Conformance to Reg Guide 1.07," technical evaluation rept, per NRC 870904 request. FIEDLER,P B. General Public Utilities Corp. GPU Service Corp 88/03/30. Document Control Branch (Document Control Dosk) 12pp. 45074:267-45074 278.
- 8804070266 Forwards safety evaluation accepting util 840131,850510,9705 & 0802 sub-mittal re-conformance to post-accident monitoring instrumentation guidelines of Reg Guldo 1.07 ENGLE, 6 Project Directorate II-2 TAC 51110 88/03/31, STEWART,W.L. Virgin a Power (Virginia Electric & Power Co.), 1p. 45043/280-45043/263
- -0804070269 Safety evaluation supporting util submittals to conformance to post-accident monitoring Instrumentation guidalines of Reg Guido 1.97.
 Project Directorate II-2. GL-92-33 -08/03/31. 3pp 45043-261-45043-263.
- -- 8605300376 EGG-EA-6800 "Conformance to Reg Guide 1 97, North Anna Power Station, Units 1 & 2."

 UDY,A.C. EG&G Idaho, Inc. (subs. of EG&G, Inc.). FIN A-6483, TAC 51110, 88/02/28, NRC - No Dotailed Affiliation Gwen. 18pp. 45043 264-45043;281.
- 8804080045 Forwards Rev 6 to util position on Reg Guide 1.97 re display of Calonery 1 variables on SPDS in response to Generic Ltr 82:33. Changes incorporated in position rev based on NUREG-0737 & NUREG-1286 documentation.

 ANDOGNING C Secremento Municipal Utility District GL-82:33. 88/03/31.

 MIRGGLIAF J. Associate Director for Projects (Post 870411). 22pp. 45099.091
- 8804120090 Forwards suppl to consultants 880325 fir re review of diesel generators at plant. STELLO,V. Old of the Executive Director for Operations 88/04/06. ZECH, ROBERTS, BERNTITAL Commissioners. 1p. 45101:004-45101:008.
- -8804120105 Forwards supplite 880325 ltr re-plant desot generators. Suppliteplaces Item 4, "Teste on Diosel Generators" 8 claniles itr concerning tests required by Reg Guide 1.108. KUSKO, A., PEERAN,S.M. Failure Analysis Associates, 88/03/28. MARINOS,A. NRC No Detailuri Afilitation Givon. 2pp. 45101.005-45101.008.
- 8804120213 Requests that immediate emergency action be taken in form of order suspending full power operation of plant until remedial action can be taken. Basis for request is feture of unit to meet requirements of Reg Guides 1.9 & 1.10s.
 BATES,A.K. Natural Rights Center. BATES,A.K. Bates, A.K. 88/03/24. ZECH,L.W. Commissioners STELLO,V. Old of the Executive Director for Operations. MURLEY,T. Olice of Nuclear Reactor Regulation, Director (Post 870411). 2pp. 45091:262-45091:263.
- 8904120384 Responds to request for specific confirmatory into to permit NRC to complete review of application for amond to Tech Specs re-diesel generator fuel of sys in order to bring plant into conformance w/Reg Guide 1,137.
 GALLAGHER J.W. Philadeliphia Electric Co. TAC 47379, 88/03/30, BUTLER,W.R. Project Directorate I-2, Spp. 45091:155-45091:159.
- 8804130322 Forwards for Into notice of consideration of Issuance of amend to License NPF-21 & opportunity for hearing re 871223 to allow continued operation until fourth refuging outage w/o meaning requirements of Prev 2 to Reg Gude 1.97. SAMWORTH, R.B. Project Directorate V. TAC 66889, 88703729. SORENSEN.G.C. Washington Public Power Supply System. 4pp. 45103.182-45103:189.
- 8804130422 Forwards draft comments as followup to metal components subcommittee maying on 880210. Strongly enduses Rav 2 to Reg Guide 1.99.

 ODET FE,G R. California, Univ. of, Santa Barbara, CA. 88/03/10. SHEWMON,P. ACRS Advisory Committee on Roactor Salaguards. 14pp. 45117:303-45117:316.

- 8804140138 Sunmary of ACRS Subcommittee on Metal Components meeting on 690218 in Weshington DC re-review of Reg Guide 1.90, "Radiation Embattlement of Reactor Vessel Mails" & Burel on low llux embrit ement of reactor support structures.
 ' ACRS Advisory Committee on Reactor Safequards 88/03/17, ACRS Advisory Committee on Reactor Safequards 18pp 45120/238-45120/315
- 8804140215 Submits summary of actions discussed at ACRS 335th meeting on 880310-12 in Washington,DC including ACRS repts/ recommendations other actions, agreements assignments & requests & luture agenda KERR,W. ACRS Advisory Committee on Reactor Safeguards 86/03/24 ZECH,L.W. Commissioners 4pp 45118:172-45118.175
- 8804190336 Discusses Rev 3 to Reg Guide 1 97, which recommends that Category 2 instrumentation be installed. Previous commitment amended to propose use of existing atternate instrumentation to provide info on component cooling water flow. WHITTLERIG D. Mane. Yankes Atomic Power Co. GDW-88-86. 88/04/08 WESSMAN,R.H. Project Directorate I-3. 4pp. 45216.342-45216.345.
- 8804 190377 Ack recept of 880404 ltr informing NRC of steps laken to correct victations noted in Insp. Rept 50-326788 01 Position re cauty of emergency air sampling, air flow or voll melening devices stated in Paragraph C of Reg Guido 8.25. WENSLAWSKI, F.A. Reg on 5, Oto of the Director 88704/11 LILLYMAN, W.J. California, Univ. of, Irvine, CA, 1p. 45225 275-45225 280.
- 8804260014 Forwards Insp. Repts 50 445/88 22 & 50 446/88 19 on 880302- 0405 No violations of devaluons noted
 WARNICK,R.F. Old of Special Projects 88/04/20, COUNS'L,W.G. TU Electric (formerly Texas Utilities Generating Co.), 4pp. 45246 095-45248:113
- --8804260016 Insp Repts 50-445/88-22 & 50-446/88-19 on 880302-0405 No violations noted Weaknesses in training programs identified. Major areas inspected NRC bulletin followup monthly mant observation, fuel facetrit & storage & Reg Gurde 1 97 OA. BITTER, SD. BURRIS, S.P., WIEBELJ S. Otc. of Special Projects. 50-446/88-19. 887-04/20. 15pp. 45248-099-45248-113.
- 8804280231 Advises that qualification of replacement recorders & new instrumentation & control room pane's by seismic experience date allowed by IEEE-344-1987 & draft Reg Guide 1.100 acceptable,subj to line! safety evaluation DROMERICK,AW Project Directorale 1-4 88/04/20 FIEDLER,P.B. General Public Utilities Corp. GPU Service Corp. 2pp. 15266-318-45266-317.
- 8804280367 Forwards elfitient monitoring rept for Quivra Mining Co Ambrosia Lake NM mill for 870701-1231. Rept includes monitoring results for gaseous, particulate, direct radiation, soils, sodiment, vegelation & water, per Reg Guida 4.14. CLEVELAND, JE Quivra Mining Co. 88/02/24 GARCIA, P. Uranium Recovery Field Otc, R4. 1p. 45269.238.45269.339
- 8804290151 Forwards FR notice ack receipt of 880324 peblion & stating that peblion being treated per 10CFR2 206.
 EBNETERS D. Otc. of Special Projects. 2 206. 88/04/22, BATES, A.K. Bates, A.K. 1p. 45322.197.45322.200.
- --8804290184 Notice of receipt of petition for Director's Decision under 10CFR2.206 for Commission order suspending full-power plant operation until remedial action taken. Request for emerygency related den.ed Further action per 10CFR2.206 penang. EBNETER,S.D. Otc. of Special Projects. 2.208. 88/04/22, 3pp. 45322, 198.45322, 200.

REVIEW GRP NRC RESEARCH REVIEW GROUPS

- 8801270288 Forwards NRC response to 871110 ltr re NUMARC Tech Specs working group key implementation issues for restructured. Tech Specs Encl. documents NRC review of industry position on each key implementation issue. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411), 68/01/22, COLVIN,J.F. Nuclear Management & Resources Council (NUMARC) (formerly Nuclear Ultrity Manage. 1p. 44974.112-44974-126
- --8801270301 "NRC Response to NUMARC Tech Specs Working Group Key Implementation Issues for Restructured Tech Specs."

 ' NRC No Detailed Affiriation Given. 88/01/31, 14pp. 44974.113-44974.128
- 8803100162 Notification of 880310 meeting w/NUMARC & EEI in Rockville, MD to discuss activities re not perticles at nuclear power plants & need to accelerate issuance of appropriate revised guidance concerning topic CUNNINGHAML J. Radiation Protection Banch. 88/03/01 STORR JP. Drysion of Radiation Protection & Emergency Preparedness (Post 870411). 2pp. 44862:118
- 8604010066 Notification of 880331 meeting w/NUMARC, INPO & EPRI in Washington, DC to discuss status of industry program on motor operated valve per-ROSENTHAL, J.E. Reactor Operations Analysis Branch 88/03/28 NOVAK, T.M. Drvision of Safety Programs (Post 870413). 1p. 44950.337-44950.338.
- 8804010186 Notification of CRGR Meeting 132 on 880330 Agenda for meeting listed, JORDAN,E.L. Committee to Review Generic Requirements. 88/03/24. BERNERO,R.M. Office of Nuclear Material Safety & Safeguards, Director. PAPEFIELD,C. J. Region 3, Qic of the Director, ROSS,D.F. Office of Nuclear Regulatory Research, Director (Post 880720). 2pp. 44948 256-44948 258.
- 8804010187 Forwards safety evaluation of recommended mod to Reg Guide 1.76, "Design Basis Tornado for Nuclear Power Plants" NRC interim position constitutes conservative reduction of design basis winds for use by EPRI until rev available. RUBENSTEIN.L.S. Standardziation & Non-Power Reactor Project Directorate. 88/03/25. KINTNER.E.E. ALWR Utility Steering Committee. 2pp. 44949:003-44949:009.
- 8804060161 Notification of 880407 meeting w/NUMARC in Rockville,MD to discuss de-lais of ISAP II.Agenda encl.
 MILLER,M & Policy Development & Technical Support Branch (Post 870411). 88/03/ 29. THOMAS,CO. Policy Development & Technical Support Branch (Post 870411). 2pp. 45029.066-45029

- 8884130212 Partal response to FOIA request for documents Forwards App N docu monts to CRIGRI treatings App N documents available in PDR App O documents withherd in entirally (rof FOIA Exemption 5)
 GRIMSLEY,D.H. Division of Rufas & Records (Post 870413). 88/04/05. WEISS,E.R.
 Harmon & Weiss, 4pp. 45102-102-45102-125.
- --8602100002 Lists concerns on GDC 4 package for distribution to CRGR members during CRGR Meeting 84 DBA containment temp 8 pressure as function of break size should be reviewed. J Scritto comments to J Shiezak and ROSSDF Office of Nuclear Regulatory Research, Director (Pre 880720) 86/01/27. SCHWINK,W. Committee to Review Generic Requirements. 54pp. 45102:283-45102.323.
- -8609170458 Summary of CHGR Meeting 91 on 860723 re proposed ravs to 10CFR50.48 (ECCS rule).App K & related draft rog guide. Attendees list & supporting documentation encl. SNIEZEK J.H. Committee to Review Generic Requirements 86/09/09 STELLO,V Ofc of the Executive Director for Operations 90pp 45102 177-45102-282.
- --8609180240 Forwards summary to proposed genoric fit to BWR Licensees transmitting technical findings related to MSIV leakage & MSIV leakage control sys.Review re-resolution of Generic Issue C-8 scheduled for CRGR Meating 96 on 860917 TAYLOR,M.A. Regional Operations & Generic Regulæments, EDO (Pia 870413), 867-9912. BERNERO,R.M. Oli ca. cl. Nuclear Reactor Regulation, Director (851125-870411), 16pp. 45102 140-45102 176
- -8804130258 Forwards summary & issue identification for CRGR Meeting 98 on 861046 re-proposed deferred plant policy.

 POLK,P.J. Regional Operations & Generic Requirements, EDO (Pro 870413), 867107-01 BERNERO,RM Duvision of Boting Water Reactor (BWR) Licensing (851125-870411) STAROSTECKIR Div. of Emergency Preparedness & Engineering Responso,(E(650212-870413) CUNNINGRIAM,RE Division of Fuel Cycle & Material Safety (Pre 970413), 4pp. 45102-136-45102-139.
- 8804130369 Notification of CRGR Meeting 133 on 880413 to review stated items, including proposed Commission papear on key policy issues resulting from NRC statt review of DOE sponsored advanced reactor concepts Review packages encl W/ o encis JORDANIE I. JORDAN,E.I. Committee to Review Genoric Requirements 88/04/05 BERNERO,R.M. Office of Nuclear Material Safety & Safeguards,Director PAPERIELLO,C.J. Region 3, Oto of the Director, ROSS,D.P. Office of Nuclear Regula-tory Research, Director (Post 860729), 2pp. 45104/044-45104.045
- 8804140361 Summary of CRGR Meeting 130 on 880309 re proposed draft resolution of USI A-40, "Scismic Design" & proposed generic lit that would aflow licensees to remove organization charts from plant Tech Spocs W/o end's JORDAN,E.L. Committee to Review Generic Requirements 88703723. STELLO,V. Old of the Executive Director for Operations. 2pp. 45118-080-45118-061.
- 8804140425 Forwards detailed plans for Chernobyl followup tasks to be managed by Dv of Operational Events Assessment in response to 871203 request ROSSI.C.E. Division of Operational Events Assessment (Post 870411) 88/04/05. STOHR.J.P. Division of Radiation Protoction & Emergency Preparedness (Post 870411) 8pp. 45118 088 45118 095.
- 8804160035 Notification of CRGR Meeting 134 on 890418 to review proposed generic litr, "Individual Plant Exams for Severe Accident Vulnerabrities." W/o stated encis JOFIDAN, E.L. Committee to Review Generic Requirements 88/04/05. BERNERO, R.M. Office of Nuclear Material Safety 8 Safeguards, Director PAPERIELLO, C.J. Region 3, Ofic of the Director, ROSS, D.F. Office of Nuclear Regulatory Research, Director (Post 860720), 2pp. 45134:011-45134.012.
- 8804150261 Summary of 880317 meeting w/NUMARC,EPRI & INPO re industry status of prosicn/cc rosion.List of attendeds & viewgraphs encil MCCRACKEN.CE. Chemical Engineering Branch. 88/04/06. RICHARDSON,J.E. Assistant Director for Engineering. 15pp. 45139.067-45139.081.
- 8804180429 Summary of 880407 moeting w/NUMARC in Rockville,MD re-proposed ISAP IRList of attendees enct.
 MILLER,MA Policy Development & Technical Support Branch (Post 870411), 88/04/11, THOMASCO, Policy Development & Technical Support Branch (Post 870411), 45p. 45165 270-45165 273
- 8804180433 Forwards NAS rept entitled, "Human Factors Research & Nuclear Safety," for comment RES in process of developing human factors research program plan that describes research NRC plans to carry out in area ever next severally is. BECKJORD.F.S. Office of Nuclear Regulatory Research, Director (Post 660720) 887-03729 LEE,B R. Nuclear Management & Resources Council (NUMARC) (formorly Nuclear Utility Manage. 1p. 45149.225-45149-225.
- 804180463 Summary of 880406 meeting w/NUMARC.ut is, Science Applications, inc, EPRI, Sandia, Trident Enginecting & Devortue in Rockville, MD resemble generator reliability programs SERKIZ, A.W. Reactor & Plant Satety Issues Branch. 88704/12 KNIEL, K. Reactor & Plant Safety Issues Branch. 165pp 45150-074-45150:230. 8804180463
- 8804190050 Final response to FO/A request for documents on NRC/IDCOR meeting on 870910 re individual plant evaluation Forwards documents listed in App 8.Apps A & 8 documents available in POR App C documents totally withheld (ref FO/A Exemption GRIMSLEY,D.H. Owision of Rules & Records (Post 870413) 88/04/13. SHOLLY,S.C. MHB Technical Associates, 11pp. 45158.314-45158:262.
- --8609190081 Forwards preliminary review of IDCOR 860502 draft, "Individual Plant Exam Methods (IPEM)," IPEM has potential to be effective alternative for individual Plant exams Areas needing add info or mods listed

 SPEIS.T.P. Division of Safety Review 8 Oversight (851125-870411), 86/09/03, BUHL.A. Industry Degraded Core Rulemaking Program 41pp 45158.197-45158.237.
- --8804190060 Forwards response to NRC comments on individual plant evaluation methodology, per 880909 request Revised version of methodology will be provided by middle of Dec. BUHL, A.R. Industry Degraded Core Rulemaking Program BUHL, A.R. International Technology Corp. 86/12/10. SPIES, T.S. Division of Safety Review & Oversight (851125-870411), 46pp. 45156-325-45157,010.

- -- 8804190069 Forwards response to BNL comments on IDCCR model of Mark I con lanmont response to direct contact w/mollen core debris

 8UHLAR Industry Degrated Core Rutemaking Program BUHLAR International
 Technology Core 87/07/09 BECKJORDE S Office of Nuclear Regulatory Research,
 Director (Post 860720) Bpp. 45157.011-45157.018
- --8804190077 Forwards revs to iDCOR individual plant evaluation PWR sys methodology PWR sys methodology considered to be final w/ integration of revs BUHLIAR industry Degraded Core Rutemaking Program BUHLIAR International Technology Corp. 87703709 SPEIST P Division of Safety Review & Oversight (851125-870411) 496pp. 45157.019.45158.196
- 8804190057 Submits agonda of CRGR Meeting 133 on 880413.W Morris will present BU4190057 Submits agonds of CHR4 Mothing 133 on 880413.W Moths will present proposed Commission papers on advanced reactor designs E Rossi will prosent proposed suppris to IE Bullatins 85-003 & 87-002 W/o encis

 JORIAN E L Committee to Review Generic Requirements. IEB:85-003 88/04/11

 BEHNERO, R.M. Office of Nuclear Material Safety & Safeguards, Director PAPERIELLO, C.J. Region 3, Ofc of the Director, ROSS, D.F. Office of Nuclear Regulatory Research, Director (Post 860720) 2pp 45158 275-45158 276
- 8804200473 Partial response to FOIA request to life protection Forwards App E documents App B & E documents available in PDR App F document completely withheld (ref FOIA Exemption 5).

 GRIMSLEY, D.H. Division of Rules & Records (Post 870413). 88/04/14 JONES, C.R. Affriation Not Assigned Spp. 45206.037-45206.043
- --8804200526 Summarizes differences which exist between fire protection requirements applied to near-term CL & operating reactors, per NUREG-0800,SRP 9.5.1. CONLCR, T.E. Fire Protection Review Group 84/11/07, ROSA, F. Fire Protection. Flev.ew Group 16pp 45206-154-45206 169
- 8804210482 Summary of 880127 CRGR Meeting 128 re-listed items.inc'uding review of proposed generic fit to inform licensees of new NRC position on guidelines for determining whether operating basis earthquaked Tims exceeded. JORDA41,E.L. Committee to Rev.ew Generic Requirements. 88/04/04. STELLIO,V. Ofcic file Executive Director for Operations. 2pp. 45192,199-45192,200.
- 8804270040 Forwards Regulatory History AC12-1 re proposed rolo 10CFR34, "Safety Requirements for Industrial Rachographic Equipment" NELUSDO Radiation Protection & Health Effects Branch 53FR8460 88/04/13 EXUM.P Document Control Branch (Document Control Desk), 15pp 45356353
- --8804280279 Summary of Radiography Steering Committee meeting on 850808 in Silver Spring MD re Wostern Stress rad ography incident in State of WY. CHAPELL.D.R. Steering Committee on Radiography Safety AC12.1 32 85/09/11. NRC- No Detailed Affiliation Given 3pp 4535/077-45357 079
- --8804280583 Requests endorsement for issuance of reg guide for design sids for radi-ography equipment Reg guide would be essentially same as proposed amend to 10CFR34 RES will proceed whappropriate task in teation it committee agrees MALARO.J.C. Office of Nuclear Regulatory Research, Director (Pro 860720). AC12-1 42. 81/10/19. CARTER,T.F. Steering Committee on Radiography Safety. 2pp. 45357:105-45357.108

SECY POSITION PAPERS BEFORE THE COMMISSION

- 8802170361 SECY 88 043 Recommends that final rule amending 10CFR0 & 2,revising agency procedures governing ax partic communications & separation of functions be issued. PARLER, W.C. Office of the General Counsel 88/02/11, 65pp. 44974 127-44974 191.
- 8802190122 SECY-88-033 Recommends that Commission approve mod to enforcement policy re reopening of closed enforcement cases & publication of mod. STELLO, V. Ofc of the Executive Director for Operations 88/01/29, 22pp. 45043-289-45043:308
- 804110248 SECY-88-075 Commission paper providing annual summary of examilicansing 8 requal licehon activities for reactor operators & sonior reactor operators.W/880404 release memo STELLOV. Oto of the Executive Director for Operations, 88/03/10, 14pp. 45078,341. 45078 354
- 8804140222 Final response to FOIA request Forwards App A document App B & C documents partially & completely withheld, respectively (ref. FOIA Examption 5). App A & portions of App B documents available in POR Requester will be billed stated amount GRIMSI EY, D.H. Division of Pules & Records (Post 870413) 88704/08. ASHBAUGH, C.E. Nuclear Theory & Tochnologies. 5pp. 45150 023-45150.069.
- --8804140243 Partially withheld Commission paper informing of NRC plans to hall distribution of radioactive going from domestic & foreign reactors to unicensed persons in US Olc of General Counsel has no legal objection STELLO.V. Olc of the Executive Director for Operations. 87/07/28.
- --8804150339 SECY-87-188A Partially withhold paper recommending position NRC should take no distribution of radioactive gems irradiated in reactors to unlicensed per-STELLO,V. Ofc of the Executive Director for Operations, 87/10/05, 31pp. 45150.039-45150.069
- 8804270040 Forwards Regulatory History AC12-1 re proposed rule 10CFR34, "Safety Requirements for Industrial Radiographic Equipment."
 NELLISD O. Radiation Protection & Health Effects Branch. 53FR8460, 88/04/13, EXUM.P. Document Control Branch (Document Control Desk) 15pp. 45356353-45357.011
- --8804280649 SECY-76-146 Responds to Chairman request for review of current level of protection associated w/portable radiography units per personnel overexposuree.Forwards appropriate recommendations for changes in NRC regula-MINOGUE, R.B. Office of Standards Development, Orroctor AC12-1 51, 76/03/15, 2pp. 45357-127-45357:128.

- ~8804280645 SECY-77 034 Responds to Charman inquest for staff to prepare coold nated MRC action plan for remorbying problem of rad agrephy overexposures. MRFOGUE R.B. Office of Standards Development. Director. AC12:1-50-77701725. Ip. 45357 124-45357.
- -8009190791 SECY-80 324 Discusses now program to improve radiation safety in industrial ratiography operations D.HCxS.W.J. Office of Nuclear Mareral Safety & Safeguards, Director. AC12+1-53, 607, 07709, 6pp. 45357, 135, 45357, 140.
- --8804280139 SECY-86 197 Provides Commission w/info relstatus of efforts to implove safety in industrial radiography operations
 STELLOV Old of the Executive Director for Operations AC12-1 28 86/07/02 6pp
 45367-061-45357-066
- --8802170349 SECY-89 010 Requests Commission approval for publication of proposed amends to 10CER34, "Safety Requirements for Industrial Radiographic Equipment," Amend will require safety performance stids for ratiographic equipment STELLQ,VIOIr. of the Executive Director for Operations. AC12-1:05 (88701713) 5pp. 45357:012-45357:016.

STATE PROG STATE PROGRAMS

- 8803080496 Reviews Third Quarter 1987 rept for Sequipyah Fuels Ccrp O Sand In Situ Leach R&D project
 JCHNSCN,S. Wyoming, State of 88/01/25, Wyoming, State of 15pp, 44639,037-
- 8803300431 Ack recept of 871203 response to NRC comments & recommendations following 1987 review of Statu of GA radiation control program & Hir 871217 in NRC pleased w/ positive actions state implemented in NRC comments KAMM-RERIC. State, 10.41 & Indian India Programs 88703728 LEG3ETTER, J G Georga, State of 16, 44967 245-44967 245.
- 8803310128 Notifies of 880318 meeting w/DCE in Reckvile,MD to discuss DCE 880120 responses to NRC request for additinfo on DOE NVO-196-17-8 NNWSI SOP-02-01 QA documents & responses to 871009 request for into reitos Alamos Nati Lab OA płan YOUNGBLOOD,B J. Operations Branch (88/03/03 LOUX R.H. Nevada, State of 2pp

44967 327-44967 328.

- 8804040076 Notifies of proposed use of softum bromde in addition to softum hypochloride in ERGW sys to control bigfouling Use of thromate reduces total residual chloride in a data in compliance w/NPDES parmit falso on products being considered enci BROOKS,R.H. Tennessee Variey Authority 88703730 SINCLAIRIRM Tennessee, Statu of 98pp. 45031,321-45032,058
- 8804060161 Respects to Leensee 880307 ftr re-disposal of water from washing & de-contamination of plant titig at Collins Draw No objection raised against disposal of wash water into spit contaminant sump pump provided no discharge outside pond, WAGNERUF Wyoring State of 88703717 AHO.6 0 Clevetand-Clifs Iron Co. Ip. 45019 257-45019 257.
- 8804060448 Confirms recent tolcons re NRC visit to pro review State of OR ratiation control program for mat's acheduled for 880502-03 to assess status of program & discuss topics of mittual concurn HDRN:27.3 PARIS,RID Oregen, State of tp 45010 215-45010 215.
- 8804070046 Comment on publich for rulemaking PRM:31-4 to FR holico on politich for in vitro gondraf ficensu General licenses should to defeted from regulations. HAZLE, A J. Colorado, Siato of S2FR2053 00004 88703708 NUSSRAUMER, D.A. Assistant Director for State, Local & Jodan Hollabons, 1p. 45022 131-45022 131.
- 8804070145 Requests that iconsec provide inspile enforcement records to hyproduct mathiconse proviously issued by State of CO for which JL Sager was principal per Sager 880420 application for NRC hoose to perform industrial radiography. CAIN.CL. Region 4, Oto of the Director 88/03/31, MATTSON,C Colorado, State of the 45001-006-45031:008
- 8804110324 Requests NRC support in obtaining FCC authorization for additiratio frequencies for two major communication interevolent projects Projects involve both omergency response 8 normal plant operations. WILLIAMS,RO Puthic Service Co. of Colorado P-89092, 88709709 MARTIN,R D. Region 4, Clc of the Director 3pp. 45129:054-45129.357
- --8804110327 Requests fit supporting request to FCC stating necessity to conduct re-modal chill as seen possible after equipment installation & operator training Special temporary authorization neceded until Leansi is received. BYRNE, IP Colorado, Stato of 88703701 MARTIN,RID. Region 4, Ote of the Director Up 45129 357-45129 357.
- 8804120412 Notifice of informativist scheduled for 880502-06 to assess status of Stato of OR rad ation program for Agreement mails HORNOR, J.W. Rogion 5, Old of the Director, 89/03/24 PARIS,R.D. Gregon, State of 1p. 45090 352-45090 352
- 8804130083 Ack receipt of 880202 lif transmitting ropt entitled. "Concopiust Considerations of Doath Velley Groundwater Sys W/Special Emphasis on Adequacy of Sys to Accommodate High Lovel Nuclear Waste Repostary." by JZ Szymanski DOE KAMMERIFER.C State, Local & Ind an Into Programs 88702/19 LOUX,R R. Noveda, State of 1p 45100 025-45100 028
- 8804130303 Advises that State of ME has no objection to Proposed Chango 137 to Toch Spec 5 2 SCHELL,R.J. Maine, State of 88/14/07, Document Control Branch (Document Control Desk). 1p 45154 071-45154 071
- 8804130358 Responds to 880212 lit resting number of concerns to plant. Decision to permit restart will not be made until Commission convinced that provious problems corrected & that operation of facility in soft manner assured. ZECILL W. Commissioners. 88/04/07. SCHAEFER.W.D. Maryland, State of 5pp. 45412 351-45412 355
- --8802250098 Discusses issues surrounding facility State of MD has no formal standing in roynew process NRC should identify specific distart chlena SCHAEFER,W.D. Maryland. State of G-94 88/02/12 ZECH,L.W. Commissioners 3pp. 45412-358-45412-358.

- 8804140450 FOIA inquest for all concurrence sheets drafts revs. annotated copies. 8 and documents re. SECY-82-414 as well as Commission Request CCMJA-82-6 contained in SECY-82-414. WEISSMAN,S. Carlomia, State of 88702709. GRIMSLEY,DH. Dws on of Rules. 8.
- Records (Post 870413) 1p. 45130.149-45130-149
- 8804180185 Advises that inclusion of Cirifor Atmospheric Chemistry Studies in energency plan for reactor unnecessary due to bldg lying outside of 6PZ boundary Safety uvaluation supporting inclusion 871:100 response on DIMEGLIO, A.F. Rhode Island, State of 6pp. 45149 303 45149 310
- 8804180288 FO'A request for listed documents including all concurrence sheets,diatis & roys of SECY 81-636 SECY 81-6368 & H Donlon 811119 ftr WEISSMANS, Childron's, State of 18702708, CRIMSLEY,D.H. Dwsori of Rules & Records (Post 870413), 2pp. 45149-354-45149-355.
- 8804180297 Partial response to FOIA request App. A documents totally withheld (ref. FOIA Exemption 5) Documents subj. to Category Filed from the tween N Brown & Hotmus. GRIMSLEFUR H. Division of Rules & Records. (Post 870413) 88704/12 WEISSMANS, California, State of 3pp. 45149,356,45149,358.

- 8804190304 Notifies that nuthor appointed as onsite coordinator for state to oversee remedial obstruip activities at Cotter U mill site located near Canon City.CO STORREY.P. Colorado, State of, 88704706 MARTIN,R. Region 4, Ote of the Director by 45217.264-45217.264
- 8804190305 Ack receipt of 880328 fit requesting time on 880422 to discuss NRC 1988 fevilaw of radiation control program for agreement malls Meeting scheduled on 880422.

DERNSTEINR. Texas, State of 68/04/07 MARTIN,R-D. Region 4, Old of the Director up 45216:358-45216.358

- 8804 190306 Responds to riolice of violation of Paragraph 3.3 of Tech Spocs at time of insp.Corective actions restrictive areas of both C.&. D decks roped cff & door from access trink affixed w/fock,chain & seal & warning signs posted WALDROP-C.G. South Carolina, State of 88/04/13. Ducument Control Branch (Document Control Deck), 2pp. 45216 359-45216:360.
- 8804200134 Confirms 880129 discussion re-roview of State of TN regulation control program Comments re-technical aspects of program explanation of policies & practicus for recovering Agrooment States program and:

 KAMMERERIC State, Local & Indian Tribe Programs 88/04/15 WORD.JE Tennassee, State of 6pp. 45226 190-45226:195
- 8804200192 Informs that State of ME has no objections to util Proposed Change 138 to Tech Spec 1.3 to increase max nominal fuel enrichment to 3.7% U.235 per 10CFR50.31(b) SCHELLRJ. Maine, State of 88/04/07 Document Control Branch (Document Con-trol Desk). 1p. 45177;194-45177;194
- 8894210335 Requests concurrence in subjidesign criteria so as act to interfere w/operalion of reactor facility exhaust stack D'MEGLIO, A.F. Ahoub Island, State of 88/04/12 MICHAELST'S Standardization & Non Power Reactor Project Directorals 2pp 45194:259-45194 260
- 8804220 155 FCIA request for outstanding items list for restart of Pigrim Nuclear Power Station in Plymouth, MA GOLDEN, W.B., Massachusetts, Commonwealth of 188/02/11, Region 1, Ofc of the Di-
- rector 1p 45201 160 45201.160.
- 8804220169 Final response to FOIA request for outstanding items list of open NRC insplicins for restart of Prigrim nuclear power Station Forwards App A document.App A document also available in PDR GRIMSEEV.O Division of Rules & Records (Post 870413) 88/04/19. GOLDEN,W.B Massachusutts, Commonwealth of 2pp. 45201;161-45201;169
- 8804270040 Forwards Regulatory History AC12-1 re proposed rule 10CFR94, "Safety Regulatoris for Industrial Had ographic Equipment."
 NELLIS,DIO Radiation Protection & Health Effects Branch 53FR8460, 88/04/13 EXUM P. Dacument Control Branch (Document Control Desk) 15pp. 45358:353 45357 011
- --8805030139 Concurs w/preposed changes to 10CFR34 re-industrial radiography safety requirements BLANTONR L. Anzona, State of AC12-1 63 87/03/03. NUSSBAUMER.D.A. Assistant Director for State Agreements Programs, 1p. 45357
- -8805030121 Concurs w/proposed amends to 10CFR34 to include safety performance requirements for radiographic exposure clowices 8 to require radiographers to wear downnotes Exportences will use of 29th Model 504 digital alarm dosimuters listed HILL T.E. Georgia, State of, AC12-1 61, 87/02/13, NUSSBAUMER,O A Assistant Director for State Agreements Programs 1p. 45357.043-45357.043
- --8804270218 Cencurs in proposed rulemaking for safety performance stds for radio-graphic exposure dovices & requirement of wearing pocket afairm dosimeters Agreement State comments erict. NUSSBAUMER,D.A. Assistant Dractor for State Agreements Programs. AC12-1-20. B7/03/11 NELUIS,D.O. Safety Research Application Branch 2pp 45357:041-45357-041
- -8805030128 Concurs w/proposed additions to 10CFR34 to require safety performance side for radiographic exposure devices & radiographiers to wear pocket alarm dos-TRIGGES EURE, JA. Towa, State of, AC12-1-62, B7/02/24, NUSSBAUMER, D.A. Office of State Programs, Director (Pro 870413), 1p. 45357.044-45357.044
- --8804270248 Recommends adoption of Alternative 3 re proposed changes to 10CF H34 re industrial radiography safety requirements Old wholeheartedly endorses proposed changes as beneficial to industry TOPPAN, W.C. Mane, State of AC12-1 21, 87/02/10 Docketing & Services Branch 1p. 45357.050-45357.050.

- --8805030170 Offers no comments re proposed changes to 10CFR34 re-industrial radiography sately requirements in response to NRC 870115 lir. Changes should be adopted a implementable as written BORCHERT.HT Nebraska, State of AC12-1 86 87/03/06 NUSSBAUMER,D A. Assistant Director for State Agreements Programs, 1p. 45357,048-45357,049.
- --8805030070 Offers no further comments on proposed changes to 10CFR34 re industrial rad ography safety requirements Concurs w/ inclusion of safety requirements for radiographic exposure devices § for radiographies to wear alarm desimplers SHEALY.H.G. South Carolina, State of ACT2+1.60. 8/7/02/02. NUSSBAUMER,D.A. Assistant Director for State Agreements Programs. 1p. 45357.042-45357.042
- **8805030151 Responds to NRC 870115 ltr to all Agreement States re proposed changes to 100FR34 re-sately requirements for rad activo exposure devices & requirement for rad ographions to wear alaim dostinations.
 FRAZEE,T.C. Washington, State of AC12-1 64 87702/27 NUSSBAUMER,D.A. Assistant Director for State Agreements Programs 1p. 45357:046 46357.048
- 8804270303 Responds to 800321 ftr to Zech expressing concerns to SMUD ability to operate facility w/o adversely affecting health & safety of general public in view of referentiums schedulfed to apppear on 806607 better to SMUD ratepayers MURILEY,T E. Office of Nuclear Reactor Regulation, Director (Post 870411). 86/04/18 CONNELLY,I. G. California, State of, 8pp. 45286-161-45266,170
- --8804270308 Request that restant of facility before 880607 be evaluated sofely on public safety considerations by NRC CONNELLYL G. Carifornia, State of 88703721, ZECH,L.W. NRC No Detailed Affiliation Given 2pp. 45266
- 8804280310 Requests inclusion of State of NM environ improvement dividentions in any actions portaining to I consing changes Need for advice & consent prime in divinterest of activities in low lever wastes affecting State of CO.
 JONES,K. New Mexico, State of 88703724 SMITH,D. Uranium Recovery Field Otc, R4. 1p. 45262 347-45262:347.
- 8804280508 Forwards hazardous waste notification form 8 hazardous waste stream repts for two waste streams generating mixed waste as defined by NRC/EPA guidolinestin response to DS Hale 880307 into 8E Knight. LONG.JA Nuclear Fuol Sonuces, Inc. (subs of Getty Oil Co.), 21G-88 0032, 86/04/15, HALE,D. Tannossae, State of .9pp. 45271 045-45271 053.

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

- 8709300402 Responds to request for review & comments on whether or not technically acceptable increed containment sys could satisfy provisions of 10CFR50 44(g).NRC awaiting plant-specific submittals on compliance.pdr 870120 meeting DORIAN,T.F. Assistant General Counset for Rulemaking & Fuot Cycle. 87708/31. JANECEK,R.F. BWR Owners Group JANECEK,R.F. Commonwealth Edison Co. 2pp. 452323254 45323255. 45722 355 45322 360
- --8804290166 Requests review & comment re-scope of Paragraph 50.44(g), whether technically acceptable inerted containment sys could satisfy provision of Paragraph. JANECEK,R.F. BWR Owners Group JANECEK,R.F. Commonwealth Edison Co. BWRCG 8737, 87/06/23, DORIAN,T. Office of the General Counsel 4pp 45322:357-
- 8803290300 Forwards proprietery & nonproprietary Rev 0 to WCAP-8587, "Equipment Ouelification Date Package ATWS Mitgating Sys Actuation Circuitry (AMSAC) in Std Seismic Cabinot." Alfedavit entil Proprietary ropt withheld (set 10CFR2.790). MAUMAN, D.A. South Carolina Efectric & Gas Co. 88/03/24. Document Control Branch (Occument Control Desk). 20pp. 44916:193-44816.236.
- --8803290305 Regrosts that Proprietary Rev 0 to WCAP-6687, "Qualification of ATWS Millgating Sys Actuation Circuitry in STD Seismic Cabinet" be withheld from public disclosure (rol 10CFR2 790).
 WIESEMANNIR A Westinghouse Electric Corp. CAW-88-021, 88/03/21, MURLEY,T. Olince of Nuclear Reactor Regulation, Director (Post 870411), 9pp. 44916-213-44016-213 44916:221.
- --8803290306 WCAP-6587 R00 Nonproprietary Rev 0 to WCAP-8587, "Equipment Qualification Data Package, ATWS Mitigeting Sys Actuation Circultry (AMSAC) in Std Seismic Cabinot."

 RYGG, DE. Wostinghouse Electric Corp. EOOP-ESE-68A. 88/02/28, 17pp. 44916:222-44016:236.
- 8804010123 Corrected transcript of 880224 BWR MARK I containment info exchange workshop in Baltimore,MD,Pp 1-161.Supporting documentation enci. * NRC No Detailed Attillation Given. 88/02/24, 429pp, 44951;154-44952;222.
- 8804010160 Notification of 880329 meeting w/Westinghouse in Rockville,MD to discuss mods to Vantage 5 fuel.

 COLLINS,T.E. Reactor Systems Branch. 88/03/25, HODGES,M.W. Reactor Systems
 Branch. 2pp. 44949-018-44949-020.
- 8804010165 Notification of 880406 meeting w/Westinghouse in Rockville, MD to discuss Wostinghouse BWR code, "Blson," Agenda enci. KATZE,D. Reactor Systems Branch. 88/03/29. HODGES,M.W. Reactor Systems Branch. 2pp. 44949.028-44949.029.
- 8804010203 Requests that new rept docketed under Project M-49 be redesignated as NUH 002 MCCONAGHY,W J. Nulec, Inc. DUK-03-075, 88/03/18. ROBERTS,J. Fuel Cycle Selety Branch. 2pp. 44919:359-44919.380.
- 8804010234 Forwards list of all util engineering calculations associated w/TDI diesel generators developed after 880222.
 CROLEY.B.G. Sacramento Municipal Utility District. AGM/TA 88-101, 88/03/24.
 MIRAGLIA.F.J. Associate Director for Projects (Post 870411). 2pp. 45031:150-45031:161.

- 8804010251 Forwards Vo's I-III of CEN:369(V), "Reciprocating Charging Pump Test Rept" & CEN:370(V), "Charging Pump Gas Binding & Cracked Block Evaluation Rept." per Condition 3 a of License NPF-51 & 851129 commitment VAN BHUNT,E.E. Anzona Nuclear Power Project (formerly Anzona Public Service Co.), 161-0845-EEVB7, 88703/02 Document Control Branch (Cocument Control Desk) 2pp. 45015.191-45016-172.
- --8804010257 CEN-370(V) "Charging Pump Gas Binding & Cracked Block Evaluation Repl * Combustion Engineering, Inc. 88/02/28, 62pp. 45015.193-45015.255.
- --8804010269 CEN:369(V) Vols I-III of "Reciprocating Charging Pump Tost Rept." Combustion Engineering, Inc. 88/02/29, 277pp. 45015-256-45016.172.
- 8804040145 Forwards Suppl 2 to A98-ATOM Topical Rept TR UR 85-225 A, "A98-ATOM 8WR Control Blades for US BWRs" for NRC approval & Rev 1 to Rept UR 87-102, "ASEA-ATOM Control Rods for BWR 2/3/4/5/6 Svc "Fee paid TENERZ.E. ASEA Atom, Inc. B 88-088, 88/03/18 MURLEY,T Office of Nuclear Re-actor Regulation, Director (Post 870411) 2pp. 44970.311-44970.346
- --8804040154 Suppl 2 to Topical Rept UR 85-225-A, "ASEA-ATOM Control Rods for US BWRs," re CR-85 control rods.
 CHRISTIANSSON, LINDNER, J. ASEA Atom, Inc. 88/03/11 9pp 44970313-44970313
- --8804040163 UF 87-102 R01 Rev 1 to "ASEA ATOM Control Rods for BWR 2/3/4/5/ 6 Svc Life Limit Recommendations" LINDNER,J ASEA Alom, Inc. 87/04/15 25pp 44970,322-44970,346.
- 8804040 153 Corrected transcript of 880225 BWR Mark I containment performance into exchange workshop in Baltimore,MD.Pp 271- 465b Supporting documentation encl * Commissioners 88/02/25; 289pp 44974:259-44975;187.
- 8804040244 Summary of 880217 meeting w/Transnuclear,Inc in Rockville,MD re Model TN-RAM cask.

 ODEGAARDEN,R.H. Transportation Branch 88/03/22. Transportation Branch to 44972 230 44972 231,
- 8804050123 Forwards safety evaluation addressing mods made to TOI diesel angines to reduce vibrations & acceptability of resultant vibration level Considers diesel vibration issues resolved. HOLAHAN,G.M. Division of Reactor Projects - III,IV,V & Special Projects (Post 870411) 88/03/28. ANDOGNINI,G.C. Sacramento Municipal Utility District. 3pp. 44897.009-44997.017.
- -8804050128 Safety evaluation supporting resolution of TDI diesel engine vibration problems at facility.

 * Office of Nuclear Reactor Regulation, Director (Post 870411) 88/03/28 6pp 44997:012-44997.017.
- 8804050159 Responds to IE Bulletin 85-003, "Motor-Operated Valve Common Mode Falluros During Plant Transients Dua to Improper Switch Settings." Valve differential pressures will be evaluated JANECEK, R.F. BWR Owners Group. IE8-85-003. 88/03/28. SNIEZEK, J.H. Offico of Nuclear Reactor Regulation, Director (Post 870411). 2pp. 45021:089-45021.070.
- 8804050206 Authorizes lacility restart & conduct of power ascension test program.Conditions of 851226 confirmatory action ltrs metibased on submittals documenting resolution of emergency diesel generator vibration problems & 24 h surveil lanca run.

 MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). CAL. 88/
 03/30. ANDGNINI,G.C. Sacramento Municipal Utility District. 3pp. 45029.08545029.087
- 8804050331 Forwards NEDO 31558, "Position of NRC Reg Guide 1.97,Rev 3 Requirements for Post-Accident Neutron Monitoring Sys."

 JANECEK.R.F. BWR Owners Group, BWROG-8817/BWR1 88/04/01 MURLEY,T.E.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 2pp. 45028.183-45028.241.
- --8804050342 NEDO-31558 "Position of NRC Rep Guide 1.97,Rev 3 Requirements for Post- Accident Neutron Monitoring Sys."
 * 8WR Owners Group. 88/03/14. \$7pp. 45028:185-45028-241.
- 8804050396 Corrected transcript of 880226 BWR Mark I containment performance info exchange workshop in Baltimore,MD. Pp 486-518.Supporting documentation encl * Commissioners. 88/02/26. 65pp. 44997:234-44997:298
- 8804060345 Forwards application fee to initiate NRC review of Amend 21 to NECE-
- 24011-P.A. CHARNLEY,J.S. General Electric Co. MFN-29-88. 88/03/28. MURLEY,T.E. Office of Nuclear Reactor Regulation, Director (Post 870411). 1p. 45047.099-45047.099.
- 8804060523 Forwards revised 870306 responses to request for additinto resulting from review of Sargent & Lundy Draft 8,proposed Rev 7 to Topical Rept SL-TR-1A.
 TAYLOR,H S. Sargent & Lundy, Inc. 88/03/31. Document Control Branch (Document Control Desk), 9pp. 45008:346-45008.354.
- 8804070003 Forwards application for amend to License DPR-16, revising Tech Spec Section 3.10 to support Cycle 12 reload. Proprietary NEDC-31462P withheld (ref 10CFR2.790), Fee paid. WILSON, R.F. General Public Utilities Corp. GPU Service Corp. 88/03/30, Document Control Brench (Document Control Desk), 2pp. 45030:105-45030:298.
- 8804070029 Forwards proprietary "Composite Summary of Evaluations of Programs for Dispositioning Safety & Performance Improvement Program Recommondations." WILGUS W.S. Babcock & Wilcox Operating Plants Owners Group. OG-167, 88/03/28. CRUTCHFIELD. Division of Reactor Projects III,IV.V & Special Projects (Post 870411), 2pp. 45098:026-45098:027.
- 8804070053 Discusses util completion of work required for TDI diesel generators in preparation for restert, per restart conditions set forth at Commissioners 880322 meeting. TDI diesel generators declared operable per Tech Spec 3.7.1.

 ANDOGNINI, G.C. Sacramento Municipal Utility District. GCA 88-199. 88/03/28. MIRAGLIA, F.J. Associate Director for Projects (Post 870411). 3pp. 45022:142-45021.42. 45022,144.

- 8804070070 Comments in support of proposed rule 10CFR50,App J re atternative method for leakage rate testing App J should be modified to allow fest duration min of 8 h when util zing mass point method GRHDLEY,R. Tennessee Valley Authority, 88/04/04 Document Control Branch (Document Control Dosk) 2pp 45048 278-45048 279
- 8804070188 Appreciates time spent on 880329 discussing status of QA Topical Rept BAW-10036A Revised rept will be issued during Sept 1988 MACKINNEY.A.L. Babcook & Wicox Co. 88/04/04 SPRAUL.J.G. NRC No Detailed Affiliation Given 1p. 45075-043-45075-043
- B804080271 Forwards Info on C-E Owners Group repts which need NRC approvel/requested at 880128 moeting Ropt on restructured Tech Spacs not included on onch because Industry Interface w/NRC on issue handled through NUVARC. GASPERJJK C-E Operating Plants Owners Group. CE06-88-092. 88/03/30. MIRAGLIA,F.J. Associate Director for Projects (Post 870411) 7pp. 45064-236-45064-249
- 8804120066 Ngthication of 880414 meeting w/8&W Owners Group steam generator committee in Rockville,MD to discuss committee accomplishments & activities during 1987 & plans for 1988 & beyond Agenda also encl.

 SIEGEL,B. Project Directoriste 1V. 88/04/05. CHENG.C.Y Materials Engineering Branch. 25pp. 45342.074-45342.098
- 8804120423 Forwards payment on invoice for costs incurred during NRC review of Revs 8 & 9 to Topical Rept NU-OA-1 MROCZKA,E.J., SEARS,C.F. Connecticut Yankee Atomic Power Co. SEARS,C.F. Northcost Nuclear Energy Co. (subs. of Northcast Utilities). A07037. 88704708. Document Control Branch (Document Control Desk). 4pp. 45091.001-45091.004
- 8804140028 Notification of cancellation of 880413 meeting w/C-E,LASL, Rochester Gas & Electric Co & Wisconsin Public Svc Corp in Rockviro,MD to discuss C-E Topical Rept CENPD-276-P, "CEUPR,C-E Upper Plenum Reful/Rollood Code" HSILY, Poactor Systems Branch, 88704/05, HODGES,M.W. Reactor Systems Branch, 3pp. 45118.350-45118:360.
- 8804140272 Forwards comments & recommendations on background book tabulation of Tec Spec Section 374.0,per 880923 letcon.
 GIARDINA,R.J. Technical Specifications Branch 88/03/31. TROSOVSKY,M. EG&G Idaho, Inc. (subs. of EG&G, Inc.). 2pp. 45118-255-45118-256.
- 8804140514 Notification of 880413 meeting w/C-E in Rockville,MD to discuss C-E Topi-cal Rept CENPD-276-P, "CEUPR,CE Upper Plenum Relitt/Relbood Code" HSII,Y. Roactor Systems Branch, 88/04/05, HODGES,M.W. Reactor Systems Branch, 3pp. 46130:183-45130:185.
- 8804150012 Application for amond to License NPF-47,changing Tech Specs to revise setpoints and limits to recirculation loop operations to allow single loop operation Fee pald.
 DEDDENS,J.C. Quil Statos Util·tios Co. RBG-27657, 88/04/06. Document Control Branch (Document Control Dask), 21pp. 45152-263-45152:352
- --8804150017 NEDO-31441 "Single-Loop Operation Analysis for Rivor Bend Station, Unit BRANDON, R.J., ROBARE, D.J., CHARNLEY, J.S., General Electric Co. 87/05/31, 38pp 45152 316-45152:352.
- 8904150034 Forwards KWU-UPC-9601-A, "Topical Rept on Replacement Steam Gen-orators," Recalculations of FSAR transients & accidents unnocessary since differencos in rolovant parameters small.
 FIGLHUBER,D. Utility Power Corp. 88/03/23, WICHMAN,K. Office of Nuclear Reactor
 Regulation, Director (Post 870411). 1p. 45142-265 45143 351.
- --8804160036 KWU-UPC-8601-A "Topical Repl on Replacement Steam Generalors."

 ** Utility Power Corp. * Kraftwerk Union Aktiengesellschaft 88/03/23. 400pp. 45142:266-45143.351.
- 8804150049 Forwards proprietary BAW-10166P, "BEACH Bost Estimate Analysis Core Hoat Transfer Computer Program for Reflood Heat Transfer During LOCA." Rept describes computer code used to predict heat transfer coefficients.

 TAYLOR,J.H. Babcock & Wilcox Co. JHT/88-72. 88/04/11, NORBERG,J.A. Division of Engineering & Systems Technology (Post 870411), 1p. 45183:123-45183:123
- 8804160166 Forwards summary rept clarifying basis of final hydrogen release histories to assist in development of generic SER for hydrogen control program Rept needed due to complete volution of accident scenarios & BWR core heatup code. LANGLEY,JR. Hydrogen Control Owners Group. HGN-132, 86704704. Office of Nuclear Reactor Regulation, Director (Post 870411), 14pp. 45131:323-45131:336.
- 8804180182 Forwards propriotary "Discussion of Survivability of Pressure Transmitter In Low Flow, Hydrogen Combustion Environs." Transmitter produced to exceed temp.Rapt withhold (rot 10CF182.790).
 LANGILEY, JR. Hydrogen Control Owners Group HGN-131, 88/04/05. Office of Nuclear Reactor Regulation, Director (Post 870411), 5pp. 45163:356-46153:360.
- 8804190185 Forwards clarified & expanded paper addressing quality of parts in control panols per 880302 totcon Enci Intended as replacement for 870702 fir to A Thadami from R Artigas.
 ARTIGAS.R. General Electric Co. MFN-023-88, 86703725, THADANI,A.C. Assistant Director for Systems, 5pp. 45165-324-45165-332.

- 8804190266 Forwards safety evaluation re-topical rept on "Relead Safety Evaluation Mothods for Application to Plant," per 670327 summittel Rept acceptable for ref in i-
- consing plant reloads.
 GIITTER.J.G. Project Directorate III-3. TAC 65155. 68/04/11, HINTZ,D.C. Washington Public Power Supply System. 2pp. 45168:001-45168.012.
- **-8804190271 Topical rept evaluation re "Reload Safety Evaluation Methods for Application to Plant." Rapt acceptable for ref in licensing documents.

 Office of Nuclear Reactor Regulation, Director (Post 870411), 88/04/11, 10pp. 45188.003-45168.012
- 8804190275 Provides addfinfo re review of Allegation 87-A-0114 & fuel bundle shipping container survey program.per 880216 request. Returned fuel bundle shipping container survey protocol modified in early 1986.
 WINSLOW,T.P. General Electric Co. 88/04/05. CLINE,W.E. Region 2, Ofc of the Director. 3pp. 45216:332-45218:334.

- 8804190362 Forwards Endorsements 120 & 51 to NELIA Policy NF-83 & MAELU Policy MF-84,respectively.

 SAMUELS,JL Warsh & McLennan, Inc. 88/04/06, DINITZ!, Office of Nuclear Reactor Regulation, Director (Post 870411), 5pp. 45164,156-45164:160
- 8804190395 Forwards proprietary Rev 4 to "Emergency Procedure Guidelines vs Hydro-gen Control Owners Group Scenarios" (ref. 10CFR2 780). Rev. Incorporates changes resulting from 861022 meeting w/NRC Affidavit requesting withholding enci LANGLEY-JR. Hydrogen Control Owners Group, HGN-129, 88704149 Office of Nu-clear Reactor Regulation, Director (Post 870411), 5pp. 45182 358-45183 001.
- 8804200280 Forwards proprietary responses to questions re BAW-10159P, "BWCMV Correlation of Critical Heat Flux in Mixing Vane Grid Fuel Assemblics" Responses
 - TAYLORJ H. Babcock & Wilcox Co. JHT/88-078, 88/04/15. NORBERG, J.A. Division of Engineering & Systems Technology (Post 870411). 1p. 45225 314-45225 315.
- 8804210061 Forwards proprietary NEDC-30844A, "BWR Owners Group Response to NRC Generic Lir 83-29,ltem 4.5.3" & NEDC-30851P-A, "Tech Spec Improvement Analyses for BWR Reactor Protection Sys." Affidavit encl Repts withheld (ref 10CFR2-790).

KLAPPROTHJ F. General Electric Co. OGB-294/32D/OG1 88/04/04. Document Control Branch (Document Control Desk). 4pp. 45194:161-45194:164.

- 8804210277 Part 21 & deliciency rept re damage to emergency diesel generator jacket water HX during flushing Initially reported on 860917 HX repaired & installed in Unit 2. Thermostalic valves being modified. RICE.P.D. Georgia Power Co. 6N-1439. 88/04/14, Document Control Branch (Document Control Desk). 3pp. 45235:257-45235:259.
- 8804210325 Summary of 880331 meeting w/util & Westinghouse re Westinghouse test results supporting change in steam generator tube sleeving process described in Topical Rept WCAP-11643.List of attendees & agenda enci.

 GITTER.J.G. Project Directorate III-3. 88/04/08. Project Directorate III-3. 9pp. 45192:113-45192:121
- 8804210327 Forwards proprietary WCAP-11787 & nonproprietary WCAP-11788, "Prane Island Units 1 & 2 Evaluation for Tube Vibration Induced Faligue," in response to NRC Compilance Bulletin 88-002 & 880325 application to withhold proprietary info LARSON,C.E. Northern States Power Co. IEB-88-002. 88/04/12. Document Control Branch (Document Control Desk). 3pp. 45194.001-45194:160.
- -8804210364 Requests that proprietary WCAP-11787, "Prairie Island Units 1 & 2 Evaluation for Tube Vibration Induced Fatigue," be withheld from public disclosure (ref 10CFR2:790(b)(1)). WIESEMANN,R.A. Westingfrouse Electric Corp. CAW-88-025, 88/03/25, MURL EY,T. Olifice of Nuclear Reactor Regulation, Director (Post 870411), 10pp. 45194.004-35194.01. 45194.013
- --8804210382 WCAP-11788 "Prairie Island Units 1 & 2 Evaluation for Tube Vibration induced Faligue."
 CONNORS,H.J., FRICK,T.M., HALL,J.M. Westinghouse Electric Corp. SG-88-03-022.
 88/03/31, 210pp. 45184.014-45184:160.
- 8804210481 Nohitication of 880428 meeting w/C-E in Rockville,Md to discuss CENPD-278-P CEUPR.CE upper plenum refill/reflood code. HSII,Y. Reactor Systems Branch. 88/04/13. HOOGES,M.W. Reactor Systems Branch. 2pp. 45200-244-45200-245.
- 8804220177 Forwards supplemental response to NRC safety evaluation of WCAP-10858, "ATWS Mitigating Sys Actuation Circuitry Generic Design Package," per request during 871214 telcon. Addl Info will be provided per commitment in 871030 tir. BARR,R C. Portland General Electric Co. 88/04/13. Document Control Brench (Document Control Desk). 10pp. 45257:185-45257:195.
- 8804260208 Forwards proprietary "ANNA:Advanced Neutron Noise Analysis Software Sys." Rept withheld (ref 10CFR2.790).
 COPELAND,R A. Advanced Nuclear Fuels Corp. (formerly Exxon Nuclear Co., Inc.) 88/04/18. Document Control Branch (Document Control Desk), 4pp. 45254:198-45254:201
- 8804270031 Notification of 880421 meeting w/BWR Owners Group in Rockville,MO,to exchange status of topical rept reviews & coordinate future activities re Tech Specs

Improvement.
BUTCHER,E.J. Technical Specifications Branch. 88/04/15. ROSSI.C.E. Division of Operational Events Assessment (Post 870411). 1p. 45243 232-45243 232.

- 8804270162 Forwards Endorsements 1 & 2 to MAELU Certificate MW-155 & Endorsements 1 & 2 to NELIA Certificate NW-75.
 HOLDER,L.S. Dow Chemical Co. 88/04/21, DINITZ,I. Office of Nuclear Reactor Regulation, Director (Post 870411), 21pp. 45245.001-45245.021.
- 8804280039 Forwards Rev S0 to CE-1-A, "QA Program for Nuclear Generating Stations." Revs being made to reflect organizational changes.

 MORGAN,WE. Commonwealth Edison Co. 88/04/18. Document Control Branch (Document Control Desk). 1p. 45281:273-45261:299.
- -8804280069 CE-1-A R50 Rev 50 to "OA Program for Nuclear Generating Stations "
 Commonwealth Edison Co. 88/04/18. 17pp. 45261:274-45261:299.
- 8804280531 Notification of 880405 meeting w/BWR Owners Group in Rockville,MO to discuss diversity requirements for ATWS rule (10CFR50.62) implementation. LI,H.C. Instrumentation & Control Systems Branch. 88/03/29. NEW8ERRY,S. Instrumentation & Control Systems Branch. 2pp. 45269.043-45269.044.

WASTE MGT NUCLEAR WASTE MANAGEMENT

45254:201.

8802040318 "Technical Assistance in Identification & Evaluation of Seismo-Tactonic Isaues re Repository Site Characterization Plans," Monthly Mgt Ltr Rept 17 for Dec 1987.

OUMMINGS.G.E. Lawrence Livermore National Laboratory. FIN A-0297. 88/01/06 BLACKFORD,M.E. Technical Review Branch. 4pp. 45234:344-45234:347.

- 8803090154 Forwards notice of upcoming NRC/DDE lechnical/programmatic meetings as rosult of 840927 FR notice Notice will 1st both tentative & firmly established meetings between NRC & DDE & will be updated weekly.
 YOUNGBLOOD 8 J. Operations Branch. 88702729 NRC No Detailed Affination Given 2pp. 45089 062-45089 063
- 8803090168 Transmits revised schedule & associated milestone definitions for development of ctrimgt planiper 1F Hagen 871118 ftr & JO Bunting 871124 & 890120 fts Enclischedule indicates timing for development of main body of plan. LATZUE Southwest Research first title NRC-02-86 005 88702705 BUNTINGUI O Systems Engineering & Evaluation Branch 11pp 45099.074-45089.084
- 8803090196 Comments on Dec 1987 monthly progress rept, "Technical Assistance in Geochemistry" Progress to date satisfactory Actions taken by ltr within scope of current Contract FIN 8-0287.
 BROCKS,D D Division of High Lovet Wasto Managament (Post 970413) FIN 8-0287.
 NRC-50-19-03-01, 88/02/19 KELMERS,A D Oak Ridge National Laboratory. 3pp. 45089.085-45089.097
- 8803090237 Dicusses review of 1987 monthly progress rept for B-0290, "Lab Evaluation of DOE Racionuc'ides Soluhity Data & Selected Retardation Parameters, Experimental Strategies, Lab Techniques & Procedures " Progress satisfications." factory BRADDURY.J.W. Technical Review Branch FIN B-0200, 88/02/19. MEYER.R.E. Oak Ridgo National Laboratory 3pp. 45089:071-45089.073.
- 8803090345 Comments on 860208 monthly progress rept describing status of Williams & Assoc technical assistance under Contract NRC 02-85 008 Progress made to date satisfactory
 POHLEJA Technical Ruview Branch FIN D-1020 NRC-02-85-008, 88/02/24,
 WILLIAMS,R.E. Williams & Associatos, 3pp. 45099-254-45099-257.

- 8803140040 Notifies of 880314 meeting in Atlantic City,NJ to work on QA guidelines document & forwards Oraft 0.12 "ASGC OA Guidelines Document." ROBERTS,G Wilderican Society for Quelty Control. 88703701, American Society for Quality Control. 15pp. 44693 187-44693 242.
- -- 8803140046 Draft 0 to "ASOC QA Guidot nes Document."

 1 American Society for Quality Control. 87/64/27, 21pp. 44693:204-44693:242
- 8803140355 Comments on progress rept for 860209-09 Provision of assistance to NRC & Cir for Nuclear Wasto Regulatory Analyses in fransfer so that emergency broadcast sys work can continue w/o delay requested CHANGK C Technical Roview Branch FIN A.4165, 88703709 STEPHENSK W. Stephens & Associates 4pp. 45089-087-45069.070
- 8803240290 Informs of plan to hold workshops during while fig. 880321 in Rockville,MD re-consultation draft site characterization plan Approx schedule for discussion of various technical areas end. STEINR, Energy, Dept. of 88/03/07 BROWNING,R. Division of fligh Level Waste Management (Post 870413) 2pp. 44978 230-44978.231.
- 8803290414 Responds to 890106 lir relisters of NRC technical position on waste form stability Topical repis for compet solidification media must address each waste stream for which NRC review & approval requested TOKAR, Technical Branch 88/03/01, PHILLIPS,WIS Stock Equipment Co. 3pp. 44978 232-44978 235.
- 8803300001 Forwards "Technical Evaluation Rept on 10CFR61 Requirements for Topical Rept Entitled, ENVIROSTONE Gypsum Cement, USG-884-1 "' Approval for use of ENVIROSTONE I mited to stipulations as contained in rept. TOKARM. Technical Branch 88/03/03 LANGE.H. USG Corp. 1p. 44945 252-44945 276
- --88B3300004 Topical rept evaluation of rept "Envirostoria Gypsum Coment USG 684-1." Rept acceptable w/stated limitations 'Office of Nuclear Material Safety & Safeguards, Director. 88/03/03, 24pp. 4945-253-44945-276
- 8803300003 Confirms 880217 telconite NRC evaluation reption GE topical rept. "Transportable Aztech Plant Licensing Topical Ropt." Enclicomments apply only to waste form site thy aspect of topical rept.NRR should be contacted at ervi to process plant TCKARM Technical Branch 88/03/02 CARSONIM Nuclear Packaging, Inc. 4pp. 44945:210-44945 213
- 8803300005 Forwards technical evaluation rept on ENVIROSTONE gypsum cement top-ical rept by USG Corp.W/o erct. SUAMEIER,J J. Technical Branch. 88/03/11. NUSSBAUMER,D A. Assistant Director for State, Local & Indian Relations. 3pp. 44945-284-44945-285.
- 8803300020 Trip rept of 880224-26 visit to LN Technologies re-status & tuture actions re-company top-cat rept review of cement solidification sys product. PERSON,L'S Technical Branch, 88703707, SURMEIER,J.J. Technical Branch, 4pp, 44945-215, 44945-217.
- 8803300268 Discusses final version of NEDE:30878-1, "Transportable Aztech Plant Li-consing Topical Rept." Status of work required to ensure rept acceptability identified in Attachment F. BALLARORIL Technical Review Branch 86/02/04. SURMEIER,J.J. Technical Branch, 6pp. 44963:005-44963
- 8803300375 Responds to 880222 ltr re low level radwaste disposal practices into provided includes estimated porosity of 26% reported in Table 2.1 of NUREG/CR-4756./ivo different types of cements & waste solidification processes GREEVES.J.T. Owiston of Low Level Waste Management & Decommissioning (Post 870413), 88/03/11, RILEY,J.U. Affiliation Not Assigned 15pp. 44945-300-44945-315.
- 8803300430 Forwards "Heat Conduction in Nuclear Waste Disposal Forms" & "Determination of Leachability of Solids" Appreciate prompt attention in approving topical
- rept BOYCE, T.D. Dow Chemical Co., 87/12/22, TOKAR, M., PETERSON, C. NRC No De-tailed Altiliation Given: 1p. 44861,030-44961/057.
- 8803300435 PMM-0235 "Heat Conduction in Nuclear Waste Disposal Forms" KUMAR,A, Dow Chemical Co. 86/10/10, 21pp. 44961-031-44961.051.
- -9803300438 "Determination of Loachability of Solids"

 ANDERS,O.U., BARTEL,J.F., ALTSCHULER,S.J. Dow Chemical Co. 87/04/30. 6pp.

- 8803310093 Advises that 880003 proposed plan to visit USGS in either Mento Park,CA or Gorden,CO to examine seismic reflection data would be more beneficial after USGS completes data. Marked-up plan ericl. HOLONICHJ. Operations. Branch 58703/16. JUSTUS.P. Technical Review Branch 5pp. 44984-036-44984-040.
- 8803310100 Trip rept of 870921-25 v.sil to DCE/NRC geology workshop & held conference on statigraphy of Columbia River Basalt Group & Ellensburg Formation BEMBIA, P.J. Tochnical Review Branch. 88702704. BROOKS, 0.J. Technical Heview Branch. 4pp. 44967-257-44967:261.
- 8803310111 Responds to 880202 ltr forwarding DOE rept re Death Valley groundwater sys.Workshop scheduled for whi of 850411 to discuss alternative conceptual models Surface-based & underground testing will be required to resolve issues STELLOY, Official for the Executive Director for Operations 88/03/15 LOUX,Right Nevada, State of 6pp 44964138-44985108
- --8803310112 Forwards "Conceptual Considerations of Death Valley Groundwater Sys W/Special Emphasis on Adequacy of Sys to Accommodate High Level Nuclear Wasta Repository" Site plan should include Szymanski recommended invustigations LOUK, P.R. Novada, State of 88/02/02, ZECH, L.W. Commissioners, 3pp. 44964:144-44665-1.00 44965:108
- -8803310113 "Conceptual Considerations of Death Vallay Groundwater Sys W/Specia" Emphasts on Adequacy of Sys to Accommodate High Level Nuclear Waste Repostory." SZYMANSKI, J.S. Energy, Dept. cf. 87/11/30, 225pp. 44964:147-44965.108
- 8803310121 Proposes NRC & DOE plan more technical meetings during wks of 890314 8 21 to discuss site characterization plan concerns Consideration of alternative con-ceptual mode's of Yucca Mountain site one concern that requires discussion YOUINGBLOODE J. Operations Branch. 88/02/12. STEIN,R. Energy. Dept. of: 2pp. 44967 325-44967-326.
- 8803310123 Forwards questions for upcoming site visit on DQE seismic monitoring program at Yucca Mountain It nerary/agenda for 880229 0303 meetings also encl YOUNGBLOODBJ Operations Branch 88/02/19 GERTZ,CP, Energy, Dept. of 7pp. 44962 132:44962 138.
- 8803310125 Forwards final comments on review of final EIS re-disposal of Hanford dofonse wastes
 BALLARD.R.L. Technical Review Branch. 88/03/01 KNAPP.M.R. Civision of Low
 Level Waste Management & Decommissioning (Post 870413). 6pp. 44967-32944967-334
- 8803310126 Confirms onsite visit re DOE/NNWSI seismic monitoring program Visit plan, summary pc nt paper & list of items NRC would expect to find at seismic monitoring data acquisition node encl. YOUNGBLOOD, B.J. Operations Branch 88/02/12 GERTZ, C.P. Energy, Dept. of. 8pp. 44967:339-44967:346
- 8803310128 Novines of 660318 meeting w/DOE in Rockville,MD to discuss DOE 880120 responses to NRC request for addumno on DOE NVO-196-17 & NNWSI SOP-02-01 DA documents & responses to 871009 request for info re Los Alamos Nati Lab OA plan. VOUNGBLOOD, B.J. Operations Branch. 88/03/03. LCUX, R.R. Nevada, State of 2pp. 44967.327-44967.328
- 8803310133 Forwards comments developed by five Technical Review Branch sections re DCE QA program Supplemental comments also provided BALLARD,R L. Technical Review Branch, 88/03/02 YOUNGBLOOD,B J. Operations Branch, 11pp. 44983:258-44983.268.
- 8803310136 Discusses high level waste package aspects of COE/E15-0113, "Disposal of Hanford Delense High Level Transurance & Tank Wastes."
 WICK,E. [echnical Branch 88/03/08 GLENN,C Regulatory Branch 2pp 44996 096-44996 097
- 8803310142 Forwards trip ropl re 871210 briefing on 8WIP stop work order/
 restart Encourages that BWIP improvements on quality aspects be reviewed & possi-bly considered by NINWSI quality may trom lesson learned perspective
 YOUNGBLCOD.B.J. Operations Branch 88/01/28 STEIN.R. Energy. Dept. of 2pp 44984.352-44984.357.
- --8803310144 Trip rept of 871210 bileting on BWIP stop work order/ restart Briefing de-scribed specific actions taken to fully rescrid stop work order issued to Rockwold by DOE in May 1986 List of attendeds end BELKE, W. Operations Branch 68/01/26. YOUNGBLOOD,8 J. Operations Branch 4pp 44984 354-44984 357.
- 8803310146 Forwards notice of upcoming meetings ro NRC high lovel waste mgt program per NRC 840827 FR notice Notice will list both tentative & firmly established meetings between NRC & DDE & will be updated weekly YOUNGBLOOD, BJ Operations 8ranch. 88/03/21 Operations Branch 2pp. 44967:335-44967:336.
- 8803310149 Responds to request for info re high level repository in Hanford,WA & rote of NRC in repository. Hanford site no longer candidate for high level waste repository. Two documents explaining NRC role end W/o ends. YOUNGBLOOD, B.J. Operations Branch. 88/01/07. Affiliation Not Assigned. 3pp 44984.358-44984:360.
- 6803310154 Forwards notice of upcoming meetings re NRC high level waste mgt program. VOUNGBLOOD,B.J. Operations Branch. 88/03/07. NRC - No Datailed Affiliation Given 2pp. 44967:323-44967:324.
- 8803310157 Inquires as to whether recipients wish to continue to receive weekly notice of upcoming meetings & all other significant NRC high level waste documents YOUNGBLOCD, B.J. Operations Branch. 88/03/04. Interior, Dept. of, Bureau of Ind-en Affairs. 3pp. 44967:301-44967:308.
- 8803310160 Forwards notice of epcoming meetings re NRC high level waste mgt program.

 gram.

 gram.

 Given. 2pp. 44962:128-44962.129.

- 8803310175 Informs of removal of tecipient name from distribution list for weekly notice of upcoming high tevel waste meetings. Distribution will be limited to State of NV 8 office parties still invalved in high level waste repository program. YOUNGBLOODEJ Operations Burach 88/03/04 LICKUS,R Region 3, Otc of the Director. SANBORN,G. Heyon 4, Citc of the Director. TROJANOWSKI,R. Region 2, Otc of the Director. 9pp. 44992 351-44982 359.
- 8803310178 Requests technical support for observing holed DOE OA audits of DOE contractor programs Names of staff assigned to task requested by 880216 Pan for observation of OA audits of matis oncl YOUNGRLOOD, BJ Operations Branch 88/02/10 BALLARD, R Technical Review Branch 14pp 44983 260-44983 202
- 8803310183 Advises that Open Item I(f) & Action Item 20 re-drilling history & results of geotechnical testing from principal beneficible USW G-4 at Yucca Mountain,can be
- EIGNETTAN, J.J. Operations Branch 88/02/08 GERTZ, C.P. Energy, Dept. of 4pp 44984 340-44984 347
- -8803310290 Forwards NRC evaluation of NNWSI project response to Open Item ((f) & Action Item 20 rei drilling history & gootechnical testing results from principal boreho'e USW-G4. Open & action item may be closed. BALLARD/B.L. Tectin cal Review Branch. 87/12/23. YOUNGBLOOD,B.J. Operations. Branch. 4pp. 44984.344-44984.347.
- 8803310188 Trip rept of 880225-26 visit to DOE technical project officers meeting in Las Vegas,NV to NNWSI Key points discussed listed HOLONICH,JJ. Operations Branch, 88703/16, LINEHAN,J. Operations Branch, 3pp
 - 44996 078-44996 080
- 8803310204 "Liconsing-Methodology Assistance," monthly rept for Feb 1988 CRANWELL R.M., Sandia National Laboratories FIN A-1165 88703715 GALSON,D Operations Branch, 46pp, 44984-263-44984-307
- 8803310211 Forwards draft "Review Plan for NRC Staff Review of DOE Study Plans & Procedures
- YOUNGBLOOD, B.J. Operations Branch 88/01/15. KALE, S.H. Energy, Dept. of 1p. 44953 209-44953 222
- --8803310215 Orafi "Roviow Plan for NHC Staff Review of DOE Study Plans & Proce-
- dures"

 * Division of High Lovel Waste Management (Post 870413) 87/12/22 13pp 44953 210-44953 222
- 8803310218 Responds to 880308 request for recommendations for addit CDSCP review needed to finalize that point papers & associated stall-days estimates Work & estimated time in stall-days required to complete additions each Tachnical Review Branch 88/03/11 YOUNGBLOOD,B J. Operations Branch 7pp. 44996
- 8803310268 Forwards DOE BWIP rept, "Project Characteristics Sacioeconomic Monitor ing Rhot." per local govt requests for socioeconomic impact data for downside high-ning efforts Data compiled as part of BWIP socioeconomic mornioning program ANT TORRUH Energy, Dept. of, 88-8W-21, 88/03/24, UNEHAN J.J. Operations Branch, COOK,F.R. NRC - No Detailed Affiliation Gwen BRAYL, Richfand, WA. 9pp. 45008 156-45008-228.
- --8803310272 Working draft of "Project Characteristics Socioeconomic Monitoring
- Hopt "
 FRIEDLIE A Battelle Human Affara Research Centers HERBORN,D.1,
 TOMI,INSON,K.M. Westinghouse Hanford Co. 88/03/31 64pp 45008,165-45008.228
- 8804010199 Provides update to author H80217 ftr in approval for WC Patrick to serve on Lawrence Berkeley Lati earth sciences diviroview committee Furthering on char-
- acter of committee listed

 LATZ.J.E. Southwest Research Institute, 88/03/22 BUNTING.J.O. Systems Engineering & Evaluation Branch. 2pp. 44945-343-44945-345.
- 8804040065 Submits agenda for work group on document control & records mgt to be huld on 880419 in Orlando,FL Supplementary requirements for QA records end WINN.J A American Society of Mechanical Engineers 88/03/18 American Society of Mechanical Engineers 22pp 45020 287-45020 308
- 8804050410 Concurs w/proposed remodial action for Commercial Vicinity Property GJ-18426-MR in Grand Junction,CO which includes application of supplemental stds to propertios based on rowe or 1860428 radiological & engineering assessment. SMITH,RID Uranium Roccopory Field Ofc. R4 88/03/24 VIRGONAUE Energy, Dept of, 1p. 45029.179-45029 179
- 8604050416 Requests revior into justifying stated deviations from NRC technical position rollesting & inspiplions during const of DOE remedial action at inactive U militalings sites noted in 070010 remedial action inspiplion. https://doi.org/10.1101/10.1
- 8804060021 Forwards table entitled "Compressive Strength After Immersion vs Cure Time" Table erroneously designated as proprietary in author 890314 ltr.Table may be used as desired by NRC MCCOY,SB LN Technologies Corp. (formerly London Niclear Sycs. Inc.) LN-88-00175-DEV-89/001/22. TOKAR,M. Division of Low Lovel Waste Management & Decommissioning (Post 870413), 3pp. 45033-086-45033-088.
- 8804060037 Forwards draft Ropt CNWRA 88-001, "Review of Literature re Transporta-
- PIERCE,R N. Southwest Rosearch Institute. NRC-02-88-005 88/03/26 BUNTING,J O Systems Engineering & Evaluation Branch 2cp 45047 176-45047.250
- -8804060041 CNWRA 88-001 DRF Draft "Review of Literature re Transportation Risk Study "
 OELKERS.E., PIERCE,R.N., WHITING,A.R. Southwest Research Institute, NAC-02-88-
- 005. 88/03/31. NRC No Dotalled Affiliation Given 73pp. 45047 179 45047 250.
- 8804060045 Informs that 871209 review of remedial action inspiplan (RAIP) for Riverton UMTRA project complete Review limited to portions of RAIP dealing w/contaminated mail to be removed from site RAIP considered acceptable. HAWKINS.E.F. Uranium Recovery Field Ofc, R4 88/03/22. ARTHUR,W J Energy, Dopt. of 1p. 45018-199-45018-199

- 8804060056 Requests NRC concurrence to early acquisition of Green River site Articipates start of vicinity proporty remedial action in April 3986 Ericl drawings endate recommendations for area of land to be acquired ARTH
- 8804060074 Forwards Roy 1 to "Manual For Use of SERIC High Integrity Container 200 1/400 1," for INRC review & approval Proposed methodology for changes also encl SUZUKIO Chighbu Cement Co., Ltd. 88/03/30, KNAPPN R. Division of Low Level Wasto Management & Decommissioning (Post 870413), 7pp. 45074-088-45074, 120
- -- 8804060076 Rev 1 to "Manual for Use of SEPIC High Integrity Container 200 17400
- * Chichibu Coment Co., Ltd. 88/03/31, 26pp. 45074.095-45074, 120
- 8804080108 Concurs w/proposed remedial action for Commercial Vicinity Property GJ. 05765-MR in Grand Jenchen.CO which includes application of supplishes to vicinity properties based on review of 880128 radiotegical & engineering assessment SMITHR D. Uranium Recovery Field Ofc. R4, 88/03/24, VIRGGNA J.E. Energy, Dept of 1p. 45018-226, 45018-226.
- 8804060133 Recommends that concurrence be granted for application of supplemental sids on contaminated area for vicinity Property GJ-18426-MR,per 880128 request & based on review of IOE Inat radiological & engineering assessment HEYER,R 5 PETTCMGILL.H J. Uranium Recovery Field Ofc. R4 88703724 Uranium Recovery Field Ofc. R4 2pp 45018-230-45018-231
- B904060139 Requests comments on enclinated draft Citi of Civilian Radwasie Rev E to "OA Requirements for High Level Nuclear Waste Repository Program" & Rev C to "OA Program Description for Headquarters," by 880323 Checklist also encl W/o revs YOUNGBLOOD.B J. Operations Banch. 88703/02 ROUSE L.C. Fuel Cycle Safety Branch. 3pp. 45073-353-45073-355
- 8804060183 Forwards Project Interface Document 07-S 02 per procedures cullined in Firenton WY remedial action plan Changes designated as Class El changes since only temporary fact thes affected Rev 2 to Spec 01500 also end MANN_DE Energy, Dept of 88/703/25 FL/EGEL,M_NRC No Detailed Affiliation Given 22pp 45047-076-45047-096
- 8804060201 Recommends that concurrence be granted for 690128 application of supplemental side on contaminated area for Victinity Property GJ-05765-MR based on review of radiological & engineering assessment & associated this HEYERIR'S , PETTENDILLIHJ Uranium Recovery Field Ofc, R4 89703724 Uranium Recovery Field Ofc, R4 2pp 45019 318-45019 319
- 8804060254 "High Level Waste Repository Performance Assessment Development," for period 890313726 Voucher for profitsives end W/o end MOLER, RB. Systems Support, Inc. Fin. A-4165, 86/03/27. CHANG, K.C., NRC. No Dote led Alfriation Given. 2pp. 45074 074-450/4 075.
- 8804060289 Forwards preliminary agenda of scheduled 860411-14 technical meeting w/ NRC re groundwater sys at Yucca Mountain STEIN,R Energy, Depthol 89/03/25 BROWNING,R Division of High Levet Wasto Managument (Post 870413) Spp. 45048 097-45048 101
- 8804060346 Comments on spec/acceptance criteria for Waste Sys Engineering & Inte-gration Milostone 18 Milostone 18 intended to demonstrate interim prototype of pro-gram architecture at current stage of development. LATZ_JE Southwest Research Institute 88/03/19 BUNTING_JO Systems Engineer-ing & Evaluation Branch. 10pp. 45073.343-45073.352
- B804060350 Rev. 0 to Scient-1c Investigation Plan USGS-SIP-3222G-01, "Seismic Reliection & Refraction Surveys"
 * Interior, Dept. of, Geological Survey. 87/04/30, 50pp. 45068-329-45007-018
- 8804060373 Forwards copyrighted "Intruence of Radiation on Corrosion Stainless Stoci" by SE Worthington GP Maish KJ Taylor & G. Bryan which appeared in Nov. 1936 "Cor-rosion Science" (Important conclusions from NRC standpoint 1sted MCNEIL M. Wasto Management Branch, 1516, 87/04/29, JUNGLING T. NRC. No. Detailed Affiliation Given 2pp 45019 356-45019 357.
- 8804070037 Forwards monthly issuance of schedules for UMTRAP sites, reflecting key project activities in areas of site characterization/NEPA compliance, dosign development, remed all action constructification in Economy 45030 344.
- 88040700\$5 Forwards "Preliminary Technical Evaluation Hest for Proposed Remedial Action at Tuba City Tallings Site,Tuba City.AZ." Open items must be resolved before NRC can grant concurrence SMITH,R O. Uranium Recovery Field Olc, R4, 88/03/07. ARTHUR,W J. Energy, Dept of 2pp. 45043 181-45043 237
- --8804070058 "Pretiminary Technical Evaluation Rept for Proposed Remedial Action at Tuba City Tailings Site Tuba City AZ" Uranium Recovery Field Otc, R4_88703707, 65pp. 45043-183-45043-237.
- 8804070084 Rev 0 to "Health Physics Monitoring Plan Ambrosia Lake,NM Site " Chem Nuclear Systems, Inc. 87/01/13, 44pp, 45021 084-45021 129
- 8804070109 Forwards listed documents to begin technical reviews on high density poly-ethylene HIC topical replis por 880310 telcon Wiolenc's WilDMAYEH, D.A. Technical Branch 88/03/11 SILTING, S. Brown Urw., Providence, HI 2pp. 45030 359 45030,360
- 8804070114 Informs of R&O Committee meeting on 880402 at Los Alamos Nati Lab to work on OA Guidelines document beginning w/ Section XI, "Nonconformances." Updated OA guidelines, rolliecting 880314 meeting decisions & comments, end ROBERTS, GW. American Society for Quality Control. 88704707. American Society for Quality Control. 1p. 45022-085-45022-091.
- --8804070120 Drafts 1 of "ASQC QA Guidelines Document" * American Society for Quality Control IBB/03/31 20pp 45022 066 45022 091.

- 8804070128 Informs that initiation of Falls City,TX site will be delayed due to DOS request for accelerated review of Green River,UT site documents
 LOHAUS,PH. Operations Branch 88/03/09. ARTHUR,W.J. Energy, Dopt of 1p. 45031:005 45031:005
- 8804070134 Lists changed milestone dates for Elements 5-7.S Spector will provide 8 develop criteria to integration of elements to support analysis. Description of miles stones encl AGLER,R.E. Southwest Research Institute, 88/03/21, DELLIGATTI,M. NRC - No De-terted Alfright on Givon, 4pp. 45075/290-45075;203.

- 8804970138 Forwards responses to NRC comments re Phase II preliminary design for review of UMTRAP Proprietary draft onch withheld WATHEN.TR. Morrison-Knudsen Engineers, Inc. 88/04/05 JOHNSON,T NRC No Octailed Affiliation Given. 56pp. 45079:175-45079:231.
- 8804070139 Ack receipt of NRC 880321 ltr re status of Task 1 in geotopic setting program element Attention of cir rigi confinues to be focused on accomplishments of assigned scope of work within resource & constraints of contract LATZ_IE Southwest Research Institute, 86/03/23, BUNTING,J.O. Systems Engineering & Evaluation Branch. 1p. 45079.253, 45070.253
- 8804070148 Press release entitled, "DOE Reviewing Mess County Conditional Use Pormit Resolution "
 * Energy, Dept. of: 88/04/04, 2pp. 45115:035-45116:035.
- 8804070156 Discusses addit CDSCP review work to finalize CDSCP draft point papers by 880422. Requests that recipient reconsider Technical Review Branch recommendations & indicate what work must be completed by 880422 to finalize draft point papers.
 YOUNGBLOOD,8 J. Operations Branch, 88/03/18, BALLARD,R L. Technical Review Branch, 2pp. 45076;175-45076;176

- 8804070164 Requests attendance at DOE/NRC Workshop on Atternative Conceptual Models in Les Vegas,NV on 880411-16 to consider different conceptual models of groundwater systheticiding chmatological influences in Yucca Mountain region JUSTUS,P.S. Tochnical Roylew Branch NRC-02-88-005, 88704704, RUSSELL,J.L. Southwest Research Institute 3pp. 45075.027-45075.029.
- 8804070167 Forwards marked-up tables of draft point paper providing revised resource estimates per 880:009 request. Outcome of workshop duting wk of 880411 may affect branch ability to finalize draft point papers by 880422.

 SALLARD.R.L. Technical Review Branch, 88/03/30, YOUNGBLOOD,B.J. Operations Branch, 7pp. 45076.044-45076.050.
- 8804070178 Forwards evaluation rept approving Waste Chem Rept.VRS-002, "10CFR61 Waste Form Conformance Program for Solid-fied Process Waste Products Produced by Waste Chem Corp Vol Reduction & Solid-fication Sys." SURMEIER, J. J. Technical Branch. 89701722, NUSSBAUMER, D. Assistant Director for State, Local & Indian Relations. 1p. 45044:199-45044:199.
- 8804070183 Advisos that recipient shou'd provide selected technical review & evalua-lion of SANO-84-1805, "Technical Basis for Performance Goals, Cesign Requirements & Mail Hecommendations for NNWSI Repository Sealing Program" by 880429. JUSTUS, P.S. Technical Review Branch, NRC-02-88-005, 88/03/24, RUSSELL, J.L. Southwest Research Institute, 2pp. 45075;219-45075 220.
- 8804070192 Requests attendance at meeting of Geological Society of America on B80329-0403 in Las Vogas,NV re geology,tectonics, geomythology,hydrology,goothemstry & natural resources JUSTUS,P.S. Technical Review Branch NRC-02-88-005, 88/03/24, RUSSELL,J.L. Southwest Research Institute 3pp. 45075:221-45075 223. geology,tectonics,
- 8804070195 Requests attendance at NRC 880308 & 09 meetings in Rockville,MD to discuss geologic setting program element operation plans for yr. JUSTUS.P.S. Technical Roview Branch. NRC-02-86-005. 66/03/30. RUSSELL,J.L. Sculhwest Research Institute. 3pp. 45075:224-45075:226.
- 8804070206 Discusses 880302 telcon w/A Campbell of Northeast Utils re clarification of info on recommendations for limiting waste forms to 18%.Util has not notified NRR of bulged liner.
 TOKAR,M. Tochnical Branch. 8B/03/08. Technical Branch. 2pp. 45044-213-
- 8804070239 Forwards comments on possible changes to CDSCP point papers re rock mechanics/design based on comments made at 880321 meeting w/DOE & internal discussions prior to meeting w/Doe oversize map. LORIGL. ITASCA Consulting Group, Inc. FIN D-1016. 88/04/04. GUPTA,D., DAEMEN,J ITASCA Consulting Group, Inc. 11pp, 45075 278-45075:288.
- 8804070256 Invites recipients to participate in NRC & DOE technical meeting on atternate conceptual models of groundwater sys at Yucca Mountain Site. GERTZ,CP. Energy, Dept. of, 98703724, YOUNGBLOODE J. NRC No Detailed Affitiation Gwen. HENDRIX,J. Novada, Univ. of, MacKay School of Mnes, Reno, NV. DINWIDDIE,G. Interior, Dept. of, Geological Survey, 35pp. 45031.053-45031.087.
- 8804070282 Forwards marked-up schedule rept that shows 1-yr window of all current NRC review activities on UMTRAP. Activities previously included in rept which contained all agency reviews.
 ARTHUR,W.J. Energy, Dept. of. 68/03/24. SMITH,D. Uranium Recovery Field Otc, R4. 7pp. 45029.252-45029.258.
- 8804070264 Forwards response to DOE Joint OA Audit 8801 of selected BNWL activities Correctiva actions now in progress as indicated in response.

 GOLDSMITH,S. Battel's Memorial Institute, Pacific Northwest Leboratories, 88/03/31,
 KEATING,J.J. Energy, Dopt. of. 20pp. 45097:183-45097:202
- 8804070274 Forwards J Warner trip rept on Geological Society of America 880313-15 meeting in Lawrence,KS re presentation of paper, "Applications of Berahole Geophysics to...Characterization of High Level Radwaste..." W/two oversize ends. JUSTUS/P.S. Technical Review Branch. 88/03/31. BALLARD.R.L. Technical Review Branch. 2pp. 45044:108-45044:131.

- --8804080103 Trip ropt of Geological Society of America Southcentral Section 880313-15 meeting in Lawronce, KS re geohydrology & weste isolation Abstract re author pres-entation on applications of borehole physics & related into and: WARNER, Technical Review Branch 68/03/31 JUSTUS.P. Technical Review Branch, 22pp. 45044 110-45044:131
- 8804070288 Discusses closure of Action Item 18 from NRC/NNWSI project moeting on 850827-28 Discusses closure of Action from 18 from NRC/NNWSI project mosting on 850827-28 Concludes that data necessary to revise modified permeability zone model adequately included in Rept SAND66-7091 flem considered closed.

 BALLARD, R.L. Technical Review Branch. 88/03/03. YOUNGBLOOD, B.J. Operations Branch. 2pp. 45098. 147-45098-146.
- 8804070298 Forwards traft "NRC Review Plan for OA Programs During Site Characterization Phase of High Level Nuclear Waste Repository" & draft, "Technical Position on OA for Sife Characterization Phase of High.," for review.
 KENNEDYJE. Operations Branch. 88/04/01 BROWNINGR. BELL,M Division of High Level Waste Management (Post 870413) WEISS,S Division of Licensee Performance & Quality Evaluation (Post 870411). 3pp. 45044:265-45045;144.
- --8804080096 "NRC Review Plan for OA Programs During Site Characterization Phase of High Level Nuclear Waste Repository."
 NRC No Detailed Affrication Given 88/04/01, 13pp. 45044:268.45044:280.
- --8804080101 "Technical Position on QA for Site Characterization Phase of High Level Nuclear Waste Repository." NRC - No Detailed Affiliation Given, 88/04/01, 224pp. 45044 281-45045,144.
- 8804070299 Forwards revised statements of work for FY88 technical assistance projects per 880202 request for updates to reflect recent amends to Nuclear Waste Portcy Act. BALLARD,R.L. Technical Hoview Branch, 88/03/21, FUNCHES,J.L. Program Management, Policy Development, & Analysis, Stall (Post, 870413), 49pp., 45098-095.
- 8804070334 Forwards preliminary technical evaluation rept for ramedial action proposed by DOE relstablization in place of estimated 689,000 cubic yards of off-pite matt.W/o OLSEN.T.T., HAWKINS,E.F. Uranium Recovery Field Otc, R4: 88/03/04. Uranium Recovery Field Otc, R4: 2pp. 45043 282-45043 283.
- 8804070335 Discusses status of review of Lakeview UMTRAP & resumption of const activities Design of radon barriers, seepage Into tailing pile, groundwater & contaminated water cleanup need NRC review. SMITH, R.O. Uranium Recovery Field Ofc, R4, 68/03/15, ARTHUR, W.J. Energy, Dept. of. 2pp. 45043.284-45043.285
- 8804080001 Forwards comments on draft of Vol 4 of, "Evaluation & Compilation of ODE Wasto Package Test Data,Biannual Rept," from Aug 1987 Jan 1988. PETERSON,C.H. Technical Brench. FIN A-4171, 88/03/31. INTERANTE,C.G. Commerce, Dept. of. 11pp. 45044;220-45044;230.
- 8604060003 Forwards activities of NRC representatives on Nellis Air Force range. PRESTHOLT.P.T. NRC No Detailed Affikation Given. 88/03/22, LINEHAN,J J. NRC No Detailed Affiliation Given. 6pp. 45044:231.45044:236.
- 8804080004 Comments on monthly progress rept for Feb 1988 re status of activities under Contract NRC-02-85-009. POHLE_JA. Technical Review Branch. FIN D-1021. NRC-02-85-009. 88/03/30. LOGSDON,M.J. Nuclear Waste Consultants, Inc. 4pp. 45079:254-45079.257.
- 8804080016 Forwards technical evaluation rept for Dow Chemical Co Topical Rept DNS-RSS-200-NP, "Dow Waste Solidification Process for Radwaste-Generic Waste Form Cartification Results."

 BALLARD.R.L. Technical Review Branch, 88/03/18, SURMEIER, J.J. Technical Branch, 28pp. 45116:152-45116.181.
- 8804080036 Discusses changes to FY88 Project A-0297. "Technical Assistance in Identification & Evaluation of Selsmic-Tectonic Issues re Repository Site Characterization Plan," per 880102 memo.

 BROWNING.R.E. Division of High Level Waste Management (Post 870413). FIN A-0297. 88/03/16. FUNCHES.J.L. Program Management, Policy Development & Analysis Staff (Post 870413). 16pp. 45116-234-45116-249.
- 8804080048 Responds to 880208 memo re review of Univ of Arizona quarterly progress rept. "Unsaturated Flow & Transport Through Fractured Rock re High Level Waste Repositiones." Comments discussed in 880307 telcon doucmented. FORD,W. Technical Review Branch FIN D-1682. 88/03/17. NICHOLSON,T.J. Waste Management Branch, 20p. 45099:128-45099.129.
- 8804080054 Record of tolcon w/Bureau of Mines (USBM) re transmittal of Work Directives 13 & 14 to USBM.Mothodology repl currently under review by NRC editor.Comments to be transmitted to USBM in next rept.
 ABRAMS.C. Technical Review Branch. FIN D-1018. NRC-02-85-004. 88/03/17. 3pp. 45116:231-45116-233.
- 8804080062 Requests technical direction to CNWRA to provide review of SAND 84-1895, "Technical Basis for Performance Goals, Design Requirements & Mall Recom-mendations for NNWSI Repository Sealing Program." Review requested by 880428. CHERY, Dt. Technical Review Branch. 88/03/17. JUSTUS.P.S. Technical Review Branch. 2pp. 45099.172-45099.173.
- 8804080065 Notifies that const start for Tuba City test tills tentatively scheduled for wk of 880404. Weather conditions may dictate change in starting date. D'ANTONIO_J.R. Energy, Dept. of. 88/03/28. HAWKINS,E.F. Uranium Recovery Field Oic, R4. 2pp. 45044:251-45044:252.
- 8804080090 Advises of likely delay in two cir milestones established in 880205 fir. Two affected milestones are main body of cir mgt plan & sys engineering mgt plan that will eppear as annex to former document.

 LATZ_JE. Southwest Research Institute. 88/03/29. BUNTING.J.O. Division of High Level Waste Management (Post 870413). 1p. 45064:250-45084:250.
- 8804080138 Proposes standardized test procedure for compression testing of bitumen soliditied fow level radwaste Methods of Interpretation as outlined in NUREG/CR-3828 discussed Test Procedures D 1074-83 & D 895-85 encl. SIMPSON.S.I. Associated Technologies, Inc. CH-171-034. 88/03/21. TOKAR.M. Technical Branch. 22pp. 45073:316-45073.337.

- 8604080142 Extends invitation to participate in NRC/DOE technical meeting on alternate conceptual models of groundwater sys at Yucca Mountain site to be field on 880411-14 in Las Vegas,NV. GERTZ.C P. Energy, Dept of 88/04/01. MCHURON,E J. Roger Foot Associates, Inc. 5pp. 45064:251-45064:256.
- 8804080157 Extends Invitation to participate in NRC/OOE technical meeting on alternate conceptual models of groundwater sys at Yucca Mountain site to be held on 860411-14 in Las Vegas,NV.
 GERTZ,CP Energy, Dept. of. 88/04/01. FENSKE,P. Desert Research Institute, 5pp 45064:195-45064:199.

- 8804080184 Forwards response to NRC 880302 ltr re proposed radon barrier borrow source tost results for proposed matts & discussion of compliance w/EPA groundwater stds.per NRC review of final remedial action plan.W/o encis. MANN_DE. New Mexico, State of .88/03/24 HAWKINS,E.F. Uranium Recovery Field Otc, R4. 1p. 45044:255-45044:255.
- 8804080202 Forwards orrata for Jen 1988 printing of site characterization plan consulta-tion draft Original missing list of lables for Chapter 2 & Pages 4R-19 through 4R-24 from Chapter 4 ref list. GERTZ,G P. Energy, Dept. of. 88/02/29. Energy, Dept. of. 9pp. 45064:209-45064:217
- 8804080254 Forwards procedures for acquisition of site-specific samples during site investigation & site characterization by NRC contractors JUSTUS-P.S. Technical Heview Branch. 89/03/18. RUSSELL, J.L. Center for Nuclear Waste Regulatory Analyses. 7pp. 45099.152-45099.158
- 8604080261 Forwards PMPR 68-6, "Program Manager Perodic Rept," for Period 6,FY88.Rept incorporates changes recommended by \$ Fortuna via 880321 telcon.Pro rata allocation of indirect costs based on actual direct costs per 880224 agreement. LAT2,JE Southwest Research Institute, NRC-02-88-005. 88/03/29. BUNTING.J.O. Division of High Level Waste Management (Post 870413). 1p. 45116:102-45116:151.
- --8804080268 PMPR 88-6 "Program Managers Periodic Rept on Activities of Ctr for Nuclear Waste Regulatory Analyses," for liscal reporting period 880220.0318.

 * Southwest Research Institute, FIN D-1035-8, NRC-02-88-005, 88/03/25, NRC No Detailed Affination Givon, 48pp. 45116.103-45116.105.
- 8804110003 Forwards draft SAND85-0598, "Analyses to Evaluate Effect of Exploratory Shalt on Repository Porformance of Yucca Mountain." Rept may not fully address NRC concerns Identified in 880307 NRC draft point papers. STEIN,R. Energy, Dept. of. 88/04/201. BROWNING.R.E. Division of High Level Waste Management (Post 670413). 1p. 45073-001-45073:184.
- --8804110006 SAND85-0598 DRFT Draft "Analyses to Evaluate Effects of Exploratory Shall on Repository Performance of Yucca Mountain." FERNANDEZ,J.A., HINKEBEIN,T.E. Sandia National Laboratories. CASE,J.A. IT Corp. 87/07/28
- 8804110013 Forwards for review & comment. Isled documents which comprise preliminary design for Slick Rock U mill tailings site, including Slick Rock subcontract documents & Vols I-IV to Slick Rock design calculations. Comments requested ARTHUR, W.J. Energy, Dept. of . UMT/NRC/0388-32. 88/03/29. LOHAUS, P. NRC NO Detailed Affriation Given. 2pp. 45080-081-45088-264.
- --8804110015 "UMTRAP Stick Rock CO.Preliminary Design for Heview Repts." Energy, Dept. of. 88/03/31. 17pp. 45080 083-45080:100.
- -8804110139 "UMTRAP Slick Rock,CO,Preliminary Design for Review,Info for Review ers." * Energy, Dept. of. 88/03/31, 53pp. 45080.101-45080.153
- --8804110016 Vols I-IV to, "UMTRAP Slick Rock,CO,Info for Bidders." Energy, Dept. of. 88/03/31, 1,300pp. 45080;164-45083 289
- --8804110020 Vols 1-IV to, "UMTRAP SIlck Rock, CO, Preliminary Design for Review Calculations" * Energy, Dept. of. 88/03/31, 2,000pp. 45083;200-45087;342.
- -8804110022 "UMTRAP Slick Rock,CO,Preliminary Design for Review SRK Subcontract Documents,Bid Schedule,Special Conditions,Specs, Subcontract Drawings."

 * Energy, Dept. of. 88/03/31, 200pp. 45088:001-45088:284.
- 8804110045 Forwards set of consultation notes for discussion purposes
 * NRC No Detailed Affiliation Given 86/03/09. NRC No Detailed Affiliation Given. 13pp. 45123:287-45123:309.
- 8804110047 Forwards Mar 1988 rev to Clive,UT remedial action inspiplian incorporating 871226 proposed mode & 880129 comments for review & concurrence Review & approval of plan requested within 21 days of lit receipt. ARTHUR,W J. Energy, Dept. of, UMT/MRC-0388-30, 88/03/30, UOHAUS,P. Operations Brench. 1p. 45089:013-45089:056.
- --8804110259 "Remedial Action Insp Plan." * Energy, Dopt. of, 88/03/30, 43ρρ, 45089.014-45080.056.
- 8804110081 Forwards documentation representing chronology of NNWSI project peer review process currently being used to review document prepared by JS Szymanski. BLANCHARD,M. Energy, Dept. of. 88/02/23. KALE,S. Energy, Dept. of. 34pp. 45129:229-45129:282.
- 8804110069 Forwards executed Mod A002 to Cooperative Agreement DE-FC04-82AL20538 between DOE & State of ND for tries. DIXSON G.R. Energy, Dept. of 88/03/31, KNAPP,M. Office of Nuclear Material Safety & Safeguards,Director
- 8804110223 Forwards "UMTRAP Integrated Monthly Vicinity Property Progress Rept (VPPR) 26 for Feb 1986."

 HOLDERNESS,J.W. Jacobs Engineering Group, Inc. JEGA/UMT/0388-0, 88/03/30.

 ARTHUR,W.J., FISKE,W. Energy, Dept. of. 2pp. 45078:001-45078:037.
- --8804110233 "UMTRAP Integrated Monthly Vicinity Property Progress Rept (VAPR) 26 MOORE Energy, Dept. of. 88/02/28, 35pp. 45078:003-45078:037.
- 8804120074 Forwards J Warner Itr rept on "Capabilities & Limitations of Borehote Geo-physics in Felsels Tuffs & Related Rocks at Yucca Mountain, NV." JUSTUS P.S. Division of High Level Waste Management (Post 870413), 88/03/29. BALLARD,R.L. Technical Review Branch. 2pp. 45089.353-45089:360.

- ---8804120082 Ltr rept, "Capabilities & timitations of Borehole Geophysics in Folsic Tults & Related Rocks at Yudda Mountgins NV."

 WARNER J. Technical Review Branch 88/03/28 JUSTUS,P.S. Technical Review Branch 5pp 45089:356-45089:360
- 8804120137 Requests Engineers Infl. participation in 880202 conceptual review strategy meeting in Rockville, MD Meeting participant should be prepared to discuss open items associated w/NNWSI conceptual resign.

 BUCKLEY, J.T. Teichnical Review Branch, FIN 0-1004, 89/01/27, SNGH,M. Engineers International, Inc. 2pp. 45090:228-45090 227
- 8804120183 Commonts on monthly progress rept for Dec 1987 re status of activities under Contract NRC-02-85-009 Overtail progress to date termicd satisfactory. POHLE_I.A. Technical Review Branch FIN D-1021. NRC-02-85-009 88/02/12 LOGSDON,M.J. Nuclear Waste Consultants, Inc. 3pp.45079.313-45079.315.
- 8804120233 Requests that CNWRA contract to modified to list WH Ford as project offi-cer for Sublask 4.1 in georogic setting program element. FORTUNA.S L. Drus on of High Level Weste Management (Post 870413). 68/03/33 MACE,M. Division of Contracts (Post 870413). 2pp. 45099 258 45099 259
- 8804120262 Comments on R Guzowski draft licensing assessment methodology interim rapt Comments not expected to be addressed in rovised ropt Suggestions for changes to rept tables & copies of lines NRC repts end W/o end.

 GALSON,D.A. Operations Branch FIN A-1165 88/03/24 CRANWELL,R.M. Sand a National Laboratories. 9pp. 45079:323-45079.331.
- 8804120271 Requests detetion of Chapters 3.4.5 & 10 from final version of revito NUREG/CR-3964, "Techniques for Estimating Probabilities of Events & Processes Affecting Performance of Geologic Repositories Literature Review." GALSON, DA Operations Branch. FIN A-1165 88/03/24 CRANWELL,R M Sandia National Laboratories. 2μp. 45080 079-45080.080.
- 8804120324 Requests that contractor be notified that operations plan to research program elament has been approved sub, to listed mandatory changes
 FORTUNA,S.L. Division of High Level Waste Management (Post 870413), 88/03/31
 MACE,M. Division of Contracts (Post 870413), 4pp. 45090 077-45090 080
- 8804120357 Requests porformance of stated work under Task Orders 001 & 006,including proparation of draft topical repts re enalyses of alternative waste emplacement concepts on performance of drifts & boreholes & disturbed zone
 TIKTINSKY,D.H. Technical Review Branch. FIN D-1016 NRC-02-85 002 88/03/28
 HART,R. ITASCA Consulting Group, Inc. 4pp. 45089.278-45099.281.
- 8804120371 Summary of 880324 mgt moeting w/DOE re high level waste YOUNGBLOOD,R.J. Operations Branch, 88/03/30, FHOMPSON,Hit. Office of Nuclear Material Safety & Safeguards,Director, 2pp. 45089,324-45089,325.
- 8804120386 Submits commonts on Cir for Nuclear Waste Regulatory Arialyses program manager Period c Rept 88-5 for 880123-0219. Serious concerns re status of Task 1 in geologic program solting plemont addressed in separate III. FORTUNAS.L. Office of Nuclear Material Safety & Safequards Director, NRC-02-88-005, 88/03/31, LATZ,J. Southwest Research Institute. 4pp. 45089-349-45089-352.
- 8804120424 Requests attendance of T Snilf at DCE-NRC 880411-14 technical meetings on afternative conceptual models of ground water sys at Yucea Mountain Current version of workshop agenda enct. POHLEJA. Technical Review Branch, FIN D-1021, NRC 02-85 009 88/03/30 LOGSDON,M.J. Nuclear Waste Consultants, Inc. 5pp. 45091.005-45091 009
- 8804120429 Forwards ASCII formatted electronic filos of operations plans data for FY88-69-Enct provides individual filo names & descriptions of contents for each file. JOLINSON, R.D. Southwest Research Institute 88/03/16 STILTENPOLEB Division of High Level Waste Management (Post 870413). 2pp. 45091:151-45091.152.
- 8804120440 Advisos that response to NRC comments on project manager periodic rept for Period 3 (871121-1218) satisfactory
 FORTUNASL. Division of High Level Weste Management (Post 870413) 88/03/30.
 LATZ,J. Center for Nuclear Weste Regulatory Analyses. 2pp. 45091:149-45091:150
- 8804120444 Forwards notice of upcoming meetings re NRC high level waste mgt program as result of 840827 FR notice.
 YOUNGBLOOD,B.J. Operations Branch. 88/04/41. Operations Branch. 2pp. 45091:024-45081.025
- 8804120471 Forwards third draft of paper entitled, "Distribution of Downward Flux in Unsaturated Hoterogenous Rock." Draft Includes clarification of positive pressures on Figure 7.
 WILLIAMS, R.E., Williams & Associates, FIN D-1020, 178, 88/04/07, POHLE, J. NRC - No Detailed Affiliation Given, 1p. 45090-174-45090-221.
- --8804120477 "Distribution of Downward Flux in Unsaturated Heterogenous Rock."
 BLOOMSBURG,G., WILLIAMS,R.E., OSIENSKY,J. Williams & Associates. FIN D-1020
 NRC-02-85-008, 88/04/30. NRC No Detailed Atti-ation Given 47pp. 45090 175-
- 8804120474 Forwards summary of 880229.0303 visit re NNWSI seismic monitoring program.List of attendees & USGS presentation also encl YOUNGBLOOD, B.J. Operations Branch. 88/03/18 STEIN, R. Energy, Dept. of. 59pp. 45090 097-45090;155.
- 8804130017 Discusses 880318 meeting w/DOE in Rockwile,MD re DOE 890120 responses to NRC comments on DOE NVO-196-17 & NNWI SOP-02-01 OA documents DOE will reconsider responses to NRC by amending responses or incorporating Into revised QA program.
 YOUNGBLOOD,BJ. Operations Branch. 88/03/24. STEIN,R. Energy, Dept. of. 3pp. 45099:309-45099.311.
- 8804130045 Submits comments from review of SWRI Ctr for Nuclear Waste Regula-tory Analysis draft QA manual dtd Feb 1988.per recipient 880229 direction.Review conducted to determine broad compliance will isled requirements. VQLTURAN Operations Branch 88703721. KENNEDY,J. Operations Branch. 12pp 45122:246-45122:257.

- 8804130056 Comments on Feb 1986 monthly progress rept under Contract NRC-02-84-002 submitted by Engineers IntliTask Orders 001-006 completed & itr summarizing review status of Doaf Smith design should be submitted BUCKLEY_JIT_Technical Review Branch, FIN O-1004_NRC-02-84-002_88703730. SINGH_MIM_Engineers International, line 4pp. 45099.348-45099.351
- 8804130057 Comments on "Geochemical Sanstiwity Analysis," monitity progress rept for Feb 1988 Progress satisfactory to date Informs that "Inform Rept on Geochemical Sensitivity Analysis" for FY84-85 currently under row ew. 8EMBIA.P.J. Technical Review Branch, FIN A-1756 50-19-03-01 8B/Q4/05 SIEGEL,M.D. Sandia National Laboratories, 13pp. 45147,293-45147,305
- 8804130078 Forwards comments on Hitman Nuclear Svcs supplemental test plan presented at NRC 880328 meeting Recommends thought be given to enticipating results of each test 8 effect of results on assessment of Hitman waste forms. PETERSONIC H. Technical Review Branch. 88/03/31. TOKARIM. Rechnical Branch. 3pp. 45099 260-45099 262.
- 8884130083 Ack receipt of 880202 tir transmitting rept entitled, "Conceptual Considerations of Doalth Valloy Groundwater Sys W/Special Emphasis on Adequacy of Sys to Accommodate High Level Nuclear Waste Ropps tory," by JZ Szymanski, DOE KAYMERER,C. Statu, Local & Indian Tirbe Programs, 88/02/19 LOUX,R R. Novada, Statu of, 1p. 45100.025-45100.028.
- 8804130090 Advisos that State of NV will attend alternative conceptual models meeting scheduled for 880411-14 State role not to generate models alternative to DOE as bas y for comprehensive understanding of site. LCUX,R R. Novadu, State of 86704/05 STEIN,R. Energy, Dept. of 2pp. 45154,088-45154,069
- 8804130099 Discussos additactivitos that should be conducted prior to finalizing CDSCP draft point papers by 880422 rolpost-closuro performance assessment COPLANIS. Operations Branch 88/03/24 LINEHANIJ Operations Branch 2pp. 45100-033-45100-034
- 8804130101 Forwards indice of upcoming meetings re NRC High Level Waste Mgt Program per 840827 FR notice.Notice will list tentative & firmly established meetings YOUNGBLOOD.B.J. Operations Branch 88/03/28 NRC - No Detailed Affiliation Given 2pp. 45099 296-45099 297.
- 8884130128 Corrocts possible NRC misinterpretation to author & DOE 880211 presentation on enhancements to UMTRAP QA program that program does not most quality requirements. Program is offective control as favorable NRC roview results venity. OLCHAN, J.G. MK-Forguson Co. 88.3050-214, 88703731, ARTHUR, W.J. Energy, Dept of 4pp 45122 224-45122 230.
- 8804130213 Forwards Mod 1 to "Remodial Action Plan & Site Concopiual Design for Stabilization of Inactive U Mil Tailings Site at Sall Lake City.UT." ARTHUR, W.J. Energy, Dept. of, UMT/NRIC/0488-39, 88/04/05, LOHAUS,P. Division of Low Love: Waste Management & Decemmissioning (Post 8/0413). Ip. 45145-211-45145-24.
- -8804130223 UMTRA-DOE/AL R01 Mod 1 to "Remedial Action Plan & Site Conceptual Dosign for Stabilization of finactive U Mil Tailings Site at Salt Lake City.UT." * Energy, Dept. at. 88/04/30, 41pp. 45145 212-45145;252
- 8804130216 Summary of 880324 mgt moeting w/OOE to high tovol waste. Agrees that QA mooting should be held in May to discuss any teedback from engoing workshop. YOUNGBLOOD,BJ. Operations Branch 80/00/30/30 THOMPSON,HL. Office of Nuclear Material Salety & Saleguards,Director. 3pp. 45122:195-45122.200.
- 8004130237 Forwards response to NRC review comments on Ritle Phase II preliminary design for review documents ARTHUR, W.J. Energy, Dept. of. 86/04/88 LOHAUS, P. Dwisten of Low Level Waste Management & Deceminiss energ (Post 970413) 67pp. 45175-146-45175-215.
- 8804130240 Forwards executed Mcd A011 to Cooperative Agreement DE-FC04-84AL20834 between DDE & State of OR DIXSON,G.R. Energy, Dopt. of 88/04/06, KNAPP.M. NRC - No Ostaled Affiliation Given 6pp 45147:282-45147.287.
- 8804130268 Forwards review of illustrative document dealing w/stress corresion cracking that would be of more immediate use in deering w/questions arising at recensing time for review, per recent checussions re NBS/NRC waste packaging database PETERSON,C.H. Technical Review Brench FIN A-4171. 88/04/06. INTERRANTE.C.G. Commerce, Dept. of, National Bureau of Standards, 13pp. 45122:185-45122-177.
- 8804130277 Advises that Task 1 to "Technical Assistance in Geophysical Methods for Site Characterization," should be modified as stated due to recent enactment of Nuclear Waste Policy Amerida Act.

 BALLARD, It. Technical Review Branch FIN D-1003, 88/09/03, BROWNING,R.E. Div.son of High Level Waste Management (Post 870413) 2pp. 45099,269-45099;269.
- 8604130335 "Lab Evaluation of COE Radionuclide Solubility Data & Selected Retardation Parameters," progress rept for Mar 4088, MEYER,R.E. Oak Regio National Laboratory, FIN 8-0290, 88/04/05, RRADBURY,J.W. Office of Nuclear Material Safety & Safeguards,Director, 4pp. 45155-001-45155.004.
- 8804130347 Requests participation in NRC DOE 880411-14 technical meeting in Las Vogas NV on alternatic conceptual mode's of groundwater sys at Yucca Mountain. GERT2CP Energy, Dopt. of 88/04/CG, SNYDERJ. Electric Power Research Institute 5pp. 45147-277-45147-281.
- 8804130353 Forwards Rev 0 to "Health Physics Monitoring Plan Green River,UT" Comments requested by 880502. ARTHUR,W.J. Energy. Dopt of UMT/NRC/0488-37. 83/04/06. LOHAUS,P. Division of Low Level Waste Management & Decommissioning (Post 870412) 1p. 45137:118-45137:149
- --8804130362 Rev 0 to "Health Physics Monitoring Plan Green River,UT." Chem-Nuclear Systems, Inc. 88/01/20, 31pp. 45437:119-45437:149.
- 8804130383 Discusses svcs rendered on high lovel waste repository performance assessment development for 880326-0409. Simplified version of chromium activity coefficient equation being developed for Monte Carlo calculations. MOLERIA B. Affiliation Not Assigned FIN A-4185. 88/04/08. CHANG.K.G. NRC No Detailed Affiliation Given 3pp. 45146:319-45146:321.

- 8804140024 Forwards notice of upcoming meetings w/DOE re NRC High Level Waste Mgt Program.
 YOUNGBLOOD.8 J. Operations Branch. 88/04/04. NRC No Detailed Affikation Given 2pp 45122:281-45122:282.
- 8604140152 Forwards proposed point paper for 880414 meeting w/new Advisory Committee on Nuclear Waste
 BROWNING.R.E. Division of High Level Waste Management (Post 870413) 88/04/
 11. STELLOV. Ofc of the Executive Director for Operations 3pp 45170,043-45170,045
- 8804140259 Comments on Monthly Mgi Ltr 17 dtd 880106 for month of Dec 1987 Trip repl by HL McKague received & distributed to appropriate stall for info & consideration.

 BLACKFORD M E. Division of High Level Wasie Management (Post 870413). FIN A-9297. 88/03/14. CHUNG,D.H. Lawrence Livermore National Laboratory. 3pp 45155:044-45155-046.
- 8804140352 Forwards NNWSI Numerical Evaluation Rept 8, "Use of Environ Tracers for Estimation of Recharge at Yucca Mountain, Summary (Subtask 15) & NNWSI Data Mgl Rept Update (Subtask 12)." W/o encl BASSE, B Nuclear Waste Consultants, Inc. FIN D-1021, 249, 88/04/06, NRC No Detailed Affiliation Given. 1p. 45163 355-45163.355.
- 8804140395 Ack receipt of 880318 ltr re US Szymanski rept & recipient description of ongoing internal peer review process State of NV role in reviewing site characterization program/ consultative draft charified. LOUX.F.R. Nevada, State of, 88/04/05, KALE,S.H. Energy, Dept. of, 3pp. 45170.334-45170.335.
- B804140417 Forwards master microfiche copies of the NNWSI Numerical Evaluation Rept. 8, "Use of Environ Tracers for Estimation of Recharge at Yucca Mountain Summary (Subtask 1.5) & NNWSI Data Mgt Rept Update (Subtask 1.2)." W/ o enct.

 BASSE.B. Nuclear Wasto Consultants, Inc. FIN D-1021, 250, 68/04/06, NRC No Detailed Afficiation Given. 1p. 45170.177-45170.177.
- 8804150071 Interim Change Notice to 033-NWMP-P 22.0, "Review of Technical Publications." RAMSPOTT, L.D., ORONKERS, J.J., Lawrence Livermore National Laboratory, 88/03/22, 3pp. 45167;111-46167;113.
- 8804150090 Forwards listed documents re high level waste OA plans KENNEDY,J E. Operations Branch. 88/04/12. BAILEY,I K. Records Services Branch (Pre 680103). 2pp. 45184:256-45190:340.
- --8804150282 Rev E to draft "QA requirements for High Level Nuclear Waste Repository Program."
 *Energy, Dept. of, 88/02/05, 70pp. 45184 262:45184-331.
- --8804150288 Rev. C. to draft. "OA Program Description for Headquarters (Ofc. of Civilian Hadwaste Mgt)." "Energy, Dept. of. 88702705, 48pp. 45184:332-45185.060.
- --8804150402 Forwards NNWSI project confrolled documents fist PRESTHOLT,P.T. NRC - No Detailed Affiliation Given 87/09/01. STABLEIN,K. NRC -No Detailed Affiliation Given. 9pp. 45185 073-45185.081
- --8804210093 Rev 1 to QMP-16-02, "Trend Analysis"
 Energy, Dept. of. 87/03/27, 4pp. 45185:132-45185:135.
- --8804150418 Rev O to OMP-16-03, "Std Deficiency Reporting Sys." * Energy, Dept. of, 87703727, 17pp. 45185:136-45185:152
- --8804150418 Rev 1 to OMP-18-01, "Audits." * Energy, Dept. of, 87/03/27, 25pp, 45185:153-45185:177.
- --8804150426 Rev O to OMP-18-02, "Surveillance" KLEIN,S.H. Energy, Dept. of. 88/04/20, 7pp. 45185:178-45186.017
- --8804150317 "Technical & Mgt Support Svcs QA Program Plan & Supporting Documents." Science Applications International Corp. (formerly Science Applications, Inc.) 87/11/30, 400pp. 45186:018-45187-231.
- --8804160330 "Nuclear Waste Mgt Program QA Program Plan."
 * Lawrence Livermore National Laboratory, 88/03/01, 300pp. 45187:232-45188 274
- --8804150345 "Holmes & Narver,Inc Energy Support Div NNWSI OA Program Plan" * Energy, Dept. of. 88/02/04, 105pp. 45188:275-45189.019.
- --8804150352 "Dopt 8310 NNWSI OA Program Plan." RICHARDS,R.R. Sandla National Laboratories. 87/04/01, 106pp. 45189.020-45189 125.
- --8604150355 Rev 5 to QA program plan for NNWSI project. * REECO, 88/01/07, 200pp. 45189:126-45190.089.
- --8804150367 Rev 2 to QA program plan for NNWSI. REGENDA,MJ. Fenix & Scisson, Inc. 88/02/16. 95pp. 45190.090-45190:188.
- --8804150371 Rev 0 QA plan for NNWSI.
 * Energy, Dept. of, 87/01/31, 100pp. 45190:189-45190:340.
- 8804150273 USGS-SIP-3221G-01 R0 NNWSI Project USGS Scientific Investigation Plan USGS-SIP-3221G-01, "Geophysical Investigations Gravity & Magnetic Methods "OLIVER.H.W., HEALEY,O.L., WILLMON.J. Interior, Dept. of, Geological Survey, 87/12/08, 28pp. 45170.045-45170.072,
- 8804160291 Forwards Mod A022 to Cooperative Agreement DE-FC04-81AL 16309 hetween DOE & State of UT.Mod increases State of UT FY88 cost estimate & associated DOE & state funding obligations.
 HERRERA,E.Y. Energy, Dopt. of, 88/04/05, MARTIN,D.E. Office of Nuclear Material Selety & Safeguards, Director, 8pp. 45192:260-45192:255.

- 8804150305 Forwards undated agenda for NRCZ/DQE technical meeting on alternate conceptual models of groundwater sys at Yucca Mountain Meeting scheduled for
 - GERTIC P Energy, Dept. of 88704706 LOUX,R.R. Nevada, State of 4pp. 45192 233 45192 236
- 8804 180002 Forwards comments on changes to Grand Junction preferency design for review documents to final design for review, inadvertently omitted from 880324 trans-
- ATTITUR,W.J. Energy, Dept. of LMT/NRC/0488-43 88/04/11, LOHAUS,P. Division of Low Level Waste Management & Decemmissioning (Post 870413). 14pp 45184 064-45184 07G
- 8804 180003 Forwards draft "Summary of Groundwater Tosting Methodofegies Applica-hio to Unsaturated Fractized Rock At Yucca Mountain "Repl updated to lesting tech-niques proposed in consultation draft SCP OSILNSKY JL Williams & Associatos FIN D-1020 NRC 02 85 008 88/03/28 POHLLJ TRC No Detailed Affiliation Given 1p 45184 078-45184.141
- --8804180006 Draft "Summary of Groundwater Testing Mulhodolog as Applicable to Un-saturated Fractured Rock at Yucca Mountain" * Williams 8 Associates FIN D-1020-88/03/31, 63pp, 45184-079-45184-141
- 0804180005 Confirms 880411 conversation Engineered barrier sys operations plan inordited plates mandatory changes have been informally sent to ctrito determine potential impaction ctrickwires Agrees to meet on 880412 to resolve issues FORTUNA,SIL Systems Engineering & Evertuation Branch 8804411, PEARRING, J.R. NRC No Detailed Milliation Givon 2pp 45170 117-45170 118.
- 8804180008 Requests comments on encl RNWL response to joint QA Audi. 8801 re selected INNWL activities by 880415.Ack recept of 880331 checklists & audit rept. & H Shaw 880401 rept. ANTTONEN.J.H. Energy, Dept. of 88-QSD-056, 88704707, DRONKERS.J. Lawrence Livermore National Laboratory. Ip. 45184 077-45184.077.
- 8804180018 Forwards briefing package used by J Konnedy in recent briefing to Div of High Level Weste Mgt for consideration of draft rev to NRC review plan IDELLIGATTIM.S Systoms Engineering & Evaluation Branch 88/04/11
- 8804180022 Responds to 880301 ltr re NRC comments on WSE&I Major Milostone IQuer 180405 & 06 discussions in San Antonio,TX, NRC request that every major milustrop be standalone document will be discussed at 880418-10 mgt medings HUNTING_JO Systems Engineering & Evaluation Branch 88/04/12 LATZ_JE Conter for Nucleur Waste Regulatory Analyses 2pp 45175-359-45175-360
- BB04190169 "Evaluation & Compilation of DOE Wasto Packago fast Data." monthly rept for Mar 1989.
 INTERIANTEC. G. Commerce, Capt. of, National Bureau of Standards FIN A 4171 BB/04/15, PETERISON, Division of High Lavel Waste Managament (Post 870413) 41pp 45208 337 45200 017
- 8804190339 Advisos that QA audit of USGS Monto Park,CA facility QA program plan & quality-related activities will be conducted on 880426-28 Areas to be audited & audit SLAYLOCK, J Energy, Dept. of. 98/04/13, HAYES, L.R. Interior, Dept. of, Geological Screen 2pp. 45216-349-45218-350.
- 8804190349 Forwards OA Stid Delicioncy Ropts 117 to 125 & 127 to 129 from Aud-L88-2 on #80328-0401 Significant delicioncy rept (SDR) 126 will be issued as observation, rather than rept. Responses to each SDR required within 20 days. BLAYLOCKJ. Energy, Dept. of 88/04/12 CALOVINIJC Holmes & Narver, Inc 27pp. 45209-020-45209-039.
- 8804190350 "NNWSLOA Program Plan" DROKERS J. Lawrenco Livermore National Leboratory, 88704711, 37pp. 45218.032-
- 8804190355 Rev 3 to OA program plan REGENDA.M.J., CROSS.J.A. Fonix & Scisson, Inc. 88/04/13 44pp 45220-140
- 8804190363 Table of contents to "T&MSS QA Program Plan & Supporting Documents" SPAF, (H.M. Science Applications International Corp. (formerly Science Applications, Inc.) 88/04/11, Spp. 45215-215-45215-219.
- 8804190372 Revised Waste MgI Project Otc OA plan including Rev 0 to QMP-01-02, "Stop Work," Rev 0 to QMP-04-01, "Procurement Document Controt," Rev 0 to QMP-05-01, "Preparation & Controt of Quality MgI Procedures" & Rev 0 to QMP-07-03. GIRTZC Science Applications International Corp. (formerly Science Applications, Inc.), 88/04/11 41pp. 45225.001-45225-041.
- 8804190384 Forwards draft point papers resulting from NRC technical review of consultation draft after characterization plan for Yucca Mountain,NV s.te.Significant concerns listed Papers will be used for workshops w/DOE in Mar & Apr. STELLO,V. Offic of the Executive Director for Operations 88/03/17, ZECH, ROBERTS, BERNTHAL Commissioners, 4pp. 45225.042-45225.250
- 8804200032 "Technical Assistance for In Situ Testing," monthly progress rept for Mar SINGH,M.M. Enginoers International, Inc. FIN D-1004, 1148-07-16 88 BUCKLEY,J.T. NAC - No Dotallod Affiliation Given 6pp. 45218:148-45218.153.
- B804200041 "Tochin.cal Assistance in Goochemistry," progress rept for Mar 1988. KELMERS,A.D., GOVE,R.M., CATLETT,C.R. Oak Ridge National Laboratory, FIN 8-0287-8 08704707. BROOKS,D.J. Tochnical Review Branch. 4pp 45219.049.
- 8804200232 Forwards addit rofs clied in Jan 1988 site characterization plan consultation draft for NNWSI project Addit documentation encl. GERTZ.C.P. Energy, Dopt. of. 88/04/15. LINEHAN.J.J. Division of High Level Waste Management (Post 8704/13). 31pp. 45235:111-45235:161.
- --8804200281 "Wasto Mgi Project Rept QA Audit Rept for 880223-880302." BLAYLOCK, J. Energy, Dept. of. 88/04/15 13pp 45235:149-45235.161.
- 8804200563 Press release announcing award of DOE contract to remove asbestos from U mill to Southwest Hazard Control Inc. Work began 880328 & scheduled to be comploted in Jul 1988. MCCARTY, B E., HOOPES, J. Energy, Dept. of. 88/04/11. 1p. 45219 048-45219 048.

- 8804210037 Forwards attendeds list for Attachment C of Mar 1989 monthly progress rept Payes should be inserted after Page 31 of rept INTERPARTE, CG COmmerce, Dept of I National Bureau of Standards FIN A-4171 88/04/18 PETERSON, C Technical Review Branch Spp 45226 305-45226 310
- 8804210049 Advises of change in organization of Oto of Civillah Radwaste Mgt New or-ganization with nucrease emphasis on OA,taci ty Teensing sys integration & external interactions 0 organization chair end KAY,CID Energy, Dept of 887041/2 BROWNING,RIE Owision of High Level Waste Management (Post 870413), 2pp. 45235 317 45235 319
- --8804210193 Ofc of Civitian Redwaste Mgt chart
 * Energy, Dept of 88/04/30 1p 45235 319-45235 319
- 8804210344 WMPO quality mgt procedures including Rev 0 to QMP-01-02. Stop Wcrk, Rev 0 to QMP-01-01, "Procedures including Control," Rev 1 to QMP-05-01. "Preparation & Control of Quality Mgt Procedures." & Rev 0 to QMP-07-03. "Control of Quality Mgt."
- * Science Applications International Corp. (formerly Science Applications, Inc.): 687-04711, 44pp. 45224-108-45224-148
- 8804210365 Forwards Sa'l Repository Project Ofc weekly highlights for for period 880411-15
 NEFF.J.O Energy, Dept. of 321-88-PM 88/04/15 KALE,S.H. Energy, Dept. of 3pp. 45226.347-45226.349.
- 8804210389 Forwards DOE rept for week ending 880401 PRESTHOLT,PIT NRC No Detailed Atlivation Given 88704708 LINEHAN,J J. Operations Branch, 6pp. 45235,330-45235,335.
- 8904210455 Forwards WMPO OA SCR Number 087 resulting from review of files PRESTHOUL,P.T. NRC No Detailed Affiliation Given 88704708 KENNEDY,J.E. Cperations Branch, 4pp, 45239,001-45239,004
- 8804210463 Forwards CCE weekly rept for week ending 880325 L. Skousen will make drawings referenced in Item II, "Sign foamt Accomplishments/Info items" available to NRC.
- PRESTHOLT,P.T. NRC No Datated Alfriation Given 86/04/06 LINEHAN,J.J. Oper-etions Branch, 5pp. 45226,337-45226,341.
- 8804220249 Requests extension of delivery date for project plan for RES 5 until 880429 Extension necessary because work on development of Waste Sys Engineering 8 Integration Major Milestone 18 more extensive than planned LATZ J.F. Center for Nuclear Waste Regulatory Analyses. LATZ J.E. Southwest Research Institute. NRC-02-88-005-88704712. MACE,M.H. NRC No Detailed Afficiation Given. 1p. 45257-233-45257-233.
- 8804260115 Trip rept of Geological Society of America 880325-0402 Corditeran section meeting & field trips in tas Vegas,NV RANEY,H.G. Geological Society of America. FIN D-1018. NRC-02-85-004. 88/04/02 Geological Society of America. 85pp. 45280-005-45280-099
- 8904260122 Forwards record of docision (ROD) for final environ impact statement (FEIS), "Disposal of Hanford Defense High Level, Transurance & Tark Wastes." ROD states DDE docision to use preferred effective from FEIS for disposal of wastes I AWRENCE MJ Engry, Dept. of 88704708 NRC No Dataled Afficiation Green 10pp. 45258 339-45258 349
- 8804260151 Forwards wasteimgt project ofc QA Audit 68-2 on 980328 0401 of Holmes & Narvorlinc Audit confirmed that implementation of certain basis requirements must be improved to achieve full compliance w/Rey 5 to NNWSI Project QA Plan NVO-196-17
- BLAYLOCK J. Energy, Dept. of. 88/04/21, CALOVINI, J.C. Holmes & Narver, Inc. 3pp. 45259 305-45250,335.
- --8804260170 "WMPO OA Audit Rept of Holmes & Narverlinc, Las Vegas, NV." conducted on 880328-0401. * Energy, Dept. of 88704720, 29pp. 45259,308-45259,335
- 8804260182 Interim change notice to 033 NNWSLP 13.1, "Collection, Storage & Distributton of J.13 Water DRONKERS.J Lawrence Livermore National Laboratory 88/04/18. 3pp. 45282 062-45282 064
- 8804260214 Forwards documents re preliminary design for Spock,WY, U mili tailings site & responses to 871015 comments on spook draft remedial action plan. ARTHUR,W J. Energy, Doptilot. 88/04/22 LOHAUS,P. NRC No Detaired Affiliation Griven 3pp. 45328-001-45330-361.
- -- 8804260238 "U Mill Tailings Remedial Action Project (UMTRAP-AML) Calculations (UMTRAP) "
 * Energy, Dept. of. 68/04/30, 188pp. 45328 604-45328 215.
- --8804260249 "U Mili Tailings Remedial Action Project (UMTRAP-AML) Calculations (AML)."
 * Energy, Dept. of: 88/04/30: 237pp: 45328 216:45329 101.
- --8804260255 "U Mrl Tarings Remedial Action Project (UMTRAP-AML) Subcontract Energy, Dept. of 88/04/30, 247pp 45329 102-45329 3\$2
- --8804260262 "U Mr. Tailings Remedial Action Project (UMTRAPIAML) Into For Bidders," Vols I & II Energy, Dept. of, 88/04/30, 510pp. 45329 353 45330 361
- 8804260344 Forwards Document Review 006-0157(a), "Chapter 2 NNWS! Consultation Draft Site Characterization Plan" HART,R.D. (TASCA Consulting Group, Inc. FIN D-1016 NRC-02-85-022 89/04/18 TIKTINSKY,D. NRC No Detaired Attriation Given 13pp 45253 050-45253 062.
- 8804260351 Forwards NRC draft point papers on DOE 680108 consultation draft site characterization plan for Yucca Mountain site, for into TANAET Operations Branch 88/03/09. Affiliation Not Assigned 8pp 45251.105

- 8804260356 Forwards newspaper article for info.
 PRESTHOLT P.T. NRC No Detailed Affiliation Given. 88/04/19, LINEHAN,J.J. NRC No Detailed Affiliation Given. 3pp. 45281:038-45281:039.
- 8804260359 Forwards exploratory shaft facility respository interface Control Drawing R07048A & request for NRWSI milestone list. PRESTHOLT.P.I. NRC No Detailed Affiliation Given. 88/04/15. LINEHAN, J.J. Operations Branch. 1p. 45281:327-45281:329.
- -8804260363 Forwards exploratory shaft facility repository interface Control Drawing R07049A.W/o enct. GERTZ,C.P., Energy, Dept. of. 88/04/13. PRESTHOLT,P.T. NRC • No Detailed Affiliation Given. 2pp. 45281;328-45281:329.
- 8804260381 Exploratory shaft facility subsystem design requirements document.

 * Science Applications International Corp. (formerly Science Applications, Inc.). 887
 04/14. 5pp. 45281:040-45281:044.
- 8804260368 Forwards NNWSI project annual rept on interactions w/pass & rept on use of performance allocation in NNWSI site characterization plan.
 PRESTHOLT.P.T. NRC No Detailed Affiliation Given. 88/04/19. LINEHAN,J.J. NRC No Detailed Affiliation Given. 1p. 45281:045-45281:055.
- -8904260370 Forwards "Annual Performance Assessment Support Svc Interaction Rept," & "Rept on Use of Performance Allocation in NWSI Site Characterization Plan." GERTZ,C.P. Energy, Dept. of. 88/04/14, PRESTHOLT,P.T. NRC - No Detailed Affiliation Given, 10pp. 45281:048-45281:055.
- 8804260372 Forwards verification of committed corrective actions to waste mgt project of a QA std deficiency repta generated against NNWSI project organizations, PRESTHOLT,P.T. NRC No Detailed Affiliation Given. 88/04/16. KENNEDY,J.E. NRC No Detailed Affiliation Given. 3pp. 45282-013-45282-015.
- 8804260376 Submits schedule for upcoming Intil Symposium on Unique Underground Structures. SINHA.R.S. Interior,Dept.of, Bureau of Reclamation. D-270. 88/04/19. NATRAJA,M. NRG - No Detailed Affiliation Given. 2pp. 45282:011-45282:012.
- 8804260378 Forwards comments on draft document "Probabilistic Safety Assessment for Selemic Events."

 IBRAHIM,A. Technical Review Branch. 88/04/20. GIULIANI,P. International Atomio Energy Agency. 31pp. 45281:340-45282:010.
- 8804260390 "Technical Assistance in Hydrogeology Project 8 Analysis," monthly progress rept for Mar 1988. Attachment A. "Financial & Administrative Rept" withheld. LOGSDON,M.J. Nuclear Waste Consultants, Inc. FIN D-1021. 253, 88/04/15. POHLE,J. Technical Review Branch. 12pp. 45259:291-45259:302.
- 8804260401 Forwards "Project Plan for Selsmic/Rock Mechanics Project," for comment. LATZ.J.E. Center for Nuclear Waste Regulatory Analyses. NRC-02-88-005, 88/04/14. MACE,M. Division of Contracts (Poet 870413). 1p. 45227:045-45227:138.
- -8804190384 Draft "Project Plan for Seismic/Rock Mechanics Project."
 NAIR,P., WHITING,A.R., PATRICK,W.C. Center for Nuclear Waste Regulatory Analyses, NRC-02-88-005, 88/04/30, NRC No Detailed Affiliation Given, 92pp, 45227:046-
- 8804280001 Summarizes 880314 meeting w/McKee,Hopl Tribe,Navajo Nation & Bureau of Indian Affairs in Albuquerque,NM re resolutions for open issues concerning test piots const at Tuba City site.Proposed excavation tocations & sampling plan encl. DrANTONIO,J.R. Fengry, Dept. of. 88/04/16. HAWKINS,E.F. Uranium Recovery Field Ofc, R4. 4pp. 45268:176-45266;179.
- 8804280131 Responds to 880302 ftr re acceptance review of Mexican Hat preliminary final remedial action plan. More detailed discussion will be provided after DOE & NRC reach general agreement on into needed to demonstrate compliance. W/enci. MANN,D.E. Energy, Dept. of. 88/03/24. HAWKINS,E.F. Uranium Recovery Field Ofc, R4. 3pp. 45263:027-45263.029.
- 8804280185 Requests approval of RAP open Issues to complete Lakeview remedial actions this const season per 880316 ftr.
 ARTHUR,W.J. Energy, Dept. of, UTM/NRC/0488-40, 88/04/08, HAWKINS,E.F. Uranium Recovery Field Otc, R4, 3pp. 45266:171-45286:173.
- 8804280473 Forwards Rev 1 to Durango,CO remedial action inso plan,for review & concurrence. Plan adequately addresses inso activities & consistent remedial action plan,design spacs, UMTRAP requirements & Rev 1 of NRC technical position. MATTHEWS,ML. Energy, Dept. of. 88/02/05. HAWKINS,E.F. Uranium Recovery Field Oto, R4. 1p. 45284:086-45264.096.
- 8804280494 Forwards Riverton remedial action insp plan for review & approval within 21 days per DOE/NRC MOU. MATTHEWS.E.F. Energy, Dept. of. 88/01/08. HAWKINS.E.F. Uranium Recovery Field Oto, R4. 1p. 45282:380-45262:380,

WASTE RES WASTE MANAGEMENT RESEARCH REPORTS

Ridge National Laboratory, 3pp. 45089:071-45089:073.

- 8802040318 "Technical Assistance In Identification & Evaluation of Seismo-Tectonic Issues re Repository Site Characterization Plans," Monthly Mgt Ltr Rept 17 for Dec 1987.
 - CUMMINGS,G.E. Lawrence Livermore National Laboratory, FIN A-0297. 88/01/06. BLACKFORD,M.E. Technical Review Branch. 4pp. 45234:344-45234;347.
- 8803090196 Comments on Dec 1987 monthly progress rept, "Technical Assistance in Geochemistry." Progress to date satisfactory. Actions taken by its within scope of cur-rent Contract FIN B-0287. BROOKS, D.J. Division of High Level Weste Management (Post 870413), FIN B-0287, NRC-50-19-03-01, 88/02/19, KELMERS, A.D. Oak Ridge National Laboratory, 3pp. 45089:085-45089:087.
- 8803090237 Dicusses review of 1987 monthly progress rept for 8-0290, "Lab Evaluation of DOE Radionuclides Solubility Data & Selected Retardation Parameters, Experimental Strategies, Lab Techniques & Procedures." Progress satisfactory.
 BRADBURY,J.W. Technical Review Branch. FIN 8-0290, 88/02/19, MEYER,R.E. Oak

- 8803090345 Comments on 880208 monthly progress rept, describing status of Williams & Assot technical assistance under Contract NRC-02-85-008. Progress made to date satisfactory.

 POHLE,J.A. Technical Heview Branch. FIN D-1020. NRC-02-85-008. 88/02/24.

 WILLIAMS,R.E. Williams & Associates. 3pp. 45099:254-45099:257.
- 8803140355 Comments on progress rept for 880208-09 Provision of assistance to NRC & Ctr for Nuclear Waste Regulatory Analyses in transfer so that emergency broadcast sys work can continue w/o delay requested. CHANG, K.C. Technical Review Branch. Fin A-4185. 88/03/09. STEPHENS,K.W. Stephens & Associates. 4pp. 45089:067-45089.070.
- 8803300336 Forwards second draft of "Distribution of Downward Flux in Unsaturated Heterogeneous Rock." WILLIAMS,R.E. Williams & Associates, 88/03/24, POHLE,J. NRC No Detailed Affiliation Given. 2pp. 44979:052-44979:100.
- —8803300340 "Distribution of Downward Flux in Unsaturated Heterogeneous Rock." BLOOMSBURG.G., WILLIAMS.R.E., OSIENSKY,J. Williams & Associates. NRC-02-85-008, 88/03/31. NRC No Detailed Affiliation Given. 47pp. 44979:054-44979:100.
- 8803310204 "Licensing-Methodology Assistance," monthly rept for Feb 1988. CRANWELL,R.M. Sandia National Laboratories. FiN A-1165, 88/03/16. GALSON,D. Operations Branch. 46pp. 44984:263-44984:307.
- 8804060254 "High Level Waste Repository Performance Assessment Development," for period 880313-26, Voucher for prof svcs encl.W/o encl. MOLER, R.B. Systems Support, Inc. FIN A-4185. 88/03/27. CHANG,K.C. NRC No Detailed Affillation Given. 2pp. 45074:074-45074.075.
- 8804060504 Forwards trip rept re L Lorig & J Daemen participation in 880321 NRC/ DOE Workshop in Rockville,MD for NRC draft point papers on consultation draft site characterization plan for Yucca Mountain,NV site. HART,RC. ITASCA Consulting Group, Inc. FIN D-1016. NRC-02-85-002. 88/03/29. TIKTINSKY,D. NRC No Detailed Affiliation Given. 4pp. 45007:087-45007:102.
- -8804060610 Trip rept of 880321-24 visit to Rockville,MD re NRC/DOE Workshop on NRC draft point papers on consultation draft site characterization plan for Yucca Mountain,NV site.
 LORIGLU, ITASCA Consulting Group, Inc. FIN D-1016. NRC-02-85-002. 88/03/29, ITASCA Consulting Group, Inc. 12pp. 45007.091-45007:102,
- 8804060527 Final progress rept for activities under FIN A-4165 for 880309-29. STEPHENS,K.W. Stephens & Associates, FIN A-4165, 88/03/29, CHANG,K.C. NRC No Detailed Affiliation Given. 8pp. 45010:279-45010:280.
- 8804070167 "Technical Assistance in Identification & Evaluation of Seismo-Tectonic Issues re Repository Site Characterization Plans," Monthly Mgt Ltr Rept 20 for Mar 1988 CHUNG.D.H., CUMMINGS.G.E. Lawrence Livermore National Laboratory, FIN A-0297. 88/04/04. BLACKFORD,M.E. Technical Review Branch. 2pp. 45076:177-45076:178.
- 8804070239 Forwards comments on possible changes to CDSCP point papers re rock mechanics/design based on comments made at 880321 meeting w/DCE & internal discussions prior to meeting w/Zone oversize map. LORIG, L. ITASCA Consulting Group, Inc. FIN D-1016. 88/04/04, GUPTA,D., DAEMEN,J. ITASCA Consulting Group, Inc. 11pp. 45075:278-45075:289.
- 8804080001 Forwards comments on draft of Vol 4 of, "Evaluation & Compilation of ODE Waste Package Test Data, Biannual Rept," from Aug 1987 Jan 1988. PETERSON,C.H. Technical Branch. Fin A-4171. 88/03/31. INTERANTE,C.G. Commerce, Dept. of. 11pp. 45044:220-45044:230.
- 8804080004 Comments on monthly progress rept for Feb 1988 re status of activities under Contract NRC-02-85-009. POHLE, J.A. Technical Review Branch. FIN D-1021. NRC-02-85-009. 88/03/30. LOGSDON,M.J. Nuclear Waste Consultants, Inc. 4pp. 45079:254-45079:257.
- 8804080036 Discusses changes to FY88 Project A-0297, "Technical Assistance in Identification & Evaluation of Selsmic-Tectonic Issues re Repository Site Characterization Plan," per 880102 memo.

 BROWNING.R.E. Division of High Level Waste Management (Post 870413). FIN A-0297. 88/03/16. FUNCHES,J.L. Program Management, Policy Development & Analysis Staff (Post 870413). 16pp. 45116:234-45116:249.
- 8804080048 Responds to 880208 memo re review of Univ of Arizona quarterly progress rept, "Unsaturated Flow & Transport Through Fractured Rock re High Level Waste Repositories." Comments discussed in 880307 telcon doucmented. FORD.W. Technical Review Branch. FIN D-1682. 88/03/17. NICHOLSON,T.J. Waste Management Branch. 2pp. 45099:128-45099:129.
- 8804090054 Record of telcon w/Bureau of Mines (USBM) re transmittal of Work Okrectives 13 & 14 to USBM.Methodology rept currently under review by NRC editor.Comments to be transmitted to USBM in next rept.
 ABRAMS.C. Technical Review Branch. FIN C-1018. NRC-02-85-004. 88/03/17. 3pp. 45118.231-45118:233.
- 8804080089 Comments on preliminary draft point papers under Contract NRC-02-84-001,Task 22.New,timely into re-consultant draft SCP document & ongoing DOE activi-ties re-document requested. ties is occurrent requested.

 MURPHY,V.J. Weston Geophysical Corp. FIN D-1003. NRC-02-84-001. 88/03/29.

 (BRAHIM.A.B. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 45045:153-45045:164.
- 8804110142 "Geochemical Sensitivity Analysis," monthly rept for Feb 1988. CRANWELL,R.M. Sandia National Laboratories. FIN A-1756. 88/03/15. SEMBIA,P. Technical Review Branch. 10pp. 45077:324-45077:333.
- 8804120137 Requests Engineers inti participation in 880202 conceptual review strategy meeting in Rockville,MD.Meeting participant should be prepared to discuss open itema associated w/NNWSI conceptual design. BUCKLEY,J.T. International, inc. 2pp. 45090:226-45090:227.

- 8804120183 Comments on monthly progress rept for Dec 1987 ra status of activities under Contract NRC-02-85-009. Overall progress to date termed satisfactory. POHLE,J.A. Technical Review Branch. FIN D-1021. NRC-02-85-009. 88/02/12. LOGSDON,M.J. Nuclear Waste Consultants, Inc. 3pp. 46079:313-45079:315.
- 8804120262 Comments on R Guzowski draft licensing assessment methodology interim rept.Comments not expected to be addressed in revised rept.Suggestions for changes to rept tables & copies of three NRC repts encl.W/o encl. GALSON,D.A. Operations Branch. FIN A-1165. 88/03/24. CRANWELL,R.M. Sandia National Laboratories. 9pp. 45079:323-45079:331.
- 8804120271 Requests deletion of Chapters 3,4,5 & 10 from final version of rev to NUREG/CR-3964, "Techniques for Estimating Probabilities of Events & Processes Aflecting Performance of Geologic Repositories:Literature Review." GALSON,D.A. Operations Branch, FIN A-1185, 88/03/24, CRANWELL,R.M. Sandia National Laboratories, 2pp. 45080:079-45080:060.
- 8804120367 Requests performance of stated work under Task Ordera 001 & 008,including preparation of draft topical repts re analyses of atternative waste emplacement concepts on performance of drifts & boreholes & disturbed zone. TikTINSKY,D.H. Technical Review Branch. FIN D-1018. NRC-02-85-002. 88/03/28. HART,R. ITASCA Consulting Group, Inc. 4pp. 45069:278-45089:281.
- 8804120424 Requests attendance of T Sniff at DOE-NRC 880411-14 technical meetings on atternative conceptual models of ground water sys at Yucca Mountain.Current version of workshop agenda enci.
 POHLE,J.A. Technical Review Branch. FIN D-1021. NRC-02-85-009, 88/03/30. LOGSDON,M.J. Nuclear Waste Consultants, Inc. 5pp. 48091:005-46091:009.
- 8804120451 Forwards comments on NRC draft generic technical position, "Guidance For Determination of Anticipated Processes & Events." Review comments subdivided into listed categories. CHUNG,D.H. Lawrence Livermore National Laboratory, FIN A-0297, 88/03/29. BLACKFORD,M.E. Technical Review Branch. 7pp. 45091:083-45091:089.
- 8804120471 Forwards third draft of paper entitled, "Distribution of Downward Flux in Unsaturated Heterogenous Rock." Draft includes clarification of positive pressures on
- Figure 7. WILLIAMS,R.E. Williams & Associates. FIN D-1020. 178. 88/04/07. POHLE,J. NRC -No Detailed Affiliation Given. 1p. 45090;174-45090;221.
- -8804120477 "Distribution of Downward Flux in Unsaturated Heterogenous Rock." BLOOMSBURG,G., WILLIAMS,R.E., OSIENSKY,J. Williams & Associates, FiN D-1020, NRC-02-85-008. 88/04/30. NRC No Detailed Affiliation Given, 47pp. 45090:175-45090:221.
- 8804130056 Comments on Feb 1988 monthly progress rept under Contract NRC-02-84-002 submitted by Engineers intt.Task Orders 001-006 completed & its summarizing review status of Deaf Smith design should be submitted. BUCKLEY.J.T. Technical Review Branch. FIN D-1004. NRC-02-84-002. 88/03/30. SINGH,M.M. Engineers International, Inc. 4pp. 45099.346-45099.351.
- 8804130067 Comments on "Geochemical Sensitivity Analysis," monthly progress rept for Feb 1988.Progress satisfactory to date. Informs that "Interim Rept on Geochemi-cal Sensitivity Analysis," for FY84-85 currently under review. BEMBIA,P.J. Technical Review Branch. F/IN A-1766. 50-19-03-01. 88/04/05. SIEGEL,M.D. Sandia National Laboratories. 13pp. 45147:293-45147:305.
- 8804130268 Forwards review of illustrative document dealing w/etress corrosion cracking that would be of more immediate use in dealing w/questions arising at licensing time for review.per recent discussions re NBS/NRC waste packaging database.
 PETERSON,C.H. Technical Review Branch. FIN A-4171. 88/04/06. INTERRANTE.C.G. Commerce, Dept. of, National Bureau of Standards. 13pp. 45122:185-45122:177.
- 8804130277 Advises that Task 1 to "Technical Assistance in Geophysical Methods for Site Characterization," should be modified as stated due to recent enactment of Nuclear Waste Policy Amends Act. BALLARD.R.L. Technical Review Branch. FIN D-1003, 88/03/03, BROWNING,R.E. Division of High Level Waste Management (Post 870413), 2pp. 45099:268-45099:268.
- 8804130335 "Lab Evaluation of DOE Radionuclide Solubility Data & Selected Retarda-tion Parameters," progress rept for Mar 1988. MEYER, R.E. Oak Ridge National Laboratory, FIN B-0290, 88/04/06. BRADBURY, J.W. Office of Nuclear Material Safety & Safeguards, Director. 4pp. 45155:001-45155:004.
- 8904130383 Discusses avcs rendered on high level waste repository performance as-sessment development for 880326-0409. Simplified version of chromium activity coef-ficient equation being developed for Morte Carlo calculations. MOLER,R.B. Atfittation Not Assigned, FIN A-4185. 88/04/08. CHANG,K.C. NRC No Detailed Affitiation Given. 3pp. 45148:319-46148:321.
- 8804140259 Comments on Monthly Mgt Ltr 17 dtd 880106 for month of Dec 1987. Trip rept by HL McKague received & distributed to appropriate staff for info & consideration. BLACKFORD,M.E. Dwision of High Level Waste Management (Post 870413). FIN A-0297, 88/03/14. CHUNG,D.H. Lawrence Livermore National Laboratory. 3pp. 45155:044-45185:048.
- 8804140271 Comments on Monthly Mgt Ltr 19 dtd 880304 for month of Feb 1988. Any further work, on Amarillo-Wichita uplifit rept must be accomplished at LLL expense. NRC funds cannot be expended on BWIP or SRPO program studies. Progress satisfactory.
 BLACKFORD, M.E. Technical Review Branch. FIN A-0297. 88/04/11. CHUNG, D.H. Lawrence Livermore National Laboratory. 4pp. 45155:040-45155:043.
- 8904140352 Forwards NNWSI Numerical Evaluation Rept 8, "Use of Environ Tracers for Estimation of Recharge at Yucca Mountain, Summary (Subtask 1.5) & NNWSI Data Mgt Rept Update (Subtask 1.2)." W/o encl. BASSE, B. Nuclear Waste Consultants, Inc. FIN D-1021, 249, 88/04/08. NRC No Detailed Affiliation Given. 1p. 46163:356-46183:356.
- 8804140417 Forwards master microfiche copies of the NNWSI Numerical Evaluation Rept 5, "Use of Environ Tracers for Estimation of Recharge at Yucca Mountain;Summary (Subtask 1.5) & NNWSI Data Mgt Rept Update (Subtask 1.2)." W/ o enci. BASSE B. Nuclear Waste Consultants, Inc. FIN D-1021, 250, 88/04/08, NRC - No De-tailed Affiliation Given, 1p.,48170:177-48170:177.

- 8804180003 Forwards draft "Summary of Groundwater Testing Methodologies Applica-ble to Unsaturated Fractured Rock At Yucca Mountain." Rept updated re testing tech-niques proposed in consultation draft SCP. OSIENSKY_LL Williams & Associates. FIN D-1020. NRC-02-85-008, 88/03/26, POHLE,J. NRC No Detailed Affiliation Given, 1p. 45184:078-45184:141.
- -8804180006 Draft "Summary of Groundwater Testing Methodologies Applicable to Unsaturated Fractured Rock at Yucca Mountain."
 * Williams & Associates. Fin D-1020. 88/03/31. 63pp. 45184:079-45184:141.
- 8804190169 "Evaluation & Compilation of DOE Waste Package Test Data," monthly rept for Mar 1988.

 INTERRANTE.C.G. Commerce, Dept. of, National Bureau of Standards, FIN A-4171.

 88/04/15. PETERSON,C. Division of High Level Waste Management (Post 870413).

 41pp. 45206:337-45206:017.
- 8804190228 "Technical Assistance for in Situ Testing," status of Deaf Smith ESF 60% design review.

 HUCK.P.J. Engineers International, Inc. FIN D-1004. NRC-02-84-002. 88/04/11.

 BUCKLEY,J.T. NRC - No Detailed Affiliation Given. 2pp. 45208:333-45208:334.
- 8804190370 "Components of Overall Licensing Assessment Methodology."
 DAVIS.P., BONANO,E. Sandia National Laboratories. FIN A-1165, 88/
 GALSON,D, NRC No Detailed Affiliation Given. 125pp. 45217:265-45218:031.
- 8804 190388 Forwards "Technical Evaluation Rept on Envirality High Integrity Container Topical Rept TP-07-P.Rev 1."

 SISKIND,B. Brookhaven National Laboratory, FIN A-3951, 88/04/12, MCDANIEL,K. Division of Low Level Waste Management & Decommissioning (Post 870413), 1p. 45215:178-45215:196.
- -- 3804190356 "Technical Evaluation Rept on Enviralloy High Integrity Container Topical Rept 1P-07-P.Rev 1."
 COWGILLM.G. Brookhaven National Laboratory. FIN A-3851, 86/04/12. Office of Nuclear Material Sefety & Safeguards, Director. 18pp. 45215;179-45215;196.
- 8804200032 "Technical Assistance for In Situ Testing," monthly progress rept for Mar 1988. SINGH.M.M. Engineers International, Inc. FIN D-1004, 1148-07-18, 88/04/11, BUOKLEY,J.T. NRC - No Detailed Affiliation Given, 6pp, 45218:148-45218:183,
- 8804200041 "Technical Assistance in Geochemistry," progress rept for Mar 1988. KELMERS.A.D., GOVE,R.M., CATLETT,C.R. Oak Ridge National Laboratory, FIN B-0287-8. 88/04/07. BROOKS,D.J. Technical Review Branch. 4pp. 45219.049-45219.052.
- 8804200892 "Coupled Thermal-Hydrological-Mechanical Assessments & Site Character-ization Activities for Geologio Repositories," monthly rept for Mar 1988. CRANWELLR M. Sandia National Laboratories. FtN A-1755, 88/04/16. PESHELL, Di-vision of High Level Waste Management (Post 870413). 3pp. 45235:019-45235:021.
- 8804210037 Forwards attendees list for Attachment C of Mar 1988 monthly progress rept.Pages should be inserted after Page 31 of rept. INTERFANTE.C.G. Commerce, Dept. of, National Bureau of Standards. FIN A-4171. 88/04/18. PETERSON,C. Technical Review Branch. 8pp. 45226:305-45226:310.
- 8804210058 "Geochemical Sensitivity Analysis," monthly rept for Mar 1988.
 CRANWELL,R.M. Sandia National Laboratories, FIN A-1758, 88/04/15, MO,T. Division of High Level Waste Management (Post 870413), 7pp. 45235:193-45235:199.
- 8804210062 Monthly rept for Mar 1988 re Fin A-1158.
 CRANWELL,R.M. Sandie National Laboratories. Fin A-1158. 68/04/15.
 COLEMAN,N.M. Division of High Level Waste Management (Post 870413). 12pp. 45235:210-45235:221.
- 8804210208 Monthly rept for Mar 1988. CRANNELL,R.M. Sandia National Laboratories. FIN A-1185. 88/04/15. GALSON,D. Operations Branch. 34pp. 45235:289-45235:303.
- 8804260115 Trip rept of Geological Society of America 680325-0402 Cordilleran section meeting & field trips in Las Vegas,NV.

 RANEY,R.G. Geological Society of America. FIN D-1018. NRC-02-85-004. 88/04/02. Geological Society of America. 85pp. 45260:005-45280:099.
- 8804260344 Forwards Document Review 008-0157(s), "Chapter 2 NNWSI Consultation Draft Site Characterization Plan."
 HART,R.D. ITASCA Consulting Group, Inc. FIN D-1018. NRC-02-85-002, 88/04/18.
 TIKTINSKY,D, NRC - No Detailed Affiliation Given, 13pp. 45253:050-45253:062.
- 8804280348 Forwards document reviews under Contract NRC-02-85-002, Task Order 006,Task 1,Including Review 006-01-43: "Exploratory Shaft Facility Water Inflow Design Calculations."
 HAPT,R.O. ITASCA Consulting Group, Inc. FIN D-1016. NRC-02-85-002, 88/04/20. TIKTINSKY,D. NRC No Detailed Affiliation Given, 43pp. 45281:191-45281:233.
- 8804280387 Submits summary of effort for tasks under FIN A-4165 which have been addressed during 880418-25. FULLER,G.H. Affiliation Not Assigned, FIN A-4165.88/04/20. CHANG,K.C. NRC No Detailed Affiliation Given. 1p. 45259:273-45259:273.
- 8804260382 Forwards summary of work to date & requirements to complete project under Contract NRC-02-81-028.per 881104 proposel. ROSSELLE.C.J. Teknekron Transportation Systems, Inc. (formerly CorSTAR Research, Inc.). FIN 8-8985, NRC-02-81-026, 88/04/07, BROOKS,P. NRC No Detailed Affiliation Given. 3pp. 45281:288-45281:290.
- 8904260390 "Technical Assistance in Hydrogeology Project B Analysis," monthly progress rept for Mer 1988. Attachment A. "Financial & Administrative Rept" withheld. LOGSDON,M.J. Nuclear Waste Consultants, Inc. Film D-1021, 263, 88/04/16, PCHLEJ. Technical Review Branch, 12pp. 45259:291-45259:302.

258 NONDOCKETED ITEMS

XPORTLIC EXPORT AND IMPORT LICENSES

- 8804040197 License for Mitsui & Co USA, Inc to export 30 kg natural U.to Japan. PETERSON,M.R. Assistant Director for International Security. 88/03/28, 2pp. 44975.188-44976.189.
- 8804040255 Requests that Federal Republic of Germany be deleted as intermediate consigned in loreign country from 871026 application for amend to License XSNM-1770.
- YOSHIMURA,T. Nissho Iwai American Corp. FDN-88-007, 88/03/17, MOORE,R.N. International Programs, 3p. 44972:232-44972:232,
- 8804040284 Clanifes actual quantity boling shipped against license & also from which MMES location, per 860321 felcon. BUONCORE J.A. Mileul & Co. (USA), Inc. (subs. of Mitsul & Co., Ltd.). 88/03/21, WRIGHT, B. NRC No Detailed Affiliation Given. 1p. 44972:233-44972:233.
- 8804050104 Forwards Nissho-iwal American Corp application for amend to license to detelo NUKEM OmbH.Hanau Federal Republic of Germany as Intermediate consigned. End application should be considered in conjunction w/880806,870901 &
- total application application and the control of th
- --8804050106 Amond to application for ficense, deteting Nukern GmbH, Federal Republic of Germany from Intermediate consigned in foreign country. YOSI:#MURA, T. Nissko Livel American Corp. FDN-88-066. 88/03/17. MOORE, R.N. Office of Governmental & Public Affeire (Post 870413). 1p. 44997:057-44997:058.
- 8804050119 Ucense for Transnuclear, Ino to export 101.100 kg U-235, contained in 108 500 kg U, to Canada. PETERSON, M.R. Assistant Director for Export/Import & International Sefeguards. 88/ 03/28. 2pp. 44997:050-44997:060.
- 8804080137 License for DANA Corp to export four-clutch couplings to Japan.
 PETERSON M.R. Assistant Director for International Security. 88/03/25. tp. 45029.074-45029.075.
- 8804050170 Forwards application for amond to export License XSNM-2365 to decrease max enrichment of U-235 from 6% to 4% & max isotopic weight from 7 kg to 6 kg.Ltr of assurance required.
 PETERSON,M.R. Assistant Director for International Security, 88/03/29, ROONEY,J. Energy, Dopt. of. 1p. 44997.064-44997.068.
- --8804050178 Amend to application for license to export U-235,changing max weight from 5 to 4% (flom 19) & max isotope weight from 7 to 6 kg (flem 20). HUDEC,W.S. Westinghouse Electric Corp. WSH-057-86, 88703/24, WRIGHT,B. NRC NO Datallod Affiliation Givon. 1p. 44997:065-44997:066.
- 8804050196 Confirms telcon requesting special assistance in getting license granted as early as possible due to listed situation at Toshiba.

 OHYAMA,T. Mitsul & Co. (USA) Inc. (subs. of Mitsul & Co., Ltd.). 88/03/09.

 WRIGHT,D. NRC No Detailed Affiliation Given. 1p. 44997:076-44997:076.
- 8804050197 Requests Executive Branch position re enci Transnuclear, Inc application for amond to export license, deleting Federal Republic of Germany as Intermediate consignoe W/o onci.
 PETERSON,M.R. Assistant Director for International Security. 88/03/25.*
 TRIORNE,C.E. State, Dept. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs.
 1p. 44997.081-44997.081.
- 8804050230 Amond to application adding E-(49-14) UESJA027 to DOE contract number (Itom 9),changing max element weight to read 23,109 kg U & changing max isotope weight to read 768 kg U U-235.

 MARUYAMA,T, Mitsubishi International Corp. (subs. of Mitsubishi Corp.). HSA-6488-04. 89/03/23. MOORE,N. Assistant Director for Export/Import & International Sefeguards, 1p. 44997;127-44097;128.
- 8804050273 Forwards application for amend to export license to increase quantity of mail requested for export for consideration in conjunction w/original application forwarded on 880210.

 PETERSON,M.R. Assistant Director for International Security, 88/03/29. ROONEY,J. Energy, Dept. of. 1p. 44997:179-44997:180.
- 8804050337 License for Mitsul & Co (USA) Ine to export 35,700 kg UF6 to Japan. PETERSON,M.R. Assistant Director for International Security. MBK-DP-1, 86/03/28. 2pp. 46029:138-45029:138.
- 8804050338 Forwards Nissho-lwal American Corp application for amend to license XSNM-1779.deleting NUKEM GmbH.Hanau Federal Republic of Germany as intermediate consignee.Conjunction w/871103 amend request should be considered. PETERSONMR. Assistant Director for International Security. 98/03/29. THORNEC.E. Stato. Dopt. of, Bureau of Oceans & Intl. Environ. & Scientific Affairs. 1p. 44997:223-44997:224.
- -8504050394 Application for amend to export license deteting NUKEM GmbH, D-6450,Hanau 11,Federal Republic of Germany from intermediate consignee in foreign
- Country, YOSHIMURA,T. Nissho Iwel American Corp. FDN-88-007, 88/03/17. MOORE,R.N. International Programs. 1p. 44997:224-44997:224.
- 8804050349 Amend 1 to license for isotope Products Labs to export 300 mCi Po-210 to all countries not listed in 10CFR110.29 & 10CFR110.29. PETERSON,MR. Assistant Director for International Security. 86/03/25. 1p. 45029:139-45000000000000000000000000000000
- -8804050346 Application for amend to license, authorizing use of electroless deposited elemental Po-210 & polonium chloride in divide HCl or citute nttric. PENA,S. Isotope Products Laboratories 86/03/11. WRIGHT,B. NRC · No Detailed Affiliation Given. 1p. 45029:140-45029:140.

- 8804050413 Executive Branch position re Mitsul & Co (USA) Inc application to export 35,700 kg of natural U in form of U hexafluoride. License should be granted. M Toshikage, Embassy of Japan 860317 ltr to JM Rooney, DOE, and. STRATFORD, R.J. State, Dept. of, Bureau of Cosens & Intl. Environ. & Scientific Affairs. 88/03/24. SHEA, J.R. International Programs. 2pp. 45029:182-45029:183.
- 8804060075 Informs that transfer of mail,identified in Westinghouse application for li-cense to export nuclear mail,will be subj to sill of terms & conditions of 840411 agree-ment of cooperation to civil use atomic energy. SANDEERG.H.N. Sweden, Govt. of. 88/03/21. ROONEY,J. Energy, Dept. of. 2pp. 45019:360-45019:362.
- 8804280206 Application for license to export 240 kg U-235, contained in 6,000 kg U,to Sweden. HUDEC,W.S. Westinghouse Electric Corp. WSH-065-88. 88/04/13. 1p. 45266-240-
- 8804280236 Application to amend license,increasing quantity from 40,000 kg to 500,000 CARPENITO, A.C. Nuclear Metals, Inc. 88/04/15. WRIGHT, B.L. International Programs. 1p. 45262:358-45282:358.
- 8804280285 Application for amend to License XU-8659,changing consignee name for mail to be exported on license. Consignee name stated. RAYENSCROFT,N. Edlow International Co. 88/04/18. WRIGHT,B. NRC No Detailed Affiliation Given. 1p. 45266:340-45286:340.
- 8804280332 Application to amend ticense, changing address, intermediate consignee & including 95.6 kg U-235.

 CUAIN,P.B. Transnucleer, Inc. 88/04/11, MOORE,N. NRC No Detailed Affiliation Given. 3pp. 45269.218-45269.218.
- 8804280381 Forwards application for license to export enriched UO2 as powder to Japan. FLOWERS,F.D. General Electric Co. 88/04/07, WRIGHT,B.L. NRC · No Detailed Af-filiation Given. 1p. 45265:123-45265;124.
- --8804280385 Application for license to export 780 kg U-235,contained in 25,497 kg U-as 28,925 kg UO2 powder,to Japan. FLOWERS,F,D. General Electric Co. 88/04/07. tp. 45265:124-45265:124.
- 8804280413 License for CERAC, inc to export 5,272.74 kg thorium, contained in 6,000 kg thorium oxides, nitrates & other compounds to Japan. PETERSON, M.R. Assistant Director for Export/Import & International Safeguards. TLX15204, 88/04/22. 1p. 45268:169-45288:160.
- -8804290063 Application for license to export 6,000 kg thorium oxide containing 5,272,74 kg thorium in forms of oxides,nitrates & other compounds to Japan. COLTON,E. Cerac, Inc. 88/04/07. HEMBY.E. Assistant Director for Export/Import & International Safeguards. 1p. 45266:160-45266:160.
- 8804280416 Ltr of assurance re export of 6.6 kg U-235,contained in 880 kg of U,to Japan. TOSHIKAGO,M. Japan, Govt. of. 88/04/07. ROONEY,J.M. Energy, Dept. of. 1p. 45284:080-45284:060.
- 8804280475 Forwards application for export license for tow enriched U for use as reload fuel in Fukushima I, Unit 2,to Japan. Lt of assurance required. W/o encl. PETERSON, M.R. Assistant Director for International Security, 88/04/13, ROONEY, J. Energy, Dept. of. 1p. 45271:028-45271:028.
- 8804280493 Forwards Transnuclear Inc 880411 It requesting amend to License XSNM-2189 to Increase quantity of matt authorized for export to Sweden. Ltr of assurance that mall will be subj to learns of agreement requested. W/o encl. PETERSON, M.R. Assistant Director for infernational Security. 88/04/16. ROONEY, J. Energy, Dept. of. 1p. 45270:341-45270:341.
- 8804280515 License for Aerojet Ordnance Tennessee to export depleted U as U letrasurgeur of License for Aerojal Orginance termessee to export depicted 0 as 0 february fluoride to Canada, PETERSON,M.R. Assistant Director for International Security, 88/04/21, 2pp. 45270:350-45270:353.
- 8804280625 License for Mitsul & Co (USA), Inc to export 0.593 kg U-235, containing 3.0 kg U.to Japan. PETERSON.M.R. Assistant Director for International Security. MSK-TSB-E/METAL. 88/04/22. 2pp. 45271:057-45271:058.
- 8804290080 Application to amend license, changing name of Intermediate consignee & description on application of UF6 38.18 Kg U & 35.6313 Kg U-235 enriched to 93.3%. QUAIN,P.9. Transnuclear, Inc. 88/04/22. WRIGHTB. Division of Safeguards & Transportation (Post 870413). 3pp. 45268:360-45268:362.
- 8804290083 Application for amend to licenses changing consignee to ABS Atom AB due to marger between Asea AB of Vasteras, Sweden & BBC Brown Boveri AG of Batten, Switzerland.

 HUDEC, W.S. Westinghouse Electric Corp. WSH-069-88. 88/04/18. MOORE, R.N. NRC No Detailed Affiliation Given. 1p. 45284:360-45284:360.
- 8804290176 Forwards Edlow intl Co application for amend to export license to change ultimate consignee from EURODIF to Cogema in France Views as to whether proposed amend meets criteria in Atomic Energy Act of 1954 as amended in 1978 requested.
 PETERSON,M.R. Assistant Director for Informational Security. 88/04/22.
 THORNE C.E. State, Dept. of, Bureau of Oceans & Init. Environ. & Scientific Affairs.
 1p. 46322:229-45322:230.
- 8804290276 Forwards application for export license for low enriched U for use in fabrication of fuel rods in Sweden, Ltr of assurance required.

 PETERSON, M.R., Assistant Director for International Security, 88/04/22, ROONEY, J. Energy, Dept. of, 1p. 45324:338-45324:339.

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example,50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	,
ABBATE, C.M. ABBOT, R.B. ABELSON, H. ABRAMS, C. ADAM, W.	8804190034° 8604260415 8804270261 8804080054 8804130193	QA999 50-220 F 50-333 P WASTE RES I&E	AMATO,C.G. AMIRIAN,A. ANDERS,O.U. ANDERSON,C.E. ANDERSON,C.J.	8804040042* 8804110012 8803300438* 8804060290* 8804120199*	50-272 Q 50-443 Q WASTE MGT 50-259 F 50-213 Q	ARTHUR,W.J. ARTHUR,W.J. ARTHUR,W.J. ARTHUR,W.J. ARTHUR,W.J.	8804110013 8804110047 8804130213 8804130237 8804130353	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT	
ADAM,W. ADAM,W.J. ADAM,W.J. ADAMOVITZ,S.S. ADAMS,A.	8804210207 8803300026 8803300036 8804080240* 8804290109	I&E I&E I&E 50-250 Q 60-123 V	ANDERSON,C.J. ANDERSON,J.D. ANDOGNINI,G.C. ANDOGNINI,G.C. ANDOGNINI,G.C.	8804120223° 8804080115 8804040148 8804050023 8804060464	60-247 Q 60-440 F 60-312 Q 60-312 S 60-312 P	ARTHUR,W.J. ARTHUR,W.J. ARTHUR,W.J. ARTHUR,W.J. ARTIGAS,R.	6804180002 8804260214 8804280185 8804280302 8803310018	WASTE MGT WASTE MGT WASTE MGT ORG 50-805	
ADAMS,A. ADAMS,J.B. ADAMS,M. ADAMS,R.E. ADDISON,E.L.	8804290217 8803300384 8803300215* 8804010223 8804270183*	50-62 P 50-208 I 50-311 Q NUREG 60-321 I	ANDOGNINI, G.C. ANDOGNINI, G.C. ANDOGNINI, G.C. ANDOGNINI, G.C. ANDOGNINI, G.C.	8804070053 8804080045 6804130288 8804190380 8804200125	50-312 P 50-312 P 50-312 P 50-312 Q 50-312 P	ARTIGAS,R. ASHBAUGH,C.E. ASKWITH,H.H. ASMUSSEN,K.E. ASMUSSEN,K.E.	8804190185 8804140209 8804200091* 8804110088 8804110092	TOPREP FOIA 50-346 F 70-734 PR	P
ADEL-HADADI,M. ADEL-HADADI,M. ADENSAM,E. ADENSAM,E.G. ADENSAM,E.G.	8804140192° 8804140226° 8803080108 8804010194 8804050164	PROJ PROJ 50-324 P 60-321 P 50-348 Q	ANDOGNINI, G.C. ANDOGNINI, G.C. ANDOGNINI, G.C. ANDOGNINI, G.C. ANDOGNINI, G.C.	8804200141 8804200272* 8804210136 8804270136 8804270218*	50-312 Q 50-312 Q 50-312 S 50-312 P 50-312 Q	ASMUSSEN,K.E. ASMUSSEN,K.E. ASMUSSEN,K.E. AUSTIN,G. AUSTIN,G.	8804110107 8804270227 8804290051* 8803300339 8804140359	70-734 70-734 70-734 50-304 F 50-295 F	R R
ADENSAM,E.G. ADENSAM,E.G. ADENSAM,E.G. ADENSAM,E.G. ADENSAM,E.G.	8804080222* 8804110236* 8804130395* 8804140132* 8804140290*	60-324 P 50-324 P 50-400 P 60-324 P 50-324 P	ANDREWS,R.L. ANDREWS,R.L. ANDREWS,R.L. ANDREWS,R.L. ANDREWS,R.L.	8803290112 8803310073 8804010081 8804040003 8804070060	50-285 F 50-285 F 50-285 P 50-285 F 50-285 O	AUSTIN,J.H. AUSTIN,J.H. AXELROD,D. AXELSON,W. AYALA,C.	8804080174 8804140067* 6804200094* 8804130151* 8804130138		G S S
ADENSAM,E.G. ADENSAM,E.G. ADENSAM,E.G. ADENSAM,E.G. ADENSAM,E.G.	8804140302* 8804150123* 8804150188 8804150434* 8804200385*	60-324 P 50-261 P 50-321 P 50-324 P 50-396 P	ANDREWS,R.L. ANDREWS,R.L. ANDREWS,R.L. ANDREWS,R.L. ANDREWS,R.L.	8804070188 8804110208 8804120358 8804130079 8804130180	50-285 Q 50-285 Q 50-285 P 50-285 S 50-285 F	AYALA,C. AYALA,C. AYALA,C. AYALA,C.A. AYALA,C.A.	8804200201 8804200218 8804260227 8803290289 8804010068	50-498 5 50-498 5 50-498 5 50-498 5	S S S S
ADENSAM,E.G, ADIGA,R. ADIGA,R. ADLER,R.E. ADLI,D.G,	8804280105 8804140192* 8804140228* 8804070134 8803310254*	60-396 P PROJ PROJ WASTE MGT 60-309 P	ANDREWS,R.L. ANDREWS,R.L. ANDREWS,R.L. ANDREWS,R.L. ANDREWS,R.L.	8804150414 8804200093 8804200142 8804200346 6804200366	50-285 S 50-285 S 50-285 R 50-285 S 50-285 S	AYALA,C.A. AYALA,C.A. AYALA,C.A. AZAB,B.A. BACHMAN,R.G.	8804010074 8804120346 8804130127 8803290069* 8804200042	50-498 \$ 50-498 \$ 50-498 \$ 50-315 \$ 60-322	S S S C T
AGARWAL, B.K. AGGARWAL, Y.P. AHO, G.D. AHO, G.D. AHO, G.D.	8804280481 8803080253* 8804060008 8804060176 8604120331	PROJ 50-440 P 40-8714 40-8714 40-8714	ANDREWS,R.L. ANDREWS,R.L. ANDREWS,R.L. ANDREWS,R.L. ANDREWS,N.J.	8804200428 8804250003 8804250004* 8804250007 8804060183	60-285 F 60-285 P 50-285 P 50-285 P 40-4492	BACHMANN, R.G. BACKUS, R.A. BACKUS, R.A. BACKUS, R.A. BACKUS, R.A.	8804290188 8804200052 8804200062* 8804200062* 8804260088	50-443 (9000
AHO,G.D. AHO,G.D. AINSWORTH,D.L. ALAMMAR,M.A. ALBRECHT,K.	8804280383 8804280652 8804010092 8804070011* 8804140481	40-8714 40-8714 NUREG 50-219 P FOIA	ANDRUS,N.J. ANDRUS,N.J. ANDRUS,N.J. ANTHONY,P. ANTHONY,P.	8804080279 8804280311 8804280391 8803310147 8804050172	40-4492 40-4492 40-4492 50-341 S 50-341 S	BACKUS,R.A. BACKUS,R.A. BACKUS,R.A. BACKUS,R.A. BACKUS,R.A.	8804260086 8804260107 8804290082 8804290082 8804290092*	50-443 (50-443 (50-443 (50-443 (6 6 6
ALBRECHT,K. ALDEN,W.M. ALDEN,W.M. ALEXANDER,R.E. ALEXANDER,R.E.	6804280278 6804190153 8604220040 6804270213* 8604270313*	FOIA 50-362 R 50-277 R PR PR	ANTHONY,P. ANTHONY,P. ANTHONY,P. ANTHONY,P. ANTHONY,P. ANTHONY,P.	8804050185 8804150405 8804160417 8804190236 8804200139	50-341 S 50-341 S 50-341 S 50-341 S 50-341 S	BACKUS, R.A. BACKUS, W.H. BACKUS, W.H. BACKUS, W.H. BAER, R.E.	8804290092* 8804140044 8804140147 8804180442 8804110211*	50-244 5 50-244 5 50-244 5 50-285 0	G S S S
ALEXICH,M.P. ALEXICH,M.P. ALEXICH,M.P. ALEXICH,M.P. ALEXICH,M.P.	8804040143 8804080095 6804110191 8804110193 8804200090	50-315 Q 50-315 P 50-315 Q 50-315 S 50-315 1	ANTHONY,P. ANTHONY,P. ANTHONY,P. ANTHONY,P.M. ANTHONY,R.L.	8804200159 8804200375 8804270004 8804190129 8804290110	60-341 S 60-341 S 50-341 S 50-341 R 50-362 G	BAER,R.E. BAILEY,E.D. BAILEY,J.A. BAILEY,J.A. BAILEY,J.A.	8804250046* 8804190170* 8804040065 8804060431 6804110053	NUREG 50-425 (50-482 (50-425 /	Q E Q A
ALEXICH,M.P. ALEXION,T.W. ALEXION,T.W. ALEXION,T.W. ALEXION,T.W.	8804210015 8804050243 8804120394 8804120403* 8804250306	60-315 Q 50-483 P 60-483 P 60-483 P 60-483 P	ANTTONEN, J.H. ANTTONEN, J.H. ANUJE, A.B. APPIGNANI, P.L. ARILDSEN, J.	8803310268 8804180008 8804120336 8804280386 8803250161*	WASTE MGT WASTE MGT 50-317 P NUREG 50-250 V	BAILEY,J.A. BAILEY,J.A. BAILEY,J.A. BAILEY,J.N. BAILEY,J.N.	8804140456 8804180410 6804260108 8804190258 8804270006	50-482 71-5450 50-499 50-499	Q A
ALLEN,C.M. ALLEN,H.P. ALLEN,R.E. ALTO,R.A. ALTSCHULER,S.J.	8804220012 8804260253* 8804200379 8804080212 8803300438*	50-373 K 60-206 Í 50-382 S 70-1201 WASTE MGT	ARNOLD,K.M. ARROWSMITH,J.B. ARTHUR,W.J. ARTHUR,W.J. ARTHUR,W.J.	8804060025* 8604140439* 8804080056 8804070037 8804070262	CONTRACT NUREG WASTE MGT WASTE MGT WASTE MGT	BAILEY,R. BAILEY,R.J. BAILEY,W.J. BAKER,O.A. BAKER,O.E.	8804130187 8804250329* 8804080131 8804140108* 8803280037	60-309 NUREG NUREG	s Q s

259

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BAKER,D.E	8804070213	50-382 S	GASSER.	8804140417	WASTE RES	BELLAMY, R.R.	8804120315	50-220 Q
BAKER D.E.	8804190262*	50-499 A	BASSETT CH	8804120303°	50-297 Q	BELLAMY, R.R.	8804120363	70-371
BAKER D.E.	8604200373	50-382 S	BASSETT CH	8604150396°	60-413 Q	BELLAMY, R.R.	8804130018	50-244 F
BAKER,D.E.	8804200377	50-382 S	BASSETT CH	8804260075°	50-280 Q	BELLAMY, R.R.	8804130123	50-293 Q
BAKER,E.T.	8604180034*	OA930	BATCS A.K.	8804120213	60-327 P	BELLAMY, R.R.	8804130162	50-213 Q
BAKER.E.T.	8804260057* 8804150094* 8804040242 8804060487 8804060149	60-327 Q	BATES,A K.	8804120213	50-327 P	BELLAMY,R.R.	8804130182	50-2/7 Q
BAKER.L.J.		CONTRACT	BATES,A.L.	8804140229°	FOIA	BELLAMY,R.R.	8804140091	50-171 F
BAKER.R.D.		60-366 S	BATES,J.W.	8804010100°	70-1113	BELLAMY,R.R.	8804150243	50-322 F
DAKER.R.L.		50-250 S	BAUER,E.R	8804200389	50-318 S	BELLAMY,R.R.	8804200040	50-334 Q
BAKER.S.J.		40-1162	BAUER,T.L.	8804010022	80-192 R	BELLAMY,R.R.	8804200119	50-317 Q
BAKER,S J.	8604060213	40-1162	BAUERICIS,E I.	8804040038	\$0-317 R • FOIA P 50-254 P 50-265 S 50-265 S	BELLAMY, R.R.	8804200155	50-286 Q
BAKER,S J	8804260290	40-1162	BAUMAN,L.	8804260168		BELLAMY, R.R.	8804250159	50-277 Q
BALDWIN,C.A.	8604280633	NUREG	BAX,R.L	8803150061		BELLAMY, R.R.	8804250197	70-371
BALL,J.	8804190164*	60-528 O	BAX,R.L.	8803300185		BELLAMY, R.R.	8804250320	50-309 Q
BALLARD,R L.	8803300268	WASTE MGT	BAX,R.L.	8803300204		BELLAMY, R.R.	8804250342	50-322 F
BALLARD,R L.	8903310125	WASTE MGT	BAX.R.L.	8804050263	50-254 S	BELLAMY,R.R.	8804260015	50-387 F
BALLARD,R L.	8803310133	WASTE MGT	BAX.R.L.	8804130047	50-265 S	BELLAMY,R.A.	8804270026	50-277 F
BALLARD,R L.	8803310218	WASTE MGT	BAX.R.L.	8804200367	50-265 S	BEMBIA,P.J.	8803310100	WASTE MGT
BALLARD,R L.	8803310290*	WASTE MGT	BAX.R.L.	8804200393	50-254 S	BEMBIA,P.J.	8804130057	WASTE RES
BALLARD,R L.	8804070187	WASTE MGT	BAXTER,T.A.	8804060117	50-320 G	BENDER,M.	8804130274	ACRS
BALLARD, R.L.	6604070208	WASTE MGT	BAXTER,T.A.	8804060117	50-320 G	BENEDICT, R.A	8804050289	50-220 P
BALLARD, R.L.	8604070299	WASTE MGT	BAXTER,T.A.	8804180018	50-320 G	BENEDICT, R.A	9804190327	50-220 P
BALLARD, R.L.	6004060016	WASTE MGT	BAXTER,T.A.	8804180018	50-320 G	BENEDICT, R.A	8804190333*	50-220 P
BALLARD, R.L.	6804130277	WASTE RES	BAXTER,T.A.	8804200055	50-320 G	BENKERT, J.W.	8804070203*	50-259 P
BANDROWSKLM S.	6604150322*	NUREG	GAXTER,T.A.	8804200055	50-320 G	BENNETT, R.D.	8804010092	NUREG
BARHAM, G.D.	8604250217	50-261 J	BAZIN,J.	8804140495	CONTRACT	BENNETT,W.R. BENSON,D.L. BENSON,D.L. BENSON,D.L. BENSON,D.L.	8804060397*	50-298 Q
BARHAM, G.D.	8804260218	50-261 J	BAZIN,J.	8804200279	CONTRACT		8804060038	50-281 S
BARHAM, G.D.	8804260219	50-324 J	BAZIN,J.	8804280429	CONTRACT		8804130308	50-280 S
BARHAM, G.D.	8804250221	60-324 J	BEAN,D L.	8804010092	NUREG		8804140048	50-280 S
BARHAM, G.D.	8804250222	60-400 J	BEAND,R M.	8804190118	50-321 R		8804140051	60-281 S
BARHAM, C.D.	8804250223	60-400 J	BEARDEN,W.C.	8803310292*	50-259 Q	BENSON,T.A.	6804210124*	FOIA
BARKATT, A.	8804140187*	PROJ	BEATTY G.P.	8804040085	50-261 V	BENSON,T.A.	6804210234*	FOIA
BARKATT, A.	6804140182*	PROJ	BECK,J.W.	8804280144*	50-265 Q	BENSON,T.A.	6804210244*	FOIA
BARKATT, A.	0804140228*	PROJ	BECK,J.W.	8804050340	50-445 S	BERGER,E.	6803080508*	50-219 P
BARNARO, E.	6804130232	ACRS	BECK,J.W.	8804080081	50-445 S	BERGER,J.	8804130379	50-289 P
BARNARD,E. BARNES,I. BARNES,I. BARNES,I. BARNES,I.	8604280410 8803300127' 6603300206' 8804120017' 6804250050'	ACRS 60-482 Q 60-498 Q 50-208 Q 60-313 Q	BECKJORD,ES. BECKJORD,ES. BECKJORD,ES.	8804060515 8804070083 8804110111 8804010249 8804010254*	50-445 A 50-445 A 70-2932 ORG ORG	BERGER, J. BERGEMANN, J.W. BERGSTROM, P.D. BERGSTROM, P.D. BERKOW, H.N.	8804130382* 8804130113 8804280174 8804280183* 8804010183	50-289 P 50-305 S 40-8902 40-8902 50-250 Q
BARNES, 9 M. BARNES, 5 M. BARR, K.P. BARR, K.P. BARR, K.P.	8804140185' 8804140200' 8803290314 8803290317' 8803290349	PROJ PROJ 50-380 O 60-380 O 50-327 G	BECKJORD,E.S. BECKJORD,E.S. BECTON,J.W. BEDESEM,P.	8804180433 8804270071* 8804270081* 8804280087 8804220104	REVIEW GR P PR PR 50-443 G 50-275 R	BERKOW,H.N. BERKOW,H.N. BERKOW,H.N. BERKOW,H.N. BERKOW,H.N.	8804050254* 8804050301* 8804130337* 8804180227* 8804190111*	50-338 P 50-338 P 60-335 P 50-250 P 50-302 P
BARRIK P. BARRIK P. BARRIK P. BARRIK P. BARRIK P.	6603210352' 8803200366 6003200390' 6803310201'	50-327 Q 50-259 Q 50-259 Q 50-250 Q 50-250 Q	BEHNKE,C. BEHNKE,C. BEILMAN,T.P. BELAIR,R.R. BELAIR,R.R.	8804180338* 8804180343* 8804210261 8804140354 8804140354	50-317 R 50-317 R 50-316 S 50-322 P 50-322 P	BERKOW,H.N. BERKOW,H.N. BERKOW,H.N. BERKOW,H.N. BERLINGER,C.H.	8804190358* 8804210345 8804210413* 8804280484* 8804180145	50-302 P 50-389 P 50-280 P 50-250 P ORG
BARR,K.P. BARR,K.P. BARR,K.P. BARR,K.P. BARR,K.P.	8604010023 8804010028 8604010030 8804010031 8804010032*	60-327 Q 50-259 Q 50-259 Q 50-250 Q 50-259 Q	BELISLE,G. BELISLE,G.A. BELKE,W. BELKE,W.	8804260114* 8803290330* 8804060268* 8803310144* 8804050220	60-261 Q 60-425 Q 60-425 Q WASTE MGT 50-603 M	BERLINGER,C.H. BERNSTEIN,R. BERRY,A.B. BERRY,G.A. BERRY,G.A.	8804270024 8804190305 8804050032 8804110036 6804180073	PT21 STATE PRO G 50-443 G 40-3453 50-443 G
BARRIK P.	8804010110	50-438 Q	BELL,D.L.	8804110157	50-604 A	BERRY,K.W.	8803300044	50-155 P
BARRIK P.	8804060224	50-259 Q	BELL,D.L.	8804250242	50-603 F	BERRY,K.W.	8804110288	50-155 P
BARRIK P.	860406052B	50-259 Q	BELL,D.L.	6804260339	50-604 F	BERRY,K.W.	8804130031	50-255 P
BARRIK P.	8804080207	60-259 Q	BELL,S.	8804040229	CONTRACT	BERRY,K.W.	8804130190	60-255 P
BARRIK P.	8804160107	50-327 Q	BELL,S.	8804060266	CONTRACT	BERRY,K.W.	8804190047	50-255 P
BARRIK P.	8804150110*	60-327 Q	BELL,S.	8604150063	CONTRACT	BERRY,K.W.	8804280058	50-155 Q
BARRIK P.	8804160159	60-327 Q	BELL,S.	8804150161	CONTRACT	BERRY,K.W.	8804280091	50-155 H
BARRIK P.	8804200555	50-259 Q	BELL,S.	8604150193	CONTRACT	BERRY,R.L.	8803300342	50-29 R
BARRIK P.	8804210471	50-259 V	RELL,S.	8804150268*	CONTRACT	BERRY,R.L.	8804190054	60-29 R
BARRIK P.	8804250088	50-327 Q	BELL,S.	8804150336*	CONTRACT	BESS,J.E.	8804070045*	50-498 Q
BARRIK P.	8804280021	50-327 O	BELL,S	6804180152°	CONTRACT	BETTENHAUSEN,L.	8804040011	50-423 Q
BARRIK P.	8804280025*	50-327 O	BELL,S	8804190178°	CONTRACT	BETTENHAUSEN,L.	8804140370	50-336 S
BARRIR C.	8604220177	50-344 P	BELL,S	8804200289°	CONTRACT	BETTENHAUSEN,L.	8804200028	50-245 Q
BARRIR C.	8804250043*	50-344 O	BELL,S	8804200362°	CONTRACT	BETTENHAUSEN,L.	8804200172	50-338 Q
BARTALIL J.	8804040038	50-317 R	BELL,S	8804200425°	CONTRACT	BETTENHAUSEN,L	8804200388	50-423 S
BARTELJ.F.	8803300438*	WASTE MGT	BELL,S.	8804200485°	CONTRACT	BICEHOUSE,H.J.	8804110319*	50-277 O
BARTON,A.H.	8804200101*	50-322 T	BELL,S.	8804200583°	CONTRACT	BICEHOUSE,H.J.	8804200163*	50-286 O
BARTON,A.H.	8804200101*	50-322 T	BELL,S.	8804210190°	CONTRACT	BIDINGER,G.H.	8804140052	70-36
BARTON,J.J.	8804080242	50-210 F	BELLAMY,R.R.	8804220162°	CONTRACT	BIGIARELU,M.J.	8804140042	60-245 S
BARTON,J.J.	8804140016	50-219 J	BELLAMY,R.R.	8804040036	50-272 Q	BINKOWSKI,J.A.	8804150380	60-302 P
BARTON,P.H. BASILE.J.A. BASILE.J.A. BASILE.J.A. BASILE.J.A.	8804130329 8804080139 8804110091* 8604110093*	ACRS 50-247 Q 50-280 R 50-280 R 50-280 R	BELLAMY,R.R. BELLAMY,R.R. BELLAMY,R.R. BELLAMY,R.R. BELLAMY,R.R.	8804050168 8804060130 8804070258 8604070259 8804080037	50-29 Q 50-244 Q 50-219 F 50-317 F 60-443 F	BIRD, C.C. BIRD, R.G. BIRD, R.G. BIRD, R.G. BIRD, R.G.	8804210020 8803300142 8803300146 8804040208 8804070129	FOIA 50-293 S 50-293 S 50-293 S 50-293 S
Basilejja.	8804110127*	50-286 R	BELLAMY,R.R.	8804080082	50·184 F	BIRD,R.G.	8804070196	50-293 P
Basilejja.	8804110141*	50-286 R	BELLAMY,R.R.	8804080159	50·54 F	BIRD,R.G.	8804080155	50-293 P
Basilejja.	8804110146*	50-288 R	BELLAMY,R.R.	8804110310	60·277 Q	BIRD,R.G.	8804110181	50-293 P
Baskinjk.p.	8804130064*	60-362 Q	BELLAMY,R.R.	8804120032	50·29 Q	BIRD,R.G.	8804130089*	50-293 C
Baskinjk.p.	8804220189	60-208 P	BELLAMY,R.R.	8804120049	50·277 Q	BIRD,R.G.	8804130191	60-293 P
Baskin K.P.	8804220202*	50-208 P	BELLAMY, R.R.	8804120193	70-1100	BIRD,R.G.	8804190065	50-293 S
Basse,B.H.	8804010276	NUREG	BELLAMY, R.R.	8804120232	50-443 Q	BIRD,R.G.	6804200145	60-293 P
Basse,B	8804140352	WASTE RES	BELLAMY, R.R.	8804120242	50-97 Q	BIRD,R.G.	8804210006	50-293 F

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	АОНТИА	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BIRD,R G. BIRD,R.G. BIRD,R G BIRD,R G BIRELY,W C	8804210008 8804210289 8804270099 8804280072 8803300272	50-293 O 50-293 P 50-293 H 50-293 O 50-277 S	BOOKER, J.E. BOOKER, J.E. BOOKER, J.E. BOOKER, J.E.	8804120098 8804120118 6804150277 8804200133 6804200187	50-456 P 50-458 J 50-458 F 50-458 H 50-458 S	BROWN,S BROWN,S R BROWN,W R BROWN,W R	6804280185 8804050264 6804220031 6604070217* 8804070234*	50-322 P NUREG 50-322 P 50-259 P 50-259 P
BIRELY,W.C.	8804040035	50-277 S	BOOKER, JE	8804200197	50-458 S	BROWNING,R E	8804580036	WASTE RES
BIRELY,W.C.	8804060043	50-277 S	BOOKER, J.E	8804220137	50-458 S	BROWNING,R E,	6904140152	WASTE MGT
BIRELY,W.C.	8804080034	50-277 S	BOOKER, J.E	8804220139	50-458 S	BROWNIEE,V L	8803290331	50-369 Q
BIRELY,W.C.	8804080056	50-277 S	BOOKER, J.E	8904220279	50-459 O	BROWNIEE,V L	6803290333*	50-369 Q
BIRELY,W.G.	8804080162	50-277 S	BOOKER, J.E	8804250036	50-458 S	BROWNIEE,V L	8803300061	50-321 O
BIRELY,W.C.	8804130063	50-277 S	BOOTH,O.W.	8804040050°	50-269 Y	BROWNLEE,V L.	8903300064*	50-321 Q
BISHOP,J.C.	8804190136	40-3392	BORCHARDT,W.	8804070246	50-272 S	BROWNLEE,V L	8803300072	50-413 D
BISHOP,J.C	8804190265	40-3392	BORCHERT,H.R	6805030170°	PR	BROWNLEE,V L.	8803300073*	50-413 Q
BISSETT,P.	8804250315*	50-334 Q	BOSE,D.D	8804130148°	CONTRACT	BROWNLEE,V L	8803310283	50-369 Q
BITTER,S.D.	8804260016*	50-445 Q	BOUCHER,T.J	8804280505	NUREG	BROWNLEE,V L.	8804010042	50-269 P
BIXBY,W.W. BIXBY,W.W. BIXBY,W.W. DIXBY,W.W BIXBY,W.W	8804080166 8804140151 8804140206* 8804190354 8804200002	LOBA COBA EORA COBA COBA	BOULETTE,E T. BOURNIA,A BOURNIA,A. BOVEJA,R K BOYCE,T.D	8804010118 8804010084 8804280157 8804190346* 8803300430	50-309 F 50-285 P 50-285 P CONTRACT WASTE MGT	BROWNLEE, V.L. BROWNLEE, V.L. BROWNLEE, V.L. BROWNLEE, V.L.	8804010050 8804050175 8804050176* 8804120023 8804250019	50-413 O 50-413 O 50-413 O 50-369 O 50-321 O
BLACKFORD,M E BLACKFORD,M E BLACKFORD,M E BLAKE,J J	8804280568 8804140259 8804140271 8803280137* 8803290325*	PROJ WASTE RES WASTE RES 50-324 Q 50-250 Q	BOYD,C C BOYLE,M.L BOYLE,M.L BOYLE,M.L	8804110056 8804010009 8804060282 8804130306 8804220227	PR 50-245 P 50-245 P 50-245 Q 50-245 F	BROWNLEE,V L BROWNLEE,V L BRUNSON,B G BRYAM,R G BRYAM,R H	8804250023* 8804250033 8804060420 8804040096 8804010275	\$0:321 O 50:424 Q 50:413 S 50:387 S NUREG
BLAKE,J J.	8803300083*	50-324 O	BRADBURNE, J C	8804130043*	COMMISSION	BRYSON J.W.	8804010275	NUREG
BLAKE,J J.	8803310280*	50-289 O	BRADBURY, J W	6803090237	WASTE RES	BUCKLES J A	8804050404'	CONTRACT
BLAKE,J J.	8804150201*	50-302 O	BRADFORD, W.H	8804060267*	50:348 Q	BUCKLES J A	8803310258	50:250 J
ULAKE,FLP.	8804050385*	50-321 O	BRADLEY, E.J.	8803310075	50:352 I	BUCKLEY B C	8804130388	50:400 P
BLANCHAND.M	8804110061	WASTE MGT	BRADLEY, E.J.	8804060204	50:352 P	BUCKLEY B C	8804210330	50:400 P
BLAYLOCK, J. BLAYLOCK, J. BLAYLOCK, J. BLAYLOCK, J. BLAYLOCK, J.	8804260151 8804260151	PR WASTE MGT WASTE MGT WASTE MGT WASTE MGT	BRADLEY,E.J. BRADLEY,E.J. BRADLEY,E.J. BRADLEY,E.J. BRADLEY,E.J.	8804130145 8804130161 6804190088 8804190387 8804270235	50-352 J 50-171 J 50-171 J 50-352 J 50-277 1	BUCKLEY, BC BUCKLEY, J.T. BUCKLEY, J.T. BUHL, A.R. BUHL, A.R.	8804210452 6804120137 8804130056 8604190060* 6804190060*	50-400 P WASTE RES WASTE RES FOIA FOIA
BLESSIE, W.J. BLISS, H.E. BLISS, H.E. BLOCH, P.B. BLOCH, P.B	8804200142 8804120020 8804220035 8004110026 8804260055	50-205 R 50-295 Q 50-454 F 50-445 G 50-445 G	BRADY,R J. BRADY,R J. BRADY,R J. BRAM,S. BRAM,S.B.	8804130071° 8804140129° 8804140142° 8804260090° 8803300333	COMMISSION COMMISSION COMMISSION 50-3 P 50-247 R	BUHLA R BUHLA R BUHLA R BUHLA R BUNCH,D F.	8804190069* 8804190069* 8604190077* 8804190077* 8804280454	FOIA FOIA FOIA PROJ
BLOOMSBURG,G.	8803300340*	WASTE RES	BRAM,S.B.	8804050042	50-3 P	BUNTING, J.O. BUNTING, J.O. BUONOCORE, J.A. BURDICK, T.M. BURDICK, T.M.	8804070121	WASTE MGT
BLOOMSBURG,G.	8804120477*	WASTE RES	BRAM,S.B.	8804120337	50-3 F		8804180022	WASTE MGT
BLOSSER,J D.	8804140088	50-483 S	BRAM,S.B.	8804190028	50-247 P		8804040264	XPORTLIC
BLOSSER,J D.	8804190100	50-483 R	BRAM,S.B.	8804200466	50-247 Q		8804060018*	50-305 V
BLOUGH,A R.	8804110066	50-293 R	BRAM,S.B.	8804200548	50-247 Q		8804200385	50-483 P
BLOUGH, A.R.	8804120228	50-293 P	BRAM,S B.	8804250138	50-247 O	BURDOIN.J.	8804180113'	50-526 O
BLOUGH, A.R.	8804120383	50-293 P	BRAM,S B	8804260085	50-3 P	BURGER.C.W	8804250034'	50-424 O
BLOUGH, A.R.	8804130097	50-293 P	BRAM,S.B.	8804260292	50-247 P	BURGESS.B.	8804080211	50-315 S
BLOUGH, A.R.	8804130121	50-387 P	BRANCH,M.	8803290355*	50-327 O	BURGESS.B.L.	8804060123'	50-315 O
BLOUGH, A.R.	8804140005	50-387 F	BRANCH,M.	8804060255*	50-327 O	BURKE.O.E.	8804270166	50-346 H
BLOUGH,A.R	8804200255	50-293 P	BRANCH,M.	8804260042'	50-327 Q	BURKHART.M	8804280600	40.8997
BLOUGH,A.R.	8004270155	60-293 R	BRANDON,R J.	8804150017'	50-458 P	BURNETT,PT.	5804120303*	50.297 Q
BLUBAUGH,R.E.	8804280115	40-3463	BRELIS,M.	8804140340	50-334 P	BURNETT,R.F.	8804050098	70.27
BLUBAUGH,R.E.	8804280359	40-3453	BREWER,D.R.	8803250294'	50-250 Q	BURNETT,R.F.	6804120347	70.27
BLUBAUGH,R.E.	8804280408	40-3453	BREWER,D.R	8804260218'	50-250 Q	BURNS,W.E.	8804080055	50.424 \$
BLUBAUGH,R E.	8804280434	40-3453	BREWER,H.E	8804250254*	50-206 I	BURNS,W.E.	8804130117	50-424 S
BLUBAUGH,R.E.	8804280507	40-3453	BREY,H.L.	8803300063	50-267 P	BURNS,W.E.	8804130120	50-424 S
BLUMBERG,N.	8804260056*	50-443 Q	BREY,H.L.	6803300350	50-267 O	BURRIS,L.O.	8804010035	50-315 F
BOARDMAN,J.R.	8804120162*	50-459 Q	BREY,H.L.	8803300359	50-267 F	BURRIS,S.P.	8804260018'	50-445 O
BOARWRIGHT,W.J.	0803250275*	50-445 A	BREY,H.L.	8804120268	50-267 J	BURSXI,R.F.	8803300176	50-382 P
BOCANEGRA,R.	8804110090*	50-331 Q	BREY,H L.	88041203B5	50-267 J	BURSKI,R F.	5803310104	50-382 J
BOCCIO,J.	8804280386	NUREG	BREY,H.L	8804200079	50-267 I	BURSKI,R F.	8803310171	50-382 P
BOCKHOLD,G.	8804250013	50-424 F	BRIGGS,L E.	8804060016'	50-305 V	BURSKI,R.F.	8804040107	50-382 F
BOECKER,B.B.	8804280444	NUREG	BRIGGS,W.H.	8604120107'	50-498 P	BURSKI,R.F.	6804040206	50-382 O
BOGER,B.A.	8804250183*	50-293 P	BRIGHT,G.O.	8804260049	50-335 G	BURSKI,R F.	8804070127	50-382 F
BOGER,BA.	8804250236	50-423 P	BRINKMAN,R.E.	8804280299'	FOIA	BURSKIR F.	8804070207	50-382 F
BOHLINGER,LH	8804140141*	NUREG	BROCHMAN,P.G.	8804040216'	50-457 Q	BURSKIR F.	6804110155	50-382 P
BOLEY,K	8804040031*	ORG	BROCK,B.L.	8804040118'	70-734	BURSKIR F.	8804110166	50-382 P
BOLEY,K.	8804180337	FOIA	BROCKMAN,K.E.	8803160337'	50-269 V	BURSKIR F.	6804110269	50-382 O
BOLEY,K.	8804210030	FOIA	BROCKMAN,K.E.	6804050378'	50-321 V	BURSKIR F.	8804130342	50-382 P
BOLON,A.	0004190351*	50-123 Q	BROCKMAN,K.E.	8804200558°	50-259 Q	BURSKI,R F.	8804190289	50-382 R
BOLON,A.E.	8804190297	50-123 Q	BRODSKY,B.G.	8804200113'	50-322 T	BURSKI,R F.	8804190291	50-382 F
BOLON,A.E.	8604190337*	50-123 Q	BRONS,J.C.	8803300015	50-333 P	BURSKI,R.F.	8804250103	50-382 I
BOLT,S.E.	8804010276	NUREG	BRONS,J.C.	8804080114	50-333 P	BUSH,J.W.	8804180282*	50-445 A
BONANO,E.	8804190370	WASTE RES	BRONS,J.C.	8804110063	50-286 R	BUTCHER,E.J.	8804270031	TOPREP
BONENBERGER,D. BONGIOVANNI,A. BONG,R. BOOK,H.E. BOOK,H.E.	8804280136 8804200408* 8804180351* 8108260077* 8109180264*	PROJ 50-461 Q 60-123 Q FOIA FOIA	BRONS,J.C. BRONS,J.C. BRONS,J.C. BRONS,J.C.	8804150269 8804190161 8804220106 8804270271 8804280258	50-286 F 50-333 P 50-333 P 50-286 Q 71-240	BUTCHER,R C. BUTLER,W.R. BUTLER,W.R. BUTLER,W.R. BUTLER,W.R.	8804120171' 8804110148 6804110161' 8804110279' 8804120157	50-416 O 50-387 P 50-387 P 50-387 P 50-387 P
BOOK.H.E.	0804280319*	FOIA	BROOKS,B.	8804280390	NUREG	BUTLER,W.R.	8804120164*	50-387 P
BOOKER.J.E.	8804040081	50-458 J	BROOKS,C.R.	6803310292°	50-259 O	BUTLER,W.R.	8804150126	50-387 P
BOOKER.J.E.	6804040212	50-458 S	BROOKS,J.	8803090196	WASTE RES	BUTLER,W.R.	8804150136*	50-387 P
BOOKER.J.E.	8804050384	50-458 S	BROOKS,J.	8804130118°	COMMISSION	BUTLER,W.R	8804150156*	50-354 P
BOOKER.J.E.	8804070166	50-458 P	BROOKS,R.H.	8804040076	50-327 P	BUTLER,W.R.	8804150169	50-354 P
BOOKER, J.E.	8804110304	50-458 Q	BROUGHTON	8804060451°	50-289 P	BUTLER,W.R.	8804190099°	50-277 P
BOOKER, J.E.	8804110306	50-468 Q	BROWN,H.	8904150390°	NUREG	BUTLER,W.R.	8804280202	50-387 P
BOOKER, J.E.	8604120068	50-458 Q	BROWN,N.H.	8804140347	50-289 F	BUTLER,W.R.	8804280223°	50-388 P

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BUTTERFIELD,L.	8004070082	50-464 Q	CALVO JA	8604270272	50-498 P	CHILK,S.J.	8804050084	50-443 G
BYRAM P G	8894040217	50-387 S	CALVO JA	8804280163*	50-285 P	CHILK,S.J.	8804050155	10CFH
BYRAM R G.	8804060257	50-387 S	CAMILERIT J	8804010271	50-461 S	CHILK,S.J.	8804050248	10CFH
BYRAM P G	8804060269	50-380 S	CAMPBELL JJ.	8804080138*	FOIA	CHILK,S.J.	8804050411	50-498 F
BYRAM R G	6804120073	50-308 S	CAMPBREL R.K	8804060175	50-387 I	CHILK,S.J.	8804080133	10CFH
BYRAM, BIG	6804200222	50-388 S	CAMPBELL,T.G. CAMPBELL,T.G. CAMPBELL,W.R. CANT.G. CANTHELL,F.	8804210054	50:368 P	CHILK,S J.	8804110079	10CFR
BYRAM, RIG	8804250032	50-388 S		8804210270	50:313 P	CHILK,S J.	8804110184	50:443 G
BYRD, B.	8804250285	50-416 S		8804140098	50:483 S	CHILK,S J.	8804110192	40:2061
BYRNE, J.P.	8804110327*	50-267 P		8804130286	I&E	CHILK,S J.	8804120236	50:277 F
CACC'APOUTI, B.	8803310254*	50-309 P		8804080259*	50:338 O	CHILK,S J.	8804120472	FOIA
CADMAN,W K	8804180432*	50-482 L	CANTRELL.F.F	8604050301	50-281 S	CHILK,S.J.	8804140322	10CFR
CAIN,C L	8804070145	STATE PRO G	CANTRELL.F.S	8204010047*	50-280 Q	CHILK,S.J.	8804140475	10CFR
CAIN,C L	8804180186*	FOIA	CANTRELL.F.S	8804260232*	50-280 O	CHILK,S.J.	88041500641	NUREG
CAIN,C L	8604180295*	FOIA	CAPOZZI,C.	8804140214*	PROJ	CHILK,S.J.	88041500991	NUREG
CAIN,J M.	8904250100*	50-382 I	CAPRA.R.A.	8803080255*	50-410 P	CHILK,S.J.	8804190078	FOIA
CAIN, J M	8804250111*	50-382 (САРПА П А.	8804050181	50-220 P	CHILK,S.J.	8804193240	FOIA
CALDWELL, C	8004190113*	50-528 Q	САРПА П А.	8804050294*	50-220 P	CHILK,S.J.	8804200374	10CFR
CALDWELL, C W	8604040235*	50-397 Q	САРПА П А	8804050306	50-220 P	CHILK,S.J.	8804250016*	ORG
CALDWELL, C W	8804190120*	50-397 Q	САРПА П А	8804140534	50-318 P	CHILK,S.J.	8804260033	50-528 G
CALDWELL, J L	8804090259*	50-338 Q	САРПА П А	8804190076*	50-410 P	CHILK,S.J.	8804260044	50-312 G
CALLAN,E J.	8003200311	50-285 V	CAPRA, IR A	8804190241*	50-410 P	CHILK, S. J.	8804260051	50-498 C
CALLAN,E J	8803300085	50-285 Q	CAPRA, IR.A	8804220014	50-410 P	CHILK, S. J.	8804260064	50-443 G
CALLAN,E J.	8803300089	50-285 Q	CAPRA, ER.A	8804280046*	50-410 P	CHILK, S. J.	8804260066	50-312 C
CALLAN,E J.	8803300104	50-285 Q	CAPSTICK, R.W	8804040122	50-271 J	CHILK, S. J.	8804260096	50-289 C
CALLAN,E.J	8603300117	50-313 P	CAPSTICK, R.W.	8804270232	50-271 P	CHILK, S. J.	8804270076*	PR
CALLAN, E.J. CALLAN, L.J. CALLAN, L.J. GALLAN, L.J. CALLAN, L.J.	8803300124 8803300135 6803300161 8803300203 8803310032	50-498 O 50-498 O 50-498 O 50-498 O	CARLILE,T.S. CARLSON,J CARNS,N S. CARNS,N S CARNS,N S	8604050122 8804040092 880328CD37 8803280065 8804070213	40-7580 50-295 S 50-382 S 50-382 S 50-382 S	CHILK, S. J. CHILK, S. J. CHILK, S. J. CHOU, R.C. CHOULES, N.C.	8804280281 8804280389 8804290236 8804050385' 8804150009'	10GFA 50:312 F 10GFA 50:321 G 50:373 G
GALLAN, L.J.	8803310114	50-313 P	CARNS,N S	8804200373	50-382 S	CHRISTENSEN,J	8804260140	50-445 C
GALLAN, L.J.	8803310127	50-192 Q	CARNS,N S	8804200377	50-382 S	CHRISTENSEN,J	8804290146*	50-445 C
GALLAN, L.J.	8804040238	50-267 Q	CARNS,N S.	8804200379	50-382 S	CHRISTIANSSON	8904040154*	FOPREP
GALLAN, L.J.	8804040246	50-382 Q	CARNS,N S.	8604200383	50-382 S	CHRISTMAN,J N	8804060219	50-322 C
GALLAN, L.J.	8804050108	50-498 Q	CAHNS,N S.	8804210259	60-382 S	CHRISTMAN,J N	8804060219	50-322 C
CALLAN, LJ. CALLAN, LJ CALLAN, LJ CALLAN, LJ. CALLAN, LJ.	8804050212 8604050234 8604060027 8804060036 8804060057	50-208 Q 50-458 Q 60-128 Q 50-298 V 50-498 Q	CARNS,N S. CARPENITO, A C CARPENTER, D R, CARPENTER,J. H. CARRICO, B	6804270055 6804280236 8604070045* 6804280035 8804280130*	50-362 S XPORTLIC 50-498 Q 50-440 G PR	CHRISTMAN, J.N. CHRISTMAN, J.N. CHRISTMAN, J.N. CHRISTMAN, J.N. CHRISTMAN, J.N.	8604110025 8804110025 8804290066 8804290066 8804290077*	50-322 C 50-322 C 50-322 C 50-322 C
CALLAN,E J CALLAN,E J. CALLAN,E J. CALLAN,E J. CALLAN,E J.	8804060320 8304080322 8604080394 8804080482 8304070031	50-286 V 50-459 O 50-289 O 50-267 O 60-498 O	CARRION,R.P. CARTER,R.S. CARTER,T.F CASE,D.T. CASE,D.T.	8804050385* 8804070152 6804280608* 8804290030 8804290030	50-321 O 50-184 R PR 60-322 G 50-322 G	CHRISTMAN, J N CHRISTMAN, J N CHRISTMAN, J N CHRISTMAN, J N CHRISTMAN, J N	8804290077* 8804290087 8804290087 8804290096* 8804290096*	50-322 C 50-322 C 50-322 C 50-322 C
CALLAN, L.J.	8804070227	50-267 Q	CASE.JA	8804110006*	WASTE MGT	CHRISTMAN J N	8804180020	50-322 C
CALLAN, L.J.	8804060189	50-458 Q	CASEY,S.M	8804260103	50-322 G	CHRISTMAN J N	8804180020	50-322 C
CALLAN, L.J.	8804080196	50-452 Q	CASEY.S.M.	8804260103	50-322 G	CHRISTNOT, E.F.	8803310292*	50-259 C
CALLAN, L.J.	6004110080	50-468 Q	CASTRO.B	8804050283	50-254 S	CHUNG, D.H	8804070157	WASTE RES
CALLAN, L.J.	8604110200	50-285 Q	CATACOSINOS,W.	8803310055	50-322 I	CHUNG, D.H	8804120451	WASTE RES
CALLAN, L.J.	8604120013	50-298 Q	CATLETT,C FI	6804200041	WASTE RES	CILLIS, M.	8804130009*	50-397 (
CALLAN, L.J.	8804120034	50-458 Q	CATTON,I	8804130272	ACRS	CIPRIIANI, J.	8804120044	50-346 H
CALLAN, L.J.	8804120040	50-458 Q	CATTON,I	8804130393	50-338 O	CLARK, A.T.	8804110254	50-603 /
CALLAN, L.J.	8604120116	50-400 Q	CATTON,I	8804130400	ACRS	CLARK, D.D.	8804120249*	50-97 (
CALLAN, L.J.	8804120128	50-287 Q	CATTON,I	8804130417	ACRS	CLARK, E.G.	8804290019	50-275 (
CALLAN, L.J. CALLAN, L.J. CALLAN, L.J. CALLAN, L.J. CALLAN, L.J. CALLAN, L.J.	8804120147 6004120323 8604120365 8804130025 8804140015	58-458 O 50-265 F 60-313 O 50-208 O 50-482 O	CESARE.J.G.	8804150249 8804150262 8803300376 8804200564 8804040252*	50-416 H 50-416 H 50-416 Q 50-415 P 50-382 Q	CLARK, P.R. CLARK, P.R. CLARK, P.R. CLARK, P.R. CLARK, P.J.	8804120356 8804130252 8804250182 8804260301* 8804110035*	50-289 (50-219 (50-219 (50-219 1 50-352 (
CALLAN, L.J. CALLAN, L.J. CALLAN, L.J. CALLAN, E.J. CALLAN, L.J.	8804140086 8804150288 8004150292 8004200296 8804200297	50-482 Q 50-482 Q 60-285 F 60-482 P 50-298 F	CHAMBERLAIN,D. CHAN,T. CHAN,T.L. CHAN,T.L. CHAN,T.L. CHAN,T.L.	8804210326* 8804040134 8804080186 8804190137 8804250203	50:313 Q 50:344 P 50:344 P 50:344 P 50:344 P	CLARKE,R A. CLARKIN.K. CLEVELAND,J E. CLINE W.E. CLINE,W.E.	8804120409 8804050424 6804280367 8803290266 6804010097	50-133 40-8502 40-8905 50-413 70-1113
CALLAN, E.J.	0804200333	50-382 F	CHANDLER L.I	8804280533	50-344 F	CLINE, W.E.	8804010214	50-321
CALLAN, E.J.	0804200513	50-498 P		8804120117*	50-498 P	CLINE, W.E.	8804040239	50-395
CALLAN, E.J.	0804210317	50-313 Q		8804060031*	50-128 O	CLINE, W.E.	8804060274	70-143
CALLAN, E.J.	8804250045	50-313 Q		8804280031*	50-313 Q	CLINE, W.E.	8804060352	70-143
CALLAN, E.J.	8804250058	50-458 V		8803140355	WASTE RES	CLINE, W.E.	8804060354	70-143
CALLAN, L.J.	8804250062	50-382 G	CHAO,B.T.	8804010116	NUREG	CLINE, W.E.	8804110322	50-280
CALLAN, L.J.	8804250091	50-267 P	CHAPELL,D.R.	9804280168*	PR	CLINE, W.E.	6804120022	50-321
CALLAN, L.J.	8804250116	50-267 G	CHAPELL,D.R.	8804280279*	PR	CLINE, W.E.	8804120067	70-27
CALLAN, L.J.	8804250123	50-458 G	CHAPELL,D.R.	8804280487*	PR	CLINE, W.E.	8804120291	50-280
CALLAN, L.J.	8804250292	50-267 P	CHAPMAN,C.C.	8804140200*	PROJ	CLINE, W.E.	8804140047	50-280
CALLAN,L J CALLAN,L J. CALLAN,L J. CALVO,J A. CALVO,J.A.	9804250334 8804260023 8804260038 8804050117 8004080221*	60-382 C 50-313 C 50-482 C 50-382 C 50-382 F	CHARNLEY,J.S CHARNLEY,J.S.	8804060345 8804060506' 8804150017' 6804220041' 8804150192'	TOPREP 50-265 P 50-458 P 50-220 P CONTRACT	CLINE, W.E. CLINE, W.E. CLINE, W.E. CLINE, W.E. CLINE, W.E.	8804140133 6804180005 8804250053 6804250059 8804260004	50-338 70-143 70-143 50-400 50-338
CALVOJ.A. CALVOJ.A CALVOJ.A. CALVOJ.A. CALVOJ.A.	8804080250° 8804080258° 8804120035° 8804140050° 8804150021	50-382 F 50-298 F 50-458 F 50-368 F 50-286 F	CHEMA,T.V. CHERY,D.L. CHILOS,W.V.	8804050074° 8804270123° 8804080062 8804130405 8804130412	50-220 O 50-440 F WASTE MGT 50-333 S 50-333 S	CLINE,W.E. CLINE,W.E. CLINE,W.E. CLINE,W.E. CLINE,W.E.	8804260008 8804260024 8804260029* 8804260112 8804260113*	50-395 50-348 50-348 70-1113 70-1113
CALVO, J.A.	8804150212	50-499 E		8804010220	50-320 P	CLINE,W.E.	8804260398	50-250
CALVO, J.A.	8804100008*	50-287 F		8804040262	50-328 P	CLINE,W.E.	8804270170	PR
CALVO, J.A.	8804190221*	60-458 F		8804050077	50-443 G	CLINE,W.E.	8804290287	70-1151

AUTHOR	ACCESSION NUMBER	SUBJEC CATEGOR		AUTHOR	ACCESSION NUMBER	SUBJECT		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CLINE, W.E. CLINE, W.E. COCHRANE, D.B. COCKFIELD, D.W. COCKFIELD, D.W.	8804290291 8804290292 8804280342 8804040048 8804040088	50-302 70-143 40-8084 50-344 50-344	F P	CONSTABLE,G L CONSTABLE,G L. CONVERSE,R.J. CONVERSE,R.J. CONVERSE,R.J	8804040240 8804070045* 8804130405 8804130412 8804150054	50-498 50-496 50-333 50-333 50-333	S Q S S R	COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G.	6804060515 8804060517 8804060525 8804070083 8804080141	50-445 A 50-445 Q 50-445 Q 50-445 A 50-445 S
COCKFIELD, D.W. COCKFIELD, D.W. COCKFIELD, D.W. COCKFIELD, D.W. COCKFIELD, D.W.	8804040160 8804060272 8804070323 8804110065 8804110067*	50-344 50-344 50-344 50-344 50-344	5 5 5 5 5 5 5 5	CONWAY,D F. CONWAY,W.F. CONWAY,W.F. CONWAY,W.F. CONWAY,W.F.	8804150270 8803100052* 8803290210 8803290280 8803290363	50-250 FOIA 50-335 50-389 50-250	F S R F	COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G.	8804110113 8804110325 8804120435 8804130003 8804130112	50-445 A 50-445 Q 50-446 Q 50-445 Q 50-445 B
COCKFIELD,D.W. COCKFIELD,D.W. COCKFIELD,D.W. COCKFIELD,D.W. COCKFIELD,D.W.	8804200013 6804200364 8804200569 8804210291 8804210294*	50-344 50-344 50-344 50-344 50-344	00 F P P	CONWAY,W.F. CONWAY,W.F. CONWAY,W.F. CONWAY,W.F.	0803300224 6803300400 8803310206 8804010049 8804060010	50-389 50-250 50-250 50-250 50-250	H H G	COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G.	8804130202 8804130207 8904130236 8804130287 8804200444	50-445 S 50-445 S 50-446 A 50-445 Q 50-445 A
COCKFIELD,D.W. COCKFIELD,D.W. COHEN,S.C. COLBURN,T.G. COLBURN,T.G.	8804220173 8804220277 8804150045* 8804010114 8804190150	50-344 50-344 NUREG 50-440 50-440	P F Q P	CONWAY,W.F. CONWAY,W.F. CONWAY,W.F. CONWAY,W.F.	8804070175 8804070179 8804070278 8804080059 8804080112	50-250 50-250 50-250 50-369 50-389	P Q R K P	COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G.	8804200472 8804200478 8604200489 8804200499 8804210092	50-445 Q 50-445 Q 50-445 Q 50-445 A 50-445 S
COLE,R.E. COLE,R.F. COLE,R.F. COLE,S. COLE,S.	8804200133 8804260049 8804260143 8804200101*	50-458 50-335 50-250 50-322 50-322	A G G T	CONWAY,W.F. CONWAY,W.F. CONWAY,W.F. CONWAY,W.F.	8804110074 8804120257 8804120332 9804120345 8804120422	50-250 50-250 50-335 50-250 50-250	Р Р О Р	COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G.	8804210145 8804210161 6804210173 8804210180 8804210188	50-445 S 50-445 S 50-445 S 50-445 S 50-445 S
COLEMAN, C. COLEMAN, C. COLEY, J. L. COLLINGS, S. P. COLLINGS, S. P.	8804070008 8604210508 6803280137* 8804280042 8804280417	27-48 27-48 50-324 40-8829 40-8829	a	CONWAY,W.F. CONWAY,W.F. CONWAY,W.F. CONWAY,W.F. CONWAY,W.F.	8804120447 8804120459 8604130144 8804130173* 8804130177	50-250 50-369 50-250 FOIA 50-250	R P S	COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G.	8804210205 8804210239 8804210249 8804210257 8804250099	50-445 S 50-445 S 50-445 S 50-445 S 50-445 S
COLLINGS,S.P. COLLINS,D.M. COLLINS,D.M. COLLINS,D.M. COLLINS,D.M.	8804280469 8803250156 8803250263 8803250265* 6803250301	40-8943 50-280 50-348 50-348 50-424	Q Q F	CONWAY,W.F. CONWAY,W.F. CONWAY,W.F. CONWAY,W.F.	8804130315 8804140297 8804150190 8804150194 8804180242	50-389 50-335 50-335 50-335 50-250	ት ት ት	COMBILL,C.J. COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G.	8804260193 8804270001 8804270002 8804270189 8804120290	50-445 A 50-445 S 50-445 S 50-445 F 50-289 P
COLLINS,D.M. COLLINS,D.M. COLLINS,D.M. COLLINS,D.M. COLLINS,D.M. COLLINS,D.M.	8803280227 8803289233* 6803260256 8804010007 8804080238	70-1201 70-1201 70-824 70-27 50-250	٥	CONWAY,W.F. CONWAY,W.F. CONWAY,W.F. CONWAY,W.F.	8804190135 8804190255* 6604180272 8804200005 8804200199	50-335 FOIA 50-335 50-250 50-250	P R R F	COWGILL,C.J. COWGILL,C.J. COWGILL,C.J.	8804120407 8804120449 8804130171 8804130179 8804190356*	50-244 O 50-219 O 50-266 P 50-289 P WASTE RES
COLLINS,D.M. COLLINS,D.M. COLLINS,D.M. COLLINS,D.M. COLLINS,D.M.	8804120124 8804120139 8804120142* 8804150325 8804150335	50-302 50-369 50-369 50-416 50-83	aaaaa	CONWAY W.F. CONWAY W.F. CONWAY W.F. CONWAY W.F.	8804200359 8804200372 8804210135 8804220108 8804250094	50-260 50-250 50-260 50-260 50-250	OR PRO	COWLES, R.B. COWLES, R.B. COWLES, R.B. COY, P. CRANWELL, R.M.	8804190025 8804200269 8804260263 8804010010 8803310204	50:354 S 50:354 S 50:354 S 50:498 H WASTE RES
COLLINS,D.M. COLLINS,D.M. COLLINS,D.M. COLLINS,S.J. COLLINS,S.J.	8804150344* 8804150392 8604150423 8804200078 8804200087*	50-83 50-413 50-413 50-293 50-293	99190	CONWAY,W.F. CONWAY,W.F. COOK,J. COOK,K.V. COOL,D.A	8804260303 8804270172 8804160054 8804080170 8804280855	60:250 50:250 50:333 NUREG MISC	9 P R	CRANWELL.R M. CRANWELL.R.M. CRANWELL,R M. CRANWELL.R M. CRANWELL.R M.	8804110142 8804200592 8804210058 8804210062 8904210208	WASTE RES WASTE RES WASTE RES WASTE RES
COLLINS,T.E. COLLINS,T.R. COLLINS,T.R. COLLINS,T.R. COLLINS,T.R. COLTON,E.	8804010160 8803280237* 8803280258* 8804120146* 8804290053*	TOPREP 70-1201 70-824 50-389 XPORTUC	Q	COOLE,M A COOPER,J,W COPELAND,R A. COPLAN,S. CORNELIUS,W.E.	8804260062 8804280503 8804260208 8804130099 8604060173	50-320 40-2061 TOPREP WASTE MO 50-483	G Fi	CRAWFORD, J.D. CRAWFORD, K.C. CRECINE, J.P. CREED, J. CREED, J.	8804190140 6804060023 8804270256 8804080211 8804130151*	50-259 R 50-128 R 50-160 Q 50-315 S 50-341 S
COLVILLE, J.M. CONDIT, R.E. CONGEL, F.J. CONGEL, F.J. CONGEL, F.J.	8804220055 8804120084 8804120263 8804120408 8804130209	50-528 50-498 70-371 70-136 50-317	A P	CORNWELL,K.F. CORWIN,W.R. COSS,H.D. COST, R.R. COST, R.R.	8804110052* 8804010275 8604120339* 8804140262 8804140269*	60:324 NUREG 50:317 71:651 71:661	Q P	CREED, J.R. CREED, J.R. CREED, J.R. CREED, J.R. CRLENJAK, G.A.	8804010D28* 8804050076* 8804200413* 8804210248* 8803250294*	50 305 O 50 341 O 50 341 O 50 268 O 50 250 O
CONGEL,F.J. CONGEL,F.J. CONGEL,F.J. CONKLIN,C. CONLON,F.B.	8804130211* 8804190341 8804250168 8804 <i>130215</i> * 8804140363*	60-317 70-1100 70-687 60-317 NUREG	Q Q	COSTLEY, W. COTTEN, P.R. COTTEN, P.R. COTTEN, P.R. COTTEN, P.R. COTTEN, P.R.	8804140295 8804180176 8804180187* 8804180456 8804180460*	71-9168 70-734 70-734 70-734 70-734		CHLENJAK,R. CRLENJAK,R.V. CHLENJAK,R.V CRLENJAK,R.V. CROCKER,D.	8803290320' 8804200286' 8804200558' 8804280218' 8804200114	50:302 Q 60:250 Q 50:250 Q 50:250 Q 50:322 T
CONLON,T.E. CONLON,T.E. CONLON,T.E. CONLON,T.E. CONLON,T.E.	8803300129* 8804010062* 8804010067* 8804060319* 8894080278*	50-395 50-335 50-416 50-324 50-425	00000	COTTER B.P. COTTER B.P. COTTER B.P. COTTER B.P. COUNCIL, W.G.	8804110019 8804120201 6604210031* 8604280049 8804110116*	50-277 MISC FOIA 50-335 70-2932	G G	CROCKER,D.M. CROCKER,L. GROCKER,L. CROCKER,L. CROCKER,L.P.	8804200147 8804150066' 8804160095' 8804220233' 8804120043	50-322 T 50-413 P 50-369 P 50-424 P 50-321 P
CONLON,T.E. CONLON,T.E. CONNELLY,L.G. CONNER,T.B. CONNER,T.B.	8804200526* 8804200579* 8804270308* 8804080044 8804080044	FOIA 50-250 50-312 50-352 50-352	Q P G	COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G.	8803250223 8804050026 8804050027 8804050034 8804050038	50-445 50-445 50-445 60-445 60-445	A \$5 \$5	CROCKER,L.P. CROCKER,L.P. CROCKER,L.P. CROCKER,L.P. CROCLEY,B.G.	8804130298 8804140037 8804210352' 8804220183' 8804010234	50-366 P 50-321 P 50-269 P 50-369 P 50-312 P
CONNOLLY, J.W. CONNOR, L. CONNOR, L. CONNOR, L. CONNOR, L.	8803310210 8804050107 8804060310 8804060369 8804120235	60-443 FOIA FOIA 50-389 FOIA	н Q	COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G. COUNSIL, W.G.	8804050340 8804060081 6604060397 8804060105 6804060186	50-445 60-445 60-445 50-446 50-445	5555	CROLEY, B.G. CROLEY, B.G. CROSS, J.A. CROUSE, T.C. CRUDEN, D.S.	8804080195 8804200184 8804190355 8803300413 8804120234	50-312 P 50-312 R WASTE MGT 50-458 Q 50-280 Q
CONNOR,L. CONNOR,L. CONNOR,L. CONNOR,L. CONNOR,L.	8804120457 8804190064 8804280143 8804280627 8804280630	FOIA FOIA FOIA FOIA		COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G.	9804080327 8804060375 8804060376 8804080393 8804080398	50-445 50-445 50-445 50-445 50-445	\$ 0\$ 50	CRUDEN,D.S. CRUDEN,D.S. CRUDEN,D.S. CRUDEN,D.S. CRUDEN,D.S.	8804130189 6604130264 8804130269 9804140013 8804190253	50-338 Q 50-336 Q 60-280 P 50-338 Q 50-338 R
CONNORS,H.J. CONRAN,J. CONROY,B.F.	8804210382* 8804130248* 8604070008*	50-282 FOIA 50-219	0 P	COUNSIL,W.G. COUNSIL,W.G. COUNSIL,W.G.	8804060398 8804060405 8804060484	50-445 50-445 50-445	s s o	CRUDEN, D.S. CRUDEN, D.S. CRUDEN, D.S.	8804250089 8804250200 8804260003	50-281 P 50-280 O 50-280 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CRUDEN.D.S.	0004260180	50.338 Q	DELLA RATTA,A	8804120198*	70-1100	DORSEY,M.	8604280615	CONTRACT
CRUDON.D.S	0804260325	50.338 R	DELLA RATTA,A.	8804250198*	70-371	DORSEY,M.	8804280643	CONTRACT
CRUNK.S.	8803200389	50.312 S	DELLIGATTI,M'S.	8804180016	WASTE MGT	DORSEY,M.	8804290190	CONTRACT
CRUNK.S.I.,	8804040073	50.312 H	DEMARCO,D.	9804280070	CONTRACT	DOSANJH,S.S.	8804080274	NUREG
CRUNK,S.L.	8804050206	50.312 P	DEMIRANDA,O.	8804260113*	70-1113	DOUGHER,J.D.	8804070011	50-219
CRUTCHFIELD,D. CRUTCHFIELD,D. CRUTCHFIELD,D. CRUTCHFIELD,D. CRUTCHFIELD,D.	6804010261*	ORG	DEMOSS,G M.	8604280386	NUREG	DOW,K.W.	6804220239*	50-443
	6804080172	50-269 P	DENSON,R H.	8804010082	NUREG	DOYLE,A.J.	6804180439*	50-482
	8804130068	50-528 Q	DENTON,H R	8405160276*	FOIA	DRAGOUN,T.	8804120053*	50-277
	8804150283	50-528 F	DEV,M.	8804260058*	50-443 Q	DRAWBRIDGE,B.L.	8803300168	50-29
	8804250210*	50 341 P	DEVINE,T.	8804150403*	NUREG	DRAWBRIDGE,B.L.	8803300217	50-29
CULBERSON, D.G.	8804050093	70-135	DEWEASE, J.G.	8803300241	\$0:382 P	DRAWBRIDGE,B.L.	8803300226	50-29
CULVER, N.	8804290019	50-276 G	DEWEASE, J.G.	8803310265	\$0:382 P	DRAWBRIDGE,B.L.	8804130376	50-29
CUMMINGS, G.E.	8802040318	WASTE RES	DEWEASE, J.G.	8804040057	\$0:382 P	DRAWBRIDGE,B.L.	8804140011	50-29
CUMMINGS, G.E.	8804070157	WASTE RES	DEWEASE, J.G.	8804080302	\$0:382 P	DREIKORN,D.P.	8804200082	50-322
CUNNINGHAM, A.L.	8804260011*	50-250 O	DEWEASE, J.G.	8804180224	\$0:382 Q	DROGGITIS,S.C.	8804060200	NUREG
CUNNINGHAM, GE CUNNINGHAM, LJ. CUNNINGHAM, LJ.	0804080205 0803100162 8804070171 0604200576 6003220208	70-754 REVIEW GRI P 50-463 S 50-298 P 50-3 O	DICK, G.F. DICK, G.F. DICK, G.F. DICK, G.F. DIDDENS, J.	8803080483 8804110316 8804140034 6804190046 6803300413	50-368 P 50-482 P 50-368 P 50-368 P 50-458 Q	DROKERS, J. DROMERICK, A.W. DROMERICK, A.W. DROMERICK, A.W. DROMERICK, A.W.	8804190350 8804050223 8804190288 8804280201 8804280231	WASTE MGT 50-219 50-219 50-219 50-219
CUNNINGHAM, R.E.	8804110200	10-8027	DIEDERICH,G J. DIEDERICH,G J. DIEDERICH,G.J. DIEDERICH,G.J. DIEDERICH,G.J.	68040\$0374	50-374 S	DROMERICK,A.W.	8804280465	50-219
CUNNINGHAM, R.E.	8804110332	PROJ		8804070326	50-373 R	DRONKERS,J	8804260182	WASTE MGT
CUNNINGHAM, R.E.	8804270093*	PR		8804080047	50-374 S	DRONKERS,J J.	8804150071	WASTE MGT
CUNNINGHAM, R.E.	8804270111*	PR		6804140127	50-374 S	DROUIN,B	8804210248*	50-266
CUNNINGHAM, R.E.	8804280352*	PR		8804140330	50-373 R	DROUIN,B.S.	8804050076'	50-341
CURAN,D. CURRAN,D. CURRAN,D. CURRAN,D. CURRAN,D.	8804260067 8804260067 8804260007 8804260076°	50-443 G 50-443 G 50-443 G 50-443 G 50-443 G	DIEDERICH,G.J. DIETZ,C.R. DIETZ,C.R. DIETZ,C.R. DIETZ,C.R. DIETZ,C.R.	8804200212 8803290261 8803300324 8804060277 8804070153	60-373 S 50-325 S 50-324 R 50-325 S 50-325 S	DRUGA,R.J. DUDLEY,N DUGSTAD,D DUNCAN.J.J. DUNDAS,W.J.	8804060095 8804250315* 8804150133 8804220054* 8804140089	50-334 50-334 50-262 50-327 50-266
CURRAN,D	8804260079	50-443 G	DIETZ,C.R.	8804110041	50-325 S	DUNLOP,A.	8804040141°	50-454
CURRAN,D.	8604260079	60-443 G	DIETZ,C.R.	8804130331	50-324 S	OUNN,G A.	8804140123	50-440
CURRAN,D.	8804260001*	50-443 G	DIETZ,C.R.	8804130350	50-324 Q	DUNN,G.A.	6804190081	50-440
CURRAN,D	8804280001*	50-443 G	DIETZ,C.R.	8804150385	50-324 F	DUPREE,D.C.	8804220020	50-327
CURRAN,D.	88042800124	50-443 G	DIETZ,C.R.	8804180454	50-324 F	DURENBERGER,D	8804130178°	COMMISSIO
CURRAN,O.	8804280124	50-443 G	DIETZ.C.R.	8804200098	50-324 Q	DURR,J.P.	8804010270	50-309
CURREN,O.	8804180087	50-443 G	DIETZ.C.R.	8804200516	50-324 Q	DURR,J.P.	8804010273	50-353
CURREN,O.	8804180087	60-443 G	DIETZ.C.R.	8804260001	50-324 S	DURR,J.P.	8804040007	50-311
CZAJKOWSKI,G.	8804280217'	50-348 Q	DIETZ.C.R.	8804270069	50-324 F	DURR,J.P.	8804050068	50-220
O'ANGELO,A J.	8804120375'	50-312 Q	DIETZ.C.R.	8804270088	60-324 P	DURR,J.P.	6804050236	50-336
D'ANGELO,T.	8803290351	50-312 S	DIFFERENT,P.M.	8804080063	50-416 S	DURR,J.P.	8804070249	50-353
D'ANTONIO,J.R.	8804080065	WASTE MGT	DIFFERENT,P.M.	8804080277	50-416 S	DURR,J.P.	8804200060	50-289
D'ANTONIO,J.R.	8804280001	WASTE MGT	DIFFERENT,P.M.	8804200007	50-416 S	EAPEN,P.K.	8804010274*	60-353
DANON,D J	8803300165*	60-315 V	DIGGS,R.M.	8803080002	50-213 P	EAPEN,P.K.	8804050240*	50-336
DAMPF.J.F.	8804200302	50-463 F	DIGGS,R.M.	8803080023	50-334 P	EAPEN,P.K.	8804070251*	50-353
DANCE, H.C.	8604060267*	50-348 Q	DIGGS,R M.	8803080514	50-331 Q	EAPEN,P.K.	8804200064* 8804040261* 8804120119* 8803310263 8804050313	50-289
DANGE, H.C.	8804120171*	50-418 Q	DIGGS,R.M.	8804220124	50-29 P	EARNEST,A.B.		50-445
DANGE, H.C.	8804160360*	50-395 Q	DIGGS,R.M.	8804220128	50-382 P	EARNEST,A.B.		50-498
DANDINI, V.J.	8804280568	NUREQ	DIGGS,R M.	8804220133	50-263 P	EBNETER,S.D.		50-327
DANIELSON, D.	6804060432*	50-249 Q	DIGGS,R.M.	8804220220	50-247 P	EBNETER,S.D.		50-327
OANIELSON,D.H.	8804060511'	50-305 Q	DIGGS,R.M.	8604280427	50-285 P	EBNETER,S.D.	8804130286	50-327
DANIELSON D.H.	8804260511'	50-237 Q	DIGGS,R.M.	6804290136	50-424 P	EBNETER,S.D.	8804140002	50-445
DANIELSON,D.H.	8804260163'	50-341 Q	DIGGS,R.M.	8604290189	60-449 P	EBNETER,S.D.	8804290151	50-327
DAVIDSON,B.S.	8804200046'	50-334 Q	DIGIOVINE,A.S.	6804210012*	60-29 P	EBNETER,S.D.	8804290164*	50-327
DAVIDSON,J.	8804130165'	50-165 P	DIGNAN,T.G.	8804050089	50-443 G	EDGAR,G.L.	8804110017	50-445
DAVIS.A.B.	8804010250	60-457 O	DIGNAN,T.G.	9804200308	50-443 G	EDGAR, G.L.	8804110017	50-445
DAVIS.A.B.	8804010266	50-263 O	DIGNAN,T.G.	8804200308	50-443 G	EDGAR, G.L.	8804110023	60-445
DAVIS.A.B.	8804050002	50-456 P	DIGNAN,T.G.	8804290028	50-443 G	EDGAR, G.L.	8804110023	50-445
GAVIS.A.B.	8804060020	50-155 O	DIGNAN,T.G.	8604 <i>290026</i>	50-443 G	EDGAR, G.L.	8804180030	50-445
DAVIS.A.B.	8804080371	50-266 P	DIGNAN,T.G.	8804290084	50-443 G	EDGAR, G.L.	8804260065	50-445
DAVIS,A B.	8804120355	60-315 P	DIGNAN,T.G.	8804290084	50 443 G	EOGAR G.L.	8804260065	50-445
DAVIS,A.B.	8804270165	60-341 P	DIIANNI,D.C.	8804190083	50-282 P	EDGAR G.L.	8804260260	50-445
DAVIS,A.B.	8804270221	60-341 S	DILANNI,D.C.	8804280101	50-282 P	EDGAR G.L.	8804260260	50-445
DAVIS,J.W.	8804080023	50-128 R	DILWOATH,S.C.	8804220023	50-424 R	EDGAR G.L.	8804260286	50-445
DAVIS,P.	8804190370	WASTE RES	DIMEGLIO,A.F.	8804210335	50-193 P	EDGAR G.L.	8804260288	50-445
DAVIS,P.R.	8804130256	50-286 O	DIPPELL, R.E.	8604200114	50-322 T	EDGAR, G.L.	8804290129	50-445
DAY,B.	8804120169	60-498 P	DIPPELL, R.E.	8804200114	50-322 T	EDISON, G.E.	8803080286	60-250
DAY,P.	8804280347	FOIA	DIRCKS, W.J.	8009190791*	PR	EDISON, G.E.	8804040098	50-250
DE AGAZIO,A.W.	8804210172	60-340 P	DIRCKS, W.J.	8408060365*	FOIA	EDISON, G.E.	8804110218	50-250
DE AGAZIO,A.W.	8804260018	50-346 P	DIRCKS, W.J.	8603120387*	FOIA	EDISON, G.E.	8804130011	50-250
DEAN,W.M.	8803180337°	50.269 V	DIXSON,G.R.	8804110069	WASTE MGT	EDISON,G.E.	8804180204	50-250
DEARIE,K.A.	8804140424	FOIA	DIXSON,G.R	8804130240	WASTE MGT	EDISON,G.E.	8804220291	50-250
DEB,A.	8801040586°	50.382 Q	DODA.R.J.	6803290137	I&E	EDISON,G.E.	8804220293*	50-250
DECKER,T.R.	9803250286°	50.348 O	DOMERTY,E.J.	8804200113*	50-322 T	EDISON,G.E.	8804280239	50-250
DECKER,T.R.	8803280132°	50.413 Q	DONLON,W.J.	8804200253	50-220 I	EDISON,G.E.	8804280470	50-250
DECKER,T.A.	8803300354°	50-321 O	DONOMBU,J.N. J.N.WEHONOD J.N.WEHONOD J.N.WEHONOD J.N.WEHONOD J.N.MAIROD	8804130392	50-327 P	EOISON G.E.	8804280498*	50-250
DECKER,T.R.	8804250011°	50-250 O		8804140178	50-327 P	EDMONSON,L.R.	8804200475*	CONTRACT
DECKER,T.A.	8804260028″	50-327 O		8804150048	50-327 P	EDWARDS,D.L.	8804290197	40-3453
DEDDENS,J.C.	8804130402	60-468 O		8804280286	50-327 P	EDWARDS,D.W.	8803310201	50-29
DEDDENS,J.C.	8804150012	60-458 P		8709300402	50-264 P	EENIGENBERG,E.	8804150406	50-237
DEELSNYDER.L.	8804220070	50-254 R	DORSEY,M.	8804050307	CONTRACT	EENIGENBURG,E.	8803280022	50-237
DEFAYETTE,R.	8804200502'	50-305 Q	DORSEY,M.	6804200305	CONTRACT	EENIGENBURG,E.	6804010238	50-10
DEFAYETTE,R.	8804200519'	50-266 Q	DORSEY,M.	8604200414	CONTRACT	EENIGENBURG,E.	8804220163	50-10
DEFAYETTE.R.	8804200560'	50-346 Q	DORSEY,M.	6804200445	CONTRACT	EENIGENBURG,E.	8804270052	50-10
DELANEY,L.H.	8804150102'	50-206 P	DORSEY,M.	9804200566	CONTRACT	EICK,S.D.	6804150009*	50-373
DELARCHE,G.	8804280388	NUREG	DORSEY,M.	8804220117	CONTRACT	EIDSON,A.F	8804280444	NUREG
DELGEORGE,L.D.	8803310282	50-456 P	DORSEY,M.	8804220127	CONTRACT	EISENHUT,D.G.	8805140252*	FOIA
DELGEORGE,L.O.	8804150084	50-456 P	DORSEY,M.	8804280607	CONTRACT	EISENSTATT,L.R.	6804140197*	PROJ

265

FREEMAN, M.D.

AUTHOR	ACCESSION NUMBER	SUBJEC		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR	[Y
GLEASON,J.P GLOERSEN,W.B. GOERING,R J GOLDBERG,J H GOLDBERG,J H	8804260035 8804150299* 8604200463 8604040054 8804060473	50-322 50-348 50-456 50-498 50-498	G O F O O	GREENMAN,E G GREENMAN,E G GREENMAN,E G GREENMAN,E G GREENMAN,E G	8804200403 8804200421 8804200424* 8804200498 8804200572	\$0-341 \$0-456 \$0-458 \$0-237 50-341	P 0 0 0 P	GRIMSLEY,D GRIMSLEY,D GRIMSLEY,D GRIMSLEY,D GRIMSLEY,D	8804210351 8804220149 8804220169 8804260069 8804280153	50-445 FOIA 50-283 50-275 FOIA	A Q P
GOLDBERG J.H. GOLDBERG J.H. GOLDEN,W.B. GOLDMAN,P.A.	8804210215 8804220001 8804250076 8804220155 8804080135	50-498 50-498 50-498 50-293 FO:A	0000	GREEN VAN E.G. GREENMAN E.G. GREENMAN E.G. GREENMAN E.G. GREEN WAN E.G.	8804200584 8804250296 8804250304* 8604250314 8804250328	50-286 50-457 50-457 50-346 50-237	80010	GRIMSLEY,D. GRIMSLEY,D. GRIMSLEY,D. GRIMSLEY,D. GRIMSLEY,D.	8804280240 8804280358 8804280395 8804280412 8804280670	FOIA FOIA FOIA 50-155 FOIA	o
GCLOSMITH,S. GOLLAJ A. GOLLER,K.R. GOLLER,K.R. GONZALEZ,R.O.	6904070264 8804200064* 8503190161* 8503260124* 8904060206	WASTE MO 50-288 PA PR 40-8905	Q Q	GREENMAN,E.G. GREEVES,JT GREGER,L.R. GREGER,L.R. GREGER,L.R.	8804260206 8803300375 8804040227* 8804060462` 6804060013*	50-461 WASTE MG 50-456 50-461 50-456	o T 000	GRIMSLEY,D. GRIMSLEY,D. GRIMSLEY,D.H. GRIMSLEY,D.H. GRIMSLEY,D.H.	8804290089 8804290137 8804060068 8804060090 8804060122	FOIA FOIA FOIA 50-458 FOIA	Q
GOOD,G.M GOODEN,A GOODEN,A GORALSKI,G. GORDON,C S	8804190134* 8803250266* 8903300354* 8804150398 8804070205	50-206 50-348 50-321 50-255 50-346	00088	GREGER, L.R. GREGER, L.R. GREGER, R. GREGER, R. GREGG, H	8804120400* 6804140070* 8804130197 8804210202 8804200064*	50-346 50-341 50-454 50-461 50-289	0 0 8 0	GRIMSLEY,D.H GRIMSLEY,D.H. GRIMSLEY,D.H. GRIMSLEY,D.H. GRIMSLEY,D.H.	8804060128 8804060377 8804050385 8804070123 8804080137	FOIA 50-214 FOIA FOIA FOIA	0
GORDON,C Z. GORDON,E C. GORE,B.F. GOULD,G.J	8804250162° 8804260415 8804290078 8804050160 8804130395	60-277 60-220 71-654 60-313 50-266	Q F P J	GRESICK, J GRESICK, JA GRIDLEY, R GRIDLEY, R GRIDLEY, R.	8804120270* 8804120042* 8803290339 8603310129 8804010212	70-371 50-29 50-300 50-259 50-259	Q K P F	GRIMSLEY,O.H. GRIMSLEY,D.H. GRIMSLEY,D.H. GRIMSLEY,D.H. GRIMSLEY,D.H	8804110274 8804120002 8804120095 8804120203 8804130125	50-334 FOIA 50-498 50-498 50-155	0 P P
GOVE,R.M GRAĐER,L GRACE,J.N. GRACE,J.N. GRACE J.N.	8804200041 8804280169 8803250307 8803280005 8803280061	WASTE RE: FOIA 50:251 50:250 50:160	S О Р	GRIDLEY,A. GRIDLEY,R GRIDLEY,A. GRIDLEY,A. GRIDLEY,R.	8804010260 8804010285 8804040016 8804040102 8804040111	50-259 50-260 50-327 50-390 50-258	P P P P P S O	GRIMSLEY,D.H. GRIMSLEY,D.H. GRIMSLEY,D.H GRIMSLEY,D.H GRIMSLEY,D.H.	8804130212 8804140222 8804140342 8804140345 8804140365	FOIA FOIA FOIA FOIA FOIA	
GRACE J.N. GRACE J.N. GRACE J.N. GRACE J.N. GRACE J.N.	8803290344 8804010005 8804010019 8804010045 8804010046	50-424 50-250 50-280 50-413 50-280	Q P Q P Q	GRIDLEY,R GRIDLEY,R GRIDLEY,R GRIDLEY,R GRIDLEY,A	8804040124 8804040129 8804040272 8804050067 8804080067	50-258 50-327 50-327 50-259 50-259	+00 JE	GRIMSLEY,D H. GRIMSLEY,D H. GRIMSLEY,D.H. GRIMSLEY,D H. GRIMSLEY,D.H	8804140462 8804140496 8804140538 8804150332 8804150433	50-275 FOIA FOIA 50-445 FOIA	Ą
GRACE J N GRACE J N GRACE J N GRACE J N GRACE J N	6804010088 8804010094 8804070075 8804070144 8804080228	50-414 70-27 50-250 50-160 70-143	P P P	GRIDLEY,R. GRIDLEY,R. GRIDLEY,R. GRIDLEY,R, GRIDLEY,R.	8804060241 8804060285 8804060383 8804060390 8804060417	50-327 50-259 50-259 50-327 50-327	O F B B B	GRIMSLEY,D.H GRIMSLEY,D.H GRIMSLEY,D.H GRIMSLEY,D.H GRIMSLEY,D.H	8804180160 8804180191 8804180297 8804180348 8804180357	FOIA FOIA FOIA FOIA	
GRACE, J.N. GRACE, J.N. GRACE, J.N. GRACE, J.N. GRACE, J.N.	8604110243 8804110298 8804110301* 8804120174 8804120338	50-280 50-338 50-338 50-335 59-413	P 0000 000	GRIDLEY,R. GRIDLEY,R. GRIDLEY,R. GRIDLEY,R. GRIDLEY,R.	8804060427 8804060439 8804060440 8804060500 8804070070	50-327 50-390 50-327 50-390 TOPREP	P S P A	GRIMBLEY, D. H GRIMBLEY, D. H. GRIMBLEY, D. H. GRIMBLEY, D. H. GRIMBLEY, D. H.	8804180389 8804190030 8804190050 8804190053 8804190191	50-482 FOIA FOIA FOIA FOIA	þ
GRACE J N GRACE J N GRACE J N GRACE J N GRACE J N	8804180255 8804190021 8804190102 8804200276 8804200552	50-302 50-321 50-270 50-250 50-250	00100	GRIDLEY,R. GRIDLEY,R. GRIDLEY,R. GRIDLEY,R. GRIDLEY,R.	6504070112 8504070254 8604110131 8804110206 8804120111	50-390 50-259 50-259 50-390 50-390	OR 000	GRIMSLEY, D.H. GRIMSLEY, D.H. GRIMSLEY, D.H. GRIMSLEY, D.H. GRIMSLEY, D.H.	8804190242 8804200473 8804210025 8804250088 8804250350	50-275 50-261 FOIA 50-3 50-293	Р О У Р
GRACE, J.N. GRACE, J.N. GRACE, J.N. GRACE, J.N. GRACE, J.N.	6804200575' 8804210162 8804210474 8804220027 8804250009	50-261 50-321 50-348 50-250 50-250	O P Q R Q	GRIDLEY,A. GRIDLEY,A. GRIDLEY,R. GRIDLEY,R. GRIDLEY,R.	8804130246 8804130374 8804140006 8804140009 8804150279	50-259 50-327 50-327 50-390 50-327	0 F P Q F	GRIMSLEY,D.H GRIMSLEY,D.H. GRIMSLEY,D.H GRIMSLEY,D.H. GRIMSLEY,D.H.	8804260011 8804270264* 8804280154 8804280178 8804280208	50-496 PR FOIA 40-2061 50-482	b b
GRACE J N GRACE J N GRACE J N GRACE S GRACE S	8804260072 8804290278 8804290281 8804050370 8804060016	50-280 50-348 50-321 40-8904 40-8904	Q Q P	GRIDLEY,R. GRIDLEY,R. GRIDLEY,R. GRIDLEY,R. GRIDLEY,R.	8804200464 8804210017 8804210022 8804210023 8804210024	50-327 60-269 60-327 60-259 50-327	00000	GRIMSLEY, D.H. GRIMSLEY, D.H. GRIMSLEY, D.H. GRIMSLEY, D.H. GRIMSLEY, D.H.	8804280287 8804280468 8804280504 8804280636 8804290240	FOIA FOIA FOIA 50-289 FOIA	Þ
GRANDSTAFF,E. GRANT,G GRANT,N W. GRANT,N W. GRANT,W,B	8604210210* 8804070248 8804220074* 8804220111* 6804040216*	CONTHACT 50-271 50-250 50-250 60-457	S R R O	GRIDLEY,R. GRIDLEY,R. GRIDLEY,R. GRIDLEY,R. GRIDLEY,R.	6804210026 8804210055 6804210312 8804220022 6804220032	50-259 50-438 50-327 50-390 50-259	P	GHIN,G M. GRISAK,G.E GRISAK,G E. GRISAK,G E. GRISAK,G E.	8804270263* 8804060300 8804140236 8804140539 8804280536	60-348 40-8904 40-8904 40-8904 40-8904	F
GRANT.W.B. GRAVES,D.N GRAVES,D.N. GREEN,A.E GREENMAN,E G	8804120400° 6803250295 6804060042° 8804060113 6803300426	50-346 50-298 50-298 71-641 50-295	Q V Q	GRIDLEY,R GRIDLEY,R. GRIDLEY,R. GRIDLEY,R. GRIDLEY,R.	8804220042 6804260032 8804260371 8804260385 8804270007	NUREG 50-259 50-327 50-327 60-390	е к О 8	GROCHOWSKI,T. GROPP,R.W. GRUHLKE,J.M. GRUNSEICH,R.W. GUCWA,L.T.	8804290229 8804190153 8804150322' 8804280248 8803250137	FOIA 50:352 NUREG 50:322 50:424	R S F
GREENMAN,E G. GREENMAN,E G. GREENMAN,E G. GREENMAN,E G. GREENMAN,E G.	8804010124 6604010282 8804050003 6804060083 8804060338	50-461 50-461 50-456 60-456 50-263	00000	GRIDLEY,R. GRIDLEY,R. GRIDLEY,R. GRIDLEY,R. GRIDLEY,R.	8804270164 8804270223 8804270299 8804280095 8804280226	50-327 50-327 50-327 50-327 40-1341	000 F	GUCWA,L.T. GUCWA,L.T. GUCWA,L.T. GUCWA,L.T. GUCWA,L.T.	8803290347 8803300016 8804010263 8804040037 8804040044	50-424 50-424 50-321 50-424 50-321	12 13 14 15 15 15 15 15 15 15
GREENMAN,E.G. GREENMAN,E.G. GREENMAN,E.G. GREENMAN,E.G. GREENMAN,E.G.	6804060441 8804060460 8804070115 6804070265 8804080019	50-254 50-373 50-341 50-237 50-440	94000	GRIDLEY, R. GRIDLEY, R. L. GRIDLEY, R. L. GRIDLEY, R. L. GRIDLEY, R. L.	8504280276 8804280635 8504070312 8804180250 8604180257	40-1341 50-259 50-390 60-327 50-269	O K F F	GUCWAL.T GUCWAL.T GUCWAL.T. GUCWAL.T. GUCWAL.T.	8804040072 8804040242 8804040277 8804070017 8804070023	50 32) 50 366 50 424 50 424 50 321	SSRPO
GREENMAN,E.G. GREENMAN,E.G. GREENMAN,E.G. GREENMAN,E.G GREENMAN,E.G.	8804080032 8804120078 8804120388 8804120398 8804130344	50-341 50-341 50-341 50-341 50-440	P0000	GRIDLEY,R.L. GRILLO,M. GRIMES,C.L. GRIMES,C.L. GRIMES,C.L.	8804220250 8803310275 8803080488 8803100014 8804010162	50-259 50-443 50-445 50-445 50-445	F 0 A E	GUCWA,L.T. GUCWA,L.T. GUCWA,L.T. GUCWA,L.T. GUCWA,L.T.	8804070322 8804080012 8804080051 8804080065 8804110024	50-424 50-424 50-366 50-424 50-321	P 888
GREENMAN,E.G. GREENMAN,E.G. GREENMAN,E.G.	8804140436 8804180098 8804190403	50-409 50-237 50-315	0 0	GRIMES,C.I. GRIMES,C.I. GRIMSELY,D.H	8804220078 8804280634 8804130119	50-445 50-445 FOIA	P	GUCWA,L.T. GUCWA,L.T. GUCWA,L.T.	8804130117 8804130120 8804130275	50-424 50-424 50-321	880

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION	
GUCWAL 1 GUCWAL 1 GUCWAL 1 GUCWAL T GUCWAL 1	8804190118 8804200164 8804200215 8804210019 8804220023	50-321 H 50-424 P 50-424 P 60-424 P 50-424 R	HARRELLE W HARRELLE W HARRELLP H HARRISH G HARRISJ R	8803310237 8804080029 8603310101 8804280144* 6803300129*	50 338 S 50 339 S 50 285 Q 50 255 Q 50 395 Q	HEITNER, K L HEITNER, K L HEITNER, K L HEIFRECHT, D. I HELTEWES, C J	8304110102 880419065 8504260271 8604260162* 8904270263*	50-267 P 50-267 P 50-267 P 50-305 I
GUCWA,L T	8804250041	50-366 P	HARRIS, J.R	8804120160*	50-369 Q	HEMMING.W.C	8904263052*	59-317 P
GUCWA,L T	8804250054	50-424 R	HARRIS, M.S	8804050160	50-313 P	HENDRICKS.D.W	8604140141*	NUREG
GUCWA,L T	8804250095	50-424 O	HARRIS, R	8804070039	50-348 F	HENDRICKS.D.W	8904190166*	NUREG
GUCWA,L T	8804260281	50-424 P	HARRIS, R	8604070285	50-348 F	HENRY.R.K	6904210653*	FOIA
GUGWA,L T	8804260233	50-424 F	HARRIS, R	8804270061	50-348 F	HENRY.R.K	8904210031*	FOIA
GECWAL T GUCWAL T GUCWAL T GUCWAL T	8804270303 8804270057 8804270175 8804270236 8804270244	50 366 S 50 366 S 50 321 I 50 424 Q 50 J21 Q	HARRIS.A HABRISON,D F HARRISON,F, HARRISON J J HARRISON J J	8604270296 8604250341 8803303324 8804060165 8604060423	50-348 F 50-368 R 50-324 R 50-456 Q 50-249 Q	HENZLER,P W HEPPNER,R D HERBORN,D I HERDT,A R HERDT,A R	8304290121 8804280586 86033102721 6803280135 6803280323	FOIA 40-1341 WASTE MGT 50-324 O 50-250 O
GUGLIELMO,F	8804220121*	CONTRACT	L L MOSIBRAH	8804060438	50-305 Q	HERDT A R	9803050079	50 324 Q
GUGLIELMO,F J	8004130285	50-213 /	L LNOSIBRAH	8804060505	50-237 Q	HERDT A R	880350030*0*	50 324 Q
GUGLIELMO,F J	8804140014	50-245 /	L LNOSIBRAH	8804120056	50-305 Q	HERDT A R	8803300122	50 395 Q
GULDEMOND,W G	8804060118	50-315 Q	L LNOSIBRAH	8804120064	50-255 Q	HERDT A R	8803310278	50 269 Q
GULDEMOND,W G	8804200538	50-346 Q	L L MOSIBRAH	8804140039	50-282 Q	HERDT A R	8803310002	50 424 Q
GULDEMOND,WG	8804200541*	50-346 O	HARRISON, J	8834150005	50-373 Q	HERDI, A R	6804010012	50-295 O
GULLICK,FR	8804060145*	40-2259	HARRISON J J	8904150008*	50-373 Q	HERDI, A R	8604010014*	50-395 O
GUSTIN,HL	8803310039*	50-324 O	HARRISON, J J	8804150050	50-315 Q	HERDI, A R	6834010061	50-395 O
GWSTIN,HL	8803310044*	50-324 O	HARRISON, J J	8604260175	50-341 Q	HERDI, A R	8804010063	50-416 O
GWALTNEY,RC	8804010215	NUREG	HART, R C	8804060504	WASTE RES	HERDI, A R	8694010064*	50-416 O
HAAG,R.C HAEHLJ G HAGAN,T.F HAGAN,T.F HAGAN,T.F	8804210326* 8804200253 8804130148* 8804150228* 8804180308*	50-313 O 50-820 i CONTRACT CONTRACT	D R,TRAH D R,1 RAH T D,ИЭДТРАН R COOWRAH A R,ЭЗЗАН	8694260344 8894269348 8894260043 8894150030 8693290369*	WASTE RES WASTE RES 50-322 T 50-304 S 50-315 O	HERDT, A R HERDT A R HERDT A R HERDT, A R HERDT, A R	6804010225 8894010245 8804050377 6804060233 8804060317	50:250 O 50:413 O 50:321 O 50:425 O 50:324 O
HAGAN, T.F. HAGAN, T.F. HAGEDOBN, H.J. HAGEY, H	8804200504* 8804210169* 8804210184* 8804130313 8804050270	CONTRACT FOIA FOIA ACRS CONTRACT	HASSE, AA HASSEL J L HAUGHEY, MF HAUGHEY, MF HAUGHEY, MF	8804040141* 8604160282* 8803C80248 8804110273 8804190063	50-454 Q 50-445 A 50-410 P 50-410 Q 50-410 P	HERDT A R HERDT A R HERDT A R HERDT A R HERDT A R	8824070056 8804080275 8804080276* 8804120003 6804120018	50-389 O 50-425 O 50-425 O 50-335 O 50-424 O
HAGEY,H	8804050387	CONTRACT	HAUGHEY,M F	8804280735	50-410 P	HEROT, A R	8804120027	59:424 Q
HAGEY,H	8804060221	50-445 A	HAUGHEY,M F	8804280735	50-410 P	HEROT, A R	6804120039	59:416 Q
HAGEY,H	8804150065	CONTRACT	HAUGHY,M F	8804202441	50-220 P	HEROT, A R	8804120050	57:321 Q
HAGEY,H,	8804150069	CONTRACT	HAVERKAMP D	8804070248	50-271 S	HEROT, A R	8804120096	50:321 Q
HAGEY,H,	8804150078	50-320 P	HAVERKAMP,D H	8804120190*	50-271 O	HEROT, A R	6804120104	50:321 Q
HAGEY,H HAGEY,H HAGEY,H HAGEY,H	8804150086 8804150237 8804150310 8804150329 8804180147	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	HAVERKAMP, D.R. HAVERKAMP, D.R. HAVERKAMP, D.R. HAWKINS, E.F. HAWKINS, E.F.	8804130185 8994200099* 8604250154* 8804050416 8904060045	50-29 F 50-440 O 50-223 O WASTE MGT WASTE MGT	HERDT, A R HERDT, A R HERDT, A R HERDT, A R HERDT, A R	8804120106° 8304120154 8604120301 8804150172 8304260057	50.425 C 50.389 O 50.297 O 50.302 O 50.425 O
HAGEY,IL	8804220061	CONTRACT	HAWKINS,E F	8804060129	40-8502	HERDI, A R	8804260188	50.424 Q
HAGEY,H.	8804220069	CONTRACT	HAWKINS,E F	8904060143	40-8907	HERDT, A R	6804270106	50.324 Q
HAGEY,H.	8804220156	CONTRACT	HAWKINS,E F	8804060170	40-3453	HERDT, A R.	6804270154	50.400 O
HAGEY,H.	8804280309	CONTRACT	HAWKINS,E F	8834060188	40-8084	HERUT, A R	860429027/	50.324 Q
HAGEY,H.	8804280420	CONTRACT	HAWKINS,E F	8804060206	40-8905	HERNAN, R W.	8804780351	50.289 P
HAGEY,H HAGEY,H. HAHN,F F HALE,G J. HALE,M	8804280459 8804280495 8804280444 8804190007* 8804190123	CONTRACT CONTRACT NUREG 50-445 Q 50-400 R	HAWKINS,E F HAWKINS,E F HAWKINS,E F HAWKINS,E F HAWKINS,E F	8804060208 8804060295 8804060353 8804060379 8804060419	40-8102 40-6659 40-8502 40-8904 40-8905	HERHERAE.Y HERTIG.H.P HESS.R.J HESSEH.O.V	6604150291 8804140121* 6604220140 8804220145* 8804050264	WASTE MGT NUREG 50 344 R 50 344 R NUREG
HALLJ.M	8804210382*	50-282 O	HAWKINS,E F	8804070048	40-8905	HEWARD,R W	8804130084	59-146 S
HALLJ.R.	8804140524	50-331 P	HAWKINS,E F	8804070086	40-1162	HEYER,R.S	8804050393	49-1162
HALLJ.R.	8804150302	50-331 O	HAWKINS,E F	8804070100	40-4492	HEYER,R.S	8804050405	40-299
HALLIDAY.K B	8804140096*	NUREG	HAWKINS,E F	8804070111	40-8783	HEYER,R.S	8604060012	40-6622
HALLSTROM.G A	8804150201*	50-302 Q	HAWKINS,E F	8804070334	WASTE MGT	HEYER,R.S	8804060133	WASTE MGI
FIALPIN, P.G.	8804200070*	50-322 G	DT'SANAWH	8804130250	50-395 P	HEYER, AS	8804060166	40.6622
HALTIWANGER, J	8804190133	50-395 R	PT'SANAWH	8804200363	50-395 P	HEYER, AS	5804060201	WASTE MGT
HALVERSON, R.D.	6804070234*	50-259 P	PT'SANAWH	8804280426	50-395 P	HEYER, AS	6804074119	40.2259
HAMID, A.A.	8604280144*	50-255 Q	PT'SANAWH	8304060158	50-528 S	HIATT, S.L.	8603030244*	50.440 P
HAMILTON, P.	6804200145	50-293 R	PT'SANAWH	8804060478	50-529 S	HIATT, S.L.	8803310185	PRM
HAMILTON,P J	8803360146	50-293 S	D LEBNYAH	8804120437	50-528 S	HIATT, S.L.	8603310238	PR
HAMILTON,P J	8804070129	50-293 S	D LEBNYAH	8804130036	50-529 S	HICKEY, J.W.N.	8804260562	ORG
HAMILTON,W H	8804140269*	71-651	D LEBNYAH	8804140106	50-529 S	HICKIN, R.A.	6804050336	CONTRACT
HAMPSHIRE,D.	8804010284	50-323 S	D LEBNYAH	8804140143	50-528 S	HICKMAN, D.E.	8804010117	50:361 P
HAMRICK,J S.	8804660140	40-8681	D LEBNYAH	8804180445	50-528 S	HICKMAN, D.E.	8604190126	50:361 P
HANNESSCHLAGER HANNESSCHLAGER HANNESSCHLAGER HANSELJLL HANSEN,W.	8804050414 8804280210 8804280543 8804200146* 8804290075*	40-8907 40-8907 40-8907 50-445 G 50-298 P	D L.REMYAH D L.REMYAH D L.REMYAH D L.REMYAH D.L.REMYAH	8804190029 880419333 880420301 8804210311 8804210329	50.528 S 50.529 S 50.528 S 50.528 S 50.528 S 50.530 S	HICKMAN,D.E HICKMAN,D E HICKMAN,D E HICKMAN D E HILDERHAND,E P.	8804190230 8904210497 8804220152 8804260447 8804070045*	50:361 O 50:206 O 50:361 P 50:361 P 50:498 O
HANSON,A S	8804280579	70-3051	MAYNES.JG	8804220055	50-528 R	HILDEBRAND, PP	8804120134*	50-267 O
HARBOUR,J	8804180096	50-275 G	MAYNES.JG	8804220255	50-528 F	HILE, J.P.	8804180136*	NUREG
HARBUCK,C.C.	8804210326*	50-313 O	MAYNES.JG	BB04260007	50-528 S	HILL, H	6803280134	50-457 S
HARDGRÖVE,T W.	8804060131	40-2259	MAYNES.LS	8804200504	CONTRACT	HILL, K.J.	8604200367	50-265 S
HARDIN,C	8804210509*	NUREG	MAYNESWORTH.V.	8804150139	50-261 R	HILL, T.E.	8805030121*	PR
HARDIN,C	8804210512*	NUREG	HAZLE A J.	8804070046	PRM	HILL-WHILTON,R	8804200030	50 443 G
HARÐIN,CM	8804140276*	NUREG	HEAD,G F	8803310019	50-424 P	HILL-WHILTON,R	880420000	50 443 G
HARDIN,CM	8804150011*	NUREG	HEALEY,D.L	8604150273	WASTE MGT	HILL-WHILTON,R	8804220213*	50 443 R
HARE,S.M.	8804040216*	50-457 Q	HEIDT,J D	8804040072	50-321 S	HILL-YER,D.W	8803280053	50 461 S
HARJO,SS.	6803160284*	COMMISSION	HEIDT,J D	8804080051	50-366 S	HINDS,J.	8604010243	50 456 S
HARLOW,DS	8804290086	50-322 G	HEIDT, J.D.	8804270003	50-366 S	L, ZONIH	8804080017	50-454 S
HARLOW,DS	8804290086	50-322 G	HEIDT, J.D.	8804270357	50-366 S	H, ZONIH	8804040142*	50-295 Q
HARRELL,EW.	8803310163	50-338 S	HEIKE, P.B.	8804060062	FOIA	M, L, ZONIH	8804150076*	50-454 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
TUNDS,J.M.	8804200429*	50-450 Q	HORN,M,	8804180455	40-7455	IRWIN D.P.	8804260047	50-322 G
HINDS,J.M.	6804250305*	50-457 Q	HORNOR,J.W,	8804060448	STATE PRO G	IRWIN D.P.	8804260047	50-322 G
FUNKEBEIN,T E.	8804110006*	WASTE MQT	HORNOR,J.W,	8804120412	STATE PRO G	IRWIN D.P.	8804260102	50-322 G
HINSON,L.	8504140109	50-344 S	HOSEY,C.M,	8803280237*	70-1201	IRWIN D.P.	8804260102	50-322 G
HINSON,L.	8804140119	50-344 S	HOSEY,C.M.	8803280258*	70-824	IVERSON O.N	8804200189	50-323 S
HINSON L. HINSON L. HINTZ, D.C. HINTZ, D.C. HINTZ, D.C.	6804140169 8804200257 6804040110 8804040156 6804060151	50-344 S 50-344 S 60-305 Q 60-305 F 50-305 I	HOSEY,C.M. HOSEY,C.M. HOSEY,C.M. HOSEY,C.M. HOSLER,C.L.	8804010008* 8804150349* 8804160396* 8804260075* 8804060443	70-27 50-83 Q 50-413 Q 50-280 Q 50-5 V	JABBOUR, K JABBOUR, K N. JABLONSKI, F. J. JABLONSKI, F. J.	8804150038 8804150199 8804130309 8804060216 8804150009	50-413 P 50-413 P 50-369 P 50-440 Q 50-373 Q
HINTZ,D.C.	8504070026	60:305 J	HOTCHKISS,W.	8803310168	NUREG	JACKIW,I.N	8804140449*	50-409 O
HINTZ,D.C.	8804070170	50:305 P	HOUSE,J.E.	8604260071*	50:373 O	JACKIW,N.	8803290359	50-282 S
HINTZ,D.C.	8804070267	60:305 P	HOUSE,W.B.	6804070126	27:47	JACKLIN,N.W.	8804080047	50-374 S
HINTZ,D.C.	8804120080	50:305 P	HOWARD,D.R.	8804060372	50:313 J	JACKSON,E.F.	8804130038	50-262 O
HINTZ,D.C.	8804120470	50:305 P	HOWARD,O.R.	8804070151	50:313 F	JACKSON,G.	8803080022	71-448
HINTZ,D.C.	8804130307	50-305 S	HOWARD,D.R.	6804200085	50-313 1	JACKSON,G.	8804290055	70-734
HINTZ,D.C.	8804130307	50-305 Q	HOWARD,D.R.	8804200173	50-313 R	JACOBY,D L.	8804070048	40-8905
HINTZ,D.C.	8304130387	50-305 P	HOWARD,D.R.	8804210163	50-313 O	JAFFE,D,H	9803080019	50-336 P
HINTZ,D.C.	8804140019	50-305 Q	HOWARD,D.R.	8804250341	50-368 R	JAFFE,D,H.	8804050317	50-336 P
HINTZ,D.C.	8804160143	50-305 R	HOWARD,J.L.	8804276253*	CONTRACT	JAFFE,D.H.	9804110150	50-336 P
HATZ,D.C.	8804250145	50-305 O	HOWE,A.	8804060126	50-400 S	JAFFE,D.H	8804120012	50-336 P
HINTZ,D.C.	8804250276	50-305 O	HOWE,A.	8804250240	50-400 S	JAFFE,D.H.	8804120047*	50-336 P
HIRT,J.A.	8804190110	60-387 R	HOYLE,A.	8804208451	CONTRACT	JAFFE,D.H.	6804120153	50-336 P
HOBBS,S.H.	8804190089	50-416 R	HOYLE,A.	8804200462*	CONTRACT	JAFFE,D.H.	8804280189	50-336 F
HOCK,D.D	6804200070	50-267 I	HOYLE,J.C.	8804280273	ADVCM	JAMES,R.J.	8804060463*	50-28 P
HODGDON,A.P.	8804180025	50-271 G	HOYLE,J.C.	8804280555	ACAS	JANECEK, H.F.	8804050159	TOPREP
HODGDON,A.P.	8804180122	60-271 G	HOYT,G.W	8804250251*	50-206 I	JANECEK, R.F.	8804050331	TOPREP
HODGE,D.A.	8804260210*	50-445 A	HSII,Y.	8804140028	TOPAEP	JANECEK, R.F.	8804290166*	50-254 P
HODGE,D.A.	8804260215*	50-445 A	HSII,Y.	8804140514	TOPAEP	JANECEK, R.F.	8804290166*	50-254 P
HODGON,R.	8804150046*	50-295 Q	HSII,Y.	8804210481	TOPAEP	JANUSKA, A.	8804110090*	60-331 O
HOFFMAN,D.P. HOFFMAN,D.P. HOFFMAN,G.L. HOFFMAN,J. HOFFMAN,J.	8804250194°	50-255 P	HSU,C,	8804080267	NUREG	JAPE,F.	8804010016*	50-395 O
	8604260397	50-255 K	HUBÐARD,G.T.	8804130302°	50-327 O	JAPE,F.	8804060298*	50-425 O
	8804080276	40-8622	HUBBARD,G.T.	8804280057°	50-327 Q	JAPE,F.	8804120303*	50-321 O
	8804070065	50-260 J	HUBER,M.P.	8804080511°	60-237 O	JAPE,F.	8804120303*	50-297 O
	8804200211	50-146 J	HUCK,P.J.	8804190228	WASTE RES	JAPE,F.	8804260060*	60-425 O
HOGDON,K.M.	8804010112	60-170 R	HUDEC,W.S.	8804050178°	XPORTLIC	JAQUEZ,S.	8804140071	50-456 S
HOLAHAN,G.	8804010096	60-237 P	HUDEC,W.S.	8804280206	XPORTLIC	JENISON,K.	8804060255*	50-327 Q
HOLAHAN,G.M.	8804050123	60-312 P	HUDEC,W.S.	8804290083	XPORTLIC	JENISON,K.	8804080188*	50-327 Q
HOLDER,L.S.	8604270162	TOPREP	HUDIBURG,J.J.	8804220245	60-260 P	JENISON,K.	8804260042*	50-327 Q
HOLDERNESS,J.W.	8804110223	WASTE MGT	HUDIBURG,J.J.	8804270258	50-250 P	JENISON,K.M.	8804150132*	50-327 Q
HOLLAND,W.E.	8804010047*	60-280 Q	HUDSON.D.F.	6804260219*	50-445 A	JENKINS,R.E.	8803290379	50-410 S
HOLLAND,W.E.	8804260232*	50-260 Q	HUDSPETH.J.B.	8603300029	50-348 F	JENKINS,R.E.	8803290401	50-410 S
HOLLEN,E.	8804140026	60-296 Q	HUEY.F.A.	8804190092*	50-206 Q	JENKINS,R.E.	8804040199	50-410 S
HOLLEN,E.J.	8804060397*	50-298 Q	HUG.M.T.	8804070019	60-275 S	JENKINS,R.E.	8804070262	50-410 S
HOLLINGS,E.F.	8804130050*	COMMISSION	HUKILL.H.	8804120277	50-289 P	JENKINS,R.E.	8804070309	50-410 S
HOLLINGSED,M,W. HOLMES,JAY,P. HOLMES-RAY,P. HOLMES-RAY,P.	8604130079 8604150046* 8803300066* 8604150208* 6804250024*	50-285 S 50-295 O 50-321 O 50-302 O 50-321 O	HUKILL,H.D. HUKILL,H.D. HUKILL,H.D. HUKILL,H.D. HUKILL,H.D.	8804050059 9804060450 8804060469 8804120295* 8804120305	50-289 P 50-289 P 50-289 R 50-289 P 50-289 P	JENKINS,R.E. JENKINS,R.E. JENNINGS,A.D. JENSEN, H JENSEN,H.	8804190038 8804200294 8804180439* 8804190301* 8804190391*	50-410 S 50-410 S 50-482 I 50-354 R 50-354 R
HOLONICH, J.	8803310093	WASTE MGT	HUKILL, H.D.	8804120312°	50-289 P	JENSEN,H.	8804190393*	50:354 R
HOLONICH J. J.	8803310188	WASTE MGT	HUKILL, H.D.	8804120393	50-289 P	JENSEN,H.	8804190394*	50:354 R
HOLTZMAN, R.B	8804120400*	50-346 O	HUKILL, H.D.	8804190158	50-289 R	JENSEN,H.	8804190396*	50:354 R
HOOD, D.	8804160087	60-369 P	HULL, J.L.	8804220055	50-528 R	JO,J.H.	8804050126*	50:389 P
HOOD, D.	8804160104*	60-369 P	HUMHREY, P.G.	8803290321°	50-390 Q	JO,J.H.	8804050231*	50:389 P
HOOD, D.S.	8803100025	50-360 P	HUMPHREY, G.J.	8804010286	50-443 U	JOHANSEN,J.	8803310045	1&E
HOOD, D.S.	8803100068	50-289 P	HUMPHREYS, M.C.	8803300296'	50-397 P	JOHANSEN,J.	8804190035	1&E
HOOD, D.S.	8804010148*	50-424 P	HUNEGS, G.	8804060255'	50-327 Q	JOHNSON,A.H.	8803310292*	50:259 Q
HOOD, D.S	8804010237*	50-389 P	HUNEGS, G.	8804080188'	50-327 Q	JOHNSON,A.H.	8804200558*	50:259 Q
HOOD, D.S.	8804050403	50-260 P	HUNNICUTT, D.M.	8803300206'	50-498 Q	JOHNSON,A.R.	8803300187*	50:498 Q
HOOD 0.6 HOOD 0.9 HOOD 0.9 HOOD 0.9 HOOD 11.	8804080124 8804080127 6804220181 8804220261 8804010232	60-369 P 60-369 P 50-369 P 60-369 P	HUNNICUTT,D.M. HUNSADER,S.C. HUNSADER,S.C. HUNSADER,S.C. HUNSADER,S.C.	8804050227* 0804120092 8604120208 0804120351 0804200154	50-496 Q 60-457 F 60-456 S 50-457 P	JOHNSON,A.R. JOHNSON,B.D. JOHNSON,B.D. JOHNSON,B.D. JOHNSON,B.D.	8804140033* 8803290278 8804050311 8804050348 8804070034	50:482 Q 50:255 S 50:255 R 60:155 R 50:255 S
HOOD, T. O.	8804060290°	50-344 P	HUNT,M D.	8804080278*	50-425 Q	JOHNSON,B.D.	8804070041	50-255 S
HOOK, W. F.	8804180209°	FOIA	HUNT,M.D.	8804260190*	50-424 Q	JOHNSON,B.D.	8804220026	50-255 R
HOOKER, C. A.	8804130015°	50-344 O	HUNTING,K.	8804070054	PT21	JOHNSON,F.N.	8804150337*	NUREG
HOOPES, J.	8804200563	WASTE MGT	HURT,R.D.	8804130401	PROJ	JOHNSON,I.M.	8803300255	50-237 P
HOPKINS, J. A.	8804050096	71-652	HUTCHISON,L.B.	8803300328	50-397 R	JOHNSON,I.M.	8804010204	50-237 P
HOPKINS.J.A.	8804050102*	71-652	HUTCHISON,L B.	8804150401	50-397 R	M.I,NORMHOL	8804060476	50-373 P
HOPKINS.J.A.	8804060018*	50-305 V	IBRAHIM,A.	6804260378	WASTE MGT	M.I,NORMHOL	8804060524	50-237 P
HOPKINS.J.B.	8804080091	50-424 P	IGNATONIS,A.J.	8803310292*	50-259 Q	M.I,NORMHOL	8804270158	50-254 S
HOPKINS.J.B.	8604110216	50-426 A	IGNATONIS,A.J.	6804010033*	50-259 Q	M.I,NORMHOL	8804290297	50-264 P
HOPKINS.J.B.	8804130276	60-425 A	IGNATONIS,A.J.	6804200558*	50-259 Q	J.I,NORMHOL	8804060185*	50-333 Q
HOPKINS,J.B.	8804130201	60-424 P	IMAN,R,L.	8804080121	NUREG	L,NORMHOL	8804120362	50-410 O
HOPKINS,J.B.	8804140220	80-424 P	INGEBRETSON,C.	8804280052	50-322 G	J,NORMHOL	8804130109	50-220 O
HOPKINS,J.B.	8804220063	50-424 P	INGEBRETSON,C.	8804280052	50-322 G	JR,NORMHOL	8804040033*	50-286 O
HOPKINS,J.B.	8804220230	50-424 P	INGRAM,F.	8804040026*	ORG	JR,NORMHOL	8804250146*	50-410 O
HOPKINS,J.B.	8804280074	50-426 A	INGRAM,F.	8804260120*	50-498 P	JR,NORMHOL	8803280354	50-361 S
HOPKINS, J.B.	8804280472	50-424 P	INTERHANTE,C.G.	8804190169	WASTE RES	JOHNSON,P.H.	8804040235*	50-397 O
HOPKINS, J.B.	8834280516	60-424 P	INTERRANTE,C.G.	6804210037	WASTE RES	JOHNSON,P.H.	8804190092*	50-206 O
HOPKINS, P.G.	8804160388*	50-395 Q	IRELAND,R.E.	8803300187*	50-498 O	JOHNSON,P.H.	8804190120*	50-397 Q
HOPPER, G.T.	6604200558*	60-259 Q	IRELAND,R.E.	8804120134*	50-267 O	JOHNSON,A.D.	8804120429	WASTE MGT
HOPA, S.C.	8804080121	NUREG	IRELAND,R.E.	8804140033*	50-482 O	JOHNSON,S.	8803080496	40-8768
HORN,G.R.	8804120306	50-298 S	IRELAND,R.E.	8804250118°	50-267 Q	JOHNSON,T.	8804150375	71-546
HORN,G.R.	8804200258	50-298 S	IRWIN,D.P.	6804110027	50-322 G	JOHNSON,T.L.	8803310120*	40-6500
HORN,G.R.	8804250074	60-298 S	IRWIN,D.P.	8804110027	50-322 G	JOHNSON,W.	8804290076*	50-298 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
JOHNSON,W.O. JOHNSON,W.G. JOHNSON,W.G. JOHNSON,W.J JOHNSON,W.J.	8804210326* 8604200114 8804200114 8803290356 8804010131	50:313 Q 50:322 T 50:322 T 50:601 A 50:601 A	KANE G E KANE G E KANE G E KANE G E KANE G E	8804130080 8804160004 8804200185 8804200432 8804200438	50-338 S 50-338 S 50-338 S 50-338 S 50-338 S	KENYON,T.J. KENYON,T.J. KENYON,T.J. KENYON,T.J.	8804070298 8804150090 8804190116 8804200460 8804220016	WASTE MGT WASTE MGT 50:601 A 50:601 A 50:601 A
JOHNSON,W.J.	8804070238	\$0:601 A	KANE,G.E.	8804220214	50-338 S	KENYON,T.J.	8804280334	50 601 A
JOHNSON,W.J.	8804080243	PT21	KANE,G.E.	8804220237	50-338 S	KENZIE,L.G.	8804070224*	50-259 P
JOHNSON,W.J.	8804220186	50:601 A	KANE,G.E.	6804250030	50-338 S	KERCH,H.W.	8804120110*	60-425 O
JOHNSTON,J.R.	8804130024	50:155 B	KANE,G.E.	8804250035	50-338 S	KERR,G.W.	6804280423*	PR
JOHNSTON,K.E.	8804130022*	50:275 Q	KANE,S.E.	8804190019	50-245 S	KERR,G.W.	8804280517*	PR
V.W.NOTZNHOL	8804040019	50-410 Q	KANE,W.F.	8804010269	50-423 Q	KERR,W.	8804140205	ACRS
V.W.NOTZNHOL	8804080111	50-311 Q	KANE,W.F.	8804120200	50-277 Q	KERR,W.	8804140215	50-247 O
V.W.NOTZNHOL	8804120184	50-213 Q	KANE,W.F.	8804200036	50-277 Q	KERR,W.	8904210316	ACRS
V.W.NOTZNHOL	8804120210	50-247 Q	KANE,W.F.	6804250153	50-223 Q	KERR,W.	8804210338	ACRS
V.W.NOTZNHOL	8804130132	50-271 Q	KANT,E.W.	8804200160	50-461 S	KERR,W.	8304210349	ACRS
JOHNSTON,W.V.	8804200049	50-293 Q	KAPLAN,A.	8804060333	50-440 Q	KERA W.	6804210397	ACRS
JOHNSTON,W.V.	8804200059*	50-293 Q	KAPLAN,A,	8804060347	50-440 Q	KERA W.	8804220204	ACRS
JOHNSTON,W.V.	8804200074	50-334 Q	KAPLAN,A,	8804060480	50-440 P	KERA W.	8804270267*	50-160 O
JONAS,S.A.	8804180092	50-443 G	KAPLAN,A.	8804070208	50-440 Q	KERA W.	8E04280175	ACRS
JONAS,S.A.	8804260052	50-443 G	KAPLAN,A.	8804070209	50-440 I	KERA W.	8804280432	ACRS
JONES,D.W. JONES,K. JONES,R.J JONES,R.J JONES,R.J	8804280310 8003130173* 8101210084* 8604280599*	70-143 40-8905 PR PR PR	KAPLAN,A. KAPLAN,A. KAPLAN,A. KAPLAN,A. KAPLAN,A.	8804070235 8804080115 8804120420 8804140123 8804190061	60-440 O 60-440 F 50-440 P 50-440 S 50-440 R	KERR,W. KEYS,P.R. KILGORE,B.E. KILGORE,B.E. KILGORE,B.E.	8804280458 88042034D1* 8804150042 8804200278 8804270157	ACRS CONTRACT 50-328 S 50-327 S 50-327 S
JONES,S.B.	8804070001	50-259 S	KAPLAN,A	8804270304	50-440 P	KING,D.B.	8804280588	NUREG
JORDAN,B.	8804130137	FOIA	KAPLAN,H	9804050074*	50-220 Q	KING,L.P.	8804080259*	50-338 D
JORDAN,E L.	8803100157	50-312 P	KARAM,H.A	8803280126	50-160 R	KINGSLEY,O.D.	8904040056	50-416 O
JORDAN,E.L.	8804010186	REVIEW GR P	KARR,J.E.	9804070217*	60-259 P	KINGSLEY,O.D.	8804070076	60-410 J
JORDAN,E.L	8804130224*	FOIA	KASHIMA,K.	8804080282	NUREG	KINGSLEY,O.D.	8904070135	50-418 P
JORDAN,E L	6804130299* 8804130369 6804140381 8804150035 8804190057	50-369 Q	KASN:CKI,D.A.	8804060278*	70-143	KINGSLEY,O.D.	6804070187	50-416 S
JORDAN,E L		HEVIEW GA P	KASSNEA,T.F.	8804080134	NUREG	KINGSLEY,O.D.	6804070275	50-416 P
JORDAN,E L		REVIEW GA P	KATALINAS,J.A.	8804160359*	NUREG	KINGSLEY,O.D.	6804090046	50-416 P
JORDAN,E L		HEVIEW GA P	KATALINAS,J.A.	8804150369*	NUREG	KINGSLEY,O.D.	6804080063	50-416 S
JORDAN,E L		REVIEW GR P	KATZE,D.	8804010165	TOPREP	KINGSLEY,O.D.	6804080118	50-416 O
JORDAN,E.L. JORDAN,W.H. JOSEPH,I. JOSEPH,V.R.	8804210462 8804110026 8804140177* 8804140214* 8804010001	REVIEW GR P 50-445 G PROJ PROJ 50-423 S	KAUFFMAN, J.T. KAUFFMAN, J.V. KAUFMAN, N.C. KAY, C.E. KEIMIG, R.	8804270047 8804250358 6804120373* 8804210049 6804130187	50-387 R ORG 70-371 WASTE MGT 50-352 S	KINGSLEY,O.D. KINGSLEY,O.D. KINGSLEY,O.D. KINGSLEY,O.D. KINGSLEY,O.D.	6804080277 8804130175 8804150100 8804190082 8804190089	50-416 \$ 50-418 \$ 50-416 Q 50-418 P 50-416 R
JOSIGER,W.A. JOSIGER,W.A. JOYCEJ W. JOYCE,J.W.	6803310297 8804110149 8804220081 8804070224* 8804070234*	50-286 F 50-286 P 50-286 R 50-259 P 50-259 P	KEIMIĞ,A.R. XEIMIĞ,A.R. KEIMIĞ,A.R. XEIMIĞ,A.R. KEIMIĞ,A.R.	6804050157° 8804050171° 8804120198° 8804120077° 8804130129°	60-333 Q 59-29 Q 70-1100 50-293 Q 60-293 Q	KINGSLEY,O.O. KINGSLEY,O.D. KINGSLEY,O.D. KINGSLEY,O.D. KINGSLEY,O.D.	8804200007 8804200116 8804210013 8804220200 6804250285	50-416 \$ 50-416 J 50-416 P 50-416 P 50-416 S
JOYNER, J.H.	8804270192*	PR	KEIMIG,R.R.	8804130169* 8804250198* 8804250329* 8803310232 8804010147	50-213 Q	KINNEMAN,J D.	8804070318	40-8938
JULIAN, C.A.	8803160322	50:269 V	KEIMIG,R.R.		70-371	KINSEY,W.	8804130034	50-498 F
JULIAN, C.A.	8803250178	50:250 V	KEIMIG,R.R.		50-309 Q	KINSMAN,S,	8804130045*	NUREG
JULIAN, C.A.	8803280058	50:297 V	KEISER,H.W.		50-389 P	KINTER,L.L	8804110158	50-416 P
JULIAN, C.A.	8803290326	50:425 Q	KEISER,H.W.		50-388 P	KINTNER,E.E.	8804110323	PROJ
JULIAN,C.A.	8804010120	50-83 V	KEISER,H.W.	8804040020	50-367 Q	KINTNER,E.E.	8804150145	PROJ
JULIAN,C.A.	8804050360	50-424 Q	KEISER,H.W.	8804040118	50-387 I	XINTNER,L.L.	8803100153	50-418 P
JULIAN,C.A.	8804050368°	50-424 Q	KEISER,H.W.	8804080175	60-387 H	KINTNER,L.L.	8804210324	50-416 Q
JULIAN,C.A.	8804050373	50-321 V	KEISER,H.W.	8804070149	50-387 H	XINTNER,L.L	8804220053	50-416 Q
JULIAN,C.A.	8804060084	50-348 Q	KEISER,H.W.	8804140003	60-387 P	KIPPEN,T.A	8804280544	40-1162
JULIAN,C.A.	8804060263	50:424 Q	KEISER,H.W.	8804140007* 8804150431* 8804150438* 8804180215 8804190110	60-387 P	KIABY,M.J.	8804120360	50-29 V
JULIAN,C.A.	8804080283	50:425 Q	XEISER,H.W.		60-388 P	KIASCH,D.F.	8804040245	50-397 O
JULIAN,C.A.	8804060344	50:280 Q	KEISER,H.W.		50-388 P	KIASCH,D.F.	8804050320	50-528 Q
JULIAN,C.A.	8804110168	50:302 P	XEISER,H.W.		71-9208	KIASCH,D.F.	8804090231	50-206 P
JULIAN,C.A.	8804280094	50:281 Q	KEISER,H.W.		60-387 R	KIASCH,D.F.	8804130019	50-275 O
JULIAN,C.A. JULIAN,E.L. JUSTUS,P.S. JUSTUS,P.S. JUSTUS,P.S. JUSTUS,P.S.	8804260111* 8804050048 8804070164 8804070183 8804070192	50-261 Q 50-341 G WASTE MGT WASTE MGT WASTE MGT	KEISER,H.W. KEISER,H.W. KELLER,C.L. KELLER,C.L. KELLER,C.L.	8804210051 8804290289 8804140453 8804140463 6804140469	50-387 Q 50-397 F FOIA FOIA FOIA	KIRSCH,D.F. KIRSCH,D.F. KIRSCH,D.F. KIRSCH,D.F. KLAPPROTH,J.F.	8804130020* 8804180182 8804180401 8804250051 8804210081	50-275 O 50-528 O 50-208 P 50-344 O TOPREP
JUSTUS,P.S.	8804070195	WASTE MGT	KELLER,C.L.	8804140476	FOIA	KLEESPIE,J M.	8804280647*	CONTRACT
JUSTUS,P.S.	8804070274	WASTE MGT	KELLER,C.L.	8804140483	FOIA	KLEIN,D.E.	8804010022	50-192 A
JUSTUS,P.S.	8804080264	WASTE MGT	KELLER,C.L.	8804140492	FOIA	KLEIN,S.H.	8804150415*	WASTE MGT
JUSTUS,P.S.	8804120074	WASTE MGT	KELLER,C.L.	8804140500	FOIA	KLEIN,S.H.	8804150426*	WASTE MGT
JUTH,C.L.	8804150082*	CONTRACT	KELLER,C.L.	8804140512	FOIA	KLEINSORGE,W.P.	8803290325*	50-260 Q
KADAMBI,N.P.	8804010077	50-499 Q	KELLER,C.L.	8804140522	FOIA	KLINE,C.	8804180113	50 440 G
KADAMBI,N.P.	8804130311	50-498 Q	KELLER,C.L.	8804140529	FOIA	KLINE,J.R.	8804180010	50 322 G
KAHLE J.	8804190094	50-338 S	KELLER,C.L.	8804140532	FOIA	KLUGE,D.	880308050B*	50 219 P
KAHLE J. B.	8804080240*	50-250 Q	KELLER,C.L.	8804140535	FOIA	KMAPP,M.R.	8804280594	PROJ
KAHLE J.B.	8804120131*	50-302 Q	KELLEY,D.L.	8804250067	50-362 Q	KNAPP,W.J.	8804280195	71-9222
KAHLE, J.B.	8804150299*	50-348 Q	KELLY,J.A.	8804080219* 8804050210 8804130358 8804140525 8804220081	50-482 Q	KNICELEY, J.A.	8804010029*	50-306 O
KAHLE, J.B.	8804150357*	50-418 Q	KELLY,J.L.		50-259 R	KNICELEY, J.A.	8804050078*	50-341 O
KAKAI, S.	8803080511*	50-219 P	KELLY,J.L.		50-259 R	KNIGHT, B.E.	8804060365	70-143
KALMAN, G.	8803080464	50-312 P	KELLY,J.L.		50-259 R	KNIGHTON, G.W.	8804050418*	50-397 P
KALMAN, G.	8804080184	50-312 P	KELLY,L.		50-266 R	KNIGHTON, G.W.	8804080197*	50-344 P
KALMAN,G	8804120044	50:312 P	KELLY, R.B.	8804200147	50-322 T	KNIGHTON,G.W.	8804120136*	50-397 P
KALMAN,G	8804120149	50:312 P	KELLY, R.B.	8804200147	50-322 T	KNIGHTON,G.W.	8804120197*	50-397 P
KALSI,M.S.	8804280619*	CONTRACT	KELMERS, A.D.	8804200041	WASTE RES	KNIGHTON,G.W.	8804120276*	50-397 P
KAM,F.B.	8804280633	NUREG	KEMPER, J.S.	8804150055	60-353 A	KNIGHTON,G.W.	8804130234*	50-397 P
KAMMERER,C.	8803300431	STATE PRO G	KENNEDY, E.E.	8804060348	40-8903	KNIGHTON,G.W.	6804130321*	50-397 P
KAMMERER,C.	8804130083	WASTE MGT	KENNEDY,E.E.	8804280218	40-8903	KNIGHTON,G.W.	8804190142°	50-344 P
KAMMERER,C.	8804200134	STATE PRO G	KENNEDY,E.M.	8804250365*	50-293 U	KNIGHTON,G W.	8804210347°	50-397 P
KAMMERER,C.	8804280639*	50-289 P	KENNEDY,J.	8804280128*	50-498 P	KNIGHTON,G.W.	8804210425°	50-397 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KNIGHTON,G.W KNIGHTON,G.W. KNIGHTON,G.W. KNIGHTON,G.W KNIGHTON,G.W.	8804280357 8804280374 8804280377 8604280442 8604280573	50-397 P 50-312 P 50-361 P 50-312 P	LANPHER L C LANPHER L C LANPHER L C	8804180042 8804180042 88042600B1 8804260118 8804260118	50-322 G 50-322 G 50-322 G 50-322 T	LEMPGES,TE LEMPGES,T.E LENPARTZ,J.A LENTINE,F.G LEONARD,J.D	8804070282 8804070309 8804060018* 8804227005 8803300380	50-410 S 50-410 S 50-305 V 50-457 P 50-322 R
KNOP.B.C. KNOP.B.C. KNOP.B.C. KNOP.B.C. KNOP.B.C.	6804110160 6804110173 8604110272 8604200394 6804200467	50-341 C 50-440 P 50-461 P 50-341 P 50-305 C	LANPHER L.C. LANPHER L.C. LANPHER L.C.	8804260118 8804260118 8804260136 8804260136 8804260136	50-322 T 50-322 T 50-322 G 50-322 G 50-322 G	LEONARD, J.D LEONARD, J.D LEONARD, J.D. LEONARD, J.D. LEONARD, J.D.	8803300434 8803300439 8803310055 8804040136 8804190368	50-322 P 50-322 J 50-322 P 50-322 P 50-322 O
KNOP,B.C. KNOP,B.C. KNOP,B.C. KNOP,B.C KNOX,E	8804200408* 8804200511 8804210262 8804270211 8804280315	50-305 C 50-266 C 50-341 C 50-341 F CONTRACT		8804290161 8804290161 8804280138 8804280180 8804010219	50-322 G 50-322 G ORG 40-7604 50-263 Q	LEONARD, J.O. LEONARD, J.D. LEONARD, R. LEONARD, R. LEROY, S.E.	8804210209 8604280081 8804010036 8804270194 8804010151	50-322 Q 50-322 F 50-369 F 50-369 F 50-370 S
KNOX,E. KOBER,R.W. KOCN G.H.M. KOENIG,B.A. KONWINSKI,O.R.	0804280590 0804120173 8004200113* 0804080218 8804060129	CONTRACT 50-244 F 50-322 T NUREG 40-8502		8804060498 8804110174 8804150374 8804180244 8804180248	50-283 O 50-283 O 50-282 O 50-263 F 50-263 F	LEROY,S.E. LEROY,S.E. LEROY,S.E LESSER,M.S. LESSER,M.S.	8804010154 8804200328 8804270345 8803300075* 8804080181*	50-370 S 50-369 S 50-370 S 50-413 Q 50-413 Q
KONWINSKI,G FI, KOSHY,T. KOWALSKI,S J KOWALSKI,S J	004060208 8604660353 8604120223* 8604120225 8804150230	40-8102 40-8502 50-247 C 50-353 S 50-277 C	LARSON, C.E.	8804180252 8804180258 8804180261 8804200554 8804210327	50-263 F 50-282 F 50-282 F 50-282 Q 50-282 Q	LETSCHE,K J. LETSCHE,K J. LEUGERS,M J. LEUGERS,M J. LEUGERS,M J.	8804200048 8804200048 8804050046 8804050046 8804080066	50-322 G 50-322 G 50-322 G 50-322 G 50-322 G
KOZUP,C.S KOZUP,C.S KOZUP,C.S. KRAEGER,B.A KRAJICEK,J.E.	0803293278 0904070034 0804070041 8804220162* 8803300201*	50-265 S 50-255 S 50-256 S CONTRACT 50-307 F	LASH,T.R. LATHAM,S.B. LATHAM,S.B	8804140204* 8803310250 8804060102 8804060102 8804180057	NUREG PRM 50-322 G 50-322 G 50-322 G	LEUGERS,M J LEUGERS,M J. LEUGERS,M J. LEVICK,M L. LEVINE,J M	8804060066 8804060238 8804080238 8804290267* 8804060211	50-322 G 50-322 G 50-322 G FOIA 50-368 S
KRAJICEK J E. KRASOPOULOS A KRASOPOULOS A KRAUSE C.W KRAUSKOPF.K.D.	6603300284* 8804080113* 8804130142* 8804130300	60-397 F 60-311 C 60-271 C 60-266 F ACRS	LATHAM,S.B. LATHAM,S.B.	6804160057 8604200048 8804200048 8804260089 6804260103	50-322 G 50-322 G 50-322 G 50-322 G 50-322 G	LEVNIC, J.M. J.M.C. JANIVEJ J.M.C. JANIVEJ J. M. C. JANIV	8804050228 8804120418 8804130399 8804200014 8804200027	50-313 S 50-313 O 50-368 S 50-368 S 50-313 S
KRAUSKOPF.K B KRAUSSJ E KREILJ L KIVEGER.K. KRIMM, I W.	6804130341 9804140206* 8804260028* 6803300333 9804270113	ACRS PROJ 50-327 C 50-247 F 50-440 I	I LATHAM,S.B.	8804260103 8804290021 8804290021 8804290030 8804290030	50-322 G 50-322 G 50-322 G 50-322 G 50-322 G	LEVINE, J.M. LEVINE, J.M. LEVINE, J.M. LEWALD, G.H. LEWALD, G.H.	8804200343 8804210168 8804210461 8804050045 8804050045	50-313 Q 50-313 Q 50-366 S 50-443 G 50-443 G
KAIMM, R. W. KROHN, J. L. KROPP, W. J. KROPP, W. J.	8804270131 6804066023 8804280323 8804040216* 8804680216*	50-440 F 50-128 F 50-254 S 50-457 C	LATHAM, S.B. LATHAM, S.B. LATHAM, S.B. LATHAM, S.B.	8804290068 8604290068 8804290161 8804290161 8803090166	50-322 G 50-322 G 50-322 G 50-322 G WASTE MGT	I.EWALD.G H. LEWALD.G.H. LEWALD.G.H. LEWALD.G.H. I.EWALD.T.G.	8804260088 8804200100 8804200100 8804290013 8804290047	50-443 G 50-443 G 50-443 G 50-443 G
KRYSIAK M.W. KUCHARSKI,S () KUEMIN J.L KUEMIN J.L KUEMIN J.L	8603230246 8804050240* 8804110010 8804130039* 6804220049	50-304 5 50-336 C 50-255 F 50-255 1 60-255 I	LATZJE LATZJE LATZJE	8804010199 8804060346 8804070139 8604080090 8804080261	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT	(.EWALD,T.G LEWIS,J.P. LEWIS,M. LI,H.C LI,H.C.	8804290047 8804200310* 8804150163* 8804050272 8804280531	50-443 G CONTRACT 50-327 O ORG TOPREP
KUMAN,A KUNCL,L.G. KUNCL,L.G KUSKO,A KUZO,G.B	88033CD435* 8804120387 8804120425 8804120105* 8804010008*	WASTE MGT 50-298 I 50-298 I 50-327 I 70-27	P LATZ,JE.	8804220249 8804220249 8804260401 8804050255* 8804200583*	WASTE MGT WASTE MGT WASTE MGT CONTRACT CONTRACT	LICHTENBERGER LICHTMAN.G.S. LICITRA,E.A. LICITRA,E.A. LICITRA,E.A.	8804190342* 8804050436* 8804050097 8804150130 8804200500*	70-1100 50-275 P 50-528 P 50-528 P 50-528 P
KUZO, O.B. LABRUNA, S LABRUNA, S LABRUNA, S LABRUNA, S.	8804160349* 8804060251 8804140155 8804190025 8804190389	50 354 S	D LAURINO,R K. S LAWRENCE,M J S LAWTON,M D. S LAWTON,M D LAZARUS,W.	8804050314* 6804260122 6804060039 6804140407 6804120237*	CONTRACT WASTE MGT 40:8084 40:8084 50:443	LICITRA,E.A. LICITRA,E.A. LIEBERMAN,E.B. LIEBERMAN,E.B. LIEBERMAN,J.	8604210437 8804280561 8804200082 8804200082 8803310033	50-528 P 50-528 P 50-322 T 50-321 Q
LABRUNA,S LABRUNA,S LABRUNA,S LAINAS,G C LAMBE,W.M.	8804200088 8804200269 8804260263 8804290070 8804130301		S LAZARUS,W J. S LAZARUS,W J. S LAZARUS,W J. P LAZO,R.M. A LE RÔY,S.E.	8604040042° 8804130215° 6804250162° 8804260143 8604180243	50-272 Q 50-317 Q 50-277 Q 50-250 G 50-369 S	LIEBERMAN,J. LIEBERMAN,J. LIEBERMAN,J. LIEBERMAN,J. LIEBERMAN,J.	8803310045 8804060334 8804060337 8804060472 8804060486	18E 18E 18E 50-285 C 50-237 C
LAMBERT,P.A. LAMBERT,P.A. LAMBERT,W.H. LANCASTER,W.K. LANCASTER,W.K.	0804060506* 0804220241* 0804200242 0804130077* 0804130120*	50-220 GA999 50-293 (P LE ROY,S.E. P LECHMAIER,J. LEE.B E. D LEE.H.W.	6804250037 8804130047 8604060390 8804210177 6804120086	50-369 S 50-265 S 50-327 R MISC 70-27	LIEBERMAN,J. LIEBERMAN,J. LIEBERMAN,J. LIEBERMAN,J. LIEBERMAN,J.	8804080008 8804080044 8804110081 8804130286 8804180309	50-62 C 50-313 C I&E I&E MISC
LANCASTER,W K. LANDIS,M R LANDRETH,K. LANDSMAN,R LANGE,D.	8804250329* 8604150181 6804180156 6803300113* 8404050383	40-7604 FOIA	D LEE.T D. LEE.W.S. LEECH.P.H. D LEITMAN.L.W. S LEMGRUBER,E	8804190006* 8804040050* 8804140422 6804260389 8804070054	70-143 50-269 Y PROJ 50-219 S PT21	LIEBERMAN,J. LIEBERMAN,J. LIEBERMAN,J. LIEBERMAN,J. LIEBERMAN,J.	8804180312 8804180457 8804180459 8804190010 8804190035	ORG ORG ORG 50-528 C I&E
LANGLEY,J.R. LANGLEY,J.R. LANGLEY,J.R. LANHPER,L.C. LANKSBUTY,R.D.	8804150168 8804160162 8804190395 8804080102 8804040216°	TOPREP TOPREP TOPREP 50:322 0 50:457 0	LEMONS.J.R. LEMONS.J.R. LEMONS.J.R. 3 LEMONS.J.R. D LEMONS.J.R.	8804080168 8804130325 8804180336 8604200389 8804200392	50-317 S 50-317 Q 50-317 R 50-318 S 50-318 S	LIEBERMAN,J LIEBERMAN,J LIEBERMAN,J LIFLLYMAN,W.J LINDBERG,B.J.	8804190248 8804200295 8604250243 8804190379* 8804210309*	50-423 C 50-285 C 50-285 C 50-326 C CONTRACT
CANNING,W. LANNING,W. LANNING,W. LANPHER,L.C. LANPHER,L.C.	6804050267 8804180374 8804210394 8804050016 6804050016	50-374 50-456 50-267 50-322 50-322	S LEMONS, J.R. S LEMPGES, T.E. S LEMPGES, T.E. LEMPGES, T.E. LEMPGES, T.E. CEMPGES, T.E.	8804220184 8803290379 8803290401 8803300346 8803310040	50-316 S 50-410 S 50-410 S 50-220 R 50-220 S	LINDELL,M.K. LINDELL,M.K. LINDEMANN,F.C. LINDEMANN,F.C. LINDEMANN,F.C.	8804200147 8804200147 8804180200* 8804180223* 8804180251*	50-322 1 50-322 1 FOIA FOIA FOIA
LANPHER.L.C. LANPHER.L.C LANPHER.L.C	8804050016 8804050016 8804060102	60-322 50-322 50-322	G LEMPGES,T.E. G LEMPGES,T.E. G LEMPGES,T.E.	8804010002 8804040199 8804060189	60-220 S 50-410 S 60-220 S	LINDEMANN,F.C. LINDEMANN,F.C. LINDNER,J.	8804180278° 8804180293° 8804040154°	FOIA FOIA TOPREP

HE THIS STATE NOTHING HIDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MCBURNETT.M.A	8804130160	50-498 H	MCLAUGHLIN,J	8804150219	71-3001	MEYER, RE	8804130335	WASTE RES
MCBURNETT.M.A.	6804150356	50-498 J	MCLAUGHLIN,J.E.	6804190302	50-142 W	MICHAELS, TS.	8804050421	50-150 P
MCBURNETT.M.A.	8804190059	50-498 R	MCMULEN,M.A.	8804080109	60-333 F	MICHAELS, TS.	8804180185	60-193 F
MCBURNETT.M.A.	8804260172	50-498 P	MCMURRAY,C.M.	8804290021	50-322 G	MICHAELS, TS.	8804220100	50-128 P
MCBURNETT.M.A.	8804270174	60-498 P	MCMURRAY,C.M.	8804290021	50-322 G	MICHAELS, TS.	8804280405	50-113 P
MCBURNETT, M.A.	8804270243	60-498 J	MCMURRAY,C.M.	8804290068	50-322 G	MICHAELSON	8803300322	50-316 A
MCCABE, E.	8804140370	60-336 S	MCMURRAY,C.M.	8804290068	50-322 G	MICHAELSON	8803300326	50-315 R
MCCABE, E.	8804200386	50-423 S	MCNAMARA,A.E.	8804220120	50-244 R	MICHALK,P.L.	8804060211	50-368 S
MCCABE, E.C.	8804010272*	60-423 Q	MCNEIL,M.	8804060373	WASTE MGT	MICHALK,P.L.	8804130399	50-368 S
MCCABE, E.C.	6804120293	50-423 Q	MCNEIL,S.A	8804210175	50-317 P	MICHALK,P.L.	8804210461	50-368 S
MCCABE,E.C.	8804200033*	50-245 Q	MCNEIL,S.A.	8804210182*	50-317 P	MICHAUD,P.W.	8804040236*	50-267 Q
MCCABE,E.C.	6804200164*	50-336 Q	MCNEIL,S.A.	8804210362	50-317 P	MIDDLETON,L.L.	8804220040	50-277 R
MCCALLUM,N.	8604070217*	50-269 P	MCNEIL,S.A.	8804210386*	50-317 P	MIHALCIK,J.A.	8803250284	50-317 P
MCCANTY,B.E.	8804200563	WASTE MGT	MCNEIL,S.A.	8804220263	50-317 P	MILETI,D.S.	8804200147	50-322 T
MCCAUGHEY,D.A.	6804110314*	70-1069	MCNEIL,S.A.	8804280034	50-317 P	MILETI,D.S.	8804200147	60-322 T
MCCLUNG,C E. MCCLUNG,R.W. MCCOLLOM,K A. MCCONAGHY,W.J. MCCOY,F.	8804260150	60-361 G	MCNEIL, S.A.	0604290090	50 317 P	MILLER,D.B.	8803280128	50-213 S
	8804060170	NUREG	MCNEIL, S.A.	8804290113	50 317 Q	MILLER,D.B.	8803290219	50-213 R
	8804110028	50-445 G	MCNEILL, C.A.	8804010144	50 277 Q	MILLER,D.B.	8803310064	50-213 S
	8804010203	PROJ	MCNEILL, C.A.	0604060210*	50 352 P	MILLER,D.B.	8804130058	50-213 S
	8803290355*	50-327 Q	MCNEILL, C.A.	8904070271	50 277 H	MILLER,D.B.	8804190130	50-213 R
MCCOY,F.	8804080188*	50-327 Q	MCNEILL,CA	8804150225	50-277 V	MILLER D.B.	8804220206	50-213 S
MCCOY,F.R.	8804060249	50-327 Q	MCNEILL,CA.	8804250020	50-277 P	MILLER D.B.	8804220209	50-213 S
MCCOY,F.R.	8804060252*	50-327 Q	MCNEILL,W.M.	8803300127*	50-482 Q	MILLER D.B.	8804270265	50-213 S
MCCOY,F.R.	6804080165	50-327 Q	MCPEEK,G.	8804130141*	50-155 P	MILLER D.E.	8804120400*	50-346 Q
MCCOY,F.R.	8804160132*	50-327 Q	MCPHERSON,D.	8804140177*	PROJ	MILLER G.	8804190289	50-382 R
MCCOY, F. FI	8804260040	50-327 Q	MCQUILLAN,P.G.	8803250320	50-445 S	MILLER,H.J.	8803300105	50-458 Q
MCCOY, S. B.	8804060021	WASTE MGT	MEADE,K.E.	8804050004	50-327 S	MILLER,H.J.	8803300109*	50-458 Q
MCCRACKEN, C. E.	6804150261	REVIEW GR P	MEADE,K.E.	8804050010	50-328 S	MILLER,H.J.	8803300164*	50-458 Q
MCCRACKEN, K. W.	8804140083	50-348 F	MEADE,K.E.	8804150029	50-328 S	MILLER,H.J.	8804060191	50-316 Q
MCCRACKEN, K. W.	8804200043	50-348 F	MEADE,K.E.	8804150033	50-328 S	MILLER,H.J.	8804060196*	50-315 Q
MCCRACKEN,K.W. MCCRORY,8 L. MCDONALD.D. MCDONALD.D. MCDONALD.D. MCDONALD.D.	8804250126 8803290324' 8803290403 8804190227 8804210519	50-348 F 60-286 V 60-293 O 50-293 O 60-293 O	MEARSE,S.D. MEARSE,S.D. MEDA,M.J. MEDFORD,M.O. MEDFORD,M.O.	6804010193 6804190346 6804280088 6803300098 8803310226	CONTRACT CONTRACT 71-853 50-206 O 50-206 P	MILLER,HJ. MILLER,HJ. MILLER,HJ. MILLER,HJ.	8804060207 8804060212* 8804070237 8804150018 8804150018*	50-440 Q 50-440 Q 60-331 P 50-295 Q 50-295 Q
MCDONALD,D,	8804220045	60-283 F	MEDFORD,M.O. MEDFORD,M.O. MEDFORD,M.O. MEDFORD,M.O. MEDFORD,M.O. MEDFORD,M.O.	8803310239	60-206 P	MILLER,J.	8803290205	I&E
MCDONALD,D.G.	8804050139	60-283 P		8804010217	60-206 P	MILLER,L.	8803290351	50:312 S
MCDONALD,D.G	8804110329	50-283 P		8804010221	60-206 S	MILLER,L.	8804070338	50:312 S
MCDONALD,D.G.	8804120416	60-283 P		8804070310	50-206 P	MILLER,L.F.	8804120375*	50:312 Q
MCDONALD,D.G.	8804190139	50-283 F		8804110104	50-206 P	MILLER,L.F.	8804280633	NUREG
MCDONALD,D G	6804250170	60-293 P	MEDFORD,M.O. MEDFORD,M.O. MEDFORD,M.O. MEDFORD,M.O. MEDFORD,M.O. MEDFORD,M.O.	8804110202	50-361 P	MILLER,M.	8804060080	I&E
MCDONALD,R P.	8803280145	50-364 S		9804120341	50-206 P	MILLER,M.A.	8804050161	REVIEW GR P
MCDONALD,R.P.	8804040093	50-348 Q		9804150019	50-206 P	MILLER,M.A.	8804180429	REVIEW GR P
MCDONALD,R.P.	8804040178	50-348 P		8804210004	50-206 Q	MILLER,M.N.	8804260190*	50-424 O
MCDONALD,R.P.	8804060324	60-348 S		8804210039	50-206 P	MILLER,M.S.	8804180057	50-322 G
MCDONALD, R.P.	8604060526	50-364 R	MEDFORD,M.O.	.8804210187	50-361 P	MILLER,M.S.	8804180057	50-322 G
MCDONALD, R.P.	8804080085	50-348 F	MEDFORD,M.O.	8804250248	50-206 I	MILLER,M.S.	8804200058	50-322 T
MCDONALD, R.P.	8804080094	50-348 Q	MEDLOCK,R.L.	8804280514	40-8462	MILLER,M.S.	8804200058	50-322 T
MCDONALD, R.P.	6804080196	50-340 S	MEEHAN,B.	8804050291	CONTRACT	MILLER,R.A.	8804070124*	50-440 I
MCDONALD, R.P.	8804110121	50-348 Q	MEEHAN,B.	8804050333	CONTRACT	MILLER,V.L.	8804140149*	NUREG
MCDONALO,R.P.	8804110134	50-348 F	MEEHAN,B.	8804050399	CONTRACT	MILLER, V.L.	8804270278*	PR
MCDONALD,R.P.	6804110147	50-348 J	MEEHAN,B.	8804060332	CONTRACT	MILLER, W.H.	8804060267*	50-346 Q
MCDONALD,R.P.	6804110277	50-348 P	MEEHAN,B.	8804200461	CONTRACT	MILLER, W.H.	8804200497*	FOIA
MCDONALD,R.P.	8804110337	50-348 R	MEEHAN,B.	8804200482	CONTRACT	MILLS, W.A.	8804280632*	PR
MCDONALD,R.P.	8804140001	50-348 Q	MEEHAN,B.	8804210306	CONTRACT	MILTENBERGER, S.	8803300046	50-272 Q
MCDONALD, R.P.	9804140005	60-348 O	MERHANB.	8604280343	CONTRACT	MILTENBERGER,S.	8803300210	50-311 O
MCDONALD, R.P.	8804160032	60-364 S	MERHANB.	8804280067	CONTRACT	MILTENBERGER,S.	8803310022	50-272 P
MCDONALD, R.P.	8804190141	60-364 R	MERHANB.	6804290099	CONTRACT	MILTENBERGER,S.	8804010180	50-272 O
MCDONALD, R.P.	8804190144	50-348 R	MERHANB.	8804290191	CONTRACT	MILTENBERGER,S.	8804010184	50-272 O
MCDONALD, R.P.	6804200371	50-364 S	MERHANB.	8804200361	CONTRACT	MILTENBERGER,S.	8804040100	50-272 P
MCDONALD, R.P.	8804220212	50-364 S	MERHAN,B.D.	8804210181	CONTRACT	MILTENBERGER,S.	8804060446	50-354 P
MCDONALD, R.P.	9804290298	50-348 S	MEHOLICK,J.J.	8804210204°	FOIA	MILTENBERGER,S.	8804070088	50-354 P
MCDONALD, W.G.	8804130371	ORG	MEISNER,M.J.	8803310009	50-382 P	MILTENBERGER,S.	8804070315	50-272 O
MCDONALD, W.G.	9804210076°	FOIA	MELFI,J.	8804190164°	50-528 O	MILTENBERGER,S.	8804120326	50-354 O
MCDONALD, W.G.	9804270119°	PR	MELLEN,L.	8804260114°	50-261 O	MILTENBERGER,S.	8804180109	50-354 P
MCDUFFIE,M.A.	8804060284	60-324 P	MELLINGER, G.B.	8804140210°	PROJ	MILTENBERGER,S.	8804210372	50-354 K
MCDUFFIE,M.A.	8804110050	60-324 Q	MENDEZ, R.	8804040141°	60-454 Q	MILTENBERGER,S.	8804220018	50-354 Q
MCELFINNEY,T.F.	6803250284	60-250 Q	MENDOCA, M.M.	8804250048°	50-344 Q	MILTENBERGER,S.	8804260194	50-354 P
MCELHINNEY,T.F.	8804260218	60-250 Q	MENDONCA, M.	8804190113°	50-528 Q	MINOGUER,B.	8804280249*	PR
MCFARLAND,J.T.	8804050029	50-322 G	MENDONCA, M.M.	6804130022°	50-275 Q	MINOGUER,B.	8804280637*	PR
MCGEE,T.D.	8804140075°	NUREG	MENDONCA,M.M.	8804250043°	50-344 Q	MINOGUE, R.B.	8804280645*	PR
MCGEE,T.D.	8804140130°	NUREG	MENGERS,C.A.	8803280104	50-352 S	MINOGUE, R.B.	8804280649*	PR
MCGOWAN,J.K.	8804270296	60:348 F	MENGERS,C.A.	8804060035	60-352 S	MINOGUE, R.B.	8804280665*	PR
MCGOWAN,J.W.	8804070285	50:348 F	MENGERS,C.A.	8804080031	50-352 S	MINOR, G.C.	8604200084*	50-322 T
MCGOWEN,J.W.	8804200045°	60:348 F	MENGERS,C.A.	8804080147	50-352 S	MINOR, G.C.	8804200084*	50-322 T
MCGUIRE, O.R. MCGUIRE, D.R MCGUIRE, D.R. MCGUIRE, D.R. MCGUIRE, D.R.	8804060386° 8804110328° 8804120029° 8804120176° 8804250056°	70-143 60-280 Q 50-321 Q 50-335 Q 70-143	MENGERS, C.A. MENGERS, C.A. MENGERS, C.A. MENNING, J.E. MENNING, J.E.	8604080151 8804080220 8804130070 8803300068* 6804250024*	50-352 S 50-352 S 50-352 S 50-321 Q	MINOR, G.C. MIRAGLIA, F.J. MIRAGLIA, F.J. MIRAGLIA, F.J. MISSAL, M.J.	8804290038* 8803240426 8804080088 8804220167 8804050031	50-322 G 50-3 P 50-3 P 50-206 P 50-322 G
MCGUIRE,D.R. MCGUIRE,D.R. MCGUIRE,D.R. MCGUIRE,D.R. MCGUIRE,D.R.	8804250061* 8804250070* 8804250085* 8804260006*	60-400 Q 50-327 Q 50-424 Q 50-338 Q 50-395 Q	MERKLE J.G. MERRICK D. MESERVE R.A. MESERVE R.A. MESERVE, R.A.	8804010275 8804050290* 9804040063 8804040063 8804190203	NUREG 50-259 F 40-2061 40-2061 40-2061	MISSAL,M.J. MITZELFELT,R. MIZNER.J.H. MOFFATT,L.W. MOFFATT,L.W.	8804050031 8604260567 8804200073 8804040103 8804120367	50-322 G 40-8811 50-443 G 50-302 S 50-302 S
MCGUIRE, D.R.	8804260034°	50-348 Q	METZENBAUM,H.M.	8804130409*	60-440 U	MOFFATT, L.W.	8804130100	60-302 5
MCINTOSH, T.W.	8804140206°	PROJ	MEYER,L.C.	8804080236	NUREG	MOFFATT, L.W.	8804200380	50-302 5
MCKNIGHT, E.M.	8804070099	50-255 P	MEYER,L.C.	8804080236	NUREG	MOFFATT, L.W.	8804200382	50-302 5

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MOIST, R.N.	8804050142*	OA999	MROCZKA,E.J.	8804110315	50 213 P	MURPHY,W P	8804010159	50-271 Q
MOKHTARIAN, K	8804010215	NUREG	MROCZKA,E.J.	8804110315	50 213 P	MURPHY,W P	6804010164	50-271 Q
MOLER, R.B	8804060254	WASTE RES	MROCZKA,E.J.	8904120247	50 423 P	MURPHY,W P	8804140477	50-271 R
MOLER, R.B.	8804130383	WASTE RES	MROCZKA,E.J.	8804120247	50 423 P	MURPHY,W P,	8804180685	50-271 Q
MOLZLER, D.S.	8804200386	50-285 S	MROCZKA,E.J.	8804120354	50 423 Q	MURRAY,B	8964050263*	50-458 Q
MONNIE D.I. MONNIE D.I. MONTOOMERY J.L. MONTOOMERY J.L. MONTOOMERY J.L.	8801260033* 8801260033* 8804040112 8804040115* 8804060475	50-395 P 50-395 P 70-734 70-734 O	MROCZKA.E.J. MROCZKA.E.J. MROCZKA.E.J. MROCZKA.E.J. MROCZKA.E.J.	8804120354 8804120364 8804120423 8804120423 8804120423	50-423 O 50-213 P 50-213 P 50-213 P 50-213 P	MURRAY.B MURRAY.B MURRAY.B MURRAY.H D MUSGLF,D	5804250336° 8804260031° 6804260046° 6804060031° 8803300236	50:382 Q 50:313 Q 50:482 Q 50:128 Q 50:263 V
MONTOOMERY, J.L. YREMOOTROM J.L. YREMOOTROM J.L. YREMOOTROM MONTOOMERY, J.L. YREMOOTROM	8804150089 8804220282 8804270037 8804270137 8804270087	70-734 50-397 Q 70-734 PR 70-734	MROCZKA,E J MROCZKA,E J MROCZKA,E J MROCZKA,E J	8804130218 8804130218 8804180173 8804180173 8804190041	50-423 P 50-423 P 71-9015 71-9015 50-423 P	MUSOLF,D. MUSOLF,D MUSOLF,D. MUSOLF,D MUSOLF,D	8803300243 8804150115 8804150133 6804150328 8804150362	50-282 V 50-263 R 50-282 R 50-263 V 50-282 V
MOORE	8804110233*	WASTE MGT	MROCZKĄĘJ	8804190041	50-423 P	MUSCLF,D.	8804220189	50-263 S
MOORE,JE.	8804050385	50-445 G	MROCZKĄĘ J	8804200508	50-245 Q	MUTO,N.F.	8804200113*	50-322 T
MOORE,JE	8804050092	50-445 G	MROCZKĄĘ J	8804200506	50-245 Q	MYERS,C.J.	8804120375*	50-312 O
MOORE,JE.	6804200031	50-446 G	MROCZKĄĘJ	8804200533	50-336 P	MYERS,H.	8604280650*	50-289 P
MOORE,M.L.	8804010112	50-170 R	MROCZKĄĘJ	8804209533	50-336 P	MYERS,H.	8804286661*	50-289 P
MOORE,P.	8804050371* 8804010215 8804080280 8804190100 8804060015	50-424 Q	MROCZKA.E.J.	8804200539	50-213 P	MYERS H.	8804280664*	60-289 P
MOORE,S.E.		NUREG	MROCZKA.E.J.	8804200539	50-213 P	MYRABO,A.U.	8804153115	50-263 R
MOORMAN,B.J		40-208	MROCZKA.E.J.	8804210077	50-420 P	NAGAI,Y.	8603680495	59-219 P
MOOSE,J.M.		50-483 R	MROCZKA.E.J.	8804210077	50-423 P	NAIK,J.A.	8804150022	50-327 S
MORALES,E.M.		40-8907	MROCZKA.E.J.	8804210150	50-423 Q	NAIK,J.A	8604200131	50-328 S
MORALES,E.M. MORAN,D.H. MORAN,D.H. MORAN,D.H MORAN,O.H.	8804280251 8804130184 8804130310 8804200368 8604280479	40-8307 50-259 P 50-259 P 50-259 P 50-259 P	MROCZKA.E.J. MROCZKA.E.J. MROCZKA.E.J. MROCZKA.E.J. MROCZKA.E.J.	8804210159 8804220097 6804220097 8804250249 8804250249	50.423 Q 50.423 P 50.423 P 50.213 I	NAIK, JA NAIA, P. NANSTAD, R.K NAPOLITANO, D.G. NAPOLITANO, O.G	8804270074 8804190384* 8804010275 8803310254* 8804210012*	50-327 S WASTE MGT NUREG 50-309 P 50-29 P
MORAN,D.H MORAN,D.M. MORGAN,,H E MORGAN,C. MORGAN,H.E	6804280618 8804200065 8804200137 8803310286 8804200216	50-259 P 40-3453 50-361 R 50-416 F 50-361 S	MROCZKA,E J MROCZKA,E J. MROCZKA,E J MROCZKA,E J. MROCZKA,E J.	8804250249 8804250267 8804250267 8804250070 8804260070	50-213 † 50-245 F 50-245 F 50-213 Q	NARBUT,P. NARBUT,P.P. NARDACCI,G.A NARDI,A J NARDI,A J.	8804190113* 8804130022* 8803280080* 8804190043 8804280003	50-528 Q 50-275 Q 50-289 R 50-87 W 70-1151
MORGAN,H E.	8803300191	50-206 S	MROCZKA,E.J	8804260285	50-423 P	NARDIAJ.	8804280015	70-1151
MORGAN,H E.	8804040105	50-361 S	MROCZKA,E.J	8804260285	50-423 P	NARDONE,P.	8804180395	50-443 R
MORGAN,H E.	8804060001	50-361 F	MROCZKA,E.J.	8804270231	50-213 P	NASHJ.D.	8804080173	PRM
MORGAN,H E.	8804060195	50-206 S	MROCZKA,E.J.	8804270231	50-213 P	NAUMAN,D A	8803250131	50-385 Q
MORGAN,H E.	8804060246	50-362 S	MROCZKA,E.J.	8804290282	60-246 P	NAUMAN,D A	8803290274	50-395 L
MORGAN,H.E. MORGAN,H.E. MORGAN,H.E. MORGAN,H.E. MORGAN,H.E.	8804200128 8804200224 8804200247 8804200267 8804210339	50-206 R 50-361 S 60-206 S 50-361 S 50-206 O	MROCZKA,E J. MUELLER,R C. MULDER,R.U. MULDER,R.U. MULDER,R U	8604290282 8804250128 8803080467 8803310227 8804060357	60.245 P 60.409 I 50.62 P 50.62 P 50.62 P	NAUMAN,D.A NAUMAN,D.A NAUMAN,D A NAUMAN,D A NAUMAN,D.A.	8803290300 8804010059 8804010239 8604010242 8804060391	50-395 P 50-395 S 50-395 P 50-395 P
MORGAN,H.E.	8804260407	50-206 S	MULDER,R.U.	8804070190*	59.62 P	NAUMAN,D.A.	8804060394	50-395 P
MORGAN,R.E.	6804150139	50-261 FI	MULLER,D.R.	6803080125	50.373 P	NAUMAN,D.A.	8934110286	50-395 Q
MORGAN,W.E.	8804140023	50-295 Q	MULLER,D.R.	6803080455*	50.373 P	NAUMAN,D.A.	8804110292	50-395 Q
MORGAN,W.E.	8804140056	50-295 Q	MULLER,D.R.	8804040248*	50.295 P	NAUMAN,D.A.	8804180137	50-395 P
MORGAN,W.E.	6804260039	50-10 P	MULLER,D.R.	8804050133*	50.254 P	NAUMAN,D.A.	8804190133	50-395 P
MORGENSTERN,M.	8803080283	40-7102	MULLER,D.R.	8804110220	50-285 P	NAUMAN,D:A	8804210242	60-395 P
MORGENSTERN,R	8604150407	50-461 S	MULLER,D.R.	8804110235*	50-285 P	NEFF,JO.	8804210365	WASTE MGT
MORONEY,R.F.	8804130111	COMMISSIO N	MULLER,D.R.	8804130243	50-461 O	NEIGHBORS,JO.	8804190165	50-286 P
MORRIS,B.M.	8804050256	PROJ	MULLER,D.R.	8804140543*	50-454 P	NEISLER,JH.	8804060168*	50-456 O
MORRIS,B.M.	6804150231	PROJ	MULLER,D.R.	8804180277	50-454 P	NEISLER,JH.	8804120080*	50-305 Q
MORRIS,B.M.	8804270062*	PR	MULLER,D.R	8804180283*	50-454 P	NEISLER,J.H.	8804150053*	50-315 Q
MORRIS,B.M.	8804270205*	PR	MULLER,D.R	8804180316	50-457 O	NELLIS,D.	8804270103*	PR
MOUNT,D.K	8805030161*	PR	MULLER,D.R.	8604180387*	60-454 P	NELLIS,D.O.	8804270040	PR
MOXLEY,M.	8804290009	40-4492	MULLER,D.R.	8804220007*	50-464 P	NELSON,J.	8804070067	50-424 Q
MROCZKA,E J.	8803300412	50-245 Q	MULLER,D.R.	8804220244*	50-295 P	NELSON,J.E	8804280382*	CONTRACT
MROCZKĄ,E.J.	8803300412	50-245 Q	MULLIKIN,R.	8803310101*	50-285 Q	NERON,G.	8804130060	50-338 R
MROCZKĄ,E.J.	8803310043	50-213 Q	MUNNO,A.M.	8804010112	50-170 R	NERSES,V.	6804060199	50-433 O
MROCZKĄ,E.J.	8803310043	50-213 Q	MUNRO,J.F.	8803250181*	50-250 V	NERSES,V.	8804130430	50-443 Q
MROCZKĄ,E.J.	8803310043	50-213 Q	MUNRO,J.F.	8804050378*	50-321 V	NERSES,V.	8804220062*	50-293 F
MROCZKĄ,E.J.	8803310109	50-336 Q	MUNRO,J.J	8804180401	71-9036	NERSES,V.	9804220246	50-443 P
MROCZKĄĘ J. MROCZKĄĘ J. MROCZKĄĘ J. MROCZKĄĘ J. MROCZKĄĘ J.	8803310117 8803310207 8803310207 8804010149 8804050005	50-213 Q 50-245 P 50-245 P 50-213 P 50-245 K	MUNSON,L.F. MURAWSKI,T.F. MURDOCK,S. MURLEY,T.E. MURLEY,T.E.	8804110039* 8804140185* 8804060278 8711030480* 8801270288	60-320 G PROJ 40-6622 PR REVIEW GR P	NESRSTA,JJ. NESRSTA,JJ. NEWBURGH,G NEWMAN,JR. NEWMAN,J.R.	8803210478 8804190059 8804130054 8804050033 8804050033	50 498 R 50 498 R 50 245 R 50 445 G
MROCZKĄ,E.J.	8804050005	50-245 K	MURLEY,T.E.	8803080223	50-440 P	R.L, MAMWAN	8904050039	50-445 G
MROCZKĄ,E.J.	8804050376	50-338 Q	MURLEY,T.E.	8803100186	ORG	R.L, MAMWAN	8804050039	50-445 G
MROCZKĄ,E.J	8804050376	50-338 Q	MURLEY,T.E.	8803100160	ORB	R.L, MAMWAN	8804050044	60-445 G
MROCZKĄ,E.J.	8804060003	60-245 F	MURLEY,T.E.	8803180091	50-312 P	R.L, MAMWAN	8804050044	50-446 G
MROCZKĄ,E.J.	8804060003	60-245 F	MURLEY,T.E.	8803280063	60-488 P	R.L, MAMWAN	8804050109	50-445 G
MROCZKĄE J.	8804060055	50-423 S	MURLEY,T.E.	8804010249	ORG	NEWMAN,J.R.	8604200023	50-445 G
MROCZKĄE J.	8804060055	50-423 S	MURLEY,T.E.	8804050083	50-312 P	NEWMAN,J.R.	6804200023	50-445 G
MROCZKĄE J.	8804070118	50-245 J	MURLEY,T.E.	8804050296	50-312 P	NEWSOME,R.W.	6803290326*	50-250 O
MROCZKĄE J.	8804070118	50-245 J	MURLEY,T.E.	8804120396*	60-483 P	NEWSOME,R.W.	6803310280*	50-269 O
MROCZKĄE J.	8804070201	60-213 H	MURLEY,T.E.	8804130241	50-320 P	NEWTON,G.J.	8904280444	NUREG
MROCZKA,E.J MROCZKA,E.J. MROCZKA,E.J. MROCZKA,E.J. MROCZKA,E.J.	8804070291 8804070291 8804070293 8804070319 8804070319	60-213 H 60-213 H 50-213 J 50-245 O 50-245 O	MURLEY,T.E. MURLEY,T.E. MURLEY,T.E. MURLEY,T.E. MURLEY,T.E.	8804130261 8804200491* 8804250297* 8804260100 8804270303	60-322 P FOIA 50-498 P 50-498 P 50-312 P	N:CHOLAS,J.B. NICHOLAS,J.B. NICHOLSON,L.E. NICKERSON,J.	8804050263* 8804250336* 8804260047* 8804260232* 8804250340	50-468 O 50-382 O 50-280 O 50-280 O 50-283 P
MROCZKA,É J.	8804080056	50-213 R	MURLEY,T.E.	8804280462	ORG	NICKERSON, J.M.	8804250313	FOIA
MROCZKA,E.J.	8804080269	50-245 F	MURPHY A G	6804180308*	CONTRACT	NICOLETTE.V.F.	8804280588	NUREG

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION	SUBJECT
NOLAN,D, NOONAN,T.P. NOONAN,T.P. NOONAN,T.P. NOONAN,T.P.	8804140188 8603280034 8803280304 8804040221 8804080060	71-4986 50-334 S 50-412 S 50-334 S 50-334 S	OSIENSKY,J.L. OSTER,J. PACE,N.E. PACE,N.E.	8804180803 8804120216 8804250042 8710140348* 8710140348	WASTE RES 50-10 J 50-254 J 50-382 P 50-382 P	PEGGJLL PELCHATJJ PELESCHAK,S PELESCHAK,S PELLET,JL	8804140218* 8804060080 8804130001 8804130066 8803230324*	PROJ 18E 50-219 O 50-289 O 50-285 V
NOONAM,T.P.	6804130086	50-334 S	PACILIO,J.D.	8803300204	50-265 S	PELLETJU	8804060042*	50-298 V
NOONAN,T.P.	8804130091	50-412 S	PACKARD,G.C.	8804150398	50-255 R	PEULETJU	8804060329*	50-285 V
NOONAN,T.P.	8804140166	50-334 S	PADOVAN,L.M.	8804130022*	50-275 Q	PELLETIERJP	8804060107	50-271 S
NOONAN,T.P.	8804220087	50-334 F	PAGE,T.A.	8804250248*	50-206 I	PELLETIERJP	8804070068	50-271 S
NOOBERG,J.	8604120048	50-336 P	PALOMINO,F.G.	8504180057	50-322 G	PELLETIERJP	8804200148	50-271 S
NORDERHAUG, LR.	8904270044*	70-734	PALOMINO,F.G.	8804290030	50:322 G	PENA,S PENNINGTON,W.S. PENNINGTON,W.S PENTZIEN,D.C. PEREJBA,D.B.	8804050346*	XPORTLIC
NORELIUS, C.E.	8804040223	50-456 O	PANG,J.F	6108260083*	FOIA		8804110205	40-3392
NORELIUS, C.E.	8804070007	50-305 F	PAOLINO,R J	8804120199*	50:213 Q		8804120166	40-3392
NORELIUS, C.E.	8804070159	50-237 O	PAPANIC,G	8804040149	50:29 J		8804220041*	50-220 P
NORELIUS, C.E.	8804200410	50-341 Q	PAPANIC,G	6804060101	50:29 H		8804250048*	50-344 O
NORELIUS, C.E. NORKIN, D.P. NORMAN, D.E. NORRIS B.S. NORRIS, B.S.	8804200481 8604280640* 8604250118* 6804060103*	50-331 O 50-445 O 50-267 O 50-57 V 50-309 V	PAPANIC,G. PAPANIC,G PAPANIC,G PAPERIELLO,G J. PAPPAS,J	8804060406 8804140117 8804210010 8804080010 8804210012*	50:29 F 50:29 P 50:29 P 50:456 Q 50:29 P	PEREZ,G PERKINS,K PERKINS,K.E. PERKINS,K.E PERKINS,K.E.	8804120375* 8804080267 8803080446* 8804110244* 8804110335*	50-312 O NUREG 50-305 P 50-305 F 50-266 F
NORRIS, D.S.	8804000072*	50-170 V	PAQUETTE, J.F.	8804130361	50-277 P	PERKINS,KE.	8804220057*	50-266 P
NORRIS, J.A.	8804040238	50-295 P	PARK, J.Y	8804080134	NUREG	PERKINS,KE.	8804220281	50-483 P
NORRIS, J.A.	8804110230	50-295 P	PARKHILL, R.	8804190113'	50-528 Q	PERKINS,KE.	8804280010	50-483 P
NORRIS, J.A.	8804220113	50-295 F	PARKINSON, K.	8604150046'	50-295 Q	PERKINS,KE	8804280551*	50-266 P
NORRIS, J.A.	8804220242	50-296 P	PARLER, W.C.	8802170361	SECY	PERKINS,KR	8804050126*	50-389 P
NORTH,H.S.	8804060509*	50-526 O	PAHLER,W.C.	8804130133	COMMISSION	PEAKINS,K.R.	8604050231*	50-382 P
NORTH,P.J.	8803300087	50-270 S	PARLER,W.C.	8804260037*	50:498 P	PEAKINS,T.J.	8804200294	50-410 S
NORTH,P.J.	8804080145	50-269 S	PARRIS,H.G.	8804260013	50:298 P	PEAKINS,T.J.	8904130159	50-220 R
NORTH,P.J	8604160256	60-269 S	PARTLOW,J.G.	8507030703*	FOIA	PEAKINS,T.J.	8804130166	50-410 F
NORTH,P.J	8804260231	50-269 S	PARTLOW,J.G.	8507030703*	FOIA	PEAKINS,T.J.	8804150075	50-220 S
NORTON B NOVACHEK F J NOVAK T.M. NOVAK T.M.	8804050041 8803290283* 8804190273 8710280311* 8804250117	50-275 G 50-267 P 50-267 R PR OAG	PARTLOW, J.G. PARTLOW, J.G. PARTLOW, J.G. PASCHIS, J.A. PASCIAK, W.	8507100054° 8507100084° 8507100091° 6804080218 8804200163°	FOIA FOIA FOIA NUREG 50:286 Q	PERKINS,T.J. PERKINS,T.J. PERKINS,T.J. PERKINS,T.J. PERKINS,T.J	8804190038 8804190067 8604190257 8804200253 8804200283	50-410 S 50-410 S 50-220 S 50-220 I 50-220 S
NUSSBAUMER, D.A. NUSSBAUMER, D.A. O'CONNELL, P.V. O'CONNOR, D.J. O'DONNELL, E.	8803080018* 6804270216* 8804040041 8804070146 8804080272	40-8027 PR 40-7604 50-29 J NUREG	PASCIAK,W.J. PASCIAK,W.J. PASCIAK,W.J. PASTIS.H.N. PASTVA,M.J.	8804110319° 8604200046′ 8804200127° 8804210350 8803290251	50-277 Q 50-334 Q 50-317 Q 50-269 P 50-325 S	PERKINS,T.J. PERRY,C.G. PERSON,L.S. PETERSEN,L.R.	8804200303 8804200084* 8804200084* 8803300020 8804150196*	50-220 S 50-322 T 50-322 T WASTE MGT CONTHACT
ODEGAANDEN,R.H	8804040244	TOPREP	PASTVA,M.J.	8804060277	50-325 S	PETERSON, C.H	8804080001	WASTE RES
ODEGAARDEN,R.H.	8804120014	71-9218	PASTVA,M.J.	8804070153	50-325 S	PETERSON, C.H.	8804130078	WASTE MGT
ODEGAARDEN,R.H.	8804120019	71-6078	PASTVA,M.J.	8604110041	50-325 S	PETERSON, C.H.	8804130268	WASTE RES
ODEGAARDEN,R.H.	88041403 6 2	MISC	PASTVA,M.J.	8804130331	50-325 S	PETERSON, G.C.	8804070027	50-331 F
ODEGAARDEN,R.H.	8804200517	MISC	PASTVA,M.J.	8804260001	50-324 S	PETERSON, M.R.	8804040197	XPORTUC
ODEGAARDEN,R H	8804200528	MISC	PATE.R J.	8804050040	50:344 O	PETERSON,MR. PETERSON,MR PETERSON,MH. PETERSON,MR. PETERSON,MR.	8804050104	XPORTLIC
ODEGAARDEN,R H	8804200580	71-9183	PATE.R J.	8804120401	50:344 O		8804050119	XPORTLIC
ODEGAARDEN,R H	8804200586	71-9212	PATE.R J.	8804180416	50:397 O		8804050137	XPORTLIC
ODEGAARDEN,R H	8804250113	71-9213	PATE.R J.	8804180381	50:27 V		8804050170	XPORTLIC
ODEGAARDEN,R H	8804250230	71-9202	PATE.Z.	8804130161	FOIA		8804050197	XPORTLIC
ODEGAARDEN,R H,	8804130422	71-202	PATE, 2.T.	8804130146*	FOIA	PETERSON,MR. PETERSON,MR. PETERSON,MR. PETERSON,MR. PETERSON,MR.	8804050273	XPORTLIC
ODETTE,G.R.	8804130422	ACRS	PATE, 2.T.	8804130167*	FOIA		8804050337	XPORTLIC
OELKERS,E	8604060041*	WASTE MGT	PATE, 2.T.	8804130284*	COMMISSION		8804050338	XPORTLIC
OHYAMA,T.	8804050196	XPORTLIC	PATE, 2.T.	8804190197*	FOIA		8804050349	XPORTLIC
OLOHAM,J.G.	8804130128	WASTE MGT	PATE, 2.T.	8804190226*	FOIA		8804280413	XPORTLIC
OUVER.H.W.	9804150273	WASTE MGT	PATE 2.T.	8804190244'	FOIA	PETERSON,M.R	8804280475	XPORTLIC
OLMSTEAD.C.A.	8804120311	50-344 R	PATE 2.T.	8804190260'	FOIA	PETERSON,M.R.	8804280493	XPORTLIC
OLMSTEAD.C.A.	8604140109	50-344 S	PATE 2.T.	8804190263'	FOIA	PETERSON,M.R.	8804280515	XPORTLIC
OLMSTEAD.C.A.	8804140119	50-344 S	PATE 2.T.	8804190276'	FOIA	PETERSON,M.R.	8804280625	XPORTLIC
OLMSTEAD.C.A.	8804140169	50-344 S	PATE 2.T.	8804190283'	FOIA	PETERSON,M.R.	8804290176	XPORTLIC
OLMSTEAD,C.A	8804200257	50-344 S	PATEL.C.	8804050204	50-280 P	PETERSON,MR.	8804290276	XPORTUC
OLSEN.A.F.	8804070047	50-13 J	PATEL.C	8804210407	50-280 P	PETERSON,M.W.	8804190114	50-456 R
OLSEN.A.F.	8804140361	70-824	PATEL.C.P.	8803080520	50-280 P	PETKUS,L.L.	8804140185*	PROJ
OLSEN.A.F.	8804270279	70-824	PATRICK,W.C.	8804190364*	WASTE MGT	PETRILAK,R.W	8804200113*	50-322 T
OLSEN.T.T.	8804070334	WASTE MGT	PATTERSON,A.A.	8804280230*	50-445 A	PETTENGILL,HJ.	8804050288	40-8064
OLSHAN, LN.	8804140541	50-454 P	PATTERSON.C. PATTERSON,J. PATTERSON,J.P. PATTERSON,J.P. PATTISON,R.S.	8804190097	50-321 S	PETTENGILLH J	8804050290	40-1162
OLSHAN, LN.	8804180381	50-454 P		6803290343°	50-237 Q	PETTENGILLH J.	8804050393	40-1162
OLSHAN, LN.	8804220004	50-454 P		6804060064°	50-266 O	PETTENGILLH J.	8804050395	40-8681
OLSHINSKI, JA.	8804220567*	FOIA		8804200509°	50-331 Q	PETTENGILLH J.	8804050405	40-299
ORDERS, W.	8803290336*	50-369 Q		8804280023	40-8084	PETTENGILLH J.	8804050412	40-1162
ORDERS,W.	8803310285*	50-369 Q	PA1 FISON, P.S	8804280530	40-8084	PETTENGILL,H.J. PETTENGILL,H.J. PETTENGILL,H.J. PETTENGILL,H.J. PETTENGILL,H.J.	8804050432	40-8902
ORLOSKY,P.M.	8804120405	71-5971	PATTON, J.D	8804080215	40-8102		8804060012	40-6622
ORSER,W.S.	8803310147	50-341 S	PAUL, P.A	8804140270'	50-341 O		8804060038	40-8752
ORSER,W.S.	8804050172	50-341 S	PAULK, G.L	8803310292'	50-259 Q		8804060133	WASTE MGT
ORSER,W.S.	8804050185	50-341 S	PAULK, G.L	8804010033'	50-259 O		8804060137	40-8452
ORSER,W.S.	8804150405	50-341 S	PAULSON,W.A.	8804060078	50-458 P	PETTENGILL,H.J. PETTENGILL,H.J. PETTENGILL,H.J. PETTENGILL,H.J. PETTENGILL,H.J.	8804060166	40-6622
ORSER,W.S.	8804150417	50-341 S	PAULSON,W.A.	8804110330	60-458 P		8804060201	WASTE MGT
ORSER,W.S.	8804190129	50-341 R	PAULSON,W.A.	8804120030	50-458 P		8804060260	40-4492
ORSER,W.S.	8804190236	50-341 S	PAULSON,W.A.	6804180326	50-458 P		8804060314	40-8908
ORSER,W.S.	8804200139	50-341 S	PAULSON,W.A.	6804190215	50-458 P		8804060339	40-8064
ORSER,W.S. ORSER,W.S. ORSER,W.S. OSBORN,T.G. OSBORN,T.G.	8804200159 8804200375 8804270004 8804060388 8804280133	50-341 S 50-341 S 50-341 S 40-8904 40-8904	PAULSON W.A. PAUSTIAN H.H PAYNE, D.F. PEEBLES, T.A. PEEBLES, T.A.	8804290172 8804070009* 8804280067* 8803290336* 8803300075*	50-458 P 50-219 P CONTRACT 50-369 Q 50-413 Q	PETTENGILL,HJ. PETTENGILL,HJ. PETTENGILL,HJ. PETTIJOHN,S PFAFF,SJ.	8804070090 8804070119 8804260119 8804140410* 8804060089	40-8907 40-2259 40-8913 NUREG 40-8659
OSBORN,T.G.	8804280538	40-8904	PEEBLES,T.A.	8803310285°	50-369 Q	PFAFF S.J.	8804140250	40-6659
OSIENSKY,J.	8803300340*	WASTE RES	PEEBLES,T.A.	8804080181'	60-413 Q	PHILLIPS,M.P.	8803290069*	50-315 C
OSIENSKY,J.	8804120477*	WASTE RES	PEERAN,S.M.	8804120105°	50-327 P	PHILLIPS,M.P.	8804040141*	50-454 C

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PHILLIPS,MP	8804209408*	50-461 Q	OUERIO,R.E.	8804190259	50-456 S	ROBARE D J.	8804150017*	50-458 P
PICK,G A	8803310134*	50-192 Q	RABY,T.M.	8804190217'	ORG	ROBERTS G W	8503140040	WASTE MGT
PICK,G A	8804060323*	50-458 Q	RAMSPOTT,L.D.	8804150071	WASTE MGT	ROBERTS G W.	6804070114	WASTE MGT
PICK,G A	8804250067*	50-382 Q	RANDAZZA,J.B.	8803310253	50-309 P	ROBERTS J.P.	8804050180	71-9010
PIEPEL,G F	8804140210*	PROJ	RANEY,R.G.	8804260115	WASTE RES	ROBERTS J.P.	8804050431	PROJ
PIERCE, R.N.	0804060037	WASTE MGT	RANGE,O M.	8604070095	40-8102	ROBERTS, J.P.	8804130203	50-269 Y
PIERSON, R.C.	0804060041*	WASTE MGT	RANGE,O.M.	8804290193	40-8064	ROBERTS, J.P.	8804280658	PROJ
PIERSON, R.C.	8804130302*	50-327 Q	RANSON,C.B	8801260033'	50-395 P	ROBEY, R.A.	8804210353	50-254 P
PIERSON, R.C.	8804280057*	50-327 Q	RASHID,Y R	8804060483'	50-29 P	ROBEY, R.A.	8804220070	50-254 R
PIGOTT, D.R.	8894260150	50-361 G	RANTELSDORFER	8804190040	FOIA	ROBINSON, E.W	8804140186*	NUREG
PIGOTT,D.R.	8804260150	50:361 G	RAVENSCROFT,N. RAY,M J. RAY,M J. RAYMOND,W. RAYMOND,W.	8804280265	XPORTLIC	ROBINSON,E W.	8804140351°	NUREG
PIGOTT,D.R.	8804260150	50:361 G		9804260095	50:327 O	ROBINSON,E W.	8504140353°	NUREG
PILMER,D.F.	8804210412	50:361 O		8804250166	50:327 Q	ROBINSON,E.W.	6804140355°	NUREG
PIRTLE,G	8804200413*	50:341 O		8804140370	50:336 S	ROBINSON,E W.	8804140358°	NUREG
PITCAIRN,D.R.	8803310039*	50:324 O		8804200386	50:423 S	ROBINSON,G C	8804010275	NUREG
PITTMAN,J.W.	8804150195	CONTRACT	REAVIS, J.A.	8804200152	50-269 R	ROBINSON,G M	8804280441	40-3453
PLENIEWICZ,R	8804150224	50-454 S	REAVIS, J.A.	8804200156	50-369 R	ROCHE M B.	8804260299	50-219 P
PLENIEWICZ,R	8804260009	50-454 R	REAVIS, J.A.	8804200168	50-413 R	ROCKHOLD,H C.	8604280052*	50-317 P
PLESSET,M.S.	8804130200	ACRS	REOMOND, L.	8804190259	50-456 S	ROCKHOLD,H C.	8804280052*	50-317 P
PLETTINGER,H.A.	8804060084	50-458 Q	REEVES, O.L.	8804190018*	50-298 S	RODABAUGH,E C	8804010215	NUREG
PLETTNER,E A.	8804060397* 8803290248 8803300339 8804040002 8804060292	50:298 Q	REEVES,D.L.	8804200256	50-298 S	RODER M J	8804180450	50-346 S
PLIML,G J.		50:304 S	REEVES,D.L.	8804250080*	50-298 S	ROESNER G J	8804270282*	50-483 P
PLIML,G J.		50:304 R	REEVES,E.A.	8804110284	50-348 M	ROGERS J J	8803290241	50-219 S
PLIML,G J.		50:295 S	REEVES,E.A.	8804280200	50-348 Q	ROGERS P C	8804200027	50-313 S
PLIML,G J.		50:295 S	REGAN,W.H.	8804290003	ORG	ROGERS T	8804050007	50-327 S
PLIML G J.	8804140350	50-205 R	REGENDA,M J.	8804150367'	WASTE MGT	ROGERS,T.	8804150022	50-327 S
PLIML G J.	8804150030	50-304 S	REGENDA,M J.	8604190355	WASTE MGT	ROGERS,T,	8804150042	50-328 S
PLIML G J.	8804150251	60-205 R	REHM,T.A.	8804060230	COMMISSION	ROGGE,JF.	8804250034*	50-424 Q
PLIML G J.	8804220153	50-205 R	REHM,T.A.	8804120055	COMMISSION	ROGGE,J.F.	8804260190*	50-424 Q
PLIML G J	8804220159*	50-295 R	REHM,T.A.	8804120123'	50-498 P	ROMAN, T.W.	8804260415	50-220 F
PLISCO,L N	8004060216*	50:440 O	REHM,T.A.	8804120211'	50-498 P	ROMAN,T.	8803300346	50-220 R
PLOSKI,T	8003290343*	50:237 O	REHM,T.A.	8804200407	COMMISSION	ROMAN,T.	8804130159	50-220 R
PLOSKI,T J.	8004050064*	50:254 O	REHM,T.A.	8804280518	COMMISSION	ROMBERG,W.O.	8804250267	50-245 F
POHLE,J.A.	8003000345	WASTE RES	REIMUS,M.A.	8804140210'	PHOJ	ROMBERG,W.D.	8804290282	50-245 P
POHLE,J.A.	8804080004	WASTE RES	REIS,E J.	8804110018	50-322 G	RONAFALVY,J.	8804190044	50-311 R
POHLE, J.A. POHLE, J.A. POLICH, T. POLK, P. J. POLLACK, M. J.	8804120183 8804120424 8804180164* 8804130258* 8804210047*	WASTE RES WASTE RES 50-528 Q FOIA 50-272 S	REIS,E.J. REIS,E.J. REIS,T. RESCHESKE,P.R.	8804200037 8804200250 8804280025 8803310101' 8804040141'	50-322 G 50-443 G 50-322 G 50-285 Q 50-454 Q	RONAFALVY,J ROOD,H ROOD,H ROOD,H ROONEY,V L	8804190048 8804010127* 8804050164* 8804050427 8804120256	50-272 R 50-361 P 50-397 P 50-275 P 50-271 P
POLLACK,M J.	8804260061	50-272 S	RESSLER,W.C.	8803280079	50-289 R	ROONEY, V.L.	8804280616	50-271 P
POLLARD,R D.	8804050094*	50-312 P	REYES,L.A.	8803250291	50-250 Q	ROSA, F.	8411130333°	FOIA
POOLE,G.R.	8804150186*	CONTRACT	REYES,L.A.	8803250292*	50-250 Q	ROSANO, R.	8804260113°	70-1113
POPARAD,C J.	8804250147	PT21	REYES,L.A	8804060392	50-261 P	ROSE, H.D.	8804050395	40-8681
POPE,J.M.	8804140200*	PROJ	REYES,L.A	8804260019	50-261 P	ROSE, H.D.	8804060314	40-8908
POTAPOVS,U. POWELL,T.B. POWELL,T.B. POWER,E.J. POWERS,C.M.	8804050142* 8003290321* 8803280303* 8804260133* 8803300320	QA909 \$0-390	REYES, L.A. REYNOLOS, N.S REYNOLOS, N.S REYNOLOS, S.A. RICCARDELLA, P.	8804270065 8804110038 8804110038 8804060216° 8803310039°	50-425 A 50-460 G 50-460 G 50-440 Q 50-324 Q	ROSE,H D. ROSENTHAL,J F. ROSENTHAL,J E. ROSENTHAL,J E. ROSENTHAL,J E	8804260121* 8804010066 8804040022 8804250106 8804260137	40-8913 REVIEW GR P ORG ORG ORG
POWERS.C.M. PRENDERGAST.K. PRENDERGAST.K. PRESCOTT.P. PRESTHOLT.P.T.	8804150401	50-397 R	RICE,P.D.	8803210067	50-425 F	ROSLONIEC,D.J.	8804200346	50-285 S
	8804040118*	70-734	RICE,P.D.	8804060098	50-424 K	ROSS,D.F.	8602100002'	FOIA
	8804040125*	50-312 Q	RICE,P.D.	6804200540	50-425 Q	ROSS,R.R	8904180125	50-322 G
	8804130098*	50-528 Q	RICE,P.D.	8804210277	60-424 S	ROSS,R.R.	8804180125	50-322 G
	8±04080003	WASTE MGT	RICE,P.D	8804210281	60-425 S	ROSS,T.	8804050127	50-254 P
PRESTHOLT,P.T. PRESTHOLT,P.T. PRESTHOLT,P.T. PRESTHOLT,P.T. PRESTHOLT,P.T.	8804150402*	WASTE MGT	RICHARDS,R.R.	8804160352*	WASTE MGT	ROSS,T.	8604210438	50-254 Q
	8804210389	WASTE MGT	RICHARDS,S.	8804190164*	50-528 Q	ROSS,T.	8804280270	50-254 F
	8804210455	WASTE MGT	RICHARDS,S.A.	8804040090*	50-528 Q	ROSS,W.J.	8604080240*	50-250 Q
	8804210463	WASTE MGT	RICHARDS,S.A.	8804180417*	50-397 Q	ROSSELLE,C.J.	8804260382	WASTE RES
	8804260356	WASTE MGT	RICHARDS,S.A.	8804190113*	50-528 Q	ROSSI,A.R	6804200113*	50-322 T
PRESTHOLT,P.T. PRESTHOLT,P.T. PRESTHOLT,P.T. PREVATTE,R.L. PRICE,E R.	8804260359	WASTE MGT	RICHARDS,W.J.	8803310243	PRM	ROSSI,CE.	8803210090	50-3 O
	8804260366	WASTE MGT	HICHARDS,W.J.	8804070098	PAM	ROSSI,CE.	6804010256	50-3 O
	8804260372	WASTE MGT	RICHARDSON,S.	8804210211	50-328 \$	ROSSI,CE.	8804060370	50-3 O
	8804150386*	50-395 O	RICHARDSON,S.D.	8804010037	50-327 Q	ROSSI,CE.	8804140425	REVIEW GR P
	8804280656*	PR	RICHARDSON,S.D.	8804010058	50-327 Q	ROTELLA,T.S	6803080517	50-327 P
PUPILS,A S.	6803300322	50-316 R	RICHARDSON,S.D.	8804010060°	50-327 Q	ROTELLA, T.S.	8803100145	50:327 T
PUPILS,A S.	8803300326	50-315 R	RICHARDSON,S.D.	8804280040	50-327 Q	ROTELLA, T.S.	8804010073	50:327 T
QUAIN,P.B.	8804280332	XPORTLIC	RICHEY,R.B.	8803310223	50-324 P	ROTELLA, T.S.	8804290167	50:328 P
QUAIN,P.B.	8804290080	XPORTLIC	RICHEY,R.B.	8804060247	50-261 Q	ROTHERT, W.C.	8804010119	50:331 Q
QUALLS,P.M.	8804120375*	50-312 Q	RICHEY,R.B.	8804210033	50-261 P	ROTHERT, W.C.	8804060493	50:331 Q
QUAY, I.	8804140488	50-341 P	RICHTER,M.H.	8804140127	50-374 S	ROTHERT, W.C.	8804110098	50-331 O
QUAY, T.R.	8803100061	50-341 P	RIDGE,T.	8804140223*	50-155 P	ROTHERT, W.C.	8804120016	50-331 P
QUAY, T.R.	8803100070*	50-341 P	RIDKY,R.W.	8804080272	NUREG	ROUGHAN, C.M.	8804180248	71-9147
QUAY, T.R.	8804080148	50-341 P	RIECK,T.	8804200260	50-295 F	ROUNTREE, R.	8804140077	50-456 S
QUAY, T.R.	8804110251	50-341 P	RIECK,T.A	8804120307	50-304 P	ROUSE, L.C.	8803080015	40-8027
QUAY,T.R.	8804120058	50-341 P	RILEY,J.A.	8804280501*	CONTRACT	ROUSE, L.C.	8803100018	40-2061
QUAY,T.R.	8804190175	50-341 P	RING,M.	8804040201	50-374 S	ROUSE, L.C.	8804110305	70-1068
QUAY,T.R.	8804190181*	60-341 P	RING,M.A.	8804080030*	50-373 Q	ROUSE, L.C.	8804220029	70-754
QUAY,T.R.	8804190196	50-341 P	RING,M.A.	8804120378*	50-237 Q	ROUSE, L.C.	8804220067	70-143
QUAY,T.R.	8804190211	50-341 F	RING,M.A.	8804190017*	50-264 Q	ROUSE, L.C.	8804220105*	70-143
OUAY,T.R.	8804210453	50-341 P	RINGSDORF, J.E.	8804070222	50-317 /	ROUTT,K.A.	8804140197*	PROJ
QUAY,T.R.	8804280303	50-341 P	RITTENBERG, R.B.	8804180133	27-48	ROY,B.A.	8804190267	71-9224
QUAY,T.R.	8804280500	50-341 P	RIVARD, D.A.	8804150111	50-309 R	RUBENSTEIN,L.S	8803080487	50-224 P
QUERIO,R.E.	8803280134	50-457 S	RIVENBARK, G.	8803100155	50-321 P	RUBENSTEIN,L.S.	8803080494*	50-224 P
QUERIO,R.E.	8804140071	50-456 S	RIVENBARK, G.	8604120031	50-354 P	RUBENSTEIN,L.S.	8803250184	50-2 P
QUERIO,R.E	8804140077	50-456 S	RIVENBARK,G.	8804150150	60-364 P	RUBENSTEIN,L.S.	8803250248	50-5 P
QUERIO,R.E.	8604100114	60-456 R	RIVENBARK,G.	8804160394	50-354 P	RUBENSTEIN,L.S.	8804010187	PROJ
QUERIO,R.E.	8804190251	60-457 S	RIVENBARK,G.	8804280222	I&E	RUBENSTEIN,L.S.	8804040265	50-409 P

ROHTUA	ACCESSION NUMBER	SUBJEC*		AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO	
Aubenstein,L S Rubenstein,L S Rubenstein,L S Rubenstein,L S Rubenstein,L S	8804080015 8804120140 8804180265 8804180296 8804180335	50-601 50-538 ORG 50-409 PROJ	A P P	SCACE,S.E. SCACE,S.E. SCACE,S.E. SCACE,S.E. SCACE,S.E.	8804070116 8804130051 8804130051 8804130054 8804130054	50-423 50-423 50-423 50-245 50-245	S FI FI FI	SHACKLETON,O.C. SHACKLETON,O.C. SHAFER,W. SHAFER,W. SHAFER,W.	8804260106* 8804260133* 8804060242 8804130197 8804210202	50-275 50-275 60-331 50-454 50-461	P Q S S S
RUBENSTEIN,L.S. RUBENSTEIN,L.S. RUBENSTEIN,L.S. RUBENSTEIN,L.S. RUBENSTEIN,L.S.	8804190071 8804190187' 8804190254 8804200493 8804220017	50-3 50-409 50-460 50-601 50-131	P A A F	SCACE, S.E. SCACE, S.E. SCACE, S.E. SCACE, S.E. SCACE, S.E.	8804130060 8804130060 8804130332 8804130332 8804140036	50-336 50-336 50-336 50-336 50-245	R F V V S	SHAFER,W.D. SHAFER,W.D. SHAFER,W.D. SHAFER,W.D. SHAFER,W.D.	8803290341 8803300310 8804050061 8804060059 8804080455	50-237 40-3392 50-254 50-266 50-461	0 000
RUBENSTEIN,L.S. RUBENSTEIN,L.S. RUBENSTEIN,L.S. RUBENSTEIN,L.S. RUBENSTEIN,L.S.	6804220024 8804220102' 8804280114 6804280275 8804280425	50-601 50-128 50-460 PROJ ORG	A P A	SCACE,S.E. SCACE,S.E. SCACE,S.E. SCACE,S.E. SCACE,S.E.	8804140036 8804140042 8804140042 8804190019 8804190019	60-245 50-245 50-245 50-245 50-245	5 5 5 5 5	SHAFER, W.D. SHAFER, W.D. SHAFER, W.D. SHAFER, W.D. SHAFER, W.D.	8804110057 8804110119 8804120178 8804120395 8804140060	50-331 50-461 40-3392 50-346 50-341	a a a
RUBENSTEIN,L.S. RUBENSTEIN,L.S RUDIS,M.A. RUOY,J.R. RUFF,A.	8804290001 8804290245* 8804060048 8804280140* 8804010067*	ORG 50-62 QA999 50-483 50-416	P P O	SCALETTI,D.C. SCALETTI,D.C. SCARANO,R.A. SCHADRACK,M.A. SCHAEFER,W.D.	8804050408 8804110232 8604070140 8804060361 8802250098*	50-605 50-605 50-275 FOIA 50-171	A A F U	SHAFER,W.D. SHAFER,W.D. SHAFER,W.D. SHAFER,W.D. SHAFER,W.D.	8804140104 8804190335 8804260068 8804270139 8804270274	50-373 50-123 50-373 50-440 50-282	р О О Р
RUFF, A B RUITER, G.H RULAND, W.H RUNION, D. RUNION, D.	8804260190° 6864150143 8804050354° 8804210197 6804210210°	50-424 50-305 50-324 CONTRACT		SCHAEVEL. SCHAPKER,J.F. SCHAUF,J.F. SCHAUF,J.M.	8804060292 6804060432* 8804060444* 8804260235* 8804260205*	60-295 60-248 50-305 60-445 50-445	S Q Q A A	SHAPER,W.D. SHAPPER,R. SHAPPER,R. SHAPPNER,JA. SHANBAKY,M.	8504270284 6604060110 6804280252 8603310063 6804120042*	50-461 40-8502 40-8684 27-48 50-29	F
RUNYAN,M.F. RUSSELLJ.E. RUSSELLJ.E. RUSSELLJ.R. RUSSELLJ.R.	8804200400° 8804150365 8804120466° 8804070057 8804070189	50-445 50-274 50-206 50-259 50-259	Q P Q P P	SCHAUF,J.M. SCHAUF,J.M. SCHAUF,J.M. SCHAUF,J.M. SCHAUF,J.M.	8804260237* 8804260241* 8804260243* 6804260247* 8804260250*	50-445 50-445 50-445 50-445 50-445	A A A A	SHANBAKY,M. SHANBAKY,M.M. SHANBAKY,M.M. SHANBAKY,M.M. SHANNON,J.M.	8804120053* 8804060136* 8804120270* 8804120327* 8804260052	50-277 50-244 70-371 50-220 50-443	00 da
RUSSELL, J.A. RUSSELL, V. RUSSELL, W.T. RUSSELL, W.T. RUSSELL, W.T.	8804070203° 8804200570° 8604050326 9804060142 8804110311	50-259 CONTRACT 60-272 60-245 50-322	P 0 0	SCHAUF,J.M. SCHAUF,J.M. SCHELL,R.J. SCHELL,R.J. SCHERER,A E	8804260253* 8804260254* 8604130303 8804200192 8804140263	50-445 50-445 50-309 50-309 70-36	A P P	SHEALY, H.G. SHEFFEY, R.A. SHEFFEY, R.A. SHEFFEY, R.A. SHEFFEY, R.A.	8805030070* 8804290091 8804290091 8804290147 8804290147	PR 50-322 50-322 50-322 50-322	G G
RUSSELL,W.T. RUSSELL,W.T. RUSSELL,W.T. RUTHER,W.E. RUTTER,S.	8804110317* 8804120432 8804120438* 6804080134 8804050023	50-322 50-311 50-311 NUREG 50-312	Q Q Q S	SCHERER,A E. SCHERER,A E. SCHERER,R.W. SCHEUERMAN,J.T. SCHIERMAN,S L.	8804150157 8804200529 8804270182' 8804120306 8804060172	70-1100 50-470 50-321 60-298 40-8681	K I R	SHELTON,D.C. SHELTON,D.C. SHELTON,D.C. SHELTON,D.C. SHELTON,D.C.	8803300054 8803300365 8804060308 8804060442 8804060449*	50-346 50-348 50-346 50-346 60-346	7 2 7 5
HUTTER,S. RYOER,T.S. RYDER,T.S. RYCER,T.S. RYGG,D E.	8804210136 8604040217 8804120073 8804250032 8803280306*	50-312 50-387 50-388 50-388 50-395	8 8 8 9	SCHMID,S P. SCHMID,S P. SCHMUTZ,T.A. SCHNEBLI,G A. SCHNEBLI,G.A	8804150363 8804270323 8804200038 8603250294* 8804260218*	70-1308 70-1308 50-445 50-250 50-250	600	SHELTON D.C. SHELTON D.C. SHELTON D.C. SHELTON D.C. SHELTON D.C.	8804110144 8804150429 880420069 8804220131 8804220134*	50-346 50-346 50-346 50-346 50-346	Р ОР Р
RYTKONEN,B. SAAD,E E. SALAMON,G. SALAMON,G. SAMOLINSKI,S J.	6804060275* 8804140224* 8804130144 6804260303 8804140330	CONTRACT PROJ 50-250 50-250 50-373	S S R	SCHNELL,O.F. SCHNELL,O.F. SCHNELL,O.F. SCHNELL,O.F. SCHNELL,O.F.	8804040119 6804060002 8804060173 8804070069 8804150408	50-483 50-483 50-483 50-483 50-483	P F 1 J O	SHELTON,D.C. SHELTON,D.C. SHELTON,D.C. SHEMANSKI,P. SHEMANSKI,P.	8804250148 8804250201 8804250005 8803080447 8804130377	50-346 50-346 50-348 50-373 50-373	P P P P
SAMPSON,P. SAMSKY,D. SAMUELS,J.L. SAMUELS,J.L. SAMUELS,J.L.	8804050374 8804070177* 8804040087* 8804140055 8804190374	50-374 50-483 50-458 50-458 50-313	5 5 J	SCHNELL,D.F. SCHNELL,D.F. SCHNELL,D.F. SCHNELL,D.F. SCHNELL,D.F.	8804150412 8804200458 8804200507 8804210016 8804210028	50-483 50-483 50-483 50-483 50-483	000FP	SHEPARD,D.L. SHERANKO,R. SHERANKO,R.G SHIFFER,J.D. SHIFFER,J.D.	88040600 : 8* 8804200222 8804060269 8803290362 8803290368	50-305 50-388 50-388 60-133 50-133	9 8 8 8
SAMUELS, J.L. SAMUELS, J.L. SAMUELS, J.L. SAMUELS, J.L. SAMUELS, J.L.	8804190382 8804200020 8804200026 8804200277 8804200420	TOPREP 50-458 50-331 50-458 50-313)))	SCHNELL,O F. SCHULTZ,D.A. SCHULZ,R.K. SCHUMACHER,M.C. SCHUMACHER,M.C.	8804210071 8804200383 6804080272 8804110090 8804120181	50-483 50-382 NUREG 50-331 40-3392	P S Q	SHIFFER J.D. SHIFFER J.D. SHIFFER J.D. SHIFFER J.D. SHIFFER J.D.	8803290400 8804010284 8804040009 8804050091 8804070014	50-323 50-323 50-275 50-275 50-323	S S F S
SAMWORTH, R.B. SAMWORTH, R.B. SAMWORTH, R.B. SAMWORTH, R.B. SAMWORTH, R.B.	8804120130 8804120186 8804120266 8804130230 8804130314	50-397 50-397 50-397 50-397 50-397	ታ ተ ተ ተ ተ ተ	SCHUMACHER,M.C. SCHUMAKER.A.R. SCHWABENBAUER SCHWARTZ.I. SCHWOERER,F.	8604260071* 8604270262 8804130293 8804080125 8804150128	60-373 50-348 60-400 NUREG 71-9102	Q F S	SHIFFER,J.D. SHIFFER,J.D. SHIFFER,J.D. SHIFFER,J.D.	8804070019 8804070024 8804200337 8804200521 8804200531	50-275 50-323 60-276 50-278 50-275	8 S F Q Q
SAMWORTH, R.B. SAMWORTH, R.B. SAMWORTH, R.B. SAMWORTH, R.B. SAMWORTH, R.B.	8804130322 8804210341 8804210418 6804210451* 8804280539	50-397 50-397 60-397 50-397 60-397	6 6 6	SCOTT,B R. SCOTT,W.E. SCOTT,W.E. SCOTT,W.E. SEARCHINGER,T.	8804280444 8803100002 8804210473 8804250298 8804290040	NUREG 50-155 50-155 50-155 60-277	P P G	SHIFFER,J.D. SHIFFER,J.D. SHIFFER,J.D. SHIFFER,J.D.	8804210449 8804220276 8804250017 8804250018* 8804260207	50-275 50-275 50-275 60-275 50-275	Q+p+O
SAMWORTH, Fl.B. SANCHEZ, C, SANDBERG, H.N. SANDOUIST, G.M. SANDS, S.P.	8804290101 8804280183° 8804060075 8804080459 8804040216°	50-397 40-8902 XPORTLIC 50-72 50-457	0 10	SEARS.C.F. SEARS.C.F. SEARS.C.F. SEARS.C.F. SEARS.C.F.	8604120423 8604120423 8604200533 8604200539 8804210159	50-213 50-213 50-336 50-213 60-423	Ք Բ Р	SHIFFER,J.D. SHOEMAKER,C.J. SHOEMAKER,C.J. SHOEMAKER,C.J. SHOEMAKER,C.J.	8804260216 8804160028 8804180048 8804290024 8804290026	50-133 50-443 50-322 50-443 50-443	P G G G
SANDS,S.P SANDS,S.P. SANDS,S.P. SANKINICK,M.G. SARTOR,W.M.	8804140541 8804180361 8804220004 8603300413 8803280132	50-454 50-454 50-454 50-458 50-413	6 A A G O	SEARS,C.F. SEARS,C.F. SEARS,C.F. SEARS,C.F. SEARS,C.F.	8804250249 8804250249 8804260070 8804260285 8804270231	50-213 50-213 50-213 50-423 50-213	- COP P	SHOEMAKER,CJ. SHOEMAKER,CJ. SHOLLY,S.C. SHOLLY,S.C. SHON,F.J.	8804290031 8804290098 8804190039 6804290036* 8804180010	50-322 50-443 FOIA 50-322 50-322	6 6 6
SATO,T, SAVIGNAC,N. SAXTON,C.H. SCACE,S.E. SCACE,S.E.	8803080511° 8804080130 8804270047 8804010001 8804010001	50-219 40-8698 50-387 50-423 50-423	P FSS	SEARS,C F. SEDAR,J.H. SEIDLE,W.C. SEIDLE,W.C. SERKIZ,A.W.	8804270231 8804220084 8804050227* 8804250067* 8804180463	50-213 50-219 50-498 50-382 REVIEW (P A Q Q GR P	SHOPENN,N.M. SHOPENN,N.M. SHOPENN,N.M. SHOPENN,N.M. SHOPENN,N.M.	6804050288 8804050290 8804080038 8804060260 8804060339	40-8064 40-1162 40-8752 40-4492 40-8064	
SCACE,S.E. SCACE,S.E. SCACE,S.E.	8804070049 8804070049 8804070118	50-245 50-245 50-423	s s	SEYMOUR,D.A. SHA,W.T. SHACK,W.J.	8803290269* 8804010116 8804080134	50-413 NUREG NUREG	Q	SHRIVER,T.D. SHRIVER,T.D. SHRIVER,T.D.	8804060158 8804130036 8804140106	60-528 50-529 50-529	999

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SHRIVER,T.D. SHRIVER,T.D. SHRIVER,T.D. SHRIVER,T.D. SHRIVER,T.D.	0804180445 8804190033 8804200301 8804210311 8804260007	50-528 S 50-529 S 50-528 S 50-528 S 50-528 S	SMITH,LW. SMITH,J.C. SMITH,J.C. SMITH,J.C.	6804260105° 8804260110° 8804060024 9804060240 8804060276	50.443 G 50.443 G 40.6622 40.6622 40.6622	SORENSEN G C SOHENSEN G C SORENSEN G C SORENSEN G C SORENSEN G C	8804120001 8604120052 8804140010 8804140062 8804150313	50-397 F 50-397 P 50-397 P 71-9079 50-397 F
SHUBERT,B.W	8804150414	50-265 \$	SMITH, J.D	8804130048*	50-324 F	SCRENSEN.G C	8804200103	50-397 Q
SHYMLOCK,M	8804050371*	50-424 Q	SMITH, J.F.	8804060432*	50-249 Q	SORENSEN.G C	8804200228	50-397 Q
SHYMLOCK,M.	8804150163*	50-327 Q	SMITH, J.F.	8804260183*	50-341 Q	SORENSEN.G C	8604210034	50-397 P
SIACOR,E.R.	8804200128	50-206 R	SMITH, J.S.	8804180461*	50-324 F	SORENSEN.G C	8804260080	50-397 F
SIACOR,E.R.	8804200137	50-361 R	SMITH, J.T	8804200113*	50-322 T	SPAETH.M	8804190363	WASTE MGT
SIEBER J.D.	8804010138	50:334 Q	SMITH, L.P.	8804130148*	CONTRACT	SPANGENBERG,F.	8803250053	50-461 S
SIEBER J.D.	8804040058	50:334 R	SMITH, M	8803290343*	50:237 Q	SPANGENBERG,F.	8604010271	50-461 S
SIEBER J.D.	8804050359	50:334 P	SMITH, M.J.	8803300319*	40:3392	SPANGENBERG,F.	8904070074	50-461 O
SIEBER J.D.	8804070110	50:412 P	SMITH, P.	8804060019	CONTRACT	SPANGENBERG,F.	8804110253	50-461 P
SIEBER J.D.	8804120352	50:334 Q	SMITH, P.	8804060025*	CONTRACT	SPANGENBERG,F.	8604150407	50-461 S
SIEBER J.D.	8804130130	50-412 P	SMITH,P.	8804150067	CONTRACT	SPANGENBERG,F	8804200160	50-461 \$
SIEBER J.D.	8804130257	50-334 Q	SMITH,P.	8804150082'	CONTRACT	SPANGENBERG,F	6804200198	50-461 R
SIEBER J.D.	8804180036	50-334 R	SMITH,P.A	8804120010	CONTRACT	SPANGENBERG,F	8804260197	50-461 S
SIEBER J.D.	8804220087	50-334 F	SMITH,P.D.	8804050410	WASTE MGT	SPANGENBERG,F	8804270178	50-461 P
SIEBER J.D.	8804260349	50-412 R	SMITH,P.D.	8804050429	40-8027	SPARKS,S E	8804010016	50-305 Q
SIEGEL,B SIEGEL,B SIEGER,J SIEGER,J D	8804260374 8804120066 8804080214 8804130172* 8804010087*	50:412 O TOPREH NUREG COMMISSION 60:237 P	SMITH, PLD. SMITH, PLD. SMITH, PLD. SMITH, PLD. SMITH, PLD.	8804060009 8804060108 8804060120 8804060194 8804060198*	40-8681 WASTE MGT 40-8752 40-8064 40-8064	SPEIS,T P. SPEIS,T P. SPEIS,T P SPESSARD,R L. SPIKER D L.	8609190081* 8702050186* 8703310385* 8904130299* 8803290283*	FOIA PR FOIA 50-369 Q 50-267 P
SILADY, J.A. SILADY, J.A. SILBERG, J.E. SILBERG, J.E.	8804060315 8804060497 8804110084 8804260088 8804280088	50.237 Q 50.285 P 50.237 P 50.440 G 50.440 G	SMITH,R.D. SMITH,R.D. SMITH,R.D. SMITH,R.D. SMITH,R.D.	8804060328 8804060328 8804060411 8804060415* 8804070056	40-8908 40-8681 40-8902 40-8902 WASTE MGT	SPINNEY, K B SPLETZER B L SPRAUL J G. ST LAURENT, N N STACHEW, J C	8804210012* 8604280588 8804060167 8804200293 8804280387*	50-29 P NUREG QA999 50-29 S 50-267 P
SILK,D	8804050358* 0804130220* 8804010163 8804010277 8804050195	50-244 V	SMITH, P.D.	8804070335	WASTE MGT	STAHLE,C.	8804050136	50-244 P
SILK,D.M.		50-336 V	SMITH, P.G.	8104020605°	PR	STAHLE,C.	8804180285	50-244 P
SILVER,H.		50-302 P	SMITH, P.M.	8804270100°	PR	STAHLE,C	6804280044	50-244 P
SILVER,H.		50-302 P	SMITH, S.J.	8803290224	50-327 S	STAHLE,C	8804280063	50-244 Q
SILVER,H.		50-302 P	SMITH, S.J.	8804010258	50-327 F	STAHLE,C	RB04280214	50-244 P
SILVER,H.	8804050300	50:302 P	SMITH, S. J.	8804050004	50-327 S	STAKEN,T H	8804040252*	50-382 O
SILVER,H.	8804190107	50:302 P	SMITH, S. J.	8604050006	50-328 S	STALLMANN F W	8804280633	NUREG
SILVER,H.	8804190357	50:302 P	SMITH, S. J.	8804050007	50-327 S	STANDERFER F H	8803310006	50-320 P
SILVER,H.	8804280182	50:302 P	SMITH, S. J.	8804050010	50-328 S	STANDERFER F R	8803310197	50-320 P
SILVER,H.	8804280498*	50:338 P	SMITH, S. J.	8804050014	50-327 S	STANDERFER F R	8804060069	50-320 P
SIMPSON,A.K.	6804210214* 8804010278 8804210001 8804080136 8803300208*	COMMISSIO N	SMITH,S.J.	8804110309	50-327 S	STANDERFER F.R.	6834086073	50·320 P
SIMPSON,E.C.		50:302 I	SMITH,S.J.	8804130343	50-327 S	STANDERFER F.R.	8604080077*	50·320 P
SIMPSON,E.C.		50:302 O	SMITH,S.J.	8804150022	50-327 S	STANDERFER F.R.	8804200551	50·320 P
SIMPSON,S.I.		WASTE MGT	SMITH,S.J.	8804150029	50-328 S	STANDERFER F.R.	8804210029	50·320 Q
SINGH,A.		50:408 O	SMITH,S.J.	8804150033	50-328 S	STANSBERRY, W.W.	8804110328*	50·280 Q
SINGH,A.	8804120134*	60-267 O	SMITH,S J.	8804150042	50-328 S	STANSBERRY, W.W.	8804120176°	50-335 O
SINGH,A.	8804250950*	50-313 O	SMITH,S J.	8804200123	50-327 S	STANTON, J.R.	8804140141'	NUREG
SINGH,M.	8804200032	WASTE RES	SMITH,S J.	8804200131	50-328 S	STASEK, S.	8804200408°	50-461 O
SINGH,S.	8804140058	50-354 P	SMITH,S J.	8804200278	60-327 S	STAUTER, J.C.	8803060530	40-8905
SINHA,R.S.	8804260378	WASTE MGT	SMITH,S J.	8804220020	50-327 R	STAUTER, J.C.	8604010136	70-925
SINKULE,M.V. SINKULE,M.V. SISK,D.P. SISKA,D.	8803300068* 8804250024* 8804260034* 8803290400 8804050004	50-321 Q 50-321 Q 50-424 Q 50-323 9 50-327 S	SMITH,S.J. SMITH,S.J. SMITH,W.F. SMITH,W.G. SMITH,W.G.	8804270074 8804270157 8804040252* 8803300322 8803300326	50-327 S 50-327 S 50-382 Q 50-316 R 50-315 R	STAUTER J.C. STAUTER J.C. STAUTER J.C. STAUTER J.C. STAUTER J.C.	8804060243 8804150366 8804190155 8804190193 8804280244	40-8027 40-8027 40-8027 40-8027 40-2061
SISKA,D.	8804050006	50-328 S	SMITH.W.G.	8804190250	50-316 S	STAUTER J C.	6804280457	4D-8027
SISKA,D.	8804160029	50-328 S	SMITH.W.G	6804210251	50-316 S	STEELE,T O	8804080218	NUREG
SISKA,D.	8804270167	50-327 S	SMITH.W.J.	8804220090	50-315 S	STEENLAND,O S.	6804050052	50-443 G
SISKA,D.P.	8804200278	60-327 S	SMITH.W.J.	6801040586*	50-382 Q	STEENLAND,O S	8804050052	50-443 G
SISKIND,B.	8804180088	WASTE RES	SMYTH.C.W.	6804190158	50-289 R	STEENLAND,O S	8804200102	50-443 G
SJOBLOM G. SKOLNICK,F. SKOLNICK,F. SKOLNICK,F. SKOLNICK,F.	8701070480* 8804110059 8804110059 8804110187 8804110187	PR 60-320 G 50-320 G 50-320 G 60-320 G	SNEIDER,CS. SNELL,W. SNELL,W. SNELL,W. SNELL,W.G.	880420068 8803290343* 8804060084* 8804060242 8804050064*	50-443 G 50-237 Q 50-266 Q 50-331 S 50-254 Q	STEENLAND,D S STEFANO,J J STEGER,W.A STEIGER,W.E	8804200102 8803100123 8804110334 8804280460 8804260248	50-443 G 50-263 O 50-263 P FOIA 50-322 S
SKOVHOLT,D.J. SLAWINSKI,W.J. SLOSSON,M. SLOSSON,M.	8804200153* 8804080462* 8804140070* 8804280081* 8804130266	60-275 P 60-481 Q 60-341 Q 50-247 P 60-247 P	SNIEZEK,JH. SNIEZEK,JH. SNIEZEK,JH. SNELEK,JH.	8804200509* 8603120377* 8609170458* 8804280626* 8804280444	50-331 O FOIA FOIA PR NUREG	STEIN,R. STEIN,R. STEINS,A.W. STEISS,A.W. STEISS,A.W.	9803240290 8804060289 8804110003 8804060335* 8804290196*	WASTE MGT WASTE MGT WASTE MGT CONTRACT CONTRACT
SLOSSON,M.M.	8804200022	60-247 O	SNOW,B A.	8804140044	50-244 S	STELLOV.	8802170349*	PR
SLOSSON,M.M.	6804260071	50-247 P	SNOW,B A.	8804140074	60-244 O	STELLOV.	8802190122	SECY
SMALLEY,M.	8804260322*	CONTRACT	SNOW,B.A.	8804140147	50-244 S	STELLOV.	8803310111	WASTE MGT
SMALLEY,M.	8804280451*	CONTRACT	SNOW,B.A.	8804180442	50-244 S	STELLOV.	8804050101	FOIA
SMEDLEY,R.W.	8804040067	50-265 P	SNOW,B.A.	8804200219	50-244 F	STELLOV.	8604050201	50-29 P
SMEDLEY,R.W. SMERDON,E.T. SMITH,D.A. SMITH,E.W. SMITH,G.C.	8804200171 8804070161 8804280668* 8804010105* 8804130077*	50-265 P 60-113 Q PR CONTRACT 50-293 Q	SNOW, 9 A. SNOW, B.A. SNOW, R.M. SOLBERG, D. SOLBERG, D.E.	8904200573 8804220120 8804060144* 8305020041* 8401200070*	50-244 P 50-244 R 50-244 Q PR PR	STELLO,V. STELLO,V. STELLO,V. STELLO,V.	8804050434 8804060180 8804060264 8804060316 8804060331	FOIA FOIA FOIA FOIA
SMITH,G.C.	8804130129*	50-293 Q	SOO,S.L.	8804280641	NUREG	STELLO,V.	8804110248	SECY
SMITH,I.W.	8804050324	50-443 T	SOONG,A	8804280641	70-143	STELLO,V.	8804120090	50-327 P
SMITH,I.W.	8804180045	60-443 G	SOONG,A.L.	8804220099*	70-143	STELLO,V.	8804120245	FOIA
SMITH,I.W.	8804180096	50-275 G	SOONG,S.	8804200455	70-143	STELLO,V.	8804130156*	FOIA
SMITH,I.W.	8804200264	50-443 G	SORENSEN,O.C.	8803300288	60-397 P	STELLO,V.	8804130260	50-369 Q
SMITH,I.W. SMITH,I.W. SMITH,I.W.	8804260058 8804260097 8804260101*	50-443 G 60-443 G 50-443 G	SORENSEN, G.C. SORENSEN, G.C. SORENSEN, G.C.	8804110122 8804110249	50-397 O 50-397 P 50-397 O	STELLO,V. STELLO,V. STELLO,V.	8804130357 8804130404 8804140193	50-171 P 50-440 U 50-155 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
STELLO,V	8804140243°	FOIA	SULLIVAN,R.L.	8804089242	50-219 F	TESTAED	8804250011°	50-250 O
STELLO,V.	8804140537	ORG	SUNDERLAND,P.R.	8804069018*	50-305 V	THADANIM	8804250021	50-387 P
STELLO,V.	6804150339°	FOIA	SUPRINA,R.N.	8804200113*	50-322 T	THADANIMC	8804080178	50-259 P
STELLO,V.	8804180322	50 322 U	SURMEJER,J.J	8803390905	WASTE MGT	THAĐANIMC	8804140484	50-387 O
STELLO,V	8804190213	ORG	SURMEJER,J.J	8804070178	WASTE MGT	THADANIMC	8804280211	50-388 P
STELLO,V. STELLO,V. STELLO,V. STELLO,V.	8804190256* 8804190084 8804220050 8804260224 8804280130*	FOIA WASTE MGT 50:327 H 50:275 E PR	SUTPHINIR N. SUZUKNO. SVILARID P. SWAILESIM P. SWAILESIM P.	890329069* 8804060374 8804060304 6804280382* 8804280501*	50-315 O WASTE MGT 40-1162 CONTRACT CONTRACT	THIELEN,L THOMAS,CO THOMAS,CO THOMAS,G THOMAS,GS	8804280333* 8804250010 8804280317 8804070051 8804040202	CONTRACT ORG 50-259 U 50-443 P 50-443 P
STEPHENS,K.W.	0804060527	WASTE HES	SWEENSY,M.	8804130280°	50-498 P	THOMAS, G.S	8804050045	50-443 G
STEPHENSON,J.D.	0804200440	50-302 F	SWETLAND,P.	8803280068°	50-247 Q	THOMAS, G.S	8804050055	50-443 O
STEPHENSON,J.D.	0804270322	50-302 F	SWETLAND,P	8803290132°	50-247 Q	THOMAS, G.S	8804050058	50-443 J
STEPHENSON,J.O.	0804290289	50-302 F	SWETLAND,P	8804070246	50-272 S	THOMAS, G.S	8804070138	PR
STETKA,T.	0803290320	50-302 Q	SWETLAND,P	6804130007	50-272 Q	THOMAS, G.S.	8804070221	50-443 F
STETKA,T. STETZ.J.P. STEVENS,G I STEVENS,J. STEVENS,J.A	8604150208* 8804260295 6804110052* 8804220161 8804110271	50-302 O 50-423 S 50-324 O 50-461 P 50-461 O	SWETLAND,P SWETLAND,P.D. SWETLAND,P.D. SWIFT,J.J. SYLVESTER,E.D.	8804130012* 8804120227 8804130407 8804110314* 8803080293	50-354 Q 50-247 Q 50-247 Q 70-1068 50-324 Q	THOMAS,G.S. THOMAS,G.S. THOMAS,G.S. THOMAS,G.S. THOMAS,G.S.	8804080122 8804140092 8804150142 8804150395 8804200004	50-443 F 50-443 F 50-443 F 50-443 R 50-443 F
STEVENS,J.A.	8804180464	50-461 P	SYLVESTER E D	6804080201	50-324 P	THOMAS, G.S. THOMAS, G.S. THOMAS, G.S. THOMAS, G.S. THOMAS, G.S. THOMAS, G.S.	8804210059	50-443 P
STEWART,M.E	6804190231	50-275 P	SYLVESTER E D	8804110227	50-324 P		8804210089	50-443 P
STEWART,A.C	8803300127*	50-482 Q	SYLVESTER E D	8804140120	50-324 P		8804220186	50-443 R
STEWART,A.C	8804250050*	50-313 Q	SYLVESTER E D	8804140285	50-324 P		8804270216	50-443 E
STEWART,S.A.	8804150380	50-302 R	SYLVESTER E D	8804140299	50-324 P		8804280084	50-443 F
STEWART, W.L.	8803300328	50-338 Q	SYLVESTER.E.D	8804150421	50-324 P	THOMAS,R D. THOMAS,W. THOMAS,W. THOMPSON,D. THOMPSON,D.	6804040118*	70-734
STEWART, W.L.	8803310012	50-280 Q	SYLVESTER.E.D	8804210336	50-324 P		8804120053*	50-277 Q
STEWART, W.L.	8804040070	50-280 P	SYLVESTER.E.O	8604210411	50-324 P		8804120270*	70-371
STEWART, W.L.	8804060248	50-338 P	SYLVESTER.E.O	8804220047	50-324 P		8804250085*	50-424 Q
STEWART, W.C.	8804060268	50-280 P	SYLVESTER.E.O	8804280160	50-324 P		8804120176*	50-335 Q
STEWART, W. L.	8804060433	\$0.338 Q	SYLVIA B R.	8604010000	50-341 P	THOMPSON, D.H. THOMPSON, D.H. THOMPSON, D.H. THOMPSON, H.L. THOMPSON, H.L. THOMPSON, H.L.	8804250056*	70-143
STEWART, W. L.	8804070142	50.280 F	SYLVIA B R.	8804010103	50-341 P		8804260034*	50-348 0
STEWART, W. L.	8804070252	50.338 R	SYLVIA B R.	8804060367	50-341 Q		8804260113*	70-1113
STEWART, W. L.	8804080097	50.338 P	SYLVIA B R.	8804060516	50-341 Q		8804140238*	FOIA
STEWART, W. L.	8804080252	50.339 Q	SYLVIA B R.	8604070133	50-341 J		8804280648	MISC
STEWART, W.L	8804080255°	50-339 Q	SYLVIA B.R.	8804110154	50-341 Q	THOMPSON,R D	8804010195*	CONTRACT
STEWART, W.L	8804120382	50-260 J	SYLVIA B.R.	B804130110	50-341 Q	THOMPSON,H D.	8804120038*	CONTRACT
STODDART, P.G.	8804120131°	50-302 Q	SYLVIA B.R.	B604140025	50-341 K	THOMPSON,R D.	8804190348*	CONTRACT
STODDART, P.G.	8804150299°	50-348 Q	SYLVIA B.R.	8804140490	50-341 P	THOMPSON,R.D.	8804280087*	CONTRACT
STOFFEY, P.	8804190304	STATE PRO G	SYLVIA B.R.	8804190008	50-341 S	TIEN,C.	8804130428	ACRS
STOUR, J.P. STOUR, J.P. STOUR, J.P. STOUL, L.M.	8803280123 8803300348 8804150289 8804250082 8804060153*	50-413 Q 50-321 Q 50-348 Q 50-424 Q 50-305 I	SYLVIA BR SYLVIA BR SYLVIA BR SYLVIA BR SYLVIA BR	8804210266 8804210319 8804260026 6804260045 6804270191	50-341 P 50-341 J 50-341 P 50-341 P 50-341 P	TIERNAN, JA TIERNAN, JA TIERNAN, JA TIERNAN, JA TIERNAN, JA	8803310247 8804010225 8804050001 8804050271 8804060481	\$0-317 P 50-317 P 50-317 P 50-317 K 50-317 O
STOLZJF.	8804010011* 8804050276* 8804050320* 6804060287* 8804110170	50-245 P	SYLVIA,B.R.	8804270203	50-341 P	TIERNAN,J.A.	8804060492	50-317 P
STOLZJF.		50-213 P	SZCZEPANIEC,A.	6804060298*	50-425 Q	TIERNAN,J.A.	8804060520	50-317 R
STOLZJF.		50-336 P	SZCZEPANIEC,A	8804260060*	50-425 Q	TIERNAN,J.A	8804110108	50-317 P
STOLZJF.		50-245 P	SZYMANSKI,J.S.	6803310113*	WASTE MGT	TIERNAN,J.A	8804120339*	50-317 P
STOLZJF.		50-320 P	TALBERT,J	8803300296*	50-397 P	TIERNAN,J.A	8804220093	50-317 Q
STOLZJF.	8804110172°	50-336 P	TALWANI,P.	8804010240*	50-395 R	TIKTINSKY,D.H.	8804120357	WASTE RES
STOLZJF.	6804120070	50-289 Q	TAM,P.S.	8804010129	50-334 P	TILLMAN,A.	8804250085*	50-424 O
STOLZJF.	8804140306	50-289 Q	TAM,P.S.	8804120025	50-334 P	TILLMAN,A	8804260010*	60-385 O
STOLZJF.	8604140515°	50-334 P	TAM,P.S.	8804120297*	50-334 P	TINGEN,S.G.	8804120054*	50-321 O
STOLZJF.	8804190214°	50-213 P	TAM,P.S.	8804140511	50-334 P	TOBIAS,M.L.	8804010223	NUREG
STOLZJF.	8804190278* 8804190314* 8804200231* 8804280194* 8804280361*	50-334 P	TAM,P.S.	8804140528*	50-334 P	TOBIN,W.	8804120028°	50-321 0
STOLZJF.		50-219 P	TAM,P.S.	8804190268	50-334 P	TOBIN,W.J.	8804060368°	70-143
STOLZJF.		50-423 P	TAM,P.S.	8804210359	50-334 P	TOBIN,W.J.	8804260113°	70-1113
STOLZJF.		50-336 F	TAM,P.S.	8804280116	50-412 Q	TODO,G.A.	8803290269°	50-413 0
STOLZJF.		50-289 P	TAM,P.S.	8804280464	50-334 P	TOXAR,M	8803290414	WASTE MGT
STOLZJF.	8804280612*	60-423 P	TANA,E T.	8804260351	WASTE MGT	TOKAR,M	8803300001	WASTE MGT
STONEJ.	8804130098*	50-528 O	TANG,S.S.	8803310044*	50-324 Q	TOKAR,M.	8803300003	WASTE MGT
STONEJ.C	8804040034	OA999	TATUM,J.	8803290364	50-361 S	TOKAR,M	8804070206	WASTE MGT
STONEJ.C	8804050134	OA999	TAYLOR,H.S.	8804060523	TOPREP	TOMLINSON,E	8804130166	50-410 A
STONEJ.C	8804060382	OA999	TAYLOR,J.H.	9804150049	TOPREP	IOMLINSON,K.M	8803310272*	WASTE MGT
STONE J.C.	8804120445	OA939	TAYLORJH.	8804180447	50-369 P	TOPPAN,W.C.	8804270248*	PR
STONE J.C.	8804140323	OA989	TAYLORJH.	8804200280	TOPREP	TORRE,J.G.	8804050246	50-414 S
STONE J.C.	8804140348*	OA989	TAYLORJL.	8804200047	50-322 G	TORRE,J.G.	9804050388	50-414 S
STONE J.C.	8804140356*	OA999	TAYLORJL.	8804200047	50-322 G	TORRE,J.G.	8804050390	50-414 S
STONE J.C.	8804190024	OA999	TAYLORJL.	8804260089	50-322 G	TORRE,J.G.	8804080030	50-413 S
STONE J.C. STONE J.C. STORZ STORZ L.F. STORZ L.F.	8804220148 8804270330 8804270263* 8803290376 8304070205	OA999 50-346 F 50-346 R 50-346 S	TAYLOR,JM TAYLOR,JM. TAYLOR,JM. TAYLOR,JM. TAYLOR,J.W.	8802090446° 8802090446° 8804210065° 8804290100° 8804080104	FOIA FOIA FOIA FOIA 50-409 P	TORRE J.G TORRE J.G TORRE J.G. TORRE J.G. TORRE J.G.	8804060032 8804080213 8804180426 8804190264 6804200317	50-414 S 50-413 S 50-414 S 50-413 S 50-414 S
STORZLE.	8804150393	50-346 F	TAYLOR,J.W.	8804080108*	50-409 P	TORHE J.G. TOSHIKAGO M. TOURIGNY E.G. TOURIGNY E.G. TOURIGNY E.G.	8804200323	50-413 S
STORZLE.	8804180450	50-346 S	TAYLOR,J.W.	8804130370	50-409 O		8804260418	XPORTLIC
STORZLE.	8804220044	60-346 R	TAYLOR,J.W.	8804250135	60-409 F		8804110266	50-335 P
STORZLE.	8804250086	50-346 S	TAYLOR,L.A.	8804060228	50-313 S		8804130333	50-335 P
STORZLE.	8804250086	50-346 S	TAYLOR,L.A	8804200014	50-368 S		8804130429	50-389 P
STOTZ J.C STRATFORD, R.J. STROSNIDER, J. STRUCKMEYER, R.	8804200311 8804050413 8804180119' 8804200075' 6804290185	50-346 S XPORTLIC NUREG 50-334 O NUREG	TAYLOR,M.A. TAYLOR,P.A. TAYLOR,R.G. TEDROW,J. TEDROW,J.	8609180240* 8804260190* 8804120017* 8803290320* 8804150208*	FOIA 50-424 O 50-298 O 50-302 O 50-302 O	TOURIGNY,E.G. TOURIGNY,E.G. TOWNSEND,J.D. TOWNSEND,J.D. TRACI,R.M.	8604280122 8604290058 8604200337 8804220104 8604190152*	50-389 P 50-335 P 50-275 F 60-275 R CONTRACT
SUH.G.Y.	8804250043*	50-344 Q	TEMUS,C J.	8804150252	71-9079	TRAFICONTE.J.	8804200106	50-443 G
SULLAWAY,M.F.	8804060483*	50-29 P	TENBROOK,W.K.	8804190160'	50-528 Q	TRAFICONTE.J.	8804260083	50-443 G
SULLIVAN,K.	8804130302*	50-327 Q	TENERZ,E.	8804040145	TOPREP	TRAFICONTE.J.C.	8804260059	50-443 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY
WARNER,J WARNER,J. WARNICK,R F. WARNICK,R.F. WARNICK,R.F.	8804080103° 8804120082° 8803080287 8803080292° 8803080301°	WASTE MGT WASTE MGT 50-445 O 50-445 O 50-445 O	WHITTIER, G.D. WHITTIER, G.D. WHITTIER, G.D. WHITTIER, G.D. WHITTIER, G.D.	8804060256 8804110278 8804150111 8804150274 8804190336	71-9222 50-309 O 60-309 R 50-309 I 50-309 P	WIGGINS,J.T. WIGGINS,J.T. WIGGINS,J.T. WIGGINS,J.T.	8804010211 8804120182 8804130029 8804130035 8804130150	50-334 P 50-271 Q 50-271 P 50-271 Q 50-309 Q
WARNICK,R.F.	8603300009	50-445 Q	WHITTER, G.D. WHITTER, G.D. WICHERS, D.L. WICHERS, D.L. WICHERS, D.L. WICHERS, D.L.	8804210232	50-309 F	WIGGINS,J.T.	8804200096	50-443 O
WARNICK,R.F.	8604040258	50-445 Q		8804270250	50-309 S	WIGGINS,J.T.	8804200209	50-322 O
WARNICK,R.F.	6604050260	50-445 Q		8804060169	40-8502	WIGGINTON,D.L.	8804080209	50-382 P
WARNICK,R.F.	8604060063	50-445 Q		8804060313	40-8502	WIGGINTON,D.L.	8804110002	50-382 P
WARNICK,R.F.	8804120431	50-445 Q		8804280035	40-8502	WIGGINTON,D.L.	8804140276	50-382 P
WARNICK,R.F.	8604190003	50-445 Q	WICHERS,D.L.	8804280097	40-8502	WIGGINTON,D.L.	8804180155	50-382 P
WARNICK,R.F.	8804200397	50-445 Q	WICHERS,D.L.	8804280477	40-8502	WIGGINTON,D.L.,	8804210376	50-382 P
WARNICK,R.F.	8804260014	50-445 Q	WICK,E.	8803310136	WASTE MGT	WILBORN,L.	8803310110	I&E
WASILK,J.S.	8804130262	50-346 F	WIDMAYER,D.A	8804070109	WASTE MGT	WILEY,J.S.	8804060079	50-352 G
WATHEN,T.R.	8804070136	WASTE MGT	WIEBE,J.S.	8804260018*	50-445 Q	WILGUS,W.S.	8804010172	50-302 P
WATSON,R.A.	8604010055	50-400 S	WIEDEMAN, D.	8804080447	I&E	WILGUS,W.S.	8804040155	50-302 F
WATSON,R.A.	8804060126	50-400 S	WIEDEMAN, D.	8804140038	I&E	WILGUS,W.S.	8804070029	TOPREP
WATSON,R.A.	8804060454	50-400 O	WIEDEMAN, D.	8804140041	I&E	WILKOWSKI,G.M.	8804080282	NUREG
WATSON,R.A.	8804130293	50-400 S	WIEDEMAN, D.	8804140383*	NUREG	WILLIAMS,F.L.	8804050185	50-252 R
WATSON,R.A.	8804190123	50-400 R	WIEDEMAN, D.	8804210194	I&E	WILLIAMS,G.	8804280574*	CONTRACT
WATSON R A.	6804250240	50-400 S	WIEDEMAN D.	8804210207	18E	WILLIAMS, J.H.	8804120212*	50-277 Q
WATSON S N.	6804050169	71-404	WIESEMANN,R A.	8803250267*	50:445 A	WILLIAMS, M.G.	8804050361	50-482 S
WATTERS J.P.	8804190329	70-1201	WIESEMANN,R.A.	8803290305*	50:395 P	WILLIAMS, M.G.	8804200204	50-482 R
WATTERS J.P.	8804280146	70-1201	WIESEMANN,R.A.	6803290358*	50:601 A	WILLIAMS, M.G.	8804200312	50-482 S
WEADOCK A.	6804060136*	50-244 Q	WIESEMANN,R.A.	8804010133*	50:801 A	WILLIAMS, R.E.	8803300336	WASTE RES
WEHRY, R.R.	8804040096	50-387 S	WIŁSEMANN,R.A	8804070243*	50-601 A	WILLIAMS, R.E.	8803300340°	WASTE RES
WEHRY, R.R.	8804060257	50-387 S	WIESEMANN,R.A.	8804210384*	60-282 Q	WILLIAMS, R.E.	8804120471	WASTE RES
WEI, P.	8804070009*	50-219 P	WIESEMANN,R.A.	8804220191*	50-601 A	WILLIAMS, R.E.	8804120477°	WASTE RES
WEIL, C.H.	9804130164*	50-155 S	WIGGINGTON,D.L.	8804080247	50-382 P	WILLIAMS, R.O.	8803290282	50-267 P
WEISMAN, R.M.	8804110030	50-352 G	WIGGINS,E.	8804060200*	CONTRACT	WILLIAMS, R.O.	8804060281	50-267 F
WEISSMAN,S.	8804140450	FOIA	Wiggins,E.	8804060275*	CONTRACT	WILLIAMS, R.O.	8804060400	50-267 P
WEISSMAN,S.	8804180288	FOIA	Wiggins,E.	8804150079*	CONTRACT	WILLIAMS, R.O.	8804060414*	50-267 P
WENSKE,P.	8804180364	50-482 P	Wiggins,E.	88041501\$1*	CONTRACT	WILLIAMS, R.O.	8804070130	50-267 P
WENSLAWSKI,F.	8804040123	50-312 Q	Wiggins,E.	8804210309*	CONTRACT	WILLIAMS, R.O.	8804070320	50-267 Q
WENSLAWSKI,F.A	8804060501	50-528 Q	Wiggins,E.	8804220129*	CONTRACT	WILLIAMS, R.O.	8804110034	50-267 P
WENSLAWSKI,F.A	8804120318	50-362 O	WIGGINS,E.	8804280451*	CONTRACT	WILLIAMS,R.O.	8804110324	50-267 F
WENSLAWSKI,F.A.	8804120442	50-206 O	WIGGINS,E.	8804280619*	CONTRACT	WILLIAMS,R.O.	8804220182	50-267 P
WENSLAWSKI,F.A.	8804120446*	50-206 O	WIGGINS,E.	8804290072*	CONTRACT	WILLMON,J.	8804150273	WASTE MGT
WENSLAWSKI,F.A.	8804130008	50-397 O	WIGGINS,E.D.	8804220088*	CONTRACT	WILSON,A.E.	8804060474	50-284 R
WENSLAWSKI,F.A.	8804130013	50-344 O	WIGGINS,E.D.	8804280264*	CONTRACT	WILSON,B.A.	8803290312	50-302 Q
WENSLAWSKLF.A. WENSLAWSKLF.A. WENSLAWSKLF.A. WENSLAWSKLF.A. WENSLAWSKLF.A.	8804130014* 8804180131 8804190132* 8804190154 8804190157*	50-344 Q 50-206 Q 50-206 Q 50-528 Q 50-528 Q	WIGGINS,E J. WIGGINS,E J. WIGGINS,E J. WIGGINS,E J.	8804040237* 8804050090* 8804050255* 8804050284* 8804050297*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	WILSON,B.A. WILSON,B.A. WILSON,B.A. WILSON,B.A. WILSON,B.A.	8803290316* 8804060381 8804080253 8804080257* 8804150205	50-302 Q 50-335 Q 50-338 Q 60-338 Q
WENSLAWSKI,F.A.	8804190377	50-326 Q	WIGGINS,E.J.	8804050314*	CONTRACT	WILSON,B.A.	8804150254	50-250 Q
WENSLAWSKI,F.A.	8804200477	50-113 Q	WIGGINS,E.J.	8804050329*	CONTRACT	WILSON,B.A.	8804260202	50-250 Q
WENZINGER,E.C	8803280066	50-247 Q	WIGGINS,E.J.	8804050336*	CONTRACT	WILSON,B.A.	8804260211*	50-250 Q
WENZINGER,E.C	8803290123	50-247 Q	WIGGINS,E.J.	8804050391*	CONTRACT	WILSON,B.A.	8804260228	50-280 O
WENZINGER,E.C.	8804040028	50-286 Q	WIGGINS,E.J.	8804050404	CONTRACT	WILSON,B.A.	8804270051	60-280 Q
WENZINGER,E.C.	8804050174	50-333 Q	WIGGINS,E.J.	8804060428*	CONTRACT	WILSON,B.A.	8804270226	50-302 O
WENZINGER,E.C.	8804070332	50-277 Q	WIGGINS,E.J.	8804060138*	CONTRACT	WILSON,K.R.	8804010169	50-302 P
WENZINGER,E.C.	8804070337	50-352 Q	WIGGINS,E.J.	8804060233*	50-445 A	WILSON,K.R.	8804040103	50-302 S
WENZINGER,E.C.	8804130006	50-354 Q	WIGGINS,E.J.	8804060270*	CONTRACT	WILSON,K.R.	8804120367	50-302 S
WENZINGER,E.C.	8804130040	50-272 Q	WIGGINS,E.J.	8804060335*	CONTRACT	WILSON,K.R.	8804130100	50-302 S
WENZINGER,E.C. WENZINGER,E.C. WENZINGER,E.C. WENZINGER,E.C. WENZINGER,E.C.	8804130052 8804200089 8804200095 8804200206 8804200221	50-247 Q 50-286 Q 50-410 Q 50-333 Q 50-220 Q	WIGGINS,E.J. WIGGINS,E.J. WIGGINS,E.J. WIGGINS,E.J.	8804060407° 8804140507° 8804150074° 8804150083° 8804150094°	CONTRACT CONTRACT CONTRACT 50-320 P CONTRACT	WILSON,K.P. WILSON,K.R. WILSON,K.R. WILSON,K.R. WILSON,K.R.	8804130352 8804150380 8804180236 8804180241 8804200380	50-302 Q 50-302 R 50-302 F 60-302 F 50-302 S
WENZINGER,E.C.	8804250144	50-410 Q	WIGGINS.E.J.	8804150186*	CONTRACT	WILSON,K.R.	8804200382	50-302 S
WESCOTT,R.G.	8804130302'	50-327 Q	WIGGINS.E.J.	8804150196*	CONTRACT	WILSON,K.R.	8804200544	50-302 Q
WESSMAN,R.H.	8803100092	50-244 P	WIGGINS.E.J.	8804150240*	CONTRACT	WILSON,R.F.	8804070003	50-219 P
WESSMAN,R.H.	8804050145'	50-283 P	WIGGINS.E.J.	8804150346*	CONTRACT	WILSON,R.F.	8804070004	50-219 P
WESSMAN,R.H.	8804050152'	50-244 P	WIGGINS.E.J.	8804200310*	CONTRACT	WILSON,R.F.	8804070005*	50-219 P
WESTERMAN,T.F.	6803310101°	50-285 Q	WIGGINS,E J.	8804200401°	CONTRACT	WILSON,R.F.	8804070198	50-219 P
WESTERMAN,T.F.	8804040236°	50-267 Q	WIGGINS,E J.	8804200449°	CONTRACT	WILSON,R.F.	8804130346	50-219 Q
WESTERMAN,T.F.	8804110265	50-267 S	WIGGINS,E J.	8804200469°	CONTRACT	WILSON,R.F.	8804190015	50-219 P
WESTERMAN,T.F.	8804140043	50-267 S	WIGGINS,E J.	8804200475°	CONTRACT	WIMBROW,R.T.	8804060290*	50-259 F
WETTERHAHN,M.J.	8804060044	50-352 G	WIGGINS,E J.	8804200570°	CONTRACT	WINDHAM,S.T.	8804190173*	NUREG
WETTERHAHN,M J.	8804080044	50-352 G	WIGGNS,E.J.	8804220072*	CONTRACT	WINGER,M.A.	8803300320*	60-334 R
WETTERHAHN,M J.	8804180024	50-352 G	WIGGNS,E.J.	8804220121*	CONTRACT	WINGER,M.A.	8804040064*	50-334 R
WETTERHAHN,M J.	8804180024	50-352 G	WIGGNS,E.J.	8804270253*	CONTRACT	WINGER,M.A.	8804190036	50-334 R
WHILTON,R.S.	8804200053	50-443 G	WIGGNS,E.J.	8804280322*	CONTRACT	WINN,J.A.	8804040055	WASTE MGT
WHILTON,R.S.	8804200053	60-443 G	WIGGNS,E.J.	8804280333*	CONTRACT	WINSLOW,T.P.	8804110101	70-1113
WHIPPLE,S. WHIPPLE,S. WHITE,J. WHITE,J.R.	8803300342 8804190054 8803290205 8804060080 8804190330	50-29 R 50-29 R 1&E 1&E 40-8936	WIGGINS.E.J. WIGGINS.E.J. WIGGINS.E.J. WIGGINS.E.J. WIGGINS.E.J.	8804280340* 8804280382* 8804280435* 8804280471* 8804280501*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	WINSLOW, T.P. WINTERS, P.A. WINTERS, R.W. WINTERS, R.W. WISE, R.	8804190275 8804150074* 8804050074* 8804200075* 8804050263*	TOPREP CONTRACT 50-220 Q 50-334 Q 50-458 Q
WHITE,P. WHITE,P. WHITE,S.A. WHITING,A.R. WHITING,A.R.	8804190044 8804190048 8804060378 8804060041* 8604190364*	\$0-311 R \$0-272 R \$0-390 A WASTE MGT WASTE MGT	WIGGINS,E.J. WIGGINS,E.J. WIGGINS,E.J. WIGGINS,E.J.	8804280574° 6804280596° 8804280609° 8804280647° 6804280666°	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	WISE,R. WISEMAN,G.R. WISEMAN,G.R. WISEMAN,G.R. WITHERS,B.D.	8804250336* 8804010062* 8804060319* 8804200497* 8804050361	50-382 Q 50-335 Q 50-324 Q FOIA 50-482 S
WHITT,M.S.	8804200173	50:313 R	WIGGINS,E.J.	8804290103°	CONTRACT	WITHERS,B.D.	8804060077	60-482 Q
WHITTEMORE,J.E.	8804080329*	50:285 V	WIGGINS,E.J.	8804290196°	CONTRACT	WITHERS,B.D.	8804060265	60-482 Q
WHITTEMORE,W.L.	8804190222*	ORG	WIGGINS,E.J.	8804290228°	CONTRACT	WITHERS,B.D.	8804060425	50-482 P

AUTHOR	ACCESSION	SUBJECT	г	AUTHOR	ACCESSION	SUBJEC	т	AUTHOR	ACCESSION	SUBJECT
	NUMBER	CATEGOR	ŧΥ		NUMBER	CATEGO			NUMBER	CATEGORY
WITHERS, B.D. WITHERS, B.D. WITHERS, B.D. WITHERS, B.D. WITHERS, B.D.	8804080225 8804080239 8804120353 8804130042 8804130425	50 482 50 482 50 482 50 482 50 482	S P F Q	WRIGHT,G C WRIGHT,G C WRIGHT,G C WRIGHT,G C WRIGHT,G.C.	8904040133 8804040193 8804040213 8804040215' 8894040233	50-454 50-156 50-457 50-467 50-255	0 V C Q V	ZAHLER,R E. ZAHNLEUTER,R J. ZAHNLEUTER,R J. ZAHNLEUTER,R J. ZAHNLEUTER,R J.	8804200090° 8804060102 8804200048 8804260103 8804290021	40-3453 50-322 G 50-322 G 50-322 G 50-322 G
WITHERS,B.D. WITHERS,B.D. WITHERS,B.D. WITHERS,B.D. WITHERS,B.D.	8804180420 6804200204 8804200268 8804200312 6804200319	50-482 50-482 50-482 50-482 50-482	1 8 1 1	WAIGHT,G C. WAIGHT,G.C WAIGHT,G C WAIGHT,G C WAIGHT,G.C	8804060013 8804060236 8804110054 8804110326 6804200405	50-305 50-266 50-282 50-346 50-461	V 4 V V V V V V V V V V V V V V V V V V	ZAHNLEUTER,R J. ZAHNLEUTER,R J. ZAHULEUTER,R J. ZAPINSKI,S M. ZAPOLSKI,M.	6804290068 8804290161 8804260089 8804190251 8804160301*	50-322 G 50-322 G 50-322 G 50-457 S 50-354 R
WITHERS, B.D. WITHERS, B.D. WITHERS, B.D. WITT, W.A. WITTMAN, R.	8804210331 8804210337 8804270151 8804270262* 8804200072	50-482 50-482 50-482 50-463 50-302	4 400 t	WRIGHT,R J. WRIGHT,R.W WRIGHT,R W. WU,S. YALE,J O.	8804150170 8803290330' 8804060286' 8604080131 8804180165'	50-263 50-425 50-425 NUFIEG FOIA	600	ZECH.G.G. ZECH.G.G. ZECH.G.G. ZECH.G.G. ZECH.G.G.	8604010052 8904110226 8904110261 8804140091 8804140097*	50-259 P 50-327 P 50-259 P 50-327 P 50-327 P
WITTMAN R. WOLD,G J. WOLFE,B. WOLFE,S J. WOLFE,S J	6804200063 6804140166* 8804060396 8804050047 8804050070	50-302 NUREG 50-603 50-443 50-443	F G G	YALE.J.O YALE.J.O YALE.J.O YAMAZAKI,F YANDELL,I. A	8804180205° 8804180238° 6804180264° 8803080511° 8804040261°	FOIA FOIA FOIA 50-219 50-445	e O	ZECH,G G ZECH,L W. ZECH,L W. ZECH,L.W. ZECH,L.W.	8804190122 8803180190 8804050343 6804130016 8804130033	50-327 O COMMISSIO N 50-293 U COMMISSIO N COMMISSIO N
WOLFE,S.J. WOLFE,S.J. WOLFE,S.J. WOLFE,S.J.	8804050116 8804050130 8804110177 8804200035 8804290015	50-352 50-381 50-320 50-320 60-320	6 6 6 6 6	YANDELL, LA YAPCHANYK,DJ. YOCHHEIM,E YORK,J. YORK,J.	8004110137 8804070049 8804060330 8804010025' 8804010115'	50-128 50-245 50-312 60-327 60-438	Q S R Q Q	ZECH,L,W ZECR,L,W ZECH,L,W, ZECH,L,W, ZECH,L,W	6804130062 8804130149 8804130206 6804130222 8804130239*	COMMISSION COMMISSION COMMISSION 50-328 U FO/A
WOLFE,S.J. WOLFE,S.L. WOLKENHAUER,W. WONG,H. WONG,K.S.	8804290027 8804050111 8803300296' 8803310033 8803310234	50-443 50-320 50-397 50-311 PR	G G P O	YOSHIMURA, F. YOSHIMURA, T YOSH: WURA, T. YOUNG, J.E. YOUNG, M.A.	8804040255 8804050108* 8804050394* 8804260140 8804050024	XPORTLIC XPORTLIC XPORTLIC 50-445 50-322	G G	ZECH, L.W. ZECH, L.W. ZECH, L.W. ZECH, L.W. ZECH, L.W.	8804130278 8804130283 8804130356 8804210195 8804130247	60-498 P COMMISSION 50-171 U COMMISSION COMMISSION
WOODARD,J.D. WOODARD,J.D. WOODARD,J.D. WOODARD,J.D. WOODARD,J.D.	8803280145 8804060324 8804080198 8804150032 8804190141	50-364 50-348 60-348 60-364 50-364	s s s s g	YOUNG,M A. YOUNG,M.A. YOUNGBLOOD,B J. YOUNGBLOOD,B.J.	8804059036 8804050037 8804280167 8803090164 8803310121	50-322 50-322 40-2061 WASTE MO WASTE MO		ZELLNER,R.J. ZEMAN,J.S. ZEUGIN,L.B. ZEUGIN,L.B. ZIBULSKY,H.	8804180334 8804060152 6804060061 8804080061 8804200127*	40 8800 FOIA 50-322 G 50-322 G 50-317 Q
WOODARD,J.D. WOODARD,J.D. WOODARD,J.D. WOODARD,J.D. WOODHEAD,C.P.	8804190144 8804200057 8804220212 8804280298 8804110032	50-348 50-348 50-364 50-348 50-320	A F S G	YOUNGBLOOD, BJ. YOUNGBLOOD, BJ. YOUNGBLOOD, BJ. YOUNGBLOOD, BJ. YOUNGBLOOD, BJ	8603310123 8603310126 8803310128 8803310142 8803310146	WASTE MO WASTE MO WASTE MO WASTE MO WASTE MO	3T 3T 3T	ZIEMIANSKI,E J. ZILL, R.D. ZILL, R.D. ZILL, R.D. ZILL, R.D.	8804130196* 8804260205* 8804260215* 8804260222* 8804260226*	50-293 F 50-445 A 50-445 A 50-445 A 50-445 A
WOODLAN,D.R. WOODLAN,D.R. WOODLAN,D.R. WOODLAN,D.R. WOODLAN,D.R.	8803250223 8804050028 8804050027 8804050034 8804050038	50-445 50-445 50-445 50-445 50-445	^ S S S S	YOUNGBLOOD, BJ YOUNGBLOOD, BJ YOUNGBLOOD, BJ YOUNGBLOOD, BJ	8803310149 8803310154 8803310157 8803310160 8803310175	WASTE MO WASTE MO WASTE MO WASTE MO	3 T 3T 3T	ZILL, R.D. ZILL, R.D. ZILL, R.D. ZILL, R.D. ZILL, R.D.	8804260230° 8804260233° 8804260237° 8804260241° 8804260243°	50-445 A 50-445 A 50-445 A 50-445 A 60-445 A
WOODLAN,D.R. WOODLAN,D.R. WOODLAN,D.R. WOODLAN,D.R. WOODLAN,D.R.	8804060186 8804060517 8804110113 8804110325 8804130238	50-445 50-445 50-445 50-445 50-445	S Q A Q A	YOUNGBLOOD, BJ. YOUNGBLOOD, BJ. YOUNGBLOOD, BJ. YOUNGBLOOD, BJ.	8803310178 8803310211 8804080439 8804070156 8804120371	WASTE MO WASTE MO WASTE MO WASTE MO	3T 3T 3T	ZILL,R.O. ZILL,R.D. ZILL,R.D. ZILL,R.O. ZIMMERMAN,R.	6804260247* 6804260250* 8694260253* 8904260254* 6804080249	50-145 A 50-145 A 50-445 A 50-445 A 50-275 O
WOODLAN,D.R. WOODLAN,D.R. WOODRUFF,R.L. WOODS,G.R. WOODWARD,J.D.	8804210092 8804270189 6804190103 8804280511* 8804200371	50-445 50-445 I&E FOIA 50-364	S F S	AONUGBFOOD'B 1 AONUGBFOOD'B 1 AONUGBFOOD'B 1 AONUGBFOOD'B 1	0804120444 0804120474 0804130017 0804130101 0804130216	WASTE MO WASTE MO WASTE MO WASTE MO	3T 3T 3T	ZIMMERMAN,R. ZIMMERMAN,R.P. ZIMMERMAN,R.P. ZIMMERMAN,R.P. ZIMMERMAN,R.P.	8804120368 6804190119 8804200261 8804250039 8804250046	50-312 O 50-397 O 50-312 O 50-344 O 50-344 O
WOODY, C.O. WOODY, C.O. WOODY, C.O. WOOLDRIDGE, R.A. WOOLDRIDGE, R.A.	8803290264' 8803290284' 8804010181' 8804180019 8804180019	50-389 50-389 50-250 50-445 50-445	R R V G	YOUNGBLOOD,B J. YOUNGBLOOD,R. YUHAS,G.P. YUHAS,G.P. YUHAS,G P.	8804140024 8804080267 8804080509° 8804120456° 8804130009°	WASTE MO NUNEG 50-528 50-206 50-397	о 0 0	ZIMMERMAN,R.P. ZLATOS,B. ZUPKO,J.M. ZUPKO,J.M. ZUPKO,J.M.	8804270208 8804110257 880406053 8804190044 6804190648	50-312 Q 50-334 Q 50-311 S 50-311 R 50-272 R
WORTHY,J.E. WRIGHT,G.C. WRIGHT,G.C.	8804070224° 8803290065 8803300025	50-259 50-315 50-315	e Q V	YUHAS,G.P. YUHAS,G.P. ZAHLER,A.E.	8804130015* 8804190160* 8804200080*	50-344 50-528 40-3453	8	ZUPKOJ M. ZUPKOJ M ZUPKOJ M ZUPKOJ M	8804210043 0804210046* 8804260054 8804260081	50-272 S 50-272 S 50-272 S 60-272 S

,			

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example,50-232 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS.

These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
ANATECH Research Corp. ASC Office Furniture ASEA Atom, Inc.	8804060483* 8804180308* 8804040145 8804040154* 8804040163*	50-28 CONTHACT TOPREP TOPREP TOPREP	P	American Electric Power Co., Inc American Nuclear Corp	8604190265 8804080095 88040601641 8804060183 8804080279	40-3392 50-315 40-4492 40-4492 40-4492
Ace-Federal Reporters, Inc. Advanced Nuclear Fuels Corp. (formerly	8804210204 ' 8803300291 '	FOIA 50-397	Р		8804280177 8804280311 8804280391	40-4492 40-4492 40-4492
Exxon Nucloar Co., Inc.)	8803300294 * 8804010143	50-397 70-1257	Р	American Nuclear Society American Society for Quality Control	8803310243 8803140040	PRM WASTE MGT
Agriculture, Dopl. of, Graduate School,	8804260208 8804150186*	TOPREP CONTRACT			8803140046* 8804070114 8804070120*	WASTE MGT WASTE MGT WASTE MGT
Washington, DC Air Forco, Dept. of	8804190179* 8804070098	CONTRACT PRM		American Society of Mechanical Engineers Ameriham Corp	8804040055 8804180246	WASTE MGT 71-9147
Airport Connection, Inc. Alabama Power Co.	8804050404* 8803280145	CONTRACT 50-364	S F	Anaconda Co. (div. of Atlantic Richfield Co.)	8804280174 8804280183*	40-8902 40-8902
	8803300029 8804040093 8804040093	50-348 50-348 50-348	o o	Anaheim, CA Anthony, R.L.	8804250251° 8804290110	50-206 50-352
	8804040178 8804060324	50-348 50-348	P 5	Argonne National Laboratory	8804010116 8804080134 8801300116	NUREG NUREG 50-528
	8804080526 8804070039 8804070039	50-364 50-348 50-348	Ř F F	Arizona Nuclear Power Project (formerly Arizona Public Service Co.)	8803300116 8803300116	50-528
	8804070285 8804070285 8804080085 8804080085 8804080094	50-348 50-348 50-348 50-348 50-348	F F F Q		8803300116 8803300123' 8803300123' 8803300123' 8803300130	50-528 50-528 50-528 50-528 50-528
	8804080094 8804080198 8804110121 8804110121 8804110134	50-348 50-348 50-348 50-348 50-348	0 8 0 F		8803300130 8803300130 8803300133* 8803300133*	50-528 50-528 50-528 50-528 50-528
	6804110147 8804110277 8804110277 8804110277 8804110337 8804130255	50-348 60-348 50-348 50-348 50-348) P ያዩ F		8803310049 8803310049 8803310049 8804010251 8804040062	50-528 50-528 50-528 50-528 50-530
	8804140001 8804140001 8804140006 8804140005 8804140093	50-348 50-348 50-348 50-348 50-348	0 0 0 0 F		8804040128 8804040128 8804040128 6804060158 8604060463	50-528 50-528 50-528 50-528 50-528
	8804140093 8804150032 8804180141 8804180144 8804200043	50-348 50-364 50-364 50-346 50-348	F S R H F		8804060463 8804060463 8804060465 8804060465 8604080465	\$0-528 50-528 50-528 50-528 50-528
	8804200045* 8804200057 8804200057 8804200371 8804220212	50-348 50-348 50-348 50-364 50-364	F F S S		8804060478 8804070002 8804070002 8604070002 8804120437	50-529 50-528 50-528 50-528 50-528
	8804250126 8804270061 8804270061 8804270296 8804270296	50-348 50-348 50-348 50-348 50-348	F F F		8804130036 8804130351 8804130365* 8804130360 8804130360	50-529 50-530 50-530 50-528 50-528
Alfred Univ., Alfred, NY All Chemical Isotope Enrichment, Inc.	8804290298 8804140214' 8804050220 8804110157 8804250242	50-348 PROJ 50-603 60-604 50-603	S M A F		8804130360 8804130363* 8804130363* 8804130363* 8804130368	50-528 50-528 50-528 50-528 50-528
Alliance Moving & Storage, Inc. Allied-Signal Corp.	8804280339 8804280501' 8804190136	50-604 CONTRACT 40-3392	f 285	3	8804130368 8804130368 8804130369*	50-528 50-528 50-528

	8804130369' 8604130369' 8804130372 8604130372	50-528 50-528 50-528 50-528 50-528	P P 0 0 0	Babcock & Wilcox Operating Plants Owners Group	8804270279 8804280146 8804280149* 8804070029	70-824 70-1201 70-1201 TOPREP
	8804130372 8804140108 8804140143 8804150028 8804150028	50-529 50-528 50-530 50-530 50-528	S S P P S	Backus, Meyer & Solomon	8804200052 8804200052 8804200062* 8804200062* 8804280086	50-443 50-443 50-443 50-443 50-443
	8804180445 8804180029 8804190033 8804200301 8804210311 8804210329	50-528 50-529 50-528 50-528 50-528 50-530	\$ \$ \$ \$ \$ \$ \$ \$	Bailoy Controls Co. (subs. of Babcock &	8804290082 8804290082 8804290092* 8804290092* 8804070169*	50-443 50-443 50-443 50-443 50-354
	8804220055 8804220255* 8804220255* 8804260007 8805030139*	50-528 50-528 50-528 50-528 PA	A F F S	Wilcox Co) Baltimore Gas & Electric Co.	8803250284 8803310247 8804010226 8804010226	50-317 50-317 50-317 50-317
Arizona, Stale of Arizona, Univ. of, Tucson, AZ	8804070161 8804200425* 8804280609* 8804280647* 8803290313	50-113 CONTRACT CONTRACT CONTRACT 50-313	Q F		8804010229* 8804010229* 8804010230* 8804040038 8804040038	50-317 50-317 50-317 50-317 50-317
Arkansas Power & Light Co.	8803290318 8803280318 8803290335 8803300352 8803300353	50-313 50-313 50-313 50-313 50-313	F F F		8804050001 8804050271 8804050271 8804060481 8804060481	50-317 50-317 50-317 50-317 50-317
	8803300360 8804060211 6804060228 8804060372 8804060372	50:313 50:368 50:313 50:313 50:313	F \$ 8 J J		8804060492 8804060492 8804060520 8804060520 8804070154	50-317 50-317 50-317 50-317 60-317
	8804070151 8604120418 8804130399 8804200014 8804200027	50-313 50-313 50-368 50-368 50-313	F Q S S S		8804070222 8804070222 8804080168 8804110108 8804110108	50-317 50-317 50-317 50-317 50-317
	8804200085 8804200173 8804200343 8804210054 8804210057*	50-313 50-313 50-313 50-368 60-368	I R Q P P		8804120336 8804120339* 8804130134 8804130134 8804130325	60-317 50-317 60-317 50-317 60-317
	8804210163 8804210168 8804210168 8804210270	50-313 50-313 50-313 50-313 50-313	GOGPP		8804130325 8804180336 8804180338* 8804180338* 8804180343*	50-317 50-317 50-317 50-317 50-317
Arkanses Tech Univ., Russollville, AR Armod Forces Radiobiological Research	8804210273* 8804210461 8804250341 8804200462* 8804010112	50-368 50-368	S R		8804200018 8804200018 8804200021 8804200021 8804200034	50-317 50-317 50-317 50-317 60-317
Institute Army, Dept. of, Army Engineer Waterways	8804010092	NUREG			6804200034 6604200389	50-317 50-318 50-318
Experiment Station Arthur Anderson & Co.	8804280596° 9804130285 8804080136	CONTRACT 60-213 WASTE MG1	1		8804200392 8604220093 8804220184	50-317 50-318
Associated Technologies, Inc. Atlas Corp.	8604200080 8804280115 8604280359 8804280408	40-3453 40-3453 40-3453 40-3453		Basier & Hofmann Bates, A.K. Battelle Human Affaks Research Centers Battelle Memorial Institute, Columbus Laboratories	8803080508 8804120213 8803310272 8804080282	• WASTE MGT
Austin, TX	8804280434 8804280507 8804280507 8804290197 8804120189 8804050158	40-3453 40-3453 40-3453 50-498	P	Battelle Memorial Institute, Pacific	8804150336 8804220068 8804280181 8804280471 8804050180	CONTRACT 50.8 CONTRACT
BWR Owners Group Babcock & Wilcox Co	8804050331 8804050342 8804290166 8804010095	TOPREP TOPREP 5' 50-254 5' 70-27	P	Northwest Laboratones	8804070264 8804080131 8804110039 8804140108	NUREG 50-320
	8804050093 8804050093 8804060273 880407004 880407016	70-135 5° CONTRACT 7 50-13 8 TOPREP	L 1	Battelle New England Marine Research Laboratory Bishop, Cook, Purcell & Reynolds	8804140200 8804140210 8804220210 880411003	0° PROJ 3° 50-443
	880408021 880411005 880412032 880414036 880415004	6 PR 9 50-289 1 70-824 19 TOPREP	P T	Boston Edison Co.	880330014 880330014 880404013 880404020 880407012	6 60-293 0 50-293 6 50-293
	880415017 880418044 880419032 880420023 880420028	7 50-389 9 70-1201 15 70-1201	P		880407018 880408018 880411018 880413008	55 50-293 31 50-293



AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8804130191 8804130194* 8804130196* 8804190065 8804190085*	50-293 50-293 50-293 50-293 50-293	F F S F		8804120450° 8804130046° 8804130293 8804130328 8804130331	50-324 50-324 60-400 50-281 50-324	PFSYS
	8804180101* 8804200145 8804200336 8804210006 8804210008	50-293 50-293 50-293 50-293 50-293	E F G		8604130350 8804130350 8804150139 8804150385 8804150385	50-324 50-324 50-261 50-324 50-324	GGEFF
Bran-Shon, Inc.	8804210299 8804270099 8804280072 8804280088 8804280093*	50-293 50-293 50-293 71-653 71-653	Р Н О		8804180454 8804180454 8804180461* 8804180461* 8804190123	50-324 50-324 50-324 50-324 50-400	ት ተ ተ
Brigham Young Univ., Provo, UT Brookhaven National Laboratory	8804130038 8804050126* 8804050231* 8804080267 8804130302*	50-282 50-389 50-382 NUREG 50-327	Q P Q		8804200098 8804200518 8804210009 8804210033 8804210035	50-324 50-324 60-281 50-261 50-400	00000
Bryan, Lykins, Hejtmanek & Wulz	8804150046* 8804190358* 8804190388 8804280217* 8804280203	50-295 WASTE RES WASTE RES 50-348 50-482	Q P		8804210036* 8804210087 8804210144 8804210218 8804210218	50-400 50-324 50-400 50-324 50-324	00000
Buffalo Materials Research Center Burditt, Bowles, Radzius & Ruberry, Ltd. C-E Operating Plants Owners Group CTI Group, Inc. CTI, Inc. (formerly Alaska Welding	8804120405 8804280167 8804080271 8804140096* 8804050169	71-5971 40-2061 TOPREP NUREG 71-404			8804250217 8804250218 8804250219 8804250219 8804250221	50-261 50-261 50-324 50-324 50-324	
Center) California Institute of Technology, Pasadena, CA California, State of	8804130290 8803310234 8804140460	ACRS PR FOIA			8804260221 8804260222 8604250223 8804250240 8804260001	50-324 50-400 50-400 80-400 80-324	ののらって
California, Univ. of, Berkeley, CA	8804150102° 8804180288 8804270308° 8804080272 8804130428	50-208 FOIA 50-312 NUREG ACRS	P P	Catholic Univ. of America, Washington, D	8804270069 6804270088 9804140187* 8804140218* 8804140224*	50-324 50-324 PROJ PROJ PROJ	FP
California, Univ. of, Irvine, CA California, Univ. of, Los Angeles, CA California, Univ. of, Santa Barbara, CA	8804190379* 8804190302 8804200101* 8804120038* 8804130422	50-328 50-142 50-322 CONTRACT ACRS	Q Ψ	Center for Nuclear Waste Regulatory Analyses	8804140226* 8804180364* 8804220249 8804260401	PROJ WASTE MGT WASTE MGT WASTE MGT	
Campaign Research, Inc. Canada, Govt. of	8804280284* 8804280340* 8804200114 8804140075* 8804140130*	CONTRACT CONTRACT 50-322 NUREG NUREG	т	Center for Planning Research, inc. Centerior Energy Central Intelligence Agency Central Research Institute of Electric	8804050314* 8804070124* 8804070215 8804130111* 8804080282	CONTRACT 50-440 50-440 COMMISSIO NUREG	- 72
Canonie, Inc. Carolina Power & Light Co.	8804280321* 8804280331* 8803290251 8803300324 8803310036	40-1162 40-1162 50-328 50-324 60-324	s R Q	Power Industry Carec, Inc. Chem-Nuclear Systems, Inc.	88042900531 8804070084 8804070126 88041303621	XPORTLIC WASTE MGT 27-47 WASTE MGT	
	8803310223 8804010055 8804040040 8804040085 8804050009	50-324 50-400 50-324 50-261 60-324	P S P V P	Chichibu Cement Co., Ltd. Citizens Association for Sound Energy Citizens Concerned About Nuclear Power,	8804060074 8804060076* 8604080049 8804260073 8604010010	WASTE MGT WASTE MGT 50-445 50-445 60-498	100
	8804050021° 8804080054 8804080126 8804080247 8804080277	50-324 50-400 50-400 50-261 50-325	PGSGS	Inc. Cleveland Electric lituminating Co.	8804080333 8804060347 8804080480 8804070208	50-440 50-440 50-440 50-440	0000
	8804080284 8804080286* 8804060446 8804080454 8804080477	50-324 50-324 50-261 50-400 50-400	6 G G G G		8804070209 8804070231* 8804070235 8804070235 8604080115	50-440 50-440 50-440 50-440 50-440	-000F
	8804070089 8804070101 8804070153 8804070174 8804070174	60-261 60-400 60-326 60-261 80-261	P 5 J		8804120420 8804120426* 6804140123 8804190081 8804280068	50-440 50-440 50-440 50-440 50-440	PPSEG
	8804070174 8804070174 8804110041 8804110050 8804120191	60-261 50-261 50-325 60-324 50-400	D000C	Cleveland-Cliffs Iron Co.	8804270166 8804270304 8804080008 8804060176 8804120331	50-346 50-440 40-8714 40-8714 40-8714	H
	8804120287 8804120287 8804120348 8804120348 8804120350*	60-324 60-324 60-324 60-324 60-324	5 5 5 5	Cohen & Dippell, P.C. Colorado State Univ., Fort Collins, CO Colorado, State of	8804280383 8804280552 8804200114 8804200147 8804070046	40-8714 40-8714 50-322 50-322 PRM	Ţ
	8804120350° 8804120434 8804120434 8804120450°	50-324 50-324 50-324 60-324	6 6	Columbis Univ., New York, NY	6604110327° 8804190304 8804280333° 8804200101°	50-267 STATE PRO CONTRACT 50-322	G T

CORPORATE SOURCE INDEX

ZUU

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Combust on Engineering, Inc.	8804200310* 8804290228* 8804010257* 8804010257* 8804010257*	CONTRACT CONTRACT 50-528 50-528 50-528	P P P		8804140056 8804140056 8804140071 8804140077 8804140127	50-295 Q 50-295 Q 50-456 S 50-456 S 50-374 S
	8804010259' 8804010259' 8804010259' 8604110085 8804110095'	50-528 50-528 50-528 70-36 70-36	P P P		8804140330 8804140330 8804140359 8804140359 8804140447	50-373 H 50-373 R 50-295 R 50-295 R 50-454 F
	8904140263 8804150157 8804190342* 8604200529 8804200542*	70-36 70-1100 70-1100 50-470 60-470	к к		8804150030 8804150084 8804150224 8804150251 8804150251	50-304 S 50-456 P 50-454 S 50-295 R 50-295 R
Commerce, Dept. of, National Bureau of Standards	8804070152 8804190169 8804190217* 8804210037	50-184 WASTE RES ORG WASTE RES	R		8804150406 8804150406 8804190114 8804190114 8804190251	50-237 R 50-237 R 50-456 R 50-456 R 50-457 S
Committee on Interagency Rad atten	8804140174*	NUREG			8804190259	50-456 S 50-10 R
Rosearch & Policy Coordination Commonwealth Edison Co.	8804150271° 8803150061 8803180044°	NUREG 50-254 50-254	P P		8804200110° 8804200110° 6604200110° 8804200154	50-10 R 50-10 R 60-457 P
	8803280022 8803280134 8803290248 8803300185 8903300204	50-237 50-457 50-304 50-265 50-265	<i>ភភភភភភ</i>		8804200212 8804200260 8804200387 8804200393 8804200483	50-373 S 50-295 F 50-265 S 50-254 S 50-456 F
	8803300255 8803300255 8803300257* 8803300257* 8803300339	50-237 50-237 50-237 50-237 50-304	6 6 6 6 6		8804210343 8804210343 8804210353 8804220005 8804220012	50-456 F 50-456 F 50-254 P 50-457 P 50-373 K
	8603310262 8804010087* 8804010204 8804010206* 8804010209*	50-458 50-237 50-237 50-237 50-237	բ Բ Ք		8804220013' 8604220035 8804220035 8804220070 8804220070	60-373 K 60-454 F 50-454 F 80-254 R
	8804010238 8804010236 8804010238 6804040092 8504050283	50-10 50-10 50-10 50-295 50-254	R R S S		8804220153 8804220153 8804220154* 8804220154*	50-295 R 50-295 R 50-295 R 50-295 R 50-295 R
	8804050374 8804060292 6804060315 8804060476 6804060497	50-374 50-295 50-237 50-373 50-265	S S O P P		8804220159* 8804220163 8804220165* 8804220165* 8804220185*	50-295 R 50-10 R 50-10 R 50-10 R 50-10 A
	8804060524 8804060524 8804060524 8804060524 8804070035	50-237 50-237 50-237 50-237 50-265	<u>የ</u> የ የ		8804250006 8804250006 8804250064 8804250064 8804250078	50-373 F 50-373 F 50-254 J 50-454 F 50-10 F
	8804070082 8804070326 8804080047 8804080115 8804110084	50-454 50-373 50-374 50-440 50-237	Q R S F P		8804260009 8804270052 8804270158 8804280038 8804280039	50-454 R 50-10 R 50-254 S 50-10 P 50-10 P
	8804110084 8804110086* 9804110086* 8804120020 8804120020	60-237 50-237 60-237 50-295 50-295	P P P C C		8804280039 8804280039 6804280039 8804280039 8804280039	50-10 P 50-10 P 60-10 P 50-10 P 50-10 P
	6804120092 6804120208 8804120216 8804120216 8804120216	50-457 50-456 50-10 50-10 50-10	5 J J		8804280039 8804280039 8804280039 8804280039 8804280039	50-10 P 50-10 P 50-10 P 50-10 P 50-10 P
	8804120307 8804120351 8804130047 8804130138 8804130152	50-304 50-457 60-265 50-454 50-373	P S F F		8804280039 8804280039 8804280069* 8804280069*	
	B804130152 8804140004 8604140023 8804140023 8804140023	50-373 50-254 50-295 50-295 50-295	F Q Q Q		8804280069* 8804280069* 8804280069* 8804280069*	50-10 P 50-10 P
	6804140023 8804140023 8804140023 8804140023 8804140056	50-295 50-295 50-295 50-295 50-295	0000		8804280069* 8804280069* 8804280069* 8804280069* 8804280069	50-10 P 50-10 P 50-10 P
	8804140056 8804140056 8804140056 8804140056	50-295 60-295 50-295 50-295	0	Computer Engineering Associates, Inc.	8804280069 8804290166 9804290297 8804200401	50-254 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
Concept Communications, Inc. Concerned Citizens of Lake, Geauge & Ashtabula Counties, OH Conference of Radiation Control Program Directors, Inc.	8804200504° 8804180113 8804140141°	CONTRACT 50:440 NUREG	G		8904190049* 8004200171 8604220028 8904220049 8804250194*	50 255 50 265 60 265 50 255 50 255	5525
	8804140276* 8804150011* 0804150403* 8804180119* 8804210509*	NUREG NUREG NUREG NUREG NUREG			8804260274 8804260397 8804280058 8804280091 8804260091	50-155 50-255 50-155 50-155 50-155	FKCHH
Connecticut Light & Pawar Co (subs of Normeast Unities) Connecticut Yankeo Atomic Power Co	8804210512* 8804140017* 8803280128	NUREG 50:245 50:213	ı S	Cooper Bessemer Corp. Cornell Univ., Ilhaca, NY Cosmos Broadcasung Corp.	8804280437* 6804200242 8604120249* 8804070117	50-155 QA999 50-97 50-346	0 0 0
	8803290219 8803290221* 8803310043 8803310064 8803310117	50-213 50-213 50-213 50-213 50-213 50-213	R ROOSQ	Covington & Burling Creare, Inc. Dairyland Power Cooperative	8894130115 8804040063 8804190203 8904050336* 8804080104 8804080108*	FOIA 40-2061 40-2061 CONTRACT 50-409	P
	8804010149 8804070291 8804070291 8804070293 8804080058	50-213 50-213 50-213 50-213 50-213	P H H J	Oata Baso, Inc. Defroit Edison Co	8804130370 8804250128 8804250135 8804200449* 8603310147	50-409 50-409 50-409 CONTRACT 50-341	Q F
	8804110315 8804120364 8804120376* 8804120423 8804130058	50-213 50-213 50-213 50-213 50-213	6 5 5 6		8804010090 8804010093* 6804010103* 8804010108*	50:341 50:341 50:341 50:341 50:341	ましたひも
	8804130285 8804180130 8804280539 8804220206 8804220209	50-213 50-213 50-213 50-213 50-213	H P S S		8804050172 8604050185 8804060085 8804060367 8804060516	50-341 50-341 50-341 50-341 50-341	SSKOO
Conner & Wetterhahn	8804250249 8804250249 8804280070 8804270265 8804080044	50-213 50-213 50-213 50-213 50-352	G G		8804070133 8804110154 8804130110 6804140025 8804140887	50-341 50-341 50-341 50-341 50-341	300KK
Consell Research Corp Consell dated Edison Co. of New York, Inc	8804180024 8804280460 880330333 8804050042 8804050051*	50-352 FOIA 50-247 50-3 50-3	G R P P		8804140490 8804140506' 8804150338 8804150405 8804150417	50-341 50-341 50-341 50-341 50-341	はひゃむの
	8804080139 6804110091* 8804110093* 8804110097* 8804110127*	50-247 50-286 50-286 50-286 50-286	Q R R R		8804190008 6804190129 8804180236 8804200139 8804200150	50-341 50-341 50-341 50-341 50-341	തയയാത
	8804110141* 8804110145* 8804110145* 8804120337 8804180028	50-288 50-288 50-286 50-3 50-247	# # # #		8604200375 8804210266 8604210319 8604260026 8804260330*	50-341 50-341 50-341 50-341 50-341	30 JEE
	8804200466 8804200548 8804250138 8804260085 8804260085	50.247 50.247 60.247 50.3 50-3	000PP		8804260048 8804280048 8804270004 8804270191 8804270203	50-341 50-341 50-341 50-341 50-341	5 5 5 5 5 5 5
	8804260090* 8804260090* 8804260093* 8804260093	50·3 50·3 50·3 50·3 50·247	P P P P	Dickstein, Shapiro & Morin Doc-Search Associates	8804210083° 8804210091° 8804050107 8804060310 8804060369	FOIA FOIA FOIA FOIA 50-369	Q
Consumers Pawer Co	8803290278 8803290282 8803300044 8803300050* 8803300051*	50-255 50-267 50-155 50-155 50-155	8 9 9		8604120235 8804120457 8804190064 8804280143 8804280627	FOIA FOIA FOIA FOIA FOIA	
	8804040087 8804050311 8804050348 8804050348 6804070034	50-255 60-256 50-155 50-155 60-255	P A A B S	Don Hendricks & Associates, Inc. Dow Chemical Co.	8804280630 6804190166* 8803300430 8803300435* 6803300438*	FOIA NUREG WASTE MGT WASTE MGT WASTE MGT	
	8804070041 6804070099 8804110010 8804110011' 6804110288	50-255 50-255 50-255 50-255 50-155	8 P P P	Oressor industries, Inc. Drexel Univ., Phi'adolphia, PA Duke Power Co	8804270162 8804060420 8804280144* 8710270269 8803250321	TOPREP 50-413 50-255 50-369 50-269	SQ2O
	8804120478* 8804120478* 8804130024 8804130031 8804130030*	50-29 50-29 50-155 50-255 60-255	> P P P	,	8803290097 8903300087 8803300263 8803300263 8803300287*	50-413 50-270 50-413 50-413 50-413	בטכדם
	8804130049* 8804:30190 8804150398 6804190047	50-255 50-255 50-255 50-255	ь Н ь		8803300257* 8803310070* 8804010036 8804010151	50 413 50-269 50-369 50-370	₽ > E 9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8804010154 8804010235 8804040024 8804040024 8804040024	50-370 50-369 50-269 50-269 50-269	S Q Y Y Y		8804190058* 8804190058* 8804190058* 8804190058* 8804190264	50-369 50-369 50-369 50-369 50-413	6668
	8804040024 8804040025* 8804040025* 8804040025* 8804040025*	50-269 50-269 50-269 60-269 50-269	Y Y Y Y		8804200152 8804200152 8804200152 8804200158 8804200168	50-269 50-269 50-369 50-369 50-413	A A A A A
	8604040029' 8804040029' 8804040029' 8804040029' 8804040049'	50-269 50-269 50-269 50-269 50-269	Y Y Y Y		8804200168 8804200317 8804200323 8804200328 8804200524	50-413 50-414 50-413 50-369 50-413	₽sssQ
	8804040049° 8804040049° 8804040050° 8804040050° 8804040053°	50-269 50-269 50-269 50-269 50-269	Y Y Y Y		8804200536 8804200571 6804200571 8804210282 8804210282	50-270 50-413 50-413 50-369 50-369	+ CCC++
	8804040053° 8804040053° 8804040053° 8804040059° 8804040059°	50-269 50-269 50-269 50-269 50-268	Y Y Y Y		6804210282 8804210282 8804210282 8804210287* 8804210287*	50-369 50-369 50-369 50-369 60-369	00000
	8804040059* 8804040059* 8804040101 8804040101 8804050246	50-269 50-269 50-413 50-413 50-414	Y Y Q Q S		8804210287* 8804210287* 8804210287* 8804250001 8804250001	50-369 50-369 60-369 50-413 50-413	0000
	8804050339 8804050339 8804050388 8804050390 8804060030	50-369 50-369 50-414 50-414 50-413	R R S S		8804250002* 8804250002* 8804250037 8804260002 8804260002	50-413 50-413 50-369 50-413 60-413	PPSOO
	8804060032 8804080409 8804060470 8804070329 8804080145	50-414 50-369 50-267 PR 50-269	s Q Q S		8804260078 8804260078 8804260078 8804260078 8804260082*	50-389 50-369 50-369 50-369 50-369	6 6 6 6
	6804080213 9804310117 8804310117 8804110123 8804110297	60-413 50-413 50-413 50-269 50-413	\$ F F P		8804260099 8804260099 8804260104* 8804260104* 8804260231	50-413 50-413 50-413 50-413 50-269	6 6 6
	8804110297 8804110299 8804110299 8804110298 8804110299	60-413 50-369 50-369 50-369 50-369	P 0000		8804260310 8804260310 8804260381 8804260381 8804270045	50-413 50-413 60-369 <i>60-</i> 369 50-370	PPRRS
	BB04110300* 8804110331 BB04120036 BB04120036 BB04120061	50-413 50-269 50-413 50-413 50-413	PQPPQ		8804270194 8804270194 8804290249 8804290274* 8804290274*	50-369 50-369 50-269 50-269 50-269	F F F
	8804120069 8804120317 6804120317 8804120317 8604120317	60-413 50-269 50-269 50-269 50-269	P P	Duquesne Light Co.	8804290274* 8803280034 8803290304 8803300320* 8804010138	50-269 50-334 50-412 50-334 50-334	F 88 A G
	8804120328 8804130081 8804130081 8804130168 8804130406	50-369 50-369 60-369 50-369 50-369	t		8804040056 8804040064* 8804040221 8804050359 8804050364*	50-334 50-334 50-334 50-334 50-334	E E S E E
	8804130408 8804130408 8804130408 8804130406 8804130410*	60-369 50-369 50-369 50-369 50-369	5555		8804060095 8804070110 8804080060 8804120352 8804130086	50-334 50-412 50-334 50-334 50-334	CE CO CO
	8804130410* 8804130410* 8804130410* 8804130410* 8804150183	50-3 69 50-3 69 50-3 69 50-3 69 50-3 69	D D D D D		8804130091 8804130130 8804130257 8804130257 8804140166	50-412 50-412 50-334 50-334 50-334	SE O O S
	8804 150183 8804 150241 8804 150241 8804 180243 8804 180266	50-369 60-369 50-369 50-369 60-269	Opps		8804190036 8804210044 8804220087 8804260349 8804260374	50-334 50-334 50-334 50-412 50-412	Feer
	8804 180424 9804 180426 9804 18044 1 8804 190056 8804 190056	50-413 50-414 50-413 50-369 50-369	5555P	EG&G Idaho, Inc. (Subs. of EG&G, Inc.)	8804260377° 8805300376° 8710140348° 8801260033° 8804050264	50-412 50-338 50-382 50-395 NUREG	
	6804190056 6804190056 8804190056 8804190056	60-369 50-369 50-369 50-369	Р Р		8804080236 8804280052* 8804280387* 8804280505	NUREG 50-317 50-267 NUREG	
							ı

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
ERC International, Inc. EcoTech, Inc. Edlow International Co. Elgen Engineering, Inc. Elgentric Power Research Institute	8804150059° 8804190402° 8804280265 8804260200° 8804060275°	50-353 70-143 XPORTLIC 50-354 CONTRACT	A P		8804150322* 8804190173* 8804280210 8804280543 8804280632*	NUREG NUREG 40-8907 40-8907 PR
Enecotech, Inc Enercon Services Energy, Dept. of	8804280441 8804220247* 8803240290 8803310113* 8803310268	40-3453 50-250 WASTE MGT WASTE MGT WASTE MGT	Р	Erin Engineering & Research, Inc. Evaluation Research Corp.	8604060280° 8604260205° 8804260210° 8804260215° 8804260219°	50-344 50-445 50-445 50-445 50-445
	8604060058 8804060163 8804060289 8804070037 8804070148	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT			8804260222° 8804260226° 8804260230° 8804260235° 8804260235°	50-445 50-445 50-445 50-445 50-445
	8804070256 8804070262 8804080065 8804080142 8804080157	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT			8804260237* 8804260241* 8804260241* 8804260243*	50-445 50-445 50-446 50-445 50-445
	8804080166 8804080180* 8804080202 8804110003 8804110013	PROJ PROJ WASTE MGT WASTE MGT WASTE MGT			8804260247° 8804260247° 8804260250° 8804260250° 8804260253°	50 445 50 445 50 446 50 445 50 445
	8604110016* 8804110016* 8804110020* 8804110022* 8804110047	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT		Еххол Согр.	8804260254* 8804260254* 8804070095 8804070104* 8804070106*	50-445 50-445 40-8102 40-8102 40-8102
	8804110061 8804110089 8804110139* 8804110233* 8804110259*	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT		FW Energy Applications, Inc. Failure Analysis Associates Fansteel Metals (subs. of Fansteel, Inc.	8604080215 8604290193 8804280481 8804120105* 8804050122	40-8102 40-8064 PROJ 50-327 40-7580
	8804130213 8804130223 8804130237 8804130240 8804130347	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT		Federal Emergency Management Agency	8804070027 8804110028 * 8804260087 8804260087 8804260092 *	60-331 50-331 50-443 50-443 50-443
	8804130353 8804140151 8804140206* 8604150037 8804150282*	WASTE MGT PROJ PROJ PROJ WASTE MGT		Fenix & Scisson, Inc.	8804260092° 8804270113 8804270131 8804150367° 8804190355	50-443 50-440 50-440 WASTE MGT WASTE MGT
	8804150288*	WASTE MOT		Forret Exploration Company of Nebraska, Inc.	8804280042	40.8820
	8804150291 8804150305 8804150345* 8804150371*	WASTE MGT WASTE MGT WASTE MGT WASTE MGT		116.	8804280048 6804280417 8804280469	40-8829 40-8829 40-8943
	8804150415° 8804150418° 8804150419° 8804150426° 8804180002	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT		Florida Power & Light Co.	8804290085* 8803290210 8803290254* 8803290280 8803290284*	40-8943 60-335 50-389 50-389 50-389
	8804 180008 8804 190339 8804 190349 8804 190354 8804 200232	WASTE MGT WASTE MGT WASTE MGT PROJ WASTE MGT			6803290363 8803290363 8603300224 8803300400 8803300400	50-250 50-250 50-389 50-250 50-250
	8804200281* 8804200563 8804210049 8804210093* 8804210193*	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT			8803300400 8803310206 8803310206 8804010049 8804010049	50-250 50-250 50-250 50-250 50-250
	8804210365 8804260122 8804260151 88042601701	WASTE MGT WASTE MGT WASTE MGT WASTE MGT WASTE MGT			8804010181* 8804050150* 8804080010 8804060010 8804070175	50-250 50-389 50-250 50-250 50-250
	8804260214 8804260238 8804260249 8804260256 8804260262 8804260363	WASTE MGT WASTE MGT WASTE MGT WASTE MGT			8804070175 8804070175 8804070175 8804070179 8804070179	50-250 50-250 60-250 50-250 50-250
	8804260363 8804260370 8804280001 8804280131 8804280185 8804280302				8804070278 8804070278 8804080059 8804080112 8804080183	50-250 50-250 60-389 50-389
	8804280464 8804280473 8804280494 6804280568	PROJ WASTE MGT WASTE MGT PROJ			8804110074 8804110074 8804110076 8804110076 8804120267	50-250 50-250 50-250 60-250 60-250
Energy, Dept. of, Idaho Operations Offic Engineers international, Inc. Environmental Protection Agency	8804200002 8804190228 8804200032 8804050414 8804140141	WASTE RES 40-8907			8804120257 8804120272 8804120272 8804120332	50-250 50-250

90 CORPURATE		ACCESSION	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
AUTHOR AFFILIATI	98 18 18	NUMBER 304120345 804120345 804120422 804120422	CATEGORY 50-250 50-250 50-250 50-250	0000		8804140492	FOIA FOIA FOIA FOIA	
	81 8 9 8 8	604120447 804120447 804120459 804130144 804130177	50-250 50-250 50-389 50-250 50-250	R P S S P	GA Technologies, Inc./General Atomic Co.	8804140529 8804140532 8804140535 8804110088 8804110092	FOIA FOIA FOIA 70-734 PR	
	8 8 8	804130315 804130318* 804140297 804140297 8804150190	50-389 50-388 50-335 50-335 50-335 50-335	, F F F	OFFAUD	8804110107 8804190222* 8804270227 8804290051* 8804260150	70-734 QRG 70-734 70-734 50-361	G
	£ 6	3804150190 3804150194 3804150194 3804150270 8804150270 8804180242	50-335 50-335 50-250 50-250 50-250	. ዩ ዩ	Gas Cooled Reactor Associates General Electric Co.	8804080146 8803310018 8803310029* 8804060345 8804080396	PHOJ 50-605 50-605 TOPREP 50-605	K K A
	:	8804180242 8804180135 6804190135 8804190272 8804200005	50.250 50.335 50.335 50.335 50.250	F P ብ ብ		8804060506* 8804070009* 8804080205 8804110052* 8804110101	50-265 50-219 70-754 50-324 70-1113	Q P
		8804200005 8804200199 8804200199 6804200359 8804200359	50 250 50 250 60 250 60 250 50 250 50 250	Я F O O		8804150017* 8804150363 6804190185 8804190275 8804210061	50-458 70-1308 TOPREP TOPREP TOPREP	
		8804200372 8804200372 8804210135 8804210135	50-250 50-250 50-250 50-250 50-250	Я В Р Р		8804210496* 8804220041* 8804270323 8804280381 8804280385*	50-354 50-220 70-1308 XPORTLIC XPORTLIC	K P
		8804220074* 8804220074* 8804220074* 8804220074* B804220108	50-250 50-250 50-250 50-250 50-250 50-250	R R R R	General Public Utilities Corp - GPU Service Corp.	8803080495 8803280079 8803290241 8803300084	60-219 50-289 50-219 50-219	P R S P
		8604220108 8804220111* 8804220245 8804220245 6804250094	50-250 50-250 50-250 50-250 50-250	R P P O O		8803300089* 8803310006 8803310197 8804050059 8804060060	50·219 50·320 50·320 50·289 50·320	P P P G
		8804250094 8804260303 9804270172 8804270172 8804270258	50-250 50-250 50-250 50-250 50-250	\$ P P		8804060089 8804060071* 8804060117 8804060237 8804060460	50-320 50-320 50-320 50-219 50-28 9	Р 9 9
Florida Power Corp. (subs. of Progress Corp.)	Florida	8804270258 8804010169 8804010172 8804010278 8804010279	50-302 50-302 50-302	Р Р І		8804060451' 8804060452' 8804060469 8804070003 8804070004	50-289 50-289 50-219 50-219	F F 1
		680404010279 6804040103 6804040155 8604120367 8804130100 8804130352	50-302 50-302 50-302 50-302	8 F 8 9	·	8604070005 8804070006 8804070011 8804070156 8804070198	50-219 50-219 50-219 50-219	•
		8804150380 8804180236 8804180241 8804200063 8804200074	50-302 50-302 50-302 60-302	A F F F		8804070202 8804080073 8804080073 8804080080 8804080243	50-320 50-320 50-320 60-219	
		880420038 880420038 880420044 880420054 880421000	50-302 50-302 50-302 50-302 4 50-302	8 8 F Q		880411032: 880412027 880412029 880412030 880412030	7 50-289 5* 50-289 2* 50-289 5 60-289	
Florida, Slate of Florida, Univ. of, Gainesville	a, FL	880427032 880429028 880408017 880401003	2 50-302 9 50-302 3 PRM 4 50-83	F S P		880412031 880412031 880412035 880412038 880413025	4 50-289 6 50-289 3 50-289 62 50-219	
ci i a Dispose IND		880405016 880405016 880408019 880428066 880419018	18* 60-83 12 50-63 19 70-1068 152* CONTRAC	P S		880413034 88041400 88041403 88041501 88041800	16 50-219 47 50-269 45 PROJ 18 50-320	
Food & Drug Administration		880414045 880418015 88041404 88042802 88042801	36 NUREG 81 FOIA 78 FOIA 44 50-256	a		88041900 88041901 88041902 88041902 88041902	58 50-289 34 50-219 39 60-219 74 50-219	
Franklin Institute Fund for Peace (National S Archive)	Security	88041404 89041404				88041902 88041902 88041903	96. 20-518	••

KAP PPPP DEGRE PPEPP

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION REMUN	SUBJECT CATEGORY	
	8804200522 8804200551 8804210029 8804210436 8804220084	50-219 50-320 50-320 50-219 50-219	О Р О F R	Georg & State of Government Accountability Project	8604270236 8604270244 8604270244 88050301211 8804060049	50-424 50-321 50-321 PR 50-445	000 G
	8804250162 8604250301 8804250309 8804260165 8804260299	50-219 50-219 50-219 50-219 50-219	Q F Q H P	Government Printing Office Government Technology Services, Inc	8804120384 8804260126* 6604260168 8804060407* 8604280574*	50 498 50-498 FOIA CONTRACT CONTRACT	t t
Genera! Sorvices Administration	8804260299 8804260301* 8804260389 8804130092* 8804130103*	50-219 50-219 50-219 COMMISSIO COMMISSIO	P 8 2 2	Gull Power Co Gull States Utilities Co	6804130402 8803309413 8804040081 8804040212 8804050384	59-458 50-458 50-458 50-458 50-458	80-00
Geo'ogical Society of America Georgia Institute of Technology, Atlanta GA	8804260115 8803280126 8604210309	WASTE RES 50-160 CONTRACT	R		8804070166 8804080194* 8804110304 8804120068	50-458 50-458 50-458 50-458	3000
Georgia Powar Co.	8804270258 8803210067 8803250137 8803250137 8803290340 8803290347	50-160 50-426 50-424 50-424 50-424 50-424	Q F F F F F		8804120098 8804120118 8904150012 8804150014 8804150277 8904200133	50-458 50-458 50-458 50-459 50-458 50-458	ነ ነው ው ር
	8803290347 8803300016 8803300016 8803300018 6803300016	50-424 50-424 50-424 50-424 50-424	ዩ F F F		8804200187 8804200197 8804220137 8804220139 8804220279	50-458 50-458 50-458 50-458 50-458	თთთიი
	8803310019 6803310021* 8803310145 8804010263 8804010263	50-424 50-424 50-425 50-321 50-321	P A J J	H.A.F.A. Intl., Inc Height, Ockson, Brown & Bonesteol Harmon & Weiss	8804250036 6904200091* 8804060152 8804180367 6804180367	50-458 50-346 FOIA 50-443 50-443	96
	8804040037 8804040039* 8804040044 8804040044 8804040085	50-424 60-424 50-321 50-321 50-425	8 8 8 8 6		8804280367 6804260076* 8804260076* 8804260079 880426C091*	50-443 50-443 50-443 50-443 50-443	00000
	8804040072 8804040089 8804040106 8804040242 8804040277	50-321 60-424 50-424 60-366 60-424	S F S R	Havorhili, MA	8804260091* 8804260102 8804260124 8804280017 8804110012	50-443 50-322 60-443 50-443 50-443	99999
	8804080098 8804080098 8804080100' 8804080100' 8804070017	50-424 50-424 50-424 50-424 50-424	К К К Р	Health & Human Services, Dept. of, U.S Public Health Service	8804140188* 8804140204* 8604140351* 8804140353*	NUAEG NUAEG NUAEG NUAEG	
	8804070023 8804070322 8804080012 8804080051 8804080055	50-321 50-424 50-424 50-388 50-424	Q P S S		8804140355* 8804140358* 8804140363* 8604150045* 8804150227*	NUREG NUREG NUREG NUREG NUREG	
	8804110024 8804110024 8804110053 8804110055* 8804130117	60-321 50-321 50-425 50-425 50-424	R A A S	Herilege Reporting Corp. Hill Fastoring Systems	8804210124* 8804210234* 8804210244* 8804250147 8804250161*	FOIA FO:A FOIA PT21 PT21	
	8804130120 8804130276 8804130276 8804190118 8804190118	50-424 50-321 50-321 50-321 50-321	S Q Q R R	Homestake Mining Co Hope College, Hol'and, MI House of Rep.	8804060349 8804280218 8804150082' 8804130280' 8804140223'	40-8903 40-8903 CONTRACT 50-498 60-155	b B
	8804200164 8804200215 8804200540 8804210019 8804210277	60-424 50-424 50-425 60-424 50-424	P P Q P S	House of Rep., Energy & Commerce House of Rep., Government Operations House of Rep., Interior & Insular Alta r	8804220054* 8804130172* 8804130118* 6804130233* 8804280657*	50 327 COMMISSIO COMMISSIO 50-28 50-289	JEZZI
	8804210277 8804210281 8804220023 8804250013 8804260013	60-424 50-425 50-424 50-424 50-424	8 8 F F F	Houston Lightin g & Power Co	8803210478 8803290289 8803300228 8803300254 8803300268	50-498 50-498 50-498 50-498 50-498	LOtol
	8804250041 8804250054 8804250095 8804260281 8804260281	50-366 50-424 60-424 50-424 60-424	P R Q P P		8803300269 8803300274' 8904010068 8804010074 8804040054	50-498 50-498 50-498 50-498 50-498	P P S S O
	8804260293 8804270003 8804270057 8804270175 8804270182*	50-424 50-366 50-366 50-321 50-321	F 8 8		8804060005 8804060473 8804070204 8804070204 8804120254	50-498 50-498 50-498 50-498 50-498	< I TOO
	8804270182° 8804270182° 8804270182° 8804270220°	50-321 50-321 50-321 60-424	 - -		8604120254 6804120259* 6804120259* 8804120264*	50-498 50-498 50-498 50-498	>>>>

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8804120264* 8804120346 6804130034 8804130034 6804130127	50-498 50-498 50-498 50-498 50-498	V S F S		8804010035 8804010035 8804040143 8804110191 6804110193	50-315 50-315 50-315 50-315 50-315	F Q Q S
	8804130136 8804130157 8804130160 8804150356 8804150368	50-498 50-498 50-498 50-498 50-498	OLHSS		8804190250 8804200090 8804210015 8804210015 8804210251	50-316 50-315 50-315 50-315 50-318	S Q Q S
	8804190059 8804190258 8804190262* 8804200201 8804200218	50-498 50-499 50-499 50-498 50-498	A A S S	Indiana Univ. Foundation, Indianapolis, IN Industry Degraded Core Rulemaking Progra	8804220090 8804220090 8804280435* 8804180060*	50-315 50-315 CONTRACT FOIA	S S
	8804210014 8804210154 8804210215 8804210332 8804220001	50-498 50-498 50-498 50-498 50-498	0 0 0 0	Institute of Nuclear Power Operations	8804190069* 8804190077* 8803100052* 8804130137 8804130146*	FOIA FOIA FOIA FOIA FOIA	
	8804250076 8804250076 8804260172 8804260227 8804270006	50-498 50-498 50-498 50-498 50-499	Q P % Q		8804130161° 8804130167° 8804130173° 8804130284° 8804190197°	FOIA FOIA FOIA COMMISSIO FOIA	N
	8804270146 8804270174 8804270243 8804290280 8804290284	50-498 50-498 50-498 50-498 50-499	Q P A		8804190226° 8804190244° 8804190255° 8804190260° 8804190263°	FOIA FOIA FOIA FOIA FOIA	
Hunton & Williams	8804290302 8804050046 8804060061 8804060066 8804060218	50-498 50-322 50-322 50-322 50-322	F G G G	Interior, Dept. of Interior, Dept. of, Bureau of Indian	8804190276° 8804190283° 8804200469° 8804280140° 8804280282	FOIA FOIA CONTRACT 50-483 40-8907	Р
	8804060238 8804110025 8804110027 8604180020 8804260047	50-322 50-322 50-322 50-322 50-322	G G G	Affairs Interior, Dept. of, Geological Survey Interior,Dept.of, Bureau of Reclamation	8804060350 8804150273 8804150365 8804260376	WASTE MGT WASTE MGT 50-274 WASTE MGT	Р
	8804290052 8804290066 8804290077* 8804290086 8804290087	50-322 50-322 50-322 50-322 50-322	G G G	International Research & Technology Corp International Technology Corp.	8804120041 8804190060' 8804190069' 8804190077' 8804010119	70-1359 FOIA FOIA FOIA 60-331	O
Hydrogen Control Owners Group	8804290091 8804290096' 8804290147 8804150166 8804180162	60-322 50-322 50-322 TOPREP TOPREP	G G	lowa, State of	8804060493 6804110098 6804120016 8804120026* 8805030128*	50-331 50-331 50-331 60-331 PR	0 0 P
INTERA Technologies, Inc.	8804190395 8804060300 8804060388 8804140236 8804140539	TOPREP 40-8904 40-8904 40-8904 40-8904		Irving Trust Co. Isham, Lincoln & Beale Isolope Products Laboratories JEBCO Seismic, Inc.	8804070025 8804210155* 8804050346* 8804050096 8804050102*	40-8681 FOIA XPORTLIC 71-652 71-852	
IT Corp. ITASCA Consulting Group, Inc.	8804280536 8804280536 8804280538 8804110006° 8804060504	40-8904 40-8904 40-8904 WASTE MGT WASTE RES		Jacobs Engineering Group, Inc. Japan, Govl. of Johnson & Higgins Insurance	8804050105* 8804050436* 8804110223 8804280418 8803310275	71-652 50-276 WASTE MGT XPORTLIC 50-443	P
idaho National Engineering Laboratory	8804060510° 8804070239 8804260344 8804260348 8710140348°	WASTE RES WASTE RES WASTE RES 50-382	ρ	Justice, Dept. of KLD Associates, Inc. Kalsl Engineering, Inc. Kansas City Power & Light	8804220121° 8804220082 8804220030 8804280619° 8804180439°	CONTRACT 50-322 50-346 CONTRACT 50-482	ř ř
Idaho State Univ., Pocatello, fO Illinois Power Co.	8801260033° 8804080236 8804280052° 8804060474 8803280053	50-395 NUREG 50-317 60-264 50-461	P R S	Kansas City Star/Kansas City Times, Kansas City, MO Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.)	8804180364 8804040063 8804280244	50-482 40-2061 40-2061	b
	8804010271 8804070062 8804070074 8804110253 8604110256	50-461 50-461 50-461 50-461 50-461	6 0 1 0	Kirkpatrick & Lockhart	8804050016 8804050031 8804060102 8804140354 8804180042	50-322 50-322 50-322 50-322 50-322	G G P G
	8804160407 6804190031 8804200160 8804200198 8804260197	50-461 60-461 50-461 50-461 50-461	S R S R S		8804180057 8804180125 8804200047 8804200048 8804200068	50-322 50-322 50-322 50-322 50-322	G G G
Illinois, State of In-Situ, Ino. Indiana Michigan Power Co. (formerly	8804270178 8803310250 8804280503 8804080218 8803300322	60-461 PRM 40-2061 NUREG 60-316	P R		8804260081 8804260103 8804260118 8804260136 8804290021	60-322 60-322 50-322 50-322 50-322	00 T 0 0
Indiana & Michigan Electric Co.)	8803300326 8804010026 8804010026	60-315 60-315 50-315	R F F	Kissimmee Utility Authority	8804290030 8804290068 8804290161 8804010281*	50-322 50-322 50-322 50-302	9 9 1

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Kraftwerk Union Aktengesellschaft LN Technologies Corp. (formerly London Nuclear Svos, Inc.) Labor, Dept. of, Occupational Safety & Health Admin.	6804150036* 8804060021 8804150359*	TOPREP WASTE MGT NUREG		Louisiana, State of Lovelace Biomed & Environmental Research Institute MHB Technical Associates	8804270055 88041401411 8804280444 8804190039	50:382 NUREG NUREG FOIA
Legoulis, Clark, Hill-Whilton & McGuire	8804150369* 8804200030 8804200030 8804200053 8804200053	NUREG 50-443 50-443 50-443 50-443	6	MK-Ferguson Co. MPR Associates, Inc. Madison Gas & Electric Co.	8804200084' 9804290038' 8804130128 8804150083' 8804060162'	50-322 50-322 WASTE MGT 50-320 50-305
Lawrence Livermore National Laboratory	8802040318 8804070157 8804120451 8804150071 8804150330*	WASTE RES WASTE RES WASTE RES WASTE MGT WASTE MGT		Maine Yankee Atomic Power Co.	8803310253 8804010118 6804060178* 8804060256 8804110278	50-309 50-309 50-309 71-9222 50-309
Limitorque Corp.	8804190350 8804280182 8804290075* 8803250320 8804220162*	WASTE MGT WASTE MGT 50-298 50-445 CONTRACT	P S		6804110280° 8804150111 8804150274 8804190336 8804210232	50-309 50-309 50-309 50-309 50-309
Linsley, Kraeger & Associates, Ltd. Long Island Lighting Co.	8803300380 8803300381* 8803300386* 8803300434 8803300439	50-322 50-322 50-322 50-322 50-322	A R P J	Maine, State of Malapal Resources Co.	8804270250 8804130303 8804200192 8804270248* 8804080169	50-309 50-309 50-309 PR 40-8502
	8803310055 8804040136 8804050048 8804060061 8804060066	50-322 50-322 50-322 60-322 50-322	- Р С С		8804060313 8804280035 8804280097 8804280103* 8804280477	40-8502 40-8502 40-8502 40-8502 40-8502
	8804060219 8804060238 8804110025 6804110027 8804180020	50-322 50-322 50-322 60-322 50-322	66666	Marsh & McLennan, Inc.	8803310258 8804040087* 8804040167 8804070065 8804070148	50-250 50-458 50-146 50-289 50-29
	8804190368 8804200082 8804200114 8604200147 6804210209	50-322 60-322 50-322 60-322 60-322	Q T T Q		8804140055 8804190374 8804190382 8804200020 8804200026	50-458 50-313 TOPREP 50-458 50-331
	8604260047 8804260102 8804260248 8804280081 8804290052	50-322 50-322 50-322 50-322 50-322	GGSFG	Martin County Conservation Alliance	8804200211 8804200277 8804200420 8804200568 8804110044	50-146 50-458 50-313 50-219 50-335
	8804290066 8804290077* 8804290086 8804290087	50-322 50-322 60-322 60-322 50-322	999	Maryland, State of Maryland, Univ. of, College Park, MD Massachuselts, Commonwealth of	8802250098* 8804080272 8804180092 8804180092 8804200068	50-171 NUREG 50-443 50-443 60-443
Louisiana Power & Light Co.	8804280091 8804290096* 8804280147 8803280037 8803280085	60-322 50-322 50-362 60-382 60-382	G G S S P		8804200068 8804200106 8804220155 8804260052 8804260052	50-443 50-443 50-293 50-443 50-443
	8803300176 8803300180* 8803300241 8803300242* 8803310009	60-382 50-382 50-382 60-382	, P P P	Materials Engineering Associates, Inc. Mathiech, Inc.	8804260059 8804260083 8804260083 8804280248* 8804050329*	50-443 50-443 50-443 FOIA CONTRACT
	8803310104 8803310171 8803310173* 8803310265 8803310268*	60-382 60-382 50-382 60-382 60-382	P P P	Maxwell, J.C. McGaan-Rohco, Inc. (formerly McGean Chemical Co., Inc.) Memorial Hosp. of Sheridan County.	8804150268* 8804130364 8804180334 8804180156	CONTRACT 50-275 40-8800 FOIA
	8804040057 8804040081* 8804040107 8804040208 8804060302	50-382 50-382 50-382 50-382 50-382	P F Q P	Sheridan, WY (formerly Memorial Hosp. o	8804180165° 8804180205' 8804180223' 8804180238'	FOIA FOIA FOIA FOIA
	8804060305* 8804070127 8804070186* 8804070207 8804070213	60-382 60-382 60-382 50-382 60-382	P F F S	Met Lab, Inc. Metallurg, Inc. (tormerly Shield Alloy Corp.)	8804180264* 8803080025* 8803080283 8804280382	40-7102
	8804110165 8804110166 8804110269 8804110270* 8804130342	50-382 50-382 50-382 50-382 50-382	P P O O P	Mefrotec, Inc Michigan State Univ., East Lansing, MI Micro Analysis & Design Microtorm, Inc.	8804200147 8804050255 8804200583 8804140424 8804250115	FOIA
	8804180224 8804190289 8804190291 8804200373 8804200377	50-382 50-382 50-382 60-382 50-382	Q R F S S S	Middle South Utilities, Inc. Missouri, Univ. of, Rolla, MO Missobishi Infernational Corp. (subs. of	8804190297 8804190337 8804190351 8804050230	50-123 50-123 50-123
	8804200379 6804200363 8804210259 8804250103 6804250109	50-382 50-382 50-382 60-382 60-382	S S I	Mitsubishi Corp.) Mitsui & Co. (USA), Inc. (subs. of Mitsu & Co., Ltd.) Moffet, Larson & Johnson, Inc.	8604040264 8804050196 8804200084	XPORTLIC

s

G P

P P C C P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Morrison-Knudsen Engineers, Inc. NUS Corp	8604070136 8604200475* 8804260159 8804280347 8803160284*	WASTE MGT CONTRACT FOIA FOIA COMMISSIO	Ň	Newbury, MA Nawman & Holtzinger	8604200030 8804200030 8804200053 8804200053 8804050033	50-443 50-443 50-443 50-443 50-445
National Congress of American Indians National Governors' Association National Rights Center Nebraska Public Power District	8804150390° 8804120213 8803290271 8804050328 6804050330°	NUREG 50-327 50-298 50-298 50-298	P F P	remin a notaliga	8804050033 8804050039 8804050039 8804050044 8804050044	50-445 50-445 50-445 50-445 50-445
	8804080233 8804120306 8804120377 8804120387 8804120404*	50-298 50-298 50-298 50-298 50-298	F R Q P		8804050109 8804050109 8804110017 8804110017 8604110023	50-445 50-445 50-445 50-445 50-445
	8804120425 8804120428' 8804130026 8604180328 8804190018'	50-298 50-298 50-298 50-298 50-298	P F O S		8804110023 8804180030 8804200023 8804200038 8804260065	50-445 50-445 50-445 50-445 50-445
	8804200129 8804200256 8804200307' 8804200559 8804250074	50-298 50-298 50-298 50-298 50-298	J 5 7 8 8 8		6804260065 8804260260 8804260260 8804260286 8804290129	50-445 50-445 50-448 50-445 50-445
Nebraska, State of Neutron Products, Inc.	8804250080° 8804260013 8804260017° 8805030170° 6804140295	50-298 50-298 50-298 PR 71-9168	8 P P	Niogara Mohawk Powor Corp	8803290379 8803290401 8803300346 8803310040 8804010002	50-410 50-410 50-220 50-220 50-220
Nevada, State of	8804150128 8803310112' 8804130090 8804140395 8804180067	71-9102 WASTE MGT WASTE MGT WASTE MGT 50-443	G		8804040158 8804040161 8804040199 8804060189 8804060291	50-410 50-220 50-410 50-220 50-220
Pallutian	8804160087 8804260067 6804260076° 8804260076°	50-443 50-443 50-443 50-443	G G G		8804060294* 8804060297* 8804060382 8804070262 8804070309	50-220 50-220 50-220 60-410 50-410
	8804260079 8804260091* 8804260091* 8804260124 8804290017	50-443 50-443 50-443 50-443 50-443	G G G G		8804110194 8804110198* 8804120230 8804130159 8804130166	50-410 50-410 50-220 50-220 50-410
New Jersey, State of New Mexico, State of	8804140058 8804080184 6804290310 8804280567 8804280600	50:354 WASTE MGT 40:8905 40:8911 40:8907	Р		8804130418 8804130421* 8804130424* 8804150075 8804150389	50-220 50-220 50-220 50-220 50-220
New Mexico, Univ. of, Albuquerque, NM New Orteans Public Service Co. New York Power Authority (formerly Power Authority of the State of New York)	8804250185 8804250111 8803300015 8803310287	50-252 50-382 50-333 50-296	R I P		8804180091° 880419003B 8804190067 8804190257 8804200253	50-220 50-410 50-410 50-220 50-220
	8804080109 8804080114 8804110063 8804110149 8804110199*	50-333 50-333 50-286 50-286 50-286	F P R		8804200283 8804200294 8804200303 8804210003 8804210007	50-220 50-410 50-220 50-410 50-220
	8804130384 8804130405 8804130412 8804150054 8804150269	50-333 50-333 50-333 50-333 50-286	F S R F		8804210082 6804220036 6804220059 8804260415 8804270118	50-220 50-220 50-220 50-220 50-410
	8804190161 8804220081 8804220106 8804220107* 6804270271	50-333 50-286 50-333 50-333 50-286	P R P P Q	Nissho lwst American Corp.	8804270167 8804270198 8804040255 8804050108* 8804050394*	50-410 50-220 XPORTLIC XPORTLIC XPORTLIC
New York, State Univ. of Albany, NY New York, State Univ. of, Stony Brook, N New York, State of	8804280258 8804150074* 8804200101* 8804050016 8804050029	71-240 CONTRACT 50-322 50-322 50-322	T G G	Norcom International Corp. (formerly Norlega Communications Corp.) Normandeau Associates, Inc. North Central Michigan College, Petoskey Mt	8804200289° 8804220207° 8804210210°	CONTRACT 50-443 CONTRACT
	6804060102 8804160042 8804160057 8604200046 8804200094	50-322 50-322 50-32 <i>2</i> 50-322 50-322	G G G	North Dakota, State of Northeast Nuclear Energy Co. (subs. of Northeast Utilities)	8805030161° 8803300412 8803310043 8803310043	PR 60-245 50-213 60-213
	8804260043 8804260089 8604260103 8804260118 8804260136	50:322 50:322 50:322 50:322 50:322	7 G T G		8803310207 8804010001 8804040196 8804050005 8804050376	50-245 50-423 50-245 50-245 50-336
; ·	8804290021 8804290030 6804290068 8804290161	50-322 50-322 50-322 50-322	G G G	· · · · · · · · · · · · · · · · · · ·	8804060003 8804060003 8804060055 6804070049	50-245 50-245 50-423 50-245

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8804070116 8804070118 8804070291 8804070291 8804070319	50-420 50-245 50-213 50-213 50-245	S H H Q	•	8604250249 8604250249 8804250249 8804250267 8804250267	50-213 50-213 50-213 50-245 50-245	
	8804080269 8804080269 8804080269 8804110320* 8804120247	50-245 50-245 50-245 50-213 50-423	6 ድ ፡፡ ድ		8804250267 8804260070 8804260285 8804260295 8804270231	50-245 50-213 50-423 50-423 50-213	4 O b o b
	8804120354 8804120423 8804130051 8804130054 8804130060	50-423 50-213 50-423 50-245 50-336	OPERA		8804270231 8804270231 8804270231 8804270282 8804290282	59-213 50-213 50-213 50-245 50-245	6666
	8804130218 8804130332 8804140036 8804140042 8804180173	50-423 50-336 50-245 50-245 71-9015	8 6 6	Northern States Power Co.	6804290282 8603300236 8603300243 8804010219 8804060498	59.245 59.263 50.282 50.263 50.263	00<
	8804190019 8804190041 8804190045* 8804200506 8804200533	50-246 50-423 50-423 50-423 60-245 60-336	8 P P P		8604110174 8804150115 8804150133 8804150328 8804150362	50-263 50-263 50-262 50-263 50-282	OE E > >
	8804210077 8804210159 8804220097 8804220098* 8804260249	50-423 50-423 60-423 50-423 50-213	Р О Р Р		8804150362 8904150374 8804180244 8804180248 8804180262	50-282 50-282 50-263 50-263 50-263	V
	8804250240 8804250249 8804250249 8804250249 8804250267	60-213 50-213 50-213 50-213 50-245	 		8804180252 8804180252 8804180258 8004180258 8904180261	50-263 50-263 50-282 50-282 50-282	++++
	8804250267 8804250267 8804260285 8804260287* 8804260295	50-245 50-245 50-423 50-423 50-423	F F P P S		8604180261 8804200189 8804200554 8804200554 8604210327	50-282 50-263 50-282 50-282 60-202	£5000
	8804270231 8804270231 8804270231	50-213 60-213 50-213	Р Р Р	Northern Wyoming D agnostic flad elegy, Inc., Sheridan, WY	8004210327 8804180200*	\$0.282 FOIA	0
	8804270231 8804270231	50-213 60-213	P P		8804180251* 8804180278*	FOIA FOIA	
Northeast Utilities	8804290282 8804290282 8804290282 8803300412 8803310043	50-245 50-245 50-245 50-245 50-213	6 6 6 6	Nucloar Assurance Corp Nucloar Data, Inc. Nucloar Energy Services, Inc.	8804180293° 6804190402′ 8804070177° 8804040041 8804040043°	FOIA 70-143 50-483 40-7604 40-7604	S
	8803310043 8803310109 8803310207 8804010001 8804050005	60-213 50-336 50-245 50-423 50-245	О Р 8 К	Nuclear Fuet Services, Inc. (subs. of Getty Oil Co.)	8804180403 8804180074* 8804080228 8804080365	71-8193 71-9193 70-143 70-143	
·	8804050376 8804060003 8804060003 8804080055 8804070049	50:336 60:246 60:245 50:423 50:245	Q F S S	Nucloar Metels, Inc Nucloar Packaging, Inc	8804190324 8804280293 8804280508 8804280236 6804150252	70-143 70-143 70-143 XPORTLIC 71-9079	
	8804070116 8804070118 8804070291 8804070319 8804080289	50-423 50-246 50-213 50-245 50-245	S J H Q F	Nuclear Theory & Technologies Nuclear Waste Consultants, Inc.	8804150253* 8804140209 8804140352 8804140417 8804280390	71-9079 FO'A WASTE RES WASTE RES WASTE RES	
	8804080269 8804080269 8804110315 8804120247 8804120364	50-245 50-245 60-213 50-423 50-423	F P O	Nutec, Inc. O'Molveny & Myers OCR Services, Inc. Oak Ridge Associated Univs.	8864010203 8804080381 8804180348* 6804150181 8804180187*	PROJ FOIA CONTRACT 40-7604 70-734	
	8804120423 8804130061 8804130054 8804130060 8604130218	50-213 50-423 50-245 60-336 50-423	P ብ ብ በ	Oak Ridge National Laboratory	8804180456 8804180460* 8804010215 8804010223 8804010275	70-734 70-734 NUREG NUREG NUREG	
	8804130332 8804140014 8804140014 8804140036 6804140042	50-336 60-246 60-246 60-246 50-245	۷ ۱ ۱ ۶ ۶		8804080170 8804080232 8804130335 8804180176 8804200041	NUREG NUREG WASTE RES 70-734 WASTE RES	
	8804180173 8804190019 6804190041 8804200506 8804200533	71-9015 50-246 50-423 80-245 60-338	S P Q P	Ohio Citizens for Responsible Energy Ohio, State of	8804280633 8803080244* 8803310185 8803310238 8804270123*	NUREG 50-440 PRM PR 50-440	P F
	6804200539 8804210077 8804210169 8804220097	50-213 50-423 50-423 50-429	P Q P	Ohsaki Research Institute, Inc. Oliver Springs, TN Omana Public Power District	88030605111 88041101711 8803290112 8803310073	50-219 60-604 50-285 50-286	Ł ¥

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8804010081 8804040003 8804070060 8804070188 8804110208	50-285 50-285 50-285 50-285 50-285	P G Q Q		8804150438* 8804150439* 8804180215 8804190110 8804190110	50-388 50-388 71-9208 50-387 50-387
	8804120356 8804130079 8804130180 8804150414 8804200093	50-285 50-285 50-285 50-285 50-285	P		8804200222 8804210051 8804250032 8804270047 8804270047	50:388 50:387 50:388 50:387 50:387
	8804200142 8804200346 8804200366 8804200428 8804250003	50-285 50-285 50-285 50-285 50-285	A 88 F P	Pennsylvania State Univ., Harrisburg, PA Pennsylvania, Commonwealth of	8804290288 8804290288 8804060443 8804060499* 8804290040	50-387 50-387 50-5 50-5 50-277
	8804250904* 8804250005* 8804250007	50-265 50-265 50-285	P P	Pepper, Hamilton & Sheetz Petrotomics Co. (formerly Getty/Petrotom ics Co.)	8804210020 8804060089	FOIA 40:6659
Orrick, Hernogton & Sutcliffe	8804250012* 8804260150	50-285 50-361	P G	Philadelphia Electric Co.	8804140250 8803280104	40-6659 50-352
Pacific Gas & Electric Co.	8803290362 6803290368 8803290400 8804010284 6804040009	50-133 50-133 50-323 50-323 50-275	R S S R		8603300272 8803310075 8804010144 8804010144 8804040035	50-277 50-352 50-277 50-277 50-277
	8804040009 8804050041 8804050091 8804050091 8804070014	50·275 50·275 50·276 50·275 50·323	R G P P S		8804040068 8804040068 8804040075* 8804040075* 8804040091	50-352 50-352 50-352 50-352 50-277
	8804070019 8804070024 8804070289* 8804120409 8804120409	50-275 50-323 50-276 50-133 50-133	SSP		8804040104 8804040104 8804040108* 8804040108*	50·352 50·352 60·352 50·352 50·352
	8804120409 8804120409 8804190231 8804200337 8804200521	50-133 50-133 50-275 60-276 50-276	P F O		8804060043 8804060044 8804060079* 8804060204 8804060204	50-277 50-352 50-352 50-352 60-352
	8604200521 6804200531 8804210449 8804210449 6804220104	50-275 50-275 50-275 50-275 50-275	9000A		8804060210* 8804060210* 8804060239* 8804060239* 8804070225	50-352 50-352 50-352 50-362 50-353
	8804220276 8804250017 8804250017 8804250018* 8804250018*	50-275 50-275 50-275 50-275 50-275	Ե Ե		8804070271 8804070271 8804070271 8804070271 8804080031	50-277 50-277 50-277 50-277 50-352
	8804250022° 8804250022° 8804260207 8804260216 8804260234°	50-275 50-275 50-275 50-133 50-133	6606		8804080034 8804080056 8804080147 8804080151 8804080162	50-277 50-277 50-352 50-352 50-277
Pailen-Johnson Associates, Inc. Perameter, Inc.	8804060200° 8804050391° 8804140507° 8804200382° 8804200485°	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT		•	8804080220 8804110096 8804120384 8804120384 6804130063	50-352 50-352 50-277 50-277 50-277
Pathfinder Mines Corp.	8804210190° 8804060024 8804060029° 8804060131 8804060145°	CONTRACT 40-6622 40-6622 40-2259 40-2259			8804130970 8804130145 8804130181 8804130361 8804130361	50-352 50-352 50-171 50-277 50-277
Pennsylvania Power & Light Co.	8804060159* 8804060240 8804060276 8803310232 8803310235*	40-2259 40-6622 40-6622 50-388 50-388	P P		8804130366° 8804130366° 8804150055 8804150225 8804150225	50-277 50-277 50-353 50-277 50-277
	8804010147 6804040020 8804040020 8804040096 8804040116	50-388 50-387 50-387 50-387 60-387	P Q Q S I		8804150230 8804150230 8804150230 8804150230 8804150230	50-277 50-277 50-277 50-277 50-277
	8804040217 6804060175 6804060257 8604060269 6804070149	50-387 50-387 50-387 50-388 50-387	S S S H		8804180024 8804190088 8804190088 8804190088 8804190153	50-352 50-171 50-171 50-171 50-352
	8804070149 8804120073 8804140003 8804140003 88041400071	50-388 50-388 50-387 50-387 50-387	10000		8804190387 8804190397* 8804190397* 8804220040 8804250020	50-352 50-277 50-277 50-277 50-277
	8804140007* 8804140008* 8804140008* 8804150431	50-387 50-387 50-387 50-386	0000	Pitisburgh Press Pittsburgh,PA	8804270235 8804280195 8804110257 8804140340	50-277 71-9222 50-334 50-334

				CORPORATE	SOURCE II	IDEN E	•
AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
Plain Dealer, Cleveland, OH Plateau Resources, Ltd. Portland General Electric Co.	8804080130 4 8804040048 5 8804040088	FOIA 40-8698 50-344 50-344 50-344	P P		8804150395 8804200004 8804200004 8804200019* 8804200019*	50-443 50-443 50-443 50-443 50-443	4. E. E. E. E.
	8804050389 8804060272 8804070294 8804070323	50-344 50-344 50-344 50-344 60-344	F F J		8804200100 8804200102 8804200102 6804200308 8804210059	50-443 50-443 50-443 50-443 50-443	90000
	8804110067* 8804110068* 8804120311 8804140109	50-344 50-344 60-344 50-344 60-344	P P R S S		8804210059 8804210089 8804210089 8804210275 8804210275	50-443 50-443 60-443 50-443 50-443	ው ው ው ተ
	8804140169 6804200013 8804200257 8804200384	50-344 50-344 50-344 50-344	S Q S Q F		8804220196 8804270216 8804270216 8804280084 8804280084	50-443 50-443 60-443 50-443 50-443	መመድ ተ
	8804200569 8804210291 8804210294* 8804210296* 8804220140	50-344 60-344 60-344 50-344 50-344	Р Р Р Я		6804290028 8804290047 8604290047 8804290054* 8804290054*	50-443 50-443 50-443 50-443 50-443	00000
	8804220145* 8804220173 8804220177 8804220277 8804270186	50-344 50-344 50-344 50-344	P	Public Service Electric & Gas Co of New Jersey	8804290084 8805030253* 8803300046 8803300210	50-443 50-443 50-272 50-311	GRO O
Potisiown, PA President of U.S. & Executive Offices Public Citizen Litigation Group Public Citizen's Critical Mass Energy	8804060025* 8804150287* 8804080135 8804040031*	CONTRACT NUREG FOIA ORG			8803300215° 8803310022 8803310023° 8804010180 8604010180	60-311 50-272 60-272 50-272 50-272	Q= 000
Project Public Service Co. of Colorado	6804180337 6804210030 6803290283* 8803300063 8803300350	FOIA FOIA 50-267 50-267 50-267	P P Q		8804010184 6804010184 8804010184 6804010184 8804040100	50-272 50-272 50-272 50-272 50-272	0000°
	8803300355* 8803300359 8803300383* 8803300391*	50-267 50-267 50-267 50-267 50-267	0 r 000		8804040100 8804060053 8804060251 8804060446 8804070088	50-272 50-311 50-354 50-354 50-354	P 88 P P
	8803300417* 8804060281 8804060400 8804060414* 8804060418*	50-267 60-267 50-267 60-267 50-267	O F P P		8804070091* 8804070315 8804070315 8804110008	50-354 50-272 50-272 50-272 50-272	BOOOE
	8804070130 8804070320 8804110034 8804110324 8804120288	50-267 50-267 50-267 50-267 50-267	P QPFJ		8804120326 9804140155 8804180109 8804190025 8804190044	50-364 60-354 50-354 50-354 60-311	OS P S
	8804120385 8804120478* 8804130327 8804190273 8804200079	50-267 60-29 60-267 50-267 60-267	J >PR-2		8804190048 8804190301 8804190369 8804190391 8804190393	50-354 • 50-354	F F F F
Public Service Co. of New Hampshire	6804220182 6803310210 8804040202 6804040202 8804050045	60-267 60-443 50-443 50-443 60-443	P H P G		6804190394 8804190396 8604200088 8804200269 8804210043	50-354 50-354 50-354	
	8804050045 8804050052 8804050052 8804050055 8804050058	60-443 60-443 60-443 60-443 50-443	9 990		8804210046 880421004 8804210376 8804210376 8804210396	50-272 60-354 60-354	
	8804050058 8804050089 8804050089 8804050401 8804050401	50-443 50-443 50-443) G F F G		880421039 880421040 880421040 880421041 880421041	1* 50-354 6* 60-364 5* 50-364	
	8604060088 8804070051 8804070051 8804070136 8804070221	50-443 50-443 PR 50-443	9 P F F		880421042 880421042 880421042 880421044 880421044	7* 50-354 9* 50-354	
	6804070221 6804080122 6804080122 680408012 880408012	2 50-443 2 50-443 3 50-443 3 60-443	F F F F		88042104 88042104 88042104 88042104 88042104	35* 50-354 39* 50-354 40* 50-354	
	680414009 680414009 880414009 880414009 880416014	2 50-443 2 50-443 4 50-443 4 60-443	r F F F		88042104 88042104 88042104 88042104	43° 50-354 44° 50-354	
Į							

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8804210448' 8804210447' 8804210450' 8804210456' 8804210458'	50-354 50-354 50-354 50-354 50-354	к к к к		8804060464 8804070053 8804080045 8804080195 8804130288	50-312 50-312 50-312 50-312 50-312	ተ ተ ተ ተ
	860421D462* 8804210466* 8604210468* 8804210469* 6804210475*	50-354 50-354 50-354 50-354 50-354	к к к к	·	6804190068 8804190380 6804200125 8804200141 8804200184	50-312 50-312 50-312 50-312 50-312	80 P O E
	8804210477* 8804210478* 8804210483* 8804210484* 8804210486*	50-354 50-354 50-354 50-354 50-354	к к к к		8804200272* 8804210136 8804210342 8804270136 8804270219*	50:312 50:312 50:312 50:312 50:312	08860
	8804210487° 8804210488° 8804210489° 8804210490° 8604210491°	50-354 50-354 50-354 50-354 50-354	к к к к	San Diego Gas & Electric Co. San Luis Obispo Mothers for Peace	8804270230* 8804270238* 8804250248* 8804260150 8804280019	50:312 50:312 50:206 50:361 50:276	00-40
	9804210492° 8804210493° 8804210494° 8804210495° 8804210499°	50-354 50-354 50-354 50-354 50-354	K K K K	Sandia National Laboratories	8803310204 8804080121 8804080274 8804110006* 8804110142	WASTE RES NUREG NUREG WASTE MGT WASTE RES	
	8804210501° 6804210502° 9504220018 8804260054 8804260061	50-354 50-354 50-354 50-272 50-272	к С С С С С		8804160352* 8804190370 8804200592 8804210058 8804210062	WASTE MGT WASTE RES WASTE RES WASTE RES WASTE RES	
Q&R Clin c, Bismarck, ND Quenytech Associates Quevira Mining Co.	8804260194 8804260263 6804180209* 8804130274 8803080530	50-354 50-354 FOIA ACRS 40-8935	P S	Sargent & Lundy, Inc. Saxton Nuclear Experimental Corp.	8804210208 8804280386 6804280588 8804060523 8804130084	WASTE RES NUREG NUREG TOPHEP 50-146	s
REECO RTS Technology, Inc. Rediation Management Corp. (RMC)	8804280367 8804280389* 8804150355* 6804180401 6803280080*	40-8905 40-8905 WASTE MGT 71-9036 50-289	R	Science & Engineering Associates, Inc. Science Applications International Corp. (formerly Science Applications, Inc.)	8804280509* 8804280511' 8710060577* 8802230016*	FOIA FOIA 50-245 50-331	۶ ا
Regulatory Group, Inc Resource Technical Services, Inc. Rhode Island, State of Rio Algom Mining Corp.	6904290103* 6604290121 8604210335 8604060039 8804140407	CONTRACT FOIA 50-193 40-8084 40-8084	þ		8803040290° 9804050297° 8804050428° 8804150317° 8804190363	50-295 CONTRACT CONTRACT WASTE MGT WASTE MGT	P
:· Riverside, CA	8804280023 8804280207 6804280342 8804280530 8804250254*	40-9084 40-8084 40-8084 40-8084 50-208	1		8804190372 8804210344 8804260361 8804280386 8804280566*	WASTE MGT WASTE MGT WASTE MGT NUREG CONTRACT	
Robert L. Cloud Associates, Inc. Rochester Gas & Electric Corp.	8804200452* 6804060144* 6804120173 6804140044 8804140074	50-445 50-244 50-244 50-244 50-244	A O P S O	Scientech, Inc.	8804290267* 8804290271* 8804050284* 6804150084* 8804220072*	FOIA FOIA CONTRACT CONTRACT CONTRACT	
	8804140147 8804180442 8804200219 8804200573 8804220120	50-244 50-244 50-244 50-244 50-244	S F P R	Seacoast Anti-Pollution League	8804200062* 6804260086 8804260107 8804290082 8804290082	50-443 50-443 50-443 50-443 50-443	00000
Rochester, Univ. of, Rochester, NY Rockwell Engineering Co., Inc. Ropes & Gray	8804150161* 8804060048 8804050045 8804050045 8804050052	CONTRACT OA999 50-443 50-443 50-443	G G	Scattle Univ., Scattle, WA Senate	8804290092* 8804290092* 8804040113 8804010286 8804130409*	50-443 50-443 70-600 50-443 50-440	0
	8804050052 8804200100 8804200102 8604200308 8804200308	50·443 50·443 50·443 50·443 50·443	6 6 6 6	Senate, Commerce, Science & Transportati on Senate, Environment & Public Works Senate, Labor & Human Resources	8804130050* 8804130178* 8804210214* 8804050365*	COMMISSIO COMMISSIO 50-293	
	8804290013 8804290013 8804290028 8804290047	60-443 50-443 50-443 50-443	0000	Sensearth, Inc. Sequoyah Fuels Corp. (subs. of Kerr-McGe Nuclear Corp.)	8803080253* 8804010136 8804060243 8804150366	50-440 70-925 40-8027 40-8027	
Ryder/Jacobs Leasing (formerly Jacobs Leasing) SCM O'Donnell & Associates, Inc. (formerly O'Donard * Associates, Inc.)	8804280084 8804280322* 8804280451* 8804050090*	CONTRACT CONTRACT CONTRACT	G	Shaw, Pittman, Potts & Trowbridge	8804190155 8804190193 8804280190 8804280457 8804060117	40-8027 40-8027 40-8768 40-8027 50-320	
ility District	8804150346* 9803290382 8803290389 8804010234 8804040073	CONTRACT 50:312 50:312 50:312 50:312	8 9 H	Simkins Industries, Ind.	8804180018 8804200055 8804200080* 8804260086 8804200570*	50-320 50-320 40-3463 50-440 CONTRACT	
	8804040148 8804050023 8804050205 8804060330	50-312 50-312 50-312 50-312	Q S P R	Small Busineas: Administrations a common for the common formation of the common formation for the common for the common formation for the common for the common formation f	8804060200° 8804130146° 8804150079° 8804150094°	CONTRACT CONTRACT CONTRACT CONTRACT	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Sonelysis, Inc.	8804280382* 8804280501* 8804040237* 8804150046* 8804150196*	CONTRACT CONTRACT CONTRACT 50:295 CONTRACT	Q.		8604120429 6804150192* 8804150202* 6804150217* 8804150223*	WASTE MGT CONTRACT CONTRACT CONTRACT CONTRACT
South Carolina Electric & Gas Co	8804290145* 8803250131 8803290274 8803290300 8804010059	FOIA 50:395 50:396 50:395 50:395	Q P S	Stanford Univ., Stanford, CA State, Dept. of, Bureau of Oceans & Intl Environ & Scientific Affairs Statistice, Inc.	8804220249 8804130341 8804050413 8804130148*	WASTE MGI ACHS XPORTLIC CONTRACT
	8804010239 8804010242 8804060391 8804060394 8804110286	50-395 50-395 50-395 50-395 50-396	R F P Q	Stephens & Associales Siler, E.H. Structural Integrity Associates	8804060527 8804250191* 8804250193* 8803310039* 8803310044*	WASTE RES 50-219 50-219 50-324 50-324
South Carolina, State of	8804110292 8804180137 8804190133 8804210242 8804190306	50-395 50-395 50-395 50-395 STATE PRO	Q P R P G	Sulfolk County, NY	8804050016 8804050031 8804060102 8804140354 8804180057	50-322 50-322 50-322 50-322 50-322
South Caro'nna, Univ. of, Columbia, SC Southampton, NY	8805030070* 8804010240* 8804050016 8804060102 8804180057	PR 50-395 50-322 50-322 50-322	R G G		8804180125 6804200047 8804200058 8804200070* 8804200084*	50-322 50-322 50-322 50-322 50-322
	8804200048 8804260103 8804260118 8804290021 8804290030	50-322 50-322 50-322 50-322 50-322	G G G G		8804200101* 8804200113* 8804260089 8804260103 8804260118	50-322 50-322 50-322 50-322 50-322
Southern Catifornia Edison Co.	8804290068 8804290161 8803300098 8803300102* 8803300191	50-322 50-322 50-206 50-206 50-206	6 0 0 0 8		8804250136 8804290021 6804290030 8804290068 8804290161	50-322 50-322 50-322 60-322 50-322
	8803300384 8603310226 8803310239 8804010217	50-206 50-206 50-206 50-206	P P P S	Susquehanna Valley Alliance, Lencastor, PA	8804110059 8804110167 8804110189* 8804110190*	50-320 50-320 50-320 50-320
	8804010221 8804040105 8804060001 8804060105 8804060248 8804070310	50-206 50-361 50-361 50-206 50-362 60-208	3 8 8 8 8 8	Swodon, Govt. of Sw.tzerland, Govt. of Systom Enorgy Resources, Inc.	8804060075 8803080508* 8804140121* 8803300376 8803310285	XPORTLIC 50-218 NUREG 50-418 50-416
	8804110104 8804110202 8804120341 8804120360 8804120360	50-206 50-361 50-20 6 50-29 50-29	P P V V		8804040056 8804070076 8804070135 8804070187 8804070275	50-416 50-416 50-416 50-416 50-416
	0804120478* 8804120476* 8804120478* 8604130064* 8804130396	50-20 50-29 60-29 60-362 50-206	,	•	6804070279° 8804080046 6804080046 8804080063 6804080118	50-416 50-416 50-416 50-416 50-416
	8804130396 8804150019 8804200128 8804200137 8804200137	50-206 50-206 50-206 60-361 50-361	ያ የ የ የ		8E04080277 8804130175 8B04150100 8B04150103* 6804150249	50-418 50-418 50-416 50-416 50-416
	8804200216 8804200224 8804200247 8804200267 8804210004	50-361 50-361 50-206 50-361 50-208	88880		6804150249 8604150262 8804150262 8604160062 8804190089	50-416 50-416 50-416 50-416 50-416
	8804210039 0804210187 8804210339 6804210412 8804220190	50-206 50-361 60-208 60-361 50-206	P P Q Q P		88041900907 6804200007 8804200116 9804200564 8804210013	50-416 50-418 50-416 60-416 50-416
	8604220202* 8804220210* 8804250246 8804250263* 8804260180	50-206 50-206 50-206 50-206 50-361	p P I G	Systems Research & Applications Group Systems Support, Inc. TET, Inc.	8804220260 8804250285 8804150240* 8804060254 8804280387*	50-416 50-416 CONTRACT WASTE RES CONTRACT
Sauthern California, Univ. of, Los	8804260407 8804130348	60-206 ACRS	s	TMI Public Health Fund	8804130379 8804130382* 8803250223	50-289 50-289 50-445
Angeles, CA Southern Co. Southwest Research Institute	8804270183° 8803090188	60-321 WASTE MGT	ı	TU Electric (formerly Texas Utilities Generating Co.)	8603250275*	60-445
	8804010199 8804060037 8804060041 8804060346 8804070134	WASTE MGT WASTE MGT			8804050026 8804050028 4804050027 6804050027 8804050033	50-445 50-445 50-445 50-446 50-445
	8804070139 8804080090 8804080261 8804080268	WASTE MOT WASTE MOT WASTE MOT WASTE MOT			8804050033 8804050034 8804050034 8804050038	50-445 50-445 50-445 50-445

CORPORATE OCC.				AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT
AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY			8804210205 8804210239	50-445 50-445
	8804050038 8804050039 6804050039 8804050044 8804050044	50-445 50-445 50-446 50-445 50-445	s G G G		8804210239 8804210249 8804210249 8804210249	50.445 50-445 50-445 50-445
	8804050340 8804050340 6804060081 8804060081	50-445 50-445 50-445 50-445	5 5 5		8804210257 8804250099 8804260065 8804260065	50-445 50-445 50-445 50-445
	8804060097 8804060097 8804060105 8804060105	50-445 50-445 50-445 50-445	s ssss		8804260140 8804260140 8804260193 8804260193 8804260260	50-445 50-445 50-445 50-446 50-445
	8804060186 8804060186 8804060327 8804060327 8804060375	50-445 50-445 50-445 50-445 50-445	S S Q		8804260260 8804260286 8804260286 8804270001 8804270001	60-445 50-445 50-445 50-445 50-445
	8804060375 8804060376	50-445 50-445	g s		8804270002	50-445 50-445
	8604060376 8804060393 8804060393 8804060398	50-445 50-445 50-445 50-445 50-445	s s s Q Q	Tailahassee, FL	8804270002 8804270189 8804290146* 8804010287*	50-445 60-445 50-302
	8804060398 8804060399	50-445		Team, Inc. Teknekron Transportation Systems, Inc.	6804070054 88042 8 0382	PT21 WASTE RES
	8804060399 8804060405 8804060405	50-445 50-445 50-445 50-445	\$ 8 8 5 Q	Teknekron Transporter (formerly CorSTAR Research, Inc.) Teledyne Engineering Services Tennessee Valley Authority	8804080233° 8803290224	50-445 50-327
	8804060494 6804060494 8804060515 8804060517 8804060517	50-445 50-445 50-445 50-445	0 A O O O		8803290339 8803290339 8803290345* 8803290345* 8803310129	50-390 50-390 60-390 50-390 50-259
	8804060525 8804060525 8804070083 8804070083	50-445 50-446 50-445 50-445 50-445	O A A S		8803310129 8803310129 8803310132* 8804010212 8804010212	50-259 50-259 50-259 50-259 50-259
	8804080141 8804110017 8804110017 8804110023	50-445 50-445 50-445	G G G G		8804010212 8804010258 8804010258 8804010260	60-327 60-327 50-259
	8804110023 8804110033 8804110111	5° 5U-445	Ť		8804010280 8804010285	50-260
	8804110113 8804110113 8804110114 880411032	3 50-445 B* 70-2932 5 50-445	8		8804040016 8804040016 8804040076 8804040076	60-327 60-327 60-327
	880411032 880412043 880412043 880413000	5 50-445 5 50-445 3 50-445	0000		880404010 880404011 880404011 880404011 880404011	1 50-259 1 50-259 1 50-259
	880413000 880413011	2 50-445	fi Fi		880404011 880404011	1 50-238
	880413011 880413020 880413020 880413020 88041302	32 50-445 37 50-445 37 60-445	SSSA		880404012 880404012 880404012	24 50-259 24 50-259 29 50-327
	88041302 88041302 88041302 88041800	87 50-445 87 60-445 19 50-445	A Q G A		88040401 88040402 88040402 88040500	72 50-327 72 50-327 04 50-327
	88041802 88042000 88042000 8804200 8804200	023 50-445 023 50-445 044 50-445	G G A Q		68040500 88040500 88040500 88040500 88040500	07 50-327 110 60-328 114 50-327
	8804200 8804200 8804200 8804200	472 50-445 478 50-445 478 50-445 489 50-445	0 0000		88040504 88040504 8804050 8804050 8804050	067 50-259 067 50-259 067 60-259
	8804200 8804200	499 50-445	Ä		8804060 8804060	MB7 50-259
	8804200 8804210 8804210 8804210 8804210	0092 50-445 0092 50-445 0145 50-445	;9999		8804080 8804060 8804060 8804080)241 50-327)241 60-327
	880421 880421 880421 880421	0161 50-446 0161 60-446 0173 50-445 0173 50-445	35 S S S S S		880406 680406 860406 860406	0241 50-327 0241 50-327 0285 50-259 0285 60-269
	880421 880421 880421 890421 880421	0180 50-445 0180 50-445 0188 50-445 0188 50-445	S S S		880406 880406 880406 880406	0290 50-259 0290 50-259
	80042					

*Რ*ᲛᲛᲛᲛ ᲛᲛᲛᲛᲛ ᲛᲛᲛᲛᲛ ᲛᲛᲛᲛᲛᲛ ᲛᲛ<mark>Მ</mark>Მ

AS KKKKP PPPFF FFFFF

				CORPORATE	SOURCE III	DEX OU	•
AUTHOR AFFILIATION	ACCESSION	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
AUTION ALVIEUR	8804060378 50- 8604060383 50- 8804060383 50-	390 390 259 259 259	A A R R		8804210027* 8804210027* 8804210027* 8804210055	50-259 50-259 50-259 50-259 50-438	P P P A O
	8804060383 50 8804060383 50 8804060383 50 4804060390 50	·259 ·259 ·259 ·327 ·327	R R A R		6804210312 8804220020 8804220020 8804220022 8804220022	50-327 50-327 50-327 50-390 50-390	00 O
	8804060417 50 8804060417 50 8804060427 50 8804060427 50	1-327 1-327 1-327 1-327 1-327	P P P S		8804220022 8604220022 8804220032 8804220032 8604220032	50-390 50-390 50-258 50-259	9000
	8804060440 5 8804060440 5 8804060487 5 8804060500 5	0-327 0-327 0-259 0-390 0-390	P P S A		8804220342 8804220250 8804220250 8804220250 8804220250	NUREG 50:259 50:259 50:259 50:259	£ E E
	8804070001 8804070057 8804070057 8804070057	60-259 60-259 60-259 50-259 50-269 50-259	\$ P P P		8804220250 8804220250 8804260032 8604260032 8804260032	50-259 50-259 50-259 50-259 50-259	ь г ь
	8604070057 8804070057 8804070070 8804070112	50-259 60-259 TOPREP 60-390 50-390	Р Р О		8804260039* 8804260039* 8804260095 8804260095	50-259 50-259 50-327 50-327 50-327	P P O O
	8804070199 8804070203* 8804070203* 6804070203* 8804070217*	60-259 60-259 50-259 50-259 60-259	6 6 6		8804260166 8804260168 8804260371 8804260371 8804260385	50-327 50-327 50-327 50-327 60-327	0 K K Q C
	8804070217* 8804070217* 8804070219 8804070224* 8804070224*	60-259 60-259 50-269 60-269 60-269	P P S P		8804260385 8804270007 8804270074 8804270167 8804270164	60-390 60-327 60-327 50-327	O 0 0 0
	8804070224* 8804070234* 8804070254 8804070254	50.259 60.259 60.259 50.259 50.259	P P R R		8804270184 8804270223 8804270223 8804270299 6804270299	50-327)0000 F
	8804070254 8804070312 8804070312 8804110131 8804110206	60-390 50-390 50-259 50-390 50-390	KK000		8804280095 8804280095 9804280226 8804280276 8804280635	60-327 40-1341 40-1341 50-259	F O R
	8804110208 8804110309 8804110309 8804120111 8804120111	60-327 50-327 50-327 50-390 50-390 60-259	s s 0	Texas A&M Univ., College Station, TX Texas Nuclear Corp. (subs. of Ramsey	8804060023 8804060270 8804130233 880420005 680415037	50-128 1 50-322	Q
	8804130246 8804130343 8804130343 8804130374 9804140006 8804140006	50-327 50-327 60-327 60-327 60-327	5 8 F P	Engineering Co.) Texas, State of Texas, Univ. of, Austin, TX	880415038 680419017 880419030 980401002	0 NUMEG 5 STATE PRO 2 60-192	G
	8804140009 8804150022 8804150023 8804150033 8804150042	60:390 60:327 60:328 60:328 60:328	0 8 8 8	Three Mile Island Alert Toledo Edison Co.	880411005 880411015 880411015 880411015 88032903	50 320 98* 50 320 90* 50 320 76 60 346	G G G R J
	8804150279 8804180250 8804180257 9804180140 8804200123	60-327 60-327 60-259 60-269 60-327	F F F A S		88033000 88033003 88040603 88040604 88040604	65 60-346 08 50-346 42 50-346 49 50-348	6 6 6 6
	8804200131 8804200138 8804200484 8804200484 8804210017	60-328 50-327 50-327 60-327	8 5 Q Q Q		88040702 8804110 88041130 8804150 8804150	205 50-346 144 50-346 262 50-346 393 50-346	9,5
	880421001 880421001 880421001 880421001	7 50-259 7 60-259 7 60-259 7 60-259	00000		9804180 6904200 6804200 8804220	450 60-346 069 50-346 0311 50-346 0044 50-346	:
	880421001 880421003 880421002 880421002 880421003	2 60-327 2 50-327 3 50-259 3 60-259	9999		6804221 8904221 8804221 880425 880425	0134* 50-346 0136* 50-346 0086 50-346 0148 50-348	
	880421003 880421003 880421003 88042100 88042100	24 50-327 24 50-327 26 50-259	age		880425 880426 880427 880427	0005 50-346 0252 50-346	

					•	
Transnuclear, Inc.	6804140189 6804140196* 8804150219 8604280332 6804280579	71-4986 71-4986 71-3001 XPORTLIC 70-3051			8803310163 8803310237 8804040070 8804060248 8804060248	50-338 50-338 50-280 50-338 50-338
Transportation, Dopt. of Twomey, Latham & Shea	8804290080 8604150056 8804060102 6804180057 8804200048	XPORTUC 71-3003 50-322 50-322 50-322	G G		8804060250* 8804060250* 8804060268 8804060268 8804060271*	50-338 50-338 50-280 50-280 50-280
	8804260089 8804260103 8804260021 8804290030 8804290068	50-322 50-322 50-322 50-322 50-322	6 6 6 6		8804060271° 8804060433 8604070142 8804070142 8804070142	50-280 50-338 50-260 50-280 50-280
U.S. Ecology, Inc. (formerly Nuclear	8804290161 8804070009	50-322 27-48	Ģ		8804070142	50-280
Engineering, Inc.)	8804180133 880421050B	27-48 27-48			8804070142 8804070252 8804080029 8804080038	50-280 50-338 60-339 50-281
U.S. Energy Corp. UMETCO Minerals Corp. (subs. of Union	8804060304 8803080526	40-1162 40-8681			8804080097	50-338 50-338
Carbide Corp.)	880406014D 8804060172	40-8681 40-8681			8804080097 8804080252 8804080255* 8804120234	50-338 50-339 50-339 50-280
	8804060177 8804080124 8804080280 8604280219 8804280247	40-299 40-299 40-299 40-299 40-209			8804120234 8804120382 8804120382 8804120382 8804130080	50-280 50-280 50-280 50-280 50-338
UNC Engineering Services, Inc	8604280254* 8804280257* 8804280260 8804280262* 8804280229	40-289 40-299 40-299 40-299 FOIA			8804130189 8604130189 8804130264 8804130269 8804130270*	50-338 50-338 50-338 50-260 50-280
UNC Resources, Inc. Uman Electric Go	8804080015 8804040119 8804040121 8804060002 8804060173	40-8907 50-483 50-483 50-483 50-463	P P F I		8804130308 8804140013 8804140013 9804140048 8804140051	50-280 50-338 50-338 50-280 50-281
	8804070069 8804130122 8804140098 8804150408 8804150412	50-483 50-483 50-483 50-483 50-483	J F S O O		8804140428* 8804140428* 8804150004 6804190253 8804180253	59-338 50-338 50-338 50-338 50-338
	8804190100 8804200302 8804200458 8804200507 8804210016	50-483 50-483 50-483 50-483 50-483	A G C F		8804200195 8804200432 8804200438 8804220214 8804220237*	50-338 50-338 50-338 50-338 50-338
Union Pacific Resources (formerly Rocky	8804210028 6804210038* 8804210071 8804270282* 8804280514	50-483 50-483 50-483 50-483 40-8452	ե 6		8804250030 8804250035 8804250089 8804250200 8804260003	50-338 50-338 50-281 50-280 5 <i>0-28</i> 0
Mountain Energy) Union of Concerned Scientists	88040500941	50-312	ρ		8804260003 8804260180	50-280 50-338
United Engineers & Constructors, Inc. (subs. of Raythean Co.)	8804280499	FOIA	,		8804260302° 8804260325	50-338 50-338
United Kingdom, Govt. of United Nuclear Corp. (subs. of UNC	6804080138° 8804120373'	FOIA 70-371		Virginia, Univ. of, Charlottesville, VA	8803080467 8803310227	50- 62 50-62
Resources, Inc.) United States Pharmacopeial Convention,	8804280251 8804280582 8804150337*	40-8907 40-8907 NUREG		Washington Public Power Supply System	8804060357 8804070190* 8803300288 8803300296*	50-62 50-62 50-397 50-397
Inc., The United States Testing Co., Inc.					8803300298*	60-397
Ulah, Univ of, Salt Lake City, UT Utility Power Corp.	8804060113 8804060518* 8804060459 8804150034	71-641 71-641 50-72 TOPREP	н		8803300329 8804070038 8804110038 8804110122	50-397 50-397 50-460 50-397
Vermont Yankee Nuclear Pawer Corp.	8804150036* 8804010159 8804010164 8804040122 8804060107	TOPREP 50-271 50-271 50-271 50-271	0 0 3 8		8804110249 8804120001 6604120052 8804140010 8804140062	50:397 50:397 50:397 50:397 71:9079
	8604070068 8804140477 8804180085 8804200148 8604270232	50-271 50-271 50-271 50-271 50-271	S R O S P		8804150152 8804150313 8804150401 8804200103 8604200228	50-397 50-397 50-397 50-397 50-397
Viking Systems International Virginia Polytechnic Institute & State	8804150079° 8804060335°	CONTRACT CONTRACT			8804210034 8804210079*	60-397 50-397
Univ , Blacksburg, VA Virginia Power (Virginia Electric & Powe	86042901961 8803300328	CONTRACT 50-338	Q	Washington, State of Water, Waste & Land, Inc.	8804260080 8605030151* 8804180006*	50-397 PR WASTE RES
Co}	8603300328 8603300334* 8803 3 10012	50-338 50-338 50-280	0 0 0	West Newbury, MA West Valley Nuclear Services Co., Inc.	8804200073 8804140177* 8804140185* 8804140182*	50-443 PROJ PROJ PROJ

	ACCESSION	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
AUTHOR AFFILIATION	NUMBER 880414D197* 8804140200* 8804140206*	PROJ PROJ PROJ PROJ PROJ			8904070267 8504120080 8804120470 6804130113 8804130307	50-305 50-305 50-305 50-305 50-305	PPPSO
Wester Services, Inc.	8804280136 88042201291	CONTRACT			8804130387	50-305	P
Hostern Massachusetts Electric Co (subs	88041400221	50-245	1		8804140019 6804150143	50-305 50-305 50-305	B
of Northeast Utilities) Western Nuclear, Inc. (subs. of Phelps	8804060149	40-1162			8804250145 8904250275	50-305	å
Oodge Corp)	B804060213	40-1162		Wolf Creek Nuclear Operating Corp	8804050361 8804060077	50-482 50-482	s O O
Shekes Coro	8804060225* 8804280290 8804280544 8801040586*	40-1162 40-1162 40-1162 50-382 50-261	Q P		8804060265 8804060425 8604060430*	50-482 50-462 50-482 50-482	P Q
Wastinghouse Electric Corp	8803100104*	50-201	Α		8804060431 88040801071 8804080225	50-482 50-482	o s
	8803250267* 8803290305* 8803290306* 8803290356	50-395 50-395 50 601	P A A		8804080239 8804120353	50-482 50-482	J P F
	8803290358*	50-601	o		8804130042 8804130425	50-482 50-482 50-482	O
	8803300330* 8804010131 8804010133*	50-338 50-601 50-601	Ä		8804140456 8804180410 8804180420	50-482 50-482	o i
	8804050178* 8804060232	XPORTLIC 71-9218			8804180432*	50-482	l ft
	6804070238	50-601	A		8804200204 8804200268	50-482 50-482 50-482	Q S
	8804070243 8804080243	60-601 PT21	Α		8804200312 8804200319	50 482	J
	8804140262 8804140269	71-651 71-651			8804210331 8804210337	50-482 50-482	P Q Q
	8804190043 8804190051*	50-87 50-87	W		8804270151 8604280108	50-482 71-6450 CONTRACT	Ü
	8504210364* 8804210362* 8804220186	50-202	Q A	Wordpro, Inc.	8804060138* 6804270253*	CONTRACT 50-445	G
	8804220191	50-601	۸ P	Worsham, Forsyllie, Sampe's & Woolridge (lormerly Worsham, Forsyllie & Sampels)	8804180019 8804010195*	CONTRACT	
	8804220235* 8804280009	70-1151 70-1151 70-1151	r	Wyla Laboratorics	8804070182*	60-354 40-8768	Р
	8804280016 8804280206	XPORTUC		Wyoming, State of	68030U0496 8804050424 8804060110	40-8502 40-8502	
	8804290083 8803310272	• MAV2 I F WOT			8804060148 8804069161	40 B76B 40 B714	
Westinghouse Hanford Co Westinghouse Hatman Nuclear, Inc	6804190267 6804190277	• 71-9224 • 71-9224	т		8604280252	40 8684 40 4492	
Weston (Roy F. Weston, Inc.)	8804200147		•	Yankee Atomic Electric Co.	8604290009 8903300168 8603300169	50.29	1
Weston Geophysical Weston Geophysical Corp	8804290072 8804080089 8803300336	WASTE RES		Talikes Moline Datas	8803300217	50-29	ļ
Will.ams & Associatos	8803300340 880412047	WASTE RES			8803300220 8903300226	50-29	
	880412047	WASTE HES			8803300230 8803300342 8803310003	2 50-29	
	880418000 880418000	G. WASTERES	s		880331000	, 60-29	
Wisconsin Electric Power Co.	880330042 880331019		H		680331025 680404014	9 20-55	
	880405008 880412041	5 50-266	P PA		880406010 88 0 406040	50-29 6 50-29	
	880412041 880414008	5 50-266 50-266	រ រ ម		890407006 880412047	ra* 50-29	
	880414008		J		880412047 880413037	76 50-29 50-29	
	88041502 88041502 88042001	78 <u>5</u> 0-266	i P		86041303	78* 50-29	
	88042100 88042100	32 50-266	a		88041400 88041400 88041400	29 50-29	
a tight Co	88040601	57 50-305	1		88041401 88041900	17 50-29	
Wiscons'n Power & Light Co. Wisconsin Public Service Corp	88040401 88040401	10 50-305 66 50-305	Q F		88042002	93 50 29	
	88040601 88040601		i		88042100 88042100	315. 2D.Sa	
i	88040700 8804070		þ	}	88042202	200 3011113	

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example,50-233 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS.

These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUB- JECT CATE- GORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUB- JECT CATE- GORY	OTHER REPORT NUMBER
2 23A5846 R00 23A5862 R01 23A6100AC 4350-3256 85-1 R06	8804140141' 8804060506' 8804220041' 8803310029' 8804060071'	NUREG 50-265 50-220 50-805 50-320	ይ የ የ	NUREG/CR: 4763 NUREG/CR: 4785 NUREG/CR: 4880 R01 NUREG/CR: 4888 NUREG/CR: 4818 V02	8804010215 8804080170 8804010275	NUREG NUREG NUREG NUREG NUREG	SAND86-2280 ORNL-6339 ORNL-71M-10364 ORNL-6377
48815-02 83A2965 87-4 ANF-87-118 ANF-87-119	8804070182° 8804040043° 8804010240° 8803300294° 8803300291°	50-354 40-7604 50-395 50-397 50-397	P 29178 R P P	NUREG/CR-4971 NUREG/CR-4989 NUREG/CR-5018 NUREG/CR-5019 NUREG/CR-5029	8804260505 8804080267 8804010223 8604280633 8804080274	NUREG NUREG NUREG KUREG NUREG	EGG-2516 BNL-NUREG-52101 ORNL/TM-10588 ORNL/TM-10582 SANO87-2384
C115-87-04 CE-1-A R50 CEN-369(V) CEN-370(V) CNWRA 88-001 DRF	6804060280° 8804280069° 6804010259° 6804010267° 8804060041°	50-344 50-10 50-528 60-528 WASTE MGT	P P P	NUREG/CR-5032 NUREG/CR-5041 V02 NUREG/CR-5050 NUREG/CR-5058 NUREG/CR-5065	8804030121 8804010092 8804050264 8804050160 8804010118	NUREG NUREG NUREG 50-313 NUREG	SAND37-2428 EGG-REQ-7827 P PNL-6394 ANL-87-51
EAS. 14-0388 FGG FA-8800 EGG NTA-7356 R01 EGG-NTA-7424 R01 EGG-NTA-7863	8804110052* 8605300376* 8804280387* 8801260033* 8710140348*	60-324 50-338 50-267 50-395 50-382	Q DRF-E21-00094 P TAC 51110 P GL-83-36 P	NUREG/CR-5087 NUREG/CR-5078 V01 NUREG/CR-5107 NUREG/CR-5107 NWD-TR-005 R01 ORAU 68/C-128	8604280444 8804280386 8804090218 8804140269* 8804180187*	NUREG NUREG NUREG 71-851 70-734	LMF-119 SAND87-7176
KLD 1R 180 RO1 KWU UPC-8801-A MORP 88-7 NEDO-31441 NEDO-31462	8804220030 8804160036* 8804140186* 8804150017* 6804070009*	50-346 TOPREP NUREG 50-458 50-219	۴ P	ORAU 88/C-44 ORO-4207-20 PMM-0235 PMPR 88-8 PN1-5948	8804160460° 8804060023 8803300435° 8804080266° 8804140108°	70-734 50-128 WASTE MGT WASTE MGT NUREG	R NRC-02-88-005 UC-23
NEDD-31558 NIS-1-00006 NUREG-0020 V12 NG2 NUREG-0090 V10 NO3 NUREG-0090 V10 NO4	8804050342* 8804150103* 8804080125 8804280308 8804280329	TOPREP 50:416 NUREG NUREG NUREG	o	OR-6106-E93-76-ADD1 APC-80-001 AXE-80-101-NP S.CM200-NDM-0610-0 SAIG-87/3084	8804070169* 8804150287* 8803250275* 8803300215* 8710080577*	50-354 NUREG 50-445 50-311 50-245	A Q F TAC 60188
NUREG-0304 V12 N04 NUREG-0430 V08 N01 NUREG-0540 V10 N02 NUREG-0863 S03 DRFT NUREG-0713 V07	6804080179 6804060112 8804280623 6804280348 6804280390	NUREG NUREG NUREG 50-320 NUREG	Р	SAIC-88/3002 SAIC-88/3121 SAND85-0598 DRFT SECY-76-146 SECY-77-034	8803040290° 8802230016° 6804210006° 8804280649° 8804280645°	60-295 50-331 WASTE MGT PR PR	P TAC 58120 AC12-1 51 AC12-1 50 AC12-1 53
NUREG-0750 V26 I01 NUREG-0750 V26 N06 NUREG-0750 V27 N01 NUREG-0781 S05 NUREG-0837 V07 N04	8804290204 8804110197 8804110195 8804080171 8804280185	NUREG NUREG NUREG 60-498 NUREG	E	SECY-80-324 SECY-86-197 SECY-87-188A SECY-88-010 SECY-88-033	8009190791* 6604280139* 8804160339* 8802170348* 8802190122	PR FOIA PR SECY	AC12-1 28 AC12-1 05
NUREG-0840 V06 N04 NUREG-1231 S01 NUREG-1248 V01 NUREG-1286 S01	8804110204 8804080214 8804080227 8804080230	NUREG NUREG NUREG 50-312	P	SECY-88-043 SECY-88-075 SIR-88-003 R00 SIR-88-010 R00 STD-7-2 2-1-8079	8802170361 0804110248 0803310044* 0803310039* 8803300330*	SECY SECY 50-324 60-324 50-338	Q Q Q SG-88-03-016
NUREG-1305 NUREG-1305 NUREG-1308 NUREG-1310	8804080191 8804080208 8804280527 8804080200 8604080174	NUREG 50-498 50-498 NUREG NUREG	P P	STD-R-02-017 R00 TR 049 R00 UMTRA-DOE/AL R01 UR 87-102 R01 USGS-SIP-3221G-01 R0	8804190277* 8804070011* 8804130223* 8804040163* 8804150273	71-9224 50-219 WASTE MGT TOPREP WASTE MGT	P 0. 00.00 02.022
NUREG/CP-0092 NUREG/CR-2000 VO7 N2 NUREG/CR-3950 VO4 NUREG/CR-4667 VO4 NUREG/CR-4740	8804080282 8804080232 8804080131 8804080134 8804080236	NUREG NUREG NUREG NUREG NUREG	ORNL/NSIC-200 PNL-6210 ANL-87-41 EGG-2487	WCAP-11788 WCAP-8587 R00 WENT 57-87-E WPPS8-EANF-115 WVDP-067 ORFT YAEC-1363	6804210382* 6803290306* 8804250161* 8803300296* 6804080180*	50-282 60-395 PT21 50-397 PROJ 60-29	Q 3G-86-93-022 P EQDP-ESE-68A P
				1 450-1003	30074 10012	~~ ~~	•

asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320P. The docket subject categories are defined in Appendix A.

entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER

ACCEDION	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			NO DEOS!O	MITOMOLII		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
6003130173	8804270040	88/04/13	PA	8803080455	8803080447	68/03/04	50-373 P
8009190791	8804270040	88/04/13	PR	8803080460	8803080447	88/03/04	50-373 P
8101210084	8804270040	88/04/13	PR	8803060494	8803080487	68/03/04	50-224 P
8104020605	8804270040	88/04/13	PA	8803080598	8803080495	88/02/26	50-219 P
8108260077	8804280287	88/04/20	POIA	8803080511	8803080495	68/02/26	50-219 P
8108260083	8804280287	88/04/20	FOIA	8803080522	8803080520	88/03/02	50-280 P
8109180254	8804280287	88/04/20	FOIA	8803108024	8803100022	88/03/04	50-338 P
8305020041	8804270040	88/04/13	PR	8803100052	8804130118	89/04/05	FOIA
8401200070	6804270040	88/64/13	PR	8803100070	8803100061	88/03/04	50-341 P
8405160278	8804130212	88/04/05	FOIA	8803100104	8803100023	88/02/23	50-261 P
8408060365	8804130212	88/04/05	FOIA	8803100147	8803100145	86/03/02	50:327 T
6411130333	8804200473	88/04/14	FOIA	8803140046	8803140040	89/03/01	WASTE MGT
8503190151	8804270040	88/04/13	PR	8803160284	8804130247	86/03/23	COVMISSIO N
8503260124	8804270040	88/04/13	PR	8803160337	8803180322	88/02/19	50:269 V
6507030700	8804080385	88/03/28	FOIA	8803180944	8803150064	88/02/22	50:254 P
8607030703	8804280670	88/04/21	FOIA	6003260161	6903250178	88/03/14	50-250 V
8507100054	8804280670	88/04/21	FOIA	8603250265	6803250263	88/03/18	50-348 Q
8507100084	8804280870	88/04/21	FOIA	6803250266	6803250263	88/03/18	50-348 Q
8507100091	8804280870	88/04/21	FOIA	6803250267	8803250223	88/03/15	50-445 A
6602100002	8804130212	88/04/05	FOIA	8803250275	6803250223	88/03/16	50-445 A
8603120377	8804130212	88/04/05	FOIA	8803250292	8803250291	88/03/18	50-250 O
6663120387	8804130212	88/04/05	FOIA	8803250294	8803250204	88/03/18	50-250 O
8605140252	8804200473	88/04/14	FOIA	8003280088	8803280066	89/03/17	50-247 O
8605300376	8804070268	88/03/31	50:338 P	8803280080	8803280079	88/03/01	50-289 R
6609170458	8804130212	88/04/05	FOIA	8803280132	8803280123	88/03/14	50-413 O
8609180240	8804130212	88/04/05	FOIA	8803280137	8803280135	88/03/11	50-324 O
8509180081	8804190050	88/04/13	FOIA	8803280233	8803280227	68/03/08	70-1201
8701070480	8804270040	88/04/13	PR	8803280237	8803280227	89/03/09	70-1201
8702050186	8804270040	88/04/13	PR	8803280258	8803280266	88/03/10	70-024
6703310385	6804190050	88/04/13	FOIA	6303280068	8803290365	68/03/22	60-315 O
8710060577 8710140348 8710280311 8711030480 8801040586	8804220227 8804210376 8804270040 8804270040 8804110269	88/04/14 88/04/05 88/04/13 88/04/13 88/03/20	50-245 F 60-382 P PR PR 50-382 Q	8603290221 8803290251	8803290123 8803290123 0803290219 8803290280 8803290268	68/03/22 88/03/22 88/03/21 88/03/23 68/03/03	60-247 Q 50-247 Q 50-213 R 50-389 R 50-413 Q
8901260033	8804280105	88/04/10	50-385 P	8803290283	8803290282	88/03/21	50-267 P
6601270301	8801270288	88/01/22	REVIEW GR P	6803290284	8803290280	86/03/23	50-369 R
6801290130	8804280358	88/04/10	FOIA	8803290305	8803290300	88/03/24	50-395 P
8802090430	8804140496	88/04/08	FOIA	8803290306	8803290300	88/03/24	50-305 P
8802090446	8804140496	88/04/08	FOIA	8803290316	8803290312	88/03/11	50-302 Q
8802176349	8804270040	88/04/13	PR	0803290317	8803290314	88/03/09	50-390 O
8802230016	8804140524	88/04/06	60-331 P	8803290320	8803200312	88/03/11	50-302 O
8802250098	8804130356	88/04/07	50-171 U	8803290321	8603280314	88/03/09	50-390 Q
8803040290	8804220242	88/04/06	50-295 P	8803290324	8803280311	88/03/22	50-285 V
6803080018	8803080016	88/01/16	40-8027	8803290325	8803280323	89/03/14	50-250 O
8803080025 8803080094 8803080107 8803080118 6803080131	8803080022 8803080083 8803080083 8803080108 8803080126	87/03/10 88/02/25 88/02/25 88/03/02 86/03/01	71-448 50-280 F 60-280 F 60-324 P 50-370 P	8803290338 8803290343	8603290326 8803280331 8803290331 8803280341 8803280339	88/03/08 88/03/10 88/03/10 88/03/18 88/03/25	50-425 O 50-360 O 60-369 Q 50-237 O 50-390 K
8803080161 6803080168 8803080244 8803080253 8803080265	8803080149 8803080149 8803080233 8803080233 8803080248	88/03/01 88/03/01 88/03/02 88/03/02 88/02/28	60-256 P 50-266 P 60-440 P 60-440 P 50-410 P	8803290355 8803290356 8803290390	8803290349 6803290349 8803290356 8803290366 8803290366	68/03/09 88/03/09 89/03/22 88/03/09 88/03/09	50-327 Q 60-327 Q 50-601 A 60-259 Q 50-259 Q
8803080292	8803080287	88/03/02	60-445 C		6803300001	88/03/03	WASTE MGT
880308030 i.	8803080287	88/03/02	60-446 C		8803300009	88/03/22	50-445 Q
880308031 t	8803080287	88/03/02	60-445 C		8803300016	88/03/16	50-424 F
8803080446	8803080441	88/03/01	60-305 F		8803300044	88/03/22	50-155 P
8803080461	8803080441	88/03/01	60-306 P		8803300044	68/03/22	50-165 P

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGORY
8803300084	8803300061	88/03/10	50.321 Q	8804010064	8804010063	88/03/25	50-418 Q
8803300088	8803300061	88/03/10	50.321 Q	8804010067	8804010063	88/03/25	50-416 Q
8803300073	8803300072	88/03/10	50.413 Q	8804010078	8804010073	88/03/22	50-927 T
8803300075	8803300072	88/03/10	50.413 Q	8804010086	8803290403	88/03/24	50-293 Q
8603300080	8803300079	88/03/10	50.324 Q	8804010087	8803290403	88/03/25	50-237 P
8603300083	8603300079	88/03/10	50-324 Q	8804010093	8804010090	88/03/28	50·341 P
8803300089	6803300084	88/03/22	50-219 P	8804010095	8604010094	88/03/24	70·27
8803300102	8603300098	88/03/25	50-206 Q	8604010100	8804010097	88/03/22	70·1113
8803300109	6803300105	88/03/18	50-456 Q	8804010108	8604010103	88/03/28	50·341 P
8803300113	8603300105	88/03/16	50-456 Q	8604010115	8804010110	88/03/22	50·438 Q
8603300123	8803300116	88/03/18	50-528 P	8804010127	8804010117	86/03/23	50:361 P
8803300126	8803300124	88/03/23	50-482 Q	8804010133	8804010131	88/03/23	50:601 A
8803300127	8803300124	88/03/23	50-482 Q	8804010148	8804060091	86/03/29	50:424 P
6803300129	8803300122	88/03/04	50-395 Q	8804010181	8803250178	88/03/14	50:250 V
8803300133	8803300130	88/03/16	60-528 P	8804010188	8804010183	88/03/28	50:250 O
8803300154	8803300105	68/03/18	50-456 Q	8804010192	8804010187	88/03/25	PROJ
8803300165	8803300025	86/03/24	50-315 V	8804010195	8804010193	88/03/22	CONTRACT
8803300169	8803300168	68/03/25	60-29 P	8804010206	8804010204	88/03/25	50.237 P
8803300180	8803300176	86/03/24	50-392 P	8804010200	8804010204	88/03/25	50.237 P
8803300187	8803300181	68/03/23	50-498 Q	8804010229	8804010226	88/03/25	50.317 R
8803300208	8803300203	88/03/22	50-498 Q	8604010230	8804010226	88/03/25	50-317 R
8803300215	8803300210	88/03/18	50-311 Q	8804010237	8804010232	88/03/28	50-369 P
8803300220	8803300217	88/03/23	50-29 P	8604010240	8804010238	86/03/25	50-385 R
8803300230	8803300226	88/03/25	50-29 P	8804010241	8804010232	88/03/28	50-369 P
8803300242	8803300241	88/03/22	50-382 P	8804010254	8804010249	88/03/14	ORG
8803300257	8803300255	88/03/18	50-237 P	8804010257	8804010251	88/03/02	50-528 P
8803300287	8803300263	88/03/23	50-413 P	8804010259	8804010251	88/03/02	50-528 P
8803300274	8803300268	88/03/18	50-498 P	8804010261	8804010249	88/03/14	ORG
8803300291	8803300288	88/03/07	50-397 P	8804010287	8804010249	88/03/14	ORG
8803300294	8803300288	88/03/07	50-397 P	8804010272	8804010269	88/03/23	50-423 Q
8803300298 8803300298 8803300318 8803300320 8803300330	8803300288 8803300288 8803300310 8804040058 8803300328	86/03/07 89/03/07 88/03/25 68/03/10 88/03/24	50-397 P 50-397 P 40-3392 50-334 R 50-338 Q	8804010274 8804010279 8804010281 8804010287 8804040025	8804010273 8804010278 8804010278 8804010278 88040404024	88/03/28 88/03/30 88/03/30 88/03/30 88/03/31	50-353 Q 50-302 I 50-302 I 50-302 I
8803300334	8803300328	88/03/24	50-338 Q	6804040028	8804040022	88/03/22	ORG
8803300340	8803300378	88/03/24	WASTE RES	6804040029	8804040024	88/03/31	50-268 Y
8803300354	8803300348	88/03/08	50-321 Q	6804040031	8804040022	88/03/22	ORG
8803300355	8603300350	66/03/16	50-267 Q	6604040033	8804040028	88/03/24	50-286 Q
8803300381	8803300380	88/03/28	50-322 R	6804040038	8804040037	88/03/28	50-424 R
8803300383	8803300350	88/03/18	50-267 Q	880 4040042	8804040038	88/03/24	50-272 Q
8603300386	8803300380	88/03/28	50-322 R	880 4040043	8804040041	88/03/30	40-7604
8803300391	8803300350	68/03/10	60-267 Q	880 4040049	8804040024	88/03/31	50-269 Y
8803300411	8803300350	88/03/18	60-267 Q	880 4040050	8804040024	88/03/31	50-269 Y
8803300417	8803300350	68/03/18	50-267 Q	880 4040053	8804040024	88/03/31	50-269 Y
8803300435	8803300430	87/12/22	WASTE MGT	8804040059	8804040024	68/03/31	50-269 Y
8803300438	8803300430	87/12/22	WASTE MGT	8804040061	8804040057	88/03/29	50-382 P
8803310021	8803310019	88/03/23	50-424 P	8804040064	8804040058	88/03/10	50-334 PI
8803310023	8803310022	88/03/25	50-272 Q	6804040075	8804040068	88/03/17	50-352 F
8803310029	8803310018	88/03/29	50-605 K	8804040087	8804040081	88/03/29	60-458 J
8803310039	8803310035	88/03/25	50-324 Q	8604040090	8804040083	88/03/18	50-528 Q
8803310044	8803310035	88/03/25	50-324 Q	6604040108	8804040104	88/03/30	50-352 P
8803310070	8803180322	88/02/19	50-269 V	8804040115	8804040112	88/03/17	70-734
8803310085	8803310063	88/03/29	27-48	6804040118	8804040112	88/03/17	70-734
6803310097	8803310092	88/03/25	50-285 Q	8804040121	8804040118	88/03/25	50-483 P
8803310101	8803310092	88/03/25	50-285 O	8804040125	8804040123	88/03/17	50-312 Q
8803310112	8803310111	88/03/15	WASTE MGT	8804040141	8804040133	88/03/29	50-454 Q
8803310113	8803310111	88/03/15	WASTE MGT	8804040142	8804040139	88/03/25	50-295 Q
8803310120	8803310116	88/03/24	40-6500	8804040151	8803310083	88/03/29	27-48
8803310130	8803310127	88/03/24	50-192 O	8804040154	8804040145	88/03/18	TOPREP
8803310132	8803310129	88/03/25	50-259 P	8804040163	8804040145	88/03/18	TOPREP
8803310134	8803310127	88/03/24	50-192 Q	8804040196	8803310207	88/03/24	50-245 P
8803310144	8803310142	88/01/28	WASTE MGT	9804040215	8804040213	88/03/29	50-457 Q
8803310173	8803310171	88/03/28	50-362 P	8804040216	8804040213	88/03/29	50-457 Q
8803310215	8803310211	88/01/15	WASTE MGT	8804040227	8804040223	88/03/26	50-458 Q
8803310235	8803310232	88/03/24	50-388 P	8804040234	8804040230	88/03/31	50-267 Q
8803310254	8803310253	88/03/24	50-309 P	8804040235	8804040225	88/03/16	50-397 Q
8803310266	8803310265	88/03/25	50-382 P	8804040236	8804040230	68/03/31	60-267 Q
8803310272	8803310268	88/03/24	WASTE MGT	8804040237	8804040229	88/03/28	CONTRACT
8803310280	8803310278	88/03/25	50-289 Q	8804040248	8804040236	66/03/28	50-266 P
6803310285	8803310283	86/03/24	50-369 Q	8804040249	8804040246	68/03/30	60-382 Q
6803310280	8803310183	88/02/08	WASTE MGT	8804040252	8804040246	88/03/30	60-382 Q
8803310281	8803310287	88/03/24	50-259 Q	8804040253	8804040238	68/03/28	50-295 P
6803310292	8803310287	88/03/24	50-259 Q	8804040261	8804040258	88/03/29	60-445 Q
6804010008	8804010007	88/03/24	70-27	8804050021	8804040008	68/03/30	60-324 P
8804010011	8804010009	88/03/28	50-245 P	8804050051	8804050042	88/03/28	50-3 P
8804010013	8804010009	88/03/28	50-245 P	8804050064	8804050061	88/03/31	50-254 O
8804010014	8804010012	68/03/24	50-395 Q	8804050074	8804050068	88/03/30	50-220 O
8804010018	8804010012	88/03/24	50-395 Q	8804050078	8804050072	88/03/31	50-341 O
8804010028	8804010023	88/03/22	50-327 Q	8804050090	8804050078	88/03/24	CONTRACT
8804010029	8804010027	88/03/25	50-305 O	8804050094	8804050083	88/03/29	50-312 P
8804010032	8804010031	88/03/24	50-259 O	8804050096	8804050093	88/03/25	70-135
8604010033	8804010031	88/03/24	50-259 Q	8804050102	8804050096	88/03/22	71-652
8804010047	8804010046	88/03/21	50-260 Q	8804050105	8804050096	88/03/22	71-662
8604010057	8804010052	88/03/23	50-269 P	8804050108	6804050104	88/03/29	XPORTLIC
8804010060	8804010058	88/03/14	50-327 Q	8804050126	8604280122	88/04/12	50-389 P
8804010062	8804010061	88/03/24	50-335 Q	8804050128	8804050123	88/03/28	50-312 P

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	OATE ISSUED	SUBJECT CATEGORY
8804050133 8804050138 8804050142 6804050143 8804050145	8804050127 8894050127 8804050134 8804050140 8804050139	88/03/28 88/03/26 88/04/01 88/03/30 88/03/28	50-254 P 50-254 P OA999 71-651 50-290 P	8804080162 8804060164 8804060168	8804060131 8804060151 8804060183 8804060165 8803310253	88/03/01 88/03/30 88/02/29 88/03/31 88/03/24	40-2259 50-305 40-4492 50-456 0
5604050149 8804050150 8804050152 8804050157 8804050171	8804050139 8804080059 8804050136 8804050163 8804050166	88/03/28 88/04/04 88/03/28 88/03/29 88/03/29	50-283 P 50-389 K 50-244 P 50-333 Q 50-29 Q	8804060184 9804060185 9804060196	8804060174 6804060179 8804060174 8804060191 6604060194	88/03/29 88/03/31 68/03/29 88/03/30 88/03/16	50-333 Q 71-9167 50-333 Q 50-315 Q 40-8064
8804050176 6804050184 8804050189 8804050199 8804050207	8804050170 8804130322 8804050177 8804050195 8804050181	88/03/29 68/03/29 88/03/22 88/03/25 68/03/29	XPORTLIC 50-387 F 50-83 F 50-302 F 50-220 F	B804060212 B804060216	8804060193 8804060204 8804060207 8804060207 8804060213	88/03/29 86/04/05 88/03/31 86/03/31 88/03/01	CONTRACT 50:352 P 50:440 Q 50:440 Q 40:1162
8804050211 8804050224 8804050226 8804050227 8804050231	8804050204 8804050198 8804050218 8804050198 8804180155	86/03/29 88/03/28 88/03/28 88/03/28 88/04/08	50.280 F 60.498 C 50.338 F 50.498 C 50.382 F	8604060239 8804060250 8804060252	8804060224 8804060204 8804060248 8804060248 8804060249	88/03/29 88/04/05 88/03/30 88/03/24 88/03/24	50-445 A 50-352 P 50-338 P 50-327 O 50-327 O
2804050240 6804050254 8804050255 8804050259 8804050263	8804050236 8804050244 8804050252 8804050244 8804050234	86/03/31 88/03/25 88/02/19 8B/03/25 88/03/25	50-336 C 50-338 F CONTRACT 60-338 F 60-458 C	8804060270 8804060271 8804060275	8804060262 8804060259 8604960268 8604060266 8804060274	88/03/28 68/03/29 86/03/30 88/03/29 88/03/25	50-348 O CONTRACT 50-280 P CONTRACT 70-143
8804050276 8804050279 6804050284 8804050294 8804050296	8804050274 8804050274 8804050270 8804050289 8804050289	68/03/28 88/03/28 88/03/25 88/03/25 88/03/25	50-213 F CONTRACT 50-220 F	9 8604060280 9 8804060288 9604060287 9 6804060288 9 8804060290	8804060272 8804060284 8804060282 8804080283 8804060285	88/03/31 88/03/30 88/03/28 88/03/25 88/04/04	50-344 P 50-324 P 50-245 P 50-425 O 50-259 F
6804050297 8804050301 6804050302 6804050309 8804050314	8804050291 8804050299 8804050299 8804050308 8804050307	88/03/26 88/03/29 88/03/29 88/03/29 88/03/25	60-338 I	9804060294 P 8804060297 P 8804060298 P 9804060305 8804060309	8804080291 8804080291 8804080293 8804080302 8804080208	88/03/28 88/03/28 88/03/29 88/03/31 88/03/14	50:220 P 50:220 P 50:425 Q 50:382 P 40:8905
8804050320 8804050322 8804050329 8804050330 8804050334	8604050317 8804050317 8804050312 8804050328 8804050328	88/03/28 88/03/28 88/03/25 86/03/29 88/03/29	50-336 CONTRACT 50-298	P 8604080318 P 8804080323 8804080329 P 8804060331 D 8804060335	8804060317 8804060322 8804060320 6804060316 8604060332	58/03/29 88/04/01 88/03/28 88/03/29 88/03/29	59-324 Q 50-4\$8 Q 50-285 V FOIA CONTRACT
8804050336 8804050342 8804050346 8804050354 8804050358	8804050333 8804050331 8804050349 8804050353 8804050355	88/03/29 88/04/01 88/03/25 88/03/30 88/03/28	CONTRACT TOPREP XPORTLIC 50-324 50-244	6804060355 8904080368 8804080387 D 8804060307 V 8904080404	8894060352 8894060364 8804080364 8804080384 8804060377	88/04/04 88/03/25 88/03/29 88/03/20 88/03/30	70-143 70-143 50-293 O 50-298 Q 50-214 O
8804050364 8804050365 8804050368 8804050371 6804050378	8804050369 8804050343 8804050380 8804050380 8804050373	88/03/21 88/03/29 88/03/30 88/03/30 88/03/28	50-293 (50-424 (P 8804080407 U 9804080414 O 8804080415 O 8604080418 V 8804080430	8804060402 8904060400 6804060411 8804060400 8804060425	88/03/29 88/03/29 88/03/10 88/03/29 88/03/28	CONTRACT 50-267 P 40-8902 50-267 P 50-482 P
8804050381 8804050385 8804050391 8804050394 8804050400	8804050136 6804050377 8804050387 8804050336 8804050397	88/03/28 68/03/31 88/03/25 88/03/29 88/03/31		P 8804060432 O 8604060444 9804060449 8804080451 8804080452	8504080423 8804060438 8804060442 8804089450 8804080450	88/04/01 88/04/01 89/03/30 88/03/28 88/03/28	50-249 Q 50-305 Q 50-346 P 50-289 P 60-289 P
8804050401 8804050404 8804050418 8804050428 8804050433	8804080122 8804050399 8804210418 8804050419 8804050431	88/04/01 88/03/21 89/04/11 88/03/21 88/03/29	CONTRACT	F 8804060453 8804060462 P 8804060483 8804060490 8804060506	8804060442 88040604\$5 8804140117 8804080443 8804080497	88/03/30 88/04/01 88/03/31 88/03/23 88/03/28	60:346 P 60:461 Q 50:29 P 50:5 V 50:265 P
8804050436 8804050018 8804050025 8804060028 8804060029	8804050427 8804080013 8804080018 8804080020 8804080024	88/03/09 86/03/30 88/04/01 88/03/30 88/02/29	50-305 CONTRACT	P 8604060509 V 6804060510 6604060511 Q 8804060519 8804070005	8804080501 8804080504 8804060505 8804060113 8804070003	88/03/22 88/03/29 88/04/01 88/03/22 88/03/30	50-528 O WASTE RES 50-237 O 71-641 50-218 P
8804080031 8804080041 8804060042 8804080084 8804080071	8804060027 8804060037 6804060036 8804060059 8804060069	88/03/30 88/03/28 88/03/30 88/03/30 88/03/29	WASTE MGT 60-298 50-268	O 8804070008 8804070009 V 8804070011 O 8804070035 P 8604070040	8804070003 8804070003 8804070003 8804080497 8804070031	88/03/30 88/03/30 88/03/30 88/03/28 88/03/25	50 219 P 50-219 P 50-219 P 50-205 P 50-498 Q
8804060076 8804060079 8804060089 8804060100 6804060103	8804060074 8804060044 8804080090 8804080098 8804060098	88/03/30 88/03/31 88/03/29 88/03/30 88/03/28		8804070045 G 8804070058 O 8804070060 K 8804070091 V 8804070104	8804070031 8804070055 8804070078 8804070099 8804070095	88/03/26 88/03/07 88/03/31 88/04/04 88/02/16	50-498 O WASTE MGT 71-9103 50-354 P 40-8102
8804060104 8804060116 8804060123 8804060127 8804060135	8804060085 8804060109 8804060118 8804060124 8804060130	88/03/26 88/03/28 88/03/26 88/03/31 88/03/29	60-369	P 8864070108 V 8604070120 Ω 8604070124 P 6804070168 Ω 8604070177	8804070085 8804070114 8804070209 8804070088 8804070171	88/02/16 88/04/07 88/03/29 88/04/04 88/03/28	40-8102 WASTE MGT 60-440 I 50-354 P 50-483 S
8904060136 8804060136 8904060144 8904060145 8804060147	8804060130 8804080134 8804080141 8804080131 8804080142	88/03/29 88/03/29 88/03/28 88/03/01 88/03/29	CONTRACT	Q 8804070182 8804070188 Q 8804070190 8804070203 Q 8804070217	6804070066 6804070127 8803310227 8804070199 8804070199	66/04/04 68/04/04 88/03/25 88/03/28 88/03/28	50-354 P 50-382 F 50-62 P 60-259 P 50-259 P
8804060153 8804060157	8804080151 8804080151	88/03/30 98/03/30	60-305 60-306	8804070224 8804070231	8804070199 8804060347	88/03/28 88/03/31	60-259 P 50-440 Q

ACCESSIO	NUMBER			ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE (SSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
6804070234 6804070243 8804070251 8804070269 6504070279	8804070199 8804070238 8804070249 8804070258 6604070275	88/03/28 88/03/24 88/03/31 88/03/31 68/04/04	50-259 P 50-601 A 50-353 Q 50-338 P 50-416 P	8904110199 8804110211 8804110229	6804110194 8804110063 8804110209 8804110226 8804110223	88/03/31 88/04/05 88/04/04 88/03/31 88/03/30	50:410 P 50:286 FI 50:285 Q 50:327 P WASTE MGT	
8804070289 8804070307 6804060013 8804080022 8934080030	8604050091 8604060020 6804080010 8804050326 8804050027	88/04/01 88/03/30 68/04/04 88/03/29 88/04/04	50:275 P 50:155 Q 50:456 Q 50:272 Q 50:373 Q	8804110236 6804110237 8804110240	8804110230 8804110227 8804110230 8804110227 8804110239	88/04/04 88/04/04 88/04/04 88/04/04 88/03/29	50-295 P 50-324 P 50-295 P 50-324 P 50-305 F	
8804080072 6804080077 8804080080 8804080096 8804080101	8804080069 6804080073 8804080073 8804070298 8804070299	88/04/01 88/04/04 88/04/04 88/04/01 88/04/01	50-170 V \$0-320 P 50-320 P WASTE MGT WASTE MGT	8804110259	8804110253 8804110047 8804180224 8804110266 8804120167	88/03/30 88/03/30 88/03/24 88/04/01 88/03/30	50-461 P WASTE MGT 50-382 Q 50-336 P 50-387 P	
8804080103 8804080107 8804080108 8804080113 8804080123	6804070274 8804140456 8804080104 8804080111 8804080122	88/03/31 88/04/04 88/03/28 88/03/31 68/04/01	WAS1E MGT 50-462 O 50-409 P 50-311 O 50-443 F	8804110300 8804110301	8804110278 8804110274 8804110297 8804110298 8804110310	88/04/05 88/04/05 88/04/05 88/03/08 88/04/04	50-309 Q FOIA 50-413 P 50-338 Q 50-277 Q	
6804080138 8804080160 8904080163 8804080167 8804080169	8804080137 8804080148 8804080112 8804080164 8804080148	88/04/04 88/03/29 88/04/04 88/03/30 88/03/29	FO!A 50:341 P 50:389 P 50:312 P 50:341 P	8804110319 8804110320	8804110305 8804110311 8804110310 8804110315 8804110324	88/04/05 88/03/28 88/04/04 68/04/05 88/03/09	70-1068 50-322 Q 50-277 Q 50-213 P 50-267 F	
6604060176 6804080180 8804080181 8804080188 8604080194	8804080175 8604080166 8804080175 8804080185 8804080189	68/03/31 68/03/26 68/03/31 88/03/29 88/03/31	50-413 O PROJ 50-413 Q 50-327 Q 50-458 O	8804110335 8804120015 8804120017	8804110322 8804110333 8804120013 8804120013 8804120016	88/04/06 88/04/04 88/04/07 88/04/07 88/03/31	60-280 Q 50-266 F 50-298 Q 50-298 Q 50-331 P	
860408D197 8604080199 8604080219 8604080221 6804080222	8804080186 8804080186 8804080196 8804080209 8804080201	88/03/31 88/03/31 88/03/28 88/04/01 88/04/01	50-344 P 50-344 P 50-462 Q 50-382 P 50-324 P	8804120035 8804120037 8804120038	8804120022 8804120030 8804120030 8804120010 8804120032	88/03/29 88/04/05 88/04/05 68/03/29 88/04/04	50-321 Q 50-458 P 50-458 P CONTRACT 50-29 O	
880408D229 8604080234 8804080240 5604080250 8804080251	B804080209 6804080201 8804080238 8804080247 8804080247	88/04/01 68/04/01 88/03/31 88/03/30 88/03/30	50-382 P 50-324 P 50-250 Q 50-382 P 50-382 P	8804120053 8804120054 8804120060	8804110150 8804120049 8804120050 8804120056 8804120039	88/03/31 88/04/04 88/04/04 88/04/05 88/04/01	50-336 P 50-277 Q 50-321 Q 50-305 Q 50-416 Q	
8804080255 8804080257 8804080258 8804080259 8804080260	8804080252 8804080253 8804080256 8804080253 8804080256	88/03/31 88/03/31 88/04/01 88/03/31 88/04/01	50-339 Q 50-338 Q 50-296 P 50-338 Q 50-298 P	8804120076 8804120082 8804120083	B804120070 B804120071 B804120074 B804110329 B804120067	88/03/25 88/04/01 88/03/29 88/03/30 88/03/29	50-289 Q 50-400 Q WASTE MGT 50-293 P 70-27	
6804060269 8804080276 8604080276 8804110004 8804110006	8804080261 8804080275 8804080275 8804110002 8804110003	88/03/29 68/03/31 66/03/31 88/03/30 88/04/01	WASTE MGT 50-425 O 50-425 O 50-382 P WASTE MGT	8804120106	8804120071 8804120090 8804120104 8804120095 8804120104	88/04/01 88/04/06 68/04/04 88/04/07 88/04/04	50-400 Q 50-327 P 50-425 Q 50-498 P 50-425 Q	
8804110011 8804110015 8804110016 8804110020 8804110022	8804110010 8804110013 8804110013 8804110013	88/03/30 88/03/29 88/03/29 88/03/29 86/03/29	50-255 P WASTE MGT WASTE MGT WASTE MGT WASTE MGT	8804120117 8804120119 8804120123 8804120131 8804120134	8804120095 8804120116 8804120095 8804120124 8804120128	88/04/07 88/04/05 88/04/07 88/04/05 88/04/05	50.498 P 50.498 Q 50.498 P 50.302 Q 50.267 Q	
8804110028 8604110033 8804110035 8804110039 8804110042	8804070027 8804110031 8804110030 8804110032 8804110032	68/03/30 88/03/29 88/04/04 88/04/04 68/04/04	50:331 F 50:445 T 50:352 G 50:320 G 50:320 G	8804120138 8804120142 8604120146	8804120130 8804120130 8804120139 8804120139 8804120154	88/04/04 88/04/04 88/04/05 88/04/05 88/04/06	50.397 P 50.397 P 50.369 C 50.369 C	
8804110049 6804110052 8804110055 8804110067 8804110068	8804110032 8804110050 8804110053 8804110065 8804110065	88/04/04 88/03/31 88/04/05 88/03/31 88/03/31	50-320 G 50-324 Q 50-425 A 50-344 P 50-344 P	8804120164 8804120167 8804120170	8904120147 8804120157 8804120163 8804120167 8804120163	88/04/06 88/03/30 88/04/05 88/03/30 88/04/05	50-458 C 50-387 F 50-416 C 50-387 F 50-416 C	
88041 10076 88041 10086 88041 10090 88041 10091 88041 10093	8804110074 6804110084 8804110057 8804110063 8804110083	88/04/04 88/03/28 88/04/05 88/04/05 88/04/05	50-250 P 50-237 P 50-331 O 50-286 R 50-286 R	8804120181 8804120187 8804120190	8804120174 8804120178 8804120182 8804120182 8804120184	88/04/04 88/04/06 88/04/01 88/04/01 88/04/01	50-335 40-3392 50-271 50-271 50-213	
8804110095 8804110097 8804110106 8804110116 8804110127	8804110085 8804110083 8804110102 8804110111 8804110083	87/12/28 88/04/05 88/04/01 88/03/25 88/04/05	70:36 50:286 R 50:267 P 70:2932 50:286 R	9 8804120199 8804120209	6604120188 9804120193 8804120184 8804120200 8804120203	88/D4/04 88/04/04 88/04/01 88/04/04 88/04/07	50-397 70-1100 50-213 50-277 50-498	
8804110132 8804110139 8804110141 8804110146 8804110161	8804110125 8804110013 8804110063 8804110063 8804110148	88/04/01 88/03/29 88/04/05 88/04/05 88/03/28	50-277 P WASTE MGT 50-286 R 50-286 R 50-387 P	8804120219 8804120223 1 8804120237	8804120200 8804120210 8804120210 8804120232 8804120188	88/04/04 88/04/05 88/04/05 88/04/04 88/04/04	\$0-277 (\$0-247 (\$0-247 (50-443 (50-397	
8804110167 8604110171 8804110172 8804110175 8604110178	8804110148 8804110157 8804110150 8804110170 8804110150	88/03/28 88/03/31 88/03/31 68/04/01 88/03/31	50:387 P 50:604 A 50:336 P 50:320 P 50:336 P	8804120255 9804120259 8804120264	8804120242 8804120012 8804120254 8804120254 8804120253	88/04/04 86/03/31 88/04/04 88/04/04 88/04/07	50-97 50-336 50-498 50-498 70-371	
8804 10189 88041 10190	8804110187 8804110187	88/03/30 88/03/30	50-320 G 50-320 G	8804120272 8804120275	8804120257 8804120267	88/04/05 88/04/05	50-250 71-490	

MCCESSION	HOMPEII				ACCCORIO	IA MOMECH			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	•
8804120276 6804120280 8604120286 8504120295 6804120297	8804120266 8804120266 8804120245 8804120277 8804120025	88/04/04 88/04/04 88/04/07 88/04/04 88/03/30	50-397 FOIA 50-289	P P P	6804130299 0804130302 6804130304 8804130316 8804130321	8804130260 8994130296 8604130298 8804130315 8804130314	89/04/08 88/04/09 89/04/07 88/04/06 88/04/05	50:789 50:327 50:368 50:369 50:307	00000
9804120302 9804120303 8804120312 8804120314 6804120325	8804120277 8804120301 8804120305 8804120305 8804120315	88/04/04 88/04/08 88/04/05 88/04/05 88/04/04	50-297 50-269 50-289	P Q P Q	8804130337 8804130340 8804130355 8804130362 8804130363	8604130333 8804130533 8934139351 8804430353 8804130360	EB/04/D5 63/04/06 68/C4/07 68/04/06 68/04/06	50-035 60-035 50-530 WASTE MOT 50-528	P P P
8884120327 8804120329 6804120339 8504120350 8804120370	8804120315 8804120305 8804120336 8804120348 8804120368	88/04/04 88/04/05 88/03/29 88/04/05 88/04/05	50-317 50-324	Q P P Q	8004130366 8804130369 8804130378 8804130382 8804130395	8904130361 8604130368 6604130376 8804130379 8604130339	83/04/08 88/04/08 88/04/04 88/03/22 88/04/07	50-277 50-528 50-29 50-289 50-400	6 6 6
2904120372 8804120373 8804120375 8904120376 8904120378	8604120368 8604120363 8804120368 8804120364 8804120366	88/03/25 88/04/04 68/03/25 88/03/31 88/04/05	70-371 50-312 50-213	0 40	8894130398 6804130403 6894430409 8804130410 8804130421	8874139388 8804130401 8804130404 8874130408 8604130418	89/04/07 88/04/06 88/04/04 88/04/01 88/04/05	50 460 PROJ 50 440 50 369 50 220	Ե Ո Ն
8864120396 6804120399 6604120400 8604120403 6604120404	8804120394 8804120394 8804120395 8804120394 8804120387	88/03/30 88/03/30 88/04/07 88/03/30 88/03/25	50-483 50-483 50-346 50-483 50-298	P Q P	8804130424 8804140007 6804140308 8804140017 8804140022	6804130418 8804146333 6804140003 6804140014 8804146314	89/04/05 88/04/06 88/04/03 89/04/07 88/04/07	50-220 50-387 50-387 50-245 50-245	9 9 1 1
8934120426 8804120428 8804120433 8504120438 8804120446	8804120420 8804120425 8804120431 8804120432 8804120442	88/04/08 88/03/25 88/04/08 88/03/29 88/03/24	50-440 50-298 50-445 50-311 50-206	P Q Q Q	8804140029 8804140030 8804140031 8804140033 8804140050	8804140011 8804140015 8804140011 8804140015 6804140034	88/04/04 88/04/68 68/04/04 88/04/68 68/04/68	50-29 60-482 60-29 60-492 50-568	P 0 P
8804120450 8304120456 6804120477 8604120478 8804130009	8804120434 8804120442 8804120471 8804120360 8804130008	88/04/06 88/03/24 88/04/07 88/04/05 88/03/28	50-324 50-206 WASTE RES 50-20 60-397	P Q V Q	8004140054 6804140067 8804140070 8804140075 8804140087	8804140034 6804080174 8804140360 8904080174 8804140025	89/04/06 88/03/31 88/04/06 88/03/31 88/04/06	50-358 NUREG 50-341 NUREG 50-341	Р О К
8804130010 8804130012 6804130014 8804130015 8804130020	8804130008 8804130008 6804130013 8804130013 8804130019	88/04/04 88/04/04 86/03/28 88/03/28 88/03/28	50-354 50-354 50-344 50-344 50-275	00000	8804140094 6804140096 8804140097 9804140101 8804140108	8904140092 8804080174 8804140081 8804140081 8804080174	88/04/08 88/03/31 88/04/04 88/04/04 88/03/31	50-443 NUREG 60 327 50 327 NUREG	b b
6804130022 854130039 8534130043 6904130048 8804130049	8804130019 8804130031 8804130033 8804180454 8804130031	88/03/28 88/03/25 88/03/14 88/03/30 88/03/25	50-275 50-265 COMMISSIO 50-324 50-255	t + 2 t 0	8804140121 8804140129 8804140130 8804140132 8804140135	6804980174 6604130062 8804080174 8804140120 8804140120	88/03/3) 88/03/14 68/03/31 08/04/08 88/04/08	NUREG COMMISSIO NUREG 60-324 60-324	N P
8804120050 6804130064 6604130071 8804130077 8804130389	8804130033 8804120318 8804130062 8804130072 8804130072	88/03/14 88/04/06 88/03/14 88/04/05 88/04/05	COMMISSIO 50-362 COMMISSIO 50-293 50-293	20200	8804140141 8804140142 8804140149 8804140167 8804140174	8904080174 6804130062 0804080174 8804149151 8804080174	88/03/31 68/03/14 88/03/31 88/03/23 68/03/31	NUREG COMMISSIO NUREG PROJ NUREG	н
6604130092 8834130398 8804130103 6804130111 8804130118	8804130062 8804130068 8804130062 8804130062 8804130062	88/03/14 88/04/05 88/03/14 88/03/14 88/03/14	COMMISSIO 50-528 COMMISSIO COMMISSIO COMMISSIO	2222	8804140177 8804140185 8804140106 8804140182 8804140186	8804140151 8804140151 8804060174 8804140151 8804140189	88/03/23 88/03/23 89/03/31 88/03/23 88/03/17	PROJ PROJ NUREG PROJ 71-4986	
6804130129 8604130140 8804130141 8804130142 6804130146	8804130123 8804130132 8804130125 8804130132 8804130118	88/04/05 88/04/08 88/04/04 88/04/06 88/04/05	50-293 50-271 50-155 60-271 FOIA	0000	8804140197 8804140200 8804140204 8804140206 8004140210	8804140151 8804140151 8804080174 8804140161 8604140151	88/03/23 88/03/23 88/03/23 88/03/23	PROJ PROJ NUREG PROJ PROJ	
8904130148 8804130151 8804130153 6804130156 8804130161	8804130143 8804130125 8804130150 8804130119 8804130119	88/03/28 88/04/04 88/04/06 88/04/05 88/04/05	CONTRACT 50:341 50:309 FOIA FOIA	S	8804140214 8804140218 8804140223 8804140224 8804140226	8804140151 8804140151 8804140183 8804140151 8904140151	08/03/23 88/03/23 88/04/06 88/03/23 88/03/23	PROJ PROJ 50-155 PROJ PROJ	P
8804130164 8804130165 6804130167 6804130169 6804130172	8804130125 8804130125 8804130119 8804130162 8804130149	89/04/04 88/04/04 88/04/05 88/04/04 89/03/17	50-155 \$0-165 FOIA 50-213 COMMISSIO	SP OZ	8804140229 8804140238 6804140243 0804140269 8804140276	8804140222 8804140222 8804140222 8804140262 8804080174	88/04/08 88/04/08 88/04/08 88/03/22 88/03/31	FOIA FOIA FO'A 71-651 NUREG	
8804130173 8804130178 6804130194 8804130196 8804130211	8904130119 8804130149 8804130191 8804130191 8804130209	88/04/05 88/03/17 88/04/08 88/04/08 88/03/24	FOIA COMMISSIO 50-293 50-293 50-317	N F G	8604140299 8804140292 6804140302 8804140304 9804140311	0804140285 8804140285 8804140299 8804140299 8804140296	88/04/07 88/04/07 88/04/08 88/04/08 88/03/31	50:324 50:324 50:324 50:324 50:280	P P P O
6804130215 8804130223 8804130224 8804130229 8804130233	8804130208 8804130213 8804130212 8804130225 8804130222	88/03/24 88/04/05 88/04/05 88/03/28 88/03/22	60-317 WASTE MGT FOIA 50-338 50-328	o V U	8804140348 8804140351 8804140353 8804140355 8804140356	8604140323 8804080174 8804090174 8804090174 8804140323	88/04/04 98/03/31 88/03/31 88/03/31 88/04/04	OA999 NUREG NUREG NUREG OA990	
6804130234 5804130239 6804130248 8804130258 8804130270	8804130230 8804130212 8804130212 8804130212 8804130289	88/04/05 68/04/05 68/04/05 88/04/05 88/04/11	50-397 FOIA FOIA FOIA 50-260	P	8804140358 8804140383 8804140383 8804140410 8804140428	8804080174 8804080174 8804080174 8804080874 8804080097	88/03/31 98/03/31 86/03/31 88/03/31 88/03/31	NUREG NUREG NUREG NUREG 50-338	P
8804130280 8804130284	8804130278 8804130283	88/03/28 88/03/31	50-498 COMMISSIO	P N	8804140439 8804140449	8804080174 8804140438	88/03/31 88/04/05	NUREG 60 409	0

ACCESSION NUMBER ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8804140506	8804140490	88/04/11	50-341 P	8804150371	8804150090	88/04/12	WASTE MGT
8804140507	8804140495	88/03/28	CONTRACT	8804150382	8804150375	88/03/25	71-545
8804140515	8804140511	88/03/21	50-334 P	8804150383	8804080174	88/03/31	NUREG
8804140520	8804140511	88/03/21	50-334 P	8804150386	8804150381	88/04/08	50-395 O
8804140526	8804140524	88/04/06	50-331 P	8804150390	8804080174	88/03/31	NUREG
8804140528	8804140511	88/03/21	50-334 P	8804150396	8804150392	88/04/07	50-413 Q
6804140543	8804140541	86/03/22	50-454 P	8804150399	8804150378	88/04/11	50-298 Q
6804140544	8804140541	88/03/22	50-454 P	8804150400	8804150087	88/04/11	50-369 P
8804150008	8804140541	88/04/08	50-373 Q	8804150402	8804150090	88/04/12	WASTE MGT
8804150009	8804150005	88/04/08	50-373 Q	8804150403	8804080174	88/03/31	NUREG
8804150011	8804080174	89/03/31	NUREG	8804150416	8804150090	88/04/12	WASTE MGT
8804150014	8804150012	88/04/06	50-458 P	8804150418	8804150090	88/04/12	WASTE MGT
8804150017	8804150012	68/04/06	50-458 P	8804150418	8804160090	88/04/12	WASTE MGT
8504150018	8804150016	8B/04/06	50-295 O	8804150425	8804150411	88/04/07	50:348 Q
8804150028	8804150023	8B/04/06	50-530 P	8804150425	8804150090	88/04/12	WASTE MGT
8804150027	8804150021	88/04/07	50-285 P	8804150434	8804150421	88/04/12	50-324 P
8804150036	8804150034	68/03/23	TOPREP	8804150436	8804150421	88/04/12	50-324 P
8804150045	8804080174	68/03/31	NUREG	8804150438	8804150431	88/04/08	50-388 P
6804150046	8804160016	88/04/08	50-295 Q	8804150439	8804150431	88/04/08	50-388 P
8804150053	8804160050	88/04/11	50-315 Q	8804180006	8804180003	88/03/28	WASTE RES
8804150059	0804150055	88/04/11	50-353 A	8804160091	8804150389	88/04/08	50-220 P
8804150064	0804080174	88/03/31	NUREG	8804180119	8804080174	89/03/31	NUREG
8804150068	9804150038	88/04/11	50-413 P	8804180136	8804080174	88/03/31	NUREG
8804150070	8604150038	88/04/11	50-413 P	8804180165	8804180160	88/04/12	FOIA
8804150074	8804150063	88/03/30	CONTRACT	6804180171	8804180155	88/04/08	50-382 P
6804150076	8804150062	88/04/11	50-454 Q	8804180186	8804180160	86/04/12	FOIA
8604150079	6804150065	68/03/30	CONTRACT	8804180187	6804180176	66/04/13	70-734
8904160082	8804150067	88/04/11	CONTRACT	8804180200	8804180160	88/04/12	FOIA
6804150083	6804150076	68/03/31	50-320 P	8804180205	6804180160	86/04/12	FOIA
8804150085	6804150068	88/04/11	50-409 F	8804180209	8804180160	88/04/12	FOIA
8804150094	8904150066	88/03/28	CONTRACT	8804180213	8804180185	88/04/11	60-183 F
8804150096	8804150087	88/04/11	50-369 P	8804180223	8804180160	88/04/12	FOIA
8804150099	8904080174	88/03/31	NUREG	8804180227	8804180204	88/04/07	50-250 P
8804150102	8804150019	88/04/11	50-206 P	8804180238	8804180160	88/04/12	FOIA
8804150103	8904160100	88/04/05	50-418 Q	8804180251	8804180160	88/04/12	FOIA
0804150104	8804150087	88/04/11	60:389 P	8804180264	8804180160	88/04/12	FOIA
8804150118	8804150107	88/04/08	50:327 Q	8804180278	8804180180	88/04/12	FOIA
8804150123	8804150117	88/04/11	50:281 P	8804180282	8804180332	88/04/08	50-445 A
8804160125	8804150117	88/04/11	50:281 P	8804180283	8804180277	88/03/18	50-454 P
6804160132	8804160107	88/04/08	50:327 Q	8804180283	8804180180	88/04/12	FOIA
6604150136	8804150126	88/04/04	50-387 P	8804180293	8804180160	68/04/12	FOIA
6804150141	8804150126	88/04/04	50-387 P	8804180295	8804180160	88/04/12	FOIA
8804150144	8804150140	88/04/12	71-423	8804180298	8804150422	88/04/11	50-338 P
8804160151	8804150089	98/03/31	CONTRACT	8804180308	8804180307	88/04/05	CONTRACT
8804160156	6804150160	88/03/30	50-354 P	8804180333	8804180322	88/04/11	50-322 U
8804150160	8804150150	88/03/30	50-354 P	8804180338	8804180336	88/04/13	50-317 A
8804150162	8904150153	88/04/12	71-545	8904180343	8804180336	88/04/13	50-317 A
8804160163	8804150159	88/04/0 8	50-327 Q	9804180387	8804180361	88/04/08	50-454 P
8804150173	8804160189	88/04/11	50-354 P	8804180397	8804180361	88/04/08	50-454 P
8804160176	8804160181	88/03/22	CONTRACT	6804180417	8804180416	88/03/31	50-397 Q
6604160186	8804150179	87/08/24	CONTRACT	8804180432	8804180420	68/04/11	60-482 1
8804150187	8804150184	88/04/12	71-841	8804180439	8804180420	88/04/11	50-482 1
6804160192	8804150182	88/03/23	CONTRACT	8804180453	8804180348	88/04/08	FOIA
8804160198	8804150183	88/03/11	CONTRACT	6804180458	8804180452	88/04/01	50-409 P
6804160198	8804150182	88/03/23	CONTRACT	8804180460	8804180456	8B/04/13	70-734
8804150199	8804150038	88/04/11	60-413 P	8804180461	8804180454	88/03/30	50.324 F
8804150201	8804150172	88/04/07	50-302 Q	8804180465	8804180464	88/04/11	50.461 P
8804160202	8804150182	88/03/23	CONTRACT	8804180006	8604190005	88/04/07	70-143
8804150208	8804150205	88/04/07	50-302 Q	8804190007	8804190003	88/04/11	60.445 Q
8804160217	8804150210	88/03/31	CONTRACT	8804190017	8804190013	88/04/12	50-254 Q
8804150222	8804150221	88/04/12	71-420	8804190018	8804250074	68/04/04	50-298 S
8804150227	8804080174	88/03/31	NUREG	8804190027	8804190024	88/04/15	QA999
8804150228	8804150210	88/03/31	CONTRACT	8804190034	8804190024	88/04/15	QA999
8804150240	8804150237	88/03/30	CONTRACT	8804190045	8804190041	88/04/12	50-423 P
8804150253	8804150252	88/03/30	71-9078	8804190049	8804190047	88/04/12	50-255 P
8804150268	8804150263	88/04/05	CONTRACT	8804190051	8804190043	88/04/11	50-87 W
8804160271	6804080174	88/03/31	NUREG	8804190058	8804190056	88/04/07	50-369 P
8804150282	8804150090	88/04/12	WASTE MGT	8804190060	8804190050	88/04/13	FOIA
8804150287	8804080174	88/03/31	NUREG	8804190069	8804190050	88/04/13	FOIA
8804150288	8804150090	88/04/12	WASTE MGT	8804190074	8804180403	88/03/24	71-9193
8604150299	8804150289	88/04/07	50-348 Q	6804190076	8804190063	88/04/11	50-410 P
8804160317	8804150090	88/04/12	WASTE MGT	8804190077	8804190050	88/04/13	FOIA
8604150322	8804080174	88/03/31	NUREG	8804190084	8804190063	88/04/11	50-410 P
8804160330	8804150090	88/04/12	WASTE MGT	8804190085	8804130191	88/04/06	50-293 F
8804150336	8804150310	88/04/04	CONTRACT	8804190087	8804190080	88/04/13	50-338 P
8804150337	8804080174	88/03/31	NUREG	8804190090	8804190082	88/04/08	50-418 P
8804150339	8804140222	88/04/08	FOIA	8804190092	8804190091	88/03/29	50-206 Q
8804150344	8804150335	88/04/07	50-83	8804190096	8804190083	88/04/05	50-282 P
8804160345	8804150090	88/04/12	WASTE MGT	8804190098	8804190086	88/04/07	50-267 P
6804150346	8804150328	88/04/05	CONTRACT	6804190099	8604190083	88/04/06	60-277 P
8804150349	8804150335	88/04/07	50-83 Q	8804190101	8804130191	88/04/08	50-293 F
8804150352	8804150080	88/04/12	WASTE MGT	8804190106	8804190086	88/04/07	60-267 P
8804150355	8804150090	88/04/12	WASTE MGT	8804190108	8804190093	88/04/06	50-277 P
8804150367	8804160326	88/04/07	50-416 Q	8804190111	6804190107	88/04/12	60-302 P
8804150359	8804080174	88/09/31	NUREG	8804190112	8804190104	88/03/30	50-528 Q
8804150367	8804160990	88/04/12	WASTE MGT	8804190113	8804190104	88/03/30	50-528 Q
8804150369	8804080174	88/03/31	NUREG	8804190115	8804190078	88/04/13	FOIA

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8804190120 8804190132 8804190134 8804190142 8804190143	8804190119 6804190131 8804190131 6804190137 8804190137	88/03/30 68/04/01 68/04/01 68/04/11 68/04/11	50-344 1	B804200112 B804200113 B804200127 B804200153 B804200163	8804200108 6804200058 8804200118 6804190242 8804200166	88/04/13 88/04/13 88/04/13 88/04/14 88/04/13	50-528 Q 50-322 T 50-317 Q 50-275 P 50-286 Q	
8804190149 8804190162 8804190167 8804190160 8804190164	8804190145 8804190147 8804190154 8804190154 8804190162	88/03/30 88/04/08 88/03/30 88/03/30 88/04/01	CONTRACT 50-528 (B804200194 8804200231 B904200235 B804200238 B804200272	8804200172 8904200223 8804190329 8804200223 8804200261	88/04/13 88/04/07 88/04/11 88/04/07 86/04/12	50-336 Q 50-423 P 70-1201 50-423 P 50-312 Q	
8804190166 8804190170 8804190173 8804190179 8804190181	8804080174 8804080174 8804080174 8804190174 8804190175	88/03/31 88/03/31 88/03/31 88/04/13 88/04/07	NUREG NUREG NUREG CONTRACT 50-341	8804200281 8804200286 8804200289 8804200307 8804200310	6804200232 8804200276 6804200279 8804200297 6804200305	8B/04/15 68/04/08 8B/04/13 8B/04/13 8B/04/12	WASTE MGT 50:250 O CONTRACT 50:298 F CONTRACT	
6804190187 8804190190 8804190197 8804190207 8604190208	9804190184 8804190184 9804190191 8804190196 8804190184	88/04/11 88/04/11 88/04/14 88/03/22 88/04/11	50-409 (FOIA 50-341 (P 8804200322 P 8804200362 8804200365 P 8804200367 P 8804200400	8904200315 8604200361 8804200363 8804200363 8804200397	88/04/08 88/04/12 88/04/13 68/04/13 88/04/15	50-305 P CONTRACT 50-395 P 50-395 P 50-445 Q	
8804190214 8804190217 8804190218 8804190220 8804190221	8604190204 8804190213 8804190211 8804190204 8804190215	68/04/08 88/04/11 68/04/13 88/04/08 68/04/11	ORG 50-341 50-213	P 8804200404 8804200408 F 8804200413 P 8604200424 P 8804200426	8804200398 8804200405 6894200440 8804200421 8804200414	86/04/05 88/04/14 88/04/13 88/04/14 88/04/12	CONTRACT 50-461 Q 50-341 Q 50-456 Q CONTRACT	
8804190222 8804190223 8804190226 8804190234 8804190239	8604190213 8804190215 8804190191 8804190274 8804190274	88/04/11 88/04/11 88/04/14 88/03/31 88/03/31	FOIA 60-219	8804200429 P 8804200449 8804200452 P 8804200462 P 8804200469	8804200421 8804200445 8804200444 8804200451 8804200465	88/04/14 88/04/05 88/04/15 88/04/04 88/04/08	50:456 Q CONTRACT 50:445 A CONTRACT CONTRACT	
8804190241 8804190244 8804190246 8804190247 8804190249	8804190235 8804190191 8804190230 8804190235 8804190230	88/04/11 88/04/14 88/04/12 88/04/11 88/04/12	FOIA 50:361 (50:410	P 8804200475 8804200485 Q 8804200488 P 8804200491 Q 8804200497	8804200461 6804200492 8804200467 6804200473 8804200473	88/04/11 88/04/12 88/03/25 88/04/14 88/04/14	CONTRACT CONTRACT 50-305 Q FOIA FOIA	
8804 190255 8804 190256 8804 190260 8804 190262 8804 190263	8804190191 8804190240 8804190191 8804190258 8804190191	88/04/14 88/04/13 88/04/14 88/04/04 88/04/14	FOIA FOIA FOIA 50-499 FOIA	8604200500 8804200502 8804200504 A 8804200505 8604200500	8804210437 8804200467 8804200494 8804200468 8804200481	88/04/13 88/03/25 88/03/28 88/04/01 88/04/12	50-528 P 50-305 Q CONTRACT 50-528 Q 50-331 Q	
8804190271 8804190276 8804190277 8804190278 8804190282	8804190266 8804190191 8804190267 8804190268 8804190268	88/04/11 88/04/14 88/03/31 88/04/07 88/04/07	FOIA 71-9224 50-334	P 8804200519 8804200528 8604200541 P 8804200542 P 8804200550	8804200511 8804200473 8804200538 8804200529 8804200538	88/04/05 88/04/14 88/04/08 88/04/11 88/04/08	50-266 O FO/A 50-346 O 50-470 K 50-346 O	
8804190283 8804190287 8804190296 8804190301 8804190314	8804190191 8804190317 8804190317 8804190389 8804190288	88/04/14 88/04/05 88/04/05 68/04/16 88/04/11	60-219 60-354	8804200556 P 8804200558 P 8804200567 F 8804200570 P 8804200576	8804200552 8804200555 8804200473 8804200588 8804200473	88/04/06 88/04/13 88/04/14 88/03/18 88/04/14	50-250 O 60-259 O FOIA CONTRACT 50-261 O	
8804190316 8804190332 8804190333 8804190337 8804190342	8804190288 8804190330 8804190327 8804190336 8804190341	88/04/11 88/04/11 88/04/11 88/04/11 88/04/12	40-893B 50-220	P 9804200579 8804200581 P 9804200583 Q 8904200589 8804210012	8804200473 8804200473 8804200577 8804200473 8804210010	88/04/14 88/04/14 99/04/14 88/04/14 88/04/11	50:250 Q FOIA CONTRACT FOIA 50:29 P	
88Q4180348 88Q4190351 88Q4190356 88Q4190358 88Q4190359	8804190348 6804190297 6604190366 6804190357 6804190367	88/04/08 88/02/10 88/04/12 88/04/13 88/04/13	WASTE RES	8804210027 Q 8804210031 8604210036 P 8804210038 P 8604210046	8804210028 8804210025 6804210035 8804210028 6804210043	88/04/13 88/04/04 88/04/13 88/04/13 88/04/13	50-259 P FOIA 50-400 P 50-483 P 50-272 S	
8604190364 8804190379 8804190391 8804190393 8604190394	8804260401 8804190377 8804190389 8804190389 8804190389	88/04/14 85/04/11 88/04/15 88/04/15 86/04/15	60-354 50-364	8804210047 O 8804210057 R 8804210065 R 8804210076 R 8804210079	8604210043 8804210054 8804210026 8804210026 8804210026	88/04/13 88/04/14 88/04/04 88/04/04 88/04/12	50-272 S 50-366 P FOIA FOIA 50-397 P	
8804190396 8804190397 8804190402 8804200019 8804200033	8804190389 8804130361 8804190324 8804200004 8804200028	88/04/15 89/04/08 88/04/07 88/04/14 88/04/11	60-277 70-143 50-443	R 8904210083 P 8804210091 6804210093 F 8804210124 Q 8804210143	8804210026 8804210025 8804160090 8804210025 8804210025	88/04/04 88/04/04 88/04/12 68/04/04 86/04/04	FOIA FOIA WASTE MGT FOIA FOIA	
8804200044 8804200045 8804200046 8804200051 8804200059	8804200040 8804200043 8804200040 8804200042 8804200043	88/04/08 88/04/12 88/04/08 88/04/13 88/04/11	60-348 60-334 50-322	O 8804210165 F 8804210169 O 8804210162 T 8804210184 O 8804210190	8804210025 8804210025 8804210175 8804210025 8804210181	88/04/04 88/04/04 88/04/12 88/04/04 88/04/12	FOIA FOIA 50-317 P FOIA CONTRACT	
8804200062 8804200064 8804200070 8804200075 8804200080	8804200062 8804200060 8804200048 8804200074 8804200065	88/04/11 66/04/08 88/04/13 88/04/08 88/04/13	60-289 60-322	G 8804210193 Q 8604210204 G 8804210210 Q 8804210214 B804210234	8804210049 8804210025 8804210197 8804210185 8804210025	88/04/30 88/04/04 88/03/31 86/03/17 88/04/04	WASTE MGT FOIA CONTRACT COMMISSIO N FOIA	
8804200084 6804200087 8804200091 8804200094 8804200099	8804200058 8804200078 8804200089 8604200048 8804200098	88/04/13 88/04/07 88/04/11 88/04/13 88/04/07	50-322	T 8804210244 Q 8804210248 P 8804210273 G 8804210287 Q 8804210294	8804210025 8804210246 8804210270 8804210282 8804210291	88/04/04 88/04/13 88/04/14 88/04/01 88/04/12	FOIA 50:266 O 50:313 P 60:369 P 50:344 P	
6804200101 8804200110	8804200058 8804270052	88/04/13 88/04/12	50-32 <i>2</i> 50-10	T 8804210296 R 8804210309	8804210291 8804210306	88/04/12 88/04/07	50-344 P CONTRACT	

.

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO!		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8804210321 8804210326 8804210347 8804210348 8804210352	8804210317 8804210317 8804210341 6804210341 8804210350	68/04/14 98/04/14 98/04/13 98/04/13 88/04/15	50 313 50 313 50 397 50 397 50 269	Q P P	8804220121 8804220129 8804220134 8804220130 8804220145	8804220117 8804220127 8804220131 8804220131 8804220140	88/04/01 88/04/05 88/04/11 89/04/11 88/04/11	CONTRACT CONTRACT 50-348 P 50-346 P 50-344 R
8904210355 8804210364 8804210378 9804210382 8804210386	8804210351 8904210327 8804210372 8804210327 8804210362	88/04/18 98/04/12 88/04/20 98/04/12 88/04/12	50-445 50-282 50-354 50-282 50-317	A Q K Q P	8804220154 8804220159 8804220162 8804220165 8804220183	8804220153 8804220153 8804220156 8804220163 8804220181	88/02/09 88/02/09 88/04/08 87/12/18 88/04/15	50-295 R 50-295 H CONTRACT 50-10 R 50-369 P
8804210392 8804210395 8804210401 8804210406 6804210413	8604210372 8804210372 8804210372 8804210372 8804210407	88/04/20 88/04/20 88/04/20 88/04/20 88/04/07	50·354 50·354 50·354 50·354 50·280	К К К Р	8604220191 8604220202 8804220207 8804220210 8804220213	880-1220186 880-1220189 880-1220196 880-1220189 880-1220196	88/04/15 88/04/15 88/04/18 88/04/15 88/04/18	50-601 A 50-206 P 50-443 F 50-206 P 50-443 R
8604210415 8804210416 6804210422 8804210424 8604210425	8804210372 8804210372 8804210372 8804210372 8804210418	88/04/20 88/04/20 86/04/20 86/04/20 88/04/11	50-354 50-354 50-354 50-354 50-397	к к к	8904220233 8904220235 8904220236 8804220237 8804220239	8804220230 8804220189 8804220230 8804220214 8804220196	88/04/16 88/04/15 88/04/16 88/04/14 88/04/18	50-424 P 50-206 P 50-424 P 50-338 S 50-443 R
8604210427 8804210429 8804210431 8804210432 8804210433	8804210372 8804210372 8804210372 8804210372 8804210418	88/04/20 88/04/20 88/04/20 88/04/20 68/04/11	50-354 50-354 50-354 50-354 50-397	К К К Р	8804220244 8804220247 8804220248 8804220255 8804220293	8804220242 8804220246 <i>8804220242</i> 8804220254 8804220291	88/04/06 88/04/18 88/04/06 88/04/15 88/04/08	50-295 P 50-250 P 50-295 P 50-528 F 50-250 P
8804210436 8804210439 8804210440 8804210441 8804210442	8804210372 8804210372 8804210372 8804210372 8804210372	88/04/29 68/04/20 88/04/20 88/04/20 68/04/20	50-354 50-354 50-354 50-354 50-354	к к к к	8804250002 6804250004 8804250005 6804250011 8804250012	8804250001 8804250003 8804250003 8804250009 8804250007	88/04/15 86/04/15 88/04/15 88/04/12 88/04/15	50-413 P 50-285 P 50-285 P 50-250 O 50-285 P
BB04210443 B804210444 8904210445 8B04210446 BB04210447	8804210372 8804210372 8804210372 8804210372 8804210372	88/04/20 88/04/20 88/04/20 88/04/20 88/04/20	50-354 50-354 50-354 50-354 50-354	K K K	8804250016 8804250018 8804260022 8804250023 8804250024	8804250010 8804250017 6804250017 8804250019 8804250019	88/04/14 88/04/18 88/04/18 88/04/12 88/04/12	ORG 50-275 P 50-275 P 50-321 Q 50-321 Q
8804210450 8804210451 8804210456 8804210457 8804210458	8804210372 8804210418 8804210372 8804210453 8804210372	88/04/20 88/04/11 88/04/20 88/04/15 88/04/20	50:354 50:397 50:354 50:341 50:354	К Р К	8604250034 8804250043 8804250048 <i>9804250</i> 050 8804250056	8804250033 6804250039 8804250046 8804250045 6804250053	86/04/12 88/04/07 88/04/07 88/04/15 88/01/21	50-424 Q 50-344 Q 50-344 Q 50-313 Q 70-143
8804210459 8804210460 8804210462 8804210466 8804210468	8604210453 8604210452 6604210372 8804210372 8804210372	88/04/15 88/04/15 88/04/20 88/04/20 88/04/20	50-341 50-400 50-354 50-354 50-354	Р К К К	8804250061 8804250067 8804250069 8804250070 #804250080	8804250059 8804250062 8804220169 8804250068 8804250074	88/03/24 88/04/15 88/04/19 88/03/28 88/04/04	50-400 O 50-382 O 50-293 Q 50-327 Q 50-298 S
8804210469 8804210475 8804210477 8804210478 8804210483	8804210372 8804210372 6804210372 8804210372 8804210372	88/04/20 88/04/20 88/04/20 88/04/20 88/04/20	50:354 50:354 50:354 50:354 50:354	к к к к	8804250085 8804250109 8804250111 6804250115 8804250118	8804250082 8604250103 8804250103 8804250103 8604250116	88/03/30 88/04/19 88/04/19 88/04/18 88/04/18	50-424 Q 50-382 I 50-382 I 50-382 I 50-267 Q
8804210484 8804210486 6804210487 8804210488 8804210488	8804210372 8804210372 8604210372 8804210372 8804210372	88/04/20 68/04/20 88/04/20 88/04/20 89/04/20	60-354 50-354 50-354 50-354 50-354	К К К К	8804250130 8804250146 8804250151 8804250154 8804250160	8804250123 8804250144 8804250147 8804250153 8804250159	88/04/18 88/04/18 88/03/18 88/04/18 88/04/16	50-458 O 50-410 Q PT21 50-223 O 60-277 Q
8804210490 6804210491 8804210492 8604210463 8804210494	8804210372 8804210372 8804210372 8804210372 8804210372	88/04/20 88/04/20 88/04/20 88/04/20 88/04/20	50:354 50:354 50:354 50:354 50:354	к к к к	8804250162 8804250167 8804250183 6804250191 8804250193	8804250159 8804250088 8804250170 8804250182 8804250182	88/04/16 88/04/19 88/04/14 88/04/11 88/04/11	50-277 Q 50-3 V 50-283 P 50-219 Q 50-219 Q
8804210495 8804210496 8804210499 8804210501 8804210502	8804210372 8804210372 8804240372 6804210372 8804210372	88/04/20 68/04/20 86/04/20 88/04/20 88/04/20	50-354 50-354 50-354 50-354 50-354	К К К К	8804250194 8804250198 8804250210 8804250248 8804250251	8804190047 8804250197 8804280500 8804250246 8804250246	88/04/12 88/04/16 68/04/15 88/04/13 68/04/13	50-255 P 70-371 50-341 P 50-206 I 50-206 I
8804210509 8804210512 8804220007 8804220010 8804220013	8804080174 8804080174 8804220004 8604220004 8804220012	88/03/31 88/03/31 88/04/15 88/04/15 88/04/08	NUHEG NUREG 80-454 80-454 50-373	Р Р К	8804250253 8804250254 8804250287 8804250303 8804250304	8804250246 8804250246 8803280063 8804250298 8804250296	88/04/13 88/04/13 88/03/18 88/03/25 88/04/15	50-208 J 50-206 J 50-498 P 50-155 P 60-457 Q
8904220041 8804220052 8804220054 8804220057 8804220080	8804220036 8804220047 8804220050 8804220048 8804220048	88/04/13 88/04/18 88/04/14 88/04/14	50-220 50-324 50-327 50-266 50-266	Р Н Р	8804250305 8804250312 8804250315 8804250329 8804250336	8804250296 8804250310 8804250310 8804250320 8604250334	88/04/15 88/04/14 88/04/14 88/04/13 88/04/15	50-457 O 50-334 O 50-334 Q 50-309 Q 50-382 Q
8804220062 8804220065 6804220068 8804220072 6804220074	8804220045 8804210336 8804220061 6804220069 8804220108	88/04/08 88/04/18 86/04/18 88/04/18	50-293 50-324 CONTHACT CONTRACT 50-250	P P	8804260008 8804260010 8804260016 8604260017 8804260025	8804260004 8804260006 8804260014 8804260013 8804260021	88/04/18 88/04/15 88/04/20 88/04/19 88/04/13	50-328 Q 50-395 Q 50-445 Q 50-298 P 50-327 Q
8604220098 8804220099 8804220102 8804220103 8804220105	8804220097 8804220067 6804220100 8804220100 8804220067	88/04/15 88/04/16 88/03/23 88/03/23 88/04/15	50-423 70+143 50-128 50-128 70-143	Р Р	8904260027 8804260028 8804260029 8804260030 4804260031	8804260023 8804260021 8804260024 8804260026 8804260023	88/04/15 88/04/13 88/04/19 88/04/20 88/04/15	50-313 Q 50-327 Q 50-348 Q 50-341 P 50-313 Q
8804220107 8804220111	8804220106 8804220108	88/04/14 88/04/15	50-333 50-250	P R	8804260034 8804260037	8804260024 8804260011	88/04/19 8B/04/18	50-348 C 50-498 F

					N0025010	A MOMBEH			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	4
8904260039 6804260041 8804260042 9804260046 8804260048	8804260032 8804260038 8804260040 8804260038 8804260045	88/04/20 88/04/15 88/04/13 88/04/15 88/04/21	50-259 50-482 50-327 50-482 50-341	P Q Q P	8804270230 8504270238 8804270248 8804270253 8804270263	8804270136 8804270136 8804270040 8904270247 8804270252	88/04/15 88/04/15 88/04/13 68/04/18 88/04/12	50:312 50:312 PH CONTRACT 50:346	p p
8804260056 8804280060 8804260071 8604260076 8804260076	8804260053 8804260057 8804260068 8804260072 8804260067	8B/04/1B 8B/04/18 6B/04/19 8B/04/1B 8B/04/15	50-443 60-425 50-373 50-280 50-443	0000	8804270284 8304270267 8804270269 8804270278 8804270282	8864270040 8804270256 8804270040 8804270040 8804270071	88/04/13 88/04/07 88/04/13 88/04/13 88/04/12	PR 50:160 PR PR 50:483	Q P
9904260092 8804260090 8804260091 9804260092 8804260093	8804260078 8804260085 8804260079 8804260087 8804260085	88/04/14 88/04/15 88/04/18 88/04/15 88/04/15	50-369 50-3 50-443 50-443 50-3	е Р С С С	6804270308 8604270313 8804280046 8604280048 8804280048	8804270303 8804270040 8804280036 8804280042 8804280038	68/04/16 88/04/13 68/04/19 68/03/24 88/04/19	50-312 PR 50-410 40-8829 50-410	P P
8604260101 8804260104 8804260105 8604280106 8804260108	6804260097 8804260099 8804260097 8804260069 8804260100	66/04/18 68/04/15 68/04/18 68/04/19 68/04/15	50.443 50.413 50.443 50.275 50.498	9 9 9 9	8804280052 8804280057 8804280069 8804280087 8804280093	6804280034 8804280040 6804280039 8804280070 8504280088	88/04/19 85/04/13 88/04/16 88/04/15 88/04/14	50-317 50-327 50-10 CONTRACT 71-653	6 0
0804260110 8804260111 8604260113 8804260114 6804260120	8804260097 8804260094 8804260112 8804260094 9804260011	88/04/18 88/04/14 88/04/18 88/04/14 88/04/18	50-443 60-261 70-1113 50-261 60-498	G Q Q P	8804280103 8804280112 8804280129 8804280130 6804280137	8804260097 8804280105 8804280101 8804270040 8804280122	88/04/04 68/04/19 88/04/18 88/04/13 88/04/12	40-8502 50-395 50-262 PR 50-389	P P
8804260121 6804260126 8904260133 8804260170 8804260183	8804260110 8804250011 8804280089 8804260151 8804260176	88/04/15 88/04/18 88/04/19 88/04/21 88/04/15	40-8913 60-498 50-275 WASTE MGT 50-341	Р (2 О	8804280138 8804280139 8804280140 8804280144 8804280149	8804280562 8804270040 8804280010 6804280110 8804280146	88/04/01 88/04/13 88/04/16 88/04/15 88/04/11	ORG PR 50-483 50-255 70-1201	٥ 0
8804260190 8804260200 8804260205 8804260210 8804260211	8804260188 8804260194 8804260193 8804260103 8804260202	88/04/15 88/04/21 88/04/16 88/04/16 88/04/16	60-424 50-364 60-446 60-445 50-260	Q P A Q	8804280156 8804280162 8804280163 8804280168 8804280173	8604280101 8804280160 6804280157 8804270040 6804280157	88/04/18 88/04/19 88/04/19 88/04/13 88/04/19	50-282 50-324 50-285 PA 50-285	P P P
6604260245 8804260218 8804260218 8804260222 8804260226	8804280193 8804260202 8804260183 8804260193 8804260193	88/04/15 88/04/15 88/04/16 88/04/15 88/04/15	50-445 50-250 50-445 50-445 60-445	A Q A A	8804280183 8804280184 8804280216 6804280217 8804280223	6804280174 8804280189 8804280208 8804280200 8804280211	88/03/14 88/04/08 68/03/30 88/04/21 88/04/12	40-8902 50-336 50-482 50-348 50-388	F S Q P
8804260230 8804260232 8804260234 8804260235 6804260237	8804260193 8804280228 8804260216 8804260193 8804280193	88/04/15 98/04/15 68/04/21 88/04/15 88/04/15	50-445 50-280 50-133 50-445 80-445	A Q P A A	8804280247 8804280248 8804280248 8804280254 8904280257	8804280219 8804280240 8804270040 8804280219 8804280219	88/03/31 88/04/21 88/04/13 88/03/31 88/03/31	40-299 FOIA PFI 40-299 40-299	
8804280238 8604260241 8804260243 8804260247 8804260249	8804280214 8804280193 8804280103 8804280193 8804280214	88/04/22 88/04/15 88/04/16 88/04/15 88/04/22	WASTE MGT 60:446 50:445 50:446 WASTE MGT	A A	8604280262 8804280264 8804280279 8804280299 8804280319	8804280219 8804260245 8804270040 8804280287 8804280287	88/03/31 88/04/11 88/04/13 88/04/20 68/04/20	40-299 CONTRACT PR FOIA FOIA	
8804260250 8804260253 8804260254 8804260255 8804260262	8804280193 8804280193 8804280193 8804280214 8804280214	88/04/15 88/04/15 88/04/15 88/04/22 88/04/22	50-445 60-445 50-445 WASTE MGT WASTE MGT	A A A	8804280321 8804280322 8804280331 8804280333 8804280340	8804280290 8804280309 8804280290 8804280315 8804280283	88/04/08 88/04/19 88/04/08 88/03/07 88/04/21	40-1162 CONTRACT 40-1162 CONTRACT CONTRACT	
8004280287 8304260301 8604260302 8804260383 8804260370	8904260285 8804280299 8804260325 8804280359 8804260366	88/04/20 88/04/15 88/04/20 88/04/15 88/04/10	50-423 60-219 50-338 WASTE MGT WASTE MGT	P P R	8804280352 8804280361 8804280382 8804280385 8804280387	8804270040 8804280351 8804280343 8804280381 8804280271	88/04/13 88/04/18 88/04/14 88/04/07 88/04/19	PR 50:289 CONTRACT XPORTLIC 50:267	P P
6604260377 8804260412 6804270044 8804270062 8804270068	8804280374 8804280224 8804270037 8804270040 8804270040	86/04/18 88/04/19 88/04/10 88/04/13 88/04/13	60-412 FOIA 70-734 PR PR	Q	8804280388 8804280423 8804280435 8804280437 8804280440	8804280367 8804270040 8804260429 8804280412 8804280406	88/02/24 88/04/13 88/04/21 88/04/21 87/11/27	40-8905 PR CONTRACT 50-155 40-3453	Q
8804270071 8804270076 8804270081 8804270093 8804270100	8804270040 8804270040 8804270040 8804270040 8804270040	88/04/13 88/04/13 88/04/13 88/04/13 88/04/13	PA PR PA PR PR		8804280451 8804280471 8804280480 8804280484 8804280487	8804280420 8804280459 8804280465 8804280470 8804270040	88/04/19 88/02/17 88/04/18 88/04/18 88/04/13	CONTRACT CONTRACT 50:219 50:250 PR	P P
8804270103 8804270111 8304270119 8804270123 8804270129	8804270040 8004270040 8804270040 8804270113 8804270040	88/04/13 88/04/13 88/04/13 88/02/26 88/04/13	PR PR PR 50-440 PR	F	8804280491 8804280496 8804280498 8804280501 8804280509	8804280470 8804280492 8804280470 8804280495 8804280504	88/04/18 88/04/19 88/04/18 88/03/08 88/04/25	50-250 50-338 50-250 CONTRACT FOIA	P P
8804270137 8804270144 8804270156 8804270170 8804270182	8B04270040 8B04270040 8804270040 8B04270040 8B04270175	88/04/13 88/04/13 68/04/13 88/04/13 88/04/19	PR PR PR PR 50-321	ı	8804280511 8804280517 8804280532 8804280551 8804280558	8804280504 8804270040 8804280465 8804280540 8804280540	88/04/25 88/04/13 88/04/18 88/04/18 88/04/18	FO(A PR 50-219 50-266 50-266	P P P
8804270183 8804270182 8804270205 6804270213 8804270218	8804270176 6804270040 8804270040 8804270040 8804270040	88/04/19 88/04/13 88/04/13 88/04/13 88/04/13	50-321 PR PR PR PR	1	8804280571 8804280574 8804280583 8804280596 8804280599	8804280561 8804280570 8804270040 8804280590 8804270040	88/04/18 68/04/21 88/04/13 88/04/13 88/04/13	50-528 CONTRACT PR CONTRACT PR	Р
8804270219 8804270220	8804270208 8804210019	88/04/18 88/04/13	50-312 50-424	Q P	8804280608 8804280609	8804270040 8804280607	88/04/13 88/04/20	PR CONTRACT	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DUCUMENTS

8804290075 8804290076

8804290064 8804290070

88/04/22 88/04/19

50-298 50-250

ACCESSIO	N NUMBER		ACCESSION NUMBER						
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	,	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
6804280612 8804280613 8804280619 8804280626	6804280611 8804280611 8804280615 6804270040	88/04/18 88/04/18 68/04/20 88/04/13	50-423 50-423 CONTRACT PR	P	8804290077 8804290081 8804290085 6804290092	8604290066 8804290071 8804280469 8604290082	88/04/22 88/04/21 88/03/28 68/04/21	50-322 50-247 40-8943 50-443	G P
8804280632	8804270040	88/04/13	PR		8804290098	8604290087	88/04/20	50-322	G
6804280637 - 8804280639 - 8804280640 - 8604280645 - 6804280647	8804270040 8804280638 8804280834 8804270040 8804280843	88/04/13 88/04/22 88/04/14 68/04/13 88/04/20	PR 50-288 60-445 PR CONTRACT	P	8804290100 6804290103 8804290145 8804290146 8804290164	8804290089 8804290089 8804290137 8804290129 8804290151	88/04/21 88/04/19 88/04/21 88/04/26 88/04/22	FOIA CONTRACT FOIA 50-445 50-327	G P
8804280649 8804280650 8804280656 8804280657	8804270040 8804280638 8804270040 8804280638	68/04/13 88/04/22 88/04/13 88/04/22	PA 50-289 PA 50-289	P P	8804290168 8804290161 8804290198 8804290228 8804290245	8709300402 8804290172 8804290191 8804290190 8804290217	87/06/31 86/04/21 86/04/19 88/04/18 88/04/25	50-254 50-458 CONTRACT CONTRACT 50-82	ъ Б
8804280661 6804280664 8804280665 8804280666 8804280669	8804280636 8804280636 8804270040 8804280663 880427004D	88/04/22 88/04/22 88/04/13 88/04/20 88/04/13	50-289 50-289 PR CONTRACT PR	Þ	8804290247 8804280265 8804290267 8804290271 8804290274	8804290217 8804280270 8804290240 8804290240 8804290240	88/04/25 88/04/20 88/04/25 88/04/25 88/04/21	50-82 50-254 FOIA FOIA 50-289	P F
8804290008 8804290038 8804290051	6804290006 6804290030 6804290055	88/04/25 88/04/21 88/02/04	71-598 50-322 70-734	G	8805030070 8805030121 8805030128 8805030139	8804270040 9804270040 8804270040 8804270040	88/04/13 88/04/13 88/04/13 88/04/13	PR PR PR PR	
6804290053 8804290054 8804290072	8804280413 8804290047 8804290067	88/04/22 88/04/15 88/04/19	XPORTLIC 50-443 CONTRACT	G	8805030161 8805030161 8805030170	8804270040 8804270040 8804270040	88/04/13 88/04/13 88/04/13	PR PR PR	_
8804290075	8804290064	88/04/22	50-298	P	8805030253	8804220196	88/04/18	50-443	R

P

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- Transmittal and acknowledgement letters.
- 4. Certificates of service to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

rictly limited to the items listed below. Other documents dealing with safety iled in categories A, P or W, depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWAs.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review"
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the Issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletius (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (ENs).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual operating reports (other than financial),
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNOS, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNs).
- Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1.7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.
- 8. Corrections to above items.

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- 3. Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

- License applications, licenses, amendments and proposed amendments to possess power reactor spent
 fuel and other radioactive materials associated with spent storage in an independent spent fuel
 storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate
 site.)
- 2. All related correspondence and reports to the above.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

ADVCM - NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

- 1. Charters of each advisory committee.
- 2. Verbatim transcripts of committee meetings.

- 3. Meeting announcements; description of meeting agendas.
- 4. Committee generated reports, memoranda, and correspondence that are publicly available.
- 5. Committee related correspondence.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

- 1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RIP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4 Contractual documents and contract modifications, if any.

DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
 - Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
- 3. Meeting notifications and minutes.
- Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. 1&F Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. 1&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. 1&F Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of livents (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG -- NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- These reports are normally final work products and are characterized by the following criteria:
 - They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
- Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

- 1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility.
 - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application.
 - 6. Early site visits.
- B. Utility PSAR and Amendments
 - 1. PSARs submitted by the utility.
 - 2. Amendments and changes to the PSAR.
 - 3. Transmittal letters.
 - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
 - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
 - 1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- 1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RJLs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- 2. Summary minutes of review group meetings representing views expressed, includo a dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG – State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of haison and cooperative activities regarding such functions as licensing and siting. It includes:

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations, i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

WASTE RES - Waste Management Research Reports

Contains interim and final reports, and correspondence submitted to NRC by its contractors doing research on topics related to the storage of high-level radioactive waste.

- 1. Periodic progress reports on the status of research.
- 2. Trip reports of travel by NRC and contractor personnel.
- 3. Draft, partial or related reports submitted for NRC review or information.
- 4. Correspondence between NRC staff and contractors relating to technical questions or issues to be resolved.

XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, liceuse amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

action of the control	VOI. 10, 110.	-1		
2 TITLE AND SUBTITLE	3 LEAVE BLANK			
Title List of Documents Made Publicly Available				
April 1-30, 1988	4 DATE REPORT CUMPLETED			
	MT AOM	>€AR		
S AUTHORISI	6 DA1E A6	PCR1 ISSUED		
	HINCM	YEAR		
	June	1988		
Division of Freedom of Information and Publications Servi	9 PROJECT TASK WORK UNIT	NUMBE 9		
Office of Administration and Resources Management U.S. Nuclear Regulatory Commission Washington, DC 20555	9 FIN OR GHANT NUMBER			
10 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Z.p. Code)	11a TYPE OF REPORT	·		
	Monthly			
Same as 7, above.	D PERIOD COVERED (Including dates)			
	b tenior covenes (meaning origi)			
	April 1-30,	1988		
17 SUPPLEMENTARY NOTES	•			
13 ABSTRACT (200 words or less)				
This document is a monthly publication containing descrip and generated by the U.S. Nuclear Regulatory Commission (includes (1) docketed material associated with civilian ruses of radioactive materials, and (2) nondocketed materi NRC pertinent to its role as a regulatory agency. The for Personal Author, Corporate Source, Report Number, and Cro Documents.	NRC). This informuclear power plantal received and collowing indexes a	rmation its and other generated by are included: Principal		
		STATEMENT		
title list		Unlimited		
		UNITMITED		
		(This page)		
6 IDENTIFIERS/OPEN-ENDED TERMS		<u>Unclassified</u>		
		(This report)		
		Unclassified		
		18 PRICE		
		<u></u>		